

Phone: +1 912-298-1325

Fax: 1-912-963-0265/1-800-944-1775

Analyst: Duane Gerdes

| Airframe & Component Times |          |                                            |            |             | Total Time |        |
|----------------------------|----------|--------------------------------------------|------------|-------------|------------|--------|
| Logbook                    | Position | Description                                | Serial No. | Log Date    | Hours      | Cycles |
| Airframe                   |          | GULFSTREAM AEROSPACE CORPORATION<br>G650   | 6160       | 23 Mar 2026 | 3046.1     | 1117   |
| Engine                     | 1        | ROLLS-ROYCE DERBY PLC BR725A1-12<br>(G650) | 26163      | 23 Mar 2026 | 994.4      | 392    |
| Engine                     | 2        | ROLLS-ROYCE DERBY PLC BR725A1-12<br>(G650) | 26162      | 23 Mar 2026 | 994.4      | 392    |
| APU                        |          | HONEYWELL RE220(GVI)                       | P-269      | 23 Mar 2026 | 2266.5     | 0      |

| ATA<br>U=Custom  | Description   |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|---------------|---------------|-----|-------------|-----------------|-----|------------------|----------|--------------------|---------|--------------|
|                  | Part Number   | Serial Number |     |             |                 |     |                  |          |                    |         | Approx Price |
| Logbook Position | HW            | SW            |     |             |                 |     |                  |          |                    |         | Manufacturer |
|                  | MM Ref        |               |     |             |                 |     |                  |          |                    |         | Date Type    |
|                  | Ops Number(s) |               |     |             |                 |     |                  |          |                    |         |              |

**00 - General****004 OK-EVO<sup>U</sup>**

English/Czech Bilingual Interior Placards Are Installed  
Instead of Only English Placards on Positions Specified  
By Customer. New Internal Placards SET Is Locally  
Manufactured. Placards Raw Material/Foils Are Approved.  
Cross Reference Tables Showing Original Ipc P/Ns and  
Production P/Ns Is Issued

HRS  
AFL  
MOS  
MSC

O/C\*\*

0  
0

Airframe

**01 - Watch List****010010**

Service Center Maintenance Induction Checklist

HRS  
AFL  
MOS  
MSC

1300.7  
507  
51.9

1745.4  
610  
15 Jan 2022

0  
0

Airframe

O/C

**05 - Time Limits/Maintenance Checks**

| ATA<br>U=Custom  | Description                                                                                        |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                                        | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                                                 | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                                             |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                                                      |               |     |             |                 |     |                  |             |                    |         |              |
| 055001           | Aircraft Exposure to Volcanic ASH - Inspection, 05-50-00, Inspection / Check                       |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                    |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                    |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                                    |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                                    |               |     |             |                 |     |                  |             |                    |         |              |
| 055002           | Aircraft Residual Deicing / Anti-Icing Fluid - Inspection / Cleaning, 05-50-00, Inspection / Check |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                    |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                    |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                                    |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                                    |               |     |             |                 |     |                  |             |                    |         |              |
| 055003           | Aircraft Runway Departure - Inspection, 05-50-00, Inspection / Check                               |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                    |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                    |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                                    |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                                    |               |     |             |                 |     |                  |             |                    |         |              |
| 055004           | Birdstrike - Inspection, 05-50-00, Inspection / Check                                              |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                    |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                    |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                                    |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                                    |               |     |             |                 |     |                  |             |                    |         |              |
| 055005           | Birdstrike to Horizontal Stabilizer Leading Edge - Inspection, 05-50-00, Inspection / Check        |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                    |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                    |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                                    |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                                    |               |     |             |                 |     |                  |             |                    |         |              |
| 055006           | Cockpit Side Window Distortion - Inspection, 05-50-00, Inspection / Check                          |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                    |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                    |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                                    |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                                    |               |     |             |                 |     |                  |             |                    |         |              |
| 055007           | Engine FIRE Extinguisher Discharge - Follow-Up Requirements, 05-50-00, Inspection / Check          |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                    |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                    |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                                    |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                                    |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                         |               | UOM  | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-------------------------------------------------------------------------------------|---------------|------|-------------|-----------------|-----|------------------|----------|--------------------|---------|--------------|
|                  | Part Number                                                                         | Serial Number |      |             |                 |     |                  |          |                    |         | Approx Price |
| Logbook Position | HW                                                                                  | SW            |      |             |                 |     |                  |          |                    |         | Manufacturer |
|                  | MM Ref                                                                              |               |      |             |                 |     |                  |          |                    |         | Date Type    |
|                  | Ops Number(s)                                                                       |               |      |             |                 |     |                  |          |                    |         |              |
| 055008           | Failure of Landing Gear Wheel or Tire - Inspection, 05-50-00, Inspection / Check    |               | HRS  |             | 3046.1          |     |                  | 0        |                    |         | 0            |
|                  |                                                                                     |               | AFL  |             | 1117            |     |                  | 0        |                    | 0       |              |
|                  |                                                                                     |               | MOS  |             | 128.6           |     | 24 Aug 2015      |          |                    |         |              |
|                  |                                                                                     |               | MSC  |             |                 | O/C |                  |          |                    |         |              |
| Airframe         |                                                                                     |               |      |             |                 |     |                  |          |                    |         |              |
| 055009           | Flap Airspeed Exceedances - Inspection, 05-50-00, Inspection / Check                |               | HRS  |             | 3046.1          |     |                  | 0        |                    |         | 0            |
|                  |                                                                                     |               | AFL  |             | 1117            |     |                  | 0        |                    | 0       |              |
|                  |                                                                                     |               | MOS  |             | 128.6           |     | 24 Aug 2015      |          |                    |         |              |
|                  |                                                                                     |               | MSC  |             |                 | O/C |                  |          |                    |         |              |
| Airframe         |                                                                                     |               |      |             |                 |     |                  |          |                    |         |              |
| 055010           | Flight Control Structures High Wind Gust - Inspection, 05-50-00, Inspection / Check |               | HRS  |             | 3046.1          |     |                  | 0        |                    |         | 0            |
|                  |                                                                                     |               | AFL  |             | 1117            |     |                  | 0        |                    | 0       |              |
|                  |                                                                                     |               | MOS  |             | 128.6           |     | 24 Aug 2015      |          |                    |         |              |
|                  |                                                                                     |               | MSC  |             |                 | O/C |                  |          |                    |         |              |
| Airframe         |                                                                                     |               |      |             |                 |     |                  |          |                    |         |              |
| 055011           | Hail Damage to Aircraft / Engine - Inspection, 05-50-00, Inspection / Check         |               | HRS  |             | 3046.1          |     |                  | 0        |                    |         | 0            |
|                  |                                                                                     |               | AFL  |             | 1117            |     |                  | 0        |                    | 0       |              |
|                  |                                                                                     |               | MOS  |             | 128.6           |     | 24 Aug 2015      |          |                    |         |              |
|                  |                                                                                     |               | MSC  |             |                 | O/C |                  |          |                    |         |              |
| Airframe         |                                                                                     |               |      |             |                 |     |                  |          |                    |         |              |
| 055012           | Hail Damage to Fan Cowl Doors - Inspection, 05-50-00, Inspection / Check            |               | HRS  |             | 3046.1          |     |                  | 0        |                    |         | 0            |
|                  |                                                                                     |               | AFL  |             | 1117            |     |                  | 0        |                    | 0       |              |
|                  |                                                                                     |               | MOS  |             | 122             |     | 11 Mar 2016      |          |                    |         |              |
|                  |                                                                                     |               | MSC  |             |                 | O/C |                  |          |                    |         |              |
| Airframe         |                                                                                     |               |      |             |                 |     |                  |          |                    |         |              |
| 055013           | Hard / Overweight Landing - Inspection, 05-50-00, Inspection / Check                |               | HRS  |             |                 |     |                  |          |                    |         | 0            |
|                  |                                                                                     |               | AFL  |             |                 |     |                  |          |                    | 0       |              |
|                  |                                                                                     |               | DATE |             |                 |     |                  |          |                    |         |              |
|                  |                                                                                     |               | MSC  |             |                 | O/C |                  |          |                    |         |              |
| Airframe         |                                                                                     |               |      |             |                 |     |                  |          |                    |         |              |
| 055014           | Landing Gear Airspeed Exceedances - Inspection, 05-50-00, Inspection / Check        |               | HRS  |             |                 |     |                  |          |                    |         | 0            |
|                  |                                                                                     |               | AFL  |             |                 |     |                  |          |                    | 0       |              |
|                  |                                                                                     |               | DATE |             |                 |     |                  |          |                    |         |              |
|                  |                                                                                     |               | MSC  |             |                 | O/C |                  |          |                    |         |              |
| Airframe         |                                                                                     |               |      |             |                 |     |                  |          |                    |         |              |

| ATA<br>U=Custom  | Description                                                                                                                                 |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|---------------------------------------------------------------------------------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|----------|--------------------|---------|--------------|
|                  | Part Number                                                                                                                                 | Serial Number |                     |             |                 |     |                  |          |                    |         | Approx Price |
| Logbook Position | HW                                                                                                                                          | SW            |                     |             |                 |     |                  |          |                    |         | Manufacturer |
|                  | MM Ref                                                                                                                                      |               |                     |             |                 |     |                  |          |                    |         | Date Type    |
|                  | Ops Number(s)                                                                                                                               |               |                     |             |                 |     |                  |          |                    |         |              |
| 055015           | Lightning Strike - Inspection, 05-50-00, Inspection / Check                                                                                 |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                  |                                                                                                                                             |               | AFL                 |             |                 |     |                  |          |                    | 0       |              |
|                  |                                                                                                                                             |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                  |                                                                                                                                             |               | MSC                 |             |                 |     | O/C              |          |                    |         |              |
| Airframe         |                                                                                                                                             |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| 055016           | Maximum Cabin Pressurization Limits Exceeded -<br>Inspection, 05-50-00, Inspection / Check                                                  |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                  |                                                                                                                                             |               | AFL                 |             |                 |     |                  |          |                    |         | 0            |
|                  |                                                                                                                                             |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                  |                                                                                                                                             |               | MSC                 |             |                 |     | O/C              |          |                    |         |              |
| Airframe         |                                                                                                                                             |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| 055017           | Nonpermissible Tire Damage - Inspection, 05-50-00,<br>Inspection / Check                                                                    |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                  |                                                                                                                                             |               | AFL                 |             |                 |     |                  |          |                    |         | 0            |
|                  |                                                                                                                                             |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                  |                                                                                                                                             |               | MSC                 |             |                 |     | O/C              |          |                    |         |              |
| Airframe         |                                                                                                                                             |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| 055018           | Nose Wheel Steering Over Travel - Inspection, 05-50-00,<br>Inspection / Check                                                               |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                  |                                                                                                                                             |               | AFL                 |             |                 |     |                  |          |                    |         | 0            |
|                  |                                                                                                                                             |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                  |                                                                                                                                             |               | MSC                 |             |                 |     | O/C              |          |                    |         |              |
| Airframe         |                                                                                                                                             |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| 055019           | Ram AIR Turbine In-Flight Deployment - Inspection, 05-50-00,<br>Inspection / Check                                                          |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                  |                                                                                                                                             |               | AFL                 |             |                 |     |                  |          |                    |         | 0            |
|                  |                                                                                                                                             |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                  |                                                                                                                                             |               | MSC                 |             |                 |     | O/C              |          |                    |         |              |
| Airframe         |                                                                                                                                             |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| 055020           | Severe Turbulence - Inspection, 05-50-00, Inspection /<br>Check                                                                             |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                  |                                                                                                                                             |               | AFL                 |             |                 |     |                  |          |                    |         | 0            |
|                  |                                                                                                                                             |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                  |                                                                                                                                             |               | MSC                 |             |                 |     | O/C              |          |                    |         |              |
| Airframe         |                                                                                                                                             |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| 055021           | Inspection Procedure IF There Is A Partial or Full Release<br>of an Lp Compressor (Fan) Blade - Inspection, 05-50-00,<br>Inspection / Check |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                  |                                                                                                                                             |               | AFL                 |             |                 |     |                  |          |                    |         | 0            |
|                  |                                                                                                                                             |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                  |                                                                                                                                             |               | MSC                 |             |                 |     | O/C              |          |                    |         |              |
| Airframe         |                                                                                                                                             |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |

| ATA<br>U=Custom                              | Description                                                                                            |               | UOM  | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|----------------------------------------------|--------------------------------------------------------------------------------------------------------|---------------|------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                              | Part Number                                                                                            | Serial Number |      |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position                             | HW                                                                                                     | SW            |      |             |                 |     |                  |             |                    |         | Manufacturer |
|                                              | MM Ref                                                                                                 |               |      |             |                 |     |                  |             |                    |         | Date Type    |
|                                              | Ops Number(s)                                                                                          |               |      |             |                 |     |                  |             |                    |         |              |
| 055022                                       | Aircraft Exposure to Dry Chemical FIRE Extinguishing Agent - Restoration, 05-50-00, Inspection / Check |               | HRS  |             |                 |     |                  |             |                    |         | 0            |
|                                              |                                                                                                        |               | AFL  |             |                 |     |                  |             |                    | 0       |              |
|                                              |                                                                                                        |               | DATE |             |                 |     |                  |             |                    |         |              |
|                                              |                                                                                                        |               | MSC  |             |                 |     | O/C              |             |                    |         |              |
| Airframe                                     | [End Of Month Item]                                                                                    |               |      |             |                 |     |                  |             |                    |         |              |
| 055023                                       | High Energy Stop on Landing or Takeoff (Brake Kinetic Energy Exceedance) - Inspection                  |               | HRS  |             |                 |     |                  |             |                    |         | 0            |
|                                              |                                                                                                        |               | AFL  |             |                 |     |                  |             |                    |         | 0            |
|                                              |                                                                                                        |               | DATE |             |                 |     |                  |             |                    |         |              |
|                                              |                                                                                                        |               | MSC  |             |                 |     | -                |             |                    |         |              |
| Airframe                                     | [End Of Month Item]                                                                                    |               |      |             |                 |     |                  |             |                    |         |              |
| 055024                                       | Inspection of the Engine after Cabin Odour or Smoke In the Cabin Event - Inspection                    |               | HRS  |             |                 |     |                  |             |                    |         | 0            |
|                                              |                                                                                                        |               | AFL  |             |                 |     |                  |             |                    |         | 0            |
|                                              |                                                                                                        |               | MOS  |             |                 |     |                  |             |                    |         |              |
|                                              |                                                                                                        |               | MSC  |             |                 |     | A/R              |             |                    |         |              |
| Airframe                                     | [End Of Month Item]                                                                                    |               |      |             |                 |     |                  |             |                    |         |              |
| 08 - Leveling and Weighing                   |                                                                                                        |               |      |             |                 |     |                  |             |                    |         |              |
| 080001                                       | Weight & Balance Aircraft                                                                              |               | HRS  |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                                              |                                                                                                        |               | AFL  |             | 315             |     |                  | 802         |                    |         | 0            |
|                                              |                                                                                                        |               | MOS  |             | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
|                                              |                                                                                                        |               | MSC  |             |                 |     | O/C              |             |                    |         |              |
| Airframe                                     |                                                                                                        |               |      |             |                 |     |                  |             |                    |         |              |
| 080009 <sup>U</sup>                          | Aircraft Weighing                                                                                      |               | HRS  |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                                              |                                                                                                        |               | AFL  |             | 315             |     |                  | 802         |                    |         | 0            |
|                                              |                                                                                                        |               | MOS  |             | 28.7            | -3  | 48               | 21 Dec 2023 | 18 Dec 2027*       |         |              |
|                                              |                                                                                                        |               |      |             |                 |     |                  |             |                    |         |              |
| Airframe                                     |                                                                                                        |               |      |             |                 |     |                  |             |                    |         |              |
| 10 - Parking, Mooring, Store and Ret to Serv |                                                                                                        |               |      |             |                 |     |                  |             |                    |         |              |
| 109995                                       | Available Code                                                                                         |               | HRS  |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                              |                                                                                                        |               | AFL  |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                              |                                                                                                        |               | MOS  |             |                 |     |                  |             |                    |         |              |
|                                              |                                                                                                        |               | MSC  |             |                 |     | O/C              |             |                    |         |              |
| Airframe                                     |                                                                                                        |               |      |             |                 |     |                  |             |                    |         |              |
| 109996                                       | Available Code                                                                                         |               | HRS  |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                              |                                                                                                        |               | AFL  |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                              |                                                                                                        |               | MOS  |             |                 |     |                  |             |                    |         |              |
|                                              |                                                                                                        |               | MSC  |             |                 |     | O/C              |             |                    |         |              |
| Airframe                                     |                                                                                                        |               |      |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom                                                                                                                                                               | Description      |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                                                                                                                                                               | Part Number      | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position                                                                                                                                                              | HW               | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                                                                                                                                                               | MM Ref           |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                                                                                                                                                                               | Ops Number(s)    |               |     |             |                 |     |                  |             |                    |         |              |
| 109997                                                                                                                                                                        | Available Code   |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                                                                                                                                                               |                  |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                                                                                                                                                               |                  |               | MOS |             |                 |     |                  |             |                    |         |              |
|                                                                                                                                                                               | Airframe         |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 109998                                                                                                                                                                        | Available Code   |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                                                                                                                                                               |                  |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                                                                                                                                                               |                  |               | MOS |             |                 |     |                  |             |                    |         |              |
|                                                                                                                                                                               | Airframe         |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 11 - Placards and Markings                                                                                                                                                    |                  |               |     |             |                 |     |                  |             |                    |         |              |
| 111000                                                                                                                                                                        | Exterior Paint 1 |               | HRS |             | 3037.4          |     |                  | 8.7         |                    |         | 0            |
|                                                                                                                                                                               |                  |               | AFL |             | 1113            |     |                  | 4           |                    |         | 0            |
|                                                                                                                                                                               |                  |               | MOS |             | 127.2           |     |                  | 05 Oct 2015 |                    |         |              |
|                                                                                                                                                                               | Airframe         |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Notes: PN: 765384 ES SN: SNOW WHITE. THE AIRCRAFT WAS REFINISHED IN ACCORDANCE WITH GULFSTREAM AEROSPACE CORPORATION DRAWING NO.: GDM904001174-501 REV. '--'<br>AXALTA DUPONT |                  |               |     |             |                 |     |                  |             |                    |         |              |
| 111001                                                                                                                                                                        | Exterior Paint 2 |               | HRS |             | 3037.4          |     |                  | 8.7         |                    |         | 0            |
|                                                                                                                                                                               |                  |               | AFL |             | 1113            |     |                  | 4           |                    |         | 0            |
|                                                                                                                                                                               |                  |               | MOS |             | 127.2           |     |                  | 05 Oct 2015 |                    |         |              |
|                                                                                                                                                                               | Airframe         |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Notes: PN: 814562 ES SN: TITANIUM. AXALTA DUPONT                                                                                                                              |                  |               |     |             |                 |     |                  |             |                    |         |              |
| 111002                                                                                                                                                                        | Exterior Paint 3 |               | HRS |             | 3037.4          |     |                  | 8.7         |                    |         | 0            |
|                                                                                                                                                                               |                  |               | AFL |             | 1113            |     |                  | 4           |                    |         | 0            |
|                                                                                                                                                                               |                  |               | MOS |             | 127.2           |     |                  | 05 Oct 2015 |                    |         |              |
|                                                                                                                                                                               | Airframe         |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Notes: PN: P2333 ES SN: GLOSS BLACK. AXALTA DUPONT                                                                                                                            |                  |               |     |             |                 |     |                  |             |                    |         |              |
| 111003                                                                                                                                                                        | Exterior Paint 4 |               | HRS |             | 3037.4          |     |                  | 8.7         |                    |         | 0            |
|                                                                                                                                                                               |                  |               | AFL |             | 1113            |     |                  | 4           |                    |         | 0            |
|                                                                                                                                                                               |                  |               | MOS |             | 127.2           |     |                  | 05 Oct 2015 |                    |         |              |
|                                                                                                                                                                               | Airframe         |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Notes: PN: P1174 ES SN: NORDIC GRAY. AXALTA DUPONT                                                                                                                            |                  |               |     |             |                 |     |                  |             |                    |         |              |
| 111004                                                                                                                                                                        | Exterior Paint 5 |               | HRS |             | 3037.4          |     |                  | 8.7         |                    |         | 0            |
|                                                                                                                                                                               |                  |               | AFL |             | 1113            |     |                  | 4           |                    |         | 0            |
|                                                                                                                                                                               |                  |               | MOS |             | 127.2           |     |                  | 05 Oct 2015 |                    |         |              |
|                                                                                                                                                                               | Airframe         |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Notes: PN: P1203 ES SN: SUNFAST RED. AXALTA DUPONT                                                                                                                            |                  |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom                                | Description                                     |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------------------------------------|-------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                                | Part Number                                     | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position                               | HW                                              | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                                | MM Ref                                          |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                                                | Ops Number(s)                                   |               |     |             |                 |     |                  |             |                    |         |              |
| 111005                                         | Exterior Paint 6                                |               | HRS |             | 3037.4          |     |                  | 8.7         |                    |         | 0            |
|                                                |                                                 |               | AFL |             | 1113            |     |                  | 4           |                    |         | 0            |
|                                                |                                                 |               | MOS |             | 127.2           |     |                  | 05 Oct 2015 |                    |         |              |
|                                                | Airframe                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Notes: PN: AF740 SN: CLEAR COAT . AXALTA DUPON |                                                 |               |     |             |                 |     |                  |             |                    |         |              |
| 111111                                         | Exterior Strip and Paint                        |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                                |                                                 |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                                |                                                 |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                                | Airframe                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 12 - Servicing                                 |                                                 |               |     |             |                 |     |                  |             |                    |         |              |
| 121100                                         | Specification and Grades of Fluid Replenishment |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                                | Materials                                       |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                                |                                                 |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                                | Airframe                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 121200                                         | Tank and Reservoir Capacities                   |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                                |                                                 |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                                |                                                 |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                                | Airframe                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 121300                                         | Refueling Procedures - Servicing                |               | HRS |             | 137             |     |                  | 2909.1      |                    |         | 0            |
|                                                |                                                 |               | AFL |             | 52              |     |                  | 1065        |                    |         | 0            |
|                                                |                                                 |               | MOS |             | 5               |     |                  | 12 Dec 2025 |                    |         |              |
|                                                | Airframe                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 121301                                         | Defueling Procedure - Servicing                 |               | HRS |             | 137             |     |                  | 2909.1      |                    |         | 0            |
|                                                |                                                 |               | AFL |             | 52              |     |                  | 1065        |                    |         | 0            |
|                                                |                                                 |               | MOS |             | 5.1             |     |                  | 07 Dec 2025 |                    |         |              |
|                                                | Airframe                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 121400                                         | Engine Oil Tank Replenishing - Servicing        |               | HRS |             | 919             |     |                  | 2127.1      |                    |         | 0            |
|                                                |                                                 |               | AFL |             | 371             |     |                  | 746         |                    |         | 0            |
|                                                |                                                 |               | MOS |             | 38              |     |                  | 10 Mar 2023 |                    |         |              |
|                                                | Airframe                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |

| ATA<br>U=Custom  | Description                                       |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|---------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                       | Serial Number |                                    |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                | SW            |                                    |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                            |               |                                    |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                     |               |                                    |             |                 |     |                  |             |                    |         |              |
| 121401           | Engine and APU Remote Oil Fill System - Servicing |               | HRS                                |             | 994.2           |     |                  | 2051.9      |                    |         | 0            |
|                  |                                                   |               | AFL                                |             | 392             |     |                  | 725         |                    | 0       |              |
|                  |                                                   |               | MOS                                |             | 40.9            |     |                  | 15 Dec 2022 |                    |         |              |
|                  |                                                   |               | MSC                                |             |                 | O/C |                  |             |                    |         |              |
| 121402           | Main Battery Servicing                            |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                   |               | AFL                                |             | 1117            |     |                  | 0           |                    | 0       |              |
|                  |                                                   |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                   |               | MSC                                |             |                 | O/C |                  |             |                    |         |              |
| 121403           | Idg (Left) - Oil System Filling                   |               | HRS                                |             | 137             |     |                  | 2909.1      |                    |         | 0            |
|                  |                                                   |               | AFL                                |             | 52              |     |                  | 1065        |                    | 0       |              |
|                  |                                                   |               | MOS                                |             | 5.3             |     |                  | 03 Dec 2025 |                    |         |              |
|                  |                                                   |               | MSC                                |             |                 | O/C |                  |             |                    |         |              |
| 121404           | Idg (Left) - Servicing                            |               | HRS                                |             | 994.2           |     |                  | 2051.9      |                    |         | 0            |
|                  |                                                   |               | AFL                                |             | 392             |     |                  | 725         |                    | 0       |              |
|                  |                                                   |               | MOS                                |             | 41.1            |     |                  | 08 Dec 2022 |                    |         |              |
|                  |                                                   |               | MSC                                |             |                 | O/C |                  |             |                    |         |              |
| 121406           | APU Oil - Servicing                               |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                   |               | AFL                                |             | 1117            |     |                  | 0           |                    | 0       |              |
|                  |                                                   |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                   |               | MSC                                |             |                 | O/C |                  |             |                    |         |              |
| 121407           | APU Manual Oil Level - Check                      |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                   |               | AFL                                |             | 1117            |     |                  | 0           |                    | 0       |              |
|                  |                                                   |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                   |               | MSC                                |             |                 | O/C |                  |             |                    |         |              |
| 121408           | No. 1 Engine - AIR Turbine Starter Oil - Discard  |               | HRS                                |             | 137             | 6.5 | 600              | 857.4       | 1463.9*            | 1513.9  | 0            |
|                  |                                                   |               | ENC                                |             | 52              |     |                  | 340         |                    | 0       |              |
|                  |                                                   |               | MOS                                |             | 5.3             |     |                  | 03 Dec 2025 |                    |         |              |
|                  |                                                   |               | [End Of Month Item] [HRS: +50/-50] |             |                 |     |                  |             |                    |         |              |
| Engine           | 052001                                            |               |                                    |             |                 |     |                  |             |                    |         |              |
| 121408           | No. 2 Engine - AIR Turbine Starter Oil - Discard  |               | HRS                                |             | 137             | 6.5 | 600              | 857.4       | 1463.9*            | 1513.9  | 0            |
|                  |                                                   |               | ENC                                |             | 52              |     |                  | 340         |                    | 0       |              |
|                  |                                                   |               | MOS                                |             | 5.3             |     |                  | 03 Dec 2025 |                    |         |              |
|                  |                                                   |               | [End Of Month Item] [HRS: +50/-50] |             |                 |     |                  |             |                    |         |              |
| Engine           | 052001                                            |               |                                    |             |                 |     |                  |             |                    |         |              |



| ATA<br>U=Custom        | Description                                                                      |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------------|----------------------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                        | Part Number                                                                      | Serial Number |                     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position       | HW                                                                               | SW            |                     |             |                 |     |                  |             |                    |         | Manufacturer |
|                        | MM Ref                                                                           |               |                     |             |                 |     |                  |             |                    |         | Date Type    |
|                        | Ops Number(s)                                                                    |               |                     |             |                 |     |                  |             |                    |         |              |
| 121409<br><br>Engine   | No. 1 Engine - AIR Turbine Starter - Servicing                                   |               | HRS                 |             | 137             |     |                  | 857.4       |                    |         | 0            |
|                        |                                                                                  |               | ENC                 |             | 52              |     |                  | 340         |                    |         | 0            |
|                        |                                                                                  |               | MOS                 |             | 5.3             |     |                  | 03 Dec 2025 |                    |         |              |
|                        |                                                                                  |               | MSC                 |             |                 |     | A/R              |             |                    |         |              |
|                        |                                                                                  |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 121409<br><br>Engine   | No. 2 Engine - AIR Turbine Starter - Servicing                                   |               | HRS                 |             | 137             |     |                  | 857.4       |                    |         | 0            |
|                        |                                                                                  |               | ENC                 |             | 52              |     |                  | 340         |                    |         | 0            |
|                        |                                                                                  |               | MOS                 |             | 5.3             |     |                  | 03 Dec 2025 |                    |         |              |
|                        |                                                                                  |               | MSC                 |             |                 |     | A/R              |             |                    |         |              |
|                        |                                                                                  |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 121411<br><br>Airframe | Idg (Right) - Servicing                                                          |               | HRS                 |             | 994.2           |     |                  | 2051.9      |                    |         | 0            |
|                        |                                                                                  |               | AFL                 |             | 392             |     |                  | 725         |                    |         | 0            |
|                        |                                                                                  |               | MOS                 |             | 41.1            |     |                  | 08 Dec 2022 |                    |         |              |
|                        |                                                                                  |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                        |                                                                                  |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 121500<br><br>Airframe | Servicing Reservoir With Onboard Hydraulic Fluid Replenisher (Left) - Servicing  |               | HRS                 |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                        |                                                                                  |               | AFL                 |             | 315             |     |                  | 802         |                    |         | 0            |
|                        |                                                                                  |               | MOS                 |             | 28.9            |     |                  | 14 Dec 2023 |                    |         |              |
|                        |                                                                                  |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                        |                                                                                  |               |                     |             |                 |     |                  |             |                    |         |              |
| 121501<br><br>Airframe | Servicing Reservoir With Onboard Hydraulic Fluid Replenisher (Right) - Servicing |               | HRS                 |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                        |                                                                                  |               | AFL                 |             | 1117            |     |                  | 0           |                    |         | 0            |
|                        |                                                                                  |               | MOS                 |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                        |                                                                                  |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                        |                                                                                  |               |                     |             |                 |     |                  |             |                    |         |              |
| 121502<br><br>Airframe | Servicing Onboard Hydraulic Fluid Replenisher Tank - Servicing                   |               | HRS                 |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                        |                                                                                  |               | AFL                 |             | 315             |     |                  | 802         |                    |         | 0            |
|                        |                                                                                  |               | MOS                 |             | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
|                        |                                                                                  |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                        |                                                                                  |               |                     |             |                 |     |                  |             |                    |         |              |
| 121505<br><br>Airframe | Main and Auxiliary Hydraulics Systems Test                                       |               | HRS                 |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                        |                                                                                  |               | AFL                 |             | 1117            |     |                  | 0           |                    |         | 0            |
|                        |                                                                                  |               | MOS                 |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                        |                                                                                  |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                        |                                                                                  |               |                     |             |                 |     |                  |             |                    |         |              |
| 121506<br><br>Airframe | Left Hydraulic System Bleed - Servicing                                          |               | HRS                 |             | 137             |     |                  | 2909.1      |                    |         | 0            |
|                        |                                                                                  |               | AFL                 |             | 52              |     |                  | 1065        |                    |         | 0            |
|                        |                                                                                  |               | MOS                 |             | 4.8             |     |                  | 18 Dec 2025 |                    |         |              |
|                        |                                                                                  |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                        |                                                                                  |               |                     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                      |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|--------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                      | Serial Number |     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                               | SW            |     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                           |               |     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                    |               |     |             |                 |     |                  |             |                     |         |              |
| 121507           | Right Hydraulic System Bleed - Servicing         |               | HRS |             | 730.5           |     |                  | 2315.6      |                     |         | 0            |
|                  |                                                  |               | AFL |             | 315             |     |                  | 802         |                     |         | 0            |
|                  |                                                  |               | MOS |             | 28.7            |     |                  | 21 Dec 2023 |                     |         |              |
|                  |                                                  |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| 121508           | Hydraulic System Reservoir (Left) - Servicing    |               | HRS |             | 137             |     |                  | 2909.1      |                     |         | 0            |
|                  |                                                  |               | AFL |             | 52              |     |                  | 1065        |                     |         | 0            |
|                  |                                                  |               | MOS |             | 4.8             |     |                  | 18 Dec 2025 |                     |         |              |
|                  |                                                  |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| 121509           | Hydraulic System Reservoir (Right) - Servicing   |               | HRS |             | 730.5           |     |                  | 2315.6      |                     |         | 0            |
|                  |                                                  |               | AFL |             |                 |     |                  |             |                     |         | 0            |
|                  |                                                  |               | MOS |             | 28.9            |     |                  | 15 Dec 2023 |                     |         |              |
|                  |                                                  |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| 121600           | Parking Brake Accumulator - Servicing            |               | HRS |             | 730.5           |     |                  | 2315.6      |                     |         | 0            |
|                  |                                                  |               | AFL |             | 315             |     |                  | 802         |                     |         | 0            |
|                  |                                                  |               | MOS |             | 28.7            |     |                  | 21 Dec 2023 |                     |         |              |
|                  |                                                  |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| 121601           | Hydraulic System Accumulator (Left) - Servicing  |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                  |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  |                                                  |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                  |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| 121602           | Hydraulic System Accumulator (Right) - Servicing |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                  |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  |                                                  |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                  |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| 121700           | Potable Water - Servicing                        |               | HRS |             | 137             |     |                  | 2909.1      |                     |         | 0            |
|                  |                                                  |               | AFL |             | 52              |     |                  | 1065        |                     |         | 0            |
|                  |                                                  |               | MOS |             | 5               |     |                  | 12 Dec 2025 |                     |         |              |
|                  |                                                  |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| 121701           | Potable Water System Line Drain - Servicing      |               | HRS |             | 137             |     |                  | 2909.1      |                     |         | 0            |
|                  |                                                  |               | AFL |             | 52              |     |                  | 1065        |                     |         | 0            |
|                  |                                                  |               | MOS |             | 4.8             |     |                  | 18 Dec 2025 |                     |         |              |
|                  |                                                  |               | MSC |             |                 |     | O/C              |             |                     |         |              |

| ATA<br>U=Custom  | Description                                                               |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W                             | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|---------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|--------------------------------------|--------------------|---------|--------------|
|                  | Part Number                                                               | Serial Number |                                    |             |                 |     |                  |                                      |                    |         | Approx Price |
| Logbook Position | HW                                                                        | SW            |                                    |             |                 |     |                  |                                      |                    |         | Manufacturer |
|                  | MM Ref                                                                    |               |                                    |             |                 |     |                  |                                      |                    |         | Date Type    |
|                  | Ops Number(s)                                                             |               |                                    |             |                 |     |                  |                                      |                    |         |              |
| 121702           | Potable Water System Purge - Servicing                                    |               | HRS                                |             | 137             |     |                  | 2909.1                               |                    |         | 0            |
|                  |                                                                           |               | AFL                                |             | 52              |     |                  | 1065                                 |                    | 0       |              |
|                  |                                                                           |               | MOS                                |             | 4.8             |     |                  | 18 Dec 2025                          |                    |         |              |
|                  |                                                                           |               | MSC                                |             |                 | O/C |                  |                                      |                    |         |              |
| 121703           | Waste Tank - Draining                                                     |               | HRS                                |             | 137             |     |                  | 2909.1                               |                    |         | 0            |
|                  |                                                                           |               | AFL                                |             | 52              |     |                  | 1065                                 |                    | 0       |              |
|                  |                                                                           |               | MOS                                |             | 4.8             |     |                  | 18 Dec 2025                          |                    |         |              |
|                  |                                                                           |               | MSC                                |             |                 | O/C |                  |                                      |                    |         |              |
| 121900           | Oxygen - Servicing                                                        |               | HRS                                |             | 730.5           |     |                  | 2315.6                               |                    |         | 0            |
|                  |                                                                           |               | AFL                                |             | 315             |     |                  | 802                                  |                    | 0       |              |
|                  |                                                                           |               | MOS                                |             | 30.1            |     |                  | 09 Nov 2023                          |                    |         |              |
|                  |                                                                           |               | MSC                                |             |                 | O/C |                  |                                      |                    |         |              |
| 122100           | Approved Fuel Additives                                                   |               | HRS                                |             | 3046.1          |     |                  | 0                                    |                    |         | 0            |
|                  |                                                                           |               | AFL                                |             | 1117            |     |                  | 0                                    |                    | 0       |              |
|                  |                                                                           |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015                          |                    |         |              |
|                  |                                                                           |               | MSC                                |             |                 | O/C |                  |                                      |                    |         |              |
| 122101           | Approved Oils - Servicing                                                 |               | HRS                                |             | 3046.1          |     |                  | 0                                    |                    |         | 0            |
|                  |                                                                           |               | AFL                                |             | 1117            |     |                  | 0                                    |                    | 0       |              |
|                  |                                                                           |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015                          |                    |         |              |
|                  |                                                                           |               | MSC                                |             |                 | O/C |                  |                                      |                    |         |              |
| 122200           | Landing Gear Emergency Extension Nitrogen Blow-Down<br>Bottle - Servicing |               | HRS                                |             | 730.5           |     |                  | 2315.6                               |                    |         | 0            |
|                  |                                                                           |               | AFL                                |             | 315             |     |                  | 802                                  |                    | 0       |              |
|                  |                                                                           |               | MOS                                |             | 28.9            |     |                  | 14 Dec 2023                          |                    |         |              |
|                  |                                                                           |               | MSC                                |             |                 | O/C |                  |                                      |                    |         |              |
| 122201           | Landing Gear Shock Struts and Actuating Cylinders -<br>Cleaning           |               | HRS                                |             | 3046.1          |     |                  | 0                                    |                    |         | 0            |
|                  |                                                                           |               | AFL                                |             | 1117            |     |                  | 0                                    |                    | 0       |              |
|                  |                                                                           |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015                          |                    |         |              |
|                  |                                                                           |               | MSC                                |             |                 | O/C |                  |                                      |                    |         |              |
| 122202           | Main Landing Gear - Lubrication                                           |               | HRS                                |             | -2              |     |                  | 3048.1                               |                    |         | 0            |
|                  |                                                                           |               | AFL                                |             | -2              |     |                  | 1119                                 |                    | 0       |              |
|                  |                                                                           |               | MOS                                |             | .2              | -16 | 4                | 06 May 2026 31 Aug 2026* 30 Sep 2026 |                    |         |              |
|                  |                                                                           |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |                                      |                    |         |              |
| Airframe         | 052024                                                                    |               |                                    |             |                 |     |                  |                                      |                    |         |              |

| ATA<br>U=Custom                        | Description                                         |               | UOM      | Times Since                                       | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|----------------------------------------|-----------------------------------------------------|---------------|----------|---------------------------------------------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                                        | Part Number                                         | Serial Number |          |                                                   |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position                       | HW                                                  | SW            |          |                                                   |                 |     |                  |             |                    |             | Manufacturer |
|                                        | MM Ref                                              |               |          |                                                   |                 |     |                  |             |                    |             | Date Type    |
|                                        | Ops Number(s)                                       |               |          |                                                   |                 |     |                  |             |                    |             |              |
| 122203                                 | Main Landing Gear Door Hinges - Lubrication         |               | HRS      |                                                   | 3037.4          |     |                  | 8.7         |                    |             | 0            |
|                                        |                                                     |               | AFL      |                                                   | 1113            |     | 4                |             | 0                  |             |              |
|                                        |                                                     |               | MOS      |                                                   | 127.5           |     | 26 Sep 2015      |             |                    |             |              |
|                                        |                                                     |               | MSC      |                                                   |                 | O/C |                  |             |                    |             |              |
| 122204                                 | Nose Landing Gear - Lubrication                     |               | HRS      |                                                   | -2              |     |                  | 3048.1      |                    |             | 0            |
|                                        |                                                     |               | AFL      |                                                   | -2              |     | 1119             |             | 0                  |             |              |
|                                        |                                                     |               | MOS      |                                                   | .2              | -16 | 4                | 06 May 2026 | 31 Aug 2026*       | 30 Sep 2026 |              |
|                                        |                                                     |               | Airframe | [End Of Month Item] [MOS: +1m/-1m]                |                 |     |                  |             |                    |             |              |
|                                        | 052024                                              |               |          |                                                   |                 |     |                  |             |                    |             |              |
| 122206                                 | Nose Tire Assembly - Servicing                      |               | HRS      |                                                   | 663.7           |     |                  | 2382.4      |                    |             | 0            |
|                                        |                                                     |               | AFL      |                                                   | 291             |     | 826              |             | 0                  |             |              |
|                                        |                                                     |               | MOS      |                                                   | 24.9            |     | 15 Apr 2024      |             |                    |             |              |
|                                        |                                                     |               | MSC      |                                                   |                 | O/C |                  |             |                    |             |              |
| 122207                                 | Main Tire Assembly - Servicing                      |               | HRS      |                                                   | 213             |     |                  | 2833.1      |                    |             | 0            |
|                                        |                                                     |               | AFL      |                                                   | 76              |     | 1041             |             | 0                  |             |              |
|                                        |                                                     |               | MOS      |                                                   | 7               |     | 10 Oct 2025      |             |                    |             |              |
|                                        |                                                     |               | MSC      |                                                   |                 | O/C |                  |             |                    |             |              |
| Notes: PN: 90005586-1 SN: JAN 15-0861. |                                                     |               |          |                                                   |                 |     |                  |             |                    |             |              |
| 122208                                 | Pressed In Grease Fittings - Installation           |               | HRS      |                                                   | 3046.1          |     |                  | 0           |                    |             | 0            |
|                                        |                                                     |               | AFL      |                                                   | 1117            |     | 0                |             | 0                  |             |              |
|                                        |                                                     |               | MOS      |                                                   | 128.6           |     | 24 Aug 2015      |             |                    |             |              |
|                                        |                                                     |               | MSC      |                                                   |                 | O/C |                  |             |                    |             |              |
| 122209                                 | Main Landing Gear Shock Absorber (Left) - Servicing |               | HRS      |                                                   | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                                        |                                                     |               | AFL      |                                                   | 315             |     | 802              |             | 0                  |             |              |
|                                        |                                                     |               | MOS      |                                                   | 28.7            |     | 48               | 21 Dec 2023 | 31 Dec 2027        | 31 Jan 2028 |              |
|                                        |                                                     |               | Airframe | [End Of Month Item] [MOS: +1m/-1m]                |                 |     |                  |             |                    |             |              |
|                                        | 052013                                              |               |          |                                                   |                 |     |                  |             |                    |             |              |
| 122210                                 | Nose Landing Gear Shock Absorber - Servicing        |               | HRS      |                                                   | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                                        |                                                     |               | AFL      |                                                   | 315             |     | 802              |             | 0                  |             |              |
|                                        |                                                     |               | MOS      |                                                   | 28.7            |     | 48               | 21 Dec 2023 | 31 Dec 2027        | 31 Jan 2028 |              |
|                                        |                                                     |               | Airframe | [End Of Month Item] [MOS: +1m/-1m]                |                 |     |                  |             |                    |             |              |
|                                        | 052013                                              |               |          |                                                   |                 |     |                  |             |                    |             |              |
| 122211                                 | Nose Wheel Steering Unit - Lubrication              |               | HRS      |                                                   | 137             |     | 600              | 2909.1      | 3509.1             | 3559.1      | 0            |
|                                        |                                                     |               | AFL      |                                                   | 52              |     | 1065             |             |                    | 0           |              |
|                                        |                                                     |               | MOS      |                                                   | 5.5             |     | 24               | 27 Nov 2025 | 30 Nov 2027        | 31 Dec 2027 |              |
|                                        |                                                     |               | Airframe | [End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50] |                 |     |                  |             |                    |             |              |
|                                        | 052001,052011                                       |               |          |                                                   |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom  | Description                                                    |               | UOM                                               | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------|----------------------------------------------------------------|---------------|---------------------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                  | Part Number                                                    | Serial Number |                                                   |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position | HW                                                             | SW            |                                                   |             |                 |     |                  |             |                    |             | Manufacturer |
|                  | MM Ref                                                         |               |                                                   |             |                 |     |                  |             |                    |             | Date Type    |
|                  | Ops Number(s)                                                  |               |                                                   |             |                 |     |                  |             |                    |             |              |
| 122212           | Nose Wheel Steering Collar Assembly / Slave Gear - Lubrication |               | HRS                                               |             | 137             |     | 600              | 2909.1      | 3509.1             |             | 0            |
|                  |                                                                |               | AFL                                               |             | 52              |     |                  | 1065        |                    |             | 0            |
|                  |                                                                |               | MOS                                               |             | 5.5             |     | 24               | 27 Nov 2025 | 30 Nov 2027        |             |              |
|                  |                                                                |               | [End Of Month Item] [MOS: -1m] [HRS: -50]         |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                | 052001,052011 |                                                   |             |                 |     |                  |             |                    |             |              |
| 122213           | Brake Bleeding Procedure                                       |               | HRS                                               |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                |               | AFL                                               |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                |               | MOS                                               |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                |               | MSC                                               |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                |               |                                                   |             |                 |     |                  |             |                    |             |              |
| 122315           | Horizontal Stabilizer Actuator - Lubrication                   |               | HRS                                               |             | 137             |     | 1200             | 2909.1      | 4109.1             | 4159.1      | 0            |
|                  |                                                                |               | AFL                                               |             | 52              |     |                  | 1065        |                    |             | 0            |
|                  |                                                                |               | MOS                                               |             | 5.3             | 18  | 24               | 03 Dec 2025 | 31 Dec 2027*       | 31 Jan 2028 |              |
|                  |                                                                |               | [End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                |               |                                                   |             |                 |     |                  |             |                    |             |              |
| 122323           | Aileron Actuator Toggle Links (Left) - Lubrication             |               | HRS                                               |             | 137             |     | 1200             | 2909.1      | 4109.1             | 4159.1      | 0            |
|                  |                                                                |               | AFL                                               |             | 52              |     |                  | 1065        |                    |             | 0            |
|                  |                                                                |               | MOS                                               |             | 5.3             | 20  | 24               | 01 Dec 2025 | 31 Dec 2027*       | 31 Jan 2028 |              |
|                  |                                                                |               | [End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                |               |                                                   |             |                 |     |                  |             |                    |             |              |
| 122324           | Aileron Actuator Toggle Links (Right) - Lubrication            |               | HRS                                               |             | 137             |     | 1200             | 2909.1      | 4109.1             | 4159.1      | 0            |
|                  |                                                                |               | AFL                                               |             | 52              |     |                  | 1065        |                    |             | 0            |
|                  |                                                                |               | MOS                                               |             | 5.3             | 20  | 24               | 01 Dec 2025 | 31 Dec 2027*       | 31 Jan 2028 |              |
|                  |                                                                |               | [End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                |               |                                                   |             |                 |     |                  |             |                    |             |              |
| 122325           | Rudder Actuator Toggle Links - Lubrication                     |               | HRS                                               |             | 137             |     | 1200             | 2909.1      | 4109.1             | 4159.1      | 0            |
|                  |                                                                |               | AFL                                               |             | 52              |     |                  | 1065        |                    |             | 0            |
|                  |                                                                |               | MOS                                               |             | 5.3             | 20  | 24               | 01 Dec 2025 | 31 Dec 2027*       | 31 Jan 2028 |              |
|                  |                                                                |               | [End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                |               |                                                   |             |                 |     |                  |             |                    |             |              |
| 122326           | Elevator Actuator Toggle Links (Left) - Lubrication            |               | HRS                                               |             | 137             |     | 1200             | 2909.1      | 4109.1             | 4159.1      | 0            |
|                  |                                                                |               | AFL                                               |             | 52              |     |                  | 1065        |                    |             | 0            |
|                  |                                                                |               | MOS                                               |             | 5.3             | 20  | 24               | 01 Dec 2025 | 31 Dec 2027*       | 31 Jan 2028 |              |
|                  |                                                                |               | [End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                |               |                                                   |             |                 |     |                  |             |                    |             |              |
| 122327           | Elevator Actuator Toggle Links (Right) - Lubrication           |               | HRS                                               |             | 137             |     | 1200             | 2909.1      | 4109.1             | 4159.1      | 0            |
|                  |                                                                |               | AFL                                               |             | 52              |     |                  | 1065        |                    |             | 0            |
|                  |                                                                |               | MOS                                               |             | 5.3             | 20  | 24               | 01 Dec 2025 | 31 Dec 2027*       | 31 Jan 2028 |              |
|                  |                                                                |               | [End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                |               |                                                   |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom  | Description                                                 |                                                   | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------|-------------------------------------------------------------|---------------------------------------------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                  | Part Number                                                 | Serial Number                                     |     |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position | HW                                                          | SW                                                |     |             |                 |     |                  |             |                    |             | Manufacturer |
|                  | MM Ref                                                      |                                                   |     |             |                 |     |                  |             |                    |             | Date Type    |
|                  | Ops Number(s)                                               |                                                   |     |             |                 |     |                  |             |                    |             |              |
| 122328           | Flap Actuator Ball Nut (Left) - Lubrication                 |                                                   | HRS |             | 137             |     | 1200             | 2909.1      | 4109.1             |             | 0            |
|                  |                                                             |                                                   | AFL |             | 52              |     |                  | 1065        |                    |             | 0            |
|                  |                                                             |                                                   | MOS |             | 5.3             | 56  | 24               | 01 Dec 2025 | 31 Jan 2028*       |             |              |
|                  | Airframe                                                    | [End Of Month Item] [MOS: -1m] [HRS: -50]         |     |             |                 |     |                  |             |                    |             |              |
| 122329           | Flap Actuator Ball Nut (Right) - Lubrication                |                                                   | HRS |             | 137             |     | 1200             | 2909.1      | 4109.1             | 4159.1      | 0            |
|                  |                                                             |                                                   | AFL |             | 52              |     |                  | 1065        |                    |             | 0            |
|                  |                                                             |                                                   | MOS |             | 5.3             | 56  | 24               | 01 Dec 2025 | 31 Jan 2028*       | 29 Feb 2028 |              |
|                  | Airframe                                                    | [End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50] |     |             |                 |     |                  |             |                    |             |              |
| 122330           | Outboard Spoiler Actuator Toggle Link (Left) - Lubrication  |                                                   | HRS |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                  |                                                             |                                                   | AFL |             | 52              |     |                  | 1065        |                    |             | 0            |
|                  |                                                             |                                                   | MOS |             | 5.3             | 56  | 24               | 01 Dec 2025 | 31 Jan 2028*       | 29 Feb 2028 |              |
|                  | Airframe                                                    | [End Of Month Item] [MOS: +1m/-1m]                |     |             |                 |     |                  |             |                    |             |              |
|                  | 052011                                                      |                                                   |     |             |                 |     |                  |             |                    |             |              |
| 122331           | Outboard Spoiler Actuator Toggle Link (Right) - Lubrication |                                                   | HRS |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                  |                                                             |                                                   | AFL |             | 52              |     |                  | 1065        |                    |             | 0            |
|                  |                                                             |                                                   | MOS |             | 5.3             | 56  | 24               | 01 Dec 2025 | 31 Jan 2028*       | 29 Feb 2028 |              |
|                  | Airframe                                                    | [End Of Month Item] [MOS: +1m/-1m]                |     |             |                 |     |                  |             |                    |             |              |
|                  | 052011                                                      |                                                   |     |             |                 |     |                  |             |                    |             |              |
| 122332           | Horizontal Actuator Oil - Discard                           |                                                   | HRS |             | 3046.1          |     | 6000             | 0           | 6000               | 6050        | 0            |
|                  |                                                             |                                                   | AFL |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                             |                                                   | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  | Airframe                                                    | [HRS: +50/-50]                                    |     |             |                 |     |                  |             |                    |             |              |
|                  | 052007                                                      |                                                   |     |             |                 |     |                  |             |                    |             |              |
| 122333           | Aileron Hinge Fitting (Left) - Lubrication                  |                                                   | HRS |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                  |                                                             |                                                   | AFL |             | 52              |     |                  | 1065        |                    |             | 0            |
|                  |                                                             |                                                   | MOS |             | 5.3             | 51  | 24               | 01 Dec 2025 | 31 Jan 2028*       | 29 Feb 2028 |              |
|                  | Airframe                                                    | [End Of Month Item] [MOS: +1m/-1m]                |     |             |                 |     |                  |             |                    |             |              |
|                  | 052011                                                      |                                                   |     |             |                 |     |                  |             |                    |             |              |
| 122334           | Aileron Hinge Fitting (Right) - Lubrication                 |                                                   | HRS |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                  |                                                             |                                                   | AFL |             | 52              |     |                  | 1065        |                    |             | 0            |
|                  |                                                             |                                                   | MOS |             | 5.3             | 51  | 24               | 01 Dec 2025 | 31 Jan 2028*       | 29 Feb 2028 |              |
|                  | Airframe                                                    | [End Of Month Item] [MOS: +1m/-1m]                |     |             |                 |     |                  |             |                    |             |              |
|                  | 052011                                                      |                                                   |     |             |                 |     |                  |             |                    |             |              |
| 122335           | Rudder Hinge Fitting - Lubrication                          |                                                   | HRS |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                  |                                                             |                                                   | AFL |             | 52              |     |                  | 1065        |                    |             | 0            |
|                  |                                                             |                                                   | MOS |             | 5.3             | 52  | 24               | 01 Dec 2025 | 31 Jan 2028*       | 29 Feb 2028 |              |
|                  | Airframe                                                    | [End Of Month Item] [MOS: +1m/-1m]                |     |             |                 |     |                  |             |                    |             |              |
|                  | 052011                                                      |                                                   |     |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom                    | Description                                  |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(* =Adj) | Max Due     | Avg Man Hrs  |
|------------------------------------|----------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|----------------------|-------------|--------------|
|                                    | Part Number                                  | Serial Number |                                    |             |                 |     |                  |             |                      |             | Approx Price |
| Logbook Position                   | HW                                           | SW            |                                    |             |                 |     |                  |             |                      |             | Manufacturer |
|                                    | MM Ref                                       |               |                                    |             |                 |     |                  |             |                      |             | Date Type    |
|                                    | Ops Number(s)                                |               |                                    |             |                 |     |                  |             |                      |             |              |
| 122336                             | Elevator Hinge Fitting (Left) - Lubrication  |               | HRS                                |             | 137             |     |                  | 2909.1      |                      |             | 0            |
|                                    |                                              |               | AFL                                |             | 52              |     |                  | 1065        |                      |             | 0            |
|                                    |                                              |               | MOS                                |             | 5.3             | 52  | 24               | 01 Dec 2025 | 31 Jan 2028*         | 29 Feb 2028 |              |
|                                    | Airframe                                     |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                      |             |              |
|                                    |                                              | 052011        |                                    |             |                 |     |                  |             |                      |             |              |
| 122337                             | Elevator Hinge Fitting (Right) - Lubrication |               | HRS                                |             | 137             |     |                  | 2909.1      |                      |             | 0            |
|                                    |                                              |               | AFL                                |             | 52              |     |                  | 1065        |                      |             | 0            |
|                                    |                                              |               | MOS                                |             | 5.3             | 52  | 24               | 01 Dec 2025 | 31 Jan 2028*         | 29 Feb 2028 |              |
|                                    | Airframe                                     |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                      |             |              |
|                                    |                                              | 052011        |                                    |             |                 |     |                  |             |                      |             |              |
| 122500                             | External Baggage Door - Lubrication          |               | HRS                                |             | 137             |     |                  | 2909.1      |                      |             | 0            |
|                                    |                                              |               | AFL                                |             | 52              |     |                  | 1065        |                      |             | 0            |
|                                    |                                              |               | MOS                                |             | 5.2             | -5  | 12               | 04 Dec 2025 | 30 Nov 2026*         | 31 Dec 2026 |              |
|                                    | Airframe                                     |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                      |             |              |
|                                    |                                              | 052010        |                                    |             |                 |     |                  |             |                      |             |              |
| 122501                             | Main Entrance Door - Lubrication             |               | HRS                                |             | 137             |     |                  | 2909.1      |                      |             | 0            |
|                                    |                                              |               | AFL                                |             | 52              |     |                  | 1065        |                      |             | 0            |
|                                    |                                              |               | MOS                                |             | 5.2             | -6  | 12               | 05 Dec 2025 | 30 Nov 2026*         | 31 Dec 2026 |              |
|                                    | Airframe                                     |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                      |             |              |
|                                    |                                              | 052010        |                                    |             |                 |     |                  |             |                      |             |              |
| 122600                             | Ram AIR Turbine - Lubrication                |               | HRS                                |             | 137             |     |                  | 2909.1      |                      |             | 0            |
|                                    |                                              |               | AFL                                |             | 52              |     |                  | 1065        |                      |             | 0            |
|                                    |                                              |               | MOS                                |             | 5.2             | 54  | 24               | 05 Dec 2025 | 31 Jan 2028*         | 29 Feb 2028 |              |
|                                    | Airframe                                     |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                      |             |              |
|                                    |                                              | 052011        |                                    |             |                 |     |                  |             |                      |             |              |
| 20 - Standard Practices - Airframe |                                              |               |                                    |             |                 |     |                  |             |                      |             |              |
| 200093                             | Post Maintenance - Servicing                 |               | HRS                                |             | 3046.1          |     |                  | 0           |                      |             | 0            |
|                                    |                                              |               | AFL                                |             | 1117            |     |                  | 0           |                      |             | 0            |
|                                    |                                              |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                      |             |              |
|                                    | Airframe                                     |               | MSC                                | O/C         |                 |     |                  |             |                      |             |              |
| 21 - AIR Conditioning              |                                              |               |                                    |             |                 |     |                  |             |                      |             |              |
| 210001                             | AIR Conditioning System - Functional Check   |               | HRS                                |             | 137             |     |                  | 2909.1      |                      |             | 0            |
|                                    |                                              |               | AFL                                |             | 52              |     |                  | 1065        |                      |             | 0            |
|                                    |                                              |               | MOS                                |             | 4.7             |     |                  | 19 Dec 2025 |                      |             |              |
|                                    | Airframe                                     |               | MSC                                | O/C         |                 |     |                  |             |                      |             |              |

| ATA<br>U=Custom  | Description                                         |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-----------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                         | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                  | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                              |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                       |               |     |             |                 |     |                  |             |                    |         |              |
| 212101           | Cabin Silencer (Forward) - Removal / Installation   |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P2121006Z005                                      | 0176          | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                     |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                            |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 212102           | Cabin Silencer (Left Aft) - Removal / Installation  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P2121006Z006                                      | 0336          | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                     |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                            |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 212103           | Cabin Silencer (Right Aft) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P2121006Z006                                      | 0342          | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                     |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                            |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 212104           | Cockpit Silencer - Removal / Installation           |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P2121002Z004                                      | 0164          | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                     |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                            |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 212121           | Pack Inlet Valve (Left) - Removal / Installation    |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 396610-6                                            | 2717          | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                     |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                            |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 212122           | Pack Inlet Valve (Right) - Removal / Installation   |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 396610-6                                            | 2716          | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                     |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                            |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 212125           | Ozone Converter (Left) - Removal / Installation     |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 1159SCAC501-1                                       | 8167          | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                     |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                            |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 212126           | Ozone Converter (Right) - Removal / Installation    |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 1159SCAC501-1                                       | 8227          | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                     |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                            |               | MSC |             |                 |     | O/C              |             |                    |         |              |



| ATA<br>U=Custom  | Description                                                       |                 | UOM            | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-------------------------------------------------------------------|-----------------|----------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                       | Serial Number   |                |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                | SW              |                |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                            |                 |                |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                     |                 |                |             |                 |     |                  |             |                    |         |              |
| 212129           | Ozone Converter (Left) (Return to Vendor) - Restore               |                 | HRS            |             | 3046.1          |     | 10000            | 0           | 10000              | 10050   | 0            |
|                  |                                                                   |                 | AFL            |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                   |                 | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                          |                 | [HRS: +50/-50] |             |                 |     |                  |             |                    |         |              |
| 212130           | Ozone Converter (Right) (Return to Vendor) - Restore              |                 | HRS            |             | 3046.1          |     | 10000            | 0           | 10000              | 10050   | 0            |
|                  |                                                                   |                 | AFL            |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                   |                 | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                          |                 | [HRS: +50/-50] |             |                 |     |                  |             |                    |         |              |
| 212200           | Ram AIR Check Valve - Removal / Installation                      |                 | HRS            |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 3202776-1                                                         | 2489            | AFL            |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                   |                 | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                          |                 | MSC            |             |                 |     | O/C              |             |                    |         |              |
| 212202           | Ram AIR Check Valve - Detailed Inspection                         |                 | HRS            |             | 3046.1          |     | 6000             | 0           | 6000               | 6050    | 0            |
|                  |                                                                   |                 | AFL            |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                   |                 | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                          |                 | [HRS: +50/-50] |             |                 |     |                  |             |                    |         |              |
| 212207           | Ram AIR Plenum Assembly Left AIR Pack - Removal / Installation    |                 | HRS            |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                   |                 | AFL            |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 1159ACP50002-31                                                   | P000080047-0000 | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                          |                 | MSC            |             |                 |     | O/C              |             |                    |         |              |
| 212208           | Ram AIR Plenum Assembly Right AIR Pack - Removal / Installation   |                 | HRS            |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                   |                 | AFL            |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 1159ACP50002-33                                                   | P000080601-0000 | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                          |                 | MSC            |             |                 |     | O/C              |             |                    |         |              |
| 212500           | Avionics Cooling Check Valve, Return AIR - Removal / Installation |                 | HRS            |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                   |                 | AFL            |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 3202776-1                                                         | 2487            | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                          |                 | MSC            |             |                 |     | O/C              |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                              |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|--------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                              | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                       | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                   |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                            |               |     |             |                 |     |                  |             |                    |         |              |
| 212501           | Avionics Cooling Turret Duct, Return AIR - Removal / Installation        |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                          |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 729611008                                                                | SN-UNKNOWN    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                          |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| 212505           | Personal Service Unit Cooling Fan - Removal / Installation               |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 011990500                                                                | C15200121     | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                          |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                          |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| 212508           | Aft Equipment Cooling Fan (Forward Baggage Eer) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                          |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 011586501                                                                | I15160389     | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                          |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| 212509           | Aft Equipment Cooling Fan (Aft Baggage Eer) - Removal / Installation     |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                          |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 011586501                                                                | I15160396     | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                          |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| 212512           | Aft Equipment Cooling Fan (Forward Baggage Eer) - Operational Test       |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                          |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                          |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                          |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| 212513           | Aft Equipment Cooling Fan (Aft Baggage Eer) - Operational Test           |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                          |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                          |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                          |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| 212515           | Leer Cooling Fan - Removal / Installation                                |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 011989500                                                                | C15030005     | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                          |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                          |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                          |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                              |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                              | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                                       | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                                   |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                                            |               |     |             |                 |     |                  |             |                    |         |              |
| 212516           | Reer Cooling Fan - Removal / Installation                                                |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 011587503                                                                                | C15150094     | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                          |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 212517           | Aft Equipment Cooling Fan (Baggage Compartment Bulkhead, Upper) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 011586501                                                                                | I15261195     | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                          |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 212518           | Aft Equipment Cooling Fan (Baggage Compartment Bulkhead, Lower) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 011586501                                                                                | I15261197     | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                          |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 212523           | Leer Cooling Fan - Operational Test                                                      |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                          |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                          |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 212524           | Reer Cooling Fan - Operational Test                                                      |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                          |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                          |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 212525           | Aft Equipment Cooling Fan (Baggage Compartment Bulkhead, Upper) - Operational Test       |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                          |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                          |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 212526           | Aft Equipment Cooling Fan (Baggage Compartment Bulkhead, Lower) - Operational Test       |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  |                                                                                          |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  |                                                                                          |               | MOS |             | 124.7           |     |                  | 19 Dec 2015 |                    |         |              |
|                  | Airframe                                                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                                                         |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|---------------------------------------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                                                         | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                                                                  | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                                                              |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| 212527           | Leer Cooling Fan - Inspection                                                                                       |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                                     |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                                     |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                                                                            |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 212528           | Reer Cooling Fan - Inspection                                                                                       |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                                     |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                                     |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                                                                            |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 212529           | Equipment Cooling Fan (Aft Upper) - Inspection                                                                      |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                                     |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                                     |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                                                                            |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 212530           | Equipment Cooling Fan (Aft Lower) - Inspection                                                                      |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                                     |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                                     |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                                                                            |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 212543           | Aft Equipment Cooling Fan Low-Speed Warning Detector (Baggage Compartment Bulkhead, Upper) - Removal / Installation |               | HRS | TSN:3.8     | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                                     |               | AFL | TSN:3       | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                                     |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | 035640501 E14400241                                                                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| 212544           | Aft Equipment Cooling Fan Low-Speed Warning Detector (Baggage Compartment Bulkhead, Lower) - Removal / Installation |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  |                                                                                                                     |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  |                                                                                                                     |               | MOS |             | 125.4           |     |                  | 29 Nov 2015 |                    |         |              |
|                  | 035640501 E15372408                                                                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| 212545           | Aft Equipment Cooling Fan Low-Speed Warning Detector (Forward Baggage Eer) - Removal / Installation                 |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                                     |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 035640501 E15140990                                                                                                 |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                                                     |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                                                     |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom                  | Description                                          |               | UOM            | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(* =Adj) | Max Due | Avg Man Hrs  |
|----------------------------------|------------------------------------------------------|---------------|----------------|-------------|-----------------|-----|------------------|-------------|----------------------|---------|--------------|
|                                  | Part Number                                          | Serial Number |                |             |                 |     |                  |             |                      |         | Approx Price |
| Logbook Position                 | HW                                                   | SW            |                |             |                 |     |                  |             |                      |         | Manufacturer |
|                                  | MM Ref                                               |               |                |             |                 |     |                  |             |                      |         | Date Type    |
|                                  | Ops Number(s)                                        |               |                |             |                 |     |                  |             |                      |         |              |
| 212546                           | Aft Equipment Cooling Fan Low-Speed Warning Detector |               | HRS            |             | 3046.1          |     |                  | 0           |                      |         | 0            |
|                                  | (Aft Baggage Eer) - Removal / Installation           |               | AFL            |             | 1117            |     |                  | 0           |                      |         | 0            |
|                                  | 035640501                                            | E15140989     | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                      |         |              |
|                                  |                                                      |               | MSC            |             |                 |     | O/C              |             |                      |         |              |
| Airframe                         |                                                      |               |                |             |                 |     |                  |             |                      |         |              |
| 213100                           | Cabin Pressure Controller - Removal / Installation   |               | HRS            |             | 3046.1          |     |                  | 0           |                      |         | 0            |
|                                  | 2119314-2                                            | 2119314-00168 | AFL            |             | 1117            |     |                  | 0           |                      |         | 0            |
|                                  |                                                      |               | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                      |         |              |
|                                  |                                                      |               | MSC            |             |                 |     | O/C              |             |                      |         |              |
| Airframe                         |                                                      |               |                |             |                 |     |                  |             |                      |         |              |
| 213102                           | Cabin Pressurization Controller - System Check       |               | HRS            |             | 3046.1          |     |                  | 0           |                      |         | 0            |
|                                  |                                                      |               | AFL            |             | 1117            |     |                  | 0           |                      |         | 0            |
|                                  |                                                      |               | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                      |         |              |
|                                  |                                                      |               | MSC            |             |                 |     | O/C              |             |                      |         |              |
| Airframe                         |                                                      |               |                |             |                 |     |                  |             |                      |         |              |
| Notes: PN: 2119314 SN: <NONE>.   |                                                      |               |                |             |                 |     |                  |             |                      |         |              |
| 213103                           | Cabin Pressurization Control - System Check          |               | HRS            |             | 1148.4          |     | 6000             | 1897.7      | 7897.7               | 7947.7  | 0            |
|                                  |                                                      |               | AFL            |             | 481             |     |                  | 636         |                      |         | 0            |
|                                  |                                                      |               | MOS            |             | 46.8            |     |                  | 17 Jun 2022 |                      |         |              |
|                                  |                                                      |               | [HRS: +50/-50] |             |                 |     |                  |             |                      |         |              |
| Airframe                         |                                                      |               |                |             |                 |     |                  |             |                      |         |              |
| Notes: PN: 2119314-2 SN: <NONE>. |                                                      |               |                |             |                 |     |                  |             |                      |         |              |
| 213107                           | Outflow Valve - Removal / Installation               |               | HRS            |             | 3046.1          |     |                  | 0           |                      |         | 0            |
|                                  | 103878-1                                             | 35-A1090      | AFL            |             | 1117            |     |                  | 0           |                      |         | 0            |
|                                  |                                                      |               | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                      |         |              |
|                                  |                                                      |               | MSC            |             |                 |     | O/C              |             |                      |         |              |
| Airframe                         |                                                      |               |                |             |                 |     |                  |             |                      |         |              |
| 213109                           | Outflow Valve - Cleaning / Painting                  |               | HRS            |             | 3046.1          |     |                  | 0           |                      |         | 0            |
|                                  |                                                      |               | AFL            |             | 1117            |     |                  | 0           |                      |         | 0            |
|                                  |                                                      |               | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                      |         |              |
|                                  |                                                      |               | MSC            |             |                 |     | O/C              |             |                      |         |              |
| Airframe                         |                                                      |               |                |             |                 |     |                  |             |                      |         |              |
| 213114                           | Cabin Pressure Control Static Inverter - Operational |               | HRS            |             | 3046.1          |     |                  | 0           |                      |         | 0            |
|                                  | Check                                                |               | AFL            |             | 1117            |     |                  | 0           |                      |         | 0            |
|                                  |                                                      |               | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                      |         |              |
|                                  |                                                      |               | MSC            |             |                 |     | O/C              |             |                      |         |              |
| Airframe                         |                                                      |               |                |             |                 |     |                  |             |                      |         |              |

| ATA<br>U=Custom                 | Description                                                     |               | UOM            | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|---------------------------------|-----------------------------------------------------------------|---------------|----------------|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                                 | Part Number                                                     | Serial Number |                |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position                | HW                                                              | SW            |                |             |                 |     |                  |             |                     |         | Manufacturer |
|                                 | MM Ref                                                          |               |                |             |                 |     |                  |             |                     |         | Date Type    |
|                                 | Ops Number(s)                                                   |               |                |             |                 |     |                  |             |                     |         |              |
| 213115                          | Cabin Pressure Control Static Inverter - Removal / Installation |               | HRS            |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                                 |                                                                 |               | AFL            |             | 1117            |     |                  | 0           |                     |         | 0            |
|                                 | 717320-2                                                        | 0121          | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                                 |                                                                 |               | MSC            |             |                 |     | O/C              |             |                     |         |              |
| Airframe                        |                                                                 |               |                |             |                 |     |                  |             |                     |         |              |
| 213117                          | Cabin Pressurization Control Panel - Removal / Installation     |               | HRS            |             | 1148.4          |     |                  | 1897.7      |                     |         | 0            |
|                                 |                                                                 |               | AFL            |             | 481             |     |                  | 636         |                     |         | 0            |
|                                 | 2119144-1                                                       | 15-A1136      | MOS            |             | 46.8            |     |                  | 17 Jun 2022 |                     |         |              |
|                                 |                                                                 |               | MSC            |             |                 |     | O/C              |             |                     |         |              |
| Airframe                        |                                                                 |               |                |             |                 |     |                  |             |                     |         |              |
| 213301                          | Pressure Relief Valve - Removal / Installation                  |               | HRS            |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                                 | 103928-1 103928-00165                                           |               | AFL            |             | 1117            |     |                  | 0           |                     |         | 0            |
|                                 |                                                                 |               | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                                 |                                                                 |               | MSC            |             |                 |     | O/C              |             |                     |         |              |
| Airframe                        |                                                                 |               |                |             |                 |     |                  |             |                     |         |              |
| 213302                          | Remote AIR Filter - Removal / Installation                      |               | HRS            |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                                 | 147240-1 SN-UNKNOWN                                             |               | AFL            |             | 1117            |     |                  | 0           |                     |         | 0            |
|                                 |                                                                 |               | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                                 |                                                                 |               | MSC            |             |                 |     | O/C              |             |                     |         |              |
| Airframe                        |                                                                 |               |                |             |                 |     |                  |             |                     |         |              |
| 213304                          | Pressure Relief Valve Remote AIR Filter - Detailed Inspection   |               | HRS            |             | 137             |     | 3000             | 2909.1      | 5909.1              | 5959.1  | 0            |
|                                 |                                                                 |               | AFL            |             | 52              |     |                  | 1065        |                     |         | 0            |
|                                 |                                                                 |               | MOS            |             | 5.5             |     |                  | 27 Nov 2025 |                     |         |              |
|                                 |                                                                 |               | [HRS: +50/-50] |             |                 |     |                  |             |                     |         |              |
| Airframe                        |                                                                 |               |                |             |                 |     |                  |             |                     |         |              |
| 052005                          |                                                                 |               |                |             |                 |     |                  |             |                     |         |              |
| Notes: PN: 147240-1 SN: <NONE>. |                                                                 |               |                |             |                 |     |                  |             |                     |         |              |
| 213305                          | Pressure Relief Valve - Inspection / Check                      |               | HRS            |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                                 |                                                                 |               | AFL            |             | 1117            |     |                  | 0           |                     |         | 0            |
|                                 |                                                                 |               | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                                 |                                                                 |               | MSC            |             |                 |     | O/C              |             |                     |         |              |
| Airframe                        |                                                                 |               |                |             |                 |     |                  |             |                     |         |              |
| 213306                          | Pressure Relief Valve - Functional Check                        |               | HRS            |             | 137             |     | 3000             | 2909.1      | 5909.1              |         | 0            |
|                                 |                                                                 |               | AFL            |             | 52              |     |                  | 1065        |                     |         | 0            |
|                                 |                                                                 |               | MOS            |             | 4.8             |     |                  | 18 Dec 2025 |                     |         |              |
|                                 |                                                                 |               | [HRS: -50]     |             |                 |     |                  |             |                     |         |              |
| Airframe                        |                                                                 |               |                |             |                 |     |                  |             |                     |         |              |
| 052005                          |                                                                 |               |                |             |                 |     |                  |             |                     |         |              |
| Notes: PN: 147240-1 SN: <NONE>. |                                                                 |               |                |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom                   | Description                                                              |               | UOM            | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|-----------------------------------|--------------------------------------------------------------------------|---------------|----------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                   | Part Number                                                              | Serial Number |                |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position                  | HW                                                                       | SW            |                |             |                 |     |                  |             |                    |         | Manufacturer |
|                                   | MM Ref                                                                   |               |                |             |                 |     |                  |             |                    |         | Date Type    |
|                                   | Ops Number(s)                                                            |               |                |             |                 |     |                  |             |                    |         |              |
| 213307                            | Baggage Compartment Shut-Off Valve - Removal / Installation              |               | HRS            |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                   |                                                                          |               | AFL            |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                   | FYLB-52635                                                               | 889           | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                   |                                                                          |               | MSC            |             |                 |     | O/C              |             |                    |         |              |
| Airframe                          |                                                                          |               |                |             |                 |     |                  |             |                    |         |              |
| 213308                            | Baggage Compartment Shut-Off Valve Reset Switch - Removal / Installation |               | HRS            |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                   |                                                                          |               | AFL            |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                   | MS24523-30                                                               | SN-UNKNOWN    | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                   |                                                                          |               | MSC            |             |                 |     | O/C              |             |                    |         |              |
| Airframe                          |                                                                          |               |                |             |                 |     |                  |             |                    |         |              |
| 213311                            | Baggage Compartment Shut-Off Valve and Reset Switch - Operational Check  |               | HRS            |             | 137             |     | 3000             | 2909.1      | 5909.1             | 5959.1  | 0            |
|                                   |                                                                          |               | AFL            |             | 52              |     |                  | 1065        |                    |         | 0            |
|                                   |                                                                          |               | MOS            |             | 4.7             |     |                  | 19 Dec 2025 |                    |         |              |
|                                   |                                                                          |               | [HRS: +50/-50] |             |                 |     |                  |             |                    |         |              |
| Airframe                          |                                                                          |               |                |             |                 |     |                  |             |                    |         |              |
| 052005                            |                                                                          |               |                |             |                 |     |                  |             |                    |         |              |
| Notes: PN: MS24523-30 SN: <NONE>. |                                                                          |               |                |             |                 |     |                  |             |                    |         |              |
| 213312                            | Baggage Compartment Ventilation Check Valve - Removal / Installation     |               | HRS            |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                   |                                                                          |               | AFL            |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                   | PN                                                                       | SN-UNKNOWN    | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                   |                                                                          |               | MSC            |             |                 |     | O/C              |             |                    |         |              |
| Airframe                          |                                                                          |               |                |             |                 |     |                  |             |                    |         |              |
| 213314                            | Baggage Compartment Ventilation Check Valve - Detailed Inspection        |               | HRS            |             | 3046.1          |     | 6000             | 0           | 6000               | 6050    | 0            |
|                                   |                                                                          |               | AFL            |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                   |                                                                          |               | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                   |                                                                          |               | [HRS: +50/-50] |             |                 |     |                  |             |                    |         |              |
| Airframe                          |                                                                          |               |                |             |                 |     |                  |             |                    |         |              |
| 052007                            |                                                                          |               |                |             |                 |     |                  |             |                    |         |              |
| 213315                            | Baggage Compartment Decompression Advisory System - Functional Check     |               | HRS            |             | 3046.1          |     | 4800             | 0           | 4800               | 4850    | 0            |
|                                   |                                                                          |               | AFL            |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                   |                                                                          |               | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                   |                                                                          |               | [HRS: +50/-50] |             |                 |     |                  |             |                    |         |              |
| Airframe                          |                                                                          |               |                |             |                 |     |                  |             |                    |         |              |
| 052006                            |                                                                          |               |                |             |                 |     |                  |             |                    |         |              |
| 213400                            | Baggage Compartment Decompression Switch - Removal / Installation        |               | HRS            |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                   |                                                                          |               | AFL            |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                   | P20M-H23                                                                 | 1111          | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                   |                                                                          |               | MSC            |             |                 |     | O/C              |             |                    |         |              |
| Airframe                          |                                                                          |               |                |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                     |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-----------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                     | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                              | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                          |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                   |               |     |             |                 |     |                  |             |                    |         |              |
| 213410           | Cabin Pressure Acquisition Module - Removal / Installation      |               | HRS | TSN:6.3     | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                 |               | AFL | TSN:6       | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 733873-1-1                                                      | 733873IN00243 | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                 |               |     |             |                 |     |                  |             |                    |         |              |
| 215101           | Pack Outlet Temperature Sensor (Left) - Removal / Installation  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                 |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 1151834-1                                                       | 1151834-12887 | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                 |               |     |             |                 |     |                  |             |                    |         |              |
| 215102           | Pack Outlet Temperature Sensor (Right) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                 |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 1151834-1                                                       | 1151834-12882 | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                 |               |     |             |                 |     |                  |             |                    |         |              |
| 215103           | AIR Conditioning Pack (Left) - Removal / Installation           |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 2215080-3                                                       | 2601          | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                 |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                 |               |     |             |                 |     |                  |             |                    |         |              |
| 215104           | AIR Conditioning Pack (Right) - Removal / Installation          |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 2215080-3                                                       | 2602          | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                 |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                 |               |     |             |                 |     |                  |             |                    |         |              |
| 215200           | AIR Cycle Machine (Left) - Removal / Installation               |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 2205590-1                                                       | SN-UNKNOWN    | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                 |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                 |               |     |             |                 |     |                  |             |                    |         |              |
| 215201           | AIR Cycle Machine (Right) - Removal / Installation              |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 1151834-1                                                       | SN-UNKNOWN    | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                 |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                 |               |     |             |                 |     |                  |             |                    |         |              |
| 215204           | Reheater / Condenser (Left) - Removal / Installation            |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  | 2341142-1                                                       | 3026          | AFL |             | 315             |     |                  | 802         |                    |         | 0            |
|                  |                                                                 |               | MOS | TSN:92      | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
|                  |                                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                 |               |     |             |                 |     |                  |             |                    |         |              |



| ATA<br>U=Custom  | Description                                                              |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(* =Adj) | Max Due | Avg Man Hrs  |
|------------------|--------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|----------------------|---------|--------------|
|                  | Part Number                                                              | Serial Number |     |             |                 |     |                  |             |                      |         | Approx Price |
| Logbook Position | HW                                                                       | SW            |     |             |                 |     |                  |             |                      |         | Manufacturer |
|                  | MM Ref                                                                   |               |     |             |                 |     |                  |             |                      |         | Date Type    |
|                  | Ops Number(s)                                                            |               |     |             |                 |     |                  |             |                      |         |              |
| 215205           | Reheater / Condenser (Right) - Removal / Installation                    |               | HRS |             | 730.5           |     |                  | 2315.6      |                      |         | 0            |
|                  | 2341142-1                                                                | 2944          | AFL |             | 315             |     |                  | 802         |                      |         | 0            |
|                  |                                                                          |               | MOS |             | 28.7            |     |                  | 21 Dec 2023 |                      |         |              |
|                  | Airframe                                                                 |               | MSC |             |                 |     | O/C              |             |                      |         |              |
| 215206           | Turbine Inlet Temperature Sensor (Left) - Removal / Installation         |               | HRS |             | 3046.1          |     |                  | 0           |                      |         | 0            |
|                  |                                                                          |               | AFL |             | 1117            |     |                  | 0           |                      |         | 0            |
|                  | 1151144-1                                                                | SN-UNKNOWN    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                      |         |              |
|                  | Airframe                                                                 |               | MSC |             |                 |     | O/C              |             |                      |         |              |
| 215207           | Turbine Inlet Temperature Sensor (Right) - Removal / Installation        |               | HRS |             | 3046.1          |     |                  | 0           |                      |         | 0            |
|                  |                                                                          |               | AFL |             | 1117            |     |                  | 0           |                      |         | 0            |
|                  | 1151144-1                                                                | SN-UNKNOWN    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                      |         |              |
|                  | Airframe                                                                 |               | MSC |             |                 |     | O/C              |             |                      |         |              |
| 215208           | Turbine Inlet Temperature Control Valve (Left) - Removal / Installation  |               | HRS |             | 3046.1          |     |                  | 0           |                      |         | 0            |
|                  |                                                                          |               | AFL |             | 1117            |     |                  | 0           |                      |         | 0            |
|                  | 2341176-1                                                                | SN-UNKNOWN    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                      |         |              |
|                  | Airframe                                                                 |               | MSC |             |                 |     | O/C              |             |                      |         |              |
| 215209           | Turbine Inlet Temperature Control Valve (Right) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                      |         | 0            |
|                  |                                                                          |               | AFL |             | 1117            |     |                  | 0           |                      |         | 0            |
|                  | 2341176-1                                                                | SN-UNKNOWN    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                      |         |              |
|                  | Airframe                                                                 |               | MSC |             |                 |     | O/C              |             |                      |         |              |
| 215210           | Low Limit Valve (Left) - Removal / Installation                          |               | HRS |             | 3046.1          |     |                  | 0           |                      |         | 0            |
|                  | 3291284-1                                                                | SN-UNKNOWN    | AFL |             | 1117            |     |                  | 0           |                      |         | 0            |
|                  |                                                                          |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                      |         |              |
|                  | Airframe                                                                 |               | MSC |             |                 |     | O/C              |             |                      |         |              |
| 215211           | Low Limit Valve (Right) - Removal / Installation                         |               | HRS |             | 3046.1          |     |                  | 0           |                      |         | 0            |
|                  | 3291284-1                                                                | SN-UNKNOWN    | AFL |             | 1117            |     |                  | 0           |                      |         | 0            |
|                  |                                                                          |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                      |         |              |
|                  | Airframe                                                                 |               | MSC |             |                 |     | O/C              |             |                      |         |              |

| ATA<br>U=Custom  | Description                                              |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                              | Serial Number |     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                       | SW            |     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                   |               |     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                            |               |     |             |                 |     |                  |             |                     |         |              |
| 215212           | Primary / Secondary Heat Exchanger (Left Primary) -      |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  | Removal / Installation                                   |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 2341680-1                                                | SN-UNKNOWN    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                          |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                          |               |     |             |                 |     |                  |             |                     |         |              |
| 215213           | Primary / Secondary Heat Exchanger (Right Primary) -     |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  | Removal / Installation                                   |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 2341680-1                                                | SN-UNKNOWN    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                          |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                          |               |     |             |                 |     |                  |             |                     |         |              |
| 215214           | Primary / Secondary Heat Exchanger (Left Secondary) -    |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  | Removal / Installation                                   |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 2341682-1                                                | SN-UNKNOWN    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                          |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                          |               |     |             |                 |     |                  |             |                     |         |              |
| 215215           | Primary / Secondary Heat Exchanger (Right Secondary) -   |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  | Removal / Installation                                   |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 2341682-1                                                | SN-UNKNOWN    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                          |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                          |               |     |             |                 |     |                  |             |                     |         |              |
| 215218           | Turbine Bypass Valve (Left) - Removal / Installation     |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  | 3291286-3                                                |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  |                                                          |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                          |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                          |               |     |             |                 |     |                  |             |                     |         |              |
| 215219           | Turbine Bypass Valve (Right) - Removal / Installation    |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  | 3291286-3                                                |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  |                                                          |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                          |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                          |               |     |             |                 |     |                  |             |                     |         |              |
| 215220           | Servo Pressure Regulator (Left) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  | 3215634-3                                                |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  |                                                          |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                          |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                          |               |     |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom                  | Description                                                       |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|----------------------------------|-------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                  | Part Number                                                       | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position                 | HW                                                                | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                  | MM Ref                                                            |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                                  | Ops Number(s)                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| 215221                           | Servo Pressure Regulator (Right) - Removal / Installation         |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                  | 3215634-3                                                         | SN-UNKNOWN    | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                  |                                                                   |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                  | Airframe                                                          |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 215238                           | Primary / Secondary Heat Exchanger (Left Primary) - Inspection    |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                  |                                                                   |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                  |                                                                   |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                  | Airframe                                                          |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Notes: PN: 2341682-1 SN: <NONE>. |                                                                   |               |     |             |                 |     |                  |             |                    |         |              |
| 215239                           | Primary / Secondary Heat Exchanger (Right Primary) - Inspection   |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                  |                                                                   |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                  |                                                                   |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                  | Airframe                                                          |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Notes: PN: 2341682-1 SN: <NONE>. |                                                                   |               |     |             |                 |     |                  |             |                    |         |              |
| 215240                           | Primary / Secondary Heat Exchanger (Left Secondary) - Inspection  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                  |                                                                   |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                  |                                                                   |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                  | Airframe                                                          |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Notes: PN: 2341682-1 SN: <NONE>. |                                                                   |               |     |             |                 |     |                  |             |                    |         |              |
| 215241                           | Primary / Secondary Heat Exchanger (Right Secondary) - Inspection |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                  |                                                                   |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                  |                                                                   |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                  | Airframe                                                          |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Notes: PN: 2341682-1 SN: <NONE>. |                                                                   |               |     |             |                 |     |                  |             |                    |         |              |
| 215242                           | Primary / Secondary Heat Exchanger (Left Primary) - Cleaning      |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                  |                                                                   |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                  |                                                                   |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                  | Airframe                                                          |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Notes: PN: 2341682-1 SN: <NONE>. |                                                                   |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom                  | Description                                                                           |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|----------------------------------|---------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|----------|---------------------|---------|--------------|
|                                  | Part Number                                                                           | Serial Number |     |             |                 |     |                  |          |                     |         | Approx Price |
| Logbook Position                 | HW                                                                                    | SW            |     |             |                 |     |                  |          |                     |         | Manufacturer |
|                                  | MM Ref                                                                                |               |     |             |                 |     |                  |          |                     |         | Date Type    |
|                                  | Ops Number(s)                                                                         |               |     |             |                 |     |                  |          |                     |         |              |
| 215243                           | Primary / Secondary Heat Exchanger (Right Primary) -<br>Cleaning                      |               | HRS |             | 3046.1          |     |                  | 0        |                     |         | 0            |
|                                  |                                                                                       |               | AFL |             | 1117            |     |                  | 0        |                     | 0       |              |
|                                  |                                                                                       |               | MOS |             | 128.6           |     | 24 Aug 2015      |          |                     |         |              |
|                                  |                                                                                       |               | MSC |             |                 | O/C |                  |          |                     |         |              |
| Airframe                         |                                                                                       |               |     |             |                 |     |                  |          |                     |         |              |
| Notes: PN: 2341682-1 SN: <NONE>. |                                                                                       |               |     |             |                 |     |                  |          |                     |         |              |
| 215244                           | Primary / Secondary Heat Exchanger (Left Secondary) -<br>Cleaning                     |               | HRS |             | 3046.1          |     |                  | 0        |                     |         | 0            |
|                                  |                                                                                       |               | AFL |             | 1117            |     |                  | 0        |                     | 0       |              |
|                                  |                                                                                       |               | MOS |             | 128.6           |     | 24 Aug 2015      |          |                     |         |              |
|                                  |                                                                                       |               | MSC |             |                 | O/C |                  |          |                     |         |              |
| Airframe                         |                                                                                       |               |     |             |                 |     |                  |          |                     |         |              |
| Notes: PN: 2341682-1 SN: <NONE>. |                                                                                       |               |     |             |                 |     |                  |          |                     |         |              |
| 215245                           | Primary / Secondary Heat Exchanger (Right Secondary) -<br>Cleaning                    |               | HRS |             | 3046.1          |     |                  | 0        |                     |         | 0            |
|                                  |                                                                                       |               | AFL |             | 1117            |     |                  | 0        |                     | 0       |              |
|                                  |                                                                                       |               | MOS |             | 128.6           |     | 24 Aug 2015      |          |                     |         |              |
|                                  |                                                                                       |               | MSC |             |                 | O/C |                  |          |                     |         |              |
| Airframe                         |                                                                                       |               |     |             |                 |     |                  |          |                     |         |              |
| Notes: PN: 2341682-1 SN: <NONE>. |                                                                                       |               |     |             |                 |     |                  |          |                     |         |              |
| 215400                           | Water Extractor (Left) - Removal / Installation<br>2341144-1 SN-UNKNOWN               |               | HRS |             | 3046.1          |     |                  | 0        |                     |         | 0            |
|                                  |                                                                                       |               | AFL |             | 1117            |     |                  | 0        |                     | 0       |              |
|                                  |                                                                                       |               | MOS |             | 128.6           |     | 24 Aug 2015      |          |                     |         |              |
|                                  |                                                                                       |               | MSC |             |                 | O/C |                  |          |                     |         |              |
| Airframe                         |                                                                                       |               |     |             |                 |     |                  |          |                     |         |              |
| 215401                           | Water Extractor (Right) - Removal / Installation<br>2341144-1 SN-UNKNOWN              |               | HRS |             | 3046.1          |     |                  | 0        |                     |         | 0            |
|                                  |                                                                                       |               | AFL |             | 1117            |     |                  | 0        |                     | 0       |              |
|                                  |                                                                                       |               | MOS |             | 128.6           |     | 24 Aug 2015      |          |                     |         |              |
|                                  |                                                                                       |               | MSC |             |                 | O/C |                  |          |                     |         |              |
| Airframe                         |                                                                                       |               |     |             |                 |     |                  |          |                     |         |              |
| 215402                           | Water Extractor Strainer (Left) - Removal / Installation<br>60P2152001S010 SN-UNKNOWN |               | HRS |             | 3046.1          |     |                  | 0        |                     |         | 0            |
|                                  |                                                                                       |               | AFL |             | 1117            |     |                  | 0        |                     | 0       |              |
|                                  |                                                                                       |               | MOS |             | 128.6           |     | 24 Aug 2015      |          |                     |         |              |
|                                  |                                                                                       |               | MSC |             |                 | O/C |                  |          |                     |         |              |
| Airframe                         |                                                                                       |               |     |             |                 |     |                  |          |                     |         |              |
| 215403                           | Water Extractor Strainer (Right) - Removal / Installation<br>60P2152001S010 NSN       |               | HRS |             | 3046.1          |     |                  | 0        |                     |         | 0            |
|                                  |                                                                                       |               | AFL |             | 1117            |     |                  | 0        |                     | 0       |              |
|                                  |                                                                                       |               | MOS |             | 128.6           |     | 24 Aug 2015      |          |                     |         |              |
|                                  |                                                                                       |               | MSC |             |                 | O/C |                  |          |                     |         |              |
| Airframe                         |                                                                                       |               |     |             |                 |     |                  |          |                     |         |              |

| ATA<br>U=Custom                       | Description                                                                                |               | UOM            | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|---------------------------------------|--------------------------------------------------------------------------------------------|---------------|----------------|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                                       | Part Number                                                                                | Serial Number |                |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position                      | HW                                                                                         | SW            |                |             |                 |     |                  |             |                     |         | Manufacturer |
|                                       | MM Ref                                                                                     |               |                |             |                 |     |                  |             |                     |         | Date Type    |
|                                       | Ops Number(s)                                                                              |               |                |             |                 |     |                  |             |                     |         |              |
| 215408                                | Water Extractor Aspirator Line and Nozzle (Left) -<br>Inspection                           |               | HRS            |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                                       |                                                                                            |               | AFL            |             | 1117            |     |                  | 0           |                     | 0       |              |
|                                       |                                                                                            |               | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                                       |                                                                                            |               | MSC            |             |                 |     | O/C              |             |                     |         |              |
| Airframe                              |                                                                                            |               |                |             |                 |     |                  |             |                     |         |              |
| Notes: PN: 60P2152001S010 SN: <NONE>. |                                                                                            |               |                |             |                 |     |                  |             |                     |         |              |
| 215409                                | Water Extractor Aspirator Line and Nozzle (Right) -<br>Inspection                          |               | HRS            |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                                       |                                                                                            |               | AFL            |             | 1117            |     |                  | 0           |                     | 0       |              |
|                                       |                                                                                            |               | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                                       |                                                                                            |               | MSC            |             |                 |     | O/C              |             |                     |         |              |
| Airframe                              |                                                                                            |               |                |             |                 |     |                  |             |                     |         |              |
| Notes: PN: 60P2152001S010 SN: <NONE>. |                                                                                            |               |                |             |                 |     |                  |             |                     |         |              |
| 216101                                | AIR Conditioning Controller (Left) - Removal / Installation<br>1153482-3 1153482-00864     |               | HRS            |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                                       |                                                                                            |               | AFL            |             | 1117            |     |                  | 0           |                     | 0       |              |
|                                       |                                                                                            |               | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                                       |                                                                                            |               | MSC            |             |                 |     | O/C              |             |                     |         |              |
| Airframe                              |                                                                                            |               |                |             |                 |     |                  |             |                     |         |              |
| 216102                                | AIR Conditioning Controller (Right) - Removal /<br>Installation<br>1153482-3 1153482-00866 |               | HRS            |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                                       |                                                                                            |               | AFL            |             | 1117            |     |                  | 0           |                     | 0       |              |
|                                       |                                                                                            |               | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                                       |                                                                                            |               | MSC            |             |                 |     | O/C              |             |                     |         |              |
| Airframe                              |                                                                                            |               |                |             |                 |     |                  |             |                     |         |              |
| 216111                                | Zone Trim AIR Check Valve (Left) - Detailed Inspection                                     |               | HRS            |             | 3046.1          |     | 6000             | 0           | 6000                | 6050    | 0            |
|                                       |                                                                                            |               | AFL            |             | 1117            |     |                  | 0           |                     | 0       |              |
|                                       |                                                                                            |               | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                                       |                                                                                            |               | [HRS: +50/-50] |             |                 |     |                  |             |                     |         |              |
| Airframe 052007                       |                                                                                            |               |                |             |                 |     |                  |             |                     |         |              |
| 216112                                | Zone Trim AIR Check Valve (Right) - Detailed Inspection                                    |               | HRS            |             | 3046.1          |     | 6000             | 0           | 6000                |         | 0            |
|                                       |                                                                                            |               | AFL            |             | 1117            |     |                  | 0           |                     | 0       |              |
|                                       |                                                                                            |               | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                                       |                                                                                            |               | [HRS: -50]     |             |                 |     |                  |             |                     |         |              |
| Airframe 052007                       |                                                                                            |               |                |             |                 |     |                  |             |                     |         |              |
| 216113                                | AIR Supply Check Valve (Left) - Detailed Inspection                                        |               | HRS            |             | 3046.1          |     | 12000            | 0           | 12000               | 12050   | 0            |
|                                       |                                                                                            |               | AFL            |             | 1117            |     |                  | 0           |                     | 0       |              |
|                                       |                                                                                            |               | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                                       |                                                                                            |               | [HRS: +50/-50] |             |                 |     |                  |             |                     |         |              |
| Airframe 052009                       |                                                                                            |               |                |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom  | Description                                                      |               | UOM            | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------------------------------|---------------|----------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                      | Serial Number |                |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                               | SW            |                |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                           |               |                |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                    |               |                |             |                 |     |                  |             |                    |         |              |
| 216114           | AIR Supply Check Valve (Right) - Detailed Inspection             |               | HRS            |             | 3046.1          |     | 12000            | 0           | 12000              | 12050   | 0            |
|                  |                                                                  |               | AFL            |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                  |               | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe         | 052009                                                           |               | [HRS: +50/-50] |             |                 |     |                  |             |                    |         |              |
| 216120           | Zone Supply Check Valve - Removal / Installation                 |               | HRS            |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 123312-9                                                         | 20523         | AFL            |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                  |               | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe         |                                                                  |               | MSC            |             |                 |     | O/C              |             |                    |         |              |
| 216121           | AIR Supply Trim AIR Check Valve (Left) - Removal / Installation  |               | HRS            |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                  |               | AFL            |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 3202758-1                                                        | 2000          | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe         |                                                                  |               | MSC            |             |                 |     | O/C              |             |                    |         |              |
| 216122           | AIR Supply Trim AIR Check Valve (Right) - Removal / Installation |               | HRS            |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                  |               | AFL            |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 3202758-1                                                        | 2001          | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe         |                                                                  |               | MSC            |             |                 |     | O/C              |             |                    |         |              |
| 216123           | Zone Trim AIR Check Valve (Left) - Removal / Installation        |               | HRS            |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 3202760-1                                                        | 2744          | AFL            |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                  |               | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe         |                                                                  |               | MSC            |             |                 |     | O/C              |             |                    |         |              |
| 216124           | Zone Trim AIR Check Valve (Right) - Removal / Installation       |               | HRS            |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                  |               | AFL            |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 3202760-1                                                        | 2745          | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe         |                                                                  |               | MSC            |             |                 |     | O/C              |             |                    |         |              |
| 216125           | Zone Trim AIR Valve Check Valve (Left) - Removal / Installation  |               | HRS            |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                  |               | AFL            |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 123312-9                                                         | 20517         | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe         |                                                                  |               | MSC            |             |                 |     | O/C              |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                              |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|--------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                                              | Serial Number |     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                                       | SW            |     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                                   |               |     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                                            |               |     |             |                 |     |                  |             |                     |         |              |
| 216126           | Zone Trim AIR Valve Check Valve (Right) - Removal / Installation         |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                          |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 123312-9                                                                 | 20524         | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                          |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                          |               |     |             |                 |     |                  |             |                     |         |              |
| 216130           | Overheat Thermostat Zone Supply (Cockpit) - Removal / Installation       |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                          |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 129740-1                                                                 | 4933          | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                          |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                          |               |     |             |                 |     |                  |             |                     |         |              |
| 216131           | Overheat Thermostat Zone Supply (Forward Cabin) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                          |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 129740-1                                                                 | 4936          | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                          |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                          |               |     |             |                 |     |                  |             |                     |         |              |
| 216132           | Overheat Thermostat Zone Supply (Aft Cabin) - Removal / Installation     |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                          |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 129740-1                                                                 | 4882          | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                          |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                          |               |     |             |                 |     |                  |             |                     |         |              |
| 216135           | Zone Trim AIR Valve (Cockpit) - Removal / Installation                   |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                          |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 3291688-3                                                                | 1769          | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                          |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                          |               |     |             |                 |     |                  |             |                     |         |              |
| 216136           | Zone Trim AIR Valve (Forward Cabin) - Removal / Installation             |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                          |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 3291688-3                                                                | 1771          | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                          |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                          |               |     |             |                 |     |                  |             |                     |         |              |
| 216137           | Zone Trim AIR Valve (Aft Cabin) - Removal / Installation                 |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                          |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 3291688-3                                                                | 1770          | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                          |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                          |               |     |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom  | Description                                                               |               | UOM            | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|---------------------------------------------------------------------------|---------------|----------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                               | Serial Number |                |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                        | SW            |                |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                    |               |                |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                             |               |                |             |                 |     |                  |             |                    |         |              |
| 216138           | Zone Trim AIR Valve Cup Assembly (Cockpit) - Removal / Installation       |               | HRS            |             | 137             |     |                  | 2909.1      |                    |         | 0            |
|                  |                                                                           |               | AFL            |             | 52              |     |                  | 1065        |                    |         | 0            |
|                  | 4000091-600-BT                                                            | NSN           | MOS            | TSN:5       | 5.3             |     |                  | 03 Dec 2025 |                    |         |              |
|                  |                                                                           |               | MSC            |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                           |               |                |             |                 |     |                  |             |                    |         |              |
| 216139           | Zone Trim AIR Valve Cup Assembly (Forward Cabin) - Removal / Installation |               | HRS            |             | 137             |     |                  | 2909.1      |                    |         | 0            |
|                  |                                                                           |               | AFL            |             | 52              |     |                  | 1065        |                    |         | 0            |
|                  | 4000091-600-BT                                                            | NSN           | MOS            | TSN:5       | 5.3             |     |                  | 03 Dec 2025 |                    |         |              |
|                  |                                                                           |               | MSC            |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                           |               |                |             |                 |     |                  |             |                    |         |              |
| 216140           | Zone Trim AIR Valve Cup Assembly (Aft Cabin) - Removal / Installation     |               | HRS            |             | 137             |     |                  | 2909.1      |                    |         | 0            |
|                  |                                                                           |               | AFL            |             | 52              |     |                  | 1065        |                    |         | 0            |
|                  | 4000091-600-BT                                                            | NSN           | MOS            | TSN:5       | 5.3             |     |                  | 03 Dec 2025 |                    |         |              |
|                  |                                                                           |               | MSC            |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                           |               |                |             |                 |     |                  |             |                    |         |              |
| 216141           | Zone Trim AIR Valve Cup Assembly (Cockpit) - Discard                      |               | HRS            |             | 137             |     | 600              | 2909.1      | 3509.1             | 3559.1  | 0            |
|                  |                                                                           |               | AFL            |             | 52              |     |                  | 1065        |                    |         | 0            |
|                  | 4000091-600-BT                                                            | NSN           | MOS            | TSN:5       | 5.3             |     |                  | 03 Dec 2025 |                    |         |              |
|                  |                                                                           |               | [HRS: +50/-50] |             |                 |     |                  |             |                    |         |              |
| Airframe         |                                                                           |               |                |             |                 |     |                  |             |                    |         |              |
| 216142           | Zone Trim AIR Valve Cup Assembly (Forward Cabin) - Discard                |               | HRS            |             | 137             |     | 600              | 2909.1      | 3509.1             | 3559.1  | 0            |
|                  |                                                                           |               | AFL            |             | 52              |     |                  | 1065        |                    |         | 0            |
|                  | 4000091-600-BT                                                            | NSN           | MOS            | TSN:5       | 5.3             |     |                  | 03 Dec 2025 |                    |         |              |
|                  |                                                                           |               | [HRS: +50/-50] |             |                 |     |                  |             |                    |         |              |
| Airframe         |                                                                           |               |                |             |                 |     |                  |             |                    |         |              |
| 216143           | Zone Trim AIR Valve Cup Assembly (Aft Cabin) - Discard                    |               | HRS            |             | 137             |     | 600              | 2909.1      | 3509.1             | 3559.1  | 0            |
|                  |                                                                           |               | AFL            |             | 52              |     |                  | 1065        |                    |         | 0            |
|                  | 4000091-600-BT                                                            | NSN           | MOS            | TSN:5       | 5.3             |     |                  | 03 Dec 2025 |                    |         |              |
|                  |                                                                           |               | [HRS: +50/-50] |             |                 |     |                  |             |                    |         |              |
| Airframe         |                                                                           |               |                |             |                 |     |                  |             |                    |         |              |
| 216206           | Cabin / Cockpit Temperature Indication - Functional Test                  |               | HRS            |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  |                                                                           |               | AFL            |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  |                                                                           |               | MOS            |             | 124.5           |     |                  | 27 Dec 2015 |                    |         |              |
|                  |                                                                           |               | MSC            |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                           |               |                |             |                 |     |                  |             |                    |         |              |



| ATA<br>U=Custom                  | Description                                                                                     |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|----------------------------------|-------------------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                                  | Part Number                                                                                     | Serial Number |     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position                 | HW                                                                                              | SW            |     |             |                 |     |                  |             |                     |         | Manufacturer |
|                                  | MM Ref                                                                                          |               |     |             |                 |     |                  |             |                     |         | Date Type    |
|                                  | Ops Number(s)                                                                                   |               |     |             |                 |     |                  |             |                     |         |              |
| 216219                           | Zone Temperature Sensor Fan (Forward Cabin) - Removal / Installation                            |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                                  |                                                                                                 |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                                  | 011590500                                                                                       | SN-UNKNOWN    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                                  |                                                                                                 |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe                         |                                                                                                 |               |     |             |                 |     |                  |             |                     |         |              |
| 216220                           | Zone Temperature Sensor Fan (Aft Cabin) - Removal / Installation                                |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                                  |                                                                                                 |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                                  | 11590500                                                                                        | SN-UNKNOWN    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                                  |                                                                                                 |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe                         |                                                                                                 |               |     |             |                 |     |                  |             |                     |         |              |
| 216223                           | Zone Temperature Sensor Fan (Forward Cabin) - Cleaning                                          |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                                  |                                                                                                 |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                                  |                                                                                                 |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                                  |                                                                                                 |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe                         |                                                                                                 |               |     |             |                 |     |                  |             |                     |         |              |
| Notes: PN: 011590500 SN: <NONE>. |                                                                                                 |               |     |             |                 |     |                  |             |                     |         |              |
| 216224                           | Zone Temperature Sensor Fan (Aft Cabin) - Cleaning                                              |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                                  |                                                                                                 |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                                  |                                                                                                 |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                                  |                                                                                                 |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe                         |                                                                                                 |               |     |             |                 |     |                  |             |                     |         |              |
| Notes: PN: 011590500 SN: <NONE>. |                                                                                                 |               |     |             |                 |     |                  |             |                     |         |              |
| 216229                           | Zone Temperature Sensor Fan Low-Speed Warning Detector (Forward Cabin) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                                  |                                                                                                 |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                                  | 035640501                                                                                       | SN-UNKNOWN    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                                  |                                                                                                 |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe                         |                                                                                                 |               |     |             |                 |     |                  |             |                     |         |              |
| 216230                           | Zone Temperature Sensor Fan Low-Speed Warning Detector (Aft Cabin) - Removal / Installation     |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                                  |                                                                                                 |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                                  | 035640501                                                                                       | SN-UNKNOWN    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                                  |                                                                                                 |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe                         |                                                                                                 |               |     |             |                 |     |                  |             |                     |         |              |
| 216235                           | Cabin Temperature Sensor (Aft) - Removal / Installation                                         |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                                  |                                                                                                 |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                                  | 1151834-1                                                                                       | 1151834-12883 | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                                  |                                                                                                 |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe                         |                                                                                                 |               |     |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom                     | Description                                                             |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|-------------------------------------|-------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                                     | Part Number                                                             | Serial Number |     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position                    | HW                                                                      | SW            |     |             |                 |     |                  |             |                     |         | Manufacturer |
|                                     | MM Ref                                                                  |               |     |             |                 |     |                  |             |                     |         | Date Type    |
|                                     | Ops Number(s)                                                           |               |     |             |                 |     |                  |             |                     |         |              |
| 216236                              | Zone Supply Temperature Sensor (Cockpit) - Removal / Installation       |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                                     |                                                                         |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                                     | 1151834-1                                                               | 1151834-12880 | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                                     |                                                                         |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe                            |                                                                         |               |     |             |                 |     |                  |             |                     |         |              |
| 216237                              | Zone Supply Temperature Sensor (Forward Cabin) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                                     |                                                                         |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                                     | 1151834-1                                                               | 1151834-09322 | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                                     |                                                                         |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe                            |                                                                         |               |     |             |                 |     |                  |             |                     |         |              |
| 216238                              | Zone Supply Temperature Sensor (Aft Cabin) - Removal / Installation     |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                                     |                                                                         |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                                     | 1151834-1                                                               | 1151834-12921 | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                                     |                                                                         |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe                            |                                                                         |               |     |             |                 |     |                  |             |                     |         |              |
| 216239                              | Cockpit Temperature Sensor - Removal / Installation                     |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                                     |                                                                         |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                                     | 1152488-1                                                               | 1152488-02890 | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                                     |                                                                         |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe                            |                                                                         |               |     |             |                 |     |                  |             |                     |         |              |
| 216240                              | Cabin Temperature Sensor (Forward) - Removal / Installation             |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                                     |                                                                         |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                                     | 1151834-1                                                               | 1151834-12920 | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                                     |                                                                         |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe                            |                                                                         |               |     |             |                 |     |                  |             |                     |         |              |
| 216241                              | Leer Temperature Sensor - Removal / Installation                        |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                                     |                                                                         |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                                     | 1152488-1                                                               | 1152488-02914 | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                                     |                                                                         |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe                            |                                                                         |               |     |             |                 |     |                  |             |                     |         |              |
| 22 - Auto Flight                    |                                                                         |               |     |             |                 |     |                  |             |                     |         |              |
| 221000                              | Autopilot - Operational Test                                            |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                                     |                                                                         |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                                     |                                                                         |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                                     |                                                                         |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe                            |                                                                         |               |     |             |                 |     |                  |             |                     |         |              |
| Notes: PN: 7028432-1902 SN: <NONE>. |                                                                         |               |     |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom                    | Description                                                 |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------------------------|-------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                    | Part Number                                                 | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position                   | HW                                                          | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                    | MM Ref                                                      |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                                    | Ops Number(s)                                               |               |     |             |                 |     |                  |             |                    |         |              |
| 221100                             | Flight Guidance Panel - Removal / Installation              |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                    | 7028660-951                                                 | 15051714      | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                    |                                                             |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                    | Airframe                                                    |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 223000                             | Auto Throttle - Operational Test                            |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                    |                                                             |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                    |                                                             |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                    | Airframe                                                    |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Notes: PN: 7028660-951 SN: <NONE>. |                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 23 - Communications                |                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 230300                             | Modular Radio Cabinet (No. 1) - Removal / Installation      |               | HRS | TSN:2483.7  | 562.4           |     |                  | 2483.7      |                    |         | 0            |
|                                    | 7517959-904                                                 | 15032891      | AFL | TSN:900     | 217             |     |                  | 900         |                    |         | 0            |
|                                    |                                                             |               | MOS | TSN:112     | 16.8            |     |                  | 16 Dec 2024 |                    |         |              |
|                                    | Airframe                                                    |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 230301                             | Modular Radio Cabinet (No. 2) - Removal / Installation      |               | HRS |             | 562.4           |     |                  | 2483.7      |                    |         | 0            |
|                                    | 7517959-904                                                 | 12090945      | AFL |             | 217             |     |                  | 900         |                    |         | 0            |
|                                    |                                                             |               | MOS |             | 16.8            |     |                  | 16 Dec 2024 |                    |         |              |
|                                    | Airframe                                                    |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 230304                             | Modular Radio System - Return to Service Test               |               | HRS |             | 562.4           |     |                  | 2483.7      |                    |         | 0            |
|                                    |                                                             |               | AFL |             | 217             |     |                  | 900         |                    |         | 0            |
|                                    |                                                             |               | MOS |             | 16.8            |     |                  | 16 Dec 2024 |                    |         |              |
|                                    | Airframe                                                    |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 230305                             | Modular Radio Cabinet Rear Fan Cover - Operational Test     |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                    |                                                             |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                    |                                                             |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                    | Airframe                                                    |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 231010                             | Configuration Module, Security Pcu - Removal / Installation |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                                    |                                                             |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                                    | 100-2625-01                                                 | 1155506       | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | SECURAPLANE  |
|                                    | Airframe                                                    |               | MSC |             |                 |     | O/C              |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                          |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                                          | Serial Number |     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                                   | SW            |     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                               |               |     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                                        |               |     |             |                 |     |                  |             |                     |         |              |
| 231200           | VHF Voice Communications - Operational Test                          |               | HRS |             | 562.4           |     |                  | 2483.7      |                     |         | 0            |
|                  |                                                                      |               | AFL |             | 217             |     |                  | 900         |                     |         | 0            |
|                  |                                                                      |               | MOS |             | 16.8            |     |                  | 16 Dec 2024 |                     |         |              |
|                  | Airframe                                                             |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| 231201           | VHF Antenna (No. 1) - Removal / Installation                         |               | HRS | TSN:1745.4  | 1300.7          |     |                  | 1745.4      |                     |         | 0            |
|                  | S65-8280-10                                                          | 310-28219     | AFL | TSN:610     | 507             |     |                  | 610         |                     |         | 0            |
|                  |                                                                      |               | MOS | TSN:77      | 51.7            |     |                  | 19 Jan 2022 |                     |         |              |
|                  | Airframe                                                             |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| 231202           | VHF Antenna (No. 2) - Removal / Installation                         |               | HRS | TSN:31.6    | 1269.1          |     |                  | 1777        |                     |         | 0            |
|                  | S65-8280-37                                                          | 868-0278      | AFL | TSN:6       | 501             |     |                  | 616         |                     |         | 0            |
|                  |                                                                      |               | MOS | TSN:1       | 50              |     |                  | 10 Mar 2022 |                     |         |              |
|                  | Airframe                                                             |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| 231203           | VHF Antenna (No. 3) - Removal / Installation                         |               | HRS |             | 1300.7          |     |                  | 1745.4      |                     |         | 0            |
|                  | S65-8280-10                                                          | 310-36164     | AFL |             | 507             |     |                  | 610         |                     |         | 0            |
|                  |                                                                      |               | MOS | TSN:8       | 51.5            |     |                  | 25 Jan 2022 |                     |         |              |
|                  | Airframe                                                             |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| 231210           | VHF Voice / Data Radio Module (No. 1) - Removal / Installation       |               | HRS |             | 562.4           |     |                  | 2483.7      |                     |         | 0            |
|                  |                                                                      |               | AFL |             | 217             |     |                  | 900         |                     |         | 0            |
|                  | 7026201-813                                                          | 09025935      | MOS |             | 16.8            |     |                  | 16 Dec 2024 |                     |         |              |
|                  | Airframe                                                             |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| 231211           | VHF Voice / Data Radio Module (No. 2) - Removal / Installation       |               | HRS |             | 562.4           |     |                  | 2483.7      |                     |         | 0            |
|                  |                                                                      |               | AFL |             | 217             |     |                  | 900         |                     |         | 0            |
|                  | 7026201-813                                                          | 1512C958      | MOS |             | 16.8            |     |                  | 16 Dec 2024 |                     |         |              |
|                  | Airframe                                                             |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| 231300           | HF Dual Coupler Mounting Tray / Shock Mount - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                      |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 622-8124-001                                                         | 4812          | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  | Airframe                                                             |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| 231301           | HF Antenna Adapter - Removal / Installation                          |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                      |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 822-0089-001                                                         | 1829          | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  | Airframe                                                             |               | MSC |             |                 |     | O/C              |             |                     |         |              |

| ATA<br>U=Custom                    | Description                                               |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------------------------|-----------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                    | Part Number                                               | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position                   | HW                                                        | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                    | MM Ref                                                    |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                                    | Ops Number(s)                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 231302                             | HF R/T (No. 1) - Removal / Installation                   |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                    | 822-0102-00                                               | 5577          | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                    |                                                           |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                    | Airframe                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 231303                             | HF Dual Coupler Mounting Tray / Shock Mount - Replacement |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                    |                                                           |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                    | 622-8124-001                                              | 4812          | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                    | Airframe                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Notes: MRI PARENT CODE: 231300     |                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| 231306                             | HF Voice Communications - Operational Check               |               | HRS |             | 562.4           |     |                  | 2483.7      |                    |         | 0            |
|                                    |                                                           |               | AFL |             | 217             |     |                  | 900         |                    |         | 0            |
|                                    |                                                           |               | MOS |             | 16.8            |     |                  | 16 Dec 2024 |                    |         |              |
|                                    | Airframe                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 231307                             | HF Shunt Antenna - Continuity Check                       |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                    |                                                           |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                    |                                                           |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                    | Airframe                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Notes: PN: S65-8280-10 SN: <NONE>. |                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| 231308                             | HF Shunt Antenna - Removal / Installation                 |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                    | 7517959-904                                               | SN-UNKNOWN    | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                    |                                                           |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                    | Airframe                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 231310                             | HF Antenna Coupler Unit (No. 1) - Removal / Installation  |               | HRS |             | 2345.1          |     |                  | 701         |                    |         | 0            |
|                                    | 622-8114-002                                              | 14469         | AFL |             | 936             |     |                  | 181         |                    |         | 0            |
|                                    |                                                           |               | MOS |             | 96.9            |     |                  | 15 Apr 2018 |                    |         |              |
|                                    | Airframe                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 231311                             | HF Antenna Coupler Unit (No. 2) - Removal / Installation  |               | HRS |             | 2345.1          |     |                  | 701         |                    |         | 0            |
|                                    | 622-8114-002                                              | 14643         | AFL |             | 936             |     |                  | 181         |                    |         | 0            |
|                                    |                                                           |               | MOS |             | 96.9            |     |                  | 15 Apr 2018 |                    |         |              |
|                                    | Airframe                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                         |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|---------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                                         | Serial Number |     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                                  | SW            |     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                              |               |     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                                       |               |     |             |                 |     |                  |             |                     |         |              |
| 231314           | HF Antenna Coupler Unit (No. 1) - Servicing                         |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                     |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  |                                                                     |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  | Airframe                                                            |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| 231315           | HF Antenna Coupler Unit (No. 2) - Servicing                         |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                     |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  |                                                                     |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  | Airframe                                                            |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| 231316           | HF R/T (No. 1) Mounting Tray / Shock Mount - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                     |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 622-8116-001                                                        | 10784         | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  | Airframe                                                            |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| 231318           | HF R/T (No. 2) Mounting Tray / Shock Mount - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                     |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 622-8116-001                                                        | 10785         | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  | Airframe                                                            |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| 231320           | HF R/T (No. 2) - Removal / Installation                             |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  | 822-0102-001                                                        | 5612          | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  |                                                                     |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  | Airframe                                                            |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| 231400           | Satellite Transceiver - Removal / Installation                      |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  | P12023                                                              | 1202314235    | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  |                                                                     |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  | Airframe                                                            |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| 231401           | Dual Channel Satellite Antenna - Removal / Installation             |               | HRS | TSN:1745.4  | 1300.7          |     |                  | 1745.4      |                     |         | 0            |
|                  | S67-1575-165                                                        | 449-7540      | AFL | TSN:610     | 507             |     |                  | 610         |                     |         | 0            |
|                  |                                                                     |               | MOS | TSN:77      | 51.5            |     |                  | 25 Jan 2022 |                     |         |              |
|                  | Airframe                                                            |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| 231402           | Satellite Interface Unit - Removal / Installation                   |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  | P12777                                                              | 1277711720    | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  |                                                                     |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  | Airframe                                                            |               | MSC |             |                 |     | O/C              |             |                     |         |              |

| ATA<br>U=Custom                | Description                                               |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|--------------------------------|-----------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                | Part Number                                               | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position               | HW                                                        | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                | MM Ref                                                    |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                                | Ops Number(s)                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 231403                         | Satellite Telephone                                       |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | P12023                                                    | 1202314235    | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                |                                                           |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Notes: MRI PARENT CODE: 231400 |                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| 231404                         | Remote Diversity Antenna (No. 1) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | S67-1575-165                                              | 449-7540      | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                |                                                           |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Notes: MRI PARENT CODE: 231401 |                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| 231405                         | Remote Diversity Antenna (No. 2) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | P12777                                                    | 1277711720    | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                |                                                           |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Notes: MRI PARENT CODE: 231402 |                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| 231406                         | In-Flight Telecommunications - Operational Check          |               | HRS |             | 1102.5          |     |                  | 1943.6      |                    |         | 0            |
|                                |                                                           |               | AFL |             | 461             |     |                  | 656         |                    |         | 0            |
|                                |                                                           |               | MOS |             | 45              |     |                  | 12 Aug 2022 |                    |         |              |
|                                | Airframe                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 231407                         | Radio Frequency Filter - Removal / Installation           |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | P13167                                                    | 1316710905    | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                |                                                           |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 231408                         | Audio Bell (Crew Rest) - Removal / Installation           |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | P13167                                                    | 1316710905    | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                |                                                           |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Notes: MRI PARENT CODE: 231407 |                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| 231419                         | Cockpit Handset - Removal / Installation                  |               | HRS |             | 1102.5          |     |                  | 1943.6      |                    |         | 0            |
|                                | P12793-011                                                | 1279371413    | AFL |             | 461             |     |                  | 656         |                    |         | 0            |
|                                |                                                           |               | MOS |             | 45              |     |                  | 12 Aug 2022 |                    |         |              |
|                                | Airframe                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                         | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                     |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                              |               |     |             |                 |     |                  |             |                    |         |              |
| 231420           | Cockpit Handset Interface Unit - Removal / Installation    |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | P12346                                                     | 1234611921    | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                            |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                   |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 231425           | Call Alerter - Removal / Installation                      |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | P12924                                                     | 1292411990    | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                            |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                   |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 231426           | Call Speaker (Galley) - Removal / Installation             |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | P12924                                                     | SN-UNKNOWN    | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                            |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                   |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 231441           | Aircell Lh Fwd Cabin Seat Handset - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                            |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | PN                                                         | SN-UNKNOWN    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                   |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 231442           | Aircell Rh Fwd Cabin Seat Handset - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                            |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | PN                                                         | SN-UNKNOWN    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                   |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 231443           | Aircell Lh Aft Cabin Seat Handset - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | PN                                                         | SN-UNKNOWN    | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                            |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                   |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 231444           | Aircell Rh Aft Cabin Seat Handset - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | PN                                                         | SN-UNKNOWN    | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                            |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                   |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 231500           | SATCOM - Operational Check                                 |               | HRS |             | 862.3           |     |                  | 2183.8      |                    |         | 0            |
|                  |                                                            |               | AFL |             | 355             |     |                  | 762         |                    |         | 0            |
|                  |                                                            |               | MOS |             | 35.9            |     |                  | 15 May 2023 |                    |         |              |
|                  | Airframe                                                   |               | MSC |             |                 |     | O/C              |             |                    |         |              |



| ATA<br>U=Custom  | Description                                             |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|---------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                             | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                      | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                  |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                           |               |     |             |                 |     |                  |             |                    |         |              |
| 231502           | Diplexer / Low Noise Amplifier - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 173628-101                                              | 1215-0480     | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                         |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 231503           | SATCOM Antenna - Removal / Installation                 |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 806-10-1001-5                                           | 001142        | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | B                                                       | B             | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 231507           | SATCOM Antenna - Adjustment / Test                      |               | HRS |             | 1178.5          |     |                  | 1867.6      |                    |         | 0            |
|                  |                                                         |               | AFL |             | 486             |     |                  | 631         |                    |         | 0            |
|                  |                                                         |               | MOS |             | 47.6            |     |                  | 22 May 2022 |                    |         |              |
|                  | Airframe                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 231508           | Satellite Data Unit - Removal / Installation            |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  | 1252-A-3800-01                                          | 2287          | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  |                                                         |               | MOS |             | 124.8           |     |                  | 18 Dec 2015 |                    |         |              |
|                  | Airframe                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 232000           | Selective Calling / Data Link - Operational Check       |               | HRS |             | 562.4           |     |                  | 2483.7      |                    |         | 0            |
|                  |                                                         |               | AFL |             | 217             |     |                  | 900         |                    |         | 0            |
|                  |                                                         |               | MOS |             | 16.8            |     |                  | 16 Dec 2024 |                    |         |              |
|                  | Airframe                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 232304           | Multi-Function Printer (Facsimile) - Adjustment / Test  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                         |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                         |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 232700           | Vmbr-1500 (Bbml) - Removal / Installation               |               | HRS |             | 1540.6          |     |                  | 1505.5      |                    |         | 0            |
|                  | 1054023                                                 | 00002792      | AFL |             | 627             |     |                  | 490         |                    |         | 0            |
|                  |                                                         |               | MOS |             | 66.8            |     |                  | 16 Oct 2020 |                    |         |              |
|                  | Airframe                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 232701           | Antenna Control Unit - Removal / Installation           |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  | 1067697                                                 | 50204-11000   | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  |                                                         |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | VIASAT       |
|                  | Airframe                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                      |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs   |
|------------------|----------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|---------------|
|                  | Part Number                                                                      | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price  |
| Logbook Position | HW                                                                               | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer  |
|                  | MM Ref                                                                           |               |     |             |                 |     |                  |             |                    |         | Date Type     |
|                  | Ops Number(s)                                                                    |               |     |             |                 |     |                  |             |                    |         |               |
| 232702           | Broad Band Multi-Link Antenna - Removal / Installation                           |               | HRS |             | 1178.5          |     |                  | 1867.6      |                    |         | 0             |
|                  | 1060076                                                                          | 50204-0837    | AFL |             | 486             |     |                  | 631         |                    |         | 0             |
|                  |                                                                                  |               | MOS |             | 47.6            |     |                  | 22 May 2022 |                    |         |               |
|                  | Airframe                                                                         |               | MSC |             |                 |     | O/C              |             |                    |         |               |
| 232900           | Wireless Local AREA Network Antenna (No. 1) - Removal / Installation             |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0             |
|                  |                                                                                  |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0             |
|                  | S65-5366-31S                                                                     | SN-UNKNOWN    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |               |
|                  | Airframe                                                                         |               | MSC |             |                 |     | O/C              |             |                    |         |               |
| 232902           | Advanced Cabin Server (No. 1) - Removal / Installation                           |               | HRS |             | 1269.1          |     |                  | 1777        |                    |         | 0             |
|                  | ACS-04-002                                                                       | 02419         | AFL |             | 501             |     |                  | 616         |                    |         | 0             |
|                  |                                                                                  |               | MOS |             | 50              |     |                  | 10 Mar 2022 |                    |         |               |
|                  | Airframe                                                                         |               | MSC |             |                 |     | O/C              |             |                    |         |               |
| 232903           | Advanced Cabin Server (No. 2) - Removal / Installation                           |               | HRS |             | 1269.1          |     |                  | 1777        |                    |         | 0             |
|                  | ACS-04-002                                                                       | 02196         | AFL |             | 501             |     |                  | 616         |                    |         | 0             |
|                  |                                                                                  |               | MOS |             | 50              |     |                  | 10 Mar 2022 |                    |         |               |
|                  | Airframe                                                                         |               | MSC |             |                 |     | O/C              |             |                    |         |               |
| 232906           | Wireless Local AREA Network Interface / Broadband Multi-Link - Adjustment / Test |               | HRS |             | 2883.3          |     |                  | 162.8       |                    |         | 0             |
|                  |                                                                                  |               | AFL |             | 1073            |     |                  | 44          |                    |         | 0             |
|                  |                                                                                  |               | MOS |             | 116.5           |     |                  | 25 Aug 2016 |                    |         |               |
|                  | Airframe                                                                         |               | MSC |             |                 |     | O/C              |             |                    |         |               |
| 232907           | Jetphone - Removal / Installation                                                |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0             |
|                  | 500040-00-30                                                                     | 0815-7784     | AFL |             | 1112            |     |                  | 5           |                    |         | 0             |
|                  |                                                                                  |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | ICG           |
|                  | Airframe                                                                         |               | MSC |             |                 |     | O/C              |             |                    |         |               |
| 232910           | SATCOM Direct Router - Removal / Installation                                    |               | HRS |             | 828.6           |     |                  | 2217.5      |                    |         | 0             |
|                  | 1233-F-2191-10                                                                   | 1841          | AFL |             | 348             |     |                  | 769         |                    |         | 0             |
|                  |                                                                                  |               | MOS |             | 34.3            |     |                  | 02 Jul 2023 |                    |         |               |
|                  | Airframe                                                                         |               | MSC |             |                 |     | O/C              |             |                    |         |               |
| 233000           | 3G/4G Antenna - Removal / Installation                                           |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0             |
|                  | P18350-001                                                                       | 1835000689    | AFL |             | 1112            |     |                  | 5           |                    |         | 0             |
|                  |                                                                                  |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | GOGO AVIATION |
|                  | Airframe                                                                         |               | MSC |             |                 |     | O/C              |             |                    |         |               |

| ATA<br>U=Custom  | Description                                                            |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                            | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                     | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                 |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| 233003           | Passenger Address - Adjustment / Test                                  |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  |                                                                        |               | AFL |             | 315             |     |                  | 802         |                    | 0       |              |
|                  |                                                                        |               | MOS |             | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
|                  |                                                                        |               | MSC |             |                 | O/C |                  |             |                    |         |              |
| 233019           | Switching Node, Cabin 4 Rh Psu - Removal / Installation<br>GCMS-01-001 |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                              |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                              | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                       | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                   |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                            |               |     |             |                 |     |                  |             |                    |         |              |
| 233026           | Switching Node, Lh Fwd Ledge #1 - Removal / Installation |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  | GCMS-01-001                                              | 07193         | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  |                                                          |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | QUALITEL     |
|                  | Airframe                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 233027           | Switching Node, Lh Fwd Ledge #2 - Removal / Installation |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  | GCMS-01-001                                              | 07192         | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  |                                                          |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | QUALITEL     |
|                  | Airframe                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 233028           | Switching Node, Lh Mid Ledge #1 - Removal / Installation |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  | GCMS-01-001                                              | 07200         | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  |                                                          |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | QUALITEL     |
|                  | Airframe                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 233030           | Switching Node, Lh Aft Ledge #1 - Removal / Installation |               | HRS |             | 1269.1          |     |                  | 1777        |                    |         | 0            |
|                  | GCMS-01-001                                              | 20350         | AFL |             | 501             |     |                  | 616         |                    |         | 0            |
|                  |                                                          |               | MOS | TSN:6       | 50              |     |                  | 10 Mar 2022 |                    |         |              |
|                  | Airframe                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 233031           | Switching Node, Lh Aft Ledge #2 - Removal / Installation |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  | GCMS-01-001                                              | 07197         | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  |                                                          |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | QUALITEL     |
|                  | Airframe                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 233036           | Switching Node, Rh Aft Ledge #1 - Removal / Installation |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  | GCMS-01-001                                              | 07161         | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  |                                                          |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | QUALITEL     |
|                  | Airframe                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 233037           | Switching Node, Rh Aft Ledge #2 - Removal / Installation |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  | GCMS-01-001                                              | 07169         | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  |                                                          |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | QUALITEL     |
|                  | Airframe                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 233038           | Switching Node, Fwd Lh Closet - Removal / Installation   |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  | GCMS-01-001                                              | 06932         | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  |                                                          |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | QUALITEL     |
|                  | Airframe                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                         | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                     |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                              |               |     |             |                 |     |                  |             |                    |         |              |
| 233039           | Switching Node, Fwd Lav - Removal / Installation           |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  | GCMS-01-001                                                | 06982         | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  |                                                            |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | QUALITEL     |
|                  | Airframe                                                   |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 233041           | Switching Node, Aft Lav Toilet - Removal / Installation    |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  | GCMS-01-001                                                | 06984         | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  |                                                            |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | QUALITEL     |
|                  | Airframe                                                   |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 233042           | Switching Node, Galley - Removal / Installation            |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  | GCMS-01-001                                                | 06988         | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  |                                                            |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | QUALITEL     |
|                  | Airframe                                                   |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 233043           | Switching Node, Galley Annex - Removal / Installation      |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  | GCMS-01-001                                                | 07034         | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  |                                                            |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | QUALITEL     |
|                  | Airframe                                                   |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 233044           | Switching Node, Crew Rest - Removal / Installation         |               | HRS |             | 2961.7          |     |                  | 84.4        |                    |         | 0            |
|                  | GCMS-01-001                                                | 06357         | AFL |             | 1096            |     |                  | 21          |                    |         | 0            |
|                  |                                                            |               | MOS | TSN:16      | 120.3           |     |                  | 03 May 2016 |                    |         | QUALITEL     |
|                  | Airframe                                                   |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 233046           | Switching Node, Credenza #1 - Removal / Installation       |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  | GCMS-01-001                                                | 07027         | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  |                                                            |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | QUALITEL     |
|                  | Airframe                                                   |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 233047           | Switching Node, Credenza #2 - Removal / Installation       |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  | GCMS-01-001                                                | 06983         | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  |                                                            |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | QUALITEL     |
|                  | Airframe                                                   |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 233056           | Gcms Switch Node Closet (Aft R/H) - Removal / Installation |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  | GCMS-01-001                                                | 06969         | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  |                                                            |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | QUALITEL     |
|                  | Airframe                                                   |               | MSC |             |                 |     | O/C              |             |                    |         |              |

| ATA<br>U=Custom  | Description                                        |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                        | Serial Number |     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                 | SW            |     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                             |               |     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                      |               |     |             |                 |     |                  |             |                     |         |              |
| 233100           | Avds Node - Rh Fwd - Removal / Installation        |               | HRS |             | 3024.9          |     |                  | 21.2        |                     |         | 0            |
|                  | 100-0031-01                                        | 121712N0002   | AFL |             | 1110            |     |                  | 7           |                     |         | 0            |
|                  |                                                    |               | MOS |             | 123.5           |     |                  | 25 Jan 2016 |                     |         | INNOVATIVE   |
|                  | Airframe                                           |               | MSC |             |                 |     | O/C              |             |                     |         | ADVANTAGE    |
| 233102           | Avds Node - Rh Aft - Removal / Installation        |               | HRS |             | 3033.8          |     |                  | 12.3        |                     |         | 0            |
|                  | 100-0037-01                                        | 130325N0004   | AFL |             | 1112            |     |                  | 5           |                     |         | 0            |
|                  |                                                    |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                     |         | INNOVATIVE   |
|                  | Airframe                                           |               | MSC |             |                 |     | O/C              |             |                     |         | ADVANTAGE    |
| 233103           | Avds Node - Lh Fwd - Removal / Installation        |               | HRS |             | 3033.8          |     |                  | 12.3        |                     |         | 0            |
|                  | 100-0038-01                                        | 129162N0004   | AFL |             | 1112            |     |                  | 5           |                     |         | 0            |
|                  |                                                    |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                     |         | INNOVATIVE   |
|                  | Airframe                                           |               | MSC |             |                 |     | O/C              |             |                     |         | ADVANTAGE    |
| 233105           | Avds Node - Lh Aft - Removal / Installation        |               | HRS |             | 3033.8          |     |                  | 12.3        |                     |         | 0            |
|                  | 100-0038-01                                        | 129478N0007   | AFL |             | 1112            |     |                  | 5           |                     |         | 0            |
|                  |                                                    |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                     |         | INNOVATIVE   |
|                  | Airframe                                           |               | MSC |             |                 |     | O/C              |             |                     |         | ADVANTAGE    |
| 233106           | Avds Node - Baggage Upper - Removal / Installation |               | HRS |             | 960.6           |     |                  | 2085.5      |                     |         | 0            |
|                  | 100-0024-01                                        | 130432N0001   | AFL |             | 377             |     |                  | 740         |                     |         | 0            |
|                  |                                                    |               | MOS |             | 39.1            |     |                  | 09 Feb 2023 |                     |         |              |
|                  | Airframe                                           |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| 233107           | Avds Node - Baggage Lower - Removal / Installation |               | HRS |             | 960.6           |     |                  | 2085.5      |                     |         | 0            |
|                  | 100-0024-01                                        | 130432N0006   | AFL |             | 377             |     |                  | 740         |                     |         | 0            |
|                  |                                                    |               | MOS |             | 39.1            |     |                  | 09 Feb 2023 |                     |         |              |
|                  | Airframe                                           |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| 233400           | Cabin Entertainment Audio - Adjustment / Test      |               | HRS |             | 730.5           |     |                  | 2315.6      |                     |         | 0            |
|                  |                                                    |               | AFL |             | 315             |     |                  | 802         |                     |         | 0            |
|                  |                                                    |               | MOS |             | 28.7            |     |                  | 21 Dec 2023 |                     |         |              |
|                  | Airframe                                           |               | MSC |             |                 |     | O/C              |             |                     |         |              |

| ATA<br>U=Custom  | Description                                                                  |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                  | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                           | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                       |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| 233500           | Cabin Entertainment Video - Adjustment Test                                  |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  |                                                                              |               | AFL |             | 315             |     |                  | 802         |                    |         | 0            |
|                  |                                                                              |               | MOS |             | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
|                  |                                                                              |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                              |               |     |             |                 |     |                  |             |                    |         |              |
| 233700           | Aft / Forward Facing Belly Camera - Removal / Installation                   |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 100-2689-03                                                                  | 1149638       | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                              |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                              |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                              |               |     |             |                 |     |                  |             |                    |         |              |
| 233702           | Fin CAP Camera - Removal / Installation                                      |               | HRS |             | 1452            |     |                  | 1594.1      |                    |         | 0            |
|                  | 100-2687-03                                                                  | 1142062       | AFL |             | 570             |     |                  | 547         |                    |         | 0            |
|                  |                                                                              |               | MOS |             | 63.9            |     |                  | 14 Jan 2021 |                    |         |              |
|                  |                                                                              |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                              |               |     |             |                 |     |                  |             |                    |         |              |
| 233704           | Video Control Unit - Removal / Installation                                  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 100-2415-01                                                                  | 1149256       | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                              |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                              |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                              |               |     |             |                 |     |                  |             |                    |         |              |
| 233706           | Video Distribution Module - Removal / Installation                           |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | MSM2925-01-1                                                                 | 121400073     | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                              |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                              |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                              |               |     |             |                 |     |                  |             |                    |         |              |
| 233708           | Camera Systems - Operational Check                                           |               | HRS |             | 1452            |     |                  | 1594.1      |                    |         | 0            |
|                  |                                                                              |               | AFL |             | 570             |     |                  | 547         |                    |         | 0            |
|                  |                                                                              |               | MOS |             | 63.9            |     |                  | 14 Jan 2021 |                    |         |              |
|                  |                                                                              |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                              |               |     |             |                 |     |                  |             |                    |         |              |
| 234300           | Call System - Adjustment / Test                                              |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                              |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                              |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                              |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                              |               |     |             |                 |     |                  |             |                    |         |              |
| 235000           | Typical Passenger Service Unit Speaker (Left No. 1) - Removal / Installation |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  |                                                                              |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  | 106508-630-4G6001                                                            | 201834        | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | ALTO         |
|                  |                                                                              |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                              |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                   |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|-------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                                                   | Serial Number |     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                                            | SW            |     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                                        |               |     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                                                 |               |     |             |                 |     |                  |             |                     |         |              |
| 235001           | Typical Passenger Service Unit Speaker (Left No. 2) - Removal / Installation  |               | HRS |             | 3033.8          |     |                  | 12.3        |                     |         | 0            |
|                  |                                                                               |               | AFL |             | 1112            |     |                  | 5           |                     |         | 0            |
|                  | 106508-630-4G6001                                                             | 201835        | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                     |         | ALTO         |
|                  |                                                                               |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                               |               |     |             |                 |     |                  |             |                     |         |              |
| 235002           | Typical Passenger Service Unit Speaker (Left No. 3) - Removal / Installation  |               | HRS |             | 3033.8          |     |                  | 12.3        |                     |         | 0            |
|                  |                                                                               |               | AFL |             | 1112            |     |                  | 5           |                     |         | 0            |
|                  | 106508-630-4G6001                                                             | 201836        | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                     |         | ALTO         |
|                  |                                                                               |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                               |               |     |             |                 |     |                  |             |                     |         |              |
| 235006           | Typical Passenger Service Unit Speaker (Right No. 1) - Removal / Installation |               | HRS |             | 3033.8          |     |                  | 12.3        |                     |         | 0            |
|                  |                                                                               |               | AFL |             | 1112            |     |                  | 5           |                     |         | 0            |
|                  | 106508-630-4G6001                                                             | 201837        | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                     |         | ALTO         |
|                  |                                                                               |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                               |               |     |             |                 |     |                  |             |                     |         |              |
| 235007           | Typical Passenger Service Unit Speaker (Right No. 2) - Removal / Installation |               | HRS |             | 3033.8          |     |                  | 12.3        |                     |         | 0            |
|                  |                                                                               |               | AFL |             | 1112            |     |                  | 5           |                     |         | 0            |
|                  | 106508-630-4G6001                                                             | 201838        | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                     |         | ALTO         |
|                  |                                                                               |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                               |               |     |             |                 |     |                  |             |                     |         |              |
| 235008           | Typical Passenger Service Unit Speaker (Right No. 3) - Removal / Installation |               | HRS |             | 3033.8          |     |                  | 12.3        |                     |         | 0            |
|                  |                                                                               |               | AFL |             | 1112            |     |                  | 5           |                     |         | 0            |
|                  | 106508-630-4G6001                                                             | 201839        | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                     |         | ALTO         |
|                  |                                                                               |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                               |               |     |             |                 |     |                  |             |                     |         |              |
| 235012           | PA/Stereo Speaker Crew Rest - Removal / Installation                          |               | HRS |             | 3033.8          |     |                  | 12.3        |                     |         | 0            |
|                  |                                                                               |               | AFL |             | 1112            |     |                  | 5           |                     |         | 0            |
|                  | 106508-630-4G6001                                                             | 201840        | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                     |         | ALTO         |
|                  |                                                                               |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                               |               |     |             |                 |     |                  |             |                     |         |              |
| 235013           | Forward Cabin Speaker AMP - Removal / Installation                            |               | HRS |             | 1269.1          |     |                  | 1777        |                     |         | 0            |
|                  |                                                                               |               | AFL |             | 501             |     |                  | 616         |                     |         | 0            |
|                  | 106500-0600-10000                                                             | 071751        | MOS | TSN:5       | 50              |     |                  | 10 Mar 2022 |                     |         |              |
|                  |                                                                               |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                               |               |     |             |                 |     |                  |             |                     |         |              |



| ATA<br>U=Custom  | Description                                                   |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|---------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                   | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                            | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                        |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                 |               |     |             |                 |     |                  |             |                    |         |              |
| 235014           | Aft Cabin Speaker AMP - Removal / Installation                |               | HRS |             | 994.2           |     |                  | 2051.9      |                    |         | 0            |
|                  | 106500-0600-10000                                             | 071326        | AFL |             | 392             |     |                  | 725         |                    |         | 0            |
|                  |                                                               |               | MOS | TSN:45      | 40.9            |     |                  | 13 Dec 2022 |                    |         |              |
|                  | Airframe                                                      |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 235019           | Subwoofer Speaker (Divan Center) - Removal / Installation     |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  |                                                               |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  | 106511-565-4G6001                                             | 270538        | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | ALTO         |
|                  | Airframe                                                      |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 235021           | Subwoofer Speaker (Right Seat No. 2) - Removal / Installation |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  |                                                               |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  | 106511-565-4G6001                                             | 270536        | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | ALTO         |
|                  | Airframe                                                      |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 235023           | Subwoofer Speaker (Left Seat No. 4) - Removal / Installation  |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  |                                                               |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  | 106511-565-4G6001                                             | 270535        | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | ALTO         |
|                  | Airframe                                                      |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 235031           | Lavatory Speaker (Forward Lavatory) - Removal / Installation  |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  |                                                               |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  | 106508-630-4G6001                                             | 201833        | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | ALTO         |
|                  | Airframe                                                      |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 235032           | Lavatory Speaker (Aft Lavatory) - Removal / Installation      |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  |                                                               |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  | 106508-630-4G6001                                             | 201841        | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | ALTO         |
|                  | Airframe                                                      |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 235035           | Galley Speaker (Forward Galley) - Removal / Installation      |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  | DT-PA2N                                                       | 144219023     | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  |                                                               |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | DT SYSTEMS   |
|                  | Airframe                                                      |               | MSC |             |                 |     | O/C              |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                           |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-----------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                           | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                    | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                         |               |     |             |                 |     |                  |             |                    |         |              |
| 235041           | Right Divan Forward Audio Video Switch Panel - Removal / Installation |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  |                                                                       |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  | RCO36790                                                              | 0933          | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | RCO          |
|                  |                                                                       |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| 235043           | Right Divan Aft Audio Video Switch Panel - Removal / Installation     |               | HRS |             | 2413.8          |     |                  | 632.3       |                    |         | 0            |
|                  |                                                                       |               | AFL |             | 949             |     |                  | 168         |                    |         | 0            |
|                  | RCO36790                                                              | 2271          | MOS |             | 98.6            |     |                  | 23 Feb 2018 |                    |         | RCO          |
|                  |                                                                       |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| 235200           | Audio Control Panel (Pilot) - Removal / Installation                  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 7511900-90302                                                         | 1504F695      | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                       |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                       |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| 235201           | Audio Control Panel (Copilot) - Removal / Installation                |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 7511900-90302                                                         | 1408E941      | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                       |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                       |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| 235202           | Audio Control Panel (Observer) - Removal / Installation               |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 7511900-90302                                                         | 1504F776      | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                       |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                       |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| 235206           | Audio Control Panel Sidetone - Adjustment                             |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                       |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                       |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                       |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| 235307           | Audio Integrating System Input / Output Device - Operational Check    |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                       |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                       |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                       |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| 235308           | Oxygen Mask Microphone - Operational Check                            |               | HRS |             | 1452            |     |                  | 1594.1      |                    |         | 0            |
|                  |                                                                       |               | AFL |             | 570             |     |                  | 547         |                    |         | 0            |
|                  |                                                                       |               | MOS |             | 64              |     |                  | 12 Jan 2021 |                    |         |              |
|                  |                                                                       |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                       |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                         |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------|---------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                  | Part Number                                                         | Serial Number |                                    |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position | HW                                                                  | SW            |                                    |             |                 |     |                  |             |                    |             | Manufacturer |
|                  | MM Ref                                                              |               |                                    |             |                 |     |                  |             |                    |             | Date Type    |
|                  | Ops Number(s)                                                       |               |                                    |             |                 |     |                  |             |                    |             |              |
| 235400           | Network / Audio Interface Module (No. 1) - Removal / Installation   |               | HRS                                |             | 562.4           |     |                  | 2483.7      |                    |             | 0            |
|                  |                                                                     |               | AFL                                |             | 217             |     |                  | 900         |                    |             | 0            |
|                  | 60000091-918                                                        | 15091365      | MOS                                |             | 16.8            |     |                  | 16 Dec 2024 |                    |             |              |
|                  |                                                                     |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                     |               |                                    |             |                 |     |                  |             |                    |             |              |
| 235401           | Network / Audio Interface Module (No. 2) - Removal / Installation   |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                     |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  | 60000091-918                                                        | 15011100      | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                     |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                     |               |                                    |             |                 |     |                  |             |                    |             |              |
| 236130           | Static Discharging (Left Wing) - Functional Check                   |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                     |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                     |               | MOS                                |             | 28.7            |     | 48               | 21 Dec 2023 | 31 Dec 2027        | 31 Jan 2028 |              |
|                  |                                                                     |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                     |               |                                    |             |                 |     |                  |             |                    |             |              |
| 052013           |                                                                     |               |                                    |             |                 |     |                  |             |                    |             |              |
| 236131           | Static Discharging (Right Wing) - Functional Check                  |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                     |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                     |               | MOS                                |             | 28.7            |     | 48               | 21 Dec 2023 | 31 Dec 2027        | 31 Jan 2028 |              |
|                  |                                                                     |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                     |               |                                    |             |                 |     |                  |             |                    |             |              |
| 052013           |                                                                     |               |                                    |             |                 |     |                  |             |                    |             |              |
| 236132           | Static Discharging (Left Horizontal Stablizer) - Functional Check   |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                     |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                     |               | MOS                                |             | 28.7            |     | 48               | 21 Dec 2023 | 31 Dec 2027        | 31 Jan 2028 |              |
|                  |                                                                     |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                     |               |                                    |             |                 |     |                  |             |                    |             |              |
| 052013           |                                                                     |               |                                    |             |                 |     |                  |             |                    |             |              |
| 236133           | Static Discharging (Right Horizontal Stablizer) - Functional Check  |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                     |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                     |               | MOS                                |             | 28.7            |     | 48               | 21 Dec 2023 | 31 Dec 2027        | 31 Jan 2028 |              |
|                  |                                                                     |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                     |               |                                    |             |                 |     |                  |             |                    |             |              |
| 052013           |                                                                     |               |                                    |             |                 |     |                  |             |                    |             |              |
| 236134           | Static Discharging (Center Horizontal Stablizer) - Functional Check |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                     |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                     |               | MOS                                |             | 28.7            |     | 48               | 21 Dec 2023 | 31 Dec 2027        | 31 Jan 2028 |              |
|                  |                                                                     |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                     |               |                                    |             |                 |     |                  |             |                    |             |              |
| 052013           |                                                                     |               |                                    |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom  | Description                                                        |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------|--------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                  | Part Number                                                        | Serial Number |                                    |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position | HW                                                                 | SW            |                                    |             |                 |     |                  |             |                    |             | Manufacturer |
|                  | MM Ref                                                             |               |                                    |             |                 |     |                  |             |                    |             | Date Type    |
|                  | Ops Number(s)                                                      |               |                                    |             |                 |     |                  |             |                    |             |              |
| 236135           | Static Discharging (Tail Cone) - Functional Check                  |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                    |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                    |               | MOS                                |             | 28.7            |     | 48               | 21 Dec 2023 | 31 Dec 2027        | 31 Jan 2028 |              |
|                  | Airframe                                                           |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
|                  |                                                                    | 052013        |                                    |             |                 |     |                  |             |                    |             |              |
| 237001           | Bulkhead Monitor (Forward Bulkhead Right) - Removal / Installation |               | HRS                                |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                  |                                                                    |               | AFL                                |             | 52              |     |                  | 1065        |                    |             | 0            |
|                  | DLD-2606D                                                          | GB0033        | MOS                                |             | 4.8             |     |                  | 18 Dec 2025 |                    |             |              |
|                  | Airframe                                                           |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| 237002           | Bulkhead Monitor (Forward Bulkhead Left) - Removal / Installation  |               | HRS                                |             | 3033.8          |     |                  | 12.3        |                    |             | 0            |
|                  |                                                                    |               | AFL                                |             | 1112            |     |                  | 5           |                    |             | 0            |
|                  | DLD-2602-01                                                        | AD0050        | MOS                                |             | 124.2           |     |                  | 05 Jan 2016 |                    |             | ACS          |
|                  | Airframe                                                           |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| 237006           | Seat Armrest Monitor (Left Seat No. 1) - Removal / Installation    |               | HRS                                | TSN:271.6   | 2762.2          |     |                  | 283.9       |                    |             | 0            |
|                  |                                                                    |               | AFL                                | TSN:71      | 1041            |     |                  | 76          |                    |             | 0            |
|                  | 1200-128                                                           | 15090177      | MOS                                | TSN:11      | 112.9           |     |                  | 14 Dec 2016 |                    |             | ROSEN        |
|                  | Airframe                                                           |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| 237008           | Seat Armrest Monitor (Left Seat No. 2) - Removal / Installation    |               | HRS                                | TSN:271.6   | 2762.2          |     |                  | 283.9       |                    |             | 0            |
|                  |                                                                    |               | AFL                                | TSN:71      | 1041            |     |                  | 76          |                    |             | 0            |
|                  | 1200-129                                                           | 15090213      | MOS                                | TSN:11      | 112.9           |     |                  | 14 Dec 2016 |                    |             | ROSEN        |
|                  | Airframe                                                           |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| 237014           | Seat Armrest Monitor (Right Seat No. 1) - Removal / Installation   |               | HRS                                | TSN:271.6   | 2762.2          |     |                  | 283.9       |                    |             | 0            |
|                  |                                                                    |               | AFL                                | TSN:71      | 1041            |     |                  | 76          |                    |             | 0            |
|                  | 1200-129                                                           | 15090209      | MOS                                | TSN:11      | 112.9           |     |                  | 14 Dec 2016 |                    |             | ROSEN        |
|                  | Airframe                                                           |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| 237015           | Seat Armrest Monitor (Right Seat No. 2) - Removal / Installation   |               | HRS                                | TSN:271.6   | 2762.2          |     |                  | 283.9       |                    |             | 0            |
|                  |                                                                    |               | AFL                                | TSN:71      | 1041            |     |                  | 76          |                    |             | 0            |
|                  | 1200-128                                                           | 15090360      | MOS                                | TSN:11      | 112.9           |     |                  | 14 Dec 2016 |                    |             | ROSEN        |
|                  | Airframe                                                           |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |

| ATA<br>U=Custom  | Description                                                  |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|--------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                  | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                           | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                       |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                |               |     |             |                 |     |                  |             |                    |         |              |
| 237020           | Crew Compartment Monitor - Removal / Installation            |               | HRS |             | 2345.1          |     |                  | 701         |                    |         | 0            |
|                  | DLD-1701D-01                                                 |               | AFL |             | 936             |     |                  | 181         |                    |         | 0            |
|                  |                                                              |               | MOS | TSN:4       | 97.1            |     |                  | 09 Apr 2018 |                    |         | ACS          |
|                  |                                                              |               | MSC |             |                 | O/C |                  |             |                    |         |              |
| 237023           | Dual Blu-Ray DVD Player #1 - Removal / Installation          |               | HRS |             | 3024.9          |     |                  | 21.2        |                    |         | 0            |
|                  | 0602-205                                                     |               | AFL |             | 1110            |     |                  | 7           |                    |         | 0            |
|                  |                                                              |               | MOS | TSN:1       | 123.5           |     |                  | 27 Jan 2016 |                    |         | ROSEN        |
|                  |                                                              |               | MSC |             |                 | O/C |                  |             |                    |         |              |
| 237025           | Vestibule Touch Screen Switch Panel - Removal / Installation |               | HRS |             | 495.8           |     |                  | 2550.3      |                    |         | 0            |
|                  |                                                              |               | AFL |             | 200             |     |                  | 917         |                    |         | 0            |
|                  | DLT-0571D                                                    |               | MOS |             | 15.2            |     |                  | 04 Feb 2025 |                    |         |              |
|                  |                                                              |               | MSC |             |                 | O/C |                  |             |                    |         |              |
| 237026           | Galley T/S Monitor - Removal / Installation                  |               | HRS |             | 216.9           |     |                  | 2829.2      |                    |         | 0            |
|                  | DLT-1011D-01                                                 |               | AFL |             | 79              |     |                  | 1038        |                    |         | 0            |
|                  |                                                              |               | MOS |             | 7.2             |     |                  | 04 Oct 2025 |                    |         |              |
|                  |                                                              |               | MSC |             |                 | O/C |                  |             |                    |         |              |
| 237033           | Rh Mid Cabin Monitor Bezel - Removal / Installation          |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  | 3201-961                                                     |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  |                                                              |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | ROSEN        |
|                  |                                                              |               | MSC |             |                 | O/C |                  |             |                    |         |              |
| 237039           | Monitor Cover, 32 Inch - Removal / Installation              |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  | 0500-861                                                     |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  |                                                              |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | ROSEN        |
|                  |                                                              |               | MSC |             |                 | O/C |                  |             |                    |         |              |
| 237040           | Monitor Swivel Mount, 32 Inch - Removal / Installation       |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  | 3201-860                                                     |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  |                                                              |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | ROSEN        |
|                  |                                                              |               | MSC |             |                 | O/C |                  |             |                    |         |              |
| 237081           | Stateroom Monitor - Removal / Installation                   |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  | 3201-201                                                     |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  |                                                              |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | ROSEN        |
|                  |                                                              |               | MSC |             |                 | O/C |                  |             |                    |         |              |
| Airframe         |                                                              |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                       |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W                             | Next Due<br>(* =Adj) | Max Due | Avg Man Hrs  |
|------------------|-------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|--------------------------------------|----------------------|---------|--------------|
|                  | Part Number                                                       | Serial Number |                                    |             |                 |     |                  |                                      |                      |         | Approx Price |
| Logbook Position | HW                                                                | SW            |                                    |             |                 |     |                  |                                      |                      |         | Manufacturer |
|                  | MM Ref                                                            |               |                                    |             |                 |     |                  |                                      |                      |         | Date Type    |
|                  | Ops Number(s)                                                     |               |                                    |             |                 |     |                  |                                      |                      |         |              |
| 237082           | Monitor Swivel, Stateroom Credenza - Removal / Installation       |               | HRS                                |             | 3033.8          |     |                  | 12.3                                 |                      |         | 0            |
|                  |                                                                   |               | AFL                                |             | 1112            |     |                  | 5                                    |                      |         | 0            |
|                  | 0500-860                                                          | 12060192      | MOS                                |             | 124.2           |     |                  | 05 Jan 2016                          |                      |         | ROSEN        |
|                  |                                                                   |               | MSC                                |             |                 |     | O/C              |                                      |                      |         |              |
| Airframe         |                                                                   |               |                                    |             |                 |     |                  |                                      |                      |         |              |
| 237098           | Right Aft Remote Monitor Electronics Box - Removal / Installation |               | HRS                                |             | 3033.8          |     |                  | 12.3                                 |                      |         | 0            |
|                  |                                                                   |               | AFL                                |             | 1112            |     |                  | 5                                    |                      |         | 0            |
|                  | 0700-105                                                          | 15050272      | MOS                                |             | 124.2           |     |                  | 05 Jan 2016                          |                      |         | ROSEN        |
|                  |                                                                   |               | MSC                                |             |                 |     | O/C              |                                      |                      |         |              |
| Airframe         |                                                                   |               |                                    |             |                 |     |                  |                                      |                      |         |              |
| 237200           | Cockpit Voice Recorder - Removal / Installation                   |               | HRS                                |             | 2120.8          |     |                  | 925.3                                |                      |         | 0            |
|                  | 1606-01-00                                                        | 1166          | AFL                                |             | 861             |     |                  | 256                                  |                      |         | 0            |
|                  |                                                                   |               | MOS                                |             | 86              |     |                  | 11 Mar 2019                          |                      |         |              |
|                  |                                                                   |               | MSC                                |             |                 |     | O/C              |                                      |                      |         |              |
| Airframe         |                                                                   |               |                                    |             |                 |     |                  |                                      |                      |         |              |
| 237202           | Cockpit Voice Recorder System - Operational Check                 |               | HRS                                |             | 137             |     |                  | 2909.1                               |                      |         | 0            |
|                  |                                                                   |               | AFL                                |             | 52              |     |                  | 1065                                 |                      |         | 0            |
|                  |                                                                   |               | MOS                                |             | 5.3             | -4  | 12               | 03 Dec 2025 30 Nov 2026* 31 Dec 2026 |                      |         |              |
|                  |                                                                   |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |                                      |                      |         |              |
| Airframe         |                                                                   |               |                                    |             |                 |     |                  |                                      |                      |         |              |
| 237203           | Remote Cockpit Control Unit - Removal / Installation              |               | HRS                                |             | 3046.1          |     |                  | 0                                    |                      |         | 0            |
|                  | 1642-110-02,200400                                                | 724           | AFL                                |             | 1117            |     |                  | 0                                    |                      |         | 0            |
|                  |                                                                   |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015                          |                      |         |              |
|                  |                                                                   |               | MSC                                |             |                 |     | O/C              |                                      |                      |         |              |
| Airframe         |                                                                   |               |                                    |             |                 |     |                  |                                      |                      |         |              |
| 237205           | Cockpit AREA Microphone - Removal / Installation                  |               | HRS                                |             | 3046.1          |     |                  | 0                                    |                      |         | 0            |
|                  | 16301-02                                                          | 5197          | AFL                                |             | 1117            |     |                  | 0                                    |                      |         | 0            |
|                  |                                                                   |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015                          |                      |         |              |
|                  |                                                                   |               | MSC                                |             |                 |     | O/C              |                                      |                      |         |              |
| Airframe         |                                                                   |               |                                    |             |                 |     |                  |                                      |                      |         |              |
| 237211           | Cockpit Voice Recorder Impact Switch - Removal / Installation     |               | HRS                                |             | 3046.1          |     |                  | 0                                    |                      |         | 0            |
|                  |                                                                   |               | AFL                                |             | 1117            |     |                  | 0                                    |                      |         | 0            |
|                  | 1159SCAV402-2                                                     | 5227          | MOS                                |             | 128.6           |     |                  | 24 Aug 2015                          |                      |         |              |
|                  |                                                                   |               | MSC                                |             |                 |     | O/C              |                                      |                      |         |              |
| Airframe         |                                                                   |               |                                    |             |                 |     |                  |                                      |                      |         |              |

| ATA<br>U=Custom  | Description                                                                              |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------|------------------------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                  | Part Number                                                                              | Serial Number |                                    |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position | HW                                                                                       | SW            |                                    |             |                 |     |                  |             |                    |             | Manufacturer |
|                  | MM Ref                                                                                   |               |                                    |             |                 |     |                  |             |                    |             | Date Type    |
|                  | Ops Number(s)                                                                            |               |                                    |             |                 |     |                  |             |                    |             |              |
| 237213           | Cockpit Voice Recorder Impact Switch - Operational<br>Check                              |               | HRS                                |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                  |                                                                                          |               | AFL                                |             | 52              |     |                  | 1065        |                    |             | 0            |
|                  |                                                                                          |               | MOS                                |             | 5.3             |     | 84               | 03 Dec 2025 | 31 Dec 2032        | 31 Jan 2033 |              |
|                  |                                                                                          |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                          |               |                                    |             |                 |     |                  |             |                    |             |              |
| 237214           | Cockpit Voice Recorder Underwater Locator Beacon -<br>Removal / Installation<br>DK120/90 |               | HRS                                |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                  |                                                                                          |               | AFL                                |             | 52              |     |                  | 1065        |                    |             | 0            |
|                  |                                                                                          |               | MOS                                | TSN:2       | 5.5             |     |                  | 27 Nov 2025 |                    |             |              |
|                  |                                                                                          |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                          |               |                                    |             |                 |     |                  |             |                    |             |              |
| 237216           | Cockpit Voice Recorder Underwater Locator Beacon -<br>Operational Check                  |               | HRS                                |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                  |                                                                                          |               | AFL                                |             | 52              |     |                  | 1065        |                    |             | 0            |
|                  |                                                                                          |               | MOS                                |             | 5.5             | 24  | 24               | 27 Nov 2025 | 31 Dec 2027*       | 31 Jan 2028 |              |
|                  |                                                                                          |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                          |               |                                    |             |                 |     |                  |             |                    |             |              |
| 052025           |                                                                                          |               |                                    |             |                 |     |                  |             |                    |             |              |
| 237217           | Cockpit Voice Recorder Underwater Locator Beacon -<br>Cleaning                           |               | HRS                                |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                  |                                                                                          |               | AFL                                |             | 52              |     |                  | 1065        |                    |             | 0            |
|                  |                                                                                          |               | MOS                                |             | 5.5             | 24  | 24               | 27 Nov 2025 | 31 Dec 2027*       | 31 Jan 2028 |              |
|                  |                                                                                          |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                          |               |                                    |             |                 |     |                  |             |                    |             |              |
| 237220           | Cockpit Voice Recorder Underwater Locator Beacon<br>Battery - Discard<br>DK120/90        |               | HRS                                |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                  |                                                                                          |               | AFL                                |             | 52              |     |                  | 1065        |                    |             | 0            |
|                  |                                                                                          |               | MOS                                |             | 5.5             |     | 84               | 27 Nov 2025 | 31 Aug 2031        |             |              |
|                  |                                                                                          |               | [End Of Month Item]                |             |                 |     |                  |             |                    |             |              |
| EXPIRATION       |                                                                                          |               |                                    |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                          |               |                                    |             |                 |     |                  |             |                    |             |              |
| 237222           | Cockpit Voice Recorder Underwater Locator Beacon -<br>Battery Replacement<br>DK120/90    |               | HRS                                |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                  |                                                                                          |               | AFL                                |             | 52              |     |                  | 1065        |                    |             | 0            |
|                  |                                                                                          |               | MOS                                | TSN:2       | 5.5             |     |                  | 27 Nov 2025 |                    |             |              |
|                  |                                                                                          |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                          |               |                                    |             |                 |     |                  |             |                    |             |              |
| 237223           | Cockpit Voice Recorder Underwater Locator Beacon<br>Battery - Functional Check           |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                          |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                          |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                          |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                          |               |                                    |             |                 |     |                  |             |                    |             |              |

24 - Electrical Power

| ATA<br>U=Custom  | Description                                                     |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W                 | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-----------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|--------------------------|--------------------|---------|--------------|
|                  | Part Number                                                     | Serial Number |                                    |             |                 |     |                  |                          |                    |         | Approx Price |
| Logbook Position | HW                                                              | SW            |                                    |             |                 |     |                  |                          |                    |         | Manufacturer |
|                  | MM Ref                                                          |               |                                    |             |                 |     |                  |                          |                    |         | Date Type    |
|                  | Ops Number(s)                                                   |               |                                    |             |                 |     |                  |                          |                    |         |              |
| 240010           | Cockpit Circuit Breaker Panel - Removal / Installation          |               | HRS                                |             | 3046.1          |     |                  | 0                        |                    |         | 0            |
|                  | 134TS11Y02                                                      | 0260          | AFL                                |             | 1117            |     |                  | 0                        |                    |         | 0            |
|                  |                                                                 |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015              |                    |         |              |
|                  | Airframe                                                        |               | MSC                                |             |                 |     | O/C              |                          |                    |         |              |
| 241206           | Idg Oil Transfer Tubes / Fittings (Left) - Detailed Inspection  |               | HRS                                |             | 3046.1          |     |                  | 0                        |                    |         | 0            |
|                  |                                                                 |               | AFL                                |             | 1117            |     |                  | 0                        |                    |         | 0            |
|                  |                                                                 |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015              |                    |         |              |
|                  | Airframe                                                        |               | MSC                                |             |                 |     | O/C              |                          |                    |         |              |
| 241207           | Idg Oil Transfer Tubes / Fittings (Right) - Detailed Inspection |               | HRS                                |             | 3046.1          |     |                  | 0                        |                    |         | 0            |
|                  |                                                                 |               | AFL                                |             | 1117            |     |                  | 0                        |                    |         | 0            |
|                  |                                                                 |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015              |                    |         |              |
|                  | Airframe                                                        |               | MSC                                |             |                 |     | O/C              |                          |                    |         |              |
| 241212           | Idg Oil Cooler and Lines (Left) - General Visual Inspection     |               | HRS                                |             | 137             |     |                  | 2909.1                   |                    |         | 0            |
|                  |                                                                 |               | AFL                                |             | 52              |     |                  | 1065                     |                    |         | 0            |
|                  |                                                                 |               | MOS                                |             | 5.3             | -5  | 12               | 03 Dec 2025 30 Nov 2026* | 31 Dec 2026        |         |              |
|                  | Airframe                                                        |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |                          |                    |         |              |
| 241213           | Idg Oil Cooler and Lines (Right) - General Visual Inspection    |               | HRS                                |             | 137             |     |                  | 2909.1                   |                    |         | 0            |
|                  |                                                                 |               | AFL                                |             | 52              |     |                  | 1065                     |                    |         | 0            |
|                  |                                                                 |               | MOS                                |             | 5.3             | -5  | 12               | 03 Dec 2025 30 Nov 2026* | 31 Dec 2026        |         |              |
|                  | Airframe                                                        |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |                          |                    |         |              |
| 242100           | Integrated Drive Generator (Left) - Removal / Installation      |               | HRS                                | TSN:2051.9  | 994.2           |     |                  | 2051.9                   |                    |         | 0            |
|                  | 1159SCAV500-3                                                   | 1932          | AFL                                | TSN:725     | 392             |     |                  | 725                      |                    |         | 0            |
|                  |                                                                 |               | MOS                                | TSN:88      | 41.2            |     |                  | 06 Dec 2022              |                    |         |              |
|                  | Airframe                                                        |               | MSC                                |             |                 |     | O/C              |                          |                    |         |              |
| 242102           | Idg - Detailed Inspection                                       |               | HRS                                |             | 3046.1          |     |                  | 0                        |                    |         | 0            |
|                  |                                                                 |               | AFL                                |             | 1117            |     |                  | 0                        |                    |         | 0            |
|                  |                                                                 |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015              |                    |         |              |
|                  | Airframe                                                        |               | MSC                                |             |                 |     | O/C              |                          |                    |         |              |
| 242103           | Integrated Drive Generator (Right) - Removal / Installation     |               | HRS                                | TSN:2051.9  | 994.2           |     |                  | 2051.9                   |                    |         | 0            |
|                  | 1159SCAV500-3                                                   | 1977          | AFL                                | TSN:725     | 392             |     |                  | 725                      |                    |         | 0            |
|                  |                                                                 |               | MOS                                | TSN:88      | 41.1            |     |                  | 08 Dec 2022              |                    |         |              |
|                  | Airframe                                                        |               | MSC                                |             |                 |     | O/C              |                          |                    |         |              |



| ATA<br>U=Custom  | Description                                                                          |               | UOM            | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|--------------------------------------------------------------------------------------|---------------|----------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                          | Serial Number |                |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                                   | SW            |                |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                               |               |                |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                                        |               |                |             |                 |     |                  |             |                    |         |              |
| 242106           | AC Generation: Engine Generators - Operational Check                                 |               | HRS            |             | 994.2           |     |                  | 2051.9      |                    |         | 0            |
|                  |                                                                                      |               | AFL            |             | 392             |     |                  | 725         |                    |         | 0            |
|                  |                                                                                      |               | MOS            |             | 40.9            |     |                  | 15 Dec 2022 |                    |         |              |
|                  | Airframe                                                                             |               | MSC            |             |                 |     | O/C              |             |                    |         |              |
| 242107           | Idg Disconnect System (Left) - Operational Test                                      |               | HRS            |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                      |               | AFL            |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                      |               | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                                             |               | MSC            |             |                 |     | O/C              |             |                    |         |              |
| 242108           | Idg Disconnect System (Right) - Operational Test                                     |               | HRS            |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                      |               | AFL            |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                      |               | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                                             |               | MSC            |             |                 |     | O/C              |             |                    |         |              |
| 242109           | Idg (Left) - Detailed Inspection                                                     |               | HRS            |             | 137             |     | 600              | 2909.1      | 3509.1             | 3559.1  | 0            |
|                  |                                                                                      |               | AFL            |             | 52              |     |                  | 1065        |                    |         | 0            |
|                  |                                                                                      |               | MOS            |             | 5.3             |     |                  | 03 Dec 2025 |                    |         |              |
|                  | Airframe                                                                             |               | [HRS: +50/-50] |             |                 |     |                  |             |                    |         |              |
|                  |                                                                                      | 052001        |                |             |                 |     |                  |             |                    |         |              |
| 242110           | Idg (Right) - Detailed Inspection                                                    |               | HRS            |             | 137             |     | 600              | 2909.1      | 3509.1             | 3559.1  | 0            |
|                  |                                                                                      |               | AFL            |             | 52              |     |                  | 1065        |                    |         | 0            |
|                  |                                                                                      |               | MOS            |             | 5.3             |     |                  | 03 Dec 2025 |                    |         |              |
|                  | Airframe                                                                             |               | [HRS: +50/-50] |             |                 |     |                  |             |                    |         |              |
|                  |                                                                                      | 052001        |                |             |                 |     |                  |             |                    |         |              |
| 242111           | Idg (Left) - Oil Level Check                                                         |               | HRS            |             | 137             |     |                  | 2909.1      |                    |         | 0            |
|                  |                                                                                      |               | AFL            |             | 52              |     |                  | 1065        |                    |         | 0            |
|                  |                                                                                      |               | MOS            |             | 5.3             |     |                  | 03 Dec 2025 |                    |         |              |
|                  | Airframe                                                                             |               | MSC            |             |                 |     | O/C              |             |                    |         |              |
| 242112           | Idg (Right) - Oil Level Check                                                        |               | HRS            |             | 137             |     |                  | 2909.1      |                    |         | 0            |
|                  |                                                                                      |               | AFL            |             | 52              |     |                  | 1065        |                    |         | 0            |
|                  |                                                                                      |               | MOS            |             | 5.3             |     |                  | 03 Dec 2025 |                    |         |              |
|                  | Airframe                                                                             |               | MSC            |             |                 |     | O/C              |             |                    |         |              |
| 242117           | Idg Oil Scavenge Filter Differential Pressure Indicator (Left) - Detailed Inspection |               | HRS            |             | 137             |     |                  | 2909.1      |                    |         | 0            |
|                  |                                                                                      |               | AFL            |             | 52              |     |                  | 1065        |                    |         | 0            |
|                  |                                                                                      |               | MOS            |             | 5.3             |     |                  | 03 Dec 2025 |                    |         |              |
|                  | Airframe                                                                             |               | MSC            |             |                 |     | O/C              |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                              |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                                                              | Serial Number |     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                                                       | SW            |     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                                                   |               |     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                                                            |               |     |             |                 |     |                  |             |                     |         |              |
| 242118           | Idg Oil Scavenge Filter Differential Pressure Indicator<br>(Right) - Detailed Inspection |               | HRS |             | 137             |     |                  | 2909.1      |                     |         | 0            |
|                  |                                                                                          |               | AFL |             | 52              |     |                  | 1065        |                     |         | 0            |
|                  |                                                                                          |               | MOS |             | 5.3             |     |                  | 03 Dec 2025 |                     |         |              |
|                  |                                                                                          |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                          |               |     |             |                 |     |                  |             |                     |         |              |
| 242119           | Idg Oil Scavenge Filter (Left) - Detailed Inspection /<br>Discard                        |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                                          |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  |                                                                                          |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                                          |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                          |               |     |             |                 |     |                  |             |                     |         |              |
| 242120           | Idg Oil Scavenge Filter (Right) - Detailed Inspection /<br>Discard                       |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                                          |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  |                                                                                          |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                                          |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                          |               |     |             |                 |     |                  |             |                     |         |              |
| 242121           | Idg Oil Scavenge Filter (Left) - Removal / Installation<br>PN SN-UNKNOWN                 |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                                          |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  |                                                                                          |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                                          |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                          |               |     |             |                 |     |                  |             |                     |         |              |
| 242122           | Idg Oil Scavenge Filter (Right) - Removal / Installation<br>PN SN-UNKNOWN                |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                                          |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  |                                                                                          |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                                          |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                          |               |     |             |                 |     |                  |             |                     |         |              |
| 242200           | APU Generator - Removal / Installation<br>1159SCAV501-1 1521                             |               | HRS |             | 137             |     |                  | 2909.1      |                     |         | 0            |
|                  |                                                                                          |               | AFL |             | 52              |     |                  | 1065        |                     |         | 0            |
|                  |                                                                                          |               | MOS |             | 5.2             |     |                  | 05 Dec 2025 |                     |         |              |
|                  |                                                                                          |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                          |               |     |             |                 |     |                  |             |                     |         |              |
| 242208           | AC Generation: APU AC Generation - Operational Check                                     |               | HRS |             | 137             |     |                  | 2909.1      |                     |         | 0            |
|                  |                                                                                          |               | AFL |             | 52              |     |                  | 1065        |                     |         | 0            |
|                  |                                                                                          |               | MOS |             | 4.7             |     |                  | 19 Dec 2025 |                     |         |              |
|                  |                                                                                          |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                          |               |     |             |                 |     |                  |             |                     |         |              |
| 242301           | Ram AIR Turbine Assembly - Removal / Installation<br>1712386 0288                        |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                                          |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  |                                                                                          |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                                          |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                          |               |     |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom  | Description                                                      |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due     | Avg Man Hrs  |
|------------------|------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|---------------------|-------------|--------------|
|                  | Part Number                                                      | Serial Number |     |             |                 |     |                  |             |                     |             | Approx Price |
| Logbook Position | HW                                                               | SW            |     |             |                 |     |                  |             |                     |             | Manufacturer |
|                  | MM Ref                                                           |               |     |             |                 |     |                  |             |                     |             | Date Type    |
|                  | Ops Number(s)                                                    |               |     |             |                 |     |                  |             |                     |             |              |
| 242302           | Ram AIR Turbine Generator Control Unit - Removal / Installation  |               | HRS |             | 3046.1          |     |                  | 0           |                     |             | 0            |
|                  |                                                                  |               | AFL |             | 1117            |     |                  | 0           |                     |             | 0            |
|                  | 1712388                                                          | 0276          | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |             |              |
|                  | -                                                                |               | MSC |             |                 |     | O/C              |             |                     |             |              |
| Airframe         |                                                                  |               |     |             |                 |     |                  |             |                     |             |              |
| 242303           | Ram AIR Turbine Restow Pump - Removal / Installation             |               | HRS |             | 3046.1          |     |                  | 0           |                     |             | 0            |
|                  |                                                                  |               | AFL |             | 1117            |     |                  | 0           |                     |             | 0            |
|                  | 5915296                                                          | C0186         | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |             |              |
|                  |                                                                  |               | MSC |             |                 |     | O/C              |             |                     |             |              |
| Airframe         |                                                                  |               |     |             |                 |     |                  |             |                     |             |              |
| 242304           | Ram AIR Turbine Control Handle Assembly - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                     |             | 0            |
|                  |                                                                  |               | AFL |             | 1117            |     |                  | 0           |                     |             | 0            |
|                  | 60P2423013Z001                                                   | 276           | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |             |              |
|                  |                                                                  |               | MSC |             |                 |     | O/C              |             |                     |             |              |
| Airframe         |                                                                  |               |     |             |                 |     |                  |             |                     |             |              |
| 242306           | Ram AIR Turbine Deploy / Stow Operation - Maintenance Practice   |               | HRS |             | 137             |     |                  | 2909.1      |                     |             | 0            |
|                  |                                                                  |               | AFL |             | 52              |     |                  | 1065        |                     |             | 0            |
|                  |                                                                  |               | MOS |             | 5.2             |     |                  | 05 Dec 2025 |                     |             |              |
|                  |                                                                  |               | MSC |             |                 |     | O/C              |             |                     |             |              |
| Airframe         |                                                                  |               |     |             |                 |     |                  |             |                     |             |              |
| 242308           | Ram AIR Turbine Ground - Functional Check                        |               | HRS |             | 137             |     | 1200             | 2909.1      | 4109.1              | 4159.1      | 0            |
|                  |                                                                  |               | AFL |             | 52              |     |                  | 1065        |                     |             | 0            |
|                  |                                                                  |               | MOS |             | 5.1             | 13  | 24               | 08 Dec 2025 | 31 Dec 2027*        | 31 Jan 2028 |              |
|                  | [End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]                |               |     |             |                 |     |                  |             |                     |             |              |
| Airframe         |                                                                  |               |     |             |                 |     |                  |             |                     |             |              |
| 242312           | Ram AIR Turbine - General Visual Inspection                      |               | HRS |             | 137             |     |                  | 2909.1      |                     |             | 0            |
|                  |                                                                  |               | AFL |             | 52              |     |                  | 1065        |                     |             | 0            |
|                  |                                                                  |               | MOS |             | 5.2             | 54  | 24               | 05 Dec 2025 | 31 Jan 2028*        | 29 Feb 2028 |              |
|                  | [End Of Month Item] [MOS: +1m/-1m]                               |               |     |             |                 |     |                  |             |                     |             |              |
| Airframe         |                                                                  |               |     |             |                 |     |                  |             |                     |             |              |
| 242313           | Ram AIR Turbine Control Assembly - Rigging                       |               | HRS |             | 3046.1          |     |                  | 0           |                     |             | 0            |
|                  |                                                                  |               | AFL |             | 1117            |     |                  | 0           |                     |             | 0            |
|                  |                                                                  |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |             |              |
|                  |                                                                  |               | MSC |             |                 |     | O/C              |             |                     |             |              |
| Airframe         |                                                                  |               |     |             |                 |     |                  |             |                     |             |              |
| 242314           | Ram AIR Turbine Control Assembly - Operational Test              |               | HRS |             | 3046.1          |     |                  | 0           |                     |             | 0            |
|                  |                                                                  |               | AFL |             | 1117            |     |                  | 0           |                     |             | 0            |
|                  |                                                                  |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |             |              |
|                  |                                                                  |               | MSC |             |                 |     | O/C              |             |                     |             |              |
| Airframe         |                                                                  |               |     |             |                 |     |                  |             |                     |             |              |

| ATA<br>U=Custom  | Description                                                           |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|-----------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                                           | Serial Number |     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                                    | SW            |     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                                |               |     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                                         |               |     |             |                 |     |                  |             |                     |         |              |
| 242315           | Restow Pump Hydraulic Fluid Fill - Servicing                          |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                       |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  |                                                                       |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  | Airframe                                                              |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| 242316           | Restow Pump Bleeding - Servicing                                      |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                       |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  |                                                                       |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  | Airframe                                                              |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| 242317           | Ram AIR Turbine Assembly - Rigging                                    |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                       |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  |                                                                       |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  | Airframe                                                              |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| 242318           | Ram AIR Turbine Uplock Assembly - Removal / Installation              |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                       |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 1712392                                                               | 0284          | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  | Airframe                                                              |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| 242320           | Ram AIR Turbine Deploy Actuator - Adjustment                          |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                       |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  |                                                                       |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  | Airframe                                                              |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| 242321           | Ram AIR Turbine Deploy Actuator - Removal / Installation              |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                       |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 1712390                                                               | 0356          | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  | Airframe                                                              |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| 242331           | Ram AIR Turbine Current Transformer Assembly - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                       |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 307-1                                                                 | 458VNR        | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  | Airframe                                                              |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| 242341           | Ram AIR Turbine Hydraulic Hose (Pressure) - Removal / Installation    |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                       |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | PN                                                                    | SN-UNKNOWN    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  | Airframe                                                              |               | MSC |             |                 |     | O/C              |             |                     |         |              |

| ATA<br>U=Custom  | Description                                                      |               | UOM                                       | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------------------------------|---------------|-------------------------------------------|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                                      | Serial Number |                                           |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                               | SW            |                                           |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                           |               |                                           |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                                    |               |                                           |             |                 |     |                  |             |                     |         |              |
| 242342           | Ram AIR Turbine Hydraulic Hose (Return) - Removal / Installation |               | HRS                                       |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                  |               | AFL                                       |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | PN                                                               | SN-UNKNOWN    | MOS                                       |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                  |               | MSC                                       |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                  |               |                                           |             |                 |     |                  |             |                     |         |              |
| 242351           | Ram AIR Turbine Built-In Test Switch - Operational Check         |               | HRS                                       |             | 137             |     | 600              | 2909.1      | 3509.1              |         | 0            |
|                  |                                                                  |               | AFL                                       |             | 52              |     |                  | 1065        |                     |         | 0            |
|                  |                                                                  |               | MOS                                       |             | 5.1             |     | 24               | 08 Dec 2025 | 31 Dec 2027         |         |              |
|                  |                                                                  |               | [End Of Month Item] [MOS: -1m] [HRS: -50] |             |                 |     |                  |             |                     |         |              |
| Airframe         | 052001,052011                                                    |               |                                           |             |                 |     |                  |             |                     |         |              |
| 242500           | Idg (Left) Generator Control Unit - Removal / Installation       |               | HRS                                       |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  | 1702787B                                                         | 3033          | AFL                                       |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  |                                                                  |               | MOS                                       |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                  |               | MSC                                       |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                  |               |                                           |             |                 |     |                  |             |                     |         |              |
| 242501           | Idg (Right) Generator Control Unit - Removal / Installation      |               | HRS                                       |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  | 1702787B                                                         | 3048          | AFL                                       |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  |                                                                  |               | MOS                                       |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                  |               | MSC                                       |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                  |               |                                           |             |                 |     |                  |             |                     |         |              |
| 242502           | APU Generator Control Unit - Removal / Installation              |               | HRS                                       |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  | 1702787B                                                         | 3127          | AFL                                       |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  |                                                                  |               | MOS                                       |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                  |               | MSC                                       |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                  |               |                                           |             |                 |     |                  |             |                     |         |              |
| 242720           | 60 HZ Converter (Left) - Removal / Installation                  |               | HRS                                       |             | 730.5           |     |                  | 2315.6      |                     |         | 0            |
|                  | 717220-2                                                         | 10171608      | AFL                                       |             | 315             |     |                  | 802         |                     |         | 0            |
|                  |                                                                  |               | MOS                                       |             | 28.7            |     |                  | 21 Dec 2023 |                     |         |              |
|                  |                                                                  |               | MSC                                       |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                  |               |                                           |             |                 |     |                  |             |                     |         |              |
| 242721           | 60 HZ Converter (Right) - Removal / Installation                 |               | HRS                                       |             | 759.6           |     |                  | 2286.5      |                     |         | 0            |
|                  | 717220-2                                                         | 08232454      | AFL                                       |             | 322             |     |                  | 795         |                     |         | 0            |
|                  |                                                                  |               | MOS                                       |             | 31.9            |     |                  | 13 Sep 2023 |                     |         |              |
|                  |                                                                  |               | MSC                                       |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                  |               |                                           |             |                 |     |                  |             |                     |         |              |
| 242724           | 60 HZ Converter - Operational Test                               |               | HRS                                       |             | 730.5           |     |                  | 2315.6      |                     |         | 0            |
|                  |                                                                  |               | AFL                                       |             | 315             |     |                  | 802         |                     |         | 0            |
|                  |                                                                  |               | MOS                                       |             | 28.7            |     |                  | 21 Dec 2023 |                     |         |              |
|                  |                                                                  |               | MSC                                       |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                  |               |                                           |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom  | Description                                                                                                |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                                                | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                                                         | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                                                     |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                                                              |               |     |             |                 |     |                  |             |                    |         |              |
| 243000           | Tail Compartment Direct Current Feeder Cables - Detailed Inspection                                        |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                            |               | AFL |             | 1117            |     |                  | 0           |                    | 0       |              |
|                  |                                                                                                            |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                                            |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                                            |               |     |             |                 |     |                  |             |                    |         |              |
| 243300           | Transformer Rectifier Unit Hall Effect Sensor (L Main HE1) - Removal / Installation<br>1159SCAV507-3458XV2 |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                            |               | AFL |             | 1117            |     |                  | 0           |                    | 0       |              |
|                  |                                                                                                            |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                                            |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                                            |               |     |             |                 |     |                  |             |                    |         |              |
| 243301           | Transformer Rectifier Unit Hall Effect Sensor (R Main HE2) - Removal / Installation<br>1159SCAV507-3458XV4 |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                            |               | AFL |             | 1117            |     |                  | 0           |                    | 0       |              |
|                  |                                                                                                            |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                                            |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                                            |               |     |             |                 |     |                  |             |                    |         |              |
| 243302           | Transformer Rectifier Unit Hall Effect Sensor (L Ess HE3) - Removal / Installation<br>1159SCAV507-34590YF  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                            |               | AFL |             | 1117            |     |                  | 0           |                    | 0       |              |
|                  |                                                                                                            |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                                            |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                                            |               |     |             |                 |     |                  |             |                    |         |              |
| 243303           | Transformer Rectifier Unit Hall Effect Sensor (R Ess HE4) - Removal / Installation<br>1159SCAV507-3458VX1  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                            |               | AFL |             | 1117            |     |                  | 0           |                    | 0       |              |
|                  |                                                                                                            |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                                            |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                                            |               |     |             |                 |     |                  |             |                    |         |              |
| 243307           | Transformer Rectifier Unit Hall Effect Sensor (Aux HE8) - Removal / Installation<br>1159SCAV507-3458XV3    |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                            |               | AFL |             | 1117            |     |                  | 0           |                    | 0       |              |
|                  |                                                                                                            |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                                            |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                                            |               |     |             |                 |     |                  |             |                    |         |              |
| 243315           | Transformer Rectifier Unit (L Ess) - Removal / Installation<br>8-832-03245113-926A                         |               | HRS |             | 3041.4          |     |                  | 4.7         |                    |         | 0            |
|                  |                                                                                                            |               | AFL |             | 1114            |     |                  | 3           |                    | 0       |              |
|                  |                                                                                                            |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                                            |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                                            |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                          |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(* =Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|----------------------|---------|--------------|
|                  | Part Number                                                          | Serial Number |     |             |                 |     |                  |             |                      |         | Approx Price |
| Logbook Position | HW                                                                   | SW            |     |             |                 |     |                  |             |                      |         | Manufacturer |
|                  | MM Ref                                                               |               |     |             |                 |     |                  |             |                      |         | Date Type    |
|                  | Ops Number(s)                                                        |               |     |             |                 |     |                  |             |                      |         |              |
| 243316           | Transformer Rectifier Unit (R Ess) - Removal / Installation          |               | HRS |             | 3041.4          |     |                  | 4.7         |                      |         | 0            |
|                  | 8-832-03                                                             | 245113-824A   | AFL |             | 1114            |     |                  | 3           |                      |         | 0            |
|                  |                                                                      |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                      |         |              |
|                  | Airframe                                                             |               | MSC |             |                 |     | O/C              |             |                      |         |              |
| 243317           | Transformer Rectifier Unit (Aux) - Removal / Installation            |               | HRS |             | 3041.4          |     |                  | 4.7         |                      |         | 0            |
|                  | 8-832-03                                                             | 245113-991A   | AFL |             | 1114            |     |                  | 3           |                      |         | 0            |
|                  |                                                                      |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                      |         |              |
|                  | Airframe                                                             |               | MSC |             |                 |     | O/C              |             |                      |         |              |
| 243318           | Transformer Rectifier Unit (L Main) - Removal / Installation         |               | HRS |             | 3041.4          |     |                  | 4.7         |                      |         | 0            |
|                  | 8-832-03                                                             | 245113-852A   | AFL |             | 1114            |     |                  | 3           |                      |         | 0            |
|                  |                                                                      |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                      |         |              |
|                  | Airframe                                                             |               | MSC |             |                 |     | O/C              |             |                      |         |              |
| 243319           | Transformer Rectifier Unit (R Main) - Removal / Installation         |               | HRS |             | 3041.4          |     |                  | 4.7         |                      |         | 0            |
|                  | 8-832-03                                                             | 245113-814A   | AFL |             | 1114            |     |                  | 3           |                      |         | 0            |
|                  |                                                                      |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                      |         |              |
|                  | Airframe                                                             |               | MSC |             |                 |     | O/C              |             |                      |         |              |
| 243329           | Auxiliary Transformer Rectifier Unit AC Contactor - Operational Test |               | HRS |             | 3046.1          |     |                  | 0           |                      |         | 0            |
|                  |                                                                      |               | AFL |             | 1117            |     |                  | 0           |                      |         | 0            |
|                  |                                                                      |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                      |         |              |
|                  | Airframe                                                             |               | MSC |             |                 |     | O/C              |             |                      |         |              |
| 243336           | Transformer Rectifier Unit - Inspection / Cleaning                   |               | HRS |             | 3046.1          |     |                  | 0           |                      |         | 0            |
|                  |                                                                      |               | AFL |             | 1117            |     |                  | 0           |                      |         | 0            |
|                  |                                                                      |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                      |         |              |
|                  | Airframe                                                             |               | MSC |             |                 |     | O/C              |             |                      |         |              |
| 243400           | Main Battery (Left) - Removal / Installation                         |               | HRS |             | 137             |     |                  | 2909.1      |                      |         | 0            |
|                  | 5317CH-1                                                             | 0905200180FC6 | AFL |             | 52              |     |                  | 1065        |                      |         | 0            |
|                  |                                                                      |               | MOS |             | 4.8             |     |                  | 18 Dec 2025 |                      |         |              |
|                  | Airframe                                                             |               | MSC |             |                 |     | O/C              |             |                      |         |              |
| 243401           | Main Battery (Right) - Removal / Installation                        |               | HRS |             | 137             |     |                  | 2909.1      |                      |         | 0            |
|                  | 5317CH-1                                                             | 090520011C369 | AFL |             | 52              |     |                  | 1065        |                      |         | 0            |
|                  |                                                                      |               | MOS |             | 5.3             |     |                  | 02 Dec 2025 |                      |         |              |
|                  | Airframe                                                             |               | MSC |             |                 |     | O/C              |             |                      |         |              |

| ATA<br>U=Custom                      | Description                                     |                                    | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due     | Avg Man Hrs  |
|--------------------------------------|-------------------------------------------------|------------------------------------|-----|-------------|-----------------|-----|------------------|-------------|---------------------|-------------|--------------|
|                                      | Part Number                                     | Serial Number                      |     |             |                 |     |                  |             |                     |             | Approx Price |
| Logbook Position                     | HW                                              | SW                                 |     |             |                 |     |                  |             |                     |             | Manufacturer |
|                                      | MM Ref                                          |                                    |     |             |                 |     |                  |             |                     |             | Date Type    |
|                                      | Ops Number(s)                                   |                                    |     |             |                 |     |                  |             |                     |             |              |
| 243404                               | Main Battery (Left) - Restore                   |                                    | HRS |             | 137             |     |                  | 2909.1      |                     |             | 0            |
|                                      |                                                 |                                    | AFL |             | 52              |     |                  | 1065        |                     |             | 0            |
|                                      |                                                 |                                    | MOS |             | 4.8             | -19 | 12               | 18 Dec 2025 | 30 Nov 2026*        | 31 Dec 2026 |              |
|                                      | Airframe                                        | [End Of Month Item] [MOS: +1m/-1m] |     |             |                 |     |                  |             |                     |             |              |
|                                      | 052010                                          |                                    |     |             |                 |     |                  |             |                     |             |              |
| 243405                               | Main Battery (Right) - Restore                  |                                    | HRS |             | 137             |     |                  | 2909.1      |                     |             | 0            |
|                                      |                                                 |                                    | AFL |             | 52              |     |                  | 1065        |                     |             | 0            |
|                                      |                                                 |                                    | MOS |             | 5.3             | -3  | 12               | 02 Dec 2025 | 30 Nov 2026*        | 31 Dec 2026 |              |
|                                      | Airframe                                        | [End Of Month Item] [MOS: +1m/-1m] |     |             |                 |     |                  |             |                     |             |              |
|                                      | 052010                                          |                                    |     |             |                 |     |                  |             |                     |             |              |
| 243406                               | Main Battery (Left) - Operational Check         |                                    | HRS |             | 3046.1          |     |                  | 0           |                     |             | 0            |
|                                      |                                                 |                                    | AFL |             | 1117            |     |                  | 0           |                     |             | 0            |
|                                      |                                                 |                                    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |             |              |
|                                      | Airframe                                        | MSC O/C                            |     |             |                 |     |                  |             |                     |             |              |
| 243407                               | Main Battery (Right) - Operational Check        |                                    | HRS |             | 2120.8          |     |                  | 925.3       |                     |             | 0            |
|                                      |                                                 |                                    | AFL |             | 861             |     |                  | 256         |                     |             | 0            |
|                                      |                                                 |                                    | MOS |             | 85.9            |     |                  | 14 Mar 2019 |                     |             |              |
|                                      | Airframe                                        | MSC O/C                            |     |             |                 |     |                  |             |                     |             |              |
| 243408                               | Main Battery (Left) - Voltage Check             |                                    | HRS |             | 562.4           |     |                  | 2483.7      |                     |             | 0            |
|                                      |                                                 |                                    | AFL |             | 217             |     |                  | 900         |                     |             | 0            |
|                                      |                                                 |                                    | MOS |             | 16.8            |     |                  | 16 Dec 2024 |                     |             |              |
|                                      | Airframe                                        | MSC O/C                            |     |             |                 |     |                  |             |                     |             |              |
| 243409                               | Main Battery (Right) - Voltage Check            |                                    | HRS |             | 562.4           |     |                  | 2483.7      |                     |             | 0            |
|                                      |                                                 |                                    | AFL |             | 217             |     |                  | 900         |                     |             | 0            |
|                                      |                                                 |                                    | MOS |             | 16.8            |     |                  | 16 Dec 2024 |                     |             |              |
|                                      | Airframe                                        | MSC O/C                            |     |             |                 |     |                  |             |                     |             |              |
| 243414                               | Main Battery Charger (Left) - Operational Test  |                                    | HRS |             | 1957.8          |     |                  | 1088.3      |                     |             | 0            |
|                                      |                                                 |                                    | AFL |             | 805             |     |                  | 312         |                     |             | 0            |
|                                      |                                                 |                                    | MOS |             | 82.4            |     |                  | 30 Jun 2019 |                     |             |              |
|                                      | Airframe                                        | MSC O/C                            |     |             |                 |     |                  |             |                     |             |              |
| Notes: PN: 100-1311-01\5 SN: <NONE>. |                                                 |                                    |     |             |                 |     |                  |             |                     |             |              |
| 243415                               | Main Battery Charger (Right) - Operational Test |                                    | HRS |             | 1877.5          |     |                  | 1168.6      |                     |             | 0            |
|                                      |                                                 |                                    | AFL |             | 773             |     |                  | 344         |                     |             | 0            |
|                                      |                                                 |                                    | MOS |             | 79.8            |     |                  | 16 Sep 2019 |                     |             |              |
|                                      | Airframe                                        | MSC O/C                            |     |             |                 |     |                  |             |                     |             |              |
| Notes: PN: 100-1311-01\5 SN: <NONE>. |                                                 |                                    |     |             |                 |     |                  |             |                     |             |              |



| ATA<br>U=Custom  | Description                                                         |                                    | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W                 | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|---------------------------------------------------------------------|------------------------------------|-----|-------------|-----------------|-----|------------------|--------------------------|---------------------|---------|--------------|
|                  | Part Number                                                         | Serial Number                      |     |             |                 |     |                  |                          |                     |         | Approx Price |
| Logbook Position | HW                                                                  | SW                                 |     |             |                 |     |                  |                          |                     |         | Manufacturer |
|                  | MM Ref                                                              |                                    |     |             |                 |     |                  |                          |                     |         | Date Type    |
|                  | Ops Number(s)                                                       |                                    |     |             |                 |     |                  |                          |                     |         |              |
| 243416           | Main Battery Charger (Left) - Removal / Installation                |                                    | HRS |             | 1735.8          |     |                  | 1310.3                   |                     |         | 0            |
|                  | 100-1311-01                                                         | 1139883M                           | AFL |             | 729             |     |                  | 388                      |                     |         | 0            |
|                  |                                                                     |                                    | MOS |             | 75.6            |     |                  | 22 Jan 2020              |                     |         |              |
|                  | Airframe                                                            |                                    | MSC |             |                 |     | O/C              |                          |                     |         |              |
| 243417           | Main Battery Charger (Right) - Removal / Installation               |                                    | HRS |             | 1735.8          |     |                  | 1310.3                   |                     |         | 0            |
|                  | 100-1311-01                                                         | 1129926M                           | AFL |             | 729             |     |                  | 388                      |                     |         | 0            |
|                  |                                                                     |                                    | MOS |             | 75.6            |     |                  | 22 Jan 2020              |                     |         |              |
|                  | Airframe                                                            |                                    | MSC |             |                 |     | O/C              |                          |                     |         |              |
| 243424           | Left Main Battery Hall Effect Sensor (HE7) - Removal / Installation |                                    | HRS |             | 3046.1          |     |                  | 0                        |                     |         | 0            |
|                  |                                                                     |                                    | AFL |             | 1117            |     |                  | 0                        |                     |         | 0            |
|                  | 1159SCAV507-3                                                       | 458XX5                             | MOS |             | 128.6           |     |                  | 24 Aug 2015              |                     |         |              |
|                  | Airframe                                                            |                                    | MSC |             |                 |     | O/C              |                          |                     |         |              |
| 243425           | Right Main Battery Hall Effect Sensor (HE6)- Removal / Installation |                                    | HRS |             | 2120.8          |     |                  | 925.3                    |                     |         | 0            |
|                  |                                                                     |                                    | AFL |             | 861             |     |                  | 256                      |                     |         | 0            |
|                  | 1159SCAV507-3                                                       | 4H57D                              | MOS |             | 85.9            |     |                  | 14 Mar 2019              |                     |         |              |
|                  | Airframe                                                            |                                    | MSC |             |                 |     | O/C              |                          |                     |         |              |
| 243428           | Main Battery Contactor (Left) - Removal / Installation              |                                    | HRS |             | 3046.1          |     |                  | 0                        |                     |         | 0            |
|                  | 352CC01                                                             | NSN                                | AFL |             | 1117            |     |                  | 0                        |                     |         | 0            |
|                  |                                                                     |                                    | MOS |             | 128.6           |     |                  | 24 Aug 2015              |                     |         |              |
|                  | Airframe                                                            |                                    | MSC |             |                 |     | O/C              |                          |                     |         |              |
| 243436           | Main Battery (Left) - Inspection / Check                            |                                    | HRS |             | 3046.1          |     |                  | 0                        |                     |         | 0            |
|                  |                                                                     |                                    | AFL |             | 1117            |     |                  | 0                        |                     |         | 0            |
|                  |                                                                     |                                    | MOS |             | 128.6           |     |                  | 24 Aug 2015              |                     |         |              |
|                  | Airframe                                                            |                                    | MSC |             |                 |     | O/C              |                          |                     |         |              |
| 243437           | Main Battery (Right) - Inspection / Check                           |                                    | HRS |             | 3046.1          |     |                  | 0                        |                     |         | 0            |
|                  |                                                                     |                                    | AFL |             | 1117            |     |                  | 0                        |                     |         | 0            |
|                  |                                                                     |                                    | MOS |             | 128.6           |     |                  | 24 Aug 2015              |                     |         |              |
|                  | Airframe                                                            |                                    | MSC |             |                 |     | O/C              |                          |                     |         |              |
| 243500           | Emergency Battery Power System (Forward) - Operational Check        |                                    | HRS |             | 137             |     |                  | 2909.1                   |                     |         | 0            |
|                  |                                                                     |                                    | AFL |             | 52              |     |                  | 1065                     |                     |         | 0            |
|                  |                                                                     |                                    | MOS |             | 5.3             | -2  | 12               | 01 Dec 2025 30 Nov 2026* | 31 Dec 2026         |         |              |
|                  | Airframe                                                            | [End Of Month Item] [MOS: +1m/-1m] |     |             |                 |     |                  |                          |                     |         |              |
| 052010           |                                                                     |                                    |     |             |                 |     |                  |                          |                     |         |              |

| ATA<br>U=Custom                    | Description                                                 |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W                 | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------------------------|-------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|--------------------------|--------------------|---------|--------------|
|                                    | Part Number                                                 | Serial Number |     |             |                 |     |                  |                          |                    |         | Approx Price |
| Logbook Position                   | HW                                                          | SW            |     |             |                 |     |                  |                          |                    |         | Manufacturer |
|                                    | MM Ref                                                      |               |     |             |                 |     |                  |                          |                    |         | Date Type    |
|                                    | Ops Number(s)                                               |               |     |             |                 |     |                  |                          |                    |         |              |
| 243501                             | Emergency Battery Power System (Aft) - Operational Check    |               | HRS |             | 137             |     |                  | 2909.1                   |                    |         | 0            |
|                                    |                                                             |               | AFL |             | 52              |     |                  | 1065                     |                    |         | 0            |
|                                    |                                                             |               | MOS |             | 5.3             | -2  | 12               | 01 Dec 2025 30 Nov 2026* | 31 Dec 2026        |         |              |
|                                    | [End Of Month Item] [MOS: +1m/-1m]                          |               |     |             |                 |     |                  |                          |                    |         |              |
| Airframe                           |                                                             | 052010        |     |             |                 |     |                  |                          |                    |         |              |
| 243502                             | Emergency Battery (Forward) - Functional Check (Level Test) |               | HRS |             | 137             |     |                  | 2909.1                   |                    |         | 0            |
|                                    |                                                             |               | AFL |             | 52              |     |                  | 1065                     |                    |         | 0            |
|                                    |                                                             |               | MOS |             | 5.3             | 44  | 24               | 01 Dec 2025 31 Jan 2028* | 29 Feb 2028        |         |              |
|                                    | [End Of Month Item] [MOS: +1m/-1m]                          |               |     |             |                 |     |                  |                          |                    |         |              |
| Airframe                           |                                                             | 052011        |     |             |                 |     |                  |                          |                    |         |              |
| Notes: PN: 100-0302-03 SN: <NONE>. |                                                             |               |     |             |                 |     |                  |                          |                    |         |              |
| 243503                             | Emergency Battery (Aft) - Functional Check (Level Test)     |               | HRS |             | 137             |     |                  | 2909.1                   |                    |         | 0            |
|                                    |                                                             |               | AFL |             | 52              |     |                  | 1065                     |                    |         | 0            |
|                                    |                                                             |               | MOS |             | 5.3             | 44  | 24               | 01 Dec 2025 31 Jan 2028* | 29 Feb 2028        |         |              |
|                                    | [End Of Month Item] [MOS: +1m/-1m]                          |               |     |             |                 |     |                  |                          |                    |         |              |
| Airframe                           |                                                             | 052011        |     |             |                 |     |                  |                          |                    |         |              |
| Notes: PN: 100-0302-03 SN: <NONE>. |                                                             |               |     |             |                 |     |                  |                          |                    |         |              |
| 243504                             | Emergency Battery Pack (Forward) - Removal / Installation   |               | HRS | TSN:21.2    | 3024.9          |     |                  | 21.2                     |                    |         | 0            |
|                                    |                                                             |               | AFL | TSN:7       | 1110            |     |                  | 7                        |                    |         | 0            |
|                                    | 100-0302-03                                                 | P4542         | MOS | TSN:5       | 123.5           |     |                  | 25 Jan 2016              |                    |         |              |
|                                    |                                                             |               | MSC |             |                 |     | O/C              |                          |                    |         |              |
|                                    | Airframe                                                    |               |     |             |                 |     |                  |                          |                    |         |              |
| 243505                             | Emergency Battery Pack (Aft) - Removal / Installation       |               | HRS |             | 3046.1          |     |                  | 0                        |                    |         | 0            |
|                                    |                                                             |               | AFL |             | 1117            |     |                  | 0                        |                    |         | 0            |
|                                    |                                                             |               | MOS |             | 128.6           |     |                  | 24 Aug 2015              |                    |         |              |
|                                    |                                                             |               | MSC |             |                 |     | O/C              |                          |                    |         |              |
| Airframe                           |                                                             |               |     |             |                 |     |                  |                          |                    |         |              |
| 243508                             | Emergency Battery (Forward) - Restore                       |               | HRS |             | 137             |     |                  | 2909.1                   |                    |         | 0            |
|                                    |                                                             |               | AFL |             | 52              |     |                  | 1065                     |                    |         | 0            |
|                                    |                                                             |               | MOS |             | 5.3             |     | 48               | 01 Dec 2025 31 Jan 2028  |                    |         |              |
|                                    | [End Of Month Item]                                         |               |     |             |                 |     |                  |                          |                    |         |              |
| Airframe                           |                                                             |               |     |             |                 |     |                  |                          |                    |         |              |
| Notes: MRI PARENT CODE: 243504     |                                                             |               |     |             |                 |     |                  |                          |                    |         |              |
| 243509                             | Emergency Battery (Aft) - Restore                           |               | HRS |             | 137             |     |                  | 2909.1                   |                    |         | 0            |
|                                    |                                                             |               | AFL |             | 52              |     |                  | 1065                     |                    |         | 0            |
|                                    |                                                             |               | MOS |             | 5.3             |     | 48               | 01 Dec 2025 31 Aug 2029  |                    |         |              |
|                                    | [End Of Month Item]                                         |               |     |             |                 |     |                  |                          |                    |         |              |
| Airframe                           |                                                             |               |     |             |                 |     |                  |                          |                    |         |              |
| Notes: MRI PARENT CODE: 243505     |                                                             |               |     |             |                 |     |                  |                          |                    |         |              |

| ATA<br>U=Custom  | Description                                                |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W                             | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|--------------------------------------|---------------------|---------|--------------|
|                  | Part Number                                                | Serial Number |                                    |             |                 |     |                  |                                      |                     |         | Approx Price |
| Logbook Position | HW                                                         | SW            |                                    |             |                 |     |                  |                                      |                     |         | Manufacturer |
|                  | MM Ref                                                     |               |                                    |             |                 |     |                  |                                      |                     |         | Date Type    |
|                  | Ops Number(s)                                              |               |                                    |             |                 |     |                  |                                      |                     |         |              |
| 243510           | Forward Emergency Battery - Removal / Installation         |               | HRS                                |             | 137             |     |                  | 2909.1                               |                     |         | 0            |
|                  | 100-0302-03                                                | P4737         | AFL                                |             | 52              |     |                  | 1065                                 |                     |         | 0            |
|                  |                                                            |               | MOS                                |             | 5.3             |     |                  | 01 Dec 2025                          |                     |         |              |
|                  | Airframe                                                   |               | MSC                                |             |                 |     | O/C              |                                      |                     |         |              |
| 243511           | Aft Emergency Battery - Removal / Installation             |               | HRS                                |             | 137             |     |                  | 2909.1                               |                     |         | 0            |
|                  | 100-0302-03                                                | P5104         | AFL                                |             | 52              |     |                  | 1065                                 |                     |         | 0            |
|                  |                                                            |               | MOS                                |             | 5.3             |     |                  | 01 Dec 2025                          |                     |         |              |
|                  | Airframe                                                   |               | MSC                                |             |                 |     | O/C              |                                      |                     |         |              |
| 243600           | Electrical Backup Hydraulic Actuator Power Distribution    |               | HRS                                |             | 3033.8          |     |                  | 12.3                                 |                     |         | 0            |
|                  | Box - Removal / Installation                               |               | AFL                                |             | 1112            |     |                  | 5                                    |                     |         | 0            |
|                  | 1712488A                                                   | 0387          | MOS                                |             | 124             |     |                  | 12 Jan 2016                          |                     |         |              |
|                  | Airframe                                                   |               | MSC                                |             |                 |     | O/C              |                                      |                     |         |              |
| 243602           | Electrical Backup Hydraulic Actuator Battery Hall Effect   |               | HRS                                |             | 3046.1          |     |                  | 0                                    |                     |         | 0            |
|                  | Sensor (HE9) - Removal / Installation                      |               | AFL                                |             | 1117            |     |                  | 0                                    |                     |         | 0            |
|                  | 1159SCAV507-3                                              | 427LGO        | MOS                                |             | 128.6           |     |                  | 24 Aug 2015                          |                     |         |              |
|                  | Airframe                                                   |               | MSC                                |             |                 |     | O/C              |                                      |                     |         |              |
| 243606           | Electrical Backup Hydraulic Actuator Battery - Operational |               | HRS                                |             | 562.4           |     |                  | 2483.7                               |                     |         | 0            |
|                  | Test                                                       |               | AFL                                |             | 217             |     |                  | 900                                  |                     |         | 0            |
|                  |                                                            |               | MOS                                |             | 17.4            |     |                  | 29 Nov 2024                          |                     |         |              |
|                  | Airframe                                                   |               | MSC                                |             |                 |     | O/C              |                                      |                     |         |              |
| 243607           | Electrical Backup Hydraulic Actuator Nicad Battery -       |               | HRS                                |             | 137             |     |                  | 2909.1                               |                     |         | 0            |
|                  | Restore                                                    |               | AFL                                |             | 52              |     |                  | 1065                                 |                     |         | 0            |
|                  |                                                            |               | MOS                                |             | 5.3             | -2  | 12               | 01 Dec 2025 30 Nov 2026* 31 Dec 2026 |                     |         |              |
|                  | Airframe                                                   |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |                                      |                     |         |              |
| 243608           | Ebha Battery - Inspection / Check                          |               | HRS                                |             | 3046.1          |     |                  | 0                                    |                     |         | 0            |
|                  |                                                            |               | AFL                                |             | 1117            |     |                  | 0                                    |                     |         | 0            |
|                  |                                                            |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015                          |                     |         |              |
|                  | Airframe                                                   |               | MSC                                |             |                 |     | O/C              |                                      |                     |         |              |

| ATA<br>U=Custom  | Description                                                                             |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W                             | Next Due<br>(* =Adj) | Max Due | Avg Man Hrs  |
|------------------|-----------------------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|--------------------------------------|----------------------|---------|--------------|
|                  | Part Number                                                                             | Serial Number |                                    |             |                 |     |                  |                                      |                      |         | Approx Price |
| Logbook Position | HW                                                                                      | SW            |                                    |             |                 |     |                  |                                      |                      |         | Manufacturer |
|                  | MM Ref                                                                                  |               |                                    |             |                 |     |                  |                                      |                      |         | Date Type    |
|                  | Ops Number(s)                                                                           |               |                                    |             |                 |     |                  |                                      |                      |         |              |
| 243610           | Electrical Backup Hydraulic Actuator Battery - Removal / Installation                   |               | HRS                                |             | 137             |     |                  | 2909.1                               |                      |         | 0            |
|                  |                                                                                         |               | AFL                                |             | 52              |     |                  | 1065                                 |                      |         | 0            |
|                  | 5317CH-1                                                                                | 090520019BC04 | MOS                                |             | 5.3             |     |                  | 01 Dec 2025                          |                      |         |              |
|                  |                                                                                         |               | MSC                                |             |                 |     | O/C              |                                      |                      |         |              |
| Airframe         |                                                                                         |               |                                    |             |                 |     |                  |                                      |                      |         |              |
| 243611           | Electrical Backup Hydraulic Actuator Battery Charger (No. 1) - Removal / Installation   |               | HRS                                |             | 1844.6          |     |                  | 1201.5                               |                      |         | 0            |
|                  |                                                                                         |               | AFL                                |             | 766             |     |                  | 351                                  |                      |         | 0            |
|                  | 100-1311-01                                                                             | 1172653M      | MOS                                |             | 79.3            |     |                  | 01 Oct 2019                          |                      |         |              |
|                  |                                                                                         |               | MSC                                |             |                 |     | O/C              |                                      |                      |         |              |
| Airframe         |                                                                                         |               |                                    |             |                 |     |                  |                                      |                      |         |              |
| 243612           | Electrical Backup Hydraulic Actuator Battery Charger (No. 2) - Removal / Installation   |               | HRS                                |             | 3046.1          |     |                  | 0                                    |                      |         | 0            |
|                  |                                                                                         |               | AFL                                |             | 1117            |     |                  | 0                                    |                      |         | 0            |
|                  | 100-1311-01                                                                             | NSN           | MOS                                |             | 128.6           |     |                  | 24 Aug 2015                          |                      |         |              |
|                  |                                                                                         |               | MSC                                |             |                 |     | O/C              |                                      |                      |         |              |
| Airframe         |                                                                                         |               |                                    |             |                 |     |                  |                                      |                      |         |              |
| 243700           | UPS Fcs Battery With Charger - Removal / Installation                                   |               | HRS                                |             | 3033.8          |     |                  | 12.3                                 |                      |         | 0            |
|                  |                                                                                         |               | AFL                                |             | 1112            |     |                  | 5                                    |                      |         | 0            |
|                  | 100-2410-07                                                                             | 1148191Z      | MOS                                |             | 125.1           |     |                  | 07 Dec 2015                          |                      |         |              |
|                  |                                                                                         |               | MSC                                |             |                 |     | O/C              |                                      |                      |         |              |
| Airframe         |                                                                                         |               |                                    |             |                 |     |                  |                                      |                      |         |              |
| 243900           | Uninterruptible Power Supply Battery Hall Effect Sensor (HE10) - Removal / Installation |               | HRS                                |             | 3046.1          |     |                  | 0                                    |                      |         | 0            |
|                  |                                                                                         |               | AFL                                |             | 1117            |     |                  | 0                                    |                      |         | 0            |
|                  | 1159SCAV507-3                                                                           | 44YYP1        | MOS                                |             | 128.6           |     |                  | 24 Aug 2015                          |                      |         |              |
|                  |                                                                                         |               | MSC                                |             |                 |     | O/C              |                                      |                      |         |              |
| Airframe         |                                                                                         |               |                                    |             |                 |     |                  |                                      |                      |         |              |
| 243902           | Uninterruptible Power Supply Battery - Operational Test                                 |               | HRS                                |             | 137             |     |                  | 2909.1                               |                      |         | 0            |
|                  |                                                                                         |               | AFL                                |             | 52              |     |                  | 1065                                 |                      |         | 0            |
|                  |                                                                                         |               | MOS                                |             | 5.5             |     |                  | 27 Nov 2025                          |                      |         |              |
|                  |                                                                                         |               | MSC                                |             |                 |     | O/C              |                                      |                      |         |              |
| Airframe         |                                                                                         |               |                                    |             |                 |     |                  |                                      |                      |         |              |
| 243903           | Uninterruptible Power Supply Sealed Lead ACID Battery - Functional Check                |               | HRS                                |             | 137             |     |                  | 2909.1                               |                      |         | 0            |
|                  |                                                                                         |               | AFL                                |             | 52              |     |                  | 1065                                 |                      |         | 0            |
|                  |                                                                                         |               | MOS                                |             | 5.5             | 24  | 12               | 27 Nov 2025 31 Dec 2026* 31 Jan 2027 |                      |         |              |
|                  |                                                                                         |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |                                      |                      |         |              |
| Airframe         |                                                                                         |               |                                    |             |                 |     |                  |                                      |                      |         |              |
| 052010           |                                                                                         |               |                                    |             |                 |     |                  |                                      |                      |         |              |

| ATA<br>U=Custom  | Description                                                             |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|-------------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                                             | Serial Number |                     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                                      | SW            |                     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                                  |               |                     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                                           |               |                     |             |                 |     |                  |             |                     |         |              |
| 243904           | Uninterruptible Power Supply Battery - Removal / Installation           |               | HRS                 |             | 862.3           |     |                  | 2183.8      |                     |         | 0            |
|                  |                                                                         |               | AFL                 |             | 355             |     |                  | 762         |                     |         | 0            |
|                  | 100-2410-07                                                             | 1216282       | MOS                 |             | 35.9            |     |                  | 15 May 2023 |                     |         |              |
|                  |                                                                         |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                         |               |                     |             |                 |     |                  |             |                     |         |              |
| 243905           | Flight Control System Uninterruptible Power Supply Battery - Restore    |               | HRS                 |             | 994.2           |     |                  | 2051.9      |                     |         | 0            |
|                  |                                                                         |               | AFL                 |             | 392             |     |                  | 725         |                     |         | 0            |
|                  |                                                                         |               | MOS                 |             | 41.1            |     | 48               | 07 Dec 2022 | 30 Nov 2026         |         |              |
|                  |                                                                         |               | [End Of Month Item] |             |                 |     |                  |             |                     |         | OVERHAUL     |
| Airframe         |                                                                         |               |                     |             |                 |     |                  |             |                     |         |              |
| 243906           | Uninterruptible Power Supply Battery Charger - Removal / Installation   |               | HRS                 |             | 1844.6          |     |                  | 1201.5      |                     |         | 0            |
|                  |                                                                         |               | AFL                 |             | 766             |     |                  | 351         |                     |         | 0            |
|                  | 100-1311-01                                                             | 1164092M      | MOS                 |             | 79.3            |     |                  | 01 Oct 2019 |                     |         |              |
|                  |                                                                         |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                         |               |                     |             |                 |     |                  |             |                     |         |              |
| 244000           | Dc External Power - Operational Check                                   |               | HRS                 |             | 3033.8          |     |                  | 12.3        |                     |         | 0            |
|                  |                                                                         |               | AFL                 |             | 1112            |     |                  | 5           |                     |         | 0            |
|                  |                                                                         |               | MOS                 |             | 126             |     |                  | 12 Nov 2015 |                     |         |              |
|                  |                                                                         |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                         |               |                     |             |                 |     |                  |             |                     |         |              |
| 244001           | AC External Power - Operational Check                                   |               | HRS                 |             | 3033.8          |     |                  | 12.3        |                     |         | 0            |
|                  |                                                                         |               | AFL                 |             | 1112            |     |                  | 5           |                     |         | 0            |
|                  |                                                                         |               | MOS                 |             | 126             |     |                  | 12 Nov 2015 |                     |         |              |
|                  |                                                                         |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                         |               |                     |             |                 |     |                  |             |                     |         |              |
| 244002           | 60 HZ External Power - Operational Check                                |               | HRS                 |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                         |               | AFL                 |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  |                                                                         |               | MOS                 |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                         |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                         |               |                     |             |                 |     |                  |             |                     |         |              |
| 244200           | External AC Power Current Transformer Assembly - Removal / Installation |               | HRS                 |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                         |               | AFL                 |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 1159SCAV504-1                                                           | 2123          | MOS                 |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                         |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                         |               |                     |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom  | Description                                                 |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs   |
|------------------|-------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|---------------|
|                  | Part Number                                                 | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price  |
| Logbook Position | HW                                                          | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer  |
|                  | MM Ref                                                      |               |     |             |                 |     |                  |             |                    |         | Date Type     |
|                  | Ops Number(s)                                               |               |     |             |                 |     |                  |             |                    |         |               |
| 245000           | AC Electrical Load Distribution - Operational Check         |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0             |
|                  |                                                             |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0             |
|                  |                                                             |               | MOS |             | 124.7           |     |                  | 20 Dec 2015 |                    |         |               |
|                  | Airframe                                                    |               | MSC |             |                 |     | O/C              |             |                    |         |               |
| 245300           | 60 Hertz Outlet (Left Seat No. 1) - Removal / Installation  |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0             |
|                  | 107047-1                                                    | 24140515      | AFL |             | 1112            |     |                  | 5           |                    |         | 0             |
|                  |                                                             |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | MID CONTINENT |
|                  | Airframe                                                    |               | MSC |             |                 |     | O/C              |             |                    |         |               |
| 245301           | 60 Hertz Outlet (Left Seat No. 2) - Removal / Installation  |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0             |
|                  | 107047-1                                                    | 24310515      | AFL |             | 1112            |     |                  | 5           |                    |         | 0             |
|                  |                                                             |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | MID CONTINENT |
|                  | Airframe                                                    |               | MSC |             |                 |     | O/C              |             |                    |         |               |
| 245306           | 60 Hertz Outlet (Right Seat No. 1) - Removal / Installation |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0             |
|                  | 107047-1                                                    | 24320515      | AFL |             | 1112            |     |                  | 5           |                    |         | 0             |
|                  |                                                             |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | MID CONTINENT |
|                  | Airframe                                                    |               | MSC |             |                 |     | O/C              |             |                    |         |               |
| 245307           | 60 Hertz Outlet (Right Seat No. 2) - Removal / Installation |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0             |
|                  | 107047-1                                                    | 23930515      | AFL |             | 1112            |     |                  | 5           |                    |         | 0             |
|                  |                                                             |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | MID CONTINENT |
|                  | Airframe                                                    |               | MSC |             |                 |     | O/C              |             |                    |         |               |
| 245312           | 60 Hertz Outlet (Crew Rest) - Removal / Installation        |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0             |
|                  | 107047-1                                                    | 23950515      | AFL |             | 1112            |     |                  | 5           |                    |         | 0             |
|                  |                                                             |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | MID CONTINENT |
|                  | Airframe                                                    |               | MSC |             |                 |     | O/C              |             |                    |         |               |
| 245313           | 60 Hertz Outlet (Forward Lavatory) - Removal / Installation |               | HRS |             | 2762.2          |     |                  | 283.9       |                    |         | 0             |
|                  |                                                             |               | AFL |             | 1041            |     |                  | 76          |                    |         | 0             |
|                  | 107047-12                                                   | 3280316       | MOS | TSN:9       | 113             |     |                  | 12 Dec 2016 |                    |         | MID CONTINENT |
|                  | Airframe                                                    |               | MSC |             |                 |     | O/C              |             |                    |         |               |
| 245314           | 60 Hertz Outlet (Aft Lavatory) - Removal / Installation     |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0             |
|                  | 107047-2                                                    | 9080215       | AFL |             | 1112            |     |                  | 5           |                    |         | 0             |
|                  |                                                             |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | MID CONTINENT |
|                  | Airframe                                                    |               | MSC |             |                 |     | O/C              |             |                    |         |               |

| ATA<br>U=Custom  | Description                                                                 |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs   |
|------------------|-----------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|---------------|
|                  | Part Number                                                                 | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price  |
| Logbook Position | HW                                                                          | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer  |
|                  | MM Ref                                                                      |               |     |             |                 |     |                  |             |                    |         | Date Type     |
|                  | Ops Number(s)                                                               |               |     |             |                 |     |                  |             |                    |         |               |
| 245322           | 60 Hertz Outlet (Forward Right Closet) - Removal / Installation             |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0             |
|                  |                                                                             |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0             |
|                  | 107047-1                                                                    | 23900515      | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | MID CONTINENT |
|                  |                                                                             |               | MSC |             |                 |     | O/C              |             |                    |         |               |
| Airframe         |                                                                             |               |     |             |                 |     |                  |             |                    |         |               |
| 245329           | 60 Hertz Outlet (Right Divan, Forward End Cabinet) - Removal / Installation |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0             |
|                  |                                                                             |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0             |
|                  | 107047-1                                                                    | 24150515      | MOS |             | 124             |     |                  | 12 Jan 2016 |                    |         | MID CONTINENT |
|                  |                                                                             |               | MSC |             |                 |     | O/C              |             |                    |         |               |
| Airframe         |                                                                             |               |     |             |                 |     |                  |             |                    |         |               |
| 245336           | 60HZ Outlet, Conference Forward - Removal / Installation                    |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0             |
|                  |                                                                             |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0             |
|                  | 107047-1                                                                    | 24300515      | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | MID CONTINENT |
|                  |                                                                             |               | MSC |             |                 |     | O/C              |             |                    |         |               |
| Airframe         |                                                                             |               |     |             |                 |     |                  |             |                    |         |               |
| 245337           | 60HZ Outlet, Conference Aft - Removal / Installation                        |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0             |
|                  |                                                                             |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0             |
|                  | 107047-1                                                                    | 24330515      | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | MID CONTINENT |
|                  |                                                                             |               | MSC |             |                 |     | O/C              |             |                    |         |               |
| Airframe         |                                                                             |               |     |             |                 |     |                  |             |                    |         |               |
| 245338           | 60 HZ Outlet #1, Aft Right Closet - Removal / Installation                  |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0             |
|                  |                                                                             |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0             |
|                  | 107047-1                                                                    | 24170515      | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | MID CONTINENT |
|                  |                                                                             |               | MSC |             |                 |     | O/C              |             |                    |         |               |
| Airframe         |                                                                             |               |     |             |                 |     |                  |             |                    |         |               |
| 245363           | 60 Hertz Outlet (Forward Right Closet No. 2) - Removal / Installation       |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0             |
|                  |                                                                             |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0             |
|                  | 107047-1                                                                    | 23940515      | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | MID CONTINENT |
|                  |                                                                             |               | MSC |             |                 |     | O/C              |             |                    |         |               |
| Airframe         |                                                                             |               |     |             |                 |     |                  |             |                    |         |               |
| 245370           | 60 HZ Power - Operational Check                                             |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0             |
|                  |                                                                             |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0             |
|                  |                                                                             |               | MOS |             | 124.5           |     |                  | 27 Dec 2015 |                    |         |               |
|                  |                                                                             |               | MSC |             |                 |     | O/C              |             |                    |         |               |
| Airframe         |                                                                             |               |     |             |                 |     |                  |             |                    |         |               |
| 245399           | 60 Hertz Power Outlet - Adjustment / Test                                   |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |         | 0             |
|                  |                                                                             |               | AFL |             | 315             |     |                  | 802         |                    |         | 0             |
|                  |                                                                             |               | MOS |             | 28.7            |     |                  | 21 Dec 2023 |                    |         |               |
|                  |                                                                             |               | MSC |             |                 |     | O/C              |             |                    |         |               |
| Airframe         |                                                                             |               |     |             |                 |     |                  |             |                    |         |               |

| ATA<br>U=Custom  | Description                                                      |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs   |
|------------------|------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|---------------|
|                  | Part Number                                                      | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price  |
| Logbook Position | HW                                                               | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer  |
|                  | MM Ref                                                           |               |     |             |                 |     |                  |             |                    |         | Date Type     |
|                  | Ops Number(s)                                                    |               |     |             |                 |     |                  |             |                    |         |               |
| 245483           | Outlet Assy, 60 HZ, Aft Bed End Cabinet - Removal / Installation |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0             |
|                  |                                                                  |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0             |
|                  | 107047-1                                                         | 23920515      | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | MID CONTINENT |
|                  |                                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |               |
| Airframe         |                                                                  |               |     |             |                 |     |                  |             |                    |         |               |
| 245484           | Outlet Assy, 60 HZ, Fwd Bed End Cabinet - Removal / Installation |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0             |
|                  |                                                                  |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0             |
|                  | 107047-1                                                         | 24160515      | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | MID CONTINENT |
|                  |                                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |               |
| Airframe         |                                                                  |               |     |             |                 |     |                  |             |                    |         |               |
| 246000           | Dc Electrical Load Distribution - Operational Check              |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0             |
|                  |                                                                  |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0             |
|                  |                                                                  |               | MOS |             | 126             |     |                  | 12 Nov 2015 |                    |         |               |
|                  |                                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |               |
| Airframe         |                                                                  |               |     |             |                 |     |                  |             |                    |         |               |
| 246406           | Ground Service Bus - Operational Check                           |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0             |
|                  |                                                                  |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0             |
|                  |                                                                  |               | MOS |             | 125.8           |     |                  | 17 Nov 2015 |                    |         |               |
|                  |                                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |               |
| Airframe         |                                                                  |               |     |             |                 |     |                  |             |                    |         |               |
| 247100           | Left Power Distribution Box - Removal / Installation             |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0             |
|                  | 1712480A                                                         | 0150          | AFL |             | 1117            |     |                  | 0           |                    |         | 0             |
|                  |                                                                  |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |               |
|                  |                                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |               |
| Airframe         |                                                                  |               |     |             |                 |     |                  |             |                    |         |               |
| 247101           | Right Power Distribution Box - Removal / Installation            |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0             |
|                  | 1712482A                                                         | 0147          | AFL |             | 1117            |     |                  | 0           |                    |         | 0             |
|                  |                                                                  |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |               |
|                  |                                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |               |
| Airframe         |                                                                  |               |     |             |                 |     |                  |             |                    |         |               |
| 247104           | Left Power Distribution Box Tray - Removal / Installation        |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0             |
|                  | 1712484                                                          | SN-UNKNOWN    | AFL |             | 1117            |     |                  | 0           |                    |         | 0             |
|                  |                                                                  |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |               |
|                  |                                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |               |
| Airframe         |                                                                  |               |     |             |                 |     |                  |             |                    |         |               |
| 247106           | Right Power Distribution Box Tray - Removal / Installation       |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0             |
|                  | 1712486                                                          | SN-UNKNOWN    | AFL |             | 1117            |     |                  | 0           |                    |         | 0             |
|                  |                                                                  |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |               |
|                  |                                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |               |
| Airframe         |                                                                  |               |     |             |                 |     |                  |             |                    |         |               |



| ATA<br>U=Custom  | Description                                                  |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|--------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                  | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                           | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                       |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                |               |     |             |                 |     |                  |             |                    |         |              |
| 247200           | Left Bus Power Control Unit - Removal / Installation         |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 1702789A                                                     | 2017          | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                              |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                     |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 247201           | Right Bus Power Control Unit - Removal / Installation        |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 1702789A                                                     | 2018          | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                              |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                     |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 247204           | Bus Power Control Unit - Operational Check                   |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  |                                                              |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  |                                                              |               | MOS |             | 126             |     |                  | 12 Nov 2015 |                    |         |              |
|                  | Airframe                                                     |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 247210           | Cabin Bus Power Controller - Removal / Installation          |               | HRS |             | 2250.2          |     |                  | 795.9       |                    |         | 0            |
|                  | GCBC-01-001                                                  | 00787         | AFL |             | 899             |     |                  | 218         |                    |         | 0            |
|                  |                                                              |               | MOS |             | 91.1            |     |                  | 08 Oct 2018 |                    |         |              |
|                  | Airframe                                                     |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 248000           | Secondary Power Distribution System - Functional Test        |               | HRS |             | 1620.7          |     |                  | 1425.4      |                    |         | 0            |
|                  |                                                              |               | AFL |             | 666             |     |                  | 451         |                    |         | 0            |
|                  |                                                              |               | MOS |             | 69              |     |                  | 11 Aug 2020 |                    |         |              |
|                  | Airframe                                                     |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 248001           | Remote Interface Unit - Data Load                            |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                              |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                              |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                     |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 248002           | Modular Power Tile - Data Load                               |               | HRS |             | 1620.7          |     |                  | 1425.4      |                    |         | 0            |
|                  |                                                              |               | AFL |             | 666             |     |                  | 451         |                    |         | 0            |
|                  |                                                              |               | MOS |             | 69              |     |                  | 11 Aug 2020 |                    |         |              |
|                  | Airframe                                                     |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 248004           | Right Forward AC Modular Power Tile - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                              |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 202MPT3-4                                                    | MPTAC0699     | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                     |               | MSC |             |                 |     | O/C              |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                         | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                     |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                              |               |     |             |                 |     |                  |             |                    |         |              |
| 248005           | Left AC Modular Power Tile - Removal / Installation        |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 202MPT3-4                                                  | MPTAC0493     | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                            |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                   |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 248006           | Right Aft AC Modular Power Tile - Removal / Installation   |               | HRS |             | 1452            |     |                  | 1594.1      |                    |         | 0            |
|                  | 202MPT3-4                                                  | MPTAC0709     | AFL |             | 570             |     |                  | 547         |                    |         | 0            |
|                  |                                                            |               | MOS |             | 63.7            |     |                  | 19 Jan 2021 |                    |         |              |
|                  | Airframe                                                   |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 248009           | 60 HZ Modular Power Tile - Removal / Installation          |               | HRS |             | 1452            |     |                  | 1594.1      |                    |         | 0            |
|                  | 202MPT3-4                                                  | MPTAC1427     | AFL |             | 570             |     |                  | 547         |                    |         | 0            |
|                  |                                                            |               | MOS |             | 63.7            |     |                  | 19 Jan 2021 |                    |         |              |
|                  | Airframe                                                   |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 248015           | Left Dc Modular Power Tile No. 1 - Removal / Installation  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 201MPT3-4                                                  | MPTDC0713     | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                            |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                   |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 248016           | Left Dc Modular Power Tile No. 2 - Removal / Installation  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 201MPT3-4                                                  | MPTDC0692     | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                            |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                   |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 248017           | Right Dc Modular Power Tile No. 1 - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 201MPT3-4                                                  | MPTDC0698     | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                            |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                   |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 248018           | Right Dc Modular Power Tile No. 2 - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 201MPT3-4                                                  | MPTDC0697     | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                            |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                   |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 248030           | Left Remote Interface Unit - Removal / Installation        |               | HRS |             | 564.8           |     |                  | 2481.3      |                    |         | 0            |
|                  | 785SUE2-3                                                  | RIU3078       | AFL |             | 219             |     |                  | 898         |                    |         | 0            |
|                  |                                                            |               | MOS |             | 18.1            |     |                  | 09 Nov 2024 |                    |         |              |
|                  | Airframe                                                   |               | MSC |             |                 |     | O/C              |             |                    |         |              |

| ATA<br>U=Custom  | Description                                              |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                              | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                       | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                   |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                            |               |     |             |                 |     |                  |             |                    |         |              |
| 248031           | Right Remote Interface Unit - Removal / Installation     |               | HRS |             | 564.8           |     |                  | 2481.3      |                    |         | 0            |
|                  | 785SUE2-3                                                | RIU3008       | AFL |             | 219             |     |                  | 898         |                    |         | 0            |
|                  |                                                          |               | MOS |             | 18.1            |     |                  | 09 Nov 2024 |                    |         |              |
|                  | Airframe                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 248034           | Secondary Power Distribution System Control Verification |               | HRS |             | 1620.7          |     |                  | 1425.4      |                    |         | 0            |
|                  | - Functional Test                                        |               | AFL |             | 666             |     |                  | 451         |                    |         | 0            |
|                  |                                                          |               | MOS |             | 69              |     |                  | 11 Aug 2020 |                    |         |              |
|                  | Airframe                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 248035           | Secondary Power Distribution System - Software Load      |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | Verification                                             |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                          |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 249400           | Switch Assy, Fwd Lav Flush - Removal / Installation      |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  | A2370-1                                                  | 000068        | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  |                                                          |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | RADIANT      |
|                  | Airframe                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 249404           | Switch Assy, Fwd Lav Psu - Removal / Installation        |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  | A2440-1                                                  | 005254        | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  |                                                          |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | RADIANT      |
|                  | Airframe                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 249418           | Switch Assy, Fwd Lav Mirror - Removal / Installation     |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  | A2430-1                                                  | 000038        | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  |                                                          |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | RADIANT      |
|                  | Airframe                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 249428           | Switch Assy, Crew Rest Bulkhead - Removal / Installation |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  | A2430-2                                                  | 005269        | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  |                                                          |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | RADIANT      |
|                  | Airframe                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 249430           | Master Switch, Crew Rest Bulkhead - Removal /            |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  | Installation                                             |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  | A2440-2                                                  | 005479        | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | RADIANT      |
|                  | Airframe                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |

| ATA<br>U=Custom  | Description                                           |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                           | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                    | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                         |               |     |             |                 |     |                  |             |                    |         |              |
| 249454           | Switch Assy, L/H Seat #1 Psu - Removal / Installation |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  | A2440-2                                               | 005689        | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  |                                                       |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | RADIANT      |
|                  | Airframe                                              |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 249470           | Switch Assy, L/H Seat #2 Psu - Removal / Installation |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  | A2440-4                                               | 005873        | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  |                                                       |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | RADIANT      |
|                  | Airframe                                              |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 249486           | Switch Assy, L/H Seat #3 Psu - Removal / Installation |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  | A2440-2                                               | 005692        | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  |                                                       |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | RADIANT      |
|                  | Airframe                                              |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 249502           | Switch Assy, L/H Seat #4 Psu - Removal / Installation |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  | A2440-4                                               | 005874        | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  |                                                       |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | RADIANT      |
|                  | Airframe                                              |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 249518           | Switch Assy, L/H Seat #5 Psu - Removal / Installation |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  | A2430-6                                               | 005386        | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  |                                                       |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | RADIANT      |
|                  | Airframe                                              |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 249534           | Switch Assy, L/H Seat #6 Psu - Removal / Installation |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  | A2430-4                                               | 005959        | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  |                                                       |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | RADIANT      |
|                  | Airframe                                              |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 249535           | Switch Assy, L/H Seat #7 Psu - Removal / Installation |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  | A2430-4                                               | 005960        | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  |                                                       |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | RADIANT      |
|                  | Airframe                                              |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 249550           | Switch Assy, R/H Seat #1 Psu - Removal / Installation |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  | A2440-4                                               | 005875        | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  |                                                       |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | RADIANT      |
|                  | Airframe                                              |               | MSC |             |                 |     | O/C              |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                          |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                          | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                   | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                               |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 249566           | Switch Assy, R/H Seat #2 Psu - Removal / Installation                |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  | A2440-2                                                              |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  |                                                                      |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | RADIANT      |
|                  | Airframe                                                             |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 249582           | Switch Assy, R/H Seat #3 Psu - Removal / Installation                |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  | A2430-4                                                              |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  |                                                                      |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | RADIANT      |
|                  | Airframe                                                             |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 249598           | Switch Assy, R/H Seat #4 Psu - Removal / Installation                |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  | A2430-4                                                              |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  |                                                                      |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | RADIANT      |
|                  | Airframe                                                             |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 249614           | Switch Assy, R/H Seat #5 Psu - Removal / Installation                |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  | A2430-6                                                              |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  |                                                                      |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | RADIANT      |
|                  | Airframe                                                             |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 249630           | Switch Assy, R/H Seat #6 Psu - Removal / Installation                |               | HRS | TSN:8.9     | 3024.9          |     |                  | 21.2        |                    |         | 0            |
|                  | A2520-2                                                              |               | AFL | TSN:2       | 1110            |     |                  | 7           |                    |         | 0            |
|                  |                                                                      |               | MOS |             | 123.5           |     |                  | 27 Jan 2016 |                    |         | RADIANT      |
|                  | Airframe                                                             |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 249806           | Switch Assy, Crew Rest Electric Table Box - Removal / Installation   |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  | A2370-4                                                              |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  |                                                                      |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | RADIANT      |
|                  | Airframe                                                             |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 249818           | Switch Assy, L/H Seat #3 Electric Table Box - Removal / Installation |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  | A2370-4                                                              |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  |                                                                      |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | RADIANT      |
|                  | Airframe                                                             |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 249822           | Switch Assy, L/H Seat #4 Electric Table Box - Removal / Installation |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  | A2370-4                                                              |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  |                                                                      |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | RADIANT      |
|                  | Airframe                                                             |               | MSC |             |                 |     | O/C              |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                        |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|--------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                                        | Serial Number |     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                                 | SW            |     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                             |               |     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                                      |               |     |             |                 |     |                  |             |                     |         |              |
| 249846           | Switch Assy, Aft Lav Psu - Removal / Installation                  |               | HRS |             | 3033.8          |     |                  | 12.3        |                     |         | 0            |
|                  | A2430-4                                                            | 005961        | AFL |             | 1112            |     |                  | 5           |                     |         | 0            |
|                  |                                                                    |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                     |         | RADIANT      |
|                  | Airframe                                                           |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| 249862           | Switch Assy, Aft Lav Toilet Flush / Vent - Removal / Installation  |               | HRS |             | 3033.8          |     |                  | 12.3        |                     |         | 0            |
|                  | A2460-1                                                            | 005243        | AFL |             | 1112            |     |                  | 5           |                     |         | 0            |
|                  |                                                                    |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                     |         | RADIANT      |
|                  | Airframe                                                           |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| 249864           | Switch Assy, Aft Lav Bulkhead - Removal / Installation             |               | HRS |             | 3033.8          |     |                  | 12.3        |                     |         | 0            |
|                  | A2520-3                                                            | 005054        | AFL |             | 1112            |     |                  | 5           |                     |         | 0            |
|                  |                                                                    |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                     |         | RADIANT      |
|                  | Airframe                                                           |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| 249876           | Switch Assy, Fwd Electric Pocket Door Fwd - Removal / Installation |               | HRS |             | 3033.8          |     |                  | 12.3        |                     |         | 0            |
|                  | A2370-12                                                           | 000142        | AFL |             | 1112            |     |                  | 5           |                     |         | 0            |
|                  |                                                                    |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                     |         | RADIANT      |
|                  | Airframe                                                           |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| 249880           | Switch Assy, Fwd Electric Pocket Door Aft - Removal / Installation |               | HRS |             | 3033.8          |     |                  | 12.3        |                     |         | 0            |
|                  | A2370-12                                                           | 000143        | AFL |             | 1112            |     |                  | 5           |                     |         | 0            |
|                  |                                                                    |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                     |         | RADIANT      |
|                  | Airframe                                                           |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| 249884           | Switch Assy, Mid Electric Pocket Door Fwd - Removal / Installation |               | HRS |             | 3033.8          |     |                  | 12.3        |                     |         | 0            |
|                  | A2370-12                                                           | 000144        | AFL |             | 1112            |     |                  | 5           |                     |         | 0            |
|                  |                                                                    |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                     |         | RADIANT      |
|                  | Airframe                                                           |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| 249888           | Switch Assy, Mid Electric Pocket Door Aft - Removal / Installation |               | HRS |             | 3033.8          |     |                  | 12.3        |                     |         | 0            |
|                  | A2370-12                                                           | 000145        | AFL |             | 1112            |     |                  | 5           |                     |         | 0            |
|                  |                                                                    |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                     |         | RADIANT      |
|                  | Airframe                                                           |               | MSC |             |                 |     | O/C              |             |                     |         |              |

| ATA<br>U=Custom            | Description                                                            |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|----------------------------|------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                            | Part Number                                                            | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position           | HW                                                                     | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                            | MM Ref                                                                 |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                            | Ops Number(s)                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| 249892                     | Switch Assy, Aft Electric Pocket Door Fwd - Removal / Installation     |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                            |                                                                        |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                            | A2370-12                                                               | 000099        | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | RADIANT      |
|                            |                                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                   |                                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 249908                     | Switch Assy, R/H Seat #3 Electric Table Box - Removal / Installation   |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                            |                                                                        |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                            | A2370-4                                                                | 002558        | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | RADIANT      |
|                            |                                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                   |                                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 249912                     | Switch Assy, R/H Seat #4 Electric Table Box - Removal / Installation   |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                            |                                                                        |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                            | A2370-4                                                                | 002559        | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | RADIANT      |
|                            |                                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                   |                                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 25 - Equipment/Furnishings |                                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 251101                     | Cockpit Overhead Panel - Removal / Installation                        |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                            | 127TS11Y07\HW:B SW:4-4                                                 |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                            |                                                                        |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                            |                                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                   |                                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 251102                     | Potentiometer, Temp Control - Cockpit (001R1) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                            |                                                                        |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                            | 1151502-1                                                              | 06486         | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                            |                                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                   |                                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 251105                     | Pilot Seat - Removal / Installation                                    |               | HRS | TSN:2315.6  | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                            | 1159SCF513-25                                                          |               | AFL | TSN:802     | 315             |     |                  | 802         |                    |         | 0            |
|                            |                                                                        |               | MOS | TSN:99      | 29.8            |     |                  | 16 Nov 2023 |                    |         |              |
|                            |                                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                   |                                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 251106                     | Copilot Seat - Removal / Installation                                  |               | HRS | TSN:2315.6  | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                            | 1159SCF513-26                                                          |               | AFL | TSN:802     | 315             |     |                  | 802         |                    |         | 0            |
|                            |                                                                        |               | MOS | TSN:99      | 29.8            |     |                  | 16 Nov 2023 |                    |         |              |
|                            |                                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                   |                                                                        |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                   |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------|-------------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                  | Part Number                                                                   | Serial Number |                                    |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position | HW                                                                            | SW            |                                    |             |                 |     |                  |             |                    |             | Manufacturer |
|                  | MM Ref                                                                        |               |                                    |             |                 |     |                  |             |                    |             | Date Type    |
|                  | Ops Number(s)                                                                 |               |                                    |             |                 |     |                  |             |                    |             |              |
| 251107           | Observer Seat - Removal / Installation                                        |               | HRS                                | TSN:1310.3  | 1735.8          |     |                  | 1310.3      |                    |             | 0            |
|                  | 1159SCF501-1                                                                  | 1077-1425     | AFL                                | TSN:388     | 729             |     |                  | 388         |                    |             | 0            |
|                  |                                                                               |               | MOS                                | TSN:53      | 75.5            |     |                  | 25 Jan 2020 |                    |             |              |
|                  | Airframe                                                                      |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| 251111           | Crew Seats Locking Mechanism and Seat Tracks (Pilot) - Detailed Inspection    |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                               |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                               |               | MOS                                |             | 28.7            |     | 48               | 21 Dec 2023 | 31 Dec 2027        | 31 Jan 2028 |              |
|                  | Airframe                                                                      |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
|                  | 052013                                                                        |               |                                    |             |                 |     |                  |             |                    |             |              |
| 251112           | Crew Seats Locking Mechanism and Seat Tracks (Copilot) - Detailed Inspection  |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                               |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                               |               | MOS                                |             | 28.7            |     | 48               | 21 Dec 2023 | 31 Dec 2027        | 31 Jan 2028 |              |
|                  | Airframe                                                                      |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
|                  | 052013                                                                        |               |                                    |             |                 |     |                  |             |                    |             |              |
| 251113           | Crew Seats Locking Mechanism and Seat Tracks (Observer) - Detailed Inspection |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                               |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                               |               | MOS                                |             | 28.7            |     | 48               | 21 Dec 2023 | 31 Dec 2027        | 31 Jan 2028 |              |
|                  | Airframe                                                                      |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
|                  | 052013                                                                        |               |                                    |             |                 |     |                  |             |                    |             |              |
| 251114           | Crew Seat Restraints (Pilot) - Detailed Inspection                            |               | HRS                                |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                  |                                                                               |               | AFL                                |             | 52              |     |                  | 1065        |                    |             | 0            |
|                  |                                                                               |               | MOS                                |             | 5.3             | 47  | 24               | 02 Dec 2025 | 31 Jan 2028*       | 29 Feb 2028 |              |
|                  | Airframe                                                                      |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
|                  | 052011                                                                        |               |                                    |             |                 |     |                  |             |                    |             |              |
| 251115           | Crew Seat Restraints (Copilot) - Detailed Inspection                          |               | HRS                                |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                  |                                                                               |               | AFL                                |             | 52              |     |                  | 1065        |                    |             | 0            |
|                  |                                                                               |               | MOS                                |             | 5.3             | 47  | 24               | 02 Dec 2025 | 31 Jan 2028*       | 29 Feb 2028 |              |
|                  | Airframe                                                                      |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
|                  | 052011                                                                        |               |                                    |             |                 |     |                  |             |                    |             |              |
| 251116           | Crew Seat Restraints (Observer) - Detailed Inspection                         |               | HRS                                |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                  |                                                                               |               | AFL                                |             | 52              |     |                  | 1065        |                    |             | 0            |
|                  |                                                                               |               | MOS                                |             | 5.3             | 47  | 24               | 02 Dec 2025 | 31 Jan 2028*       | 29 Feb 2028 |              |
|                  | Airframe                                                                      |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
|                  | 052011                                                                        |               |                                    |             |                 |     |                  |             |                    |             |              |
| 251117           | Crew Seat Inertia Reels (Pilot) - Operational Check                           |               | HRS                                |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                  |                                                                               |               | AFL                                |             | 52              |     |                  | 1065        |                    |             | 0            |
|                  |                                                                               |               | MOS                                |             | 5.3             | 47  | 24               | 02 Dec 2025 | 31 Jan 2028*       | 29 Feb 2028 |              |
|                  | Airframe                                                                      |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
|                  | 052011                                                                        |               |                                    |             |                 |     |                  |             |                    |             |              |



| ATA<br>U=Custom     | Description                                                                      |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|---------------------|----------------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                     | Part Number                                                                      | Serial Number |                                    |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position    | HW                                                                               | SW            |                                    |             |                 |     |                  |             |                    |             | Manufacturer |
|                     | MM Ref                                                                           |               |                                    |             |                 |     |                  |             |                    |             | Date Type    |
|                     | Ops Number(s)                                                                    |               |                                    |             |                 |     |                  |             |                    |             |              |
| 251118              | Crew Seat Inertia Reels (Copilot) - Operational Check                            |               | HRS                                |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                     |                                                                                  |               | AFL                                |             | 52              |     |                  | 1065        |                    |             | 0            |
|                     |                                                                                  |               | MOS                                |             | 5.3             | 47  | 24               | 02 Dec 2025 | 31 Jan 2028*       | 29 Feb 2028 |              |
|                     | Airframe                                                                         |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
|                     | 052011                                                                           |               |                                    |             |                 |     |                  |             |                    |             |              |
| 251119              | Crew Seat Inertia Reels (Observer) - Operational Check                           |               | HRS                                |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                     |                                                                                  |               | AFL                                |             | 52              |     |                  | 1065        |                    |             | 0            |
|                     |                                                                                  |               | MOS                                |             | 5.3             | 47  | 24               | 02 Dec 2025 | 31 Jan 2028*       | 29 Feb 2028 |              |
|                     | Airframe                                                                         |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
|                     | 052011                                                                           |               |                                    |             |                 |     |                  |             |                    |             |              |
| 252100              | Passenger Seats Attachments and Locking (Left Seat No. 1) - Detailed Inspection  |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                     |                                                                                  |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                     |                                                                                  |               | MOS                                |             | 28.7            | 28  | 48               | 21 Dec 2023 | 31 Jan 2028*       | 29 Feb 2028 |              |
|                     | Airframe                                                                         |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| 252101              | Passenger Seats Restraints - Detailed Inspection                                 |               | HRS                                |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                     |                                                                                  |               | AFL                                |             | 52              |     |                  | 1065        |                    |             | 0            |
|                     |                                                                                  |               | MOS                                |             | 5.3             | 47  | 24               | 02 Dec 2025 | 31 Jan 2028*       | 29 Feb 2028 |              |
|                     | Airframe                                                                         |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
|                     | 052011                                                                           |               |                                    |             |                 |     |                  |             |                    |             |              |
| 252102              | Passenger Seats Inertia Reels - Operational Check                                |               | HRS                                |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                     |                                                                                  |               | AFL                                |             | 52              |     |                  | 1065        |                    |             | 0            |
|                     |                                                                                  |               | MOS                                |             | 5.3             | 48  | 24               | 01 Dec 2025 | 31 Jan 2028*       | 29 Feb 2028 |              |
|                     | Airframe                                                                         |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
|                     | 052011                                                                           |               |                                    |             |                 |     |                  |             |                    |             |              |
| 252129 <sup>U</sup> | Passenger Seats Attachments and Locking (Left Seat No. 2) - Detailed Inspection  |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                     |                                                                                  |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                     |                                                                                  |               | MOS                                |             | 28.7            | 28  | 48               | 21 Dec 2023 | 31 Jan 2028*       | 29 Feb 2028 |              |
|                     | Airframe                                                                         |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| 252134 <sup>U</sup> | Passenger Seats Attachments and Locking (Right Seat No. 1) - Detailed Inspection |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                     |                                                                                  |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                     |                                                                                  |               | MOS                                |             | 28.7            | 28  | 48               | 21 Dec 2023 | 31 Jan 2028*       | 29 Feb 2028 |              |
|                     | Airframe                                                                         |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom     | Description                                                                                             |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|---------------------|---------------------------------------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                     | Part Number                                                                                             | Serial Number |                                    |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position    | HW                                                                                                      | SW            |                                    |             |                 |     |                  |             |                    |             | Manufacturer |
|                     | MM Ref                                                                                                  |               |                                    |             |                 |     |                  |             |                    |             | Date Type    |
|                     | Ops Number(s)                                                                                           |               |                                    |             |                 |     |                  |             |                    |             |              |
| 252135 <sup>U</sup> | Passenger Seats Attachments and Locking (Right Seat No. 2) - Detailed Inspection                        |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                     |                                                                                                         |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                     |                                                                                                         |               | MOS                                |             | 28.7            | 28  | 48               | 21 Dec 2023 | 31 Jan 2028*       | 29 Feb 2028 |              |
|                     |                                                                                                         |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe            |                                                                                                         |               |                                    |             |                 |     |                  |             |                    |             |              |
| 252140 <sup>U</sup> | Passenger Seats Attachments and Locking (Conference Table, Forward Inboard Seat) - Detailed Inspection  |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                     |                                                                                                         |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                     |                                                                                                         |               | MOS                                |             | 28.7            | 28  | 48               | 21 Dec 2023 | 31 Jan 2028*       | 29 Feb 2028 |              |
|                     |                                                                                                         |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe            |                                                                                                         |               |                                    |             |                 |     |                  |             |                    |             |              |
| 252141 <sup>U</sup> | Passenger Seats Attachments and Locking (Conference Table, Forward Outboard Seat) - Detailed Inspection |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                     |                                                                                                         |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                     |                                                                                                         |               | MOS                                |             | 28.7            | 28  | 48               | 21 Dec 2023 | 31 Jan 2028*       | 29 Feb 2028 |              |
|                     |                                                                                                         |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe            |                                                                                                         |               |                                    |             |                 |     |                  |             |                    |             |              |
| 252142 <sup>U</sup> | Passenger Seats Attachments and Locking (Conference Table, Aft Inboard Seat) - Detailed Inspection      |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                     |                                                                                                         |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                     |                                                                                                         |               | MOS                                |             | 28.7            | 28  | 48               | 21 Dec 2023 | 31 Jan 2028*       | 29 Feb 2028 |              |
|                     |                                                                                                         |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe            |                                                                                                         |               |                                    |             |                 |     |                  |             |                    |             |              |
| 252143 <sup>U</sup> | Passenger Seats Attachments and Locking (Conference Table, Aft Outboard Seat) - Detailed Inspection     |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                     |                                                                                                         |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                     |                                                                                                         |               | MOS                                |             | 28.7            | 28  | 48               | 21 Dec 2023 | 31 Jan 2028*       | 29 Feb 2028 |              |
|                     |                                                                                                         |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe            |                                                                                                         |               |                                    |             |                 |     |                  |             |                    |             |              |
| 252148 <sup>U</sup> | Passenger Seats Attachments and Locking (Right Divan Seat No. 1) - Detailed Inspection                  |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                     |                                                                                                         |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                     |                                                                                                         |               | MOS                                |             | 28.7            | 28  | 48               | 21 Dec 2023 | 31 Jan 2028*       | 29 Feb 2028 |              |
|                     |                                                                                                         |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe            |                                                                                                         |               |                                    |             |                 |     |                  |             |                    |             |              |
| 252149 <sup>U</sup> | Passenger Seats Attachments and Locking (Right Divan Seat No. 2) - Detailed Inspection                  |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                     |                                                                                                         |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                     |                                                                                                         |               | MOS                                |             | 28.7            | 28  | 48               | 21 Dec 2023 | 31 Jan 2028*       | 29 Feb 2028 |              |
|                     |                                                                                                         |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe            |                                                                                                         |               |                                    |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom     | Description                                                                                             |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due     | Avg Man Hrs  |
|---------------------|---------------------------------------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|---------------------|-------------|--------------|
|                     | Part Number                                                                                             | Serial Number |                                    |             |                 |     |                  |             |                     |             | Approx Price |
| Logbook Position    | HW                                                                                                      | SW            |                                    |             |                 |     |                  |             |                     |             | Manufacturer |
|                     | MM Ref                                                                                                  |               |                                    |             |                 |     |                  |             |                     |             | Date Type    |
|                     | Ops Number(s)                                                                                           |               |                                    |             |                 |     |                  |             |                     |             |              |
| 252150 <sup>U</sup> | Passenger Seats Attachments and Locking (Right Divan<br>Seat No. 3) - Detailed Inspection               |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                     |             | 0            |
|                     |                                                                                                         |               | AFL                                |             | 315             |     |                  | 802         |                     |             | 0            |
|                     |                                                                                                         |               | MOS                                |             | 28.7            | 28  | 48               | 21 Dec 2023 | 31 Jan 2028*        | 29 Feb 2028 |              |
|                     |                                                                                                         |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                     |             |              |
| Airframe            |                                                                                                         |               |                                    |             |                 |     |                  |             |                     |             |              |
| 252151 <sup>U</sup> | Passenger Seats Attachments and Locking (Right Divan<br>Seat No. 4) - Detailed Inspection               |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                     |             | 0            |
|                     |                                                                                                         |               | AFL                                |             | 315             |     |                  | 802         |                     |             | 0            |
|                     |                                                                                                         |               | MOS                                |             | 28.7            | 28  | 48               | 21 Dec 2023 | 31 Jan 2028*        | 29 Feb 2028 |              |
|                     |                                                                                                         |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                     |             |              |
| Airframe            |                                                                                                         |               |                                    |             |                 |     |                  |             |                     |             |              |
| 252152 <sup>U</sup> | Passenger Seats Attachments and Locking (Crew<br>Compartment Seat) - Detailed Inspection                |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                     |             | 0            |
|                     |                                                                                                         |               | AFL                                |             | 315             |     |                  | 802         |                     |             | 0            |
|                     |                                                                                                         |               | MOS                                |             | 28.7            | 28  | 48               | 21 Dec 2023 | 31 Jan 2028*        | 29 Feb 2028 |              |
|                     |                                                                                                         |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                     |             |              |
| Airframe            |                                                                                                         |               |                                    |             |                 |     |                  |             |                     |             |              |
| 252164              | Crew Rest Seat - Removal / Installation<br>G6CMF24RS.A10                      6112420083                |               | HRS                                |             | 3033.8          |     |                  | 12.3        |                     |             | 0            |
|                     |                                                                                                         |               | AFL                                |             | 1112            |     |                  | 5           |                     |             | 0            |
|                     |                                                                                                         |               | MOS                                |             | 124.2           |     |                  | 05 Jan 2016 |                     |             | RCO          |
|                     |                                                                                                         |               | MSC                                |             |                 |     | O/C              |             |                     |             |              |
| Airframe            |                                                                                                         |               |                                    |             |                 |     |                  |             |                     |             |              |
| 252165              | Cabin Seat (Left Seat No. 1) - Removal / Installation<br>G6SMA28LS.D01                      5222870003  |               | HRS                                |             | 2762.2          |     |                  | 283.9       |                     |             | 0            |
|                     |                                                                                                         |               | AFL                                |             | 1041            |     |                  | 76          |                     |             | 0            |
|                     |                                                                                                         |               | MOS                                |             | 112.9           |     |                  | 14 Dec 2016 |                     |             | RCO          |
|                     |                                                                                                         |               | MSC                                |             |                 |     | O/C              |             |                     |             |              |
| Airframe            |                                                                                                         |               |                                    |             |                 |     |                  |             |                     |             |              |
| 252166              | Cabin Seat (Left Seat No. 2) - Removal / Installation<br>G6SMF28LS.D01                      5212870032  |               | HRS                                |             | 2762.2          |     |                  | 283.9       |                     |             | 0            |
|                     |                                                                                                         |               | AFL                                |             | 1041            |     |                  | 76          |                     |             | 0            |
|                     |                                                                                                         |               | MOS                                |             | 112.9           |     |                  | 14 Dec 2016 |                     |             | RCO          |
|                     |                                                                                                         |               | MSC                                |             |                 |     | O/C              |             |                     |             |              |
| Airframe            |                                                                                                         |               |                                    |             |                 |     |                  |             |                     |             |              |
| 252171              | Cabin Seat (Right Seat No. 1) - Removal / Installation<br>G6SMA28RS.D01                      5222880003 |               | HRS                                |             | 2762.2          |     |                  | 283.9       |                     |             | 0            |
|                     |                                                                                                         |               | AFL                                |             | 1041            |     |                  | 76          |                     |             | 0            |
|                     |                                                                                                         |               | MOS                                |             | 112.9           |     |                  | 14 Dec 2016 |                     |             | RCO          |
|                     |                                                                                                         |               | MSC                                |             |                 |     | O/C              |             |                     |             |              |
| Airframe            |                                                                                                         |               |                                    |             |                 |     |                  |             |                     |             |              |
| 252172              | Cabin Seat (Right Seat No. 2) - Removal / Installation<br>G6SMF28RS.D01                      5212880030 |               | HRS                                |             | 2762.2          |     |                  | 283.9       |                     |             | 0            |
|                     |                                                                                                         |               | AFL                                |             | 1041            |     |                  | 76          |                     |             | 0            |
|                     |                                                                                                         |               | MOS                                |             | 112.9           |     |                  | 15 Dec 2016 |                     |             | RCO          |
|                     |                                                                                                         |               | MSC                                |             |                 |     | O/C              |             |                     |             |              |
| Airframe            |                                                                                                         |               |                                    |             |                 |     |                  |             |                     |             |              |

| ATA<br>U=Custom  | Description                                            |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|--------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                            | Serial Number |     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                     | SW            |     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                 |               |     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                          |               |     |             |                 |     |                  |             |                     |         |              |
| 252177           | Fwd Double Seat - Removal / Installation               |               | HRS |             | 3033.8          |     |                  | 12.3        |                     |         | 0            |
|                  | G6DMF45LS.A00                                          | 7114510097    | AFL |             | 1112            |     |                  | 5           |                     |         | 0            |
|                  |                                                        |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                     |         | RCO          |
|                  | Airframe                                               |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| 252178           | Aft Double Seat - Removal / Installation               |               | HRS |             | 3033.8          |     |                  | 12.3        |                     |         | 0            |
|                  | G6DMA45LS.A00                                          | 7124510096    | AFL |             | 1112            |     |                  | 5           |                     |         | 0            |
|                  |                                                        |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                     |         | RCO          |
|                  | Airframe                                               |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| 252181           | Divan (Manual, Forward Right) - Removal / Installation |               | HRS |             | 3033.8          |     |                  | 12.3        |                     |         | 0            |
|                  | G6VMS77RS-000                                          | 4117720112    | AFL |             | 1112            |     |                  | 5           |                     |         | 0            |
|                  |                                                        |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                     |         | RCO          |
|                  | Airframe                                               |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| 252200           | Single Seat (Left Seat No. 1) - Adjustment / Test      |               | HRS |             | 2762.2          |     |                  | 283.9       |                     |         | 0            |
|                  |                                                        |               | AFL |             | 1041            |     |                  | 76          |                     |         | 0            |
|                  |                                                        |               | MOS |             | 112.9           |     |                  | 14 Dec 2016 |                     |         |              |
|                  | Airframe                                               |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| 252201           | Single Seat (Left Seat No. 2) - Adjustment / Test      |               | HRS |             | 2762.2          |     |                  | 283.9       |                     |         | 0            |
|                  |                                                        |               | AFL |             | 1041            |     |                  | 76          |                     |         | 0            |
|                  |                                                        |               | MOS |             | 112.9           |     |                  | 14 Dec 2016 |                     |         |              |
|                  | Airframe                                               |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| 252206           | Single Seat (Right Seat No. 1) - Adjustment / Test     |               | HRS |             | 2762.2          |     |                  | 283.9       |                     |         | 0            |
|                  |                                                        |               | AFL |             | 1041            |     |                  | 76          |                     |         | 0            |
|                  |                                                        |               | MOS |             | 112.9           |     |                  | 14 Dec 2016 |                     |         |              |
|                  | Airframe                                               |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| 252207           | Single Seat (Right Seat No. 2) - Adjustment / Test     |               | HRS |             | 2762.2          |     |                  | 283.9       |                     |         | 0            |
|                  |                                                        |               | AFL |             | 1041            |     |                  | 76          |                     |         | 0            |
|                  |                                                        |               | MOS |             | 112.9           |     |                  | 15 Dec 2016 |                     |         |              |
|                  | Airframe                                               |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| 252212           | Double Seat (Forward) - Adjustment / Test              |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                        |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  |                                                        |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  | Airframe                                               |               | MSC |             |                 |     | O/C              |             |                     |         |              |

| ATA<br>U=Custom  | Description                                                                                              |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|----------|---------------------|---------|--------------|
|                  | Part Number                                                                                              | Serial Number |     |             |                 |     |                  |          |                     |         | Approx Price |
| Logbook Position | HW                                                                                                       | SW            |     |             |                 |     |                  |          |                     |         | Manufacturer |
|                  | MM Ref                                                                                                   |               |     |             |                 |     |                  |          |                     |         | Date Type    |
|                  | Ops Number(s)                                                                                            |               |     |             |                 |     |                  |          |                     |         |              |
| 252213           | Double Seat (Aft) - Adjustment / Test                                                                    |               | HRS |             | 3046.1          |     |                  | 0        |                     |         | 0            |
|                  |                                                                                                          |               | AFL |             | 1117            |     | 0                |          | 0                   |         |              |
|                  |                                                                                                          |               | MOS |             | 128.6           |     | 24 Aug 2015      |          |                     |         |              |
|                  |                                                                                                          |               | MSC |             |                 | O/C |                  |          |                     |         |              |
| 252300           | Pocket Door, Electric Fwd - Removal / Installation<br>42600-240L-101                      65211-4        |               | HRS |             | 3033.8          |     |                  | 12.3     |                     |         | 0            |
|                  |                                                                                                          |               | AFL |             | 1112            |     | 5                |          | 0                   |         |              |
|                  |                                                                                                          |               | MOS |             | 124.2           |     | 05 Jan 2016      |          | ENFLITE             |         |              |
|                  |                                                                                                          |               | MSC |             |                 | O/C |                  |          |                     |         |              |
| 252301           | Pocket Door, Electric Aft - Removal / Installation<br>42600-210L-006                      65474-1        |               | HRS |             | 3033.8          |     |                  | 12.3     |                     |         | 0            |
|                  |                                                                                                          |               | AFL |             | 1112            |     | 5                |          | 0                   |         |              |
|                  |                                                                                                          |               | MOS |             | 124.2           |     | 05 Jan 2016      |          | ENFLITE             |         |              |
|                  |                                                                                                          |               | MSC |             |                 | O/C |                  |          |                     |         |              |
| 252302           | Pocket Door, Electric Mid - Removal / Installation<br>42600-240L-107                      65031-2        |               | HRS |             | 3033.8          |     |                  | 12.3     |                     |         | 0            |
|                  |                                                                                                          |               | AFL |             | 1112            |     | 5                |          | 0                   |         |              |
|                  |                                                                                                          |               | MOS |             | 124.2           |     | 05 Jan 2016      |          | ENFLITE             |         |              |
|                  |                                                                                                          |               | MSC |             |                 | O/C |                  |          |                     |         |              |
| 252325           | Electric Console Table, Crew Rest - Removal / Installation<br>83650-22R-101                      65440-1 |               | HRS |             | 3033.8          |     |                  | 12.3     |                     |         | 0            |
|                  |                                                                                                          |               | AFL |             | 1112            |     | 5                |          | 0                   |         |              |
|                  |                                                                                                          |               | MOS |             | 124.2           |     | 05 Jan 2016      |          | ENFLITE             |         |              |
|                  |                                                                                                          |               | MSC |             |                 | O/C |                  |          |                     |         |              |
| 252326           | Electric Console Table, Left #1- Removal / Installation<br>83650-28-101                      65098-4     |               | HRS |             | 3033.8          |     |                  | 12.3     |                     |         | 0            |
|                  |                                                                                                          |               | AFL |             | 1112            |     | 5                |          | 0                   |         |              |
|                  |                                                                                                          |               | MOS |             | 124.2           |     | 05 Jan 2016      |          | ENFLITE             |         |              |
|                  |                                                                                                          |               | MSC |             |                 | O/C |                  |          |                     |         |              |
| 252329           | Electric Console Table, Right #1 - Removal / Installation<br>83650-28-101                      65098-3   |               | HRS |             | 3033.8          |     |                  | 12.3     |                     |         | 0            |
|                  |                                                                                                          |               | AFL |             | 1112            |     | 5                |          | 0                   |         |              |
|                  |                                                                                                          |               | MOS |             | 124.2           |     | 05 Jan 2016      |          | ENFLITE             |         |              |
|                  |                                                                                                          |               | MSC |             |                 | O/C |                  |          |                     |         |              |
| 252332           | Conference Table - Removal / Installation<br>80150-01                      65509-1                       |               | HRS |             | 3033.8          |     |                  | 12.3     |                     |         | 0            |
|                  |                                                                                                          |               | AFL |             | 1112            |     | 5                |          | 0                   |         |              |
|                  |                                                                                                          |               | MOS |             | 124.2           |     | 05 Jan 2016      |          | ENFLITE             |         |              |
|                  |                                                                                                          |               | MSC |             |                 | O/C |                  |          |                     |         |              |
| Airframe         |                                                                                                          |               |     |             |                 |     |                  |          |                     |         |              |

| ATA<br>U=Custom  | Description                                                                       |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|-----------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                                                       | Serial Number |     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                                                | SW            |     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                                            |               |     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                                                     |               |     |             |                 |     |                  |             |                     |         |              |
| 252400           | Window Shade Assembly (Left Window No. 1) - Removal / Installation                |               | HRS |             | 3033.8          |     |                  | 12.3        |                     |         | 0            |
|                  |                                                                                   |               | AFL |             | 1112            |     |                  | 5           |                     |         | 0            |
|                  | ATG25F009                                                                         | 8218-101      | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                     |         | ATG          |
|                  |                                                                                   |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                   |               |     |             |                 |     |                  |             |                     |         |              |
| 252401           | Window Shade Assembly (Left Window No. 2) - Removal / Installation                |               | HRS |             | 3033.8          |     |                  | 12.3        |                     |         | 0            |
|                  |                                                                                   |               | AFL |             | 1112            |     |                  | 5           |                     |         | 0            |
|                  | ATG25F009                                                                         | 8218-103      | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                     |         | ATG          |
|                  |                                                                                   |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                   |               |     |             |                 |     |                  |             |                     |         |              |
| 252402           | Window Shade Assembly (Left Window No. 3) - Removal / Installation                |               | HRS |             | 3033.8          |     |                  | 12.3        |                     |         | 0            |
|                  |                                                                                   |               | AFL |             | 1112            |     |                  | 5           |                     |         | 0            |
|                  | ATG25F009                                                                         | 8218-105      | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                     |         | ATG          |
|                  |                                                                                   |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                   |               |     |             |                 |     |                  |             |                     |         |              |
| 252403           | Window Shade Assembly (Left Window No. 4) - Removal / Installation                |               | HRS |             | 3033.8          |     |                  | 12.3        |                     |         | 0            |
|                  |                                                                                   |               | AFL |             | 1112            |     |                  | 5           |                     |         | 0            |
|                  | ATG25F009                                                                         | 8218-107      | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                     |         | ATG          |
|                  |                                                                                   |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                   |               |     |             |                 |     |                  |             |                     |         |              |
| 252404           | Emergency Exit Window Shade Assembly (Left Window No. 5) - Removal / Installation |               | HRS | TSN:412.6   | 2621.2          |     |                  | 424.9       |                     |         | 0            |
|                  |                                                                                   |               | AFL | TSN:103     | 1009            |     |                  | 108         |                     |         | 0            |
|                  | ATG25F010                                                                         | 8218-501      | MOS | TSN:17      | 107.2           |     |                  | 06 Jun 2017 |                     |         | ATG          |
|                  |                                                                                   |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                   |               |     |             |                 |     |                  |             |                     |         |              |
| 252405           | Emergency Exit Window Shade Assembly (Left Window No. 6) - Removal / Installation |               | HRS |             | 3033.8          |     |                  | 12.3        |                     |         | 0            |
|                  |                                                                                   |               | AFL |             | 1112            |     |                  | 5           |                     |         | 0            |
|                  | ATG25F010                                                                         | 8218-503      | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                     |         | ATG          |
|                  |                                                                                   |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                   |               |     |             |                 |     |                  |             |                     |         |              |
| 252406           | Window Shade Assembly (Left Window No. 7) - Removal / Installation                |               | HRS |             | 3033.8          |     |                  | 12.3        |                     |         | 0            |
|                  |                                                                                   |               | AFL |             | 1112            |     |                  | 5           |                     |         | 0            |
|                  | ATG25F009                                                                         | 8218-109      | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                     |         | ATG          |
|                  |                                                                                   |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                   |               |     |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom  | Description                                                                        |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                        | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                                 | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                             |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                                      |               |     |             |                 |     |                  |             |                    |         |              |
| 252407           | Window Shade Assembly (Left Window No. 8) - Removal / Installation                 |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  |                                                                                    |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  | ATG25F009                                                                          | 8218-111      | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | ATG          |
|                  |                                                                                    |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                    |               |     |             |                 |     |                  |             |                    |         |              |
| 252408           | Window Shade Assembly (Right Window No. 1) - Removal / Installation                |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  |                                                                                    |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  | ATG25F009                                                                          | 8218-102      | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | ATG          |
|                  |                                                                                    |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                    |               |     |             |                 |     |                  |             |                    |         |              |
| 252409           | Window Shade Assembly (Right Window No. 2) - Removal / Installation                |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  |                                                                                    |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  | ATG25F009                                                                          | 8218-104      | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | ATG          |
|                  |                                                                                    |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                    |               |     |             |                 |     |                  |             |                    |         |              |
| 252410           | Window Shade Assembly (Right Window No. 3) - Removal / Installation                |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  |                                                                                    |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  | ATG25F009                                                                          | 8218-106      | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | ATG          |
|                  |                                                                                    |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                    |               |     |             |                 |     |                  |             |                    |         |              |
| 252411           | Window Shade Assembly (Right Window No. 4) - Removal / Installation                |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  |                                                                                    |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  | ATG25F009                                                                          | 8218-108      | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | ATG          |
|                  |                                                                                    |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                    |               |     |             |                 |     |                  |             |                    |         |              |
| 252412           | Emergency Exit Window Shade Assembly (Right Window No. 5) - Removal / Installation |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  |                                                                                    |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  | ATG25T010                                                                          | 8218-502      | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | ATG          |
|                  |                                                                                    |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                    |               |     |             |                 |     |                  |             |                    |         |              |
| 252413           | Emergency Exit Window Shade Assembly (Right Window No. 6) - Removal / Installation |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  |                                                                                    |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  | ATG25T010                                                                          | 8218-504      | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | ATG          |
|                  |                                                                                    |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                    |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                         |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|---------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                         | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                  | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                              |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| 252414           | Window Shade Assembly (Right Window No. 7) - Removal / Installation |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  |                                                                     |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  | ATG25F009                                                           | 8218-110      | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | ATG          |
|                  |                                                                     |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| 252415           | Window Shade Assembly (Right Window No. 8) - Removal / Installation |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  |                                                                     |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  | ATG25F009                                                           | 8218-112      | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | ATG          |
|                  |                                                                     |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| 252416           | Lh Cockpit Window Shade                                             |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 1-6151-100                                                          | 339           | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                     |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                     |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| 252417           | Rh Cockpit Window Shade                                             |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 1-6152-100                                                          | 324           | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                     |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                     |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| 252444           | Window Shade (Right Window No. 5) - Adjustment / Test               |               | HRS |             | 2621.2          |     |                  | 424.9       |                    |         | 0            |
|                  |                                                                     |               | AFL |             | 1009            |     |                  | 108         |                    |         | 0            |
|                  |                                                                     |               | MOS |             | 107.2           |     |                  | 06 Jun 2017 |                    |         |              |
|                  |                                                                     |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| 252662           | Console Table - Adjustment / Test                                   |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  |                                                                     |               | AFL |             | 315             |     |                  | 802         |                    |         | 0            |
|                  |                                                                     |               | MOS |             | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
|                  |                                                                     |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| 252667           | Switch Panel Control, Aft Bed Cabinet - Removal / Installation      |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  |                                                                     |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  | RCO36790                                                            | 0941          | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | RCO          |
|                  |                                                                     |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                     |               |     |             |                 |     |                  |             |                    |         |              |



| ATA<br>U=Custom  | Description                                                    |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                    | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                             | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                         |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                  |               |     |             |                 |     |                  |             |                    |         |              |
| 252668           | Switch Panel Control, Fwd Bed Cabinet - Removal / Installation |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  |                                                                |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  | RCO36790                                                       | 1053          | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | RCO          |
|                  |                                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| 252700           | Passenger Service Unit (Crew Compartment) - Servicing          |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| 253202           | Water Tank, Coffee/Espresso Maker - Removal / Installation     |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  |                                                                |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  | HFWTBAA15-0100                                                 | 05104         | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | IACOBUCCI    |
|                  |                                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| 253210           | Espresso Maker (No. 1) - Removal / Installation                |               | HRS |             | 2120.8          |     |                  | 925.3       |                    |         | 0            |
|                  | HFE2005-30 5456                                                |               | AFL |             | 861             |     |                  | 256         |                    |         | 0            |
|                  |                                                                |               | MOS |             | 86              |     |                  | 12 Mar 2019 |                    |         | IACOBUCCI    |
|                  |                                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| 253212           | RAIL, Coffee Maker / Espresso Machine                          |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  | HFRLBAA15-0100 10109                                           |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  |                                                                |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | IACOBUCCI    |
|                  |                                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| 253302           | Refrigerator - Removal / Installation                          |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  | DRF-1000-103 DRF103-194                                        |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  |                                                                |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | DYNAMO       |
|                  |                                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| 253700           | Oven - Removal / Installation                                  |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  | 91155-003 65695-1                                              |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  |                                                                |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | ENFLITE      |
|                  |                                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| 253701           | Microwave Oven - Removal / Installation                        |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  | DMO-1000-103 DMO103-184T                                       |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  |                                                                |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | ENFLITE      |
|                  |                                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom                  | Description                                               |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W                             | Next Due<br>(* =Adj) | Max Due | Avg Man Hrs  |
|----------------------------------|-----------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|--------------------------------------|----------------------|---------|--------------|
|                                  | Part Number                                               | Serial Number |                                    |             |                 |     |                  |                                      |                      |         | Approx Price |
| Logbook Position                 | HW                                                        | SW            |                                    |             |                 |     |                  |                                      |                      |         | Manufacturer |
|                                  | MM Ref                                                    |               |                                    |             |                 |     |                  |                                      |                      |         | Date Type    |
|                                  | Ops Number(s)                                             |               |                                    |             |                 |     |                  |                                      |                      |         |              |
| 256000                           | Flashlight (Pilot) - Removal / Installation               |               | HRS                                | TSN:2051.9  | 994.2           |     |                  | 2051.9                               |                      |         | 0            |
|                                  | FLOX43553                                                 | 1409-05A      | AFL                                | TSN:725     | 392             |     |                  | 725                                  |                      |         | 0            |
|                                  |                                                           |               | MOS                                | TSN:87      | 41.4            |     |                  | 29 Nov 2022                          |                      |         |              |
|                                  | Airframe                                                  |               | MSC                                |             |                 |     | O/C              |                                      |                      |         |              |
| 256001                           | Flashlight (Copilot) - Removal / Installation             |               | HRS                                | TSN:2082.1  | 964             |     |                  | 2082.1                               |                      |         | 0            |
|                                  | FLOX43553                                                 | 13499-04A     | AFL                                | TSN:736     | 381             |     |                  | 736                                  |                      |         | 0            |
|                                  |                                                           |               | MOS                                | TSN:89      | 39.7            |     |                  | 20 Jan 2023                          |                      |         |              |
|                                  | Airframe                                                  |               | MSC                                |             |                 |     | O/C              |                                      |                      |         |              |
| 256003                           | Flashlight (Baggage Compartment) - Removal / Installation |               | HRS                                | TSN:2069.8  | 964             |     |                  | 2082.1                               |                      |         | 0            |
|                                  | FLOX43553                                                 | 14902-02      | AFL                                | TSN:731     | 381             |     |                  | 736                                  |                      |         | 0            |
|                                  |                                                           |               | MOS                                | TSN:84      | 39.7            |     |                  | 20 Jan 2023                          |                      |         |              |
|                                  | Airframe                                                  |               | MSC                                |             |                 |     | O/C              |                                      |                      |         |              |
| 256005                           | Flashlight Batteries (Observer) - Discard                 |               | HRS                                |             | 3046.1          |     |                  | 0                                    |                      |         | 0            |
|                                  | PN                                                        | SN-UNKNOWN    | AFL                                |             | 1117            |     |                  | 0                                    |                      |         | 0            |
|                                  |                                                           |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015                          |                      |         |              |
|                                  | Airframe                                                  |               | MSC                                |             |                 |     | O/C              |                                      |                      |         |              |
| 256006                           | Flashlight (Observer) - Operational Check                 |               | HRS                                |             | 137             |     |                  | 2909.1                               |                      |         | 0            |
|                                  |                                                           |               | AFL                                |             | 52              |     |                  | 1065                                 |                      |         | 0            |
|                                  |                                                           |               | MOS                                |             | 5.5             | 2   | 12               | 27 Nov 2025 30 Nov 2026* 31 Dec 2026 |                      |         |              |
|                                  | Airframe                                                  |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |                                      |                      |         |              |
| Notes: PN: FLOX43553 SN: <NONE>. |                                                           |               |                                    |             |                 |     |                  |                                      |                      |         |              |
| 256007                           | Flashlight (Pilot) - Operational Check                    |               | HRS                                |             | 137             |     |                  | 2909.1                               |                      |         | 0            |
|                                  |                                                           |               | AFL                                |             | 52              |     |                  | 1065                                 |                      |         | 0            |
|                                  |                                                           |               | MOS                                |             | 5.5             | -2  | 12               | 27 Nov 2025 30 Nov 2026* 31 Dec 2026 |                      |         |              |
|                                  | Airframe                                                  |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |                                      |                      |         |              |
| 052010                           |                                                           |               |                                    |             |                 |     |                  |                                      |                      |         |              |
| 256008                           | Flashlight Batteries (Pilot) - Discard                    |               | HRS                                |             | 3046.1          |     |                  | 0                                    |                      |         | 0            |
|                                  | PN                                                        | SN-UNKNOWN    | AFL                                |             | 1117            |     |                  | 0                                    |                      |         | 0            |
|                                  |                                                           |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015                          |                      |         |              |
|                                  | Airframe                                                  |               | MSC                                |             |                 |     | O/C              |                                      |                      |         |              |
| 256009                           | Flashlight Batteries (Copilot) - Discard                  |               | HRS                                |             | 3046.1          |     |                  | 0                                    |                      |         | 0            |
|                                  | PN                                                        | SN-UNKNOWN    | AFL                                |             | 1117            |     |                  | 0                                    |                      |         | 0            |
|                                  |                                                           |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015                          |                      |         |              |
|                                  | Airframe                                                  |               | MSC                                |             |                 |     | O/C              |                                      |                      |         |              |

| ATA<br>U=Custom  | Description                                                 |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W                 | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|--------------------------|--------------------|---------|--------------|
|                  | Part Number                                                 | Serial Number |                                    |             |                 |     |                  |                          |                    |         | Approx Price |
| Logbook Position | HW                                                          | SW            |                                    |             |                 |     |                  |                          |                    |         | Manufacturer |
|                  | MM Ref                                                      |               |                                    |             |                 |     |                  |                          |                    |         | Date Type    |
|                  | Ops Number(s)                                               |               |                                    |             |                 |     |                  |                          |                    |         |              |
| 256010           | Flashlight Batteries (Baggage Compartment) - Discard        |               | HRS                                |             | 3046.1          |     |                  | 0                        |                    |         | 0            |
|                  | PN                                                          | SN-UNKNOWN    | AFL                                |             | 1117            |     |                  | 0                        |                    |         | 0            |
|                  |                                                             |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015              |                    |         |              |
|                  | Airframe                                                    |               | MSC                                |             |                 |     | O/C              |                          |                    |         |              |
| 256014           | Flashlight (Copilot) - Operational Check                    |               | HRS                                |             | 137             |     |                  | 2909.1                   |                    |         | 0            |
|                  |                                                             |               | AFL                                |             | 52              |     |                  | 1065                     |                    |         | 0            |
|                  |                                                             |               | MOS                                |             | 5.5             | 2   | 12               | 27 Nov 2025 30 Nov 2026* | 31 Dec 2026        |         |              |
|                  | Airframe                                                    |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |                          |                    |         |              |
|                  | 052010                                                      |               |                                    |             |                 |     |                  |                          |                    |         |              |
| 256015           | Flashlight (Baggage Compartment) - Operational Check        |               | HRS                                |             | 137             |     |                  | 2909.1                   |                    |         | 0            |
|                  |                                                             |               | AFL                                |             | 52              |     |                  | 1065                     |                    |         | 0            |
|                  |                                                             |               | MOS                                |             | 5.5             | 2   | 12               | 27 Nov 2025 30 Nov 2026* | 31 Dec 2026        |         |              |
|                  | Airframe                                                    |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |                          |                    |         |              |
|                  | 052010                                                      |               |                                    |             |                 |     |                  |                          |                    |         |              |
| 256016           | Flashlight (Observer) - Removal / Installation              |               | HRS                                | TSN:2082.1  | 964             |     |                  | 2082.1                   |                    |         | 0            |
|                  | FLOX43553                                                   | 13785-04A     | AFL                                | TSN:736     | 381             |     |                  | 736                      |                    |         | 0            |
|                  |                                                             |               | MOS                                | TSN:89      | 39.7            |     |                  | 20 Jan 2023              |                    |         |              |
|                  | Airframe                                                    |               | MSC                                |             |                 |     | O/C              |                          |                    |         |              |
| 256060           | Flashlight Charger Base (Pilot) - Removal / Installation    |               | HRS                                |             | 3046.1          |     |                  | 0                        |                    |         | 0            |
|                  | FLCOX43554                                                  | 14125-05      | AFL                                |             | 1117            |     |                  | 0                        |                    |         | 0            |
|                  |                                                             |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015              |                    |         |              |
|                  | Airframe                                                    |               | MSC                                |             |                 |     | O/C              |                          |                    |         |              |
| 256061           | Flashlight Charger Base (Copilot) - Removal / Installation  |               | HRS                                |             | 3046.1          |     |                  | 0                        |                    |         | 0            |
|                  | FLCOX43554                                                  | 14595-02      | AFL                                |             | 1117            |     |                  | 0                        |                    |         | 0            |
|                  |                                                             |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015              |                    |         |              |
|                  | Airframe                                                    |               | MSC                                |             |                 |     | O/C              |                          |                    |         |              |
| 256062           | Flashlight Charger Base (Observer) - Removal / Installation |               | HRS                                |             | 3033.8          |     |                  | 12.3                     |                    |         | 0            |
|                  |                                                             |               | AFL                                |             | 1112            |     |                  | 5                        |                    |         | 0            |
|                  | FLCOX43554                                                  | 14787-01      | MOS                                |             | 124.2           |     |                  | 05 Jan 2016              |                    |         | OXLEY        |
|                  | Airframe                                                    |               | MSC                                |             |                 |     | O/C              |                          |                    |         |              |
| 256063           | Flashlight Charger Base (Baggage) - Removal / Installation  |               | HRS                                |             | 3046.1          |     |                  | 0                        |                    |         | 0            |
|                  |                                                             |               | AFL                                |             | 1117            |     |                  | 0                        |                    |         | 0            |
|                  | FLCOX43554                                                  | 14125-04      | MOS                                |             | 128.6           |     |                  | 24 Aug 2015              |                    |         |              |
|                  | Airframe                                                    |               | MSC                                |             |                 |     | O/C              |                          |                    |         |              |

| ATA<br>U=Custom  | Description                       |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|-----------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                       | Serial Number |     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                | SW            |     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                            |               |     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                     |               |     |             |                 |     |                  |             |                     |         |              |
| 256070           | Life Vest (Pilot) - Restore       |               | HRS |             | 730.5           |     |                  | 2315.6      |                     |         | 0            |
|                  | 63600-505                         |               | AFL |             | 315             |     |                  | 802         |                     |         | 0            |
|                  | L5553348                          |               | MOS | TSN:17      | 28.7            |     | 120              | 21 Dec 2023 | 01 Aug 2032         |         |              |
|                  | Airframe                          |               |     |             |                 |     |                  |             |                     |         | EXPIRATION   |
| 256071           | Life Vest (Copilot) - Restore     |               | HRS |             | 137             |     |                  | 2909.1      |                     |         | 0            |
|                  | 63600-505                         |               | AFL |             | 52              |     |                  | 1065        |                     |         | 0            |
|                  | L2386620                          |               | MOS |             | 5.3             |     | 120              | 02 Dec 2025 | 19 Jan 2034         |         |              |
|                  | Airframe                          |               |     |             |                 |     |                  |             |                     |         | EXPIRATION   |
| 256072           | Life Vest (Observer) - Restore    |               | HRS |             | 137             |     |                  | 2909.1      |                     |         | 0            |
|                  | 63600-505                         |               | AFL |             | 52              |     |                  | 1065        |                     |         | 0            |
|                  | L1777715                          |               | MOS |             | 5.3             |     | 120              | 02 Dec 2025 | 02 Mar 2032         |         |              |
|                  | Airframe                          |               |     |             |                 |     |                  |             |                     |         | EXPIRATION   |
| 256073           | Life Vest (Crew Member) - Restore |               | HRS |             | 730.5           |     |                  | 2315.6      |                     |         | 0            |
|                  | 63600-505                         |               | AFL |             | 315             |     |                  | 802         |                     |         | 0            |
|                  | L5368365                          |               | MOS | TSN:25      | 28.7            |     | 120              | 21 Dec 2023 | 31 Dec 2031         |         |              |
|                  | Airframe                          |               |     |             |                 |     |                  |             |                     |         | EXPIRATION   |
| 256074           | Life Vest (No. 1) - Restore       |               | HRS |             | 137             |     |                  | 2909.1      |                     |         | 0            |
|                  | 63600-105                         |               | AFL |             | 52              |     |                  | 1065        |                     |         | 0            |
|                  | L5718406                          |               | MOS |             | 5.2             |     | 120              | 05 Dec 2025 | 08 Oct 2035         |         |              |
|                  | Airframe                          |               |     |             |                 |     |                  |             |                     |         | EXPIRATION   |
| 256075           | Life Vest (No. 2) - Restore       |               | HRS |             | 137             |     |                  | 2909.1      |                     |         | 0            |
|                  | 63600-105                         |               | AFL |             | 52              |     |                  | 1065        |                     |         | 0            |
|                  | L5929098                          |               | MOS |             | 5.2             |     | 120              | 05 Dec 2025 | 22 Oct 2034         |         |              |
|                  | Airframe                          |               |     |             |                 |     |                  |             |                     |         | EXPIRATION   |
| 256076           | Life Vest (No. 3) - Restore       |               | HRS |             | 137             |     |                  | 2909.1      |                     |         | 0            |
|                  | 63600-105                         |               | AFL |             | 52              |     |                  | 1065        |                     |         | 0            |
|                  | L5718409                          |               | MOS |             | 5.2             |     | 120              | 05 Dec 2025 | 08 Oct 2035         |         |              |
|                  | Airframe                          |               |     |             |                 |     |                  |             |                     |         | EXPIRATION   |
| 256077           | Life Vest (No. 4) - Restore       |               | HRS |             | 137             |     |                  | 2909.1      |                     |         | 0            |
|                  | 63600-105                         |               | AFL |             | 52              |     |                  | 1065        |                     |         | 0            |
|                  | L2708719                          |               | MOS |             | 5.2             |     | 120              | 05 Dec 2025 | 22 Oct 2034         |         |              |
|                  | Airframe                          |               |     |             |                 |     |                  |             |                     |         | EXPIRATION   |

| ATA<br>U=Custom  | Description                  |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                  | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                           | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                       |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                |               |     |             |                 |     |                  |             |                    |         |              |
| 256078           | Life Vest (No. 5) - Restore  |               | HRS |             | 137             |     |                  | 2909.1      |                    |         | 0            |
|                  | 63600-105                    |               | AFL |             | 52              |     |                  | 1065        |                    |         | 0            |
|                  | L5631032                     |               | MOS |             | 5.2             |     | 120              | 05 Dec 2025 | 08 Oct 2035        |         |              |
|                  | Airframe                     |               |     |             |                 |     |                  |             |                    |         | EXPIRATION   |
| 256079           | Life Vest (No. 6) - Restore  |               | HRS |             | 137             |     |                  | 2909.1      |                    |         | 0            |
|                  | 63600-105                    |               | AFL |             | 52              |     |                  | 1065        |                    |         | 0            |
|                  | L2444944                     |               | MOS |             | 5.2             |     | 120              | 05 Dec 2025 | 18 Jul 2033        |         |              |
|                  | Airframe                     |               |     |             |                 |     |                  |             |                    |         | EXPIRATION   |
| 256080           | Life Vest (No. 7) - Restore  |               | HRS |             | 137             |     |                  | 2909.1      |                    |         | 0            |
|                  | 63600-105                    |               | AFL |             | 52              |     |                  | 1065        |                    |         | 0            |
|                  | L2708728                     |               | MOS |             | 5.2             |     | 120              | 05 Dec 2025 | 22 Oct 2034        |         |              |
|                  | Airframe                     |               |     |             |                 |     |                  |             |                    |         | EXPIRATION   |
| 256081           | Life Vest (No. 8) - Restore  |               | HRS |             | 137             |     |                  | 2909.1      |                    |         | 0            |
|                  | 63600-105                    |               | AFL |             | 52              |     |                  | 1065        |                    |         | 0            |
|                  | L2708753                     |               | MOS |             | 5.2             |     | 120              | 05 Dec 2025 | 22 Oct 2034        |         |              |
|                  | Airframe                     |               |     |             |                 |     |                  |             |                    |         | EXPIRATION   |
| 256082           | Life Vest (No. 9) - Restore  |               | HRS |             | 137             |     |                  | 2909.1      |                    |         | 0            |
|                  | 63600-105                    |               | AFL |             | 52              |     |                  | 1065        |                    |         | 0            |
|                  | L5929093                     |               | MOS |             | 5.2             |     | 120              | 05 Dec 2025 | 22 Oct 2034        |         |              |
|                  | Airframe                     |               |     |             |                 |     |                  |             |                    |         | EXPIRATION   |
| 256083           | Life Vest (No. 10) - Restore |               | HRS |             | 137             |     |                  | 2909.1      |                    |         | 0            |
|                  | 63600-105                    |               | AFL |             | 52              |     |                  | 1065        |                    |         | 0            |
|                  | L2708752                     |               | MOS |             | 5.2             |     | 120              | 05 Dec 2025 | 22 Oct 2034        |         |              |
|                  | Airframe                     |               |     |             |                 |     |                  |             |                    |         | EXPIRATION   |
| 256084           | Life Vest (No. 11) - Restore |               | HRS |             | 137             |     |                  | 2909.1      |                    |         | 0            |
|                  | 63600-105                    |               | AFL |             | 52              |     |                  | 1065        |                    |         | 0            |
|                  | L4248662                     |               | MOS |             | 5.2             |     | 120              | 05 Dec 2025 | 22 Oct 2034        |         |              |
|                  | Airframe                     |               |     |             |                 |     |                  |             |                    |         | EXPIRATION   |
| 256085           | Life Vest (No. 12) - Restore |               | HRS |             | 562.4           |     |                  | 2483.7      |                    |         | 0            |
|                  | 00002260                     |               | AFL |             | 217             |     |                  | 900         |                    |         | 0            |
|                  | 1597-073                     |               | MOS | TSN:194     | 16.8            |     |                  | 16 Dec 2024 | 31 Oct 2028        |         |              |
|                  | Airframe                     |               | MSC |             |                 |     | N/A              |             |                    |         |              |

| ATA<br>U=Custom  | Description                                      |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|--------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                      | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                               | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                           |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                    |               |     |             |                 |     |                  |             |                    |         |              |
| 256086           | Life Vest (No. 13) - Restore                     |               | HRS |             | 562.4           |     |                  | 2483.7      |                    |         | 0            |
|                  | 00002143                                         | 16075-014     | AFL |             | 217             |     |                  | 900         |                    |         | 0            |
|                  |                                                  |               | MOS | TSN:194     | 16.8            |     |                  | 16 Dec 2024 | 01 Dec 2027        |         |              |
|                  | Airframe                                         |               | MSC |             |                 |     | N/A              |             |                    |         |              |
| 256100           | Life Vest (Pilot) - Removal / Installation       |               | HRS |             | 562.4           |     |                  | 2483.7      |                    |         | 0            |
|                  | 63600-505                                        | L3112482      | AFL |             | 217             |     |                  | 900         |                    |         | 0            |
|                  |                                                  |               | MOS | TSN:62      | 17.5            |     |                  | 26 Nov 2024 |                    |         |              |
|                  | Airframe                                         |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 256101           | Life Vest (Copilot) - Removal / Installation     |               | HRS |             | 137             |     |                  | 2909.1      |                    |         | 0            |
|                  | 63600-505                                        | L2386620      | AFL |             | 52              |     |                  | 1065        |                    |         | 0            |
|                  |                                                  |               | MOS |             | 5.3             |     |                  | 02 Dec 2025 |                    |         |              |
|                  | Airframe                                         |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 256102           | Life Vest (Observer) - Removal / Installation    |               | HRS |             | 137             |     |                  | 2909.1      |                    |         | 0            |
|                  | 63600-505                                        | L1777715      | AFL |             | 52              |     |                  | 1065        |                    |         | 0            |
|                  |                                                  |               | MOS |             | 5.3             |     |                  | 02 Dec 2025 |                    |         |              |
|                  | Airframe                                         |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 256103           | Life Vest (Crew Member) - Removal / Installation |               | HRS | TSN:168.066 | 562.4           |     |                  | 2483.7      |                    |         | 0            |
|                  | 63600-505                                        | L5368365      | AFL | TSN:98      | 217             |     |                  | 900         |                    |         | 0            |
|                  |                                                  |               | MOS | TSN:36      | 17.5            |     |                  | 26 Nov 2024 |                    |         |              |
|                  | Airframe                                         |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 256104           | Life Vest (No. 1) - Removal / Installation       |               | HRS |             | 137             |     |                  | 2909.1      |                    |         | 0            |
|                  | 63600-105                                        | L5718406      | AFL |             | 52              |     |                  | 1065        |                    |         | 0            |
|                  |                                                  |               | MOS |             | 5.2             |     |                  | 05 Dec 2025 |                    |         |              |
|                  | Airframe                                         |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 256105           | Life Vest (No. 2) - Removal / Installation       |               | HRS |             | 137             |     |                  | 2909.1      |                    |         | 0            |
|                  | 63600-105                                        | L3111664      | AFL |             | 52              |     |                  | 1065        |                    |         | 0            |
|                  |                                                  |               | MOS |             | 5.2             |     |                  | 05 Dec 2025 |                    |         |              |
|                  | Airframe                                         |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 256106           | Life Vest (No. 3) - Removal / Installation       |               | HRS |             | 137             |     |                  | 2909.1      |                    |         | 0            |
|                  | 63600-105                                        | L5718409      | AFL |             | 52              |     |                  | 1065        |                    |         | 0            |
|                  |                                                  |               | MOS |             | 5.2             |     |                  | 05 Dec 2025 |                    |         |              |
|                  | Airframe                                         |               | MSC |             |                 |     | O/C              |             |                    |         |              |

| ATA<br>U=Custom  | Description                                 |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|---------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                 | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                          | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                      |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                               |               |     |             |                 |     |                  |             |                    |         |              |
| 256107           | Life Vest (No. 4) - Removal / Installation  |               | HRS |             | 137             |     |                  | 2909.1      |                    |         | 0            |
|                  | 63600-105                                   | L2708719      | AFL |             | 52              |     |                  | 1065        |                    |         | 0            |
|                  |                                             |               | MOS |             | 5.2             |     |                  | 05 Dec 2025 |                    |         |              |
|                  | Airframe                                    |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 256108           | Life Vest (No. 5) - Removal / Installation  |               | HRS |             | 137             |     |                  | 2909.1      |                    |         | 0            |
|                  | 63600-105                                   | L5631032      | AFL |             | 52              |     |                  | 1065        |                    |         | 0            |
|                  |                                             |               | MOS |             | 5.2             |     |                  | 05 Dec 2025 |                    |         |              |
|                  | Airframe                                    |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 256109           | Life Vest (No. 6) - Removal / Installation  |               | HRS |             | 137             |     |                  | 2909.1      |                    |         | 0            |
|                  | 63600-105                                   | L2444944      | AFL |             | 52              |     |                  | 1065        |                    |         | 0            |
|                  |                                             |               | MOS |             | 5.2             |     |                  | 05 Dec 2025 |                    |         |              |
|                  | Airframe                                    |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 256110           | Life Vest (No. 7) - Removal / Installation  |               | HRS |             | 137             |     |                  | 2909.1      |                    |         | 0            |
|                  | 63600-105                                   | L2708728      | AFL |             | 52              |     |                  | 1065        |                    |         | 0            |
|                  |                                             |               | MOS |             | 5.2             |     |                  | 05 Dec 2025 |                    |         |              |
|                  | Airframe                                    |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 256111           | Life Vest (No. 8) - Removal / Installation  |               | HRS |             | 137             |     |                  | 2909.1      |                    |         | 0            |
|                  | 63600-105                                   | L2708753      | AFL |             | 52              |     |                  | 1065        |                    |         | 0            |
|                  |                                             |               | MOS |             | 5.2             |     |                  | 05 Dec 2025 |                    |         |              |
|                  | Airframe                                    |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 256112           | Life Vest (No. 9) - Removal / Installation  |               | HRS |             | 137             |     |                  | 2909.1      |                    |         | 0            |
|                  | 63600-105                                   | L5929093      | AFL |             | 52              |     |                  | 1065        |                    |         | 0            |
|                  |                                             |               | MOS |             | 5.2             |     |                  | 05 Dec 2025 |                    |         |              |
|                  | Airframe                                    |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 256113           | Life Vest (No. 10) - Removal / Installation |               | HRS |             | 137             |     |                  | 2909.1      |                    |         | 0            |
|                  | 63600-105                                   | L2708752      | AFL |             | 52              |     |                  | 1065        |                    |         | 0            |
|                  |                                             |               | MOS |             | 5.2             |     |                  | 05 Dec 2025 |                    |         |              |
|                  | Airframe                                    |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 256114           | Life Vest (No. 11) - Removal / Installation |               | HRS |             | 137             |     |                  | 2909.1      |                    |         | 0            |
|                  | 63600-105                                   | L4248662      | AFL |             | 52              |     |                  | 1065        |                    |         | 0            |
|                  |                                             |               | MOS |             | 5.2             |     |                  | 05 Dec 2025 |                    |         |              |
|                  | Airframe                                    |               | MSC |             |                 |     | O/C              |             |                    |         |              |

| ATA<br>U=Custom                             | Description                                 |               | UOM | Times Since    | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due     | Avg Man Hrs  |
|---------------------------------------------|---------------------------------------------|---------------|-----|----------------|-----------------|-----|------------------|-------------|---------------------|-------------|--------------|
|                                             | Part Number                                 | Serial Number |     |                |                 |     |                  |             |                     |             | Approx Price |
| Logbook Position                            | HW                                          | SW            |     |                |                 |     |                  |             |                     |             | Manufacturer |
|                                             | MM Ref                                      |               |     |                |                 |     |                  |             |                     |             | Date Type    |
|                                             | Ops Number(s)                               |               |     |                |                 |     |                  |             |                     |             |              |
| 256115                                      | Life Vest (No. 12) - Removal / Installation |               | HRS |                | 562.4           |     |                  | 2483.7      |                     |             | 0            |
|                                             | 00002260                                    | 1597-073      | AFL |                | 217             |     |                  | 900         |                     |             | 0            |
|                                             |                                             |               | MOS | TSN:194        | 16.8            |     |                  | 16 Dec 2024 |                     |             |              |
|                                             | Airframe                                    |               | MSC |                |                 |     | O/C              |             |                     |             |              |
| 256116                                      | Life Vest (No. 13) - Removal / Installation |               | HRS |                | 562.4           |     |                  | 2483.7      |                     |             | 0            |
|                                             | 00002143                                    | 16075-014     | AFL |                | 217             |     |                  | 900         |                     |             | 0            |
|                                             |                                             |               | MOS |                | 16.8            |     |                  | 16 Dec 2024 |                     |             |              |
|                                             | Airframe                                    |               | MSC |                |                 |     | O/C              |             |                     |             |              |
| 256135                                      | Life Raft (No. 1) - Removal /Installation   |               | HRS |                | 137             |     |                  | 2909.1      |                     |             | 0            |
|                                             | 1320FAUL-6K4-1-904                          | 13UL-01602    | AFL |                | 52              |     |                  | 1065        |                     |             | 0            |
|                                             |                                             |               | MOS |                | 5               |     |                  | 12 Dec 2025 |                     |             |              |
|                                             | Airframe                                    |               | MSC |                |                 |     | O/C              |             |                     |             |              |
| Notes: RAFT MOVED FROM AFT POSN TO FWD POSN |                                             |               |     |                |                 |     |                  |             |                     |             |              |
| 256136                                      | Life Raft (No. 2) - Removal /Installation   |               | HRS |                | 137             |     |                  | 2909.1      |                     |             | 0            |
|                                             | 1320FAUL-6K4-1-904                          | 13UL-01603    | AFL |                | 52              |     |                  | 1065        |                     |             | 0            |
|                                             |                                             |               | MOS |                | 5               |     |                  | 12 Dec 2025 |                     |             |              |
|                                             | Airframe                                    |               | MSC |                |                 |     | O/C              |             |                     |             |              |
| 256143                                      | Life Raft (No. 1) - Restore                 |               | HRS |                | 730.5           |     |                  | 2315.6      |                     |             | 0            |
|                                             | 1320FAUL-6K4-1-904                          | 13UL-01602    | AFL |                | 315             |     |                  | 802         |                     |             | 0            |
|                                             |                                             |               | MOS |                | 28.7            |     | 36               | 21 Dec 2023 | 31 Oct 2026         |             |              |
|                                             | Airframe                                    |               |     |                |                 |     |                  |             |                     |             | EXPIRATION   |
| Notes: History on 256146                    |                                             |               |     |                |                 |     |                  |             |                     |             |              |
| 256144                                      | Life Raft (No. 2) - Restore                 |               | HRS |                | 730.5           |     |                  | 2315.6      |                     |             | 0            |
|                                             | 1320FAUL-6K4-1-904                          | 13UL-01603    | AFL |                | 315             |     |                  | 802         |                     |             | 0            |
|                                             |                                             |               | MOS |                | 28.7            |     | 36               | 21 Dec 2023 | 31 Oct 2026         |             |              |
|                                             | Airframe                                    |               |     |                |                 |     |                  |             |                     |             | EXPIRATION   |
| Notes: History on 256145                    |                                             |               |     |                |                 |     |                  |             |                     |             |              |
| 256147                                      | Life Raft (No. 1) - Detailed Inspection     |               | HRS |                | 137             |     |                  | 2909.1      |                     |             | 0            |
|                                             |                                             |               | AFL |                | 52              |     |                  | 1065        |                     |             | 0            |
|                                             |                                             |               | MOS |                | 5               | -17 | 12               | 12 Dec 2025 | 25 Nov 2026*        | 25 Dec 2026 |              |
|                                             | Airframe                                    |               |     | [MOS: +1m/-1m] |                 |     |                  |             |                     |             |              |



| ATA<br>U=Custom  | Description                                       |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------|---------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                  | Part Number                                       | Serial Number |                                    |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position | HW                                                | SW            |                                    |             |                 |     |                  |             |                    |             | Manufacturer |
|                  | MM Ref                                            |               |                                    |             |                 |     |                  |             |                    |             | Date Type    |
|                  | Ops Number(s)                                     |               |                                    |             |                 |     |                  |             |                    |             |              |
| 256148           | Life Raft (No. 2) - Detailed Inspection           |               | HRS                                |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                  |                                                   |               | AFL                                |             | 52              |     |                  | 1065        |                    |             | 0            |
|                  |                                                   |               | MOS                                |             | 5               | -17 | 12               | 12 Dec 2025 | 25 Nov 2026*       | 25 Dec 2026 |              |
|                  | Airframe                                          |               | [MOS: +1m/-1m]                     |             |                 |     |                  |             |                    |             |              |
| 256181           | Life Vest(S) - Detailed Inspection                |               | HRS                                |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                  |                                                   |               | AFL                                |             | 52              |     |                  | 1065        |                    |             | 0            |
|                  |                                                   |               | MOS                                |             | 5.2             | -6  | 12               | 05 Dec 2025 | 30 Nov 2026*       | 31 Dec 2026 |              |
|                  | Airframe                                          |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| 256219           | Smoke Hood / Protective Breathing Equipment (Pbe) |               | HRS                                |             | 562.4           |     |                  | 2483.7      |                    |             | 0            |
|                  | (Pilot) - Discard                                 |               | AFL                                |             | 217             |     |                  | 900         |                    |             | 0            |
|                  | MR-10051N                                         | E2405009      | MOS                                | TSN:4       | 17.2            |     | 120              | 05 Dec 2024 | 28 Feb 2035        |             |              |
|                  | Airframe                                          |               | EXPIRATION                         |             |                 |     |                  |             |                    |             |              |
| 256220           | Smoke Hood / Protective Breathing Equipment (Pbe) |               | HRS                                |             |                 |     |                  |             |                    |             | 0            |
|                  | (Copilot) - Discard                               |               | AFL                                |             |                 |     |                  |             |                    |             | 0            |
|                  | PN                                                | SN-UNKNOWN    | MOS                                |             |                 |     |                  |             |                    |             |              |
|                  | Airframe                                          |               | MSC O/C                            |             |                 |     |                  |             |                    |             |              |
| 256221           | Smoke Hood / Protective Breathing Equipment (Pbe) |               | HRS                                |             |                 |     |                  |             |                    |             | 0            |
|                  | (Observer) - Discard                              |               | AFL                                |             |                 |     |                  |             |                    |             | 0            |
|                  | PN                                                | SN-UNKNOWN    | MOS                                |             |                 |     |                  |             |                    |             |              |
|                  | Airframe                                          |               | MSC O/C                            |             |                 |     |                  |             |                    |             |              |
| 256262           | Smoke Hood / Protective Breathing Equipment (Pbe) |               | HRS                                |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                  | (Pilot) - Visual Check                            |               | AFL                                |             | 52              |     |                  | 1065        |                    |             | 0            |
|                  |                                                   |               | MOS                                |             | 5.3             | 41  | 12               | 01 Dec 2025 | 11 Jan 2027*       | 11 Feb 2027 |              |
|                  | Airframe                                          |               | [MOS: +1m/-1m]                     |             |                 |     |                  |             |                    |             |              |
| 256271           | Observers Smoke Goggles / Detachable Facepiece    |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  | (Observers) - Detailed Inspection                 |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                   |               | MOS                                |             | 28.7            |     | 36               | 21 Dec 2023 | 31 Dec 2026        | 31 Jan 2027 |              |
|                  | Airframe                                          |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                   | 052012        |                                    |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom                  | Description                                                                          |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq        | Last C/W                             | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|----------------------------------|--------------------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|-------------------------|--------------------------------------|---------------------|---------|--------------|
|                                  | Part Number                                                                          | Serial Number |                                    |             |                 |     |                         |                                      |                     |         | Approx Price |
| Logbook Position                 | HW                                                                                   | SW            |                                    |             |                 |     |                         |                                      |                     |         | Manufacturer |
|                                  | MM Ref                                                                               |               |                                    |             |                 |     |                         |                                      |                     |         | Date Type    |
|                                  | Ops Number(s)                                                                        |               |                                    |             |                 |     |                         |                                      |                     |         |              |
| 256272                           | Smoke Hood / Protective Breathing Equipment (Pbe)<br>(Copilot) - Visual Check        |               | HRS                                |             | 3046.1          |     |                         | 0                                    |                     | 0       |              |
|                                  |                                                                                      |               | AFL                                |             | 1117            |     | 0                       |                                      | 0                   |         |              |
|                                  |                                                                                      |               | MOS                                |             | 122             |     | 11 Mar 2016             |                                      |                     |         |              |
|                                  |                                                                                      |               | MSC                                |             |                 | N/A |                         |                                      |                     |         |              |
| Airframe                         |                                                                                      |               |                                    |             |                 |     |                         |                                      |                     |         |              |
| 256273                           | Smoke Hood / Protective Breathing Equipment (Pbe) /<br>Pbe (Observer) - Visual Check |               | HRS                                |             | 3046.1          |     |                         | 0                                    |                     | 0       |              |
|                                  |                                                                                      |               | AFL                                |             | 1117            |     | 0                       |                                      | 0                   |         |              |
|                                  |                                                                                      |               | MOS                                |             | 122             |     | 11 Mar 2016             |                                      |                     |         |              |
|                                  |                                                                                      |               | MSC                                |             |                 | N/A |                         |                                      |                     |         |              |
| Airframe                         |                                                                                      |               |                                    |             |                 |     |                         |                                      |                     |         |              |
| 256294                           | Smoke Hood (Aft Lavatory) - Removal / Installation<br>MR10039N E1508076              |               | HRS                                |             | 3033.8          |     |                         | 12.3                                 |                     | 0       |              |
|                                  |                                                                                      |               | AFL                                |             | 1112            |     | 5                       |                                      | 0                   |         |              |
|                                  |                                                                                      |               | MOS                                |             | 124.2           |     | 06 Jan 2016             |                                      |                     |         |              |
|                                  |                                                                                      |               | MSC                                |             |                 | O/C |                         |                                      |                     |         |              |
| Airframe                         |                                                                                      |               |                                    |             |                 |     |                         |                                      |                     |         |              |
| 256295                           | Smoke Hood (Aft Lavatory) - Discard<br>MR-10039N E2410531                            |               | HRS                                |             | 137             |     |                         | 2909.1                               |                     | 0       |              |
|                                  |                                                                                      |               | AFL                                |             | 52              |     | 1065                    |                                      | 0                   |         |              |
|                                  |                                                                                      |               | MOS                                | TSN:8       | 5.2             |     | 05 Dec 2025 30 Sep 2035 |                                      |                     |         |              |
|                                  |                                                                                      |               | MSC                                |             |                 | DUE |                         |                                      | EXPIRATION          |         |              |
| Airframe                         |                                                                                      |               |                                    |             |                 |     |                         |                                      |                     |         |              |
| Notes: EXPIRES 2-2026            |                                                                                      |               |                                    |             |                 |     |                         |                                      |                     |         |              |
| 256296                           | Smoke Hood Tamper-Evident Seals (Aft Lavatory) -<br>Detailed Inspection              |               | HRS                                |             | 137             |     |                         | 2909.1                               |                     | 0       |              |
|                                  |                                                                                      |               | AFL                                |             | 52              |     | 1065                    |                                      | 0                   |         |              |
|                                  |                                                                                      |               | MOS                                |             | 5.2             | -10 | 12                      | 05 Dec 2025 30 Nov 2026* 31 Dec 2026 |                     |         |              |
|                                  |                                                                                      |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                         |                                      |                     |         |              |
| Airframe                         |                                                                                      |               |                                    |             |                 |     |                         |                                      |                     |         |              |
| Notes: PN: MR-10039N SN: <NONE>. |                                                                                      |               |                                    |             |                 |     |                         |                                      |                     |         |              |
| 256303                           | Emergency Locator Transmitter - Removal / Installation<br>453-5060 16071             |               | HRS                                |             | 562.4           |     |                         | 2483.7                               |                     | 0       |              |
|                                  |                                                                                      |               | AFL                                |             | 217             |     | 900                     |                                      | 0                   |         |              |
|                                  |                                                                                      |               | MOS                                |             | 17.5            |     | 26 Nov 2024             |                                      |                     |         |              |
|                                  |                                                                                      |               | MSC                                |             |                 | O/C |                         |                                      |                     |         |              |
| Airframe                         |                                                                                      |               |                                    |             |                 |     |                         |                                      |                     |         |              |
| 256304                           | ELT Transmitter Battery - Removal / Installation<br>452-0133 366510-072              |               | HRS                                |             | 3046.1          |     |                         | 0                                    |                     | 0       |              |
|                                  |                                                                                      |               | AFL                                |             | 1117            |     | 0                       |                                      | 0                   |         |              |
|                                  |                                                                                      |               | MOS                                | TSN:4       | 128.6           |     | 24 Aug 2015             |                                      |                     |         |              |
|                                  |                                                                                      |               | MSC                                |             |                 | O/C |                         |                                      |                     |         |              |
| Airframe                         |                                                                                      |               |                                    |             |                 |     |                         |                                      |                     |         |              |

| ATA<br>U=Custom                   | Description                                                    |                     | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|-----------------------------------|----------------------------------------------------------------|---------------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                   | Part Number                                                    | Serial Number       |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position                  | HW                                                             | SW                  |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                   | MM Ref                                                         |                     |     |             |                 |     |                  |             |                    |         | Date Type    |
|                                   | Ops Number(s)                                                  |                     |     |             |                 |     |                  |             |                    |         |              |
| 256307                            | Emergency Locator Transmitter - Detailed Inspection            |                     | HRS |             | 137             |     |                  | 2909.1      |                    |         | 0            |
|                                   |                                                                |                     | AFL |             | 52              |     |                  | 1065        |                    |         | 0            |
|                                   |                                                                |                     | MOS |             | 5.3             | -3  | 12               | 02 Dec 2025 | 30 Nov 2026*       |         |              |
| Airframe                          |                                                                | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
|                                   |                                                                | 052010              |     |             |                 |     |                  |             |                    |         |              |
| 256308                            | Emergency Locator Transmitter Battery Pack - Discard           |                     | HRS |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                                   | 452-0133                                                       | 397417-034          | AFL |             | 315             |     |                  | 802         |                    |         | 0            |
|                                   |                                                                |                     | MOS | TSN:14      | 31.1            |     | 60               | 08 Oct 2023 | 31 Oct 2027        |         |              |
| Airframe                          |                                                                | EXPIRATION          |     |             |                 |     |                  |             |                    |         |              |
| 256309                            | Emergency Locator Transmitter - Operational Check (FAR 91.207) |                     | HRS |             | 137             |     |                  | 2909.1      |                    |         | 0            |
|                                   |                                                                |                     | AFL |             | 52              |     |                  | 1065        |                    |         | 0            |
|                                   |                                                                |                     | MOS |             | 5.3             | -6  | 12               | 02 Dec 2025 | 30 Nov 2026*       |         |              |
|                                   |                                                                | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| Airframe                          |                                                                | 052010              |     |             |                 |     |                  |             |                    |         |              |
| Notes: BATTERY EXPIRATION 10-2020 |                                                                |                     |     |             |                 |     |                  |             |                    |         |              |
| 256310                            | Emergency Locator Transmitter - Functional Check               |                     | HRS |             | 562.4           |     |                  | 2483.7      |                    |         | 0            |
|                                   |                                                                |                     | AFL |             | 217             |     |                  | 900         |                    |         | 0            |
|                                   |                                                                |                     | MOS |             | 17.5            |     |                  | 26 Nov 2024 |                    |         |              |
| Airframe                          |                                                                | MSC O/C             |     |             |                 |     |                  |             |                    |         |              |
| 256313                            | Emergency Locator Transmitter Antenna - Removal / Installation |                     | HRS | TSN:1745.4  | 1300.7          |     |                  | 1745.4      |                    |         | 0            |
|                                   |                                                                |                     | AFL | TSN:610     | 507             |     |                  | 610         |                    |         | 0            |
|                                   | 110-341                                                        | 50518               | MOS | TSN:77      | 51.7            |     |                  | 19 Jan 2022 |                    |         |              |
| Airframe                          |                                                                | MSC O/C             |     |             |                 |     |                  |             |                    |         |              |
| 256315                            | Emergency Locator Transmitter Antenna - Functional Test        |                     | HRS |             | 1300.7          |     |                  | 1745.4      |                    |         | 0            |
|                                   |                                                                |                     | AFL |             | 507             |     |                  | 610         |                    |         | 0            |
|                                   |                                                                |                     | MOS |             | 51.4            |     |                  | 31 Jan 2022 |                    |         |              |
| Airframe                          |                                                                | MSC O/C             |     |             |                 |     |                  |             |                    |         |              |
| 256316                            | Emergency Locator Transmitter Buzzer - Functional Test         |                     | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                   |                                                                |                     | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                   |                                                                |                     | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                          |                                                                | MSC O/C             |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom                | Description                                           |                     | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W                 | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|--------------------------------|-------------------------------------------------------|---------------------|------------------------------------|-------------|-----------------|-----|------------------|--------------------------|---------------------|---------|--------------|
|                                | Part Number                                           | Serial Number       |                                    |             |                 |     |                  |                          |                     |         | Approx Price |
| Logbook Position               | HW                                                    | SW                  |                                    |             |                 |     |                  |                          |                     |         | Manufacturer |
|                                | MM Ref                                                |                     |                                    |             |                 |     |                  |                          |                     |         | Date Type    |
|                                | Ops Number(s)                                         |                     |                                    |             |                 |     |                  |                          |                     |         |              |
| 256320                         | ELT Programming Adapter - Removal / Installation      |                     | HRS                                |             | 3033.8          |     |                  | 12.3                     |                     |         | 0            |
|                                | 453-5068                                              | 366424-013          | AFL                                |             | 1112            |     |                  | 5                        |                     |         | 0            |
|                                |                                                       |                     | MOS                                |             | 124.2           |     |                  | 05 Jan 2016              |                     |         | ACR          |
|                                | Airframe                                              |                     | MSC                                |             |                 |     | O/C              |                          |                     |         | ELECTRONICS  |
| 256400                         | First AID Kit (No. 1) - Removal / Installation        |                     | HRS                                |             | 251.5           |     |                  | 2794.6                   |                     |         | 0            |
|                                | AFAK 1.0                                              | 101515005           | AFL                                |             | 95              |     |                  | 1022                     |                     |         | 0            |
|                                |                                                       |                     | MOS                                |             | 8.3             |     |                  | 01 Sep 2025              |                     |         |              |
|                                | Airframe                                              |                     | MSC                                |             |                 |     | O/C              |                          |                     |         |              |
| 256404                         | First AID Kit (No. 1) - Detailed Inspection           |                     | HRS                                |             | 137             |     |                  | 2909.1                   |                     |         | 0            |
|                                |                                                       |                     | AFL                                |             | 52              |     |                  | 1065                     |                     |         | 0            |
|                                |                                                       |                     | MOS                                |             | 5.3             | -5  | 12               | 01 Dec 2025 30 Nov 2026* | 31 Dec 2026         |         |              |
|                                | Airframe                                              |                     | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |                          |                     |         |              |
| Notes: PN: AFAK SN: 101515005. |                                                       |                     |                                    |             |                 |     |                  |                          |                     |         |              |
| 256405                         | First AID Kit (No. 2) - Detailed Inspection           |                     | HRS                                |             | 3046.1          |     |                  | 0                        |                     |         | 0            |
|                                |                                                       |                     | AFL                                |             | 1117            |     |                  | 0                        |                     |         | 0            |
|                                |                                                       |                     | MOS                                |             | 122             |     |                  | 11 Mar 2016              |                     |         |              |
|                                | Airframe                                              |                     | MSC                                |             |                 |     | N/A              |                          |                     |         |              |
|                                |                                                       | [End Of Month Item] |                                    |             |                 |     |                  |                          |                     |         |              |
| 256406                         | First AID Kit (No. 1) Time Limited Supplies - Discard |                     | HRS                                |             | 251.5           |     |                  | 2794.6                   |                     |         | 0            |
|                                | AFAK 1.0                                              | 101515005           | AFL                                |             | 95              |     |                  | 1022                     |                     |         | 0            |
|                                |                                                       |                     | MOS                                |             | 8.3             |     | 12               | 01 Sep 2025 31 Aug 2026  |                     |         |              |
|                                | Airframe                                              |                     | [End Of Month Item] EXPIRATION     |             |                 |     |                  |                          |                     |         |              |
| 256416                         | Defibrillator - Removal / Installation                |                     | HRS                                | TSN:2471.46 | 562.4           |     |                  | 2483.7                   |                     |         | 0            |
|                                | 502861                                                | B15H-00458          | AFL                                | TSN:895     | 217             |     |                  | 900                      |                     |         | 0            |
|                                |                                                       |                     | MOS                                | TSN:119     | 17.2            |     |                  | 04 Dec 2024              |                     |         |              |
|                                | Airframe                                              |                     | MSC                                |             |                 |     | O/C              |                          |                     |         |              |
| 256418                         | Defibrillator - Detailed Inspection                   |                     | HRS                                |             | 137             |     |                  | 2909.1                   |                     |         | 0            |
|                                |                                                       |                     | AFL                                |             | 52              |     |                  | 1065                     |                     |         | 0            |
|                                |                                                       |                     | MOS                                |             | 5.2             | -6  | 12               | 05 Dec 2025 30 Nov 2026* | 31 Dec 2026         |         |              |
|                                | Airframe                                              |                     | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |                          |                     |         |              |
| Notes: PN: 502861 SN: <NONE>.  |                                                       |                     |                                    |             |                 |     |                  |                          |                     |         |              |
| 256419                         | Defibrillator Time Limited Supplies - Discard         |                     | HRS                                |             | 562.4           |     |                  | 2483.7                   |                     |         | 0            |
|                                | 502861                                                | B15H-00458          | AFL                                |             | 217             |     |                  | 900                      |                     |         | 0            |
|                                |                                                       |                     | MOS                                |             | 17.2            |     | 12               | 04 Dec 2024 01 Jan 2027  |                     |         |              |
|                                | Airframe                                              |                     | [End Of Month Item]                |             |                 |     |                  |                          |                     |         |              |

| ATA<br>U=Custom                                          | Description                                            |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|----------------------------------------------------------|--------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                                                          | Part Number                                            | Serial Number |                                    |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position                                         | HW                                                     | SW            |                                    |             |                 |     |                  |             |                    |             | Manufacturer |
|                                                          | MM Ref                                                 |               |                                    |             |                 |     |                  |             |                    |             | Date Type    |
|                                                          | Ops Number(s)                                          |               |                                    |             |                 |     |                  |             |                    |             |              |
| 256420                                                   | Defibrillator Battery - Removal / Installation         |               | HRS                                |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                                                          | 989803139301                                           | NSN           | AFL                                |             | 52              |     |                  | 1065        |                    |             | 0            |
|                                                          |                                                        |               | MOS                                |             | 5.2             |     |                  | 05 Dec 2025 |                    |             |              |
|                                                          | Airframe                                               |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| 256421                                                   | Defibrillator Battery (Spare) - Removal / Installation |               | HRS                                |             | 562.4           |     |                  | 2483.7      |                    |             | 0            |
|                                                          | M5070A                                                 | 208240566     | AFL                                |             | 217             |     |                  | 900         |                    |             | 0            |
|                                                          |                                                        |               | MOS                                |             | 16.8            |     |                  | 16 Dec 2024 | 31 Mar 2030        |             |              |
|                                                          | Airframe                                               |               | MSC                                |             |                 |     | -                |             |                    |             |              |
| 256422                                                   | Defibrillator Pads (SET 1) - Removal / Installation    |               | HRS                                |             | 562.4           |     |                  | 2483.7      |                    |             | 0            |
|                                                          | 989803139261                                           | SN-UNKNOWN    | AFL                                |             | 217             |     |                  | 900         |                    |             | 0            |
|                                                          |                                                        |               | MOS                                |             | 16.8            |     |                  | 16 Dec 2024 | 05 Jan 2027        |             |              |
|                                                          | Airframe                                               |               | MSC                                |             |                 |     | -                |             |                    |             |              |
| 256423                                                   | Defibrillator Pads (SET 2) - Removal / Installation    |               | HRS                                |             | 562.4           |     |                  | 2483.7      |                    |             | 0            |
|                                                          | 989803139261                                           | SN-UNKNOWN    | AFL                                |             | 217             |     |                  | 900         |                    |             | 0            |
|                                                          |                                                        |               | MOS                                |             | 16.8            |     |                  | 16 Dec 2024 | 05 Jan 2027        |             |              |
|                                                          | Airframe                                               |               | MSC                                |             |                 |     | -                |             |                    |             |              |
| 256608                                                   | Ditching Line - Detailed Inspection                    |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                                                          |                                                        |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                                                          |                                                        |               | MOS                                |             | 28.7            |     | 48               | 21 Dec 2023 | 31 Dec 2027        | 31 Jan 2028 |              |
|                                                          | Airframe                                               |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Notes: FOR S/N"S S02335912,S02362665,S02362658,S02357165 |                                                        |               |                                    |             |                 |     |                  |             |                    |             |              |
| 256611                                                   | FIRE / Crash Axe - Detailed Inspection                 |               | HRS                                |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                                                          |                                                        |               | AFL                                |             | 52              |     |                  | 1065        |                    |             | 0            |
|                                                          |                                                        |               | MOS                                |             | 5.3             | -2  | 12               | 01 Dec 2025 | 29 Nov 2026*       | 29 Dec 2026 |              |
|                                                          | Airframe                                               |               | [MOS: +1m/-1m]                     |             |                 |     |                  |             |                    |             |              |
| 052010                                                   |                                                        |               |                                    |             |                 |     |                  |             |                    |             |              |
| 257052                                                   | Underwater Acoustic Beacon (Aft Equipment Bay) -       |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                                                          | Operational Check                                      |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                                                          |                                                        |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                                                          | Airframe                                               |               | MSC                                |             |                 |     | N/A              |             |                    |             |              |
| 257053                                                   | Underwater Acoustic Beacon (Baggage Compartment) -     |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                                                          | Operational Check                                      |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                                                          |                                                        |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                                                          | Airframe                                               |               | MSC                                |             |                 |     | N/A              |             |                    |             |              |

| ATA<br>U=Custom                               | Description                                            |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|-----------------------------------------------|--------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                                               | Part Number                                            | Serial Number |     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position                              | HW                                                     | SW            |     |             |                 |     |                  |             |                     |         | Manufacturer |
|                                               | MM Ref                                                 |               |     |             |                 |     |                  |             |                     |         | Date Type    |
|                                               | Ops Number(s)                                          |               |     |             |                 |     |                  |             |                     |         |              |
| 257056                                        | Underwater Acoustic Beacon Battery (Aft Equipment Bay) |               | HRS |             |                 |     |                  |             |                     |         | 0            |
|                                               | - Restore                                              |               | AFL |             |                 |     |                  |             |                     |         | 0            |
|                                               | PN                                                     | SN-UNKNOWN    | MOS |             |                 |     |                  |             |                     |         |              |
|                                               |                                                        |               | MSC |             |                 |     | N/A              |             |                     |         |              |
| Airframe                                      |                                                        |               |     |             |                 |     |                  |             |                     |         |              |
| 257057                                        | Underwater Acoustic Beacon Battery (Baggage            |               | HRS |             |                 |     |                  |             |                     |         | 0            |
|                                               | Compartment) - Restore                                 |               | AFL |             |                 |     |                  |             |                     |         | 0            |
|                                               | PN                                                     | SN-UNKNOWN    | MOS |             |                 |     |                  |             |                     |         |              |
|                                               |                                                        |               | MSC |             |                 |     | N/A              |             |                     |         |              |
| Airframe                                      |                                                        |               |     |             |                 |     |                  |             |                     |         |              |
| 257206                                        | Tail Compartment Ladder - Removal / Installation       |               | HRS | TSN:8.7     | 3037.4          |     |                  | 8.7         |                     |         | 0            |
|                                               | 1159SCB750-401                                         | 1488          | AFL | TSN:4       | 1113            |     |                  | 4           |                     |         | 0            |
|                                               |                                                        |               | MOS | TSN:1       | 127.5           |     |                  | 28 Sep 2015 |                     |         |              |
|                                               |                                                        |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe                                      |                                                        |               |     |             |                 |     |                  |             |                     |         |              |
| 257208                                        | Tail Access Door- Removal / Installation               |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                                               | 60P5240051A016P01                                      | 6160          | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                                               |                                                        |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                                               |                                                        |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe                                      |                                                        |               |     |             |                 |     |                  |             |                     |         |              |
| 25-CUS-001 <sup>U</sup>                       | Paediatric Kit Removal/Installation                    |               | HRS |             | 1452            |     |                  | 1594.1      |                     |         | 0            |
|                                               |                                                        |               | AFL |             | 570             |     |                  | 547         |                     |         | 0            |
|                                               |                                                        |               | MOS |             | 63.6            |     |                  | 23 Jan 2021 |                     |         |              |
|                                               |                                                        |               | MSC |             |                 |     | -                |             |                     |         |              |
| Airframe                                      |                                                        |               |     |             |                 |     |                  |             |                     |         |              |
| Notes: PN: 851201/851311 SN: 080419-002LEW.   |                                                        |               |     |             |                 |     |                  |             |                     |         |              |
| 25-CUS-003 <sup>U</sup>                       | Emergency Fak Removal/Installation                     |               | HRS |             | 1300.7          |     |                  | 1745.4      |                     |         | 0            |
|                                               |                                                        |               | AFL |             | 507             |     |                  | 610         |                     |         | 0            |
|                                               |                                                        |               | MOS |             | 51.5            |     |                  | 26 Jan 2022 |                     |         |              |
|                                               |                                                        |               | MSC |             |                 |     | -                |             |                     |         |              |
| Airframe                                      |                                                        |               |     |             |                 |     |                  |             |                     |         |              |
| Notes: PN: 725095 / 725096 SN: 080419-001LEW. |                                                        |               |     |             |                 |     |                  |             |                     |         |              |
| 26 - FIRE Protection                          |                                                        |               |     |             |                 |     |                  |             |                     |         |              |
| 260300                                        | Smoke Evacuation Valve - Removal / Installation        |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                                               | GACSEV1VLV001-1                                        | 0205          | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                                               |                                                        |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                                               |                                                        |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe                                      |                                                        |               |     |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom  | Description                                                               |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------|---------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                  | Part Number                                                               | Serial Number |                                    |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position | HW                                                                        | SW            |                                    |             |                 |     |                  |             |                    |             | Manufacturer |
|                  | MM Ref                                                                    |               |                                    |             |                 |     |                  |             |                    |             | Date Type    |
|                  | Ops Number(s)                                                             |               |                                    |             |                 |     |                  |             |                    |             |              |
| 260302           | Baggage Compartment Smoke Evacuation System -<br>Operational Check        |               | HRS                                |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                  |                                                                           |               | AFL                                |             | 52              |     |                  | 1065        |                    |             | 0            |
|                  |                                                                           |               | MOS                                |             | 4.8             |     | 120              | 18 Dec 2025 | 31 Dec 2035        | 31 Jan 2036 |              |
|                  |                                                                           |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                           | 052018        |                                    |             |                 |     |                  |             |                    |             |              |
| 261102           | Engine FIRE and Heat Sensing (Left) - Functional Test                     |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                           |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                           |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                           |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                           |               |                                    |             |                 |     |                  |             |                    |             |              |
| 261103           | Engine FIRE and Heat Sensing (Right) - Functional Test                    |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                           |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                           |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                           |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                           |               |                                    |             |                 |     |                  |             |                    |             |              |
| 261104           | Engine Firewire (Left) - Continuity / Resistance Test                     |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                           |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                           |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                           |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                           |               |                                    |             |                 |     |                  |             |                    |             |              |
| 261105           | Engine Firewire (Right) - Continuity / Resistance Test                    |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                           |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                           |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                           |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                           |               |                                    |             |                 |     |                  |             |                    |             |              |
| 261106           | Engine FIRE Detection Assembly RAIL 1 (Left) - Removal<br>/ Installation  |               | HRS                                | TSN:2051.9  | 994.2           |     |                  | 2051.9      |                    |             | 0            |
|                  |                                                                           |               | AFL                                | TSN:725     | 392             |     |                  | 725         |                    |             | 0            |
|                  |                                                                           |               | MOS                                | TSN:88      | 41.2            |     |                  | 05 Dec 2022 |                    |             |              |
|                  |                                                                           |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                           |               |                                    |             |                 |     |                  |             |                    |             |              |
| 261107           | Engine FIRE Detection Assembly RAIL 1 (Right) -<br>Removal / Installation |               | HRS                                | TSN:2051.9  | 994.2           |     |                  | 2051.9      |                    |             | 0            |
|                  |                                                                           |               | AFL                                | TSN:725     | 392             |     |                  | 725         |                    |             | 0            |
|                  |                                                                           |               | MOS                                | TSN:88      | 41.1            |     |                  | 08 Dec 2022 |                    |             |              |
|                  |                                                                           |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                           |               |                                    |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom  | Description                                            |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|--------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                            | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                     | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                 |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                          |               |     |             |                 |     |                  |             |                    |         |              |
| 261108           | Engine FIRE Detection Assembly RAIL 2 (Left) - Removal |               | HRS | TSN:2051.9  | 994.2           |     |                  | 2051.9      |                    |         | 0            |
|                  | / Installation                                         |               | AFL | TSN:725     | 392             |     |                  | 725         |                    |         | 0            |
|                  | 51291-230                                              | 14-06-7035    | MOS | TSN:88      | 41.2            |     |                  | 05 Dec 2022 |                    |         |              |
|                  |                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 261109           | Engine FIRE Detection Assembly RAIL 2 (Right) -        |               | HRS | TSN:2051.9  | 994.2           |     |                  | 2051.9      |                    |         | 0            |
|                  | Removal / Installation                                 |               | AFL | TSN:725     | 392             |     |                  | 725         |                    |         | 0            |
|                  | 51291-230                                              | 15-04-7981    | MOS | TSN:88      | 41.1            |     |                  | 08 Dec 2022 |                    |         |              |
|                  |                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 261110           | Engine FIRE Detection Assembly RAIL 3 (Left) - Removal |               | HRS |             | 994.2           |     |                  | 2051.9      |                    |         | 0            |
|                  | / Installation                                         |               | AFL |             | 392             |     |                  | 725         |                    |         | 0            |
|                  | 51291-231                                              | 14-12-7637    | MOS |             | 41.2            |     |                  | 05 Dec 2022 |                    |         |              |
|                  |                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 261111           | Engine FIRE Detection Assembly RAIL 3 (Right) -        |               | HRS |             | 994.2           |     |                  | 2051.9      |                    |         | 0            |
|                  | Removal / Installation                                 |               | AFL |             | 392             |     |                  | 725         |                    |         | 0            |
|                  | 51291-231                                              | 14-12-7641    | MOS |             | 41.1            |     |                  | 08 Dec 2022 |                    |         |              |
|                  |                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 261112           | Engine FIRE Detection Assembly RAIL 4 (Left) - Removal |               | HRS |             | 994.2           |     |                  | 2051.9      |                    |         | 0            |
|                  | / Installation                                         |               | AFL |             | 392             |     |                  | 725         |                    |         | 0            |
|                  | 51291-232                                              | 15-03-7873    | MOS |             | 41.2            |     |                  | 05 Dec 2022 |                    |         |              |
|                  |                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 261113           | Engine FIRE Detection Assembly RAIL 4 (Right) -        |               | HRS |             | 994.2           |     |                  | 2051.9      |                    |         | 0            |
|                  | Removal / Installation                                 |               | AFL |             | 392             |     |                  | 725         |                    |         | 0            |
|                  | 51291-232                                              | 15-03-7861    | MOS |             | 41.1            |     |                  | 08 Dec 2022 |                    |         |              |
|                  |                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 261114           | Engine FIRE Detection Assembly RAIL 5 (Left) - Removal |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | / Installation                                         |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 51291-233                                              | 15-09-7915    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                        |               |     |             |                 |     |                  |             |                    |         |              |



| ATA<br>U=Custom  | Description                                                            |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due     | Avg Man Hrs  |
|------------------|------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|---------------------|-------------|--------------|
|                  | Part Number                                                            | Serial Number |                                    |             |                 |     |                  |             |                     |             | Approx Price |
| Logbook Position | HW                                                                     | SW            |                                    |             |                 |     |                  |             |                     |             | Manufacturer |
|                  | MM Ref                                                                 |               |                                    |             |                 |     |                  |             |                     |             | Date Type    |
|                  | Ops Number(s)                                                          |               |                                    |             |                 |     |                  |             |                     |             |              |
| 261115           | Engine FIRE Detection Assembly RAIL 5 (Right) - Removal / Installation |               | HRS                                |             | 3046.1          |     |                  | 0           |                     |             | 0            |
|                  |                                                                        |               | AFL                                |             | 1117            |     |                  | 0           |                     |             | 0            |
|                  | 51291-233                                                              | 15-03-7919    | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                     |             |              |
|                  |                                                                        |               | MSC                                |             |                 |     | O/C              |             |                     |             |              |
| Airframe         |                                                                        |               |                                    |             |                 |     |                  |             |                     |             |              |
| 261140           | Engine FIRE Detection Assembly RAIL (Left) - Removal / Installation    |               | HRS                                |             | 3046.1          |     |                  | 0           |                     |             | 0            |
|                  |                                                                        |               | AFL                                |             | 1117            |     |                  | 0           |                     |             | 0            |
|                  | 51291-234                                                              | 15-01-7666    | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                     |             |              |
|                  |                                                                        |               | MSC                                |             |                 |     | O/C              |             |                     |             |              |
| Airframe         |                                                                        |               |                                    |             |                 |     |                  |             |                     |             |              |
| 261141           | Engine FIRE Detection Assembly RAIL (Right) - Removal / Installation   |               | HRS                                |             | 3046.1          |     |                  | 0           |                     |             | 0            |
|                  |                                                                        |               | AFL                                |             | 1117            |     |                  | 0           |                     |             | 0            |
|                  | 51291-234                                                              | 15-01-7667    | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                     |             |              |
|                  |                                                                        |               | MSC                                |             |                 |     | O/C              |             |                     |             |              |
| Airframe         |                                                                        |               |                                    |             |                 |     |                  |             |                     |             |              |
| 261200           | Pylon FIRE and Heat (Left) - Functional Test                           |               | HRS                                |             | 3046.1          |     |                  | 0           |                     |             | 0            |
|                  |                                                                        |               | AFL                                |             | 1117            |     |                  | 0           |                     |             | 0            |
|                  |                                                                        |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                     |             |              |
|                  |                                                                        |               | MSC                                |             |                 |     | O/C              |             |                     |             |              |
| Airframe         |                                                                        |               |                                    |             |                 |     |                  |             |                     |             |              |
| 261201           | Pylon FIRE and Heat (Right) - Functional Test                          |               | HRS                                |             | 3046.1          |     |                  | 0           |                     |             | 0            |
|                  |                                                                        |               | AFL                                |             | 1117            |     |                  | 0           |                     |             | 0            |
|                  |                                                                        |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                     |             |              |
|                  |                                                                        |               | MSC                                |             |                 |     | O/C              |             |                     |             |              |
| Airframe         |                                                                        |               |                                    |             |                 |     |                  |             |                     |             |              |
| 261202           | Pylon Thermal Switch (Left) - Functional Check                         |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                     |             | 0            |
|                  |                                                                        |               | AFL                                |             | 315             |     |                  | 802         |                     |             | 0            |
|                  |                                                                        |               | MOS                                |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031         | 31 Jan 2032 |              |
|                  |                                                                        |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                     |             |              |
| Airframe         |                                                                        |               |                                    |             |                 |     |                  |             |                     |             |              |
| 052016           |                                                                        |               |                                    |             |                 |     |                  |             |                     |             |              |
| 261203           | Pylon Thermal Switch (Right) - Functional Check                        |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                     |             | 0            |
|                  |                                                                        |               | AFL                                |             | 315             |     |                  | 802         |                     |             | 0            |
|                  |                                                                        |               | MOS                                |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031         | 31 Jan 2032 |              |
|                  |                                                                        |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                     |             |              |
| Airframe         |                                                                        |               |                                    |             |                 |     |                  |             |                     |             |              |
| 052016           |                                                                        |               |                                    |             |                 |     |                  |             |                     |             |              |
| 261300           | APU FIRE Detection Loop - Removal / Installation                       |               | HRS                                |             | 3046.1          |     |                  | 0           |                     |             | 0            |
|                  |                                                                        |               | AFL                                |             | 1117            |     |                  | 0           |                     |             | 0            |
|                  | 6360-12-1000                                                           | 204170        | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                     |             |              |
|                  |                                                                        |               | MSC                                |             |                 |     | O/C              |             |                     |             |              |
| Airframe         |                                                                        |               |                                    |             |                 |     |                  |             |                     |             |              |

| ATA<br>U=Custom                           | Description                                                         |               | UOM            | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |  |  |
|-------------------------------------------|---------------------------------------------------------------------|---------------|----------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|--|--|
|                                           | Part Number                                                         | Serial Number |                |             |                 |     |                  |             |                    |         | Approx Price |  |  |
| Logbook Position                          | HW                                                                  | SW            |                |             |                 |     |                  |             |                    |         | Manufacturer |  |  |
|                                           | MM Ref                                                              |               |                |             |                 |     |                  |             |                    |         | Date Type    |  |  |
|                                           | Ops Number(s)                                                       |               |                |             |                 |     |                  |             |                    |         |              |  |  |
| 261302                                    | APU FIRE Detection Loop - Temperature Trip Point Check              |               | HRS            |             | 3046.1          |     |                  | 0           |                    |         | 0            |  |  |
|                                           |                                                                     |               | AFL            |             | 1117            |     |                  | 0           |                    | 0       |              |  |  |
|                                           |                                                                     |               | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |  |  |
|                                           |                                                                     |               | MSC            |             |                 |     | O/C              |             |                    |         |              |  |  |
| Airframe                                  |                                                                     |               |                |             |                 |     |                  |             |                    |         |              |  |  |
| Notes: PN: 6360-12-1000/450-7 SN: <NONE>. |                                                                     |               |                |             |                 |     |                  |             |                    |         |              |  |  |
| 261303                                    | APU FIRE Detection Loop - Continuity / Resistance Test              |               | HRS            |             | 3046.1          |     |                  | 0           |                    |         | 0            |  |  |
|                                           |                                                                     |               | AFL            |             | 1117            |     |                  | 0           |                    | 0       |              |  |  |
|                                           |                                                                     |               | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |  |  |
|                                           |                                                                     |               | MSC            |             |                 |     | O/C              |             |                    |         |              |  |  |
| Airframe                                  |                                                                     |               |                |             |                 |     |                  |             |                    |         |              |  |  |
| Notes: PN: 6360-12-1000/450-7 SN: <NONE>. |                                                                     |               |                |             |                 |     |                  |             |                    |         |              |  |  |
| 261304                                    | APU (FIRE) Shut-Down Circuit - Operational Check                    |               | HRS            |             | 730.5           |     | 2400             | 2315.6      | 4715.6             | 4765.6  | 0            |  |  |
|                                           |                                                                     |               | AFL            |             | 315             |     |                  | 802         |                    | 0       |              |  |  |
|                                           |                                                                     |               | MOS            |             | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |  |  |
|                                           |                                                                     |               | [HRS: +50/-50] |             |                 |     |                  |             |                    |         |              |  |  |
| Airframe                                  |                                                                     |               |                |             |                 |     |                  |             |                    |         |              |  |  |
| 052004                                    |                                                                     |               |                |             |                 |     |                  |             |                    |         |              |  |  |
| 261305                                    | APU Compartment FIRE Detect Loop - Operational Check                |               | HRS            |             | 730.5           |     | 2400             | 2315.6      | 4715.6             | 4765.6  | 0            |  |  |
|                                           |                                                                     |               | AFL            |             | 315             |     |                  | 802         |                    | 0       |              |  |  |
|                                           |                                                                     |               | MOS            |             | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |  |  |
|                                           |                                                                     |               | [HRS: +50/-50] |             |                 |     |                  |             |                    |         |              |  |  |
| Airframe                                  |                                                                     |               |                |             |                 |     |                  |             |                    |         |              |  |  |
| 052004                                    |                                                                     |               |                |             |                 |     |                  |             |                    |         |              |  |  |
| 261446                                    | Equipment Overheat Thermal Switch (Leer) - Functional Test          |               | HRS            |             | 3046.1          |     |                  | 0           |                    |         | 0            |  |  |
|                                           |                                                                     |               | AFL            |             | 1117            |     |                  | 0           |                    | 0       |              |  |  |
|                                           |                                                                     |               | MOS            |             | 122             |     |                  | 11 Mar 2016 |                    |         |              |  |  |
|                                           |                                                                     |               | MSC            |             |                 |     | O/C              |             |                    |         |              |  |  |
| Airframe                                  |                                                                     |               |                |             |                 |     |                  |             |                    |         |              |  |  |
| 261447                                    | Equipment Overheat Thermal Switch (Reer) - Functional Test          |               | HRS            |             | 3046.1          |     |                  | 0           |                    |         | 0            |  |  |
|                                           |                                                                     |               | AFL            |             | 1117            |     |                  | 0           |                    | 0       |              |  |  |
|                                           |                                                                     |               | MOS            |             | 122             |     |                  | 11 Mar 2016 |                    |         |              |  |  |
|                                           |                                                                     |               | MSC            |             |                 |     | O/C              |             |                    |         |              |  |  |
| Airframe                                  |                                                                     |               |                |             |                 |     |                  |             |                    |         |              |  |  |
| 261448                                    | Equipment Overheat Thermal Switch (Forward Floor) - Functional Test |               | HRS            |             | 3046.1          |     |                  | 0           |                    |         | 0            |  |  |
|                                           |                                                                     |               | AFL            |             | 1117            |     |                  | 0           |                    | 0       |              |  |  |
|                                           |                                                                     |               | MOS            |             | 122             |     |                  | 11 Mar 2016 |                    |         |              |  |  |
|                                           |                                                                     |               | MSC            |             |                 |     | O/C              |             |                    |         |              |  |  |
| Airframe                                  |                                                                     |               |                |             |                 |     |                  |             |                    |         |              |  |  |

| ATA<br>U=Custom  | Description                                                                    |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(* =Adj) | Max Due     | Avg Man Hrs  |
|------------------|--------------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|----------------------|-------------|--------------|
|                  | Part Number                                                                    | Serial Number |                                    |             |                 |     |                  |             |                      |             | Approx Price |
| Logbook Position | HW                                                                             | SW            |                                    |             |                 |     |                  |             |                      |             | Manufacturer |
|                  | MM Ref                                                                         |               |                                    |             |                 |     |                  |             |                      |             | Date Type    |
|                  | Ops Number(s)                                                                  |               |                                    |             |                 |     |                  |             |                      |             |              |
| 261449           | Equipment Overheat Thermal Switch (Forward Baggage Eer) - Functional Test      |               | HRS                                |             | 3046.1          |     |                  | 0           |                      |             | 0            |
|                  |                                                                                |               | AFL                                |             | 1117            |     |                  | 0           |                      | 0           |              |
|                  |                                                                                |               | MOS                                |             | 122             |     |                  | 11 Mar 2016 |                      |             |              |
|                  |                                                                                |               | MSC                                |             |                 |     | O/C              |             |                      |             |              |
| Airframe         |                                                                                |               |                                    |             |                 |     |                  |             |                      |             |              |
| 261450           | Aft Baggage Eer Overheat Thermal Switch - Functional Check                     |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                      |             | 0            |
|                  |                                                                                |               | AFL                                |             | 315             |     |                  | 802         |                      | 0           |              |
|                  |                                                                                |               | MOS                                |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031          | 31 Jan 2032 |              |
|                  |                                                                                |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                      |             |              |
| Airframe         |                                                                                |               |                                    |             |                 |     |                  |             |                      |             |              |
| 052016           |                                                                                |               |                                    |             |                 |     |                  |             |                      |             |              |
| 261451           | Baggage Compartment Below Floor Overheat Thermal Switch - Functional Check     |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                      |             | 0            |
|                  |                                                                                |               | AFL                                |             | 315             |     |                  | 802         |                      | 0           |              |
|                  |                                                                                |               | MOS                                |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031          | 31 Jan 2032 |              |
|                  |                                                                                |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                      |             |              |
| Airframe         |                                                                                |               |                                    |             |                 |     |                  |             |                      |             |              |
| 052016           |                                                                                |               |                                    |             |                 |     |                  |             |                      |             |              |
| 261452           | Aft Equipment Overheat Thermal Switch - Functional Check                       |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                      |             | 0            |
|                  |                                                                                |               | AFL                                |             | 315             |     |                  | 802         |                      | 0           |              |
|                  |                                                                                |               | MOS                                |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031          | 31 Jan 2032 |              |
|                  |                                                                                |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                      |             |              |
| Airframe         |                                                                                |               |                                    |             |                 |     |                  |             |                      |             |              |
| 052016           |                                                                                |               |                                    |             |                 |     |                  |             |                      |             |              |
| 261500           | FIRE Detection Control Box (Left) - Removal / Installation<br>51653-274 00968  |               | HRS                                |             | 3046.1          |     |                  | 0           |                      |             | 0            |
|                  |                                                                                |               | AFL                                |             | 1117            |     |                  | 0           |                      | 0           |              |
|                  |                                                                                |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                      |             |              |
|                  |                                                                                |               | MSC                                |             |                 |     | O/C              |             |                      |             |              |
| Airframe         |                                                                                |               |                                    |             |                 |     |                  |             |                      |             |              |
| 261501           | FIRE Detection Control Box (Right) - Removal / Installation<br>51653-274 00974 |               | HRS                                |             | 3046.1          |     |                  | 0           |                      |             | 0            |
|                  |                                                                                |               | AFL                                |             | 1117            |     |                  | 0           |                      | 0           |              |
|                  |                                                                                |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                      |             |              |
|                  |                                                                                |               | MSC                                |             |                 |     | O/C              |             |                      |             |              |
| Airframe         |                                                                                |               |                                    |             |                 |     |                  |             |                      |             |              |
| 261504           | FIRE Detection Control Box (Left) - Functional Test                            |               | HRS                                |             | 3046.1          |     |                  | 0           |                      |             | 0            |
|                  |                                                                                |               | AFL                                |             | 1117            |     |                  | 0           |                      | 0           |              |
|                  |                                                                                |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                      |             |              |
|                  |                                                                                |               | MSC                                |             |                 |     | O/C              |             |                      |             |              |
| Airframe         |                                                                                |               |                                    |             |                 |     |                  |             |                      |             |              |

| ATA<br>U=Custom                      | Description                                              |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|--------------------------------------|----------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                      | Part Number                                              | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position                     | HW                                                       | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                      | MM Ref                                                   |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                                      | Ops Number(s)                                            |               |     |             |                 |     |                  |             |                    |         |              |
| 261505                               | FIRE Detection Control Box (Right) - Functional Test     |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                      |                                                          |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                      |                                                          |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                      | Airframe                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 261525                               | Smoke Detection Unit - Removal / Installation            |               | HRS | TSN:12.3    | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                                      | 72-130001-006                                            | 11717         | AFL | TSN:5       | 1112            |     |                  | 5           |                    |         | 0            |
|                                      |                                                          |               | MOS | TSN:4       | 124.8           |     |                  | 17 Dec 2015 |                    |         |              |
|                                      | Airframe                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 261527                               | Smoke Detection Unit - Functional Test                   |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                                      |                                                          |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                                      |                                                          |               | MOS |             | 124.7           |     |                  | 19 Dec 2015 |                    |         |              |
|                                      | Airframe                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Notes: PN: 72-130001-006 SN: <NONE>. |                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| 261600                               | FIRE Detection and Indication - Functional Test          |               | HRS |             | 994.2           |     |                  | 2051.9      |                    |         | 0            |
|                                      |                                                          |               | AFL |             | 392             |     |                  | 725         |                    |         | 0            |
|                                      |                                                          |               | MOS |             | 40.9            |     |                  | 15 Dec 2022 |                    |         |              |
|                                      | Airframe                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 262100                               | Engine FIRE Pull Handle (Left) - Removal / Installation  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                      | D533-55-001                                              | 1018/05-2014  | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                      |                                                          |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                      | Airframe                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 262101                               | Engine FIRE Pull Handle (Right) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                      | D533-56-001                                              | 1268          | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                      |                                                          |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                      | Airframe                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 262102                               | Engine FIRE Bottle (Left) - Removal / Installation       |               | HRS |             | 137             |     |                  | 2909.1      |                    |         | 0            |
|                                      | 33600102-1                                               | 95933D1       | AFL |             | 52              |     |                  | 1065        |                    |         | 0            |
|                                      |                                                          |               | MOS |             | 5               |     |                  | 12 Dec 2025 |                    |         |              |
|                                      | Airframe                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 262103                               | Engine FIRE Bottle (Right) - Removal / Installation      |               | HRS |             | 137             |     |                  | 2909.1      |                    |         | 0            |
|                                      | 33600102-1                                               | 95934D1       | AFL |             | 52              |     |                  | 1065        |                    |         | 0            |
|                                      |                                                          |               | MOS |             | 5               |     |                  | 12 Dec 2025 |                    |         |              |
|                                      | Airframe                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |

| ATA<br>U=Custom                                            | Description                                                    |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------------------------------------------------|----------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                                                            | Part Number                                                    | Serial Number |                                    |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position                                           | HW                                                             | SW            |                                    |             |                 |     |                  |             |                    |             | Manufacturer |
|                                                            | MM Ref                                                         |               |                                    |             |                 |     |                  |             |                    |             | Date Type    |
|                                                            | Ops Number(s)                                                  |               |                                    |             |                 |     |                  |             |                    |             |              |
| 262104                                                     | Engine FIRE Extinguisher Bottle (Left) - Weight Check          |               | HRS                                |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                                                            |                                                                |               | AFL                                |             | 52              |     |                  | 1065        |                    |             | 0            |
|                                                            |                                                                |               | MOS                                |             | 5               | 31  | 60               | 12 Dec 2025 | 12 Jan 2031*       | 12 Feb 2031 |              |
|                                                            | Airframe                                                       |               | [MOS: +1m/-1m]                     |             |                 |     |                  |             |                    |             |              |
|                                                            |                                                                | 052014        |                                    |             |                 |     |                  |             |                    |             |              |
| 262105                                                     | Engine FIRE Extinguisher Bottle (Right) - Weight Check         |               | HRS                                |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                                                            |                                                                |               | AFL                                |             | 52              |     |                  | 1065        |                    |             | 0            |
|                                                            |                                                                |               | MOS                                |             | 5               | 31  | 60               | 12 Dec 2025 | 12 Jan 2031*       | 12 Feb 2031 |              |
|                                                            | Airframe                                                       |               | [MOS: +1m/-1m]                     |             |                 |     |                  |             |                    |             |              |
|                                                            |                                                                | 052014        |                                    |             |                 |     |                  |             |                    |             |              |
| 262106                                                     | Engine FIRE Bottle (Left) - (Hydrostatic) Functional Check     |               | HRS                                |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                                                            |                                                                |               | AFL                                |             | 52              |     |                  | 1065        |                    |             | 0            |
|                                                            |                                                                |               | MOS                                |             | 5               |     | 60               | 12 Dec 2025 | 31 Dec 2030        |             |              |
|                                                            | Airframe                                                       |               | [End Of Month Item] HYDRO CHECK    |             |                 |     |                  |             |                    |             |              |
| Notes: PN: 33600102-1 SN: 95933D1. MRI PARENT CODE: 262102 |                                                                |               |                                    |             |                 |     |                  |             |                    |             |              |
| 262107                                                     | Engine FIRE Bottle (Right) - (Hydrostatic) Functional Check    |               | HRS                                |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                                                            |                                                                |               | AFL                                |             | 52              |     |                  | 1065        |                    |             | 0            |
|                                                            |                                                                |               | MOS                                |             | 5               |     | 60               | 12 Dec 2025 | 31 Dec 2030        |             |              |
|                                                            | Airframe                                                       |               | [End Of Month Item] HYDRO CHECK    |             |                 |     |                  |             |                    |             |              |
| Notes: PN: 33600102-1 SN: 95934D1. MRI PARENT CODE: 262103 |                                                                |               |                                    |             |                 |     |                  |             |                    |             |              |
| 262108                                                     | Engine FIRE Bottle Pressure Switch (Left) - Operational Check  |               | HRS                                |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                                                            |                                                                |               | AFL                                |             | 52              |     |                  | 1065        |                    |             | 0            |
|                                                            |                                                                |               | MOS                                |             | 5               |     | 60               | 12 Dec 2025 | 31 Dec 2030        | 31 Jan 2031 |              |
|                                                            | Airframe                                                       |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
|                                                            |                                                                | 052014        |                                    |             |                 |     |                  |             |                    |             |              |
| 262109                                                     | Engine FIRE Bottle Pressure Switch (Right) - Operational Check |               | HRS                                |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                                                            |                                                                |               | AFL                                |             | 52              |     |                  | 1065        |                    |             | 0            |
|                                                            |                                                                |               | MOS                                |             | 5               |     | 60               | 12 Dec 2025 | 31 Dec 2030        | 31 Jan 2031 |              |
|                                                            | Airframe                                                       |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
|                                                            |                                                                | 052014        |                                    |             |                 |     |                  |             |                    |             |              |
| 262112                                                     | Engine FIRE Pull Handle (Left) - Functional Test               |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                                                            |                                                                |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                                                            |                                                                |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                                                            | Airframe                                                       |               | MSC O/C                            |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom  | Description                                                                                      |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|--------------------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                                      | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                                               | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                                           |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                                                    |               |     |             |                 |     |                  |             |                    |         |              |
| 262113           | Engine FIRE Pull Handle (Right) - Functional Test                                                |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                  |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                  |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                                                         |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 262115           | Engine FIRE Extinguishing Shuttle Valve (Double Check Valve Tee, Left) - Removal / Installation  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                  |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 35201023-1                                                                                       | SN-UNKNOWN    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                                                         |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 262116           | Engine FIRE Extinguishing Shuttle Valve (Double Check Valve Tee, Right) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                  |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 35201023-1                                                                                       | SN-UNKNOWN    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                                                         |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 262120           | Engine FIRE Bottle Cartridge (Left Bottle, Left Squib) - Removal / Installation                  |               | HRS |             | 562.4           |     |                  | 2483.7      |                    |         | 0            |
|                  |                                                                                                  |               | AFL |             | 217             |     |                  | 900         |                    |         | 0            |
|                  | 30903876                                                                                         | 0672DE        | MOS | TSN:19      | 17.2            |     |                  | 06 Dec 2024 |                    |         |              |
|                  | Airframe                                                                                         |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 262121           | Engine FIRE Bottle Cartridge (Left Bottle, Right Squib) - Removal / Installation                 |               | HRS |             | 562.4           |     |                  | 2483.7      |                    |         | 0            |
|                  |                                                                                                  |               | AFL |             | 217             |     |                  | 900         |                    |         | 0            |
|                  | 30903828                                                                                         | 1120CM        | MOS | TSN:24      | 17.2            |     |                  | 06 Dec 2024 |                    |         |              |
|                  | Airframe                                                                                         |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 262122           | Engine FIRE Bottle Cartridge (Left Bottle, APU Squib) - Removal / Installation                   |               | HRS |             | 562.4           |     |                  | 2483.7      |                    |         | 0            |
|                  |                                                                                                  |               | AFL |             | 217             |     |                  | 900         |                    |         | 0            |
|                  | 30903852                                                                                         | 0061CC        | MOS | TSN:33      | 17.2            |     |                  | 06 Dec 2024 |                    |         |              |
|                  | Airframe                                                                                         |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 262123           | Engine FIRE Bottle Cartridge (Right Bottle, Left Squib) - Removal / Installation                 |               | HRS |             | 562.4           |     |                  | 2483.7      |                    |         | 0            |
|                  |                                                                                                  |               | AFL |             | 217             |     |                  | 900         |                    |         | 0            |
|                  | 30903876                                                                                         | 2641DB        | MOS |             | 17.2            |     |                  | 06 Dec 2024 |                    |         |              |
|                  | Airframe                                                                                         |               | MSC |             |                 |     | O/C              |             |                    |         |              |

| ATA<br>U=Custom                | Description                                                                           |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|--------------------------------|---------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                | Part Number                                                                           | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position               | HW                                                                                    | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                | MM Ref                                                                                |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                                | Ops Number(s)                                                                         |               |     |             |                 |     |                  |             |                    |         |              |
| 262124                         | Engine FIRE Bottle Cartridge (Right Bottle, Right Squib) - Removal / Installation     |               | HRS |             | 562.4           |     |                  | 2483.7      |                    |         | 0            |
|                                |                                                                                       |               | AFL |             | 217             |     |                  | 900         |                    |         | 0            |
|                                | 30903828                                                                              | 1082CM        | MOS | TSN:24      | 17.2            |     |                  | 06 Dec 2024 |                    |         |              |
|                                |                                                                                       |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                       |                                                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| 262125                         | Engine FIRE Bottle Cartridge (Right Bottle, Spare Squib) - Removal / Installation     |               | HRS |             | 562.4           |     |                  | 2483.7      |                    |         | 0            |
|                                |                                                                                       |               | AFL |             | 217             |     |                  | 900         |                    |         | 0            |
|                                | 30908522                                                                              | 0099CC        | MOS | TSN:33      | 17.2            |     |                  | 06 Dec 2024 |                    |         |              |
|                                |                                                                                       |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                       |                                                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| 262132                         | Engine FIRE Bottle Cartridge (Left Bottle, Left Squib, Service Life) - Discard        |               | HRS |             | 562.4           |     |                  | 2483.7      |                    |         | 0            |
|                                |                                                                                       |               | AFL |             | 217             |     |                  | 900         |                    |         | 0            |
|                                | 30903876                                                                              | 0672DE        | MOS |             | 17.2            |     | 120              | 06 Dec 2024 | 06 Dec 2034        |         |              |
|                                |                                                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                       |                                                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 262120 |                                                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| 262133                         | Engine FIRE Bottle Cartridge (Left Bottle, Left Squib, Manufacturers Life) - Discard  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                                                       |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                | 30903876                                                                              | 0672DE        | MOS | TSN:116     | 17.2            |     | 180              | 06 Dec 2024 | 01 Mar 2037        |         |              |
|                                |                                                                                       |               |     |             |                 |     |                  |             |                    |         | MANUFACTURE  |
| Airframe                       |                                                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 262120 |                                                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| 262134                         | Engine FIRE Bottle Cartridge (Left Bottle, Right Squib, Service Life) - Discard       |               | HRS |             | 562.4           |     |                  | 2483.7      |                    |         | 0            |
|                                |                                                                                       |               | AFL |             | 217             |     |                  | 900         |                    |         | 0            |
|                                | 30903824                                                                              | 1120CM        | MOS |             | 17.2            |     | 120              | 06 Dec 2024 | 06 Dec 2034        |         |              |
|                                |                                                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                       |                                                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 262121 |                                                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| 262135                         | Engine FIRE Bottle Cartridge (Left Bottle, Right Squib, Manufacturers Life) - Discard |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                                                       |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                | 30903824                                                                              | 1120CM        | MOS | TSN:116     | 17.2            |     | 180              | 06 Dec 2024 | 01 Mar 2037        |         |              |
|                                |                                                                                       |               |     |             |                 |     |                  |             |                    |         | MANUFACTURE  |
| Airframe                       |                                                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 262121 |                                                                                       |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom                | Description                                                                               |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|--------------------------------|-------------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                | Part Number                                                                               | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position               | HW                                                                                        | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                | MM Ref                                                                                    |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                                | Ops Number(s)                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 262136                         | Engine FIRE Bottle Cartridge (Left Bottle, APU Squib,<br>Service Life) - Discard          |               | HRS |             | 562.4           |     |                  | 2483.7      |                    |         | 0            |
|                                |                                                                                           |               | AFL |             | 217             |     |                  | 900         |                    |         | 0            |
|                                | 30903852                                                                                  | 0061CC        | MOS |             | 17.2            |     | 120              | 06 Dec 2024 | 06 Dec 2034        |         |              |
| Airframe                       |                                                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 262122 |                                                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| 262137                         | Engine FIRE Bottle Cartridge (Left Bottle, APU Squib,<br>Manufacturers Life) - Discard    |               | HRS |             | 562.4           |     |                  | 2483.7      |                    |         | 0            |
|                                |                                                                                           |               | AFL |             | 217             |     |                  | 900         |                    |         | 0            |
|                                | 30903852                                                                                  | 0061CC        | MOS | TSN:116     | 17.2            |     | 180              | 06 Dec 2024 | 01 Mar 2037        |         |              |
| MANUFACTURE                    |                                                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                       |                                                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 262122 |                                                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| 262138                         | Engine FIRE Bottle Cartridge (Right Bottle, Left Squib,<br>Service Life) - Discard        |               | HRS |             | 562.4           |     |                  | 2483.7      |                    |         | 0            |
|                                |                                                                                           |               | AFL |             | 217             |     |                  | 900         |                    |         | 0            |
|                                | 30903876                                                                                  | 2641DB        | MOS |             | 17.2            |     | 120              | 06 Dec 2024 | 06 Dec 2034        |         |              |
| Airframe                       |                                                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 262123 |                                                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| 262139                         | Engine FIRE Bottle Cartridge (Right Bottle, Left Squib,<br>Manufacturers Life) - Discard  |               | HRS |             | 562.4           |     |                  | 2483.7      |                    |         | 0            |
|                                |                                                                                           |               | AFL |             | 217             |     |                  | 900         |                    |         | 0            |
|                                | 30903876                                                                                  | 2641DB        | MOS | TSN:116     | 17.2            |     | 180              | 06 Dec 2024 | 01 Feb 2038        |         |              |
| MANUFACTURE                    |                                                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                       |                                                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 262123 |                                                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| 262140                         | Engine FIRE Bottle Cartridge (Right Bottle, Right Squib,<br>Service Life) - Discard       |               | HRS |             | 562.4           |     |                  | 2483.7      |                    |         | 0            |
|                                |                                                                                           |               | AFL |             | 217             |     |                  | 900         |                    |         | 0            |
|                                | 30903828                                                                                  | 1082CM        | MOS |             | 17.2            |     | 120              | 06 Dec 2024 | 06 Dec 2034        |         |              |
| Airframe                       |                                                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 262124 |                                                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| 262141                         | Engine FIRE Bottle Cartridge (Right Bottle, Right Squib,<br>Manufacturers Life) - Discard |               | HRS |             | 562.4           |     |                  | 2483.7      |                    |         | 0            |
|                                |                                                                                           |               | AFL |             | 217             |     |                  | 900         |                    |         | 0            |
|                                | 30903828                                                                                  | 1082CM        | MOS | TSN:116     | 17.2            |     | 180              | 06 Dec 2024 | 01 Dec 2037        |         |              |
| MANUFACTURE                    |                                                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                       |                                                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 262124 |                                                                                           |               |     |             |                 |     |                  |             |                    |         |              |



| ATA<br>U=Custom                 | Description                                                                            |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |  |
|---------------------------------|----------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|--|
|                                 | Part Number                                                                            | Serial Number |     |             |                 |     |                  |             |                     |         | Approx Price |  |
| Logbook Position                | HW                                                                                     | SW            |     |             |                 |     |                  |             |                     |         | Manufacturer |  |
|                                 | MM Ref                                                                                 |               |     |             |                 |     |                  |             |                     |         | Date Type    |  |
|                                 | Ops Number(s)                                                                          |               |     |             |                 |     |                  |             |                     |         |              |  |
| 262142                          | Engine FIRE Bottle Cartridge (Right Bottle, Spare Squib, Service Life) - Discard       |               | HRS |             | 562.4           |     |                  | 2483.7      |                     |         | 0            |  |
|                                 |                                                                                        |               | AFL |             | 217             |     |                  | 900         |                     |         | 0            |  |
|                                 | 30908552                                                                               | 0099CC        | MOS |             | 17.2            |     | 120              | 06 Dec 2024 | 06 Dec 2034         |         |              |  |
| Airframe                        |                                                                                        |               |     |             |                 |     |                  |             |                     |         |              |  |
| Notes: MRI PARENT CODE: 262125  |                                                                                        |               |     |             |                 |     |                  |             |                     |         |              |  |
| 262143                          | Engine FIRE Bottle Cartridge (Right Bottle, Spare Squib, Manufacturers Life) - Discard |               | HRS |             | 562.4           |     |                  | 2483.7      |                     |         | 0            |  |
|                                 |                                                                                        |               | AFL |             | 217             |     |                  | 900         |                     |         | 0            |  |
|                                 | 30908552                                                                               | 0099CC        | MOS | TSN:116     | 17.2            |     | 180              | 06 Dec 2024 | 01 Mar 2037         |         |              |  |
| MANUFACTURE                     |                                                                                        |               |     |             |                 |     |                  |             |                     |         |              |  |
| Airframe                        |                                                                                        |               |     |             |                 |     |                  |             |                     |         |              |  |
| Notes: MRI PARENT CODE: 262125  |                                                                                        |               |     |             |                 |     |                  |             |                     |         |              |  |
| 262144                          | Engine FIRE Bottle Cartridge (Left Bottle, Left Squib) - Inspection                    |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |  |
|                                 |                                                                                        |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |  |
|                                 |                                                                                        |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |  |
| O/C                             |                                                                                        |               |     |             |                 |     |                  |             |                     |         |              |  |
| Airframe                        |                                                                                        |               |     |             |                 |     |                  |             |                     |         |              |  |
| Notes: PN: 30903959 SN: 0299TC. |                                                                                        |               |     |             |                 |     |                  |             |                     |         |              |  |
| 262145                          | Engine FIRE Bottle Cartridge (Left Bottle, Right Squib) - Inspection                   |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |  |
|                                 |                                                                                        |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |  |
|                                 |                                                                                        |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |  |
| O/C                             |                                                                                        |               |     |             |                 |     |                  |             |                     |         |              |  |
| Airframe                        |                                                                                        |               |     |             |                 |     |                  |             |                     |         |              |  |
| Notes: PN: 30903931 SN: 1719TA. |                                                                                        |               |     |             |                 |     |                  |             |                     |         |              |  |
| 262146                          | Engine FIRE Bottle Cartridge (Left Bottle, APU Squib) - Inspection                     |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |  |
|                                 |                                                                                        |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |  |
|                                 |                                                                                        |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |  |
| O/C                             |                                                                                        |               |     |             |                 |     |                  |             |                     |         |              |  |
| Airframe                        |                                                                                        |               |     |             |                 |     |                  |             |                     |         |              |  |
| Notes: PN: 30903933 SN: 0611TB. |                                                                                        |               |     |             |                 |     |                  |             |                     |         |              |  |
| 262147                          | Engine FIRE Bottle Cartridge (Right Bottle, Left Squib) - Inspection                   |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |  |
|                                 |                                                                                        |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |  |
|                                 |                                                                                        |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |  |
| O/C                             |                                                                                        |               |     |             |                 |     |                  |             |                     |         |              |  |
| Airframe                        |                                                                                        |               |     |             |                 |     |                  |             |                     |         |              |  |
| Notes: PN: 30903959 SN: 0298TC. |                                                                                        |               |     |             |                 |     |                  |             |                     |         |              |  |

| ATA<br>U=Custom                 | Description                                                                              |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W                             | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|---------------------------------|------------------------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|--------------------------------------|--------------------|---------|--------------|
|                                 | Part Number                                                                              | Serial Number |                                    |             |                 |     |                  |                                      |                    |         | Approx Price |
| Logbook Position                | HW                                                                                       | SW            |                                    |             |                 |     |                  |                                      |                    |         | Manufacturer |
|                                 | MM Ref                                                                                   |               |                                    |             |                 |     |                  |                                      |                    |         | Date Type    |
|                                 | Ops Number(s)                                                                            |               |                                    |             |                 |     |                  |                                      |                    |         |              |
| 262148                          | Engine FIRE Bottle Cartridge (Right Bottle, Right Squib) - Inspection                    |               | HRS                                |             | 3046.1          |     |                  | 0                                    |                    |         | 0            |
|                                 |                                                                                          |               | AFL                                |             | 1117            |     |                  | 0                                    |                    |         | 0            |
|                                 |                                                                                          |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015                          |                    |         |              |
|                                 |                                                                                          |               | MSC                                |             |                 |     | O/C              |                                      |                    |         |              |
| Airframe                        |                                                                                          |               |                                    |             |                 |     |                  |                                      |                    |         |              |
| Notes: PN: 30903931 SN: 1720TA. |                                                                                          |               |                                    |             |                 |     |                  |                                      |                    |         |              |
| 262149                          | Engine FIRE Bottle Cartridge (Right Bottle, Spare Squib) - Inspection                    |               | HRS                                |             | 3046.1          |     |                  | 0                                    |                    |         | 0            |
|                                 |                                                                                          |               | AFL                                |             | 1117            |     |                  | 0                                    |                    |         | 0            |
|                                 |                                                                                          |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015                          |                    |         |              |
|                                 |                                                                                          |               | MSC                                |             |                 |     | O/C              |                                      |                    |         |              |
| Airframe                        |                                                                                          |               |                                    |             |                 |     |                  |                                      |                    |         |              |
| Notes: PN: 30903933 SN: 0615TB. |                                                                                          |               |                                    |             |                 |     |                  |                                      |                    |         |              |
| 262150                          | Engine FIRE Extinguishing Firing Circuitry Integrity (Left) - Operational Check          |               | HRS                                |             | 137             |     |                  | 2909.1                               |                    |         | 0            |
|                                 |                                                                                          |               | AFL                                |             | 52              |     |                  | 1065                                 |                    |         | 0            |
|                                 |                                                                                          |               | MOS                                |             | 4.8             | 3   | 24               | 18 Dec 2025 31 Dec 2027* 31 Jan 2028 |                    |         |              |
|                                 |                                                                                          |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |                                      |                    |         |              |
| Airframe                        |                                                                                          |               |                                    |             |                 |     |                  |                                      |                    |         |              |
| 052011                          |                                                                                          |               |                                    |             |                 |     |                  |                                      |                    |         |              |
| 262151                          | Engine FIRE Extinguishing Firing Circuitry Integrity (Right) - Operational Check         |               | HRS                                |             | 137             |     |                  | 2909.1                               |                    |         | 0            |
|                                 |                                                                                          |               | AFL                                |             | 52              |     |                  | 1065                                 |                    |         | 0            |
|                                 |                                                                                          |               | MOS                                |             | 4.8             | 3   | 24               | 18 Dec 2025 31 Dec 2027* 31 Jan 2028 |                    |         |              |
|                                 |                                                                                          |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |                                      |                    |         |              |
| Airframe                        |                                                                                          |               |                                    |             |                 |     |                  |                                      |                    |         |              |
| 052011                          |                                                                                          |               |                                    |             |                 |     |                  |                                      |                    |         |              |
| 262152                          | APU FIRE Extinguishing Firing Circuitry Integrity - Operational Check                    |               | HRS                                |             | 137             |     |                  | 2909.1                               |                    |         | 0            |
|                                 |                                                                                          |               | AFL                                |             | 52              |     |                  | 1065                                 |                    |         | 0            |
|                                 |                                                                                          |               | MOS                                |             | 4.8             | 3   | 24               | 18 Dec 2025 31 Dec 2027* 31 Jan 2028 |                    |         |              |
|                                 |                                                                                          |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |                                      |                    |         |              |
| Airframe                        |                                                                                          |               |                                    |             |                 |     |                  |                                      |                    |         |              |
| 052011                          |                                                                                          |               |                                    |             |                 |     |                  |                                      |                    |         |              |
| 262161                          | Engine FIRE Extinguishing Shuttle Valve (Double Check Valve Tee, Left) - Functional Test |               | HRS                                |             | 3046.1          |     |                  | 0                                    |                    |         | 0            |
|                                 |                                                                                          |               | AFL                                |             | 1117            |     |                  | 0                                    |                    |         | 0            |
|                                 |                                                                                          |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015                          |                    |         |              |
|                                 |                                                                                          |               | MSC                                |             |                 |     | O/C              |                                      |                    |         |              |
| Airframe                        |                                                                                          |               |                                    |             |                 |     |                  |                                      |                    |         |              |

| ATA<br>U=Custom                                       | Description                                                                                   |               | UOM                                | Times Since | Time<br>Accrued | Adj    | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|-------------------------------------------------------|-----------------------------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|--------|------------------|-------------|--------------------|-------------|--------------|
|                                                       | Part Number                                                                                   | Serial Number |                                    |             |                 |        |                  |             |                    |             | Approx Price |
| Logbook Position                                      | HW                                                                                            | SW            |                                    |             |                 |        |                  |             |                    |             | Manufacturer |
|                                                       | MM Ref                                                                                        |               |                                    |             |                 |        |                  |             |                    |             | Date Type    |
|                                                       | Ops Number(s)                                                                                 |               |                                    |             |                 |        |                  |             |                    |             |              |
| 262162                                                | Engine FIRE Extinguishing Shuttle Valve (Double Check Valve Tee, Right) - Functional Test     |               | HRS                                |             | 3046.1          |        |                  | 0           |                    |             | 0            |
|                                                       |                                                                                               |               | AFL                                |             | 1117            |        | 0                |             | 0                  |             |              |
|                                                       |                                                                                               |               | MOS                                |             | 128.6           |        | 24 Aug 2015      |             |                    |             |              |
|                                                       |                                                                                               |               | MSC                                |             |                 | O/C    |                  |             |                    |             |              |
| Airframe                                              |                                                                                               |               |                                    |             |                 |        |                  |             |                    |             |              |
| 262163                                                | Engine FIRE Extinguishing Shuttle Valve (Double Check Valve Tee, Left) - Detailed Inspection  |               | HRS                                |             | 137             |        |                  | 2909.1      |                    |             | 0            |
|                                                       |                                                                                               |               | AFL                                |             | 52              |        | 1065             |             |                    | 0           |              |
|                                                       |                                                                                               |               | MOS                                |             | 5.4             | 120    | 29 Nov 2025      | 29 Nov 2035 | 29 Dec 2035        |             |              |
|                                                       |                                                                                               |               | [MOS: +1m/-1m]                     |             |                 |        |                  |             |                    |             |              |
| Airframe                                              |                                                                                               |               |                                    |             |                 |        |                  |             |                    |             |              |
| 262164                                                | Engine FIRE Extinguishing Shuttle Valve (Double Check Valve Tee, Right) - Detailed Inspection |               | HRS                                |             | 137             |        |                  | 2909.1      |                    |             | 0            |
|                                                       |                                                                                               |               | AFL                                |             | 52              |        | 1065             |             |                    | 0           |              |
|                                                       |                                                                                               |               | MOS                                |             | 5.4             | 120    | 29 Nov 2025      | 29 Nov 2035 | 29 Dec 2035        |             |              |
|                                                       |                                                                                               |               | [MOS: +1m/-1m]                     |             |                 |        |                  |             |                    |             |              |
| Airframe                                              |                                                                                               |               |                                    |             |                 |        |                  |             |                    |             |              |
| 262204                                                | APU FIRE Bottle Pressure Switch - Operational Test                                            |               | HRS                                |             | 1452            |        |                  | 1594.1      |                    |             | 0            |
|                                                       |                                                                                               |               | AFL                                |             | 570             |        | 547              |             |                    | 0           |              |
|                                                       |                                                                                               |               | MOS                                |             | 63.9            |        | 14 Jan 2021      |             |                    |             |              |
|                                                       |                                                                                               |               | MSC                                |             |                 | O/C    |                  |             |                    |             |              |
| Airframe                                              |                                                                                               |               |                                    |             |                 |        |                  |             |                    |             |              |
| 262400                                                | Portable FIRE Extinguisher (Cockpit) - Removal / Installation                                 |               | HRS                                |             | 137             |        |                  | 2909.1      |                    |             | 0            |
|                                                       |                                                                                               |               | AFL                                |             | 52              |        | 1065             |             |                    | 0           |              |
|                                                       |                                                                                               |               | MOS                                | 347TS       | G-98646650      | TSN:48 | 5.2              |             | 05 Dec 2025        |             |              |
|                                                       |                                                                                               |               | MSC                                |             |                 | O/C    |                  |             |                    |             |              |
| Airframe                                              |                                                                                               |               |                                    |             |                 |        |                  |             |                    |             |              |
| 262402                                                | Portable FIRE Extinguisher (Cockpit) - Detailed Inspection                                    |               | HRS                                |             | 137             |        |                  | 2909.1      |                    |             | 0            |
|                                                       |                                                                                               |               | AFL                                |             | 52              |        | 1065             |             |                    | 0           |              |
|                                                       |                                                                                               |               | MOS                                |             | 5.2             | -6     | 12               | 05 Dec 2025 | 30 Nov 2026*       | 31 Dec 2026 |              |
|                                                       |                                                                                               |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |        |                  |             |                    |             |              |
| Airframe                                              |                                                                                               |               |                                    |             |                 |        |                  |             |                    |             |              |
| 052010                                                |                                                                                               |               |                                    |             |                 |        |                  |             |                    |             |              |
| Notes: PN: 898052 SN: <NONE>.                         |                                                                                               |               |                                    |             |                 |        |                  |             |                    |             |              |
| 262403                                                | Portable FIRE Extinguisher (Cockpit) - Weight Check                                           |               | HRS                                |             | 137             |        |                  | 2909.1      |                    |             | 0            |
|                                                       |                                                                                               |               | AFL                                |             | 52              |        | 1065             |             |                    | 0           |              |
|                                                       |                                                                                               |               | MOS                                |             | 5.2             | -63    | 12               | 05 Dec 2025 | 31 Oct 2026*       | 30 Nov 2026 |              |
|                                                       |                                                                                               |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |        |                  |             |                    |             |              |
| Airframe                                              |                                                                                               |               |                                    |             |                 |        |                  |             |                    |             |              |
| 052010                                                |                                                                                               |               |                                    |             |                 |        |                  |             |                    |             |              |
| Notes: PN: 898052 SN: <NONE>. MRI PARENT CODE: 262400 |                                                                                               |               |                                    |             |                 |        |                  |             |                    |             |              |
| WEIGHT CHECK                                          |                                                                                               |               |                                    |             |                 |        |                  |             |                    |             |              |

| ATA<br>U=Custom                                          | Description                                            |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|----------------------------------------------------------|--------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                                                          | Part Number                                            | Serial Number |                                    |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position                                         | HW                                                     | SW            |                                    |             |                 |     |                  |             |                    |             | Manufacturer |
|                                                          | MM Ref                                                 |               |                                    |             |                 |     |                  |             |                    |             | Date Type    |
|                                                          | Ops Number(s)                                          |               |                                    |             |                 |     |                  |             |                    |             |              |
| 262404                                                   | Portable FIRE Extinguisher (Cockpit) - (Hydrostatic)   |               | HRS                                |             | 3033.8          |     |                  | 12.3        |                    |             | 0            |
|                                                          | Functional Check                                       |               | AFL                                |             | 1112            |     |                  | 5           |                    |             | 0            |
|                                                          |                                                        |               | MOS                                |             | 53.3            |     | 144              | 01 Dec 2021 | 31 Dec 2033        |             |              |
|                                                          |                                                        |               | [End Of Month Item]                |             |                 |     |                  |             |                    |             | HYDRO CHECK  |
| Airframe                                                 |                                                        |               |                                    |             |                 |     |                  |             |                    |             |              |
| Notes: PN: 898052 SN: A93830406. MRI PARENT CODE: 262400 |                                                        |               |                                    |             |                 |     |                  |             |                    |             |              |
| 262412                                                   | Portable FIRE Extinguisher (Forward Cabin) - Removal / |               | HRS                                |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                                                          | Installation                                           |               | AFL                                |             | 52              |     |                  | 1065        |                    |             | 0            |
|                                                          | 347TS                                                  | I-70853393    | MOS                                |             | 5.2             |     |                  | 05 Dec 2025 |                    |             |              |
|                                                          |                                                        |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe                                                 |                                                        |               |                                    |             |                 |     |                  |             |                    |             |              |
| 262414                                                   | Portable FIRE Extinguisher (Forward Cabin) - Detailed  |               | HRS                                |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                                                          | Inspection                                             |               | AFL                                |             | 52              |     |                  | 1065        |                    |             | 0            |
|                                                          |                                                        |               | MOS                                |             | 5.2             | -6  | 12               | 05 Dec 2025 | 30 Nov 2026*       | 31 Dec 2026 |              |
|                                                          |                                                        |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe                                                 |                                                        |               |                                    |             |                 |     |                  |             |                    |             |              |
| 052010                                                   |                                                        |               |                                    |             |                 |     |                  |             |                    |             |              |
| Notes: PN: C354TS SN: <NONE>.                            |                                                        |               |                                    |             |                 |     |                  |             |                    |             |              |
| 262415                                                   | Portable FIRE Extinguisher (Forward Cabin) - Weight    |               | HRS                                |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                                                          | Check                                                  |               | AFL                                |             | 52              |     |                  | 1065        |                    |             | 0            |
|                                                          |                                                        |               | MOS                                |             | 5.2             | -63 | 12               | 05 Dec 2025 | 31 Oct 2026*       | 30 Nov 2026 |              |
|                                                          |                                                        |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             | WEIGHT CHECK |
| Airframe                                                 |                                                        |               |                                    |             |                 |     |                  |             |                    |             |              |
| 052010                                                   |                                                        |               |                                    |             |                 |     |                  |             |                    |             |              |
| Notes: PN: C354TS SN: <NONE>.                            |                                                        |               |                                    |             |                 |     |                  |             |                    |             |              |
| 262416                                                   | Portable FIRE Extinguisher (Forward Cabin) -           |               | HRS                                |             | 3033.8          |     |                  | 12.3        |                    |             | 0            |
|                                                          | (Hydrostatic) Functional Check                         |               | AFL                                |             | 1112            |     |                  | 5           |                    |             | 0            |
|                                                          |                                                        |               | MOS                                |             | 5.6             |     | 144              | 22 Nov 2025 | 30 Nov 2037        |             |              |
|                                                          |                                                        |               | [End Of Month Item]                |             |                 |     |                  |             |                    |             | HYDRO CHECK  |
| Airframe                                                 |                                                        |               |                                    |             |                 |     |                  |             |                    |             |              |
| Notes: PN: C354TS SN: A-94385911.                        |                                                        |               |                                    |             |                 |     |                  |             |                    |             |              |
| 262436                                                   | Portable FIRE Extinguisher (Aft Lavatory) - Removal /  |               | HRS                                |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                                                          | Installation                                           |               | AFL                                |             | 52              |     |                  | 1065        |                    |             | 0            |
|                                                          | 351BRX                                                 | I-10084359    | MOS                                | TSN:4       | 5.2             |     |                  | 05 Dec 2025 |                    |             |              |
|                                                          |                                                        |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe                                                 |                                                        |               |                                    |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom                 | Description                                                                |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|---------------------------------|----------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                                 | Part Number                                                                | Serial Number |                                    |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position                | HW                                                                         | SW            |                                    |             |                 |     |                  |             |                    |             | Manufacturer |
|                                 | MM Ref                                                                     |               |                                    |             |                 |     |                  |             |                    |             | Date Type    |
|                                 | Ops Number(s)                                                              |               |                                    |             |                 |     |                  |             |                    |             |              |
| 262438                          | Portable FIRE Extinguisher (Aft Lavatory) - Detailed Inspection            |               | HRS                                |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                                 |                                                                            |               | AFL                                |             | 52              |     |                  | 1065        |                    |             | 0            |
|                                 |                                                                            |               | MOS                                |             | 5.2             | -6  | 12               | 05 Dec 2025 | 30 Nov 2026*       | 31 Dec 2026 |              |
|                                 |                                                                            |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe                        |                                                                            |               |                                    |             |                 |     |                  |             |                    |             |              |
| Notes: PN: B371 SN: <NONE>.     |                                                                            |               |                                    |             |                 |     |                  |             |                    |             |              |
| 262439                          | Portable FIRE Extinguisher (Aft Lavatory) - Weight Check                   |               | HRS                                |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                                 |                                                                            |               | AFL                                |             | 52              |     |                  | 1065        |                    |             | 0            |
|                                 |                                                                            |               | MOS                                |             | 5.2             | -63 | 12               | 05 Dec 2025 | 31 Oct 2026*       | 30 Nov 2026 |              |
|                                 |                                                                            |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe                        |                                                                            |               |                                    |             |                 |     |                  |             |                    |             |              |
| Notes: PN: B371 SN: <NONE>.     |                                                                            |               |                                    |             |                 |     |                  |             |                    |             |              |
| 262440                          | Portable FIRE Extinguisher (Aft Lavatory) - (Hydrostatic) Functional Check |               | HRS                                |             | 3033.8          |     |                  | 12.3        |                    |             | 0            |
|                                 |                                                                            |               | AFL                                |             | 1112            |     |                  | 5           |                    |             | 0            |
|                                 |                                                                            |               | MOS                                |             | 10.1            |     | 144              | 09 Jul 2025 | 31 Jul 2037        |             |              |
|                                 |                                                                            |               | [End Of Month Item]                |             |                 |     |                  |             |                    |             |              |
| Airframe                        |                                                                            |               |                                    |             |                 |     |                  |             |                    |             |              |
| Notes: PN: B371 SN: A-97640921. |                                                                            |               |                                    |             |                 |     |                  |             |                    |             |              |
| 262448                          | Portable Water FIRE Extinguisher - Removal / Installation<br>89248030816   |               | HRS                                | TSN:2303.3  | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                                 |                                                                            |               | AFL                                | TSN:797     | 315             |     |                  | 802         |                    |             | 0            |
|                                 |                                                                            |               | MOS                                | TSN:100     | 28.7            |     |                  | 21 Dec 2023 |                    |             |              |
|                                 |                                                                            |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe                        |                                                                            |               |                                    |             |                 |     |                  |             |                    |             |              |
| 262450                          | Portable Water FIRE Extinguisher - Detailed Inspection                     |               | HRS                                |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                                 |                                                                            |               | AFL                                |             | 52              |     |                  | 1065        |                    |             | 0            |
|                                 |                                                                            |               | MOS                                |             | 5.2             | -5  | 12               | 04 Dec 2025 | 30 Nov 2026*       | 31 Dec 2026 |              |
|                                 |                                                                            |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe                        |                                                                            |               |                                    |             |                 |     |                  |             |                    |             |              |
| Notes: PN: 892480 SN: <NONE>.   |                                                                            |               |                                    |             |                 |     |                  |             |                    |             |              |
| 262451                          | Portable Water FIRE Extinguisher - Weight Check                            |               | HRS                                |             | 3014.9          |     |                  | 31.2        |                    |             | 0            |
|                                 |                                                                            |               | AFL                                |             | 1106            |     |                  | 11          |                    |             | 0            |
|                                 |                                                                            |               | MOS                                |             | 122.1           |     |                  | 09 Mar 2016 |                    |             |              |
|                                 |                                                                            |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe                        |                                                                            |               |                                    |             |                 |     |                  |             |                    |             |              |
| Notes: PN: 892480 SN: 30816.    |                                                                            |               |                                    |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom              | Description                                              |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due     | Avg Man Hrs  |
|------------------------------|----------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|---------------------|-------------|--------------|
|                              | Part Number                                              | Serial Number |                                    |             |                 |     |                  |             |                     |             | Approx Price |
| Logbook Position             | HW                                                       | SW            |                                    |             |                 |     |                  |             |                     |             | Manufacturer |
|                              | MM Ref                                                   |               |                                    |             |                 |     |                  |             |                     |             | Date Type    |
|                              | Ops Number(s)                                            |               |                                    |             |                 |     |                  |             |                     |             |              |
| 262452                       | Portable Water FIRE Extinguisher - (Hydrostatic)         |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                     |             | 0            |
|                              | Functional Check                                         |               | AFL                                |             | 315             |     |                  | 802         |                     |             | 0            |
|                              |                                                          |               | MOS                                |             | 28.7            |     | 60               | 21 Dec 2023 | 31 Oct 2028         |             |              |
|                              |                                                          |               | [End Of Month Item]                |             |                 |     |                  |             |                     |             | HYDRO CHECK  |
| Airframe                     |                                                          |               |                                    |             |                 |     |                  |             |                     |             |              |
| Notes: PN: 892480 SN: 30816. |                                                          |               |                                    |             |                 |     |                  |             |                     |             |              |
| 262500                       | Trash Receptacle Enclosure (Forward Lavatory) - Detailed |               | HRS                                |             | 137             |     |                  | 2909.1      |                     |             | 0            |
|                              | Inspection                                               |               | AFL                                |             | 52              |     |                  | 1065        |                     |             | 0            |
|                              |                                                          |               | MOS                                |             | 4.8             | -19 | 12               | 18 Dec 2025 | 30 Nov 2026*        | 31 Dec 2026 |              |
|                              |                                                          |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                     |             |              |
| Airframe                     |                                                          |               |                                    |             |                 |     |                  |             |                     |             |              |
| 052010                       |                                                          |               |                                    |             |                 |     |                  |             |                     |             |              |
| 262501                       | Trash Receptacle Enclosure (Forward Galley / Annex) -    |               | HRS                                |             | 137             |     |                  | 2909.1      |                     |             | 0            |
|                              | Detailed Inspection                                      |               | AFL                                |             | 52              |     |                  | 1065        |                     |             | 0            |
|                              |                                                          |               | MOS                                |             | 4.8             | -19 | 12               | 18 Dec 2025 | 30 Nov 2026*        | 31 Dec 2026 |              |
|                              |                                                          |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                     |             |              |
| Airframe                     |                                                          |               |                                    |             |                 |     |                  |             |                     |             |              |
| 052010                       |                                                          |               |                                    |             |                 |     |                  |             |                     |             |              |
| 262505                       | Trash Receptacle Enclosure (Aft Lavatory) - Detailed     |               | HRS                                |             | 137             |     |                  | 2909.1      |                     |             | 0            |
|                              | Inspection                                               |               | AFL                                |             | 52              |     |                  | 1065        |                     |             | 0            |
|                              |                                                          |               | MOS                                |             | 4.8             | -19 | 12               | 18 Dec 2025 | 30 Nov 2026*        | 31 Dec 2026 |              |
|                              |                                                          |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                     |             |              |
| Airframe                     |                                                          |               |                                    |             |                 |     |                  |             |                     |             |              |
| 052010                       |                                                          |               |                                    |             |                 |     |                  |             |                     |             |              |
| 27 - Flight Controls         |                                                          |               |                                    |             |                 |     |                  |             |                     |             |              |
| 270001                       | Flight Control Cable Tension - Adjustment / Test         |               | HRS                                |             | 3046.1          |     |                  | 0           |                     |             | 0            |
|                              |                                                          |               | AFL                                |             | 1117            |     |                  | 0           |                     |             | 0            |
|                              |                                                          |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                     |             |              |
|                              |                                                          |               | MSC                                |             |                 |     | O/C              |             |                     |             |              |
| Airframe                     |                                                          |               |                                    |             |                 |     |                  |             |                     |             |              |
| 270002                       | Flight Control System Rigging (Cockpit) - Adjustment /   |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                     |             | 0            |
|                              | Test                                                     |               | AFL                                |             | 315             |     |                  | 802         |                     |             | 0            |
|                              |                                                          |               | MOS                                |             | 28.7            |     |                  | 21 Dec 2023 |                     |             |              |
|                              |                                                          |               | MSC                                |             |                 |     | O/C              |             |                     |             |              |
| Airframe                     |                                                          |               |                                    |             |                 |     |                  |             |                     |             |              |
| 270003                       | Control Cable Tension - Check                            |               | HRS                                |             | 3046.1          |     |                  | 0           |                     |             | 0            |
|                              |                                                          |               | AFL                                |             | 1117            |     |                  | 0           |                     |             | 0            |
|                              |                                                          |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                     |             |              |
|                              |                                                          |               | MSC                                |             |                 |     | O/C              |             |                     |             |              |
| Airframe                     |                                                          |               |                                    |             |                 |     |                  |             |                     |             |              |

| ATA<br>U=Custom  | Description                                                                   |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                   | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                            | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                        |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                                 |               |     |             |                 |     |                  |             |                    |         |              |
| 270100           | Flight Control Computer (No. 1) Channel A Mon Module - Removal / Installation |               | HRS |             | 2120.8          |     |                  | 925.3       |                    |         | 0            |
|                  |                                                                               |               | AFL |             | 861             |     |                  | 256         |                    |         | 0            |
|                  | 60P2700001Z105/NB05                                                           | C13204006116  | MOS |             | 85.9            |     |                  | 14 Mar 2019 |                    |         |              |
|                  |                                                                               |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                               |               |     |             |                 |     |                  |             |                    |         |              |
| 270101           | Flight Control Computer (No. 1) Channel B Com Module - Removal / Installation |               | HRS |             | 2120.8          |     |                  | 925.3       |                    |         | 0            |
|                  |                                                                               |               | AFL |             | 861             |     |                  | 256         |                    |         | 0            |
|                  | 60P2700001Z205/NB05                                                           | C13212006201  | MOS |             | 85.9            |     |                  | 14 Mar 2019 |                    |         |              |
|                  |                                                                               |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                               |               |     |             |                 |     |                  |             |                    |         |              |
| 270102           | Flight Control Computer (No. 1) Fan Module - Removal / Installation           |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                               |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P2700001Z301                                                                | C13211004114  | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                               |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                               |               |     |             |                 |     |                  |             |                    |         |              |
| 270103           | Flight Control Computer (No. 2) Fan Module - Removal / Installation           |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                               |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P2700001Z301                                                                | C13211004081  | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                               |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                               |               |     |             |                 |     |                  |             |                    |         |              |
| 270104           | Flight Control Computer (No. 1) Channel A Com Module - Removal / Installation |               | HRS |             | 2120.8          |     |                  | 925.3       |                    |         | 0            |
|                  |                                                                               |               | AFL |             | 861             |     |                  | 256         |                    |         | 0            |
|                  | 60P2700001Z105/NB05                                                           | C13204006117  | MOS |             | 85.9            |     |                  | 14 Mar 2019 |                    |         |              |
|                  |                                                                               |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                               |               |     |             |                 |     |                  |             |                    |         |              |
| 270105           | Flight Control Computer (No. 1) Channel B Mon Module - Removal / Installation |               | HRS |             | 2120.8          |     |                  | 925.3       |                    |         | 0            |
|                  |                                                                               |               | AFL |             | 861             |     |                  | 256         |                    |         | 0            |
|                  | 60P2700001Z205/NB05                                                           | C13212006205  | MOS |             | 85.9            |     |                  | 14 Mar 2019 |                    |         |              |
|                  |                                                                               |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                               |               |     |             |                 |     |                  |             |                    |         |              |
| 270110           | Flight Control Computer (No. 2) Channel A Mon Module - Removal / Installation |               | HRS |             | 2120.8          |     |                  | 925.3       |                    |         | 0            |
|                  |                                                                               |               | AFL |             | 861             |     |                  | 256         |                    |         | 0            |
|                  | 60P2700001Z105/NB05                                                           | C13204006119  | MOS |             | 85.9            |     |                  | 14 Mar 2019 |                    |         |              |
|                  |                                                                               |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                               |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                   |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                   | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                            | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                        |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                                 |               |     |             |                 |     |                  |             |                    |         |              |
| 270111           | Flight Control Computer (No. 2) Channel B Com Module - Removal / Installation |               | HRS |             | 2120.8          |     |                  | 925.3       |                    |         | 0            |
|                  |                                                                               |               | AFL |             | 861             |     |                  | 256         |                    |         | 0            |
|                  | 60P2700001Z205/NB05                                                           | C13212006221  | MOS |             | 85.9            |     |                  | 14 Mar 2019 |                    |         |              |
|                  |                                                                               |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                               |               |     |             |                 |     |                  |             |                    |         |              |
| 270112           | Flight Control Computer (No. 2) Channel A Com Module - Removal / Installation |               | HRS |             | 2120.8          |     |                  | 925.3       |                    |         | 0            |
|                  |                                                                               |               | AFL |             | 861             |     |                  | 256         |                    |         | 0            |
|                  | 60P2700001Z105/NB05                                                           | C13204006109  | MOS |             | 85.9            |     |                  | 14 Mar 2019 |                    |         |              |
|                  |                                                                               |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                               |               |     |             |                 |     |                  |             |                    |         |              |
| 270113           | Flight Control Computer (No. 2) Channel B Mon Module - Removal / Installation |               | HRS |             | 2120.8          |     |                  | 925.3       |                    |         | 0            |
|                  |                                                                               |               | AFL |             | 861             |     |                  | 256         |                    |         | 0            |
|                  | 60P2700001Z205/NB05                                                           | C13212006223  | MOS |             | 85.9            |     |                  | 14 Mar 2019 |                    |         |              |
|                  |                                                                               |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                               |               |     |             |                 |     |                  |             |                    |         |              |
| 270120           | Flight Control Computer Rack (No. 1) - Removal / Installation                 |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                               |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P2700001Z400                                                                | C13213004054  | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                               |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                               |               |     |             |                 |     |                  |             |                    |         |              |
| 270121           | Flight Control Computer Rack (No. 2) - Removal / Installation                 |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                               |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P2700001Z400                                                                | C13213004127  | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                               |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                               |               |     |             |                 |     |                  |             |                    |         |              |
| 270126           | Flight Control Computer - Functional Test                                     |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  |                                                                               |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  |                                                                               |               | MOS |             | 123.9           |     |                  | 15 Jan 2016 |                    |         |              |
|                  |                                                                               |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                               |               |     |             |                 |     |                  |             |                    |         |              |
| 270127           | Flight Control Electrical Backup MODE - Functional Test                       |               | HRS |             | 663.7           |     |                  | 2382.4      |                    |         | 0            |
|                  |                                                                               |               | AFL |             | 291             |     |                  | 826         |                    |         | 0            |
|                  |                                                                               |               | MOS |             | 24.9            |     |                  | 13 Apr 2024 |                    |         |              |
|                  |                                                                               |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                               |               |     |             |                 |     |                  |             |                    |         |              |



| ATA<br>U=Custom                                               | Description                                                                     |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|---------------------------------------------------------------|---------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                                               | Part Number                                                                     | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position                                              | HW                                                                              | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                                               | MM Ref                                                                          |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                                                               | Ops Number(s)                                                                   |               |     |             |                 |     |                  |             |                    |         |              |
| 270200                                                        | Backup Flight Control Unit - Removal / Installation                             |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                                               | 60P2700002Z004                                                                  | C13174003242  | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                                               |                                                                                 |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                                               | Airframe                                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 270201                                                        | Backup Flight Control Unit - Communication Check                                |               | HRS |             | 2345.1          |     |                  | 701         |                    |         | 0            |
|                                                               |                                                                                 |               | AFL |             | 936             |     |                  | 181         |                    |         | 0            |
|                                                               |                                                                                 |               | MOS |             | 96.6            |     |                  | 23 Apr 2018 |                    |         |              |
|                                                               | Airframe                                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Notes: PN: 60P2700002Z004 SN: <NONE>. MRI PARENT CODE: 270200 |                                                                                 |               |     |             |                 |     |                  |             |                    |         |              |
| 270202                                                        | Backup Flight Control Unit - Functional Test                                    |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                                               |                                                                                 |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                                               |                                                                                 |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                                               | Airframe                                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 270300                                                        | Aileron and Elevator Control Module Assembly (Pilot) - Removal / Installation   |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                                               | 60P2711101Z004                                                                  | 230281        | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                                               |                                                                                 |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                                               | Airframe                                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 270301                                                        | Aileron and Elevator Control Module Assembly (Copilot) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                                               | 60P2711201Z004                                                                  | 167765        | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                                               |                                                                                 |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                                               | Airframe                                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 270308                                                        | Trim Control Module - Functional Test                                           |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                                               |                                                                                 |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                                               |                                                                                 |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                                               | Airframe                                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 270310                                                        | Aileron and Elevator Control Module Assembly ROD (Pilot, Inboard) - Discard     |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                                               | 60P2711003Z001                                                                  | 197912        | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                                               |                                                                                 |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                                               | Airframe                                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |

| ATA<br>U=Custom                | Description                                      |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|--------------------------------|--------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                | Part Number                                      | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position               | HW                                               | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                | MM Ref                                           |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                                | Ops Number(s)                                    |               |     |             |                 |     |                  |             |                    |         |              |
| 270311                         | Aileron and Elevator Control Module Assembly ROD |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | (Copilot, Inboard) - Discard                     |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                | 60P2711003Z001                                   | 197915        | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                |                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                       |                                                  |               |     |             |                 |     |                  |             |                    |         |              |
| 270312                         | Aileron and Elevator Control Module Assembly ROD |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | (Pilot, Outboard) - Discard                      |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                | 60P2711004Z001                                   | 218802        | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                |                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                       |                                                  |               |     |             |                 |     |                  |             |                    |         |              |
| 270313                         | Aileron and Elevator Control Module Assembly ROD |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | (Copilot, Outboard) - Discard                    |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                | 60P2711004Z001                                   | 218759        | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                |                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                       |                                                  |               |     |             |                 |     |                  |             |                    |         |              |
| 270314                         | Aileron and Elevator Control Module Assembly ROD |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | (Pilot, Center) - Discard                        |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                | 60P2711005Z001                                   | 231825        | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                |                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                       |                                                  |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 271112 |                                                  |               |     |             |                 |     |                  |             |                    |         |              |
| 270315                         | Aileron and Elevator Control Module Assembly ROD |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | (Copilot, Center) - Discard                      |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                | 60P2711005Z001                                   | 231822        | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                |                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                       |                                                  |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 271113 |                                                  |               |     |             |                 |     |                  |             |                    |         |              |
| 270316                         | Aileron and Elevator Control Module Assembly     |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | Interconnect ROD - Discard                       |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                | 60P2711006Z001                                   | 238462        | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                |                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                       |                                                  |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 271140 |                                                  |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom                       | Description                                                      |               | UOM            | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|---------------------------------------|------------------------------------------------------------------|---------------|----------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                       | Part Number                                                      | Serial Number |                |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position                      | HW                                                               | SW            |                |             |                 |     |                  |             |                    |         | Manufacturer |
|                                       | MM Ref                                                           |               |                |             |                 |     |                  |             |                    |         | Date Type    |
|                                       | Ops Number(s)                                                    |               |                |             |                 |     |                  |             |                    |         |              |
| 270317                                | Aileron and Elevator Control Module Assembly (Pilot) - Discard   |               | HRS            |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                       |                                                                  |               | AFL            |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                       | 60P2711101Z004                                                   | 230281        | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                       |                                                                  |               | MSC            |             |                 |     | O/C              |             |                    |         |              |
| Airframe                              |                                                                  |               |                |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 270300        |                                                                  |               |                |             |                 |     |                  |             |                    |         |              |
| 270318                                | Aileron and Elevator Control Module Assembly (Copilot) - Discard |               | HRS            |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                       |                                                                  |               | AFL            |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                       | 60P2711201Z004                                                   | 167765        | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                       |                                                                  |               | MSC            |             |                 |     | O/C              |             |                    |         |              |
| Airframe                              |                                                                  |               |                |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 270301        |                                                                  |               |                |             |                 |     |                  |             |                    |         |              |
| 271000                                | Aileron Electrical Rig (Left) - Functional Check                 |               | HRS            |             | 1452            |     |                  | 1594.1      |                    |         | 0            |
|                                       |                                                                  |               | AFL            |             | 570             |     |                  | 547         |                    |         | 0            |
|                                       |                                                                  |               | MOS            |             | 63.6            |     |                  | 24 Jan 2021 |                    |         |              |
|                                       |                                                                  |               | MSC            |             |                 |     | O/C              |             |                    |         |              |
| Airframe                              |                                                                  |               |                |             |                 |     |                  |             |                    |         |              |
| 271001                                | Aileron Electrical Rig (Right) - Functional Check                |               | HRS            |             | 1452            |     |                  | 1594.1      |                    |         | 0            |
|                                       |                                                                  |               | AFL            |             | 570             |     |                  | 547         |                    |         | 0            |
|                                       |                                                                  |               | MOS            |             | 63.5            |     |                  | 25 Jan 2021 |                    |         |              |
|                                       |                                                                  |               | MSC            |             |                 |     | O/C              |             |                    |         |              |
| Airframe                              |                                                                  |               |                |             |                 |     |                  |             |                    |         |              |
| 271002                                | Aileron Actuating System Ibit Suite A Test - Operational Check   |               | HRS            |             | 137             |     | 600              | 2909.1      | 3509.1             | 3559.1  | 0            |
|                                       |                                                                  |               | AFL            |             | 52              |     |                  | 1065        |                    |         | 0            |
|                                       |                                                                  |               | MOS            |             | 5.3             |     |                  | 02 Dec 2025 |                    |         |              |
|                                       |                                                                  |               | [HRS: +50/-50] |             |                 |     |                  |             |                    |         |              |
| Airframe                              |                                                                  |               |                |             |                 |     |                  |             |                    |         |              |
| Notes: PN: 60P5760001A008 SN: <NONE>. |                                                                  |               |                |             |                 |     |                  |             |                    |         |              |
| 271004                                | Aileron (Left) - Functional Test                                 |               | HRS            |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                                       |                                                                  |               | AFL            |             | 315             |     |                  | 802         |                    |         | 0            |
|                                       |                                                                  |               | MOS            |             | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
|                                       |                                                                  |               | MSC            |             |                 |     | O/C              |             |                    |         |              |
| Airframe                              |                                                                  |               |                |             |                 |     |                  |             |                    |         |              |
| 271005                                | Aileron (Right) - Functional Test                                |               | HRS            |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                                       |                                                                  |               | AFL            |             | 315             |     |                  | 802         |                    |         | 0            |
|                                       |                                                                  |               | MOS            |             | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
|                                       |                                                                  |               | MSC            |             |                 |     | O/C              |             |                    |         |              |
| Airframe                              |                                                                  |               |                |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                                                 |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|-------------------------------------------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                                                                                 | Serial Number |                                    |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                                                                          | SW            |                                    |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                                                                      |               |                                    |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                                                                               |               |                                    |             |                 |     |                  |             |                     |         |              |
| 271006           | Aileron / Flight Spoiler System - Functional Test                                                           |               | HRS                                |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                                                             |               | AFL                                |             | 1117            |     |                  | 0           |                     | 0       |              |
|                  |                                                                                                             |               | MOS                                |             | 128.6           |     | 24 Aug 2015      |             |                     |         |              |
|                  |                                                                                                             |               | MSC                                |             |                 | O/C |                  |             |                     |         |              |
| 271007           | Aileron Attachment (Left) - Detailed Inspection                                                             |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                     |         | 0            |
|                  |                                                                                                             |               | AFL                                |             | 315             |     |                  | 802         |                     |         | 0            |
|                  |                                                                                                             |               | MOS                                |             | 28.7            | 48  | 21 Dec 2023      | 31 Dec 2027 | 31 Jan 2028         |         |              |
|                  |                                                                                                             |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                     |         |              |
| Airframe         | 052013                                                                                                      |               |                                    |             |                 |     |                  |             |                     |         |              |
| 271008           | Aileron Attachment (Right) - Detailed Inspection                                                            |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                     |         | 0            |
|                  |                                                                                                             |               | AFL                                |             | 315             |     |                  | 802         |                     |         | 0            |
|                  |                                                                                                             |               | MOS                                |             | 28.7            | 48  | 21 Dec 2023      | 31 Dec 2027 | 31 Jan 2028         |         |              |
|                  |                                                                                                             |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                     |         |              |
| Airframe         | 052013                                                                                                      |               |                                    |             |                 |     |                  |             |                     |         |              |
| 271009           | Primary Flight Control System Actuator Integrity (Suite B)<br>- Initiated Built-In Test - Operational Check |               | HRS                                |             | 3046.1          |     | 6000             | 0           | 6000                | 6050    | 0            |
|                  |                                                                                                             |               | AFL                                |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  |                                                                                                             |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                                                             |               | [HRS: +50/-50]                     |             |                 |     |                  |             |                     |         |              |
| Airframe         |                                                                                                             |               |                                    |             |                 |     |                  |             |                     |         |              |
| 271100           | Aileron (Left) - Removal / Installation<br>60P5760001A012-01A LM0137                                        |               | HRS                                |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                                                             |               | AFL                                |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  |                                                                                                             |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                                                             |               | MSC                                |             |                 | O/C |                  |             |                     |         |              |
| Airframe         |                                                                                                             |               |                                    |             |                 |     |                  |             |                     |         |              |
| 271101           | Aileron (Right) - Removal / Installation<br>60P5760002A008-02A LM0145                                       |               | HRS                                |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                                                             |               | AFL                                |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  |                                                                                                             |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                                                             |               | MSC                                |             |                 | O/C |                  |             |                     |         |              |
| Airframe         |                                                                                                             |               |                                    |             |                 |     |                  |             |                     |         |              |
| 271102           | Cockpit Flight Control Cable (Pilot Inboard Forward) -<br>Removal / Installation<br>60P2711303Z300 NSN      |               | HRS                                |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                                                             |               | AFL                                |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  |                                                                                                             |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                                                             |               | MSC                                |             |                 | O/C |                  |             |                     |         |              |
| Airframe         |                                                                                                             |               |                                    |             |                 |     |                  |             |                     |         |              |
| 271103           | Cockpit Flight Control Cable (Copilot Inboard Forward) -<br>Removal / Installation<br>60P2711303Z300 NSN    |               | HRS                                |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                                                             |               | AFL                                |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  |                                                                                                             |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                                                             |               | MSC                                |             |                 | O/C |                  |             |                     |         |              |
| Airframe         |                                                                                                             |               |                                    |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom  | Description                                                                      |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                      | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                               | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                           |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                                    |               |     |             |                 |     |                  |             |                    |         |              |
| 271104           | Cockpit Flight Control Cable (Pilot Inboard Aft) - Removal / Installation        |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                  |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P2711301Z400                                                                   | NSN           | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                  |               |     |             |                 |     |                  |             |                    |         |              |
| 271105           | Cockpit Flight Control Cable (Copilot Inboard Aft) - Removal / Installation      |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                  |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P2711301Z400                                                                   | NSN           | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                  |               |     |             |                 |     |                  |             |                    |         |              |
| 271106           | Cockpit Flight Control Cable (Pilot Outboard Forward) - Removal / Installation   |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                  |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P2711301Z100                                                                   | NSN           | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                  |               |     |             |                 |     |                  |             |                    |         |              |
| 271107           | Cockpit Flight Control Cable (Copilot Outboard Forward) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                  |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P2711301Z100                                                                   | NSN           | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                  |               |     |             |                 |     |                  |             |                    |         |              |
| 271108           | Cockpit Flight Control Cable (Pilot Outboard Aft) - Removal / Installation       |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                  |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P2711301Z200                                                                   | NSN           | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                  |               |     |             |                 |     |                  |             |                    |         |              |
| 271109           | Cockpit Flight Control Cable (Copilot Outboard Aft) - Removal / Installation     |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                  |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P2711301Z200                                                                   | NSN           | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                  |               |     |             |                 |     |                  |             |                    |         |              |
| 271110           | Aileron Force Sensor (Pilot) - Removal / Installation                            |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P2711106Z003                                                                   | P1408F        | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                  |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                  |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                         | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                     |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                              |               |     |             |                 |     |                  |             |                    |         |              |
| 271111           | Aileron Force Sensor (Copilot) - Removal / Installation    |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P2711106Z003                                             | Q121DP        | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                            |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                   |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 271112           | Secondary Load Path Lateral / Longitudinal Control (Pilot) |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | - Removal / Installation                                   |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P2711005Z001                                             | 231825        | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                   |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 271113           | Secondary Load Path Lateral / Longitudinal Control         |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | (Copilot) - Removal / Installation                         |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P2711005Z001                                             | 231822        | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                   |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 271114           | Aileron Control Override Pushrod - Removal / Installation  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P2711310Z002                                             | 249111        | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                            |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                   |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 271115           | Aileron Trim Interconnect Pushrod - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P2711309Z001                                             | 168679        | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                            |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                   |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 271119           | Aileron Trim Actuator - Removal / Installation             |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P2711110Z001                                             | 171           | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                            |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                   |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 271120           | Trim Control Module - Removal / Installation               |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P2711002Z005                                             | 237526        | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                            |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                   |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 271122           | Aileron Control Module Rvdt (Pilot) - Removal /            |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | Installation                                               |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P2711107Z002                                             | A827          | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                   |               | MSC |             |                 |     | O/C              |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                                         |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------|-----------------------------------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                  | Part Number                                                                                         | Serial Number |                                    |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position | HW                                                                                                  | SW            |                                    |             |                 |     |                  |             |                    |             | Manufacturer |
|                  | MM Ref                                                                                              |               |                                    |             |                 |     |                  |             |                    |             | Date Type    |
|                  | Ops Number(s)                                                                                       |               |                                    |             |                 |     |                  |             |                    |             |              |
| 271123           | Elevator Control Module Rvdt (Pilot) - Removal / Installation                                       |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                     |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  | 60P2711107Z002                                                                                      | A828          | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                                     |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                                     |               |                                    |             |                 |     |                  |             |                    |             |              |
| 271124           | Elevator Control Module Rvdt (Copilot) - Removal / Installation                                     |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                     |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  | 60P2711107Z002                                                                                      | A1037         | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                                     |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                                     |               |                                    |             |                 |     |                  |             |                    |             |              |
| 271125           | Aileron Control Module Rvdt (Copilot) - Removal / Installation                                      |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                     |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  | 60P2711107Z002                                                                                      | A193          | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                                     |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                                     |               |                                    |             |                 |     |                  |             |                    |             |              |
| 271126           | Aileron Control Override Pushrod Bungee Torque - Functional Check                                   |               | HRS                                |             | 730.5           |     | 6000             | 2315.6      | 8315.6             | 8365.6      | 0            |
|                  |                                                                                                     |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                                                     |               | MOS                                |             | 28.7            |     |                  | 21 Dec 2023 |                    |             |              |
|                  |                                                                                                     |               | [HRS: +50/-50]                     |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                                     |               |                                    |             |                 |     |                  |             |                    |             |              |
| 052007           |                                                                                                     |               |                                    |             |                 |     |                  |             |                    |             |              |
| 271127           | Aileron Trim Centering Bungee - General Visual Inspection                                           |               | HRS                                |             | 3046.1          |     | 6000             | 0           | 6000               |             | 0            |
|                  |                                                                                                     |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                     |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                                     |               | [HRS: -50]                         |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                                     |               |                                    |             |                 |     |                  |             |                    |             |              |
| 052007           |                                                                                                     |               |                                    |             |                 |     |                  |             |                    |             |              |
| 271128           | Cockpit Flight Control Cable - Detailed Inspection                                                  |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                                                     |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                                                     |               | MOS                                |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031        | 31 Jan 2032 |              |
|                  |                                                                                                     |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                                     |               |                                    |             |                 |     |                  |             |                    |             |              |
| 052016           |                                                                                                     |               |                                    |             |                 |     |                  |             |                    |             |              |
| 271134           | Cockpit Flight Control Cable Retaining Pin (Pilot Control Module, Inboard) - Removal / Installation |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                     |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  | 60P2700005Z001                                                                                      | SN-UNKNOWN    | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                                     |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                                     |               |                                    |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom                | Description                                                                                           |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(* =Adj) | Max Due | Avg Man Hrs  |
|--------------------------------|-------------------------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|----------------------|---------|--------------|
|                                | Part Number                                                                                           | Serial Number |     |             |                 |     |                  |             |                      |         | Approx Price |
| Logbook Position               | HW                                                                                                    | SW            |     |             |                 |     |                  |             |                      |         | Manufacturer |
|                                | MM Ref                                                                                                |               |     |             |                 |     |                  |             |                      |         | Date Type    |
|                                | Ops Number(s)                                                                                         |               |     |             |                 |     |                  |             |                      |         |              |
| 271135                         | Cockpit Flight Control Cable Retaining Pin (Copilot Control Module, Inboard) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                      |         | 0            |
|                                |                                                                                                       |               | AFL |             | 1117            |     |                  | 0           |                      |         | 0            |
|                                | 60P2700005Z001                                                                                        | SN-UNKNOWN    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                      |         |              |
|                                |                                                                                                       |               | MSC |             |                 |     | O/C              |             |                      |         |              |
| Airframe                       |                                                                                                       |               |     |             |                 |     |                  |             |                      |         |              |
| 271140                         | ROD - Reaction, Lateral / Longitudinal Control Module - Removal / Installation                        |               | HRS |             | 3046.1          |     |                  | 0           |                      |         | 0            |
|                                |                                                                                                       |               | AFL |             | 1117            |     |                  | 0           |                      |         | 0            |
|                                | 60P2711006Z001                                                                                        | 238462        | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                      |         |              |
|                                |                                                                                                       |               | MSC |             |                 |     | O/C              |             |                      |         |              |
| Airframe                       |                                                                                                       |               |     |             |                 |     |                  |             |                      |         |              |
| 271168                         | Aileron Trim Interconnect Pushrod - Discard                                                           |               | HRS |             | 3046.1          |     |                  | 0           |                      |         | 0            |
|                                |                                                                                                       |               | AFL |             | 1117            |     |                  | 0           |                      |         | 0            |
|                                | 60P2711309Z001                                                                                        | 168679        | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                      |         |              |
|                                |                                                                                                       |               | MSC |             |                 |     | O/C              |             |                      |         |              |
| Airframe                       |                                                                                                       |               |     |             |                 |     |                  |             |                      |         |              |
| Notes: MRI PARENT CODE: 271115 |                                                                                                       |               |     |             |                 |     |                  |             |                      |         |              |
| 271169                         | Aileron Control Override Pushrod - Discard                                                            |               | HRS |             | 3046.1          |     |                  | 0           |                      |         | 0            |
|                                |                                                                                                       |               | AFL |             | 1117            |     |                  | 0           |                      |         | 0            |
|                                | 60P2711310Z002                                                                                        | 249111        | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                      |         |              |
|                                |                                                                                                       |               | MSC |             |                 |     | O/C              |             |                      |         |              |
| Airframe                       |                                                                                                       |               |     |             |                 |     |                  |             |                      |         |              |
| Notes: MRI PARENT CODE: 271114 |                                                                                                       |               |     |             |                 |     |                  |             |                      |         |              |
| 271170                         | Aileron Control Cable Pulley Bracket (Pilot Inboard) - Discard                                        |               | HRS |             | 3046.1          |     |                  | 0           |                      |         | 0            |
|                                |                                                                                                       |               | AFL |             | 1117            |     |                  | 0           |                      |         | 0            |
|                                | 60P2711501Z001                                                                                        | 214           | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                      |         |              |
|                                |                                                                                                       |               | MSC |             |                 |     | O/C              |             |                      |         |              |
| Airframe                       |                                                                                                       |               |     |             |                 |     |                  |             |                      |         |              |
| 271171                         | Aileron Control Cable Pulley Bracket (Pilot Outboard) - Discard                                       |               | HRS |             | 3046.1          |     |                  | 0           |                      |         | 0            |
|                                |                                                                                                       |               | AFL |             | 1117            |     |                  | 0           |                      |         | 0            |
|                                | 60P2711502Z001                                                                                        | 194           | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                      |         |              |
|                                |                                                                                                       |               | MSC |             |                 |     | O/C              |             |                      |         |              |
| Airframe                       |                                                                                                       |               |     |             |                 |     |                  |             |                      |         |              |
| 271172                         | Aileron Control Cable Pulley Bracket (Copilot Inboard) - Discard                                      |               | HRS |             | 3046.1          |     |                  | 0           |                      |         | 0            |
|                                |                                                                                                       |               | AFL |             | 1117            |     |                  | 0           |                      |         | 0            |
|                                | 60P2711503Z001                                                                                        | 238           | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                      |         |              |
|                                |                                                                                                       |               | MSC |             |                 |     | O/C              |             |                      |         |              |
| Airframe                       |                                                                                                       |               |     |             |                 |     |                  |             |                      |         |              |



| ATA<br>U=Custom  | Description                                                                                            |               | UOM                                               | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due     | Avg Man Hrs  |
|------------------|--------------------------------------------------------------------------------------------------------|---------------|---------------------------------------------------|-------------|-----------------|-----|------------------|-------------|---------------------|-------------|--------------|
|                  | Part Number                                                                                            | Serial Number |                                                   |             |                 |     |                  |             |                     |             | Approx Price |
| Logbook Position | HW                                                                                                     | SW            |                                                   |             |                 |     |                  |             |                     |             | Manufacturer |
|                  | MM Ref                                                                                                 |               |                                                   |             |                 |     |                  |             |                     |             | Date Type    |
|                  | Ops Number(s)                                                                                          |               |                                                   |             |                 |     |                  |             |                     |             |              |
| 271173           | Aileron Control Cable Pulley Bracket (Copilot Outboard) - Discard                                      |               | HRS                                               |             | 3046.1          |     |                  | 0           |                     |             | 0            |
|                  |                                                                                                        |               | AFL                                               |             | 1117            |     |                  | 0           |                     |             | 0            |
|                  | 60P2711504Z001                                                                                         | 237           | MOS                                               |             | 128.6           |     |                  | 24 Aug 2015 |                     |             |              |
|                  |                                                                                                        |               | MSC                                               |             |                 |     | O/C              |             |                     |             |              |
| Airframe         |                                                                                                        |               |                                                   |             |                 |     |                  |             |                     |             |              |
| 271182           | Aileron Free Play Backlash (Left) - Functional Check                                                   |               | HRS                                               |             | 730.5           |     | 1200             | 2315.6      | 3515.6              | 3565.6      | 0            |
|                  |                                                                                                        |               | AFL                                               |             | 315             |     |                  | 802         |                     |             | 0            |
|                  |                                                                                                        |               | MOS                                               |             | 28.7            |     | 120              | 21 Dec 2023 | 31 Dec 2033         | 31 Jan 2034 |              |
|                  |                                                                                                        |               | [End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50] |             |                 |     |                  |             |                     |             |              |
| Airframe         |                                                                                                        |               |                                                   |             |                 |     |                  |             |                     |             |              |
| 271183           | Aileron Free Play Backlash (Right) - Functional Check                                                  |               | HRS                                               |             | 730.5           |     | 1200             | 2315.6      | 3515.6              | 3565.6      | 0            |
|                  |                                                                                                        |               | AFL                                               |             | 315             |     |                  | 802         |                     |             | 0            |
|                  |                                                                                                        |               | MOS                                               |             | 28.7            |     | 120              | 21 Dec 2023 | 31 Dec 2033         | 31 Jan 2034 |              |
|                  |                                                                                                        |               | [End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50] |             |                 |     |                  |             |                     |             |              |
| Airframe         |                                                                                                        |               |                                                   |             |                 |     |                  |             |                     |             |              |
| 271184           | Aileron Control Cable Pulley (Pilot Outboard) - Removal / Installation                                 |               | HRS                                               |             | 3046.1          |     |                  | 0           |                     |             | 0            |
|                  |                                                                                                        |               | AFL                                               |             | 1117            |     |                  | 0           |                     |             | 0            |
|                  | PN                                                                                                     | SN-UNKNOWN    | MOS                                               |             | 128.6           |     |                  | 24 Aug 2015 |                     |             |              |
|                  |                                                                                                        |               | MSC                                               |             |                 |     | O/C              |             |                     |             |              |
| Airframe         |                                                                                                        |               |                                                   |             |                 |     |                  |             |                     |             |              |
| 271185           | Aileron Control Cable Pulley (Pilot Inboard) - Removal / Installation                                  |               | HRS                                               |             | 3046.1          |     |                  | 0           |                     |             | 0            |
|                  |                                                                                                        |               | AFL                                               |             | 1117            |     |                  | 0           |                     |             | 0            |
|                  | PN                                                                                                     | SN-UNKNOWN    | MOS                                               |             | 128.6           |     |                  | 24 Aug 2015 |                     |             |              |
|                  |                                                                                                        |               | MSC                                               |             |                 |     | O/C              |             |                     |             |              |
| Airframe         |                                                                                                        |               |                                                   |             |                 |     |                  |             |                     |             |              |
| 271186           | Cockpit Flight Control Cable Retaining Pin (Pilot Control Module, Outboard) - Removal / Installation   |               | HRS                                               |             | 3046.1          |     |                  | 0           |                     |             | 0            |
|                  |                                                                                                        |               | AFL                                               |             | 1117            |     |                  | 0           |                     |             | 0            |
|                  | PN                                                                                                     | SN-UNKNOWN    | MOS                                               |             | 128.6           |     |                  | 24 Aug 2015 |                     |             |              |
|                  |                                                                                                        |               | MSC                                               |             |                 |     | O/C              |             |                     |             |              |
| Airframe         |                                                                                                        |               |                                                   |             |                 |     |                  |             |                     |             |              |
| 271187           | Cockpit Flight Control Cable Retaining Pin (Copilot Control Module, Outboard) - Removal / Installation |               | HRS                                               |             | 3046.1          |     |                  | 0           |                     |             | 0            |
|                  |                                                                                                        |               | AFL                                               |             | 1117            |     |                  | 0           |                     |             | 0            |
|                  | PN                                                                                                     | SN-UNKNOWN    | MOS                                               |             | 128.6           |     |                  | 24 Aug 2015 |                     |             |              |
|                  |                                                                                                        |               | MSC                                               |             |                 |     | O/C              |             |                     |             |              |
| Airframe         |                                                                                                        |               |                                                   |             |                 |     |                  |             |                     |             |              |

| ATA<br>U=Custom  | Description                                                              |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|--------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                              | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                       | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                   |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                            |               |     |             |                 |     |                  |             |                    |         |              |
| 271192           | Aileron Control Cable Pulley (Copilot Outboard) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                          |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | PN                                                                       | SN-UNKNOWN    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                          |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| 271193           | Aileron Control Cable Pulley (Copilot Inboard) - Removal / Installation  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                          |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | PN                                                                       | SN-UNKNOWN    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                          |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| 271300           | Elevator Remote Electronics Unit (Left Ehsa) - Removal / Installation    |               | HRS |             | 2345.1          |     |                  | 701         |                    |         | 0            |
|                  |                                                                          |               | AFL |             | 936             |     |                  | 181         |                    |         | 0            |
|                  | 60P2715001Z006                                                           | 3387          | MOS |             | 96.7            |     |                  | 20 Apr 2018 |                    |         |              |
|                  |                                                                          |               | 34  | MSC         |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| 271301           | Elevator Remote Electronics Unit (Left Ebha) - Removal / Installation    |               | HRS |             | 2345.1          |     |                  | 701         |                    |         | 0            |
|                  |                                                                          |               | AFL |             | 936             |     |                  | 181         |                    |         | 0            |
|                  | 60P2715001Z007                                                           | 5703          | MOS |             | 96.8            |     |                  | 17 Apr 2018 |                    |         |              |
|                  |                                                                          |               | 34  | MSC         |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| 271302           | Elevator Remote Electronics Unit (Right Ehsa) - Removal / Installation   |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  |                                                                          |               | AFL |             | 315             |     |                  | 802         |                    |         | 0            |
|                  | 60P2715001Z006                                                           | 3870          | MOS |             | 29.9            |     |                  | 15 Nov 2023 |                    |         |              |
|                  |                                                                          |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| 271303           | Elevator Remote Electronics Unit (Right Ebha) - Removal / Installation   |               | HRS |             | 2345.1          |     |                  | 701         |                    |         | 0            |
|                  |                                                                          |               | AFL |             | 936             |     |                  | 181         |                    |         | 0            |
|                  | 60P2715001Z006                                                           | 3870          | MOS |             | 96.7            |     |                  | 20 Apr 2018 |                    |         |              |
|                  |                                                                          |               | 34  | MSC         |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| 271304           | Elevator Eb Manifold (Left) - Removal / Installation                     |               | HRS |             | 1452            |     |                  | 1594.1      |                    |         | 0            |
|                  |                                                                          |               | AFL |             | 570             |     |                  | 547         |                    |         | 0            |
|                  | 60P2713301Z004                                                           | 0081D         | MOS |             | 63.9            |     |                  | 14 Jan 2021 |                    |         |              |
|                  |                                                                          |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                          |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                          |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                          | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                   | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                               |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 271305           | Elevator Eb Manifold (Right) - Removal / Installation                |               | HRS |             | 1452            |     |                  | 1594.1      |                    |         | 0            |
|                  | 60P2713301Z004                                                       | 1457D         | AFL |             | 570             |     |                  | 547         |                    |         | 0            |
|                  |                                                                      |               | MOS |             | 63.9            |     |                  | 14 Jan 2021 |                    |         |              |
|                  | Airframe                                                             |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 271306           | Elevator Motor Control Electronics (Left) - Removal / Installation   |               | HRS | TSN:1594.1  | 1452            |     |                  | 1594.1      |                    |         | 0            |
|                  |                                                                      |               | AFL | TSN:547     | 570             |     |                  | 547         |                    |         | 0            |
|                  | 60P2715003Z309                                                       | 0588          | MOS | TSN:65      | 63.9            |     |                  | 15 Jan 2021 |                    |         |              |
|                  | Airframe                                                             |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 271307           | Elevator Motor Control Electronics (Right) - Removal / Installation  |               | HRS | TSN:1594.1  | 1452            |     |                  | 1594.1      |                    |         | 0            |
|                  |                                                                      |               | AFL | TSN:547     | 570             |     |                  | 547         |                    |         | 0            |
|                  | 60P2715003Z309                                                       | 0577          | MOS | TSN:65      | 63.9            |     |                  | 15 Jan 2021 |                    |         |              |
|                  | Airframe                                                             |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 271308           | Rudder Remote Electronics Unit (Ehsa) - Removal / Installation       |               | HRS |             | 2345.1          |     |                  | 701         |                    |         | 0            |
|                  |                                                                      |               | AFL |             | 936             |     |                  | 181         |                    |         | 0            |
|                  | 60P2715001Z006                                                       | 3872          | MOS |             | 96.7            |     |                  | 20 Apr 2018 |                    |         |              |
|                  | Airframe                                                             |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 271309           | Rudder Remote Electronics Unit (Ha) - Removal / Installation         |               | HRS |             | 2345.1          |     |                  | 701         |                    |         | 0            |
|                  |                                                                      |               | AFL |             | 936             |     |                  | 181         |                    |         | 0            |
|                  | 60P2715001Z006                                                       | 3871          | MOS |             | 96.7            |     |                  | 20 Apr 2018 |                    |         |              |
|                  | Airframe                                                             |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 271310           | Aileron Remote Electronics Unit (Left Ehsa) - Removal / Installation |               | HRS |             | 2345.1          |     |                  | 701         |                    |         | 0            |
|                  |                                                                      |               | AFL |             | 936             |     |                  | 181         |                    |         | 0            |
|                  | 60P2715001Z006                                                       | 3163          | MOS |             | 96.7            |     |                  | 20 Apr 2018 |                    |         |              |
|                  | Airframe                                                             |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 271311           | Aileron Remote Electronics Unit (Left Ha) - Removal / Installation   |               | HRS |             | 2345.1          |     |                  | 701         |                    |         | 0            |
|                  |                                                                      |               | AFL |             | 936             |     |                  | 181         |                    |         | 0            |
|                  | 60P2715001Z007                                                       | 4257          | MOS |             | 96.6            |     |                  | 22 Apr 2018 |                    |         |              |
|                  | Airframe                                                             |               | MSC |             |                 |     | O/C              |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                           |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(* = Adj) | Max Due | Avg Man Hrs  |
|------------------|-----------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|-----------------------|---------|--------------|
|                  | Part Number                                                           | Serial Number |     |             |                 |     |                  |             |                       |         | Approx Price |
| Logbook Position | HW                                                                    | SW            |     |             |                 |     |                  |             |                       |         | Manufacturer |
|                  | MM Ref                                                                |               |     |             |                 |     |                  |             |                       |         | Date Type    |
|                  | Ops Number(s)                                                         |               |     |             |                 |     |                  |             |                       |         |              |
| 271312           | Aileron Remote Electronics Unit (Right Ehsa) - Removal / Installation |               | HRS |             | 2345.1          |     |                  | 701         |                       |         | 0            |
|                  |                                                                       |               | AFL |             | 936             |     |                  | 181         |                       |         | 0            |
|                  | 60P2715001Z000                                                        | 4052          | MOS |             | 96.7            |     |                  | 20 Apr 2018 |                       |         |              |
|                  | 34                                                                    |               | MSC |             |                 |     | O/C              |             |                       |         |              |
| Airframe         |                                                                       |               |     |             |                 |     |                  |             |                       |         |              |
| 271313           | Aileron Remote Electronics Unit (Right Ha) - Removal / Installation   |               | HRS |             | 2345.1          |     |                  | 701         |                       |         | 0            |
|                  |                                                                       |               | AFL |             | 936             |     |                  | 181         |                       |         | 0            |
|                  | 60P2715001Z006                                                        | 4040          | MOS |             | 96.7            |     |                  | 20 Apr 2018 |                       |         |              |
|                  | 34                                                                    |               | MSC |             |                 |     | O/C              |             |                       |         |              |
| Airframe         |                                                                       |               |     |             |                 |     |                  |             |                       |         |              |
| 271314           | Aileron Motor Control Electronics (Left) - Removal / Installation     |               | HRS | TSN:1594.1  | 1452            |     |                  | 1594.1      |                       |         | 0            |
|                  |                                                                       |               | AFL | TSN:547     | 570             |     |                  | 547         |                       |         | 0            |
|                  | 60P2715003Z310                                                        | 0764          | MOS | TSN:65      | 63.9            |     |                  | 15 Jan 2021 |                       |         |              |
|                  |                                                                       |               | MSC |             |                 |     | O/C              |             |                       |         |              |
| Airframe         |                                                                       |               |     |             |                 |     |                  |             |                       |         |              |
| 271315           | Aileron Motor Control Electronics (Right) - Removal / Installation    |               | HRS |             | 1452            |     |                  | 1594.1      |                       |         | 0            |
|                  |                                                                       |               | AFL |             | 570             |     |                  | 547         |                       |         | 0            |
|                  | 60P2725003Z322                                                        | 3705          | MOS |             | 63.6            |     |                  | 24 Jan 2021 |                       |         |              |
|                  |                                                                       |               | MSC |             |                 |     | O/C              |             |                       |         |              |
| Airframe         |                                                                       |               |     |             |                 |     |                  |             |                       |         |              |
| 271320           | Aileron Ha Manifold (Left) - Removal / Installation                   |               | HRS |             | 3046.1          |     |                  | 0           |                       |         | 0            |
|                  | 60P2713101Z006                                                        |               | AFL |             | 1117            |     |                  | 0           |                       |         | 0            |
|                  | 0374A                                                                 |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                       |         |              |
|                  |                                                                       |               | MSC |             |                 |     | O/C              |             |                       |         |              |
| Airframe         |                                                                       |               |     |             |                 |     |                  |             |                       |         |              |
| 271321           | Aileron Ha Manifold (Right) - Removal / Installation                  |               | HRS |             | 3046.1          |     |                  | 0           |                       |         | 0            |
|                  | 60P2713101Z006                                                        |               | AFL |             | 1117            |     |                  | 0           |                       |         | 0            |
|                  | 0376A                                                                 |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                       |         |              |
|                  |                                                                       |               | MSC |             |                 |     | O/C              |             |                       |         |              |
| Airframe         |                                                                       |               |     |             |                 |     |                  |             |                       |         |              |
| 271322           | Aileron Eb Manifold (Left) - Removal / Installation                   |               | HRS |             | 1452            |     |                  | 1594.1      |                       |         | 0            |
|                  | 60P2713301Z004                                                        |               | AFL |             | 570             |     |                  | 547         |                       |         | 0            |
|                  | 1197D                                                                 |               | MOS |             | 63.9            |     |                  | 14 Jan 2021 |                       |         |              |
|                  |                                                                       |               | MSC |             |                 |     | O/C              |             |                       |         |              |
| Airframe         |                                                                       |               |     |             |                 |     |                  |             |                       |         |              |

| ATA<br>U=Custom                | Description                                            |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|--------------------------------|--------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                | Part Number                                            | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position               | HW                                                     | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                | MM Ref                                                 |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                                | Ops Number(s)                                          |               |     |             |                 |     |                  |             |                    |         |              |
| 271323                         | Aileron Eb Manifold (Right) - Removal / Installation   |               | HRS |             | 1452            |     |                  | 1594.1      |                    |         | 0            |
|                                | 60P2713301Z004                                         | 0877D         | AFL |             | 570             |     |                  | 547         |                    |         | 0            |
|                                |                                                        |               | MOS |             | 63.6            |     |                  | 24 Jan 2021 |                    |         |              |
|                                | Airframe                                               |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 271324                         | Aileron Ehsa Manifold (Left) - Removal / Installation  |               | HRS |             | 2345.1          |     |                  | 701         |                    |         | 0            |
|                                | 60P2713201Z005                                         | 0405A         | AFL |             | 936             |     |                  | 181         |                    |         | 0            |
|                                |                                                        |               | MOS |             | 96.9            |     |                  | 15 Apr 2018 |                    |         |              |
|                                | Airframe                                               |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 271325                         | Aileron Ehsa Manifold (Right) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | 60P2713201Z005                                         | 0361A         | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                |                                                        |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                               |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 271326                         | Aileron Ehsa Actuator (Left) - Removal / Installation  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | 60P2713002Z101                                         | 0728          | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                |                                                        |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                               |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 271327                         | Aileron Ehsa Actuator (Right) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | 60P2713002Z201                                         | 0763          | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                |                                                        |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                               |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 271328                         | Aileron Ebha Actuator (Left) - Removal / Installation  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | 60P2713001Z101                                         | 0743          | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                |                                                        |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                               |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 271329                         | Aileron Ebha Actuator (Right) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | 60P2713001Z201                                         | 0754          | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                |                                                        |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                               |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 271360                         | Aileron Ha Manifold (Left) - Discard                   |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | 60P2713101Z006                                         | 0374A         | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                |                                                        |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                               |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Notes: MRI PARENT CODE: 271320 |                                                        |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom                | Description                                                |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|--------------------------------|------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                                | Part Number                                                | Serial Number |     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position               | HW                                                         | SW            |     |             |                 |     |                  |             |                     |         | Manufacturer |
|                                | MM Ref                                                     |               |     |             |                 |     |                  |             |                     |         | Date Type    |
|                                | Ops Number(s)                                              |               |     |             |                 |     |                  |             |                     |         |              |
| 271361                         | Aileron Ha Manifold (Right) - Discard                      |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                                | 60P2713101Z006                                             | 0376A         | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                                |                                                            |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                                | Airframe                                                   |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Notes: MRI PARENT CODE: 271321 |                                                            |               |     |             |                 |     |                  |             |                     |         |              |
| 271362                         | Aileron Ehsa Manifold (Left) - Discard                     |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                                | 60P2713201Z005                                             | 0365A         | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                                |                                                            |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                                | Airframe                                                   |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Notes: MRI PARENT CODE: 271324 |                                                            |               |     |             |                 |     |                  |             |                     |         |              |
| 271363                         | Aileron Ehsa Manifold (Right) - Discard                    |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                                | 60P2713201Z005                                             | 0361A         | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                                |                                                            |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                                | Airframe                                                   |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Notes: MRI PARENT CODE: 271325 |                                                            |               |     |             |                 |     |                  |             |                     |         |              |
| 271530                         | Aileron Trim Actuator Range of Motion - Functional Test    |               | HRS |             | 730.5           |     |                  | 2315.6      |                     |         | 0            |
|                                |                                                            |               | AFL |             | 315             |     |                  | 802         |                     |         | 0            |
|                                |                                                            |               | MOS |             | 28.7            |     |                  | 21 Dec 2023 |                     |         |              |
|                                | Airframe                                                   |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| 271600                         | Aileron Autopilot Servo (Pilot) - Removal / Installation   |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                                | 60P2212001Z001                                             | 0784          | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                                |                                                            |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                                | Airframe                                                   |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| 271601                         | Aileron Autopilot Servo (Copilot) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                                | 60P2212001Z001                                             | 0114          | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                                |                                                            |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                                | Airframe                                                   |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| 272000                         | Rudder - Removal / Installation                            |               | HRS |             | 1784.3          |     |                  | 1261.8      |                     |         | 0            |
|                                | 60P5540000-001                                             | 6158          | AFL |             | 751             |     |                  | 366         |                     |         | 0            |
|                                |                                                            |               | MOS |             | 77.1            |     |                  | 08 Dec 2019 |                     |         |              |
|                                | Airframe                                                   |               | MSC |             |                 |     | O/C              |             |                     |         |              |

| ATA<br>U=Custom                       | Description                                                     |                                                   | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|---------------------------------------|-----------------------------------------------------------------|---------------------------------------------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                                       | Part Number                                                     | Serial Number                                     |     |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position                      | HW                                                              | SW                                                |     |             |                 |     |                  |             |                    |             | Manufacturer |
|                                       | MM Ref                                                          |                                                   |     |             |                 |     |                  |             |                    |             | Date Type    |
|                                       | Ops Number(s)                                                   |                                                   |     |             |                 |     |                  |             |                    |             |              |
| 272002                                | Rudder Free Play Backlash - Functional Check                    |                                                   | HRS |             | 730.5           |     | 1200             | 2315.6      | 3515.6             | 3565.6      | 0            |
|                                       |                                                                 |                                                   | AFL |             | 315             |     | 802              |             |                    | 0           |              |
|                                       |                                                                 |                                                   | MOS |             | 28.7            |     | 120              | 21 Dec 2023 | 31 Dec 2033        | 31 Jan 2034 |              |
|                                       | Airframe                                                        | [End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50] |     |             |                 |     |                  |             |                    |             |              |
| Notes: PN: 60P2212001Z001 SN: <NONE>. |                                                                 |                                                   |     |             |                 |     |                  |             |                    |             |              |
| 272003                                | Rudder Electrical Rig - Functional Check                        |                                                   | HRS |             | 1452            |     |                  | 1594.1      |                    |             | 0            |
|                                       |                                                                 |                                                   | AFL |             | 570             |     | 547              |             |                    | 0           |              |
|                                       |                                                                 |                                                   | MOS |             | 63.6            |     | 24 Jan 2021      |             |                    |             |              |
|                                       | Airframe                                                        | MSC O/C                                           |     |             |                 |     |                  |             |                    |             |              |
| Notes: PN: 60P2212001Z001 SN: <NONE>. |                                                                 |                                                   |     |             |                 |     |                  |             |                    |             |              |
| 272004                                | Rudder Actuating System Ibit Suite A Test - Operational Check   |                                                   | HRS |             | 137             |     | 600              | 2909.1      | 3509.1             | 3559.1      | 0            |
|                                       |                                                                 |                                                   | AFL |             | 52              |     | 1065             |             |                    | 0           |              |
|                                       |                                                                 |                                                   | MOS |             | 5.3             |     | 02 Dec 2025      |             |                    |             |              |
|                                       | Airframe                                                        | [HRS: +50/-50]                                    |     |             |                 |     |                  |             |                    |             |              |
| Notes: PN: 60P2212001Z001 SN: <NONE>. |                                                                 |                                                   |     |             |                 |     |                  |             |                    |             |              |
| 272006                                | Rudder - Functional Test                                        |                                                   | HRS |             | 2345.1          |     |                  | 701         |                    |             | 0            |
|                                       |                                                                 |                                                   | AFL |             | 936             |     | 181              |             |                    | 0           |              |
|                                       |                                                                 |                                                   | MOS |             | 96.6            |     | 23 Apr 2018      |             |                    |             |              |
|                                       | Airframe                                                        | MSC O/C                                           |     |             |                 |     |                  |             |                    |             |              |
| 272008                                | Rudder Control Linkages and Dampers - General Visual Inspection |                                                   | HRS |             | 3046.1          |     | 6000             | 0           | 6000               | 6050        | 0            |
|                                       |                                                                 |                                                   | AFL |             | 1117            |     | 0                |             |                    | 0           |              |
|                                       |                                                                 |                                                   | MOS |             | 128.6           |     | 24 Aug 2015      |             |                    |             |              |
|                                       | Airframe                                                        | [HRS: +50/-50]                                    |     |             |                 |     |                  |             |                    |             |              |
| 052007                                |                                                                 |                                                   |     |             |                 |     |                  |             |                    |             |              |
| Notes: PN: 60P2212001Z001 SN: <NONE>. |                                                                 |                                                   |     |             |                 |     |                  |             |                    |             |              |
| 272009                                | Rudder Control Module Primary Stops - General Visual Inspection |                                                   | HRS |             | 3046.1          |     | 6000             | 0           | 6000               | 6050        | 0            |
|                                       |                                                                 |                                                   | AFL |             | 1117            |     | 0                |             |                    | 0           |              |
|                                       |                                                                 |                                                   | MOS |             | 128.6           |     | 24 Aug 2015      |             |                    |             |              |
|                                       | Airframe                                                        | [HRS: +50/-50]                                    |     |             |                 |     |                  |             |                    |             |              |
| 052007                                |                                                                 |                                                   |     |             |                 |     |                  |             |                    |             |              |
| 272010                                | Rudder Attachment - Detailed Inspection                         |                                                   | HRS |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                                       |                                                                 |                                                   | AFL |             | 315             |     | 802              |             |                    | 0           |              |
|                                       |                                                                 |                                                   | MOS |             | 28.7            |     | 48               | 21 Dec 2023 | 31 Dec 2027        | 31 Jan 2028 |              |
|                                       | Airframe                                                        | [End Of Month Item] [MOS: +1m/-1m]                |     |             |                 |     |                  |             |                    |             |              |
| 052013                                |                                                                 |                                                   |     |             |                 |     |                  |             |                    |             |              |
| Notes: PN: 60P2212001Z001 SN: <NONE>. |                                                                 |                                                   |     |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom                | Description                                              |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|--------------------------------|----------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                | Part Number                                              | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position               | HW                                                       | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                | MM Ref                                                   |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                                | Ops Number(s)                                            |               |     |             |                 |     |                  |             |                    |         |              |
| 272100                         | Rudder Pedal Assembly (Pilot) - Removal / Installation   |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | 60P2721100Z004                                           | 246878        | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                |                                                          |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 272101                         | Rudder Pedal Assembly (Copilot) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | 60P2721200Z005                                           | 248415        | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                |                                                          |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 272102                         | Rudder Force Sensor (Pilot) - Removal / Installation     |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | 60P2721101Z002                                           | 236976        | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                |                                                          |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 272103                         | Rudder Force Sensor (Copilot) - Removal / Installation   |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | 60P2721101Z002                                           | 235466        | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                |                                                          |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 272106                         | Rudder Pedal Assembly (Pilot) - Discard                  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | 60P2721100Z004                                           | 246878        | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                |                                                          |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Notes: MRI PARENT CODE: 272100 |                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| 272107                         | Rudder Pedal Assembly (Copilot) - Discard                |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | 60P2721200Z005                                           | 248415        | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                |                                                          |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Notes: MRI PARENT CODE: 272101 |                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| 272108                         | Rudder Force Sensor (Pilot) - Discard                    |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | 60P2721101Z002                                           | 236976        | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                |                                                          |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Notes: MRI PARENT CODE: 272102 |                                                          |               |     |             |                 |     |                  |             |                    |         |              |



| ATA<br>U=Custom                | Description                                               |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|--------------------------------|-----------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                                | Part Number                                               | Serial Number |     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position               | HW                                                        | SW            |     |             |                 |     |                  |             |                     |         | Manufacturer |
|                                | MM Ref                                                    |               |     |             |                 |     |                  |             |                     |         | Date Type    |
|                                | Ops Number(s)                                             |               |     |             |                 |     |                  |             |                     |         |              |
| 272109                         | Rudder Force Sensor (Copilot) - Discard                   |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                                | 60P2721101Z002                                            | 235466        | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                                |                                                           |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                                | Airframe                                                  |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Notes: MRI PARENT CODE: 272103 |                                                           |               |     |             |                 |     |                  |             |                     |         |              |
| 272204                         | Rudder Control Module Rvdt - Removal / Installation       |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                                | 60P2711107Z002                                            | A984          | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                                |                                                           |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                                | Airframe                                                  |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| 272300                         | Rudder Ehsa Actuator - Removal / Installation             |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                                | 60P2723002Z003                                            | 0384          | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                                |                                                           |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                                | Airframe                                                  |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| 272301                         | Rudder Ebha Actuator - Removal / Installation             |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                                | 60P2723001Z004                                            | 0240          | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                                |                                                           |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                                | Airframe                                                  |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| 272302                         | Rudder Ha Manifold - Removal / Installation               |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                                | 60P2723101Z004                                            | 0178          | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                                |                                                           |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                                | Airframe                                                  |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| 272303                         | Rudder Eb Manifold - Removal / Installation               |               | HRS |             | 1452            |     |                  | 1594.1      |                     |         | 0            |
|                                | 60P2713301Z004                                            | 1196D         | AFL |             | 570             |     |                  | 547         |                     |         | 0            |
|                                |                                                           |               | MOS |             | 63.9            |     |                  | 14 Jan 2021 |                     |         |              |
|                                | Airframe                                                  |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| 272304                         | Rudder Ehsa Manifold - Removal / Installation             |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                                | 60P2723201Z003                                            | 0185A         | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                                |                                                           |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                                | Airframe                                                  |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| 272306                         | Rudder Motor Control Electronics - Removal / Installation |               | HRS | TSN:1594.1  | 1452            |     |                  | 1594.1      |                     |         | 0            |
|                                | 60P2715003Z309                                            | 0473          | AFL | TSN:547     | 570             |     |                  | 547         |                     |         | 0            |
|                                |                                                           |               | MOS | TSN:65      | 63.9            |     |                  | 15 Jan 2021 |                     |         |              |
|                                | Airframe                                                  |               | MSC |             |                 |     | O/C              |             |                     |         |              |

| ATA<br>U=Custom                | Description                                             |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|--------------------------------|---------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                | Part Number                                             | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position               | HW                                                      | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                | MM Ref                                                  |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                                | Ops Number(s)                                           |               |     |             |                 |     |                  |             |                    |         |              |
| 272314                         | Rudder Ha Manifold - Discard                            |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | 60P2723101Z004                                          | 0178          | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                |                                                         |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Notes: MRI PARENT CODE: 272302 |                                                         |               |     |             |                 |     |                  |             |                    |         |              |
| 272315                         | Rudder Ehsa Manifold - Discard                          |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | 60P2723201Z003                                          | 0185A         | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                |                                                         |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Notes: MRI PARENT CODE: 272304 |                                                         |               |     |             |                 |     |                  |             |                    |         |              |
| 272400                         | Rudder Control Module Assembly - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | 60P2721300Z003                                          | 242395        | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                |                                                         |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 272402                         | Rudder Control Module Assembly - Discard                |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | 60P2721300Z003                                          | 242395        | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                |                                                         |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Notes: MRI PARENT CODE: 272400 |                                                         |               |     |             |                 |     |                  |             |                    |         |              |
| 272503                         | Rudder Damper (Pilot) - Removal / Installation          |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | 60P2711108Z001                                          | 1094          | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                |                                                         |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 272504                         | Rudder Damper (Copilot) - Removal / Installation        |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | 60P2711108Z001                                          | 1091          | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                |                                                         |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 273000                         | Aileron Damper (Pilot) - Removal / Installation         |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | 60P2711108Z001                                          | 0898          | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                |                                                         |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                     |               | UOM                                               | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due     | Avg Man Hrs  |
|------------------|-----------------------------------------------------------------|---------------|---------------------------------------------------|-------------|-----------------|-----|------------------|-------------|---------------------|-------------|--------------|
|                  | Part Number                                                     | Serial Number |                                                   |             |                 |     |                  |             |                     |             | Approx Price |
| Logbook Position | HW                                                              | SW            |                                                   |             |                 |     |                  |             |                     |             | Manufacturer |
|                  | MM Ref                                                          |               |                                                   |             |                 |     |                  |             |                     |             | Date Type    |
|                  | Ops Number(s)                                                   |               |                                                   |             |                 |     |                  |             |                     |             |              |
| 273001           | Aileron Damper (Copilot) - Removal / Installation               |               | HRS                                               |             | 3046.1          |     |                  | 0           |                     |             | 0            |
|                  | 60P2711108Z001                                                  | 0230          | AFL                                               |             | 1117            |     |                  | 0           |                     |             | 0            |
|                  |                                                                 |               | MOS                                               |             | 128.6           |     |                  | 24 Aug 2015 |                     |             |              |
|                  | Airframe                                                        |               | MSC                                               |             |                 |     | O/C              |             |                     |             |              |
| 273002           | Elevator (Left) - Functional Test                               |               | HRS                                               |             | 730.5           |     |                  | 2315.6      |                     |             | 0            |
|                  |                                                                 |               | AFL                                               |             | 315             |     |                  | 802         |                     |             | 0            |
|                  |                                                                 |               | MOS                                               |             | 28.7            |     |                  | 21 Dec 2023 |                     |             |              |
|                  | Airframe                                                        |               | MSC                                               |             |                 |     | O/C              |             |                     |             |              |
| 273003           | Elevator (Right) - Functional Test                              |               | HRS                                               |             | 730.5           |     |                  | 2315.6      |                     |             | 0            |
|                  |                                                                 |               | AFL                                               |             | 315             |     |                  | 802         |                     |             | 0            |
|                  |                                                                 |               | MOS                                               |             | 28.7            |     |                  | 21 Dec 2023 |                     |             |              |
|                  | Airframe                                                        |               | MSC                                               |             |                 |     | O/C              |             |                     |             |              |
| 273004           | Elevator Electrical Rig (Left) - Functional Check               |               | HRS                                               |             | 730.5           |     |                  | 2315.6      |                     |             | 0            |
|                  |                                                                 |               | AFL                                               |             | 315             |     |                  | 802         |                     |             | 0            |
|                  |                                                                 |               | MOS                                               |             | 28.7            |     |                  | 21 Dec 2023 |                     |             |              |
|                  | Airframe                                                        |               | MSC                                               |             |                 |     | O/C              |             |                     |             |              |
| 273005           | Elevator Electrical Rig (Right) - Functional Check              |               | HRS                                               |             | 730.5           |     |                  | 2315.6      |                     |             | 0            |
|                  |                                                                 |               | AFL                                               |             | 315             |     |                  | 802         |                     |             | 0            |
|                  |                                                                 |               | MOS                                               |             | 28.7            |     |                  | 21 Dec 2023 |                     |             |              |
|                  | Airframe                                                        |               | MSC                                               |             |                 |     | O/C              |             |                     |             |              |
| 273006           | Elevator Actuating System Ibit Suite A Test - Operational Check |               | HRS                                               |             | 137             |     | 600              | 2909.1      | 3509.1              | 3559.1      | 0            |
|                  |                                                                 |               | AFL                                               |             | 52              |     |                  | 1065        |                     |             | 0            |
|                  |                                                                 |               | MOS                                               |             | 5.3             |     |                  | 02 Dec 2025 |                     |             |              |
|                  | Airframe                                                        |               | [HRS: +50/-50]                                    |             |                 |     |                  |             |                     |             |              |
| 273008           | Elevator Free Play Backlash (Left) - Functional Check           |               | HRS                                               |             | 730.5           |     | 1200             | 2315.6      | 3515.6              | 3565.6      | 0            |
|                  |                                                                 |               | AFL                                               |             | 315             |     |                  | 802         |                     |             | 0            |
|                  |                                                                 |               | MOS                                               |             | 28.7            |     | 120              | 21 Dec 2023 | 31 Dec 2033         | 31 Jan 2034 |              |
|                  | Airframe                                                        |               | [End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50] |             |                 |     |                  |             |                     |             |              |
| 273009           | Elevator Free Play Backlash (Right) - Functional Check          |               | HRS                                               |             | 730.5           |     | 1200             | 2315.6      | 3515.6              | 3565.6      | 0            |
|                  |                                                                 |               | AFL                                               |             | 315             |     |                  | 802         |                     |             | 0            |
|                  |                                                                 |               | MOS                                               |             | 28.7            |     | 120              | 21 Dec 2023 | 31 Dec 2033         | 31 Jan 2034 |              |
|                  | Airframe                                                        |               | [End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50] |             |                 |     |                  |             |                     |             |              |

| ATA<br>U=Custom  | Description                                                            |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------|------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                  | Part Number                                                            | Serial Number |                                    |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position | HW                                                                     | SW            |                                    |             |                 |     |                  |             |                    |             | Manufacturer |
|                  | MM Ref                                                                 |               |                                    |             |                 |     |                  |             |                    |             | Date Type    |
|                  | Ops Number(s)                                                          |               |                                    |             |                 |     |                  |             |                    |             |              |
| 273010           | Elevator Attachment (Left) - Detailed Inspection                       |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                        |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                        |               | MOS                                |             | 28.7            |     | 48               | 21 Dec 2023 | 31 Dec 2027        | 31 Jan 2028 |              |
|                  | Airframe                                                               |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
|                  | 052013                                                                 |               |                                    |             |                 |     |                  |             |                    |             |              |
| 273011           | Elevator Attachment (Right) - Detailed Inspection                      |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                        |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                        |               | MOS                                |             | 28.7            |     | 48               | 21 Dec 2023 | 31 Dec 2027        | 31 Jan 2028 |              |
|                  | Airframe                                                               |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
|                  | 052013                                                                 |               |                                    |             |                 |     |                  |             |                    |             |              |
| 273012           | Elevator Control System - General Visual Inspection                    |               | HRS                                |             | 3046.1          |     | 6000             | 0           | 6000               | 6050        | 0            |
|                  |                                                                        |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                        |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  | Airframe                                                               |               | [HRS: +50/-50]                     |             |                 |     |                  |             |                    |             |              |
|                  | 052007                                                                 |               |                                    |             |                 |     |                  |             |                    |             |              |
| 273100           | Aileron Control Wheel (Left) - Removal / Installation                  |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  | 60P2711103Z004                                                         | 248216        | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                        |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  | Airframe                                                               |               | MSC                                |             |                 |     |                  |             |                    |             |              |
|                  |                                                                        |               | O/C                                |             |                 |     |                  |             |                    |             |              |
| 273101           | Aileron Control Wheel (Right) - Removal / Installation                 |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  | 60P2711203Z004                                                         | 245078        | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                        |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  | Airframe                                                               |               | MSC                                |             |                 |     |                  |             |                    |             |              |
|                  |                                                                        |               | O/C                                |             |                 |     |                  |             |                    |             |              |
| 273102           | Control Column (Pilot) - Removal / Installation                        |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  | 60P2711100Z005                                                         | SN-UNKNOWN    | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                        |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  | Airframe                                                               |               | MSC                                |             |                 |     |                  |             |                    |             |              |
|                  |                                                                        |               | O/C                                |             |                 |     |                  |             |                    |             |              |
| 273103           | Control Column (Copilot) - Removal / Installation                      |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  | 60P2711200Z005                                                         | SN-UNKNOWN    | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                        |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  | Airframe                                                               |               | MSC                                |             |                 |     |                  |             |                    |             |              |
|                  |                                                                        |               | O/C                                |             |                 |     |                  |             |                    |             |              |
| 273104           | Aileron Control Column/Wheel Assembly (Pilot) - Removal / Installation |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                        |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  | 60P2711100Z006                                                         | 251808        | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  | Airframe                                                               |               | MSC                                |             |                 |     |                  |             |                    |             |              |
|                  |                                                                        |               | O/C                                |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom                | Description                                                              |               | UOM            | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|--------------------------------|--------------------------------------------------------------------------|---------------|----------------|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                                | Part Number                                                              | Serial Number |                |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position               | HW                                                                       | SW            |                |             |                 |     |                  |             |                     |         | Manufacturer |
|                                | MM Ref                                                                   |               |                |             |                 |     |                  |             |                     |         | Date Type    |
|                                | Ops Number(s)                                                            |               |                |             |                 |     |                  |             |                     |         |              |
| 273105                         | Aileron Control Column/Wheel Assembly (Copilot) - Removal / Installation |               | HRS            |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                                |                                                                          |               | AFL            |             | 1117            |     |                  | 0           |                     |         | 0            |
|                                | 60P2711200Z006                                                           | 250705        | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                                |                                                                          |               | MSC            |             |                 |     | O/C              |             |                     |         |              |
| Airframe                       |                                                                          |               |                |             |                 |     |                  |             |                     |         |              |
| 273112                         | Control Column and Control Wheel (Pilot) - Discard                       |               | HRS            |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                                | 60P2711100Z006                                                           |               | AFL            |             | 1117            |     |                  | 0           |                     |         | 0            |
|                                |                                                                          |               | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                                |                                                                          |               | MSC            |             |                 |     | O/C              |             |                     |         |              |
| Airframe                       |                                                                          |               |                |             |                 |     |                  |             |                     |         |              |
| Notes: MRI PARENT CODE: 273104 |                                                                          |               |                |             |                 |     |                  |             |                     |         |              |
| 273113                         | Control Column and Control Wheel (Copilot) - Discard                     |               | HRS            |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                                | 60P2711200Z006                                                           |               | AFL            |             | 1117            |     |                  | 0           |                     |         | 0            |
|                                |                                                                          |               | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                                |                                                                          |               | MSC            |             |                 |     | O/C              |             |                     |         |              |
| Airframe                       |                                                                          |               |                |             |                 |     |                  |             |                     |         |              |
| Notes: MRI PARENT CODE: 273105 |                                                                          |               |                |             |                 |     |                  |             |                     |         |              |
| 273120                         | Elevator Force Sensor (Pilot) - Removal / Installation                   |               | HRS            |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                                | 60P2731101Z002                                                           |               | AFL            |             | 1117            |     |                  | 0           |                     |         | 0            |
|                                |                                                                          |               | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                                |                                                                          |               | MSC            |             |                 |     | O/C              |             |                     |         |              |
| Airframe                       |                                                                          |               |                |             |                 |     |                  |             |                     |         |              |
| 273121                         | Elevator Force Sensor (Copilot) - Removal / Installation                 |               | HRS            |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                                | 60P2731101Z002                                                           |               | AFL            |             | 1117            |     |                  | 0           |                     |         | 0            |
|                                |                                                                          |               | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                                |                                                                          |               | MSC            |             |                 |     | O/C              |             |                     |         |              |
| Airframe                       |                                                                          |               |                |             |                 |     |                  |             |                     |         |              |
| 273122                         | Elevator Control Override Pushrod - Removal / Installation               |               | HRS            |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                                | 60P2731305Z002                                                           |               | AFL            |             | 1117            |     |                  | 0           |                     |         | 0            |
|                                |                                                                          |               | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                                |                                                                          |               | MSC            |             |                 |     | O/C              |             |                     |         |              |
| Airframe                       |                                                                          |               |                |             |                 |     |                  |             |                     |         |              |
| 273124                         | Elevator Control Override Pushrod - Functional Check                     |               | HRS            |             | 3046.1          |     | 6000             | 0           | 6000                | 6050    | 0            |
|                                |                                                                          |               | AFL            |             | 1117            |     |                  | 0           |                     |         | 0            |
|                                |                                                                          |               | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                                |                                                                          |               | [HRS: +50/-50] |             |                 |     |                  |             |                     |         |              |
| Airframe                       |                                                                          |               |                |             |                 |     |                  |             |                     |         |              |
| 052007                         |                                                                          |               |                |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom                | Description                                           |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|--------------------------------|-------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                | Part Number                                           | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position               | HW                                                    | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                | MM Ref                                                |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                                | Ops Number(s)                                         |               |     |             |                 |     |                  |             |                    |         |              |
| 273125                         | Elevator (Left) - Removal / Installation              |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                                | 60A5520001-005                                        | 6112          | AFL |             | 315             |     |                  | 802         |                    |         | 0            |
|                                |                                                       |               | MOS |             | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
|                                | Airframe                                              |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 273126                         | Elevator (Right) - Removal / Installation             |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                                | 60A5520002-005                                        | 6116          | AFL |             | 315             |     |                  | 802         |                    |         | 0            |
|                                |                                                       |               | MOS |             | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
|                                | Airframe                                              |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 273129                         | Elevator Control Override Pushrod - Discard           |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | 60P2731305Z002                                        | 196889        | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                |                                                       |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                              |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Notes: MRI PARENT CODE: 273122 |                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| 273200                         | Stick Shaker Motor (Pilot) - Removal / Installation   |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | 60P2731104Z002                                        | 410           | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                |                                                       |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                              |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 273201                         | Stick Shaker Motor (Copilot) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | 60P2731104Z002                                        | 405           | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                |                                                       |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                              |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 273212                         | Elevator Force Sensor (Pilot) - Discard               |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | 60P2731101Z002                                        | 236966        | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                |                                                       |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                              |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Notes: MRI PARENT CODE: 273120 |                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| 273213                         | Elevator Force Sensor (Copilot) - Discard             |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | 60P2731101Z002                                        | 236968        | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                |                                                       |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                              |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Notes: MRI PARENT CODE: 273121 |                                                       |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                             |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|---------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                             | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                      | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                  |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                           |               |     |             |                 |     |                  |             |                    |         |              |
| 273300           | Elevator Ebha Actuator (Left) - Removal / Installation  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P2733001Z004 0718                                     |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                         |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 273301           | Elevator Ebha Actuator (Right) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P2733001Z004 0750                                     |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                         |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 273302           | Elevator Ehsa Actuator (Left) - Removal / Installation  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P2733002Z005 0744                                     |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                         |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 273303           | Elevator Ehsa Actuator (Right) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P2733002Z005 0720                                     |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                         |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 273304           | Elevator Ehsa Manifold (Left) - Removal / Installation  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P2733201Z002 0329                                     |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                         |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 273305           | Elevator Ehsa Manifold (Right) - Removal / Installation |               | HRS | TSN:2315.58 | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  | 60P2733201Z002 0363                                     |               | AFL | TSN:802     | 315             |     |                  | 802         |                    |         | 0            |
|                  |                                                         |               | MOS | TSN:99      | 29.9            |     |                  | 15 Nov 2023 |                    |         |              |
|                  | Airframe                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 273306           | Elevator Ha Manifold (Left) - Removal / Installation    |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P2733101Z003 0358A                                    |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                         |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 273307           | Elevator Ha Manifold (Right) - Removal / Installation   |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P2733101Z003 0360A                                    |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                         |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                     |               | UOM            | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-----------------------------------------------------------------|---------------|----------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                     | Serial Number |                |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                              | SW            |                |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                          |               |                |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                   |               |                |             |                 |     |                  |             |                    |         |              |
| 273500           | Elevator Lvd (Left) - Removal / Installation                    |               | HRS            |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P2734000Z001                                                  | 151795        | AFL            |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                 |               | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                        |               | MSC            |             |                 |     | O/C              |             |                    |         |              |
| 273501           | Elevator Lvd (Right) - Removal / Installation                   |               | HRS            |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P2734000Z001                                                  | 154010        | AFL            |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                 |               | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                        |               | MSC            |             |                 |     | O/C              |             |                    |         |              |
| 273508           | Elevator Damper (Pilot) - Removal / Installation                |               | HRS            |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P2711108Z001                                                  | 1161          | AFL            |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                 |               | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                        |               | MSC            |             |                 |     | O/C              |             |                    |         |              |
| 273509           | Elevator Damper (Copilot) - Removal / Installation              |               | HRS            |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P2711108Z001                                                  | 1167          | AFL            |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                 |               | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                        |               | MSC            |             |                 |     | O/C              |             |                    |         |              |
| 273600           | Elevator Autopilot Servo (Pilot) - Removal / Installation       |               | HRS            |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P2212001Z001                                                  | 0788          | AFL            |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                 |               | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                        |               | MSC            |             |                 |     | O/C              |             |                    |         |              |
| 273601           | Elevator Autopilot Servo (Copilot) - Removal / Installation     |               | HRS            |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P2212001Z001                                                  | 0843          | AFL            |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                 |               | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                        |               | MSC            |             |                 |     | O/C              |             |                    |         |              |
| 274000           | Horizontal Stabilizer Electrical Rig - Functional Check         |               | HRS            |             | 2345.1          |     |                  | 701         |                    |         | 0            |
|                  |                                                                 |               | AFL            |             | 936             |     |                  | 181         |                    |         | 0            |
|                  |                                                                 |               | MOS            |             | 96.8            |     |                  | 18 Apr 2018 |                    |         |              |
|                  | Airframe                                                        |               | MSC            |             |                 |     | O/C              |             |                    |         |              |
| 274001           | Horizontal Stabilizer Trim Actuator Backlash - Functional Check |               | HRS            |             | 3046.1          |     | 6000             | 0           | 6000               | 6050    | 0            |
|                  |                                                                 |               | AFL            |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                 |               | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                        |               | [HRS: +50/-50] |             |                 |     |                  |             |                    |         |              |



| ATA<br>U=Custom  | Description                                                                                  |               | UOM                            | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------------------------------------------------|---------------|--------------------------------|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                                                                  | Serial Number |                                |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                                                           | SW            |                                |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                                                       |               |                                |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                                                                |               |                                |             |                 |     |                  |             |                     |         |              |
| 274002           | Horizontal Stabilizer Trim Actuator Secondary Nut Mechanism and Clutch - Operational Check   |               | HRS                            |             | 3046.1          |     | 4800             | 0           | 4800                | 4850    | 0            |
|                  |                                                                                              |               | AFL                            |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  |                                                                                              |               | MOS                            |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                                              |               | [HRS: +50/-50]                 |             |                 |     |                  |             |                     |         |              |
| Airframe         |                                                                                              |               |                                |             |                 |     |                  |             |                     |         |              |
| 274003           | Horizontal Stabilizer Trim Actuator Tie ROD Mechanism (Return to Vendor) - Operational Check |               | HRS                            |             | 3046.1          |     | 4800             | 0           | 4800                | 4850    | 0            |
|                  |                                                                                              |               | AFL                            |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  |                                                                                              |               | MOS                            |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                                              |               | [HRS: +50/-50]                 |             |                 |     |                  |             |                     |         |              |
| Airframe         |                                                                                              |               |                                |             |                 |     |                  |             |                     |         |              |
| 274005           | Horizontal Stabilizer Trim Actuator Structure - Detailed Inspection                          |               | HRS                            |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                                              |               | AFL                            |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  |                                                                                              |               | MOS                            |             | 122             |     | 144              | 11 Mar 2016 | 31 Mar 2028         |         |              |
|                  |                                                                                              |               | [End Of Month Item] [MOS: -1m] |             |                 |     |                  |             |                     |         |              |
| Airframe         |                                                                                              |               |                                |             |                 |     |                  |             |                     |         |              |
| 052019           |                                                                                              |               |                                |             |                 |     |                  |             |                     |         |              |
| 274006           | Horizontal Stabilizer Trim Actuator - Detailed Inspection                                    |               | HRS                            |             | 3046.1          |     | 6000             | 0           | 6000                | 6050    | 0            |
|                  |                                                                                              |               | AFL                            |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  |                                                                                              |               | MOS                            |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                                              |               | [HRS: +50/-50]                 |             |                 |     |                  |             |                     |         |              |
| Airframe         |                                                                                              |               |                                |             |                 |     |                  |             |                     |         |              |
| 052007           |                                                                                              |               |                                |             |                 |     |                  |             |                     |         |              |
| 274007           | Horizontal Stabilizer Trim Actuator Motor CAP - Inspection                                   |               | HRS                            |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                                              |               | AFL                            |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  |                                                                                              |               | MOS                            |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                                              |               | MSC                            |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                              |               |                                |             |                 |     |                  |             |                     |         |              |
| 274008           | Horizontal Stabilizer - Functional Test                                                      |               | HRS                            |             | 2345.1          |     |                  | 701         |                     |         | 0            |
|                  |                                                                                              |               | AFL                            |             | 936             |     |                  | 181         |                     |         | 0            |
|                  |                                                                                              |               | MOS                            |             | 96.8            |     |                  | 18 Apr 2018 |                     |         |              |
|                  |                                                                                              |               | MSC                            |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                              |               |                                |             |                 |     |                  |             |                     |         |              |
| 274200           | Horizontal Stabilizer Trim Actuator - Removal / Installation                                 |               | HRS                            |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  | 60P2743000Z004                                                                               | 00181         | AFL                            |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  |                                                                                              |               | MOS                            |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                                              |               | MSC                            |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                              |               |                                |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom  | Description                                                                |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------|----------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                  | Part Number                                                                | Serial Number |                                    |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position | HW                                                                         | SW            |                                    |             |                 |     |                  |             |                    |             | Manufacturer |
|                  | MM Ref                                                                     |               |                                    |             |                 |     |                  |             |                    |             | Date Type    |
|                  | Ops Number(s)                                                              |               |                                    |             |                 |     |                  |             |                    |             |              |
| 274201           | Horizontal Stabilizer Trim Actuator Motor (Left) - Removal / Installation  |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                            |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  | 60P2743001Z006                                                             | 492           | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                            |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                            |               |                                    |             |                 |     |                  |             |                    |             |              |
| 274202           | Horizontal Stabilizer Trim Actuator Motor (Right) - Removal / Installation |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                            |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  | 60P2743001Z006                                                             | 501           | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                            |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                            |               |                                    |             |                 |     |                  |             |                    |             |              |
| 274300           | Horizontal Stabilizer Position Resolver (Left) - Removal / Installation    |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                            |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  | 60P2744000Z001                                                             | BB122         | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                            |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                            |               |                                    |             |                 |     |                  |             |                    |             |              |
| 274301           | Horizontal Stabilizer Position Resolver (Right) - Removal / Installation   |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                            |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  | 60P2744000Z001                                                             | BB135         | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                            |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                            |               |                                    |             |                 |     |                  |             |                    |             |              |
| 274500           | Horizontal Stabilizer - Seating Check                                      |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                            |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                            |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                            |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                            |               |                                    |             |                 |     |                  |             |                    |             |              |
| 274501           | Horizontal Stabilizer Control Unit - Removal / Installation                |               | HRS                                |             | 2345.1          |     |                  | 701         |                    |             | 0            |
|                  | 60P2745000Z106                                                             | 4286F9        | AFL                                |             | 936             |     |                  | 181         |                    |             | 0            |
|                  |                                                                            |               | MOS                                |             | 97.1            |     |                  | 09 Apr 2018 |                    |             |              |
|                  |                                                                            |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                            |               |                                    |             |                 |     |                  |             |                    |             |              |
| 275000           | Flap Drive System - General Visual Inspection                              |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                            |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                            |               | MOS                                |             | 28.7            |     | 48               | 21 Dec 2023 | 31 Dec 2027        | 31 Jan 2028 |              |
|                  |                                                                            |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                            |               |                                    |             |                 |     |                  |             |                    |             |              |
| 052013           |                                                                            |               |                                    |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom                | Description                                                        |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|--------------------------------|--------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                                | Part Number                                                        | Serial Number |                                    |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position               | HW                                                                 | SW            |                                    |             |                 |     |                  |             |                    |             | Manufacturer |
|                                | MM Ref                                                             |               |                                    |             |                 |     |                  |             |                    |             | Date Type    |
|                                | Ops Number(s)                                                      |               |                                    |             |                 |     |                  |             |                    |             |              |
| 275001                         | Flap System - Functional Test                                      |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                                |                                                                    |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                                |                                                                    |               | MOS                                |             | 28.7            |     |                  | 21 Dec 2023 |                    |             |              |
|                                |                                                                    |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe                       |                                                                    |               |                                    |             |                 |     |                  |             |                    |             |              |
| 275002                         | Flap System - Operational Test                                     |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                                |                                                                    |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                                |                                                                    |               | MOS                                |             | 28.7            |     |                  | 21 Dec 2023 |                    |             |              |
|                                |                                                                    |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe                       |                                                                    |               |                                    |             |                 |     |                  |             |                    |             |              |
| 275003                         | Flap System Electrical Rig - Functional Check                      |               | HRS                                |             | 730.52          |     |                  | 2315.58     |                    |             | 0            |
|                                |                                                                    |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                                |                                                                    |               | MOS                                |             | 28.9            |     |                  | 14 Dec 2023 |                    |             |              |
|                                |                                                                    |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe                       |                                                                    |               |                                    |             |                 |     |                  |             |                    |             |              |
| 275004                         | Flap System - Mechanical Rig                                       |               | HRS                                |             | 730.52          |     |                  | 2315.58     |                    |             | 0            |
|                                |                                                                    |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                                |                                                                    |               | MOS                                |             | 28.9            |     |                  | 14 Dec 2023 |                    |             |              |
|                                |                                                                    |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe                       |                                                                    |               |                                    |             |                 |     |                  |             |                    |             |              |
| 275009                         | Flap Attaching Points - Detailed Inspection                        |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                                |                                                                    |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                                |                                                                    |               | MOS                                |             | 28.7            |     | 48               | 21 Dec 2023 | 31 Dec 2027        | 31 Jan 2028 |              |
|                                |                                                                    |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe                       |                                                                    |               |                                    |             |                 |     |                  |             |                    |             |              |
| 052013                         |                                                                    |               |                                    |             |                 |     |                  |             |                    |             |              |
| 275058                         | A Track Flap Roller (Left Inboard) - Discard<br>60P5755371Z019NSN  |               | HRS                                |             | 473             |     | 2400             | 2573.1      | 4973.1             | 5023.1      | 0            |
|                                |                                                                    |               | AFL                                |             | 185             |     |                  | 932         |                    |             | 0            |
|                                |                                                                    |               | MOS                                | TSN:6       | 14.5            |     |                  | 25 Feb 2025 |                    |             |              |
|                                |                                                                    |               | [HRS: +50/-50]                     |             |                 |     |                  |             |                    |             |              |
| Airframe                       |                                                                    |               |                                    |             |                 |     |                  |             |                    |             |              |
| Notes: MRI PARENT CODE: 275109 |                                                                    |               |                                    |             |                 |     |                  |             |                    |             |              |
| 275059                         | A Track Flap Roller (Left Outboard) - Discard<br>60P5755371Z019NSN |               | HRS                                |             | 473             |     | 2400             | 2573.1      | 4973.1             | 5023.1      | 0            |
|                                |                                                                    |               | AFL                                |             | 185             |     |                  | 932         |                    |             | 0            |
|                                |                                                                    |               | MOS                                | TSN:6       | 14.5            |     |                  | 25 Feb 2025 |                    |             |              |
|                                |                                                                    |               | [HRS: +50/-50]                     |             |                 |     |                  |             |                    |             |              |
| Airframe                       |                                                                    |               |                                    |             |                 |     |                  |             |                    |             |              |
| Notes: MRI PARENT CODE: 275110 |                                                                    |               |                                    |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom                | Description                                             |               | UOM            | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|--------------------------------|---------------------------------------------------------|---------------|----------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                | Part Number                                             | Serial Number |                |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position               | HW                                                      | SW            |                |             |                 |     |                  |             |                    |         | Manufacturer |
|                                | MM Ref                                                  |               |                |             |                 |     |                  |             |                    |         | Date Type    |
|                                | Ops Number(s)                                           |               |                |             |                 |     |                  |             |                    |         |              |
| 275060                         | A Track Flap Roller (Left Trailing Edge) - Discard      |               | HRS            |             | 730.5           |     | 2400             | 2315.6      | 4715.6             | 4765.6  | 0            |
|                                | KRP505-04VT                                             |               | AFL            |             | 315             |     |                  | 802         |                    |         | 0            |
|                                |                                                         |               | MOS            | TSN:4       | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
| Airframe                       |                                                         |               | [HRS: +50/-50] |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 275111 |                                                         |               |                |             |                 |     |                  |             |                    |         |              |
| 275061                         | A Track Flap Roller (Right Inboard) - Discard           |               | HRS            |             | 473             |     | 2400             | 2573.1      | 4973.1             | 5023.1  | 0            |
|                                | 60P5755371Z019                                          |               | AFL            |             | 185             |     |                  | 932         |                    |         | 0            |
|                                |                                                         |               | MOS            | TSN:6       | 14.5            |     |                  | 25 Feb 2025 |                    |         |              |
| Airframe                       |                                                         |               | [HRS: +50/-50] |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 275112 |                                                         |               |                |             |                 |     |                  |             |                    |         |              |
| 275062                         | A Track Flap Roller (Right Outboard) - Discard          |               | HRS            |             | 473             |     | 2400             | 2573.1      | 4973.1             | 5023.1  | 0            |
|                                | 60P5755371Z019                                          |               | AFL            |             | 185             |     |                  | 932         |                    |         | 0            |
|                                |                                                         |               | MOS            | TSN:6       | 14.5            |     |                  | 25 Feb 2025 |                    |         |              |
| Airframe                       |                                                         |               | [HRS: +50/-50] |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 275113 |                                                         |               |                |             |                 |     |                  |             |                    |         |              |
| 275063                         | A Track Flap Roller (Right Trailing Edge) - Discard     |               | HRS            |             | 730.5           |     | 2400             | 2315.6      | 4715.6             | 4765.6  | 0            |
|                                | KRP505-04VT                                             |               | AFL            |             | 315             |     |                  | 802         |                    |         | 0            |
|                                |                                                         |               | MOS            | TSN:4       | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
| Airframe                       |                                                         |               | [HRS: +50/-50] |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 275114 |                                                         |               |                |             |                 |     |                  |             |                    |         |              |
| 275064                         | B Track Flap Roller (Left Inboard Upper Aft) - Discard  |               | HRS            |             | 473             |     | 2400             | 2573.1      | 4973.1             | 5023.1  | 0            |
|                                | 60P5755371Z014                                          |               | AFL            |             | 185             |     |                  | 932         |                    |         | 0            |
|                                |                                                         |               | MOS            | TSN:4       | 14.5            |     |                  | 25 Feb 2025 |                    |         |              |
| Airframe                       |                                                         |               | [HRS: +50/-50] |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 275121 |                                                         |               |                |             |                 |     |                  |             |                    |         |              |
| 275065                         | B Track Flap Roller (Left Outboard Upper Aft) - Discard |               | HRS            |             | 473             |     | 2400             | 2573.1      | 4973.1             | 5023.1  | 0            |
|                                | 60P5755371Z014                                          |               | AFL            |             | 185             |     |                  | 932         |                    |         | 0            |
|                                |                                                         |               | MOS            | TSN:4       | 14.5            |     |                  | 25 Feb 2025 |                    |         |              |
| Airframe                       |                                                         |               | [HRS: +50/-50] |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 275122 |                                                         |               |                |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom                | Description                                                 |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|--------------------------------|-------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                | Part Number                                                 | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position               | HW                                                          | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                | MM Ref                                                      |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                                | Ops Number(s)                                               |               |     |             |                 |     |                  |             |                    |         |              |
| 275066                         | B Track Flap Roller (Left Inboard Upper Forward) - Discard  |               | HRS |             | 473             |     | 2400             | 2573.1      | 4973.1             | 5023.1  | 0            |
|                                |                                                             |               | AFL |             | 185             |     |                  | 932         |                    |         | 0            |
|                                | 60P5755371Z002                                              | NSN           | MOS | TSN:20      | 14.5            |     |                  | 25 Feb 2025 |                    |         |              |
| [HRS: +50/-50]                 |                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                       |                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 275123 |                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 275067                         | B Track Flap Roller (Left Outboard Upper Forward) - Discard |               | HRS |             | 730.5           |     | 2400             | 2315.6      | 4715.6             | 4765.6  | 0            |
|                                |                                                             |               | AFL |             | 315             |     |                  | 802         |                    |         | 0            |
|                                | 60P5755371Z002                                              | NSN           | MOS | TSN:7       | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
| [HRS: +50/-50]                 |                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                       |                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 275124 |                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 275068                         | B Track Flap Roller (Left Inboard Lower Forward) - Discard  |               | HRS |             | 730.5           |     | 2400             | 2315.6      | 4715.6             | 4765.6  | 0            |
|                                |                                                             |               | AFL |             | 315             |     |                  | 802         |                    |         | 0            |
|                                | 60P5755371Z003                                              | NSN           | MOS | TSN:6       | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
| [HRS: +50/-50]                 |                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                       |                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 275125 |                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 275069                         | B Track Flap Roller (Left Outboard Lower Forward) - Discard |               | HRS |             | 730.5           |     | 2400             | 2315.6      | 4715.6             | 4765.6  | 0            |
|                                |                                                             |               | AFL |             | 315             |     |                  | 802         |                    |         | 0            |
|                                | 60P5755371Z003                                              | NSN           | MOS | TSN:6       | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
| [HRS: +50/-50]                 |                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                       |                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 275126 |                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 275070                         | B Track Flap Roller (Right Inboard Upper Aft) - Discard     |               | HRS |             | 730.5           |     | 2400             | 2315.6      | 4715.6             | 4765.6  | 0            |
|                                | 60P5755371Z014                                              |               | AFL |             | 315             |     |                  | 802         |                    |         | 0            |
|                                |                                                             | NSN           | MOS | TSN:6       | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
| [HRS: +50/-50]                 |                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                       |                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 275127 |                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 275071                         | B Track Flap Roller (Right Outboard Upper Aft) - Discard    |               | HRS |             | 1844.6          |     | 2400             | 1201.5      | 3601.5             | 3651.5  | 0            |
|                                | 60P5755371Z001                                              |               | AFL |             | 766             |     |                  | 351         |                    |         | 0            |
|                                |                                                             | NSN           | MOS |             | 79.3            |     |                  | 02 Oct 2019 |                    |         |              |
| [HRS: +50/-50]                 |                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                       |                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 275128 |                                                             |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom                | Description                                            |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|--------------------------------|--------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                | Part Number                                            | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position               | HW                                                     | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                | MM Ref                                                 |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                                | Ops Number(s)                                          |               |     |             |                 |     |                  |             |                    |         |              |
| 275072                         | B Track Flap Roller (Right Inboard Upper Forward) -    |               | HRS |             | 730.5           |     | 2400             | 2315.6      | 4800               | 4850    | 0            |
|                                | Discard                                                |               | AFL |             | 315             |     |                  | 802         |                    |         | 0            |
|                                | 60P5755371Z002                                         | NSN           | MOS |             | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
|                                | [HRS: +50/-50]                                         |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                       |                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 275129 |                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 275073                         | B Track Flap Roller (Right Outboard Upper Forward) -   |               | HRS |             | 730.5           |     | 2400             | 2315.6      | 4715.6             | 4765.6  | 0            |
|                                | Discard                                                |               | AFL |             | 315             |     |                  | 802         |                    |         | 0            |
|                                | 60P5755371Z002                                         | NSN           | MOS | TSN:7       | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
|                                | [HRS: +50/-50]                                         |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                       |                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 275130 |                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 275074                         | B Track Flap Roller (Right Inboard Lower Forward) -    |               | HRS |             | 730.5           |     | 2400             | 2315.6      | 4715.6             | 4765.6  | 0            |
|                                | Discard                                                |               | AFL |             | 315             |     |                  | 802         |                    |         | 0            |
|                                | 60P5755371Z003                                         | NSN           | MOS | TSN:6       | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
|                                | [HRS: +50/-50]                                         |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                       |                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 275131 |                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 275075                         | B Track Flap Roller (Right Outboard Lower Forward) -   |               | HRS |             | 730.5           |     | 2400             | 2315.6      | 4715.6             | 4765.6  | 0            |
|                                | Discard                                                |               | AFL |             | 315             |     |                  | 802         |                    |         | 0            |
|                                | 60P5755371Z003                                         | NSN           | MOS | TSN:5       | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
|                                | [HRS: +50/-50]                                         |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                       |                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 275132 |                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 275076                         | C Track Flap Roller (Left Inboard Upper Aft) - Discard |               | HRS |             | 1452            |     | 2400             | 1594.1      | 3994.1             | 4044.1  | 0            |
|                                | 60P5755371Z011                                         |               | AFL |             | 570             |     |                  | 547         |                    |         | 0            |
|                                |                                                        | NSN           | MOS |             | 64              |     |                  | 11 Jan 2021 |                    |         |              |
|                                | [HRS: +50/-50]                                         |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                       |                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 275145 |                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 275077                         | C Track Flap Roller (Left Inboard Lower Forward) -     |               | HRS |             | 730.5           |     | 2400             | 2315.6      | 4715.6             | 4765.6  | 0            |
|                                | Discard                                                |               | AFL |             | 315             |     |                  | 802         |                    |         | 0            |
|                                | 60P5755371Z003                                         | NSN           | MOS | TSN:6       | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
|                                | [HRS: +50/-50]                                         |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                       |                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 275146 |                                                        |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom                | Description                                             |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|--------------------------------|---------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                | Part Number                                             | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position               | HW                                                      | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                | MM Ref                                                  |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                                | Ops Number(s)                                           |               |     |             |                 |     |                  |             |                    |         |              |
| 275078                         | C Track Flap Roller (Left Inboard Upper Forward) -      |               | HRS |             | 730.5           |     | 2400             | 2315.6      | 4715.6             | 4765.6  | 0            |
|                                | Discard                                                 |               | AFL |             | 315             |     |                  | 802         |                    |         | 0            |
|                                | 60P5755371Z007                                          | NSN           | MOS | TSN:19      | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
|                                | [HRS: +50/-50]                                          |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                       |                                                         |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 275147 |                                                         |               |     |             |                 |     |                  |             |                    |         |              |
| 275079                         | C Track Flap Roller (Left Outboard Upper Forward) -     |               | HRS |             | 1452            |     | 2400             | 1594.1      | 3994.1             | 4044.1  | 0            |
|                                | Discard                                                 |               | AFL |             | 570             |     |                  | 547         |                    |         | 0            |
|                                | 60P5755371Z007                                          | NSN           | MOS |             | 63.9            |     |                  | 15 Jan 2021 |                    |         |              |
|                                | [HRS: +50/-50]                                          |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                       |                                                         |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 275148 |                                                         |               |     |             |                 |     |                  |             |                    |         |              |
| 275080                         | C Track Flap Roller (Left Outboard Upper Aft) - Discard |               | HRS |             | 1452            |     | 2400             | 1594.1      | 3994.1             | 4044.1  | 0            |
|                                | 60P5755371Z011                                          |               | AFL |             | 570             |     |                  | 547         |                    |         | 0            |
|                                |                                                         | NSN           | MOS |             | 63.9            |     |                  | 15 Jan 2021 |                    |         |              |
|                                | [HRS: +50/-50]                                          |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                       |                                                         |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 275149 |                                                         |               |     |             |                 |     |                  |             |                    |         |              |
| 275081                         | C Track Flap Roller (Left Outboard Lower Forward) -     |               | HRS |             | 730.5           |     | 2400             | 2315.6      | 4800               | 4850    | 0            |
|                                | Discard                                                 |               | AFL |             | 315             |     |                  | 802         |                    |         | 0            |
|                                | 60P5755371Z003                                          | NSN           | MOS |             | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
|                                | [HRS: +50/-50]                                          |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                       |                                                         |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 275150 |                                                         |               |     |             |                 |     |                  |             |                    |         |              |
| 275082                         | C Track Flap Roller (Right Inboard Upper Aft) - Discard |               | HRS |             | 1452            |     | 2400             | 1594.1      | 3994.1             | 4044.1  | 0            |
|                                | 60P5755371Z011                                          |               | AFL |             | 570             |     |                  | 547         |                    |         | 0            |
|                                |                                                         | NSN           | MOS |             | 64              |     |                  | 12 Jan 2021 |                    |         |              |
|                                | [HRS: +50/-50]                                          |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                       |                                                         |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 275151 |                                                         |               |     |             |                 |     |                  |             |                    |         |              |
| 275083                         | C Track Flap Roller (Right Inboard Lower Forward) -     |               | HRS |             | 730.5           |     | 2400             | 2315.6      | 4800               | 4850    | 0            |
|                                | Discard                                                 |               | AFL |             | 315             |     |                  | 802         |                    |         | 0            |
|                                | 60P5755371Z003                                          | NSN           | MOS |             | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
|                                | [HRS: +50/-50]                                          |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                       |                                                         |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 275152 |                                                         |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom                | Description                                                  |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|--------------------------------|--------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                                | Part Number                                                  | Serial Number |     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position               | HW                                                           | SW            |     |             |                 |     |                  |             |                     |         | Manufacturer |
|                                | MM Ref                                                       |               |     |             |                 |     |                  |             |                     |         | Date Type    |
|                                | Ops Number(s)                                                |               |     |             |                 |     |                  |             |                     |         |              |
| 275084                         | C Track Flap Roller (Right Inboard Upper Forward) - Discard  |               | HRS |             | 730.5           |     | 2400             | 2315.6      | 4715.6              | 4765.6  | 0            |
|                                |                                                              |               | AFL |             | 315             |     |                  | 802         |                     |         | 0            |
|                                | 60P5755371Z007                                               | NSN           | MOS | TSN:19      | 28.7            |     |                  | 21 Dec 2023 |                     |         |              |
|                                | [HRS: +50/-50]                                               |               |     |             |                 |     |                  |             |                     |         |              |
| Airframe                       |                                                              |               |     |             |                 |     |                  |             |                     |         |              |
| Notes: MRI PARENT CODE: 275153 |                                                              |               |     |             |                 |     |                  |             |                     |         |              |
| 275085                         | C Track Flap Roller (Right Outboard Upper Forward) - Discard |               | HRS |             | 1452            |     | 2400             | 1594.1      | 3994.1              | 4044.1  | 0            |
|                                |                                                              |               | AFL |             | 570             |     |                  | 547         |                     |         | 0            |
|                                | 60P5755371Z007                                               | NSN           | MOS |             | 63.9            |     |                  | 15 Jan 2021 |                     |         |              |
|                                | [HRS: +50/-50]                                               |               |     |             |                 |     |                  |             |                     |         |              |
| Airframe                       |                                                              |               |     |             |                 |     |                  |             |                     |         |              |
| Notes: MRI PARENT CODE: 275154 |                                                              |               |     |             |                 |     |                  |             |                     |         |              |
| 275086                         | C Track Flap Roller (Right Outboard Upper Aft) - Discard     |               | HRS |             | 1452            |     | 2400             | 1594.1      | 3994.1              | 4044.1  | 0            |
|                                | 60P5755371Z011                                               |               | AFL |             | 570             |     |                  | 547         |                     |         | 0            |
|                                | NSN                                                          |               | MOS |             | 63.9            |     |                  | 15 Jan 2021 |                     |         |              |
|                                | [HRS: +50/-50]                                               |               |     |             |                 |     |                  |             |                     |         |              |
| Airframe                       |                                                              |               |     |             |                 |     |                  |             |                     |         |              |
| Notes: MRI PARENT CODE: 275155 |                                                              |               |     |             |                 |     |                  |             |                     |         |              |
| 275087                         | C Track Flap Roller (Right Outboard Lower Forward) - Discard |               | HRS |             | 730.5           |     | 2400             | 2315.6      | 4715.6              | 4765.6  | 0            |
|                                |                                                              |               | AFL |             | 315             |     |                  | 802         |                     |         | 0            |
|                                | 60P5755371Z003                                               | NSN           | MOS | TSN:7       | 28.7            |     |                  | 21 Dec 2023 |                     |         |              |
|                                | [HRS: +50/-50]                                               |               |     |             |                 |     |                  |             |                     |         |              |
| Airframe                       |                                                              |               |     |             |                 |     |                  |             |                     |         |              |
| Notes: MRI PARENT CODE: 275156 |                                                              |               |     |             |                 |     |                  |             |                     |         |              |
| 275088                         | D Track Flap Roller (Left Inboard Upper) - Discard           |               | HRS |             | 730.5           |     | 2400             | 2315.6      | 4715.6              | 4765.6  | 0            |
|                                | 60P5755371Z010                                               |               | AFL |             | 315             |     |                  | 802         |                     |         | 0            |
|                                | NSN                                                          |               | MOS | TSN:4       | 28.7            |     |                  | 21 Dec 2023 |                     |         |              |
|                                | [HRS: +50/-50]                                               |               |     |             |                 |     |                  |             |                     |         |              |
| Airframe                       |                                                              |               |     |             |                 |     |                  |             |                     |         |              |
| Notes: MRI PARENT CODE: 275169 |                                                              |               |     |             |                 |     |                  |             |                     |         |              |
| 275089                         | D Track Flap Roller (Left Outboard Upper) - Discard          |               | HRS |             | 730.5           |     | 2400             | 2315.6      | 4715.6              | 4765.6  | 0            |
|                                | 60P5755371Z010                                               |               | AFL |             | 315             |     |                  | 802         |                     |         | 0            |
|                                | NSN                                                          |               | MOS | TSN:18      | 28.7            |     |                  | 21 Dec 2023 |                     |         |              |
|                                | [HRS: +50/-50]                                               |               |     |             |                 |     |                  |             |                     |         |              |
| Airframe                       |                                                              |               |     |             |                 |     |                  |             |                     |         |              |
| Notes: MRI PARENT CODE: 275170 |                                                              |               |     |             |                 |     |                  |             |                     |         |              |



| ATA<br>U=Custom                | Description                                                 |               | UOM            | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|--------------------------------|-------------------------------------------------------------|---------------|----------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                | Part Number                                                 | Serial Number |                |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position               | HW                                                          | SW            |                |             |                 |     |                  |             |                    |         | Manufacturer |
|                                | MM Ref                                                      |               |                |             |                 |     |                  |             |                    |         | Date Type    |
|                                | Ops Number(s)                                               |               |                |             |                 |     |                  |             |                    |         |              |
| 275090                         | D Track Flap Roller (Left Trailing Edge Forward) - Discard  |               | HRS            |             | 730.5           |     | 2400             | 2315.6      | 4800               | 4850    | 0            |
|                                | 60P5755371Z004                                              |               | AFL            |             | 315             |     |                  | 802         |                    |         | 0            |
|                                | NSN                                                         |               | MOS            |             | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
|                                | Airframe                                                    |               | [HRS: +50/-50] |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 275171 |                                                             |               |                |             |                 |     |                  |             |                    |         |              |
| 275091                         | D Track Flap Roller (Left Trailing Edge Aft) - Discard      |               | HRS            |             | 730.5           |     | 2400             | 2315.6      | 4715.6             | 4765.6  | 0            |
|                                | 60P5755371Z004                                              |               | AFL            |             | 315             |     |                  | 802         |                    |         | 0            |
|                                | NSN                                                         |               | MOS            | TSN:18      | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
|                                | Airframe                                                    |               | [HRS: +50/-50] |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 275172 |                                                             |               |                |             |                 |     |                  |             |                    |         |              |
| 275092                         | D Track Flap Roller (Right Inboard Upper) - Discard         |               | HRS            |             | 730.5           |     | 2400             | 2315.6      | 4715.6             | 4765.6  | 0            |
|                                | 60P5755371Z010                                              |               | AFL            |             | 315             |     |                  | 802         |                    |         | 0            |
|                                | NSN                                                         |               | MOS            | TSN:18      | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
|                                | Airframe                                                    |               | [HRS: +50/-50] |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 275173 |                                                             |               |                |             |                 |     |                  |             |                    |         |              |
| 275093                         | D Track Flap Roller (Right Outboard Upper) - Discard        |               | HRS            |             | 730.5           |     | 2400             | 2315.6      | 4715.6             | 4765.6  | 0            |
|                                | 60P5755371Z010                                              |               | AFL            |             | 315             |     |                  | 802         |                    |         | 0            |
|                                | NSN                                                         |               | MOS            | TSN:4       | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
|                                | Airframe                                                    |               | [HRS: +50/-50] |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 275174 |                                                             |               |                |             |                 |     |                  |             |                    |         |              |
| 275094                         | D Track Flap Roller (Right Trailing Edge Forward) - Discard |               | HRS            |             | 730.5           |     | 2400             | 2315.6      | 4800               | 4850    | 0            |
|                                | Discard                                                     |               | AFL            |             | 315             |     |                  | 802         |                    |         | 0            |
|                                | 60P5755371Z004                                              |               | MOS            |             | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
|                                | NSN                                                         |               | [HRS: +50/-50] |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 275175 |                                                             |               |                |             |                 |     |                  |             |                    |         |              |
| 275095                         | D Track Flap Roller (Right Trailing Edge Aft) - Discard     |               | HRS            |             | 730.5           |     | 2400             | 2315.6      | 4715.6             | 4765.6  | 0            |
|                                | 60P5755371Z004                                              |               | AFL            |             | 315             |     |                  | 802         |                    |         | 0            |
|                                | NSN                                                         |               | MOS            | TSN:18      | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
|                                | Airframe                                                    |               | [HRS: +50/-50] |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 275176 |                                                             |               |                |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom                | Description                                            |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|--------------------------------|--------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                | Part Number                                            | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position               | HW                                                     | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                | MM Ref                                                 |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                                | Ops Number(s)                                          |               |     |             |                 |     |                  |             |                    |         |              |
| 275096                         | D Track Flap Down Load Catch Roller (Left Inboard) -   |               | HRS |             | 730.5           |     | 2400             | 2315.6      | 4715.6             | 4765.6  | 0            |
|                                | Discard                                                |               | AFL |             | 315             |     |                  | 802         |                    |         | 0            |
|                                | 60P5755371Z008                                         | NSN           | MOS | TSN:20      | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
|                                | [HRS: +50/-50]                                         |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                       |                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 275185 |                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 275097                         | D Track Flap Down Load Catch Roller (Left Outboard) -  |               | HRS |             | 730.5           |     | 2400             | 2315.6      | 4800               | 4850    | 0            |
|                                | Discard                                                |               | AFL |             | 315             |     |                  | 802         |                    |         | 0            |
|                                | 60P5755371Z008                                         | NSN           | MOS |             | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
|                                | [HRS: +50/-50]                                         |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                       |                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 275186 |                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 275098                         | D Track Flap Down Load Catch Roller (Right Inboard) -  |               | HRS |             | 730.5           |     | 2400             | 2315.6      | 4715.6             | 4765.6  | 0            |
|                                | Discard                                                |               | AFL |             | 315             |     |                  | 802         |                    |         | 0            |
|                                | 60P5755371Z008                                         | NSN           | MOS | TSN:20      | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
|                                | [HRS: +50/-50]                                         |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                       |                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 275187 |                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 275099                         | D Track Flap Down Load Catch Roller (Right Outboard) - |               | HRS |             | 730.5           |     | 2400             | 2315.6      | 4715.6             | 4765.6  | 0            |
|                                | Discard                                                |               | AFL |             | 315             |     |                  | 802         |                    |         | 0            |
|                                | 60P5755371Z008                                         | NSN           | MOS | TSN:20      | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
|                                | [HRS: +50/-50]                                         |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                       |                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 275188 |                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 275101                         | Horizontal Stabilizer Control Unit Tray - Removal /    |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | Installation                                           |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                | 60P2745001Z001                                         | 44YLNf        | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                |                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                       |                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 275103                         | Flap Yoke Fitting (Left) - Visual Inspection           |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                        |               | AFL |             | 1117            |     | 15000**          | 0           | 15000              |         | 0            |
|                                |                                                        |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                |                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                       |                                                        |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom                                   | Description                                                                          |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|---------------------------------------------------|--------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                                                   | Part Number                                                                          | Serial Number |     |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position                                  | HW                                                                                   | SW            |     |             |                 |     |                  |             |                    |             | Manufacturer |
|                                                   | MM Ref                                                                               |               |     |             |                 |     |                  |             |                    |             | Date Type    |
|                                                   | Ops Number(s)                                                                        |               |     |             |                 |     |                  |             |                    |             |              |
| 275104                                            | Flap Yoke Fitting (Right) - Visual Inspection                                        |               | HRS |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                                                   |                                                                                      |               | AFL |             | 1117            |     | 15000**          | 0           | 15000              | 0           |              |
|                                                   |                                                                                      |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
| Airframe                                          |                                                                                      |               |     |             |                 |     |                  |             |                    |             |              |
| 275108                                            | Flap Track and Roller - Detailed Inspection                                          |               | HRS |             | 137             |     | 600              | 2909.1      | 3509.1             | 3559.1      | 0            |
|                                                   |                                                                                      |               | AFL |             | 52              |     |                  | 1065        |                    | 0           |              |
|                                                   |                                                                                      |               | MOS |             | 5.3             | -6  | 12               | 02 Dec 2025 | 30 Nov 2026*       | 31 Dec 2026 |              |
| [End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50] |                                                                                      |               |     |             |                 |     |                  |             |                    |             |              |
| Airframe                                          |                                                                                      |               |     |             |                 |     |                  |             |                    |             |              |
| 275109                                            | A Track Flap Roller (Left Inboard) - Removal / Installation<br>60P5755371Z019 NSN    |               | HRS |             | 473             |     |                  | 2573.1      |                    |             | 0            |
|                                                   |                                                                                      |               | AFL |             | 185             |     |                  | 932         |                    | 0           |              |
|                                                   |                                                                                      |               | MOS | TSN:6       | 14.5            |     | 25 Feb 2025      |             |                    |             |              |
| Airframe                                          |                                                                                      |               |     |             |                 |     |                  |             |                    |             |              |
| 275110                                            | A Track Flap Roller (Left Outboard) - Removal / Installation<br>60P5755371Z019 NSN   |               | HRS |             | 473             |     |                  | 2573.1      |                    |             | 0            |
|                                                   |                                                                                      |               | AFL |             | 185             |     |                  | 932         |                    | 0           |              |
|                                                   |                                                                                      |               | MOS | TSN:6       | 14.5            |     | 25 Feb 2025      |             |                    |             |              |
| Airframe                                          |                                                                                      |               |     |             |                 |     |                  |             |                    |             |              |
| 275111                                            | A Track Flap Roller (Left Trailing Edge) - Removal / Installation<br>KRP505-04VT NSN |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                                                   |                                                                                      |               | AFL |             | 315             |     |                  | 802         |                    | 0           |              |
|                                                   |                                                                                      |               | MOS | TSN:4       | 28.7            |     | 21 Dec 2023      |             |                    |             |              |
| Airframe                                          |                                                                                      |               |     |             |                 |     |                  |             |                    |             |              |
| 275112                                            | A Track Flap Roller (Right Inboard) - Removal / Installation<br>60P5755371Z019 NSN   |               | HRS |             | 473             |     |                  | 2573.1      |                    |             | 0            |
|                                                   |                                                                                      |               | AFL |             | 185             |     |                  | 932         |                    | 0           |              |
|                                                   |                                                                                      |               | MOS | TSN:6       | 14.5            |     | 25 Feb 2025      |             |                    |             |              |
| Airframe                                          |                                                                                      |               |     |             |                 |     |                  |             |                    |             |              |
| 275113                                            | A Track Flap Roller (Right Outboard) - Removal / Installation<br>60P5755371Z019 NSN  |               | HRS |             | 473             |     |                  | 2573.1      |                    |             | 0            |
|                                                   |                                                                                      |               | AFL |             | 185             |     |                  | 932         |                    | 0           |              |
|                                                   |                                                                                      |               | MOS | TSN:6       | 14.5            |     | 25 Feb 2025      |             |                    |             |              |
| Airframe                                          |                                                                                      |               |     |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom  | Description                                                                |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                         | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                     |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                              |               |     |             |                 |     |                  |             |                    |         |              |
| 275114           | A Track Flap Roller (Right Trailing Edge) - Removal / Installation         |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  |                                                                            |               | AFL |             | 315             |     |                  | 802         |                    |         | 0            |
|                  | KRP505-04VT                                                                | NSN           | MOS | TSN:4       | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
|                  |                                                                            |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                            |               |     |             |                 |     |                  |             |                    |         |              |
| 275121           | B Track Flap Roller (Left Inboard Upper Aft) - Removal / Installation      |               | HRS |             | 473             |     |                  | 2573.1      |                    |         | 0            |
|                  |                                                                            |               | AFL |             | 185             |     |                  | 932         |                    |         | 0            |
|                  | 60P5755371Z014                                                             | NSN           | MOS | TSN:4       | 14.5            |     |                  | 25 Feb 2025 |                    |         |              |
|                  |                                                                            |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                            |               |     |             |                 |     |                  |             |                    |         |              |
| 275122           | B Track Flap Roller (Left Outboard Upper Aft) - Removal / Installation     |               | HRS |             | 473             |     |                  | 2573.1      |                    |         | 0            |
|                  |                                                                            |               | AFL |             | 185             |     |                  | 932         |                    |         | 0            |
|                  | 60P5755371Z014                                                             | NSN           | MOS | TSN:4       | 14.5            |     |                  | 25 Feb 2025 |                    |         |              |
|                  |                                                                            |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                            |               |     |             |                 |     |                  |             |                    |         |              |
| 275123           | B Track Flap Roller (Left Inboard Upper Forward) - Removal / Installation  |               | HRS |             | 473             |     |                  | 2573.1      |                    |         | 0            |
|                  |                                                                            |               | AFL |             | 185             |     |                  | 932         |                    |         | 0            |
|                  | 60P5755371Z002                                                             | NSN           | MOS | TSN:20      | 14.5            |     |                  | 25 Feb 2025 |                    |         |              |
|                  |                                                                            |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                            |               |     |             |                 |     |                  |             |                    |         |              |
| 275124           | B Track Flap Roller (Left Outboard Upper Forward) - Removal / Installation |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  |                                                                            |               | AFL |             | 315             |     |                  | 802         |                    |         | 0            |
|                  | 60P5755371Z002                                                             | NSN           | MOS | TSN:7       | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
|                  |                                                                            |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                            |               |     |             |                 |     |                  |             |                    |         |              |
| 275125           | B Track Flap Roller (Left Inboard Lower Forward) - Removal / Installation  |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  |                                                                            |               | AFL |             | 315             |     |                  | 802         |                    |         | 0            |
|                  | 60P5755371Z003                                                             | NSN           | MOS | TSN:6       | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
|                  |                                                                            |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                            |               |     |             |                 |     |                  |             |                    |         |              |
| 275126           | B Track Flap Roller (Left Outboard Lower Forward) - Removal / Installation |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  |                                                                            |               | AFL |             | 315             |     |                  | 802         |                    |         | 0            |
|                  | 60P5755371Z003                                                             | NSN           | MOS | TSN:6       | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
|                  |                                                                            |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                            |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                 |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-----------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                 | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                          | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                      |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                               |               |     |             |                 |     |                  |             |                    |         |              |
| 275127           | B Track Flap Roller (Right Inboard Upper Aft) - Removal / Installation      |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  |                                                                             |               | AFL |             | 315             |     |                  | 802         |                    |         | 0            |
|                  | 60P5755371Z014                                                              | NSN           | MOS |             | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
|                  |                                                                             |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 275128           | B Track Flap Roller (Right Outboard Upper Aft) - Removal / Installation     |               | HRS |             | 994.2           |     |                  | 2051.9      |                    |         | 0            |
|                  |                                                                             |               | AFL |             | 392             |     |                  | 725         |                    |         | 0            |
|                  | 60P5755371Z014                                                              | NSN           | MOS | TSN:5       | 41.2            |     |                  | 05 Dec 2022 |                    |         |              |
|                  |                                                                             |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 275129           | B Track Flap Roller (Right Inboard Upper Forward) - Removal / Installation  |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  |                                                                             |               | AFL |             | 315             |     |                  | 802         |                    |         | 0            |
|                  | 60P5755371Z002                                                              | NSN           | MOS | TSN:18      | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
|                  |                                                                             |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 275130           | B Track Flap Roller (Right Outboard Upper Forward) - Removal / Installation |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  |                                                                             |               | AFL |             | 315             |     |                  | 802         |                    |         | 0            |
|                  | 60P5755371Z002                                                              | NSN           | MOS | TSN:7       | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
|                  |                                                                             |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 275131           | B Track Flap Roller (Right Inboard Lower Forward) - Removal / Installation  |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  |                                                                             |               | AFL |             | 315             |     |                  | 802         |                    |         | 0            |
|                  | 60P5755371Z003                                                              | NSN           | MOS | TSN:6       | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
|                  |                                                                             |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 275132           | B Track Flap Roller (Right Outboard Lower Forward) - Removal / Installation |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  |                                                                             |               | AFL |             | 315             |     |                  | 802         |                    |         | 0            |
|                  | 60P5755371Z003                                                              | NSN           | MOS | TSN:5       | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
|                  |                                                                             |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 275145           | C Track Flap Roller (Left Inboard Upper Aft) - Removal / Installation       |               | HRS |             | 994.2           |     |                  | 2051.9      |                    |         | 0            |
|                  |                                                                             |               | AFL |             | 392             |     |                  | 725         |                    |         | 0            |
|                  | 60P5755371Z014                                                              | NSN           | MOS | TSN:5       | 41.2            |     |                  | 04 Dec 2022 |                    |         |              |
|                  |                                                                             |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                             |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                         | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                     |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                              |               |     |             |                 |     |                  |             |                    |         |              |
| 275146           | C Track Flap Roller (Left Inboard Lower Forward) - Removal / Installation  |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  |                                                                            |               | AFL |             | 315             |     |                  | 802         |                    |         | 0            |
|                  | 60P5755371Z003                                                             | NSN           | MOS | TSN:6       | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
|                  |                                                                            |               | MSC |             |                 | O/C |                  |             |                    |         |              |
| Airframe         |                                                                            |               |     |             |                 |     |                  |             |                    |         |              |
| 275147           | C Track Flap Roller (Left Inboard Upper Forward) - Removal / Installation  |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  |                                                                            |               | AFL |             | 315             |     |                  | 802         |                    |         | 0            |
|                  | 60P5755371Z007                                                             | NSN           | MOS | TSN:19      | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
|                  |                                                                            |               | MSC |             |                 | O/C |                  |             |                    |         |              |
| Airframe         |                                                                            |               |     |             |                 |     |                  |             |                    |         |              |
| 275148           | C Track Flap Roller (Left Outboard Upper Forward) - Removal / Installation |               | HRS |             | 1452            |     |                  | 1594.1      |                    |         | 0            |
|                  |                                                                            |               | AFL |             | 570             |     |                  | 547         |                    |         | 0            |
|                  | 60P5755371Z007                                                             | NSN           | MOS |             | 63.9            |     |                  | 15 Jan 2021 |                    |         |              |
|                  |                                                                            |               | MSC |             |                 | O/C |                  |             |                    |         |              |
| Airframe         |                                                                            |               |     |             |                 |     |                  |             |                    |         |              |
| 275149           | C Track Flap Roller (Left Outboard Upper Aft) - Removal / Installation     |               | HRS |             | 994.2           |     |                  | 2051.9      |                    |         | 0            |
|                  |                                                                            |               | AFL |             | 392             |     |                  | 725         |                    |         | 0            |
|                  | 60P5755371Z014                                                             | NSN           | MOS | TSN:5       | 41.2            |     |                  | 04 Dec 2022 |                    |         |              |
|                  |                                                                            |               | MSC |             |                 | O/C |                  |             |                    |         |              |
| Airframe         |                                                                            |               |     |             |                 |     |                  |             |                    |         |              |
| 275150           | C Track Flap Roller (Left Outboard Lower Forward) - Removal / Installation |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  |                                                                            |               | AFL |             | 315             |     |                  | 802         |                    |         | 0            |
|                  | 60P5755371Z003                                                             | NSN           | MOS |             | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
|                  |                                                                            |               | MSC |             |                 | O/C |                  |             |                    |         |              |
| Airframe         |                                                                            |               |     |             |                 |     |                  |             |                    |         |              |
| 275151           | C Track Flap Roller (Right Inboard Upper Aft) - Removal / Installation     |               | HRS |             | 994.2           |     |                  | 2051.9      |                    |         | 0            |
|                  |                                                                            |               | AFL |             | 392             |     |                  | 725         |                    |         | 0            |
|                  | 60P5755371Z014                                                             | NSN           | MOS | TSN:5       | 41.2            |     |                  | 05 Dec 2022 |                    |         |              |
|                  |                                                                            |               | MSC |             |                 | O/C |                  |             |                    |         |              |
| Airframe         |                                                                            |               |     |             |                 |     |                  |             |                    |         |              |
| 275152           | C Track Flap Roller (Right Inboard Lower Forward) - Removal / Installation |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  |                                                                            |               | AFL |             | 315             |     |                  | 802         |                    |         | 0            |
|                  | 60P5755371Z003                                                             | NSN           | MOS | TSN:7       | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
|                  |                                                                            |               | MSC |             |                 | O/C |                  |             |                    |         |              |
| Airframe         |                                                                            |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                 |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-----------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                 | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                          | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                      |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                               |               |     |             |                 |     |                  |             |                    |         |              |
| 275153           | C Track Flap Roller (Right Inboard Upper Forward) - Removal / Installation  |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  |                                                                             |               | AFL |             | 315             |     |                  | 802         |                    |         | 0            |
|                  | 60P5755371Z007                                                              | NSN           | MOS | TSN:19      | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
|                  |                                                                             |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 275154           | C Track Flap Roller (Right Outboard Upper Forward) - Removal / Installation |               | HRS |             | 1452            |     |                  | 1594.1      |                    |         | 0            |
|                  |                                                                             |               | AFL |             | 570             |     |                  | 547         |                    |         | 0            |
|                  | 60P5755371Z007                                                              | NSN           | MOS |             | 63.9            |     |                  | 15 Jan 2021 |                    |         |              |
|                  |                                                                             |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 275155           | C Track Flap Roller (Right Outboard Upper Aft) - Removal / Installation     |               | HRS |             | 994.2           |     |                  | 2051.9      |                    |         | 0            |
|                  |                                                                             |               | AFL |             | 392             |     |                  | 725         |                    |         | 0            |
|                  | 60P5755371Z014                                                              | NSN           | MOS | TSN:5       | 41.2            |     |                  | 05 Dec 2022 |                    |         |              |
|                  |                                                                             |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 275156           | C Track Flap Roller (Right Outboard Lower Forward) - Removal / Installation |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  |                                                                             |               | AFL |             | 315             |     |                  | 802         |                    |         | 0            |
|                  | 60P5755371Z003                                                              | NSN           | MOS | TSN:6       | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
|                  |                                                                             |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 275169           | D Track Flap Roller (Left Inboard Upper) - Removal / Installation           |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  |                                                                             |               | AFL |             | 315             |     |                  | 802         |                    |         | 0            |
|                  | 60P5755371Z010                                                              | NSN           | MOS | TSN:5       | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
|                  |                                                                             |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 275170           | D Track Flap Roller (Left Outboard Upper) - Removal / Installation          |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  |                                                                             |               | AFL |             | 315             |     |                  | 802         |                    |         | 0            |
|                  | 60P5755371Z010                                                              | NSN           | MOS | TSN:18      | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
|                  |                                                                             |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 275171           | D Track Flap Roller (Left Trailing Edge Forward) - Removal / Installation   |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  |                                                                             |               | AFL |             | 315             |     |                  | 802         |                    |         | 0            |
|                  | 60P5755371Z004                                                              | NSN           | MOS | TSN:18      | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
|                  |                                                                             |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                             |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                  |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                  | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                           | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                       |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| 275172           | D Track Flap Roller (Left Trailing Edge Aft) - Removal / Installation        |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  |                                                                              |               | AFL |             | 315             |     |                  | 802         |                    |         | 0            |
|                  | 60P5755371Z004                                                               | NSN           | MOS |             | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
|                  |                                                                              |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                              |               |     |             |                 |     |                  |             |                    |         |              |
| 275173           | D Track Flap Roller (Right Inboard Upper) - Removal / Installation           |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  |                                                                              |               | AFL |             | 315             |     |                  | 802         |                    |         | 0            |
|                  | 60P5755371Z010                                                               | NSN           | MOS | TSN:18      | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
|                  |                                                                              |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                              |               |     |             |                 |     |                  |             |                    |         |              |
| 275174           | D Track Flap Roller (Right Outboard Upper) - Removal / Installation          |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  |                                                                              |               | AFL |             | 315             |     |                  | 802         |                    |         | 0            |
|                  | 60P5755371Z010                                                               | NSN           | MOS | TSN:5       | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
|                  |                                                                              |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                              |               |     |             |                 |     |                  |             |                    |         |              |
| 275175           | D Track Flap Roller (Right Trailing Edge Forward) - Removal / Installation   |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  |                                                                              |               | AFL |             | 315             |     |                  | 802         |                    |         | 0            |
|                  | 60P5755371Z004                                                               | NSN           | MOS | TSN:18      | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
|                  |                                                                              |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                              |               |     |             |                 |     |                  |             |                    |         |              |
| 275176           | D Track Flap Roller (Right Trailing Edge Aft) - Removal / Installation       |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  |                                                                              |               | AFL |             | 315             |     |                  | 802         |                    |         | 0            |
|                  | 60P5755371Z004                                                               | NSN           | MOS |             | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
|                  |                                                                              |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                              |               |     |             |                 |     |                  |             |                    |         |              |
| 275185           | D Track Flap Down Load Catch Roller (Left Inboard) - Removal / Installation  |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  |                                                                              |               | AFL |             | 315             |     |                  | 802         |                    |         | 0            |
|                  | 60P5755371Z008                                                               | NSN           | MOS |             | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
|                  |                                                                              |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                              |               |     |             |                 |     |                  |             |                    |         |              |
| 275186           | D Track Flap Down Load Catch Roller (Left Outboard) - Removal / Installation |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  |                                                                              |               | AFL |             | 315             |     |                  | 802         |                    |         | 0            |
|                  | 60P5755371Z008                                                               | NSN           | MOS | TSN:20      | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
|                  |                                                                              |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                              |               |     |             |                 |     |                  |             |                    |         |              |



| ATA<br>U=Custom  | Description                                                                   |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                   | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                            | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                        |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                                 |               |     |             |                 |     |                  |             |                    |         |              |
| 275187           | D Track Flap Down Load Catch Roller (Right Inboard) - Removal / Installation  |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  |                                                                               |               | AFL |             | 315             |     |                  | 802         |                    |         | 0            |
|                  | 60P5755371Z008                                                                | NSN           | MOS | TSN:20      | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
|                  |                                                                               |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                               |               |     |             |                 |     |                  |             |                    |         |              |
| 275188           | D Track Flap Down Load Catch Roller (Right Outboard) - Removal / Installation |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  |                                                                               |               | AFL |             | 315             |     |                  | 802         |                    |         | 0            |
|                  | 60P5755371Z008                                                                | NSN           | MOS | TSN:20      | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
|                  |                                                                               |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                               |               |     |             |                 |     |                  |             |                    |         |              |
| 275200           | Flap Electronic Control Unit - Removal / Installation                         |               | HRS | TSN:12.3    | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  |                                                                               |               | AFL | TSN:5       | 1112            |     |                  | 5           |                    |         | 0            |
|                  | 60P2755001Z005                                                                | 504           | MOS | TSN:3       | 126.3           |     |                  | 02 Nov 2015 |                    |         |              |
|                  |                                                                               |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                               |               |     |             |                 |     |                  |             |                    |         |              |
| 275300           | Flap (Left) - Removal / Installation                                          |               | HRS | TSN:2316    | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  |                                                                               |               | AFL | TSN:803     | 315             |     |                  | 802         |                    |         | 0            |
|                  | 60P5755003-004                                                                | S179          | MOS | TSN:100     | 28.9            |     |                  | 14 Dec 2023 |                    |         |              |
|                  |                                                                               |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                               |               |     |             |                 |     |                  |             |                    |         |              |
| 275301           | Flap (Right) - Removal / Installation                                         |               | HRS | TSN:2315.98 | 730.52          |     |                  | 2315.58     |                    |         | 0            |
|                  |                                                                               |               | AFL | TSN:803     | 315             |     |                  | 802         |                    |         | 0            |
|                  | 60P5755004-004                                                                | S177          | MOS | TSN:100     | 28.9            |     |                  | 14 Dec 2023 |                    |         |              |
|                  |                                                                               |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                               |               |     |             |                 |     |                  |             |                    |         |              |
| 275302           | Flap Door (Left Inboard) - Removal / Installation                             |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                               |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P5755901A001                                                                | SN-UNKNOWN    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                               |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                               |               |     |             |                 |     |                  |             |                    |         |              |
| 275303           | Flap Door (Right Inboard) - Removal / Installation                            |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                               |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P5755902A001                                                                | SN-UNKNOWN    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                               |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                               |               |     |             |                 |     |                  |             |                    |         |              |
| 275304           | Flap Door (Left Mid) - Removal / Installation                                 |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                               |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P5755905A001                                                                | SN-UNKNOWN    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                               |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                               |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                             |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|---------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                             | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                      | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                  |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                           |               |     |             |                 |     |                  |             |                    |         |              |
| 275305           | Flap Door (Right Mid) - Removal / Installation          |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P5755906A001                                          | SN-UNKNOWN    | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                         |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 275306           | Flap Door (Left Outboard) - Removal / Installation      |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P5755909A001                                          | SN-UNKNOWN    | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                         |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 275307           | Flap Door (Right Outboard) - Removal / Installation     |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P5755910A001                                          | SN-UNKNOWN    | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                         |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 275308           | Flap Power Drive Unit - Removal / Installation          |               | HRS | TSN:2525.9  | 2120.8          |     |                  | 925.3       |                    |         | 0            |
|                  | 60P2756001Z003                                          | 0026          | AFL | TSN:834     | 861             |     |                  | 256         |                    |         | 0            |
|                  |                                                         |               | MOS |             | 86.2            |     |                  | 04 Mar 2019 |                    |         |              |
|                  | Airframe                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 275315           | Flap Actuator (Left Inboard) - Removal / Installation   |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P2753003Z005                                          | 0334          | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                         |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 275316           | Flap Actuator (Right Inboard) - Removal / Installation  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P2753003Z005                                          | 0331          | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                         |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 275317           | Flap Actuator (Left Outboard) - Removal / Installation  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P2753001Z004                                          | B0008         | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                         |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 275318           | Flap Actuator (Right Outboard) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P2753002Z006                                          | 0163          | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                         |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |

| ATA<br>U=Custom  | Description                                             |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|---------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                             | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                      | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                  |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                           |               |     |             |                 |     |                  |             |                    |         |              |
| 275319           | Flap Torque Shaft (Left No. 1) - Removal / Installation |               | HRS | TSN:925.3   | 2120.8          |     |                  | 925.3       |                    |         | 0            |
|                  | 60P2756003Z001                                          | 0370          | AFL | TSN:256     | 861             |     |                  | 256         |                    |         | 0            |
|                  |                                                         |               | MOS | TSN:43      | 86.2            |     |                  | 04 Mar 2019 |                    |         |              |
|                  | Airframe                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 275320           | Flap Torque Shaft (Left No. 2) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P2756003Z003                                          | 0353          | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                         |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 275321           | Flap Torque Shaft (Left No. 3) - Removal / Installation |               | HRS | TSN:2315.58 | 730.52          |     |                  | 2315.58     |                    |         | 0            |
|                  | 60P2756003Z004                                          | 0365          | AFL | TSN:802     | 315             |     |                  | 802         |                    |         | 0            |
|                  |                                                         |               | MOS | TSN:100     | 28.9            |     |                  | 14 Dec 2023 |                    |         |              |
|                  | Airframe                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 275322           | Flap Torque Shaft (Left No. 4) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P2756003Z005                                          | 0348          | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                         |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 275323           | Flap Torque Shaft (Left No. 5) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P2756003Z006                                          | 0317          | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                         |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 275324           | Flap Torque Shaft (Left No. 6) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P2756003Z008                                          | 0314          | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                         |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 275325           | Flap Torque Shaft (Left No. 7) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P2756003Z009                                          | 0340          | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                         |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 275326           | Flap Torque Shaft (Left No. 8) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P2756003Z010                                          | 0280          | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                         |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |

| ATA<br>U=Custom  | Description                                              |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                              | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                       | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                   |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                            |               |     |             |                 |     |                  |             |                    |         |              |
| 275327           | Flap Torque Shaft (Right No. 1) - Removal / Installation |               | HRS | TSN:925.3   | 2120.8          |     |                  | 925.3       |                    |         | 0            |
|                  | 60P2756003Z001                                           | 0364          | AFL | TSN:256     | 861             |     |                  | 256         |                    |         | 0            |
|                  |                                                          |               | MOS | TSN:43      | 86.2            |     |                  | 04 Mar 2019 |                    |         |              |
|                  | Airframe                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 275328           | Flap Torque Shaft (Right No. 2) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P2756003Z003                                           | 0350          | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                          |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 275329           | Flap Torque Shaft (Right No. 3) - Removal / Installation |               | HRS | TSN:2315.58 | 730.52          |     |                  | 2315.58     |                    |         | 0            |
|                  | 60P2756003Z004                                           | 0320          | AFL | TSN:802     | 315             |     |                  | 802         |                    |         | 0            |
|                  |                                                          |               | MOS | TSN:100     | 28.9            |     |                  | 14 Dec 2023 |                    |         |              |
|                  | Airframe                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 275330           | Flap Torque Shaft (Right No. 4) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P2756003Z005                                           | 0377          | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                          |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 275331           | Flap Torque Shaft (Right No. 5) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P2756003Z006                                           | 0330          | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                          |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 275332           | Flap Torque Shaft (Right No. 6) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P2756003Z008                                           | 0304          | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                          |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 275333           | Flap Torque Shaft (Right No. 7) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P2756003Z009                                           | 0367          | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                          |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 275334           | Flap Torque Shaft (Right No. 8) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P2756003Z010                                           | 0451          | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                          |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                            |               | UOM                                               | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------|----------------------------------------------------------------------------------------|---------------|---------------------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                  | Part Number                                                                            | Serial Number |                                                   |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position | HW                                                                                     | SW            |                                                   |             |                 |     |                  |             |                    |             | Manufacturer |
|                  | MM Ref                                                                                 |               |                                                   |             |                 |     |                  |             |                    |             | Date Type    |
|                  | Ops Number(s)                                                                          |               |                                                   |             |                 |     |                  |             |                    |             |              |
| 275341           | Flap Actuator No-Back Mechanism (Left Inboard) (Return to Vendor) - Functional Check   |               | HRS                                               |             | 3046.1          |     | 8500             | 0           | 8500               | 8550        | 0            |
|                  |                                                                                        |               | AFL                                               |             | 1117            |     | 0                |             |                    | 0           |              |
|                  |                                                                                        |               | MOS                                               |             | 122             |     | 250              | 11 Mar 2016 | 31 Jan 2037        | 28 Feb 2037 |              |
|                  |                                                                                        |               | [End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50] |             |                 |     |                  |             |                    |             |              |
| Airframe         | 052026                                                                                 |               |                                                   |             |                 |     |                  |             |                    |             |              |
| 275342           | Flap Actuator No-Back Mechanism (Right Inboard) (Return to Vendor) - Functional Check  |               | HRS                                               |             | 3046.1          |     | 8500             | 0           | 8500               | 8550        | 0            |
|                  |                                                                                        |               | AFL                                               |             | 1117            |     | 0                |             |                    | 0           |              |
|                  |                                                                                        |               | MOS                                               |             | 122             |     | 250              | 11 Mar 2016 | 31 Jan 2037        | 28 Feb 2037 |              |
|                  |                                                                                        |               | [End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50] |             |                 |     |                  |             |                    |             |              |
| Airframe         | 052026                                                                                 |               |                                                   |             |                 |     |                  |             |                    |             |              |
| 275343           | Flap Actuator No-Back Mechanism (Left Outboard) (Return to Vendor) - Functional Check  |               | HRS                                               |             | 3046.1          |     | 8500             | 0           | 8500               | 8550        | 0            |
|                  |                                                                                        |               | AFL                                               |             | 1117            |     | 0                |             |                    | 0           |              |
|                  |                                                                                        |               | MOS                                               |             | 122             |     | 250              | 11 Mar 2016 | 31 Jan 2037        | 28 Feb 2037 |              |
|                  |                                                                                        |               | [End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50] |             |                 |     |                  |             |                    |             |              |
| Airframe         | 052026                                                                                 |               |                                                   |             |                 |     |                  |             |                    |             |              |
| 275344           | Flap Actuator No-Back Mechanism (Right Outboard) (Return to Vendor) - Functional Check |               | HRS                                               |             | 3046.1          |     | 8500             | 0           | 8500               | 8550        | 0            |
|                  |                                                                                        |               | AFL                                               |             | 1117            |     | 0                |             |                    | 0           |              |
|                  |                                                                                        |               | MOS                                               |             | 122             |     | 250              | 11 Mar 2016 | 31 Jan 2037        | 28 Feb 2037 |              |
|                  |                                                                                        |               | [End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50] |             |                 |     |                  |             |                    |             |              |
| Airframe         | 052026                                                                                 |               |                                                   |             |                 |     |                  |             |                    |             |              |
| 275356           | Flap Power Drive Unit Motor - Removal / Installation<br>CA97330-001 0347               |               | HRS                                               | TSN:7.5     | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                        |               | AFL                                               | TSN:4       | 1117            |     | 0                |             |                    | 0           |              |
|                  |                                                                                        |               | MOS                                               |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                        |               | MSC                                               |             |                 |     | O/C              |             |                    |             |              |
| Airframe         | 052026                                                                                 |               |                                                   |             |                 |     |                  |             |                    |             |              |
| 275358           | Flap Actuator Force Limiter (Left Inboard) (Return to Vendor) - Functional Check       |               | HRS                                               |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                        |               | AFL                                               |             | 1117            |     | 0                |             |                    | 0           |              |
|                  |                                                                                        |               | MOS                                               |             | 122             |     | 240              | 11 Mar 2016 | 31 Mar 2036        | 30 Apr 2036 |              |
|                  |                                                                                        |               | [End Of Month Item] [MOS: +1m/-1m]                |             |                 |     |                  |             |                    |             |              |
| Airframe         | 052023                                                                                 |               |                                                   |             |                 |     |                  |             |                    |             |              |
| 275359           | Flap Actuator Force Limiter (Left Outboard) (Return to Vendor) - Functional Check      |               | HRS                                               |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                        |               | AFL                                               |             | 1117            |     | 0                |             |                    | 0           |              |
|                  |                                                                                        |               | MOS                                               |             | 122             |     | 240              | 11 Mar 2016 | 31 Mar 2036        | 30 Apr 2036 |              |
|                  |                                                                                        |               | [End Of Month Item] [MOS: +1m/-1m]                |             |                 |     |                  |             |                    |             |              |
| Airframe         | 052023                                                                                 |               |                                                   |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom                | Description                                                                        |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due     | Avg Man Hrs  |
|--------------------------------|------------------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|---------------------|-------------|--------------|
|                                | Part Number                                                                        | Serial Number |                                    |             |                 |     |                  |             |                     |             | Approx Price |
| Logbook Position               | HW                                                                                 | SW            |                                    |             |                 |     |                  |             |                     |             | Manufacturer |
|                                | MM Ref                                                                             |               |                                    |             |                 |     |                  |             |                     |             | Date Type    |
|                                | Ops Number(s)                                                                      |               |                                    |             |                 |     |                  |             |                     |             |              |
| 275360                         | Flap Actuator Force Limiter (Right Inboard) (Return to Vendor) - Functional Check  |               | HRS                                |             | 3046.1          |     |                  | 0           |                     |             | 0            |
|                                |                                                                                    |               | AFL                                |             | 1117            |     |                  | 0           |                     |             | 0            |
|                                |                                                                                    |               | MOS                                |             | 122             |     | 240              | 11 Mar 2016 | 31 Mar 2036         | 30 Apr 2036 |              |
|                                |                                                                                    |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                     |             |              |
| Airframe                       |                                                                                    | 052023        |                                    |             |                 |     |                  |             |                     |             |              |
| 275361                         | Flap Actuator Force Limiter (Right Outboard) (Return to Vendor) - Functional Check |               | HRS                                |             | 3046.1          |     |                  | 0           |                     |             | 0            |
|                                |                                                                                    |               | AFL                                |             | 1117            |     |                  | 0           |                     |             | 0            |
|                                |                                                                                    |               | MOS                                |             | 122             |     | 240              | 11 Mar 2016 | 31 Mar 2036         | 30 Apr 2036 |              |
|                                |                                                                                    |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                     |             |              |
| Airframe                       |                                                                                    | 052023        |                                    |             |                 |     |                  |             |                     |             |              |
| 275400                         | Flap Position Resolver (Left) - Removal / Installation<br>60P2754001Z001A0434      |               | HRS                                |             | 3046.1          |     |                  | 0           |                     |             | 0            |
|                                |                                                                                    |               | AFL                                |             | 1117            |     |                  | 0           |                     |             | 0            |
|                                |                                                                                    |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                     |             |              |
|                                |                                                                                    |               | MSC                                |             |                 |     | O/C              |             |                     |             |              |
| Airframe                       |                                                                                    |               |                                    |             |                 |     |                  |             |                     |             |              |
| 275401                         | Flap Position Resolver (Right) - Removal / Installation<br>60P2754001Z0010409      |               | HRS                                |             | 3046.1          |     |                  | 0           |                     |             | 0            |
|                                |                                                                                    |               | AFL                                |             | 1117            |     |                  | 0           |                     |             | 0            |
|                                |                                                                                    |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                     |             |              |
|                                |                                                                                    |               | MSC                                |             |                 |     | O/C              |             |                     |             |              |
| Airframe                       |                                                                                    |               |                                    |             |                 |     |                  |             |                     |             |              |
| 275500                         | Flap Control Module - Removal / Installation<br>60P2751100Z006250084               |               | HRS                                |             | 3046.1          |     |                  | 0           |                     |             | 0            |
|                                |                                                                                    |               | AFL                                |             | 1117            |     |                  | 0           |                     |             | 0            |
|                                |                                                                                    |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                     |             |              |
|                                |                                                                                    |               | MSC                                |             |                 |     | O/C              |             |                     |             |              |
| Airframe                       |                                                                                    |               |                                    |             |                 |     |                  |             |                     |             |              |
| 275502                         | Flap Hydraulic Control Module - Removal / Installation<br>60P2756002Z007B0370      |               | HRS                                |             | 3046.1          |     |                  | 0           |                     |             | 0            |
|                                |                                                                                    |               | AFL                                |             | 1117            |     |                  | 0           |                     |             | 0            |
|                                |                                                                                    |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                     |             |              |
|                                |                                                                                    |               | MSC                                |             |                 |     | O/C              |             |                     |             |              |
| Airframe                       |                                                                                    |               |                                    |             |                 |     |                  |             |                     |             |              |
| 275507                         | Flap Hydraulic Control Module - Discard<br>60P2756002Z007B0370                     |               | HRS                                |             | 3046.1          |     |                  | 0           |                     |             | 0            |
|                                |                                                                                    |               | AFL                                |             | 1117            |     |                  | 0           |                     |             | 0            |
|                                |                                                                                    |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                     |             |              |
|                                |                                                                                    |               | MSC                                |             |                 |     | O/C              |             |                     |             |              |
| Airframe                       |                                                                                    |               |                                    |             |                 |     |                  |             |                     |             |              |
| Notes: MRI PARENT CODE: 275502 |                                                                                    |               |                                    |             |                 |     |                  |             |                     |             |              |

| ATA<br>U=Custom  | Description                                       |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|---------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                       | Serial Number |     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                | SW            |     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                            |               |     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                     |               |     |             |                 |     |                  |             |                     |         |              |
| 275617           | Flap Drive Pillow Block (Left No. 1) - Removal /  |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  | Installation                                      |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 60P2756011Z001                                    | B0797         | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                   |               | MSC |             |                 |     | O/C              |             |                     |         |              |
|                  | Airframe                                          |               |     |             |                 |     |                  |             |                     |         |              |
| 275618           | Flap Drive Pillow Block (Left No. 2) - Removal /  |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  | Installation                                      |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 60P2756011Z001                                    | B0796         | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                   |               | MSC |             |                 |     | O/C              |             |                     |         |              |
|                  | Airframe                                          |               |     |             |                 |     |                  |             |                     |         |              |
| 275619           | Flap Drive Pillow Block (Left No. 3) - Removal /  |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  | Installation                                      |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 60P2756011Z001                                    | B0808         | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                   |               | MSC |             |                 |     | O/C              |             |                     |         |              |
|                  | Airframe                                          |               |     |             |                 |     |                  |             |                     |         |              |
| 275620           | Flap Drive Pillow Block (Left No. 4) - Removal /  |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  | Installation                                      |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 60P2756011Z001                                    | B0802         | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                   |               | MSC |             |                 |     | O/C              |             |                     |         |              |
|                  | Airframe                                          |               |     |             |                 |     |                  |             |                     |         |              |
| 275621           | Flap Drive Pillow Block (Left No. 5) - Removal /  |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  | Installation                                      |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 60P2756011Z001                                    | B0789         | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                   |               | MSC |             |                 |     | O/C              |             |                     |         |              |
|                  | Airframe                                          |               |     |             |                 |     |                  |             |                     |         |              |
| 275622           | Flap Drive Pillow Block (Left No. 6) - Removal /  |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  | Installation                                      |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 60P2756011Z001                                    | B0790         | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                   |               | MSC |             |                 |     | O/C              |             |                     |         |              |
|                  | Airframe                                          |               |     |             |                 |     |                  |             |                     |         |              |
| 275623           | Flap Drive Pillow Block (Right No. 1) - Removal / |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  | Installation                                      |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 60P2756011Z001                                    | B0826         | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                   |               | MSC |             |                 |     | O/C              |             |                     |         |              |
|                  | Airframe                                          |               |     |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom  | Description                                                    |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                    | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                             | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                         |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                  |               |     |             |                 |     |                  |             |                    |         |              |
| 275624           | Flap Drive Pillow Block (Right No. 2) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P2756011Z001                                                 | B0786         | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| 275625           | Flap Drive Pillow Block (Right No. 3) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P2756011Z001                                                 | B0793         | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| 275626           | Flap Drive Pillow Block (Right No. 4) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P2756011Z001                                                 | B0803         | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| 275627           | Flap Drive Pillow Block (Right No. 5) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P2756011Z001                                                 | B0792         | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| 275628           | Flap Drive Pillow Block (Right No. 6) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P2756011Z001                                                 | B0783         | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| 276001           | Ground Spoiler System - Functional Test                        |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| 276002           | Spoiler System - Mechanical Rig                                |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                |               |     |             |                 |     |                  |             |                    |         |              |



| ATA<br>U=Custom  | Description                                                                       |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------|-----------------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                  | Part Number                                                                       | Serial Number |                                    |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position | HW                                                                                | SW            |                                    |             |                 |     |                  |             |                    |             | Manufacturer |
|                  | MM Ref                                                                            |               |                                    |             |                 |     |                  |             |                    |             | Date Type    |
|                  | Ops Number(s)                                                                     |               |                                    |             |                 |     |                  |             |                    |             |              |
| 276003           | Spoiler Attachment Fittings (Corrosion) - Detailed Inspection                     |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                                   |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                                   |               | MOS                                |             | 28.7            |     | 48               | 21 Dec 2023 | 31 Dec 2027        | 31 Jan 2028 |              |
|                  |                                                                                   |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                   |               | 052013                             |             |                 |     |                  |             |                    |             |              |
| 276004           | Spoiler Actuating System Ibit Suite A Test - Operational Check                    |               | HRS                                |             | 536.8           |     | 7200             | 2509.3      | 9709.3             | 9759.3      | 0            |
|                  |                                                                                   |               | AFL                                |             | 206             |     |                  | 911         |                    |             | 0            |
|                  |                                                                                   |               | MOS                                |             | 15.8            |     |                  | 16 Jan 2025 |                    |             |              |
|                  |                                                                                   |               | [HRS: +50/-50]                     |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                   |               | 052008                             |             |                 |     |                  |             |                    |             |              |
| 276005           | Spoiler Actuator Integrity (Suite B) - Initiated Built-In Test - Functional Check |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                   |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                   |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                   |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                   |               |                                    |             |                 |     |                  |             |                    |             |              |
| 276008           | Spoiler Free Play Backlash (Left Inboard) - Functional Check                      |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                   |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                   |               | MOS                                |             | 122             |     |                  | 11 Mar 2016 |                    |             |              |
|                  |                                                                                   |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                   |               |                                    |             |                 |     |                  |             |                    |             |              |
| 276009           | Spoiler Free Play Backlash (Left Midboard) - Functional Check                     |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                   |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                   |               | MOS                                |             | 122             |     |                  | 11 Mar 2016 |                    |             |              |
|                  |                                                                                   |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                   |               |                                    |             |                 |     |                  |             |                    |             |              |
| 276010           | Spoiler Free Play Backlash (Left Outboard) - Functional Check                     |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                   |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                   |               | MOS                                |             | 122             |     |                  | 11 Mar 2016 |                    |             |              |
|                  |                                                                                   |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                   |               |                                    |             |                 |     |                  |             |                    |             |              |
| 276011           | Spoiler Free Play Backlash (Right Inboard) - Functional Check                     |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                   |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                   |               | MOS                                |             | 122             |     |                  | 11 Mar 2016 |                    |             |              |
|                  |                                                                                   |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                   |               |                                    |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom  | Description                                                    |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|----------|--------------------|---------|--------------|
|                  | Part Number                                                    | Serial Number |     |             |                 |     |                  |          |                    |         | Approx Price |
| Logbook Position | HW                                                             | SW            |     |             |                 |     |                  |          |                    |         | Manufacturer |
|                  | MM Ref                                                         |               |     |             |                 |     |                  |          |                    |         | Date Type    |
|                  | Ops Number(s)                                                  |               |     |             |                 |     |                  |          |                    |         |              |
| 276012           | Spoiler Free Play Backlash (Right Midboard) - Functional Check |               | HRS |             | 3046.1          |     |                  | 0        |                    |         | 0            |
|                  |                                                                |               | AFL |             | 1117            |     | 0                |          | 0                  |         |              |
|                  |                                                                |               | MOS |             | 122             |     | 11 Mar 2016      |          |                    |         |              |
|                  |                                                                |               | MSC |             |                 | O/C |                  |          |                    |         |              |
| Airframe         |                                                                |               |     |             |                 |     |                  |          |                    |         |              |
| 276013           | Spoiler Free Play Backlash (Right Outboard) - Functional Check |               | HRS |             | 3046.1          |     |                  | 0        |                    |         | 0            |
|                  |                                                                |               | AFL |             | 1117            |     | 0                |          | 0                  |         |              |
|                  |                                                                |               | MOS |             | 122             |     | 11 Mar 2016      |          |                    |         |              |
|                  |                                                                |               | MSC |             |                 | O/C |                  |          |                    |         |              |
| Airframe         |                                                                |               |     |             |                 |     |                  |          |                    |         |              |
| 276014           | Spoiler Electrical Rig (Left Inboard) - Functional Check       |               | HRS |             | 536.8           |     |                  | 2509.3   |                    |         | 0            |
|                  |                                                                |               | AFL |             | 206             |     | 911              |          | 0                  |         |              |
|                  |                                                                |               | MOS |             | 15.8            |     | 16 Jan 2025      |          |                    |         |              |
|                  |                                                                |               | MSC |             |                 | O/C |                  |          |                    |         |              |
| Airframe         |                                                                |               |     |             |                 |     |                  |          |                    |         |              |
| 276015           | Spoiler Electrical Rig (Left Midboard) - Functional Check      |               | HRS |             | 2345.1          |     |                  | 701      |                    |         | 0            |
|                  |                                                                |               | AFL |             | 936             |     | 181              |          | 0                  |         |              |
|                  |                                                                |               | MOS |             | 96.7            |     | 19 Apr 2018      |          |                    |         |              |
|                  |                                                                |               | MSC |             |                 | O/C |                  |          |                    |         |              |
| Airframe         |                                                                |               |     |             |                 |     |                  |          |                    |         |              |
| 276016           | Spoiler Electrical Rig (Left Outboard) - Functional Check      |               | HRS |             | 663.7           |     |                  | 2382.4   |                    |         | 0            |
|                  |                                                                |               | AFL |             | 291             |     | 826              |          | 0                  |         |              |
|                  |                                                                |               | MOS |             | 24.9            |     | 13 Apr 2024      |          |                    |         |              |
|                  |                                                                |               | MSC |             |                 | O/C |                  |          |                    |         |              |
| Airframe         |                                                                |               |     |             |                 |     |                  |          |                    |         |              |
| 276017           | Spoiler Electrical Rig (Right Inboard) - Functional Check      |               | HRS |             | 2345.1          |     |                  | 701      |                    |         | 0            |
|                  |                                                                |               | AFL |             | 936             |     | 181              |          | 0                  |         |              |
|                  |                                                                |               | MOS |             | 96.6            |     | 23 Apr 2018      |          |                    |         |              |
|                  |                                                                |               | MSC |             |                 | O/C |                  |          |                    |         |              |
| Airframe         |                                                                |               |     |             |                 |     |                  |          |                    |         |              |
| 276018           | Spoiler Electrical Rig (Right Midboard) - Functional Check     |               | HRS |             | 2345.1          |     |                  | 701      |                    |         | 0            |
|                  |                                                                |               | AFL |             | 936             |     | 181              |          | 0                  |         |              |
|                  |                                                                |               | MOS |             | 96.7            |     | 19 Apr 2018      |          |                    |         |              |
|                  |                                                                |               | MSC |             |                 | O/C |                  |          |                    |         |              |
| Airframe         |                                                                |               |     |             |                 |     |                  |          |                    |         |              |
| 276019           | Spoiler Electrical Rig (Right Outboard) - Functional Check     |               | HRS |             | 663.7           |     |                  | 2382.4   |                    |         | 0            |
|                  |                                                                |               | AFL |             | 291             |     | 826              |          | 0                  |         |              |
|                  |                                                                |               | MOS |             | 24.9            |     | 13 Apr 2024      |          |                    |         |              |
|                  |                                                                |               | MSC |             |                 | O/C |                  |          |                    |         |              |
| Airframe         |                                                                |               |     |             |                 |     |                  |          |                    |         |              |

| ATA<br>U=Custom  | Description                                                                      |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                      | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                               | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                           |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                                    |               |     |             |                 |     |                  |             |                    |         |              |
| 276020           | Spoiler (Left Inboard) - Functional Test                                         |               | HRS |             | 536.8           |     |                  | 2509.3      |                    |         | 0            |
|                  |                                                                                  |               | AFL |             | 206             |     |                  | 911         |                    |         | 0            |
|                  |                                                                                  |               | MOS |             | 15.8            |     |                  | 16 Jan 2025 |                    |         |              |
|                  |                                                                                  |               | MSC |             |                 |     |                  | O/C         |                    |         |              |
| Airframe         |                                                                                  |               |     |             |                 |     |                  |             |                    |         |              |
| 276021           | Spoiler (Right Inboard) - Functional Test                                        |               | HRS |             | 2345.1          |     |                  | 701         |                    |         | 0            |
|                  |                                                                                  |               | AFL |             | 936             |     |                  | 181         |                    |         | 0            |
|                  |                                                                                  |               | MOS |             | 96.6            |     |                  | 23 Apr 2018 |                    |         |              |
|                  |                                                                                  |               | MSC |             |                 |     |                  | O/C         |                    |         |              |
| Airframe         |                                                                                  |               |     |             |                 |     |                  |             |                    |         |              |
| 276022           | Spoiler (Left Midboard) - Functional Test                                        |               | HRS |             | 2345.1          |     |                  | 701         |                    |         | 0            |
|                  |                                                                                  |               | AFL |             | 936             |     |                  | 181         |                    |         | 0            |
|                  |                                                                                  |               | MOS |             | 96.6            |     |                  | 24 Apr 2018 |                    |         |              |
|                  |                                                                                  |               | MSC |             |                 |     |                  | O/C         |                    |         |              |
| Airframe         |                                                                                  |               |     |             |                 |     |                  |             |                    |         |              |
| 276023           | Spoiler (Right Midboard) - Functional Test                                       |               | HRS |             | 2345.1          |     |                  | 701         |                    |         | 0            |
|                  |                                                                                  |               | AFL |             | 936             |     |                  | 181         |                    |         | 0            |
|                  |                                                                                  |               | MOS |             | 96.6            |     |                  | 23 Apr 2018 |                    |         |              |
|                  |                                                                                  |               | MSC |             |                 |     |                  | O/C         |                    |         |              |
| Airframe         |                                                                                  |               |     |             |                 |     |                  |             |                    |         |              |
| 276024           | Spoiler (Left Outboard) - Functional Test                                        |               | HRS |             | 663.7           |     |                  | 2382.4      |                    |         | 0            |
|                  |                                                                                  |               | AFL |             | 291             |     |                  | 826         |                    |         | 0            |
|                  |                                                                                  |               | MOS |             | 24.9            |     |                  | 13 Apr 2024 |                    |         |              |
|                  |                                                                                  |               | MSC |             |                 |     |                  | O/C         |                    |         |              |
| Airframe         |                                                                                  |               |     |             |                 |     |                  |             |                    |         |              |
| 276025           | Spoiler (Right Outboard) - Functional Test                                       |               | HRS |             | 663.7           |     |                  | 2382.4      |                    |         | 0            |
|                  |                                                                                  |               | AFL |             | 291             |     |                  | 826         |                    |         | 0            |
|                  |                                                                                  |               | MOS |             | 24.9            |     |                  | 13 Apr 2024 |                    |         |              |
|                  |                                                                                  |               | MSC |             |                 |     |                  | O/C         |                    |         |              |
| Airframe         |                                                                                  |               |     |             |                 |     |                  |             |                    |         |              |
| 276100           | Speed Brake Control Module - Removal / Installation<br>60P2761100Z006251348      |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                  |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                  |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                  |               | MSC |             |                 |     |                  | O/C         |                    |         |              |
| Airframe         |                                                                                  |               |     |             |                 |     |                  |             |                    |         |              |
| 276148           | Inboard Spoiler (Left Ground) - Removal / Installation<br>60P5771001A015-01A0188 |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                  |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                  |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                  |               | MSC |             |                 |     |                  | O/C         |                    |         |              |
| Airframe         |                                                                                  |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                       |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                       | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                            |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| 276149           | Inboard Spoiler (Right Ground) - Removal / Installation           |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P5771002A009-02A                                                |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 0175                                                              |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                          |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 276150           | Midboard Spoiler (Left Inboard Flight) - Removal / Installation   |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P5772001A011-01A                                                |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 0188                                                              |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                          |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 276151           | Midboard Spoiler (Right Inboard Flight) - Removal / Installation  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P5772002A009-02A                                                |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 0188                                                              |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                          |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 276152           | Outboard Spoiler (Left Outboard Flight) - Removal / Installation  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P5773001A015-01A                                                |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 0188                                                              |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                          |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 276153           | Outboard Spoiler (Right Outboard Flight) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P5773002A009-02A                                                |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 0188                                                              |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                          |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 276154           | Fitting, Outboard Spoiler - Hinge, Outboard (Left)                |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | PN                                                                | SN-UNKNOWN    | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                   |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                          |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 276155           | Fitting, Outboard Spoiler - Hinge, Inboard (Left)                 |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | PN                                                                | SN-UNKNOWN    | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                   |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                          |               | MSC |             |                 |     | O/C              |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                     |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|---------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                     | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                              | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                          |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                                   |               |     |             |                 |     |                  |             |                    |         |              |
| 276156           | Fitting, Outboard Spoiler - Hinge, Outboard (Right)                             |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P5773224M001                                                                  | SN-UNKNOWN    | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                 |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 276157           | Fitting, Outboard Spoiler - Hinge, Inboard (Right)                              |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P5773222M002                                                                  | SN-UNKNOWN    | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                 |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 276225           | Inboard (Ground) Spoiler Link (Left Inboard) - Removal / Installation           |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P5771259A001                                                                  | SN-UNKNOWN    | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                 |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 276226           | Inboard (Ground) Spoiler Link (Right Inboard) - Removal / Installation          |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P5771259A001                                                                  | SN-UNKNOWN    | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                 |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 276227           | Inboard (Ground) Spoiler Link (Left Outboard) - Removal / Installation          |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P5772289A001                                                                  | SN-UNKNOWN    | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                 |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 276228           | Inboard (Ground) Spoiler Link (Right Outboard) - Removal / Installation         |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P5771259A001                                                                  | SN-UNKNOWN    | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                 |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 276300           | Outboard (Outboard Flight) Spoiler Link (Left Inboard) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P5773259A001                                                                  | SN-UNKNOWN    | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                 |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                       |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-----------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                       | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                                | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                            |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| 276301           | Outboard (Outboard Flight) Spoiler Link (Right Inboard) - Removal / Installation  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                   |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P5773259A001                                                                    | SN-UNKNOWN    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                   |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                   |               |     |             |                 |     |                  |             |                    |         |              |
| 276302           | Outboard (Outboard Flight) Spoiler Link (Left Outboard) - Removal / Installation  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                   |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P5773289A001                                                                    | SN-UNKNOWN    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                   |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                   |               |     |             |                 |     |                  |             |                    |         |              |
| 276303           | Outboard (Outboard Flight) Spoiler Link (Right Outboard) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                   |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P5773289A001                                                                    | SN-UNKNOWN    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                   |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                   |               |     |             |                 |     |                  |             |                    |         |              |
| 276305           | Midboard (Inboard Flight) Spoiler Link (Left Inboard) - Removal / Installation    |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                   |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P577289A001                                                                     | SN-UNKNOWN    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                   |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                   |               |     |             |                 |     |                  |             |                    |         |              |
| 276306           | Midboard (Inboard Flight) Spoiler Link (Right Inboard) - Removal / Installation   |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                   |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P5771259A001                                                                    | SN-UNKNOWN    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                   |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                   |               |     |             |                 |     |                  |             |                    |         |              |
| 276307           | Midboard (Inboard Flight) Spoiler Link (Left Outboard) - Removal / Installation   |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                   |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P5772289A001                                                                    | SN-UNKNOWN    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                   |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                   |               |     |             |                 |     |                  |             |                    |         |              |
| 276308           | Midboard (Inboard Flight) Spoiler Link (Right Outboard) - Removal / Installation  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                   |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P5771259A001                                                                    | SN-UNKNOWN    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                   |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                   |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                        |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                        | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                 | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                             |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                      |               |     |             |                 |     |                  |             |                    |         |              |
| 276326           | Spoiler Ha Manifold (Left Outboard) - Removal /    |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | Installation                                       |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P2763101Z004                                     | 0385          | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                    |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                    |               |     |             |                 |     |                  |             |                    |         |              |
| 276327           | Spoiler Ha Manifold (Right Outboard) - Removal /   |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | Installation                                       |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P2763101Z004                                     | 0357          | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                    |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                    |               |     |             |                 |     |                  |             |                    |         |              |
| 276328           | Spoiler Ehsa Manifold (Left Inboard) - Removal /   |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | Installation                                       |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P2763201Z004                                     | 0707          | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                    |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                    |               |     |             |                 |     |                  |             |                    |         |              |
| 276329           | Spoiler Ehsa Manifold (Left Midboard) - Removal /  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | Installation                                       |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P2763201Z004                                     | 0716          | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                    |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                    |               |     |             |                 |     |                  |             |                    |         |              |
| 276330           | Spoiler Ehsa Manifold (Right Inboard) - Removal /  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | Installation                                       |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P2763201Z004                                     | 0710          | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                    |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                    |               |     |             |                 |     |                  |             |                    |         |              |
| 276331           | Spoiler Ehsa Manifold (Right Midboard) - Removal / |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | Installation                                       |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P2763201Z004                                     | 0709          | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                    |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                    |               |     |             |                 |     |                  |             |                    |         |              |
| 276333           | Spoiler Eb Manifold (Left Outboard) - Removal /    |               | HRS |             | 1452            |     |                  | 1594.1      |                    |         | 0            |
|                  | Installation                                       |               | AFL |             | 570             |     |                  | 547         |                    |         | 0            |
|                  | 60P2763301Z006                                     | 0293D         | MOS |             | 63.8            |     |                  | 17 Jan 2021 |                    |         |              |
|                  |                                                    |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                    |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                             |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-----------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                             | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                                      | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                                  |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| 276334           | Spoiler Eb Manifold (Right Outboard) - Removal / Installation                           |               | HRS |             | 1452            |     |                  | 1594.1      |                    |         | 0            |
|                  |                                                                                         |               | AFL |             | 570             |     |                  | 547         |                    |         | 0            |
|                  | 60P2763301Z006                                                                          | 0473D         | MOS |             | 63.9            |     |                  | 14 Jan 2021 |                    |         |              |
|                  |                                                                                         |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                         |               |     |             |                 |     |                  |             |                    |         |              |
| 276335           | Spoiler Motor Control Electronics (Left Outboard Eb Manifold) - Removal / Installation  |               | HRS |             | 663.7           |     |                  | 2382.4      |                    |         | 0            |
|                  |                                                                                         |               | AFL |             | 291             |     |                  | 826         |                    |         | 0            |
|                  | 60P2715003Z310                                                                          | 0763          | MOS |             | 24.9            |     |                  | 13 Apr 2024 |                    |         |              |
|                  |                                                                                         |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                         |               |     |             |                 |     |                  |             |                    |         |              |
| 276336           | Spoiler Motor Control Electronics (Right Outboard Eb Manifold) - Removal / Installation |               | HRS |             | 663.7           |     |                  | 2382.4      |                    |         | 0            |
|                  |                                                                                         |               | AFL |             | 291             |     |                  | 826         |                    |         | 0            |
|                  | 60P2715003Z312                                                                          | 4968          | MOS |             | 24.9            |     |                  | 13 Apr 2024 |                    |         |              |
|                  |                                                                                         |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                         |               |     |             |                 |     |                  |             |                    |         |              |
| 276337           | Inboard Spoiler (Ground) Ehsa Actuator (Left) - Removal / Installation                  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                         |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P2763001Z001                                                                          | 0740          | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                         |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                         |               |     |             |                 |     |                  |             |                    |         |              |
| 276338           | Inboard Spoiler (Ground) Ehsa Actuator (Right) - Removal / Installation                 |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                         |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P2763001Z001                                                                          | 0712          | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                         |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                         |               |     |             |                 |     |                  |             |                    |         |              |
| 276339           | Midboard Spoiler (Inboard Flight) Ehsa Actuator (Left) - Removal / Installation         |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                         |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P2763001Z001                                                                          | 0739          | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                         |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                         |               |     |             |                 |     |                  |             |                    |         |              |
| 276340           | Midboard Spoiler (Inboard Flight) Ehsa Actuator (Right) - Removal / Installation        |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                         |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P2763001Z001                                                                          | 0747          | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                         |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                         |               |     |             |                 |     |                  |             |                    |         |              |



| ATA<br>U=Custom             | Description                                                                             |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|-----------------------------|-----------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                             | Part Number                                                                             | Serial Number |     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position            | HW                                                                                      | SW            |     |             |                 |     |                  |             |                     |         | Manufacturer |
|                             | MM Ref                                                                                  |               |     |             |                 |     |                  |             |                     |         | Date Type    |
|                             | Ops Number(s)                                                                           |               |     |             |                 |     |                  |             |                     |         |              |
| 276341                      | Outboard Spoiler (Outboard Flight) Ebha Actuator (Left) - Removal / Installation        |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                             |                                                                                         |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                             | 60P2763002Z101                                                                          | 0331          | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                             |                                                                                         |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe                    |                                                                                         |               |     |             |                 |     |                  |             |                     |         |              |
| 276342                      | Outboard Spoiler (Outboard Flight) Ebha Actuator (Right) - Removal / Installation       |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                             |                                                                                         |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                             | 60P2763002Z201                                                                          | 0365          | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                             |                                                                                         |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe                    |                                                                                         |               |     |             |                 |     |                  |             |                     |         |              |
| 276508                      | Spoiler Remote Electronics Unit (Left Inboard Ehsa Manifold) - Removal / Installation   |               | HRS |             | 536.8           |     |                  | 2509.3      |                     |         | 0            |
|                             |                                                                                         |               | AFL |             | 206             |     |                  | 911         |                     |         | 0            |
|                             | 60P2715001Z007                                                                          | 5845          | MOS |             | 15.8            |     |                  | 16 Jan 2025 |                     |         |              |
|                             |                                                                                         |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe                    |                                                                                         |               |     |             |                 |     |                  |             |                     |         |              |
| 276509                      | Spoiler Remote Electronics Unit (Left Midboard Ehsa Manifold) - Removal / Installation  |               | HRS |             | 536.8           |     |                  | 2509.3      |                     |         | 0            |
|                             |                                                                                         |               | AFL |             | 206             |     |                  | 911         |                     |         | 0            |
|                             | 60P2715001Z006                                                                          | 4053          | MOS |             | 15.8            |     |                  | 16 Jan 2025 |                     |         |              |
|                             |                                                                                         |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe                    |                                                                                         |               |     |             |                 |     |                  |             |                     |         |              |
| 276510                      | Spoiler Remote Electronics Unit (Left Outboard Ha Manifold) - Removal / Installation    |               | HRS |             | 657.2           |     |                  | 2388.9      |                     |         | 0            |
|                             |                                                                                         |               | AFL |             | 287             |     |                  | 830         |                     |         | 0            |
|                             | 60P2715001Z007                                                                          | 4255          | MOS |             | 23              |     |                  | 10 Jun 2024 |                     |         |              |
|                             |                                                                                         |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe                    |                                                                                         |               |     |             |                 |     |                  |             |                     |         |              |
| Notes: REU MODIFIED ON WING |                                                                                         |               |     |             |                 |     |                  |             |                     |         |              |
| 276511                      | Spoiler Remote Electronics Unit (Right Inboard Ehsa Manifold) - Removal / Installation  |               | HRS |             | 657.2           |     |                  | 2388.9      |                     |         | 0            |
|                             |                                                                                         |               | AFL |             | 287             |     |                  | 830         |                     |         | 0            |
|                             | 60P2715001Z006                                                                          | 3454          | MOS |             | 23              |     |                  | 10 Jun 2024 |                     |         |              |
|                             |                                                                                         |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe                    |                                                                                         |               |     |             |                 |     |                  |             |                     |         |              |
| 276512                      | Spoiler Remote Electronics Unit (Right Midboard Ehsa Manifold) - Removal / Installation |               | HRS |             | 2345.1          |     |                  | 701         |                     |         | 0            |
|                             |                                                                                         |               | AFL |             | 936             |     |                  | 181         |                     |         | 0            |
|                             | 60P2715001Z006                                                                          | 4042          | MOS |             | 96.7            |     |                  | 20 Apr 2018 |                     |         |              |
|                             |                                                                                         |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe                    |                                                                                         |               |     |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom  | Description                                            |               | UOM            | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|--------------------------------------------------------|---------------|----------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                            | Serial Number |                |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                     | SW            |                |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                 |               |                |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                          |               |                |             |                 |     |                  |             |                    |         |              |
| 276513           | Spoiler Remote Electronics Unit (Right Outboard Ha     |               | HRS            |             | 2345.1          |     |                  | 701         |                    |         | 0            |
|                  | Manifold) - Removal / Installation                     |               | AFL            |             | 936             |     |                  | 181         |                    |         | 0            |
|                  | 60P2715001Z006                                         | 4048          | MOS            |             | 96.7            |     |                  | 20 Apr 2018 |                    |         |              |
|                  |                                                        | 34            | MSC            |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                        |               |                |             |                 |     |                  |             |                    |         |              |
| 28 - Fuel        |                                                        |               |                |             |                 |     |                  |             |                    |         |              |
| 280001           | APU Fuel System - Bleed                                |               | HRS            |             | 2120.8          |     |                  | 925.3       |                    |         | 0            |
|                  |                                                        |               | AFL            |             | 861             |     |                  | 256         |                    |         | 0            |
|                  |                                                        |               | MOS            |             | 85.9            |     |                  | 13 Mar 2019 |                    |         |              |
|                  | Airframe                                               |               | MSC            |             |                 |     | O/C              |             |                    |         |              |
|                  |                                                        |               |                |             |                 |     |                  |             |                    |         |              |
| 280002           | Fuel Tank Vapor Hazards - Reduction                    |               | HRS            |             | 663.7           |     |                  | 2382.4      |                    |         | 0            |
|                  |                                                        |               | AFL            |             | 291             |     |                  | 826         |                    |         | 0            |
|                  |                                                        |               | MOS            |             | 25              |     |                  | 12 Apr 2024 |                    |         |              |
|                  | Airframe                                               |               | MSC            |             |                 |     | O/C              |             |                    |         |              |
|                  |                                                        |               |                |             |                 |     |                  |             |                    |         |              |
| 280003           | Fuel Tank - Biocide Treatment                          |               | HRS            |             | 137             |     |                  | 2909.1      | 0                  |         | 0            |
|                  |                                                        |               | AFL            |             | 52              |     |                  | 1065        | 0                  |         | 0            |
|                  |                                                        |               | MOS            |             | 4.8             |     | 12               | 18 Dec 2025 |                    |         |              |
|                  | Airframe                                               |               | [MOS: +1m/-1m] |             |                 |     |                  |             |                    |         |              |
|                  |                                                        |               |                |             |                 |     |                  |             |                    |         |              |
| 280004           | Fuel System - Upstream (Tank) Side Bleed               |               | HRS            |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                        |               | AFL            |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                        |               | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                               |               | MSC            |             |                 |     | O/C              |             |                    |         |              |
|                  |                                                        |               |                |             |                 |     |                  |             |                    |         |              |
| 280005           | Fuel System - Engine Bleed                             |               | HRS            |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                        |               | AFL            |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                        |               | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                               |               | MSC            |             |                 |     | O/C              |             |                    |         |              |
|                  |                                                        |               |                |             |                 |     |                  |             |                    |         |              |
| 280006           | Complete Fuel System Bleed Procedure - Adjustment Test |               | HRS            |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                        |               | AFL            |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                        |               | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                               |               | MSC            |             |                 |     | O/C              |             |                    |         |              |
|                  |                                                        |               |                |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                    |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------|--------------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                  | Part Number                                                                    | Serial Number |                                    |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position | HW                                                                             | SW            |                                    |             |                 |     |                  |             |                    |             | Manufacturer |
|                  | MM Ref                                                                         |               |                                    |             |                 |     |                  |             |                    |             | Date Type    |
|                  | Ops Number(s)                                                                  |               |                                    |             |                 |     |                  |             |                    |             |              |
| 280007           | Microbiological Contamination Test of Fuel Tank - Special<br>Detail Inspection |               | HRS                                |             | -2              |     |                  | 3048.1      |                    |             | 0            |
|                  |                                                                                |               | AFL                                |             | -2              |     |                  | 1119        |                    |             | 0            |
|                  |                                                                                |               | MOS                                |             | .2              | -16 | 4                | 06 May 2026 | 31 Aug 2026*       | 30 Sep 2026 |              |
|                  |                                                                                |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                |               |                                    |             |                 |     |                  |             |                    |             |              |
| 280008           | Fuel Tank - Sumping                                                            |               | HRS                                |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                  |                                                                                |               | AFL                                |             | 52              |     |                  | 1065        |                    |             | 0            |
|                  |                                                                                |               | MOS                                |             | 5.4             |     |                  | 29 Nov 2025 |                    |             |              |
|                  |                                                                                |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                |               |                                    |             |                 |     |                  |             |                    |             |              |
| 281000           | Wing Center Line Rib Leak Test - Functional Check                              |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                |               |                                    |             |                 |     |                  |             |                    |             |              |
| 281001           | Fuel Tank (Left Wing) - Leak Check                                             |               | HRS                                |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                  |                                                                                |               | AFL                                |             | 52              |     |                  | 1065        |                    |             | 0            |
|                  |                                                                                |               | MOS                                |             | 5               |     |                  | 12 Dec 2025 |                    |             |              |
|                  |                                                                                |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                |               |                                    |             |                 |     |                  |             |                    |             |              |
| 281002           | Fuel Tank (Right Wing) - Leak Check                                            |               | HRS                                |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                  |                                                                                |               | AFL                                |             | 52              |     |                  | 1065        |                    |             | 0            |
|                  |                                                                                |               | MOS                                |             | 5               |     |                  | 12 Dec 2025 |                    |             |              |
|                  |                                                                                |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                |               |                                    |             |                 |     |                  |             |                    |             |              |
| 281003           | Fuel Tank (Left Hopper) - Leak Check                                           |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                |               |                                    |             |                 |     |                  |             |                    |             |              |
| 281004           | Fuel Tank (Right Hopper) - Leak Check                                          |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                |               |                                    |             |                 |     |                  |             |                    |             |              |
| 281005           | Fuel Tank Contamination (Left) - Cleaning                                      |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                |               |                                    |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom  | Description                                                                                   |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-----------------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                                   | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                                            | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                                        |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                                                 |               |     |             |                 |     |                  |             |                    |         |              |
| 281006           | Fuel Tank Contamination (Right) - Cleaning                                                    |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                               |               | AFL |             | 1117            |     |                  | 0           |                    | 0       |              |
|                  |                                                                                               |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                               |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                               |               |     |             |                 |     |                  |             |                    |         |              |
| 281200           | Fuel Hopper Check Valve (Left) - Leakage Check                                                |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                               |               | AFL |             | 1117            |     |                  | 0           |                    | 0       |              |
|                  |                                                                                               |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                               |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                               |               |     |             |                 |     |                  |             |                    |         |              |
| 281201           | Fuel Hopper Check Valve (Right) - Leakage Check                                               |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                               |               | AFL |             | 1117            |     |                  | 0           |                    | 0       |              |
|                  |                                                                                               |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                               |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                               |               |     |             |                 |     |                  |             |                    |         |              |
| 281300           | Overwing Gravity Fueling Adapter Assembly (Left) -<br>Removal / Installation<br>372890010386  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                               |               | AFL |             | 1117            |     |                  | 0           |                    | 0       |              |
|                  |                                                                                               |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                               |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                               |               |     |             |                 |     |                  |             |                    |         |              |
| 281301           | Overwing Gravity Fueling Adapter Assembly (Right) -<br>Removal / Installation<br>372890010356 |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                               |               | AFL |             | 1117            |     |                  | 0           |                    | 0       |              |
|                  |                                                                                               |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                               |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                               |               |     |             |                 |     |                  |             |                    |         |              |
| 281304           | Gravity Fueling Adapter Assembly (Left) - Inspection                                          |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                               |               | AFL |             | 1117            |     |                  | 0           |                    | 0       |              |
|                  |                                                                                               |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                               |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                               |               |     |             |                 |     |                  |             |                    |         |              |
| 281305           | Gravity Fueling Adapter Assembly (Right) - Inspection                                         |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                               |               | AFL |             | 1117            |     |                  | 0           |                    | 0       |              |
|                  |                                                                                               |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                               |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                               |               |     |             |                 |     |                  |             |                    |         |              |
| 281306           | Gravity Fueling Adapter Assembly (Left) - Repair                                              |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                               |               | AFL |             | 1117            |     |                  | 0           |                    | 0       |              |
|                  |                                                                                               |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                               |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                               |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                     |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-----------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                     | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                              | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                          |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                   |               |     |             |                 |     |                  |             |                    |         |              |
| 281307           | Gravity Fueling Adapter Assembly (Right) - Repair               |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                 |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                 |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 281308           | Left Gravity Fuel Filler CAP - Removal / Installation           |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 37299001                                                        | 495           | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                 |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 281309           | Right Gravity Fuel Filler CAP - Removal / Installation          |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 37299001                                                        | 494           | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                 |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 281400           | Fuel / Water Drain Valve (Left No. 1) - Removal / Installation  |               | HRS |             | 2345.1          |     |                  | 701         |                    |         | 0            |
|                  |                                                                 |               | AFL |             | 936             |     |                  | 181         |                    |         | 0            |
|                  | L83A13-633                                                      | J86815        | MOS | TSN:3       | 97.1            |     |                  | 09 Apr 2018 |                    |         |              |
|                  | Airframe                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 281401           | Fuel / Water Drain Valve (Left No. 2) - Removal / Installation  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                 |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | L83A13-633                                                      | J17168        | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 281402           | Fuel / Water Drain Valve (Left No. 3) - Removal / Installation  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                 |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | L83A13-633                                                      | J22994        | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 281403           | Fuel / Water Drain Valve (Right No. 1) - Removal / Installation |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  |                                                                 |               | AFL |             | 315             |     |                  | 802         |                    |         | 0            |
|                  | L83A13-633                                                      | N62639        | MOS | TSN:3       | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
|                  | Airframe                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                     |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-----------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                     | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                              | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                          |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                   |               |     |             |                 |     |                  |             |                    |         |              |
| 281404           | Fuel / Water Drain Valve (Right No. 2) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                 |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | L83A13-633                                                      | J24399        | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                 |               |     |             |                 |     |                  |             |                    |         |              |
| 281405           | Fuel / Water Drain Valve (Right No. 3) - Removal / Installation |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  |                                                                 |               | AFL |             | 315             |     |                  | 802         |                    |         | 0            |
|                  | L83A13-633                                                      | N62626        | MOS | TSN:3       | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
|                  |                                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                 |               |     |             |                 |     |                  |             |                    |         |              |
| 281413           | Defuel Valve - Removal / Installation                           |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 775C-80NW                                                       | 5177          | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                 |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                 |               |     |             |                 |     |                  |             |                    |         |              |
| 281420           | Fuel / Water Drain Valve - Operational Test                     |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  |                                                                 |               | AFL |             | 315             |     |                  | 802         |                    |         | 0            |
|                  |                                                                 |               | MOS |             | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
|                  |                                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                 |               |     |             |                 |     |                  |             |                    |         |              |
| 281421           | Fuel / Water Drain Valve - Repair                               |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                 |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                 |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                 |               |     |             |                 |     |                  |             |                    |         |              |
| 281511           | Inboard Vent Float Valve (Left) - Removal / Installation        |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | L87-31-603                                                      | G47898        | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                 |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                 |               |     |             |                 |     |                  |             |                    |         |              |
| 281512           | Outboard Vent Float Valve (Left) - Removal / Installation       |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | L87-31-604                                                      | H72614        | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                 |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                 |               |     |             |                 |     |                  |             |                    |         |              |
| 281513           | Inboard Vent Float Valve (Right) - Removal / Installation       |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | L87-31-603                                                      | H66888        | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                 |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                 |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                    |               | UOM                                               | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------|--------------------------------------------------------------------------------|---------------|---------------------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                  | Part Number                                                                    | Serial Number |                                                   |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position | HW                                                                             | SW            |                                                   |             |                 |     |                  |             |                    |             | Manufacturer |
|                  | MM Ref                                                                         |               |                                                   |             |                 |     |                  |             |                    |             | Date Type    |
|                  | Ops Number(s)                                                                  |               |                                                   |             |                 |     |                  |             |                    |             |              |
| 281514           | Outboard Vent Float Valve (Right) - Removal / Installation<br>L87-31-604H72605 |               | HRS                                               |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                |               | AFL                                               |             | 1117            |     |                  | 0           |                    | 0           |              |
|                  |                                                                                |               | MOS                                               |             | 128.6           |     | 24 Aug 2015      |             |                    |             |              |
|                  |                                                                                |               | MSC                                               |             |                 | O/C |                  |             |                    |             |              |
| 281521           | Overboard Vent / Ram AIR Inlet (Left) - Inspection                             |               | HRS                                               |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                |               | AFL                                               |             | 1117            |     |                  | 0           |                    | 0           |              |
|                  |                                                                                |               | MOS                                               |             | 128.6           |     | 24 Aug 2015      |             |                    |             |              |
|                  |                                                                                |               | MSC                                               |             |                 | O/C |                  |             |                    |             |              |
| 281522           | Overboard Vent / Ram AIR Inlet (Right) - Inspection                            |               | HRS                                               |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                |               | AFL                                               |             | 1117            |     |                  | 0           |                    | 0           |              |
|                  |                                                                                |               | MOS                                               |             | 128.6           |     | 24 Aug 2015      |             |                    |             |              |
|                  |                                                                                |               | MSC                                               |             |                 | O/C |                  |             |                    |             |              |
| 281524           | Pressure Relief Valve (Left) - Removal / Installation<br>L97-63-613J29476      |               | HRS                                               |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                |               | AFL                                               |             | 1117            |     |                  | 0           |                    | 0           |              |
|                  |                                                                                |               | MOS                                               |             | 128.6           |     | 24 Aug 2015      |             |                    |             |              |
|                  |                                                                                |               | MSC                                               |             |                 | O/C |                  |             |                    |             |              |
| 281525           | Pressure Relief Valve (Right) - Removal / Installation<br>L97-63-613J29088     |               | HRS                                               |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                |               | AFL                                               |             | 1117            |     |                  | 0           |                    | 0           |              |
|                  |                                                                                |               | MOS                                               |             | 128.6           |     | 24 Aug 2015      |             |                    |             |              |
|                  |                                                                                |               | MSC                                               |             |                 | O/C |                  |             |                    |             |              |
| 281528           | Wing Vent Float Valve (Left) - Operational Check                               |               | HRS                                               |             | 730.5           |     | 4800             | 2315.6      | 7115.6             | 7165.6      | 0            |
|                  |                                                                                |               | AFL                                               |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                                |               | MOS                                               |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031        | 31 Jan 2032 |              |
|                  |                                                                                |               | [End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50] |             |                 |     |                  |             |                    |             |              |
| 281529           | Wing Vent Float Valve (Right) - Operational Check                              |               | HRS                                               |             | 730.5           |     | 4800             | 2315.6      | 7115.6             | 7165.6      | 0            |
|                  |                                                                                |               | AFL                                               |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                                |               | MOS                                               |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031        | 31 Jan 2032 |              |
|                  |                                                                                |               | [End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50] |             |                 |     |                  |             |                    |             |              |
| 281530           | Fuel Vent System (Left) - Operational Check                                    |               | HRS                                               |             | 137             |     | 600              | 2909.1      | 3509.1             | 3559.1      | 0            |
|                  |                                                                                |               | AFL                                               |             | 52              |     |                  | 1065        |                    |             | 0            |
|                  |                                                                                |               | MOS                                               |             | 5               |     |                  | 12 Dec 2025 |                    |             |              |
|                  |                                                                                |               | [HRS: +50/-50]                                    |             |                 |     |                  |             |                    |             |              |
| Airframe         | 052001                                                                         |               |                                                   |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom  | Description                                                         |               | UOM                                               | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|---------------------------------------------------------------------|---------------|---------------------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                         | Serial Number |                                                   |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                  | SW            |                                                   |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                              |               |                                                   |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                       |               |                                                   |             |                 |     |                  |             |                    |         |              |
| 281531           | Fuel Vent System (Right) - Operational Check                        |               | HRS                                               |             | 137             |     | 600              | 2909.1      | 3509.1             |         | 0            |
|                  |                                                                     |               | AFL                                               |             | 52              |     | 1065             |             | 0                  |         |              |
|                  |                                                                     |               | MOS                                               |             | 5               |     | 12 Dec 2025      |             |                    |         |              |
|                  | Airframe                                                            |               | [HRS: -50]                                        |             |                 |     |                  |             |                    |         |              |
|                  |                                                                     | 052001        |                                                   |             |                 |     |                  |             |                    |         |              |
| 281532           | Flame Arrestor (Left) - Detailed Inspection                         |               | HRS                                               |             | 730.5           |     | 4800             | 2315.6      | 7115.6             | 7165.6  | 0            |
|                  |                                                                     |               | AFL                                               |             | 315             |     | 802              |             | 0                  |         |              |
|                  |                                                                     |               | MOS                                               |             | 28.7            | 96  | 21 Dec 2023      | 31 Dec 2031 | 31 Jan 2032        |         |              |
|                  | Airframe                                                            |               | [End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50] |             |                 |     |                  |             |                    |         |              |
| 281533           | Flame Arrestor (Right) - Detailed Inspection                        |               | HRS                                               |             | 730.5           |     | 4800             | 2315.6      | 7115.6             | 7165.6  | 0            |
|                  |                                                                     |               | AFL                                               |             | 315             |     | 802              |             | 0                  |         |              |
|                  |                                                                     |               | MOS                                               |             | 28.7            | 96  | 21 Dec 2023      | 31 Dec 2031 | 31 Jan 2032        |         |              |
|                  | Airframe                                                            |               | [End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50] |             |                 |     |                  |             |                    |         |              |
| 281534           | Flame Arrestor (Left) - Removal / Installation<br>130-0510-03R0346  |               | HRS                                               | TSN:2365.5  | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  |                                                                     |               | AFL                                               | TSN:823     | 315             |     | 802              |             | 0                  |         |              |
|                  |                                                                     |               | MOS                                               |             | 28.7            |     | 21 Dec 2023      |             |                    |         |              |
|                  | Airframe                                                            |               | MSC                                               |             |                 |     | O/C              |             |                    |         |              |
| 281535           | Flame Arrestor (Right) - Removal / Installation<br>130-0510-03R0275 |               | HRS                                               | TSN:1227.4  | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  |                                                                     |               | AFL                                               | TSN:520     | 315             |     | 802              |             | 0                  |         |              |
|                  |                                                                     |               | MOS                                               |             | 28.7            |     | 21 Dec 2023      |             |                    |         |              |
|                  | Airframe                                                            |               | MSC                                               |             |                 |     | O/C              |             |                    |         |              |
| 281537           | Flame Arrestor (Left) - Operational Check                           |               | HRS                                               |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  |                                                                     |               | AFL                                               |             | 315             |     | 802              |             | 0                  |         |              |
|                  |                                                                     |               | MOS                                               |             | 28.7            | 96  | 21 Dec 2023      | 21 Dec 2031 | 21 Jan 2032        |         |              |
|                  | Airframe                                                            |               | [MOS: +1m/-1m]                                    |             |                 |     |                  |             |                    |         |              |
|                  |                                                                     | 052016        |                                                   |             |                 |     |                  |             |                    |         |              |
| 281538           | Flame Arrestor (Right) - Operational Check                          |               | HRS                                               |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  |                                                                     |               | AFL                                               |             | 315             |     | 802              |             | 0                  |         |              |
|                  |                                                                     |               | MOS                                               |             | 28.7            | 96  | 21 Dec 2023      | 21 Dec 2031 | 21 Jan 2032        |         |              |
|                  | Airframe                                                            |               | [MOS: +1m/-1m]                                    |             |                 |     |                  |             |                    |         |              |
|                  |                                                                     | 052016        |                                                   |             |                 |     |                  |             |                    |         |              |
| 281541           | Wing Tank Pressure Relief Valve (Left) - Operational<br>Check       |               | HRS                                               |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  |                                                                     |               | AFL                                               |             | 315             |     | 802              |             | 0                  |         |              |
|                  |                                                                     |               | MOS                                               |             | 28.7            | 96  | 21 Dec 2023      | 21 Dec 2031 | 21 Jan 2032        |         |              |
|                  | Airframe                                                            |               | [MOS: +1m/-1m]                                    |             |                 |     |                  |             |                    |         |              |
|                  |                                                                     | 052016        |                                                   |             |                 |     |                  |             |                    |         |              |



| ATA<br>U=Custom  | Description                                                                                  |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------|----------------------------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                  | Part Number                                                                                  | Serial Number |                                    |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position | HW                                                                                           | SW            |                                    |             |                 |     |                  |             |                    |             | Manufacturer |
|                  | MM Ref                                                                                       |               |                                    |             |                 |     |                  |             |                    |             | Date Type    |
|                  | Ops Number(s)                                                                                |               |                                    |             |                 |     |                  |             |                    |             |              |
| 281542           | Wing Tank Pressure Relief Valve (Right) - Operational Check                                  |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                                              |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                                              |               | MOS                                |             | 28.7            |     | 96               | 21 Dec 2023 | 21 Dec 2031        | 21 Jan 2032 |              |
|                  |                                                                                              |               | [MOS: +1m/-1m]                     |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                              | 052016        |                                    |             |                 |     |                  |             |                    |             |              |
| 281602           | Heated Fuel Return System Valve - Operational Check                                          |               | HRS                                |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                  |                                                                                              |               | AFL                                |             | 52              |     |                  | 1065        |                    |             | 0            |
|                  |                                                                                              |               | MOS                                |             | 5.5             | 24  | 24               | 27 Nov 2025 | 31 Dec 2027*       | 31 Jan 2028 |              |
|                  |                                                                                              |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                              | 052011        |                                    |             |                 |     |                  |             |                    |             |              |
| 281603           | Heated Fuel Return Shut-Off Valve (Left) - Removal / Installation<br>B97-13-608H74033        |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                              |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                              |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                              |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                              |               |                                    |             |                 |     |                  |             |                    |             |              |
| 281604           | Heated Fuel Return Shut-Off Valve Motor (Left) - Removal / Installation<br>D97C00-652G51173  |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                              |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                              |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                              |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                              |               |                                    |             |                 |     |                  |             |                    |             |              |
| 281605           | Heated Fuel Return Shut-Off Valve (Right) - Removal / Installation<br>B97-13-608H74034       |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                              |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                              |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                              |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                              |               |                                    |             |                 |     |                  |             |                    |             |              |
| 281606           | Heated Fuel Return Shut-Off Valve Motor (Right) - Removal / Installation<br>D97C00-652G51164 |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                              |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                              |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                              |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                              |               |                                    |             |                 |     |                  |             |                    |             |              |
| 281611           | Heated Fuel Return Check Valve (Left) - Removal / Installation<br>L96-13-002H71302           |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                              |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                              |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                              |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                              |               |                                    |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom  | Description                                                                                           |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------|-------------------------------------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                  | Part Number                                                                                           | Serial Number |                                    |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position | HW                                                                                                    | SW            |                                    |             |                 |     |                  |             |                    |             | Manufacturer |
|                  | MM Ref                                                                                                |               |                                    |             |                 |     |                  |             |                    |             | Date Type    |
|                  | Ops Number(s)                                                                                         |               |                                    |             |                 |     |                  |             |                    |             |              |
| 281612           | Heated Fuel Return Check Valve (Right) - Removal / Installation                                       |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                       |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  | L96-13-002                                                                                            | H71303        | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                                       |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                                       |               |                                    |             |                 |     |                  |             |                    |             |              |
| 281615           | Pylon Heated Fuel Return System (Hfrs) Shut-Off Valve FIRE Shield (Left) - General Visual Inspection  |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                                                       |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                                                       |               | MOS                                |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031        | 31 Jan 2032 |              |
|                  |                                                                                                       |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                                       |               |                                    |             |                 |     |                  |             |                    |             |              |
| 052016           |                                                                                                       |               |                                    |             |                 |     |                  |             |                    |             |              |
| 281616           | Pylon Heated Fuel Return System (Hfrs) Shut-Off Valve FIRE Shield (Right) - General Visual Inspection |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                                                       |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                                                       |               | MOS                                |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031        | 31 Jan 2032 |              |
|                  |                                                                                                       |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                                       |               |                                    |             |                 |     |                  |             |                    |             |              |
| 052016           |                                                                                                       |               |                                    |             |                 |     |                  |             |                    |             |              |
| 282100           | Pressure Fueling / Defueling Adapter - Removal / Installation                                         |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                       |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  | K97-63-615                                                                                            | J30773        | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                                       |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                                       |               |                                    |             |                 |     |                  |             |                    |             |              |
| 282101           | Defueling Suction Check Valve (Left) - Removal / Installation                                         |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                       |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  | L85H31-601                                                                                            | H70662        | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                                       |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                                       |               |                                    |             |                 |     |                  |             |                    |             |              |
| 282102           | Defueling Suction Check Valve (Right) - Removal / Installation                                        |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                       |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  | L85H31-601                                                                                            | H64170        | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                                       |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                                       |               |                                    |             |                 |     |                  |             |                    |             |              |
| 282103           | Double Flap Check Valve Refuel (Left) - Removal / Installation                                        |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                       |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  | L85E51-602                                                                                            | H71272        | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                                       |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                                       |               |                                    |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom  | Description                                                      |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                                      | Serial Number |     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                               | SW            |     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                           |               |     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                                    |               |     |             |                 |     |                  |             |                     |         |              |
| 282104           | Double Flap Check Valve Refuel (Right) - Removal / Installation  |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                  |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | L85E51-602                                                       | H62592        | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                  |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                  |               |     |             |                 |     |                  |             |                     |         |              |
| 282106           | Pressure Fueling - Operational Check                             |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                  |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  |                                                                  |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                  |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                  |               |     |             |                 |     |                  |             |                     |         |              |
| 282107           | Suction Defueling - Operational Check                            |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                  |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  |                                                                  |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                  |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                  |               |     |             |                 |     |                  |             |                     |         |              |
| 282108           | Pressure Fueling / Defueling Adapter - Inspection                |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                  |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  |                                                                  |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                  |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                  |               |     |             |                 |     |                  |             |                     |         |              |
| 282111           | Right Wing Pressure Refuel Non-Return Valve                      |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  | L96-31-602                                                       | H68893        | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  |                                                                  |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                  |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                  |               |     |             |                 |     |                  |             |                     |         |              |
| 282200           | Pressure Fueling Shut-Off Valve (Left) - Removal / Installation  |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                  |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | L94-51-602                                                       | H69814        | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                  |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                  |               |     |             |                 |     |                  |             |                     |         |              |
| 282201           | Pressure Fueling Shut-Off Valve (Right) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                  |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | L94-51-602                                                       | H69483        | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                  |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                  |               |     |             |                 |     |                  |             |                     |         |              |
| 282400           | Intertank Shut-Off Valve - Removal / Installation                |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                  |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | B97H51-610                                                       | H69884        | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                  |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                  |               |     |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom  | Description                                                               |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|---------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                               | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                        | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                    |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 282401           | Intertank Shut-Off Valve Motor - Removal / Installation                   |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | D97C00-652                                                                | G44058        | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                           |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 282402           | Cross-Flow Shut-Off Valve - Removal / Installation                        |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | B97-31-616                                                                | G44190        | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                           |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 282403           | Cross-Flow Shut-Off Valve Motor - Removal / Installation                  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | D97C00-652                                                                | G44052        | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                           |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 282408           | Fuel Cross-Flow / Intertank System - Operational Check                    |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                           |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                           |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 282409           | Cross-Flow Shut-Off Valve - Functional Check                              |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                           |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                           |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 282410           | Intertank Shut-Off Valve / Low Fuel Sensor - Functional Check             |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                           |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                           |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 282500           | Fuel Boost Pump Inlet Filter Screen (Left Main) - Removal / Installation  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P2820401S001                                                            | NSN           | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                           |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 282501           | Fuel Boost Pump Inlet Filter Screen (Right Main) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P2820405S001                                                            | NSN           | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                           |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                    |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|--------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                    | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                             | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                         |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                                  |               |     |             |                 |     |                  |             |                    |         |              |
| 282502           | Fuel Boost Pump Inlet Filter Screen (Left Alternate) - Removal / Installation  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P2820401S001                                                                 | NSN           | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| 282503           | Fuel Boost Pump Inlet Filter Screen (Right Alternate) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P2820401S001                                                                 | NSN           | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| 282516           | Fuel Boost Pump Inlet Filter Screen (Left Main) - Inspection                   |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| 282517           | Fuel Boost Pump Inlet Filter Screen (Left Alternate) - Inspection              |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| 282518           | Fuel Boost Pump Inlet Filter Screen (Right Main) - Inspection                  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| 282519           | Fuel Boost Pump Inlet Filter Screen (Right Alternate) - Inspection             |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| 282520           | Fuel Boost Pump Inlet Filter Screen (Left Main) - Cleaning                     |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                              |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                                                              | Serial Number |     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                                                       | SW            |     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                                                   |               |     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                                                            |               |     |             |                 |     |                  |             |                     |         |              |
| 282521           | Fuel Boost Pump Inlet Filter Screen (Left Alternate) -<br>Cleaning                       |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                                          |               | AFL |             | 1117            |     |                  | 0           |                     | 0       |              |
|                  |                                                                                          |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                                          |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                          |               |     |             |                 |     |                  |             |                     |         |              |
| 282522           | Fuel Boost Pump Inlet Filter Screen (Right Main) -<br>Cleaning                           |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                                          |               | AFL |             | 1117            |     |                  | 0           |                     | 0       |              |
|                  |                                                                                          |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                                          |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                          |               |     |             |                 |     |                  |             |                     |         |              |
| 282523           | Fuel Boost Pump Inlet Filter Screen (Right Alternate) -<br>Cleaning                      |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                                          |               | AFL |             | 1117            |     |                  | 0           |                     | 0       |              |
|                  |                                                                                          |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                                          |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                          |               |     |             |                 |     |                  |             |                     |         |              |
| 282600           | Engine Fuel Shut-Off Valve Motor (Left) - Removal /<br>Installation<br>D97C00-652G44042  |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                                          |               | AFL |             | 1117            |     |                  | 0           |                     | 0       |              |
|                  |                                                                                          |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                                          |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                          |               |     |             |                 |     |                  |             |                     |         |              |
| 282601           | Engine Fuel Shut-Off Valve Motor (Right) - Removal /<br>Installation<br>D97C00-652G41572 |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                                          |               | AFL |             | 1117            |     |                  | 0           |                     | 0       |              |
|                  |                                                                                          |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                                          |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                          |               |     |             |                 |     |                  |             |                     |         |              |
| 282602           | Engine Fuel Shut-Off Valve (Left) - Removal / Installation<br>B97-31-613G44638           |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                                          |               | AFL |             | 1117            |     |                  | 0           |                     | 0       |              |
|                  |                                                                                          |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                                          |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                          |               |     |             |                 |     |                  |             |                     |         |              |
| 282603           | Engine Fuel Shut-Off Valve (Right) - Removal / Installation<br>B97-31-613G47270          |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                                          |               | AFL |             | 1117            |     |                  | 0           |                     | 0       |              |
|                  |                                                                                          |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                                          |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                          |               |     |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom  | Description                                                    |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                    | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                             | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                         |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                  |               |     |             |                 |     |                  |             |                    |         |              |
| 282604           | Fuel Ejector Pump (Left) - Removal / Installation              |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | T99A38-607                                                     | G30400        | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                       |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 282605           | Fuel Ejector Pump (Right) - Removal / Installation             |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | T99A38-607                                                     | G44758        | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                       |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 282606           | Fuel Boost Pump (Left Main) - Removal / Installation           |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  | P99C31-616                                                     | G44546        | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  |                                                                |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         |              |
|                  | Airframe                                                       |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 282607           | Fuel Boost Pump (Right Main) - Removal / Installation          |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | P99C31-616                                                     | F96724        | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                       |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 282608           | Fuel Boost Pump (Left Alternate) - Removal / Installation      |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | P99C31-616                                                     | H10302        | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                       |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 282609           | Fuel Boost Pump (Right Alternate) - Removal / Installation     |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | P99C31-616                                                     | G39838        | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                       |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 282610           | Fuel Boost Pump Canister (Left Main) - Removal / Installation  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | C93R31-612                                                     | G39002        | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                       |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 282611           | Fuel Boost Pump Canister (Right Main) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | C93R31-613                                                     | G37986        | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                       |               | MSC |             |                 |     | O/C              |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                         |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------|---------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                  | Part Number                                                         | Serial Number |                                    |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position | HW                                                                  | SW            |                                    |             |                 |     |                  |             |                    |             | Manufacturer |
|                  | MM Ref                                                              |               |                                    |             |                 |     |                  |             |                    |             | Date Type    |
|                  | Ops Number(s)                                                       |               |                                    |             |                 |     |                  |             |                    |             |              |
| 282612           | Fuel Boost Pump Canister (Left Alternate) - Removal / Installation  |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                     |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  | C93R31-613                                                          | G38006        | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                     |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                     |               |                                    |             |                 |     |                  |             |                    |             |              |
| 282613           | Fuel Boost Pump Canister (Right Alternate) - Removal / Installation |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                     |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  | C93R31-613                                                          | G34203        | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                     |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                     |               |                                    |             |                 |     |                  |             |                    |             |              |
| 282614           | APU Fuel Shut-Off Valve - Removal / Installation                    |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  | B97-13-606                                                          |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  | G15477                                                              |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                     |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                     |               |                                    |             |                 |     |                  |             |                    |             |              |
| 282615           | APU Fuel Shut-Off Valve Motor - Removal / Installation              |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  | D97C00-652                                                          |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  | G40876                                                              |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                     |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                     |               |                                    |             |                 |     |                  |             |                    |             |              |
| 282632           | APU Fuel Shut-Off Valve - Operational Check                         |               | HRS                                |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                  |                                                                     |               | AFL                                |             | 52              |     |                  | 1065        |                    |             | 0            |
|                  |                                                                     |               | MOS                                |             | 5.3             | 44  | 24               | 02 Dec 2025 | 31 Jan 2028*       | 29 Feb 2028 |              |
|                  |                                                                     |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                     |               |                                    |             |                 |     |                  |             |                    |             |              |
| 052011           |                                                                     |               |                                    |             |                 |     |                  |             |                    |             |              |
| 282633           | Engine Fuel Shut-Off Valve (Left) - Operational Check               |               | HRS                                |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                  |                                                                     |               | AFL                                |             | 52              |     |                  | 1065        |                    |             | 0            |
|                  |                                                                     |               | MOS                                |             | 4.9             | 6   | 24               | 15 Dec 2025 | 31 Dec 2027*       | 31 Jan 2028 |              |
|                  |                                                                     |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                     |               |                                    |             |                 |     |                  |             |                    |             |              |
| 052011           |                                                                     |               |                                    |             |                 |     |                  |             |                    |             |              |
| 282634           | Engine Fuel Shut-Off Valve (Right) - Operational Check              |               | HRS                                |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                  |                                                                     |               | AFL                                |             | 52              |     |                  | 1065        |                    |             | 0            |
|                  |                                                                     |               | MOS                                |             | 4.9             | 6   | 24               | 15 Dec 2025 | 31 Dec 2027*       | 31 Jan 2028 |              |
|                  |                                                                     |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                     |               |                                    |             |                 |     |                  |             |                    |             |              |
| 052011           |                                                                     |               |                                    |             |                 |     |                  |             |                    |             |              |
| 282635           | Fuel Boost Pump Control System - Operational Check                  |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                     |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                     |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                     |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                     |               |                                    |             |                 |     |                  |             |                    |             |              |



| ATA<br>U=Custom  | Description                                                   |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|---------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                                   | Serial Number |                                    |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                            | SW            |                                    |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                        |               |                                    |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                                 |               |                                    |             |                 |     |                  |             |                     |         |              |
| 282636           | Fuel Boost Pump (Left Main) - Inspection                      |               | HRS                                |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                               |               | AFL                                |             | 1117            |     |                  | 0           |                     | 0       |              |
|                  |                                                               |               | MOS                                |             | 128.6           |     | 24 Aug 2015      |             |                     |         |              |
|                  |                                                               |               | MSC                                |             |                 | O/C |                  |             |                     |         |              |
| 282637           | Fuel Boost Pump (Left Alternate) - Inspection                 |               | HRS                                |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                               |               | AFL                                |             | 1117            |     |                  | 0           |                     | 0       |              |
|                  |                                                               |               | MOS                                |             | 128.6           |     | 24 Aug 2015      |             |                     |         |              |
|                  |                                                               |               | MSC                                |             |                 | O/C |                  |             |                     |         |              |
| 282638           | Fuel Boost Pump (Right Main) - Inspection                     |               | HRS                                |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                               |               | AFL                                |             | 1117            |     |                  | 0           |                     | 0       |              |
|                  |                                                               |               | MOS                                |             | 128.6           |     | 24 Aug 2015      |             |                     |         |              |
|                  |                                                               |               | MSC                                |             |                 | O/C |                  |             |                     |         |              |
| 282639           | Fuel Boost Pump (Right Alternate) - Inspection                |               | HRS                                |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                               |               | AFL                                |             | 1117            |     |                  | 0           |                     | 0       |              |
|                  |                                                               |               | MOS                                |             | 128.6           |     | 24 Aug 2015      |             |                     |         |              |
|                  |                                                               |               | MSC                                |             |                 | O/C |                  |             |                     |         |              |
| 282640           | Fuel Distribution System (Fuel Flow, Left) - Functional Test  |               | HRS                                |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                               |               | AFL                                |             | 1117            |     |                  | 0           |                     | 0       |              |
|                  |                                                               |               | MOS                                |             | 128.6           |     | 24 Aug 2015      |             |                     |         |              |
|                  |                                                               |               | MSC                                |             |                 | O/C |                  |             |                     |         |              |
| 282641           | Fuel Distribution System (Fuel Flow, Right) - Functional Test |               | HRS                                |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                               |               | AFL                                |             | 1117            |     |                  | 0           |                     | 0       |              |
|                  |                                                               |               | MOS                                |             | 128.6           |     | 24 Aug 2015      |             |                     |         |              |
|                  |                                                               |               | MSC                                |             |                 | O/C |                  |             |                     |         |              |
| 282642           | Dual Wall Fuel Line Shroud (Left Engine) - Functional Check   |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                     |         | 0            |
|                  |                                                               |               | AFL                                |             | 315             |     |                  | 802         |                     | 0       |              |
|                  |                                                               |               | MOS                                |             | 28.7            | 96  | 21 Dec 2023      | 31 Dec 2031 | 31 Jan 2032         |         |              |
|                  |                                                               |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                     |         |              |
| Airframe         | 052016                                                        |               |                                    |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom  | Description                                                                |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(* =Adj) | Max Due     | Avg Man Hrs  |
|------------------|----------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|----------------------|-------------|--------------|
|                  | Part Number                                                                | Serial Number |                                    |             |                 |     |                  |             |                      |             | Approx Price |
| Logbook Position | HW                                                                         | SW            |                                    |             |                 |     |                  |             |                      |             | Manufacturer |
|                  | MM Ref                                                                     |               |                                    |             |                 |     |                  |             |                      |             | Date Type    |
|                  | Ops Number(s)                                                              |               |                                    |             |                 |     |                  |             |                      |             |              |
| 282643           | Dual Wall Fuel Line Shroud (Right Engine) - Functional Check               |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                      |             | 0            |
|                  |                                                                            |               | AFL                                |             | 315             |     |                  | 802         |                      |             | 0            |
|                  |                                                                            |               | MOS                                |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031          | 31 Jan 2032 |              |
|                  |                                                                            |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                      |             |              |
| Airframe         |                                                                            | 052016        |                                    |             |                 |     |                  |             |                      |             |              |
| 282644           | Dual Wall Fuel Line Shroud (APU) - Functional Check                        |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                      |             | 0            |
|                  |                                                                            |               | AFL                                |             | 315             |     |                  | 802         |                      |             | 0            |
|                  |                                                                            |               | MOS                                |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031          | 31 Jan 2032 |              |
|                  |                                                                            |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                      |             |              |
| Airframe         |                                                                            | 052016        |                                    |             |                 |     |                  |             |                      |             |              |
| 282645           | Dual Wall Fuel Line Shroud (Left Engine Heated Return) - Functional Check  |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                      |             | 0            |
|                  |                                                                            |               | AFL                                |             | 315             |     |                  | 802         |                      |             | 0            |
|                  |                                                                            |               | MOS                                |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031          | 31 Jan 2032 |              |
|                  |                                                                            |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                      |             |              |
| Airframe         |                                                                            | 052016        |                                    |             |                 |     |                  |             |                      |             |              |
| 282646           | Dual Wall Fuel Line Shroud (Right Engine Heated Return) - Functional Check |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                      |             | 0            |
|                  |                                                                            |               | AFL                                |             | 315             |     |                  | 802         |                      |             | 0            |
|                  |                                                                            |               | MOS                                |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031          | 31 Jan 2032 |              |
|                  |                                                                            |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                      |             |              |
| Airframe         |                                                                            | 052016        |                                    |             |                 |     |                  |             |                      |             |              |
| 282647           | Dual Wall Fuel Line (Left Engine) - Inspection                             |               | HRS                                |             | 3046.1          |     |                  | 0           |                      |             | 0            |
|                  |                                                                            |               | AFL                                |             | 1117            |     |                  | 0           |                      |             | 0            |
|                  |                                                                            |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                      |             |              |
|                  |                                                                            |               | MSC                                |             |                 |     | O/C              |             |                      |             |              |
| Airframe         |                                                                            |               |                                    |             |                 |     |                  |             |                      |             |              |
| 282648           | Dual Wall Fuel Line (Right Engine) - Inspection                            |               | HRS                                |             | 3046.1          |     |                  | 0           |                      |             | 0            |
|                  |                                                                            |               | AFL                                |             | 1117            |     |                  | 0           |                      |             | 0            |
|                  |                                                                            |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                      |             |              |
|                  |                                                                            |               | MSC                                |             |                 |     | O/C              |             |                      |             |              |
| Airframe         |                                                                            |               |                                    |             |                 |     |                  |             |                      |             |              |
| 282649           | Dual Wall Fuel Line (APU) - Inspection                                     |               | HRS                                |             | 3046.1          |     |                  | 0           |                      |             | 0            |
|                  |                                                                            |               | AFL                                |             | 1117            |     |                  | 0           |                      |             | 0            |
|                  |                                                                            |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                      |             |              |
|                  |                                                                            |               | MSC                                |             |                 |     | O/C              |             |                      |             |              |
| Airframe         |                                                                            |               |                                    |             |                 |     |                  |             |                      |             |              |

| ATA<br>U=Custom                   | Description                                                                                                                       |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|-----------------------------------|-----------------------------------------------------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                   | Part Number                                                                                                                       | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position                  | HW                                                                                                                                | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                   | MM Ref                                                                                                                            |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                                   | Ops Number(s)                                                                                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| 282650                            | Dual Wall Fuel Line (Left Engine Heated Return) -<br>Inspection                                                                   |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                   |                                                                                                                                   |               | AFL |             | 1117            |     |                  | 0           |                    | 0       |              |
|                                   |                                                                                                                                   |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                   |                                                                                                                                   |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                          |                                                                                                                                   |               |     |             |                 |     |                  |             |                    |         |              |
| 282651                            | Dual Wall Fuel Line (Right Engine Heated Return) -<br>Inspection                                                                  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                   |                                                                                                                                   |               | AFL |             | 1117            |     |                  | 0           |                    | 0       |              |
|                                   |                                                                                                                                   |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                   |                                                                                                                                   |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                          |                                                                                                                                   |               |     |             |                 |     |                  |             |                    |         |              |
| 284100                            | Ground Service Control Panel - Removal / Installation<br>742400-1-1                      742400IN00283                            |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                   |                                                                                                                                   |               | AFL |             | 1117            |     |                  | 0           |                    | 0       |              |
|                                   |                                                                                                                                   |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                   |                                                                                                                                   |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                          |                                                                                                                                   |               |     |             |                 |     |                  |             |                    |         |              |
| 284102                            | Fuel Ground Service Control Panel - Operational Check                                                                             |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                   |                                                                                                                                   |               | AFL |             | 1117            |     |                  | 0           |                    | 0       |              |
|                                   |                                                                                                                                   |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                   |                                                                                                                                   |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                          |                                                                                                                                   |               |     |             |                 |     |                  |             |                    |         |              |
| 284103                            | Refueling Door Fuel High-Level Warning Light -<br>Operational Check                                                               |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                   |                                                                                                                                   |               | AFL |             | 1117            |     |                  | 0           |                    | 0       |              |
|                                   |                                                                                                                                   |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                   |                                                                                                                                   |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                          |                                                                                                                                   |               |     |             |                 |     |                  |             |                    |         |              |
| 284106                            | Refueling Door Fuel High-Level Warning Light Assembly -<br>Removal / Installation<br>20-3501-0001                      145061-7-1 |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                   |                                                                                                                                   |               | AFL |             | 1117            |     |                  | 0           |                    | 0       |              |
|                                   |                                                                                                                                   |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                   |                                                                                                                                   |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                          |                                                                                                                                   |               |     |             |                 |     |                  |             |                    |         |              |
| 284107                            | Fuel System Interface to Aircraft Systems - Operational<br>Check                                                                  |               | HRS |             | 663.7           |     |                  | 2382.4      |                    |         | 0            |
|                                   |                                                                                                                                   |               | AFL |             | 291             |     |                  | 826         |                    | 0       |              |
|                                   |                                                                                                                                   |               | MOS |             | 25              |     |                  | 12 Apr 2024 |                    |         |              |
|                                   |                                                                                                                                   |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                          |                                                                                                                                   |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: PN: 738740-1-1 SN: <NONE>. |                                                                                                                                   |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom                   | Description                                                                            |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(* =Adj) | Max Due | Avg Man Hrs  |
|-----------------------------------|----------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|----------|----------------------|---------|--------------|
|                                   | Part Number                                                                            | Serial Number |     |             |                 |     |                  |          |                      |         | Approx Price |
| Logbook Position                  | HW                                                                                     | SW            |     |             |                 |     |                  |          |                      |         | Manufacturer |
|                                   | MM Ref                                                                                 |               |     |             |                 |     |                  |          |                      |         | Date Type    |
|                                   | Ops Number(s)                                                                          |               |     |             |                 |     |                  |          |                      |         |              |
| 284108                            | Fuel Quantity Measuring / Indication System - Functional Check                         |               | HRS |             | 3046.1          |     |                  | 0        |                      |         | 0            |
|                                   |                                                                                        |               | AFL |             | 1117            |     |                  | 0        |                      | 0       |              |
|                                   |                                                                                        |               | MOS |             | 128.6           |     | 24 Aug 2015      |          |                      |         |              |
|                                   |                                                                                        |               | MSC |             |                 | O/C |                  |          |                      |         |              |
| Airframe                          |                                                                                        |               |     |             |                 |     |                  |          |                      |         |              |
| Notes: PN: 738740-1-1 SN: <NONE>. |                                                                                        |               |     |             |                 |     |                  |          |                      |         |              |
| 284109                            | Fuel Quantity Signal Conditioner High-Level Shutoff - Operational Check                |               | HRS |             | 3046.1          |     |                  | 0        |                      |         | 0            |
|                                   |                                                                                        |               | AFL |             | 1117            |     |                  | 0        |                      | 0       |              |
|                                   |                                                                                        |               | MOS |             | 128.6           |     | 24 Aug 2015      |          |                      |         |              |
|                                   |                                                                                        |               | MSC |             |                 | O/C |                  |          |                      |         |              |
| Airframe                          |                                                                                        |               |     |             |                 |     |                  |          |                      |         |              |
| Notes: PN: 738740-1-1 SN: <NONE>. |                                                                                        |               |     |             |                 |     |                  |          |                      |         |              |
| 284110                            | Fuel Quantity Signal Conditioner - Removal / Installation<br>738741-1-4738741IN00285   |               | HRS |             | 3046.1          |     |                  | 0        |                      |         | 0            |
|                                   |                                                                                        |               | AFL |             | 1117            |     |                  | 0        |                      | 0       |              |
|                                   |                                                                                        |               | MOS |             | 128.6           |     | 24 Aug 2015      |          |                      |         |              |
|                                   |                                                                                        |               | MSC |             |                 | O/C |                  |          |                      |         |              |
| Airframe                          |                                                                                        |               |     |             |                 |     |                  |          |                      |         |              |
| 284112                            | Fuel Quantity System - Capacitance Check                                               |               | HRS |             | 3046.1          |     |                  | 0        |                      |         | 0            |
|                                   |                                                                                        |               | AFL |             | 1117            |     |                  | 0        |                      | 0       |              |
|                                   |                                                                                        |               | MOS |             | 128.6           |     | 24 Aug 2015      |          |                      |         |              |
|                                   |                                                                                        |               | MSC |             |                 | O/C |                  |          |                      |         |              |
| Airframe                          |                                                                                        |               |     |             |                 |     |                  |          |                      |         |              |
| Notes: PN: 738740-1-1 SN: <NONE>. |                                                                                        |               |     |             |                 |     |                  |          |                      |         |              |
| 284113                            | Fuel Quantity Signal Conditioner - Power / Ground Diode Test                           |               | HRS |             | 3046.1          |     |                  | 0        |                      |         | 0            |
|                                   |                                                                                        |               | AFL |             | 1117            |     |                  | 0        |                      | 0       |              |
|                                   |                                                                                        |               | MOS |             | 128.6           |     | 24 Aug 2015      |          |                      |         |              |
|                                   |                                                                                        |               | MSC |             |                 | O/C |                  |          |                      |         |              |
| Airframe                          |                                                                                        |               |     |             |                 |     |                  |          |                      |         |              |
| Notes: PN: 738740-1-1 SN: <NONE>. |                                                                                        |               |     |             |                 |     |                  |          |                      |         |              |
| 284120                            | Fuel High-Level Sensor (Left Wing) - Removal / Installation<br>722863-1-0722863IN00523 |               | HRS |             | 3046.1          |     |                  | 0        |                      |         | 0            |
|                                   |                                                                                        |               | AFL |             | 1117            |     |                  | 0        |                      | 0       |              |
|                                   |                                                                                        |               | MOS |             | 128.6           |     | 24 Aug 2015      |          |                      |         |              |
|                                   |                                                                                        |               | MSC |             |                 | O/C |                  |          |                      |         |              |
| Airframe                          |                                                                                        |               |     |             |                 |     |                  |          |                      |         |              |

| ATA<br>U=Custom  | Description                                                                   |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                   | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                            | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                        |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                                 |               |     |             |                 |     |                  |             |                    |         |              |
| 284121           | Fuel High-Level Sensor (Right Wing) - Removal / Installation                  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                               |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 722863-1-0                                                                    | 722863IN00505 | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                               |               | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Airframe                                                                      |               |     |             |                 |     |                  |             |                    |         |              |
| 284124           | Fuel Tank Temperature Sensor (Left Wing) - Removal / Installation             |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                               |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 722872-1-0                                                                    | 722872IN00615 | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                               |               | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Airframe                                                                      |               |     |             |                 |     |                  |             |                    |         |              |
| 284125           | Fuel Tank Temperature Sensor (Right Wing) - Removal / Installation            |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                               |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 722872-1-0                                                                    | 722872IN00626 | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                               |               | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Airframe                                                                      |               |     |             |                 |     |                  |             |                    |         |              |
| 284130           | Remote Data Concentrator (Left Inboard, Channel A) - Removal / Installation   |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                               |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 738740-2-2                                                                    | 73881801664   | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                               |               | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Airframe                                                                      |               |     |             |                 |     |                  |             |                    |         |              |
| 284131           | Remote Data Concentrator (Right Inboard, Channel A) - Removal / Installation  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                               |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 738740-2-2                                                                    | 738818IN01672 | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                               |               | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Airframe                                                                      |               |     |             |                 |     |                  |             |                    |         |              |
| 284137           | Remote Data Concentrator (Left Outboard, Channel B) - Removal / Installation  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                               |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 738740-2-2                                                                    | 738818IN01692 | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                               |               | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Airframe                                                                      |               |     |             |                 |     |                  |             |                    |         |              |
| 284138           | Remote Data Concentrator (Right Outboard, Channel B) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                               |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 738740-2-2                                                                    | 73881801695   | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                               |               | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Airframe                                                                      |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                       |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|---------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                       | Serial Number |     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                | SW            |     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                            |               |     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                     |               |     |             |                 |     |                  |             |                     |         |              |
| 284150           | Fuel Quantity Probe No. 3 (Left Wing) - Removal / |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  | Installation                                      |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 746046-1-0                                        | 746046IN00522 | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                   |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                   |               |     |             |                 |     |                  |             |                     |         |              |
| 284151           | Fuel Quantity Probe No. 2 (Left Wing) - Removal / |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  | Installation                                      |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 746045-1-0                                        | 746045IN00517 | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                   |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                   |               |     |             |                 |     |                  |             |                     |         |              |
| 284152           | Fuel Quantity Probe No. 5 (Left Wing) - Removal / |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  | Installation                                      |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 746050-1-0                                        | 746050IN00544 | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                   |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                   |               |     |             |                 |     |                  |             |                     |         |              |
| 284153           | Fuel Quantity Probe No. 4 (Left Wing) - Removal / |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  | Installation                                      |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 746049-1-0                                        | 746049IN00561 | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                   |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                   |               |     |             |                 |     |                  |             |                     |         |              |
| 284154           | Fuel Quantity Probe No. 6 (Left Wing) - Removal / |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  | Installation                                      |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 746051-1-0                                        | 746051IN00518 | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                   |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                   |               |     |             |                 |     |                  |             |                     |         |              |
| 284155           | Fuel Quantity Probe No. 7 (Left Wing) - Removal / |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  | Installation                                      |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 746052-1-0                                        | 746052IN00532 | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                   |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                   |               |     |             |                 |     |                  |             |                     |         |              |
| 284156           | Fuel Quantity Probe No. 8 (Left Wing) - Removal / |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  | Installation                                      |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 746054-1-0                                        | 746054IN00510 | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                   |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                   |               |     |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom  | Description                                        |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                        | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                 | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                             |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                      |               |     |             |                 |     |                  |             |                    |         |              |
| 284157           | Fuel Quantity Probe No. 9 (Left Wing) - Removal /  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | Installation                                       |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 746053-1-0                                         | 746053IN00529 | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                    |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                    |               |     |             |                 |     |                  |             |                    |         |              |
| 284158           | Fuel Quantity Probe No. 10 (Left Wing) - Removal / |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | Installation                                       |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 746055-1-0                                         | 746055IN00545 | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                    |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                    |               |     |             |                 |     |                  |             |                    |         |              |
| 284159           | Fuel Quantity Probe No. 11 (Left Wing) - Removal / |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | Installation                                       |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 746056-1-0                                         | 746056IN00540 | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                    |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                    |               |     |             |                 |     |                  |             |                    |         |              |
| 284160           | Fuel Quantity Probe No. 13 (Left Wing) - Removal / |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | Installation                                       |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 746058-1-0                                         | 746058IN00535 | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                    |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                    |               |     |             |                 |     |                  |             |                    |         |              |
| 284161           | Fuel Quantity Probe No. 12 (Left Wing) - Removal / |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | Installation                                       |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 746057-1-0                                         | 746057IN00528 | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                    |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                    |               |     |             |                 |     |                  |             |                    |         |              |
| 284162           | Fuel Quantity Probe No. 14 (Left Wing) - Removal / |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | Installation                                       |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 746059-1-0                                         | 746059IN00523 | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                    |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                    |               |     |             |                 |     |                  |             |                    |         |              |
| 284163           | Fuel Quantity Probe No. 15 (Left Wing) - Removal / |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | Installation                                       |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 746047-1-0                                         | 746047IN00529 | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                    |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                    |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                    |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|--------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                    | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                             | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                         |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                                  |               |     |             |                 |     |                  |             |                    |         |              |
| 284164           | Double Gaging Fuel Quantity Probe No. 1 (Left Hopper) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 746048-1-0                                                                     | 746048IN00526 | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| 284165           | Fuel Characteristic Sensor (Left Wing) - Removal / Installation                |               | HRS |             | 663.7           |     |                  | 2382.4      |                    |         | 0            |
|                  |                                                                                |               | AFL |             | 291             |     |                  | 826         |                    |         | 0            |
|                  | 799493-1-0                                                                     | 799493IN01593 | MOS | TSN:2       | 25              |     |                  | 12 Apr 2024 |                    |         |              |
|                  |                                                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| 284166           | Fuel Quantity Probe No. 3 (Right Wing) - Removal / Installation                |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 746046-1-0                                                                     | 746046IN00514 | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| 284167           | Fuel Quantity Probe No. 2 (Right Wing) - Removal / Installation                |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 746045-1-0                                                                     | 746045IN00526 | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| 284168           | Fuel Quantity Probe No. 5 (Right Wing) - Removal / Installation                |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 746050-1-0                                                                     | 746050IN00528 | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| 284169           | Fuel Quantity Probe No. 4 (Right Wing) - Removal / Installation                |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 746049-1-0                                                                     | 746049IN00558 | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| 284170           | Fuel Quantity Probe No. 6 (Right Wing) - Removal / Installation                |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 746051-1-0                                                                     | 746051IN00506 | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                |               |     |             |                 |     |                  |             |                    |         |              |



| ATA<br>U=Custom  | Description                                                      |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                      | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                               | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                           |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                    |               |     |             |                 |     |                  |             |                    |         |              |
| 284171           | Fuel Quantity Probe No. 7 (Right Wing) - Removal / Installation  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                  |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 746052-1-0                                                       | 746052IN00520 | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                  |               |     |             |                 |     |                  |             |                    |         |              |
| 284172           | Fuel Quantity Probe No. 8 (Right Wing) - Removal / Installation  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                  |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 746053-1-0                                                       | 746053IN00492 | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                  |               |     |             |                 |     |                  |             |                    |         |              |
| 284173           | Fuel Quantity Probe No. 9 (Right Wing) - Removal / Installation  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                  |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 746054-1-0                                                       | 746054IN00529 | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                  |               |     |             |                 |     |                  |             |                    |         |              |
| 284174           | Fuel Quantity Probe No. 10 (Right Wing) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                  |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 746055-1-0                                                       | 746055IN00520 | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                  |               |     |             |                 |     |                  |             |                    |         |              |
| 284175           | Fuel Quantity Probe No. 11 (Right Wing) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                  |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 746056-1-0                                                       | 746056IN00518 | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                  |               |     |             |                 |     |                  |             |                    |         |              |
| 284176           | Fuel Quantity Probe No. 13 (Right Wing) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                  |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 746058-1-0                                                       | 746058IN00514 | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                  |               |     |             |                 |     |                  |             |                    |         |              |
| 284177           | Fuel Quantity Probe No. 12 (Right Wing) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                  |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 746057-1-0                                                       | 746057IN00527 | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                  |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                     |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|---------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                                                     | Serial Number |     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                                              | SW            |     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                                          |               |     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                                                   |               |     |             |                 |     |                  |             |                     |         |              |
| 284178           | Fuel Quantity Probe No. 14 (Right Wing) - Removal / Installation                |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                                 |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 746059-1-0                                                                      | 746059IN00517 | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                                 |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                 |               |     |             |                 |     |                  |             |                     |         |              |
| 284179           | Fuel Quantity Probe No. 15 (Right Wing) - Removal / Installation                |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                                 |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 746047-1-0                                                                      | 746047IN00497 | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                                 |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                 |               |     |             |                 |     |                  |             |                     |         |              |
| 284180           | Double Gaging Fuel Quantity Probe No. 1 (Right Hopper) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                                 |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 746048-1-0                                                                      | 746048IN00506 | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                                 |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                 |               |     |             |                 |     |                  |             |                     |         |              |
| 284181           | Fuel Characteristic Sensor (Right Wing) - Removal / Installation                |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                                 |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 799493-1-0                                                                      | 799493IN00488 | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                                 |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                 |               |     |             |                 |     |                  |             |                     |         |              |
| 289700           | Fqms Harness, Rdc A (Left) - Removal / Installation                             |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                                 |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 746060-4-0                                                                      | 746060IN00303 | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                                 |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                 |               |     |             |                 |     |                  |             |                     |         |              |
| 289701           | Fqms Harness, Rdc B (Left) - Removal / Installation                             |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                                 |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 746061-4-0                                                                      | 746061IN00303 | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                                 |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                 |               |     |             |                 |     |                  |             |                     |         |              |
| 289702           | Fqms Harness, Rdc A (Right) - Removal / Installation                            |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                                 |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 746073-3-0                                                                      | 746073IN00306 | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                                 |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                 |               |     |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom      | Description                                           |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|----------------------|-------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                      | Part Number                                           | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position     | HW                                                    | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                      | MM Ref                                                |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                      | Ops Number(s)                                         |               |     |             |                 |     |                  |             |                    |         |              |
| 289703               | Fqms Harness, Rdc B (Right) - Removal / Installation  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                      | 746074-3-0                                            | 746074IN00300 | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                      |                                                       |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                      | Airframe                                              |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 29 - Hydraulic Power |                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| 290001               | Engine-Driven Hydraulic Pump, Power Transfer Unit and |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                      | Auxiliary Pump Case Drain Filter (Left) - Check       |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                      |                                                       |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                      | Airframe                                              |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 290002               | Engine-Driven Hydraulic Pump, Power Transfer Unit and |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                      | Auxiliary Pump Case Drain Filter (Right) - Check      |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                      |                                                       |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                      | Airframe                                              |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 290003               | Hydraulic Fluid (Left) - Sampling / Analysis          |               | HRS |             | 2120.8          |     |                  | 925.3       |                    |         | 0            |
|                      |                                                       |               | AFL |             | 861             |     |                  | 256         |                    |         | 0            |
|                      |                                                       |               | MOS |             | 85.9            |     |                  | 13 Mar 2019 |                    |         |              |
|                      | Airframe                                              |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 290004               | Hydraulic Fluid (Right) - Sampling / Analysis         |               | HRS |             | 2120.8          |     |                  | 925.3       |                    |         | 0            |
|                      |                                                       |               | AFL |             | 861             |     |                  | 256         |                    |         | 0            |
|                      |                                                       |               | MOS |             | 85.9            |     |                  | 13 Mar 2019 |                    |         |              |
|                      | Airframe                                              |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 290005               | Hydraulic Fluid (Power Transfer Unit) - Sampling /    |               | HRS |             | 2120.8          |     |                  | 925.3       |                    |         | 0            |
|                      | Analysis                                              |               | AFL |             | 861             |     |                  | 256         |                    |         | 0            |
|                      |                                                       |               | MOS |             | 85.9            |     |                  | 13 Mar 2019 |                    |         |              |
|                      | Airframe                                              |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 290500               | Hydraulic Fluid Heat Exchanger (Left) - Removal /     |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                      | Installation                                          |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                      | 60P2910077Z002                                        | 0164          | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                      | Airframe                                              |               | MSC |             |                 |     | O/C              |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                             |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                             | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                      | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                  |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| 290501           | Hydraulic Fluid Heat Exchanger (Right) - Removal / Installation         |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                         |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P2910077Z001                                                          | 0224          | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                         |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                         |               |     |             |                 |     |                  |             |                    |         |              |
| 291000           | Left Hydraulic System - Functional Test                                 |               | HRS |             | 564.9           |     |                  | 2481.2      |                    |         | 0            |
|                  |                                                                         |               | AFL |             | 219             |     |                  | 898         |                    |         | 0            |
|                  |                                                                         |               | MOS |             | 17.7            |     |                  | 21 Nov 2024 |                    |         |              |
|                  |                                                                         |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                         |               |     |             |                 |     |                  |             |                    |         |              |
| 291001           | Right Hydraulic System - Functional Test                                |               | HRS |             | 1300.7          |     |                  | 1745.4      |                    |         | 0            |
|                  |                                                                         |               | AFL |             | 507             |     |                  | 610         |                    |         | 0            |
|                  |                                                                         |               | MOS |             | 51.3            |     |                  | 03 Feb 2022 |                    |         |              |
|                  |                                                                         |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                         |               |     |             |                 |     |                  |             |                    |         |              |
| 291002           | Hydraulic Systems - Functional Test                                     |               | HRS |             | 1300.7          |     |                  | 1745.4      |                    |         | 0            |
|                  |                                                                         |               | AFL |             | 507             |     |                  | 610         |                    |         | 0            |
|                  |                                                                         |               | MOS |             | 51.3            |     |                  | 03 Feb 2022 |                    |         |              |
|                  |                                                                         |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                         |               |     |             |                 |     |                  |             |                    |         |              |
| 291200           | Engine-Driven Hydraulic Pump (Left) - Removal / Installation            |               | HRS |             | 994.2           |     |                  | 2051.9      |                    |         | 0            |
|                  |                                                                         |               | AFL |             | 392             |     |                  | 725         |                    |         | 0            |
|                  | 60P2910001Z002                                                          | K0062         | MOS |             | 41.2            |     |                  | 05 Dec 2022 |                    |         |              |
|                  |                                                                         |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                         |               |     |             |                 |     |                  |             |                    |         |              |
| 291201           | Engine-Driven Hydraulic Pump (Right) - Removal / Installation           |               | HRS | TSN:2051.9  | 994.2           |     |                  | 2051.9      |                    |         | 0            |
|                  |                                                                         |               | AFL | TSN:725     | 392             |     |                  | 725         |                    |         | 0            |
|                  | 60P2910001Z002                                                          | K0330         | MOS | TSN:88      | 41.1            |     |                  | 09 Dec 2022 |                    |         |              |
|                  |                                                                         |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                         |               |     |             |                 |     |                  |             |                    |         |              |
| 291202           | Engine-Driven Hydraulic Pump Attenuator (Left) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                         |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P2910072Z001                                                          | 0389          | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                         |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                         |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                         | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                     |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                              |               |     |             |                 |     |                  |             |                    |         |              |
| 291203           | Engine-Driven Hydraulic Pump Attenuator (Right) - Removal / Installation   |               | HRS | TSN:2051.7  | 994.4           |     |                  | 2051.7      |                    |         | 0            |
|                  |                                                                            |               | AFL | TSN:725     | 392             |     |                  | 725         |                    |         | 0            |
|                  | 60P2910072Z001                                                             | 0400          | MOS | TSN:88      | 40.9            |     |                  | 15 Dec 2022 |                    |         |              |
|                  |                                                                            |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                            |               |     |             |                 |     |                  |             |                    |         |              |
| 291208           | Engine-Driven Hydraulic Pump (Left) - Case Drain Line Flushing             |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                            |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                            |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                            |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                            |               |     |             |                 |     |                  |             |                    |         |              |
| 291209           | Engine-Driven Hydraulic Pump (Right) - Case Drain Line Flushing            |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                            |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                            |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                            |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                            |               |     |             |                 |     |                  |             |                    |         |              |
| 291300           | Hydraulic System Relief / Unloading Valve (Left) - Removal / Installation  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                            |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P2910025Z002                                                             | 0402          | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                            |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                            |               |     |             |                 |     |                  |             |                    |         |              |
| 291301           | Hydraulic System Relief / Unloading Valve (Right) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                            |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P2910025Z002                                                             | 0379          | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                            |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                            |               |     |             |                 |     |                  |             |                    |         |              |
| 291400           | Left System Manifold - Removal / Installation                              |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                            |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P2911073Z002                                                             | H7119         | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                            |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                            |               |     |             |                 |     |                  |             |                    |         |              |
| 291401           | Right System Manifold - Removal / Installation                             |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                            |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P2912074Z001                                                             | H6603         | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                            |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                            |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                                         |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-----------------------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                                         | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                                                  | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                                              |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| 291416           | Left System Manifold Filter / Filter Bowl (Return) - Removal / Installation                         |               | HRS |             | 1300.7          |     |                  | 1745.4      |                    |         | 0            |
|                  |                                                                                                     |               | AFL |             | 507             |     |                  | 610         |                    |         | 0            |
|                  | 339913                                                                                              | NSN           | MOS |             | 51.6            |     |                  | 22 Jan 2022 |                    |         |              |
|                  |                                                                                                     |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| 291417           | Left System Manifold Filter / Filter Bowl (Engine-Driven Pump Pressure) - Removal / Installation    |               | HRS |             | 1300.7          |     |                  | 1745.4      |                    |         | 0            |
|                  |                                                                                                     |               | AFL |             | 507             |     |                  | 610         |                    |         | 0            |
|                  | 339913                                                                                              | NSN           | MOS |             | 51.6            |     |                  | 22 Jan 2022 |                    |         |              |
|                  |                                                                                                     |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| 291418           | Left System Manifold Filter / Filter Bowl (Engine-Driven Pump Case Drain) - Removal / Installation  |               | HRS |             | 1300.7          |     |                  | 1745.4      |                    |         | 0            |
|                  |                                                                                                     |               | AFL |             | 507             |     |                  | 610         |                    |         | 0            |
|                  | 339482                                                                                              | NSN           | MOS |             | 51.6            |     |                  | 22 Jan 2022 |                    |         |              |
|                  |                                                                                                     |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| 291419           | Left System Manifold Filter / Filter Bowl (Power Transfer Unit Case Drain) - Removal / Installation |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  |                                                                                                     |               | AFL |             | 315             |     |                  | 802         |                    |         | 0            |
|                  | 339482                                                                                              | NSN           | MOS | TSN:7       | 30.5            |     |                  | 27 Oct 2023 |                    |         |              |
|                  |                                                                                                     |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| 291420           | Left System Manifold Filter / Filter Bowl (Power Transfer Unit Pressure) - Removal / Installation   |               | HRS |             | 1300.7          |     |                  | 1745.4      |                    |         | 0            |
|                  |                                                                                                     |               | AFL |             | 507             |     |                  | 610         |                    |         | 0            |
|                  | 339474                                                                                              | NSN           | MOS |             | 51.6            |     |                  | 22 Jan 2022 |                    |         |              |
|                  |                                                                                                     |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| 291421           | Left System Manifold Filter / Filter Bowl (Auxiliary Pump Case Drain) - Removal / Installation      |               | HRS |             | 1300.7          |     |                  | 1745.4      |                    |         | 0            |
|                  |                                                                                                     |               | AFL |             | 507             |     |                  | 610         |                    |         | 0            |
|                  | 339482                                                                                              | NSN           | MOS |             | 51.6            |     |                  | 22 Jan 2022 |                    |         |              |
|                  |                                                                                                     |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| 291422           | Left System Manifold Filter Indicator (Ptu CD) - Removal / Installation                             |               | HRS |             | 1300.7          |     |                  | 1745.4      |                    |         | 0            |
|                  |                                                                                                     |               | AFL |             | 507             |     |                  | 610         |                    |         | 0            |
|                  | R021191-4                                                                                           | M22934        | MOS |             | 51.6            |     |                  | 22 Jan 2022 |                    |         |              |
|                  |                                                                                                     |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                                     |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                           |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|---------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                           | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                                    | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                                |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                                         |               |     |             |                 |     |                  |             |                    |         |              |
| 291423           | Left System Manifold Filter Indicator (Ptu PR) - Removal / Installation               |               | HRS |             | 1300.7          |     |                  | 1745.4      |                    |         | 0            |
|                  |                                                                                       |               | AFL |             | 507             |     |                  | 610         |                    |         | 0            |
|                  | R021192-6                                                                             | L13589        | MOS |             | 51.6            |     |                  | 22 Jan 2022 |                    |         |              |
|                  |                                                                                       |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| 291424           | Left System Manifold Filter Indicator (Aux CD) - Removal / Installation               |               | HRS |             | 1300.7          |     |                  | 1745.4      |                    |         | 0            |
|                  |                                                                                       |               | AFL |             | 507             |     |                  | 610         |                    |         | 0            |
|                  | R021191-5                                                                             | M22715        | MOS |             | 51.6            |     |                  | 22 Jan 2022 |                    |         |              |
|                  |                                                                                       |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| 291425           | Left System Manifold Filter Indicator (Return) - Removal / Installation               |               | HRS |             | 1300.7          |     |                  | 1745.4      |                    |         | 0            |
|                  |                                                                                       |               | AFL |             | 507             |     |                  | 610         |                    |         | 0            |
|                  | R021192-2                                                                             | M23223        | MOS |             | 51.6            |     |                  | 22 Jan 2022 |                    |         |              |
|                  |                                                                                       |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| 291426           | Left System Manifold Filter Indicator (Edp Case Drain) - Removal / Installation       |               | HRS |             | 1300.7          |     |                  | 1745.4      |                    |         | 0            |
|                  |                                                                                       |               | AFL |             | 507             |     |                  | 610         |                    |         | 0            |
|                  | R021191-3                                                                             | M22917        | MOS |             | 51.6            |     |                  | 22 Jan 2022 |                    |         |              |
|                  |                                                                                       |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| 291427           | Left System Manifold Intelligent Filter Indicator (Pressure) - Removal / Installation |               | HRS |             | 1300.7          |     |                  | 1745.4      |                    |         | 0            |
|                  |                                                                                       |               | AFL |             | 507             |     |                  | 610         |                    |         | 0            |
|                  | R021192-1                                                                             | M23913        | MOS |             | 51.6            |     |                  | 22 Jan 2022 |                    |         |              |
|                  |                                                                                       |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| 291429           | Left System Manifold Power Transfer Unit Bypass Restrictor - Removal / Installation   |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                       |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | VXLX0503100B                                                                          | SN-UNKNOWN    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                       |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| 291460           | Manifold Hydraulic Lines, Attachments and Wiring - Inspection                         |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                       |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                       |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                       |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                       |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                                         |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-----------------------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                                         | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                                                  | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                                              |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| 291461           | Left System Manifold - Cleaning                                                                     |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                     |               | AFL |             | 1117            |     |                  | 0           |                    | 0       |              |
|                  |                                                                                                     |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                                     |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| 291462           | Right System Manifold - Cleaning                                                                    |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                     |               | AFL |             | 1117            |     |                  | 0           |                    | 0       |              |
|                  |                                                                                                     |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                                     |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| 291465           | Left System Manifold Component - Leak Check                                                         |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                     |               | AFL |             | 1117            |     |                  | 0           |                    | 0       |              |
|                  |                                                                                                     |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                                     |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| 291466           | Right System Manifold Component - Leak Check                                                        |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                     |               | AFL |             | 1117            |     |                  | 0           |                    | 0       |              |
|                  |                                                                                                     |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                                     |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| 291467           | Hydraulic System Acoustical Filter (Left) - Removal /<br>Installation<br>1159H47440-1 PMS2230       |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                     |               | AFL |             | 1117            |     |                  | 0           |                    | 0       |              |
|                  |                                                                                                     |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                                     |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| 291468           | Hydraulic System Acoustical Filter (Right) - Removal /<br>Installation<br>1159H47440-1 PMS2245      |               | HRS | TSN:1867.2  | 1178.9          |     |                  | 1867.2      |                    |         | 0            |
|                  |                                                                                                     |               | AFL | TSN:630     | 487             |     |                  | 630         |                    | 0       |              |
|                  |                                                                                                     |               | MOS | TSN:81      | 48.2            |     |                  | 05 May 2022 |                    |         |              |
|                  |                                                                                                     |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| 291471           | Left System Manifold Fluid Sampling Valve (Return) -<br>Removal / Installation<br>239855 SN-UNKNOWN |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                     |               | AFL |             | 1117            |     |                  | 0           |                    | 0       |              |
|                  |                                                                                                     |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                                     |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                                     |               |     |             |                 |     |                  |             |                    |         |              |



| ATA<br>U=Custom  | Description                                                                                         |               | UOM            | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-----------------------------------------------------------------------------------------------------|---------------|----------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                                         | Serial Number |                |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                                                  | SW            |                |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                                              |               |                |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                                                       |               |                |             |                 |     |                  |             |                    |         |              |
| 291472           | Right System Manifold Fluid Sampling Valve (Return) - Removal / Installation                        |               | HRS            |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                     |               | AFL            |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 239855                                                                                              | SN-UNKNOWN    | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                                     |               | MSC            |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                                     |               |                |             |                 |     |                  |             |                    |         |              |
| 291475           | Left System Manifold Fluid Sampling Valve (Engine-Driven Pump Case Drain) - Removal / Installation  |               | HRS            |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                     |               | AFL            |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 239855                                                                                              | SN-UNKNOWN    | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                                     |               | MSC            |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                                     |               |                |             |                 |     |                  |             |                    |         |              |
| 291476           | Right System Manifold Fluid Sampling Valve (Engine-Driven Pump Case Drain) - Removal / Installation |               | HRS            |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                     |               | AFL            |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 239855                                                                                              | SN-UNKNOWN    | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                                     |               | MSC            |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                                     |               |                |             |                 |     |                  |             |                    |         |              |
| 291479           | Left System Manifold Fluid Sampling Valve (Power Transfer Unit Case Drain) - Removal / Installation |               | HRS            |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                     |               | AFL            |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 239855                                                                                              | SN-UNKNOWN    | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                                     |               | MSC            |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                                     |               |                |             |                 |     |                  |             |                    |         |              |
| 291481           | Left System Manifold Fluid Sampling Valve (Auxiliary Pump) - Removal / Installation                 |               | HRS            |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                     |               | AFL            |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 239855                                                                                              | SN-UNKNOWN    | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                                     |               | MSC            |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                                     |               |                |             |                 |     |                  |             |                    |         |              |
| 291487           | Left System Manifold Filter (Return) - Discard                                                      |               | HRS            |             | 1300.7          |     | 3600             | 1745.4      | 5345.4             | 5395.4  | 0            |
|                  | 339913                                                                                              | NSN           | AFL            |             | 507             |     |                  | 610         |                    |         | 0            |
|                  |                                                                                                     |               | MOS            |             | 51.6            |     |                  | 22 Jan 2022 |                    |         |              |
|                  |                                                                                                     |               | [HRS: +50/-50] |             |                 |     |                  |             |                    |         |              |
| Airframe         |                                                                                                     |               |                |             |                 |     |                  |             |                    |         |              |
| 291488           | Left System Manifold Filter (Engine-Driven Pump Pressure) - Discard                                 |               | HRS            |             | 1300.7          |     | 3600             | 1745.4      | 5345.4             | 5395.4  | 0            |
|                  |                                                                                                     |               | AFL            |             | 507             |     |                  | 610         |                    |         | 0            |
|                  | 339913                                                                                              | NSN           | MOS            |             | 51.6            |     |                  | 22 Jan 2022 |                    |         |              |
|                  |                                                                                                     |               | [HRS: +50/-50] |             |                 |     |                  |             |                    |         |              |
| Airframe         |                                                                                                     |               |                |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                  |               | UOM            | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------------------------------------------|---------------|----------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                  | Serial Number |                |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                           | SW            |                |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                       |               |                |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                                |               |                |             |                 |     |                  |             |                    |         |              |
| 291489           | Left System Manifold Filter (Engine-Driven Pump Case Drain) - Discard        |               | HRS            |             | 1300.7          |     | 3600             | 1745.4      | 5345.4             | 5395.4  | 0            |
|                  |                                                                              |               | AFL            |             | 507             |     |                  | 610         |                    |         | 0            |
|                  | 339482                                                                       | NSN           | MOS            |             | 51.6            |     |                  | 22 Jan 2022 |                    |         |              |
|                  |                                                                              |               | [HRS: +50/-50] |             |                 |     |                  |             |                    |         |              |
| Airframe         |                                                                              |               |                |             |                 |     |                  |             |                    |         |              |
| 291490           | Left System Manifold Filter (Power Transfer Unit Case Drain) - Discard       |               | HRS            |             | 1300.7          |     | 3600             | 1745.4      | 5345.4             | 5395.4  | 0            |
|                  |                                                                              |               | AFL            |             | 507             |     |                  | 610         |                    |         | 0            |
|                  | 339482                                                                       | NSN           | MOS            |             | 51.6            |     |                  | 22 Jan 2022 |                    |         |              |
|                  |                                                                              |               | [HRS: +50/-50] |             |                 |     |                  |             |                    |         |              |
| Airframe         |                                                                              |               |                |             |                 |     |                  |             |                    |         |              |
| 291491           | Left System Manifold Filter (Power Transfer Unit Pressure) - Discard         |               | HRS            |             | 1300.7          |     | 3600             | 1745.4      | 5345.4             | 5395.4  | 0            |
|                  |                                                                              |               | AFL            |             | 507             |     |                  | 610         |                    |         | 0            |
|                  | 339474                                                                       | NSN           | MOS            |             | 51.6            |     |                  | 22 Jan 2022 |                    |         |              |
|                  |                                                                              |               | [HRS: +50/-50] |             |                 |     |                  |             |                    |         |              |
| Airframe         |                                                                              |               |                |             |                 |     |                  |             |                    |         |              |
| 291492           | Left System Manifold Filter (Auxiliary Pump Case Drain) - Discard            |               | HRS            |             | 1300.7          |     | 3600             | 1745.4      | 5345.4             | 5395.4  | 0            |
|                  |                                                                              |               | AFL            |             | 507             |     |                  | 610         |                    |         | 0            |
|                  | 339482                                                                       | NSN           | MOS            |             | 51.6            |     |                  | 22 Jan 2022 |                    |         |              |
|                  |                                                                              |               | [HRS: +50/-50] |             |                 |     |                  |             |                    |         |              |
| Airframe         |                                                                              |               |                |             |                 |     |                  |             |                    |         |              |
| 291500           | Left Hydraulic System Service Line Shut-Off Valve - Removal / Installation   |               | HRS            |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                              |               | AFL            |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P2921023Z001                                                               | 0544          | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                              |               | MSC            |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                              |               |                |             |                 |     |                  |             |                    |         |              |
| 291501           | Right Hydraulic System Service Line Shut-Off Valve - Removal / Installation  |               | HRS            |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                              |               | AFL            |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P2921023Z001                                                               | 0549          | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                              |               | MSC            |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                              |               |                |             |                 |     |                  |             |                    |         |              |
| 291502           | Right System Manifold Filter / Filter Bowl (Return) - Removal / Installation |               | HRS            |             | 1300.7          |     |                  | 1745.4      |                    |         | 0            |
|                  |                                                                              |               | AFL            |             | 507             |     |                  | 610         |                    |         | 0            |
|                  | 339913                                                                       | NSN           | MOS            |             | 51.6            |     |                  | 22 Jan 2022 |                    |         |              |
|                  |                                                                              |               | MSC            |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                              |               |                |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom                | Description                                                                                        |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|--------------------------------|----------------------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                | Part Number                                                                                        | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position               | HW                                                                                                 | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                | MM Ref                                                                                             |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                                | Ops Number(s)                                                                                      |               |     |             |                 |     |                  |             |                    |         |              |
| 291503                         | Right System Manifold Filter / Filter Bowl (Engine-Driven Pump Pressure) - Removal / Installation  |               | HRS |             | 1300.7          |     |                  | 1745.4      |                    |         | 0            |
|                                |                                                                                                    |               | AFL |             | 507             |     |                  | 610         |                    |         | 0            |
|                                | 339913                                                                                             | NSN           | MOS |             | 51.6            |     |                  | 22 Jan 2022 |                    |         |              |
|                                |                                                                                                    |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                       |                                                                                                    |               |     |             |                 |     |                  |             |                    |         |              |
| 291504                         | Right System Manifold Filter/ Filter Bowl (Engine-Driven Pump Case Drain) - Removal / Installation |               | HRS |             | 1300.7          |     |                  | 1745.4      |                    |         | 0            |
|                                |                                                                                                    |               | AFL |             | 507             |     |                  | 610         |                    |         | 0            |
|                                | 339482                                                                                             | NSN           | MOS |             | 51.6            |     |                  | 22 Jan 2022 |                    |         |              |
|                                |                                                                                                    |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                       |                                                                                                    |               |     |             |                 |     |                  |             |                    |         |              |
| 291505                         | Right System Manifold Filter Indicator (Return) - Removal / Installation                           |               | HRS |             | 1300.7          |     |                  | 1745.4      |                    |         | 0            |
|                                |                                                                                                    |               | AFL |             | 507             |     |                  | 610         |                    |         | 0            |
|                                | R021192-2                                                                                          | M23222        | MOS |             | 51.6            |     |                  | 22 Jan 2022 |                    |         |              |
|                                |                                                                                                    |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                       |                                                                                                    |               |     |             |                 |     |                  |             |                    |         |              |
| 291506                         | Right System Manifold Filter Indicator (Edp Case Drain) - Removal / Installation                   |               | HRS |             | 1300.7          |     |                  | 1745.4      |                    |         | 0            |
|                                |                                                                                                    |               | AFL |             | 507             |     |                  | 610         |                    |         | 0            |
|                                | R021191-3                                                                                          | M22916        | MOS |             | 51.6            |     |                  | 22 Jan 2022 |                    |         |              |
|                                |                                                                                                    |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                       |                                                                                                    |               |     |             |                 |     |                  |             |                    |         |              |
| 291507                         | Right System Manifold Filter Indicator (Edp Pressure) - Removal / Installation                     |               | HRS |             | 1300.7          |     |                  | 1745.4      |                    |         | 0            |
|                                |                                                                                                    |               | AFL |             | 507             |     |                  | 610         |                    |         | 0            |
|                                | R021192-1                                                                                          | M23912        | MOS |             | 51.6            |     |                  | 22 Jan 2022 |                    |         |              |
|                                |                                                                                                    |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                       |                                                                                                    |               |     |             |                 |     |                  |             |                    |         |              |
| 291508                         | Left Hydraulic System Firewall Shut-Off Valve (FS 899) - Removal / Installation                    |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                                                                    |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                | 60P2910022Z005                                                                                     | 15-050541     | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                |                                                                                                    |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                       |                                                                                                    |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 291510 |                                                                                                    |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom                   | Description                                                                      |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W                             | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|-----------------------------------|----------------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|--------------------------------------|---------------------|---------|--------------|
|                                   | Part Number                                                                      | Serial Number |                                    |             |                 |     |                  |                                      |                     |         | Approx Price |
| Logbook Position                  | HW                                                                               | SW            |                                    |             |                 |     |                  |                                      |                     |         | Manufacturer |
|                                   | MM Ref                                                                           |               |                                    |             |                 |     |                  |                                      |                     |         | Date Type    |
|                                   | Ops Number(s)                                                                    |               |                                    |             |                 |     |                  |                                      |                     |         |              |
| 291509                            | Right Hydraulic System Firewall Shut-Off Valve (FS 901) - Removal / Installation |               | HRS                                |             | 3046.1          |     |                  | 0                                    |                     |         | 0            |
|                                   |                                                                                  |               | AFL                                |             | 1117            |     |                  | 0                                    |                     |         | 0            |
|                                   | 60P2910022Z005                                                                   | 14-080840     | MOS                                |             | 128.6           |     |                  | 24 Aug 2015                          |                     |         |              |
|                                   |                                                                                  |               | MSC                                |             |                 |     | O/C              |                                      |                     |         |              |
| Airframe                          |                                                                                  |               |                                    |             |                 |     |                  |                                      |                     |         |              |
| Notes: MRI PARENT CODE: 291511    |                                                                                  |               |                                    |             |                 |     |                  |                                      |                     |         |              |
| 291510                            | Left Hydraulic System Shut-Off Valve - Removal / Installation                    |               | HRS                                |             | 3046.1          |     |                  | 0                                    |                     |         | 0            |
|                                   |                                                                                  |               | AFL                                |             | 1117            |     |                  | 0                                    |                     |         | 0            |
|                                   | 60P2910022Z005                                                                   | 15-050541     | MOS                                |             | 128.6           |     |                  | 24 Aug 2015                          |                     |         |              |
|                                   |                                                                                  |               | MSC                                |             |                 |     | O/C              |                                      |                     |         |              |
| Airframe                          |                                                                                  |               |                                    |             |                 |     |                  |                                      |                     |         |              |
| 291511                            | Right Hydraulic System Shut-Off Valve - Removal / Installation                   |               | HRS                                |             | 3046.1          |     |                  | 0                                    |                     |         | 0            |
|                                   |                                                                                  |               | AFL                                |             | 1117            |     |                  | 0                                    |                     |         | 0            |
|                                   | 60P2910022Z005                                                                   | 14-080840     | MOS                                |             | 128.6           |     |                  | 24 Aug 2015                          |                     |         |              |
|                                   |                                                                                  |               | MSC                                |             |                 |     | O/C              |                                      |                     |         |              |
| Airframe                          |                                                                                  |               |                                    |             |                 |     |                  |                                      |                     |         |              |
| 291520                            | Left Hydraulic System Shut-Off Valve Motor - Removal / Installation              |               | HRS                                |             | 3046.1          |     |                  | 0                                    |                     |         | 0            |
|                                   |                                                                                  |               | AFL                                |             | 1117            |     |                  | 0                                    |                     |         | 0            |
|                                   | A2350-0129                                                                       | SN-UNKNOWN    | MOS                                |             | 128.6           |     |                  | 24 Aug 2015                          |                     |         |              |
|                                   |                                                                                  |               | MSC                                |             |                 |     | O/C              |                                      |                     |         |              |
| Airframe                          |                                                                                  |               |                                    |             |                 |     |                  |                                      |                     |         |              |
| 291521                            | Right Hydraulic System Shut-Off Valve Motor - Removal / Installation             |               | HRS                                |             | 3046.1          |     |                  | 0                                    |                     |         | 0            |
|                                   |                                                                                  |               | AFL                                |             | 1117            |     |                  | 0                                    |                     |         | 0            |
|                                   | A2350-0129                                                                       | SN-UNKNOWN    | MOS                                |             | 128.6           |     |                  | 24 Aug 2015                          |                     |         |              |
|                                   |                                                                                  |               | MSC                                |             |                 |     | O/C              |                                      |                     |         |              |
| Airframe                          |                                                                                  |               |                                    |             |                 |     |                  |                                      |                     |         |              |
| 291524                            | Hydraulic System Shut-Off Valves - Operational Check                             |               | HRS                                |             | 137             |     |                  | 2909.1                               |                     |         | 0            |
|                                   |                                                                                  |               | AFL                                |             | 52              |     |                  | 1065                                 |                     |         | 0            |
|                                   |                                                                                  |               | MOS                                |             | 4.9             | 6   | 24               | 15 Dec 2025 31 Dec 2027* 31 Jan 2028 |                     |         |              |
|                                   |                                                                                  |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |                                      |                     |         |              |
| Airframe                          |                                                                                  |               |                                    |             |                 |     |                  |                                      |                     |         |              |
| 052011                            |                                                                                  |               |                                    |             |                 |     |                  |                                      |                     |         |              |
| Notes: PN: A2350-0129 SN: <NONE>. |                                                                                  |               |                                    |             |                 |     |                  |                                      |                     |         |              |
| 291525                            | Right System Manifold Filter (Return) - Discard                                  |               | HRS                                |             | 1300.7          |     | 3600             | 1745.4                               | 5345.4              | 5395.4  | 0            |
|                                   |                                                                                  |               | AFL                                |             | 507             |     |                  | 610                                  |                     |         | 0            |
|                                   | 339913                                                                           | NSN           | MOS                                |             | 51.6            |     |                  | 22 Jan 2022                          |                     |         |              |
|                                   |                                                                                  |               | [HRS: +50/-50]                     |             |                 |     |                  |                                      |                     |         |              |
| Airframe                          |                                                                                  |               |                                    |             |                 |     |                  |                                      |                     |         |              |

| ATA<br>U=Custom  | Description                                                            |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                            | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                     | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                 |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| 291526           | Right System Manifold Filter (Engine-Driven Pump Pressure) - Discard   |               | HRS |             | 1300.7          |     | 3600             | 1745.4      | 5345.4             | 5395.4  | 0            |
|                  |                                                                        |               | AFL |             | 507             |     |                  | 610         |                    |         | 0            |
|                  | 339913                                                                 | NSN           | MOS |             | 51.6            |     |                  | 22 Jan 2022 |                    |         |              |
|                  | [HRS: +50/-50]                                                         |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe         |                                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 291527           | Right System Manifold Filter (Engine-Driven Pump Case Drain) - Discard |               | HRS |             | 1300.7          |     | 3600             | 1745.4      | 5345.4             | 5395.4  | 0            |
|                  |                                                                        |               | AFL |             | 507             |     |                  | 610         |                    |         | 0            |
|                  | 339482                                                                 | NSN           | MOS |             | 51.6            |     |                  | 22 Jan 2022 |                    |         |              |
|                  | [HRS: +50/-50]                                                         |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe         |                                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 291600           | Left System Reservoir - Removal / Installation                         |               | HRS |             | 564.9           |     |                  | 2481.2      |                    |         | 0            |
|                  | 60P2911011A030                                                         | 55-6075 GT    | AFL |             | 219             |     |                  | 898         |                    |         | 0            |
|                  |                                                                        |               | MOS |             | 17.7            |     |                  | 21 Nov 2024 |                    |         |              |
|                  |                                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 291601           | Right System Reservoir - Removal / Installation                        |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P2912012A018P01                                                      | 55-6161 GT    | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                        |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 291602           | Left Hydraulic System Reservoir Bleed Valve - Removal / Installation   |               | HRS |             | 3021.1          |     |                  | 25          |                    |         | 0            |
|                  |                                                                        |               | AFL |             | 1108            |     |                  | 9           |                    |         | 0            |
|                  | 60P2910031Z004                                                         | 0496          | MOS |             | 122.6           |     |                  | 24 Feb 2016 |                    |         |              |
|                  |                                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 291603           | Right Hydraulic System Reservoir Bleed Valve - Removal / Installation  |               | HRS |             | 3021.1          |     |                  | 25          |                    |         | 0            |
|                  |                                                                        |               | AFL |             | 1108            |     |                  | 9           |                    |         | 0            |
|                  | 60P2910031Z004                                                         | 0503          | MOS |             | 122.6           |     |                  | 24 Feb 2016 |                    |         |              |
|                  |                                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 291608           | Left System Reservoir Inspection - Leak Check                          |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                        |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                        |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                        |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                           |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|---------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                           | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                                    | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                                |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                                         |               |     |             |                 |     |                  |             |                    |         |              |
| 291609           | Right System Reservoir Inspection - Leak Check                                        |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                       |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                       |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                                              |               |     | MSC         |                 |     | O/C              |             |                    |         |              |
| 291610           | Left System Reservoir - Cleaning                                                      |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                       |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                       |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                                              |               |     | MSC         |                 |     | O/C              |             |                    |         |              |
| 291611           | Right System Reservoir - Cleaning                                                     |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                       |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                       |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                                              |               |     | MSC         |                 |     | O/C              |             |                    |         |              |
| 291615           | Ecology Bottle (Left System) - Removal / Installation                                 |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P2900014Z001                                                                        | SN-UNKNOWN    | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                       |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                                              |               |     | MSC         |                 |     | O/C              |             |                    |         |              |
| 291616           | Ecology Bottle (Right System) - Removal / Installation                                |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P2900014Z001                                                                        | SN-UNKNOWN    | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                       |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                                              |               |     | MSC         |                 |     | O/C              |             |                    |         |              |
| 291626           | Left Hydraulic System Reservoir Relief Valve - Removal / Installation                 |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P2910024Z001                                                                        | 0362          | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                       |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                                              |               |     | MSC         |                 |     | O/C              |             |                    |         |              |
| 291627           | Right Hydraulic System Reservoir Relief Valve - Removal / Installation                |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P2910024Z001                                                                        | 0191          | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                       |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                                              |               |     | MSC         |                 |     | O/C              |             |                    |         |              |
| 291630           | Hydraulic Replenisher Tank Selector Valve Check Valve (Left) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | M25675-6                                                                              | SN-UNKNOWN    | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                       |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                                              |               |     | MSC         |                 |     | O/C              |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                            |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(* =Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|----------------------|---------|--------------|
|                  | Part Number                                                                            | Serial Number |     |             |                 |     |                  |             |                      |         | Approx Price |
| Logbook Position | HW                                                                                     | SW            |     |             |                 |     |                  |             |                      |         | Manufacturer |
|                  | MM Ref                                                                                 |               |     |             |                 |     |                  |             |                      |         | Date Type    |
|                  | Ops Number(s)                                                                          |               |     |             |                 |     |                  |             |                      |         |              |
| 291635           | Hydraulic Replenisher Tank - Removal / Installation                                    |               | HRS |             | 3046.1          |     |                  | 0           |                      |         | 0            |
|                  | 1159SCH519-7                                                                           | 1215          | AFL |             | 1117            |     |                  | 0           |                      |         | 0            |
|                  |                                                                                        |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                      |         |              |
|                  | Airframe                                                                               |               | MSC |             |                 |     | O/C              |             |                      |         |              |
| 291636           | Hydraulic Replenisher Tank Selector Valve - Removal / Installation                     |               | HRS |             | 3046.1          |     |                  | 0           |                      |         | 0            |
|                  |                                                                                        |               | AFL |             | 1117            |     |                  | 0           |                      |         | 0            |
|                  | 60P2900028Z003                                                                         | 0226          | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                      |         |              |
|                  | Airframe                                                                               |               | MSC |             |                 |     | O/C              |             |                      |         |              |
| 291637           | Hydraulic Replenisher Tank Selector Valve Check Valve (Right) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                      |         | 0            |
|                  |                                                                                        |               | AFL |             | 1117            |     |                  | 0           |                      |         | 0            |
|                  | M25675-6                                                                               | SN-UNKNOWN    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                      |         |              |
|                  | Airframe                                                                               |               | MSC |             |                 |     | O/C              |             |                      |         |              |
| 291640           | Hydraulic Replenisher Pump - Removal / Installation                                    |               | HRS |             | 3046.1          |     |                  | 0           |                      |         | 0            |
|                  | 1159SCH604-2                                                                           | 192           | AFL |             | 1117            |     |                  | 0           |                      |         | 0            |
|                  |                                                                                        |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                      |         |              |
|                  | Airframe                                                                               |               | MSC |             |                 |     | O/C              |             |                      |         |              |
| 291700           | Hydraulic System Accumulator (Left) - Removal / Installation                           |               | HRS |             | 3046.1          |     |                  | 0           |                      |         | 0            |
|                  |                                                                                        |               | AFL |             | 1117            |     |                  | 0           |                      |         | 0            |
|                  | 60P2910081Z003                                                                         | 366           | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                      |         |              |
|                  | Airframe                                                                               |               | MSC |             |                 |     | O/C              |             |                      |         |              |
| 291701           | Hydraulic System Accumulator (Right) - Removal / Installation                          |               | HRS |             | 3046.1          |     |                  | 0           |                      |         | 0            |
|                  |                                                                                        |               | AFL |             | 1117            |     |                  | 0           |                      |         | 0            |
|                  | 60P2910081Z003                                                                         | 370           | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                      |         |              |
|                  | Airframe                                                                               |               | MSC |             |                 |     | O/C              |             |                      |         |              |
| 291702           | Hydraulic System Accumulator Pressure Gage (Left) - Removal / Installation             |               | HRS |             | 3046.1          |     |                  | 0           |                      |         | 0            |
|                  |                                                                                        |               | AFL |             | 1117            |     |                  | 0           |                      |         | 0            |
|                  | GP20-36                                                                                | 15-031327     | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                      |         |              |
|                  | Airframe                                                                               |               | MSC |             |                 |     | O/C              |             |                      |         |              |

| ATA<br>U=Custom  | Description                                                                           |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W                 | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|---------------------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|--------------------------|--------------------|---------|--------------|
|                  | Part Number                                                                           | Serial Number |                                    |             |                 |     |                  |                          |                    |         | Approx Price |
| Logbook Position | HW                                                                                    | SW            |                                    |             |                 |     |                  |                          |                    |         | Manufacturer |
|                  | MM Ref                                                                                |               |                                    |             |                 |     |                  |                          |                    |         | Date Type    |
|                  | Ops Number(s)                                                                         |               |                                    |             |                 |     |                  |                          |                    |         |              |
| 291703           | Hydraulic System Accumulator Pressure Gage (Right) - Removal / Installation           |               | HRS                                |             | 3046.1          |     |                  | 0                        |                    |         | 0            |
|                  |                                                                                       |               | AFL                                |             | 1117            |     |                  | 0                        |                    |         | 0            |
|                  | GP20-36                                                                               | 15-031330     | MOS                                |             | 128.6           |     |                  | 24 Aug 2015              |                    |         |              |
|                  |                                                                                       |               | MSC                                |             |                 |     | O/C              |                          |                    |         |              |
| Airframe         |                                                                                       |               |                                    |             |                 |     |                  |                          |                    |         |              |
| 291704           | Autobrake System Accumulator (3RD) - Removal / Installation                           |               | HRS                                |             | 2673.8          |     |                  | 372.3                    |                    |         | 0            |
|                  |                                                                                       |               | AFL                                |             | 1020            |     |                  | 97                       |                    |         | 0            |
|                  | 90008132                                                                              | SEP15-0622    | MOS                                | TSN:15      | 109.4           |     |                  | 29 Mar 2017              |                    |         |              |
|                  |                                                                                       |               | MSC                                |             |                 |     | O/C              |                          |                    |         |              |
| Airframe         |                                                                                       |               |                                    |             |                 |     |                  |                          |                    |         |              |
| 291708           | Hydraulic System Accumulator Precharge (Left Hydraulic System) - Detailed Inspection  |               | HRS                                |             | 137             |     |                  | 2909.1                   |                    |         | 0            |
|                  |                                                                                       |               | AFL                                |             | 52              |     |                  | 1065                     |                    |         | 0            |
|                  |                                                                                       |               | MOS                                |             | 4.8             | 27  | 24               | 18 Dec 2025 31 Jan 2028* | 29 Feb 2028        |         |              |
|                  |                                                                                       |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |                          |                    |         |              |
| Airframe         |                                                                                       |               |                                    |             |                 |     |                  |                          |                    |         |              |
| 052011           |                                                                                       |               |                                    |             |                 |     |                  |                          |                    |         |              |
| 291709           | Hydraulic System Accumulator Precharge (Right Hydraulic System) - Detailed Inspection |               | HRS                                |             | 137             |     |                  | 2909.1                   |                    |         | 0            |
|                  |                                                                                       |               | AFL                                |             | 52              |     |                  | 1065                     |                    |         | 0            |
|                  |                                                                                       |               | MOS                                |             | 4.8             | 27  | 24               | 18 Dec 2025 31 Jan 2028* | 29 Feb 2028        |         |              |
|                  |                                                                                       |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |                          |                    |         |              |
| Airframe         |                                                                                       |               |                                    |             |                 |     |                  |                          |                    |         |              |
| 052011           |                                                                                       |               |                                    |             |                 |     |                  |                          |                    |         |              |
| 291710           | Hydraulic System Accumulator Precharge (Inboard Brake System) - Detailed Inspection   |               | HRS                                |             | 137             |     |                  | 2909.1                   |                    |         | 0            |
|                  |                                                                                       |               | AFL                                |             | 52              |     |                  | 1065                     |                    |         | 0            |
|                  |                                                                                       |               | MOS                                |             | 4.8             | 27  | 24               | 18 Dec 2025 31 Jan 2028* | 29 Feb 2028        |         |              |
|                  |                                                                                       |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |                          |                    |         |              |
| Airframe         |                                                                                       |               |                                    |             |                 |     |                  |                          |                    |         |              |
| 052011           |                                                                                       |               |                                    |             |                 |     |                  |                          |                    |         |              |
| 291711           | Hydraulic System Accumulator Precharge (Outboard Brake System) - Detailed Inspection  |               | HRS                                |             | 137             |     |                  | 2909.1                   |                    |         | 0            |
|                  |                                                                                       |               | AFL                                |             | 52              |     |                  | 1065                     |                    |         | 0            |
|                  |                                                                                       |               | MOS                                |             | 4.8             | 27  | 24               | 18 Dec 2025 31 Jan 2028* | 29 Feb 2028        |         |              |
|                  |                                                                                       |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |                          |                    |         |              |
| Airframe         |                                                                                       |               |                                    |             |                 |     |                  |                          |                    |         |              |
| 052011           |                                                                                       |               |                                    |             |                 |     |                  |                          |                    |         |              |
| 291712           | Hydraulic System Accumulator Precharge (Autobrake System) - Detailed Inspection       |               | HRS                                |             | 137             |     |                  | 2909.1                   |                    |         | 0            |
|                  |                                                                                       |               | AFL                                |             | 52              |     |                  | 1065                     |                    |         | 0            |
|                  |                                                                                       |               | MOS                                |             | 4.8             | 3   | 24               | 18 Dec 2025 31 Dec 2027* | 31 Jan 2028        |         |              |
|                  |                                                                                       |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |                          |                    |         |              |
| Airframe         |                                                                                       |               |                                    |             |                 |     |                  |                          |                    |         |              |



| ATA<br>U=Custom  | Description                                  |                                                                                         | UOM | Times Since | Time<br>Accrued | Adj    | Required<br>Freq | Last C/W    | Next Due<br>(* =Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------|-----------------------------------------------------------------------------------------|-----|-------------|-----------------|--------|------------------|-------------|----------------------|---------|--------------|
|                  | Part Number                                  | Serial Number                                                                           |     |             |                 |        |                  |             |                      |         | Approx Price |
| Logbook Position | HW                                           | SW                                                                                      |     |             |                 |        |                  |             |                      |         | Manufacturer |
|                  | MM Ref                                       |                                                                                         |     |             |                 |        |                  |             |                      |         | Date Type    |
|                  | Ops Number(s)                                |                                                                                         |     |             |                 |        |                  |             |                      |         |              |
| 292000           | Auxiliary Hydraulic System - Functional Test |                                                                                         | HRS |             | 3033.8          |        |                  | 12.3        |                      |         | 0            |
|                  |                                              |                                                                                         | AFL |             | 1112            |        |                  | 5           |                      | 0       |              |
|                  |                                              |                                                                                         | MOS |             | 125.1           |        |                  | 07 Dec 2015 |                      |         |              |
|                  |                                              |                                                                                         | MSC |             |                 | O/C    |                  |             |                      |         |              |
| Airframe         |                                              |                                                                                         |     |             |                 |        |                  |             |                      |         |              |
|                  | 292100                                       | Auxiliary Hydraulic Pump - Removal / Installation<br>1159SCH603-1 K0498                 |     | HRS         |                 | 3046.1 |                  |             | 0                    |         | 0            |
|                  |                                              |                                                                                         |     | AFL         |                 | 1117   |                  |             | 0                    |         | 0            |
|                  |                                              |                                                                                         |     | MOS         |                 | 128.6  |                  |             | 24 Aug 2015          |         |              |
| MSC              |                                              |                                                                                         |     |             |                 | O/C    |                  |             |                      |         |              |
| Airframe         |                                              |                                                                                         |     |             |                 |        |                  |             |                      |         |              |
|                  | 292102                                       | Auxiliary Hydraulic Pump Component Inspection - Leak<br>Test                            |     | HRS         |                 | 3046.1 |                  |             | 0                    |         | 0            |
|                  |                                              |                                                                                         |     | AFL         |                 | 1117   |                  |             | 0                    |         | 0            |
|                  |                                              |                                                                                         |     | MOS         |                 | 128.6  |                  |             | 24 Aug 2015          |         |              |
| MSC              |                                              |                                                                                         |     |             |                 | O/C    |                  |             |                      |         |              |
| Airframe         |                                              |                                                                                         |     |             |                 |        |                  |             |                      |         |              |
|                  | 292200                                       | Power Transfer Unit Hydraulic Pump - Removal /<br>Installation<br>1159SCH511-4 MX786867 |     | HRS         |                 | 3046.1 |                  |             | 0                    |         | 0            |
|                  |                                              |                                                                                         |     | AFL         |                 | 1117   |                  |             | 0                    |         | 0            |
|                  |                                              |                                                                                         |     | MOS         |                 | 128.6  |                  |             | 24 Aug 2015          |         |              |
| MSC              |                                              |                                                                                         |     |             |                 | O/C    |                  |             |                      |         |              |
| Airframe         |                                              |                                                                                         |     |             |                 |        |                  |             |                      |         |              |
|                  | 292201                                       | Power Transfer Unit Check Valve - Removal / Installation<br>M25675-6 SN-UNKNOWN         |     | HRS         |                 | 3046.1 |                  |             | 0                    |         | 0            |
|                  |                                              |                                                                                         |     | AFL         |                 | 1117   |                  |             | 0                    |         | 0            |
|                  |                                              |                                                                                         |     | MOS         |                 | 128.6  |                  |             | 24 Aug 2015          |         |              |
| MSC              |                                              |                                                                                         |     |             |                 | O/C    |                  |             |                      |         |              |
| Airframe         |                                              |                                                                                         |     |             |                 |        |                  |             |                      |         |              |
|                  | 292204                                       | Power Transfer Unit - Functional Test                                                   |     | HRS         |                 | 3033.8 |                  |             | 12.3                 |         | 0            |
|                  |                                              |                                                                                         |     | AFL         |                 | 1112   |                  |             | 5                    |         | 0            |
|                  |                                              |                                                                                         |     | MOS         |                 | 125.1  |                  |             | 07 Dec 2015          |         |              |
| MSC              |                                              |                                                                                         |     |             |                 | O/C    |                  |             |                      |         |              |
| Airframe         |                                              |                                                                                         |     |             |                 |        |                  |             |                      |         |              |
|                  | 292205                                       | Power Transfer Unit ARM Circuit - Operational Test                                      |     | HRS         |                 | 3046.1 |                  |             | 0                    |         | 0            |
|                  |                                              |                                                                                         |     | AFL         |                 | 1117   |                  |             | 0                    |         | 0            |
|                  |                                              |                                                                                         |     | MOS         |                 | 128.6  |                  |             | 24 Aug 2015          |         |              |
| MSC              |                                              |                                                                                         |     |             |                 | O/C    |                  |             |                      |         |              |
| Airframe         |                                              |                                                                                         |     |             |                 |        |                  |             |                      |         |              |
|                  | 292206                                       | Power Transfer Unit Hydraulic Pump Inspection - Leak<br>Test                            |     | HRS         |                 | 3046.1 |                  |             | 0                    |         | 0            |
|                  |                                              |                                                                                         |     | AFL         |                 | 1117   |                  |             | 0                    |         | 0            |
|                  |                                              |                                                                                         |     | MOS         |                 | 128.6  |                  |             | 24 Aug 2015          |         |              |
| MSC              |                                              |                                                                                         |     |             |                 | O/C    |                  |             |                      |         |              |
| Airframe         |                                              |                                                                                         |     |             |                 |        |                  |             |                      |         |              |

| ATA<br>U=Custom  | Description                                                                        |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                        | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                                 | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                             |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                                      |               |     |             |                 |     |                  |             |                    |         |              |
| 292207           | Power Transfer Unit Bearing Wear Indicator - Inspection                            |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                    |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                    |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                                           |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 292500           | Auxiliary Hydraulic Pump Manifold - Removal / Installation                         |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P2921076Z001                                                                     | H6682         | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                    |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                                           |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 292501           | Auxiliary Hydraulic Pump Manifold Filter Element and Bowl - Removal / Installation |               | HRS |             | 137             |     |                  | 2909.1      |                    |         | 0            |
|                  |                                                                                    |               | AFL |             | 52              |     |                  | 1065        |                    |         | 0            |
|                  | 339980                                                                             | NSN           | MOS | TSN:2       | 4.8             |     |                  | 18 Dec 2025 |                    |         |              |
|                  | Airframe                                                                           |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 292504           | Auxiliary Hydraulic Pump Manifold Check Valve - Removal / Installation             |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                    |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | MS25676-6                                                                          | SN-UNKNOWN    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                                           |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 292506           | Auxiliary Hydraulic Pump Manifold - Cleaning                                       |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                    |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                    |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                                           |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 292507           | Auxiliary Hydraulic Pump Manifold Filter Indicator - Removal / Installation        |               | HRS |             | 1300.7          |     |                  | 1745.4      |                    |         | 0            |
|                  |                                                                                    |               | AFL |             | 507             |     |                  | 610         |                    |         | 0            |
|                  | R021192-7                                                                          | M22977        | MOS |             | 51.6            |     |                  | 22 Jan 2022 |                    |         |              |
|                  | Airframe                                                                           |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 292509           | Auxiliary Hydraulic Pump Acoustical Filter (Muffler) - Removal / Installation      |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                    |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 1159SCH603-1                                                                       | SN-UNKNOWN    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                                           |               | MSC |             |                 |     | O/C              |             |                    |         |              |

| ATA<br>U=Custom  | Description                                              |               | UOM            | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------------|---------------|----------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                              | Serial Number |                |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                       | SW            |                |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                   |               |                |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                            |               |                |             |                 |     |                  |             |                    |         |              |
| 292511           | Auxiliary Hydraulic Pump Manifold Filter - Discard       |               | HRS            |             | 137             |     | 600              | 2909.1      | 3509.1             | 3559.1  | 0            |
|                  | 339980                                                   | NSN           | AFL            |             | 52              |     |                  | 1065        |                    |         | 0            |
|                  |                                                          |               | MOS            | TSN:4       | 2.8             |     |                  | 17 Feb 2026 |                    |         |              |
|                  | Airframe                                                 |               | [HRS: +50/-50] |             |                 |     |                  |             |                    |         |              |
| 292605           | Power Transfer Unit Shut-Off Valve - Removal /           |               | HRS            |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | Installation                                             |               | AFL            |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P2921023Z001                                           | 0515          | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                 |               | MSC            |             |                 |     | O/C              |             |                    |         |              |
| 293100           | Hydraulic System Reservoir Temperature Transducer (Left  |               | HRS            |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | Forward) - Removal / Installation                        |               | AFL            |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P2930064Z003                                           | DTU5238       | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                 |               | MSC            |             |                 |     | O/C              |             |                    |         |              |
| 293101           | Hydraulic System Reservoir Temperature Transducer        |               | HRS            |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | (Right Upper) - Removal / Installation                   |               | AFL            |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P2930064Z003                                           | DTW0469       | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                 |               | MSC            |             |                 |     | O/C              |             |                    |         |              |
| 293104           | Hydraulic System Reservoir Temperature Transducer (Left  |               | HRS            |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | Aft) - Removal / Installation                            |               | AFL            |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P2930064Z003                                           | DTW0764       | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                 |               | MSC            |             |                 |     | O/C              |             |                    |         |              |
| 293105           | Hydraulic System Reservoir Temperature Transducer        |               | HRS            |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | (Right Lower) - Removal / Installation                   |               | AFL            |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P2930064Z003                                           | DTP8711       | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                 |               | MSC            |             |                 |     | O/C              |             |                    |         |              |
| 293200           | Left System Pressure Transducer - Removal / Installation |               | HRS            |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P2930061Z001                                           | 62225         | AFL            |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                          |               | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                 |               | MSC            |             |                 |     | O/C              |             |                    |         |              |

| ATA<br>U=Custom              | Description                                                             |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------------------|-------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                              | Part Number                                                             | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position             | HW                                                                      | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                              | MM Ref                                                                  |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                              | Ops Number(s)                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| 293201                       | Right System Pressure Transducer - Removal / Installation               |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                              |                                                                         |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                              | 60P2930061Z001                                                          | 62224         | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                              |                                                                         |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                     |                                                                         |               |     |             |                 |     |                  |             |                    |         |              |
| 293202                       | Auxiliary Pressure Transducer - Removal / Installation                  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                              |                                                                         |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                              | 60P2930061Z001                                                          | 62130         | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                              |                                                                         |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                     |                                                                         |               |     |             |                 |     |                  |             |                    |         |              |
| 293203                       | Power Transfer Unit Pressure Transducer - Removal / Installation        |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                              |                                                                         |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                              | 60P2930061Z001                                                          | 62229         | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                              |                                                                         |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                     |                                                                         |               |     |             |                 |     |                  |             |                    |         |              |
| 293300                       | Left Reservoir Hydraulic Quantity Transmitter - Removal / Installation  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                              |                                                                         |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                              | 60P2930063Z001                                                          | A0202         | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                              |                                                                         |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                     |                                                                         |               |     |             |                 |     |                  |             |                    |         |              |
| 293301                       | Right Reservoir Hydraulic Quantity Transmitter - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                              |                                                                         |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                              | 60P2930063Z002                                                          | A0196         | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                              |                                                                         |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                     |                                                                         |               |     |             |                 |     |                  |             |                    |         |              |
| 293304                       | Fluid Quantity Indicator - Removal / Installation                       |               | HRS |             | 1269.1          |     |                  | 1777        |                    |         | 0            |
|                              |                                                                         |               | AFL |             | 501             |     |                  | 616         |                    |         | 0            |
|                              | 366-220-003                                                             | 1272          | MOS |             | 50              |     |                  | 10 Mar 2022 |                    |         |              |
|                              |                                                                         |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                     |                                                                         |               |     |             |                 |     |                  |             |                    |         |              |
| 293306                       | Hydraulic Reservoir Quantity Transmitter - Adjustment                   |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                              |                                                                         |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                              |                                                                         |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                              |                                                                         |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                     |                                                                         |               |     |             |                 |     |                  |             |                    |         |              |
| 30 - Ice and Rain Protection |                                                                         |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                        |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                        | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                                 | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                             |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                                      |               |     |             |                 |     |                  |             |                    |         |              |
| 301100           | Wing Anti-Ice Control Valve (Left) - Removal / Installation                        |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 3291928-1                                                                          | 465           | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                    |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                                           |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 301101           | Wing Anti-Ice Control Valve (Right) - Removal / Installation                       |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 3291928-1                                                                          | 464           | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                    |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                                           |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 301102           | Wing Anti-Ice Temperature Sensor (Left) - Removal / Installation                   |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 1151834-1                                                                          | 1151834-12854 | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                    |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                                           |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 301103           | Wing Anti-Ice Temperature Sensor (Right) - Removal / Installation                  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 1151834-1                                                                          | 1151834-12953 | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                    |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                                           |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 301104           | Wing Anti-Ice Overheat Temperature Switch (Left Inboard) - Removal / Installation  |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  | 975-0113-001                                                                       | SN-UNKNOWN    | AFL |             | 315             |     |                  | 802         |                    |         | 0            |
|                  |                                                                                    |               | MOS |             | 31              |     |                  | 10 Oct 2023 |                    |         |              |
|                  | Airframe                                                                           |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 301105           | Wing Anti-Ice Overheat Temperature Switch (Left Mid) - Removal / Installation      |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  | 975-0113-001                                                                       | SN-UNKNOWN    | AFL |             | 315             |     |                  | 802         |                    |         | 0            |
|                  |                                                                                    |               | MOS |             | 31              |     |                  | 10 Oct 2023 |                    |         |              |
|                  | Airframe                                                                           |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 301106           | Wing Anti-Ice Overheat Temperature Switch (Right Inboard) - Removal / Installation |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  | 975-0113-001                                                                       | SN-UNKNOWN    | AFL |             | 315             |     |                  | 802         |                    |         | 0            |
|                  |                                                                                    |               | MOS |             | 31              |     |                  | 10 Oct 2023 |                    |         |              |
|                  | Airframe                                                                           |               | MSC |             |                 |     | O/C              |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                               |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-------------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                               | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                                        | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                                    |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 301107           | Wing Anti-Ice Overheat Temperature Switch (Right Mid) - Removal / Installation            |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  |                                                                                           |               | AFL |             | 315             |     |                  | 802         |                    |         | 0            |
|                  | 975-0113-001                                                                              | SN-UNKNOWN    | MOS |             | 31              |     |                  | 10 Oct 2023 |                    |         |              |
|                  |                                                                                           |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| 301108           | Wing Anti-Ice Overheat / Low Temperature Switch (Left Outboard) - Removal / Installation  |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  |                                                                                           |               | AFL |             | 315             |     |                  | 802         |                    |         | 0            |
|                  | 975-0114-001                                                                              | SN-UNKNOWN    | MOS |             | 31              |     |                  | 10 Oct 2023 |                    |         |              |
|                  |                                                                                           |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| 301109           | Wing Anti-Ice Overheat / Low Temperature Switch (Right Outboard) - Removal / Installation |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  |                                                                                           |               | AFL |             | 315             |     |                  | 802         |                    |         | 0            |
|                  | 975-0114-001                                                                              | SN-UNKNOWN    | MOS |             | 31              |     |                  | 10 Oct 2023 |                    |         |              |
|                  |                                                                                           |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| 301120           | Wing Anti-Ice Overheat Temperature Switch (Left Inboard) - Operational Test               |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                           |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                           |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                           |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| 301121           | Wing Anti-Ice Overheat Temperature Switch (Left Mid) - Operational Test                   |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                           |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                           |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                           |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| 301122           | Wing Anti-Ice Overheat Temperature Switch (Right Inboard) - Operational Test              |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                           |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                           |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                           |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| 301123           | Wing Anti-Ice Overheat Temperature Switch (Right Mid) - Operational Test                  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                           |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                           |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                           |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                           |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                         |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|-------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                                                         | Serial Number |     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                                                  | SW            |     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                                              |               |     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                                                       |               |     |             |                 |     |                  |             |                     |         |              |
| 301124           | Wing Anti-Ice Overheat / Low Temperature Switch (Left Outboard) - Operational Test  |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                                     |               | AFL |             | 1117            |     |                  | 0           |                     | 0       |              |
|                  |                                                                                     |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                                     |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                     |               |     |             |                 |     |                  |             |                     |         |              |
| 301125           | Wing Anti-Ice Overheat / Low Temperature Switch (Right Outboard) - Operational Test |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                                     |               | AFL |             | 1117            |     |                  | 0           |                     | 0       |              |
|                  |                                                                                     |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                                     |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                     |               |     |             |                 |     |                  |             |                     |         |              |
| 301126           | Wing Anti-Ice Control System - Functional Test                                      |               | HRS |             | 730.5           |     |                  | 2315.6      |                     |         | 0            |
|                  |                                                                                     |               | AFL |             | 315             |     |                  | 802         |                     | 0       |              |
|                  |                                                                                     |               | MOS |             | 28.7            |     |                  | 21 Dec 2023 |                     |         |              |
|                  |                                                                                     |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                     |               |     |             |                 |     |                  |             |                     |         |              |
| 301127           | Wing Anti-Ice (Left) - Operational Test                                             |               | HRS |             | 730.5           |     |                  | 2315.6      |                     |         | 0            |
|                  |                                                                                     |               | AFL |             | 315             |     |                  | 802         |                     | 0       |              |
|                  |                                                                                     |               | MOS |             | 28.7            |     |                  | 21 Dec 2023 |                     |         |              |
|                  |                                                                                     |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                     |               |     |             |                 |     |                  |             |                     |         |              |
| 301128           | Wing Anti-Ice (Right) - Operational Test                                            |               | HRS |             | 730.5           |     |                  | 2315.6      |                     |         | 0            |
|                  |                                                                                     |               | AFL |             | 315             |     |                  | 802         |                     | 0       |              |
|                  |                                                                                     |               | MOS |             | 28.7            |     |                  | 21 Dec 2023 |                     |         |              |
|                  |                                                                                     |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                     |               |     |             |                 |     |                  |             |                     |         |              |
| 301129           | Wing Hot / Wing Temp Low Message (Left) - Functional Test                           |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                                     |               | AFL |             | 1117            |     |                  | 0           |                     | 0       |              |
|                  |                                                                                     |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                                     |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                     |               |     |             |                 |     |                  |             |                     |         |              |
| 301130           | Wing Hot / Wing Temp Low Message (Right) - Functional Test                          |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                                     |               | AFL |             | 1117            |     |                  | 0           |                     | 0       |              |
|                  |                                                                                     |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                                     |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                     |               |     |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom  | Description                                                                       |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------|-----------------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                  | Part Number                                                                       | Serial Number |                                    |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position | HW                                                                                | SW            |                                    |             |                 |     |                  |             |                    |             | Manufacturer |
|                  | MM Ref                                                                            |               |                                    |             |                 |     |                  |             |                    |             | Date Type    |
|                  | Ops Number(s)                                                                     |               |                                    |             |                 |     |                  |             |                    |             |              |
| 301131           | Wing Anti-Ice Temperature Switch (Left) - Functional Test                         |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                   |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                   |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                   |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                   |               |                                    |             |                 |     |                  |             |                    |             |              |
| 301132           | Wing Anti-Ice Temperature Switch (Right) - Functional Test                        |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                   |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                   |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                   |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                   |               |                                    |             |                 |     |                  |             |                    |             |              |
| 301137           | Wing Anti-Ice Temperature Switch - Temperature Trip Point Functional Check        |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                                   |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                                   |               | MOS                                |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031        | 31 Jan 2032 |              |
|                  |                                                                                   |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         | 052016                                                                            |               |                                    |             |                 |     |                  |             |                    |             |              |
| 301301           | Primary Wing Duct Tube (Left No. 1) - Removal / Installation<br>60P3013113A007NSN |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                   |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                   |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                   |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                   |               |                                    |             |                 |     |                  |             |                    |             |              |
| 301302           | Primary Wing Duct Tube (Left No. 2) - Removal / Installation<br>60P3013121A008NSN |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                   |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                   |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                   |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                   |               |                                    |             |                 |     |                  |             |                    |             |              |
| 301303           | Primary Wing Duct Tube (Left No. 3) - Removal / Installation<br>60P3013131A004NSN |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                   |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                   |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                   |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                   |               |                                    |             |                 |     |                  |             |                    |             |              |
| 301304           | Primary Wing Duct Tube (Left No. 4) - Removal / Installation<br>60P3013141A004NSN |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                   |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                   |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                   |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                   |               |                                    |             |                 |     |                  |             |                    |             |              |



| ATA<br>U=Custom  | Description                                                   |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(* =Adj) | Max Due | Avg Man Hrs  |
|------------------|---------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|----------------------|---------|--------------|
|                  | Part Number                                                   | Serial Number |     |             |                 |     |                  |             |                      |         | Approx Price |
| Logbook Position | HW                                                            | SW            |     |             |                 |     |                  |             |                      |         | Manufacturer |
|                  | MM Ref                                                        |               |     |             |                 |     |                  |             |                      |         | Date Type    |
|                  | Ops Number(s)                                                 |               |     |             |                 |     |                  |             |                      |         |              |
| 301305           | Primary Wing Duct Tube (Left No. 5) - Removal / Installation  |               | HRS |             | 3046.1          |     |                  | 0           |                      |         | 0            |
|                  |                                                               |               | AFL |             | 1117            |     |                  | 0           |                      |         | 0            |
|                  | 60P3013151A004                                                | NSN           | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                      |         |              |
|                  |                                                               |               | MSC |             |                 |     | O/C              |             |                      |         |              |
| Airframe         |                                                               |               |     |             |                 |     |                  |             |                      |         |              |
| 301313           | Primary Wing Duct Tube (Right No. 1) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                      |         | 0            |
|                  |                                                               |               | AFL |             | 1117            |     |                  | 0           |                      |         | 0            |
|                  | 60P3013114A004                                                | NSN           | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                      |         |              |
|                  |                                                               |               | MSC |             |                 |     | O/C              |             |                      |         |              |
| Airframe         |                                                               |               |     |             |                 |     |                  |             |                      |         |              |
| 301314           | Primary Wing Duct Tube (Right No. 2) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                      |         | 0            |
|                  |                                                               |               | AFL |             | 1117            |     |                  | 0           |                      |         | 0            |
|                  | 60P3013122A004                                                | NSN           | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                      |         |              |
|                  |                                                               |               | MSC |             |                 |     | O/C              |             |                      |         |              |
| Airframe         |                                                               |               |     |             |                 |     |                  |             |                      |         |              |
| 301315           | Primary Wing Duct Tube (Right No. 3) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                      |         | 0            |
|                  |                                                               |               | AFL |             | 1117            |     |                  | 0           |                      |         | 0            |
|                  | 60P3013132A004                                                | NSN           | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                      |         |              |
|                  |                                                               |               | MSC |             |                 |     | O/C              |             |                      |         |              |
| Airframe         |                                                               |               |     |             |                 |     |                  |             |                      |         |              |
| 301316           | Primary Wing Duct Tube (Right No. 4) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                      |         | 0            |
|                  |                                                               |               | AFL |             | 1117            |     |                  | 0           |                      |         | 0            |
|                  | 60P3013142A004                                                | NSN           | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                      |         |              |
|                  |                                                               |               | MSC |             |                 |     | O/C              |             |                      |         |              |
| Airframe         |                                                               |               |     |             |                 |     |                  |             |                      |         |              |
| 301317           | Primary Wing Duct Tube (Right No. 5) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                      |         | 0            |
|                  |                                                               |               | AFL |             | 1117            |     |                  | 0           |                      |         | 0            |
|                  | 60P3013152A004                                                | NSN           | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                      |         |              |
|                  |                                                               |               | MSC |             |                 |     | O/C              |             |                      |         |              |
| Airframe         |                                                               |               |     |             |                 |     |                  |             |                      |         |              |
| 302100           | Cowl Thermal Anti-Ice Valve (Left) - Removal / Installation   |               | HRS |             | 564.8           |     |                  | 2481.3      |                      |         | 0            |
|                  | RD001C0007-5 0351                                             |               | AFL |             | 219             |     |                  | 898         |                      |         | 0            |
|                  |                                                               |               | MOS |             | 18.3            |     |                  | 02 Nov 2024 |                      |         |              |
|                  |                                                               |               | MSC |             |                 |     | O/C              |             |                      |         |              |
| Airframe         |                                                               |               |     |             |                 |     |                  |             |                      |         |              |

| ATA<br>U=Custom  | Description                                                                                     |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-------------------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                                     | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                                              | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                                          |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                                                   |               |     |             |                 |     |                  |             |                    |         |              |
| 302101           | Cowl Thermal Anti-Ice Valve (Right) - Removal / Installation                                    |               | HRS |             | 564.8           |     |                  | 2481.3      |                    |         | 0            |
|                  |                                                                                                 |               | AFL |             | 219             |     |                  | 898         |                    |         | 0            |
|                  | RD001C0007-5                                                                                    | 1035          | MOS |             | 18.3            |     |                  | 02 Nov 2024 |                    |         |              |
|                  |                                                                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                                 |               |     |             |                 |     |                  |             |                    |         |              |
| 302108           | Cowl Thermal Anti-Ice AIR Ducts and Tubes (Left) - Removal / Installation                       |               | HRS |             | 994.2           |     |                  | 2051.9      |                    |         | 0            |
|                  |                                                                                                 |               | AFL |             | 392             |     |                  | 725         |                    |         | 0            |
|                  | PN                                                                                              | NOT INSTALLED | MOS |             | 41.2            |     |                  | 05 Dec 2022 |                    |         |              |
|                  |                                                                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                                 |               |     |             |                 |     |                  |             |                    |         |              |
| 302109           | Cowl Thermal Anti-Ice AIR Ducts and Tubes (Right) - Removal / Installation                      |               | HRS |             | 994.2           |     |                  | 2051.9      |                    |         | 0            |
|                  |                                                                                                 |               | AFL |             | 392             |     |                  | 725         |                    |         | 0            |
|                  | PN                                                                                              | NSN           | MOS |             | 41.1            |     |                  | 09 Dec 2022 |                    |         |              |
|                  |                                                                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                                 |               |     |             |                 |     |                  |             |                    |         |              |
| 302114           | Cowl Thermal Anti-Ice Valve Open / Close Switch / Pressure Transducer (Left) - Functional Test  |               | HRS |             | 564.8           |     |                  | 2481.3      |                    |         | 0            |
|                  |                                                                                                 |               | AFL |             | 219             |     |                  | 898         |                    |         | 0            |
|                  |                                                                                                 |               | MOS |             | 18.3            |     |                  | 02 Nov 2024 |                    |         |              |
|                  |                                                                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                                 |               |     |             |                 |     |                  |             |                    |         |              |
| 302115           | Cowl Thermal Anti-Ice Valve Open / Close Switch / Pressure Transducer (Right) - Functional Test |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                 |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                 |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                                 |               |     |             |                 |     |                  |             |                    |         |              |
| 302116           | Cowl Anti-Ice System Operational Test - Dynamic                                                 |               | HRS |             | 564.8           |     |                  | 2481.3      |                    |         | 0            |
|                  |                                                                                                 |               | AFL |             | 219             |     |                  | 898         |                    |         | 0            |
|                  |                                                                                                 |               | MOS |             | 18.3            |     |                  | 02 Nov 2024 |                    |         |              |
|                  |                                                                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                                 |               |     |             |                 |     |                  |             |                    |         |              |
| 302117           | Cowl Thermal Anti-Ice Valve (Left) - Deactivate (Manual Lock Open) / Activate Procedure         |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                 |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                 |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                                 |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom                  | Description                                                                                           |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(* =Adj) | Max Due | Avg Man Hrs  |
|----------------------------------|-------------------------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|----------------------|---------|--------------|
|                                  | Part Number                                                                                           | Serial Number |     |             |                 |     |                  |             |                      |         | Approx Price |
| Logbook Position                 | HW                                                                                                    | SW            |     |             |                 |     |                  |             |                      |         | Manufacturer |
|                                  | MM Ref                                                                                                |               |     |             |                 |     |                  |             |                      |         | Date Type    |
|                                  | Ops Number(s)                                                                                         |               |     |             |                 |     |                  |             |                      |         |              |
| 302118                           | Cowl Thermal Anti-Ice Valve (Right) - Deactivate (Manual Lock Open) / Activate Procedure              |               | HRS |             | 3046.1          |     |                  | 0           |                      |         | 0            |
|                                  |                                                                                                       |               | AFL |             | 1117            |     |                  | 0           |                      |         | 0            |
|                                  |                                                                                                       |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                      |         |              |
|                                  |                                                                                                       |               | MSC |             |                 |     | O/C              |             |                      |         |              |
| Airframe                         |                                                                                                       |               |     |             |                 |     |                  |             |                      |         |              |
| 302200                           | Cowl Thermal Anti-Ice Pressure Transducer (Left) - Removal / Installation<br>APTE227SA-75G8134-4-331  |               | HRS |             | 994.2           |     |                  | 2051.9      |                      |         | 0            |
|                                  |                                                                                                       |               | AFL |             | 392             |     |                  | 725         |                      |         | 0            |
|                                  |                                                                                                       |               | MOS |             | 41.1            |     |                  | 09 Dec 2022 |                      |         |              |
|                                  |                                                                                                       |               | MSC |             |                 |     | O/C              |             |                      |         |              |
| Airframe                         |                                                                                                       |               |     |             |                 |     |                  |             |                      |         |              |
| 302201                           | Cowl Thermal Anti-Ice Pressure Transducer (Right) - Removal / Installation<br>APTE227SA-75G8134-4-331 |               | HRS | TSN:1867.2  | 1178.9          |     |                  | 1867.2      |                      |         | 0            |
|                                  |                                                                                                       |               | AFL | TSN:630     | 487             |     |                  | 630         |                      |         | 0            |
|                                  |                                                                                                       |               | MOS | TSN:81      | 48.2            |     |                  | 05 May 2022 |                      |         |              |
|                                  |                                                                                                       |               | MSC |             |                 |     | O/C              |             |                      |         |              |
| Airframe                         |                                                                                                       |               |     |             |                 |     |                  |             |                      |         |              |
| 303108                           | AIR Data System Probe and Total AIR Temperature Probe Heater (Left) - Operational Check               |               | HRS |             | 2430.9          |     |                  | 615.2       |                      |         | 0            |
|                                  |                                                                                                       |               | AFL |             | 952             |     |                  | 165         |                      |         | 0            |
|                                  |                                                                                                       |               | MOS |             | 99.1            |     |                  | 08 Feb 2018 |                      |         |              |
|                                  |                                                                                                       |               | MSC |             |                 |     | O/C              |             |                      |         |              |
| Airframe                         |                                                                                                       |               |     |             |                 |     |                  |             |                      |         |              |
| 303109                           | AIR Data System Probe and Total AIR Temperature Probe Heater (Right) - Operational Check              |               | HRS |             | 3033.8          |     |                  | 12.3        |                      |         | 0            |
|                                  |                                                                                                       |               | AFL |             | 1112            |     |                  | 5           |                      |         | 0            |
|                                  |                                                                                                       |               | MOS |             | 125             |     |                  | 11 Dec 2015 |                      |         |              |
|                                  |                                                                                                       |               | MSC |             |                 |     | O/C              |             |                      |         |              |
| Airframe                         |                                                                                                       |               |     |             |                 |     |                  |             |                      |         |              |
| Notes: PN: 0102LV1DF SN: <NONE>. |                                                                                                       |               |     |             |                 |     |                  |             |                      |         |              |
| 304108                           | Cockpit Front and Side Window Power and Thermal Sensor Blocks (Left Front) - Repair                   |               | HRS |             | 3046.1          |     |                  | 0           |                      |         | 0            |
|                                  |                                                                                                       |               | AFL |             | 1117            |     |                  | 0           |                      |         | 0            |
|                                  |                                                                                                       |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                      |         |              |
|                                  |                                                                                                       |               | MSC |             |                 |     | O/C              |             |                      |         |              |
| Airframe                         |                                                                                                       |               |     |             |                 |     |                  |             |                      |         |              |
| 304109                           | Cockpit Front and Side Window Power and Thermal Sensor Blocks (Left Side) - Repair                    |               | HRS |             | 3046.1          |     |                  | 0           |                      |         | 0            |
|                                  |                                                                                                       |               | AFL |             | 1117            |     |                  | 0           |                      |         | 0            |
|                                  |                                                                                                       |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                      |         |              |
|                                  |                                                                                                       |               | MSC |             |                 |     | O/C              |             |                      |         |              |
| Airframe                         |                                                                                                       |               |     |             |                 |     |                  |             |                      |         |              |

| ATA<br>U=Custom  | Description                                                                             |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-----------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|----------|--------------------|---------|--------------|
|                  | Part Number                                                                             | Serial Number |     |             |                 |     |                  |          |                    |         | Approx Price |
| Logbook Position | HW                                                                                      | SW            |     |             |                 |     |                  |          |                    |         | Manufacturer |
|                  | MM Ref                                                                                  |               |     |             |                 |     |                  |          |                    |         | Date Type    |
|                  | Ops Number(s)                                                                           |               |     |             |                 |     |                  |          |                    |         |              |
| 304110           | Cockpit Front and Side Window Power and Thermal<br>Sensor Blocks (Right Front) - Repair |               | HRS |             | 3046.1          |     |                  | 0        |                    |         | 0            |
|                  |                                                                                         |               | AFL |             | 1117            |     | 0                |          | 0                  |         |              |
|                  |                                                                                         |               | MOS |             | 128.6           |     | 24 Aug 2015      |          |                    |         |              |
|                  |                                                                                         |               | MSC |             |                 | O/C |                  |          |                    |         |              |
| Airframe         |                                                                                         |               |     |             |                 |     |                  |          |                    |         |              |
| 304111           | Cockpit Front and Side Window Power and Thermal<br>Sensor Blocks (Right Side) - Repair  |               | HRS |             | 3046.1          |     |                  | 0        |                    |         | 0            |
|                  |                                                                                         |               | AFL |             | 1117            |     | 0                |          | 0                  |         |              |
|                  |                                                                                         |               | MOS |             | 128.6           |     | 24 Aug 2015      |          |                    |         |              |
|                  |                                                                                         |               | MSC |             |                 | O/C |                  |          |                    |         |              |
| Airframe         |                                                                                         |               |     |             |                 |     |                  |          |                    |         |              |
| 304112           | Windshield Heat (Left) - Operational Test                                               |               | HRS |             | 663.7           |     |                  | 2382.4   |                    |         | 0            |
|                  |                                                                                         |               | AFL |             | 291             |     | 826              |          | 0                  |         |              |
|                  |                                                                                         |               | MOS |             | 24.9            |     | 15 Apr 2024      |          |                    |         |              |
|                  |                                                                                         |               | MSC |             |                 | O/C |                  |          |                    |         |              |
| Airframe         |                                                                                         |               |     |             |                 |     |                  |          |                    |         |              |
| 304113           | Windshield Heat (Right) - Operational Test                                              |               | HRS |             | 564.8           |     |                  | 2481.3   |                    |         | 0            |
|                  |                                                                                         |               | AFL |             | 219             |     | 898              |          | 0                  |         |              |
|                  |                                                                                         |               | MOS |             | 17.8            |     | 17 Nov 2024      |          |                    |         |              |
|                  |                                                                                         |               | MSC |             |                 | O/C |                  |          |                    |         |              |
| Airframe         |                                                                                         |               |     |             |                 |     |                  |          |                    |         |              |
| 304114           | Windshield Heat (Left) - Functional Test                                                |               | HRS |             | 3046.1          |     |                  | 0        |                    |         | 0            |
|                  |                                                                                         |               | AFL |             | 1117            |     | 0                |          | 0                  |         |              |
|                  |                                                                                         |               | MOS |             | 128.6           |     | 24 Aug 2015      |          |                    |         |              |
|                  |                                                                                         |               | MSC |             |                 | O/C |                  |          |                    |         |              |
| Airframe         |                                                                                         |               |     |             |                 |     |                  |          |                    |         |              |
| 304115           | Windshield Heat (Right) - Functional Test                                               |               | HRS |             | 3046.1          |     |                  | 0        |                    |         | 0            |
|                  |                                                                                         |               | AFL |             | 1117            |     | 0                |          | 0                  |         |              |
|                  |                                                                                         |               | MOS |             | 128.6           |     | 24 Aug 2015      |          |                    |         |              |
|                  |                                                                                         |               | MSC |             |                 | O/C |                  |          |                    |         |              |
| Airframe         |                                                                                         |               |     |             |                 |     |                  |          |                    |         |              |
| 304116           | Windshield Surface Seal (Left) - Serviceability Inspection                              |               | HRS |             | 3046.1          |     |                  | 0        |                    |         | 0            |
|                  |                                                                                         |               | AFL |             | 1117            |     | 0                |          | 0                  |         |              |
|                  |                                                                                         |               | MOS |             | 128.6           |     | 24 Aug 2015      |          |                    |         |              |
|                  |                                                                                         |               | MSC |             |                 | O/C |                  |          |                    |         |              |
| Airframe         |                                                                                         |               |     |             |                 |     |                  |          |                    |         |              |
| 304117           | Windshield Surface Seal (Right) - Serviceability Inspection                             |               | HRS |             | 3046.1          |     |                  | 0        |                    |         | 0            |
|                  |                                                                                         |               | AFL |             | 1117            |     | 0                |          | 0                  |         |              |
|                  |                                                                                         |               | MOS |             | 128.6           |     | 24 Aug 2015      |          |                    |         |              |
|                  |                                                                                         |               | MSC |             |                 | O/C |                  |          |                    |         |              |
| Airframe         |                                                                                         |               |     |             |                 |     |                  |          |                    |         |              |

| ATA<br>U=Custom  | Description                                                                                          |               | UOM                                               | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------|------------------------------------------------------------------------------------------------------|---------------|---------------------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                  | Part Number                                                                                          | Serial Number |                                                   |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position | HW                                                                                                   | SW            |                                                   |             |                 |     |                  |             |                    |             | Manufacturer |
|                  | MM Ref                                                                                               |               |                                                   |             |                 |     |                  |             |                    |             | Date Type    |
|                  | Ops Number(s)                                                                                        |               |                                                   |             |                 |     |                  |             |                    |             |              |
| 304118           | Windshield Surface Seal (Left) - Detailed Inspection                                                 |               | HRS                                               |             | 137             |     | 600              | 2909.1      | 3509.1             | 3559.1      | 0            |
|                  |                                                                                                      |               | AFL                                               |             | 52              |     |                  | 1065        |                    |             | 0            |
|                  |                                                                                                      |               | MOS                                               |             | 5.5             | 1   | 12               | 27 Nov 2025 | 30 Nov 2026*       | 31 Dec 2026 |              |
|                  |                                                                                                      |               | [End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                                      |               |                                                   |             |                 |     |                  |             |                    |             |              |
| 304119           | Windshield Surface Seal (Right) - Detailed Inspection                                                |               | HRS                                               |             | 137             |     | 600              | 2909.1      | 3509.1             |             | 0            |
|                  |                                                                                                      |               | AFL                                               |             | 52              |     |                  | 1065        |                    |             | 0            |
|                  |                                                                                                      |               | MOS                                               |             | 5.5             | 1   | 12               | 27 Nov 2025 | 30 Nov 2026*       |             |              |
|                  |                                                                                                      |               | [End Of Month Item] [MOS: -1m] [HRS: -50]         |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                                      |               |                                                   |             |                 |     |                  |             |                    |             |              |
| 304400           | Cabin Window Heat - Operational Test                                                                 |               | HRS                                               |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                                                      |               | AFL                                               |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                                                      |               | MOS                                               |             | 28.7            |     |                  | 21 Dec 2023 |                    |             |              |
|                  |                                                                                                      |               | MSC                                               |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                                      |               |                                                   |             |                 |     |                  |             |                    |             |              |
| 304401           | Cabin Window Heat Switch - Removal / Installation<br>318VL23AAAMNY00                      SN-UNKNOWN |               | HRS                                               |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                      |               | AFL                                               |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                      |               | MOS                                               |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                                      |               | MSC                                               |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                                      |               |                                                   |             |                 |     |                  |             |                    |             |              |
| 304411           | Cabin Emergency Exit Window Heat Switch (Left No. 5) -<br>Adjustment                                 |               | HRS                                               |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                      |               | AFL                                               |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                      |               | MOS                                               |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                                      |               | MSC                                               |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                                      |               |                                                   |             |                 |     |                  |             |                    |             |              |
| 304412           | Cabin Emergency Exit Window Heat Switch (Left No. 6) -<br>Adjustment                                 |               | HRS                                               |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                      |               | AFL                                               |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                      |               | MOS                                               |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                                      |               | MSC                                               |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                                      |               |                                                   |             |                 |     |                  |             |                    |             |              |
| 304413           | Cabin Emergency Exit Window Heat Switch (Right No. 5)<br>- Adjustment                                |               | HRS                                               |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                      |               | AFL                                               |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                      |               | MOS                                               |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                                      |               | MSC                                               |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                                      |               |                                                   |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom                   | Description                                                           |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|-----------------------------------|-----------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|----------|---------------------|---------|--------------|
|                                   | Part Number                                                           | Serial Number |     |             |                 |     |                  |          |                     |         | Approx Price |
| Logbook Position                  | HW                                                                    | SW            |     |             |                 |     |                  |          |                     |         | Manufacturer |
|                                   | MM Ref                                                                |               |     |             |                 |     |                  |          |                     |         | Date Type    |
|                                   | Ops Number(s)                                                         |               |     |             |                 |     |                  |          |                     |         |              |
| 304414                            | Cabin Emergency Exit Window Heat Switch (Right No. 6)<br>- Adjustment |               | HRS |             | 3046.1          |     |                  | 0        |                     |         | 0            |
|                                   |                                                                       |               | AFL |             | 1117            |     |                  | 0        |                     | 0       |              |
|                                   |                                                                       |               | MOS |             | 128.6           |     | 24 Aug 2015      |          |                     |         |              |
|                                   |                                                                       |               | MSC |             |                 | O/C |                  |          |                     |         |              |
| Airframe                          |                                                                       |               |     |             |                 |     |                  |          |                     |         |              |
| 308100                            | Ice Detector Probe (Left) - Removal / Installation<br>0871HH 02490    |               | HRS |             | 3046.1          |     |                  | 0        |                     |         | 0            |
|                                   |                                                                       |               | AFL |             | 1117            |     |                  | 0        |                     | 0       |              |
|                                   |                                                                       |               | MOS |             | 128.6           |     | 24 Aug 2015      |          |                     |         |              |
|                                   |                                                                       |               | MSC |             |                 | O/C |                  |          |                     |         |              |
| Airframe                          |                                                                       |               |     |             |                 |     |                  |          |                     |         |              |
| 308101                            | Ice Detector Probe (Right) - Removal / Installation<br>0871HH 02596   |               | HRS |             | 3046.1          |     |                  | 0        |                     |         | 0            |
|                                   |                                                                       |               | AFL |             | 1117            |     |                  | 0        |                     | 0       |              |
|                                   |                                                                       |               | MOS |             | 128.6           |     | 24 Aug 2015      |          |                     |         |              |
|                                   |                                                                       |               | MSC |             |                 | O/C |                  |          |                     |         |              |
| Airframe                          |                                                                       |               |     |             |                 |     |                  |          |                     |         |              |
| 308104                            | Ice Detector Probes (Left) - Operational Test                         |               | HRS |             | 3046.1          |     |                  | 0        |                     |         | 0            |
|                                   |                                                                       |               | AFL |             | 1117            |     |                  | 0        |                     | 0       |              |
|                                   |                                                                       |               | MOS |             | 128.6           |     | 24 Aug 2015      |          |                     |         |              |
|                                   |                                                                       |               | MSC |             |                 | O/C |                  |          |                     |         |              |
| Airframe                          |                                                                       |               |     |             |                 |     |                  |          |                     |         |              |
| 308105                            | Ice Detector Probes (Right) - Operational Test                        |               | HRS |             | 3046.1          |     |                  | 0        |                     |         | 0            |
|                                   |                                                                       |               | AFL |             | 1117            |     |                  | 0        |                     | 0       |              |
|                                   |                                                                       |               | MOS |             | 128.6           |     | 24 Aug 2015      |          |                     |         |              |
|                                   |                                                                       |               | MSC |             |                 | O/C |                  |          |                     |         |              |
| Airframe                          |                                                                       |               |     |             |                 |     |                  |          |                     |         |              |
| 308106                            | Ice Detector Logic (Left) - Functional Test                           |               | HRS |             | 3046.1          |     |                  | 0        |                     |         | 0            |
|                                   |                                                                       |               | AFL |             | 1117            |     |                  | 0        |                     | 0       |              |
|                                   |                                                                       |               | MOS |             | 128.6           |     | 24 Aug 2015      |          |                     |         |              |
|                                   |                                                                       |               | MSC |             |                 | O/C |                  |          |                     |         |              |
| Airframe                          |                                                                       |               |     |             |                 |     |                  |          |                     |         |              |
| 308107                            | Ice Detector Logic (Right) - Functional Test                          |               | HRS |             | 3046.1          |     |                  | 0        |                     |         | 0            |
|                                   |                                                                       |               | AFL |             | 1117            |     |                  | 0        |                     | 0       |              |
|                                   |                                                                       |               | MOS |             | 128.6           |     | 24 Aug 2015      |          |                     |         |              |
|                                   |                                                                       |               | MSC |             |                 | O/C |                  |          |                     |         |              |
| Airframe                          |                                                                       |               |     |             |                 |     |                  |          |                     |         |              |
| 31 - Indicating/Recording Systems |                                                                       |               |     |             |                 |     |                  |          |                     |         |              |
| 311202                            | Pedestal Switch Panel - Servicing                                     |               | HRS |             | 3046.1          |     |                  | 0        |                     |         | 0            |
|                                   |                                                                       |               | AFL |             | 1117            |     |                  | 0        |                     | 0       |              |
|                                   |                                                                       |               | MOS |             | 128.6           |     | 24 Aug 2015      |          |                     |         |              |
|                                   |                                                                       |               | MSC |             |                 | O/C |                  |          |                     |         |              |
| Airframe                          |                                                                       |               |     |             |                 |     |                  |          |                     |         |              |

| ATA<br>U=Custom                                      | Description                                                      |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(* =Adj) | Max Due | Avg Man Hrs  |
|------------------------------------------------------|------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|----------------------|---------|--------------|
|                                                      | Part Number                                                      | Serial Number |     |             |                 |     |                  |             |                      |         | Approx Price |
| Logbook Position                                     | HW                                                               | SW            |     |             |                 |     |                  |             |                      |         | Manufacturer |
|                                                      | MM Ref                                                           |               |     |             |                 |     |                  |             |                      |         | Date Type    |
|                                                      | Ops Number(s)                                                    |               |     |             |                 |     |                  |             |                      |         |              |
| 311600                                               | Pilot Switch Panel - Removal / Installation                      |               | HRS |             | 3046.1          |     |                  | 0           |                      |         | 0            |
|                                                      | G7285-01                                                         | 414           | AFL |             | 1117            |     |                  | 0           |                      |         | 0            |
|                                                      |                                                                  |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                      |         |              |
|                                                      | Airframe                                                         |               | MSC |             |                 |     | O/C              |             |                      |         |              |
| 311601                                               | Copilot Switch Panel - Removal / Installation                    |               | HRS |             | 3046.1          |     |                  | 0           |                      |         | 0            |
|                                                      | G7285-01                                                         | 415           | AFL |             | 1117            |     |                  | 0           |                      |         | 0            |
|                                                      |                                                                  |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                      |         |              |
|                                                      | Airframe                                                         |               | MSC |             |                 |     | O/C              |             |                      |         |              |
| 311602                                               | Cabin Touch Control Panel - Adjustment / Test                    |               | HRS |             | 3046.1          |     |                  | 0           |                      |         | 0            |
|                                                      |                                                                  |               | AFL |             | 1117            |     |                  | 0           |                      |         | 0            |
|                                                      |                                                                  |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                      |         |              |
|                                                      | Airframe                                                         |               | MSC |             |                 |     | O/C              |             |                      |         |              |
| Notes: PN: G7285-01 SN: 414. MRI PARENT CODE: 311600 |                                                                  |               |     |             |                 |     |                  |             |                      |         |              |
| 311603                                               | Shower Controller Assembly Aft Lavatory - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                      |         | 0            |
|                                                      | G7285-01                                                         | 415           | AFL |             | 1117            |     |                  | 0           |                      |         | 0            |
|                                                      |                                                                  |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                      |         |              |
|                                                      | Airframe                                                         |               | MSC |             |                 |     | O/C              |             |                      |         |              |
| Notes: MRI PARENT CODE: 311601                       |                                                                  |               |     |             |                 |     |                  |             |                      |         |              |
| 311716                                               | Window Shade Switch Panel #1 (Left) - Removal / Installation     |               | HRS |             | 3033.8          |     |                  | 12.3        |                      |         | 0            |
|                                                      | A2455                                                            | 007912        | AFL |             | 1112            |     |                  | 5           |                      |         | 0            |
|                                                      |                                                                  |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                      |         | RADIANT      |
|                                                      | Airframe                                                         |               | MSC |             |                 |     | O/C              |             |                      |         |              |
| 311718                                               | Window Shade Switch Panel #3 (Left) - Removal / Installation     |               | HRS |             | 3033.8          |     |                  | 12.3        |                      |         | 0            |
|                                                      | A2455                                                            | 007913        | AFL |             | 1112            |     |                  | 5           |                      |         | 0            |
|                                                      |                                                                  |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                      |         | RADIANT      |
|                                                      | Airframe                                                         |               | MSC |             |                 |     | O/C              |             |                      |         |              |
| 311719                                               | Window Shade Switch Panel #4 (Left) - Removal / Installation     |               | HRS |             | 3033.8          |     |                  | 12.3        |                      |         | 0            |
|                                                      | A2455                                                            | 007914        | AFL |             | 1112            |     |                  | 5           |                      |         | 0            |
|                                                      |                                                                  |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                      |         | RADIANT      |
|                                                      | Airframe                                                         |               | MSC |             |                 |     | O/C              |             |                      |         |              |

| ATA<br>U=Custom  | Description                                      |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|--------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                      | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                               | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                           |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                    |               |     |             |                 |     |                  |             |                    |         |              |
| 311720           | Window Shade Switch Panel #5 (Left) - Removal /  |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  | Installation                                     |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  | A2455                                            | 007915        | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | RADIANT      |
|                  |                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                  |               |     |             |                 |     |                  |             |                    |         |              |
| 311721           | Window Shade Switch Panel #6 (Left) - Removal /  |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  | Installation                                     |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  | A2455                                            | 007916        | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | RADIANT      |
|                  |                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                  |               |     |             |                 |     |                  |             |                    |         |              |
| 311722           | Window Shade Switch Panel #7 (Left) - Removal /  |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  | Installation                                     |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  | A2455                                            | 007917        | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | RADIANT      |
|                  |                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                  |               |     |             |                 |     |                  |             |                    |         |              |
| 311723           | Window Shade Switch Panel #8 (Left) - Removal /  |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  | Installation                                     |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  | A2455                                            | 007918        | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | RADIANT      |
|                  |                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                  |               |     |             |                 |     |                  |             |                    |         |              |
| 311724           | Window Shade Switch Panel #1 (Right) - Removal / |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  | Installation                                     |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  | A2455                                            | 007905        | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | RADIANT      |
|                  |                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                  |               |     |             |                 |     |                  |             |                    |         |              |
| 311726           | Window Shade Switch Panel #3 (Right) - Removal / |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  | Installation                                     |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  | A2455                                            | 007906        | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | RADIANT      |
|                  |                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                  |               |     |             |                 |     |                  |             |                    |         |              |
| 311727           | Window Shade Switch Panel #4 (Right) - Removal / |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  | Installation                                     |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  | A2455                                            | 007907        | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | RADIANT      |
|                  |                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                  |               |     |             |                 |     |                  |             |                    |         |              |



| ATA<br>U=Custom                                  | Description                                                   |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|--------------------------------------------------|---------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                                  | Part Number                                                   | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position                                 | HW                                                            | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                                  | MM Ref                                                        |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                                                  | Ops Number(s)                                                 |               |     |             |                 |     |                  |             |                    |         |              |
| 311728                                           | Window Shade Switch Panel #5 (Right) - Removal / Installation |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                                                  |                                                               |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                                                  | A2455                                                         | 007908        | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | RADIANT      |
|                                                  |                                                               |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                                         |                                                               |               |     |             |                 |     |                  |             |                    |         |              |
| 311729                                           | Window Shade Switch Panel #6 (Right) - Removal / Installation |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                                                  |                                                               |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                                                  | A2455                                                         | 007909        | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | RADIANT      |
|                                                  |                                                               |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                                         |                                                               |               |     |             |                 |     |                  |             |                    |         |              |
| 311730                                           | Window Shade Switch Panel #7 (Right) - Removal / Installation |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                                                  |                                                               |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                                                  | A2455                                                         | 008309        | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | RADIANT      |
|                                                  |                                                               |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                                         |                                                               |               |     |             |                 |     |                  |             |                    |         |              |
| 311731                                           | Window Shade Switch Panel #8 (Right) - Removal / Installation |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                                                  |                                                               |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                                                  | A2455                                                         | 007911        | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | RADIANT      |
|                                                  |                                                               |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                                         |                                                               |               |     |             |                 |     |                  |             |                    |         |              |
| 312200                                           | Cockpit Clock (Pilot) - Removal / Installation                |               | HRS |             | 59.3            |     |                  | 2986.8      |                    |         | 0            |
|                                                  | 1159SCAV409-2                                                 |               | AFL |             | 32              |     |                  | 1085        |                    |         | 0            |
|                                                  |                                                               | 6482          | MOS |             | 3.2             |     |                  | 06 Feb 2026 |                    |         |              |
|                                                  |                                                               |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                                         |                                                               |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: REMOVED TO REPLACE BATTERY - EXP DEC 2019 |                                                               |               |     |             |                 |     |                  |             |                    |         |              |
| 312201                                           | Cockpit Clock (Copilot) - Removal / Installation              |               | HRS |             | 59.3            |     |                  | 2986.8      |                    |         | 0            |
|                                                  | 1159SCAV409-2                                                 |               | AFL |             | 32              |     |                  | 1085        |                    |         | 0            |
|                                                  |                                                               | 4088          | MOS |             | 3.2             |     |                  | 06 Feb 2026 |                    |         |              |
|                                                  |                                                               |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                                         |                                                               |               |     |             |                 |     |                  |             |                    |         |              |
| 312204                                           | Cockpit Clock (Pilot) - Functional Test                       |               | HRS |             | 59.3            |     |                  | 2986.8      |                    |         | 0            |
|                                                  |                                                               |               | AFL |             | 32              |     |                  | 1085        |                    |         | 0            |
|                                                  |                                                               |               | MOS |             | 3.2             |     |                  | 06 Feb 2026 |                    |         |              |
|                                                  |                                                               |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                                         |                                                               |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                 |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                 | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                          | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                      |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                               |               |     |             |                 |     |                  |             |                    |         |              |
| 312205           | Cockpit Clock (Copilot) - Functional Test                   |               | HRS |             | 59.3            |     |                  | 2986.8      |                    |         | 0            |
|                  |                                                             |               | AFL |             | 32              |     |                  | 1085        |                    |         | 0            |
|                  |                                                             |               | MOS |             | 3.2             |     |                  | 06 Feb 2026 |                    |         |              |
|                  | Airframe                                                    |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 312206           | Cockpit Clock Battery (Pilot) - Servicing                   |               | HRS |             | 994.2           |     |                  | 2051.9      |                    |         | 0            |
|                  |                                                             |               | AFL |             | 392             |     |                  | 725         |                    |         | 0            |
|                  |                                                             |               | MOS |             | 40.9            |     |                  | 13 Dec 2022 |                    |         |              |
|                  | Airframe                                                    |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 312207           | Cockpit Clock Battery (Copilot) - Servicing                 |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                             |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                             |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                    |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 312500           | Cockpit Printer - Removal / Installation                    |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  | 42905411                                                    | 16M1019       | AFL |             | 315             |     |                  | 802         |                    |         | 0            |
|                  |                                                             |               | MOS |             | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
|                  | Airframe                                                    |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 312502           | Cockpit Printer - Functional Test                           |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  |                                                             |               | AFL |             | 315             |     |                  | 802         |                    |         | 0            |
|                  |                                                             |               | MOS |             | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
|                  | Airframe                                                    |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 312503           | Cockpit Printer Paper - Servicing                           |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  |                                                             |               | AFL |             | 315             |     |                  | 802         |                    |         | 0            |
|                  |                                                             |               | MOS |             | 30.8            |     |                  | 17 Oct 2023 |                    |         |              |
|                  | Airframe                                                    |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 313031           | Flight Data Recorder (FDR) - Download and Analyse           |               | HRS |             | 137             |     | 3000             | 2909.1      | 5909.1             |         | 0            |
|                  | Whole Flight Recording (EASA EUROCAE)                       |               | AFL |             | 52              |     |                  | 1065        |                    |         | 0            |
|                  |                                                             |               | MOS |             | 5.3             |     | 12               | 01 Dec 2025 | 01 Dec 2026        |         |              |
|                  | Airframe                                                    |               |     |             |                 |     |                  |             |                    |         |              |
| 313032           | Cockpit Voice Recorder (Cvr) - Inspect the Cvr Installation |               | HRS |             | 137             |     |                  | 2909.1      |                    |         | 0            |
|                  | (EASA EUROCAE)                                              |               | AFL |             | 52              |     |                  | 1065        |                    |         | 0            |
|                  |                                                             |               | MOS |             | 5.3             | -8  | 6                | 01 Dec 2025 | 24 May 2026*       |         |              |
|                  | Airframe                                                    |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom                             | Description                                                                                       |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq                    | Last C/W                             | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|---------------------------------------------|---------------------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|-------------------------------------|--------------------------------------|--------------------|---------|--------------|
|                                             | Part Number                                                                                       | Serial Number |     |             |                 |     |                                     |                                      |                    |         | Approx Price |
| Logbook Position                            | HW                                                                                                | SW            |     |             |                 |     |                                     |                                      |                    |         | Manufacturer |
|                                             | MM Ref                                                                                            |               |     |             |                 |     |                                     |                                      |                    |         | Date Type    |
|                                             | Ops Number(s)                                                                                     |               |     |             |                 |     |                                     |                                      |                    |         |              |
| 313033                                      | Flight Data Recorder (FDR) - Read-Out of Recorded Data (EASA ICAO)                                |               | HRS |             | 137             |     |                                     | 2909.1                               |                    |         | 0            |
|                                             |                                                                                                   |               | AFL |             | 52              |     | 1065                                |                                      | 0                  |         |              |
|                                             |                                                                                                   |               | MOS |             | 5.3             | -3  | 12                                  | 01 Dec 2025 28 Nov 2026*             |                    |         |              |
| Airframe                                    |                                                                                                   |               |     |             |                 |     |                                     |                                      |                    |         |              |
| 313034                                      | Flight Data Recorder (FDR) - Calibration of the FDR System (EASA ICAO)                            |               | HRS |             | 137             |     |                                     | 2909.1                               |                    |         | 0            |
|                                             |                                                                                                   |               | AFL |             | 52              |     | 1065                                |                                      | 0                  |         |              |
|                                             |                                                                                                   |               | MOS |             | 5.3             |     | 60                                  | 01 Dec 2025 01 Dec 2030              |                    |         |              |
| Airframe                                    |                                                                                                   |               |     |             |                 |     |                                     |                                      |                    |         |              |
| 313035                                      | Cockpit Voice Recorder (Cvr) - Read-Out of Recorded Data (EASA ICAO)& Otar (Bermudan & Cayman Is) |               | HRS |             | 137             |     |                                     | 2909.1                               |                    |         | 0            |
|                                             |                                                                                                   |               | AFL |             | 52              |     | 1065                                |                                      | 0                  |         |              |
|                                             |                                                                                                   |               | MOS |             | 5.3             |     | 12                                  | 01 Dec 2025 01 Dec 2026              |                    |         |              |
| Airframe                                    |                                                                                                   |               |     |             |                 |     |                                     |                                      |                    |         |              |
| 313100                                      | Tri-Axial Accelerometer - Removal / Installation<br>3001-01-100 0415-DTW1853                      |               | HRS |             | 3046.1          |     |                                     | 0                                    |                    |         | 0            |
|                                             |                                                                                                   |               | AFL |             | 1117            |     | 0                                   |                                      | 0                  |         |              |
|                                             |                                                                                                   |               | MOS |             | 128.6           |     | 24 Aug 2015                         |                                      |                    |         |              |
|                                             |                                                                                                   |               | MSC |             |                 | O/C |                                     |                                      |                    |         |              |
| Airframe                                    |                                                                                                   |               |     |             |                 |     |                                     |                                      |                    |         |              |
| 313101                                      | FDR Unit - Removal / Installation<br>1607-00-00 806                                               |               | HRS |             | 1300.7          |     |                                     | 1745.4                               |                    |         | 0            |
|                                             |                                                                                                   |               | AFL |             | 507             |     | 610                                 |                                      | 0                  |         |              |
|                                             |                                                                                                   |               | MOS |             | 51.4            |     | 30 Jan 2022                         |                                      |                    |         |              |
|                                             |                                                                                                   |               | MSC |             |                 | O/C |                                     |                                      |                    |         |              |
| Airframe                                    |                                                                                                   |               |     |             |                 |     |                                     |                                      |                    |         |              |
| 313104                                      | FDR - Functional / Reasonableness Check                                                           |               | HRS |             | 137             |     |                                     | 2909.1                               |                    |         | 0            |
|                                             |                                                                                                   |               | AFL |             | 52              |     | 1065                                |                                      | 0                  |         |              |
|                                             |                                                                                                   |               | MOS |             | 5.5             | 24  | 27 Nov 2025 30 Nov 2027 31 Dec 2027 |                                      |                    |         |              |
| Airframe [End Of Month Item] [MOS: +1m/-1m] |                                                                                                   |               |     |             |                 |     |                                     |                                      |                    |         |              |
| 052011                                      |                                                                                                   |               |     |             |                 |     |                                     |                                      |                    |         |              |
| 313105                                      | FDR Fail Message - Operational Check                                                              |               | HRS |             | 137             |     |                                     | 2909.1                               |                    |         | 0            |
|                                             |                                                                                                   |               | AFL |             | 52              |     | 1065                                |                                      | 0                  |         |              |
|                                             |                                                                                                   |               | MOS |             | 5.3             | 44  | 24                                  | 01 Dec 2025 31 Jan 2028* 29 Feb 2028 |                    |         |              |
| Airframe [End Of Month Item] [MOS: +1m/-1m] |                                                                                                   |               |     |             |                 |     |                                     |                                      |                    |         |              |
| 052011                                      |                                                                                                   |               |     |             |                 |     |                                     |                                      |                    |         |              |
| 313106                                      | FDR Impact Switch - Removal / Installation<br>1159SCAV402-2 5250                                  |               | HRS |             | 3046.1          |     |                                     | 0                                    |                    |         | 0            |
|                                             |                                                                                                   |               | AFL |             | 1117            |     | 0                                   |                                      | 0                  |         |              |
|                                             |                                                                                                   |               | MOS |             | 128.6           |     | 24 Aug 2015                         |                                      |                    |         |              |
|                                             |                                                                                                   |               | MSC |             |                 | O/C |                                     |                                      |                    |         |              |
| Airframe                                    |                                                                                                   |               |     |             |                 |     |                                     |                                      |                    |         |              |

| ATA<br>U=Custom  | Description                                                                  |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------|------------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                  | Part Number                                                                  | Serial Number |                                    |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position | HW                                                                           | SW            |                                    |             |                 |     |                  |             |                    |             | Manufacturer |
|                  | MM Ref                                                                       |               |                                    |             |                 |     |                  |             |                    |             | Date Type    |
|                  | Ops Number(s)                                                                |               |                                    |             |                 |     |                  |             |                    |             |              |
| 313108           | FDR Impact Switch - Operational Check                                        |               | HRS                                |             | 994.2           |     |                  | 2051.9      |                    |             | 0            |
|                  |                                                                              |               | AFL                                |             | 392             |     |                  | 725         |                    |             | 0            |
|                  |                                                                              |               | MOS                                |             | 40.9            |     | 84               | 13 Dec 2022 | 31 Dec 2029        | 31 Jan 2030 |              |
|                  | Airframe                                                                     |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| 313111           | FDR Underwater Locator Beacon - Removal / Installation                       |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  | DK120/90                                                                     | AT197300      | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                              |               | MOS                                |             | 30.1            |     |                  | 09 Nov 2023 |                    |             |              |
|                  | Airframe                                                                     |               | MSC                                |             | O/C             |     |                  |             |                    |             |              |
| 313113           | FDR Underwater Locator Beacon - Operational Check                            |               | HRS                                |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                  |                                                                              |               | AFL                                |             | 52              |     |                  | 1065        |                    |             | 0            |
|                  |                                                                              |               | MOS                                |             | 5.5             | 24  | 24               | 27 Nov 2025 | 31 Dec 2027*       | 31 Jan 2028 |              |
|                  | Airframe                                                                     |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| 313114           | FDR Underwater Locator Beacon - Cleaning                                     |               | HRS                                |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                  |                                                                              |               | AFL                                |             | 52              |     |                  | 1065        |                    |             | 0            |
|                  |                                                                              |               | MOS                                |             | 5.5             | 24  | 24               | 27 Nov 2025 | 21 Dec 2027*       | 21 Jan 2028 |              |
|                  | Airframe                                                                     |               | [MOS: +1m/-1m]                     |             |                 |     |                  |             |                    |             |              |
| 313115           | FDR Underwater Locator Beacon (DK120 or DK120/90) - Battery Replacement      |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  | DK120/90                                                                     | AT197300      | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                              |               | MOS                                | TSN:2       | 28.7            |     |                  | 21 Dec 2023 |                    |             |              |
|                  | Airframe                                                                     |               | MSC                                |             | O/C             |     |                  |             |                    |             |              |
| 313117           | FDR Underwater Locator Beacon Battery (DK120, DK120/90 or DK290) - Discard   |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  | DK120/90                                                                     | AT197300      | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                              |               | MOS                                | TSN:2       | 28.7            |     | 84               | 21 Dec 2023 | 31 Dec 2030        |             |              |
|                  | Airframe                                                                     |               | [End Of Month Item] EXPIRATION     |             |                 |     |                  |             |                    |             |              |
| 313118           | FDR Underwater Locator Beacon Battery (DK120 or DK120/90) - Functional Check |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                              |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                              |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  | Airframe                                                                     |               | MSC                                |             | O/C             |     |                  |             |                    |             |              |
| 313119           | FDR Underwater Locator Beacon Battery- Servicing                             |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                              |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                              |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  | Airframe                                                                     |               | MSC                                |             | O/C             |     |                  |             |                    |             |              |

| ATA<br>U=Custom  | Description                                                                                            |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|--------------------------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                                            | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                                                     | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                                                 |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| 314000           | Modular Avionics Unit AIR Inlet Screen (Mau No.1) -<br>Clean / Inspect                                 |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                        |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                        |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 314001           | Modular Avionics Unit AIR Inlet Screen (Mau No.2) -<br>Clean / Inspect                                 |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                        |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                        |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 314002           | Modular Avionics Unit AIR Inlet Screen (Mau No.3) -<br>Clean / Inspect                                 |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                        |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                        |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 314102           | Avionics Standard Communication Bus Coupler (Mau 2) -<br>Removal / Installation<br>7027566-9021502B102 |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                        |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                        |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 314110           | Avionics Standard Communication Bus Coupler (Mau 1) -<br>Removal / Installation<br>7027566-9021504B301 |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                        |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                        |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 314130           | Avionics Standard Communication Bus Coupler (Mau 3) -<br>Removal / Installation<br>7027566-9021504B330 |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                        |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                        |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 314274           | Actuator Input / Output Processor Module (1A) - Removal<br>/ Installation<br>7028432-19021505L362      |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                        |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                        |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                                        |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                             |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|---------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                             | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                      | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                  |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                           |               |     |             |                 |     |                  |             |                    |         |              |
| 314275           | Actuator Input / Output Processor Module (1B) - Removal |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | / Installation                                          |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 7028432-1902                                            | 1504L333      | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                         |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                         |               |     |             |                 |     |                  |             |                    |         |              |
| 314276           | Actuator Input / Output Processor Module (2A) - Removal |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | / Installation                                          |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 7028432-1902                                            | 1501K919      | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                         |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                         |               |     |             |                 |     |                  |             |                    |         |              |
| 314277           | Actuator Input / Output Processor Module (2B) - Removal |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | / Installation                                          |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 7028432-1902                                            | 1505L361      | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                         |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                         |               |     |             |                 |     |                  |             |                    |         |              |
| 314300           | Modular Avionics Unit Dual Channel Chassis (No. 1) -    |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | Removal / Installation                                  |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 7024404-2913                                            | 15034542      | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                         |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                         |               |     |             |                 |     |                  |             |                    |         |              |
| 314301           | Modular Avionics Unit Dual Channel Chassis (No. 2) -    |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | Removal / Installation                                  |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 7024404-2913                                            | 15044574      | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                         |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                         |               |     |             |                 |     |                  |             |                    |         |              |
| 314302           | Modular Avionics Unit Dual Channel Chassis (No. 3) -    |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | Removal / Installation                                  |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 7024404-2913                                            | 15044563      | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                         |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                         |               |     |             |                 |     |                  |             |                    |         |              |
| 314306           | Modular Avionics Unit - Operational Check               |               | HRS |             | 2360.6          |     |                  | 685.5       |                    |         | 0            |
|                  |                                                         |               | AFL |             | 939             |     |                  | 178         |                    |         | 0            |
|                  |                                                         |               | MOS |             | 97.6            |     |                  | 23 Mar 2018 |                    |         |              |
|                  |                                                         |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                         |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                     |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|---------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                     | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                              | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                          |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                                   |               |     |             |                 |     |                  |             |                    |         |              |
| 314309           | Single Channel Generic Input / Output Module (No. 2) - Removal / Installation   |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                 |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 7038485-1901                                                                    | 15011028      | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                 |               |     |             |                 |     |                  |             |                    |         |              |
| 314313           | Airflow Blockage Module No. 3 Mau No. 2 (Forward Reer) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                 |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 7027208-1903                                                                    | NSN           | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                 |               |     |             |                 |     |                  |             |                    |         |              |
| 314314           | Airflow Blockage Module No. 4 Mau No. 2 (Forward Reer) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                 |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 7027208-1903                                                                    | NSN           | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                 |               |     |             |                 |     |                  |             |                    |         |              |
| 314315           | Airflow Blockage Module No. 1 Mau No. 1 - Removal / Installation                |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                 |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 7027208-1903                                                                    | NSN           | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                 |               |     |             |                 |     |                  |             |                    |         |              |
| 314316           | Airflow Blockage Module No. 2 Mau No. 1 - Removal / Installation                |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                 |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 7027208-1903                                                                    | NSN           | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                 |               |     |             |                 |     |                  |             |                    |         |              |
| 314317           | Airflow Blockage Module - No. 9 Mau No. 2 - Removal / Installation              |               | HRS |             | 562.4           |     |                  | 2483.7      |                    |         | 0            |
|                  |                                                                                 |               | AFL |             | 217             |     |                  | 900         |                    |         | 0            |
|                  | 7027208-1903                                                                    | 2209GA85      | MOS | TSN:26      | 17.2            |     |                  | 06 Dec 2024 |                    |         |              |
|                  |                                                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                 |               |     |             |                 |     |                  |             |                    |         |              |
| 314321           | Airflow Blockage Module No. 5 Mau No. 3 - Removal / Installation                |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                 |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 7027208-1903                                                                    | NSN           | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                 |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                   |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|-------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                                                   | Serial Number |     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                                            | SW            |     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                                        |               |     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                                                 |               |     |             |                 |     |                  |             |                     |         |              |
| 314322           | Airflow Blockage Module No. 6 Mau No. 3 - Removal / Installation              |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                               |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 7027208-1903                                                                  | NSN           | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                               |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                               |               |     |             |                 |     |                  |             |                     |         |              |
| 314323           | Airflow Blockage Module No. 7 Mau No. 3 - Removal / Installation              |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                               |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 7027208-1903                                                                  | NSN           | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                               |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                               |               |     |             |                 |     |                  |             |                     |         |              |
| 314324           | Airflow Blockage Module No. 8 Mau No. 3 - Removal / Installation              |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                               |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 7027208-1903                                                                  | NSN           | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                               |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                               |               |     |             |                 |     |                  |             |                     |         |              |
| 314325           | Control Input / Output Module (No.1) - Removal / Installation                 |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                               |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 7038472-1901                                                                  | 15040677      | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                               |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                               |               |     |             |                 |     |                  |             |                     |         |              |
| 314327           | Control Input / Output Module (No.3) - Removal / Installation                 |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                               |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | PN                                                                            | SN-UNKNOWN    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                               |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                               |               |     |             |                 |     |                  |             |                     |         |              |
| 314328           | Single Channel Generic Input / Output Module (No. 4) - Removal / Installation |               | HRS |             | 2983.5          |     |                  | 62.6        |                     |         | 0            |
|                  |                                                                               |               | AFL |             | 1098            |     |                  | 19          |                     |         | 0            |
|                  | 7038485-1901                                                                  | 15031166      | MOS |             | 121.2           |     |                  | 06 Apr 2016 |                     |         |              |
|                  |                                                                               |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                               |               |     |             |                 |     |                  |             |                     |         |              |
| 314329           | Single Channel Generic Input / Output Module (No. 3) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                               |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 7038485-1901                                                                  | 15041256      | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                               |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                               |               |     |             |                 |     |                  |             |                     |         |              |



| ATA<br>U=Custom  | Description                                                                   |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                   | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                            | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                        |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                                 |               |     |             |                 |     |                  |             |                    |         |              |
| 314330           | Single Channel Generic Input / Output Module (No. 1) - Removal / Installation |               | HRS |             | 2983.5          |     |                  | 62.6        |                    |         | 0            |
|                  |                                                                               |               | AFL |             | 1098            |     |                  | 19          |                    |         | 0            |
|                  | 7038485-1901                                                                  | 15041256      | MOS |             | 121.2           |     |                  | 06 Apr 2016 |                    |         |              |
|                  |                                                                               |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                               |               |     |             |                 |     |                  |             |                    |         |              |
| 314331           | Single Channel Generic Input / Output Module (No. 5) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                               |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 7038485-1901                                                                  | 15041229      | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                               |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                               |               |     |             |                 |     |                  |             |                    |         |              |
| 314332           | Single Channel Generic Input / Output Module (No. 6) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                               |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 7038485-1901                                                                  | 15041257      | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                               |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                               |               |     |             |                 |     |                  |             |                    |         |              |
| 314333           | Dual Channel Generic Input / Output Module (No. 1) - Removal / Installation   |               | HRS | TSN:2505.1  | 541             |     |                  | 2505.1      |                    |         | 0            |
|                  |                                                                               |               | AFL | TSN:906     | 211             |     |                  | 906         |                    |         | 0            |
|                  | 7025365-1902                                                                  | 1503A772      | MOS | TSN:113     | 16              |     |                  | 10 Jan 2025 |                    |         |              |
|                  |                                                                               |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                               |               |     |             |                 |     |                  |             |                    |         |              |
| 314334           | Dual Channel Generic Input / Output Module (No. 2) - Removal / Installation   |               | HRS | TSN:2505.1  | 541             |     |                  | 2505.1      |                    |         | 0            |
|                  |                                                                               |               | AFL | TSN:906     | 211             |     |                  | 906         |                    |         | 0            |
|                  | 7025365-1902                                                                  | 1504A821      | MOS | TSN:113     | 16              |     |                  | 10 Jan 2025 |                    |         |              |
|                  |                                                                               |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                               |               |     |             |                 |     |                  |             |                    |         |              |
| 314337           | Custom Input / Output Module (No. 1) - Removal / Installation                 |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                               |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 7026540-1903                                                                  | 15045427      | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                               |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                               |               |     |             |                 |     |                  |             |                    |         |              |
| 314338           | Custom Input / Output Module (No. 2) - Removal / Installation                 |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                               |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 7026540-1903                                                                  | 15045455      | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                               |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                               |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                                  |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                                  | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                                           | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                                       |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| 314339           | Custom Input / Output Module (No. 3) - Removal / Installation                                |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                              |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 7026540-1903                                                                                 | 15045491      | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                              |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                              |               |     |             |                 |     |                  |             |                    |         |              |
| 314342           | Network Interface Controller / Processor Module (No. 1) (Mau No. 1) - Removal / Installation |               | HRS |             | 2762.2          |     |                  | 283.9       |                    |         | 0            |
|                  |                                                                                              |               | AFL |             | 1041            |     |                  | 76          |                    |         | 0            |
|                  | 7038231-1902                                                                                 | 1504C635      | MOS |             | 112.8           |     |                  | 16 Dec 2016 |                    |         |              |
|                  |                                                                                              |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                              |               |     |             |                 |     |                  |             |                    |         |              |
| 314343           | Network Interface Controller / Processor Module (No. 2) (Mau No. 1) - Removal / Installation |               | HRS |             | 886.8           |     |                  | 2159.3      |                    |         | 0            |
|                  |                                                                                              |               | AFL |             | 359             |     |                  | 758         |                    |         | 0            |
|                  | 7038231-1902                                                                                 | 14027407      | MOS |             | 37.5            |     |                  | 26 Mar 2023 |                    |         |              |
|                  |                                                                                              |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                              |               |     |             |                 |     |                  |             |                    |         |              |
| 314344           | Network Interface Controller / Processor Module (No. 3) (Mau No. 2) - Removal / Installation |               | HRS |             | 2549.5          |     |                  | 496.6       |                    |         | 0            |
|                  |                                                                                              |               | AFL |             | 979             |     |                  | 138         |                    |         | 0            |
|                  | 7038231-1902                                                                                 | 1411B335      | MOS |             | 103             |     |                  | 11 Oct 2017 |                    |         |              |
|                  |                                                                                              |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                              |               |     |             |                 |     |                  |             |                    |         |              |
| 314345           | Network Interface Controller / Processor Module (No. 4) (Mau No. 2) - Removal / Installation |               | HRS |             | 2762.2          |     |                  | 283.9       |                    |         | 0            |
|                  |                                                                                              |               | AFL |             | 1041            |     |                  | 76          |                    |         | 0            |
|                  | 7038231-1902                                                                                 | 1504C607      | MOS |             | 112.8           |     |                  | 16 Dec 2016 |                    |         |              |
|                  |                                                                                              |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                              |               |     |             |                 |     |                  |             |                    |         |              |
| 314346           | Network Interface Controller / Processor Module (No. 5) (Mau No. 3) - Removal / Installation |               | HRS |             | 2524.6          |     |                  | 521.5       |                    |         | 0            |
|                  |                                                                                              |               | AFL |             | 974             |     |                  | 143         |                    |         | 0            |
|                  | 7038231-1902                                                                                 | 1411B231      | MOS |             | 102.5           |     |                  | 27 Oct 2017 |                    |         |              |
|                  |                                                                                              |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                              |               |     |             |                 |     |                  |             |                    |         |              |
| 314347           | Network Interface Controller / Processor Module (No. 6) (Mau No. 3) - Removal / Installation |               | HRS |             | 2360.6          |     |                  | 685.5       |                    |         | 0            |
|                  |                                                                                              |               | AFL |             | 939             |     |                  | 178         |                    |         | 0            |
|                  | 7038231-1902                                                                                 | 1603F506      | MOS |             | 97.6            |     |                  | 23 Mar 2018 |                    |         |              |
|                  |                                                                                              |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                              |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                 |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|-----------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                                                 | Serial Number |     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                                          | SW            |     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                                      |               |     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                                               |               |     |             |                 |     |                  |             |                     |         |              |
| 314348           | Dual Channel Generic Input / Output Module (No. 3) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                             |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 7025365-1902                                                                | 1504A826      | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                             |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                             |               |     |             |                 |     |                  |             |                     |         |              |
| 314350           | Power Supply Module (No. 1) - Removal / Installation                        |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                             |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 7038248-1901                                                                | 14071753      | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                             |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                             |               |     |             |                 |     |                  |             |                     |         |              |
| 314351           | Power Supply Module (No. 2) - Removal / Installation                        |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                             |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 7038248-1901                                                                | 14051541      | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                             |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                             |               |     |             |                 |     |                  |             |                     |         |              |
| 314352           | Power Supply Module (No. 3) - Removal / Installation                        |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                             |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 7038248-1901                                                                | 14061663      | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                             |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                             |               |     |             |                 |     |                  |             |                     |         |              |
| 314353           | Power Supply Module (No. 4)- Removal / Installation                         |               | HRS | TSN:685.5   | 2360.6          |     |                  | 685.5       |                     |         | 0            |
|                  |                                                                             |               | AFL | TSN:178     | 939             |     |                  | 178         |                     |         | 0            |
|                  | 7038248-1901                                                                | 14051553      | MOS | TSN:31      | 97.6            |     |                  | 23 Mar 2018 |                     |         |              |
|                  |                                                                             |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                             |               |     |             |                 |     |                  |             |                     |         |              |
| 314354           | Advanced Graphic Module (No. 1) - Removal / Installation                    |               | HRS |             | 562.4           |     |                  | 2483.7      |                     |         | 0            |
|                  |                                                                             |               | AFL |             | 217             |     |                  | 900         |                     |         | 0            |
|                  | 60000770-1901                                                               | 24049803      | MOS | TSN:7       | 17.4            |     |                  | 29 Nov 2024 |                     |         |              |
|                  |                                                                             |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                             |               |     |             |                 |     |                  |             |                     |         |              |
| 314355           | Advanced Graphic Module (No. 2) - Removal / Installation                    |               | HRS |             | 562.4           |     |                  | 2483.7      |                     |         | 0            |
|                  |                                                                             |               | AFL |             | 217             |     |                  | 900         |                     |         | 0            |
|                  | 60000770-1901                                                               | 24049811      | MOS | TSN:7       | 17.4            |     |                  | 29 Nov 2024 |                     |         |              |
|                  |                                                                             |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                             |               |     |             |                 |     |                  |             |                     |         |              |
| 314356           | Power Supply Module (No. 5) - Removal / Installation                        |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                             |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 7038248-1901                                                                | 14051537      | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                             |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                             |               |     |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom  | Description                                                               |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|---------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                               | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                        | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                    |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 314357           | Power Supply Module (No. 6) - Removal / Installation                      |               | HRS |             | 2360.6          |     |                  | 685.5       |                    |         | 0            |
|                  | 7038248-1901                                                              | 17075741      | AFL |             | 939             |     |                  | 178         |                    |         | 0            |
|                  |                                                                           |               | MOS | TSN:6       | 97.6            |     |                  | 23 Mar 2018 |                    |         |              |
|                  | Airframe                                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 314358           | Advanced Graphic Module (No. 4) - Removal / Installation                  |               | HRS |             | 562.4           |     |                  | 2483.7      |                    |         | 0            |
|                  | 60000770-1901                                                             | 24049805      | AFL |             | 217             |     |                  | 900         |                    |         | 0            |
|                  |                                                                           |               | MOS | TSN:7       | 17.4            |     |                  | 29 Nov 2024 |                    |         |              |
|                  | Airframe                                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 314359           | Video Module (No. 1) - Removal / Installation                             |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 7038630-1901                                                              | 15030743      | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                           |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 314360           | Video Module (No. 2) - Removal / Installation                             |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 7038630-1901                                                              | 15030741      | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                           |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 314369           | Modular Avionics Unit Personality Module (No. 1) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 7519272-901                                                               | 40473868      | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                           |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 314370           | Modular Avionics Unit Personality Module (No. 2) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 7519272-901                                                               | 40473869      | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                           |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 314373           | Integrated Engine Vibration Monitor Module - Removal / Installation       |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 241-326-005-011                                                           | AL39338       | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                           |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 314375           | Advanced Graphic Module (No. 3) - Removal / Installation                  |               | HRS |             | 562.4           |     |                  | 2483.7      |                    |         | 0            |
|                  | 60000770-1901                                                             | 24049821      | AFL |             | 217             |     |                  | 900         |                    |         | 0            |
|                  |                                                                           |               | MOS | TSN:7       | 17.4            |     |                  | 29 Nov 2024 |                    |         |              |
|                  | Airframe                                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |

| ATA<br>U=Custom       | Description                                                  |               | UOM  | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due    | Avg Man Hrs  |
|-----------------------|--------------------------------------------------------------|---------------|------|-------------|-----------------|-----|------------------|-------------|---------------------|------------|--------------|
|                       | Part Number                                                  | Serial Number |      |             |                 |     |                  |             |                     |            | Approx Price |
| Logbook Position      | HW                                                           | SW            |      |             |                 |     |                  |             |                     |            | Manufacturer |
|                       | MM Ref                                                       |               |      |             |                 |     |                  |             |                     |            | Date Type    |
|                       | Ops Number(s)                                                |               |      |             |                 |     |                  |             |                     |            |              |
| 314400                | Central Maintenance Computer Module - Removal / Installation |               | HRS  |             | 2762.2          |     |                  | 283.9       |                     |            | 0            |
|                       |                                                              |               | AFL  |             | 1041            |     |                  | 76          |                     |            | 0            |
|                       | 7034055-1901                                                 | 14023671      | MOS  |             | 112.9           |     |                  | 15 Dec 2016 |                     |            |              |
|                       |                                                              |               | MSC  |             |                 |     | O/C              |             |                     |            |              |
| Airframe              |                                                              |               |      |             |                 |     |                  |             |                     |            |              |
| 314402                | Central Maintenance System - Operational Check               |               | HRS  |             | 3033.8          |     |                  | 12.3        |                     |            | 0            |
|                       |                                                              |               | AFL  |             | 1112            |     |                  | 5           |                     |            | 0            |
|                       |                                                              |               | MOS  |             | 126             |     |                  | 12 Nov 2015 |                     |            |              |
|                       |                                                              |               | MSC  |             |                 |     | O/C              |             |                     |            |              |
| Airframe              |                                                              |               |      |             |                 |     |                  |             |                     |            |              |
| 314405                | Pentium-M Processor Module - Removal / Installation          |               | HRS  |             | 562.4           |     |                  | 2483.7      |                     |            | 0            |
|                       | 7034056-1903                                                 | 24068387      | AFL  |             | 217             |     |                  | 900         |                     |            | 0            |
|                       |                                                              |               | MOS  | TSN:6       | 17.2            |     |                  | 06 Dec 2024 |                     |            |              |
|                       |                                                              |               | MSC  |             |                 |     | O/C              |             |                     |            |              |
| Airframe              |                                                              |               |      |             |                 |     |                  |             |                     |            |              |
| 315000                | Central Warning System - Operational Test                    |               | HRS  |             | 3033.8          |     |                  | 12.3        |                     |            | 0            |
|                       |                                                              |               | AFL  |             | 1112            |     |                  | 5           |                     |            | 0            |
|                       |                                                              |               | MOS  |             | 126             |     |                  | 12 Nov 2015 |                     |            |              |
|                       |                                                              |               | MSC  |             |                 |     | O/C              |             |                     |            |              |
| Airframe              |                                                              |               |      |             |                 |     |                  |             |                     |            |              |
| 315100                | Planeview Software - Top Level System (TIs)                  |               | HRS  |             | 562.4           |     |                  | 2483.7      |                     |            | 0            |
|                       | EB7038694-00105                                              | 35725762      | AFL  |             | 217             |     |                  | 900         |                     |            | 0            |
|                       |                                                              |               | MOS  |             | 17.2            |     |                  | 06 Dec 2024 |                     |            |              |
|                       |                                                              |               | MSC  |             |                 |     | O/C              |             |                     |            |              |
| Airframe              |                                                              |               |      |             |                 |     |                  |             |                     |            |              |
| 315101 <sup>U</sup>   | Blue Disc - Planeview System Charts - Update                 |               | HRS  |             | -2              |     |                  | 3048.1      |                     |            | 0            |
|                       |                                                              |               | AFL  |             | -2              |     |                  | 1119        |                     |            | 0            |
|                       |                                                              |               | DATE |             | 5 d             |     | 14d              | 06 May 2026 | 27 May 2026         |            |              |
|                       |                                                              |               |      |             |                 |     |                  |             |                     | EXPIRATION |              |
| Airframe              |                                                              |               |      |             |                 |     |                  |             |                     |            |              |
| Notes: CHARTS 14-2024 |                                                              |               |      |             |                 |     |                  |             |                     |            |              |
| 315102                | Planeview Master Operating System (Mos) Media                |               | HRS  |             | 562.4           |     |                  | 2483.7      |                     |            | 0            |
|                       | MM7038690-008                                                | 35725762      | AFL  |             | 217             |     |                  | 900         |                     |            | 0            |
|                       |                                                              |               | MOS  | TSN:3       | 17.2            |     |                  | 06 Dec 2024 |                     |            |              |
|                       |                                                              |               | MSC  |             |                 |     | O/C              |             |                     |            |              |
| Airframe              |                                                              |               |      |             |                 |     |                  |             |                     |            |              |
| 315103                | Options Software                                             |               | HRS  |             | 562.4           |     |                  | 2483.7      |                     |            | 0            |
|                       | TT60004484-60160                                             | 84438         | AFL  |             | 217             |     |                  | 900         |                     |            | 0            |
|                       |                                                              |               | MOS  |             | 17.2            |     |                  | 06 Dec 2024 |                     |            |              |
|                       |                                                              |               | MSC  |             |                 |     | O/C              |             |                     |            |              |
| Airframe              |                                                              |               |      |             |                 |     |                  |             |                     |            |              |

| ATA<br>U=Custom                               | Description                    |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|-----------------------------------------------|--------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                               | Part Number                    | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position                              | HW                             | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                               | MM Ref                         |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                                               | Ops Number(s)                  |               |     |             |                 |     |                  |             |                    |         |              |
| 315104                                        | CD, Options Data Media         |               | HRS |             | 562.4           |     |                  | 2483.7      |                    |         | 0            |
|                                               | DM60004484-60160               |               | AFL |             | 217             |     |                  | 900         |                    |         | 0            |
|                                               | 84438                          |               | MOS |             | 17.2            |     |                  | 06 Dec 2024 |                    |         |              |
|                                               | Airframe                       |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 315105                                        | Electronic Checklist S/W       |               | HRS |             | 562.4           |     |                  | 2483.7      |                    |         | 0            |
|                                               | GVIPV0076000006L               |               | AFL |             | 217             |     |                  | 900         |                    |         | 0            |
|                                               | NSN                            |               | MOS |             | 17.2            |     |                  | 06 Dec 2024 |                    |         |              |
|                                               | Airframe                       |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 315107                                        | Settings/Rigging S/W-TIs       |               | HRS |             | 562.4           |     |                  | 2483.7      |                    |         | 0            |
|                                               | OKEVO 0X49D5C0                 |               | AFL |             | 217             |     |                  | 900         |                    |         | 0            |
|                                               | ASC002-005-100                 |               | MOS |             | 17.2            |     |                  | 06 Dec 2024 |                    |         |              |
|                                               | Airframe                       |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 315108                                        | CD, Settings/Rigging Media     |               | HRS |             | 562.4           |     |                  | 2483.7      |                    |         | 0            |
|                                               | OKEVO 0X49D5C0                 |               | AFL |             | 217             |     |                  | 900         |                    |         | 0            |
|                                               | ASC002-005-100                 |               | MOS |             | 17.2            |     |                  | 06 Dec 2024 |                    |         |              |
|                                               | Airframe                       |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 315109                                        | Cmc Diagnostic S/W-TIs         |               | HRS |             | 562.4           |     |                  | 2483.7      |                    |         | 0            |
|                                               | GVI_902_00105_13_10102         |               | AFL |             | 217             |     |                  | 900         |                    |         | 0            |
|                                               | 3                              |               | MOS |             | 17.2            |     |                  | 06 Dec 2024 |                    |         |              |
|                                               | Airframe                       |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 315110                                        | CD, Cmc Diagnostic Media (Ldi) |               | HRS |             | 562.4           |     |                  | 2483.7      |                    |         | 0            |
|                                               | GVI_903_00105_13_10102         |               | AFL |             | 217             |     |                  | 900         |                    |         | 0            |
|                                               | 3                              |               | MOS |             | 17.2            |     |                  | 06 Dec 2024 |                    |         |              |
|                                               | Airframe                       |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 315111                                        | Programmable CAS               |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                                               |                                |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                                               |                                |               | MOS |             | 126             |     |                  | 11 Nov 2015 |                    |         |              |
|                                               | Airframe                       |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Notes: PN: 0FC2E081 GVI BLANK PRO SN: <NONE>. |                                |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom                          | Description                                                                    |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W                            | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------------------------------|--------------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------------------------------|--------------------|---------|--------------|
|                                          | Part Number                                                                    | Serial Number |                                    |             |                 |     |                  |                                     |                    |         | Approx Price |
| Logbook Position                         | HW                                                                             | SW            |                                    |             |                 |     |                  |                                     |                    |         | Manufacturer |
|                                          | MM Ref                                                                         |               |                                    |             |                 |     |                  |                                     |                    |         | Date Type    |
|                                          | Ops Number(s)                                                                  |               |                                    |             |                 |     |                  |                                     |                    |         |              |
| 315112                                   | Airline Modifiable Software                                                    |               | HRS                                |             | 562.4           |     |                  | 2483.7                              |                    |         | 0            |
|                                          |                                                                                |               | AFL                                |             | 217             |     |                  | 900                                 |                    |         | 0            |
|                                          |                                                                                |               | MOS                                |             | 17.2            |     |                  | 06 Dec 2024                         |                    |         |              |
|                                          |                                                                                |               | MSC                                |             |                 |     | O/C              |                                     |                    |         |              |
| Airframe                                 |                                                                                |               |                                    |             |                 |     |                  |                                     |                    |         |              |
| Notes: PN: 69003983-501 SN: 08 DEC 2016. |                                                                                |               |                                    |             |                 |     |                  |                                     |                    |         |              |
| 315113                                   | Magnetic Variation Database - Update                                           |               | HRS                                |             | 562.4           |     |                  | 2483.7                              |                    |         | 0            |
|                                          |                                                                                |               | AFL                                |             | 217             |     |                  | 900                                 |                    |         | 0            |
|                                          |                                                                                |               | MOS                                |             | 17.2            |     |                  | 06 Dec 2024                         |                    |         |              |
|                                          |                                                                                |               | MSC                                |             |                 |     | -                |                                     |                    |         |              |
| Airframe                                 |                                                                                |               |                                    |             |                 |     |                  |                                     |                    |         |              |
| 315205                                   | Warn Inhibit Panel - Operational Test                                          |               | HRS                                |             | 3046.1          |     |                  | 0                                   |                    |         | 0            |
|                                          |                                                                                |               | AFL                                |             | 1117            |     |                  | 0                                   |                    |         | 0            |
|                                          |                                                                                |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015                         |                    |         |              |
|                                          |                                                                                |               | MSC                                |             |                 |     | O/C              |                                     |                    |         |              |
| Airframe                                 |                                                                                |               |                                    |             |                 |     |                  |                                     |                    |         |              |
| 315400                                   | Aircraft Configuration Message - Operational Check                             |               | HRS                                |             | 663.7           |     |                  | 2382.4                              |                    |         | 0            |
|                                          |                                                                                |               | AFL                                |             | 291             |     |                  | 826                                 |                    |         | 0            |
|                                          |                                                                                |               | MOS                                |             | 25.5            |     | 36               | 27 Mar 2024 31 Mar 2027 30 Apr 2027 |                    |         |              |
|                                          |                                                                                |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |                                     |                    |         |              |
| Airframe                                 |                                                                                |               |                                    |             |                 |     |                  |                                     |                    |         |              |
| 052012                                   |                                                                                |               |                                    |             |                 |     |                  |                                     |                    |         |              |
| 316000                                   | Electronic Display System - Display Format Control - Adjustment / Test         |               | HRS                                |             | 2170.4          |     |                  | 875.7                               |                    |         | 0            |
|                                          |                                                                                |               | AFL                                |             | 873             |     |                  | 244                                 |                    |         | 0            |
|                                          |                                                                                |               | MOS                                |             | 88.7            |     |                  | 21 Dec 2018                         |                    |         |              |
|                                          |                                                                                |               | MSC                                |             |                 |     | O/C              |                                     |                    |         |              |
| Airframe                                 |                                                                                |               |                                    |             |                 |     |                  |                                     |                    |         |              |
| 316300                                   | Cursor Control Device (Pilot) - Removal / Installation<br>1159F57160-9 0193    |               | HRS                                |             | 1452            |     |                  | 1594.1                              |                    |         | 0            |
|                                          |                                                                                |               | AFL                                |             | 570             |     |                  | 547                                 |                    |         | 0            |
|                                          |                                                                                |               | MOS                                |             | 64              |     |                  | 12 Jan 2021                         |                    |         |              |
|                                          |                                                                                |               | MSC                                |             |                 |     | O/C              |                                     |                    |         |              |
| Airframe                                 |                                                                                |               |                                    |             |                 |     |                  |                                     |                    |         |              |
| 316301                                   | Cursor Control Device (Copilot) - Removal / Installation<br>1159F57160-10 0183 |               | HRS                                |             | 1452            |     |                  | 1594.1                              |                    |         | 0            |
|                                          |                                                                                |               | AFL                                |             | 570             |     |                  | 547                                 |                    |         | 0            |
|                                          |                                                                                |               | MOS                                |             | 64              |     |                  | 11 Jan 2021                         |                    |         |              |
|                                          |                                                                                |               | MSC                                |             |                 |     | O/C              |                                     |                    |         |              |
| Airframe                                 |                                                                                |               |                                    |             |                 |     |                  |                                     |                    |         |              |
| 316302                                   | Display Unit (No. 1) - Removal / Installation<br>7028140-911 13067877          |               | HRS                                |             | 730.5           |     |                  | 2315.6                              |                    |         | 0            |
|                                          |                                                                                |               | AFL                                |             | 315             |     |                  | 802                                 |                    |         | 0            |
|                                          |                                                                                |               | MOS                                |             | 30.3            |     |                  | 03 Nov 2023                         |                    |         |              |
|                                          |                                                                                |               | MSC                                |             |                 |     | O/C              |                                     |                    |         |              |
| Airframe                                 |                                                                                |               |                                    |             |                 |     |                  |                                     |                    |         |              |

| ATA<br>U=Custom                     | Description                                               |               | UOM            | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|-------------------------------------|-----------------------------------------------------------|---------------|----------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                     | Part Number                                               | Serial Number |                |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position                    | HW                                                        | SW            |                |             |                 |     |                  |             |                    |         | Manufacturer |
|                                     | MM Ref                                                    |               |                |             |                 |     |                  |             |                    |         | Date Type    |
|                                     | Ops Number(s)                                             |               |                |             |                 |     |                  |             |                    |         |              |
| 316303                              | Display Unit (No. 2) - Removal / Installation             |               | HRS            | TSN:2315.6  | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                                     | 7028140-911                                               | 15049490      | AFL            | TSN:802     | 315             |     |                  | 802         |                    |         | 0            |
|                                     |                                                           |               | MOS            | TSN:99      | 30.3            |     |                  | 03 Nov 2023 |                    |         |              |
|                                     | Airframe                                                  |               | MSC            |             |                 |     | O/C              |             |                    |         |              |
| 316304                              | Display Unit (No. 3) - Removal / Installation             |               | HRS            |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                                     | 7028140-911                                               | 14098925      | AFL            |             | 315             |     |                  | 802         |                    |         | 0            |
|                                     |                                                           |               | MOS            |             | 30.3            |     |                  | 03 Nov 2023 |                    |         |              |
|                                     | Airframe                                                  |               | MSC            |             |                 |     | O/C              |             |                    |         |              |
| 316305                              | Display Unit (No. 4) - Removal / Installation             |               | HRS            | TSN:1439.9  | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                                     | 7028140-911                                               | 18112042      | AFL            | TSN:558     | 315             |     |                  | 802         |                    |         | 0            |
|                                     |                                                           |               | MOS            | TSN:60      | 30.3            |     |                  | 03 Nov 2023 |                    |         |              |
|                                     | Airframe                                                  |               | MSC            |             |                 |     | O/C              |             |                    |         |              |
| 316318                              | Display Unit - Cleaning                                   |               | HRS            |             | 2170.4          |     |                  | 875.7       |                    |         | 0            |
|                                     |                                                           |               | AFL            |             | 873             |     |                  | 244         |                    |         | 0            |
|                                     |                                                           |               | MOS            |             | 88.7            |     |                  | 21 Dec 2018 |                    |         |              |
|                                     | Airframe                                                  |               | MSC            |             |                 |     | O/C              |             |                    |         |              |
| 316320                              | Display Brightness Control Panel - Removal / Installation |               | HRS            |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                     | 7007543-903                                               | 15032088      | AFL            |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                     |                                                           |               | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                     | Airframe                                                  |               | MSC            |             |                 |     | O/C              |             |                    |         |              |
| 316322                              | Displays Manual Reversion - Operational Check             |               | HRS            |             | 1300.7          |     | 1800             | 1745.4      | 3545.4             | 3595.4  | 0            |
|                                     |                                                           |               | AFL            |             | 507             |     |                  | 610         |                    |         | 0            |
|                                     |                                                           |               | MOS            |             | 51.8            |     |                  | 16 Jan 2022 |                    |         |              |
|                                     | Airframe                                                  |               | [HRS: +50/-50] |             |                 |     |                  |             |                    |         |              |
|                                     |                                                           | 052003        |                |             |                 |     |                  |             |                    |         |              |
| 316325                              | Cursor Control Device - Operational Test                  |               | HRS            |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                     |                                                           |               | AFL            |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                     |                                                           |               | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                     | Airframe                                                  |               | MSC            |             |                 |     | O/C              |             |                    |         |              |
| Notes: PN: 1159F57160-9 SN: <NONE>. |                                                           |               |                |             |                 |     |                  |             |                    |         |              |
| 316327                              | Cursor Control Device - Nulling Procedure                 |               | HRS            |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                     |                                                           |               | AFL            |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                     |                                                           |               | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                     | Airframe                                                  |               | MSC            |             |                 |     | O/C              |             |                    |         |              |



| ATA<br>U=Custom                     | Description                                                              |               | UOM                                               | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|-------------------------------------|--------------------------------------------------------------------------|---------------|---------------------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                                     | Part Number                                                              | Serial Number |                                                   |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position                    | HW                                                                       | SW            |                                                   |             |                 |     |                  |             |                    |             | Manufacturer |
|                                     | MM Ref                                                                   |               |                                                   |             |                 |     |                  |             |                    |             | Date Type    |
|                                     | Ops Number(s)                                                            |               |                                                   |             |                 |     |                  |             |                    |             |              |
| 316340                              | Video Amplifier - Removal / Installation                                 |               | HRS                                               |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                                     | VA-400-1                                                                 | 031500026     | AFL                                               |             | 1117            |     |                  | 0           |                    |             | 0            |
|                                     |                                                                          |               | MOS                                               |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                                     | Airframe                                                                 |               | MSC                                               |             |                 |     | O/C              |             |                    |             |              |
| 316600                              | McdU Capability to Display Standby Engine Instruments - Operational Test |               | HRS                                               |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                                     |                                                                          |               | AFL                                               |             | 1117            |     |                  | 0           |                    |             | 0            |
|                                     |                                                                          |               | MOS                                               |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                                     | Airframe                                                                 |               | MSC                                               |             |                 |     | O/C              |             |                    |             |              |
| Notes: PN: 1159F57160-9 SN: <NONE>. |                                                                          |               |                                                   |             |                 |     |                  |             |                    |             |              |
| 32 - Landing Gear                   |                                                                          |               |                                                   |             |                 |     |                  |             |                    |             |              |
| 320001                              | Landing Gear Doors - Operational Check                                   |               | HRS                                               |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                                     |                                                                          |               | AFL                                               |             | 1117            |     |                  | 0           |                    |             | 0            |
|                                     |                                                                          |               | MOS                                               |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                                     | Airframe                                                                 |               | MSC                                               |             |                 |     | O/C              |             |                    |             |              |
| 320002                              | Nose and Main Landing Gear and Doors - General Visual Inspection         |               | HRS                                               |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                                     |                                                                          |               | AFL                                               |             | 52              |     |                  | 1065        |                    |             | 0            |
|                                     |                                                                          |               | MOS                                               |             | 5.5             | -1  | 12               | 27 Nov 2025 | 30 Nov 2026*       | 31 Dec 2026 |              |
|                                     | Airframe                                                                 |               | [End Of Month Item] [MOS: +1m/-1m]                |             |                 |     |                  |             |                    |             |              |
|                                     |                                                                          | 052010        |                                                   |             |                 |     |                  |             |                    |             |              |
| 320003                              | Nose and Main Landing Gear and Doors - Zonal Inspection                  |               | HRS                                               |             | 137             |     | 600              | 2909.1      | 3509.1             | 3559.1      | 0            |
|                                     |                                                                          |               | AFL                                               |             | 52              |     |                  | 1065        |                    |             | 0            |
|                                     |                                                                          |               | MOS                                               |             | 5.3             |     | 24               | 01 Dec 2025 | 31 Dec 2027        | 31 Jan 2028 |              |
|                                     | Airframe                                                                 |               | [End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50] |             |                 |     |                  |             |                    |             |              |
|                                     |                                                                          | 052001,052011 |                                                   |             |                 |     |                  |             |                    |             |              |
| 320004                              | Landing Gear - Operational Test                                          |               | HRS                                               |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                                     |                                                                          |               | AFL                                               |             | 52              |     |                  | 1065        |                    |             | 0            |
|                                     |                                                                          |               | MOS                                               |             | 4.8             |     |                  | 18 Dec 2025 |                    |             |              |
|                                     | Airframe                                                                 |               | MSC                                               |             |                 |     | O/C              |             |                    |             |              |
| 320005                              | Landing Gear Cycling - Operational Test                                  |               | HRS                                               |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                                     |                                                                          |               | AFL                                               |             | 52              |     |                  | 1065        |                    |             | 0            |
|                                     |                                                                          |               | MOS                                               |             | 4.8             |     |                  | 18 Dec 2025 |                    |             |              |
|                                     | Airframe                                                                 |               | MSC                                               |             |                 |     | O/C              |             |                    |             |              |

| ATA<br>U=Custom                | Description                                                                                                       |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|--------------------------------|-------------------------------------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                | Part Number                                                                                                       | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position               | HW                                                                                                                | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                | MM Ref                                                                                                            |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                                | Ops Number(s)                                                                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| 320006                         | Landing Gear - Free Fall Check                                                                                    |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                                |                                                                                                                   |               | AFL |             | 315             |     |                  | 802         |                    |         | 0            |
|                                |                                                                                                                   |               | MOS |             | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
|                                |                                                                                                                   |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                       |                                                                                                                   |               |     |             |                 |     |                  |             |                    |         |              |
| 321000                         | Main Landing Gear (Left) - Removal / Installation<br>60P3212010A019                      GLG0164                  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                                                                                   |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                |                                                                                                                   |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                |                                                                                                                   |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                       |                                                                                                                   |               |     |             |                 |     |                  |             |                    |         |              |
| 321001                         | Main Landing Gear (Right) - Removal / Installation<br>60P3212011A017                      GLG0164                 |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                                                                                   |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                |                                                                                                                   |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                |                                                                                                                   |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                       |                                                                                                                   |               |     |             |                 |     |                  |             |                    |         |              |
| 321002                         | Main Landing Gear Structural Post (Left) - Removal /<br>Installation<br>C1A5300LA003                      CD0346  |               | HRS | TSN:2315.6  | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                                |                                                                                                                   |               | AFL | TSN:802     | 315             |     |                  | 802         |                    |         | 0            |
|                                |                                                                                                                   |               | MOS | TSN:100     | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
|                                |                                                                                                                   |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                       |                                                                                                                   |               |     |             |                 |     |                  |             |                    |         |              |
| 321003                         | Main Landing Gear Structural Post (Right) - Removal /<br>Installation<br>C1A5300RA003                      CD0380 |               | HRS | TSN:2315.6  | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                                |                                                                                                                   |               | AFL | TSN:802     | 315             |     |                  | 802         |                    |         | 0            |
|                                |                                                                                                                   |               | MOS | TSN:100     | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
|                                |                                                                                                                   |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                       |                                                                                                                   |               |     |             |                 |     |                  |             |                    |         |              |
| 321008                         | Main Landing Gear (Left) - Restore<br>60P3212010A019                      GLG0164                                 |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                                                                                   |               | AFL |             | 1117            |     | 10000            | 0           | 10000              |         | 0            |
|                                |                                                                                                                   |               | MOS |             | 128.6           |     | 192              | 24 Aug 2015 | 24 Aug 2031        |         |              |
|                                |                                                                                                                   |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                       |                                                                                                                   |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 321000 |                                                                                                                   |               |     |             |                 |     |                  |             |                    |         |              |
| 321009                         | Main Landing Gear (Right) - Restore<br>60P3212011A017                      GLG0164                                |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                                                                                   |               | AFL |             | 1117            |     | 10000            | 0           | 10000              |         | 0            |
|                                |                                                                                                                   |               | MOS |             | 128.6           |     | 192              | 24 Aug 2015 | 24 Aug 2031        |         |              |
|                                |                                                                                                                   |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                       |                                                                                                                   |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 321001 |                                                                                                                   |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom                | Description                                              |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|--------------------------------|----------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                | Part Number                                              | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position               | HW                                                       | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                | MM Ref                                                   |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                                | Ops Number(s)                                            |               |     |             |                 |     |                  |             |                    |         |              |
| 321010                         | Main Landing Gear Components (Left) - Discard            |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | 60P3212010A019                                           | GLG0164       | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                |                                                          |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Notes: MRI PARENT CODE: 321000 |                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| 321011                         | Main Landing Gear Components (Right) - Discard           |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | 60P3212011A017                                           | GLG0164       | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                |                                                          |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Notes: MRI PARENT CODE: 321001 |                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| 321012                         | Main Landing Gear - Rigging / Adjustment                 |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                          |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                |                                                          |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 321013                         | Main Landing Gear Post Machining (Left) - Discard        |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | C1A5300LA003                                             | CD0346        | AFL |             | 1117            |     | 20000            | 0           | 20000              |         | 0            |
|                                |                                                          |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                                 |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 321002 |                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| 321014                         | Main Landing Gear Post Machining (Right) - Discard       |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | C1A5300RA003                                             | CD0380        | AFL |             | 1117            |     | 20000            | 0           | 20000              |         | 0            |
|                                |                                                          |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                                 |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 321003 |                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| 321017                         | Main Landing Gear Trunnion Lugs (Left) - Ndt Inspection  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                          |               | AFL |             | 1117            |     | 4745**           | 0           | 4745               |         | 0            |
|                                |                                                          |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                                 |               |     |             |                 |     |                  |             |                    |         |              |
| 321018                         | Main Landing Gear Trunnion Lugs (Right) - Ndt Inspection |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                          |               | AFL |             | 1117            |     | 4745**           | 0           | 4745               |         | 0            |
|                                |                                                          |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                                 |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                                                          |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------|----------------------------------------------------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                  | Part Number                                                                                                          | Serial Number |                                    |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position | HW                                                                                                                   | SW            |                                    |             |                 |     |                  |             |                    |             | Manufacturer |
|                  | MM Ref                                                                                                               |               |                                    |             |                 |     |                  |             |                    |             | Date Type    |
|                  | Ops Number(s)                                                                                                        |               |                                    |             |                 |     |                  |             |                    |             |              |
| 321029           | Main Landing Gear Door - Rigging / Adjustment                                                                        |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                                      |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                                      |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                                                      |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| 321030           | Main Landing Gear Door (Left) - Removal / Installation<br>60P5280410A018                      0001870418             |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                                      |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                                      |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                                                      |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| 321031           | Main Landing Gear Door (Right) - Removal / Installation<br>60P5280310A023                      0001882865            |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                                      |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                                      |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                                                      |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| 321032           | Main Landing Gear Fairing Door (Left) - Removal /<br>Installation<br>60P5280421A009                      0001921995  |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                                      |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                                      |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                                                      |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| 321033           | Main Landing Gear Fairing Door (Right) - Removal /<br>Installation<br>60P5280321A006                      0001921996 |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                                      |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                                      |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                                                      |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| 321038           | Main Landing Gear Fairing Door - Rigging / Adjustment                                                                |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                                      |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                                      |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                                                      |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| 321050           | Main Landing Gear and Components (Left) - Detailed<br>Inspection                                                     |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                                                                      |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                                                                      |               | MOS                                |             | 28.7            |     | 48               | 21 Dec 2023 | 31 Dec 2027        | 31 Jan 2028 |              |
|                  |                                                                                                                      |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         | 052013                                                                                                               |               |                                    |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom                | Description                                                                                                       |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|--------------------------------|-------------------------------------------------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                                | Part Number                                                                                                       | Serial Number |                                    |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position               | HW                                                                                                                | SW            |                                    |             |                 |     |                  |             |                    |             | Manufacturer |
|                                | MM Ref                                                                                                            |               |                                    |             |                 |     |                  |             |                    |             | Date Type    |
|                                | Ops Number(s)                                                                                                     |               |                                    |             |                 |     |                  |             |                    |             |              |
| 321051                         | Main Landing Gear and Components (Right) - Detailed Inspection                                                    |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                                |                                                                                                                   |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                                |                                                                                                                   |               | MOS                                |             | 28.7            |     | 48               | 21 Dec 2023 | 31 Dec 2027        | 31 Jan 2028 |              |
|                                |                                                                                                                   |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe                       |                                                                                                                   |               | 052013                             |             |                 |     |                  |             |                    |             |              |
| 321052                         | Main Landing Gear Corrosion Inhibiting Compound Reapplication (Left)                                              |               | HRS                                |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                                |                                                                                                                   |               | AFL                                |             | 52              |     |                  | 1065        |                    |             | 0            |
|                                |                                                                                                                   |               | MOS                                |             | 5.4             |     | 24               | 29 Nov 2025 | 30 Nov 2027        | 31 Dec 2027 |              |
|                                |                                                                                                                   |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe                       |                                                                                                                   |               | 052011                             |             |                 |     |                  |             |                    |             |              |
| 321053                         | Main Landing Gear Corrosion Inhibiting Compound Reapplication (Right)                                             |               | HRS                                |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                                |                                                                                                                   |               | AFL                                |             | 52              |     |                  | 1065        |                    |             | 0            |
|                                |                                                                                                                   |               | MOS                                |             | 5.4             |     | 24               | 29 Nov 2025 | 30 Nov 2027        | 31 Dec 2027 |              |
|                                |                                                                                                                   |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe                       |                                                                                                                   |               | 052011                             |             |                 |     |                  |             |                    |             |              |
| 321200                         | Main Landing Gear Shock Absorber (Left) - Removal / Installation<br><br>C1A4200CA002                      GK0659  |               | HRS                                | TSN:1767.4  | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                                |                                                                                                                   |               | AFL                                | TSN:490     |                 |     |                  |             |                    |             | 0            |
|                                |                                                                                                                   |               | MOS                                |             | 29.2            |     |                  | 04 Dec 2023 |                    |             |              |
|                                |                                                                                                                   |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe                       |                                                                                                                   |               |                                    |             |                 |     |                  |             |                    |             |              |
| Notes: MRI PARENT CODE: 321208 |                                                                                                                   |               |                                    |             |                 |     |                  |             |                    |             |              |
| 321201                         | Main Landing Gear Shock Absorber (Right) - Removal / Installation<br><br>C1A4200CA002                      GK0271 |               | HRS                                |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                                |                                                                                                                   |               | AFL                                |             | 52              |     |                  | 1065        |                    |             | 0            |
|                                |                                                                                                                   |               | MOS                                |             | 4.8             |     |                  | 18 Dec 2025 |                    |             |              |
|                                |                                                                                                                   |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe                       |                                                                                                                   |               |                                    |             |                 |     |                  |             |                    |             |              |
| Notes: MRI PARENT CODE: 321209 |                                                                                                                   |               |                                    |             |                 |     |                  |             |                    |             |              |
| 321202                         | Main Gear Shock Strut Cylinder (Left) - Removal / Installation<br><br>C1A4200CA002                      GK0659    |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                                |                                                                                                                   |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                                |                                                                                                                   |               | MOS                                |             | 28.7            |     |                  | 21 Dec 2023 |                    |             |              |
|                                |                                                                                                                   |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe                       |                                                                                                                   |               |                                    |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom  | Description                                                                             |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-----------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                             | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                                      | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                                  |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| 321203           | Main Gear Shock Strut Cylinder (Right) - Removal / Installation                         |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  |                                                                                         |               | AFL |             | 315             |     |                  | 802         |                    |         | 0            |
|                  | C1A4200CA002                                                                            | GK0274        | MOS |             | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
|                  |                                                                                         |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                         |               |     |             |                 |     |                  |             |                    |         |              |
| 321204           | Main Landing Gear Side Brace Actuator Cylinder End CAP (Left) - Removal / Installation  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                         |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | C1M5601CA001                                                                            | PLT0248       | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                         |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                         |               |     |             |                 |     |                  |             |                    |         |              |
| 321205           | Main Landing Gear Side Brace Actuator Cylinder End CAP (Right) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                         |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | C1M5601CA001                                                                            | PLT0262       | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                         |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                         |               |     |             |                 |     |                  |             |                    |         |              |
| 321206           | Main Gear Shock Strut Metering Pin (Left) - Removal / Installation                      |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                         |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | C1M5221CA001                                                                            | NSN           | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                         |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                         |               |     |             |                 |     |                  |             |                    |         |              |
| 321207           | Main Gear Shock Strut Metering Pin (Right) - Removal / Installation                     |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                         |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | C1M5221CA001                                                                            | NSN           | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                         |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                         |               |     |             |                 |     |                  |             |                    |         |              |
| 321208           | Main Landing Gear Shock Absorber (Left) - Removal / Installation                        |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                         |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | C1A4200CA001                                                                            | GK0380        | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                         |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                         |               |     |             |                 |     |                  |             |                    |         |              |
| 321209           | Main Landing Gear Shock Absorber (Right) - Removal / Installation                       |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                         |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | C1A4200CA001                                                                            | GK0348        | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                         |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                         |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                                                        |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|--------------------------------------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                                                                                        | Serial Number |     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                                                                                 | SW            |     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                                                                             |               |     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                                                                                      |               |     |             |                 |     |                  |             |                     |         |              |
| 321211           | Upper Main Gear Shock Strut Attachment Pin (Left) - Removal / Installation                                         |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                                                                    |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | C1M5415CA002                                                                                                       | EXC0719       | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                                                                    |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                                                    |               |     |             |                 |     |                  |             |                     |         |              |
| 321212           | Lower Main Gear Shock Strut Attachment Pin (Left) - Removal / Installation                                         |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                                                                    |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | C1M5415CA002                                                                                                       | EXC0718       | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                                                                    |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                                                    |               |     |             |                 |     |                  |             |                     |         |              |
| 321213           | Upper Main Gear Shock Strut Attachment Pin (Right) - Removal / Installation                                        |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                                                                    |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | C1M5415CA002                                                                                                       | EXC0720       | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                                                                    |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                                                    |               |     |             |                 |     |                  |             |                     |         |              |
| 321214           | Lower Main Gear Shock Strut Attachment Pin (Right) - Removal / Installation                                        |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                                                                    |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | C1M5415CA002                                                                                                       | EXC0735       | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                                                                    |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                                                    |               |     |             |                 |     |                  |             |                     |         |              |
| 321215           | Main Gear Shock Strut Piston Assembly (Left) - Removal / Installation                                              |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                                                                    |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | C1A5201CA001                                                                                                       | GK0407        | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                                                                    |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                                                    |               |     |             |                 |     |                  |             |                     |         |              |
| 321216           | Main Gear Shock Strut Piston Assembly (Right) - Removal / Installation                                             |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                                                                    |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | C1A5201CA001                                                                                                       | GK0368        | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                                                                    |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                                                    |               |     |             |                 |     |                  |             |                     |         |              |
| 321235           | Main Landing Gear Shock Absorber Upper and Lower Attach Pins Corrosion Inhibiting Compound Application - Servicing |               | HRS |             | 137             |     |                  | 2909.1      |                     |         | 0            |
|                  |                                                                                                                    |               | AFL |             | 52              |     |                  | 1065        |                     |         | 0            |
|                  |                                                                                                                    |               | MOS |             | 4.8             |     |                  | 18 Dec 2025 |                     |         |              |
|                  |                                                                                                                    |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                                                    |               |     |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom                | Description                                                         |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|--------------------------------|---------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                | Part Number                                                         | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position               | HW                                                                  | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                | MM Ref                                                              |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                                | Ops Number(s)                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| 321236                         | Main Landing Gear Shock Absorber (Left) - Discard                   |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | C1A4200CA001                                                        | GK0380        | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                |                                                                     |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                                            |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Notes: MRI PARENT CODE: 321208 |                                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| 321237                         | Main Landing Gear Shock Absorber (Right) - Discard                  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | C1A4200CA001                                                        | GK0348        | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                |                                                                     |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                                            |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Notes: MRI PARENT CODE: 321209 |                                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| 321238                         | Main Landing Gear Shock Absorber Cylinder Body (Left) - Discard     |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                                     |               | AFL |             | 1117            |     | 20000            | 0           | 20000              |         | 0            |
|                                | C1M5210CA001                                                        | GK0385        | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 321202 |                                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| 321239                         | Main Landing Gear Shock Absorber Cylinder Body (Right) - Discard    |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                                     |               | AFL |             | 1117            |     | 20000            | 0           | 20000              |         | 0            |
|                                | C1M5210CA001                                                        | GK0353        | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 321203 |                                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| 321240                         | Main Landing Gear Shock Absorber Piston Machining (Left) - Discard  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                                     |               | AFL |             | 1117            |     | 20000            | 0           | 20000              |         | 0            |
|                                | C1A5201CA001                                                        | GK0407        | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 321215 |                                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| 321241                         | Main Landing Gear Shock Absorber Piston Machining (Right) - Discard |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                                     |               | AFL |             | 1117            |     | 20000            | 0           | 20000              |         | 0            |
|                                | C1A5201CA001                                                        | GK0368        | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 321216 |                                                                     |               |     |             |                 |     |                  |             |                    |         |              |



| ATA<br>U=Custom                | Description                                        |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|--------------------------------|----------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                | Part Number                                        | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position               | HW                                                 | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                | MM Ref                                             |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                                | Ops Number(s)                                      |               |     |             |                 |     |                  |             |                    |         |              |
| 321242                         | Main Landing Gear Shock Absorber Metering Pin      |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | Assembly (Left) - Discard                          |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                | C1M5221CA001                                       | NSN           | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                |                                                    |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                       |                                                    |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 321206 |                                                    |               |     |             |                 |     |                  |             |                    |         |              |
| 321243                         | Main Landing Gear Shock Absorber Metering Pin      |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | Assembly (Right) - Discard                         |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                | C1M5221CA001                                       | NSN           | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                |                                                    |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                       |                                                    |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 321207 |                                                    |               |     |             |                 |     |                  |             |                    |         |              |
| 321244                         | Main Landing Gear Shock Absorber Attach Pin (Left  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | Upper) - Discard                                   |               | AFL |             | 1117            |     | 20000            | 0           | 20000              |         | 0            |
|                                | C1M5415CA002                                       | EXC0719       | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                |                                                    |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                       |                                                    |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 321211 |                                                    |               |     |             |                 |     |                  |             |                    |         |              |
| 321245                         | Main Landing Gear Shock Absorber Attach Pin (Left  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | Lower) - Discard                                   |               | AFL |             | 1117            |     | 20000            | 0           | 20000              |         | 0            |
|                                | C1M5415CA002                                       | EXC0718       | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                |                                                    |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                       |                                                    |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 321212 |                                                    |               |     |             |                 |     |                  |             |                    |         |              |
| 321246                         | Main Landing Gear Shock Absorber Attach Pin (Right |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | Upper) - Discard                                   |               | AFL |             | 1117            |     | 20000            | 0           | 20000              |         | 0            |
|                                | C1M5415CA002                                       | EXC0720       | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                |                                                    |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                       |                                                    |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 321213 |                                                    |               |     |             |                 |     |                  |             |                    |         |              |
| 321247                         | Main Landing Gear Shock Absorber Attach Pin (Right |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | Lower) - Discard                                   |               | AFL |             | 1117            |     | 20000            | 0           | 20000              |         | 0            |
|                                | C1M5415CA002                                       | EXC0735       | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                |                                                    |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                       |                                                    |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 321214 |                                                    |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom                | Description                                            |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|--------------------------------|--------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                | Part Number                                            | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position               | HW                                                     | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                | MM Ref                                                 |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                                | Ops Number(s)                                          |               |     |             |                 |     |                  |             |                    |         |              |
| 321248                         | Main Landing Gear Side Brace Actuator Cylinder End     |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | CAP (Left) - Discard                                   |               | AFL |             | 1117            |     | 20000            | 0           | 20000              |         | 0            |
|                                | C1M5601CA001                                           | PLT0248       | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 321204 |                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 321249                         | Main Landing Gear Side Brace Actuator Cylinder End     |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | CAP (Right) - Discard                                  |               | AFL |             | 1117            |     | 20000            | 0           | 20000              |         | 0            |
|                                | C1M5601CA001                                           | PLT0262       | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 321205 |                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 321300                         | Main Landing Gear Axle Fitting Pin (Left) - Removal /  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | Installation                                           |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                | C1A5425CA001                                           | EXC0361       | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| O/C                            |                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                       |                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 321301                         | Main Landing Gear Axle Fitting Pin (Right) - Removal / |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | Installation                                           |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                | C1A5425CA001                                           | EXC0339       | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| O/C                            |                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                       |                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 321303                         | Main Landing Gear Axle Fitting (Left) - Removal /      |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                                | Installation                                           |               | AFL |             |                 |     |                  |             |                    |         | 0            |
|                                | C1A5400CA001                                           | ZKM0253       | MOS |             | 29.2            |     |                  | 04 Dec 2023 |                    |         |              |
| O/C                            |                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                       |                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 321304                         | Main Landing Gear Axle Fitting (Right) - Removal /     |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                                | Installation                                           |               | AFL |             | 315             |     |                  | 802         |                    |         | 0            |
|                                | C1A5400CA001                                           | ZKM0251       | MOS |             | 28.8            |     |                  | 18 Dec 2023 |                    |         |              |
| O/C                            |                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                       |                                                        |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom                                          | Description                                                                                                                |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|----------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|----------|--------------------|---------|--------------|
|                                                          | Part Number                                                                                                                | Serial Number |     |             |                 |     |                  |          |                    |         | Approx Price |
| Logbook Position                                         | HW                                                                                                                         | SW            |     |             |                 |     |                  |          |                    |         | Manufacturer |
|                                                          | MM Ref                                                                                                                     |               |     |             |                 |     |                  |          |                    |         | Date Type    |
|                                                          | Ops Number(s)                                                                                                              |               |     |             |                 |     |                  |          |                    |         |              |
| 321305                                                   | Main Landing Gear Axle Fitting and Axle Fitting Nut (Left Inboard) Corrosion Inhibiting Compound Application - Servicing   |               | HRS |             | 559.7           |     |                  | 2486.4   |                    |         | 0            |
|                                                          |                                                                                                                            |               | AFL |             | 214             |     |                  | 903      |                    | 0       |              |
|                                                          |                                                                                                                            |               | MOS |             | 16.8            |     | 18 Dec 2024      |          |                    |         |              |
|                                                          |                                                                                                                            |               | MSC |             |                 | O/C |                  |          |                    |         |              |
| Airframe                                                 |                                                                                                                            |               |     |             |                 |     |                  |          |                    |         |              |
| 321306                                                   | Main Landing Gear Axle Fitting and Axle Fitting Nut (Right Outboard) Corrosion Inhibiting Compound Application - Servicing |               | HRS |             | 251.5           |     |                  | 2794.6   |                    |         | 0            |
|                                                          |                                                                                                                            |               | AFL |             | 95              |     |                  | 1022     |                    | 0       |              |
|                                                          |                                                                                                                            |               | MOS |             | 8.4             |     | 31 Aug 2025      |          |                    |         |              |
|                                                          |                                                                                                                            |               | MSC |             |                 | O/C |                  |          |                    |         |              |
| Airframe                                                 |                                                                                                                            |               |     |             |                 |     |                  |          |                    |         |              |
| 321307                                                   | Main Landing Gear Axle Fitting and Axle Fitting Nut (Right Inboard) Corrosion Inhibiting Compound Application - Servicing  |               | HRS |             | 730.5           |     |                  | 2315.6   |                    |         | 0            |
|                                                          |                                                                                                                            |               | AFL |             | 315             |     |                  | 802      |                    | 0       |              |
|                                                          |                                                                                                                            |               | MOS |             | 28.8            |     | 18 Dec 2023      |          |                    |         |              |
|                                                          |                                                                                                                            |               | MSC |             |                 | O/C |                  |          |                    |         |              |
| Airframe                                                 |                                                                                                                            |               |     |             |                 |     |                  |          |                    |         |              |
| Notes: PN: C1A4400CA001 SN: NSN. MRI PARENT CODE: 321303 |                                                                                                                            |               |     |             |                 |     |                  |          |                    |         |              |
| 321308                                                   | Main Landing Gear Axle Fitting Attach Pin (Right) Corrosion Inhibiting Compound Application - Servicing                    |               | HRS |             | 730.5           |     |                  | 2315.6   |                    |         | 0            |
|                                                          |                                                                                                                            |               | AFL |             | 315             |     |                  | 802      |                    | 0       |              |
|                                                          |                                                                                                                            |               | MOS |             | 28.8            |     | 18 Dec 2023      |          |                    |         |              |
|                                                          |                                                                                                                            |               | MSC |             |                 | O/C |                  |          |                    |         |              |
| Airframe                                                 |                                                                                                                            |               |     |             |                 |     |                  |          |                    |         |              |
| Notes: PN: C1A4400CA001 SN: NSN. MRI PARENT CODE: 321304 |                                                                                                                            |               |     |             |                 |     |                  |          |                    |         |              |
| 321309                                                   | Main Landing Gear Axle Fitting Attach Pin (Left) Corrosion Inhibiting Compound Application - Servicing                     |               | HRS |             | 730.5           |     |                  | 2315.6   |                    |         | 0            |
|                                                          |                                                                                                                            |               | AFL |             |                 |     |                  |          | 0                  |         |              |
|                                                          |                                                                                                                            |               | MOS |             | 29.2            |     | 04 Dec 2023      |          |                    |         |              |
|                                                          |                                                                                                                            |               | MSC |             |                 | O/C |                  |          |                    |         |              |
| Airframe                                                 |                                                                                                                            |               |     |             |                 |     |                  |          |                    |         |              |
| 321310                                                   | Main Landing Gear Axle Fitting and Axle Fitting Nut (Left Outboard) Corrosion Inhibiting Compound Application - Servicing  |               | HRS |             | 730.5           |     |                  | 2315.6   |                    |         | 0            |
|                                                          |                                                                                                                            |               | AFL |             |                 |     |                  |          | 0                  |         |              |
|                                                          |                                                                                                                            |               | MOS |             | 29.2            |     | 04 Dec 2023      |          |                    |         |              |
|                                                          |                                                                                                                            |               | MSC |             |                 | O/C |                  |          |                    |         |              |
| Airframe                                                 |                                                                                                                            |               |     |             |                 |     |                  |          |                    |         |              |

| ATA<br>U=Custom                | Description                                              |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|--------------------------------|----------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                | Part Number                                              | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position               | HW                                                       | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                | MM Ref                                                   |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                                | Ops Number(s)                                            |               |     |             |                 |     |                  |             |                    |         |              |
| 321311                         | Main Landing Gear Axle Fitting (Left) - Discard          |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | C1A4400CA001                                             | NSN           | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                |                                                          |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Notes: MRI PARENT CODE: 321303 |                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| 321312                         | Main Landing Gear Axle Fitting (Right) - Discard         |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | C1A4400CA001                                             | NSN           | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                |                                                          |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Notes: MRI PARENT CODE: 321304 |                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| 321313                         | Main Landing Gear Knee Joint Pin (Left) - Discard        |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | C1A5425CA001                                             | EXC0361       | AFL |             | 1117            |     | 20000            | 0           | 20000              |         | 0            |
|                                |                                                          |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                                 |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 321300 |                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| 321314                         | Main Landing Gear Knee Joint Pin (Right) - Discard       |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | C1A5425CA001                                             | EXC0339       | AFL |             | 1117            |     | 20000            | 0           | 20000              |         | 0            |
|                                |                                                          |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                                 |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 321301 |                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| 321400                         | Main Landing Gear Side Brace Actuator Fuse Pin Link      |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | Assembly (Left) - Removal / Installation                 |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                | 60P3215911M001                                           | SN-UNKNOWN    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 321401                         | Main Landing Gear Side Brace Actuator Fuse Pin Link      |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | Assembly (Right) - Removal / Installation                |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                | 60P3215911M001                                           | SN-UNKNOWN    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 321402                         | Main Landing Gear Side Brace Actuator (Left) - Removal / |               | HRS | TSN:1763.28 | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                                | Installation                                             |               | AFL |             |                 |     |                  |             |                    |         | 0            |
|                                | 60P3214000Z009                                           | PLT0586       | MOS | TSN:67      | 29.2            |     |                  | 04 Dec 2023 |                    |         |              |
|                                | Airframe                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                            |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                            | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                     | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                 |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| 321403           | Main Landing Gear Side Brace Actuator (Right) - Removal / Installation |               | HRS | TSN:1103.18 | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  |                                                                        |               | AFL | TSN:392     | 315             |     |                  | 802         |                    |         | 0            |
|                  | 60P3214000Z009                                                         | PLT0394       | MOS | TSN:88      | 28.8            |     |                  | 18 Dec 2023 |                    |         |              |
|                  |                                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 321404           | Main Landing Gear Spindle Pin (Left) - Removal / Installation          |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  |                                                                        |               | AFL |             |                 |     |                  |             |                    |         | 0            |
|                  | C1A5315CA002                                                           | EXC0360       | MOS |             | 29.2            |     |                  | 04 Dec 2023 |                    |         |              |
|                  |                                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 321405           | Main Landing Gear Spindle Pin (Right) - Removal / Installation         |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  |                                                                        |               | AFL |             | 315             |     |                  | 802         |                    |         | 0            |
|                  | C1A5315CA002                                                           | EXC0357       | MOS |             | 28.8            |     |                  | 18 Dec 2023 |                    |         |              |
|                  |                                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 321408           | Side Brace Fitting (Left) - Removal / Installation                     |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                        |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P3215103M006                                                         | 0082          | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 321409           | Side Brace Fitting (Right) - Removal / Installation                    |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                        |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P3215104M005                                                         | 000125        | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 321410           | Side Brace Fitting Assembly (Left) - Removal / Installation            |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                        |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P3215003A005-01A                                                     | 0082          | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 321411           | Side Brace Fitting Assembly (Right) - Removal / Installation           |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                        |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P3215004A004-02A                                                     | 000125        | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                        |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                 |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-----------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                 | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                          | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                      |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                               |               |     |             |                 |     |                  |             |                    |         |              |
| 321412           | Outboard Side Brace Fitting (Left) - Removal / Installation                 |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P3215805M006-01A                                                          | H20495-7-2    | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                             |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                                    |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 321413           | Outboard Side Brace Fitting (Right) - Removal / Installation                |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P3215806M004-01A                                                          | H20495-1-2    | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                             |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                                    |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 321416           | Main Landing Gear Side Brace Upper Tie ROD (Left) - Removal / Installation  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P3215901M001                                                              | SN-UNKNOWN    | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                             |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                                    |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 321417           | Main Landing Gear Side Brace Upper Tie ROD (Right) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P3215901M001                                                              | SN-UNKNOWN    | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                             |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                                    |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 321420           | Main Landing Gear Fuse Pin Link Assembly (Left) - Removal / Installation    |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P3215833A001                                                              | SN-UNKNOWN    | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                             |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                                    |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 321421           | Main Landing Gear Fuse Pin Link Assembly (Right) - Removal / Installation   |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P3215833A001                                                              | SN-UNKNOWN    | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                             |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                                    |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 321428           | Main Landing Gear Side Brace Fitting Pin (Left) - Removal / Installation    |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | C1M5640CA001                                                                | EXC0353       | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                             |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                                    |               | MSC |             |                 |     | O/C              |             |                    |         |              |

| ATA<br>U=Custom                | Description                                                                                                              |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|--------------------------------|--------------------------------------------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                | Part Number                                                                                                              | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position               | HW                                                                                                                       | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                | MM Ref                                                                                                                   |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                                | Ops Number(s)                                                                                                            |               |     |             |                 |     |                  |             |                    |         |              |
| 321429                         | Main Landing Gear Side Brace Fitting Pin (Right) - Removal / Installation                                                |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                                                                                          |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                | C1M5640CA001                                                                                                             | EXC0340       | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                |                                                                                                                          |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                       |                                                                                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| 321432                         | Main Landing Gear Side Brace Actuator Attach Pins / Trunnion AREA Corrosion Inhibiting Coumpound Application - Servicing |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                                |                                                                                                                          |               | AFL |             |                 |     |                  |             |                    |         | 0            |
|                                |                                                                                                                          |               | MOS |             | 28.8            |     |                  | 18 Dec 2023 |                    |         |              |
|                                |                                                                                                                          |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                       |                                                                                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| 321433                         | Main Landing Gear Spindle Pin (Left) - Discard                                                                           |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | C1A5315CA002                                                                                                             | EXC0360       | AFL |             | 1117            |     | 20000            | 0           | 20000              |         | 0            |
|                                |                                                                                                                          |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                |                                                                                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                       |                                                                                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 321404 |                                                                                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| 321434                         | Main Landing Gear Spindle Pin (Right) - Discard                                                                          |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | C1A5315CA002                                                                                                             | EXC0357       | AFL |             | 1117            |     | 20000            | 0           | 20000              |         | 0            |
|                                |                                                                                                                          |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                |                                                                                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                       |                                                                                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 321405 |                                                                                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| 321435                         | Main Landing Gear Side Brace Actuator (Left) - Discard                                                                   |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | 60P3214000Z007                                                                                                           | PLT0241       | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                |                                                                                                                          |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                |                                                                                                                          |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                       |                                                                                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 321402 |                                                                                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| 321436                         | Main Landing Gear Side Brace Actuator (Right) - Discard                                                                  |               | HRS | TSN:533     | 1300.7          |     |                  | 1745.4      |                    |         | 0            |
|                                | 60P3214000Z007                                                                                                           | PLT0394       | AFL | TSN:200     | 507             |     |                  | 610         |                    |         | 0            |
|                                |                                                                                                                          |               | MOS |             | 51.3            |     |                  | 02 Feb 2022 |                    |         |              |
|                                |                                                                                                                          |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                       |                                                                                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 321403 |                                                                                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| 321437                         | Main Landing Gear Side Brace Fitting Pin (Left) - Discard                                                                |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | C1M5640CA001                                                                                                             | EXC0353       | AFL |             | 1117            |     | 20000            | 0           | 20000              |         | 0            |
|                                |                                                                                                                          |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                |                                                                                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                       |                                                                                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 321428 |                                                                                                                          |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom                | Description                                                             |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|--------------------------------|-------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                                | Part Number                                                             | Serial Number |     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position               | HW                                                                      | SW            |     |             |                 |     |                  |             |                     |         | Manufacturer |
|                                | MM Ref                                                                  |               |     |             |                 |     |                  |             |                     |         | Date Type    |
|                                | Ops Number(s)                                                           |               |     |             |                 |     |                  |             |                     |         |              |
| 321438                         | Main Landing Gear Side Brace Fitting Pin (Right) - Discard              |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                                |                                                                         |               | AFL |             | 1117            |     | 20000            | 0           | 20000               |         | 0            |
|                                | C1M5640CA001                                                            | EXC0340       | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
| Airframe                       |                                                                         |               |     |             |                 |     |                  |             |                     |         |              |
| Notes: MRI PARENT CODE: 321429 |                                                                         |               |     |             |                 |     |                  |             |                     |         |              |
| 321443                         | Main Landing Gear Side Brace Pin (Lh) (Upper) - Discard                 |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                                | 60P3215911M001                                                          | SN-UNKNOWN    | AFL |             | 1117            |     | 20000            | 0           | 20000               |         | 0            |
|                                |                                                                         |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
| Airframe                       |                                                                         |               |     |             |                 |     |                  |             |                     |         |              |
| 321445                         | Main Landing Gear Side Brace Pin (Rh) (Upper)- Discard                  |               | HRS |             | 730.5           |     |                  | 2315.6      |                     |         | 0            |
|                                | 60P3215911M004                                                          | GMI00707      | AFL |             | 315             |     | 20000            | 802         | 20802               |         | 0            |
|                                |                                                                         |               | MOS | TSN:6       | 28.7            |     |                  | 21 Dec 2023 |                     |         |              |
| Airframe                       |                                                                         |               |     |             |                 |     |                  |             |                     |         |              |
| 321500                         | Main Landing Gear Trunnion Pin (Left Forward) - Removal / Installation  |               | HRS |             | 730.5           |     |                  | 2315.6      |                     |         | 0            |
|                                | C1A5310CA002                                                            | EXC0343       | AFL |             |                 |     |                  |             |                     |         | 0            |
|                                |                                                                         |               | MOS |             | 29.2            |     |                  | 04 Dec 2023 |                     |         |              |
|                                |                                                                         |               |     |             |                 |     | O/C              |             |                     |         |              |
| Airframe                       |                                                                         |               |     |             |                 |     |                  |             |                     |         |              |
| 321501                         | Main Landing Gear Trunnion Pin (Left Aft) - Removal / Installation      |               | HRS |             | 730.5           |     |                  | 2315.6      |                     |         | 0            |
|                                | C1A5311CA002                                                            | EXC0358       | AFL |             |                 |     |                  |             |                     |         | 0            |
|                                |                                                                         |               | MOS |             | 29.2            |     |                  | 04 Dec 2023 |                     |         |              |
|                                |                                                                         |               |     |             |                 |     | O/C              |             |                     |         |              |
| Airframe                       |                                                                         |               |     |             |                 |     |                  |             |                     |         |              |
| 321502                         | Main Landing Gear Trunnion Pin (Right Forward) - Removal / Installation |               | HRS |             | 730.5           |     |                  | 2315.6      |                     |         | 0            |
|                                | C1A5310CA002                                                            | EXC0346       | AFL |             | 315             |     |                  | 802         |                     |         | 0            |
|                                |                                                                         |               | MOS |             | 30.5            |     |                  | 25 Oct 2023 |                     |         |              |
|                                |                                                                         |               |     |             |                 |     | O/C              |             |                     |         |              |
| Airframe                       |                                                                         |               |     |             |                 |     |                  |             |                     |         |              |
| 321503                         | Main Landing Gear Trunnion Pin (Right Aft) - Removal / Installation     |               | HRS |             | 730.5           |     |                  | 2315.6      |                     |         | 0            |
|                                | C1A5311CA002                                                            | EXC0359       | AFL |             | 315             |     |                  | 802         |                     |         | 0            |
|                                |                                                                         |               | MOS |             | 30.5            |     |                  | 25 Oct 2023 |                     |         |              |
|                                |                                                                         |               |     |             |                 |     | O/C              |             |                     |         |              |
| Airframe                       |                                                                         |               |     |             |                 |     |                  |             |                     |         |              |



| ATA<br>U=Custom                | Description                                                                    |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|--------------------------------|--------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                | Part Number                                                                    | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position               | HW                                                                             | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                | MM Ref                                                                         |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                                | Ops Number(s)                                                                  |               |     |             |                 |     |                  |             |                    |         |              |
| 321508                         | Main Landing Gear Forward Trunnion Pin (Left) - Discard                        |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | C1A5310CA002                                                                   | EXC0343       | AFL |             | 1117            |     | 20000            | 0           | 20000              |         | 0            |
|                                |                                                                                |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 321500 |                                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| 321509                         | Main Landing Gear Aft Trunnion Pin (Left) - Discard                            |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | C1A5311CA002                                                                   | EXC0358       | AFL |             | 1117            |     | 20000            | 0           | 20000              |         | 0            |
|                                |                                                                                |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 321501 |                                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| 321510                         | Main Landing Gear Forward Trunnion Pin (Right) - Discard                       |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | C1A5310CA002                                                                   | EXC0346       | AFL |             | 1117            |     | 20000            | 0           | 20000              |         | 0            |
|                                |                                                                                |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 321502 |                                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| 321511                         | Main Landing Gear Aft Trunnion Pin (Right) - Discard                           |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | C1A5311CA002                                                                   | EXC0359       | AFL |             | 1117            |     | 20000            | 0           | 20000              |         | 0            |
|                                |                                                                                |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 321503 |                                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| 321600                         | Main Landing Gear Electrical Harness (Left Outboard) - Removal / Installation  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | C1E5906CA002                                                                   | ICO00228      | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                |                                                                                |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| 321601                         | Main Landing Gear Electrical Harness (Right Outboard) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | C1E5908CA002                                                                   | ICO00218      | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                |                                                                                |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| 321604                         | Main Landing Gear Electrical Harness (Left Inboard) - Removal / Installation   |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | C1E5903CA004                                                                   | ICO00215      | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                |                                                                                |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                                                |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom                | Description                                                                   |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|--------------------------------|-------------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                                | Part Number                                                                   | Serial Number |                                    |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position               | HW                                                                            | SW            |                                    |             |                 |     |                  |             |                    |             | Manufacturer |
|                                | MM Ref                                                                        |               |                                    |             |                 |     |                  |             |                    |             | Date Type    |
|                                | Ops Number(s)                                                                 |               |                                    |             |                 |     |                  |             |                    |             |              |
| 321605                         | Main Landing Gear Electrical Harness (Right Inboard) - Removal / Installation |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                                |                                                                               |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                                | C1E5907CA002                                                                  | ICO00225      | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                                |                                                                               |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe                       |                                                                               |               |                                    |             |                 |     |                  |             |                    |             |              |
| 321800                         | Main Landing Gear Door Control Links (Left) - Removal / Installation          |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                                |                                                                               |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                                | 60P5280332A001                                                                | SN-UNKNOWN    | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                                |                                                                               |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe                       |                                                                               |               |                                    |             |                 |     |                  |             |                    |             |              |
| 321801                         | Main Landing Gear Door Control Links (Right) - Removal / Installation         |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                                |                                                                               |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                                | 60P5280332A007                                                                | SN-UNKNOWN    | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                                |                                                                               |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe                       |                                                                               |               |                                    |             |                 |     |                  |             |                    |             |              |
| 322000                         | Nose Landing Gear - Removal / Installation                                    |               | HRS                                | TSN:18.4    | 3023            |     |                  | 23.1        |                    |             | 0            |
|                                | 60P3222010A009                                                                | GLG0179       | AFL                                | TSN:5       | 1109            |     |                  | 8           |                    |             | 0            |
|                                |                                                                               |               | MOS                                | TSN:6       | 122.9           |     |                  | 13 Feb 2016 |                    |             |              |
|                                |                                                                               |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe                       |                                                                               |               |                                    |             |                 |     |                  |             |                    |             |              |
| 322002                         | Nose Landing Gear - Restore                                                   |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                                | 60P3222010A009                                                                | GLG0179       | AFL                                |             | 1117            |     | 10000            | 0           | 10000              |             | 0            |
|                                |                                                                               |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                                |                                                                               |               |                                    |             |                 |     |                  |             |                    |             |              |
| Airframe                       |                                                                               |               |                                    |             |                 |     |                  |             |                    |             |              |
| Notes: MRI PARENT CODE: 322000 |                                                                               |               |                                    |             |                 |     |                  |             |                    |             |              |
| 322004                         | Nose Landing Gear Components - Detailed Inspection                            |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                                |                                                                               |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                                |                                                                               |               | MOS                                |             | 28.7            |     | 48               | 21 Dec 2023 | 31 Dec 2027        | 31 Jan 2028 |              |
|                                |                                                                               |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe                       |                                                                               |               |                                    |             |                 |     |                  |             |                    |             |              |
| 052013                         |                                                                               |               |                                    |             |                 |     |                  |             |                    |             |              |
| 322005                         | Nose Landing Gear Corrosion Inhibiting Compound Reapplication                 |               | HRS                                |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                                |                                                                               |               | AFL                                |             | 52              |     |                  | 1065        |                    |             | 0            |
|                                |                                                                               |               | MOS                                |             | 5.5             |     | 24               | 27 Nov 2025 | 30 Nov 2027        | 31 Dec 2027 |              |
|                                |                                                                               |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe                       |                                                                               |               |                                    |             |                 |     |                  |             |                    |             |              |
| 052011                         |                                                                               |               |                                    |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom  | Description                                             |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|---------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                             | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                      | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                  |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                           |               |     |             |                 |     |                  |             |                    |         |              |
| 322006           | Nose Landing Gear Door (Left) - Removal / Installation  |               | HRS | TSN:23.1    | 3023            |     |                  | 23.1        |                    |         | 0            |
|                  | 60P5280111A020                                          | 6160          | AFL | TSN:8       | 1109            |     |                  | 8           |                    |         | 0            |
|                  |                                                         |               | MOS | TSN:6       | 123             |     |                  | 10 Feb 2016 |                    |         |              |
|                  | Airframe                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 322007           | Nose Landing Gear Door (Right) - Removal / Installation |               | HRS |             | 3023            |     |                  | 23.1        |                    |         | 0            |
|                  | 60P5280121A020                                          | 6160          | AFL |             | 1109            |     |                  | 8           |                    |         | 0            |
|                  |                                                         |               | MOS |             | 123             |     |                  | 10 Feb 2016 |                    |         |              |
|                  | Airframe                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 322008           | Nose Landing Gear Downlock Swivel (Lh)                  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | LSA14-14J4S                                             | SN-UNKNOWN    | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                         |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 322009           | Nose Landing Gear Downlock Swivel (Rh)                  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | PSA14-14J4S                                             | SN-UNKNOWN    | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                         |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 322010           | Nose Landing Gear Fairing Door - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P5280131A019P01                                       | G0192457601   | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                         |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 322012           | Nose Landing Gear - Rigging / Adjustment                |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                         |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                         |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 322013           | Nose Landing Gear Door - Rigging / Adjustment           |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                         |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                         |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 322014           | Nose Landing Gear Fairing Door - Rigging / Adjustment   |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                         |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                         |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |

| ATA<br>U=Custom                | Description                                                 |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|--------------------------------|-------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                | Part Number                                                 | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position               | HW                                                          | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                | MM Ref                                                      |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                                | Ops Number(s)                                               |               |     |             |                 |     |                  |             |                    |         |              |
| 322200                         | Nose Landing Gear Shock Absorber - Removal / Installation   |               | HRS | TSN:125.4   | 2549.5          |     |                  | 496.6       |                    |         | 0            |
|                                |                                                             |               | AFL | TSN:41      | 979             |     |                  | 138         |                    |         | 0            |
|                                | C2A4200CA006                                                | PLT0211       | MOS | TSN:6       | 103             |     |                  | 11 Oct 2017 |                    |         |              |
|                                |                                                             |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                       |                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 322202                         | Nose Landing Gear Shock Absorber and Axle Assembly          |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                                | Corrosion Inhibiting Compound Application                   |               | AFL |             | 315             |     |                  | 802         |                    |         | 0            |
|                                |                                                             |               | MOS |             | 30.7            |     |                  | 20 Oct 2023 |                    |         |              |
|                                |                                                             |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                       |                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 322203                         | Nose Landing Gear Shock Absorber - Discard                  |               | HRS | TSN:125.4   | 2549.5          |     |                  | 496.6       |                    |         | 0            |
|                                | C2A4200CA006                                                | PLT0211       | AFL | TSN:41      | 979             |     |                  | 138         |                    |         | 0            |
|                                |                                                             |               | MOS | TSN:6       | 103             |     |                  | 11 Oct 2017 |                    |         |              |
|                                |                                                             |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                       |                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 322200 |                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 322205                         | Nose Landing Gear Upper Torsion Link Attach Pin - Discard   |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                             |               | AFL |             | 1117            |     | 20000            | 0           | 20000              |         | 0            |
|                                | C2E5251CA001                                                | SN-UNKNOWN    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                |                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                       |                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 322206                         | Nose Landing Gear Upper Torque ARM - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                             |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                | PN                                                          | SN-UNKNOWN    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                |                                                             |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                       |                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 322207                         | Nose Landing Gear Lower Torque ARM - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                             |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                | C2M5203CA001                                                | SN-UNKNOWN    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                |                                                             |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                       |                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 322212                         | Upper Torsion Link, Machined - Removal / Installation       |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | C2M5202CA001                                                | SN-UNKNOWN    | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                |                                                             |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                |                                                             |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                       |                                                             |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                          |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|--------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                          | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                                   | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                               |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 322213           | Lower Torsion Link, Machined - Removal / Installation                                |               | HRS |             | 3041.4          |     |                  | 4.7         |                    |         | 0            |
|                  | C2M5203CA001                                                                         | PLT190158     | AFL |             | 1114            |     |                  | 3           |                    |         | 0            |
|                  |                                                                                      |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                                             |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 322300           | Nose Landing Gear Axle Assembly - Removal / Installation                             |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | C2A5201CA001                                                                         | SN-UNKNOWN    | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                      |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                                             |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 322401           | Nose Landing Gear Aft Truss Brace - Removal / Installation                           |               | HRS |             | 3041.4          |     |                  | 4.7         |                    |         | 0            |
|                  | C2A5413CA001                                                                         | PLT190146     | AFL |             | 1114            |     |                  | 3           |                    |         | 0            |
|                  |                                                                                      |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                                             |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 322402           | Nose Landing Gear Truss Brace / Trunnion Attach Pin (Left) - Removal / Installation  |               | HRS |             | 3023            |     |                  | 23.1        |                    |         | 0            |
|                  | C2M5423CA001                                                                         | PLT291153     | AFL |             | 1109            |     |                  | 8           |                    |         | 0            |
|                  |                                                                                      |               | MOS | TSN:30      | 122.8           |     |                  | 16 Feb 2016 |                    |         |              |
|                  | Airframe                                                                             |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 322403           | Nose Landing Gear Truss Brace / Trunnion Attach Pin (Right) - Removal / Installation |               | HRS |             | 3041.4          |     |                  | 4.7         |                    |         | 0            |
|                  | C2M5423CA001                                                                         | PLT420377     | AFL |             | 1114            |     |                  | 3           |                    |         | 0            |
|                  |                                                                                      |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                                             |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 322405           | Nose Landing Gear Truss Brace Forward Link Assembly - Removal / Installation         |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | C2M5404CA001                                                                         | SN-UNKNOWN    | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                      |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                                             |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 322406           | Nose Landing Gear Truss Brace Aft Link Assembly - Removal / Installation             |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | C2M5408CA001                                                                         | SN-UNKNOWN    | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                      |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                                             |               | MSC |             |                 |     | O/C              |             |                    |         |              |

| ATA<br>U=Custom                | Description                                           |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|--------------------------------|-------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                | Part Number                                           | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position               | HW                                                    | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                | MM Ref                                                |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                                | Ops Number(s)                                         |               |     |             |                 |     |                  |             |                    |         |              |
| 322407                         | Nose Landing Gear Trunnion - Removal / Installation   |               | HRS |             | 3041.4          |     |                  | 4.7         |                    |         | 0            |
|                                | C2A4300CA001                                          | PLT0192       | AFL |             | 1114            |     |                  | 3           |                    |         | 0            |
|                                |                                                       |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                              |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 322409                         | Nose Landing Gear Upper Drag Brace Attach Pin         |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                                | Corrosion Inhibiting Compound Application             |               | AFL |             | 315             |     |                  | 802         |                    |         | 0            |
|                                |                                                       |               | MOS |             | 30.7            |     |                  | 20 Oct 2023 |                    |         |              |
|                                | Airframe                                              |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 322410                         | Nose Landing Gear Truss Brace Assembly Corrosion      |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                                | Inhibiting Compound Application                       |               | AFL |             | 315             |     |                  | 802         |                    |         | 0            |
|                                |                                                       |               | MOS |             | 30.7            |     |                  | 20 Oct 2023 |                    |         |              |
|                                | Airframe                                              |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 322411                         | Nose Landing Gear Forward Truss Brace - Removal /     |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                                | Installation                                          |               | AFL |             | 315             |     |                  | 802         |                    |         | 0            |
|                                | C2M5400CA001                                          | PLT190144     | MOS |             | 30.7            |     |                  | 20 Oct 2023 |                    |         |              |
|                                | Airframe                                              |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 322413                         | Nose Landing Gear Truss Brace Forward Machining -     |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | Discard                                               |               | AFL |             | 1117            |     | 20000            | 0           | 20000              |         | 0            |
|                                | C2M5400CA001                                          | PLT190144     | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                              |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 322411 |                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| 322416                         | Nose Landing Gear Truss Brace Apex Pin (Left) -       |               | HRS |             | 3041.4          |     |                  | 4.7         |                    |         | 0            |
|                                | Removal / Installation                                |               | AFL |             | 1114            |     |                  | 3           |                    |         | 0            |
|                                | C2M5423CA001                                          | PLT420376     | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                              |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 322418                         | Nose Landing Gear Drag Brace - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | C2M4601CA001                                          | NSN           | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                |                                                       |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                              |               | MSC |             |                 |     | O/C              |             |                    |         |              |

| ATA<br>U=Custom                | Description                                                                  |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|--------------------------------|------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                | Part Number                                                                  | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position               | HW                                                                           | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                | MM Ref                                                                       |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                                | Ops Number(s)                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| 322420                         | Nose Landing Gear Trunnion Assembly Corrosion                                |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                                | Inhibiting Compound Application                                              |               | AFL |             | 315             |     |                  | 802         |                    |         | 0            |
|                                |                                                                              |               | MOS |             | 30.7            |     |                  | 20 Oct 2023 |                    |         |              |
|                                |                                                                              |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                       |                                                                              |               |     |             |                 |     |                  |             |                    |         |              |
| 322421                         | Nose Landing Gear Trunnion Fitting - Ndt Inspection                          |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                                              |               | AFL |             | 1117            |     | 11140**          | 0           | 11140              |         | 0            |
|                                |                                                                              |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                                              |               |     |             |                 |     |                  |             |                    |         |              |
| 322423                         | Nose Landing Gear Drag Brace Fitting Lug - Ndt Inspection                    |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                                              |               | AFL |             | 1117            |     | 13830**          | 0           | 13830              |         | 0            |
|                                |                                                                              |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                                              |               |     |             |                 |     |                  |             |                    |         |              |
| 322426                         | Nose Landing Gear Cylinder / Trunnion Attach Pin - Removal / Installation    |               | HRS |             | 3041.4          |     |                  | 4.7         |                    |         | 0            |
|                                |                                                                              |               | AFL |             | 1114            |     |                  | 3           |                    |         | 0            |
|                                | C2M5312CA001                                                                 | PLT420077     | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                |                                                                              |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                       |                                                                              |               |     |             |                 |     |                  |             |                    |         |              |
| 322428                         | Nose Landing Gear Cylinder / Trunnion Attach Pin - Discard                   |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                                              |               | AFL |             | 1117            |     | 20000            | 0           | 20000              |         | 0            |
|                                | C2M5312CA001                                                                 | PLT420077     | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                                              |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 322426 |                                                                              |               |     |             |                 |     |                  |             |                    |         |              |
| 322429                         | Nose Landing Gear Truss Brace Aft Machining - Discard                        |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | C2A5413CA001                                                                 | PLT190146     | AFL |             | 1117            |     | 20000            | 0           | 20000              |         | 0            |
|                                |                                                                              |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                                              |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 322401 |                                                                              |               |     |             |                 |     |                  |             |                    |         |              |
| 322430                         | Nose Landing Gear Drag Brace / Aft Truss Attach Pin - Removal / Installation |               | HRS |             | 3041.4          |     |                  | 4.7         |                    |         | 0            |
|                                |                                                                              |               | AFL |             | 1114            |     |                  | 3           |                    |         | 0            |
|                                | C2M5421CA001                                                                 | PLT420090     | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                |                                                                              |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                       |                                                                              |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom                | Description                                                     |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|--------------------------------|-----------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                                | Part Number                                                     | Serial Number |     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position               | HW                                                              | SW            |     |             |                 |     |                  |             |                     |         | Manufacturer |
|                                | MM Ref                                                          |               |     |             |                 |     |                  |             |                     |         | Date Type    |
|                                | Ops Number(s)                                                   |               |     |             |                 |     |                  |             |                     |         |              |
| 322432                         | Nose Landing Gear Drag Brace Upper Attach Pin - Discard         |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                                |                                                                 |               | AFL |             | 1117            |     | 20000            | 0           | 20000               |         | 0            |
|                                | C2M5421CA001                                                    | PLT420090     | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
| Airframe                       |                                                                 |               |     |             |                 |     |                  |             |                     |         |              |
| Notes: MRI PARENT CODE: 322430 |                                                                 |               |     |             |                 |     |                  |             |                     |         |              |
| 322433                         | Nose Landing Gear Drag Brace - Discard                          |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                                | C2A4600CA002                                                    | NSN           | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                                |                                                                 |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                                |                                                                 |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe                       |                                                                 |               |     |             |                 |     |                  |             |                     |         |              |
| 322434                         | Nose Landing Gear Trunnion - Discard                            |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                                | C2A4300CA001                                                    | PLT0192       | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                                |                                                                 |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                                |                                                                 |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe                       |                                                                 |               |     |             |                 |     |                  |             |                     |         |              |
| Notes: MRI PARENT CODE: 322407 |                                                                 |               |     |             |                 |     |                  |             |                     |         |              |
| 322435                         | Nose Landing Gear Truss Brace Apex Pin (Left) - Restore         |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                                | PN                                                              | SN-UNKNOWN    | AFL |             | 1117            |     | 10000            | 0           | 10000               |         | 0            |
|                                |                                                                 |               | MOS |             | 128.6           |     | 192              | 24 Aug 2015 | 24 Aug 2031         |         |              |
| Airframe                       |                                                                 |               |     |             |                 |     |                  |             |                     |         |              |
| 322436                         | Nose Landing Gear Truss Brace Apex Pin (Left) - Discard         |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                                | C2M5423CA001                                                    | PLT420376     | AFL |             | 1117            |     | 20000            | 0           | 20000               |         | 0            |
|                                |                                                                 |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
| Airframe                       |                                                                 |               |     |             |                 |     |                  |             |                     |         |              |
| Notes: MRI PARENT CODE: 322416 |                                                                 |               |     |             |                 |     |                  |             |                     |         |              |
| 322500                         | Nose Landing Gear Trunnion Pin (Left) - Removal / Installation  |               | HRS |             | 3023            |     |                  | 23.1        |                     |         | 0            |
|                                |                                                                 |               | AFL |             | 1109            |     |                  | 8           |                     |         | 0            |
|                                | C2M5310CA001                                                    | PCT291114     | MOS | TSN:30      | 123             |     |                  | 10 Feb 2016 |                     |         |              |
|                                |                                                                 |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe                       |                                                                 |               |     |             |                 |     |                  |             |                     |         |              |
| 322501                         | Nose Landing Gear Trunnion Pin (Right) - Removal / Installation |               | HRS | TSN:18.4    | 3023            |     |                  | 23.1        |                     |         | 0            |
|                                |                                                                 |               | AFL | TSN:5       | 1109            |     |                  | 8           |                     |         | 0            |
|                                | C2M5310CA001                                                    | DL0092        | MOS | TSN:6       | 123             |     |                  | 10 Feb 2016 |                     |         |              |
|                                |                                                                 |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe                       |                                                                 |               |     |             |                 |     |                  |             |                     |         |              |



| ATA<br>U=Custom                | Description                                                      |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|--------------------------------|------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                | Part Number                                                      | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position               | HW                                                               | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                | MM Ref                                                           |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                                | Ops Number(s)                                                    |               |     |             |                 |     |                  |             |                    |         |              |
| 322504                         | Outer Cylinder, Machined - Removal / Installation                |               | HRS |             | 3041.4          |     |                  | 4.7         |                    |         | 0            |
|                                | C2M5200CA001                                                     | PLT0201       | AFL |             | 1114            |     |                  | 3           |                    |         | 0            |
|                                |                                                                  |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                                         |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 322507                         | Nose Landing Gear Cylinder Machining - Discard                   |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | C2M5200CA001                                                     | PLT0201       | AFL |             | 1117            |     | 20000            | 0           | 20000              |         | 0            |
|                                |                                                                  |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                                         |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 322504 |                                                                  |               |     |             |                 |     |                  |             |                    |         |              |
| 322508                         | Piston, Machined - Removal / Installation                        |               | HRS |             | 3041.4          |     |                  | 4.7         |                    |         | 0            |
|                                | C2M5201CA001                                                     | PLT0231       | AFL |             | 1114            |     |                  | 3           |                    |         | 0            |
|                                |                                                                  |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                                         |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 322511                         | Nose Landing Gear Piston Machining - Discard                     |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | C2M5201CA001                                                     | PLT0231       | AFL |             | 1117            |     | 20000            | 0           | 20000              |         | 0            |
|                                |                                                                  |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                                         |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 322508 |                                                                  |               |     |             |                 |     |                  |             |                    |         |              |
| 322512                         | Nose Landing Gear Upper Torque ARM Link - Removal / Installation |               | HRS |             | 3041.4          |     |                  | 4.7         |                    |         | 0            |
|                                | C2M5202CA001                                                     | PLT190162     | AFL |             | 1114            |     |                  | 3           |                    |         | 0            |
|                                |                                                                  |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                                         |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 322515                         | Nose Landing Gear Upper Torque ARM - Discard                     |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | C2M5202CA001                                                     | PLT190162     | AFL |             | 1117            |     | 20000            | 0           | 20000              |         | 0            |
|                                |                                                                  |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                                         |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 322512 |                                                                  |               |     |             |                 |     |                  |             |                    |         |              |
| 322516                         | Nose Landing Gear Lower Torque ARM Link - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | C2M5203CA001                                                     | SN-UNKNOWN    | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                |                                                                  |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                                         |               | MSC |             |                 |     | O/C              |             |                    |         |              |

| ATA<br>U=Custom                | Description                                                                 |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|--------------------------------|-----------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                | Part Number                                                                 | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position               | HW                                                                          | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                | MM Ref                                                                      |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                                | Ops Number(s)                                                               |               |     |             |                 |     |                  |             |                    |         |              |
| 322519                         | Nose Landing Gear Lower Torque ARM - Discard                                |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | C2M5203CA001                                                                | PLT190158     | AFL |             | 1117            |     | 20000            | 0           | 20000              |         | 0            |
|                                |                                                                             |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 322213 |                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 322520                         | Metering Pin - Removal / Installation                                       |               | HRS |             | 3041.4          |     |                  | 4.7         |                    |         | 0            |
|                                | C2M5206CA002                                                                | PLT290050     | AFL |             | 1114            |     |                  | 3           |                    |         | 0            |
|                                |                                                                             |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 322523                         | Nose Landing Gear Metering Pin - Discard                                    |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | C2M5206CA002                                                                | PLT290050     | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                |                                                                             |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 322520 |                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 322524                         | Nose Landing Gear Drag Brace / Cylinder Attach Pin - Removal / Installation |               | HRS |             | 3041.4          |     |                  | 4.7         |                    |         | 0            |
|                                | C2A5234CA001                                                                | PLT420072     | AFL |             | 1114            |     |                  | 3           |                    |         | 0            |
|                                |                                                                             |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 322527                         | Nose Landing Gear Drag Brace Lower Attach Pin - Discard                     |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | C2A5234CA001                                                                | PLT420072     | AFL |             | 1117            |     | 20000            | 0           | 20000              |         | 0            |
|                                |                                                                             |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 322524 |                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 322528                         | Pin, Lower Torsion Link Attach - Removal / Installation                     |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | C2M5235CA001                                                                | NSN           | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                |                                                                             |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 322531                         | Nose Landing Gear Lower Torque ARM Attach Pin - Discard                     |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | C2M5235CA001                                                                | NSN           | AFL |             | 1117            |     | 20000            | 0           | 20000              |         | 0            |
|                                |                                                                             |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 322528 |                                                                             |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom                | Description                                              |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|--------------------------------|----------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                | Part Number                                              | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position               | HW                                                       | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                | MM Ref                                                   |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                                | Ops Number(s)                                            |               |     |             |                 |     |                  |             |                    |         |              |
| 322532                         | Pin, Torsion ARM Apex - Removal / Installation           |               | HRS |             | 3041.4          |     |                  | 4.7         |                    |         | 0            |
|                                | C2M5250CA001                                             | PLT420068     | AFL |             | 1114            |     |                  | 3           |                    |         | 0            |
|                                |                                                          |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 322535                         | Nose Landing Gear Torque ARM Apex Pin - Discard          |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | C2M5250CA001                                             | PLT420068     | AFL |             | 1117            |     | 20000            | 0           | 20000              |         | 0            |
|                                |                                                          |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                                 |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 322532 |                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| 322536                         | Trunnion Frame, Machining - Removal / Installation       |               | HRS |             | 3041.4          |     |                  | 4.7         |                    |         | 0            |
|                                | C2M5300CA001                                             | PLT0118       | AFL |             | 1114            |     |                  | 3           |                    |         | 0            |
|                                |                                                          |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 322539                         | Nose Landing Gear Trunnion Frame Machining - Discard     |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | C2M5300CA001                                             | PLT0118       | AFL |             | 1117            |     | 20000            | 0           | 20000              |         | 0            |
|                                |                                                          |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                                 |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 322536 |                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| 322540                         | Bolt, Retaining - Removal / Installation                 |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | C2M5314CA001                                             | NSN           | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                |                                                          |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 322543                         | Nose Landing Gear Cylinder / Trunnion Pin Retaining Bolt |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | - Discard                                                |               | AFL |             | 1117            |     | 20000            | 0           | 20000              |         | 0            |
|                                | C2M5314CA001                                             | NSN           | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                                 |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 322540 |                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| 322544                         | Truss Brace Assembly - Removal / Installation            |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | C2A4400CA004                                             | NSN           | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                |                                                          |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |

| ATA<br>U=Custom                | Description                                      |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(* =Adj) | Max Due | Avg Man Hrs  |
|--------------------------------|--------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|----------------------|---------|--------------|
|                                | Part Number                                      | Serial Number |     |             |                 |     |                  |             |                      |         | Approx Price |
| Logbook Position               | HW                                               | SW            |     |             |                 |     |                  |             |                      |         | Manufacturer |
|                                | MM Ref                                           |               |     |             |                 |     |                  |             |                      |         | Date Type    |
|                                | Ops Number(s)                                    |               |     |             |                 |     |                  |             |                      |         |              |
| 322547                         | Nose Landing Gear Truss Brace - Discard          |               | HRS |             | 3046.1          |     |                  | 0           |                      |         | 0            |
|                                | C2A4400CA004                                     | NSN           | AFL |             | 1117            |     |                  | 0           |                      |         | 0            |
|                                |                                                  |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                      |         |              |
|                                | Airframe                                         |               | MSC |             |                 |     | O/C              |             |                      |         |              |
| Notes: MRI PARENT CODE: 322544 |                                                  |               |     |             |                 |     |                  |             |                      |         |              |
| 322548                         | Nose Landing Gear Truss Brace Apex Pin (Right) - |               | HRS |             | 3041.4          |     |                  | 4.7         |                      |         | 0            |
|                                | Removal / Installation                           |               | AFL |             | 1114            |     |                  | 3           |                      |         | 0            |
|                                | C2M5423CA001                                     | PLT420266     | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                      |         |              |
|                                | Airframe                                         |               | MSC |             |                 |     | O/C              |             |                      |         |              |
| 322550                         | Nose Landing Gear Truss Brace Apex Pin (Right) - |               | HRS |             | 3046.1          |     |                  | 0           |                      |         | 0            |
|                                | Restore                                          |               | AFL |             | 1117            |     | 10000            | 0           | 10000                |         | 0            |
|                                | PN                                               | SN-UNKNOWN    | MOS |             | 128.6           |     | 192              | 24 Aug 2015 | 24 Aug 2031          |         |              |
|                                | Airframe                                         |               |     |             |                 |     |                  |             |                      |         |              |
| 322551                         | Nose Landing Gear Truss Brace Apex Pin (Right) - |               | HRS |             | 3046.1          |     |                  | 0           |                      |         | 0            |
|                                | Discard                                          |               | AFL |             | 1117            |     | 20000            | 0           | 20000                |         | 0            |
|                                | C2M5423CA001                                     | PLT420266     | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                      |         |              |
|                                | Airframe                                         |               |     |             |                 |     |                  |             |                      |         |              |
| Notes: MRI PARENT CODE: 322548 |                                                  |               |     |             |                 |     |                  |             |                      |         |              |
| 322552                         | Pin, Apex Downlock - Removal / Installation      |               | HRS |             | 3041.4          |     |                  | 4.7         |                      |         | 0            |
|                                | C2M5425CA001                                     | PLT420045     | AFL |             | 1114            |     |                  | 3           |                      |         | 0            |
|                                |                                                  |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                      |         |              |
|                                | Airframe                                         |               | MSC |             |                 |     | O/C              |             |                      |         |              |
| 322555                         | Nose Landing Gear Downlock Apex Pin - Discard    |               | HRS |             | 3046.1          |     |                  | 0           |                      |         | 0            |
|                                | C2M5425CA001                                     | PLT420045     | AFL |             | 1117            |     | 20000            | 0           | 20000                |         | 0            |
|                                |                                                  |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                      |         |              |
|                                | Airframe                                         |               |     |             |                 |     |                  |             |                      |         |              |
| Notes: MRI PARENT CODE: 322552 |                                                  |               |     |             |                 |     |                  |             |                      |         |              |
| 322556                         | Pin, Aft Downlock - Removal / Installation       |               | HRS |             | 3041.4          |     |                  | 4.7         |                      |         | 0            |
|                                | C2M5426CA001                                     | PLT420047     | AFL |             | 1114            |     |                  | 3           |                      |         | 0            |
|                                |                                                  |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                      |         |              |
|                                | Airframe                                         |               | MSC |             |                 |     | O/C              |             |                      |         |              |

| ATA<br>U=Custom                | Description                                                |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|--------------------------------|------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                | Part Number                                                | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position               | HW                                                         | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                | MM Ref                                                     |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                                | Ops Number(s)                                              |               |     |             |                 |     |                  |             |                    |         |              |
| 322559                         | Nose Landing Gear Aft Lock Link Pin - Discard              |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | C2M5426CA001                                               | PLT420047     | AFL |             | 1117            |     | 20000            | 0           | 20000              |         | 0            |
|                                |                                                            |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                            |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 322556 |                                                            |               |     |             |                 |     |                  |             |                    |         |              |
| 322560                         | Aft Lock Link, Machining - Removal / Installation          |               | HRS |             | 3041.4          |     |                  | 4.7         |                    |         | 0            |
|                                | C2M5408CA001                                               | PLT420038     | AFL |             | 1114            |     |                  | 3           |                    |         | 0            |
|                                |                                                            |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                            |               |     |             |                 |     |                  |             |                    |         |              |
|                                |                                                            |               |     |             |                 |     | O/C              |             |                    |         |              |
| 322563                         | Nose Landing Gear Aft Lock Link Machining - Discard        |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | C2M5408CA001                                               | PLT420038     | AFL |             | 1117            |     | 20000            | 0           | 20000              |         | 0            |
|                                |                                                            |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                            |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 322560 |                                                            |               |     |             |                 |     |                  |             |                    |         |              |
| 322564                         | Sleeve, Drag Brace Attach Long - Removal / Installation    |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | C2M5419CA001                                               | NSN           | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                |                                                            |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                            |               |     |             |                 |     |                  |             |                    |         |              |
|                                |                                                            |               |     |             |                 |     | O/C              |             |                    |         |              |
| 322567                         | Nose Landing Gear Drag Brace Attach Long Sleeve - Discard  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | C2M5419CA001                                               | NSN           | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                |                                                            |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                            |               |     |             |                 |     |                  |             |                    |         |              |
|                                |                                                            |               |     |             |                 |     | O/C              |             |                    |         |              |
| Notes: MRI PARENT CODE: 322564 |                                                            |               |     |             |                 |     |                  |             |                    |         |              |
| 322568                         | Sleeve, Drag Brace Attach Short - Removal / Installation   |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | C2M5420CA001                                               | NSN           | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                |                                                            |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                            |               |     |             |                 |     |                  |             |                    |         |              |
|                                |                                                            |               |     |             |                 |     | O/C              |             |                    |         |              |
| 322571                         | Nose Landing Gear Drag Brace Attach Short Sleeve - Discard |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | C2M5420CA001                                               | NSN           | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                |                                                            |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                            |               |     |             |                 |     |                  |             |                    |         |              |
|                                |                                                            |               |     |             |                 |     | O/C              |             |                    |         |              |
| Notes: MRI PARENT CODE: 322568 |                                                            |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom                | Description                                       |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|--------------------------------|---------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                | Part Number                                       | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position               | HW                                                | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                | MM Ref                                            |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                                | Ops Number(s)                                     |               |     |             |                 |     |                  |             |                    |         |              |
| 322572                         | Pin, Forward Lock Link - Removal / Installation   |               | HRS |             | 3041.4          |     |                  | 4.7         |                    |         | 0            |
|                                | C2M5424CA002                                      | PLT420062     | AFL |             | 1114            |     |                  | 3           |                    |         | 0            |
|                                |                                                   |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                          |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 322575                         | Nose Landing Gear Forward Lock Link Pin - Discard |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | C2M5424CA002                                      | PLT420062     | AFL |             | 1117            |     | 20000            | 0           | 20000              |         | 0            |
|                                |                                                   |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                          |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 322572 |                                                   |               |     |             |                 |     |                  |             |                    |         |              |
| 322576                         | Strut Body - Removal / Installation               |               | HRS |             | 3041.4          |     |                  | 4.7         |                    |         | 0            |
|                                | C2M4601CA001                                      | PLT420004     | AFL |             | 1114            |     |                  | 3           |                    |         | 0            |
|                                |                                                   |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                          |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 322579                         | Nose Landing Gear Drag Brace Strut Body - Discard |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | C2M4601CA001                                      | PLT420004     | AFL |             | 1117            |     | 20000            | 0           | 20000              |         | 0            |
|                                |                                                   |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                          |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 322576 |                                                   |               |     |             |                 |     |                  |             |                    |         |              |
| 322580                         | ROD End - Removal / Installation                  |               | HRS |             | 3041.4          |     |                  | 4.7         |                    |         | 0            |
|                                | C2M4602CA002                                      | DL0160        | AFL |             | 1114            |     |                  | 3           |                    |         | 0            |
|                                |                                                   |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                          |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 322583                         | Nose Landing Gear Drag Brace ROD End - Discard    |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | C2M4602CA002                                      | DL0160        | AFL |             | 1117            |     | 20000            | 0           | 20000              |         | 0            |
|                                |                                                   |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                          |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 322580 |                                                   |               |     |             |                 |     |                  |             |                    |         |              |
| 322584                         | Drag Brace Nut - Removal / Installation           |               | HRS |             | 3041.4          |     |                  | 4.7         |                    |         | 0            |
|                                | C2M4605CA001                                      | PLT370203     | AFL |             | 1114            |     |                  | 3           |                    |         | 0            |
|                                |                                                   |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                          |               | MSC |             |                 |     | O/C              |             |                    |         |              |

| ATA<br>U=Custom                | Description                                               |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|--------------------------------|-----------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                | Part Number                                               | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position               | HW                                                        | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                | MM Ref                                                    |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                                | Ops Number(s)                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 322587                         | Nose Landing Gear Drag Brace Nut - Discard                |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | C2M4605CA001                                              | PLT370203     | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                |                                                           |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Notes: MRI PARENT CODE: 322584 |                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| 322588                         | Nose Landing Gear Trunnion Pin (Left) - Discard           |               | HRS |             | 3023            |     |                  | 23.1        |                    |         | 0            |
|                                | C2M5310CA001                                              | PLT29114      | AFL |             | 1109            |     | 20000            | 8           | 20008              |         | 0            |
|                                |                                                           |               | MOS | TSN:30      | 123.2           |     |                  | 04 Feb 2016 |                    |         |              |
|                                | Airframe                                                  |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 322500 |                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| 322589                         | Nose Landing Gear Trunnion Pin (Right) - Discard          |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | C2M5310CA001                                              | DL0092        | AFL |             | 1117            |     | 20000            | 0           | 20000              |         | 0            |
|                                |                                                           |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                                  |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 322501 |                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| 322590                         | Forward Lock Link, Machining - Removal / Installation     |               | HRS |             | 3041.4          |     |                  | 4.7         |                    |         | 0            |
|                                | C2M5404CA001                                              | PLT190222     | AFL |             | 1114            |     |                  | 3           |                    |         | 0            |
|                                |                                                           |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                                  |               |     |             |                 |     | O/C              |             |                    |         |              |
| 322593                         | Nose Landing Gear Forward Lock Link Machining - Discard   |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | C2M5404CA001                                              | PLT190222     | AFL |             | 1117            |     | 20000            | 0           | 20000              |         | 0            |
|                                |                                                           |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                                  |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 322590 |                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| 322600                         | NLG Taxi Light Assembly (Left) - Removal / Installation   |               | HRS |             | 3041.4          |     |                  | 4.7         |                    |         | 0            |
|                                | 01-0790460-00                                             | 00732         | AFL |             | 1114            |     |                  | 3           |                    |         | 0            |
|                                |                                                           |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                                  |               |     |             |                 |     | O/C              |             |                    |         |              |
| 322601                         | NLG Taxi Light Assembly (Center) - Removal / Installation |               | HRS |             | 136.2           |     |                  | 2909.9      |                    |         | 0            |
|                                | 01-0790460-00                                             | 207941900019  | AFL |             | 51              |     |                  | 1066        |                    |         | 0            |
|                                |                                                           |               | MOS | TSN:6       | 4.7             |     |                  | 19 Dec 2025 |                    |         |              |
|                                | Airframe                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                          |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                          | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                   | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                               |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 322602           | NLG Taxi Light Assembly (Right) - Removal / Installation             |               | HRS |             | 3041.4          |     |                  | 4.7         |                    |         | 0            |
|                  | 01-0790460-00                                                        | 00763         | AFL |             | 1114            |     |                  | 3           |                    |         | 0            |
|                  |                                                                      |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                             |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 322603           | Nose Landing Gear Down and Lock Harness - Discard                    |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | C2E4901CA002                                                         | SN-UNKNOWN    | AFL |             | 1117            |     | 18000            | 0           | 18000              |         | 0            |
|                  |                                                                      |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 322606           | Nose Landing Gear Upper Electrical Harness - Removal / Installation  |               | HRS |             | 3041.4          |     |                  | 4.7         |                    |         | 0            |
|                  | C2E4901CA003                                                         | ICO10251      | AFL |             | 1114            |     |                  | 3           |                    |         | 0            |
|                  |                                                                      |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                             |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 322608           | Nose Landing Gear Middle Electrical Harness - Removal / Installation |               | HRS |             | 2549.5          |     |                  | 496.6       |                    |         | 0            |
|                  | C2E4904CA003                                                         | 02121         | AFL |             | 979             |     |                  | 138         |                    |         | 0            |
|                  |                                                                      |               | MOS |             | 103             |     |                  | 11 Oct 2017 |                    |         |              |
|                  | Airframe                                                             |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 322610           | Nose Landing Gear Lower Electrical Harness - Removal / Installation  |               | HRS |             | 3041.4          |     |                  | 4.7         |                    |         | 0            |
|                  | C2E4905CA003                                                         | ICO10267      | AFL |             | 1114            |     |                  | 3           |                    |         | 0            |
|                  |                                                                      |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                             |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 322612           | Taxi Light Assembly Mounting (Upper) - Removal / Installation        |               | HRS |             | 2549.5          |     |                  | 496.6       |                    |         | 0            |
|                  | PN                                                                   | SN-UNKNOWN    | AFL |             | 979             |     |                  | 138         |                    |         | 0            |
|                  |                                                                      |               | MOS |             | 103             |     |                  | 11 Oct 2017 |                    |         |              |
|                  | Airframe                                                             |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 322613           | Taxi Light Assembly Mounting (Lower) - Removal / Installation        |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | PN                                                                   | SN-UNKNOWN    | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                      |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                             |               | MSC |             |                 |     | O/C              |             |                    |         |              |



| ATA<br>U=Custom                | Description                                           |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|--------------------------------|-------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                | Part Number                                           | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position               | HW                                                    | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                | MM Ref                                                |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                                | Ops Number(s)                                         |               |     |             |                 |     |                  |             |                    |         |              |
| 322616                         | Nose Landing Gear Harness - Removal / Installation    |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | 60P3222010Z004 SN-UNKNOWN                             |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                |                                                       |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                              |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 322618                         | Nose Landing Gear Middle Electrical Harness - Discard |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | C2E4904CA003 ICO10280                                 |               | AFL |             | 1117            |     | 10000            | 0           | 10000              |         | 0            |
|                                |                                                       |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                              |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 322608 |                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| 322700                         | CAP, Machining (Left) - Removal / Installation        |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | C1A5205CA001 AP0446                                   |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                |                                                       |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                              |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 322703                         | Main Landing Gear Shock Absorber CAP Machining (Left) |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | - Discard                                             |               | AFL |             | 1117            |     | 7000             | 0           | 7000               |         | 0            |
|                                | C1A5205CA001 AP0446                                   |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                              |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 322700 |                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| 322704                         | CAP, Machining (Right) - Removal / Installation       |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | C1A5205CA001 AP0422                                   |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                |                                                       |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                              |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 322707                         | Main Landing Gear Shock Absorber CAP Machining        |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | (Right) - Discard                                     |               | AFL |             | 1117            |     | 7000             | 0           | 7000               |         | 0            |
|                                | C1A5205CA001 AP0422                                   |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                              |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 322704 |                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| 322708                         | Nut, Cylinder (Left) - Removal / Installation         |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | C1M5217CA001 GK0415                                   |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                |                                                       |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                              |               | MSC |             |                 |     | O/C              |             |                    |         |              |

| ATA<br>U=Custom                | Description                                                     |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(* =Adj) | Max Due | Avg Man Hrs  |
|--------------------------------|-----------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|----------------------|---------|--------------|
|                                | Part Number                                                     | Serial Number |     |             |                 |     |                  |             |                      |         | Approx Price |
| Logbook Position               | HW                                                              | SW            |     |             |                 |     |                  |             |                      |         | Manufacturer |
|                                | MM Ref                                                          |               |     |             |                 |     |                  |             |                      |         | Date Type    |
|                                | Ops Number(s)                                                   |               |     |             |                 |     |                  |             |                      |         |              |
| 322711                         | Main Landing Gear Shock Absorber Cylinder Nut (Left) - Discard  |               | HRS |             | 3046.1          |     |                  | 0           |                      |         | 0            |
|                                |                                                                 |               | AFL |             | 1117            |     | 20000            | 0           | 20000                |         | 0            |
|                                | C1M5217CA001                                                    | GK0415        | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                      |         |              |
| Airframe                       |                                                                 |               |     |             |                 |     |                  |             |                      |         |              |
| Notes: MRI PARENT CODE: 322708 |                                                                 |               |     |             |                 |     |                  |             |                      |         |              |
| 322712                         | Nut, Cylinder (Right) - Removal / Installation                  |               | HRS |             | 3046.1          |     |                  | 0           |                      |         | 0            |
|                                | C1M5217CA001                                                    | GK0381        | AFL |             | 1117            |     |                  | 0           |                      |         | 0            |
|                                |                                                                 |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                      |         |              |
|                                |                                                                 |               | MSC |             |                 |     | O/C              |             |                      |         |              |
| Airframe                       |                                                                 |               |     |             |                 |     |                  |             |                      |         |              |
| 322715                         | Main Landing Gear Shock Absorber Cylinder Nut (Right) - Discard |               | HRS |             | 3046.1          |     |                  | 0           |                      |         | 0            |
|                                |                                                                 |               | AFL |             | 1117            |     | 20000            | 0           | 20000                |         | 0            |
|                                | C1M5217CA001                                                    | GK0381        | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                      |         |              |
| Airframe                       |                                                                 |               |     |             |                 |     |                  |             |                      |         |              |
| Notes: MRI PARENT CODE: 322712 |                                                                 |               |     |             |                 |     |                  |             |                      |         |              |
| 322716                         | Left Main Post Assembly, - Removal / Installation               |               | HRS | TSN:2315.6  | 730.5           |     |                  | 2315.6      |                      |         | 0            |
|                                | C1A5300LA003                                                    | CD0346        | AFL | TSN:802     | 315             |     |                  | 802         |                      |         | 0            |
|                                |                                                                 |               | MOS | TSN:100     | 28.7            |     |                  | 21 Dec 2023 |                      |         |              |
|                                |                                                                 |               | MSC |             |                 |     | O/C              |             |                      |         |              |
| Airframe                       |                                                                 |               |     |             |                 |     |                  |             |                      |         |              |
| Notes: MRI PARENT CODE: 321002 |                                                                 |               |     |             |                 |     |                  |             |                      |         |              |
| 322719                         | Main Landing Gear Post Assembly (Left) - Discard                |               | HRS |             | 3046.1          |     |                  | 0           |                      |         | 0            |
|                                | C1A5300LA003                                                    | CD0346        | AFL |             | 1117            |     |                  | 0           |                      |         | 0            |
|                                |                                                                 |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                      |         |              |
|                                |                                                                 |               | MSC |             |                 |     | O/C              |             |                      |         |              |
| Airframe                       |                                                                 |               |     |             |                 |     |                  |             |                      |         |              |
| Notes: MRI PARENT CODE: 321002 |                                                                 |               |     |             |                 |     |                  |             |                      |         |              |
| 322720                         | Right Main Post Assembly, - Removal / Installation              |               | HRS | TSN:2315.6  | 730.5           |     |                  | 2315.6      |                      |         | 0            |
|                                | C1A5300RA003                                                    | CD0380        | AFL | TSN:802     | 315             |     |                  | 802         |                      |         | 0            |
|                                |                                                                 |               | MOS | TSN:100     | 28.7            |     |                  | 21 Dec 2023 |                      |         |              |
|                                |                                                                 |               | MSC |             |                 |     | O/C              |             |                      |         |              |
| Airframe                       |                                                                 |               |     |             |                 |     |                  |             |                      |         |              |
| Notes: MRI PARENT CODE: 321003 |                                                                 |               |     |             |                 |     |                  |             |                      |         |              |

| ATA<br>U=Custom                | Description                                           |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|--------------------------------|-------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                | Part Number                                           | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position               | HW                                                    | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                | MM Ref                                                |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                                | Ops Number(s)                                         |               |     |             |                 |     |                  |             |                    |         |              |
| 322723                         | Main Landing Gear Post Assembly (Right) - Discard     |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | C1A5300RA003                                          | CD0380        | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                |                                                       |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                              |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Notes: MRI PARENT CODE: 321003 |                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| 322724                         | Nut, Spindle Pin (Left) - Removal / Installation      |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | C1M5316CA002                                          | LHM0085       | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                |                                                       |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                              |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 322727                         | Main Landing Gear Spindle Pin Nut (Left) - Discard    |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | C1M5316CA002                                          | LHM0085       | AFL |             | 1117            |     | 20000            | 0           | 20000              |         | 0            |
|                                |                                                       |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                              |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 322724 |                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| 322728                         | Nut, Spindle Pin (Right) - Removal / Installation     |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | C1M5316CA002                                          | LHM0094       | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                |                                                       |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                              |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 322731                         | Main Landing Gear Spindle Pin Nut (Right) - Discard   |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | C1M5316CA002                                          | LHM0094       | AFL |             | 1117            |     | 20000            | 0           | 20000              |         | 0            |
|                                |                                                       |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                              |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 322728 |                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| 322732                         | Nut, Aft Pintle Pin (Left) - Removal / Installation   |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | C1M5313CA001                                          | EXC0402       | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                |                                                       |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                              |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 322735                         | Main Landing Gear Aft Pintle Pin Nut (Left) - Discard |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | C1M5313CA001                                          | EXC0402       | AFL |             | 1117            |     | 20000            | 0           | 20000              |         | 0            |
|                                |                                                       |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                              |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 322732 |                                                       |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom                | Description                                                  |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|--------------------------------|--------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                | Part Number                                                  | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position               | HW                                                           | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                | MM Ref                                                       |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                                | Ops Number(s)                                                |               |     |             |                 |     |                  |             |                    |         |              |
| 322736                         | Nut, Aft Pintle Pin (Right) - Removal / Installation         |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | C1M5313CA001                                                 | EXC0404       | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                |                                                              |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                                     |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 322739                         | Main Landing Gear Aft Pintle Pin Nut (Right) - Discard       |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | C1M5313CA001                                                 | EXC0404       | AFL |             | 1117            |     | 20000            | 0           | 20000              |         | 0            |
|                                |                                                              |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 322736 |                                                              |               |     |             |                 |     |                  |             |                    |         |              |
| 322740                         | Bolt, Forward Pintle Cross (Left) - Removal / Installation   |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | C1A5319CA001                                                 | EXC0379       | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                |                                                              |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                                     |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 322743                         | Main Landing Gear Forward Pintle Crossbolt (Left) - Discard  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | C1A5319CA001                                                 | EXC0379       | AFL |             | 1117            |     | 20000            | 0           | 20000              |         | 0            |
|                                |                                                              |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 322740 |                                                              |               |     |             |                 |     |                  |             |                    |         |              |
| 322744                         | Bolt, Forward Pintle Cross (Right) - Removal / Installation  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | C1A5319CA001                                                 | EXC0383       | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                |                                                              |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                                     |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 322747                         | Main Landing Gear Forward Pintle Crossbolt (Right) - Discard |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | C1A5319CA001                                                 | EXC0383       | AFL |             | 1117            |     | 20000            | 0           | 20000              |         | 0            |
|                                |                                                              |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 322744 |                                                              |               |     |             |                 |     |                  |             |                    |         |              |
| 322748                         | Bolt, Aft Pintle Cross (Left) - Removal / Installation       |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | C1A5322CA001                                                 | EXC0366       | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                |                                                              |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                                     |               | MSC |             |                 |     | O/C              |             |                    |         |              |

| ATA<br>U=Custom                | Description                                                |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(* =Adj) | Max Due | Avg Man Hrs  |
|--------------------------------|------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|----------------------|---------|--------------|
|                                | Part Number                                                | Serial Number |     |             |                 |     |                  |             |                      |         | Approx Price |
| Logbook Position               | HW                                                         | SW            |     |             |                 |     |                  |             |                      |         | Manufacturer |
|                                | MM Ref                                                     |               |     |             |                 |     |                  |             |                      |         | Date Type    |
|                                | Ops Number(s)                                              |               |     |             |                 |     |                  |             |                      |         |              |
| 322751                         | Main Landing Gear Aft Pintle Crossbolt (Left) - Discard    |               | HRS |             | 3046.1          |     |                  | 0           |                      |         | 0            |
|                                | C1A5322CA001                                               | EXC0366       | AFL |             | 1117            |     | 20000            | 0           | 20000                |         | 0            |
|                                |                                                            |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                      |         |              |
| Airframe                       |                                                            |               |     |             |                 |     |                  |             |                      |         |              |
| Notes: MRI PARENT CODE: 322748 |                                                            |               |     |             |                 |     |                  |             |                      |         |              |
| 322752                         | Bolt, Aft Pintle Cross (Right) - Removal / Installation    |               | HRS |             | 3046.1          |     |                  | 0           |                      |         | 0            |
|                                | C1A5322CA001                                               | EXC0369       | AFL |             | 1117            |     |                  | 0           |                      |         | 0            |
|                                |                                                            |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                      |         |              |
| Airframe                       |                                                            |               |     |             |                 |     |                  |             |                      |         |              |
| O/C                            |                                                            |               |     |             |                 |     |                  |             |                      |         |              |
| 322755                         | Main Landing Gear Aft Pintle Crossbolt (Right) - Discard   |               | HRS |             | 3046.1          |     |                  | 0           |                      |         | 0            |
|                                | C1A5322CA001                                               | EXC0369       | AFL |             | 1117            |     | 20000            | 0           | 20000                |         | 0            |
|                                |                                                            |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                      |         |              |
| Airframe                       |                                                            |               |     |             |                 |     |                  |             |                      |         |              |
| Notes: MRI PARENT CODE: 322752 |                                                            |               |     |             |                 |     |                  |             |                      |         |              |
| 322756                         | Trailing ARM Machining (Left) - Removal / Installation     |               | HRS |             | 3046.1          |     |                  | 0           |                      |         | 0            |
|                                | C1A5400CA001                                               | ZKM0253       | AFL |             | 1117            |     |                  | 0           |                      |         | 0            |
|                                |                                                            |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                      |         |              |
| Airframe                       |                                                            |               |     |             |                 |     |                  |             |                      |         |              |
| O/C                            |                                                            |               |     |             |                 |     |                  |             |                      |         |              |
| 322759                         | Main Landing Gear Trailing ARM Machining (Left) - Discard  |               | HRS |             | 3046.1          |     |                  | 0           |                      |         | 0            |
|                                | C1A5400CA001                                               | ZKM0253       | AFL |             | 1117            |     | 20000            | 0           | 20000                |         | 0            |
|                                |                                                            |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                      |         |              |
| Airframe                       |                                                            |               |     |             |                 |     |                  |             |                      |         |              |
| Notes: MRI PARENT CODE: 322756 |                                                            |               |     |             |                 |     |                  |             |                      |         |              |
| 322760                         | Trailing ARM Machining (Right) - Removal / Installation    |               | HRS |             | 3046.1          |     |                  | 0           |                      |         | 0            |
|                                | C1A5400CA001                                               | ZKM0251       | AFL |             | 1117            |     |                  | 0           |                      |         | 0            |
|                                |                                                            |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                      |         |              |
| Airframe                       |                                                            |               |     |             |                 |     |                  |             |                      |         |              |
| O/C                            |                                                            |               |     |             |                 |     |                  |             |                      |         |              |
| 322763                         | Main Landing Gear Trailing ARM Machining (Right) - Discard |               | HRS |             | 3046.1          |     |                  | 0           |                      |         | 0            |
|                                | C1A5400CA001                                               | ZKM0251       | AFL |             | 1117            |     | 20000            | 0           | 20000                |         | 0            |
|                                |                                                            |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                      |         |              |
| Airframe                       |                                                            |               |     |             |                 |     |                  |             |                      |         |              |
| Notes: MRI PARENT CODE: 322760 |                                                            |               |     |             |                 |     |                  |             |                      |         |              |

| ATA<br>U=Custom                | Description                                                         |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|--------------------------------|---------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                | Part Number                                                         | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position               | HW                                                                  | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                | MM Ref                                                              |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                                | Ops Number(s)                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| 322764                         | Nut, Shock Absorber Attach (Left Upper) - Removal / Installation    |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                                     |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                | C1M5417CA001                                                        | NSN           | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                |                                                                     |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                       |                                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| 322767                         | Main Landing Gear Shock Absorber Attach Nut (Left Upper) - Discard  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                                     |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                | C1M5417CA001                                                        | NSN           | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                |                                                                     |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                       |                                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 322764 |                                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| 322768                         | Nut, Shock Absorber Attach (Right Upper) - Removal / Installation   |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                                     |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                | C1M5417CA001                                                        | NSN           | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                |                                                                     |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                       |                                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| 322771                         | Main Landing Gear Shock Absorber Attach Nut (Right Upper) - Discard |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                                     |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                | C1M5417CA001                                                        | NSN           | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                |                                                                     |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                       |                                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 322768 |                                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| 322772                         | Nut, Shock Absorber Attach (Left Lower) - Removal / Installation    |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                                     |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                | C1M5417CA001                                                        | NSN           | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                |                                                                     |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                       |                                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| 322775                         | Main Landing Gear Shock Absorber Attach Nut (Left Lower) - Discard  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                                     |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                | C1M5417CA001                                                        | NSN           | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                |                                                                     |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                       |                                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 322772 |                                                                     |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom                | Description                                                         |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|--------------------------------|---------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                | Part Number                                                         | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position               | HW                                                                  | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                | MM Ref                                                              |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                                | Ops Number(s)                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| 322776                         | Nut, Shock Absorber Attach (Right Lower) - Removal / Installation   |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                                     |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                | C1M5417CA001                                                        | NSN           | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                |                                                                     |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                       |                                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| 322779                         | Main Landing Gear Shock Absorber Attach Nut (Right Lower) - Discard |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                                     |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                | C1M5417CA001                                                        | NSN           | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                |                                                                     |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                       |                                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 322776 |                                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| 322780                         | Pin, Knee Joint Retention (Left) - Removal / Installation           |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                                | C1M5426CA001                                                        | GRZ0060       | AFL |             | 315             |     |                  | 802         |                    |         | 0            |
|                                |                                                                     |               | MOS | TSN:59      | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
|                                |                                                                     |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                       |                                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| 322783                         | Main Landing Gear Knee Joint Retention Pin (Left) - Discard         |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                                |                                                                     |               | AFL |             | 315             |     | 20000            | 802         | 20802              |         | 0            |
|                                | C1M5426CA001                                                        | GRZ0060       | MOS | TSN:59      | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
|                                |                                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                       |                                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 322780 |                                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| 322784                         | Pin, Knee Joint Retention (Right) - Removal / Installation          |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | C1M5426CA001                                                        | CFN0262       | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                |                                                                     |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                |                                                                     |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                       |                                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| 322787                         | Main Landing Gear Knee Joint Retention Pin (Right) - Discard        |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                                     |               | AFL |             | 1117            |     | 20000            | 0           | 20000              |         | 0            |
|                                | C1M5426CA001                                                        | CFN0262       | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                |                                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                       |                                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 322784 |                                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| 322788                         | Cylinder Machining (Left) - Removal / Installation                  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | C1M5605CA002                                                        | PLT0268       | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                |                                                                     |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                |                                                                     |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                       |                                                                     |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom                | Description                                            |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|--------------------------------|--------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                | Part Number                                            | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position               | HW                                                     | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                | MM Ref                                                 |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                                | Ops Number(s)                                          |               |     |             |                 |     |                  |             |                    |         |              |
| 322791                         | Main Landing Gear Side Brace Actuator Cylinder         |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | Machining (Left) - Discard                             |               | AFL |             | 1117            |     | 20000            | 0           | 20000              |         | 0            |
|                                | C1M5210CA001                                           | GK0385        | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 321202 |                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 322792                         | Cylinder Machining (Right) - Removal / Installation    |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | C1M5210CA001                                           | GK0353        | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                |                                                        |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                |                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                       |                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 321203 |                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 322795                         | Main Landing Gear Side Brace Actuator Cylinder         |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | Machining (Right) - Discard                            |               | AFL |             | 1117            |     | 20000            | 0           | 20000              |         | 0            |
|                                | C1M5210CA001                                           | GK0353        | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 321203 |                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 322796                         | Piston Machining (Left) - Removal / Installation       |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | C1M5651CA002                                           | PLT0260       | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                |                                                        |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                |                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                       |                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 322799                         | Main Landing Gear Side Brace Actuator Piston Machining |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | (Left) - Discard                                       |               | AFL |             | 1117            |     | 20000            | 0           | 20000              |         | 0            |
|                                | C1M5651CA002                                           | PLT0260       | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 322796 |                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 322800                         | Piston Machining (Right) - Removal / Installation      |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | C1M5651CA002                                           | PLT0278       | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                |                                                        |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                |                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                       |                                                        |               |     |             |                 |     |                  |             |                    |         |              |



| ATA<br>U=Custom                | Description                                                                                 |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|--------------------------------|---------------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                | Part Number                                                                                 | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position               | HW                                                                                          | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                | MM Ref                                                                                      |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                                | Ops Number(s)                                                                               |               |     |             |                 |     |                  |             |                    |         |              |
| 322803                         | Main Landing Gear Side Brace Actuator Piston Machining (Right) - Discard                    |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                                                             |               | AFL |             | 1117            |     | 20000            | 0           | 20000              |         | 0            |
|                                | C1M5651CA002                                                                                | PLT0278       | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 322800 |                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 322804                         | Lock Spool (Left) - Removal / Installation                                                  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                                                             |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                | C1M5654CA001                                                                                | PLT320334     | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 322807                         | Main Landing Gear Side Brace Actuator Lock Spool (Left) - Discard                           |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                                                             |               | AFL |             | 1117            |     | 20000            | 0           | 20000              |         | 0            |
|                                | C1M5654CA001                                                                                | PLT320334     | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 322804 |                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 322808                         | Lock Spool (Right) - Removal / Installation                                                 |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                                                             |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                | C1M5654CA001                                                                                | PLT320316     | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 322811                         | Main Landing Gear Side Brace Actuator Lock Spool (Right) - Discard                          |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                                                             |               | AFL |             | 1117            |     | 20000            | 0           | 20000              |         | 0            |
|                                | C1M5654CA001                                                                                | PLT320316     | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 322808 |                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 322812                         | Main Landing Gear Side Brace Actuator Locking Segments (Left) (#1) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                                                             |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                | C1M5655CA002                                                                                | PLT320158     | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 322808 |                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 322812                         | Main Landing Gear Side Brace Actuator Locking Segments (Left) (#1) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                                                             |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                | C1M5655CA002                                                                                | PLT320158     | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 322808 |                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 322812                         | Main Landing Gear Side Brace Actuator Locking Segments (Left) (#1) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                                                             |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                | C1M5655CA002                                                                                | PLT320158     | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 322808 |                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 322812                         | Main Landing Gear Side Brace Actuator Locking Segments (Left) (#1) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                                                             |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                | C1M5655CA002                                                                                | PLT320158     | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 322808 |                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 322812                         | Main Landing Gear Side Brace Actuator Locking Segments (Left) (#1) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                                                             |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                | C1M5655CA002                                                                                | PLT320158     | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 322808 |                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 322812                         | Main Landing Gear Side Brace Actuator Locking Segments (Left) (#1) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                                                             |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                | C1M5655CA002                                                                                | PLT320158     | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 322808 |                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 322812                         | Main Landing Gear Side Brace Actuator Locking Segments (Left) (#1) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                                                             |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                | C1M5655CA002                                                                                | PLT320158     | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 322808 |                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 322812                         | Main Landing Gear Side Brace Actuator Locking Segments (Left) (#1) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                                                             |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                | C1M5655CA002                                                                                | PLT320158     | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 322808 |                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 322812                         | Main Landing Gear Side Brace Actuator Locking Segments (Left) (#1) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                                                             |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                | C1M5655CA002                                                                                | PLT320158     | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 322808 |                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 322812                         | Main Landing Gear Side Brace Actuator Locking Segments (Left) (#1) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                                                             |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                | C1M5655CA002                                                                                | PLT320158     | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 322808 |                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 322812                         | Main Landing Gear Side Brace Actuator Locking Segments (Left) (#1) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                                                             |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                | C1M5655CA002                                                                                | PLT320158     | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 322808 |                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 322812                         | Main Landing Gear Side Brace Actuator Locking Segments (Left) (#1) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                                                             |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                | C1M5655CA002                                                                                | PLT320158     | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 322808 |                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 322812                         | Main Landing Gear Side Brace Actuator Locking Segments (Left) (#1) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                                                             |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                | C1M5655CA002                                                                                | PLT320158     | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 322808 |                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 322812                         | Main Landing Gear Side Brace Actuator Locking Segments (Left) (#1) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                                                             |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                | C1M5655CA002                                                                                | PLT320158     | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 322808 |                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 322812                         | Main Landing Gear Side Brace Actuator Locking Segments (Left) (#1) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                                                             |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                | C1M5655CA002                                                                                | PLT320158     | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 322808 |                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 322812                         | Main Landing Gear Side Brace Actuator Locking Segments (Left) (#1) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                                                             |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                | C1M5655CA002                                                                                | PLT320158     | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 322808 |                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 322812                         | Main Landing Gear Side Brace Actuator Locking Segments (Left) (#1) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                                                             |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                | C1M5655CA002                                                                                | PLT320158     | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 322808 |                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 322812                         | Main Landing Gear Side Brace Actuator Locking Segments (Left) (#1) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                                                             |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                | C1M5655CA002                                                                                | PLT320158     | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 322808 |                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 322812                         | Main Landing Gear Side Brace Actuator Locking Segments (Left) (#1) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                                                             |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                | C1M5655CA002                                                                                | PLT320158     | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 322808 |                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 322812                         | Main Landing Gear Side Brace Actuator Locking Segments (Left) (#1) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                                                             |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                | C1M5655CA002                                                                                | PLT320158     | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 322808 |                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 322812                         | Main Landing Gear Side Brace Actuator Locking Segments (Left) (#1) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                                                             |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                | C1M5655CA002                                                                                | PLT320158     | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 322808 |                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 322812                         | Main Landing Gear Side Brace Actuator Locking Segments (Left) (#1) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                                                             |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                | C1M5655CA002                                                                                | PLT320158     | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 322808 |                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 322812                         | Main Landing Gear Side Brace Actuator Locking Segments (Left) (#1) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                                                             |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                | C1M5655CA002                                                                                | PLT320158     | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 322808 |                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 322812                         | Main Landing Gear Side Brace Actuator Locking Segments (Left) (#1) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                                                             |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                | C1M5655CA002                                                                                | PLT320158     | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 322808 |                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 322812                         | Main Landing Gear Side Brace Actuator Locking Segments (Left) (#1) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                                                             |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                | C1M5655CA002                                                                                | PLT320158     | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 322808 |                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 322812                         | Main Landing Gear Side Brace Actuator Locking Segments (Left) (#1) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                                                             |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                | C1M5655CA002                                                                                | PLT320158     | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 322808 |                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 322812                         | Main Landing Gear Side Brace Actuator Locking Segments (Left) (#1) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                                                             |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                | C1M5655CA002                                                                                | PLT320158     | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 322808 |                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 322812                         | Main Landing Gear Side Brace Actuator Locking Segments (Left) (#1) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                                                             |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                | C1M5655CA002                                                                                | PLT320158     | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 322808 |                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 322812                         | Main Landing Gear Side Brace Actuator Locking Segments (Left) (#1) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                                                             |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                | C1M5655CA002                                                                                | PLT320158     | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 322808 |                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 322812                         | Main Landing Gear Side Brace Actuator Locking Segments (Left) (#1) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                                                             |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                | C1M5655CA002                                                                                | PLT320158     | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 322808 |                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 322812                         | Main Landing Gear Side Brace Actuator Locking Segments (Left) (#1) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                                                             |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                | C1M5655CA002                                                                                | PLT320158     | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 322808 |                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 322812                         | Main Landing Gear Side Brace Actuator Locking Segments (Left) (#1) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                                                             |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                | C1M5655CA002                                                                                | PLT320158     | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 322808 |                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 322812                         | Main Landing Gear Side Brace Actuator Locking Segments (Left) (#1) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                                                             |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                | C1M5655CA002                                                                                | PLT320158     | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 322808 |                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 322812                         | Main Landing Gear Side Brace Actuator Locking Segments (Left) (#1) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                                                             |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                | C1M5655CA002                                                                                | PLT320158     | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 322808 |                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 322812                         | Main Landing Gear Side Brace Actuator Locking Segments (Left) (#1) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                                                             |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                | C1M5655CA002                                                                                | PLT320158     | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 322808 |                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 322812                         | Main Landing Gear Side Brace Actuator Locking Segments (Left) (#1) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                                                             |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                | C1M5655CA002                                                                                | PLT320158     | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 322808 |                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 322812                         | Main Landing Gear Side Brace Actuator Locking Segments (Left) (#1) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                                                             |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                | C1M5655CA002                                                                                | PLT320158     | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 322808 |                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 322812                         | Main Landing Gear Side Brace Actuator Locking Segments (Left) (#1) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                                                             |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                | C1M5655CA002                                                                                | PLT320158     | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 322808 |                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 322812                         | Main Landing Gear Side Brace Actuator Locking Segments (Left) (#1) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         |              |

| ATA<br>U=Custom                | Description                                          |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|--------------------------------|------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                | Part Number                                          | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position               | HW                                                   | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                | MM Ref                                               |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                                | Ops Number(s)                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 322815                         | Main Landing Gear Side Brace Actuator Locking        |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | Segments (Left) - Discard                            |               | AFL |             | 1117            |     | 20000            | 0           | 20000              |         | 0            |
|                                | C1M5655CA002                                         | PLT320158     | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                      |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 322812 |                                                      |               |     |             |                 |     |                  |             |                    |         |              |
| 322816                         | Main Landing Gear Side Brace Actuator Locking        |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | Segments (Right) (#1) - Removal / Installation       |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                | C1M5655CA002                                         | PLT100154     | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                |                                                      |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                       |                                                      |               |     |             |                 |     |                  |             |                    |         |              |
| 322819                         | Main Landing Gear Side Brace Actuator Locking        |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | Segments (Right) - Discard                           |               | AFL |             | 1117            |     | 20000            | 0           | 20000              |         | 0            |
|                                | C1M5655CA002                                         | PLT100154     | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                      |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 322816 |                                                      |               |     |             |                 |     |                  |             |                    |         |              |
| 322820                         | Gland, Cylinder (Left) - Removal / Installation      |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | C1M5602CA002                                         | PLT320248     | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                |                                                      |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                |                                                      |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                       |                                                      |               |     |             |                 |     |                  |             |                    |         |              |
| 322823                         | Main Landing Gear Side Brace Actuator Cylinder Gland |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | (Left) - Discard                                     |               | AFL |             | 1117            |     | 20000            | 0           | 20000              |         | 0            |
|                                | C1M5602CA002                                         | PLT320248     | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                      |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 322820 |                                                      |               |     |             |                 |     |                  |             |                    |         |              |
| 322824                         | Gland, Cylinder (Right) - Removal / Installation     |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | C1M5602CA002                                         | PLT320270     | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                |                                                      |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                |                                                      |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                       |                                                      |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom                | Description                                                               |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|--------------------------------|---------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                | Part Number                                                               | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position               | HW                                                                        | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                | MM Ref                                                                    |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                                | Ops Number(s)                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 322827                         | Main Landing Gear Side Brace Actuator Cylinder Gland (Right) - Discard    |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                                           |               | AFL |             | 1117            |     | 20000            | 0           | 20000              |         | 0            |
|                                | C1M5602CA002                                                              | PLT320270     | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 322824 |                                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| 322828                         | ROD End Machining (Left) - Removal / Installation                         |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                                           |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                | C1M5670CA001                                                              | PLT0192       | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                |                                                                           |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                       |                                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| 322831                         | Main Landing Gear Side Brace Actuator ROD End Machining (Left) - Discard  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                                           |               | AFL |             | 1117            |     | 20000            | 0           | 20000              |         | 0            |
|                                | C1M5670CA001                                                              | PLT0192       | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 322828 |                                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| 322832                         | ROD End Machining (Right) - Removal / Installation                        |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                                           |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                | C1M5670CA001                                                              | PLT0207       | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                |                                                                           |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                       |                                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| 322835                         | Main Landing Gear Side Brace Actuator ROD End Machining (Right) - Discard |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                                           |               | AFL |             | 1117            |     | 20000            | 0           | 20000              |         | 0            |
|                                | C1M5670CA001                                                              | PLT0207       | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 322832 |                                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| 322836                         | Nose Landing Gear Door Control Rods (Left) - Removal / Installation       |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                                           |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                | 60P5200902Z070                                                            | NSN           | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                |                                                                           |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                       |                                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| 322837                         | Nose Landing Gear Door Control Rods (Right) - Removal / Installation      |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                                           |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                | 60P5200902Z070                                                            | NSN           | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                |                                                                           |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                       |                                                                           |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                            |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                                            | Serial Number |     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                                     | SW            |     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                                 |               |     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                                          |               |     |             |                 |     |                  |             |                     |         |              |
| 322840           | Nose Landing Gear Door Hinges (Left Forward) - Removal / Installation  |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                        |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 60P5280111A019                                                         | SN-UNKNOWN    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                        |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                        |               |     |             |                 |     |                  |             |                     |         |              |
| 322841           | Nose Landing Gear Door Hinges (Right Forward) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                        |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 60P5280121A017                                                         | SN-UNKNOWN    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                        |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                        |               |     |             |                 |     |                  |             |                     |         |              |
| 322842           | Nose Landing Gear Door Hinges (Left Aft) - Removal / Installation      |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                        |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 60P5280111A013                                                         | SN-UNKNOWN    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                        |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                        |               |     |             |                 |     |                  |             |                     |         |              |
| 322843           | Nose Landing Gear Door Hinges (Right Aft) - Removal / Installation     |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                        |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 60P5280121A012                                                         | SN-UNKNOWN    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                        |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                        |               |     |             |                 |     |                  |             |                     |         |              |
| 323000           | Main Landing Gear Control Manifold - Removal / Installation            |               | HRS |             | 2120.8          |     |                  | 925.3       |                     |         | 0            |
|                  |                                                                        |               | AFL |             | 861             |     |                  | 256         |                     |         | 0            |
|                  | 60P3230031Z005                                                         | 0141          | MOS |             | 86              |     |                  | 10 Mar 2019 |                     |         |              |
|                  |                                                                        |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                        |               |     |             |                 |     |                  |             |                     |         |              |
| 323001           | Landing Gear Control Unit - Removal / Installation                     |               | HRS |             | 2345.1          |     |                  | 701         |                     |         | 0            |
|                  |                                                                        |               | AFL |             | 936             |     |                  | 181         |                     |         | 0            |
|                  | 60P3230090Z002                                                         | 016LG01108C   | MOS |             | 97.1            |     |                  | 09 Apr 2018 |                     |         |              |
|                  |                                                                        |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                        |               |     |             |                 |     |                  |             |                     |         |              |
| 323200           | Main Landing Gear Door Actuator (Left) - Removal / Installation        |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                        |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 60P5280901Z004                                                         | 0347          | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                        |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                        |               |     |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom                | Description                                                                           |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|--------------------------------|---------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                | Part Number                                                                           | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position               | HW                                                                                    | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                | MM Ref                                                                                |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                                | Ops Number(s)                                                                         |               |     |             |                 |     |                  |             |                    |         |              |
| 323201                         | Main Landing Gear Door Actuator (Right) - Removal / Installation                      |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                                                       |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                | 60P5280901Z004                                                                        | 0345          | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                |                                                                                       |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                       |                                                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| 323204                         | Main Landing Gear Uplock Roller Corrosion Inhibiting Compound Application - Servicing |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                                |                                                                                       |               | AFL |             |                 |     |                  |             |                    |         | 0            |
|                                |                                                                                       |               | MOS |             | 28.8            |     |                  | 18 Dec 2023 |                    |         |              |
|                                |                                                                                       |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                       |                                                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| 323205                         | Main Landing Gear Uplock Roller (Left) - Removal / Installation                       |               | HRS |             | 2345.1          |     |                  | 701         |                    |         | 0            |
|                                |                                                                                       |               | AFL |             | 936             |     |                  | 181         |                    |         | 0            |
|                                | C1M5331CA001                                                                          | N/A           | MOS |             | 97              |     |                  | 10 Apr 2018 |                    |         |              |
|                                |                                                                                       |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                       |                                                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| 323206                         | Main Landing Gear Uplock Roller (Right) - Removal / Installation                      |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                                                       |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                | C1M5330CA001                                                                          | SN-UNKNOWN    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                |                                                                                       |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                       |                                                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| 323209                         | Main Landing Gear Door Actuator (Left) - Discard                                      |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | 60P5280901Z004                                                                        |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                |                                                                                       |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                |                                                                                       |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                       |                                                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 323200 |                                                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| 323210                         | Main Landing Gear Door Actuator (Right) - Discard                                     |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | 60P5280901Z004                                                                        |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                |                                                                                       |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                |                                                                                       |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                       |                                                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 323201 |                                                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| 323300                         | Main Landing Gear Uplock Hook / Latch Assembly (Left) - Removal / Installation        |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                                                       |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                | 60P3232030Z005                                                                        | PLT0196       | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                |                                                                                       |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                       |                                                                                       |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom                | Description                                              |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|--------------------------------|----------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                                | Part Number                                              | Serial Number |     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position               | HW                                                       | SW            |     |             |                 |     |                  |             |                     |         | Manufacturer |
|                                | MM Ref                                                   |               |     |             |                 |     |                  |             |                     |         | Date Type    |
|                                | Ops Number(s)                                            |               |     |             |                 |     |                  |             |                     |         |              |
| 323301                         | Main Landing Gear Uplock Hook / Latch Assembly (Right)   |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                                | - Removal / Installation                                 |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                                | 60P3232031Z005                                           | PLT0199       | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                                |                                                          |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe                       |                                                          |               |     |             |                 |     |                  |             |                     |         |              |
| 323304                         | Main Landing Gear Uplock Hook / Latch Assembly           |               | HRS |             | 730.5           |     |                  | 2315.6      |                     |         | 0            |
|                                | Corrosion Inhibiting Compound Application - Servicing    |               | AFL |             |                 |     |                  |             |                     |         | 0            |
|                                |                                                          |               | MOS |             | 28.8            |     |                  | 18 Dec 2023 |                     |         |              |
|                                |                                                          |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe                       |                                                          |               |     |             |                 |     |                  |             |                     |         |              |
| 323305                         | Main Landing Gear Uplock Hook / Latch Assembly (Left) -  |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                                | Discard                                                  |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                                | 60P3232030Z005                                           | PLT0196       | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                                |                                                          |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe                       |                                                          |               |     |             |                 |     |                  |             |                     |         |              |
| Notes: MRI PARENT CODE: 323300 |                                                          |               |     |             |                 |     |                  |             |                     |         |              |
| 323306                         | Main Landing Gear Uplock Hook / Latch Assembly (Right)   |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                                | - Discard                                                |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                                | 60P3232031Z005                                           | PLT0199       | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                                |                                                          |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe                       |                                                          |               |     |             |                 |     |                  |             |                     |         |              |
| Notes: MRI PARENT CODE: 323301 |                                                          |               |     |             |                 |     |                  |             |                     |         |              |
| 323600                         | Nose Landing Gear Control Manifold - Removal /           |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                                | Installation                                             |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                                | 60P3230030Z005                                           | 0220          | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                                |                                                          |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe                       |                                                          |               |     |             |                 |     |                  |             |                     |         |              |
| 323602                         | Nose Landing Gear Door Actuator - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                                | 60P5280902Z004                                           |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                                | 0182                                                     |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                                |                                                          |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe                       |                                                          |               |     |             |                 |     |                  |             |                     |         |              |
| 323700                         | Nose Landing Gear Uplock Hook and Latch Assembly -       |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                                | Removal / Installation                                   |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                                | 60P3237010Z004                                           | PLT0195       | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                                |                                                          |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe                       |                                                          |               |     |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom  | Description                                                                                |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(* =Adj) | Max Due | Avg Man Hrs  |
|------------------|--------------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|----------------------|---------|--------------|
|                  | Part Number                                                                                | Serial Number |     |             |                 |     |                  |             |                      |         | Approx Price |
| Logbook Position | HW                                                                                         | SW            |     |             |                 |     |                  |             |                      |         | Manufacturer |
|                  | MM Ref                                                                                     |               |     |             |                 |     |                  |             |                      |         | Date Type    |
|                  | Ops Number(s)                                                                              |               |     |             |                 |     |                  |             |                      |         |              |
| 323702           | Nose Landing Gear Uplock Roller - Removal / Installation                                   |               | HRS |             | 3046.1          |     |                  | 0           |                      |         | 0            |
|                  | C2M5244CA001                                                                               | NSN           | AFL |             | 1117            |     |                  | 0           |                      |         | 0            |
|                  |                                                                                            |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                      |         |              |
|                  | Airframe                                                                                   |               | MSC |             |                 |     | O/C              |             |                      |         |              |
| 323800           | Nose Landing Gear Downlock Actuator - Removal / Installation                               |               | HRS |             | 3041.4          |     |                  | 4.7         |                      |         | 0            |
|                  | C2A4650CA002                                                                               | PLT0294       | AFL |             | 1114            |     |                  | 3           |                      |         | 0            |
|                  |                                                                                            |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                      |         |              |
|                  | Airframe                                                                                   |               | MSC |             |                 |     | O/C              |             |                      |         |              |
| 323801           | Nose Landing Gear Actuator - Removal / Installation                                        |               | HRS |             | 3046.1          |     |                  | 0           |                      |         | 0            |
|                  | 60P3238010Z002                                                                             | 0174          | AFL |             | 1117            |     |                  | 0           |                      |         | 0            |
|                  |                                                                                            |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                      |         |              |
|                  | Airframe                                                                                   |               | MSC |             |                 |     | O/C              |             |                      |         |              |
| 323811           | Nose Landing Gear Retraction Actuator Attach Pin - Discard                                 |               | HRS |             | 3046.1          |     |                  | 0           |                      |         | 0            |
|                  | C2M5311CA001                                                                               | PLT420097     | AFL |             | 1117            |     | 20000            | 0           | 20000                |         | 0            |
|                  |                                                                                            |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                      |         |              |
|                  | Airframe                                                                                   |               |     |             |                 |     |                  |             |                      |         |              |
| 323815           | Nose Landing Gear Downlock Spring (Left) - Discard                                         |               | HRS |             | 3046.1          |     |                  | 0           |                      |         | 0            |
|                  | C2E5441LA001                                                                               | SN-UNKNOWN    | AFL |             | 1117            |     | 20000            | 0           | 20000                |         | 0            |
|                  |                                                                                            |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                      |         |              |
|                  | Airframe                                                                                   |               |     |             |                 |     |                  |             |                      |         |              |
| 323816           | Nose Landing Gear Downlock Spring (Right) - Discard                                        |               | HRS |             | 3046.1          |     |                  | 0           |                      |         | 0            |
|                  | C2E5441RA001                                                                               | SN-UNKNOWN    | AFL |             | 1117            |     | 20000            | 0           | 20000                |         | 0            |
|                  |                                                                                            |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                      |         |              |
|                  | Airframe                                                                                   |               |     |             |                 |     |                  |             |                      |         |              |
| 323900           | Landing Gear Emergency Extension Nitrogen Blow-Down Bottle (Left) - Removal / Installation |               | HRS |             | 730.5           |     |                  | 2315.6      |                      |         | 0            |
|                  | 1159SCH233-11                                                                              | ALT603-16300  | AFL |             | 315             |     |                  | 802         |                      |         | 0            |
|                  |                                                                                            |               | MOS | TSN:6       | 28.7            |     |                  | 21 Dec 2023 |                      |         |              |
|                  | Airframe                                                                                   |               | MSC |             |                 |     | O/C              |             |                      |         |              |

| ATA<br>U=Custom                | Description                                                                                 |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|--------------------------------|---------------------------------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                | Part Number                                                                                 | Serial Number |                     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position               | HW                                                                                          | SW            |                     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                | MM Ref                                                                                      |               |                     |             |                 |     |                  |             |                    |         | Date Type    |
|                                | Ops Number(s)                                                                               |               |                     |             |                 |     |                  |             |                    |         |              |
| 323901                         | Landing Gear Emergency Extension Nitrogen Blow-Down Bottle (Right) - Removal / Installation |               | HRS                 |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                                |                                                                                             |               | AFL                 |             | 315             |     |                  | 802         |                    |         | 0            |
|                                | 1159SCH233-11                                                                               | ALT603-16310  | MOS                 | TSN:6       | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
|                                |                                                                                             |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
| Airframe                       |                                                                                             |               |                     |             |                 |     |                  |             |                    |         |              |
| 323904                         | Landing Gear Emergency Extension Blow-Down Bottle Transducer - Removal / Installation       |               | HRS                 |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                                                             |               | AFL                 |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                | 60P2930061Z001                                                                              | 62140         | MOS                 |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                |                                                                                             |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
| Airframe                       |                                                                                             |               |                     |             |                 |     |                  |             |                    |         |              |
| 323905                         | Landing Gear Blow-Down Bottle AIR Release Valve - Removal / Installation                    |               | HRS                 |             | 2673.9          |     |                  | 372.2       |                    |         | 0            |
|                                |                                                                                             |               | AFL                 |             | 1020            |     |                  | 97          |                    |         | 0            |
|                                | 60P3239029Z004                                                                              | 0049          | MOS                 |             | 109.4           |     |                  | 29 Mar 2017 |                    |         |              |
|                                |                                                                                             |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
| Airframe                       |                                                                                             |               |                     |             |                 |     |                  |             |                    |         |              |
| 323906                         | Landing Gear Blow-Down Bottle Pressure Gage - Removal / Installation                        |               | HRS                 |             | 2762.2          |     |                  | 283.9       |                    |         | 0            |
|                                |                                                                                             |               | AFL                 |             | 1041            |     |                  | 76          |                    |         | 0            |
|                                | GP20-36                                                                                     | 14-090911     | MOS                 | TSN:17      | 112.9           |     |                  | 14 Dec 2016 |                    |         |              |
|                                |                                                                                             |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
| Airframe                       |                                                                                             |               |                     |             |                 |     |                  |             |                    |         |              |
| 323910                         | Landing Gear Emergency Extension Nitrogen Blow-Down Bottle (Left) - Discard                 |               | HRS                 |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                                                             |               | AFL                 |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                | 1159SCH233-11                                                                               | ALT603-12656  | MOS                 |             | 128.6           |     | 180              | 24 Aug 2015 | 31 Jan 2030        |         |              |
|                                |                                                                                             |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Airframe                       |                                                                                             |               |                     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 323900 |                                                                                             |               |                     |             |                 |     |                  |             |                    |         |              |
| 323911                         | Landing Gear Emergency Extension Nitrogen Blow-Down Bottle (Right) - Discard                |               | HRS                 |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                                                             |               | AFL                 |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                | 1159SCH233-11                                                                               | ALT603-12659  | MOS                 |             | 128.6           |     | 180              | 24 Aug 2015 | 31 Jan 2030        |         |              |
|                                |                                                                                             |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Airframe                       |                                                                                             |               |                     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 323901 |                                                                                             |               |                     |             |                 |     |                  |             |                    |         |              |



| ATA<br>U=Custom                                                    | Description                                                                                            |               | UOM                                               | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due     | Avg Man Hrs  |
|--------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------|---------------|---------------------------------------------------|-------------|-----------------|-----|------------------|-------------|---------------------|-------------|--------------|
|                                                                    | Part Number                                                                                            | Serial Number |                                                   |             |                 |     |                  |             |                     |             | Approx Price |
| Logbook Position                                                   | HW                                                                                                     | SW            |                                                   |             |                 |     |                  |             |                     |             | Manufacturer |
|                                                                    | MM Ref                                                                                                 |               |                                                   |             |                 |     |                  |             |                     |             | Date Type    |
|                                                                    | Ops Number(s)                                                                                          |               |                                                   |             |                 |     |                  |             |                     |             |              |
| 323912                                                             | Landing Gear Emergency Extension Nitrogen Blow-Down<br>Bottle (Hydrostatic) (Left) - Functional Check  |               | HRS                                               |             | 730.5           |     |                  | 2315.6      |                     |             | 0            |
|                                                                    |                                                                                                        |               | AFL                                               |             | 315             |     |                  | 802         |                     |             | 0            |
|                                                                    |                                                                                                        |               | MOS                                               |             | 28.7            |     | 60               | 21 Dec 2023 | 30 Jun 2028         |             |              |
|                                                                    |                                                                                                        |               | [End Of Month Item]                               |             |                 |     |                  |             |                     |             | HYDRO CHECK  |
| Airframe                                                           |                                                                                                        |               |                                                   |             |                 |     |                  |             |                     |             |              |
| Notes: PN: 1159SCH233-11 SN: ALT603-12656. MRI PARENT CODE: 323900 |                                                                                                        |               |                                                   |             |                 |     |                  |             |                     |             |              |
| 323913                                                             | Landing Gear Emergency Extension Nitrogen Blow-Down<br>Bottle (Hydrostatic) (Right) - Functional Check |               | HRS                                               |             | 730.5           |     |                  | 2315.6      |                     |             | 0            |
|                                                                    |                                                                                                        |               | AFL                                               |             | 315             |     |                  | 802         |                     |             | 0            |
|                                                                    |                                                                                                        |               | MOS                                               |             | 28.7            |     | 60               | 21 Dec 2023 | 30 Jun 2028         |             |              |
|                                                                    |                                                                                                        |               | [End Of Month Item]                               |             |                 |     |                  |             |                     |             | HYDRO CHECK  |
| Airframe                                                           |                                                                                                        |               |                                                   |             |                 |     |                  |             |                     |             |              |
| Notes: PN: 1159SCH233-11 SN: ALT603-12659. MRI PARENT CODE: 323901 |                                                                                                        |               |                                                   |             |                 |     |                  |             |                     |             |              |
| 323916                                                             | Landing Gear Emergency Extension System - Operational<br>Check                                         |               | HRS                                               |             | 730.5           |     | 1800             | 2315.6      | 4115.6              | 4165.6      | 0            |
|                                                                    |                                                                                                        |               | AFL                                               |             | 315             |     |                  | 802         |                     |             | 0            |
|                                                                    |                                                                                                        |               | MOS                                               |             | 28.7            |     | 36               | 21 Dec 2023 | 31 Dec 2026         | 31 Jan 2027 |              |
|                                                                    |                                                                                                        |               | [End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50] |             |                 |     |                  |             |                     |             |              |
| Airframe                                                           |                                                                                                        |               |                                                   |             |                 |     |                  |             |                     |             |              |
| 323917                                                             | Landing Gear Emergency Extension System - General<br>Visual Inspection                                 |               | HRS                                               |             | 137             |     |                  | 2909.1      |                     |             | 0            |
|                                                                    |                                                                                                        |               | AFL                                               |             | 52              |     |                  | 1065        |                     |             | 0            |
|                                                                    |                                                                                                        |               | MOS                                               |             | 5.5             |     | 24               | 27 Nov 2025 | 30 Nov 2027         | 31 Dec 2027 |              |
|                                                                    |                                                                                                        |               | [End Of Month Item] [MOS: +1m/-1m]                |             |                 |     |                  |             |                     |             |              |
| Airframe                                                           |                                                                                                        |               |                                                   |             |                 |     |                  |             |                     |             |              |
| 052011                                                             |                                                                                                        |               |                                                   |             |                 |     |                  |             |                     |             |              |
| 323918                                                             | Landing Gear Emergency Extension T-Handle - Rigging                                                    |               | HRS                                               |             | 3046.1          |     |                  | 0           |                     |             | 0            |
|                                                                    |                                                                                                        |               | AFL                                               |             | 1117            |     |                  | 0           |                     |             | 0            |
|                                                                    |                                                                                                        |               | MOS                                               |             | 128.6           |     |                  | 24 Aug 2015 |                     |             |              |
|                                                                    |                                                                                                        |               | MSC                                               |             |                 |     | O/C              |             |                     |             |              |
| Airframe                                                           |                                                                                                        |               |                                                   |             |                 |     |                  |             |                     |             |              |
| 323919                                                             | Landing Gear Blow-Down Bottle Relief Valve - Removal /<br>Installation<br>60P3239072Z0060193           |               | HRS                                               |             | 3046.1          |     |                  | 0           |                     |             | 0            |
|                                                                    |                                                                                                        |               | AFL                                               |             | 1117            |     |                  | 0           |                     |             | 0            |
|                                                                    |                                                                                                        |               | MOS                                               |             | 128.6           |     |                  | 24 Aug 2015 |                     |             |              |
|                                                                    |                                                                                                        |               | MSC                                               |             |                 |     | O/C              |             |                     |             |              |
| Airframe                                                           |                                                                                                        |               |                                                   |             |                 |     |                  |             |                     |             |              |

| ATA<br>U=Custom                | Description                                                                 |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|--------------------------------|-----------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                | Part Number                                                                 | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position               | HW                                                                          | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                | MM Ref                                                                      |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                                | Ops Number(s)                                                               |               |     |             |                 |     |                  |             |                    |         |              |
| 323920                         | Landing Gear Emergency Extension T-Handle Assembly - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                                             |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                | 60P3239072Z006                                                              | 0193          | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                |                                                                             |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                       |                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 323919 |                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 323921                         | Landing Gear Emergency Extension Cable Assembly - Removal / Installation    |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                                             |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                | 60P3239032Z002                                                              | 142           | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                |                                                                             |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                       |                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 324100                         | Nose Wheel (Left) - Removal / Installation                                  |               | HRS | TSN:1614    | 298.3           |     |                  | 2747.8      |                    |         | 0            |
|                                | 90005587                                                                    | JUL19-1392    | AFL | TSN:734     | 114             |     |                  | 1003        |                    |         | 0            |
|                                |                                                                             |               | MOS |             | 9.4             |     |                  | 30 Jul 2025 |                    |         |              |
|                                |                                                                             |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                       |                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 324101                         | Nose Wheel (Right) - Removal / Installation                                 |               | HRS | TSN:554.6   | 298.3           |     |                  | 2747.8      |                    |         | 0            |
|                                | 90005587                                                                    | MAR20-1612    | AFL | TSN:273     | 114             |     |                  | 1003        |                    |         | 0            |
|                                |                                                                             |               | MOS |             | 9.4             |     |                  | 30 Jul 2025 |                    |         |              |
|                                |                                                                             |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                       |                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 324102                         | Nose Wheel and Tire Assembly (Left) - Removal / Installation                |               | HRS | TSN:1614    | 298.3           |     |                  | 2747.8      |                    |         | 0            |
|                                |                                                                             |               | AFL | TSN:734     | 114             |     |                  | 1003        |                    |         | 0            |
|                                | 60P3241101A001                                                              | JUL19-1392    | MOS |             | 9.4             |     |                  | 30 Jul 2025 |                    |         |              |
|                                |                                                                             |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                       |                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 324103                         | Nose Wheel and Tire Assembly (Right) - Removal / Installation               |               | HRS | TSN:554.6   | 298.3           |     |                  | 2747.8      |                    |         | 0            |
|                                |                                                                             |               | AFL | TSN:273     | 114             |     |                  | 1003        |                    |         | 0            |
|                                | 60P3241101A001                                                              | MAR20-1612    | MOS |             | 9.4             |     |                  | 30 Jul 2025 |                    |         |              |
|                                |                                                                             |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                       |                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 324106                         | Nose Tire (Left) - Removal / Installation                                   |               | HRS |             | 298.3           |     |                  | 2747.8      |                    |         | 0            |
|                                | 217K42-1                                                                    | 42290529      | AFL |             | 114             |     |                  | 1003        |                    |         | 0            |
|                                |                                                                             |               | MOS | TSN:11      | 9.4             |     |                  | 30 Jul 2025 |                    |         |              |
|                                |                                                                             |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                       |                                                                             |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                            |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|--------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                            | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                     | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                 |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                          |               |     |             |                 |     |                  |             |                    |         |              |
| 324107           | Nose Tire (Right) - Removal / Installation             |               | HRS |             | 298.3           |     |                  | 2747.8      |                    |         | 0            |
|                  | 217K42-1                                               | 42300410      | AFL |             | 844             |     |                  | 273         |                    |         | 0            |
|                  |                                                        |               | MOS | TSN:11      | 9.4             |     |                  | 30 Jul 2025 |                    |         |              |
|                  | Airframe                                               |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 324108           | Nose Wheel Axle Nut (Left) - Removal / Installation    |               | HRS |             | 3041.4          |     |                  | 4.7         |                    |         | 0            |
|                  | C2M5248CA001                                           | PLT241390     | AFL |             | 1114            |     |                  | 3           |                    |         | 0            |
|                  |                                                        |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                               |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 324109           | Nose Wheel Axle Nut (Right) - Removal / Installation   |               | HRS |             | 3041.4          |     |                  | 4.7         |                    |         | 0            |
|                  | C2M5248CA001                                           | PLT241414     | AFL |             | 1114            |     |                  | 3           |                    |         | 0            |
|                  |                                                        |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                               |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 324115           | Nose Tire Assembly - Check                             |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                        |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                        |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                               |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 324116           | Nose Wheel Bearing (Left) - Inspection / Grease        |               | HRS |             | 663.7           |     |                  | 2382.4      |                    |         | 0            |
|                  |                                                        |               | AFL |             | 291             |     |                  | 826         |                    |         | 0            |
|                  |                                                        |               | MOS |             | 24.9            |     |                  | 15 Apr 2024 |                    |         |              |
|                  | Airframe                                               |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 324117           | Nose Wheel Bearing (Right) - Inspection / Grease       |               | HRS |             | 663.7           |     |                  | 2382.4      |                    |         | 0            |
|                  |                                                        |               | AFL |             | 291             |     |                  | 826         |                    |         | 0            |
|                  |                                                        |               | MOS |             | 24.9            |     |                  | 15 Apr 2024 |                    |         |              |
|                  | Airframe                                               |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 324120           | Nose Wheel (Left) - Special Detailed Inspection (Ndt)  |               | HRS |             | 867.07          |     |                  | 2179.03     |                    |         | 0            |
|                  |                                                        |               | AFL |             | 357             |     |                  | 760         |                    |         | 0            |
|                  |                                                        |               | MOS |             | 36.9            |     |                  | 13 Apr 2023 |                    |         |              |
|                  | Airframe                                               |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 324121           | Nose Wheel (Right) - Special Detailed Inspection (Ndt) |               | HRS |             | 867.07          |     |                  | 2179.03     |                    |         | 0            |
|                  |                                                        |               | AFL |             | 357             |     |                  | 760         |                    |         | 0            |
|                  |                                                        |               | MOS |             | 36.9            |     |                  | 13 Apr 2023 |                    |         |              |
|                  | Airframe                                               |               | MSC |             |                 |     | O/C              |             |                    |         |              |

| ATA<br>U=Custom  | Description                                          |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                          | Serial Number |                     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                   | SW            |                     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                               |               |                     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                        |               |                     |             |                 |     |                  |             |                    |         |              |
| 324122           | Nose Wheel (Left) - Restore                          |               | HRS                 |             |                 |     |                  |             |                    |         | 0            |
|                  | PN                                                   | SN-UNKNOWN    | AFL                 |             |                 |     |                  |             |                    |         | 0            |
|                  |                                                      |               | DATE                |             |                 |     |                  |             |                    |         |              |
|                  | Airframe                                             |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  |                                                      |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 324200           | Main Wheel (Left Inboard) - Removal / Installation   |               | HRS                 | TSN:2137.7  | 213             |     |                  | 2833.1      |                    |         | 0            |
|                  | 90005586-1                                           | MAR18-1975    | AFL                 | TSN:932     | 76              |     |                  | 1041        |                    |         | 0            |
|                  |                                                      |               | MOS                 |             | 7               |     |                  | 10 Oct 2025 |                    |         |              |
|                  | Airframe                                             |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
| 324201           | Main Wheel (Left Outboard) - Removal / Installation  |               | HRS                 |             | 489.6           |     |                  | 2556.5      |                    |         | 0            |
|                  | 90005586-1                                           | AUG-1803      | AFL                 |             | 196             |     |                  | 921         |                    |         | 0            |
|                  |                                                      |               | MOS                 |             | 15.2            |     |                  | 06 Feb 2025 |                    |         |              |
|                  | Airframe                                             |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
| 324202           | Main Wheel (Right Inboard) - Removal / Installation  |               | HRS                 |             | 392.4           |     |                  | 2653.7      |                    |         | 0            |
|                  | 90005586-1                                           | JUL12-0261    | AFL                 |             | 162             |     |                  | 955         |                    |         | 0            |
|                  |                                                      |               | MOS                 |             | 12.2            |     |                  | 06 May 2025 |                    |         |              |
|                  | Airframe                                             |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
| 324203           | Main Wheel (Right Outboard) - Removal / Installation |               | HRS                 |             | 251.5           |     |                  | 2794.6      |                    |         | 0            |
|                  | 90005586-1                                           | MAY13-0410    | AFL                 |             | 95              |     |                  | 1022        |                    |         | 0            |
|                  |                                                      |               | MOS                 |             | 8.4             |     |                  | 31 Aug 2025 |                    |         |              |
|                  | Airframe                                             |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
| 324204           | Main Tire (Left Inboard) - Removal / Installation    |               | HRS                 |             | 213             |     |                  | 2833.1      |                    |         | 0            |
|                  | 379Q02-2                                             | 51251301      | AFL                 |             | 76              |     |                  | 1041        |                    |         | 0            |
|                  |                                                      |               | MOS                 | TSN:3       | 7               |     |                  | 10 Oct 2025 |                    |         |              |
|                  | Airframe                                             |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
| 324205           | Main Tire (Left Outboard) - Removal / Installation   |               | HRS                 |             | 489.6           |     |                  | 2556.5      |                    |         | 0            |
|                  | 379Q02-2                                             | 40311291      | AFL                 |             | 196             |     |                  | 921         |                    |         | 0            |
|                  |                                                      |               | MOS                 | TSN:11      | 15.2            |     |                  | 06 Feb 2025 |                    |         |              |
|                  | Airframe                                             |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
| 324206           | Main Tire (Right Inboard) - Removal / Installation   |               | HRS                 |             | 392.4           |     |                  | 2653.7      |                    |         | 0            |
|                  | 379Q02-2                                             | 42331304      | AFL                 |             | 162             |     |                  | 955         |                    |         | 0            |
|                  |                                                      |               | MOS                 | TSN:7       | 12.2            |     |                  | 06 May 2025 |                    |         |              |
|                  | Airframe                                             |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                           |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-----------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                           | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                    | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                         |               |     |             |                 |     |                  |             |                    |         |              |
| 324207           | Main Tire (Right Outboard) - Removal / Installation                   |               | HRS |             | 251.5           |     |                  | 2794.6      |                    |         | 0            |
|                  | 379Q02-2                                                              | 50651317      | AFL |             | 95              |     |                  | 1022        |                    |         | 0            |
|                  |                                                                       |               | MOS | TSN:5       | 8.4             |     |                  | 31 Aug 2025 |                    |         |              |
|                  | Airframe                                                              |               |     | MSC         |                 |     |                  | O/C         |                    |         |              |
| 324208           | Main Wheel CAP (Left Inboard) - Removal / Installation                |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P3247030Z001                                                        | SN-UNKNOWN    | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                       |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                              |               |     | MSC         |                 |     |                  | O/C         |                    |         |              |
| 324209           | Main Wheel CAP (Left Outboard) - Removal / Installation               |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P3247030Z001                                                        | SN-UNKNOWN    | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                       |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                              |               |     | MSC         |                 |     |                  | O/C         |                    |         |              |
| 324210           | Main Wheel CAP (Right Inboard) - Removal / Installation               |               | HRS |             | 2430.9          |     |                  | 615.2       |                    |         | 0            |
|                  | 60P3247030Z001                                                        | SN-UNKNOWN    | AFL |             | 952             |     |                  | 165         |                    |         | 0            |
|                  |                                                                       |               | MOS |             | 99.1            |     |                  | 08 Feb 2018 |                    |         |              |
|                  | Airframe                                                              |               |     | MSC         |                 |     |                  | O/C         |                    |         |              |
| 324211           | Main Wheel CAP (Right Outboard) - Removal / Installation              |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P3247030Z001                                                        | SN-UNKNOWN    | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                       |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                              |               |     | MSC         |                 |     |                  | O/C         |                    |         |              |
| 324213           | Main Wheel and Tire Assembly (Left Inboard) - Removal / Installation  |               | HRS | TSN:2137.7  | 213             |     |                  | 2833.1      |                    |         | 0            |
|                  |                                                                       |               | AFL | TSN:932     | 76              |     |                  | 1041        |                    |         | 0            |
|                  | 60P3242101A005                                                        | MAR18-1975    | MOS |             | 7               |     |                  | 10 Oct 2025 |                    |         |              |
|                  | Airframe                                                              |               |     | MSC         |                 |     |                  | O/C         |                    |         |              |
| 324214           | Main Wheel and Tire Assembly (Left Outboard) - Removal / Installation |               | HRS |             | 489.6           |     |                  | 2556.5      |                    |         | 0            |
|                  |                                                                       |               | AFL |             | 196             |     |                  | 921         |                    |         | 0            |
|                  | 60P3242101A005                                                        | AUG17-1803    | MOS |             | 15.2            |     |                  | 06 Feb 2025 |                    |         |              |
|                  | Airframe                                                              |               |     | MSC         |                 |     |                  | O/C         |                    |         |              |
| 324215           | Main Wheel and Tire Assembly (Right Inboard) - Removal / Installation |               | HRS |             | 392.4           |     |                  | 2653.7      |                    |         | 0            |
|                  |                                                                       |               | AFL |             | 162             |     |                  | 955         |                    |         | 0            |
|                  | 60P3242101A005                                                        | JUL12-0261    | MOS |             | 12.2            |     |                  | 06 May 2025 |                    |         |              |
|                  | Airframe                                                              |               |     | MSC         |                 |     |                  | O/C         |                    |         |              |

| ATA<br>U=Custom  | Description                                                            |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                            | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                     | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                 |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| 324216           | Main Wheel and Tire Assembly (Right Outboard) - Removal / Installation |               | HRS |             | 251.5           |     |                  | 2794.6      |                    |         | 0            |
|                  | 60P3242101A005                                                         |               | AFL |             | 95              |     |                  | 1022        |                    |         | 0            |
|                  | MAY13-0410                                                             |               | MOS |             | 8.4             |     |                  | 31 Aug 2025 |                    |         |              |
|                  |                                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 324221           | Main Landing Gear Wheel Bearing (Left Inboard) - Inspection / Grease   |               | HRS |             | 213             |     |                  | 2833.1      |                    |         | 0            |
|                  |                                                                        |               | AFL |             | 76              |     |                  | 1041        |                    |         | 0            |
|                  |                                                                        |               | MOS |             | 7               |     |                  | 10 Oct 2025 |                    |         |              |
|                  |                                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 324222           | Main Landing Gear Wheel Bearing (Left Outboard) - Inspection / Grease  |               | HRS |             | 1038.6          |     |                  | 2007.5      |                    |         | 0            |
|                  |                                                                        |               | AFL |             | 409             |     |                  | 708         |                    |         | 0            |
|                  |                                                                        |               | MOS |             | 42.6            |     |                  | 23 Oct 2022 |                    |         |              |
|                  |                                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 324223           | Main Landing Gear Wheel Bearing (Right Inboard) - Inspection / Grease  |               | HRS |             | 392.4           |     |                  | 2653.7      |                    |         | 0            |
|                  |                                                                        |               | AFL |             | 162             |     |                  | 955         |                    |         | 0            |
|                  |                                                                        |               | MOS |             | 12.2            |     |                  | 06 May 2025 |                    |         |              |
|                  |                                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 324224           | Main Landing Gear Wheel Bearing (Right Outboard) - Inspection / Grease |               | HRS |             | 251.5           |     |                  | 2794.6      |                    |         | 0            |
|                  |                                                                        |               | AFL |             | 95              |     |                  | 1022        |                    |         | 0            |
|                  |                                                                        |               | MOS |             | 8.4             |     |                  | 31 Aug 2025 |                    |         |              |
|                  |                                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 324225           | Main Wheel (Left Inboard) - Special Detailed Inspection (Ndt)          |               | HRS |             | 1038.6          |     |                  | 2007.5      |                    |         | 0            |
|                  |                                                                        |               | AFL |             | 409             |     |                  | 708         |                    |         | 0            |
|                  |                                                                        |               | MOS |             | 42.6            |     |                  | 23 Oct 2022 |                    |         |              |
|                  |                                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 052029           |                                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 324226           | Main Wheel (Left Outboard) - Special Detailed Inspection (Ndt)         |               | HRS |             | 1038.6          |     |                  | 2007.5      |                    |         | 0            |
|                  |                                                                        |               | AFL |             | 409             |     |                  | 708         |                    |         | 0            |
|                  |                                                                        |               | MOS |             | 42.6            |     |                  | 23 Oct 2022 |                    |         |              |
|                  |                                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 052029           |                                                                        |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                                |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|--------------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                                | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                                         | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                                     |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                                              |               |     |             |                 |     |                  |             |                    |         |              |
| 324227           | Main Wheel (Right Inboard) - Special Detailed Inspection (Ndt)                             |               | HRS |             | 1038.6          |     |                  | 2007.5      |                    |         | 0            |
|                  |                                                                                            |               | AFL |             | 409             |     |                  | 708         |                    |         | 0            |
|                  |                                                                                            |               | MOS |             | 42.6            |     |                  | 23 Oct 2022 |                    |         |              |
|                  |                                                                                            |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                            |               |     |             |                 |     |                  |             |                    |         |              |
| 052029           |                                                                                            |               |     |             |                 |     |                  |             |                    |         |              |
| 324228           | Main Wheel (Right Outboard) - Special Detailed Inspection (Ndt)                            |               | HRS |             | 759.6           |     |                  | 2286.5      |                    |         | 0            |
|                  |                                                                                            |               | AFL |             | 322             |     |                  | 795         |                    |         | 0            |
|                  |                                                                                            |               | MOS |             | 31.9            |     |                  | 13 Sep 2023 |                    |         |              |
|                  |                                                                                            |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                            |               |     |             |                 |     |                  |             |                    |         |              |
| 052029           |                                                                                            |               |     |             |                 |     |                  |             |                    |         |              |
| 324231           | Weight on Wheels Harness (Left Outboard) - Removal / Installation<br>C1E5901CA004ICO00396  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                            |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                            |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                            |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                            |               |     |             |                 |     |                  |             |                    |         |              |
| 324232           | Weight on Wheels Harness (Left Inboard) - Removal / Installation<br>C1E5902CA004ICO00399   |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                            |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                            |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                            |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                            |               |     |             |                 |     |                  |             |                    |         |              |
| 324233           | Weight on Wheels Harness (Right Inboard) - Removal / Installation<br>C1E5902CA004ICO00400  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                            |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                            |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                            |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                            |               |     |             |                 |     |                  |             |                    |         |              |
| 324234           | Weight on Wheels Harness (Right Outboard) - Removal / Installation<br>C1E5901CA004ICO00397 |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                            |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                            |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                            |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                            |               |     |             |                 |     |                  |             |                    |         |              |
| 324235           | Main Wheel (Left Outboard) - Restore<br>PN                                                 |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                 |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                 | Serial Number |                     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                          | SW            |                     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                      |               |                     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                               |               |                     |             |                 |     |                  |             |                    |         |              |
| 324236           | Main Wheel (Left Inboard) - Restore                         |               | HRS                 |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | PN                                                          | SN-UNKNOWN    | AFL                 |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                             |               | MOS                 |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                    |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  |                                                             |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 324237           | Main Wheel (Right Inboard) - Restore                        |               | HRS                 |             |                 |     |                  |             |                    |         | 0            |
|                  | PN                                                          | SN-UNKNOWN    | AFL                 |             |                 |     |                  |             |                    |         | 0            |
|                  |                                                             |               | DATE                |             |                 |     |                  |             |                    |         |              |
|                  | Airframe                                                    |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  |                                                             |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 324238           | Main Wheel (Right Outboard) - Restore                       |               | HRS                 |             |                 |     |                  |             |                    |         | 0            |
|                  | PN                                                          | SN-UNKNOWN    | AFL                 |             |                 |     |                  |             |                    |         | 0            |
|                  |                                                             |               | DATE                |             |                 |     |                  |             |                    |         |              |
|                  | Airframe                                                    |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  |                                                             |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 324300           | Brake Assembly (Left Inboard) - Removal / Installation      |               | HRS                 |             | 663.7           |     |                  | 2382.4      |                    |         | 0            |
|                  | 90005585-4                                                  | APR15-0716    | AFL                 |             | 291             |     |                  | 826         |                    |         | 0            |
|                  |                                                             |               | MOS                 |             | 25.1            |     |                  | 08 Apr 2024 |                    |         |              |
|                  | Airframe                                                    |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  |                                                             |               |                     |             |                 |     |                  |             |                    |         |              |
| 324301           | Brake Assembly (Left Outboard) - Removal / Installation     |               | HRS                 |             | 663.7           |     |                  | 2382.4      |                    |         | 0            |
|                  | 90005585-4                                                  | APR15-0710    | AFL                 |             | 291             |     |                  | 826         |                    |         | 0            |
|                  |                                                             |               | MOS                 |             | 25.1            |     |                  | 08 Apr 2024 |                    |         |              |
|                  | Airframe                                                    |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  |                                                             |               |                     |             |                 |     |                  |             |                    |         |              |
| 324302           | Brake Assembly (Right Inboard) - Removal / Installation     |               | HRS                 | TSN:2382.38 | 663.7           |     |                  | 2382.4      |                    |         | 0            |
|                  | 90005585-2                                                  | APR15-0715    | AFL                 | TSN:826     | 291             |     |                  | 826         |                    |         | 0            |
|                  |                                                             |               | MOS                 | TSN:104     | 25.1            |     |                  | 08 Apr 2024 |                    |         |              |
|                  | Airframe                                                    |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  |                                                             |               |                     |             |                 |     |                  |             |                    |         |              |
| 324303           | Brake Assembly (Right Outboard) - Removal / Installation    |               | HRS                 | TSN:2382.38 | 663.7           |     |                  | 2382.4      |                    |         | 0            |
|                  | 90005585-2                                                  | APR15-0714    | AFL                 | TSN:826     | 291             |     |                  | 826         |                    |         | 0            |
|                  |                                                             |               | MOS                 | TSN:104     | 25.1            |     |                  | 08 Apr 2024 |                    |         |              |
|                  | Airframe                                                    |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  |                                                             |               |                     |             |                 |     |                  |             |                    |         |              |
| 324304           | Brake Wear Indicators (Left Outboard) - Detailed Inspection |               | HRS                 |             | 137             |     | 600              | 2909.1      | 3509.1             | 3559.1  | 0            |
|                  |                                                             |               | AFL                 |             | 52              |     |                  | 1065        |                    |         | 0            |
|                  |                                                             |               | MOS                 |             | 5.3             |     |                  | 02 Dec 2025 |                    |         |              |
|                  | Airframe                                                    |               | [HRS: +50/-50]      |             |                 |     |                  |             |                    |         |              |
|                  |                                                             |               | 052001              |             |                 |     |                  |             |                    |         |              |



| ATA<br>U=Custom                | Description                                                  |               | UOM            | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|--------------------------------|--------------------------------------------------------------|---------------|----------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                | Part Number                                                  | Serial Number |                |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position               | HW                                                           | SW            |                |             |                 |     |                  |             |                    |         | Manufacturer |
|                                | MM Ref                                                       |               |                |             |                 |     |                  |             |                    |         | Date Type    |
|                                | Ops Number(s)                                                |               |                |             |                 |     |                  |             |                    |         |              |
| 324305                         | Brake Wear Indicators (Left Inboard) - Detailed Inspection   |               | HRS            |             | 137             |     | 600              | 2909.1      | 3509.1             | 3559.1  | 0            |
|                                |                                                              |               | AFL            |             | 52              |     |                  | 1065        |                    |         | 0            |
|                                |                                                              |               | MOS            |             | 5.3             |     |                  | 02 Dec 2025 |                    |         |              |
| Airframe                       |                                                              |               | [HRS: +50/-50] |             |                 |     |                  |             |                    |         |              |
| 052001                         |                                                              |               |                |             |                 |     |                  |             |                    |         |              |
| 324306                         | Brake Wear Indicators (Right Inboard) - Detailed Inspection  |               | HRS            |             | 137             |     | 600              | 2909.1      | 3509.1             | 3559.1  | 0            |
|                                |                                                              |               | AFL            |             | 52              |     |                  | 1065        |                    |         | 0            |
|                                |                                                              |               | MOS            |             | 5.3             |     |                  | 02 Dec 2025 |                    |         |              |
| Airframe                       |                                                              |               | [HRS: +50/-50] |             |                 |     |                  |             |                    |         |              |
| 052001                         |                                                              |               |                |             |                 |     |                  |             |                    |         |              |
| 324307                         | Brake Wear Indicators (Right Outboard) - Detailed Inspection |               | HRS            |             | 137             |     | 600              | 2909.1      | 3509.1             | 3559.1  | 0            |
|                                |                                                              |               | AFL            |             | 52              |     |                  | 1065        |                    |         | 0            |
|                                |                                                              |               | MOS            |             | 5.3             |     |                  | 02 Dec 2025 |                    |         |              |
| Airframe                       |                                                              |               | [HRS: +50/-50] |             |                 |     |                  |             |                    |         |              |
| 052001                         |                                                              |               |                |             |                 |     |                  |             |                    |         |              |
| 324308                         | Brake Assembly Torque Pin (Left) - Removal / Installation    |               | HRS            |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | C1M5420CA001                                                 | EXC0350       | AFL            |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                |                                                              |               | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                              |               | MSC            |             | O/C             |     |                  |             |                    |         |              |
| 324309                         | Brake Assembly Torque Pin (Right) - Removal / Installation   |               | HRS            |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                              |               | AFL            |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                | C1M5420CA001                                                 | EXC0351       | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                              |               | MSC            |             | O/C             |     |                  |             |                    |         |              |
| 324312                         | Main Landing Gear Brake Torque Takeout Pin (Left) - Discard  |               | HRS            |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                              |               | AFL            |             | 1117            |     | 20000            | 0           | 20000              |         | 0            |
|                                | C1M5420CA001                                                 | EXC0350       | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                              |               |                |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 324308 |                                                              |               |                |             |                 |     |                  |             |                    |         |              |
| 324313                         | Main Landing Gear Brake Torque Takeout Pin (Right) - Discard |               | HRS            |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                              |               | AFL            |             | 1117            |     | 20000            | 0           | 20000              |         | 0            |
|                                | C1M5420CA001                                                 | EXC0351       | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe                       |                                                              |               |                |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 324309 |                                                              |               |                |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                                                     |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-----------------------------------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                                                     | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                                                              | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                                                          |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                                                                   |               |     |             |                 |     |                  |             |                    |         |              |
| 324320           | Main Wheel Brakes (Left Inboard) - Operational Check                                                            |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                                 |               | AFL |             | 1117            |     |                  | 0           |                    | 0       |              |
|                  |                                                                                                                 |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                                                 |               |     |             |                 |     |                  |             |                    |         |              |
| 324321           | Main Wheel Brakes (Left Outboard) - Operational Check                                                           |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                                 |               | AFL |             | 1117            |     |                  | 0           |                    | 0       |              |
|                  |                                                                                                                 |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                                                 |               |     |             |                 |     |                  |             |                    |         |              |
| 324322           | Main Wheel Brakes (Right Inboard) - Operational Check                                                           |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                                 |               | AFL |             | 1117            |     |                  | 0           |                    | 0       |              |
|                  |                                                                                                                 |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                                                 |               |     |             |                 |     |                  |             |                    |         |              |
| 324323           | Main Wheel Brakes (Right Outboard) - Operational Check                                                          |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                                 |               | AFL |             | 1117            |     |                  | 0           |                    | 0       |              |
|                  |                                                                                                                 |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                                                 |               |     |             |                 |     |                  |             |                    |         |              |
| 324400           | Brake Shuttle Valve (Left Inboard) - Removal / Installation<br>60P3244030Z002                      MAR14-0590   |               | HRS | TSN:2315.6  | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  |                                                                                                                 |               | AFL | TSN:802     | 315             |     |                  | 802         |                    |         | 0            |
|                  |                                                                                                                 |               | MOS | TSN:100     | 28.8            |     |                  | 18 Dec 2023 |                    |         |              |
|                  |                                                                                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                                                 |               |     |             |                 |     |                  |             |                    |         |              |
| 324401           | Brake Shuttle Valve (Left Outboard) - Removal / Installation<br>60P3244030Z002                      SEP14-0678  |               | HRS | TSN:2315.6  | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  |                                                                                                                 |               | AFL | TSN:802     | 315             |     |                  | 802         |                    |         | 0            |
|                  |                                                                                                                 |               | MOS | TSN:100     | 28.8            |     |                  | 18 Dec 2023 |                    |         |              |
|                  |                                                                                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                                                 |               |     |             |                 |     |                  |             |                    |         |              |
| 324402           | Brake Shuttle Valve (Right Inboard) - Removal / Installation<br>60P3244030Z002                      SEP14-0689  |               | HRS | TSN:2315.6  | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  |                                                                                                                 |               | AFL | TSN:802     | 315             |     |                  | 802         |                    |         | 0            |
|                  |                                                                                                                 |               | MOS | TSN:100     | 28.8            |     |                  | 18 Dec 2023 |                    |         |              |
|                  |                                                                                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                                                 |               |     |             |                 |     |                  |             |                    |         |              |
| 324403           | Brake Shuttle Valve (Right Outboard) - Removal / Installation<br>60P3244030Z002                      DEC13-0531 |               | HRS | TSN:2315.6  | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  |                                                                                                                 |               | AFL | TSN:802     | 315             |     |                  | 802         |                    |         | 0            |
|                  |                                                                                                                 |               | MOS | TSN:100     | 28.8            |     |                  | 18 Dec 2023 |                    |         |              |
|                  |                                                                                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                                                 |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                    |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                                    | Serial Number |     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                             | SW            |     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                         |               |     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                                  |               |     |             |                 |     |                  |             |                     |         |              |
| 324404           | Brake Shut-Off Valve (Left Inboard) - Removal / Installation   |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 60P3244070Z002                                                 | MAR15-0288    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                |               |     |             |                 |     |                  |             |                     |         |              |
| 324405           | Brake Shut-Off Valve (Right Outboard) - Removal / Installation |               | HRS |             | 3045.4          |     |                  | 0.7         |                     |         | 0            |
|                  |                                                                |               | AFL |             | 1116            |     |                  | 1           |                     |         | 0            |
|                  | 60P3244070Z002                                                 | MAR15-0302    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                |               |     |             |                 |     |                  |             |                     |         |              |
| 324410           | Brake Control Valve (Left Inboard) - Removal / Installation    |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  | 60P3244110Z001                                                 | 15-03-0743    | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  |                                                                |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                |               |     |             |                 |     |                  |             |                     |         |              |
| 324411           | Brake Control Valve (Right Inboard) - Removal / Installation   |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 60P3244110Z001                                                 | 15-04-0770    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                |               |     |             |                 |     |                  |             |                     |         |              |
| 324412           | Brake Control Valve (Left Outboard) - Removal / Installation   |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 60P3244110Z001                                                 | 15-03-0739    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                |               |     |             |                 |     |                  |             |                     |         |              |
| 324413           | Brake Control Valve (Right Outboard) - Removal / Installation  |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 60P3244110Z001                                                 | 15-02-0703    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                |               |     |             |                 |     |                  |             |                     |         |              |
| 324420           | Brake Control Unit - Removal / Installation                    |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  | 60P3244090Z002                                                 | APR15-0198    | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | B                                                              |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                |               |     |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom  | Description                                          |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------|------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                  | Part Number                                          | Serial Number |     |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position | HW                                                   | SW            |     |             |                 |     |                  |             |                    |             | Manufacturer |
|                  | MM Ref                                               |               |     |             |                 |     |                  |             |                    |             | Date Type    |
|                  | Ops Number(s)                                        |               |     |             |                 |     |                  |             |                    |             |              |
| 324422           | Brake Pedal Position Transducer (Pilot Inboard) -    |               | HRS |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  | Removal / Installation                               |               | AFL |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  | 60P3244010Z004                                       | JAN15-0961    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                      |               | MSC |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                      |               |     |             |                 |     |                  |             |                    |             |              |
| 324423           | Brake Pedal Position Transducer (Copilot Inboard) -  |               | HRS |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  | Removal / Installation                               |               | AFL |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  | 60P3244010Z004                                       | JAN15-0990    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                      |               | MSC |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                      |               |     |             |                 |     |                  |             |                    |             |              |
| 324424           | Brake Pedal Position Transducer (Pilot Outboard) -   |               | HRS |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  | Removal / Installation                               |               | AFL |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  | 60P3244010Z004                                       | JAN15-0957    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                      |               | MSC |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                      |               |     |             |                 |     |                  |             |                    |             |              |
| 324425           | Brake Pedal Position Transducer (Copilot Outboard) - |               | HRS |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  | Removal / Installation                               |               | AFL |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  | 60P3244010Z004                                       | JAN15-0984    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                      |               | MSC |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                      |               |     |             |                 |     |                  |             |                    |             |              |
| 324431           | Brake Pedal Position Transducer - General Visual     |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  | Inspection                                           |               | AFL |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                      |               | MOS |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031        | 31 Jan 2032 |              |
|                  | [End Of Month Item] [MOS: +1m/-1m]                   |               |     |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                      |               |     |             |                 |     |                  |             |                    |             |              |
| 052016           |                                                      |               |     |             |                 |     |                  |             |                    |             |              |
| 324432           | Main Wheel Brakes - Functional Check                 |               | HRS |             | 663.7           |     |                  | 2382.4      |                    |             | 0            |
|                  |                                                      |               | AFL |             | 291             |     |                  | 826         |                    |             | 0            |
|                  |                                                      |               | MOS |             | 24.9            |     |                  | 15 Apr 2024 |                    |             |              |
|                  |                                                      |               | MSC |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                      |               |     |             |                 |     |                  |             |                    |             |              |
| 324433           | Antiskid - Operational Check                         |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                      |               | AFL |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                      |               | MOS |             | 28.7            |     |                  | 21 Dec 2023 |                    |             |              |
|                  |                                                      |               | MSC |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                      |               |     |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom  | Description                                                                                                                     |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|---------------------------------------------------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|----------|--------------------|---------|--------------|
|                  | Part Number                                                                                                                     | Serial Number |     |             |                 |     |                  |          |                    |         | Approx Price |
| Logbook Position | HW                                                                                                                              | SW            |     |             |                 |     |                  |          |                    |         | Manufacturer |
|                  | MM Ref                                                                                                                          |               |     |             |                 |     |                  |          |                    |         | Date Type    |
|                  | Ops Number(s)                                                                                                                   |               |     |             |                 |     |                  |          |                    |         |              |
| 324434           | Wheel Despin - Operational Check                                                                                                |               | HRS |             | 3046.1          |     |                  | 0        |                    |         | 0            |
|                  |                                                                                                                                 |               | AFL |             | 1117            |     | 0                |          | 0                  |         |              |
|                  |                                                                                                                                 |               | MOS |             | 128.6           |     | 24 Aug 2015      |          |                    |         |              |
|                  |                                                                                                                                 |               | MSC |             |                 | O/C |                  |          |                    |         |              |
| Airframe         |                                                                                                                                 |               |     |             |                 |     |                  |          |                    |         |              |
| 324435           | Autobrakes - Operational Check                                                                                                  |               | HRS |             | 3046.1          |     |                  | 0        |                    |         | 0            |
|                  |                                                                                                                                 |               | AFL |             | 1117            |     | 0                |          | 0                  |         |              |
|                  |                                                                                                                                 |               | MOS |             | 128.6           |     | 24 Aug 2015      |          |                    |         |              |
|                  |                                                                                                                                 |               | MSC |             |                 | O/C |                  |          |                    |         |              |
| Airframe         |                                                                                                                                 |               |     |             |                 |     |                  |          |                    |         |              |
| 324500           | Nose Static Interface Unit (Left) - Removal / Installation<br>60P3247090Z001                      MAR15-0487                    |               | HRS |             | 3041.4          |     |                  | 4.7      |                    |         | 0            |
|                  |                                                                                                                                 |               | AFL |             | 1114            |     | 3                |          | 0                  |         |              |
|                  |                                                                                                                                 |               | MOS |             | 128.6           |     | 24 Aug 2015      |          |                    |         |              |
|                  |                                                                                                                                 |               | MSC |             |                 | O/C |                  |          |                    |         |              |
| Airframe         |                                                                                                                                 |               |     |             |                 |     |                  |          |                    |         |              |
| 324501           | Nose Static Interface Unit (Right) - Removal / Installation<br>60P3247090Z001                      MAR15-0488                   |               | HRS |             | 3041.4          |     |                  | 4.7      |                    |         | 0            |
|                  |                                                                                                                                 |               | AFL |             | 1114            |     | 3                |          | 0                  |         |              |
|                  |                                                                                                                                 |               | MOS |             | 128.6           |     | 24 Aug 2015      |          |                    |         |              |
|                  |                                                                                                                                 |               | MSC |             |                 | O/C |                  |          |                    |         |              |
| Airframe         |                                                                                                                                 |               |     |             |                 |     |                  |          |                    |         |              |
| 324504           | Combined Wheel Static Interface Unit (Left Inboard) - Removal / Installation<br>60P3247070Z003                      OCT14-0683  |               | HRS | TSN:2315.58 | 730.5           |     |                  | 2315.6   |                    |         | 0            |
|                  |                                                                                                                                 |               | AFL |             |                 |     |                  |          | 0                  |         |              |
|                  |                                                                                                                                 |               | MOS | TSN:100     | 29.2            |     | 04 Dec 2023      |          |                    |         |              |
|                  |                                                                                                                                 |               | MSC |             |                 | O/C |                  |          |                    |         |              |
| Airframe         |                                                                                                                                 |               |     |             |                 |     |                  |          |                    |         |              |
| 324505           | Combined Wheel Static Interface Unit (Left Outboard) - Removal / Installation<br>60P3247070Z003                      NOV14-0699 |               | HRS | TSN:2315.58 | 730.5           |     |                  | 2315.6   |                    |         | 0            |
|                  |                                                                                                                                 |               | AFL |             |                 |     |                  |          | 0                  |         |              |
|                  |                                                                                                                                 |               | MOS | TSN:100     | 29.2            |     | 04 Dec 2023      |          |                    |         |              |
|                  |                                                                                                                                 |               | MSC |             |                 | O/C |                  |          |                    |         |              |
| Airframe         |                                                                                                                                 |               |     |             |                 |     |                  |          |                    |         |              |
| 324506           | Combined Wheel Static Interface Unit (Right Inboard) - Removal / Installation<br>60P3247070Z003                      FEB15-0755 |               | HRS | TSN:2315.58 | 730.5           |     |                  | 2315.6   |                    |         | 0            |
|                  |                                                                                                                                 |               | AFL | TSN:802     | 315             |     | 802              |          | 0                  |         |              |
|                  |                                                                                                                                 |               | MOS | TSN:100     | 28.8            |     | 18 Dec 2023      |          |                    |         |              |
|                  |                                                                                                                                 |               | MSC |             |                 | O/C |                  |          |                    |         |              |
| Airframe         |                                                                                                                                 |               |     |             |                 |     |                  |          |                    |         |              |

| ATA<br>U=Custom  | Description                                                                    |               | UOM            | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------|--------------------------------------------------------------------------------|---------------|----------------|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                  | Part Number                                                                    | Serial Number |                |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position | HW                                                                             | SW            |                |             |                 |     |                  |             |                    |             | Manufacturer |
|                  | MM Ref                                                                         |               |                |             |                 |     |                  |             |                    |             | Date Type    |
|                  | Ops Number(s)                                                                  |               |                |             |                 |     |                  |             |                    |             |              |
| 324507           | Combined Wheel Static Interface Unit (Right Outboard) - Removal / Installation |               | HRS            | TSN:2315.58 | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                                |               | AFL            | TSN:802     | 315             |     |                  | 802         |                    |             | 0            |
|                  | 60P3247070Z003                                                                 | NOV14-0698    | MOS            | TSN:100     | 28.8            |     |                  | 18 Dec 2023 |                    |             |              |
|                  |                                                                                |               | MSC            |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                |               |                |             |                 |     |                  |             |                    |             |              |
| 324600           | Brake System Hydraulic Fuse (Left Inboard) - Removal / Installation            |               | HRS            | TSN:2315.6  | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                                |               | AFL            | TSN:802     | 315             |     |                  | 802         |                    |             | 0            |
|                  | 60P3244130Z001                                                                 | JAN15-0791    | MOS            | TSN:100     | 28.8            |     |                  | 18 Dec 2023 |                    |             |              |
|                  |                                                                                |               | MSC            |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                |               |                |             |                 |     |                  |             |                    |             |              |
| 324601           | Brake System Hydraulic Fuse (Left Outboard) - Removal / Installation           |               | HRS            | TSN:2315.6  | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                                |               | AFL            | TSN:802     | 315             |     |                  | 802         |                    |             | 0            |
|                  | 60P3244130Z001                                                                 | OCT14-0709    | MOS            | TSN:100     | 28.8            |     |                  | 18 Dec 2023 |                    |             |              |
|                  |                                                                                |               | MSC            |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                |               |                |             |                 |     |                  |             |                    |             |              |
| 324602           | Brake System Hydraulic Fuse (Right Inboard) - Removal / Installation           |               | HRS            | TSN:2315.6  | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                                |               | AFL            | TSN:802     | 315             |     |                  | 802         |                    |             | 0            |
|                  | 60P3244130Z001                                                                 | JAN15-0766    | MOS            | TSN:100     | 28.8            |     |                  | 18 Dec 2023 |                    |             |              |
|                  |                                                                                |               | MSC            |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                |               |                |             |                 |     |                  |             |                    |             |              |
| 324603           | Brake System Hydraulic Fuse (Right Outboard) - Removal / Installation          |               | HRS            | TSN:2315.6  | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                                |               | AFL            | TSN:802     | 315             |     |                  | 802         |                    |             | 0            |
|                  | 60P3244130Z001                                                                 | JAN15-0783    | MOS            | TSN:100     | 28.8            |     |                  | 18 Dec 2023 |                    |             |              |
|                  |                                                                                |               | MSC            |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                |               |                |             |                 |     |                  |             |                    |             |              |
| 324607           | Brake Control System Hydraulic Fuse (Left, Outboard No. 1) - Operational Check |               | HRS            |             | 663.7           |     |                  | 2382.4      |                    |             | 0            |
|                  |                                                                                |               | AFL            |             | 291             |     |                  | 826         |                    |             | 0            |
|                  |                                                                                |               | MOS            |             | 24.9            |     | 125              | 15 Apr 2024 | 15 Sep 2034        | 15 Oct 2034 |              |
|                  |                                                                                |               | [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                |               |                |             |                 |     |                  |             |                    |             |              |
| 324608           | Brake System Hydraulic Fuse - Functional Check                                 |               | HRS            |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                |               | AFL            |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                |               | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                |               | MSC            |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                |               |                |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom  | Description                                                                     |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due     | Avg Man Hrs  |
|------------------|---------------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|---------------------|-------------|--------------|
|                  | Part Number                                                                     | Serial Number |                                    |             |                 |     |                  |             |                     |             | Approx Price |
| Logbook Position | HW                                                                              | SW            |                                    |             |                 |     |                  |             |                     |             | Manufacturer |
|                  | MM Ref                                                                          |               |                                    |             |                 |     |                  |             |                     |             | Date Type    |
|                  | Ops Number(s)                                                                   |               |                                    |             |                 |     |                  |             |                     |             |              |
| 324609           | Parking Brake Accumulator Pressure Indicator - Removal                          |               | HRS                                |             | 3046.1          |     |                  | 0           |                     |             | 0            |
|                  | / Installation                                                                  |               | AFL                                |             | 1117            |     |                  | 0           |                     |             | 0            |
|                  | 60P2512201Z005                                                                  | 139           | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                     |             |              |
|                  |                                                                                 |               | MSC                                |             |                 |     | O/C              |             |                     |             |              |
| Airframe         |                                                                                 |               |                                    |             |                 |     |                  |             |                     |             |              |
| 324610           | Brake Control System Hydraulic Fuse (Left, Inboard No. 2) - Operational Check   |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                     |             | 0            |
|                  |                                                                                 |               | AFL                                |             | 315             |     |                  | 802         |                     |             | 0            |
|                  |                                                                                 |               | MOS                                |             | 28.7            |     | 125              | 21 Dec 2023 | 31 May 2034         | 30 Jun 2034 |              |
|                  |                                                                                 |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                     |             |              |
| Airframe         |                                                                                 |               |                                    |             |                 |     |                  |             |                     |             |              |
| 324611           | Brake Control System Hydraulic Fuse (Right, Inboard No. 3) - Operational Check  |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                     |             | 0            |
|                  |                                                                                 |               | AFL                                |             | 315             |     |                  | 802         |                     |             | 0            |
|                  |                                                                                 |               | MOS                                |             | 28.7            |     | 125              | 21 Dec 2023 | 31 May 2034         | 30 Jun 2034 |              |
|                  |                                                                                 |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                     |             |              |
| Airframe         |                                                                                 |               |                                    |             |                 |     |                  |             |                     |             |              |
| 324612           | Brake Control System Hydraulic Fuse (Right, Outboard No. 4) - Operational Check |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                     |             | 0            |
|                  |                                                                                 |               | AFL                                |             | 315             |     |                  | 802         |                     |             | 0            |
|                  |                                                                                 |               | MOS                                |             | 28.7            |     | 125              | 21 Dec 2023 | 31 May 2034         | 30 Jun 2034 |              |
|                  |                                                                                 |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                     |             |              |
| Airframe         |                                                                                 |               |                                    |             |                 |     |                  |             |                     |             |              |
| 324700           | Tire Pressure Monitor Unit - Removal / Installation                             |               | HRS                                |             | 2673.8          |     |                  | 372.3       |                     |             | 0            |
|                  | 60P32470102005                                                                  |               | AFL                                |             | 1020            |     |                  | 97          |                     |             | 0            |
|                  | 0421                                                                            |               | MOS                                |             | 109.7           |     |                  | 21 Mar 2017 |                     |             |              |
|                  |                                                                                 |               | MSC                                |             |                 |     | O/C              |             |                     |             |              |
| Airframe         |                                                                                 |               |                                    |             |                 |     |                  |             |                     |             |              |
| 324701           | Tire Pressure Monitor System - Functional Check                                 |               | HRS                                |             | 137             |     |                  | 2909.1      |                     |             | 0            |
|                  |                                                                                 |               | AFL                                |             | 52              |     |                  | 1065        |                     |             | 0            |
|                  |                                                                                 |               | MOS                                |             | 4.9             | 28  | 24               | 15 Dec 2025 | 31 Jan 2028*        | 29 Feb 2028 |              |
|                  |                                                                                 |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                     |             |              |
| Airframe         |                                                                                 |               |                                    |             |                 |     |                  |             |                     |             |              |
| 052011           |                                                                                 |               |                                    |             |                 |     |                  |             |                     |             |              |
| 324703           | Brake System Temperature Indication - Operational Check                         |               | HRS                                |             | 137             |     |                  | 2909.1      |                     |             | 0            |
|                  |                                                                                 |               | AFL                                |             | 52              |     |                  | 1065        |                     |             | 0            |
|                  |                                                                                 |               | MOS                                |             | 4.8             |     |                  | 18 Dec 2025 |                     |             |              |
|                  |                                                                                 |               | MSC                                |             |                 |     | O/C              |             |                     |             |              |
| Airframe         |                                                                                 |               |                                    |             |                 |     |                  |             |                     |             |              |

| ATA<br>U=Custom  | Description                                                                      |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                      | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                               | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                           |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                                    |               |     |             |                 |     |                  |             |                    |         |              |
| 324704           | Inboard Brake Pressure Transducer (Left) - Removal / Installation                |               | HRS | TSN:2315.6  | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  |                                                                                  |               | AFL | TSN:802     | 315             |     |                  | 802         |                    |         | 0            |
|                  | 60P3244150Z002                                                                   | FEB15-0754    | MOS | TSN:100     | 28.8            |     |                  | 18 Dec 2023 |                    |         |              |
|                  |                                                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                  |               |     |             |                 |     |                  |             |                    |         |              |
| 324705           | Inboard Brake Pressure Transducer (Right) - Removal / Installation               |               | HRS | TSN:2315.6  | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  |                                                                                  |               | AFL | TSN:802     | 315             |     |                  | 802         |                    |         | 0            |
|                  | 60P3244150Z002                                                                   | FEB15-0748    | MOS | TSN:100     | 28.8            |     |                  | 18 Dec 2023 |                    |         |              |
|                  |                                                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                  |               |     |             |                 |     |                  |             |                    |         |              |
| 324706           | Outboard Brake Pressure Transducer (Left) - Removal / Installation               |               | HRS | TSN:2315.6  | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  |                                                                                  |               | AFL | TSN:802     | 315             |     |                  | 802         |                    |         | 0            |
|                  | 60P3244150Z002                                                                   | FEB15-0744    | MOS | TSN:100     | 28.8            |     |                  | 18 Dec 2023 |                    |         |              |
|                  |                                                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                  |               |     |             |                 |     |                  |             |                    |         |              |
| 324707           | Outboard Brake Pressure Transducer (Right) - Removal / Installation              |               | HRS | TSN:2315.6  | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  |                                                                                  |               | AFL | TSN:802     | 315             |     |                  | 802         |                    |         | 0            |
|                  | 60P3244150Z002                                                                   | FEB 15-0762   | MOS | TSN:100     | 28.8            |     |                  | 18 Dec 2023 |                    |         |              |
|                  |                                                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                  |               |     |             |                 |     |                  |             |                    |         |              |
| 324712           | Parking Brake Pressure Transducer (Inboard) - Removal / Installation             |               | HRS | TSN:2315.6  | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  |                                                                                  |               | AFL | TSN:802     | 315             |     |                  | 802         |                    |         | 0            |
|                  | 60P2930061Z001                                                                   | 62099         | MOS | TSN:100     | 28.8            |     |                  | 18 Dec 2023 |                    |         |              |
|                  |                                                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                  |               |     |             |                 |     |                  |             |                    |         |              |
| 324713           | Parking Brake Pressure Transducer (Outboard) - Removal / Installation            |               | HRS | TSN:2315.6  | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  |                                                                                  |               | AFL | TSN:802     | 315             |     |                  | 802         |                    |         | 0            |
|                  | 60P2930061Z001                                                                   | 62041         | MOS | TSN:100     | 28.8            |     |                  | 18 Dec 2023 |                    |         |              |
|                  |                                                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                  |               |     |             |                 |     |                  |             |                    |         |              |
| 324716           | Parking Brake Accumulator Pressure Transducer (Inboard) - Removal / Installation |               | HRS | TSN:2315.6  | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  |                                                                                  |               | AFL | TSN:802     | 315             |     |                  | 802         |                    |         | 0            |
|                  | 60P2930061Z001                                                                   | 60638         | MOS | TSN:100     | 28.8            |     |                  | 18 Dec 2023 |                    |         |              |
|                  |                                                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                  |               |     |             |                 |     |                  |             |                    |         |              |



| ATA<br>U=Custom  | Description                                           |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                           | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                    | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                         |               |     |             |                 |     |                  |             |                    |         |              |
| 324717           | Parking Brake Accumulator Pressure Transducer         |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | (Outboard) - Removal / Installation                   |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P2930061Z001                                        | 61382         | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                       |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| 324800           | Parking Brake Accumulator Thermal Relief / Dump Valve |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | (Outboard) - Removal / Installation                   |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P3244050Z001                                        | 0364          | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                       |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| 324801           | Parking Brake Accumulator Thermal Relief / Dump Valve |               | HRS | TSN:2315.6  | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  | (Inboard) - Removal / Installation                    |               | AFL | TSN:802     | 315             |     |                  | 802         |                    |         | 0            |
|                  | 60P3244050Z001                                        | 0362          | MOS | TSN:100     | 28.8            |     |                  | 18 Dec 2023 |                    |         |              |
|                  |                                                       |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| 324807           | Parking Brake Handle / Cable Assembly - Rigging /     |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | Adjustment                                            |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                       |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                       |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| 324808           | Parking Brake Control Handle Assembly - Removal /     |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | Installation                                          |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P3248023Z003                                        | 275           | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                       |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| 324810           | Hydraulic Repeater Valve - Removal / Installation     |               | HRS | TSN:2315.6  | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  | 60P3248030Z003                                        | NOV14-0188    | AFL | TSN:802     | 315             |     |                  | 802         |                    |         | 0            |
|                  |                                                       |               | MOS | TSN:100     | 28.8            |     |                  | 18 Dec 2023 |                    |         |              |
|                  |                                                       |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| 324814           | Parking Brake Cable Assembly - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P3248022Z003                                        | 118           | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                       |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                       |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                       |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                              |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|--------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                                              | Serial Number |     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                                       | SW            |     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                                   |               |     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                                            |               |     |             |                 |     |                  |             |                     |         |              |
| 324815           | Parking Brake Control Valve - Removal / Installation                     |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  | 60P3248010Z003                                                           | MAR15-0200    | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  |                                                                          |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  | Airframe                                                                 |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| 324816           | Parking Brake Accumulator (Outboard) - Removal / Installation            |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                          |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 90008132                                                                 | FEB15-0389    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  | Airframe                                                                 |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| 324817           | Parking Brake Accumulator (Inboard) - Removal / Installation             |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                          |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 90008132                                                                 | APR15-0413    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  | Airframe                                                                 |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| 324820           | Parking Brake Accumulator Filler Gage (Inboard)- Removal / Installation  |               | HRS |             | 730.5           |     |                  | 2315.6      |                     |         | 0            |
|                  |                                                                          |               | AFL |             | 315             |     |                  | 802         |                     |         | 0            |
|                  | GP20-36                                                                  | 15-12918      | MOS |             | 29              |     |                  | 12 Dec 2023 |                     |         |              |
|                  | Airframe                                                                 |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| 324821           | Parking Brake Accumulator Filler Gage (Outboard)- Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                          |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | GP20-36                                                                  | 15-0316291    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  | Airframe                                                                 |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| 324824           | Parking Brake - Operational Test                                         |               | HRS |             | 663.7           |     |                  | 2382.4      |                     |         | 0            |
|                  |                                                                          |               | AFL |             | 291             |     |                  | 826         |                     |         | 0            |
|                  |                                                                          |               | MOS |             | 24.9            |     |                  | 15 Apr 2024 |                     |         |              |
|                  | Airframe                                                                 |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| 324825           | Accumulator Pressure Transducer (Left) - Removal / Installation          |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                          |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 60P2930061Z001                                                           | SN-UNKNOWN    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  | Airframe                                                                 |               | MSC |             |                 |     | O/C              |             |                     |         |              |

| ATA<br>U=Custom  | Description                                              |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                              | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                       | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                   |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                            |               |     |             |                 |     |                  |             |                    |         |              |
| 324900           | Brake System Temperature Sensor (Left Inboard) -         |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | Removal / Installation                                   |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 6007300                                                  | DEC14-8481    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                          |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| 324901           | Brake System Temperature Sensor (Left Outboard) -        |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | Removal / Installation                                   |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 6007300                                                  | DEC14-8494    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                          |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| 324902           | Brake System Temperature Sensor (Right Inboard) -        |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | Removal / Installation                                   |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 6007300                                                  | DEC14-8498    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                          |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| 324903           | Brake System Temperature Sensor (Right Outboard) -       |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | Removal / Installation                                   |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 6007300                                                  | DEC14-8496    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                          |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| 324908           | Nose Rotating Sensing Assembly (Left) - Removal /        |               | HRS |             | 3041.4          |     |                  | 4.7         |                    |         | 0            |
|                  | Installation                                             |               | AFL |             | 1114            |     |                  | 3           |                    |         | 0            |
|                  | 60P3247050Z002                                           | FEB15-0676    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                          |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| 324909           | Nose Rotating Sensing Assembly (Right) - Removal /       |               | HRS |             | 1784.3          |     |                  | 1261.8      |                    |         | 0            |
|                  | Installation                                             |               | AFL |             | 751             |     |                  | 366         |                    |         | 0            |
|                  | 60P3247050Z002                                           | JUN11-0175    | MOS |             | 77.1            |     |                  | 08 Dec 2019 |                    |         |              |
|                  |                                                          |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| 324912           | Main Rotating Pressure Sensing Assembly (Left Inboard) - |               | HRS |             | 759.6           |     |                  | 2286.5      |                    |         | 0            |
|                  | Removal / Installation                                   |               | AFL |             | 322             |     |                  | 795         |                    |         | 0            |
|                  | 60P3247030Z005                                           | JUL23-3778    | MOS | TSN:2       | 31.9            |     |                  | 13 Sep 2023 |                    |         |              |
|                  |                                                          |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                          |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                               |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-----------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                               | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                        | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                    |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 324913           | Main Rotating Pressure Sensing Assembly (Left             |               | HRS |             | 663.7           |     |                  | 2382.4      |                    |         | 0            |
|                  | Outboard) - Removal / Installation                        |               | AFL |             | 291             |     |                  | 826         |                    |         | 0            |
|                  | 60P3247030Z005                                            | JUN14-0766    | MOS |             | 25              |     |                  | 12 Apr 2024 |                    |         |              |
|                  |                                                           |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| 324914           | Main Rotating Pressure Sensing Assembly (Right            |               | HRS |             | 1784.3          |     |                  | 1261.8      |                    |         | 0            |
|                  | Inboard) - Removal / Installation                         |               | AFL |             | 751             |     |                  | 366         |                    |         | 0            |
|                  | 60P3247030Z004                                            | JAN15-0901    | MOS |             | 77.1            |     |                  | 08 Dec 2019 |                    |         |              |
|                  |                                                           |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| 324915           | Main Rotating Pressure Sensing Assembly (Right            |               | HRS |             | 994.2           |     |                  | 2051.9      |                    |         | 0            |
|                  | Outboard) - Removal / Installation                        |               | AFL |             | 392             |     |                  | 725         |                    |         | 0            |
|                  | 60P3247030Z004                                            | APR14-0732    | MOS |             | 41.1            |     |                  | 08 Dec 2022 |                    |         |              |
|                  |                                                           |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| 325000           | Nose Wheel Steering - Functional Test                     |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  |                                                           |               | AFL |             | 315             |     |                  | 802         |                    |         | 0            |
|                  |                                                           |               | MOS |             | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
|                  |                                                           |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| 325001           | Nose Wheel Steering - Autorig Test                        |               | HRS |             | 2120.8          |     |                  | 925.3       |                    |         | 0            |
|                  |                                                           |               | AFL |             | 861             |     |                  | 256         |                    |         | 0            |
|                  |                                                           |               | MOS |             | 86.1            |     |                  | 09 Mar 2019 |                    |         |              |
|                  |                                                           |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| 325100           | Nose Wheel Steering Control Unit - Removal / Installation |               | HRS |             | 3013.1          |     |                  | 33          |                    |         | 0            |
|                  | 60P3252010Z006                                            | 0246          | AFL |             | 1105            |     |                  | 12          |                    |         | 0            |
|                  |                                                           |               | MOS |             | 122             |     |                  | 10 Mar 2016 |                    |         |              |
|                  |                                                           |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| 325200           | Nose Wheel Steering Actuator - Removal / Installation     |               | HRS |             | 2120.8          |     |                  | 925.3       |                    |         | 0            |
|                  | 72434-6                                                   | 0617          | AFL |             | 861             |     |                  | 256         |                    |         | 0            |
|                  |                                                           |               | MOS | TSN:1       | 86              |     |                  | 11 Mar 2019 |                    |         |              |
|                  |                                                           |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                           |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom                | Description                                                     |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|--------------------------------|-----------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                                | Part Number                                                     | Serial Number |     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position               | HW                                                              | SW            |     |             |                 |     |                  |             |                     |         | Manufacturer |
|                                | MM Ref                                                          |               |     |             |                 |     |                  |             |                     |         | Date Type    |
|                                | Ops Number(s)                                                   |               |     |             |                 |     |                  |             |                     |         |              |
| 325202                         | Nose Wheel Steering Equipment Assembly - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                                |                                                                 |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                                | 72434-5                                                         | SN-UNKNOWN    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                                |                                                                 |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe                       |                                                                 |               |     |             |                 |     |                  |             |                     |         |              |
| 325203                         | Nose Wheel Steering Collar Nut - Discard                        |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                                | MS14144L6                                                       | SN-UNKNOWN    | AFL |             | 1117            |     | 12000            | 0           | 12000               |         | 0            |
|                                |                                                                 |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                                |                                                                 |               |     |             |                 |     |                  |             |                     |         |              |
| Airframe                       |                                                                 |               |     |             |                 |     |                  |             |                     |         |              |
| 325204                         | Nose Wheel Steering Collar Bolt - Discard                       |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                                | NAS6706DU12                                                     | SN-UNKNOWN    | AFL |             | 1117            |     | 12000            | 0           | 12000               |         | 0            |
|                                |                                                                 |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                                |                                                                 |               |     |             |                 |     |                  |             |                     |         |              |
| Airframe                       |                                                                 |               |     |             |                 |     |                  |             |                     |         |              |
| 325205                         | Steering Equipment Assembly - Removal / Installation            |               | HRS |             | 3041.4          |     |                  | 4.7         |                     |         | 0            |
|                                | C2E4800CA006                                                    | 0203          | AFL |             | 1114            |     |                  | 3           |                     |         | 0            |
|                                |                                                                 |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                                |                                                                 |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe                       |                                                                 |               |     |             |                 |     |                  |             |                     |         |              |
| 325208                         | Nose Wheel Steering Equipment Assembly - Discard                |               | HRS |             | 2120.8          |     |                  | 925.3       |                     |         | 0            |
|                                | C2E4800CA006                                                    | SN-UNKNOWN    | AFL |             | 861             |     |                  | 256         | 20256               |         | 0            |
|                                |                                                                 |               | MOS |             | 86              |     |                  | 11 Mar 2019 |                     |         |              |
|                                |                                                                 |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe                       |                                                                 |               |     |             |                 |     |                  |             |                     |         |              |
| Notes: MRI PARENT CODE: 325205 |                                                                 |               |     |             |                 |     |                  |             |                     |         |              |
| 325210                         | Oversteer Proximity Sensor - Operational Check                  |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                                |                                                                 |               | AFL |             | 1117            |     | 10000            | 0           | 10000               |         | 0            |
|                                |                                                                 |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                                |                                                                 |               |     |             |                 |     |                  |             |                     |         |              |
| Airframe                       |                                                                 |               |     |             |                 |     |                  |             |                     |         |              |
| 052028                         |                                                                 |               |     |             |                 |     |                  |             |                     |         |              |
| 325212                         | Nose Wheel Steering Actuator - Discard                          |               | HRS |             | 2120.8          |     |                  | 925.3       |                     |         | 0            |
|                                | 72434-6                                                         | 0617          | AFL |             | 861             |     | 2500             | 256         | 2756                |         | 0            |
|                                |                                                                 |               | MOS | TSN:1       | 86              |     |                  | 11 Mar 2019 |                     |         |              |
|                                |                                                                 |               |     |             |                 |     |                  |             |                     |         |              |
| Airframe                       |                                                                 |               |     |             |                 |     |                  |             |                     |         |              |
| 325213                         | Nose Wheel Steering Collar Assembly - Discard                   |               | HRS | TSN:554     | 2120.8          |     |                  | 925.3       |                     |         | 0            |
|                                | C2E4810CA006                                                    | 237           | AFL | TSN:159     | 861             |     | 20000            | 256         | 20097               |         | 0            |
|                                |                                                                 |               | MOS |             | 86              |     |                  | 11 Mar 2019 |                     |         |              |
|                                |                                                                 |               |     |             |                 |     |                  |             |                     |         |              |
| Airframe                       |                                                                 |               |     |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom  | Description                                                          |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                          | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                   | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                               |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 325401           | Steering Unit Motor - Removal / Installation                         |               | HRS |             | 2120.8          |     |                  | 925.3       |                    |         | 0            |
|                  | 72434-6                                                              | 0617          | AFL |             | 861             |     |                  | 256         |                    |         | 0            |
|                  |                                                                      |               | MOS | TSN:1       | 86              |     |                  | 11 Mar 2019 |                    |         |              |
|                  | Airframe                                                             |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 326100           | Landing Gear Selector Panel - Removal / Installation                 |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | A486-19                                                              | 1485          | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                      |               | MOS | TSN:8       | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                             |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 326106           | Nose Landing Gear Door Sensor - Adjustment                           |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                      |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                      |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                             |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 326107           | Main Landing Gear Door Sensor - Adjustment                           |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                      |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                      |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                             |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 326120           | Nose Landing Gear Door Sensor (Left Open) - Removal / Installation   |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                      |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P3261030Z001                                                       | 009201        | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                             |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 326121           | Nose Landing Gear Door Sensor (Left Closed) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                      |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P3261030Z001                                                       | 009199        | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                             |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 326122           | Nose Landing Gear Door Sensor (Right Open) - Removal / Installation  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                      |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P3261030Z001                                                       | 009741        | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                             |               | MSC |             |                 |     | O/C              |             |                    |         |              |

| ATA<br>U=Custom  | Description                                           |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                           | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                    | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                         |               |     |             |                 |     |                  |             |                    |         |              |
| 326123           | Nose Landing Gear Door Sensor (Right Closed) -        |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | Removal / Installation                                |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P3261030Z001                                        | 009736        | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                       |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| 326124           | Main Landing Gear Door Sensor (Left Open Forward) -   |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | Removal / Installation                                |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P3261030Z001                                        | 009922        | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                       |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| 326125           | Main Landing Gear Door Sensor (Left Open Aft) -       |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | Removal / Installation                                |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P3261030Z001                                        | 009848        | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                       |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| 326126           | Main Landing Gear Door Sensor (Left Closed Forward) - |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | Removal / Installation                                |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P3261030Z001                                        | 009458        | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                       |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| 326127           | Main Landing Gear Door Sensor (Left Closed Aft) -     |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | Removal / Installation                                |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P3261030Z001                                        | 009808        | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                       |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| 326128           | Main Landing Gear Door Sensor (Right Open Forward) -  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | Removal / Installation                                |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P3261030Z001                                        | 009825        | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                       |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| 326129           | Main Landing Gear Door Sensor (Right Open Aft) -      |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | Removal / Installation                                |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P3261030Z001                                        | 009811        | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                       |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                       |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                   |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(* = Adj) | Max Due | Avg Man Hrs  |
|------------------|-------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|-----------------------|---------|--------------|
|                  | Part Number                                                                   | Serial Number |     |             |                 |     |                  |             |                       |         | Approx Price |
| Logbook Position | HW                                                                            | SW            |     |             |                 |     |                  |             |                       |         | Manufacturer |
|                  | MM Ref                                                                        |               |     |             |                 |     |                  |             |                       |         | Date Type    |
|                  | Ops Number(s)                                                                 |               |     |             |                 |     |                  |             |                       |         |              |
| 326130           | Main Landing Gear Door Sensor (Right Closed Forward) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                       |         | 0            |
|                  |                                                                               |               | AFL |             | 1117            |     |                  | 0           |                       |         | 0            |
|                  | 60P3261030Z001                                                                | 009812        | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                       |         |              |
|                  |                                                                               |               | MSC |             |                 |     | O/C              |             |                       |         |              |
| Airframe         |                                                                               |               |     |             |                 |     |                  |             |                       |         |              |
| 326131           | Main Landing Gear Door Sensor (Right Closed Aft) - Removal / Installation     |               | HRS |             | 3046.1          |     |                  | 0           |                       |         | 0            |
|                  |                                                                               |               | AFL |             | 1117            |     |                  | 0           |                       |         | 0            |
|                  | 60P3261030Z001                                                                | 009813        | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                       |         |              |
|                  |                                                                               |               | MSC |             |                 |     | O/C              |             |                       |         |              |
| Airframe         |                                                                               |               |     |             |                 |     |                  |             |                       |         |              |
| 326132           | Nose Landing Gear Uplock Sensor - Adjustment                                  |               | HRS |             | 3046.1          |     |                  | 0           |                       |         | 0            |
|                  |                                                                               |               | AFL |             | 1117            |     |                  | 0           |                       |         | 0            |
|                  |                                                                               |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                       |         |              |
|                  |                                                                               |               | MSC |             |                 |     | O/C              |             |                       |         |              |
| Airframe         |                                                                               |               |     |             |                 |     |                  |             |                       |         |              |
| 326133           | Nose Landing Gear Downlock Sensor - Adjustment                                |               | HRS |             | 3046.1          |     |                  | 0           |                       |         | 0            |
|                  |                                                                               |               | AFL |             | 1117            |     |                  | 0           |                       |         | 0            |
|                  |                                                                               |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                       |         |              |
|                  |                                                                               |               | MSC |             |                 |     | O/C              |             |                       |         |              |
| Airframe         |                                                                               |               |     |             |                 |     |                  |             |                       |         |              |
| 326134           | Main Landing Gear Uplock Sensor - Adjustment                                  |               | HRS |             | 3046.1          |     |                  | 0           |                       |         | 0            |
|                  |                                                                               |               | AFL |             | 1117            |     |                  | 0           |                       |         | 0            |
|                  |                                                                               |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                       |         |              |
|                  |                                                                               |               | MSC |             |                 |     | O/C              |             |                       |         |              |
| Airframe         |                                                                               |               |     |             |                 |     |                  |             |                       |         |              |
| 326135           | Main Landing Gear Downlock Sensor - Adjustment                                |               | HRS |             | 3046.1          |     |                  | 0           |                       |         | 0            |
|                  |                                                                               |               | AFL |             | 1117            |     |                  | 0           |                       |         | 0            |
|                  |                                                                               |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                       |         |              |
|                  |                                                                               |               | MSC |             |                 |     | O/C              |             |                       |         |              |
| Airframe         |                                                                               |               |     |             |                 |     |                  |             |                       |         |              |
| 326136           | Nose Landing Gear Uplock Sensor (Left) - Removal / Installation               |               | HRS |             | 3046.1          |     |                  | 0           |                       |         | 0            |
|                  |                                                                               |               | AFL |             | 1117            |     |                  | 0           |                       |         | 0            |
|                  | 60P3261030Z001                                                                | 007704        | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                       |         |              |
|                  |                                                                               |               | MSC |             |                 |     | O/C              |             |                       |         |              |
| Airframe         |                                                                               |               |     |             |                 |     |                  |             |                       |         |              |



| ATA<br>U=Custom  | Description                                                              |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|--------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                              | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                       | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                   |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                            |               |     |             |                 |     |                  |             |                    |         |              |
| 326137           | Nose Landing Gear Uplock Sensor (Right) - Removal / Installation         |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                          |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P3261030Z001                                                           | 007584        | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                          |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| 326140           | Nose Landing Gear Downlock Sensor (Left) - Removal / Installation        |               | HRS |             | 3041.4          |     |                  | 4.7         |                    |         | 0            |
|                  |                                                                          |               | AFL |             | 1114            |     |                  | 3           |                    |         | 0            |
|                  | 60P3261030Z001                                                           | 009779        | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                          |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| 326141           | Nose Landing Gear Downlock Sensor (Right) - Removal / Installation       |               | HRS |             | 3041.4          |     |                  | 4.7         |                    |         | 0            |
|                  |                                                                          |               | AFL |             | 1114            |     |                  | 3           |                    |         | 0            |
|                  | 60P3261030Z001                                                           | 009782        | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                          |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| 326144           | Main Landing Gear Uplock Sensor (Left Forward) - Removal / Installation  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                          |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P3261030Z001                                                           | 007406        | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                          |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| 326145           | Main Landing Gear Uplock Sensor (Right Forward) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                          |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P3261030Z001                                                           | 009257        | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                          |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| 326146           | Main Landing Gear Uplock Sensor (Left Aft) - Removal / Installation      |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                          |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P3261030Z001                                                           | 007472        | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                          |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| 326147           | Main Landing Gear Uplock Sensor (Right Aft) - Removal / Installation     |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                          |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P3261030Z001                                                           | 009281        | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                          |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                          |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                         | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                     |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                              |               |     |             |                 |     |                  |             |                    |         |              |
| 326152           | Main Landing Gear Downlock Sensor (Left Forward) - Removal / Installation  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                            |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P3261030Z001                                                             | 009348        | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                            |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                            |               |     |             |                 |     |                  |             |                    |         |              |
| 326153           | Main Landing Gear Downlock Sensor (Right Forward) - Removal / Installation |               | HRS | TSN:10      | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                            |               | AFL | TSN:5       | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P3261030Z001                                                             | 007661        | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                            |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                            |               |     |             |                 |     |                  |             |                    |         |              |
| 326154           | Main Landing Gear Downlock Sensor (Left Aft) - Removal / Installation      |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                            |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P3261030Z001                                                             | 009653        | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                            |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                            |               |     |             |                 |     |                  |             |                    |         |              |
| 326155           | Main Landing Gear Downlock Sensor (Right Aft) - Removal / Installation     |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                            |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P3261030Z001                                                             | 009545        | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                            |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                            |               |     |             |                 |     |                  |             |                    |         |              |
| 326200           | Wow System - Functional Test                                               |               | HRS |             | 2549.5          |     |                  | 496.6       |                    |         | 0            |
|                  |                                                                            |               | AFL |             | 979             |     |                  | 138         |                    |         | 0            |
|                  |                                                                            |               | MOS |             | 103             |     |                  | 11 Oct 2017 |                    |         |              |
|                  |                                                                            |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                            |               |     |             |                 |     |                  |             |                    |         |              |
| 326201           | Nose Landing Gear Wow Sensor - Adjustment                                  |               | HRS |             | 2549.5          |     |                  | 496.6       |                    |         | 0            |
|                  |                                                                            |               | AFL |             | 979             |     |                  | 138         |                    |         | 0            |
|                  |                                                                            |               | MOS |             | 103             |     |                  | 11 Oct 2017 |                    |         |              |
|                  |                                                                            |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                            |               |     |             |                 |     |                  |             |                    |         |              |
| 326202           | Main Landing Gear Wow Sensor - Adjustment                                  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                            |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                            |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                            |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                            |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom     | Description                                                            |               | UOM            | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due     | Avg Man Hrs  |
|---------------------|------------------------------------------------------------------------|---------------|----------------|-------------|-----------------|-----|------------------|-------------|---------------------|-------------|--------------|
|                     | Part Number                                                            | Serial Number |                |             |                 |     |                  |             |                     |             | Approx Price |
| Logbook Position    | HW                                                                     | SW            |                |             |                 |     |                  |             |                     |             | Manufacturer |
|                     | MM Ref                                                                 |               |                |             |                 |     |                  |             |                     |             | Date Type    |
|                     | Ops Number(s)                                                          |               |                |             |                 |     |                  |             |                     |             |              |
| 326203              | Nose Landing Gear Wow Sensor (Left) - Removal / Installation           |               | HRS            |             | 2549.5          |     |                  | 496.6       |                     |             | 0            |
|                     |                                                                        |               | AFL            |             | 979             |     |                  | 138         |                     |             | 0            |
|                     | 60P3261031Z001                                                         | SN-UNKNOWN    | MOS            |             | 103             |     |                  | 11 Oct 2017 |                     |             |              |
|                     |                                                                        |               | MSC            |             |                 |     | O/C              |             |                     |             |              |
| Airframe            |                                                                        |               |                |             |                 |     |                  |             |                     |             |              |
| 326204              | Nose Landing Gear Wow Sensor (Right) - Removal / Installation          |               | HRS            | TSN:491.9   | 2549.5          |     |                  | 496.6       |                     |             | 0            |
|                     |                                                                        |               | AFL            | TSN:135     | 979             |     |                  | 138         |                     |             | 0            |
|                     | 60P3261031Z001                                                         | 3401          | MOS            | TSN:26      | 103             |     |                  | 11 Oct 2017 |                     |             |              |
|                     |                                                                        |               | MSC            |             |                 |     | O/C              |             |                     |             |              |
| Airframe            |                                                                        |               |                |             |                 |     |                  |             |                     |             |              |
| 326207              | Main Landing Gear Wow Sensor (Left Inboard) - Removal / Installation   |               | HRS            |             | 3046.1          |     |                  | 0           |                     |             | 0            |
|                     |                                                                        |               | AFL            |             | 1117            |     |                  | 0           |                     |             | 0            |
|                     | 60P3261030Z001                                                         | 009627        | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                     |             |              |
|                     |                                                                        |               | MSC            |             |                 |     | O/C              |             |                     |             |              |
| Airframe            |                                                                        |               |                |             |                 |     |                  |             |                     |             |              |
| 326208              | Main Landing Gear Wow Sensor (Left Outboard) - Removal / Installation  |               | HRS            |             | 3046.1          |     |                  | 0           |                     |             | 0            |
|                     |                                                                        |               | AFL            |             | 1117            |     |                  | 0           |                     |             | 0            |
|                     | 60P3261030Z001                                                         | 009634        | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                     |             |              |
|                     |                                                                        |               | MSC            |             |                 |     | O/C              |             |                     |             |              |
| Airframe            |                                                                        |               |                |             |                 |     |                  |             |                     |             |              |
| 326209              | Main Landing Gear Wow Sensor (Right Inboard) - Removal / Installation  |               | HRS            |             | 3046.1          |     |                  | 0           |                     |             | 0            |
|                     |                                                                        |               | AFL            |             | 1117            |     |                  | 0           |                     |             | 0            |
|                     | 60P3261030Z001                                                         | 009636        | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                     |             |              |
|                     |                                                                        |               | MSC            |             |                 |     | O/C              |             |                     |             |              |
| Airframe            |                                                                        |               |                |             |                 |     |                  |             |                     |             |              |
| 326210              | Main Landing Gear Wow Sensor (Right Outboard) - Removal / Installation |               | HRS            |             | 3046.1          |     |                  | 0           |                     |             | 0            |
|                     |                                                                        |               | AFL            |             | 1117            |     |                  | 0           |                     |             | 0            |
|                     | 60P3261030Z001                                                         | 009637        | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                     |             |              |
|                     |                                                                        |               | MSC            |             |                 |     | O/C              |             |                     |             |              |
| Airframe            |                                                                        |               |                |             |                 |     |                  |             |                     |             |              |
| 923200 <sup>U</sup> | Brake Wear Indicators - Detail Inspection                              |               | HRS            |             | 0               |     |                  | 3046.1      |                     |             | 0            |
|                     |                                                                        |               | AFL            |             | 0               |     |                  | 1117        |                     |             | 0            |
|                     |                                                                        |               | MOS            |             | .7              | -18 | 2                | 20 Apr 2026 | 02 Jun 2026*        | 02 Jul 2026 |              |
|                     |                                                                        |               | [MOS: +1m/-1m] |             |                 |     |                  |             |                     |             |              |
| Airframe            |                                                                        |               |                |             |                 |     |                  |             |                     |             |              |
| 33 - Lights         |                                                                        |               |                |             |                 |     |                  |             |                     |             |              |

| ATA<br>U=Custom  | Description                                                               |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|---------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                               | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                        | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                    |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 331100           | Annunciator Dim and Test Controller - Removal / Installation              |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                           |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 1159SCAV526-7                                                             | 1637          | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                           |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| 331102           | Annunciator Lights Dim and Test System (Press to Test) - Operational Test |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                           |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                           |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                           |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| 331103           | Annunciator Lights Dim and Test System (Dimming) - Operational Test       |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                           |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                           |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                           |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| 331205           | Side Console Panel Lighting Control - Operational Test                    |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                           |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                           |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                           |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| 331206           | Glareshield and Flight Panel Lighting Control - Operational Test          |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                           |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                           |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                           |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| 331207           | Standby Instrument Lighting - Operational Test                            |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                           |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                           |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                           |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| 331216           | Dimming Unit (Overhead and Pedestal Lights) - Removal / Installation      |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                           |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 110ZT02Y04                                                                | 370           | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                           |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                           |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom                   | Description                                                      |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|-----------------------------------|------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                                   | Part Number                                                      | Serial Number |     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position                  | HW                                                               | SW            |     |             |                 |     |                  |             |                     |         | Manufacturer |
|                                   | MM Ref                                                           |               |     |             |                 |     |                  |             |                     |         | Date Type    |
|                                   | Ops Number(s)                                                    |               |     |             |                 |     |                  |             |                     |         |              |
| 331217                            | Dimming Unit (Glareshield and Console) - Removal / Installation  |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                                   |                                                                  |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                                   | 110ZT02Y04                                                       | 369           | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                                   |                                                                  |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe                          |                                                                  |               |     |             |                 |     |                  |             |                     |         |              |
| 331220                            | Cockpit Side Console Floodlight - Operational Test               |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                                   |                                                                  |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                                   |                                                                  |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                                   |                                                                  |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe                          |                                                                  |               |     |             |                 |     |                  |             |                     |         |              |
| Notes: PN: 1 SN: <NONE>.          |                                                                  |               |     |             |                 |     |                  |             |                     |         |              |
| 331221                            | Cockpit Side Console Floodlight (Left) - Removal / Installation  |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                                   |                                                                  |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                                   | GAC-ELRD-1000                                                    | SN-UNKNOWN    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                                   |                                                                  |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe                          |                                                                  |               |     |             |                 |     |                  |             |                     |         |              |
| 331222                            | Cockpit Side Console Floodlight (Right) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                                   |                                                                  |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                                   | GAC-ELRD-1000                                                    | SN-UNKNOWN    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                                   |                                                                  |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe                          |                                                                  |               |     |             |                 |     |                  |             |                     |         |              |
| 331225                            | MAP Lights - Operational Test                                    |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                                   |                                                                  |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                                   |                                                                  |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                                   |                                                                  |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe                          |                                                                  |               |     |             |                 |     |                  |             |                     |         |              |
| Notes: PN: 503L0200-1 SN: <NONE>. |                                                                  |               |     |             |                 |     |                  |             |                     |         |              |
| 331230                            | Overhead MAP Lights (Pilot) - Removal / Installation             |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                                   |                                                                  |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                                   | GAC-ELRD-1000                                                    | SN-UNKNOWN    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                                   |                                                                  |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe                          |                                                                  |               |     |             |                 |     |                  |             |                     |         |              |
| 331231                            | Overhead MAP Lights (Copilot) - Removal / Installation           |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                                   |                                                                  |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                                   | GAC-ELRD-1000                                                    | SN-UNKNOWN    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                                   |                                                                  |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe                          |                                                                  |               |     |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom                   | Description                                               |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|-----------------------------------|-----------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                   | Part Number                                               | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position                  | HW                                                        | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                   | MM Ref                                                    |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                                   | Ops Number(s)                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 331318                            | Cockpit Dome Light - Operational Test                     |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                                   |                                                           |               | AFL |             | 315             |     |                  | 802         |                    |         | 0            |
|                                   |                                                           |               | MOS |             | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
|                                   | Airframe                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 331321                            | Cockpit Observer Light - Operational Check                |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                   |                                                           |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                   |                                                           |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                   | Airframe                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 331336                            | Cockpit Overhead Panel Lighting - Operational Test        |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                   |                                                           |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                   |                                                           |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                   | Airframe                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Notes: PN: 503L0200-1 SN: <NONE>. |                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| 331337                            | Cockpit Center Pedestal Lighting - Operational Test       |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                   |                                                           |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                   |                                                           |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                   | Airframe                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Notes: PN: 503L0200-1 SN: <NONE>. |                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| 331338                            | Cockpit Circuit Breaker Panel Lighting - Operational Test |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                   |                                                           |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                   |                                                           |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                   | Airframe                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Notes: PN: 503L0200-1 SN: <NONE>. |                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| 331339                            | Cockpit Overhead Floodlights - Operational Test           |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                                   |                                                           |               | AFL |             | 315             |     |                  | 802         |                    |         | 0            |
|                                   |                                                           |               | MOS |             | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
|                                   | Airframe                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Notes: PN: 503L0200-1 SN: <NONE>. |                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| 332100                            | Airstair Lighting - Operational Test                      |               | HRS |             | 1300.7          |     |                  | 1745.4      |                    |         | 0            |
|                                   |                                                           |               | AFL |             | 507             |     |                  | 610         |                    |         | 0            |
|                                   |                                                           |               | MOS |             | 52              |     |                  | 12 Jan 2022 |                    |         |              |
|                                   | Airframe                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |

| ATA<br>U=Custom                   | Description                                                                                    |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|-----------------------------------|------------------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|----------|--------------------|---------|--------------|
|                                   | Part Number                                                                                    | Serial Number |     |             |                 |     |                  |          |                    |         | Approx Price |
| Logbook Position                  | HW                                                                                             | SW            |     |             |                 |     |                  |          |                    |         | Manufacturer |
|                                   | MM Ref                                                                                         |               |     |             |                 |     |                  |          |                    |         | Date Type    |
|                                   | Ops Number(s)                                                                                  |               |     |             |                 |     |                  |          |                    |         |              |
| 332202                            | Vestibule Lighting (Fwd) - Adjustment - Test                                                   |               | HRS |             | 730.5           |     |                  | 2315.6   |                    | 0       |              |
|                                   |                                                                                                |               | AFL |             | 315             |     | 802              |          | 0                  |         |              |
|                                   |                                                                                                |               | MOS |             | 28.7            |     | 21 Dec 2023      |          |                    |         |              |
|                                   |                                                                                                |               | MSC |             |                 | O/C |                  |          |                    |         |              |
| 332203                            | Vestibule Lighting (Aft) - Adjustment - Test                                                   |               | HRS |             | 730.5           |     |                  | 2315.6   |                    | 0       |              |
|                                   |                                                                                                |               | AFL |             | 315             |     | 802              |          | 0                  |         |              |
|                                   |                                                                                                |               | MOS |             | 28.7            |     | 21 Dec 2023      |          |                    |         |              |
|                                   |                                                                                                |               | MSC |             |                 | O/C |                  |          |                    |         |              |
| 332627                            | Forward Right Psu Upper Effect Light #2 - Removal /<br>Installation<br>GAC-ELMW-036200979-1-21 |               | HRS |             | 994.2           |     |                  | 2051.9   |                    | 0       |              |
|                                   |                                                                                                |               | AFL |             | 392             |     | 725              |          | 0                  |         |              |
|                                   |                                                                                                |               | MOS | TSN:56      | 41.1            |     | 07 Dec 2022      |          |                    |         |              |
|                                   |                                                                                                |               | MSC |             |                 | O/C |                  |          |                    |         |              |
| 333100                            | Baggage Compartment Lights - Operational Test                                                  |               | HRS |             | 3046.1          |     |                  | 0        |                    | 0       |              |
|                                   |                                                                                                |               | AFL |             | 1117            |     | 0                |          | 0                  |         |              |
|                                   |                                                                                                |               | MOS |             | 128.6           |     | 24 Aug 2015      |          |                    |         |              |
|                                   |                                                                                                |               | MSC |             |                 | O/C |                  |          |                    |         |              |
| 333204                            | Tail Compartment Lighting - Operational Test                                                   |               | HRS |             | 3046.1          |     |                  | 0        |                    | 0       |              |
|                                   |                                                                                                |               | AFL |             | 1117            |     | 0                |          | 0                  |         |              |
|                                   |                                                                                                |               | MOS |             | 128.6           |     | 24 Aug 2015      |          |                    |         |              |
|                                   |                                                                                                |               | MSC |             |                 | O/C |                  |          |                    |         |              |
| 333205                            | Service Lighting - Operational Test                                                            |               | HRS |             | 3046.1          |     |                  | 0        |                    | 0       |              |
|                                   |                                                                                                |               | AFL |             | 1117            |     | 0                |          | 0                  |         |              |
|                                   |                                                                                                |               | MOS |             | 128.6           |     | 24 Aug 2015      |          |                    |         |              |
|                                   |                                                                                                |               | MSC |             |                 | O/C |                  |          |                    |         |              |
| 333306                            | Wheel Well Lights - Operational Test                                                           |               | HRS |             | 3046.1          |     |                  | 0        |                    | 0       |              |
|                                   |                                                                                                |               | AFL |             | 1117            |     | 0                |          | 0                  |         |              |
|                                   |                                                                                                |               | MOS |             | 128.6           |     | 24 Aug 2015      |          |                    |         |              |
|                                   |                                                                                                |               | MSC |             |                 | O/C |                  |          |                    |         |              |
| Notes: PN: 503L0200-1 SN: <NONE>. |                                                                                                |               |     |             |                 |     |                  |          |                    |         |              |
| 334004                            | Ramp Lights - Operational Test                                                                 |               | HRS |             | 3046.1          |     |                  | 0        |                    | 0       |              |
|                                   |                                                                                                |               | AFL |             | 1117            |     | 0                |          | 0                  |         |              |
|                                   |                                                                                                |               | MOS |             | 128.6           |     | 24 Aug 2015      |          |                    |         |              |
|                                   |                                                                                                |               | MSC |             |                 | O/C |                  |          |                    |         |              |
| Airframe                          |                                                                                                |               |     |             |                 |     |                  |          |                    |         |              |

| ATA<br>U=Custom  | Description                                                                           |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|---------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                                                           | Serial Number |     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                                                    | SW            |     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                                                |               |     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                                                         |               |     |             |                 |     |                  |             |                     |         |              |
| 334103           | Left Wing-Tip Flood / Taxi Light Assembly (Forward Facing) - Removal / Installation   |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                                       |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 01-0771125-30                                                                         | 01079         | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                                       |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                       |               |     |             |                 |     |                  |             |                     |         |              |
| 334104           | Right Wing-Tip Flood / Taxi Light Assembly (Forward Facing) - Removal / Installation  |               | HRS |             | 1021.9          |     |                  | 2024.2      |                     |         | 0            |
|                  |                                                                                       |               | AFL |             | 397             |     |                  | 720         |                     |         | 0            |
|                  | 01-0771125-30                                                                         | 210300        | MOS |             | 41.8            |     |                  | 18 Nov 2022 |                     |         |              |
|                  |                                                                                       |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                       |               |     |             |                 |     |                  |             |                     |         |              |
| 334105           | Left Wing-Tip Flood / Taxi Light Assembly (Downward Facing) - Removal / Installation  |               | HRS |             | 1452            |     |                  | 1594.1      |                     |         | 0            |
|                  |                                                                                       |               | AFL |             | 570             |     |                  | 547         |                     |         | 0            |
|                  | 01-0771125-30                                                                         | 02076         | MOS |             | 63.9            |     |                  | 14 Jan 2021 |                     |         |              |
|                  |                                                                                       |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                       |               |     |             |                 |     |                  |             |                     |         |              |
| 334106           | Right Wing-Tip Flood / Taxi Light Assembly (Downward Facing) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                                       |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 01-0771125-30                                                                         | SN-UNKNOWN    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                                       |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                       |               |     |             |                 |     |                  |             |                     |         |              |
| 334109           | Landing Light (Left) - Removal / Installation                                         |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  | 503H0081-6 GLB00592                                                                   |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  |                                                                                       |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                                       |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                       |               |     |             |                 |     |                  |             |                     |         |              |
| 334110           | Landing Light (Right) - Removal / Installation                                        |               | HRS |             | 536.8           |     |                  | 2509.3      |                     |         | 0            |
|                  | 503H0081-6 GLL02013                                                                   |               | AFL |             | 206             |     |                  | 911         |                     |         | 0            |
|                  |                                                                                       |               | MOS |             | 15.8            |     |                  | 16 Jan 2025 |                     |         |              |
|                  |                                                                                       |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                       |               |     |             |                 |     |                  |             |                     |         |              |
| 334113           | Landing Light Ballast (Left) - Removal / Installation                                 |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  | 503H0200-3 GLL00676                                                                   |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  |                                                                                       |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                                       |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                       |               |     |             |                 |     |                  |             |                     |         |              |



| ATA<br>U=Custom                   | Description                                            |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|-----------------------------------|--------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                   | Part Number                                            | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position                  | HW                                                     | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                   | MM Ref                                                 |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                                   | Ops Number(s)                                          |               |     |             |                 |     |                  |             |                    |         |              |
| 334114                            | Landing Light Ballast (Right) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                   | 503H0200-3                                             | GLB00569      | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                   |                                                        |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                   | Airframe                                               |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 334119                            | Landing Lights - Operational Test                      |               | HRS |             | 536.8           |     |                  | 2509.3      |                    |         | 0            |
|                                   |                                                        |               | AFL |             | 206             |     |                  | 911         |                    |         | 0            |
|                                   |                                                        |               | MOS |             | 15.8            |     |                  | 16 Jan 2025 |                    |         |              |
|                                   | Airframe                                               |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Notes: PN: 503L0200-1 SN: <NONE>. |                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 334120                            | Landing Lights - Adjustment                            |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                   |                                                        |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                   |                                                        |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                   | Airframe                                               |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Notes: PN: 503L0200-1 SN: <NONE>. |                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 334125                            | Landing Lights Control Unit - Removal / Installation   |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                   | 503H8901-3                                             | GLC00329      | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                   |                                                        |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                   | Airframe                                               |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 334127                            | Nose Wheel Taxi Lights - Operational Test              |               | HRS |             | 663.7           |     |                  | 2382.4      |                    |         | 0            |
|                                   |                                                        |               | AFL |             | 291             |     |                  | 826         |                    |         | 0            |
|                                   |                                                        |               | MOS |             | 24.9            |     |                  | 15 Apr 2024 |                    |         |              |
|                                   | Airframe                                               |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Notes: PN: 503L0200-1 SN: <NONE>. |                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 334128                            | Wing-Tip Floodlights / Taxi Lights - Operational Test  |               | HRS |             | 1021.9          |     |                  | 2024.2      |                    |         | 0            |
|                                   |                                                        |               | AFL |             | 397             |     |                  | 720         |                    |         | 0            |
|                                   |                                                        |               | MOS |             | 41.8            |     |                  | 18 Nov 2022 |                    |         |              |
|                                   | Airframe                                               |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Notes: PN: 503L0200-1 SN: <NONE>. |                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 334129                            | Nose Wheel Taxi Light (Left) - Removal / Installation  |               | HRS |             | 964             |     |                  | 2082.1      |                    |         | 0            |
|                                   | 01-0790460-00                                          | 12246060008   | AFL |             | 381             |     |                  | 736         |                    |         | 0            |
|                                   |                                                        |               | MOS |             | 39.3            |     |                  | 01 Feb 2023 |                    |         |              |
|                                   | Airframe                                               |               | MSC |             |                 |     | O/C              |             |                    |         |              |

| ATA<br>U=Custom                | Description                                                            |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|--------------------------------|------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                | Part Number                                                            | Serial Number |                                    |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position               | HW                                                                     | SW            |                                    |             |                 |     |                  |             |                    |         | Manufacturer |
|                                | MM Ref                                                                 |               |                                    |             |                 |     |                  |             |                    |         | Date Type    |
|                                | Ops Number(s)                                                          |               |                                    |             |                 |     |                  |             |                    |         |              |
| 334130                         | Nose Wheel Taxi Light (Center) - Removal / Installation                |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | 01-0790460-00 SN-UNKNOWN                                               |               | AFL                                |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                |                                                                        |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                                               |               | MSC                                |             |                 |     | O/C              |             |                    |         |              |
| 334131                         | Nose Wheel Taxi Light (Right) - Removal / Installation                 |               | HRS                                |             | 2413.3          |     |                  | 632.8       |                    |         | 0            |
|                                | 01-0790460-00 01270                                                    |               | AFL                                |             | 949             |     |                  | 168         |                    |         | 0            |
|                                |                                                                        |               | MOS                                |             | 98.8            |     |                  | 18 Feb 2018 |                    |         |              |
|                                | Airframe                                                               |               | MSC                                |             |                 |     | O/C              |             |                    |         |              |
| 334200                         | Anticollision Beacon Light - Removal / Installation                    |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                | 01-0771065-02 00296                                                    |               | AFL                                |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                |                                                                        |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                                               |               | MSC                                |             |                 |     | O/C              |             |                    |         |              |
| 334202                         | Anticollision Beacon Light - Operational Check                         |               | HRS                                |             | 137             |     |                  | 2909.1      |                    |         | 0            |
|                                |                                                                        |               | AFL                                |             | 52              |     |                  | 1065        |                    |         | 0            |
|                                |                                                                        |               | MOS                                |             | 5.5             | 12  | 27 Nov 2025      | 30 Nov 2026 | 31 Dec 2026        |         |              |
|                                | Airframe                                                               |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |         |              |
| 334203                         | Wing Anticollision / Navigation Light (Left) - Removal / Installation  |               | HRS                                |             | 1452            |     |                  | 1594.1      |                    |         | 0            |
|                                | 01-0790453-02 01183                                                    |               | AFL                                |             | 570             |     |                  | 547         |                    |         | 0            |
|                                |                                                                        |               | MOS                                |             | 64              |     |                  | 11 Jan 2021 |                    |         |              |
|                                | Airframe                                                               |               | MSC                                |             |                 |     | O/C              |             |                    |         |              |
| 334204                         | Wing Anticollision / Navigation Light (Right) - Removal / Installation |               | HRS                                |             | 1844.6          |     |                  | 1201.5      |                    |         | 0            |
|                                | 01-0790453-01 01135                                                    |               | AFL                                |             | 766             |     |                  | 351         |                    |         | 0            |
|                                |                                                                        |               | MOS                                |             | 79.4            |     |                  | 29 Sep 2019 |                    |         |              |
|                                | Airframe                                                               |               | MSC                                |             |                 |     | O/C              |             |                    |         |              |
| 334207                         | Wing Anticollision / Navigation Light (Left) - Discard                 |               | HRS                                |             | 3046.1          |     | 20000            | 0           | 20000              |         | 0            |
|                                | 1007-3342A002-003 LM0664                                               |               | AFL                                |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                |                                                                        |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                | Airframe                                                               |               |                                    |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 334203 |                                                                        |               |                                    |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom                    | Description                                                    |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due     | Avg Man Hrs  |
|------------------------------------|----------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|---------------------|-------------|--------------|
|                                    | Part Number                                                    | Serial Number |     |             |                 |     |                  |             |                     |             | Approx Price |
| Logbook Position                   | HW                                                             | SW            |     |             |                 |     |                  |             |                     |             | Manufacturer |
|                                    | MM Ref                                                         |               |     |             |                 |     |                  |             |                     |             | Date Type    |
|                                    | Ops Number(s)                                                  |               |     |             |                 |     |                  |             |                     |             |              |
| 334208                             | Wing Anticollision / Navigation Light (Right) - Discard        |               | HRS |             | 1844.6          |     | 20000            | 1201.5      | 21201.5             |             | 0            |
|                                    | 01-0790453-01                                                  | 01135         | AFL |             | 766             |     |                  | 351         |                     |             | 0            |
|                                    |                                                                |               | MOS |             | 79.4            |     |                  | 29 Sep 2019 |                     |             |              |
| Airframe                           |                                                                |               |     |             |                 |     |                  |             |                     |             |              |
| Notes: MRI PARENT CODE: 334204     |                                                                |               |     |             |                 |     |                  |             |                     |             |              |
| 334211                             | Navigation Lights - Operational Check                          |               | HRS |             | 137             |     |                  | 2909.1      |                     |             | 0            |
|                                    |                                                                |               | AFL |             | 52              |     |                  | 1065        |                     |             | 0            |
|                                    |                                                                |               | MOS |             | 5.5             | 7   | 12               | 27 Nov 2025 | 31 Dec 2026*        | 31 Jan 2027 |              |
| [End Of Month Item] [MOS: +1m/-1m] |                                                                |               |     |             |                 |     |                  |             |                     |             |              |
| Airframe                           |                                                                |               |     |             |                 |     |                  |             |                     |             |              |
| 334212                             | Anticollision Lights - Operational Test                        |               | HRS |             | 663.7           |     |                  | 2382.4      |                     |             | 0            |
|                                    |                                                                |               | AFL |             | 291             |     |                  | 826         |                     |             | 0            |
|                                    |                                                                |               | MOS |             | 24.9            |     |                  | 15 Apr 2024 |                     |             |              |
| Airframe                           |                                                                |               |     |             |                 |     |                  |             |                     |             |              |
| 334213                             | Tail Anticollision / Navigation Light - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                     |             | 0            |
|                                    | 01-0790450-00                                                  | SN-UNKNOWN    | AFL |             | 1117            |     |                  | 0           |                     |             | 0            |
|                                    |                                                                |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |             |              |
| Airframe                           |                                                                |               |     |             |                 |     |                  |             |                     |             |              |
| 334215                             | Tail Anticollision / Navigation Light - Discard                |               | HRS |             | 3046.1          |     | 20000            | 0           | 20000               |             | 0            |
|                                    | 01-0790450-00                                                  | NSN           | AFL |             | 1117            |     |                  | 0           |                     |             | 0            |
|                                    |                                                                |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |             |              |
| Airframe                           |                                                                |               |     |             |                 |     |                  |             |                     |             |              |
| 334216                             | Left Wing-Tip Flood / Taxi Lights - Removal / Installation     |               | HRS |             | 3046.1          |     |                  | 0           |                     |             | 0            |
|                                    | 01-0771125-30                                                  | SN-UNKNOWN    | AFL |             | 1117            |     |                  | 0           |                     |             | 0            |
|                                    |                                                                |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |             |              |
| Airframe                           |                                                                |               |     |             |                 |     |                  |             |                     |             |              |
| 334217                             | Right Wing-Tip Flood / Taxi Lights - Removal / Installation    |               | HRS |             | 3046.1          |     |                  | 0           |                     |             | 0            |
|                                    | 01-0771125-30                                                  | SN-UNKNOWN    | AFL |             | 1117            |     |                  | 0           |                     |             | 0            |
|                                    |                                                                |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |             |              |
| Airframe                           |                                                                |               |     |             |                 |     |                  |             |                     |             |              |
| 334218                             | Fin CAP Nav / Acl Kit - Removal / Installation                 |               | HRS |             | 3046.1          |     |                  | 0           |                     |             | 0            |
|                                    | 1007-3342N001-007                                              | 00329         | AFL |             | 1117            |     |                  | 0           |                     |             | 0            |
|                                    |                                                                |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |             |              |
| Airframe                           |                                                                |               |     |             |                 |     |                  |             |                     |             |              |
| MSC                                |                                                                |               |     |             |                 |     |                  |             |                     |             |              |
| O/C                                |                                                                |               |     |             |                 |     |                  |             |                     |             |              |

| ATA<br>U=Custom  | Description                                                                  |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                                                  | Serial Number |     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                                           | SW            |     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                                       |               |     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                                                |               |     |             |                 |     |                  |             |                     |         |              |
| 334220           | Wingtip Flasher / Current Source (Left) - Removal / Installation             |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                              |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 01-0790456-00                                                                | 00695         | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                              |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                              |               |     |             |                 |     |                  |             |                     |         |              |
| 334221           | Wingtipflasher / Current Source (Right) - Removal / Installation             |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                              |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 01-0790456-00                                                                | 00687         | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                              |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                              |               |     |             |                 |     |                  |             |                     |         |              |
| 334224           | Winglet Light Assembly (Left) - Removal Installation                         |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  | 1007-3342A001-003                                                            | NSN           | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  |                                                                              |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                              |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                              |               |     |             |                 |     |                  |             |                     |         |              |
| 334225           | Winglet Light Assembly (Right) - Removal Installation                        |               | HRS |             | 2612.1          |     |                  | 434         |                     |         | 0            |
|                  | 1007-3342A001-004                                                            | SN-UNKNOWN    | AFL |             | 1002            |     |                  | 115         |                     |         | 0            |
|                  |                                                                              |               | MOS |             | 106             |     |                  | 11 Jul 2017 |                     |         |              |
|                  |                                                                              |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                              |               |     |             |                 |     |                  |             |                     |         |              |
| 334228           | Tail Navigation / Anticollision Light Lens Assembly - Removal / Installation |               | HRS |             | 663.7           |     |                  | 2382.4      |                     |         | 0            |
|                  |                                                                              |               | AFL |             | 291             |     |                  | 826         |                     |         | 0            |
|                  | 1007-3342A010-001                                                            | SN-UNKNOWN    | MOS | TSN:14      | 24.9            |     |                  | 15 Apr 2024 |                     |         |              |
|                  |                                                                              |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                              |               |     |             |                 |     |                  |             |                     |         |              |
| 334302           | Ice Inspection Lights - Operational Test                                     |               | HRS |             | 663.7           |     |                  | 2382.4      |                     |         | 0            |
|                  |                                                                              |               | AFL |             | 291             |     |                  | 826         |                     |         | 0            |
|                  |                                                                              |               | MOS |             | 24.9            |     |                  | 15 Apr 2024 |                     |         |              |
|                  |                                                                              |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                              |               |     |             |                 |     |                  |             |                     |         |              |
| 334303           | Ice Inspection Lights (Left) - Removal / Installation                        |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  | 20-2001-0002                                                                 | NSN           | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  |                                                                              |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                              |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                              |               |     |             |                 |     |                  |             |                     |         |              |
| 334304           | Ice Inspection Lights (Right) - Removal / Installation                       |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  | 20-2001-0001                                                                 | NSN           | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  |                                                                              |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                              |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                              |               |     |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom  | Description                                     |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------|-------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                  | Part Number                                     | Serial Number |                                    |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position | HW                                              | SW            |                                    |             |                 |     |                  |             |                    |             | Manufacturer |
|                  | MM Ref                                          |               |                                    |             |                 |     |                  |             |                    |             | Date Type    |
|                  | Ops Number(s)                                   |               |                                    |             |                 |     |                  |             |                    |             |              |
| 334400           | Left Logo Light - Removal / Installation        |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  | 20-3101-0002                                    | 133892-15-3   | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                 |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  | Airframe                                        |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| 334401           | Right Logo Light - Removal / Installation       |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  | 20-3101-0001                                    | 133888-6-2    | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                 |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  | Airframe                                        |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| 334404           | Logo Lights - Operational Test                  |               | HRS                                |             | 663.7           |     |                  | 2382.4      |                    |             | 0            |
|                  |                                                 |               | AFL                                |             | 291             |     |                  | 826         |                    |             | 0            |
|                  |                                                 |               | MOS                                |             | 24.9            |     |                  | 15 Apr 2024 |                    |             |              |
|                  | Airframe                                        |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| 335000           | Exterior Emergency Lighting - Operational Check |               | HRS                                |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                  |                                                 |               | AFL                                |             | 52              |     |                  | 1065        |                    |             | 0            |
|                  |                                                 |               | MOS                                |             | 5.5             |     | 24               | 27 Nov 2025 | 30 Nov 2027        | 31 Dec 2027 |              |
|                  | Airframe                                        |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| 335001           | Left Overwing Emergency Egress Light (FS 517)   |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  | 503L1300-2                                      | GEC01085      | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                 |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  | Airframe                                        |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| 335002           | Left Overwing Emergency Egress Light (FS 558)   |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  | 503L1300-2                                      | GEC01185      | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                 |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  | Airframe                                        |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| 335003           | Left Overwing Emergency Egress Light (FS 615)   |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  | 503L1300-2                                      | GEC01173      | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                 |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  | Airframe                                        |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| 335004           | Right Overwing Emergency Egress Light (FS 517)  |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  | 503L1300-2                                      | GEC01009      | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                 |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  | Airframe                                        |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |

| ATA<br>U=Custom  | Description                                                       |               | UOM | Times Since                        | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due     | Avg Man Hrs  |
|------------------|-------------------------------------------------------------------|---------------|-----|------------------------------------|-----------------|-----|------------------|-------------|---------------------|-------------|--------------|
|                  | Part Number                                                       | Serial Number |     |                                    |                 |     |                  |             |                     |             | Approx Price |
| Logbook Position | HW                                                                | SW            |     |                                    |                 |     |                  |             |                     |             | Manufacturer |
|                  | MM Ref                                                            |               |     |                                    |                 |     |                  |             |                     |             | Date Type    |
|                  | Ops Number(s)                                                     |               |     |                                    |                 |     |                  |             |                     |             |              |
| 335005           | Right Overwing Emergency Egress Light (FS 558)                    |               | HRS |                                    | 3046.1          |     |                  | 0           |                     |             | 0            |
|                  | 503L1300-2                                                        | GEC01019      | AFL |                                    | 1117            |     |                  | 0           |                     |             | 0            |
|                  |                                                                   |               | MOS |                                    | 128.6           |     |                  | 24 Aug 2015 |                     |             |              |
|                  | Airframe                                                          |               | MSC |                                    |                 |     | O/C              |             |                     |             |              |
| 335006           | Right Overwing Emergency Egress Light (FS 615)                    |               | HRS |                                    | 3046.1          |     |                  | 0           |                     |             | 0            |
|                  | 503L1300-2                                                        | GEC01179      | AFL |                                    | 1117            |     |                  | 0           |                     |             | 0            |
|                  |                                                                   |               | MOS |                                    | 128.6           |     |                  | 24 Aug 2015 |                     |             |              |
|                  | Airframe                                                          |               | MSC |                                    |                 |     | O/C              |             |                     |             |              |
| 335100           | Cabin Emergency Lighting - Operational Check                      |               | HRS |                                    | 137             |     |                  | 2909.1      |                     |             | 0            |
|                  |                                                                   |               | AFL |                                    | 52              |     |                  | 1065        |                     |             | 0            |
|                  |                                                                   |               | MOS |                                    | 5.3             |     | 24               | 01 Dec 2025 | 31 Dec 2027         | 31 Jan 2028 |              |
|                  | Airframe                                                          | 052011        |     | [End Of Month Item] [MOS: +1m/-1m] |                 |     |                  |             |                     |             |              |
| 335101           | Main Entrance Door Emergency Exit Light - Removal / Installation  |               | HRS |                                    | 3046.1          |     |                  | 0           |                     |             | 0            |
|                  |                                                                   |               | AFL |                                    | 1117            |     |                  | 0           |                     |             | 0            |
|                  | GAC-ELES-1000                                                     | 6160          | MOS |                                    | 128.6           |     |                  | 24 Aug 2015 |                     |             |              |
|                  | Airframe                                                          |               | MSC |                                    |                 |     | O/C              |             |                     |             |              |
| 335106           | Cabin Emergency Lighting - Adjustment / Test                      |               | HRS |                                    | 730.5           |     |                  | 2315.6      |                     |             | 0            |
|                  |                                                                   |               | AFL |                                    | 315             |     |                  | 802         |                     |             | 0            |
|                  |                                                                   |               | MOS |                                    | 28.7            |     |                  | 21 Dec 2023 |                     |             |              |
|                  | Airframe                                                          |               | MSC |                                    |                 |     | O/C              |             |                     |             |              |
| 335223           | Underwing Emergency Egress Light (Left) - Removal / Installation  |               | HRS |                                    | 3046.1          |     |                  | 0           |                     |             | 0            |
|                  |                                                                   |               | AFL |                                    | 1117            |     |                  | 0           |                     |             | 0            |
|                  | 503L1200-3                                                        | GEL00180      | MOS |                                    | 128.6           |     |                  | 24 Aug 2015 |                     |             |              |
|                  | Airframe                                                          |               | MSC |                                    |                 |     | O/C              |             |                     |             |              |
| 335224           | Underwing Emergency Egress Light (Right) - Removal / Installation |               | HRS |                                    | 3046.1          |     |                  | 0           |                     |             | 0            |
|                  |                                                                   |               | AFL |                                    | 1117            |     |                  | 0           |                     |             | 0            |
|                  | 503L1200-4                                                        | GER00164      | MOS |                                    | 128.6           |     |                  | 24 Aug 2015 |                     |             |              |
|                  | Airframe                                                          |               | MSC |                                    |                 |     | O/C              |             |                     |             |              |
| 335400           | Cabin Floorpath Lighting - Adjustment / Test                      |               | HRS |                                    | 730.5           |     |                  | 2315.6      |                     |             | 0            |
|                  |                                                                   |               | AFL |                                    | 315             |     |                  | 802         |                     |             | 0            |
|                  |                                                                   |               | MOS |                                    | 28.7            |     |                  | 21 Dec 2023 |                     |             |              |
|                  | Airframe                                                          |               | MSC |                                    |                 |     | O/C              |             |                     |             |              |

| ATA<br>U=Custom  | Description   |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|---------------|---------------|-----|-------------|-----------------|-----|------------------|----------|--------------------|---------|--------------|
|                  | Part Number   | Serial Number |     |             |                 |     |                  |          |                    |         | Approx Price |
| Logbook Position | HW            | SW            |     |             |                 |     |                  |          |                    |         | Manufacturer |
|                  | MM Ref        |               |     |             |                 |     |                  |          |                    |         | Date Type    |
|                  | Ops Number(s) |               |     |             |                 |     |                  |          |                    |         |              |

|                 |                                                                                                     |  |                     |  |        |  |     |             |             |  |   |
|-----------------|-----------------------------------------------------------------------------------------------------|--|---------------------|--|--------|--|-----|-------------|-------------|--|---|
| 34 - Navigation |                                                                                                     |  |                     |  |        |  |     |             |             |  |   |
| 340100          | Reduced Vertical Separation Minimum (RVSM) Monitoring Policy                                        |  | HRS                 |  | 562.4  |  |     | 2483.7      |             |  | 0 |
|                 |                                                                                                     |  | AFL                 |  | 217    |  |     | 900         |             |  | 0 |
|                 |                                                                                                     |  | MOS                 |  | 16.8   |  | 24  | 16 Dec 2024 | 31 Dec 2026 |  |   |
|                 |                                                                                                     |  | [End Of Month Item] |  |        |  |     |             |             |  |   |
| Airframe        |                                                                                                     |  |                     |  |        |  |     |             |             |  |   |
| 341200          | AIR Data Probe (No. 1 - Left Upper) - Removal / Installation<br>2015G2H2CLU-2<br>A<br>0784<br>0011  |  | HRS                 |  | 2430.9 |  |     | 615.2       |             |  | 0 |
|                 |                                                                                                     |  | AFL                 |  | 952    |  |     | 165         |             |  | 0 |
|                 |                                                                                                     |  | MOS                 |  | 99.1   |  |     | 08 Feb 2018 |             |  |   |
|                 |                                                                                                     |  | MSC                 |  |        |  | O/C |             |             |  |   |
| Airframe        |                                                                                                     |  |                     |  |        |  |     |             |             |  |   |
| 341201          | AIR Data Probe (No. 3 - Left Lower) - Removal / Installation<br>2015G2H2CLL-2<br>1332               |  | HRS                 |  | 829    |  |     | 2217.1      |             |  | 0 |
|                 |                                                                                                     |  | AFL                 |  | 349    |  |     | 768         |             |  | 0 |
|                 |                                                                                                     |  | MOS                 |  | 34.9   |  |     | 13 Jun 2023 |             |  |   |
|                 |                                                                                                     |  | MSC                 |  |        |  | O/C |             |             |  |   |
| Airframe        |                                                                                                     |  |                     |  |        |  |     |             |             |  |   |
| 341202          | AIR Data Probe (No. 2 - Right Upper) - Removal / Installation<br>2015G2H2CRU-2<br>A<br>0805<br>0011 |  | HRS                 |  | 3046.1 |  |     | 0           |             |  | 0 |
|                 |                                                                                                     |  | AFL                 |  | 1117   |  |     | 0           |             |  | 0 |
|                 |                                                                                                     |  | MOS                 |  | 128.6  |  |     | 24 Aug 2015 |             |  |   |
|                 |                                                                                                     |  | MSC                 |  |        |  | O/C |             |             |  |   |
| Airframe        |                                                                                                     |  |                     |  |        |  |     |             |             |  |   |
| 341203          | AIR Data Probe (No. 4 - Right Lower) - Removal / Installation<br>2015G2H2CRL-2<br>A<br>0833<br>0011 |  | HRS                 |  | 3046.1 |  |     | 0           |             |  | 0 |
|                 |                                                                                                     |  | AFL                 |  | 1117   |  |     | 0           |             |  | 0 |
|                 |                                                                                                     |  | MOS                 |  | 128.6  |  |     | 24 Aug 2015 |             |  |   |
|                 |                                                                                                     |  | MSC                 |  |        |  | O/C |             |             |  |   |
| Airframe        |                                                                                                     |  |                     |  |        |  |     |             |             |  |   |
| 341208          | AIR Data Probe (No. 1) - Functional Check                                                           |  | HRS                 |  | 2430.9 |  |     | 615.2       |             |  | 0 |
|                 |                                                                                                     |  | AFL                 |  | 952    |  |     | 165         |             |  | 0 |
|                 |                                                                                                     |  | MOS                 |  | 99.1   |  |     | 08 Feb 2018 |             |  |   |
|                 |                                                                                                     |  | MSC                 |  |        |  | O/C |             |             |  |   |
| Airframe        |                                                                                                     |  |                     |  |        |  |     |             |             |  |   |
| 341209          | AIR Data Probe (No. 2) - Functional Check                                                           |  | HRS                 |  | 3046.1 |  |     | 0           |             |  | 0 |
|                 |                                                                                                     |  | AFL                 |  | 1117   |  |     | 0           |             |  | 0 |
|                 |                                                                                                     |  | MOS                 |  | 128.6  |  |     | 24 Aug 2015 |             |  |   |
|                 |                                                                                                     |  | MSC                 |  |        |  | O/C |             |             |  |   |
| Airframe        |                                                                                                     |  |                     |  |        |  |     |             |             |  |   |

| ATA<br>U=Custom  | Description                                                   |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq        | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|---------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|-------------------------|----------|--------------------|---------|--------------|
|                  | Part Number                                                   | Serial Number |                     |             |                 |     |                         |          |                    |         | Approx Price |
| Logbook Position | HW                                                            | SW            |                     |             |                 |     |                         |          |                    |         | Manufacturer |
|                  | MM Ref                                                        |               |                     |             |                 |     |                         |          |                    |         | Date Type    |
|                  | Ops Number(s)                                                 |               |                     |             |                 |     |                         |          |                    |         |              |
| 341210           | AIR Data Probe (No. 3) - Functional Check                     |               | HRS                 |             | 3033.8          |     |                         | 12.3     |                    |         | 0            |
|                  |                                                               |               | AFL                 |             | 1112            |     | 5                       |          | 0                  |         |              |
|                  |                                                               |               | MOS                 |             | 125             |     | 11 Dec 2015             |          |                    |         |              |
|                  |                                                               |               | MSC                 |             |                 | O/C |                         |          |                    |         |              |
| 341211           | AIR Data Probe (Standby) - Functional Check                   |               | HRS                 |             | 3046.1          |     |                         | 0        |                    |         | 0            |
|                  |                                                               |               | AFL                 |             | 1117            |     | 0                       |          | 0                  |         |              |
|                  |                                                               |               | MOS                 |             | 128.6           |     | 24 Aug 2015             |          | 0                  |         |              |
|                  |                                                               |               | MSC                 |             |                 | O/C |                         |          |                    |         |              |
| 341212           | Digital AIR Data Computing System - Functional Test           |               | HRS                 |             | 3033.8          |     |                         | 12.3     |                    |         | 0            |
|                  |                                                               |               | AFL                 |             | 1112            |     | 5                       |          | 0                  |         |              |
|                  |                                                               |               | MOS                 |             | 125             |     | 11 Dec 2015             |          |                    |         |              |
|                  |                                                               |               | MSC                 |             |                 | O/C |                         |          |                    |         |              |
| 341213           | AIR Data System (No. 1) - Operational Check                   |               | HRS                 |             | 3046.1          |     |                         | 0        |                    |         | 0            |
|                  |                                                               |               | AFL                 |             | 1117            |     | 0                       |          | 0                  |         |              |
|                  |                                                               |               | MOS                 |             | 128.6           |     | 24 Aug 2015             |          | 0                  |         |              |
|                  |                                                               |               | MSC                 |             |                 | O/C |                         |          |                    |         |              |
| 341214           | AIR Data System (No. 2) - Operational Check                   |               | HRS                 |             | 3046.1          |     |                         | 0        |                    |         | 0            |
|                  |                                                               |               | AFL                 |             | 1117            |     | 0                       |          | 0                  |         |              |
|                  |                                                               |               | MOS                 |             | 128.6           |     | 24 Aug 2015             |          | 0                  |         |              |
|                  |                                                               |               | MSC                 |             |                 | O/C |                         |          |                    |         |              |
| 341215           | AIR Data System (No. 3) - Operational Check                   |               | HRS                 |             | 3046.1          |     |                         | 0        |                    |         | 0            |
|                  |                                                               |               | AFL                 |             | 1117            |     | 0                       |          | 0                  |         |              |
|                  |                                                               |               | MOS                 |             | 128.6           |     | 24 Aug 2015             |          | 0                  |         |              |
|                  |                                                               |               | MSC                 |             |                 | O/C |                         |          |                    |         |              |
| 341216           | AIR Data System (Standby) - Operational Check                 |               | HRS                 |             | 3046.1          |     |                         | 0        |                    |         | 0            |
|                  |                                                               |               | AFL                 |             | 1117            |     | 0                       |          | 0                  |         |              |
|                  |                                                               |               | MOS                 |             | 128.6           |     | 24 Aug 2015             |          | 0                  |         |              |
|                  |                                                               |               | MSC                 |             |                 | O/C |                         |          |                    |         |              |
| 341300           | AIR Data System (No. 1 - Left Upper) - Functional / Leak Test |               | HRS                 |             | 137             |     |                         | 2909.1   |                    |         | 0            |
|                  |                                                               |               | AFL                 |             | 52              |     | 1065                    |          | 0                  |         |              |
|                  |                                                               |               | MOS                 |             | 5.1             | 24  | 08 Dec 2025 31 Dec 2027 |          |                    |         |              |
|                  |                                                               |               | [End Of Month Item] |             |                 |     |                         |          |                    |         |              |
| Airframe         | 052025                                                        |               |                     |             |                 |     |                         |          |                    |         |              |



| ATA<br>U=Custom  | Description                                                                    |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|--------------------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                    | Serial Number |                     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                             | SW            |                     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                         |               |                     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                                  |               |                     |             |                 |     |                  |             |                    |         |              |
| 341301           | AIR Data System (No. 2 - Right Upper) - Functional / Leak Test                 |               | HRS                 |             | 137             |     |                  | 2909.1      |                    |         | 0            |
|                  |                                                                                |               | AFL                 |             | 52              |     |                  | 1065        |                    |         | 0            |
|                  |                                                                                |               | MOS                 |             | 5.1             |     | 24               | 08 Dec 2025 | 31 Dec 2027        |         |              |
|                  |                                                                                |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Airframe         |                                                                                | 052025        |                     |             |                 |     |                  |             |                    |         |              |
| 341302           | AIR Data System (No. 3 - Left Lower) - Functional / Leak Test                  |               | HRS                 |             | 137             |     |                  | 2909.1      |                    |         | 0            |
|                  |                                                                                |               | AFL                 |             | 52              |     |                  | 1065        |                    |         | 0            |
|                  |                                                                                |               | MOS                 |             | 5.1             |     | 24               | 08 Dec 2025 | 31 Dec 2027        |         |              |
|                  |                                                                                |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Airframe         |                                                                                | 052025        |                     |             |                 |     |                  |             |                    |         |              |
| 341303           | AIR Data System (No. 4 / Standby - Right Lower) - Functional / Leak Test       |               | HRS                 |             | 137             |     |                  | 2909.1      |                    |         | 0            |
|                  |                                                                                |               | AFL                 |             | 52              |     |                  | 1065        |                    |         | 0            |
|                  |                                                                                |               | MOS                 |             | 5.1             |     | 24               | 08 Dec 2025 | 31 Dec 2027        |         |              |
|                  |                                                                                |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Airframe         |                                                                                | 052025        |                     |             |                 |     |                  |             |                    |         |              |
| 341305           | AIR Data Probe - Cleaning                                                      |               | HRS                 |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                |               | AFL                 |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                |               | MOS                 |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                |               |                     |             |                 |     |                  |             |                    |         |              |
| 341306           | AIR Data Probe - Inspection Check                                              |               | HRS                 |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  |                                                                                |               | AFL                 |             | 315             |     |                  | 802         |                    |         | 0            |
|                  |                                                                                |               | MOS                 |             | 29.2            |     |                  | 06 Dec 2023 |                    |         |              |
|                  |                                                                                |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                |               |                     |             |                 |     |                  |             |                    |         |              |
| 341311           | Multi-Function Probe / AIR Data Computer (No. 1 - Left Upper) - Certification  |               | HRS                 |             | 137             |     |                  | 2909.1      |                    |         | 0            |
|                  |                                                                                |               | AFL                 |             | 52              |     |                  | 1065        |                    |         | 0            |
|                  |                                                                                |               | MOS                 |             | 5.1             |     | 24               | 08 Dec 2025 | 31 Dec 2027        |         |              |
|                  |                                                                                |               | [End Of Month Item] |             |                 |     |                  |             |                    |         | CALIBRATION  |
| Airframe         |                                                                                | 052025        |                     |             |                 |     |                  |             |                    |         |              |
| 341312           | Multi-Function Probe / AIR Data Computer (No. 2 - Right Upper) - Certification |               | HRS                 |             | 137             |     |                  | 2909.1      |                    |         | 0            |
|                  |                                                                                |               | AFL                 |             | 52              |     |                  | 1065        |                    |         | 0            |
|                  |                                                                                |               | MOS                 |             | 5.1             |     | 24               | 08 Dec 2025 | 31 Dec 2027        |         |              |
|                  |                                                                                |               | [End Of Month Item] |             |                 |     |                  |             |                    |         | CALIBRATION  |
| Airframe         |                                                                                | 052025        |                     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                              |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                                                              | Serial Number |                     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                                                       | SW            |                     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                                                   |               |                     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                                                            |               |                     |             |                 |     |                  |             |                     |         |              |
| 341313           | Multi-Function Probe / AIR Data Computer (No. 3 - Left Lower) - Certification            |               | HRS                 |             | 137             |     |                  | 2909.1      |                     |         | 0            |
|                  |                                                                                          |               | AFL                 |             | 52              |     |                  | 1065        |                     |         | 0            |
|                  |                                                                                          |               | MOS                 |             | 5.1             |     | 24               | 08 Dec 2025 | 31 Dec 2027         |         |              |
|                  |                                                                                          |               | [End Of Month Item] |             |                 |     |                  |             |                     |         | CALIBRATION  |
| Airframe         |                                                                                          | 052025        |                     |             |                 |     |                  |             |                     |         |              |
| 341314           | Multi-Function Probe / AIR Data Computer (No. 4 / Standby - Right Lower) - Certification |               | HRS                 |             | 137             |     |                  | 2909.1      |                     |         | 0            |
|                  |                                                                                          |               | AFL                 |             | 52              |     |                  | 1065        |                     |         | 0            |
|                  |                                                                                          |               | MOS                 |             | 5.1             |     | 24               | 08 Dec 2025 | 31 Dec 2027         |         |              |
|                  |                                                                                          |               | [End Of Month Item] |             |                 |     |                  |             |                     |         | CALIBRATION  |
| Airframe         |                                                                                          | 052025        |                     |             |                 |     |                  |             |                     |         |              |
| 341315           | AIR Data System - Leak Check                                                             |               | HRS                 |             | 137             |     |                  | 2909.1      |                     |         | 0            |
|                  |                                                                                          |               | AFL                 |             | 52              |     |                  | 1065        |                     |         | 0            |
|                  |                                                                                          |               | MOS                 |             | 5.1             |     |                  | 08 Dec 2025 |                     |         |              |
|                  |                                                                                          |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                          |               |                     |             |                 |     |                  |             |                     |         |              |
| 341316           | AIR Data System - Altitude Accuracy Check                                                |               | HRS                 |             | 137             |     |                  | 2909.1      |                     |         | 0            |
|                  |                                                                                          |               | AFL                 |             | 52              |     |                  | 1065        |                     |         | 0            |
|                  |                                                                                          |               | MOS                 |             | 5.1             |     |                  | 08 Dec 2025 |                     |         |              |
|                  |                                                                                          |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                          |               |                     |             |                 |     |                  |             |                     |         |              |
| 341317           | AIR Data System - Probe Heat Verification Test                                           |               | HRS                 |             | 137             |     |                  | 2909.1      |                     |         | 0            |
|                  |                                                                                          |               | AFL                 |             | 52              |     |                  | 1065        |                     |         | 0            |
|                  |                                                                                          |               | MOS                 |             | 5.1             |     |                  | 08 Dec 2025 |                     |         |              |
|                  |                                                                                          |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                          |               |                     |             |                 |     |                  |             |                     |         |              |
| 341318           | AIR Data System - Transponder Interface Test                                             |               | HRS                 |             | 137             |     |                  | 2909.1      |                     |         | 0            |
|                  |                                                                                          |               | AFL                 |             | 52              |     |                  | 1065        |                     |         | 0            |
|                  |                                                                                          |               | MOS                 |             | 5.1             |     |                  | 08 Dec 2025 |                     |         |              |
|                  |                                                                                          |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                          |               |                     |             |                 |     |                  |             |                     |         |              |
| 341319           | Multi-Function Probe / AIR Data Computer - Interface Validation Test                     |               | HRS                 |             | 730.5           |     |                  | 2315.6      |                     |         | 0            |
|                  |                                                                                          |               | AFL                 |             | 315             |     |                  | 802         |                     |         | 0            |
|                  |                                                                                          |               | MOS                 |             | 29.2            |     |                  | 06 Dec 2023 |                     |         |              |
|                  |                                                                                          |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                          |               |                     |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom  | Description                                                                                             |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|---------------------------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                                             | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                                                      | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                                                  |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| 341321           | Multi-Function Probe / AIR Data Computer - Heater Power<br>Interface Validation Test                    |               | HRS |             | 137             |     |                  | 2909.1      |                    |         | 0            |
|                  |                                                                                                         |               | AFL |             | 52              |     |                  | 1065        |                    |         | 0            |
|                  |                                                                                                         |               | MOS |             | 5.1             |     |                  | 08 Dec 2025 |                    |         |              |
|                  |                                                                                                         |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                                         |               |     |             |                 |     |                  |             |                    |         |              |
| 341400           | Total AIR Temperature Probe (Left) - Removal /<br>Installation<br>0102LV1DF                             |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                         |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                         |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                                         |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                                         |               |     |             |                 |     |                  |             |                    |         |              |
| 341401           | Total AIR Temperature Probe (Right) - Removal /<br>Installation<br>0102LV1DF                            |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                         |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                         |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                                         |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                                         |               |     |             |                 |     |                  |             |                    |         |              |
| 341402           | Total AIR Temperature Probe / Cabin Pressure Relief AIR<br>Valve - Removal / Installation<br>320154-4-1 |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                         |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                         |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                                         |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                                         |               |     |             |                 |     |                  |             |                    |         |              |
| 341410           | Total AIR Temperature Probe - Operational Check                                                         |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  |                                                                                                         |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  |                                                                                                         |               | MOS |             | 125             |     |                  | 11 Dec 2015 |                    |         |              |
|                  |                                                                                                         |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                                         |               |     |             |                 |     |                  |             |                    |         |              |
| 341412           | Total AIR Temperature Probe - Cleaning                                                                  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                         |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                         |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                                         |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                                         |               |     |             |                 |     |                  |             |                    |         |              |
| 341413           | Total AIR Temperature Probe - Inspection Check                                                          |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                         |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                         |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                                         |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                                         |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                           |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|---------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                           | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                                    | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                                |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                                         |               |     |             |                 |     |                  |             |                    |         |              |
| 342300           | Attitude Heading Reference Unit (No. 1) - Removal / Installation                      |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                       |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | HG2205AB02                                                                            | 56083114      | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | -                                                                                     |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| 342301           | Attitude Heading Reference Unit (No. 2) - Removal / Installation                      |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                       |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | HG2205AB02                                                                            | 56083374      | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | -                                                                                     |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| 342302           | Attitude Heading Reference Unit Configuration Module (No. 1) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                       |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 071-00188-0101                                                                        | 4053          | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                       |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| 342303           | Attitude Heading Reference Unit Configuration Module (No. 2) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                       |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 071-00188-0101                                                                        | 4062          | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                       |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| 342308           | Attitude Heading Reference Unit Tray (No. 1) - Removal / Installation                 |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                       |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | WG2005AB02                                                                            | 0488          | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                       |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| 342309           | Attitude Heading Reference Unit Tray (No. 2) - Removal / Installation                 |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                       |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | WG2005AB02                                                                            | 0489          | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                       |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| 342312           | Attitude Heading Reference System - Operational Check                                 |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                       |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                       |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                       |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                       |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                        |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                        | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                 | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                             |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                      |               |     |             |                 |     |                  |             |                    |         |              |
| 342314           | Attitude Heading Reference Unit - Tray Alignment   |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                    |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                    |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                           |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 342600           | HUD li Overhead Unit - Removal / Installation      |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 1500-3070-001                                      | 45736         | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                    |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                           |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 342601           | HUD li Combiner Assembly - Removal / Installation  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 1500-3080-601                                      | 45854         | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                    |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                           |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 342602           | HUD li Computer - Removal / Installation           |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 1500-3060-001                                      | 46184         | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                    |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                           |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 342603           | HUD li Personality Module - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 822-1424-001                                       | 45C2L9        | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                    |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                           |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 342608           | HUD li Overhead Unit Lens - Cleaning               |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                    |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                    |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                           |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 342609           | HUD li Combiner Assembly - Cleaning                |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                    |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                    |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                           |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 342610           | HUD li System - Operational Check                  |               | HRS |             | 3024.9          |     |                  | 21.2        |                    |         | 0            |
|                  |                                                    |               | AFL |             | 1110            |     |                  | 7           |                    |         | 0            |
|                  |                                                    |               | MOS |             | 123.5           |     |                  | 26 Jan 2016 |                    |         |              |
|                  | Airframe                                           |               | MSC |             |                 |     | O/C              |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                         | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                     |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                              |               |     |             |                 |     |                  |             |                    |         |              |
| 342611           | HUD li System - Software Check                                             |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                            |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                            |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                                   |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 342612           | HUD li System - Rigging Adjustment                                         |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                            |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                            |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                                   |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 342700           | Standby Multi-Function Controller Unit (No. 1) - Removal / Installation    |               | HRS | TSN:2252.38 | 793.7           |     |                  | 2252.4      |                    |         | 0            |
|                  |                                                                            |               | AFL | TSN:778     | 339             |     |                  | 778         |                    |         | 0            |
|                  | G7284-03                                                                   | 412           | MOS | TSN:95      | 33.4            |     |                  | 29 Jul 2023 |                    |         |              |
|                  | Airframe                                                                   |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 342701           | Standby Multi-Function Controller Unit (No. 2) - Removal / Installation    |               | HRS |             | 318.6           |     |                  | 2727.5      |                    |         | 0            |
|                  |                                                                            |               | AFL |             | 119             |     |                  | 998         |                    |         | 0            |
|                  | G7284-03                                                                   | 43504         | MOS |             | 9.5             |     |                  | 25 Jul 2025 |                    |         |              |
|                  | Airframe                                                                   |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 342704           | Standby Multi-Function Controller - Operational Check                      |               | HRS |             | 318.6           |     |                  | 2727.5      |                    |         | 0            |
|                  |                                                                            |               | AFL |             | 119             |     |                  | 998         |                    |         | 0            |
|                  |                                                                            |               | MOS |             | 9.5             |     |                  | 25 Jul 2025 |                    |         |              |
|                  | Airframe                                                                   |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 342710           | Standby Multi-Function Controller / Magnetometer - Compensation Adjustment |               | HRS |             | 1241.9          |     |                  | 1804.2      |                    |         | 0            |
|                  |                                                                            |               | AFL |             | 497             |     |                  | 620         |                    |         | 0            |
|                  |                                                                            |               | MOS |             | 49.3            |     |                  | 01 Apr 2022 |                    |         |              |
|                  | Airframe                                                                   |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 342712           | Standby Multi-Function Controller / Magnetometer - Calibration Check       |               | HRS |             | 1241.9          |     |                  | 1804.2      |                    |         | 0            |
|                  |                                                                            |               | AFL |             | 497             |     |                  | 620         |                    |         | 0            |
|                  |                                                                            |               | MOS |             | 49.3            |     |                  | 01 Apr 2022 |                    |         |              |
|                  | Airframe                                                                   |               | MSC |             |                 |     | O/C              |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                                 |               | UOM            | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|---------------------------------------------------------------------------------------------|---------------|----------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                                 | Serial Number |                |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                                          | SW            |                |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                                      |               |                |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                                               |               |                |             |                 |     |                  |             |                    |         |              |
| 342718           | Switch Panel Unit - Operational Check                                                       |               | HRS            |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                             |               | AFL            |             | 1117            |     |                  | 0           |                    | 0       |              |
|                  |                                                                                             |               | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                             |               | MSC            |             |                 |     | O/C              |             |                    |         |              |
| 342800           | Magnetometer (160A7) - Removal / Installation<br>065-00189-0101 KMG7010-2138                |               | HRS            |             | 1241.9          |     |                  | 1804.2      |                    |         | 0            |
|                  |                                                                                             |               | AFL            |             | 497             |     |                  | 620         |                    | 0       |              |
|                  |                                                                                             |               | MOS            |             | 49.3            |     |                  | 01 Apr 2022 |                    |         |              |
|                  |                                                                                             |               | MSC            |             |                 |     | O/C              |             |                    |         |              |
| 342801           | Magnetometer (160A8) - Removal / Installation<br>065-00189-0101 KMG7010-3977                |               | HRS            |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                             |               | AFL            |             | 1117            |     |                  | 0           |                    | 0       |              |
|                  |                                                                                             |               | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                             |               | MSC            |             |                 |     | O/C              |             |                    |         |              |
| 342900           | Enhanced Vision System li Infrared Camera - Removal /<br>Installation<br>58534-101 1740 005 |               | HRS            |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                             |               | AFL            |             | 1117            |     |                  | 0           |                    | 0       |              |
|                  |                                                                                             |               | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                             |               | MSC            |             |                 |     | O/C              |             |                    |         |              |
| 342901           | Enhanced Vision System li Processor - Removal /<br>Installation<br>48539-101 1727           |               | HRS            | TSN:21.2    | 3024.9          |     |                  | 21.2        |                    |         | 0            |
|                  |                                                                                             |               | AFL            | TSN:7       | 1110            |     |                  | 7           |                    | 0       |              |
|                  |                                                                                             |               | MOS            | TSN:5       | 123.5           |     |                  | 25 Jan 2016 |                    |         |              |
|                  |                                                                                             |               | MSC            |             |                 |     | O/C              |             |                    |         |              |
| 342902           | Enhanced Vision System li Window Assembly - Removal /<br>Installation<br>50889-101 310      |               | HRS            |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                             |               | AFL            |             | 1117            |     |                  | 0           |                    | 0       |              |
|                  |                                                                                             |               | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                             |               | MSC            |             |                 |     | O/C              |             |                    |         |              |
| 342907           | Enhanced Vision System li Sapphire Window Assembly<br>(Return to Vendor) - Functional Test  |               | HRS            |             | 3046.1          |     | 10000            | 0           | 10000              | 10050   | 0            |
|                  |                                                                                             |               | AFL            |             | 1117            |     |                  | 0           |                    | 0       |              |
|                  |                                                                                             |               | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                             |               | [HRS: +50/-50] |             |                 |     |                  |             |                    |         |              |
| Airframe         | 052027                                                                                      |               |                |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                                                                  |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                                                                  | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                                                                           | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                                                                       |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| 342908           | Enhanced Vision System Ii - Functional Check                                                                                 |               | HRS |             | 3024.9          |     |                  | 21.2        |                    |         | 0            |
|                  |                                                                                                                              |               | AFL |             | 1110            |     |                  | 7           |                    | 0       |              |
|                  |                                                                                                                              |               | MOS |             | 123.5           |     |                  | 26 Jan 2016 |                    |         |              |
|                  |                                                                                                                              |               | MSC |             |                 | O/C |                  |             |                    |         |              |
| Airframe         |                                                                                                                              |               |     |             |                 |     |                  |             |                    |         |              |
| 342909           | Enhanced Vision System Infrared Camera Lens / Sapphire Window - Cleaning                                                     |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                                              |               | AFL |             | 1117            |     |                  | 0           |                    | 0       |              |
|                  |                                                                                                                              |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                                                              |               | MSC |             |                 | O/C |                  |             |                    |         |              |
| Airframe         |                                                                                                                              |               |     |             |                 |     |                  |             |                    |         |              |
| 342910           | Enhanced Vision System Ii Windshield Heat Switch - Removal / Installation<br>318VL23AAAMEY00                      SN-UNKNOWN |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                                              |               | AFL |             | 1117            |     |                  | 0           |                    | 0       |              |
|                  |                                                                                                                              |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                                                              |               | MSC |             |                 | O/C |                  |             |                    |         |              |
| Airframe         |                                                                                                                              |               |     |             |                 |     |                  |             |                    |         |              |
| 342912           | Enhanced Vision System Ii Manual Window Heat - Operational Check                                                             |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                                              |               | AFL |             | 1117            |     |                  | 0           |                    | 0       |              |
|                  |                                                                                                                              |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                                                              |               | MSC |             |                 | O/C |                  |             |                    |         |              |
| Airframe         |                                                                                                                              |               |     |             |                 |     |                  |             |                    |         |              |
| 344200           | Inertial Reference Unit (No. 1) - Removal / Installation<br>HG2100BB02                      56083543                         |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                                              |               | AFL |             | 1117            |     |                  | 0           |                    | 0       |              |
|                  |                                                                                                                              |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                                                              |               | MSC |             |                 | O/C |                  |             |                    |         |              |
| Airframe         |                                                                                                                              |               |     |             |                 |     |                  |             |                    |         |              |
| 344201           | Inertial Reference Unit (No. 2) - Removal / Installation<br>HG2100BB02                      56083658                         |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                                              |               | AFL |             | 1117            |     |                  | 0           |                    | 0       |              |
|                  |                                                                                                                              |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                                                              |               | MSC |             |                 | O/C |                  |             |                    |         |              |
| Airframe         |                                                                                                                              |               |     |             |                 |     |                  |             |                    |         |              |
| 344202           | Inertial Reference Unit (No. 3) - Removal / Installation<br>HG2100BB02                      56083604                         |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                                              |               | AFL |             | 1117            |     |                  | 0           |                    | 0       |              |
|                  |                                                                                                                              |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                                                              |               | MSC |             |                 | O/C |                  |             |                    |         |              |
| Airframe         |                                                                                                                              |               |     |             |                 |     |                  |             |                    |         |              |



| ATA<br>U=Custom  | Description                                                                   |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|-------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                                                   | Serial Number |     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                                            | SW            |     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                                        |               |     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                                                 |               |     |             |                 |     |                  |             |                     |         |              |
| 344211           | Inertial Reference System Personality Module (No. 1) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                               |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 7519272-901                                                                   | 40473870      | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                               |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                               |               |     |             |                 |     |                  |             |                     |         |              |
| 344212           | Inertial Reference System Personality Module (No. 2) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                               |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 7519272-901                                                                   | 40473871      | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                               |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                               |               |     |             |                 |     |                  |             |                     |         |              |
| 344213           | Inertial Reference System Personality Module (No. 3) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                               |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 7519272-901                                                                   | 40473872      | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                               |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                               |               |     |             |                 |     |                  |             |                     |         |              |
| 344214           | Inertial Reference Unit (No. 1) Mounting Tray - Removal / Installation        |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                               |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | WG2001AA03                                                                    | 3928          | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                               |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                               |               |     |             |                 |     |                  |             |                     |         |              |
| 344215           | Inertial Reference Unit (No. 2) Mounting Tray - Removal / Installation        |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                               |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | WG2001AA03                                                                    | 3933          | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                               |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                               |               |     |             |                 |     |                  |             |                     |         |              |
| 344216           | Inertial Reference Unit (No. 3) Mounting Tray - Removal / Installation        |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                               |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | WG2001AA03                                                                    | 3946          | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                               |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                               |               |     |             |                 |     |                  |             |                     |         |              |
| 344220           | Radio Altimeter R/T Unit (No. 1) - Removal / Installation                     |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  | 066-01153-0101                                                                | KRA405B-16504 | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  |                                                                               |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                               |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                               |               |     |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom  | Description                                                       |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|-------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                                       | Serial Number |     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                                | SW            |     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                            |               |     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                                     |               |     |             |                 |     |                  |             |                     |         |              |
| 344221           | Radio Altimeter R/T Unit (No. 2) - Removal / Installation         |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  | 066-01153-0101                                                    | KRA405B-16431 | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  |                                                                   |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  | Airframe                                                          |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| 344224           | Inertial Reference System - Operation Check                       |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                   |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  |                                                                   |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  | Airframe                                                          |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| 344227           | Inertial Reference Unit Tray (No. 1) - Alignment                  |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                   |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  |                                                                   |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  | Airframe                                                          |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| 344228           | Inertial Reference Unit Tray (No. 2) - Alignment                  |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                   |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  |                                                                   |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  | Airframe                                                          |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| 344229           | Inertial Reference Unit Tray (No. 3) - Alignment                  |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                   |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  |                                                                   |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  | Airframe                                                          |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| 344234           | Inertial Reference System MODE Select Panel - Operational Check   |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                   |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  |                                                                   |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  | Airframe                                                          |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| 344300           | Radio Altimeter (No. 1) Transmit Antenna - Removal / Installation |               | HRS | TSN:1745.4  | 1300.7          |     |                  | 1745.4      |                     |         | 0            |
|                  |                                                                   |               | AFL | TSN:610     | 507             |     |                  | 610         |                     |         | 0            |
|                  | DM PN19-2-1                                                       | 8843          | MOS | TSN:78      | 51.3            |     |                  | 01 Feb 2022 |                     |         |              |
|                  | Airframe                                                          |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| 344301           | Radio Altimeter (No. 2) Transmit Antenna - Removal / Installation |               | HRS | TSN:1745.4  | 1300.7          |     |                  | 1745.4      |                     |         | 0            |
|                  |                                                                   |               | AFL | TSN:610     | 507             |     |                  | 610         |                     |         | 0            |
|                  | DM PN19-2-1                                                       | 8881          | MOS | TSN:78      | 51.3            |     |                  | 02 Feb 2022 |                     |         |              |
|                  | Airframe                                                          |               | MSC |             |                 |     | O/C              |             |                     |         |              |

| ATA<br>U=Custom  | Description                                                           |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-----------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                           | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                    | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                         |               |     |             |                 |     |                  |             |                    |         |              |
| 344302           | Radio Altimeter Configuration Module (No. 1) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                       |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 071-00097-0100                                                        | CM2000-30605  | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | -                                                                     |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| 344303           | Radio Altimeter Configuration Module (No. 2) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                       |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 071-00097-0100                                                        | CM2000-30635  | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | -                                                                     |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| 344304           | Radio Altimeter (No. 1) Receive Antenna - Removal / Installation      |               | HRS | TSN:1745.4  | 1300.7          |     |                  | 1745.4      |                    |         | 0            |
|                  |                                                                       |               | AFL | TSN:610     | 507             |     |                  | 610         |                    |         | 0            |
|                  | DM PN19-2-1                                                           | 8882          | MOS | TSN:78      | 51.3            |     |                  | 01 Feb 2022 |                    |         |              |
|                  |                                                                       |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| 344305           | Radio Altimeter (No. 2) Receive Antenna - Removal / Installation      |               | HRS | TSN:1745.4  | 1300.7          |     |                  | 1745.4      |                    |         | 0            |
|                  |                                                                       |               | AFL | TSN:610     | 507             |     |                  | 610         |                    |         | 0            |
|                  | DM PN19-2-1                                                           | 8883          | MOS | TSN:78      | 51.3            |     |                  | 02 Feb 2022 |                    |         |              |
|                  |                                                                       |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| 344316           | Radio Altimeter System - Operational Check                            |               | HRS |             | 137             |     |                  | 2909.1      |                    |         | 0            |
|                  |                                                                       |               | AFL |             | 52              |     |                  | 1065        |                    |         | 0            |
|                  |                                                                       |               | MOS |             | 5.3             |     |                  | 01 Dec 2025 |                    |         |              |
|                  |                                                                       |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| 344318           | Radio Altimeter R/T Unit - Zero Altitude Adjustment                   |               | HRS |             | 137             |     |                  | 2909.1      |                    |         | 0            |
|                  |                                                                       |               | AFL |             | 52              |     |                  | 1065        |                    |         | 0            |
|                  |                                                                       |               | MOS |             | 5.2             |     |                  | 05 Dec 2025 |                    |         |              |
|                  |                                                                       |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| 344320           | Radio Altimeter Configuration Module - Configuration Check            |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                       |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                       |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                       |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                       |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                              |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                              | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                       | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                   |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                            |               |     |             |                 |     |                  |             |                    |         |              |
| 344400           | Weather Radar Flatplate Antenna - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 930-4241-001                                             | 287           | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                          |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 344401           | Weather Radar Processor - Removal / Installation         |               | HRS | TSN:2483.66 | 562.4           |     |                  | 2483.7      |                    |         | 0            |
|                  | 930-1003-0013                                            | RP03411       | AFL | TSN:900     | 217             |     |                  | 900         |                    |         | 0            |
|                  |                                                          |               | MOS | TSN:112     | 17.2            |     |                  | 06 Dec 2024 |                    |         |              |
|                  | Airframe                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 344404           | Weather Radar Antenna Drive - Removal / Installation     |               | HRS |             | 2937.3          |     |                  | 108.8       |                    |         | 0            |
|                  | 930-3002-001                                             | DA1S01228     | AFL |             | 1089            |     |                  | 28          |                    |         | 0            |
|                  |                                                          |               | MOS |             | 118.4           |     |                  | 29 Jun 2016 |                    |         |              |
|                  | Airframe                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 344406           | Weather Radar System - Operational Check                 |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                          |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                          |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 344407           | Weather Radar R/T - Removal / Installation               |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 930-2000-001                                             | TR03880       | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                          |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 344500           | Processor, Lightning Sensor - Removal / Installation     |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  | 7011822-904                                              | 15053033      | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  |                                                          |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | HONEYWELL    |
|                  | Airframe                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 344502           | Antenna, Lightning Sensor - Removal / Installation       |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  | 7014062-901                                              | 14081998      | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  |                                                          |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | HONEYWELL    |
|                  | Airframe                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 344504           | Controller, Lightning Sensor - Removal / Installation    |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  | 7012738-905                                              | 15021219      | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  |                                                          |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | HONEYWELL    |
|                  | Airframe                                                 |               | MSC |             |                 |     | O/C              |             |                    |         |              |

| ATA<br>U=Custom  | Description                                   |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|-----------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                   | Serial Number |     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                            | SW            |     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                        |               |     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                 |               |     |             |                 |     |                  |             |                     |         |              |
| 344600           | Egpws Module (No. 1) - Removal / Installation |               | HRS |             | 562.4           |     |                  | 2483.7      |                     |         | 0            |
|                  | 7034056-1903                                  | 24068387      | AFL |             | 217             |     |                  | 900         |                     |         | 0            |
|                  |                                               |               | MOS |             | 16.8            |     |                  | 16 Dec 2024 |                     |         |              |
|                  | Airframe                                      |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| 344601           | Egpws Module (No. 2) - Removal / Installation |               | HRS |             | 562.4           |     |                  | 2483.7      |                     |         | 0            |
|                  | 7027208-1903                                  | 2209GA85      | AFL |             | 217             |     |                  | 900         |                     |         | 0            |
|                  |                                               |               | MOS |             | 16.8            |     |                  | 16 Dec 2024 |                     |         |              |
|                  | Airframe                                      |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| 344604           | Egpws - Return to Service Test                |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                               |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  |                                               |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  | Airframe                                      |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| 344605           | Egpws - Operational Test                      |               | HRS |             | 562.4           |     |                  | 2483.7      |                     |         | 0            |
|                  |                                               |               | AFL |             | 217             |     |                  | 900         |                     |         | 0            |
|                  |                                               |               | MOS |             | 16.8            |     |                  | 16 Dec 2024 |                     |         |              |
|                  | Airframe                                      |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| 344625           | Egpwm Terrain Threat                          |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                               |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  |                                               |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  | Airframe                                      |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| 344700           | TCAS Computer - Removal / Installation        |               | HRS |             | 1385.2          |     |                  | 1660.9      |                     |         | 0            |
|                  | 9003500-55905                                 | TSE03715      | AFL |             | 524             |     |                  | 593         |                     |         | 0            |
|                  |                                               |               | MOS |             | 56.6            |     |                  | 24 Aug 2021 |                     |         |              |
|                  | Airframe                                      |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| 344701           | TCAS Antenna (Lower) - Removal / Installation |               | HRS | TSN:1745.4  | 1300.7          |     |                  | 1745.4      |                     |         | 0            |
|                  | DM NI50-9-2                                   | 18674         | AFL | TSN:610     | 507             |     |                  | 610         |                     |         | 0            |
|                  |                                               |               | MOS | TSN:77      | 51.7            |     |                  | 19 Jan 2022 |                     |         |              |
|                  | Airframe                                      |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| 344702           | TCAS Antenna (Upper) - Removal / Installation |               | HRS | TSN:1745.4  | 1300.7          |     |                  | 1745.4      |                     |         | 0            |
|                  | 7514060-902                                   | ANE46085      | AFL | TSN:610     | 507             |     |                  | 610         |                     |         | 0            |
|                  |                                               |               | MOS | TSN:78      | 51.3            |     |                  | 02 Feb 2022 |                     |         |              |
|                  | Airframe                                      |               | MSC |             |                 |     | O/C              |             |                     |         |              |

| ATA<br>U=Custom  | Description                                                                               |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-------------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                               | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                                        | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                                    |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 344706           | TCAS - Operational Check                                                                  |               | HRS |             | 1300.7          |     |                  | 1745.4      |                    |         | 0            |
|                  |                                                                                           |               | AFL |             | 507             |     |                  | 610         |                    |         | 0            |
|                  |                                                                                           |               | MOS |             | 51.3            |     |                  | 03 Feb 2022 |                    |         |              |
|                  |                                                                                           |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| 345200           | GPS Antenna (No. 1) - Removal / Installation                                              |               | HRS | TSN:1745.4  | 1300.7          |     |                  | 1745.4      |                    |         | 0            |
|                  | S67-1575-147                                                                              | 888-0484      | AFL | TSN:610     | 507             |     |                  | 610         |                    |         | 0            |
|                  |                                                                                           |               | MOS | TSN:77      | 51.5            |     |                  | 25 Jan 2022 |                    |         |              |
|                  |                                                                                           |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| 345201           | GPS Antenna (No. 2) - Removal / Installation                                              |               | HRS | TSN:1745.4  | 1300.7          |     |                  | 1745.4      |                    |         | 0            |
|                  | S67-1575-147                                                                              | 888-0485      | AFL | TSN:610     | 507             |     |                  | 610         |                    |         | 0            |
|                  |                                                                                           |               | MOS | TSN:77      | 51.5            |     |                  | 25 Jan 2022 |                    |         |              |
|                  |                                                                                           |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| 345300           | VOR / Localizer Antenna Bonding - Detailed Inspection                                     |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                           |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                           |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                           |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| 345304           | VOR / Localizer Antenna Coupler / Diplexer (Verticle Stabilizer) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | DM N4-17-4                                                                                | 9201          | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                           |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                           |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| 345305           | VOR / Localizer Antenna (Left) - Removal / Installation                                   |               | HRS |             | 465.2           |     |                  | 2580.9      |                    |         | 0            |
|                  | N4-17-1/AD                                                                                | 58410         | AFL |             | 177             |     |                  | 940         |                    |         | 0            |
|                  |                                                                                           |               | MOS | TSN:20      | 14.2            |     |                  | 06 Mar 2025 |                    |         |              |
|                  |                                                                                           |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| 345306           | VOR / Localizer Antenna (Right) - Removal / Installation                                  |               | HRS |             | 465.2           |     |                  | 2580.9      |                    |         | 0            |
|                  | N4-17-1/AD                                                                                | 38247         | AFL |             | 177             |     |                  | 940         |                    |         | 0            |
|                  |                                                                                           |               | MOS | TSN:8       | 14.2            |     |                  | 06 Mar 2025 |                    |         |              |
|                  |                                                                                           |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| 345307           | VOR / ILS / Data Link / GPS Module (No. 1) - Removal / Installation                       |               | HRS |             | 473             |     |                  | 2573.1      |                    |         | 0            |
|                  | 7026208-805                                                                               | 15040843      | AFL |             | 185             |     |                  | 932         |                    |         | 0            |
|                  |                                                                                           |               | MOS |             | 14.5            |     |                  | 25 Feb 2025 |                    |         |              |
|                  |                                                                                           |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                           |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                               |               | UOM            | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W                            | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|---------------------------------------------------------------------------|---------------|----------------|-------------|-----------------|-----|------------------|-------------------------------------|---------------------|---------|--------------|
|                  | Part Number                                                               | Serial Number |                |             |                 |     |                  |                                     |                     |         | Approx Price |
| Logbook Position | HW                                                                        | SW            |                |             |                 |     |                  |                                     |                     |         | Manufacturer |
|                  | MM Ref                                                                    |               |                |             |                 |     |                  |                                     |                     |         | Date Type    |
|                  | Ops Number(s)                                                             |               |                |             |                 |     |                  |                                     |                     |         |              |
| 345308           | VOR / ILS / Data Link / GPS Module (No. 2) - Removal / Installation       |               | HRS            |             | 465.2           |     |                  | 2580.9                              |                     |         | 0            |
|                  |                                                                           |               | AFL            |             | 177             |     |                  | 940                                 |                     |         | 0            |
|                  | 7026208-805                                                               | 20062362      | MOS            |             | 14.2            |     |                  | 06 Mar 2025                         |                     |         |              |
|                  |                                                                           |               | MSC            |             |                 |     | O/C              |                                     |                     |         |              |
| Airframe         |                                                                           |               |                |             |                 |     |                  |                                     |                     |         |              |
| 345309           | Glide Slope Antenna Diplexer - Removal / Installation                     |               | HRS            |             | 3046.1          |     |                  | 0                                   |                     |         | 0            |
|                  | SSPD-332-3                                                                |               | AFL            |             | 1117            |     |                  | 0                                   |                     |         | 0            |
|                  |                                                                           |               | MOS            |             | 128.6           |     |                  | 24 Aug 2015                         |                     |         |              |
|                  |                                                                           |               | MSC            |             |                 |     | O/C              |                                     |                     |         |              |
| Airframe         |                                                                           |               |                |             |                 |     |                  |                                     |                     |         |              |
| 345310           | Glide Slope Dual Antenna - Removal / Installation                         |               | HRS            |             | 3046.1          |     |                  | 0                                   |                     |         | 0            |
|                  | S41422-2                                                                  |               | AFL            |             | 1117            |     |                  | 0                                   |                     |         | 0            |
|                  |                                                                           |               | MOS            |             | 128.6           |     |                  | 24 Aug 2015                         |                     |         |              |
|                  |                                                                           |               | MSC            |             |                 |     | O/C              |                                     |                     |         |              |
| Airframe         |                                                                           |               |                |             |                 |     |                  |                                     |                     |         |              |
| 345313           | Glide Slope Antenna - Inspection                                          |               | HRS            |             | 3046.1          |     |                  | 0                                   |                     |         | 0            |
|                  |                                                                           |               | AFL            |             | 1117            |     |                  | 0                                   |                     |         | 0            |
|                  |                                                                           |               | MOS            |             | 128.6           |     |                  | 24 Aug 2015                         |                     |         |              |
|                  |                                                                           |               | MSC            |             |                 |     | O/C              |                                     |                     |         |              |
| Airframe         |                                                                           |               |                |             |                 |     |                  |                                     |                     |         |              |
| 345316           | VOR / ILS / Data Link / GPS - Functional Check                            |               | HRS            |             | 137             |     |                  | 2909.1                              |                     |         | 0            |
|                  |                                                                           |               | AFL            |             | 52              |     |                  | 1065                                |                     |         | 0            |
|                  |                                                                           |               | MOS            |             | 5.2             |     | 12               | 04 Dec 2025 04 Dec 2026 04 Jan 2027 |                     |         |              |
|                  |                                                                           |               | [MOS: +1m/-1m] |             |                 |     |                  |                                     |                     |         |              |
| Airframe         |                                                                           |               |                |             |                 |     |                  |                                     |                     |         |              |
| 345317           | VHF / VOR / ILS / Data Link / GPS Module - Return to Service Test         |               | HRS            |             | 3024.9          |     |                  | 21.2                                |                     |         | 0            |
|                  |                                                                           |               | AFL            |             | 1110            |     |                  | 7                                   |                     |         | 0            |
|                  |                                                                           |               | MOS            |             | 123.5           |     |                  | 26 Jan 2016                         |                     |         |              |
|                  |                                                                           |               | MSC            |             |                 |     | O/C              |                                     |                     |         |              |
| Airframe         |                                                                           |               |                |             |                 |     |                  |                                     |                     |         |              |
| 345320           | Marker Beacon Antenna Diplexer (Bottom Fuselage) - Removal / Installation |               | HRS            |             | 3046.1          |     |                  | 0                                   |                     |         | 0            |
|                  |                                                                           |               | AFL            |             | 1117            |     |                  | 0                                   |                     |         | 0            |
|                  | DMH21-1                                                                   | 52415         | MOS            |             | 128.6           |     |                  | 24 Aug 2015                         |                     |         |              |
|                  |                                                                           |               | MSC            |             |                 |     | O/C              |                                     |                     |         |              |
| Airframe         |                                                                           |               |                |             |                 |     |                  |                                     |                     |         |              |
| 345321           | Marker Beacon Antenna - Removal / Installation                            |               | HRS            | TSN:1745.4  | 1300.7          |     |                  | 1745.4                              |                     |         | 0            |
|                  | S35-2000-10                                                               |               | AFL            | TSN:610     | 507             |     |                  | 610                                 |                     |         | 0            |
|                  |                                                                           |               | MOS            | TSN:77      | 51.7            |     |                  | 19 Jan 2022                         |                     |         |              |
|                  |                                                                           |               | MSC            |             |                 |     | O/C              |                                     |                     |         |              |
| Airframe         |                                                                           |               |                |             |                 |     |                  |                                     |                     |         |              |

| ATA<br>U=Custom  | Description                                                                |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                                                | Serial Number |     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                                         | SW            |     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                                     |               |     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                                              |               |     |             |                 |     |                  |             |                     |         |              |
| 345324           | Marker Beacon Antenna Diplexer (Reer) - Removal / Installation             |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                            |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | SSPD-113-39                                                                | 4207          | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                            |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                            |               |     |             |                 |     |                  |             |                     |         |              |
| 345330           | Navigation / Communication Module - Removal / Installation                 |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                            |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 7026203-813                                                                | 15021201      | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                            |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                            |               |     |             |                 |     |                  |             |                     |         |              |
| 345331           | Navigation / Communication System - Functional Check                       |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                            |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  |                                                                            |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                            |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                            |               |     |             |                 |     |                  |             |                     |         |              |
| 345332           | VOR / Localizer Antenna Coupler / Diplexer (Reer) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                            |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | DMH21-1                                                                    | 53708         | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                            |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                            |               |     |             |                 |     |                  |             |                     |         |              |
| 345402           | ADF - Operational Check                                                    |               | HRS |             | 562.4           |     |                  | 2483.7      |                     |         | 0            |
|                  |                                                                            |               | AFL |             | 217             |     |                  | 900         |                     |         | 0            |
|                  |                                                                            |               | MOS |             | 16.8            |     |                  | 16 Dec 2024 |                     |         |              |
|                  |                                                                            |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                            |               |     |             |                 |     |                  |             |                     |         |              |
| 345403           | ADF Receiver - Return to Service Test                                      |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                            |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  |                                                                            |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                            |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                            |               |     |             |                 |     |                  |             |                     |         |              |
| 345406           | ADF Receiver - Removal / Installation                                      |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  | 7510114-855                                                                | 1504H828      | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  |                                                                            |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                            |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                            |               |     |             |                 |     |                  |             |                     |         |              |
| 345408           | ADF Antenna - Removal / Installation                                       |               | HRS | TSN:1745.4  | 1300.7          |     |                  | 1745.4      |                     |         | 0            |
|                  | 7510300-901                                                                | 1502N503      | AFL | TSN:610     | 507             |     |                  | 610         |                     |         | 0            |
|                  |                                                                            |               | MOS | TSN:77      | 51.5            |     |                  | 26 Jan 2022 |                     |         |              |
|                  |                                                                            |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                            |               |     |             |                 |     |                  |             |                     |         |              |



| ATA<br>U=Custom  | Description                                                          |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W                | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------------------|--------------------|---------|--------------|
|                  | Part Number                                                          | Serial Number |                     |             |                 |     |                  |                         |                    |         | Approx Price |
| Logbook Position | HW                                                                   | SW            |                     |             |                 |     |                  |                         |                    |         | Manufacturer |
|                  | MM Ref                                                               |               |                     |             |                 |     |                  |                         |                    |         | Date Type    |
|                  | Ops Number(s)                                                        |               |                     |             |                 |     |                  |                         |                    |         |              |
| 345500           | ATC MODE S Antenna (No. 1) Lower - Removal / Installation            |               | HRS                 | TSN:1745.4  | 1300.7          |     |                  | 1745.4                  |                    |         | 0            |
|                  |                                                                      |               | AFL                 | TSN:610     | 507             |     |                  | 610                     |                    |         | 0            |
|                  | DM NI50-9-2                                                          | 18675         | MOS                 | TSN:77      | 51.7            |     |                  | 19 Jan 2022             |                    |         |              |
|                  |                                                                      |               | MSC                 |             |                 |     | O/C              |                         |                    |         |              |
| Airframe         |                                                                      |               |                     |             |                 |     |                  |                         |                    |         |              |
| 345501           | ATC MODE S Antenna (No. 2) Lower - Removal / Installation            |               | HRS                 | TSN:1745.4  | 1300.7          |     |                  | 1745.4                  |                    |         | 0            |
|                  |                                                                      |               | AFL                 | TSN:610     | 507             |     |                  | 610                     |                    |         | 0            |
|                  | DM NI50-9-2                                                          | 18677         | MOS                 | TSN:77      | 51.7            |     |                  | 19 Jan 2022             |                    |         |              |
|                  |                                                                      |               | MSC                 |             |                 |     | O/C              |                         |                    |         |              |
| Airframe         |                                                                      |               |                     |             |                 |     |                  |                         |                    |         |              |
| 345502           | MODE S Diversity Transponder Module (No. 1) - Removal / Installation |               | HRS                 |             | 562.4           |     |                  | 2483.7                  |                    |         | 0            |
|                  |                                                                      |               | AFL                 |             | 217             |     |                  | 900                     |                    |         | 0            |
|                  | 7517402-970                                                          | 1811N414      | MOS                 |             | 16.8            |     |                  | 16 Dec 2024             |                    |         |              |
|                  |                                                                      |               | MSC                 |             |                 |     | O/C              |                         |                    |         |              |
| Airframe         |                                                                      |               |                     |             |                 |     |                  |                         |                    |         |              |
| 345503           | MODE S Diversity Transponder Module (No. 2) - Removal / Installation |               | HRS                 |             | 562.4           |     |                  | 2483.7                  |                    |         | 0            |
|                  |                                                                      |               | AFL                 |             | 217             |     |                  | 900                     |                    |         | 0            |
|                  | 7517402-970                                                          | 0604A969      | MOS                 |             | 16.8            |     |                  | 16 Dec 2024             |                    |         |              |
|                  |                                                                      |               | MSC                 |             |                 |     | O/C              |                         |                    |         |              |
| Airframe         |                                                                      |               |                     |             |                 |     |                  |                         |                    |         |              |
| 345504           | ATC MODE S Antenna (No. 1) Upper - Removal / Installation            |               | HRS                 | TSN:1745.4  | 1300.7          |     |                  | 1745.4                  |                    |         | 0            |
|                  |                                                                      |               | AFL                 | TSN:610     | 507             |     |                  | 610                     |                    |         | 0            |
|                  | DM NI50-9-2                                                          | 18209         | MOS                 | TSN:77      | 51.5            |     |                  | 25 Jan 2022             |                    |         |              |
|                  |                                                                      |               | MSC                 |             |                 |     | O/C              |                         |                    |         |              |
| Airframe         |                                                                      |               |                     |             |                 |     |                  |                         |                    |         |              |
| 345505           | ATC MODE S Antenna (No. 2) Upper - Removal / Installation            |               | HRS                 |             | 1300.7          |     |                  | 1745.4                  |                    |         | 0            |
|                  |                                                                      |               | AFL                 |             | 507             |     |                  | 610                     |                    |         | 0            |
|                  | DM NI50-9-2                                                          | 18544         | MOS                 |             | 51.5            |     |                  | 25 Jan 2022             |                    |         |              |
|                  |                                                                      |               | MSC                 |             |                 |     | O/C              |                         |                    |         |              |
| Airframe         |                                                                      |               |                     |             |                 |     |                  |                         |                    |         |              |
| 345512           | ATC (No. 1) - Operational Check                                      |               | HRS                 |             | 137             |     |                  | 2909.1                  |                    |         | 0            |
|                  |                                                                      |               | AFL                 |             | 52              |     |                  | 1065                    |                    |         | 0            |
|                  |                                                                      |               | MOS                 |             | 5.2             |     | 24               | 05 Dec 2025 31 Dec 2027 |                    |         |              |
|                  |                                                                      |               | [End Of Month Item] |             |                 |     |                  |                         |                    |         |              |
| Airframe         | 052025                                                               |               |                     |             |                 |     |                  |                         |                    |         |              |

| ATA<br>U=Custom  | Description                                                  |                     | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|--------------------------------------------------------------|---------------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                  | Serial Number       |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                           | SW                  |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                       |                     |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                |                     |     |             |                 |     |                  |             |                    |         |              |
| 345513           | ATC (No. 2) - Operational Check                              |                     | HRS |             | 137             |     |                  | 2909.1      |                    |         | 0            |
|                  |                                                              |                     | AFL |             | 52              |     |                  | 1065        |                    |         | 0            |
|                  |                                                              |                     | MOS |             | 5.2             |     | 24               | 05 Dec 2025 | 31 Dec 2027        |         |              |
| Airframe         |                                                              | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
|                  |                                                              | 052025              |     |             |                 |     |                  |             |                    |         |              |
| 345514           | MODE S Diversity Transponder Module - Return to Service Test |                     | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                              |                     | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                              |                     | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                              |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                              |                     |     |             |                 |     |                  |             |                    |         |              |
| 345600           | DME Antenna (No. 1) - Removal / Installation                 |                     | HRS | TSN:1745.4  | 1300.7          |     |                  | 1745.4      |                    |         | 0            |
|                  | DM NI50-9-2                                                  | 18671               | AFL | TSN:610     | 507             |     |                  | 610         |                    |         | 0            |
|                  |                                                              |                     | MOS | TSN:77      | 51.7            |     |                  | 19 Jan 2022 |                    |         |              |
|                  |                                                              |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                              |                     |     |             |                 |     |                  |             |                    |         |              |
| 345601           | DME Antenna (No. 2) - Removal / Installation                 |                     | HRS | TSN:1745.4  | 1300.7          |     |                  | 1745.4      |                    |         | 0            |
|                  | DM NI50-9-2                                                  | 18672               | AFL | TSN:610     | 507             |     |                  | 610         |                    |         | 0            |
|                  |                                                              |                     | MOS | TSN:77      | 51.7            |     |                  | 19 Jan 2022 |                    |         |              |
|                  |                                                              |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                              |                     |     |             |                 |     |                  |             |                    |         |              |
| 345602           | DME Module (No. 1) - Removal / Installation                  |                     | HRS | TSN:2483.7  | 562.4           |     |                  | 2483.7      |                    |         | 0            |
|                  | 7510184-855                                                  | 1504K944            | AFL | TSN:900     | 217             |     |                  | 900         |                    |         | 0            |
|                  |                                                              |                     | MOS | TSN:112     | 16.8            |     |                  | 16 Dec 2024 |                    |         |              |
|                  |                                                              |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                              |                     |     |             |                 |     |                  |             |                    |         |              |
| 345603           | DME Module (No. 2) - Removal / Installation                  |                     | HRS | TSN:2483.7  | 562.4           |     |                  | 2483.7      |                    |         | 0            |
|                  | 7510184-855                                                  | 1504K925            | AFL | TSN:900     | 217             |     |                  | 900         |                    |         | 0            |
|                  |                                                              |                     | MOS | TSN:112     | 16.8            |     |                  | 16 Dec 2024 |                    |         |              |
|                  |                                                              |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                              |                     |     |             |                 |     |                  |             |                    |         |              |
| 345608           | DME - Functional Check                                       |                     | HRS |             | 562.4           |     |                  | 2483.7      |                    |         | 0            |
|                  |                                                              |                     | AFL |             | 217             |     |                  | 900         |                    |         | 0            |
|                  |                                                              |                     | MOS |             | 16.8            |     |                  | 16 Dec 2024 |                    |         |              |
|                  |                                                              |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                              |                     |     |             |                 |     |                  |             |                    |         |              |
| 345609           | DME Module - Return to Service Test                          |                     | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                              |                     | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                              |                     | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                              |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                              |                     |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom            | Description                                                          |               | UOM        | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|----------------------------|----------------------------------------------------------------------|---------------|------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                            | Part Number                                                          | Serial Number |            |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position           | HW                                                                   | SW            |            |             |                 |     |                  |             |                    |         | Manufacturer |
|                            | MM Ref                                                               |               |            |             |                 |     |                  |             |                    |         | Date Type    |
|                            | Ops Number(s)                                                        |               |            |             |                 |     |                  |             |                    |         |              |
| 346000                     | Multi-Function Control Display Unit (No. 1) - Removal / Installation |               | HRS        |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                            |                                                                      |               | AFL        |             | 1117            |     |                  | 0           |                    |         | 0            |
|                            | A50A000-00-450                                                       | A4503075      | MOS        |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                            |                                                                      |               | MSC        |             |                 |     | O/C              |             |                    |         |              |
| Airframe                   |                                                                      |               |            |             |                 |     |                  |             |                    |         |              |
| 346001                     | Multi-Function Control Display Unit (No. 2) - Removal / Installation |               | HRS        |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                            |                                                                      |               | AFL        |             | 1117            |     |                  | 0           |                    |         | 0            |
|                            | A50A000-00-450                                                       | A4503080      | MOS        |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                            |                                                                      |               | MSC        |             |                 |     | O/C              |             |                    |         |              |
| Airframe                   |                                                                      |               |            |             |                 |     |                  |             |                    |         |              |
| 346002                     | Multi-Function Control Display Unit (No. 3) - Removal / Installation |               | HRS        |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                            |                                                                      |               | AFL        |             | 1117            |     |                  | 0           |                    |         | 0            |
|                            | A50A000-00-450                                                       | A4503081      | MOS        |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                            |                                                                      |               | MSC        |             |                 |     | O/C              |             |                    |         |              |
| Airframe                   |                                                                      |               |            |             |                 |     |                  |             |                    |         |              |
| 346006                     | Multi-Function Control Display Unit - Operational Test               |               | HRS        |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                            |                                                                      |               | AFL        |             | 1117            |     |                  | 0           |                    |         | 0            |
|                            |                                                                      |               | MOS        |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                            |                                                                      |               | MSC        |             |                 |     | O/C              |             |                    |         |              |
| Airframe                   |                                                                      |               |            |             |                 |     |                  |             |                    |         |              |
| 346012                     | FMS - Operational Check                                              |               | HRS        |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                            |                                                                      |               | AFL        |             | 1117            |     |                  | 0           |                    |         | 0            |
|                            |                                                                      |               | MOS        |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                            |                                                                      |               | MSC        |             |                 |     | O/C              |             |                    |         |              |
| Airframe                   |                                                                      |               |            |             |                 |     |                  |             |                    |         |              |
| 346025                     | FMS Nav Database - Update                                            |               | HRS        |             | -2              |     |                  | 3048.1      |                    |         | 0            |
|                            |                                                                      |               | AFL        |             | -2              |     |                  | 1119        |                    |         | 0            |
|                            |                                                                      |               | DATE       |             | 5 d             |     | 28d              | 06 May 2026 | 11 Jun 2026        |         |              |
|                            |                                                                      |               | [DAYS: -8] |             |                 |     |                  |             |                    |         | EXPIRATION   |
| Airframe                   |                                                                      |               |            |             |                 |     |                  |             |                    |         |              |
| Notes: NAV cycle 2407      |                                                                      |               |            |             |                 |     |                  |             |                    |         |              |
| 346050                     | Planeview Terrain Database Update (Green Disk)                       |               | HRS        |             | 137.9           |     |                  | 2908.2      |                    |         | 0            |
|                            |                                                                      |               | AFL        |             | 53              |     |                  | 1064        |                    |         | 0            |
|                            |                                                                      |               | MOS        |             | 5.7             |     |                  | 21 Nov 2025 |                    |         |              |
|                            |                                                                      |               | MSC        |             |                 |     | O/C              |             |                    |         |              |
| Airframe                   |                                                                      |               |            |             |                 |     |                  |             |                    |         |              |
| Notes: 996-0146-606 LOADED |                                                                      |               |            |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom                      | Description                                                     |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|--------------------------------------|-----------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                      | Part Number                                                     | Serial Number |                     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position                     | HW                                                              | SW            |                     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                      | MM Ref                                                          |               |                     |             |                 |     |                  |             |                    |         | Date Type    |
|                                      | Ops Number(s)                                                   |               |                     |             |                 |     |                  |             |                    |         |              |
| 346051 <sup>U</sup>                  | Planeview Terrain Threat Database Update                        |               | HRS                 |             | 137.9           |     |                  | 2908.2      |                    |         | 0            |
|                                      | 996-1045-639                                                    | 649           | AFL                 |             | 53              |     |                  | 1064        |                    |         | 0            |
|                                      |                                                                 |               | MOS                 |             | 5.7             |     |                  | 21 Nov 2025 |                    |         |              |
|                                      | Airframe                                                        |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
| Notes: DATABASE LOADED: 996-0145-611 |                                                                 |               |                     |             |                 |     |                  |             |                    |         |              |
| 923400 <sup>U</sup>                  | Aircraft Health and Trend Monitoring Data Download and Analyze  |               | HRS                 |             | -2              |     |                  | 3048.1      |                    |         | 0            |
|                                      |                                                                 |               | AFL                 |             | -2              |     |                  | 1119        |                    |         | 0            |
|                                      |                                                                 |               | MOS                 |             | .2              |     | 1                | 06 May 2026 | 30 Jun 2026        |         |              |
|                                      | Airframe                                                        |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 35 - Oxygen                          |                                                                 |               |                     |             |                 |     |                  |             |                    |         |              |
| 350001                               | Oxygen System Torque Requirements                               |               | HRS                 |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                      |                                                                 |               | AFL                 |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                      |                                                                 |               | MOS                 |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                      | Airframe                                                        |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
| 350002                               | Oxygen System - Operational Test                                |               | HRS                 |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                      |                                                                 |               | AFL                 |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                      |                                                                 |               | MOS                 |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                      | Airframe                                                        |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
| 350003                               | Oxygen System Venting Procedure                                 |               | HRS                 |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                      |                                                                 |               | AFL                 |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                      |                                                                 |               | MOS                 |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                      | Airframe                                                        |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
| 351000                               | Crew Oxygen System - Leak and Pressure Decay Test               |               | HRS                 |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                      |                                                                 |               | AFL                 |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                      |                                                                 |               | MOS                 |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                      | Airframe                                                        |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
| 351100                               | Crew Oxygen Mask and Regulator (Pilot) - Removal / Installation |               | HRS                 |             | 1452            |     |                  | 1594.1      |                    |         | 0            |
|                                      |                                                                 |               | AFL                 |             | 570             |     |                  | 547         |                    |         | 0            |
|                                      | MLD20-564                                                       | B165248       | MOS                 |             | 64              |     |                  | 12 Jan 2021 |                    |         |              |
|                                      | Airframe                                                        |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |

| ATA<br>U=Custom                | Description                                                       |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|--------------------------------|-------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                                | Part Number                                                       | Serial Number |                     |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position               | HW                                                                | SW            |                     |             |                 |     |                  |             |                    |             | Manufacturer |
|                                | MM Ref                                                            |               |                     |             |                 |     |                  |             |                    |             | Date Type    |
|                                | Ops Number(s)                                                     |               |                     |             |                 |     |                  |             |                    |             |              |
| 351101                         | Crew Oxygen Mask and Regulator (Copilot) - Removal / Installation |               | HRS                 |             | 1452            |     |                  | 1594.1      |                    |             | 0            |
|                                |                                                                   |               | AFL                 |             | 570             |     |                  | 547         |                    |             | 0            |
|                                | MLD20-564                                                         | B165431       | MOS                 |             | 64              |     |                  | 12 Jan 2021 |                    |             |              |
|                                |                                                                   |               | MSC                 |             |                 |     | O/C              |             |                    |             |              |
| Airframe                       |                                                                   |               |                     |             |                 |     |                  |             |                    |             |              |
| 351102                         | Observer Oxygen Mask and Regulator - Removal / Installation       |               | HRS                 |             | 1452            |     |                  | 1594.1      |                    |             | 0            |
|                                |                                                                   |               | AFL                 |             | 570             |     |                  | 547         |                    |             | 0            |
|                                | MLD20-564                                                         | B165359       | MOS                 |             | 64              |     |                  | 12 Jan 2021 |                    |             |              |
|                                |                                                                   |               | MSC                 |             |                 |     | O/C              |             |                    |             |              |
| Airframe                       |                                                                   |               |                     |             |                 |     |                  |             |                    |             |              |
| 351103                         | Crew Oxygen Mask (Pilot) - Restore                                |               | HRS                 |             | 1452            |     |                  | 1594.1      |                    |             | 0            |
|                                | MLD20-564                                                         | B165248       | AFL                 |             | 570             |     |                  | 547         |                    |             | 0            |
|                                |                                                                   |               | MOS                 |             | 64              |     | 72               | 12 Jan 2021 | 31 Dec 2026        |             |              |
|                                |                                                                   |               | [End Of Month Item] |             |                 |     |                  |             |                    |             | OVERHAUL     |
| Notes: MRI PARENT CODE: 351100 |                                                                   |               |                     |             |                 |     |                  |             |                    |             |              |
| 351104                         | Crew Oxygen Mask (Copilot) - Restore                              |               | HRS                 |             | 1452            |     |                  | 1594.1      |                    |             | 0            |
|                                | MLD20-564                                                         | B165431       | AFL                 |             | 570             |     |                  | 547         |                    |             | 0            |
|                                |                                                                   |               | MOS                 |             | 64              |     | 72               | 12 Jan 2021 | 31 Dec 2026        |             |              |
|                                |                                                                   |               | [End Of Month Item] |             |                 |     |                  |             |                    |             | OVERHAUL     |
| Notes: MRI PARENT CODE: 351101 |                                                                   |               |                     |             |                 |     |                  |             |                    |             |              |
| 351105                         | Crew Oxygen Mask (Observer) - Restore                             |               | HRS                 |             | 1452            |     |                  | 1594.1      |                    |             | 0            |
|                                | MLD20-564                                                         | B165359       | AFL                 |             | 570             |     |                  | 547         |                    |             | 0            |
|                                |                                                                   |               | MOS                 |             | 64              |     | 72               | 12 Jan 2021 | 31 Dec 2026        |             |              |
|                                |                                                                   |               | [End Of Month Item] |             |                 |     |                  |             |                    |             | OVERHAUL     |
| Notes: MRI PARENT CODE: 351102 |                                                                   |               |                     |             |                 |     |                  |             |                    |             |              |
| 351106                         | Crew Oxygen Mask and Regulator (Pilot) - Functional Test          |               | HRS                 |             | 1452            |     |                  | 1594.1      |                    |             | 0            |
|                                |                                                                   |               | AFL                 |             | 570             |     |                  | 547         |                    |             | 0            |
|                                |                                                                   |               | MOS                 |             | 64              |     | 75               | 12 Jan 2021 | 12 Apr 2027        | 12 May 2027 |              |
|                                |                                                                   |               | [MOS: +1m/-1m]      |             |                 |     |                  |             |                    |             |              |
| Airframe                       |                                                                   |               |                     |             |                 |     |                  |             |                    |             |              |
| 351107                         | Crew Oxygen Mask and Regulator (Copilot) - Functional Test        |               | HRS                 |             | 1452            |     |                  | 1594.1      |                    |             | 0            |
|                                |                                                                   |               | AFL                 |             | 570             |     |                  | 547         |                    |             | 0            |
|                                |                                                                   |               | MOS                 |             | 64              |     | 75               | 12 Jan 2021 | 12 Apr 2027        | 12 May 2027 |              |
|                                |                                                                   |               | [MOS: +1m/-1m]      |             |                 |     |                  |             |                    |             |              |
| Airframe                       |                                                                   |               |                     |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom  | Description                                                                      |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------|----------------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                  | Part Number                                                                      | Serial Number |                                    |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position | HW                                                                               | SW            |                                    |             |                 |     |                  |             |                    |             | Manufacturer |
|                  | MM Ref                                                                           |               |                                    |             |                 |     |                  |             |                    |             | Date Type    |
|                  | Ops Number(s)                                                                    |               |                                    |             |                 |     |                  |             |                    |             |              |
| 351108           | Crew Oxygen Mask and Regulator (Observer) -<br>Functional Test                   |               | HRS                                |             | 1452            |     |                  | 1594.1      |                    |             | 0            |
|                  |                                                                                  |               | AFL                                |             | 570             |     |                  | 547         |                    |             | 0            |
|                  |                                                                                  |               | MOS                                |             | 64              |     | 75               | 12 Jan 2021 | 12 Apr 2027        | 12 May 2027 |              |
|                  |                                                                                  |               | [MOS: +1m/-1m]                     |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                  |               |                                    |             |                 |     |                  |             |                    |             |              |
| 351112           | Crew Oxygen Mask / Regulator and Stowage Box (Pilot) -<br>Detailed Inspection    |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                                  |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                                  |               | MOS                                |             | 28.7            | 22  | 36               | 21 Dec 2023 | 31 Jan 2027*       | 28 Feb 2027 |              |
|                  |                                                                                  |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                  |               |                                    |             |                 |     |                  |             |                    |             |              |
| 052012           |                                                                                  |               |                                    |             |                 |     |                  |             |                    |             |              |
| 351113           | Crew Oxygen Mask / Regulator and Stowage Box<br>(Copilot) - Detailed Inspection  |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                                  |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                                  |               | MOS                                |             | 28.7            | 22  | 36               | 21 Dec 2023 | 31 Jan 2027*       | 28 Feb 2027 |              |
|                  |                                                                                  |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                  |               |                                    |             |                 |     |                  |             |                    |             |              |
| 052012           |                                                                                  |               |                                    |             |                 |     |                  |             |                    |             |              |
| 351114           | Crew Oxygen Mask / Regulator and Stowage Box<br>(Observer) - Detailed Inspection |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                                  |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                                  |               | MOS                                |             | 28.7            | 22  | 36               | 21 Dec 2023 | 31 Jan 2027*       | 28 Feb 2027 |              |
|                  |                                                                                  |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                  |               |                                    |             |                 |     |                  |             |                    |             |              |
| 052012           |                                                                                  |               |                                    |             |                 |     |                  |             |                    |             |              |
| 351125           | Crew Oxygen Mask Storage Box (Pilot) - Removal /<br>Installation                 |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                  |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                  |               | MOS                                | TSN:3       | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                  |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                  |               |                                    |             |                 |     |                  |             |                    |             |              |
| 351126           | Crew Oxygen Mask Storage Box (Copilot) - Removal /<br>Installation               |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                  |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                  |               | MOS                                | TSN:3       | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                  |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                  |               |                                    |             |                 |     |                  |             |                    |             |              |
| 351127           | Observer Oxygen Mask Storage Box - Removal /<br>Installation                     |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                  |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                  |               | MOS                                | TSN:3       | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                  |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                  |               |                                    |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom                                             | Description                                                |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|-------------------------------------------------------------|------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                                                             | Part Number                                                | Serial Number |                     |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position                                            | HW                                                         | SW            |                     |             |                 |     |                  |             |                    |             | Manufacturer |
|                                                             | MM Ref                                                     |               |                     |             |                 |     |                  |             |                    |             | Date Type    |
|                                                             | Ops Number(s)                                              |               |                     |             |                 |     |                  |             |                    |             |              |
| 351200                                                      | Crew Oxygen Cylinder - Removal / Installation              |               | HRS                 | TSN:1310.3  | 1735.8          |     |                  | 1310.3      |                    |             | 0            |
|                                                             | 805983-15                                                  | C15060698     | AFL                 | TSN:388     | 729             |     |                  | 388         |                    |             | 0            |
|                                                             |                                                            |               | MOS                 | TSN:56      | 75.2            |     |                  | 05 Feb 2020 |                    |             |              |
|                                                             | Airframe                                                   |               | MSC                 |             |                 |     | O/C              |             |                    |             |              |
| 351202                                                      | Crew Oxygen Cylinder - Discard                             |               | HRS                 |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                                                             | 805983-15                                                  | C15060698     | AFL                 |             | 1117            |     |                  | 0           |                    |             | 0            |
|                                                             |                                                            |               | MOS                 |             | 128.6           |     | 180              | 24 Aug 2015 | 31 Mar 2030        |             |              |
|                                                             | Airframe                                                   |               | [End Of Month Item] |             |                 |     |                  |             |                    |             | MANUFACTURE  |
| Notes: MRI PARENT CODE: 351200                              |                                                            |               |                     |             |                 |     |                  |             |                    |             |              |
| 351203                                                      | Crew Oxygen Cylinder - (Hydrostatic) Functional Check      |               | HRS                 |             |                 |     |                  |             |                    |             | 0            |
|                                                             |                                                            |               | AFL                 |             |                 |     |                  |             |                    |             | 0            |
|                                                             |                                                            |               | MOS                 |             | 75.2            |     |                  | 05 Feb 2020 |                    |             |              |
|                                                             | Airframe                                                   |               | MSC                 |             |                 |     | O/C              |             |                    |             | HYDRO CHECK  |
| Notes: PN: 805983-15 SN: C15060698. MRI PARENT CODE: 351200 |                                                            |               |                     |             |                 |     |                  |             |                    |             |              |
| 351205                                                      | Crew Oxygen Pressure Transducer - Removal / Installation   |               | HRS                 |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                                                             |                                                            |               | AFL                 |             | 1117            |     |                  | 0           |                    |             | 0            |
|                                                             | P24160                                                     | 1319733       | MOS                 |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                                                             | Airframe                                                   |               | MSC                 |             |                 |     | O/C              |             |                    |             |              |
| 351206                                                      | Crew Oxygen Lp Switch - Removal / Installation             |               | HRS                 |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                                                             | P24029                                                     | 4957          | AFL                 |             | 1117            |     |                  | 0           |                    |             | 0            |
|                                                             |                                                            |               | MOS                 |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                                                             | Airframe                                                   |               | MSC                 |             |                 |     | O/C              |             |                    |             |              |
| 351207                                                      | Crew Oxygen Lp Switch Check Valve - Removal / Installation |               | HRS                 |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                                                             |                                                            |               | AFL                 |             | 1117            |     |                  | 0           |                    |             | 0            |
|                                                             | 170602                                                     | SN-UNKNOWN    | MOS                 |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                                                             | Airframe                                                   |               | MSC                 |             |                 |     | O/C              |             |                    |             |              |
| 351208                                                      | Crew Oxygen System Check Valves - Operational Check        |               | HRS                 |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                                                             |                                                            |               | AFL                 |             | 315             |     |                  | 802         |                    |             | 0            |
|                                                             |                                                            |               | MOS                 |             | 28.7            |     | 75               | 21 Dec 2023 | 21 Mar 2030        | 21 Apr 2030 |              |
|                                                             | Airframe                                                   |               | [MOS: +1m/-1m]      |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom               | Description                                                  |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|-------------------------------|--------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                               | Part Number                                                  | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position              | HW                                                           | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                               | MM Ref                                                       |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                               | Ops Number(s)                                                |               |     |             |                 |     |                  |             |                    |         |              |
| 351210                        | Crew Oxygen Lp Switch - Operational Check                    |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                               |                                                              |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                               |                                                              |               | MOS |             | 126             |     |                  | 12 Nov 2015 |                    |         |              |
|                               | Airframe                                                     |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 351211                        | Crew Oxygen Quantity Gage - Removal / Installation           |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                               | 163LCP81                                                     | 14100748      | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                               |                                                              |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                               | Airframe                                                     |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 351213                        | Crew Oxygen Cylinder - General Visual Inspection             |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                               |                                                              |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                               |                                                              |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                               | Airframe                                                     |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 351300                        | Crew Oxygen Servicing Pressure Gage - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                               |                                                              |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                               | P24094-1                                                     | 2296          | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                               | Airframe                                                     |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 351301                        | Oxygen Servicing Filler Valve - Removal / Installation       |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                               | P21103                                                       | 1022          | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                               |                                                              |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                               | Airframe                                                     |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 351304                        | Crew Oxygen Servicing Pressure Gage - Inspection             |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                               |                                                              |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                               |                                                              |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                               | Airframe                                                     |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Notes: PN: P21103 SN: <NONE>. |                                                              |               |     |             |                 |     |                  |             |                    |         |              |
| 351305                        | Oxygen Supply Pressure Valve - Removal / Installation        |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                               | O2C74T01-1                                                   | 17086         | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                               |                                                              |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                               | Airframe                                                     |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 352001                        | Passenger Oxygen Controller - Removal / Installation         |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                               | P27122                                                       | 0521          | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                               |                                                              |               | MOS | TSN:3       | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                               | Airframe                                                     |               | MSC |             |                 |     | O/C              |             |                    |         |              |



| ATA<br>U=Custom                                             | Description                                          |                                    | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|-------------------------------------------------------------|------------------------------------------------------|------------------------------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                                                             | Part Number                                          | Serial Number                      |     |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position                                            | HW                                                   | SW                                 |     |             |                 |     |                  |             |                    |             | Manufacturer |
|                                                             | MM Ref                                               |                                    |     |             |                 |     |                  |             |                    |             | Date Type    |
|                                                             | Ops Number(s)                                        |                                    |     |             |                 |     |                  |             |                    |             |              |
| 352002                                                      | Oxygen System Panel - Removal / Installation         |                                    | HRS |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                                                             | 60P3110911A004                                       | NSN                                | AFL |             | 1117            |     |                  | 0           |                    |             | 0            |
|                                                             |                                                      |                                    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                                                             | Airframe                                             |                                    | MSC |             |                 |     | O/C              |             |                    |             |              |
| 352100                                                      | Passenger Oxygen Drop-Down Mask Assemblies -         |                                    | HRS |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                                                             | Detailed Inspection                                  |                                    | AFL |             | 52              |     |                  | 1065        |                    |             | 0            |
|                                                             |                                                      |                                    | MOS |             | 5.2             |     | 24               | 04 Dec 2025 | 31 Dec 2027        | 31 Jan 2028 |              |
|                                                             | Airframe                                             | [End Of Month Item] [MOS: +1m/-1m] |     |             |                 |     |                  |             |                    |             |              |
| 352300                                                      | Passenger Oxygen Cylinder - Removal / Installation   |                                    | HRS | TSN:2315.6  | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                                                             | 805983-15                                            | C15051134                          | AFL | TSN:802     | 315             |     |                  | 802         |                    |             | 0            |
|                                                             |                                                      |                                    | MOS | TSN:103     | 28.7            |     |                  | 21 Dec 2023 |                    |             |              |
|                                                             | Airframe                                             |                                    | MSC |             |                 |     | O/C              |             |                    |             |              |
| 352302                                                      | Passenger Oxygen Cylinder - Discard                  |                                    | HRS |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                                                             | 805983-15                                            | C15051134                          | AFL |             | 1117            |     |                  | 0           |                    |             | 0            |
|                                                             |                                                      |                                    | MOS |             | 128.6           |     | 180              | 24 Aug 2015 | 28 Feb 2030        |             |              |
|                                                             | Airframe                                             | [End Of Month Item] MANUFACTURE    |     |             |                 |     |                  |             |                    |             |              |
| Notes: MRI PARENT CODE: 352300                              |                                                      |                                    |     |             |                 |     |                  |             |                    |             |              |
| 352303                                                      | Passenger Oxygen Cylinder - (Hydrostatic) Functional |                                    | HRS |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                                                             | Check                                                |                                    | AFL |             | 315             |     |                  | 802         |                    |             | 0            |
|                                                             |                                                      |                                    | MOS |             | 28.7            |     | 60               | 21 Dec 2023 | 31 Oct 2028        |             |              |
|                                                             | Airframe                                             | [End Of Month Item] HYDRO CHECK    |     |             |                 |     |                  |             |                    |             |              |
| Notes: PN: 805983-15 SN: C15051134. MRI PARENT CODE: 352300 |                                                      |                                    |     |             |                 |     |                  |             |                    |             |              |
| 352305                                                      | Passenger Oxygen Lp Switch Check Valve - Removal /   |                                    | HRS |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                                                             | Installation                                         |                                    | AFL |             | 1117            |     |                  | 0           |                    |             | 0            |
|                                                             | 170602                                               | SN-UNKNOWN                         | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                                                             | Airframe                                             |                                    | MSC |             |                 |     | O/C              |             |                    |             |              |
| 352306                                                      | Passenger Oxygen Pressure Transducer - Removal /     |                                    | HRS |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                                                             | Installation                                         |                                    | AFL |             | 1117            |     |                  | 0           |                    |             | 0            |
|                                                             | P24160                                               | 1319763                            | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                                                             | Airframe                                             |                                    | MSC |             |                 |     | O/C              |             |                    |             |              |

| ATA<br>U=Custom  | Description                                             |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------|---------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                  | Part Number                                             | Serial Number |                                    |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position | HW                                                      | SW            |                                    |             |                 |     |                  |             |                    |             | Manufacturer |
|                  | MM Ref                                                  |               |                                    |             |                 |     |                  |             |                    |             | Date Type    |
|                  | Ops Number(s)                                           |               |                                    |             |                 |     |                  |             |                    |             |              |
| 352307           | Passenger Oxygen Lp Switch - Removal / Installation     |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  | P24029                                                  | 4961          | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                         |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  | Airframe                                                |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| 352308           | Passenger Oxygen System Check Valve - Operational       |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  | Check                                                   |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                         |               | MOS                                |             | 122             |     | 75               | 11 Mar 2016 | 28 Feb 2027        | 31 Mar 2027 |              |
|                  | Airframe                                                |               | [MOS: +1m/-1m]                     |             |                 |     |                  |             |                    |             |              |
| 352310           | Passenger Oxygen Lp Switch - Operational Check          |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                         |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                         |               | MOS                                |             | 28.7            |     |                  | 21 Dec 2023 |                    |             |              |
|                  | Airframe                                                |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| 352311           | Passenger Oxygen Quantity Gage - Removal / Installation |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  | 163LCP81                                                | 14110977      | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                         |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  | Airframe                                                |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| 352313           | Passenger Oxygen Cylinder - General Visual Inspection   |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                         |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                         |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  | Airframe                                                |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| 352400           | Passenger Oxygen Servicing Pressure Gage - Removal /    |               | HRS                                |             | 2673.9          |     |                  | 372.2       |                    |             | 0            |
|                  | Installation                                            |               | AFL                                |             | 1020            |     |                  | 97          |                    |             | 0            |
|                  | P24094-1                                                | 2893          | MOS                                | TSN:2       | 109.5           |     |                  | 28 Mar 2017 |                    |             |              |
|                  | Airframe                                                |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| 352402           | Passenger Oxygen Servicing Pressure Gage - Inspection   |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                         |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                         |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  | Airframe                                                |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| 352403           | Passenger Oxygen System (Manual MODE) - Operational     |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  | Check                                                   |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                         |               | MOS                                |             | 28.7            |     | 36               | 21 Dec 2023 | 31 Dec 2026        | 31 Jan 2027 |              |
|                  | Airframe                                                |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
|                  | 052012                                                  |               |                                    |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom                        | Description                                                                |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due     | Avg Man Hrs  |
|----------------------------------------|----------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|---------------------|-------------|--------------|
|                                        | Part Number                                                                | Serial Number |                                    |             |                 |     |                  |             |                     |             | Approx Price |
| Logbook Position                       | HW                                                                         | SW            |                                    |             |                 |     |                  |             |                     |             | Manufacturer |
|                                        | MM Ref                                                                     |               |                                    |             |                 |     |                  |             |                     |             | Date Type    |
|                                        | Ops Number(s)                                                              |               |                                    |             |                 |     |                  |             |                     |             |              |
| 352404                                 | Passenger Oxygen System (Auto MODE) - Functional Check                     |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                     |             | 0            |
|                                        |                                                                            |               | AFL                                |             | 315             |     |                  | 802         |                     |             | 0            |
|                                        |                                                                            |               | MOS                                |             | 28.7            |     | 36               | 21 Dec 2023 | 31 Dec 2026         | 31 Jan 2027 |              |
|                                        |                                                                            |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                     |             |              |
| Airframe                               |                                                                            |               | 052012                             |             |                 |     |                  |             |                     |             |              |
| 352600                                 | Therapeutic Oxygen Shut-Off Valve - Removal / Installation<br>P21046-10960 |               | HRS                                |             | 3046.1          |     |                  | 0           |                     |             | 0            |
|                                        |                                                                            |               | AFL                                |             | 1117            |     |                  | 0           |                     |             | 0            |
|                                        |                                                                            |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                     |             |              |
|                                        |                                                                            |               | MSC                                |             |                 |     | O/C              |             |                     |             |              |
| Airframe                               |                                                                            |               |                                    |             |                 |     |                  |             |                     |             |              |
| 352601                                 | Therapeutic Oxygen Pressure Switch - Removal / Installation<br>P240294962  |               | HRS                                |             | 3046.1          |     |                  | 0           |                     |             | 0            |
|                                        |                                                                            |               | AFL                                |             | 1117            |     |                  | 0           |                     |             | 0            |
|                                        |                                                                            |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                     |             |              |
|                                        |                                                                            |               | MSC                                |             |                 |     | O/C              |             |                     |             |              |
| Airframe                               |                                                                            |               |                                    |             |                 |     |                  |             |                     |             |              |
| 352604                                 | Therapeutic Oxygen System - Functional Check                               |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                     |             | 0            |
|                                        |                                                                            |               | AFL                                |             | 315             |     |                  | 802         |                     |             | 0            |
|                                        |                                                                            |               | MOS                                |             | 28.7            |     | 36               | 21 Dec 2023 | 31 Dec 2026         | 31 Jan 2027 |              |
|                                        |                                                                            |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                     |             |              |
| Airframe                               |                                                                            |               | 052012                             |             |                 |     |                  |             |                     |             |              |
| 352605                                 | Therapeutic Oxygen Mask - Detailed Inspection                              |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                     |             | 0            |
|                                        |                                                                            |               | AFL                                |             | 315             |     |                  | 802         |                     |             | 0            |
|                                        |                                                                            |               | MOS                                |             | 28.7            |     | 36               | 21 Dec 2023 | 31 Dec 2026         | 31 Jan 2027 |              |
|                                        |                                                                            |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                     |             |              |
| Airframe                               |                                                                            |               | 052012                             |             |                 |     |                  |             |                     |             |              |
| Notes: PN: O2C33K08-01-030 SN: <NONE>. |                                                                            |               |                                    |             |                 |     |                  |             |                     |             |              |
| 352606                                 | Therapeutic Oxygen Mask #1- Removal / Installation<br>02C5T08-4M419        |               | HRS                                |             | 3033.8          |     |                  | 12.3        |                     |             | 0            |
|                                        |                                                                            |               | AFL                                |             | 1112            |     |                  | 5           |                     |             | 0            |
|                                        |                                                                            |               | MOS                                |             | 124.2           |     |                  | 05 Jan 2016 |                     |             | OXYGEN CORP  |
|                                        |                                                                            |               | MSC                                |             |                 |     | O/C              |             |                     |             |              |
| Airframe                               |                                                                            |               |                                    |             |                 |     |                  |             |                     |             |              |
| 352607                                 | Therapeutic Oxygen Mask #2- Removal / Installation<br>02C52T08-4SN-UNKNOWN |               | HRS                                |             | 3046.1          |     |                  | 0           |                     |             | 0            |
|                                        |                                                                            |               | AFL                                |             | 1117            |     |                  | 0           |                     |             | 0            |
|                                        |                                                                            |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                     |             |              |
|                                        |                                                                            |               | MSC                                |             |                 |     | O/C              |             |                     |             |              |
| Airframe                               |                                                                            |               |                                    |             |                 |     |                  |             |                     |             |              |

| ATA<br>U=Custom  | Description                                                      |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                                      | Serial Number |     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                               | SW            |     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                           |               |     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                                    |               |     |             |                 |     |                  |             |                     |         |              |
| 354100           | Forward Left Psu Oxygen Box Assembly #1 - Removal / Installation |               | HRS |             | 3033.8          |     |                  | 12.3        |                     |         | 0            |
|                  |                                                                  |               | AFL |             | 1112            |     |                  | 5           |                     |         | 0            |
|                  | P28452                                                           | 0146          | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                     |         | PACIFIC      |
|                  |                                                                  |               | MSC |             |                 |     | O/C              |             |                     |         | PRECISION    |
| Airframe         |                                                                  |               |     |             |                 |     |                  |             |                     |         |              |
| 354101           | Forward Left Psu Oxygen Box Assembly #2 - Removal / Installation |               | HRS |             | 3033.8          |     |                  | 12.3        |                     |         | 0            |
|                  |                                                                  |               | AFL |             | 1112            |     |                  | 5           |                     |         | 0            |
|                  | P28457                                                           | 0102          | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                     |         | PACIFIC      |
|                  |                                                                  |               | MSC |             |                 |     | O/C              |             |                     |         | PRECISION    |
| Airframe         |                                                                  |               |     |             |                 |     |                  |             |                     |         |              |
| 354102           | Forward Left Psu Oxygen Box Assembly #3 - Removal / Installation |               | HRS |             | 3033.8          |     |                  | 12.3        |                     |         | 0            |
|                  |                                                                  |               | AFL |             | 1112            |     |                  | 5           |                     |         | 0            |
|                  | P28453                                                           | 0146          | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                     |         | PACIFIC      |
|                  |                                                                  |               | MSC |             |                 |     | O/C              |             |                     |         | PRECISION    |
| Airframe         |                                                                  |               |     |             |                 |     |                  |             |                     |         |              |
| 354106           | Mid Left Psu Oxygen Box Assembly #1 - Removal / Installation     |               | HRS |             | 3033.8          |     |                  | 12.3        |                     |         | 0            |
|                  |                                                                  |               | AFL |             | 1112            |     |                  | 5           |                     |         | 0            |
|                  | P28542                                                           | 0148          | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                     |         | PACIFIC      |
|                  |                                                                  |               | MSC |             |                 |     | O/C              |             |                     |         | PRECISION    |
| Airframe         |                                                                  |               |     |             |                 |     |                  |             |                     |         |              |
| 354107           | Mid Left Psu Oxygen Box Assembly #2 - Removal / Installation     |               | HRS |             | 3033.8          |     |                  | 12.3        |                     |         | 0            |
|                  |                                                                  |               | AFL |             | 1112            |     |                  | 5           |                     |         | 0            |
|                  | P28459                                                           | 0043          | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                     |         | PACIFIC      |
|                  |                                                                  |               | MSC |             |                 |     | O/C              |             |                     |         | PRECISION    |
| Airframe         |                                                                  |               |     |             |                 |     |                  |             |                     |         |              |
| 354108           | Mid Left Psu Oxygen Box Assembly #3 - Removal / Installation     |               | HRS |             | 3033.8          |     |                  | 12.3        |                     |         | 0            |
|                  |                                                                  |               | AFL |             | 1112            |     |                  | 5           |                     |         | 0            |
|                  | P28453                                                           | 0147          | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                     |         | PACIFIC      |
|                  |                                                                  |               | MSC |             |                 |     | O/C              |             |                     |         | PRECISION    |
| Airframe         |                                                                  |               |     |             |                 |     |                  |             |                     |         |              |
| 354112           | Aft Left Psu Oxygen Box Assembly #1 - Removal / Installation     |               | HRS |             | 3033.8          |     |                  | 12.3        |                     |         | 0            |
|                  |                                                                  |               | AFL |             | 1112            |     |                  | 5           |                     |         | 0            |
|                  | P28452                                                           | 0147          | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                     |         | PACIFIC      |
|                  |                                                                  |               | MSC |             |                 |     | O/C              |             |                     |         | PRECISION    |
| Airframe         |                                                                  |               |     |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom  | Description                                                       |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|-------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                                       | Serial Number |     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                                | SW            |     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                            |               |     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                                     |               |     |             |                 |     |                  |             |                     |         |              |
| 354113           | Aft Left Psu Oxygen Box Assembly #2 - Removal / Installation      |               | HRS |             | 3033.8          |     |                  | 12.3        |                     |         | 0            |
|                  |                                                                   |               | AFL |             | 1112            |     |                  | 5           |                     |         | 0            |
|                  | P28461                                                            | 0001          | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                     |         | PACIFIC      |
|                  |                                                                   |               | MSC |             |                 |     | O/C              |             |                     |         | PRECISION    |
| Airframe         |                                                                   |               |     |             |                 |     |                  |             |                     |         |              |
| 354114           | Aft Left Psu Oxygen Box Assembly #3 - Removal / Installation      |               | HRS |             | 3033.8          |     |                  | 12.3        |                     |         | 0            |
|                  |                                                                   |               | AFL |             | 1112            |     |                  | 5           |                     |         | 0            |
|                  | P28453                                                            | 0149          | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                     |         | PACIFIC      |
|                  |                                                                   |               | MSC |             |                 |     | O/C              |             |                     |         | PRECISION    |
| Airframe         |                                                                   |               |     |             |                 |     |                  |             |                     |         |              |
| 354118           | Forward Right Psu Oxygen Box Assembly #1 - Removal / Installation |               | HRS |             | 3033.8          |     |                  | 12.3        |                     |         | 0            |
|                  |                                                                   |               | AFL |             | 1112            |     |                  | 5           |                     |         | 0            |
|                  | P28453                                                            | 0145          | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                     |         | PACIFIC      |
|                  |                                                                   |               | MSC |             |                 |     | O/C              |             |                     |         | PRECISION    |
| Airframe         |                                                                   |               |     |             |                 |     |                  |             |                     |         |              |
| 354119           | Forward Right Psu Oxygen Box Assembly #2 - Removal / Installation |               | HRS |             | 3033.8          |     |                  | 12.3        |                     |         | 0            |
|                  |                                                                   |               | AFL |             | 1112            |     |                  | 5           |                     |         | 0            |
|                  | P28457                                                            | 0121          | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                     |         | PACIFIC      |
|                  |                                                                   |               | MSC |             |                 |     | O/C              |             |                     |         | PRECISION    |
| Airframe         |                                                                   |               |     |             |                 |     |                  |             |                     |         |              |
| 354120           | Forward Right Psu Oxygen Box Assembly #3 - Removal / Installation |               | HRS |             | 3033.8          |     |                  | 12.3        |                     |         | 0            |
|                  |                                                                   |               | AFL |             | 1112            |     |                  | 5           |                     |         | 0            |
|                  | P28452                                                            | 0210          | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                     |         | PACIFIC      |
|                  |                                                                   |               | MSC |             |                 |     | O/C              |             |                     |         | PRECISION    |
| Airframe         |                                                                   |               |     |             |                 |     |                  |             |                     |         |              |
| 354124           | Mid Right Psu Oxygen Box Assembly #1 - Removal / Installation     |               | HRS |             | 3033.8          |     |                  | 12.3        |                     |         | 0            |
|                  |                                                                   |               | AFL |             | 1112            |     |                  | 5           |                     |         | 0            |
|                  | P28453                                                            | 0203          | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                     |         | PACIFIC      |
|                  |                                                                   |               | MSC |             |                 |     | O/C              |             |                     |         | PRECISION    |
| Airframe         |                                                                   |               |     |             |                 |     |                  |             |                     |         |              |
| 354125           | Mid Right Psu Oxygen Box Assembly #2 - Removal / Installation     |               | HRS |             | 3033.8          |     |                  | 12.3        |                     |         | 0            |
|                  |                                                                   |               | AFL |             | 1112            |     |                  | 5           |                     |         | 0            |
|                  | P28457                                                            | 0101          | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                     |         | PACIFIC      |
|                  |                                                                   |               | MSC |             |                 |     | O/C              |             |                     |         | PRECISION    |
| Airframe         |                                                                   |               |     |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom  | Description                                                   |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|---------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                                   | Serial Number |     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                            | SW            |     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                        |               |     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                                 |               |     |             |                 |     |                  |             |                     |         |              |
| 354126           | Mid Right Psu Oxygen Box Assembly #3 - Removal / Installation |               | HRS |             | 3033.8          |     |                  | 12.3        |                     |         | 0            |
|                  |                                                               |               | AFL |             | 1112            |     |                  | 5           |                     |         | 0            |
|                  | P28452                                                        | 0145          | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                     |         | PACIFIC      |
|                  |                                                               |               | MSC |             |                 |     | O/C              |             |                     |         | PRECISION    |
| Airframe         |                                                               |               |     |             |                 |     |                  |             |                     |         |              |
| 354130           | Aft Right Psu Oxygen Box Assembly #1 - Removal / Installation |               | HRS |             | 3033.8          |     |                  | 12.3        |                     |         | 0            |
|                  |                                                               |               | AFL |             | 1112            |     |                  | 5           |                     |         | 0            |
|                  | P28453                                                        | 0205          | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                     |         | PACIFIC      |
|                  |                                                               |               | MSC |             |                 |     | O/C              |             |                     |         | PRECISION    |
| Airframe         |                                                               |               |     |             |                 |     |                  |             |                     |         |              |
| 354131           | Aft Right Psu Oxygen Box Assembly #2 - Removal / Installation |               | HRS |             | 3033.8          |     |                  | 12.3        |                     |         | 0            |
|                  |                                                               |               | AFL |             | 1112            |     |                  | 5           |                     |         | 0            |
|                  | P28457                                                        | 0122          | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                     |         | PACIFIC      |
|                  |                                                               |               | MSC |             |                 |     | O/C              |             |                     |         | PRECISION    |
| Airframe         |                                                               |               |     |             |                 |     |                  |             |                     |         |              |
| 354132           | Aft Right Psu Oxygen Box Assembly #3 - Removal / Installation |               | HRS |             | 3033.8          |     |                  | 12.3        |                     |         | 0            |
|                  |                                                               |               | AFL |             | 1112            |     |                  | 5           |                     |         | 0            |
|                  | P28452                                                        | 0206          | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                     |         | PACIFIC      |
|                  |                                                               |               | MSC |             |                 |     | O/C              |             |                     |         | PRECISION    |
| Airframe         |                                                               |               |     |             |                 |     |                  |             |                     |         |              |
| 354208           | Vestibule Oxygen Mask Box - Removal / Installation            |               | HRS |             | 3033.8          |     |                  | 12.3        |                     |         | 0            |
|                  | P25027-1 0166                                                 |               | AFL |             | 1112            |     |                  | 5           |                     |         | 0            |
|                  |                                                               |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                     |         | PACIFIC      |
|                  |                                                               |               | MSC |             |                 |     | O/C              |             |                     |         | PRECISION    |
| Airframe         |                                                               |               |     |             |                 |     |                  |             |                     |         |              |
| 354210           | Crew Rest Oxygen Mask Box - Removal / Installation            |               | HRS |             | 3033.8          |     |                  | 12.3        |                     |         | 0            |
|                  | P25059 0846                                                   |               | AFL |             | 1112            |     |                  | 5           |                     |         | 0            |
|                  |                                                               |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                     |         | PACIFIC      |
|                  |                                                               |               | MSC |             |                 |     | O/C              |             |                     |         | PRECISION    |
| Airframe         |                                                               |               |     |             |                 |     |                  |             |                     |         |              |
| 354212           | Galley Oxygen Mask Box - Removal / Installation               |               | HRS |             | 3033.8          |     |                  | 12.3        |                     |         | 0            |
|                  | P25059 0841                                                   |               | AFL |             | 1112            |     |                  | 5           |                     |         | 0            |
|                  |                                                               |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                     |         | PACIFIC      |
|                  |                                                               |               | MSC |             |                 |     | O/C              |             |                     |         | PRECISION    |
| Airframe         |                                                               |               |     |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom  | Description                                                             |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                             | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                      | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                  |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| 354214           | Forward Lav Oxygen Mask Box - Removal / Installation                    |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  | P25059                                                                  | 0843          | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  |                                                                         |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | PACIFIC      |
|                  | Airframe                                                                |               | MSC |             |                 |     | O/C              |             |                    |         | PRECISION    |
| 354216           | Aft Lav Oxygen Mask Box - Removal / Installation                        |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  | P25059                                                                  | 0848          | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  |                                                                         |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | PACIFIC      |
|                  | Airframe                                                                |               | MSC |             |                 |     | O/C              |             |                    |         | PRECISION    |
| 36 - Pneumatic   |                                                                         |               |     |             |                 |     |                  |             |                    |         |              |
| 361100           | Hp Shut-Off Valve (Left) - Removal / Installation                       |               | HRS | TSN:2051.7  | 994.4           |     |                  | 2051.7      |                    |         | 0            |
|                  | 3215974-1                                                               | 416           | AFL | TSN:725     | 392             |     |                  | 725         |                    |         | 0            |
|                  |                                                                         |               | MOS | TSN:88      | 40.9            |     |                  | 15 Dec 2022 |                    |         |              |
|                  | Airframe                                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 361101           | Hp Shut-Off Valve (Right) - Removal / Installation                      |               | HRS | TSN:1866.5  | 1178.9          |     |                  | 1867.2      |                    |         | 0            |
|                  | 3215974-1                                                               | 432           | AFL | TSN:629     | 487             |     |                  | 630         |                    |         | 0            |
|                  |                                                                         |               | MOS | TSN:81      | 48.2            |     |                  | 05 May 2022 |                    |         |              |
|                  | Airframe                                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 361104           | Pressure Regulating and Shut-Off Valve (Left) - Removal / Installation  |               | HRS |             | 994.2           |     |                  | 2051.9      |                    |         | 0            |
|                  | 3215662-2                                                               | 1917          | AFL |             | 392             |     |                  | 725         |                    |         | 0            |
|                  |                                                                         |               | MOS |             | 40.9            |     |                  | 13 Dec 2022 |                    |         |              |
|                  | Airframe                                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 361105           | Pressure Regulating and Shut-Off Valve (Right) - Removal / Installation |               | HRS | TSN:1867.2  | 1178.9          |     |                  | 1867.2      |                    |         | 0            |
|                  | 3215662-2                                                               | 1917          | AFL | TSN:630     | 487             |     |                  | 630         |                    |         | 0            |
|                  |                                                                         |               | MOS | TSN:81      | 48.2            |     |                  | 05 May 2022 |                    |         |              |
|                  | Airframe                                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 361108           | Hp Stage 5 AIR Nonreturn Valve (Left) - Removal / Installation          |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 3202908-2                                                               | 998           | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                         |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |

| ATA<br>U=Custom                | Description                                                            |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|--------------------------------|------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                | Part Number                                                            | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position               | HW                                                                     | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                | MM Ref                                                                 |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                                | Ops Number(s)                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| 361109                         | Hp Stage 5 AIR Nonreturn Valve (Right) - Removal / Installation        |               | HRS |             | 1178.9          |     |                  | 1867.2      |                    |         | 0            |
|                                |                                                                        |               | AFL |             | 487             |     |                  | 630         |                    |         | 0            |
|                                | 3202908-2                                                              | 702           | MOS |             | 48.2            |     |                  | 06 May 2022 |                    |         |              |
|                                |                                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                       |                                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 361110                         | Hp Stage 5 AIR Nonreturn Valve (Left) - Restore                        |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                                        |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                | 3202908-2                                                              | 998           | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                |                                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                       |                                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 361108 |                                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 361111                         | Hp Stage 5 AIR Nonreturn Valve (Right) - Restore                       |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                |                                                                        |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                | 3202908-2                                                              | 702           | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                |                                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                       |                                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 361109 |                                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 361112                         | Hp Stage 5 Bleed AIR Duct (Left) - Removal / Installation              |               | HRS |             | 994.2           |     |                  | 2051.9      |                    |         | 0            |
|                                | RD001C0006-1011                                                        | SN-UNKNOWN    | AFL |             | 392             |     |                  | 725         |                    |         | 0            |
|                                |                                                                        |               | MOS |             | 41.1            |     |                  | 07 Dec 2022 |                    |         |              |
|                                |                                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                       |                                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 361113                         | Hp Stage 5 Bleed AIR Duct (Right) - Removal / Installation             |               | HRS |             | 994.2           |     |                  | 2051.9      |                    |         | 0            |
|                                | RD001C0006-1011                                                        | NSN           | AFL |             | 392             |     |                  | 725         |                    |         | 0            |
|                                |                                                                        |               | MOS |             | 40.9            |     |                  | 13 Dec 2022 |                    |         |              |
|                                |                                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                       |                                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 361116                         | Hp Stage 5 / Stage 8 Interface Y-Duct (Left) - Removal / Installation  |               | HRS |             | 994.2           |     |                  | 2051.9      |                    |         | 0            |
|                                |                                                                        |               | AFL |             | 392             |     |                  | 725         |                    |         | 0            |
|                                | RD001C0006-1003                                                        | SN-UNKNOWN    | MOS |             | 41.1            |     |                  | 08 Dec 2022 |                    |         |              |
|                                |                                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                       |                                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 361117                         | Hp Stage 5 / Stage 8 Interface Y-Duct (Right) - Removal / Installation |               | HRS |             | 994.2           |     |                  | 2051.9      |                    |         | 0            |
|                                |                                                                        |               | AFL |             | 392             |     |                  | 725         |                    |         | 0            |
|                                | RD001C0006-1003                                                        | SN-UNKNOWN    | MOS |             | 40.9            |     |                  | 13 Dec 2022 |                    |         |              |
|                                |                                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                       |                                                                        |               |     |             |                 |     |                  |             |                    |         |              |



| ATA<br>U=Custom  | Description                                                |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                         | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                     |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                              |               |     |             |                 |     |                  |             |                    |         |              |
| 361120           | Hp Stage 8 Bleed AIR Duct (Left) - Removal / Installation  |               | HRS |             | 994.2           |     |                  | 2051.9      |                    |         | 0            |
|                  | RD001C0006-1013 SN-UNKNOWN                                 |               | AFL |             | 392             |     |                  | 725         |                    |         | 0            |
|                  |                                                            |               | MOS |             | 41.2            |     |                  | 06 Dec 2022 |                    |         |              |
|                  | Airframe                                                   |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 361121           | Hp Stage 8 Bleed AIR Duct (Right) - Removal / Installation |               | HRS |             | 994.2           |     |                  | 2051.9      |                    |         | 0            |
|                  | RD001C0006-1013 NSN                                        |               | AFL |             | 392             |     |                  | 725         |                    |         | 0            |
|                  |                                                            |               | MOS |             | 40.9            |     |                  | 13 Dec 2022 |                    |         |              |
|                  | Airframe                                                   |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 361124           | Combined Bleed AIR Duct (Left) - Removal / Installation    |               | HRS |             | 994.2           |     |                  | 2051.9      |                    |         | 0            |
|                  | RD001C0006-1004 SN-UNKNOWN                                 |               | AFL |             | 392             |     |                  | 725         |                    |         | 0            |
|                  |                                                            |               | MOS |             | 41.1            |     |                  | 08 Dec 2022 |                    |         |              |
|                  | Airframe                                                   |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 361125           | Combined Bleed AIR Duct (Right) - Removal / Installation   |               | HRS |             | 994.2           |     |                  | 2051.9      |                    |         | 0            |
|                  | RD001C0006-1004 SN-UNKNOWN                                 |               | AFL |             | 392             |     |                  | 725         |                    |         | 0            |
|                  |                                                            |               | MOS |             | 40.9            |     |                  | 13 Dec 2022 |                    |         |              |
|                  | Airframe                                                   |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 361128           | Handed Bleed AIR Duct (Left) - Removal / Installation      |               | HRS |             | 994.2           |     |                  | 2051.9      |                    |         | 0            |
|                  | RD001C0006-1007 SN-UNKNOWN                                 |               | AFL |             | 392             |     |                  | 725         |                    |         | 0            |
|                  |                                                            |               | MOS |             | 41.1            |     |                  | 08 Dec 2022 |                    |         |              |
|                  | Airframe                                                   |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 361129           | Handed Bleed AIR Duct (Right) - Removal / Installation     |               | HRS |             | 994.2           |     |                  | 2051.9      |                    |         | 0            |
|                  | RD001C0006-1007 SN-UNKNOWN                                 |               | AFL |             | 392             |     |                  | 725         |                    |         | 0            |
|                  |                                                            |               | MOS |             | 40.9            |     |                  | 13 Dec 2022 |                    |         |              |
|                  | Airframe                                                   |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 361132           | Precooler AIR Off-Take (Left) - Removal / Installation     |               | HRS |             | 994.4           |     |                  | 2051.7      |                    |         | 0            |
|                  | RD001C0006-4003 SN-UNKNOWN                                 |               | AFL |             | 392             |     |                  | 725         |                    |         | 0            |
|                  |                                                            |               | MOS |             | 40.9            |     |                  | 15 Dec 2022 |                    |         |              |
|                  | Airframe                                                   |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 361133           | Precooler AIR Off-Take (Right) - Removal / Installation    |               | HRS |             | 994.2           |     |                  | 2051.9      |                    |         | 0            |
|                  | RD001C0006-4003 230813-003                                 |               | AFL |             | 392             |     |                  | 725         |                    |         | 0            |
|                  |                                                            |               | MOS |             | 41.1            |     |                  | 09 Dec 2022 |                    |         |              |
|                  | Airframe                                                   |               | MSC |             |                 |     | O/C              |             |                    |         |              |

| ATA<br>U=Custom  | Description                                               |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-----------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                               | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                        | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                    |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 361136           | Precooler AIR Duct (Left) - Removal / Installation        |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | RD001C0006-4002                                           | SN-UNKNOWN    | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                           |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 361137           | Precooler AIR Duct (Right) - Removal / Installation       |               | HRS | TSN:1867.2  | 1178.9          |     |                  | 1867.2      |                    |         | 0            |
|                  | RD001C0006-4002                                           | SN-UNKNOWN    | AFL | TSN:630     | 487             |     |                  | 630         |                    |         | 0            |
|                  |                                                           |               | MOS | TSN:81      | 48.2            |     |                  | 05 May 2022 |                    |         |              |
|                  | Airframe                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 361140           | Bleed AIR Ducts (Left) - Inspection                       |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                           |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                           |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 361141           | Bleed AIR Ducts (Right) - Inspection                      |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                           |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                           |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 361142           | Precooler AIR Duct (Left) - Inspection / Check            |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                           |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                           |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 361143           | Precooler AIR Duct (Right) - Inspection / Check           |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                           |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                           |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 361144           | High Stage 8 Check Valve (Left) - Removal / Installation  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 3215974-1                                                 | SN-UNKNOWN    | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                           |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 361145           | High Stage 8 Check Valve (Right) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 3215974-1                                                 | SN-UNKNOWN    | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                           |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                              |               | UOM            | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|--------------------------------------------------------------------------|---------------|----------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                              | Serial Number |                |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                       | SW            |                |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                   |               |                |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                            |               |                |             |                 |     |                  |             |                    |         |              |
| 361148           | Cabin AIR Ducts and Insulation Blankets - Inspection                     |               | HRS            |             | 994.2           |     |                  | 2051.9      |                    |         | 0            |
|                  |                                                                          |               | AFL            |             | 392             |     |                  | 725         |                    |         | 0            |
|                  |                                                                          |               | MOS            |             | 41.1            |     |                  | 09 Dec 2022 |                    |         |              |
|                  | Airframe                                                                 |               | MSC            |             |                 |     | O/C              |             |                    |         |              |
| 361200           | Bleed AIR Isolation Shut-Off Valve - Removal / Installation              |               | HRS            |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 3291826-1                                                                | 1037          | AFL            |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                          |               | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                                 |               | MSC            |             |                 |     | O/C              |             |                    |         |              |
| 361201           | Bleed AIR Controller (Left) - Removal / Installation                     |               | HRS            |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 1153482-3                                                                | 1153482-00877 | AFL            |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                          |               | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                                 |               | MSC            |             |                 |     | O/C              |             |                    |         |              |
| 361202           | Bleed AIR Controller (Right) - Removal / Installation                    |               | HRS            |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 1153482-3                                                                | 1153482-00871 | AFL            |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                          |               | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                                 |               | MSC            |             |                 |     | O/C              |             |                    |         |              |
| 361206           | Bleed AIR Isolation Shut-Off Valve - Manual Override                     |               | HRS            |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                          |               | AFL            |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                          |               | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                                 |               | MSC            |             |                 |     | O/C              |             |                    |         |              |
| 361207           | APU Check Valve - Removal / Installation                                 |               | HRS            |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 3202754-1                                                                | 2014          | AFL            |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                          |               | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                                 |               | MSC            |             |                 |     | O/C              |             |                    |         |              |
| 361209           | APU Check Valve - Detailed Inspection                                    |               | HRS            |             | 3046.1          |     | 4800             | 0           | 4800               | 4850    | 0            |
|                  |                                                                          |               | AFL            |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                          |               | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                                 |               | [HRS: +50/-50] |             |                 |     |                  |             |                    |         |              |
|                  | 052006                                                                   |               |                |             |                 |     |                  |             |                    |         |              |
| 361210           | Bleed AIR Flow Control and Pressure Regulation (Left) - Operational Test |               | HRS            |             | 994.2           |     |                  | 2051.9      |                    |         | 0            |
|                  |                                                                          |               | AFL            |             | 392             |     |                  | 725         |                    |         | 0            |
|                  |                                                                          |               | MOS            |             | 40.9            |     |                  | 15 Dec 2022 |                    |         |              |
|                  | Airframe                                                                 |               | MSC            |             |                 |     | O/C              |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                                                                                      |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|--------------------------------------------------------------------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                                                                                      | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                                                                                               | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                                                                                           |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                                                                                                    |               |     |             |                 |     |                  |             |                    |         |              |
| 361211           | Bleed AIR Flow Control and Pressure Regulation (Right) -<br>Operational Test                                                                     |               | HRS |             | 994.2           |     |                  | 2051.9      |                    |         | 0            |
|                  |                                                                                                                                                  |               | AFL |             | 392             |     |                  | 725         |                    |         | 0            |
|                  |                                                                                                                                                  |               | MOS |             | 40.9            |     |                  | 15 Dec 2022 |                    |         |              |
|                  |                                                                                                                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                                                                                  |               |     |             |                 |     |                  |             |                    |         |              |
| 361212           | Servo Pressure Regulator / Torque Motor (Left) - Detailed<br>Inspection                                                                          |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                                                                  |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                                                                  |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                                                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                                                                                  |               |     |             |                 |     |                  |             |                    |         |              |
| 361213           | Servo Pressure Regulator / Torque Motor (Right) -<br>Detailed Inspection                                                                         |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                                                                  |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                                                                  |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                                                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                                                                                  |               |     |             |                 |     |                  |             |                    |         |              |
| 361214           | Bleed AIR System Sense Tubes (Left Hp Shutoff Valve) -<br>Removal / Installation<br>RD00104631-3                      SN-UNKNOWN                 |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                                                                  |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                                                                  |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                                                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                                                                                  |               |     |             |                 |     |                  |             |                    |         |              |
| 361215           | Bleed AIR System Sense Tubes (Right Hp Shutoff Valve) -<br>Removal / Installation<br>RD00104631-3                      SN-UNKNOWN                |               | HRS | TSN:1867.2  | 1178.9          |     |                  | 1867.2      |                    |         | 0            |
|                  |                                                                                                                                                  |               | AFL | TSN:630     | 487             |     |                  | 630         |                    |         | 0            |
|                  |                                                                                                                                                  |               | MOS | TSN:81      | 48.2            |     |                  | 05 May 2022 |                    |         |              |
|                  |                                                                                                                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                                                                                  |               |     |             |                 |     |                  |             |                    |         |              |
| 361216           | Bleed AIR System Sense Tubes (Left Manifold Pressure<br>Shutoff Valve) - Removal / Installation<br>RD00104631-2                      SN-UNKNOWN  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                                                                  |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                                                                  |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                                                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                                                                                  |               |     |             |                 |     |                  |             |                    |         |              |
| 361217           | Bleed AIR System Sense Tubes (Right Manifold Pressure<br>Shutoff Valve) - Removal / Installation<br>RD00104631-2                      SN-UNKNOWN |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                                                                  |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                                                                  |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                                                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                                                                                  |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                          |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|--------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                                                          | Serial Number |     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                                                   | SW            |     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                                               |               |     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                                                        |               |     |             |                 |     |                  |             |                     |         |              |
| 361218           | Bleed AIR System Sense Tubes (Left Fan AIR Valve) - Removal / Installation           |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                                      |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | RD00104631-1                                                                         | SN-UNKNOWN    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                                      |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                      |               |     |             |                 |     |                  |             |                     |         |              |
| 361219           | Bleed AIR System Sense Tubes (Right Fan AIR Valve, Inboard) - Removal / Installation |               | HRS | TSN:1867.2  | 1178.9          |     |                  | 1867.2      |                     |         | 0            |
|                  |                                                                                      |               | AFL | TSN:630     | 487             |     |                  | 630         |                     |         | 0            |
|                  | RD00104632-2                                                                         | SN-UNKNOWN    | MOS | TSN:81      | 48.2            |     |                  | 05 May 2022 |                     |         |              |
|                  |                                                                                      |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                      |               |     |             |                 |     |                  |             |                     |         |              |
| 361220           | Bleed AIR System Sense Tubes (Right Fan AIR Valve, Mid) - Removal / Installation     |               | HRS | TSN:1867.2  | 1178.9          |     |                  | 1867.2      |                     |         | 0            |
|                  |                                                                                      |               | AFL | TSN:630     | 487             |     |                  | 630         |                     |         | 0            |
|                  | RD00104632-4                                                                         | SN-UNKNOWN    | MOS | TSN:81      | 48.2            |     |                  | 05 May 2022 |                     |         |              |
|                  |                                                                                      |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                      |               |     |             |                 |     |                  |             |                     |         |              |
| 361221           | Bleed AIR System Sense Tubes (Right Fan AIR Valve, Y-Duct) - Removal / Installation  |               | HRS | TSN:1867.2  | 1178.9          |     |                  | 1867.2      |                     |         | 0            |
|                  |                                                                                      |               | AFL | TSN:630     | 487             |     |                  | 630         |                     |         | 0            |
|                  | RD00104632-1                                                                         | SN-UNKNOWN    | MOS | TSN:81      | 48.2            |     |                  | 05 May 2022 |                     |         |              |
|                  |                                                                                      |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                      |               |     |             |                 |     |                  |             |                     |         |              |
| 361401           | Fan AIR Valve (Left) - Removal / Installation                                        |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  | 3291954-2 497                                                                        |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  |                                                                                      |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                                      |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                      |               |     |             |                 |     |                  |             |                     |         |              |
| 361402           | Fan AIR Valve (Right) - Removal / Installation                                       |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  | 3291954-2 466                                                                        |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  |                                                                                      |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                                      |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                      |               |     |             |                 |     |                  |             |                     |         |              |
| 361403           | Bleed AIR Precooler (Left) - Removal / Installation                                  |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  | 2341172-1 1033                                                                       |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  |                                                                                      |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                                      |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                      |               |     |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom  | Description                                                          |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                          | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                   | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                               |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 361404           | Bleed AIR Precooler (Right) - Removal / Installation                 |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 2341172-2                                                            | 1032          | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                      |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                             |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 361405           | Precooler Inlet Temperature Sensor (Left) - Removal / Installation   |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                      |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 1150124-2                                                            | 1150124-11520 | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                             |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 361406           | Precooler Inlet Temperature Sensor (Right) - Removal / Installation  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                      |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 1150124-2                                                            | 1150124-12925 | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                             |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 361407           | Precooler Outlet Temperature Sensor (Left) - Removal / Installation  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                      |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 1150124-2                                                            | SN-UNKNOWN    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                             |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 361408           | Precooler Outlet Temperature Sensor (Right) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                      |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 1150124-2                                                            | SN-UNKNOWN    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                             |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 361417           | Fan AIR Valve (Left) - Functional Check                              |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                      |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                      |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                             |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 361418           | Fan AIR Valve (Right) - Functional Check                             |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                      |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                      |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                             |               | MSC |             |                 |     | O/C              |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                  |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|--------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                  | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                           | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                       |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                |               |     |             |                 |     |                  |             |                    |         |              |
| 361419           | Bleed AIR Precooler (Left) - Cleaning                        |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                              |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                              |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                     |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 361420           | Bleed AIR Precooler (Right) - Cleaning                       |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                              |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                              |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                     |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 361600           | External AIR Connector - Removal / Installation              |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 4663                                                         | SN-UNKNOWN    | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                              |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                     |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 361602           | External AIR Connector Check Valve - Removal / Installation  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                              |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 3202754-1                                                    | 2003          | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                     |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 361606           | External AIR Connector Duct (Lower) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                              |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | GA0236160213-1                                               | SN-UNKNOWN    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                     |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 361607           | External AIR Connector Duct (Mid) - Removal / Installation   |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                              |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | GA0236160212-1                                               | SN-UNKNOWN    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                     |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 361608           | External AIR Connector Duct (Upper) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                              |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | GA0236160210-1                                               | SN-UNKNOWN    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                     |               | MSC |             |                 |     | O/C              |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                       |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                       | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                            |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| 361612           | Manifold Lower Bleed AIR Duct (Left) - Removal / Installation     |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                   |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P3616001A004                                                    | SN-UNKNOWN    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                   |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                   |               |     |             |                 |     |                  |             |                    |         |              |
| 361613           | Manifold Lower Bleed AIR Duct (Right) - Removal / Installation    |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                   |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P3616001A005                                                    | SN-UNKNOWN    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                   |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                   |               |     |             |                 |     |                  |             |                    |         |              |
| 361616           | Manifold Crossover AIR Duct (Left) - Removal / Installation       |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                   |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | GA236160102-5                                                     | SN-UNKNOWN    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                   |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                   |               |     |             |                 |     |                  |             |                    |         |              |
| 361617           | Manifold Crossover AIR Duct (Right) - Removal / Installation      |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                   |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | GA236160102-7                                                     | SN-UNKNOWN    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                   |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                   |               |     |             |                 |     |                  |             |                    |         |              |
| 361620           | Pack Inlet Supply AIR Duct (Left) - Removal / Installation        |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | GA236160106-1                                                     |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                   |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                   |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                   |               |     |             |                 |     |                  |             |                    |         |              |
| 361621           | Pack Inlet Supply AIR Duct (Right) - Removal / Installation       |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | GA236160103-1                                                     |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                   |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                   |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                   |               |     |             |                 |     |                  |             |                    |         |              |
| 361624           | Precooler Ducting (Left Precooler Inlet) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                   |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | GA0236160001-1                                                    | SN-UNKNOWN    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                   |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                   |               |     |             |                 |     |                  |             |                    |         |              |



| ATA<br>U=Custom  | Description                                                         |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|---------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                         | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                  | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                              |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| 361625           | Precooler Ducting (Left Precooler Outlet) - Removal / Installation  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                     |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | GA0236160002-1                                                      | SN-UNKNOWN    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                     |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| 361626           | Precooler Ducting (Left Fan AIR Valve) - Removal / Installation     |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                     |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | GA0236160003-1                                                      | SN-UNKNOWN    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                     |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| 361627           | Precooler Ducting (Left Outflow) - Removal / Installation           |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | GA0236160004-1                                                      |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                     |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                     |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| 361632           | Precooler Ducting (Right Precooler Inlet) - Removal / Installation  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                     |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | GA0236160001-1                                                      | SN-UNKNOWN    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                     |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| 361633           | Precooler Ducting (Right Precooler Outlet) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                     |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | GA0236160002-1                                                      | SN-UNKNOWN    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                     |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| 361634           | Precooler Ducting (Right Fan AIR Valve) - Removal / Installation    |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                     |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | GA0236160003-2                                                      | SN-UNKNOWN    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                     |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| 361635           | Precooler Ducting (Right Outflow) - Removal / Installation          |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | GA0236160004-11                                                     |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                     |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                     |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                     |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom     | Description                                                          |                                    | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W                             | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|---------------------|----------------------------------------------------------------------|------------------------------------|-----|-------------|-----------------|-----|------------------|--------------------------------------|--------------------|---------|--------------|
|                     | Part Number                                                          | Serial Number                      |     |             |                 |     |                  |                                      |                    |         | Approx Price |
| Logbook Position    | HW                                                                   | SW                                 |     |             |                 |     |                  |                                      |                    |         | Manufacturer |
|                     | MM Ref                                                               |                                    |     |             |                 |     |                  |                                      |                    |         | Date Type    |
|                     | Ops Number(s)                                                        |                                    |     |             |                 |     |                  |                                      |                    |         |              |
| 362100              | Manifold Pressure Sensor (Left) - Removal / Installation             |                                    | HRS |             | 3046.1          |     |                  | 0                                    |                    |         | 0            |
|                     | 1151584-1                                                            | 1151584-07389                      | AFL |             | 1117            |     |                  | 0                                    |                    |         | 0            |
|                     |                                                                      |                                    | MOS |             | 128.6           |     |                  | 24 Aug 2015                          |                    |         |              |
|                     | Airframe                                                             |                                    | MSC |             |                 |     | O/C              |                                      |                    |         |              |
| 362101              | Manifold Pressure Sensor (Right) - Removal / Installation            |                                    | HRS |             | 3046.1          |     |                  | 0                                    |                    |         | 0            |
|                     | 1151584-1                                                            | 1151584-07419                      | AFL |             | 1117            |     |                  | 0                                    |                    |         | 0            |
|                     |                                                                      |                                    | MOS |             | 128.6           |     |                  | 24 Aug 2015                          |                    |         |              |
|                     | Airframe                                                             |                                    | MSC |             |                 |     | O/C              |                                      |                    |         |              |
| 38 - Water/Waste    |                                                                      |                                    |     |             |                 |     |                  |                                      |                    |         |              |
| 381000              | Water System - Operational Test                                      |                                    | HRS |             | 137             |     |                  | 2909.1                               |                    |         | 0            |
|                     |                                                                      |                                    | AFL |             | 52              |     |                  | 1065                                 |                    |         | 0            |
|                     |                                                                      |                                    | MOS |             | 4.8             |     |                  | 18 Dec 2025                          |                    |         |              |
|                     | Airframe                                                             |                                    | MSC |             |                 |     | O/C              |                                      |                    |         |              |
| 381002              | Potable Water System (System A) - Cleaning / Sanitizing              |                                    | HRS |             | 2673.8          |     |                  | 372.3                                |                    |         | 0            |
|                     |                                                                      |                                    | AFL |             | 1020            |     |                  | 97                                   |                    |         | 0            |
|                     |                                                                      |                                    | MOS |             | 109.7           |     |                  | 21 Mar 2017                          |                    |         |              |
|                     | Airframe                                                             |                                    | MSC |             |                 |     | O/C              |                                      |                    |         |              |
| 381003              | Potable Water System (System B) - Cleaning / Sanitizing              |                                    | HRS |             | 2673.8          |     |                  | 372.3                                |                    |         | 0            |
|                     |                                                                      |                                    | AFL |             | 1020            |     |                  | 97                                   |                    |         | 0            |
|                     |                                                                      |                                    | MOS |             | 109.7           |     |                  | 21 Mar 2017                          |                    |         |              |
|                     | Airframe                                                             |                                    | MSC |             |                 |     | O/C              |                                      |                    |         |              |
| 381004 <sup>U</sup> | Shower Water System - Cleaning/Sanitisation                          |                                    | HRS |             | 137             |     |                  | 2909.1                               |                    |         | 0            |
|                     |                                                                      |                                    | AFL |             | 52              |     |                  | 1065                                 |                    |         | 0            |
|                     |                                                                      |                                    | MOS |             | 4.8             | -22 | 12               | 18 Dec 2025 30 Nov 2026* 31 Dec 2026 |                    |         |              |
|                     | Airframe                                                             | [End Of Month Item] [MOS: +1m/-1m] |     |             |                 |     |                  |                                      |                    |         |              |
| 381200              | Water System Level Indicators - Operational Test                     |                                    | HRS |             | 2120.8          |     |                  | 925.3                                |                    |         | 0            |
|                     |                                                                      |                                    | AFL |             | 861             |     |                  | 256                                  |                    |         | 0            |
|                     |                                                                      |                                    | MOS |             | 86.1            |     |                  | 09 Mar 2019                          |                    |         |              |
|                     | Airframe                                                             |                                    | MSC |             |                 |     | O/C              |                                      |                    |         |              |
| 381203              | Level Sensor Assembly (System A, Half Full) - Removal / Installation |                                    | HRS |             | 2120.8          |     |                  | 925.3                                |                    |         | 0            |
|                     |                                                                      |                                    | AFL |             | 861             |     |                  | 256                                  |                    |         | 0            |
|                     | 3E3723-1                                                             | NSN                                | MOS |             | 86.2            |     |                  | 05 Mar 2019                          |                    |         |              |
|                     | Airframe                                                             |                                    | MSC |             |                 |     | O/C              |                                      |                    |         |              |

| ATA<br>U=Custom                                              | Description                                                                          |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|--------------------------------------------------------------|--------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                                              | Part Number                                                                          | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position                                             | HW                                                                                   | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                                              | MM Ref                                                                               |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                                                              | Ops Number(s)                                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 381211                                                       | Water System Level Indicator (Internal) - Removal / Installation                     |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                                              |                                                                                      |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                                              | 4E4884-2                                                                             | UA810         | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                                              |                                                                                      |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                                                     |                                                                                      |               |     |             |                 |     |                  |             |                    |         |              |
| 381212                                                       | Water System Level Indicator (External) - Removal / Installation                     |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                                              |                                                                                      |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                                              | 4E4884-1                                                                             | UA659         | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                                              |                                                                                      |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                                                     |                                                                                      |               |     |             |                 |     |                  |             |                    |         |              |
| 381215                                                       | Water Sterilizer Quartz Glass Sleeve (System A) - Removal / Installation             |               | HRS | TSN:2373.5  | 672.6           |     |                  | 2373.5      |                    |         | 0            |
|                                                              |                                                                                      |               | AFL | TSN:818     | 299             |     |                  | 818         |                    |         | 0            |
|                                                              | 09-130121-303                                                                        | 1358          | MOS | TSN:104     | 26.5            |     |                  | 26 Feb 2024 |                    |         |              |
|                                                              |                                                                                      |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                                                     |                                                                                      |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 381225                               |                                                                                      |               |     |             |                 |     |                  |             |                    |         |              |
| 381216                                                       | Water Sterilizer Quartz Glass Sleeve (System B) - Removal / Installation             |               | HRS | TSN:2373.5  | 672.6           |     |                  | 2373.5      |                    |         | 0            |
|                                                              |                                                                                      |               | AFL | TSN:818     | 299             |     |                  | 818         |                    |         | 0            |
|                                                              | 09-130121-303                                                                        | 1382          | MOS | TSN:104     | 26.5            |     |                  | 26 Feb 2024 |                    |         |              |
|                                                              |                                                                                      |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                                                     |                                                                                      |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: MRI PARENT CODE: 381226                               |                                                                                      |               |     |             |                 |     |                  |             |                    |         |              |
| 381219                                                       | Clean Water Sterilizer Quartz Glass Sleeve and Uv Sensor Window (System A) - Restore |               | HRS |             | 137             |     | 800              | 2909.1      | 3709.1             |         | 0            |
|                                                              |                                                                                      |               | AFL |             | 52              |     |                  | 1065        |                    |         | 0            |
|                                                              |                                                                                      |               | MOS |             | 5               |     |                  | 12 Dec 2025 |                    |         |              |
| Airframe                                                     |                                                                                      |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: PN: 02-100102-004 SN: <NONE>. MRI PARENT CODE: 381225 |                                                                                      |               |     |             |                 |     |                  |             |                    |         |              |
| 381220                                                       | Clean Water Sterilizer Quartz Glass Sleeve and Uv Sensor Window (System B) - Restore |               | HRS |             | 137             |     | 800              | 2909.1      | 3709.1             |         | 0            |
|                                                              |                                                                                      |               | AFL |             | 52              |     |                  | 1065        |                    |         | 0            |
|                                                              |                                                                                      |               | MOS |             | 5               |     |                  | 12 Dec 2025 |                    |         |              |
| Airframe                                                     |                                                                                      |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: PN: 02-100102-004 SN: <NONE>. MRI PARENT CODE: 381226 |                                                                                      |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                          |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due                       | Avg Man Hrs  |
|------------------|----------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|-------------------------------|--------------|
|                  | Part Number                                                          | Serial Number |     |             |                 |     |                  |             |                    |                               | Approx Price |
| Logbook Position | HW                                                                   | SW            |     |             |                 |     |                  |             |                    |                               | Manufacturer |
|                  | MM Ref                                                               |               |     |             |                 |     |                  |             |                    |                               | Date Type    |
|                  | Ops Number(s)                                                        |               |     |             |                 |     |                  |             |                    |                               |              |
| 381221           | Water Sterilizer Filter (System A) - Removal / Installation          |               | HRS |             | 137             |     |                  | 2909.1      |                    |                               | 0            |
|                  | 05-01-0001                                                           | NSN           | AFL |             | 52              |     |                  | 1065        |                    |                               | 0            |
|                  |                                                                      |               | MOS | TSN:8       | 5               |     |                  | 12 Dec 2025 |                    |                               |              |
|                  | Airframe                                                             |               |     | MSC         |                 |     |                  | O/C         |                    |                               |              |
| 381222           | Water Sterilizer Filter (System B) - Removal / Installation          |               | HRS |             | 137             |     |                  | 2909.1      |                    |                               | 0            |
|                  | 05-01-0001                                                           | NSN           | AFL |             | 52              |     |                  | 1065        |                    |                               | 0            |
|                  |                                                                      |               | MOS | TSN:8       | 5               |     |                  | 12 Dec 2025 |                    |                               |              |
|                  | Airframe                                                             |               |     | MSC         |                 |     |                  | O/C         |                    |                               |              |
| 381225           | Water Sterilizer (System A) - Removal / Installation                 |               | HRS |             | 672.6           |     |                  | 2373.5      |                    |                               | 0            |
|                  | 09-130121-303                                                        | 1358          | AFL |             | 299             |     |                  | 818         |                    |                               | 0            |
|                  |                                                                      |               | MOS |             | 26.5            |     |                  | 26 Feb 2024 |                    |                               |              |
|                  | Airframe                                                             |               |     | MSC         |                 |     |                  | O/C         |                    |                               |              |
| 381226           | Water Sterilizer (System B) - Removal / Installation                 |               | HRS |             | 672.6           |     |                  | 2373.5      |                    |                               | 0            |
|                  | 09-130121-303                                                        | 1436          | AFL |             | 299             |     |                  | 818         |                    |                               | 0            |
|                  |                                                                      |               | MOS |             | 26.5            |     |                  | 26 Feb 2024 |                    |                               |              |
|                  | Airframe                                                             |               |     | MSC         |                 |     |                  | O/C         |                    |                               |              |
| 381229           | Water Sterilizer Germicidal Lamp (System A) - Removal / Installation |               | HRS | TSN:925.3   | 2120.8          |     |                  | 925.3       |                    |                               | 0            |
|                  |                                                                      |               | AFL | TSN:256     | 861             |     |                  | 256         |                    |                               | 0            |
|                  | 08-130800-003                                                        | NSN           | MOS | TSN:42      | 86.5            |     |                  | 28 Feb 2019 |                    |                               |              |
|                  | Airframe                                                             |               |     | MSC         |                 |     |                  | O/C         |                    |                               |              |
| 381230           | Water Sterilizer Germicidal Lamp (System B) - Removal / Installation |               | HRS | TSN:925.3   | 2120.8          |     |                  | 925.3       |                    |                               | 0            |
|                  |                                                                      |               | AFL | TSN:256     | 861             |     |                  | 256         |                    |                               | 0            |
|                  | 08-130800-003                                                        | NSN           | MOS | TSN:43      | 86.3            |     |                  | 01 Mar 2019 |                    |                               |              |
|                  | Airframe                                                             |               |     | MSC         |                 |     |                  | O/C         |                    |                               |              |
| 381233           | Water Sterilizer Germicidal Lamp (System A) - Discard                |               | HRS |             | 3046.1          |     | 4500             | 0           | 4500               |                               | 0            |
|                  | 08-130800-003                                                        | NSN           | AFL |             | 1117            |     |                  | 0           |                    |                               | 0            |
|                  |                                                                      |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    | International Water<br>-Guard |              |
| Airframe         |                                                                      |               |     |             |                 |     |                  |             |                    |                               |              |

Notes: MRI PARENT CODE: 381229

| ATA<br>U=Custom                            | Description                                                                           |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs         |
|--------------------------------------------|---------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|---------------------|---------|---------------------|
|                                            | Part Number                                                                           | Serial Number |     |             |                 |     |                  |             |                     |         | Approx Price        |
| Logbook Position                           | HW                                                                                    | SW            |     |             |                 |     |                  |             |                     |         | Manufacturer        |
|                                            | MM Ref                                                                                |               |     |             |                 |     |                  |             |                     |         | Date Type           |
|                                            | Ops Number(s)                                                                         |               |     |             |                 |     |                  |             |                     |         |                     |
| 381234                                     | Water Sterilizer Germicidal Lamp (System B) - Discard                                 |               | HRS |             | 3046.1          |     | 4500             | 0           | 4500                |         | 0                   |
|                                            | 08-130800-003                                                                         |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0                   |
|                                            | NSN                                                                                   |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         | International Water |
|                                            | Airframe                                                                              |               |     |             |                 |     |                  |             |                     |         | -Guard              |
| Notes: MRI PARENT CODE: 381230             |                                                                                       |               |     |             |                 |     |                  |             |                     |         |                     |
| 381239                                     | Water Sterilizer Sediment Filter Cartridge (System A, Polypropylene Filter) - Discard |               | HRS |             | 137             |     | 800              | 2909.1      | 3709.1              |         | 0                   |
|                                            | 05-01-0001                                                                            |               | AFL |             | 52              |     |                  | 1065        |                     |         | 0                   |
|                                            | NSN                                                                                   |               | MOS | TSN:8       | 5               |     |                  | 12 Dec 2025 |                     |         |                     |
|                                            | Airframe                                                                              |               |     |             |                 |     |                  |             |                     |         |                     |
| Notes: COMPLIANCE TRANSFERRED FROM 381237. |                                                                                       |               |     |             |                 |     |                  |             |                     |         |                     |
| 381240                                     | Water Sterilizer Sediment Filter Cartridge (System B, Polypropylene Filter) - Discard |               | HRS |             | 137             |     | 800              | 2909.1      | 3709.1              |         | 0                   |
|                                            | 05-01-0001                                                                            |               | AFL |             | 52              |     |                  | 1065        |                     |         | 0                   |
|                                            | NSN                                                                                   |               | MOS | TSN:8       | 5               |     |                  | 12 Dec 2025 |                     |         |                     |
|                                            | Airframe                                                                              |               |     |             |                 |     |                  |             |                     |         |                     |
| 381300                                     | Water Tank Motor Shut-Off Valve (System A V2A) - Removal / Installation               |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0                   |
|                                            | 4E4872-1                                                                              |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0                   |
|                                            | N1508603                                                                              |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |                     |
|                                            |                                                                                       |               | MSC |             |                 |     | O/C              |             |                     |         |                     |
| Airframe                                   |                                                                                       |               |     |             |                 |     |                  |             |                     |         |                     |
| 381301                                     | Water Tank Motor Shut-Off Valve (System B V2B) - Removal / Installation               |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0                   |
|                                            | 4E4872-2                                                                              |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0                   |
|                                            | N1508301                                                                              |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |                     |
|                                            |                                                                                       |               | MSC |             |                 |     | O/C              |             |                     |         |                     |
| Airframe                                   |                                                                                       |               |     |             |                 |     |                  |             |                     |         |                     |
| 381306                                     | Water Supply Line Motor Drain Valve (System A, V3A) - Removal / Installation          |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0                   |
|                                            | 4E4873-11                                                                             |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0                   |
|                                            | N1508607                                                                              |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |                     |
|                                            |                                                                                       |               | MSC |             |                 |     | O/C              |             |                     |         |                     |
| Airframe                                   |                                                                                       |               |     |             |                 |     |                  |             |                     |         |                     |

| ATA<br>U=Custom                 | Description                                                                  |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|---------------------------------|------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                 | Part Number                                                                  | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position                | HW                                                                           | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                 | MM Ref                                                                       |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                                 | Ops Number(s)                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| 381307                          | Water Supply Line Motor Drain Valve (System B, V3B) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                 |                                                                              |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                 | 4E4873-2                                                                     | SN-UNKNOWN    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                 |                                                                              |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                        |                                                                              |               |     |             |                 |     |                  |             |                    |         |              |
| 381314                          | Water Supply Line Motor Drain Valve (System A V4A) - Removal / Installation  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                 |                                                                              |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                 | 4E4874-11                                                                    | N1508503      | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                 |                                                                              |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                        |                                                                              |               |     |             |                 |     |                  |             |                    |         |              |
| 381315                          | Water Supply Line Motor Drain Valve (System A V11A) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                 |                                                                              |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                 | 4E4872-3                                                                     | N1505802      | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                 |                                                                              |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                        |                                                                              |               |     |             |                 |     |                  |             |                    |         |              |
| 381316                          | Water Supply Line Motor Drain Valve (System B V11B) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                 |                                                                              |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                 | 4E4873-22                                                                    | N1406901      | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                 |                                                                              |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                        |                                                                              |               |     |             |                 |     |                  |             |                    |         |              |
| 381317                          | Water Supply Line Motor Drain Valve (System B V4B) - Removal / Installation  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                 |                                                                              |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                 | 4E4874-22                                                                    | N1508601      | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                 |                                                                              |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                        |                                                                              |               |     |             |                 |     |                  |             |                    |         |              |
| 381318                          | Water Supply Line Motor Drain Valve - Operational Test                       |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                 |                                                                              |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                 |                                                                              |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                 |                                                                              |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                        |                                                                              |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: PN: 4E4875-2 SN: <NONE>. |                                                                              |               |     |             |                 |     |                  |             |                    |         |              |
| 381319                          | Water Supply Line Drain Valve                                                |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                 | 4E4872-4                                                                     | N1508304      | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                 |                                                                              |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                 |                                                                              |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                        |                                                                              |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom                 | Description                                                      |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|---------------------------------|------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                 | Part Number                                                      | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position                | HW                                                               | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                 | MM Ref                                                           |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                                 | Ops Number(s)                                                    |               |     |             |                 |     |                  |             |                    |         |              |
| 381320                          | Water Drain Line Motor Drain Valve (V5) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                 |                                                                  |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                 | 4E4875-33                                                        | N1328701      | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                 |                                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                        |                                                                  |               |     |             |                 |     |                  |             |                    |         |              |
| 381322                          | Drain Line Motor Drain Valve - Operational Test                  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                 |                                                                  |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                 |                                                                  |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                 |                                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                        |                                                                  |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: PN: 4E4875-2 SN: <NONE>. |                                                                  |               |     |             |                 |     |                  |             |                    |         |              |
| 381325                          | Aft Drain Mast - Removal / Installation                          |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                 | 4E4878-6 N1511403                                                |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                 |                                                                  |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                 |                                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                        |                                                                  |               |     |             |                 |     |                  |             |                    |         |              |
| 381340                          | Water Supply Fill Port (System A) - Removal / Installation       |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                 | 3E3203-3 T2210                                                   |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                 |                                                                  |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                 |                                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                        |                                                                  |               |     |             |                 |     |                  |             |                    |         |              |
| 381341                          | Water Supply Fill Port (System B) - Removal / Installation       |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                 | 3E3203-3 T2257                                                   |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                 |                                                                  |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                 |                                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                        |                                                                  |               |     |             |                 |     |                  |             |                    |         |              |
| 381344                          | Water System Servicing Cable (System A) - Rigging                |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                 |                                                                  |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                 |                                                                  |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                 |                                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                        |                                                                  |               |     |             |                 |     |                  |             |                    |         |              |
| 381345                          | Water System Servicing Cable (System B) - Rigging                |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                 |                                                                  |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                 |                                                                  |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                 |                                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                        |                                                                  |               |     |             |                 |     |                  |             |                    |         |              |
| 381346                          | Water System Servicing Cable (System A) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                 |                                                                  |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                 | 4E4877-1                                                         | J57189-20     | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                 |                                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                        |                                                                  |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                            |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------|----------------------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                  | Part Number                                                                            | Serial Number |                                    |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position | HW                                                                                     | SW            |                                    |             |                 |     |                  |             |                    |             | Manufacturer |
|                  | MM Ref                                                                                 |               |                                    |             |                 |     |                  |             |                    |             | Date Type    |
|                  | Ops Number(s)                                                                          |               |                                    |             |                 |     |                  |             |                    |             |              |
| 381347           | Water System Servicing Cable (System B) - Removal / Installation                       |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                        |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  | 4E4877-2                                                                               | J57190-20     | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                        |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                        |               |                                    |             |                 |     |                  |             |                    |             |              |
| 381366           | Forward Water Supply Heated Line (System A, Forward Lavatory) - Removal / Installation |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                        |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  | 4E4882-111                                                                             | AU35          | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                        |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                        |               |                                    |             |                 |     |                  |             |                    |             |              |
| 381400           | Conformal Water Tank (System A) - Removal / Installation                               |               | HRS                                | TSN:925.3   | 2120.8          |     |                  | 925.3       |                    |             | 0            |
|                  | 4E4979-1                                                                               | N1512001      | AFL                                | TSN:256     | 861             |     |                  | 256         |                    |             | 0            |
|                  |                                                                                        |               | MOS                                | TSN:43      | 86.2            |     |                  | 05 Mar 2019 |                    |             |              |
|                  |                                                                                        |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                        |               |                                    |             |                 |     |                  |             |                    |             |              |
| 381401           | Conformal Water Tank (System B) - Removal / Installation                               |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  | 4E4979-2                                                                               | N1310802      | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                        |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                        |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                        |               |                                    |             |                 |     |                  |             |                    |             |              |
| 381424           | Water Tank - General Visual Inspection                                                 |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                                        |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                                        |               | MOS                                |             | 28.7            |     | 48               | 21 Dec 2023 | 31 Dec 2027        | 31 Jan 2028 |              |
|                  |                                                                                        |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                        |               |                                    |             |                 |     |                  |             |                    |             |              |
| 052013           |                                                                                        |               |                                    |             |                 |     |                  |             |                    |             |              |
| 381500           | Water Tank Motor Shut-Off Valve Heater (System A, V2A) - Removal / Installation        |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                        |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  | 4E4882-103                                                                             | Z711          | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                        |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                        |               |                                    |             |                 |     |                  |             |                    |             |              |
| 381501           | Water Tank Motor Shut-Off Valve Heater (System B, V2B) - Removal / Installation        |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                        |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  | 4E4882-108                                                                             | AU30          | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                        |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                        |               |                                    |             |                 |     |                  |             |                    |             |              |



| ATA<br>U=Custom  | Description                                                                                   |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-----------------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                                   | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                                            | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                                        |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                                                 |               |     |             |                 |     |                  |             |                    |         |              |
| 381504           | Water Supply Line Drain Fitting Heater - Removal / Installation                               |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                               |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 4E4887-104                                                                                    | W928          | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                               |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                               |               |     |             |                 |     |                  |             |                    |         |              |
| 381505           | Water Drain Line Motor Drain Valve Heater (V5) - Removal / Installation                       |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                               |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 4E4882-102                                                                                    | AM85          | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                               |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                               |               |     |             |                 |     |                  |             |                    |         |              |
| 381508           | Water Supply Line Motor Drain Valve Heater (System A, V4A) - Removal / Installation           |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                               |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 4E4882-105                                                                                    | AU98          | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                               |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                               |               |     |             |                 |     |                  |             |                    |         |              |
| 381509           | Water Supply Line Motor Drain Valve Heater (System B, V4B) - Removal / Installation           |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                               |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 4E4882-101                                                                                    | AW78          | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                               |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                               |               |     |             |                 |     |                  |             |                    |         |              |
| 381510           | Water Supply Line Motor Drain Valve Heater (System A, V3A) - Removal / Installation           |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                               |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 4E4882-106                                                                                    | AU27          | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                               |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                               |               |     |             |                 |     |                  |             |                    |         |              |
| 381511           | Water Supply Line Motor Drain Valve Heater (System B, V3B) - Removal / Installation           |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                               |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 4E4882-109                                                                                    | AE07          | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                               |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                               |               |     |             |                 |     |                  |             |                    |         |              |
| 381512           | Water Supply Line Innerline Heater (System A, Left Aft Supply Drain) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                               |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 4E4880-129                                                                                    | U01495        | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                               |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                               |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                                   |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|-----------------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                                                                   | Serial Number |     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                                                            | SW            |     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                                                        |               |     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                                                                 |               |     |             |                 |     |                  |             |                     |         |              |
| 381513           | Water Supply Line Innerline Heater (System B, Left Aft Supply Drain) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                                               |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 4E4880-133                                                                                    | U01484        | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                                               |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                               |               |     |             |                 |     |                  |             |                     |         |              |
| 381517           | Water System Heaters - Operational Test                                                       |               | HRS |             | 137             |     |                  | 2909.1      |                     |         | 0            |
|                  |                                                                                               |               | AFL |             | 52              |     |                  | 1065        |                     |         | 0            |
|                  |                                                                                               |               | MOS |             | 5.1             |     |                  | 09 Dec 2025 |                     |         |              |
|                  |                                                                                               |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                               |               |     |             |                 |     |                  |             |                     |         |              |
| 381520           | Aft Drain Mast Controller - Removal / Installation                                            |               | HRS |             | 730.5           |     |                  | 2315.6      |                     |         | 0            |
|                  | 4E4952-101 UG066                                                                              |               | AFL |             | 315             |     |                  | 802         |                     |         | 0            |
|                  |                                                                                               |               | MOS |             | 28.7            |     |                  | 21 Dec 2023 |                     |         |              |
|                  |                                                                                               |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                               |               |     |             |                 |     |                  |             |                     |         |              |
| 381530           | Forward Drain Port - Removal / Installation                                                   |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  | 4E4879-101 N1512502                                                                           |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  |                                                                                               |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                                               |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                               |               |     |             |                 |     |                  |             |                     |         |              |
| 381549           | Water Supply Line Innerline Heater (Forward Supply Drain) - Removal / Installation            |               | HRS |             | 2120.8          |     |                  | 925.3       |                     |         | 0            |
|                  | 4E4880-123 U04008                                                                             |               | AFL |             | 861             |     |                  | 256         |                     |         | 0            |
|                  |                                                                                               |               | MOS |             | 86.1            |     |                  | 08 Mar 2019 |                     |         |              |
|                  |                                                                                               |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                               |               |     |             |                 |     |                  |             |                     |         |              |
| 381553           | Water Drain Line Innerline Heater (Right Aft Drain) - Removal / Installation                  |               | HRS |             | 3033.8          |     |                  | 12.3        |                     |         | 0            |
|                  | 4E4880-126 U01293                                                                             |               | AFL |             | 1112            |     |                  | 5           |                     |         | 0            |
|                  |                                                                                               |               | MOS |             | 126             |     |                  | 11 Nov 2015 |                     |         |              |
|                  |                                                                                               |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                               |               |     |             |                 |     |                  |             |                     |         |              |
| 381555           | Water Drain Line Innerline Heater (Forward Drain) - Removal / Installation                    |               | HRS |             | 137             |     |                  | 2909.1      |                     |         | 0            |
|                  | 4E4880-135 U10266R                                                                            |               | AFL |             | 52              |     |                  | 1065        |                     |         | 0            |
|                  |                                                                                               |               | MOS | TSN:9       | 5.1             |     |                  | 09 Dec 2025 |                     |         |              |
|                  |                                                                                               |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                               |               |     |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom  | Description                                                                          |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|--------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                                                          | Serial Number |     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                                                   | SW            |     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                                               |               |     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                                                        |               |     |             |                 |     |                  |             |                     |         |              |
| 381564           | Water Supply Line Motor Drain Valve Heater (System A, V11A) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                                      |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 4E4882-110                                                                           | AW84          | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                                      |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                      |               |     |             |                 |     |                  |             |                     |         |              |
| 381597           | Water Heater- Removal / Installation                                                 |               | HRS |             | 3033.8          |     |                  | 12.3        |                     |         | 0            |
|                  | MRX-1000-102                                                                         | 1002-3030     | AFL |             | 1112            |     |                  | 5           |                     |         | 0            |
|                  |                                                                                      |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                     |         | DYNAMO       |
|                  |                                                                                      |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                      |               |     |             |                 |     |                  |             |                     |         |              |
| 381598           | Water Heater (Lav) - Removal / Installation                                          |               | HRS |             | 3033.8          |     |                  | 12.3        |                     |         | 0            |
|                  | MRX-1000-102                                                                         | 1002-3027     | AFL |             | 1112            |     |                  | 5           |                     |         | 0            |
|                  |                                                                                      |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                     |         | DYNAMO       |
|                  |                                                                                      |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                      |               |     |             |                 |     |                  |             |                     |         |              |
| 381599           | Water Heater (Galley) (No. 1) - Removal / Installation                               |               | HRS |             | 3033.8          |     |                  | 12.3        |                     |         | 0            |
|                  | MRX-3000-505                                                                         | 3005-215      | AFL |             | 1112            |     |                  | 5           |                     |         | 0            |
|                  |                                                                                      |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                     |         | DYNAMO       |
|                  |                                                                                      |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                      |               |     |             |                 |     |                  |             |                     |         |              |
| 381600           | Check Valve, Forward Lavatory - Removal / Installation                               |               | HRS |             | 3033.8          |     |                  | 12.3        |                     |         | 0            |
|                  | 4E4350-1                                                                             | N1325621      | AFL |             | 1112            |     |                  | 5           |                     |         | 0            |
|                  |                                                                                      |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                     |         | GOODRICH     |
|                  |                                                                                      |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                      |               |     |             |                 |     |                  |             |                     |         |              |
| 381602           | Check Valve, Aft Lavatory - Removal / Installation                                   |               | HRS |             | 3033.8          |     |                  | 12.3        |                     |         | 0            |
|                  | 4E4350-1                                                                             | N1507210      | AFL |             | 1112            |     |                  | 5           |                     |         | 0            |
|                  |                                                                                      |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                     |         | GOODRICH     |
|                  |                                                                                      |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                      |               |     |             |                 |     |                  |             |                     |         |              |
| 381604           | Check Valve, Forward Galley - Removal / Installation                                 |               | HRS |             | 3033.8          |     |                  | 12.3        |                     |         | 0            |
|                  | 4E4350-1                                                                             | N1507207      | AFL |             | 1112            |     |                  | 5           |                     |         | 0            |
|                  |                                                                                      |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                     |         | GOODRICH     |
|                  |                                                                                      |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                      |               |     |             |                 |     |                  |             |                     |         |              |
| 381606           | Check Valve, Aft Galley - Removal / Installation                                     |               | HRS |             | 3033.8          |     |                  | 12.3        |                     |         | 0            |
|                  | 4E4350-1                                                                             | N1521704      | AFL |             | 1112            |     |                  | 5           |                     |         | 0            |
|                  |                                                                                      |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                     |         | GOODRICH     |
|                  |                                                                                      |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                      |               |     |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom  | Description                                                  |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|--------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                                  | Serial Number |     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                           | SW            |     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                       |               |     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                                |               |     |             |                 |     |                  |             |                     |         |              |
| 381608           | Check Valve, Forward Galley Annex - Removal / Installation   |               | HRS |             | 3033.8          |     |                  | 12.3        |                     |         | 0            |
|                  |                                                              |               | AFL |             | 1112            |     |                  | 5           |                     |         | 0            |
|                  | 4E4350-1                                                     | N1507208      | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                     |         | GOODRICH     |
|                  |                                                              |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                              |               |     |             |                 |     |                  |             |                     |         |              |
| 381610           | Check Valve, Aft Galley Annex - Removal / Installation       |               | HRS |             | 3033.8          |     |                  | 12.3        |                     |         | 0            |
|                  | 4E4350-1                                                     |               | AFL |             | 1112            |     |                  | 5           |                     |         | 0            |
|                  |                                                              |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                     |         | GOODRICH     |
|                  |                                                              |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                              |               |     |             |                 |     |                  |             |                     |         |              |
| 381611           | Check Valve, Aft Vanity - Removal / Installation             |               | HRS |             | 3033.8          |     |                  | 12.3        |                     |         | 0            |
|                  | 4E4350-1                                                     |               | AFL |             | 1112            |     |                  | 5           |                     |         | 0            |
|                  |                                                              |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                     |         | GOODRICH     |
|                  |                                                              |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                              |               |     |             |                 |     |                  |             |                     |         |              |
| 381612           | Manual Supply Valve, Forward Galley - Removal / Installation |               | HRS |             | 3033.8          |     |                  | 12.3        |                     |         | 0            |
|                  |                                                              |               | AFL |             | 1112            |     |                  | 5           |                     |         | 0            |
|                  | 4E4474-1                                                     | N1502312      | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                     |         | GOODRICH     |
|                  |                                                              |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                              |               |     |             |                 |     |                  |             |                     |         |              |
| 381616           | Manual Drain Valve, Forward Galley - Removal / Installation  |               | HRS |             | 3033.8          |     |                  | 12.3        |                     |         | 0            |
|                  |                                                              |               | AFL |             | 1112            |     |                  | 5           |                     |         | 0            |
|                  | 4E4474-1                                                     | N1500626      | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                     |         | GOODRICH     |
|                  |                                                              |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                              |               |     |             |                 |     |                  |             |                     |         |              |
| 381624           | Manual Supply Valve, Aft Vanity - Removal / Installation     |               | HRS |             | 3033.8          |     |                  | 12.3        |                     |         | 0            |
|                  | 4E4474-1                                                     |               | AFL |             | 1112            |     |                  | 5           |                     |         | 0            |
|                  |                                                              |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                     |         | GOODRICH     |
|                  |                                                              |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                              |               |     |             |                 |     |                  |             |                     |         |              |
| 381626           | Manual Drain Valve, Aft Vanity - Removal / Installation      |               | HRS |             | 3033.8          |     |                  | 12.3        |                     |         | 0            |
|                  | 4E4474-1                                                     |               | AFL |             | 1112            |     |                  | 5           |                     |         | 0            |
|                  |                                                              |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                     |         | GOODRICH     |
|                  |                                                              |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                              |               |     |             |                 |     |                  |             |                     |         |              |
| 381628           | Coffee Drain Valve - Removal / Installation                  |               | HRS |             | 3033.8          |     |                  | 12.3        |                     |         | 0            |
|                  | 300-0015-01                                                  |               | AFL |             | 1112            |     |                  | 5           |                     |         | 0            |
|                  |                                                              |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                     |         | PARKER       |
|                  |                                                              |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                              |               |     |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom  | Description                                                         |               | UOM | Times Since                        | Time<br>Accrued | Adj | Required<br>Freq | Last C/W                 | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|---------------------------------------------------------------------|---------------|-----|------------------------------------|-----------------|-----|------------------|--------------------------|--------------------|---------|--------------|
|                  | Part Number                                                         | Serial Number |     |                                    |                 |     |                  |                          |                    |         | Approx Price |
| Logbook Position | HW                                                                  | SW            |     |                                    |                 |     |                  |                          |                    |         | Manufacturer |
|                  | MM Ref                                                              |               |     |                                    |                 |     |                  |                          |                    |         | Date Type    |
|                  | Ops Number(s)                                                       |               |     |                                    |                 |     |                  |                          |                    |         |              |
| 383100           | Vacuum Toilet (Aft) - Removal / Installation                        |               | HRS |                                    | 3046.1          |     |                  | 0                        |                    |         | 0            |
|                  | 7900446                                                             | 0140          | AFL |                                    | 1117            |     |                  | 0                        |                    |         | 0            |
|                  |                                                                     |               | MOS |                                    | 128.6           |     |                  | 24 Aug 2015              |                    |         |              |
|                  | Airframe                                                            |               | MSC |                                    |                 |     | O/C              |                          |                    |         |              |
| 383101           | Vacuum Toilet (Forward) - Removal / Installation                    |               | HRS |                                    | 3046.1          |     |                  | 0                        |                    |         | 0            |
|                  | 7900446                                                             | 0349          | AFL |                                    | 1117            |     |                  | 0                        |                    |         | 0            |
|                  |                                                                     |               | MOS |                                    | 128.6           |     |                  | 24 Aug 2015              |                    |         |              |
|                  | Airframe                                                            |               | MSC |                                    |                 |     | O/C              |                          |                    |         |              |
| 383104           | Vacuum Toilet System (Forward) - Cleaning                           |               | HRS |                                    | 137             |     |                  | 2909.1                   |                    |         | 0            |
|                  |                                                                     |               | AFL |                                    | 52              |     |                  | 1065                     |                    |         | 0            |
|                  |                                                                     |               | MOS |                                    | 5               | -16 | 12               | 12 Dec 2025 30 Nov 2026* | 31 Dec 2026        |         |              |
|                  | Airframe                                                            | 052010        |     | [End Of Month Item] [MOS: +1m/-1m] |                 |     |                  |                          |                    |         |              |
| 383105           | Vacuum Toilet System (Aft) - Cleaning                               |               | HRS |                                    | 137             |     |                  | 2909.1                   |                    |         | 0            |
|                  |                                                                     |               | AFL |                                    | 52              |     |                  | 1065                     |                    |         | 0            |
|                  |                                                                     |               | MOS |                                    | 5               | -16 | 12               | 12 Dec 2025 30 Nov 2026* | 31 Dec 2026        |         |              |
|                  | Airframe                                                            | 052010        |     | [End Of Month Item] [MOS: +1m/-1m] |                 |     |                  |                          |                    |         |              |
| 383106           | Vacuum Toilet Waste Line - Cleaning                                 |               | HRS |                                    | 137             |     |                  | 2909.1                   |                    |         | 0            |
|                  |                                                                     |               | AFL |                                    | 52              |     |                  | 1065                     |                    |         | 0            |
|                  |                                                                     |               | MOS |                                    | 5               |     |                  | 12 Dec 2025              |                    |         |              |
|                  | Airframe                                                            |               | MSC |                                    |                 |     | O/C              |                          |                    |         |              |
| 383107           | Vacuum Toilet Flush Control Unit (Forward) - Removal / Installation |               | HRS |                                    | 3046.1          |     |                  | 0                        |                    |         | 0            |
|                  | 7800551                                                             | 1515          | AFL |                                    | 1117            |     |                  | 0                        |                    |         | 0            |
|                  |                                                                     |               | MOS |                                    | 128.6           |     |                  | 24 Aug 2015              |                    |         |              |
|                  | Airframe                                                            |               | MSC |                                    |                 |     | O/C              |                          |                    |         |              |
| 383108           | Vacuum Toilet Flush Control Unit (Aft) - Removal / Installation     |               | HRS |                                    | 3046.1          |     |                  | 0                        |                    |         | 0            |
|                  | 7800551                                                             | 0296          | AFL |                                    | 1117            |     |                  | 0                        |                    |         | 0            |
|                  |                                                                     |               | MOS |                                    | 128.6           |     |                  | 24 Aug 2015              |                    |         |              |
|                  | Airframe                                                            |               | MSC |                                    |                 |     | O/C              |                          |                    |         |              |
| 383300           | Vacuum Generator - Removal / Installation                           |               | HRS |                                    | 3046.1          |     |                  | 0                        |                    |         | 0            |
|                  | 7800403-1                                                           | 0507          | AFL |                                    | 1117            |     |                  | 0                        |                    |         | 0            |
|                  |                                                                     |               | MOS |                                    | 128.6           |     |                  | 24 Aug 2015              |                    |         |              |
|                  | Airframe                                                            |               | MSC |                                    |                 |     | O/C              |                          |                    |         |              |

| ATA<br>U=Custom  | Description                                                     |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-----------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                     | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                              | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                          |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                   |               |     |             |                 |     |                  |             |                    |         |              |
| 383310           | Waste Tank - Removal / Installation                             |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 7900402-5                                                       | 0097          | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                 |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 383325           | Supply A/B/Drain 3 Way Valve (548L6) - Removal / Installation   |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  |                                                                 |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  | 4E4916-11                                                       | N1520806      | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | GOODRICH     |
|                  | Airframe                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 383327           | Sink Water Service/Drain Valve (548L1) - Removal / Installation |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  |                                                                 |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  | 4E4916-5                                                        | N1512602      | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | GOODRICH     |
|                  | Airframe                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 383328           | Supply A/B/Drain 3 Way Valve (548L2) - Removal / Installation   |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  |                                                                 |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  | 4E4916-33                                                       | N1519602      | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | GOODRICH     |
|                  | Airframe                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 383329           | Supply A/B/Drain 3 Way Valve (548L4) - Removal / Installation   |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  |                                                                 |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  | 4E4916-33                                                       | N1519601      | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | GOODRICH     |
|                  | Airframe                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 383330           | Sink Water Service/Drain Valve (548L3) - Removal / Installation |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                  |                                                                 |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                  | 4E4916-5                                                        | N1512601      | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         | GOODRICH     |
|                  | Airframe                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 384100           | AIR Compressor - Removal / Installation                         |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 4E3271-1                                                        | 15030032      | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                 |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |

| ATA<br>U=Custom                                           | Description                                                        |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|-----------------------------------------------------------|--------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                                           | Part Number                                                        | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position                                          | HW                                                                 | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                                           | MM Ref                                                             |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                                                           | Ops Number(s)                                                      |               |     |             |                 |     |                  |             |                    |         |              |
| 384101                                                    | AIR Compressor Line AIR Filter - Removal / Installation            |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                                           | 3E3291-1                                                           | 2309          | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                                           |                                                                    |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                                           | Airframe                                                           |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 384106                                                    | Bleed AIR Line AIR Filter - Removal / Installation                 |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                                           | 3E3291-1                                                           | 2313          | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                                           |                                                                    |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                                           | Airframe                                                           |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 384200                                                    | Bleed AIR Supply Shut-Off Valve - Removal / Installation           |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                                           | 4E4876-1                                                           | N1508904      | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                                           |                                                                    |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                                           | Airframe                                                           |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 384201                                                    | AIR Compressor Line Pressure Relief Valve - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                                           |                                                                    |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                                           | 4E3263-1                                                           | 4248          | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                                           | Airframe                                                           |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 44 - Cabin Systems                                        |                                                                    |               |     |             |                 |     |                  |             |                    |         |              |
| 441101                                                    | Left Gulfstream Cabin Management System Input / Output             |               | HRS |             | 1529.5          |     |                  | 1516.6      |                    |         | 0            |
|                                                           | Concentrator - Removal / Installation                              |               | AFL |             | 619             |     |                  | 498         |                    |         | 0            |
|                                                           | GCMS-02-001                                                        | 00644         | MOS |             | 66.3            |     |                  | 01 Nov 2020 |                    |         |              |
|                                                           | Airframe                                                           |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 441102                                                    | Gulfstream Cabin Management System - Adjustment / Test             |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                                           |                                                                    |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                                           |                                                                    |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                                           | Airframe                                                           |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Notes: PN: GCMS-02-001 SN: 02882. MRI PARENT CODE: 441101 |                                                                    |               |     |             |                 |     |                  |             |                    |         |              |
| 441103                                                    | Right Gulfstream Cabin Management System Input / Output            |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                                           | Concentrator - Removal / Installation                              |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                                           | GCMS-02-001                                                        | 02921         | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                                           | Airframe                                                           |               | MSC |             |                 |     | O/C              |             |                    |         |              |

| ATA<br>U=Custom              | Description                                                                    |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------------------|--------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                              | Part Number                                                                    | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position             | HW                                                                             | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                              | MM Ref                                                                         |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                              | Ops Number(s)                                                                  |               |     |             |                 |     |                  |             |                    |         |              |
| 441105                       | Aft No. 1 Input / Output Concentrator - Removal / Installation                 |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                              |                                                                                |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                              | GCMS-02-001                                                                    | 02937         | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                              |                                                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                     |                                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| 441107                       | Aft No. 2 Input / Output Concentrator - Removal / Installation                 |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                              |                                                                                |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                              | GCMS-02-001                                                                    | 02952         | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                              |                                                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                     |                                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| 441109                       | Left Gulfstream Cabin Management System Controller - Removal / Installation    |               | HRS | TSN:1516.3  | 1529.5          |     |                  | 1516.6      |                    |         | 0            |
|                              |                                                                                |               | AFL | TSN:498     | 619             |     |                  | 498         |                    |         | 0            |
|                              | GCMS-02-0014                                                                   | 2882          | MOS | TSN:55      | 66.3            |     |                  | 01 Nov 2020 |                    |         |              |
|                              |                                                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                     |                                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| 441111                       | Right Gulfstream Cabin Management System Controller - Removal / Installation   |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                              |                                                                                |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                              | GCMS-02-001                                                                    | 02912         | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                              |                                                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                     |                                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| 441113                       | Gulfstream Cabin Management System Maintenance Server - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                              |                                                                                |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                              | GCMS-02-001                                                                    | 02907         | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                              |                                                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                     |                                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| 449004                       | Csb 003A - Advanced Cabin Server (Acs) System Firmware Update 4.4.3.3          |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                              |                                                                                |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                              |                                                                                |               | MOS |             |                 |     |                  |             |                    |         |              |
|                              |                                                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe                     |                                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| 45 - Central Maint System    |                                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| 453700 <sup>u</sup>          | Cmc Data - Download and Memory Clear                                           |               | HRS |             | 661.2           |     |                  | 2384.9      | 0                  |         | 0            |
|                              |                                                                                |               | AFL |             | 289             |     |                  | 828         | 0                  |         | 0            |
|                              |                                                                                |               | MOS |             | 23.6            |     | 1                | 22 May 2024 |                    |         |              |
| Airframe [End Of Month Item] |                                                                                |               |     |             |                 |     |                  |             |                    |         |              |



| ATA<br>U=Custom  | Description   |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|---------------|---------------|-----|-------------|-----------------|-----|------------------|----------|--------------------|---------|--------------|
|                  | Part Number   | Serial Number |     |             |                 |     |                  |          |                    |         | Approx Price |
| Logbook Position | HW            | SW            |     |             |                 |     |                  |          |                    |         | Manufacturer |
|                  | MM Ref        |               |     |             |                 |     |                  |          |                    |         | Date Type    |
|                  | Ops Number(s) |               |     |             |                 |     |                  |          |                    |         |              |

|                                   |                                                                        |              |     |  |        |  |  |             |  |  |   |  |
|-----------------------------------|------------------------------------------------------------------------|--------------|-----|--|--------|--|--|-------------|--|--|---|--|
| 46 - Information Systems          |                                                                        |              |     |  |        |  |  |             |  |  |   |  |
| 462100                            | Data LAN Management Unit - Removal / Installation                      |              | HRS |  | 730.5  |  |  | 2315.6      |  |  | 0 |  |
|                                   | 940-000175-211                                                         | 211-1099     | AFL |  | 315    |  |  | 802         |  |  | 0 |  |
|                                   |                                                                        |              | MOS |  | 28.7   |  |  | 21 Dec 2023 |  |  |   |  |
|                                   | Airframe                                                               |              | MSC |  |        |  |  | O/C         |  |  |   |  |
| 462102                            | Data LAN Management Unit - Operational Test                            |              | HRS |  | 730.5  |  |  | 2315.6      |  |  | 0 |  |
|                                   |                                                                        |              | AFL |  | 315    |  |  | 802         |  |  | 0 |  |
|                                   |                                                                        |              | MOS |  | 28.7   |  |  | 21 Dec 2023 |  |  |   |  |
|                                   | Airframe                                                               |              | MSC |  |        |  |  | O/C         |  |  |   |  |
| Notes: PN: 940-000175 SN: <NONE>. |                                                                        |              |     |  |        |  |  |             |  |  |   |  |
| 463500                            | Aircraft Health and Trend Monitoring Unit - Removal / Installation     |              | HRS |  | 3046.1 |  |  | 0           |  |  | 0 |  |
|                                   |                                                                        |              | AFL |  | 1117   |  |  | 0           |  |  | 0 |  |
|                                   | 186702-003                                                             | 0000194      | MOS |  | 128.6  |  |  | 24 Aug 2015 |  |  |   |  |
|                                   | Airframe                                                               |              | MSC |  |        |  |  | O/C         |  |  |   |  |
| 463502                            | Aircraft Health and Trend Monitoring System - Operational Test         |              | HRS |  | 3046.1 |  |  | 0           |  |  | 0 |  |
|                                   |                                                                        |              | AFL |  | 1117   |  |  | 0           |  |  | 0 |  |
|                                   |                                                                        |              | MOS |  | 128.6  |  |  | 24 Aug 2015 |  |  |   |  |
|                                   | Airframe                                                               |              | MSC |  |        |  |  | O/C         |  |  |   |  |
| Notes: PN: 186702-003 SN: <NONE>. |                                                                        |              |     |  |        |  |  |             |  |  |   |  |
| 463505                            | Wireless Data Network Unit - Removal / Installation                    |              | HRS |  | 3046.1 |  |  | 0           |  |  | 0 |  |
|                                   | 100-004-745-005                                                        | 00409D7F9206 | AFL |  | 1117   |  |  | 0           |  |  | 0 |  |
|                                   |                                                                        |              | MOS |  | 128.6  |  |  | 24 Aug 2015 |  |  |   |  |
|                                   | Airframe                                                               |              | MSC |  |        |  |  | O/C         |  |  |   |  |
| 463507                            | Remote Data Concentrator - Removal / Installation                      |              | HRS |  | 3046.1 |  |  | 0           |  |  | 0 |  |
|                                   | 804-1250                                                               | 1240086      | AFL |  | 1117   |  |  | 0           |  |  | 0 |  |
|                                   |                                                                        |              | MOS |  | 128.6  |  |  | 24 Aug 2015 |  |  |   |  |
|                                   | Airframe                                                               |              | MSC |  |        |  |  | O/C         |  |  |   |  |
| 463509                            | Aircraft Health and Trend Monitoring System - Maintenance Laptop Setup |              | HRS |  | 3046.1 |  |  | 0           |  |  | 0 |  |
|                                   |                                                                        |              | AFL |  | 1117   |  |  | 0           |  |  | 0 |  |
|                                   |                                                                        |              | MOS |  | 128.6  |  |  | 24 Aug 2015 |  |  |   |  |
|                                   | Airframe                                                               |              | MSC |  |        |  |  | O/C         |  |  |   |  |

| ATA<br>U=Custom                 | Description                                                                               |               | UOM  | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|---------------------------------|-------------------------------------------------------------------------------------------|---------------|------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                 | Part Number                                                                               | Serial Number |      |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position                | HW                                                                                        | SW            |      |             |                 |     |                  |             |                    |         | Manufacturer |
|                                 | MM Ref                                                                                    |               |      |             |                 |     |                  |             |                    |         | Date Type    |
|                                 | Ops Number(s)                                                                             |               |      |             |                 |     |                  |             |                    |         |              |
| 463510                          | Aircraft Health and Trend Monitoring System - Access Menu Functions                       |               | HRS  |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                 |                                                                                           |               | AFL  |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                 |                                                                                           |               | MOS  |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                 |                                                                                           |               | MSC  |             |                 |     | O/C              |             |                    |         |              |
| Airframe                        |                                                                                           |               |      |             |                 |     |                  |             |                    |         |              |
| 463517                          | Aircraft Health and Trend Monitoring System / Remote Data Concentrator - Operational Test |               | HRS  |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                 |                                                                                           |               | AFL  |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                 |                                                                                           |               | MOS  |             | 128.6           |     |                  | 24 Aug 2015 |                    |         | AVIONICA INC |
|                                 |                                                                                           |               | MSC  |             |                 |     | O/C              |             |                    |         |              |
| Airframe                        |                                                                                           |               |      |             |                 |     |                  |             |                    |         |              |
| Notes: PN: 804-1250 SN: <NONE>. |                                                                                           |               |      |             |                 |     |                  |             |                    |         |              |
| 49 - Airborne Auxiliary Power   |                                                                                           |               |      |             |                 |     |                  |             |                    |         |              |
| 490001                          | APU - APU - Removal / Installation<br>WE3800836-1                                         |               | HRS  | TSN:4.9     | 2266.5          |     |                  | 0           |                    |         | 0            |
|                                 |                                                                                           |               | APUS | TSN:3       | 0               |     |                  | 0           |                    |         | 0            |
|                                 |                                                                                           |               | MOS  | TSN:8       | 124.9           |     |                  | 15 Dec 2015 |                    |         |              |
|                                 |                                                                                           |               | MSC  |             |                 |     | O/C              |             |                    |         |              |
| APU                             |                                                                                           |               |      |             |                 |     |                  |             |                    |         |              |
| 490003                          | APU - APU - Functional Test                                                               |               | HRS  |             | 87.5            |     |                  | 2179        |                    |         | 0            |
|                                 |                                                                                           |               | APUS |             | 0               |     |                  | 0           |                    |         | 0            |
|                                 |                                                                                           |               | MOS  |             | 4.7             |     |                  | 19 Dec 2025 |                    |         |              |
|                                 |                                                                                           |               | MSC  |             |                 |     | O/C              |             |                    |         |              |
| APU                             |                                                                                           |               |      |             |                 |     |                  |             |                    |         |              |
| 491104                          | Isolator Mounts - General Visual Inspection                                               |               | HRS  |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                 |                                                                                           |               | AFL  |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                 |                                                                                           |               | MOS  |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                 |                                                                                           |               | MSC  |             |                 |     | O/C              |             |                    |         |              |
| Airframe                        |                                                                                           |               |      |             |                 |     |                  |             |                    |         |              |
| 491107                          | Mount Bracket - General Visual Inspection                                                 |               | HRS  |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                 |                                                                                           |               | AFL  |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                 |                                                                                           |               | MOS  |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                 |                                                                                           |               | MSC  |             |                 |     | O/C              |             |                    |         |              |
| Airframe                        |                                                                                           |               |      |             |                 |     |                  |             |                    |         |              |
| 491204                          | APU Inlet Door Motor Controller Actuator - Removal / Installation<br>HYLZ-53077           |               | HRS  |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                 |                                                                                           |               | AFL  |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                 |                                                                                           |               | MOS  |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                 |                                                                                           |               | MSC  |             |                 |     | O/C              |             |                    |         |              |
| Airframe                        |                                                                                           |               |      |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                   |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W                             | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-------------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|--------------------------------------|--------------------|---------|--------------|
|                  | Part Number                                                                   | Serial Number |                                    |             |                 |     |                  |                                      |                    |         | Approx Price |
| Logbook Position | HW                                                                            | SW            |                                    |             |                 |     |                  |                                      |                    |         | Manufacturer |
|                  | MM Ref                                                                        |               |                                    |             |                 |     |                  |                                      |                    |         | Date Type    |
|                  | Ops Number(s)                                                                 |               |                                    |             |                 |     |                  |                                      |                    |         |              |
| 491205           | APU Inlet Door Actuator - Removal / Installation                              |               | HRS                                |             | 3046.1          |     |                  | 0                                    |                    |         | 0            |
|                  | SYLC-52630-3 880                                                              |               | AFL                                |             | 1117            |     |                  | 0                                    |                    |         | 0            |
|                  |                                                                               |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015                          |                    |         |              |
|                  | Airframe                                                                      |               | MSC                                |             |                 |     | O/C              |                                      |                    |         |              |
| 491206           | APU AIR Inlet Door Actuator - Adjustment / Test                               |               | HRS                                |             | 3046.1          |     |                  | 0                                    |                    |         | 0            |
|                  |                                                                               |               | AFL                                |             | 1117            |     |                  | 0                                    |                    |         | 0            |
|                  |                                                                               |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015                          |                    |         |              |
|                  | Airframe                                                                      |               | MSC                                |             |                 |     | O/C              |                                      |                    |         |              |
| 491207           | APU Inlet Door Actuator - Inspection / Check                                  |               | HRS                                |             | 3046.1          |     |                  | 0                                    |                    |         | 0            |
|                  |                                                                               |               | AFL                                |             | 1117            |     |                  | 0                                    |                    |         | 0            |
|                  |                                                                               |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015                          |                    |         |              |
|                  | Airframe                                                                      |               | MSC                                |             |                 |     | O/C              |                                      |                    |         |              |
| 491215           | APU AIR Inlet Ducts and APU Inlet Boot Assemblies - General Visual Inspection |               | HRS                                |             | 137             |     |                  | 2909.1                               |                    |         | 0            |
|                  |                                                                               |               | AFL                                |             | 52              |     |                  | 1065                                 |                    |         | 0            |
|                  |                                                                               |               | MOS                                |             | 5.4             |     | 120              | 29 Nov 2025 29 Nov 2035 29 Dec 2035  |                    |         |              |
|                  | Airframe                                                                      |               | [MOS: +1m/-1m]                     |             |                 |     |                  |                                      |                    |         |              |
| 491217           | APU AIR Inlet Duct Door and Actuator - Detailed Inspection                    |               | HRS                                |             | 730.5           |     |                  | 2315.6                               |                    |         | 0            |
|                  |                                                                               |               | AFL                                |             | 315             |     |                  | 802                                  |                    |         | 0            |
|                  |                                                                               |               | MOS                                |             | 28.7            | 41  | 48               | 21 Dec 2023 31 Jan 2028* 29 Feb 2028 |                    |         |              |
|                  | Airframe                                                                      |               | [MOS: +1m/-1m]                     |             |                 |     |                  |                                      |                    |         |              |
| 491300           | APU Turbine Plenum Drain - Operational Check                                  |               | HRS                                |             | 137             |     |                  | 2909.1                               |                    |         | 0            |
|                  |                                                                               |               | AFL                                |             | 52              |     |                  | 1065                                 |                    |         | 0            |
|                  |                                                                               |               | MOS                                |             | 5.5             | 24  | 24               | 27 Nov 2025 31 Dec 2027* 31 Jan 2028 |                    |         |              |
|                  | Airframe                                                                      |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |                                      |                    |         |              |
| 491301           | APU Drains - Operational Test                                                 |               | HRS                                |             | 3046.1          |     |                  | 0                                    |                    |         | 0            |
|                  |                                                                               |               | AFL                                |             | 1117            |     |                  | 0                                    |                    |         | 0            |
|                  |                                                                               |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015                          |                    |         |              |
|                  | Airframe                                                                      |               | MSC                                |             |                 |     | O/C              |                                      |                    |         |              |
| 491302           | APU Compartment Drains - General Visual Inspection                            |               | HRS                                |             | 137             |     |                  | 2909.1                               |                    |         | 0            |
|                  |                                                                               |               | AFL                                |             | 52              |     |                  | 1065                                 |                    |         | 0            |
|                  |                                                                               |               | MOS                                |             | 5.4             |     | 24               | 29 Nov 2025 30 Nov 2027 31 Dec 2027  |                    |         |              |
|                  | Airframe                                                                      |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |                                      |                    |         |              |
|                  |                                                                               | 052011        |                                    |             |                 |     |                  |                                      |                    |         |              |

| ATA<br>U=Custom  | Description                                                                                                |               | UOM            | Times Since | Time<br>Accrued | Adj   | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------------------------------------------------------------------------|---------------|----------------|-------------|-----------------|-------|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                                                | Serial Number |                |             |                 |       |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                                                         | SW            |                |             |                 |       |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                                                     |               |                |             |                 |       |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                                                              |               |                |             |                 |       |                  |             |                    |         |              |
| 491303           | Interior and Exterior Surfaces of APU Compartment (APU Box) - Detailed Inspection                          |               | HRS            |             | 730.5           |       |                  | 2315.6      |                    |         | 0            |
|                  |                                                                                                            |               | AFL            |             | 315             |       | 802              |             |                    | 0       |              |
|                  |                                                                                                            |               | MOS            |             | 28.7            | 48    | 21 Dec 2023      | 21 Dec 2027 | 21 Jan 2028        |         |              |
|                  |                                                                                                            |               | [MOS: +1m/-1m] |             |                 |       |                  |             |                    |         |              |
| Airframe         |                                                                                                            | 052013        |                |             |                 |       |                  |             |                    |         |              |
| 491304           | APU Compartment Drains - Operational Check                                                                 |               | HRS            |             | 137             |       |                  | 2909.1      |                    |         | 0            |
|                  |                                                                                                            |               | AFL            |             | 52              |       | 1065             |             |                    | 0       |              |
|                  |                                                                                                            |               | MOS            |             | 5.4             | 24    | 29 Nov 2025      | 29 Nov 2027 | 29 Dec 2027        |         |              |
|                  |                                                                                                            |               | [MOS: +1m/-1m] |             |                 |       |                  |             |                    |         |              |
| Airframe         |                                                                                                            | 052011        |                |             |                 |       |                  |             |                    |         |              |
| 492000           | APU - APU Combustor - Wash                                                                                 |               | HRS            |             | 2266.5          |       |                  | 0           |                    |         | 0            |
|                  |                                                                                                            |               | APUS           |             | 0               |       | 0                |             |                    | 0       |              |
|                  |                                                                                                            |               | MOS            |             | 132.5           |       | 25 Apr 2015      |             |                    |         |              |
|                  |                                                                                                            |               | MSC            |             |                 | O/C   |                  |             |                    |         |              |
| APU              |                                                                                                            |               |                |             |                 |       |                  |             |                    |         |              |
| 492001           | APU - APU Fuel and Oil System (External) - General Visual Inspection                                       |               | HRS            |             | 87.5            | 600   | 2179             | 2779        | 2829               |         | 0            |
|                  |                                                                                                            |               | APUS           |             | 0               |       | 0                |             |                    | 0       |              |
|                  |                                                                                                            |               | MOS            |             | 5.4             |       | 29 Nov 2025      |             |                    |         |              |
|                  |                                                                                                            |               | [HRS: +50/-50] |             |                 |       |                  |             |                    |         |              |
| APU              |                                                                                                            |               |                |             |                 |       |                  |             |                    |         |              |
| 492100           | APU - Branched Wiring Harness - Removal / Installation<br>WE3888569-2                      15-150262-38700 |               | HRS            | TSN:4.9     | 2266.5          |       |                  | 0           |                    |         | 0            |
|                  |                                                                                                            |               | APUS           | TSN:3       | 0               |       | 0                |             |                    | 0       |              |
|                  |                                                                                                            |               | MOS            |             | 132.5           |       | 25 Apr 2015      |             |                    |         |              |
|                  |                                                                                                            |               | MSC            |             |                 | O/C   |                  |             |                    |         |              |
| APU              |                                                                                                            |               |                |             |                 |       |                  |             |                    |         |              |
| 492102           | APU - Branched Wiring Harness (Wiring Harness) - General Visual Inspection                                 |               | HRS            |             | 87.5            | 600   | 2179             | 2779        | 2829               |         | 0            |
|                  |                                                                                                            |               | APUS           |             | 0               |       | 0                |             |                    | 0       |              |
|                  |                                                                                                            |               | MOS            |             | 5.4             |       | 29 Nov 2025      |             |                    |         |              |
|                  |                                                                                                            |               | [HRS: +50/-50] |             |                 |       |                  |             |                    |         |              |
| APU              |                                                                                                            |               |                |             |                 |       |                  |             |                    |         |              |
| 492300           | APU - Compressor Impeller - Discard<br>WB3822573-1                      14-162053-06763                    |               | HRS            | TSN:4.9     | 2266.5          | 10000 | 0                | 9995.1      |                    |         | 0            |
|                  |                                                                                                            |               | APUS           | TSN:3       | 0               |       | 0                |             |                    | 0       |              |
|                  |                                                                                                            |               | MOS            |             | 132.5           |       | 25 Apr 2015      |             |                    |         |              |
|                  |                                                                                                            |               |                |             |                 |       |                  |             |                    |         |              |
| APU              |                                                                                                            |               |                |             |                 |       |                  |             |                    |         |              |
| 492301           | APU - First Stage Turbine Rotor Disc - Discard<br>WK3840141-3                      142241003312            |               | HRS            | TSN:4.9     | 2266.5          | 10000 | 0                | 9995.1      |                    |         | 0            |
|                  |                                                                                                            |               | APUS           | TSN:3       | 0               |       | 0                |             |                    | 0       |              |
|                  |                                                                                                            |               | MOS            |             | 132.5           |       | 25 Apr 2015      |             |                    |         |              |
|                  |                                                                                                            |               |                |             |                 |       |                  |             |                    |         |              |
| APU              |                                                                                                            |               |                |             |                 |       |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                              |                 | UOM            | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------------|-----------------|----------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                              | Serial Number   |                |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                       | SW              |                |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                   |                 |                |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                            |                 |                |             |                 |     |                  |             |                    |         |              |
| 492302           | APU - Second Stage Turbine Rotor - Discard               |                 | HRS            | TSN:4.9     | 2266.5          |     | 10000            | 0           | 9995.1             |         | 0            |
|                  | WE897994-3                                               | 14-156101-11797 | APUS           | TSN:3       | 0               |     |                  | 0           |                    |         | 0            |
|                  |                                                          |                 | MOS            |             | 132.5           |     |                  | 25 Apr 2015 |                    |         |              |
| APU              |                                                          |                 |                |             |                 |     |                  |             |                    |         |              |
| 492303           | APU - APU Compressor and Turbine Section - Rotation      |                 | HRS            |             | 2266.5          |     |                  | 0           |                    |         | 0            |
|                  | Check and / or Borescope Inspection                      |                 | APUS           |             | 0               |     |                  | 0           |                    |         | 0            |
|                  |                                                          |                 | MOS            |             | 132.5           |     |                  | 25 Apr 2015 |                    |         |              |
|                  |                                                          |                 | MSC            |             |                 |     | O/C              |             |                    |         |              |
| APU              |                                                          |                 |                |             |                 |     |                  |             |                    |         |              |
| 493000           | APU - Engine Fuel and Control System - Inspection        |                 | HRS            |             | 2266.5          |     |                  | 0           |                    |         | 0            |
|                  |                                                          |                 | APUS           |             | 0               |     |                  | 0           |                    |         | 0            |
|                  |                                                          |                 | MOS            |             | 132.5           |     |                  | 25 Apr 2015 |                    |         |              |
|                  |                                                          |                 | MSC            |             |                 |     | O/C              |             |                    |         |              |
| APU              |                                                          |                 |                |             |                 |     |                  |             |                    |         |              |
| 493100           | APU - Fuel Control Unit - Removal / Installation         |                 | HRS            | TSN:4.9     | 2266.5          |     |                  | 0           |                    |         | 0            |
|                  | 441903-4                                                 | CUB11079        | APUS           | TSN:3       | 0               |     |                  | 0           |                    |         | 0            |
|                  |                                                          |                 | MOS            |             | 132.5           |     |                  | 25 Apr 2015 |                    |         |              |
|                  |                                                          |                 | MSC            |             |                 |     | O/C              |             |                    |         |              |
| APU              |                                                          |                 |                |             |                 |     |                  |             |                    |         |              |
| 493104           | APU - Fuel Filter Element - Removal / Installation       |                 | HRS            |             | 216.5           |     |                  | 2050        |                    |         | 0            |
|                  | 3882496-1                                                | NSN             | APUS           |             | 0               |     |                  | 0           |                    |         | 0            |
|                  |                                                          |                 | MOS            |             | 9.9             |     |                  | 15 Jul 2025 |                    |         |              |
|                  |                                                          |                 | MSC            |             |                 |     | O/C              |             |                    |         |              |
| APU              |                                                          |                 |                |             |                 |     |                  |             |                    |         |              |
| 493106           | Seal Witness Drain - Inspection                          |                 | HRS            |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                          |                 | AFL            |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                          |                 | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                          |                 | MSC            |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                          |                 |                |             |                 |     |                  |             |                    |         |              |
| 493108           | APU - Fuel Strainer Element (Strainer) - Inspection /    |                 | HRS            |             | 2266.5          |     |                  | 0           |                    |         | 0            |
|                  | Check                                                    |                 | APUS           |             | 0               |     |                  | 0           |                    |         | 0            |
|                  |                                                          |                 | MOS            |             | 132.5           |     |                  | 25 Apr 2015 |                    |         |              |
|                  |                                                          |                 | MSC            |             |                 |     | O/C              |             |                    |         |              |
| APU              |                                                          |                 |                |             |                 |     |                  |             |                    |         |              |
| 493402           | APU - Fuel Filter Bypass Indicator - Detailed Inspection |                 | HRS            |             | 87.5            |     | 600              | 2179        | 2779               | 2829    | 0            |
|                  | (Delta P Indicator)                                      |                 | APUS           |             | 0               |     |                  | 0           |                    |         | 0            |
|                  |                                                          |                 | MOS            |             | 5.4             |     |                  | 29 Nov 2025 |                    |         |              |
|                  |                                                          |                 | [HRS: +50/-50] |             |                 |     |                  |             |                    |         |              |
| APU              |                                                          |                 |                |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                    |               | UOM  | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------------------|---------------|------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                    | Serial Number |      |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                             | SW            |      |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                         |               |      |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                  |               |      |             |                 |     |                  |             |                    |         |              |
| 494100           | APU - Ignition Exciter - Removal / Installation                |               | HRS  | TSN:4.9     | 2266.5          |     |                  | 0           |                    |         | 0            |
|                  | WE3876295-7 J15160086                                          |               | APUS | TSN:3       | 0               |     |                  | 0           |                    |         | 0            |
|                  |                                                                |               | MOS  |             | 132.5           |     |                  | 25 Apr 2015 |                    |         |              |
|                  | APU                                                            |               | MSC  |             |                 |     | O/C              |             |                    |         |              |
| 494110           | APU - Igniter Plug Lead (A) - Inspection                       |               | HRS  |             | 2266.5          |     |                  | 0           |                    |         | 0            |
|                  |                                                                |               | APUS |             | 0               |     |                  | 0           |                    |         | 0            |
|                  |                                                                |               | MOS  |             | 132.5           |     |                  | 25 Apr 2015 |                    |         |              |
|                  | APU                                                            |               | MSC  |             |                 |     | O/C              |             |                    |         |              |
| 494111           | APU - Igniter Plug Lead (B) - Inspection                       |               | HRS  |             | 2266.5          |     |                  | 0           |                    |         | 0            |
|                  |                                                                |               | APUS |             | 0               |     |                  | 0           |                    |         | 0            |
|                  |                                                                |               | MOS  |             | 132.5           |     |                  | 25 Apr 2015 |                    |         |              |
|                  | APU                                                            |               | MSC  |             |                 |     | O/C              |             |                    |         |              |
| 494112           | APU - Igniter Plug (A) - Inspection                            |               | HRS  |             | 2266.5          |     |                  | 0           |                    |         | 0            |
|                  |                                                                |               | APUS |             | 0               |     |                  | 0           |                    |         | 0            |
|                  |                                                                |               | MOS  |             | 132.5           |     |                  | 25 Apr 2015 |                    |         |              |
|                  | APU                                                            |               | MSC  |             |                 |     | O/C              |             |                    |         |              |
| 494113           | APU - Igniter Plug (B) - Inspection                            |               | HRS  |             | 2266.5          |     |                  | 0           |                    |         | 0            |
|                  |                                                                |               | APUS |             | 0               |     |                  | 0           |                    |         | 0            |
|                  |                                                                |               | MOS  |             | 132.5           |     |                  | 25 Apr 2015 |                    |         |              |
|                  | APU                                                            |               | MSC  |             |                 |     | O/C              |             |                    |         |              |
| 494114           | APU - Igniter Plug (A) - Cleaning                              |               | HRS  |             | 2266.5          |     |                  | 0           |                    |         | 0            |
|                  |                                                                |               | APUS |             | 0               |     |                  | 0           |                    |         | 0            |
|                  |                                                                |               | MOS  |             | 132.5           |     |                  | 25 Apr 2015 |                    |         |              |
|                  | APU                                                            |               | MSC  |             |                 |     | O/C              |             |                    |         |              |
| 494115           | APU - Igniter Plug (B) - Cleaning                              |               | HRS  |             | 2266.5          |     |                  | 0           |                    |         | 0            |
|                  |                                                                |               | APUS |             | 0               |     |                  | 0           |                    |         | 0            |
|                  |                                                                |               | MOS  |             | 132.5           |     |                  | 25 Apr 2015 |                    |         |              |
|                  | APU                                                            |               | MSC  |             |                 |     | O/C              |             |                    |         |              |
| 494116           | APU - Igniter Plug Lead (A) Electrical Properties - Inspection |               | HRS  |             | 2266.5          |     |                  | 0           |                    |         | 0            |
|                  |                                                                |               | APUS |             | 0               |     |                  | 0           |                    |         | 0            |
|                  |                                                                |               | MOS  |             | 132.5           |     |                  | 25 Apr 2015 |                    |         |              |
|                  | APU                                                            |               | MSC  |             |                 |     | O/C              |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                  |               | UOM            | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------------------------------------------|---------------|----------------|-------------|-----------------|-----|------------------|----------|---------------------|---------|--------------|
|                  | Part Number                                                                  | Serial Number |                |             |                 |     |                  |          |                     |         | Approx Price |
| Logbook Position | HW                                                                           | SW            |                |             |                 |     |                  |          |                     |         | Manufacturer |
|                  | MM Ref                                                                       |               |                |             |                 |     |                  |          |                     |         | Date Type    |
|                  | Ops Number(s)                                                                |               |                |             |                 |     |                  |          |                     |         |              |
| 494117           | APU - Igniter Plug Lead (B) Electrical Properties -<br>Inspection            |               | HRS            |             | 2266.5          |     |                  | 0        |                     |         | 0            |
|                  |                                                                              |               | APUS           |             | 0               |     | 0                |          | 0                   |         |              |
|                  |                                                                              |               | MOS            |             | 132.5           |     | 25 Apr 2015      |          |                     |         |              |
|                  |                                                                              |               | MSC            |             |                 | O/C |                  |          |                     |         |              |
| APU              |                                                                              |               |                |             |                 |     |                  |          |                     |         |              |
| 494200           | APU - Starter Motor - Removal / Installation<br>2704554-3 3593               |               | HRS            |             | 158.5           |     |                  | 2108     |                     |         | 0            |
|                  |                                                                              |               | APUS           |             |                 |     |                  |          | 0                   |         |              |
|                  |                                                                              |               | MOS            |             | 7.8             |     | 16 Sep 2025      |          |                     |         |              |
|                  |                                                                              |               | MSC            |             |                 | O/C |                  |          |                     |         |              |
| APU              |                                                                              |               |                |             |                 |     |                  |          |                     |         |              |
| 494202           | APU - Starter Motor - Detailed Inspection                                    |               | HRS            |             | 87.5            |     | 600              | 2179     | 2779                | 2829    | 0            |
|                  |                                                                              |               | APUS           |             | 0               |     | 0                |          | 0                   |         |              |
|                  |                                                                              |               | MOS            |             | 5.4             |     | 29 Nov 2025      |          |                     |         |              |
|                  |                                                                              |               | [HRS: +50/-50] |             |                 |     |                  |          |                     |         |              |
| APU              |                                                                              |               |                |             |                 |     |                  |          |                     |         |              |
| 494203           | APU - Starter Motor - Cleaning                                               |               | HRS            |             | 2266.5          |     |                  | 0        |                     |         | 0            |
|                  |                                                                              |               | APUS           |             | 0               |     | 0                |          | 0                   |         |              |
|                  |                                                                              |               | MOS            |             | 132.5           |     | 25 Apr 2015      |          |                     |         |              |
|                  |                                                                              |               | MSC            |             |                 | O/C |                  |          |                     |         |              |
| APU              |                                                                              |               |                |             |                 |     |                  |          |                     |         |              |
| 495100           | APU - Surge Control Valve - Removal / Installation<br>3291212-4 1837         |               | HRS            | TSN:4.9     | 2266.5          |     |                  | 0        |                     |         | 0            |
|                  |                                                                              |               | APUS           | TSN:3       | 0               |     | 0                |          | 0                   |         |              |
|                  |                                                                              |               | MOS            |             | 132.5           |     | 25 Apr 2015      |          |                     |         |              |
|                  |                                                                              |               | MSC            |             |                 | O/C |                  |          |                     |         |              |
| APU              |                                                                              |               |                |             |                 |     |                  |          |                     |         |              |
| 495101           | APU - Load Control Valve - Removal / Installation<br>3291210-6 3069          |               | HRS            | TSN:4.9     | 2266.5          |     |                  | 0        |                     |         | 0            |
|                  |                                                                              |               | APUS           | TSN:3       | 0               |     | 0                |          | 0                   |         |              |
|                  |                                                                              |               | MOS            |             | 132.5           |     | 25 Apr 2015      |          |                     |         |              |
|                  |                                                                              |               | MSC            |             |                 | O/C |                  |          |                     |         |              |
| APU              |                                                                              |               |                |             |                 |     |                  |          |                     |         |              |
| 495104           | APU - Load Control Valve Filter - Removal / Cleaning /<br>Installation       |               | HRS            |             | 2266.5          |     |                  | 0        |                     |         | 0            |
|                  |                                                                              |               | APUS           |             | 0               |     | 0                |          | 0                   |         |              |
|                  |                                                                              |               | MOS            |             | 132.5           |     | 25 Apr 2015      |          |                     |         |              |
|                  |                                                                              |               | MSC            |             |                 | O/C |                  |          |                     |         |              |
| APU              |                                                                              |               |                |             |                 |     |                  |          |                     |         |              |
| 495200           | APU - Bleed Diffuser - Removal / Installation<br>WB3827396-1 15-190742-00323 |               | HRS            | TSN:4.9     | 2266.5          |     |                  | 0        |                     |         | 0            |
|                  |                                                                              |               | APUS           | TSN:3       | 0               |     | 0                |          | 0                   |         |              |
|                  |                                                                              |               | MOS            |             | 132.5           |     | 25 Apr 2015      |          |                     |         |              |
|                  |                                                                              |               | MSC            |             |                 | O/C |                  |          |                     |         |              |
| APU              |                                                                              |               |                |             |                 |     |                  |          |                     |         |              |

| ATA<br>U=Custom  | Description                                                                      |               | UOM            | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------------------------------------|---------------|----------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                      | Serial Number |                |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                               | SW            |                |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                           |               |                |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                                    |               |                |             |                 |     |                  |             |                    |         |              |
| 496100           | Electronic Control Unit - Removal / Installation                                 |               | HRS            |             | 1844.6          |     |                  | 1201.5      |                    |         | 0            |
|                  | WE3888570-3                                                                      | 2119326-D14   | AFL            |             | 766             |     |                  | 351         |                    |         | 0            |
|                  |                                                                                  |               | MOS            |             | 79.3            |     |                  | 03 Oct 2019 |                    |         |              |
|                  | Airframe                                                                         |               | MSC            |             |                 |     | O/C              |             |                    |         |              |
| 496110           | APU - Inlet Pressure Sensor - Removal / Installation                             |               | HRS            | TSN:4.9     | 2266.5          |     |                  | 0           |                    |         | 0            |
|                  | WE3876283-1                                                                      | 1515047122227 | APUS           | TSN:3       | 0               |     |                  | 0           |                    |         | 0            |
|                  |                                                                                  |               | MOS            |             | 132.5           |     |                  | 25 Apr 2015 |                    |         |              |
|                  | APU                                                                              |               | MSC            |             |                 |     | O/C              |             |                    |         |              |
| 497502           | APU - Time Totalizing Meter - Read and Record                                    |               | HRS            |             | 158.5           |     |                  | 2108        |                    |         | 0            |
|                  |                                                                                  |               | APUS           |             |                 |     |                  |             |                    |         | 0            |
|                  |                                                                                  |               | MOS            |             | 7.8             |     |                  | 16 Sep 2025 |                    |         |              |
|                  | APU                                                                              |               | MSC            |             |                 |     | O/C              |             |                    |         |              |
| 498100           | APU - APU Exhaust Duct (Internal Only) - General Visual Inspection               |               | HRS            |             | 87.5            |     | 600              | 2179        | 2779               | 2829    | 0            |
|                  |                                                                                  |               | APUS           |             | 0               |     |                  | 0           |                    |         | 0            |
|                  |                                                                                  |               | MOS            |             | 5.4             |     |                  | 29 Nov 2025 |                    |         |              |
|                  | APU                                                                              |               | [HRS: +50/-50] |             |                 |     |                  |             |                    |         |              |
| 498101           | APU - APU Fluted Exhaust and Turbine Bearing Support - General Visual Inspection |               | HRS            |             | 87.5            |     | 600              | 2179        | 2779               | 2829    | 0            |
|                  |                                                                                  |               | APUS           |             | 0               |     |                  | 0           |                    |         | 0            |
|                  |                                                                                  |               | MOS            |             | 5.4             |     |                  | 29 Nov 2025 |                    |         |              |
|                  | APU                                                                              |               | [HRS: +50/-50] |             |                 |     |                  |             |                    |         |              |
| 499000           | APU - APU Oil System - Inspection                                                |               | HRS            |             | 2266.5          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                  |               | APUS           |             | 0               |     |                  | 0           |                    |         | 0            |
|                  |                                                                                  |               | MOS            |             | 132.5           |     |                  | 25 Apr 2015 |                    |         |              |
|                  | APU                                                                              |               | MSC            |             |                 |     | O/C              |             |                    |         |              |
| 499002           | APU - APU Soap Sample                                                            |               | HRS            |             | 501             |     |                  | 1765.5      |                    |         | 0            |
|                  |                                                                                  |               | APUS           |             |                 |     |                  |             |                    |         | 0            |
|                  |                                                                                  |               | MOS            |             | 25.5            |     |                  | 26 Mar 2024 |                    |         |              |
|                  | APU                                                                              |               | MSC            |             |                 |     | O/C              |             |                    |         |              |
| 499100           | APU - Lube Pump Assembly - Removal / Installation                                |               | HRS            | TSN:4.9     | 2266.5          |     |                  | 0           |                    |         | 0            |
|                  | WE3881781-1                                                                      | VE3661        | APUS           | TSN:3       | 0               |     |                  | 0           |                    |         | 0            |
|                  |                                                                                  |               | MOS            |             | 132.5           |     |                  | 25 Apr 2015 |                    |         |              |
|                  | APU                                                                              |               | MSC            |             |                 |     | O/C              |             |                    |         |              |



| ATA<br>U=Custom                     | Description                                      |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|-------------------------------------|--------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                                     | Part Number                                      | Serial Number |                                    |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position                    | HW                                               | SW            |                                    |             |                 |     |                  |             |                    |             | Manufacturer |
|                                     | MM Ref                                           |               |                                    |             |                 |     |                  |             |                    |             | Date Type    |
|                                     | Ops Number(s)                                    |               |                                    |             |                 |     |                  |             |                    |             |              |
| 499204                              | APU - Chip Collector - Inspection                |               | HRS                                |             | 2266.5          |     |                  | 0           |                    |             | 0            |
|                                     |                                                  |               | APUS                               |             | 0               |     |                  | 0           |                    |             | 0            |
|                                     |                                                  |               | MOS                                |             | 132.5           |     |                  | 25 Apr 2015 |                    |             |              |
|                                     | APU                                              |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| 499300                              | APU - AIR / Oil Cooler - Removal / Installation  |               | HRS                                | TSN:4.9     | 2266.5          |     |                  | 0           |                    |             | 0            |
|                                     | 160534-1                                         | 2942          | APUS                               | TSN:3       | 0               |     |                  | 0           |                    |             | 0            |
|                                     |                                                  |               | MOS                                |             | 132.5           |     |                  | 25 Apr 2015 |                    |             |              |
|                                     | APU                                              |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| 49APU1                              | APU                                              |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                                     | WE3800700-1                                      | P-269         | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                                     |                                                  |               | MOS                                |             | 128.9           |     |                  | 13 Aug 2015 |                    |             |              |
|                                     | Airframe                                         |               | MSC                                |             |                 |     | E/C              |             |                    |             |              |
| 51 - STD Practices and Struct-Genrl |                                                  |               |                                    |             |                 |     |                  |             |                    |             |              |
| 512414                              | External Metallic Surfaces - Visual Inspection   |               | HRS                                |             | 663.7           |     |                  | 2382.4      |                    |             | 0            |
|                                     |                                                  |               | AFL                                |             | 291             |     |                  | 826         |                    |             | 0            |
|                                     |                                                  |               | MOS                                |             | 24.9            |     |                  | 15 Apr 2024 |                    |             |              |
|                                     | Airframe                                         |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| 52 - Doors                          |                                                  |               |                                    |             |                 |     |                  |             |                    |             |              |
| 520001                              | Fuselage Doors (External) - Zonal Inspection     |               | HRS                                |             | 1300.7          |     |                  | 1745.4      |                    |             | 0            |
|                                     |                                                  |               | AFL                                |             | 507             |     |                  | 610         |                    |             | 0            |
|                                     |                                                  |               | MOS                                |             | 51.7            |     | 72               | 20 Jan 2022 | 31 Jan 2028        | 29 Feb 2028 |              |
|                                     | Airframe                                         |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
|                                     |                                                  | 052015        |                                    |             |                 |     |                  |             |                    |             |              |
| 520002                              | Fuselage Doors (Interior) - Zonal Inspection     |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                                     |                                                  |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                                     |                                                  |               | MOS                                |             | 122             |     | 144              | 11 Mar 2016 | 31 Mar 2028        | 30 Apr 2028 |              |
|                                     | Airframe                                         |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
|                                     |                                                  | 052019        |                                    |             |                 |     |                  |             |                    |             |              |
| 521001                              | Main Entrance Door (Internal) - Zonal Inspection |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                                     |                                                  |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                                     |                                                  |               | MOS                                |             | 28.7            |     | 48               | 21 Dec 2023 | 31 Dec 2027        | 31 Jan 2028 |              |
|                                     | Airframe                                         |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
|                                     |                                                  | 052013        |                                    |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom  | Description                                                                         |               | UOM            | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------|-------------------------------------------------------------------------------------|---------------|----------------|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                  | Part Number                                                                         | Serial Number |                |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position | HW                                                                                  | SW            |                |             |                 |     |                  |             |                    |             | Manufacturer |
|                  | MM Ref                                                                              |               |                |             |                 |     |                  |             |                    |             | Date Type    |
|                  | Ops Number(s)                                                                       |               |                |             |                 |     |                  |             |                    |             |              |
| 521002           | Main Entrance Door - FS 273 - FS 309 - Detailed Inspection                          |               | HRS            |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                                     |               | AFL            |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                                     |               | MOS            |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031        | 31 Jan 2032 |              |
|                  | [End Of Month Item] [MOS: +1m/-1m]                                                  |               |                |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                     | 052016        |                |             |                 |     |                  |             |                    |             |              |
| 521003           | Main Entrance Door Viewport - Operational Check                                     |               | HRS            |             | 2345.1          |     |                  | 701         |                    |             | 0            |
|                  |                                                                                     |               | AFL            |             | 936             |     |                  | 181         |                    |             | 0            |
|                  |                                                                                     |               | MOS            |             | 97.2            |     |                  | 05 Apr 2018 |                    |             |              |
|                  | Airframe                                                                            |               | MSC O/C        |             |                 |     |                  |             |                    |             |              |
| 521004           | Main Entrance Door Cockpit Overhead Panel Safety Switch - Operational Check         |               | HRS            |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                  |                                                                                     |               | AFL            |             | 52              |     |                  | 1065        |                    |             | 0            |
|                  |                                                                                     |               | MOS            |             | 5.3             | 41  | 24               | 01 Dec 2025 | 31 Jan 2028*       | 29 Feb 2028 |              |
|                  | [End Of Month Item] [MOS: +1m/-1m]                                                  |               |                |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                     | 052011        |                |             |                 |     |                  |             |                    |             |              |
| 521005           | Main Entrance Door - Functional Check                                               |               | HRS            |             | 137             |     | 600              | 2909.1      | 3509.1             | 3559.1      | 0            |
|                  |                                                                                     |               | AFL            |             | 52              |     |                  | 1065        |                    |             | 0            |
|                  |                                                                                     |               | MOS            |             | 5.2             |     |                  | 05 Dec 2025 |                    |             |              |
|                  | Airframe                                                                            |               | [HRS: +50/-50] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                     | 052001        |                |             |                 |     |                  |             |                    |             |              |
| 521012           | Main Entrance Door Locking Actuator - Removal / Installation<br>60P5210915Z0010194  |               | HRS            |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                     |               | AFL            |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                     |               | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  | Airframe                                                                            |               | MSC O/C        |             |                 |     |                  |             |                    |             |              |
| 521016           | Main Entrance Door Latching Actuator - Removal / Installation<br>60P5210905Z1010243 |               | HRS            |             | 2345.1          |     |                  | 701         |                    |             | 0            |
|                  |                                                                                     |               | AFL            |             | 936             |     |                  | 181         |                    |             | 0            |
|                  |                                                                                     |               | MOS            | TSN:3       | 96.7            |     |                  | 19 Apr 2018 |                    |             |              |
|                  | Airframe                                                                            |               | MSC O/C        |             |                 |     |                  |             |                    |             |              |
| 521025           | Main Entrance Door Rigging - Adjustment / Test                                      |               | HRS            |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                     |               | AFL            |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                     |               | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  | Airframe                                                                            |               | MSC O/C        |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom  | Description                                                                                 |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------|---------------------------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                  | Part Number                                                                                 | Serial Number |                                    |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position | HW                                                                                          | SW            |                                    |             |                 |     |                  |             |                    |             | Manufacturer |
|                  | MM Ref                                                                                      |               |                                    |             |                 |     |                  |             |                    |             | Date Type    |
|                  | Ops Number(s)                                                                               |               |                                    |             |                 |     |                  |             |                    |             |              |
| 521100           | Main Entrance Door Fuselage Surround and Support<br>Structure - General Visual Inspection   |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                                             |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                                             |               | MOS                                |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031        | 31 Jan 2032 |              |
|                  |                                                                                             |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                             |               | 052016                             |             |                 |     |                  |             |                    |             |              |
| 521101           | Main Entrance Door Airstair Support Box Frame -<br>Removal / Installation<br>60P5210104N001 |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                             |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                             |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                             |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                             |               |                                    |             |                 |     |                  |             |                    |             |              |
| 521102           | External Door Locks - Key Code<br>ASG650M-17P2                                              |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                             |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                             |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                             |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                             |               |                                    |             |                 |     |                  |             |                    |             |              |
| 521210           | Main Entrance Door - Removal / Installation<br>60P5210101N001                               |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                             |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                             |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                             |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                             |               |                                    |             |                 |     |                  |             |                    |             |              |
| 521216           | Airstair Bottom Folding Step - Adjustment / Test                                            |               | HRS                                |             | 1300.7          |     |                  | 1745.4      |                    |             | 0            |
|                  |                                                                                             |               | AFL                                |             | 507             |     |                  | 610         |                    |             | 0            |
|                  |                                                                                             |               | MOS                                |             | 51.9            |     |                  | 14 Jan 2022 |                    |             |              |
|                  |                                                                                             |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                             |               |                                    |             |                 |     |                  |             |                    |             |              |
| 521217           | Main Entrance Door Handrail - Adjustment / Test                                             |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                             |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                             |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                             |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                             |               |                                    |             |                 |     |                  |             |                    |             |              |
| 521218           | Vestibule Upper Folding Step - Removal / Installation<br>60P5210600A039                     |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                             |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                             |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                             |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                             |               |                                    |             |                 |     |                  |             |                    |             |              |
| 521226           | Main Entrance Door Airstair - Removal / Installation<br>60P5210107N001                      |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                                             |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                                             |               | MOS                                |             | 28.8            |     |                  | 16 Dec 2023 |                    |             |              |
|                  |                                                                                             |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                             |               |                                    |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom  | Description                                                                   |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(* =Adj) | Max Due     | Avg Man Hrs  |
|------------------|-------------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|----------------------|-------------|--------------|
|                  | Part Number                                                                   | Serial Number |                                    |             |                 |     |                  |             |                      |             | Approx Price |
| Logbook Position | HW                                                                            | SW            |                                    |             |                 |     |                  |             |                      |             | Manufacturer |
|                  | MM Ref                                                                        |               |                                    |             |                 |     |                  |             |                      |             | Date Type    |
|                  | Ops Number(s)                                                                 |               |                                    |             |                 |     |                  |             |                      |             |              |
| 521300           | Main Entrance Door Latching and Locking System -<br>General Visual Inspection |               | HRS                                |             | 3046.1          |     |                  | 0           |                      |             | 0            |
|                  |                                                                               |               | AFL                                |             | 1117            |     |                  | 0           |                      |             | 0            |
|                  |                                                                               |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                      |             |              |
|                  |                                                                               |               | MSC                                |             |                 |     | O/C              |             |                      |             |              |
| Airframe         |                                                                               |               |                                    |             |                 |     |                  |             |                      |             |              |
| 521301           | Main Entrance Door Pressure Relief Valve - General<br>Visual Inspection       |               | HRS                                |             | 3046.1          |     |                  | 0           |                      |             | 0            |
|                  |                                                                               |               | AFL                                |             | 1117            |     |                  | 0           |                      |             | 0            |
|                  |                                                                               |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                      |             |              |
|                  |                                                                               |               | MSC                                |             |                 |     | O/C              |             |                      |             |              |
| Airframe         |                                                                               |               |                                    |             |                 |     |                  |             |                      |             |              |
| 521302           | Main Entrance Door Pressure Relief Valve Seal - Detailed<br>Inspection        |               | HRS                                |             | 137             |     |                  | 2909.1      |                      |             | 0            |
|                  |                                                                               |               | AFL                                |             | 52              |     |                  | 1065        |                      |             | 0            |
|                  |                                                                               |               | MOS                                |             | 5.2             |     | 120              | 05 Dec 2025 | 31 Dec 2035          | 31 Jan 2036 |              |
|                  |                                                                               |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                      |             |              |
| Airframe         |                                                                               |               |                                    |             |                 |     |                  |             |                      |             |              |
| 052018           |                                                                               |               |                                    |             |                 |     |                  |             |                      |             |              |
| 521303           | Main Entrance Door Latching Actuator - Discard<br>60P5210905Z101              |               |                                    |             |                 |     |                  |             |                      |             |              |

| ATA<br>U=Custom                | Description                                       |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|--------------------------------|---------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                                | Part Number                                       | Serial Number |                                    |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position               | HW                                                | SW            |                                    |             |                 |     |                  |             |                    |             | Manufacturer |
|                                | MM Ref                                            |               |                                    |             |                 |     |                  |             |                    |             | Date Type    |
|                                | Ops Number(s)                                     |               |                                    |             |                 |     |                  |             |                    |             |              |
| 521406                         | Main Entrance Door Selector Valve - Removal /     |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                                | Installation                                      |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                                | 60P2910032Z001                                    | 0192          | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                                |                                                   |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe                       |                                                   |               |                                    |             |                 |     |                  |             |                    |             |              |
| 521410                         | Main Entrance Door Damper - Discard               |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                                | 60P5210904Z003                                    | L208          | AFL                                |             | 1117            |     | 5000             | 0           | 5000               |             | 0            |
|                                |                                                   |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                                |                                                   |               |                                    |             |                 |     |                  |             |                    |             |              |
| Airframe                       |                                                   |               |                                    |             |                 |     |                  |             |                    |             |              |
| Notes: MRI PARENT CODE: 521400 |                                                   |               |                                    |             |                 |     |                  |             |                    |             |              |
| 521500                         | Main Entrance Door Inner and Outer Seal - General |               | HRS                                |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                                | Visual Inspection                                 |               | AFL                                |             | 52              |     |                  | 1065        |                    |             | 0            |
|                                |                                                   |               | MOS                                |             | 5.3             |     | 60               | 01 Dec 2025 | 31 Dec 2030        | 31 Jan 2031 |              |
|                                |                                                   |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe                       |                                                   |               |                                    |             |                 |     |                  |             |                    |             |              |
| 052014                         |                                                   |               |                                    |             |                 |     |                  |             |                    |             |              |
| 522000                         | Emergency Exit Doors - Functional Check           |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                                |                                                   |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                                |                                                   |               | MOS                                |             | 28.7            |     | 48               | 21 Dec 2023 | 31 Dec 2027        | 31 Jan 2028 |              |
|                                |                                                   |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe                       |                                                   |               |                                    |             |                 |     |                  |             |                    |             |              |
| 052013                         |                                                   |               |                                    |             |                 |     |                  |             |                    |             |              |
| 522001                         | Emergency Exit Door Seals - Detailed Inspection   |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                                |                                                   |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                                |                                                   |               | MOS                                |             | 28.7            |     | 48               | 21 Dec 2023 | 31 Dec 2027        | 31 Jan 2028 |              |
|                                |                                                   |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe                       |                                                   |               |                                    |             |                 |     |                  |             |                    |             |              |
| 052013                         |                                                   |               |                                    |             |                 |     |                  |             |                    |             |              |
| 522200                         | Emergency Exit Door FS 616.5 (Left) - Removal /   |               | HRS                                | TSN:2314.88 | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                                | Installation                                      |               | AFL                                | TSN:801     | 315             |     |                  | 802         |                    |             | 0            |
|                                | 60P5220101M020                                    | S02362665     | MOS                                | TSN:99      | 29.6            |     |                  | 22 Nov 2023 |                    |             |              |
|                                |                                                   |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe                       |                                                   |               |                                    |             |                 |     |                  |             |                    |             |              |
| 522201                         | Emergency Exit Door FS 616.5 (Right) - Removal /  |               | HRS                                | TSN:2315.58 | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                                | Installation                                      |               | AFL                                | TSN:802     | 315             |     |                  | 802         |                    |             | 0            |
|                                | 60P5220101M020                                    | S02357165     | MOS                                | TSN:99      | 30.1            |     |                  | 08 Nov 2023 |                    |             |              |
|                                |                                                   |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe                       |                                                   |               |                                    |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom  | Description                                                   |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due     | Avg Man Hrs  |
|------------------|---------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|---------------------|-------------|--------------|
|                  | Part Number                                                   | Serial Number |                                    |             |                 |     |                  |             |                     |             | Approx Price |
| Logbook Position | HW                                                            | SW            |                                    |             |                 |     |                  |             |                     |             | Manufacturer |
|                  | MM Ref                                                        |               |                                    |             |                 |     |                  |             |                     |             | Date Type    |
|                  | Ops Number(s)                                                 |               |                                    |             |                 |     |                  |             |                     |             |              |
| 522202           | Emergency Exit Doors - Zonal Inspection                       |               | HRS                                |             | 3046.1          |     |                  | 0           |                     |             | 0            |
|                  |                                                               |               | AFL                                |             | 1117            |     |                  | 0           |                     |             | 0            |
|                  |                                                               |               | MOS                                |             | 122             |     | 144              | 11 Mar 2016 | 31 Mar 2028         | 30 Apr 2028 |              |
|                  | Airframe                                                      |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                     |             |              |
|                  |                                                               | 052019        |                                    |             |                 |     |                  |             |                     |             |              |
| 522203           | Emergency Exit Doors Internal Structure - Detailed Inspection |               | HRS                                |             | 3046.1          |     |                  | 0           |                     |             | 0            |
|                  |                                                               |               | AFL                                |             | 1117            |     |                  | 0           |                     |             | 0            |
|                  |                                                               |               | MOS                                |             | 122             |     | 144              | 11 Mar 2016 | 31 Mar 2028         | 30 Apr 2028 |              |
|                  | Airframe                                                      |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                     |             |              |
|                  |                                                               | 052019        |                                    |             |                 |     |                  |             |                     |             |              |
| 522204           | Emergency Exit Door FS 564 (Left) - Removal / Installation    |               | HRS                                | TSN:2315.58 | 730.5           |     |                  | 2315.6      |                     |             | 0            |
|                  |                                                               |               | AFL                                | TSN:802     | 315             |     |                  | 802         |                     |             | 0            |
|                  | 60P5220101M020                                                | S02335912     | MOS                                | TSN:99      | 30.1            |     |                  | 08 Nov 2023 |                     |             |              |
|                  | Airframe                                                      |               | MSC                                |             | O/C             |     |                  |             |                     |             |              |
| 522205           | Emergency Exit Door FS 564 (Right) - Removal / Installation   |               | HRS                                | TSN:2315.58 | 730.5           |     |                  | 2315.6      |                     |             | 0            |
|                  |                                                               |               | AFL                                | TSN:802     | 315             |     |                  | 802         |                     |             | 0            |
|                  | 60P5220101M020                                                | S02362658     | MOS                                | TSN:99      | 30.1            |     |                  | 08 Nov 2023 |                     |             |              |
|                  | Airframe                                                      |               | MSC                                |             | O/C             |     |                  |             |                     |             |              |
| 522210           | Emergency Exit Door - Rigging                                 |               | HRS                                |             | 1735.8          |     |                  | 1310.3      |                     |             | 0            |
|                  |                                                               |               | AFL                                |             | 729             |     |                  | 388         |                     |             | 0            |
|                  |                                                               |               | MOS                                |             | 75.2            |     |                  | 05 Feb 2020 |                     |             |              |
|                  | Airframe                                                      |               | MSC                                |             | O/C             |     |                  |             |                     |             |              |
| 522219           | Emergency Exit Door Release Handle Switch - Adjustment / Test |               | HRS                                |             | 1735.8          |     |                  | 1310.3      |                     |             | 0            |
|                  |                                                               |               | AFL                                |             | 729             |     |                  | 388         |                     |             | 0            |
|                  |                                                               |               | MOS                                |             | 75.2            |     |                  | 05 Feb 2020 |                     |             |              |
|                  | Airframe                                                      |               | MSC                                |             | O/C             |     |                  |             |                     |             |              |
| 522221           | Emergency Exit Stop Fittings (Left) - Ndt Inspection          |               | HRS                                |             | 3046.1          |     |                  | 0           |                     |             | 0            |
|                  |                                                               |               | AFL                                |             | 1117            |     | 13580**          | 0           | 13580               |             | 0            |
|                  |                                                               |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                     |             |              |
| Airframe         |                                                               |               |                                    |             |                 |     |                  |             |                     |             |              |

| ATA<br>U=Custom  | Description                                                    |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                    | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                             | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                         |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                  |               |     |             |                 |     |                  |             |                    |         |              |
| 522222           | Emergency Exit Stop Fittings (Right) - Ndt Inspection          |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                |               | AFL |             | 1117            |     | 13580**          | 0           | 13580              |         | 0            |
|                  |                                                                |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe         |                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| 523000           | Baggage Door - Detailed Inspection                             |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe         |                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| 523001           | Baggage Compartment Door - Zonal Inspection                    |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                |               | MOS |             | 122             | 144 | 11 Mar 2016      | 31 Mar 2028 | 30 Apr 2028        |         |              |
| Airframe         |                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| 052019           |                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| 523110           | Baggage Door - Removal / Installation                          |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P5230110A047P02                                              | G0192892301   | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe         |                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| 523111           | Baggage Door Interior Skin and Structure - Detailed Inspection |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                |               | MOS |             | 122             | 144 | 11 Mar 2016      | 31 Mar 2028 | 30 Apr 2028        |         |              |
| Airframe         |                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| 052019           |                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| 523112           | Baggage Door Cable - Adjustment / Test                         |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe         |                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| 523113           | Baggage Door Stops - Adjustment                                |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe         |                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| 523400           | Baggage Door Seal FS 824.5 - FS 867- Detailed Inspection       |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  |                                                                |               | AFL |             | 315             |     |                  | 802         |                    |         | 0            |
|                  |                                                                |               | MOS |             | 28.7            | 48  | 21 Dec 2023      | 31 Dec 2027 | 31 Jan 2028        |         |              |
| Airframe         |                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| 052013           |                                                                |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                 |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------|-------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                  | Part Number                                                 | Serial Number |                                    |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position | HW                                                          | SW            |                                    |             |                 |     |                  |             |                    |             | Manufacturer |
|                  | MM Ref                                                      |               |                                    |             |                 |     |                  |             |                    |             | Date Type    |
|                  | Ops Number(s)                                               |               |                                    |             |                 |     |                  |             |                    |             |              |
| 524400           | Tail Compartment Door - Zonal Inspection                    |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                             |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                             |               | MOS                                |             | 128.6           |     | 24 Aug 2015      |             |                    |             |              |
|                  | Airframe                                                    |               | MSC                                |             |                 | O/C |                  |             |                    |             |              |
| 524401           | Tail Access Door Assembly - Removal / Installation          |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  | 60P5240051A010                                              | SN-UNKNOWN    | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                             |               | MOS                                |             | 128.6           |     | 24 Aug 2015      |             |                    |             |              |
|                  | Airframe                                                    |               | MSC                                |             |                 | O/C |                  |             |                    |             |              |
| 525100           | Auxiliary Pressure Bulkhead Door - Removal / Installation   |               | HRS                                |             | 1300.7          |     |                  | 1745.4      |                    |             | 0            |
|                  | 60P5250110C016                                              | SN-UNKNOWN    | AFL                                |             | 507             |     |                  | 610         |                    |             | 0            |
|                  |                                                             |               | MOS                                |             | 52              |     | 12 Jan 2022      |             |                    |             |              |
|                  | Airframe                                                    |               | MSC                                |             |                 | O/C |                  |             |                    |             |              |
| 525102           | Auxiliary Pressure Bulkhead Door Seal - Detailed Inspection |               | HRS                                |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                  |                                                             |               | AFL                                |             | 52              |     |                  | 1065        |                    |             | 0            |
|                  |                                                             |               | MOS                                |             | 5.3             | -3  | 12               | 02 Dec 2025 | 30 Nov 2026*       | 31 Dec 2026 |              |
|                  | Airframe                                                    |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
|                  | 052010                                                      |               |                                    |             |                 |     |                  |             |                    |             |              |
| 525200           | Acoustic Door Automatic Opening - Operational Check         |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                             |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                             |               | MOS                                |             | 28.7            |     | 36               | 21 Dec 2023 | 31 Dec 2026        | 31 Jan 2027 |              |
|                  | Airframe                                                    |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
|                  | 052012                                                      |               |                                    |             |                 |     |                  |             |                    |             |              |
| 525205           | Acoustic Door Warning Switch - Removal / Installation       |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  | 80-133                                                      | 734           | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                             |               | MOS                                |             | 128.6           |     | 24 Aug 2015      |             |                    |             |              |
|                  | Airframe                                                    |               | MSC                                |             |                 | O/C |                  |             |                    |             |              |
| 525211           | Acoustic Door Reels - Adjustment / Test                     |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                             |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                             |               | MOS                                |             | 128.6           |     | 24 Aug 2015      |             |                    |             |              |
|                  | Airframe                                                    |               | MSC                                |             |                 | O/C |                  |             |                    |             |              |
| 525212           | Acoustic Door Latch and Soleniod - Adjustment / Test        |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                             |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                             |               | MOS                                |             | 128.6           |     | 24 Aug 2015      |             |                    |             |              |
|                  | Airframe                                                    |               | MSC                                |             |                 | O/C |                  |             |                    |             |              |



| ATA<br>U=Custom  | Description                                                             |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|-------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                                             | Serial Number |                                    |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                                      | SW            |                                    |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                                  |               |                                    |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                                           |               |                                    |             |                 |     |                  |             |                     |         |              |
| 525213           | Acoustic Door Warning Switch - Adjustment Test                          |               | HRS                                |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                         |               | AFL                                |             | 1117            |     |                  | 0           |                     | 0       |              |
|                  |                                                                         |               | MOS                                |             | 128.6           |     | 24 Aug 2015      |             |                     |         |              |
|                  |                                                                         |               | MSC                                |             |                 | O/C |                  |             |                     |         |              |
| Airframe         |                                                                         |               |                                    |             |                 |     |                  |             |                     |         |              |
| 527100           | Main Entrance Door Warning Indication - Operational Test                |               | HRS                                |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                         |               | AFL                                |             | 1117            |     |                  | 0           |                     | 0       |              |
|                  |                                                                         |               | MOS                                |             | 128.6           |     | 24 Aug 2015      |             |                     |         |              |
|                  |                                                                         |               | MSC                                |             |                 | O/C |                  |             |                     |         |              |
| Airframe         |                                                                         |               |                                    |             |                 |     |                  |             |                     |         |              |
| 527101           | Emergency Exit Doors Open Warning Indication - Operational Check        |               | HRS                                |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                         |               | AFL                                |             | 1117            |     |                  | 0           |                     | 0       |              |
|                  |                                                                         |               | MOS                                |             | 128.6           |     | 24 Aug 2015      |             |                     |         |              |
|                  |                                                                         |               | MSC                                |             |                 | O/C |                  |             |                     |         |              |
| Airframe         |                                                                         |               |                                    |             |                 |     |                  |             |                     |         |              |
| 527102           | Emergency Exit Door Release Latch Switches - Operational Check          |               | HRS                                |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                         |               | AFL                                |             | 1117            |     |                  | 0           |                     | 0       |              |
|                  |                                                                         |               | MOS                                |             | 128.6           |     | 24 Aug 2015      |             |                     |         |              |
|                  |                                                                         |               | MSC                                |             |                 | O/C |                  |             |                     |         |              |
| Airframe         |                                                                         |               |                                    |             |                 |     |                  |             |                     |         |              |
| 527103           | Auxiliary Pressure Bulkhead Door Warning Indication - Operational Check |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                     |         | 0            |
|                  |                                                                         |               | AFL                                |             | 315             |     |                  | 802         |                     | 0       |              |
|                  |                                                                         |               | MOS                                |             | 28.7            | 48  | 21 Dec 2023      | 31 Dec 2027 | 31 Jan 2028         |         |              |
|                  |                                                                         |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                     |         |              |
| Airframe         | 052013                                                                  |               |                                    |             |                 |     |                  |             |                     |         |              |
| 527105           | Baggage Door Warning Switch - Adjustment / Test                         |               | HRS                                |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                         |               | AFL                                |             | 1117            |     |                  | 0           |                     | 0       |              |
|                  |                                                                         |               | MOS                                |             | 128.6           |     | 24 Aug 2015      |             |                     |         |              |
|                  |                                                                         |               | MSC                                |             |                 | O/C |                  |             |                     |         |              |
| Airframe         |                                                                         |               |                                    |             |                 |     |                  |             |                     |         |              |
| 527110           | Service Door Warning Switch - Adjustment / Test                         |               | HRS                                |             | 663.7           |     |                  | 2382.4      |                     |         | 0            |
|                  |                                                                         |               | AFL                                |             | 291             |     |                  | 826         |                     | 0       |              |
|                  |                                                                         |               | MOS                                |             | 24.9            |     | 15 Apr 2024      |             |                     |         |              |
|                  |                                                                         |               | MSC                                |             |                 | O/C |                  |             |                     |         |              |
| Airframe         |                                                                         |               |                                    |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom  | Description                                                                                |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|--------------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                                                                | Serial Number |     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                                                         | SW            |     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                                                     |               |     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                                                              |               |     |             |                 |     |                  |             |                     |         |              |
| 527113           | Auxiliary Pressure Bulkhead Door Switch - Adjustment /<br>Test                             |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                                            |               | AFL |             | 1117            |     |                  | 0           |                     | 0       |              |
|                  |                                                                                            |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                                            |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                            |               |     |             |                 |     |                  |             |                     |         |              |
| 527502           | Control Display Unit - Removal / Installation<br>100-0106-01115290301-04002                |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                                            |               | AFL |             | 1117            |     |                  | 0           |                     | 0       |              |
|                  |                                                                                            |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                                            |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                            |               |     |             |                 |     |                  |             |                     |         |              |
| 527503           | Securaplane Control Module - Removal / Installation<br>100-2825-01NSN                      |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                                            |               | AFL |             | 1117            |     |                  | 0           |                     | 0       |              |
|                  |                                                                                            |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                                            |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                            |               |     |             |                 |     |                  |             |                     |         |              |
| 527506           | Security System Digital Video Recorder - Removal /<br>Installation<br>S65-5366-715784-1758 |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                                            |               | AFL |             | 1117            |     |                  | 0           |                     | 0       |              |
|                  |                                                                                            |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                                            |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                            |               |     |             |                 |     |                  |             |                     |         |              |
| 527510           | Battery Pack - Removal / Installation<br>100-1032-021155474                                |               | HRS |             | 3033.8          |     |                  | 12.3        |                     |         | 0            |
|                  |                                                                                            |               | AFL |             | 1112            |     |                  | 5           |                     | 0       |              |
|                  |                                                                                            |               | MOS |             | 126             |     |                  | 11 Nov 2015 |                     |         |              |
|                  |                                                                                            |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                            |               |     |             |                 |     |                  |             |                     |         |              |
| 527515           | Ultra High Frequency Antenna (Security) - Removal /<br>Installation<br>100-2617-010484     |               | HRS | TSN:1733.1  | 1300.7          |     |                  | 1745.4      |                     |         | 0            |
|                  |                                                                                            |               | AFL | TSN:605     | 507             |     |                  | 610         |                     | 0       |              |
|                  |                                                                                            |               | MOS | TSN:74      | 51.7            |     |                  | 19 Jan 2022 |                     |         |              |
|                  |                                                                                            |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                            |               |     |             |                 |     |                  |             |                     |         |              |
| 527517           | Ultra High Frequency Voice Communications / Security<br>System - Operational Test          |               | HRS |             | 1300.7          |     |                  | 1745.4      |                     |         | 0            |
|                  |                                                                                            |               | AFL |             | 507             |     |                  | 610         |                     | 0       |              |
|                  |                                                                                            |               | MOS |             | 51.3            |     |                  | 02 Feb 2022 |                     |         |              |
|                  |                                                                                            |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                            |               |     |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom  | Description                                                                      |                                    | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W                             | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------------------------------------|------------------------------------|-----|-------------|-----------------|-----|------------------|--------------------------------------|--------------------|---------|--------------|
|                  | Part Number                                                                      | Serial Number                      |     |             |                 |     |                  |                                      |                    |         | Approx Price |
| Logbook Position | HW                                                                               | SW                                 |     |             |                 |     |                  |                                      |                    |         | Manufacturer |
|                  | MM Ref                                                                           |                                    |     |             |                 |     |                  |                                      |                    |         | Date Type    |
|                  | Ops Number(s)                                                                    |                                    |     |             |                 |     |                  |                                      |                    |         |              |
| 527518           | Security System Radio - Removal / Installation                                   |                                    | HRS |             | 3046.1          |     |                  | 0                                    |                    |         | 0            |
|                  | 800-0025-02                                                                      | 004TQU2000                         | AFL |             | 1117            |     |                  | 0                                    |                    |         | 0            |
|                  |                                                                                  |                                    | MOS |             | 128.6           |     |                  | 24 Aug 2015                          |                    |         |              |
|                  | Airframe                                                                         |                                    | MSC |             |                 |     | O/C              |                                      |                    |         |              |
| 527520           | Digital Alarm Indicator - Removal / Installation                                 |                                    | HRS |             | 3046.1          |     |                  | 0                                    |                    |         | 0            |
|                  | 100-0651-01                                                                      | 1148237                            | AFL |             | 1117            |     |                  | 0                                    |                    |         | 0            |
|                  |                                                                                  |                                    | MOS |             | 128.6           |     |                  | 24 Aug 2015                          |                    |         |              |
|                  | Airframe                                                                         |                                    | MSC |             |                 |     | O/C              |                                      |                    |         |              |
| 527524           | Passive Infrared Sensor (Nose Wheel Well Right Forward) - Removal / Installation |                                    | HRS |             | 3033.8          |     |                  | 12.3                                 |                    |         | 0            |
|                  |                                                                                  |                                    | AFL |             | 1112            |     |                  | 5                                    |                    |         | 0            |
|                  | 100-2418-01                                                                      | 1155825                            | MOS |             | 126.6           |     |                  | 22 Oct 2015                          |                    |         |              |
|                  | Airframe                                                                         |                                    | MSC |             |                 |     | O/C              |                                      |                    |         |              |
| 527526           | Passive Infrared Sensor (Nose Wheel Well Right Aft) - Removal / Installation     |                                    | HRS |             | 3033.8          |     |                  | 12.3                                 |                    |         | 0            |
|                  |                                                                                  |                                    | AFL |             | 1112            |     |                  | 5                                    |                    |         | 0            |
|                  | 100-0401-11                                                                      | DELETED                            | MOS |             | 126             |     |                  | 11 Nov 2015                          |                    |         |              |
|                  | Airframe                                                                         |                                    | MSC |             |                 |     | O/C              |                                      |                    |         |              |
| 527528           | Passive Infrared Sensor (Main Wheel Well Left) - Removal / Installation          |                                    | HRS |             | 1844.6          |     |                  | 1201.5                               |                    |         | 0            |
|                  |                                                                                  |                                    | AFL |             | 766             |     |                  | 351                                  |                    |         | 0            |
|                  | 100-2418-01                                                                      | 1155826                            | MOS |             | 79.5            |     |                  | 28 Sep 2019                          |                    |         |              |
|                  | Airframe                                                                         |                                    | MSC |             |                 |     | O/C              |                                      |                    |         |              |
| 527530           | Passive Infrared Sensor (Main Wheel Well Right) - Removal / Installation         |                                    | HRS | TSN:1189.2  | 1844.6          |     |                  | 1201.5                               |                    |         | 0            |
|                  |                                                                                  |                                    | AFL | TSN:346     | 766             |     |                  | 351                                  |                    |         | 0            |
|                  | 100-2418-01                                                                      | 1155827                            | MOS | TSN:47      | 79.5            |     |                  | 28 Sep 2019                          |                    |         |              |
|                  | Airframe                                                                         |                                    | MSC |             |                 |     | O/C              |                                      |                    |         |              |
| 53 - Fuselage    |                                                                                  |                                    |     |             |                 |     |                  |                                      |                    |         |              |
| 530001           | Antenna Interface - Detailed Inspection                                          |                                    | HRS |             | 1300.7          |     |                  | 1745.4                               |                    |         | 0            |
|                  |                                                                                  |                                    | AFL |             | 507             |     |                  | 610                                  |                    |         | 0            |
|                  |                                                                                  |                                    | MOS |             | 51.3            | 37  | 72               | 03 Feb 2022 31 Mar 2028* 30 Apr 2028 |                    |         |              |
| Airframe         |                                                                                  | [End Of Month Item] [MOS: +1m/-1m] |     |             |                 |     |                  |                                      |                    |         |              |
| 052015           |                                                                                  |                                    |     |             |                 |     |                  |                                      |                    |         |              |

| ATA<br>U=Custom  | Description                                                                                       |                                    | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------|---------------------------------------------------------------------------------------------------|------------------------------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                  | Part Number                                                                                       | Serial Number                      |     |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position | HW                                                                                                | SW                                 |     |             |                 |     |                  |             |                    |             | Manufacturer |
|                  | MM Ref                                                                                            |                                    |     |             |                 |     |                  |             |                    |             | Date Type    |
|                  | Ops Number(s)                                                                                     |                                    |     |             |                 |     |                  |             |                    |             |              |
| 530002           | Cabin Fixed Windows Internal - Detailed Inspection                                                |                                    | HRS |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                   |                                    | AFL |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                   |                                    | MOS |             | 122             |     | 144              | 11 Mar 2016 | 31 Mar 2028        | 30 Apr 2028 |              |
|                  | Airframe                                                                                          | [End Of Month Item] [MOS: +1m/-1m] |     |             |                 |     |                  |             |                    |             |              |
|                  | 052019                                                                                            |                                    |     |             |                 |     |                  |             |                    |             |              |
| 530003           | Exterior Skin Panel Installations (Enclosed By Pylons) FS 838 - FS 1059.625 - Detailed Inspection |                                    | HRS |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                                                   |                                    | AFL |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                                                   |                                    | MOS |             | 28.7            |     | 48               | 21 Dec 2023 | 31 Dec 2027        | 31 Jan 2028 |              |
|                  | Airframe                                                                                          | [End Of Month Item] [MOS: +1m/-1m] |     |             |                 |     |                  |             |                    |             |              |
|                  | 052017                                                                                            |                                    |     |             |                 |     |                  |             |                    |             |              |
| 530004           | External Lower Fuselage FS 100 - FS 886 - Zonal Inspection                                        |                                    | HRS |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                  |                                                                                                   |                                    | AFL |             | 52              |     |                  | 1065        |                    |             | 0            |
|                  |                                                                                                   |                                    | MOS |             | 4.8             |     | 24               | 18 Dec 2025 | 31 Dec 2027        | 31 Jan 2028 |              |
|                  | Airframe                                                                                          | [End Of Month Item] [MOS: +1m/-1m] |     |             |                 |     |                  |             |                    |             |              |
|                  | 052011                                                                                            |                                    |     |             |                 |     |                  |             |                    |             |              |
| 530005           | Radome (Interior) and Equipment AREA Behind Radome - Zonal Inspection                             |                                    | HRS |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                   |                                    | AFL |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                   |                                    | MOS |             | 122             |     | 144              | 11 Mar 2016 | 31 Mar 2028        | 30 Apr 2028 |              |
|                  | Airframe                                                                                          | [End Of Month Item] [MOS: +1m/-1m] |     |             |                 |     |                  |             |                    |             |              |
|                  | 052019                                                                                            |                                    |     |             |                 |     |                  |             |                    |             |              |
| 530006           | Lower Forward Cabin and Midcabin Sections FS 245.5 - FS 511.5 - Zonal Inspection                  |                                    | HRS |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                                                   |                                    | AFL |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                                                   |                                    | MOS |             | 28.7            |     | 48               | 21 Dec 2023 | 31 Dec 2027        | 31 Jan 2028 |              |
|                  | Airframe                                                                                          | [End Of Month Item] [MOS: +1m/-1m] |     |             |                 |     |                  |             |                    |             |              |
|                  | 052013                                                                                            |                                    |     |             |                 |     |                  |             |                    |             |              |
| 530007           | Aft Midcabin Fuselage Below Floor Level FS 739 - FS 886 - Zonal Inspection                        |                                    | HRS |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                                                   |                                    | AFL |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                                                   |                                    | MOS |             | 28.7            |     | 48               | 21 Dec 2023 | 31 Dec 2027        | 31 Jan 2028 |              |
|                  | Airframe                                                                                          | [End Of Month Item] [MOS: +1m/-1m] |     |             |                 |     |                  |             |                    |             |              |
|                  | 052013                                                                                            |                                    |     |             |                 |     |                  |             |                    |             |              |
| 530008           | External Upper Fuselage (Viewed from Platform) FS 148.5 - FS 886 - Zonal Inspection               |                                    | HRS |             | 663.7           |     |                  | 2382.4      |                    |             | 0            |
|                  |                                                                                                   |                                    | AFL |             | 291             |     |                  | 826         |                    |             | 0            |
|                  |                                                                                                   |                                    | MOS |             | 25.5            |     | 72               | 28 Mar 2024 | 31 Mar 2030        | 30 Apr 2030 |              |
|                  | Airframe                                                                                          | [End Of Month Item] [MOS: +1m/-1m] |     |             |                 |     |                  |             |                    |             |              |
|                  | 052015                                                                                            |                                    |     |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom  | Description                                               |               | UOM    | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due     | Avg Man Hrs  |
|------------------|-----------------------------------------------------------|---------------|--------|-------------|-----------------|-----|------------------|-------------|---------------------|-------------|--------------|
|                  | Part Number                                               | Serial Number |        |             |                 |     |                  |             |                     |             | Approx Price |
| Logbook Position | HW                                                        | SW            |        |             |                 |     |                  |             |                     |             | Manufacturer |
|                  | MM Ref                                                    |               |        |             |                 |     |                  |             |                     |             | Date Type    |
|                  | Ops Number(s)                                             |               |        |             |                 |     |                  |             |                     |             |              |
| 530009           | Cabin Above Floor from Vestibule to Baggage               |               | HRS    |             | 3046.1          |     |                  | 0           |                     |             | 0            |
|                  | Compartment FS 245.5 - FS 886 - Zonal Inspection          |               | AFL    |             | 1117            |     |                  | 0           |                     |             | 0            |
|                  |                                                           |               | MOS    |             | 122             |     | 144              | 11 Mar 2016 | 31 Mar 2028         | 30 Apr 2028 |              |
|                  | [End Of Month Item] [MOS: +1m/-1m]                        |               |        |             |                 |     |                  |             |                     |             |              |
| Airframe         |                                                           |               | 052019 |             |                 |     |                  |             |                     |             |              |
| 530010           | External Aft Fuselage and Empennage FS 886 - FS           |               | HRS    |             | 663.7           |     |                  | 2382.4      |                     |             | 0            |
|                  | 1199.475 - Zonal Inspection                               |               | AFL    |             | 291             |     |                  | 826         |                     |             | 0            |
|                  |                                                           |               | MOS    |             | 25.5            |     | 72               | 28 Mar 2024 | 31 Mar 2030         | 30 Apr 2030 |              |
|                  | [End Of Month Item] [MOS: +1m/-1m]                        |               |        |             |                 |     |                  |             |                     |             |              |
| Airframe         |                                                           |               | 052015 |             |                 |     |                  |             |                     |             |              |
| 530011           | Lower Forward Cabin and Midcabin Sections FS 245.5 -      |               | HRS    |             | 730.5           |     |                  | 2315.6      |                     |             | 0            |
|                  | FS 511.5 - Enhanced Zonal Inspection                      |               | AFL    |             | 315             |     |                  | 802         |                     |             | 0            |
|                  |                                                           |               | MOS    |             | 28.7            |     | 48               | 21 Dec 2023 | 31 Dec 2027         | 31 Jan 2028 |              |
|                  | [End Of Month Item] [MOS: +1m/-1m]                        |               |        |             |                 |     |                  |             |                     |             |              |
| Airframe         |                                                           |               | 052013 |             |                 |     |                  |             |                     |             |              |
| 530012           | Lower Forward Cabin and Midcabin Cleaning and Dust        |               | HRS    |             | 730.5           |     |                  | 2315.6      |                     |             | 0            |
|                  | Removal - Enhanced Zonal Inspection                       |               | AFL    |             | 315             |     |                  | 802         |                     |             | 0            |
|                  |                                                           |               | MOS    |             | 28.7            |     | 48               | 21 Dec 2023 | 31 Dec 2027         | 31 Jan 2028 |              |
|                  | [End Of Month Item] [MOS: +1m/-1m]                        |               |        |             |                 |     |                  |             |                     |             |              |
| Airframe         |                                                           |               | 052013 |             |                 |     |                  |             |                     |             |              |
| 530013           | Aft Midcabin Fuselage Below Floor Level FS 739 - FS 886   |               | HRS    |             | 730.5           |     |                  | 2315.6      |                     |             | 0            |
|                  | - Enhanced Zonal Inspection                               |               | AFL    |             | 315             |     |                  | 802         |                     |             | 0            |
|                  |                                                           |               | MOS    |             | 28.7            |     | 48               | 21 Dec 2023 | 31 Dec 2027         | 31 Jan 2028 |              |
|                  | [End Of Month Item] [MOS: +1m/-1m]                        |               |        |             |                 |     |                  |             |                     |             |              |
| Airframe         |                                                           |               | 052013 |             |                 |     |                  |             |                     |             |              |
| 530014           | Vestibule and Forward Cabin Below Floor Hirf/L - Detailed |               | HRS    |             | 1300.7          |     |                  | 1745.4      |                     |             | 0            |
|                  | Inspection                                                |               | AFL    |             | 507             |     |                  | 610         |                     |             | 0            |
|                  |                                                           |               | MOS    |             | 51.7            |     | 72               | 19 Jan 2022 | 31 Jan 2028         | 29 Feb 2028 |              |
|                  | [End Of Month Item] [MOS: +1m/-1m]                        |               |        |             |                 |     |                  |             |                     |             |              |
| Airframe         |                                                           |               | 052015 |             |                 |     |                  |             |                     |             |              |
| 530015           | Tail Compartment Hirf/L - Detailed Inspection             |               | HRS    |             | 730.5           |     |                  | 2315.6      |                     |             | 0            |
|                  |                                                           |               | AFL    |             | 315             |     |                  | 802         |                     |             | 0            |
|                  |                                                           |               | MOS    |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031         | 31 Jan 2032 |              |
|                  | [End Of Month Item] [MOS: +1m/-1m]                        |               |        |             |                 |     |                  |             |                     |             |              |
| Airframe         |                                                           |               | 052016 |             |                 |     |                  |             |                     |             |              |

| ATA<br>U=Custom  | Description                                                                  |               | UOM                                | Times Since | Time<br>Accrued | Adj    | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|--------|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                  | Serial Number |                                    |             |                 |        |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                           | SW            |                                    |             |                 |        |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                       |               |                                    |             |                 |        |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                                |               |                                    |             |                 |        |                  |             |                    |         |              |
| 530016           | Cabin Fixed Window Frames and Surrounds (Left No. 1) - Detailed Inspection   |               | HRS                                |             | 3046.1          |        |                  | 0           |                    |         | 0            |
|                  |                                                                              |               | AFL                                |             | 1117            |        | 0                |             |                    | 0       |              |
|                  |                                                                              |               | MOS                                |             | 122             | 192    | 11 Mar 2016      | 31 Mar 2032 | 30 Apr 2032        |         |              |
|                  |                                                                              |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |        |                  |             |                    |         |              |
| Airframe         |                                                                              |               | 052021                             |             |                 |        |                  |             |                    |         |              |
| 530017           | External Fuselage - General Visual Inspection                                |               | HRS                                |             | 994.2           |        |                  | 2051.9      |                    |         | 0            |
|                  |                                                                              |               | AFL                                |             | 392             | 800    | 725              | 1525        |                    | 0       |              |
|                  |                                                                              |               | MOS                                |             | 41.1            |        | 07 Dec 2022      |             |                    |         |              |
|                  |                                                                              |               | Airframe                           |             |                 |        |                  |             |                    |         |              |
| 530022           | Mid Cabin Window Rings (Left) - Ndt Inspection                               |               | HRS                                |             | 3046.1          |        |                  | 0           |                    |         | 0            |
|                  |                                                                              |               | AFL                                |             | 1117            | 8955** | 0                | 8955        |                    | 0       |              |
|                  |                                                                              |               | MOS                                |             | 128.6           |        | 24 Aug 2015      |             |                    |         |              |
|                  |                                                                              |               | Airframe                           |             |                 |        |                  |             |                    |         |              |
| 530023           | Mid Cabin Window Rings (Right) - Ndt Inspection                              |               | HRS                                |             | 3046.1          |        |                  | 0           |                    |         | 0            |
|                  |                                                                              |               | AFL                                |             | 1117            | 8955** | 0                | 8955        |                    | 0       |              |
|                  |                                                                              |               | MOS                                |             | 128.6           |        | 24 Aug 2015      |             |                    |         |              |
|                  |                                                                              |               | Airframe                           |             |                 |        |                  |             |                    |         |              |
| 530100           | Vortex Generator - Removal / Installation<br>PN SN-UNKNOWN                   |               | HRS                                |             | 3046.1          |        |                  | 0           |                    |         | 0            |
|                  |                                                                              |               | AFL                                |             | 1117            |        | 0                |             |                    | 0       |              |
|                  |                                                                              |               | MOS                                |             | 128.6           |        | 24 Aug 2015      |             |                    |         |              |
|                  |                                                                              |               | MSC                                |             |                 | O/C    |                  |             |                    |         |              |
| Airframe         |                                                                              |               |                                    |             |                 |        |                  |             |                    |         |              |
| 531000           | Radome - Removal / Installation<br>1159B57292-7 1-202                        |               | HRS                                | TSN:2315.58 | 730.5           |        |                  | 2315.6      |                    |         | 0            |
|                  |                                                                              |               | AFL                                | TSN:802     | 315             |        | 802              |             |                    | 0       |              |
|                  |                                                                              |               | MOS                                | TSN:100     | 28.7            |        | 21 Dec 2023      |             |                    |         |              |
|                  |                                                                              |               | MSC                                |             |                 | O/C    |                  |             |                    |         |              |
| Airframe         |                                                                              |               |                                    |             |                 |        |                  |             |                    |         |              |
| 531001           | Bird Impact Plate (Left) - Removal / Installation<br>60P5318001N021 NSN      |               | HRS                                |             | 3046.1          |        |                  | 0           |                    |         | 0            |
|                  |                                                                              |               | AFL                                |             | 1117            |        | 0                |             |                    | 0       |              |
|                  |                                                                              |               | MOS                                |             | 128.6           |        | 24 Aug 2015      |             |                    |         |              |
|                  |                                                                              |               | MSC                                |             |                 | O/C    |                  |             |                    |         |              |
| Airframe         |                                                                              |               |                                    |             |                 |        |                  |             |                    |         |              |
| 531002           | Bird Impact Plate (Center) - Removal / Installation<br>60P5312001S132L01 NSN |               | HRS                                |             | 3046.1          |        |                  | 0           |                    |         | 0            |
|                  |                                                                              |               | AFL                                |             | 1117            |        | 0                |             |                    | 0       |              |
|                  |                                                                              |               | MOS                                |             | 128.6           |        | 24 Aug 2015      |             |                    |         |              |
|                  |                                                                              |               | MSC                                |             |                 | O/C    |                  |             |                    |         |              |
| Airframe         |                                                                              |               |                                    |             |                 |        |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                          |                                    | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------|--------------------------------------------------------------------------------------|------------------------------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                  | Part Number                                                                          | Serial Number                      |     |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position | HW                                                                                   | SW                                 |     |             |                 |     |                  |             |                    |             | Manufacturer |
|                  | MM Ref                                                                               |                                    |     |             |                 |     |                  |             |                    |             | Date Type    |
|                  | Ops Number(s)                                                                        |                                    |     |             |                 |     |                  |             |                    |             |              |
| 531003           | Bird Impact Plate (Right) - Removal / Installation                                   |                                    | HRS |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  | 60P5318002N005                                                                       | NSN                                | AFL |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                      |                                    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  | Airframe                                                                             |                                    | MSC |             |                 |     | O/C              |             |                    |             |              |
| 531007           | Forward Fuselage Above Floor FS 148.5 - FS 245.5 - Detailed Inspection               |                                    | HRS |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                      |                                    | AFL |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                      |                                    | MOS |             | 122             |     | 192              | 11 Mar 2016 | 31 Mar 2032        | 30 Apr 2032 |              |
|                  | Airframe                                                                             | [End Of Month Item] [MOS: +1m/-1m] |     |             |                 |     |                  |             |                    |             |              |
|                  | 052021                                                                               |                                    |     |             |                 |     |                  |             |                    |             |              |
| 531008           | Forward Fuselage Below Floor FS 148.5 - FS 245.5 - Detailed Inspection               |                                    | HRS |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                      |                                    | AFL |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                      |                                    | MOS |             | 122             |     | 144              | 11 Mar 2016 | 31 Mar 2028        | 30 Apr 2028 |              |
|                  | Airframe                                                                             | [End Of Month Item] [MOS: +1m/-1m] |     |             |                 |     |                  |             |                    |             |              |
|                  | 052019                                                                               |                                    |     |             |                 |     |                  |             |                    |             |              |
| 531010           | Canopy Roof - Detailed Inspection                                                    |                                    | HRS |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                      |                                    | AFL |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                      |                                    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  | Airframe                                                                             |                                    | MSC |             |                 |     | O/C              |             |                    |             |              |
| 531011           | Cockpit Interior Above Headliner FS 167 - FS 245.5 - Zonal Inspection                |                                    | HRS |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                      |                                    | AFL |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                      |                                    | MOS |             | 122             |     | 144              | 11 Mar 2016 | 31 Mar 2028        | 30 Apr 2028 |              |
|                  | Airframe                                                                             | [End Of Month Item] [MOS: +1m/-1m] |     |             |                 |     |                  |             |                    |             |              |
|                  | 052019                                                                               |                                    |     |             |                 |     |                  |             |                    |             |              |
| 531012           | Left and Right Cockpit Interior Floor Up to Window Level - Zonal Inspection          |                                    | HRS |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                                      |                                    | AFL |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                                      |                                    | MOS |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031        | 31 Jan 2032 |              |
|                  | Airframe                                                                             | [End Of Month Item] [MOS: +1m/-1m] |     |             |                 |     |                  |             |                    |             |              |
|                  | 052016                                                                               |                                    |     |             |                 |     |                  |             |                    |             |              |
| 531013           | Left and Right Cockpit Interior Floor Up to Window Level - Enhanced Zonal Inspection |                                    | HRS |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                      |                                    | AFL |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                      |                                    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  | Airframe                                                                             |                                    | MSC |             |                 |     | O/C              |             |                    |             |              |

| ATA<br>U=Custom  | Description                                                                                         |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due     | Avg Man Hrs  |
|------------------|-----------------------------------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|---------------------|-------------|--------------|
|                  | Part Number                                                                                         | Serial Number |                                    |             |                 |     |                  |             |                     |             | Approx Price |
| Logbook Position | HW                                                                                                  | SW            |                                    |             |                 |     |                  |             |                     |             | Manufacturer |
|                  | MM Ref                                                                                              |               |                                    |             |                 |     |                  |             |                     |             | Date Type    |
|                  | Ops Number(s)                                                                                       |               |                                    |             |                 |     |                  |             |                     |             |              |
| 531014           | Internal Left and Right Fuselage Below Cockpit Floor AT<br>FS 189.375 - FS 223 - Zonal Inspection   |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                     |             | 0            |
|                  |                                                                                                     |               | AFL                                |             | 315             |     |                  | 802         |                     |             | 0            |
|                  |                                                                                                     |               | MOS                                |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031         | 31 Jan 2032 |              |
|                  |                                                                                                     |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                     |             |              |
| Airframe         |                                                                                                     |               | 052016                             |             |                 |     |                  |             |                     |             |              |
| 531015           | Internal Left and Right Fuselage Below Cockpit Floor AT<br>FS 223 - FS 243 - Zonal Inspection       |               | HRS                                |             | 137             |     |                  | 2909.1      |                     |             | 0            |
|                  |                                                                                                     |               | AFL                                |             | 52              |     |                  | 1065        |                     |             | 0            |
|                  |                                                                                                     |               | MOS                                |             | 5.1             | 42  | 24               | 09 Dec 2025 | 31 Jan 2028*        | 29 Feb 2028 |              |
|                  |                                                                                                     |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                     |             |              |
| Airframe         |                                                                                                     |               | 052011                             |             |                 |     |                  |             |                     |             |              |
| 531016           | Internal Left and Right Fuselage Below Cockpit Floor FS<br>223 - FS 243 - Enhanced Zonal Inspection |               | HRS                                |             | 1300.7          |     |                  | 1745.4      |                     |             | 0            |
|                  |                                                                                                     |               | AFL                                |             | 507             |     |                  | 610         |                     |             | 0            |
|                  |                                                                                                     |               | MOS                                |             | 51.8            |     | 72               | 18 Jan 2022 | 31 Jan 2028         | 29 Feb 2028 |              |
|                  |                                                                                                     |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                     |             |              |
| Airframe         |                                                                                                     |               | 052015                             |             |                 |     |                  |             |                     |             |              |
| 531017           | Cockpit Above Floor Hirf/L - Detailed Inspection                                                    |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                     |             | 0            |
|                  |                                                                                                     |               | AFL                                |             | 315             |     |                  | 802         |                     |             | 0            |
|                  |                                                                                                     |               | MOS                                |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031         | 31 Jan 2032 |              |
|                  |                                                                                                     |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                     |             |              |
| Airframe         |                                                                                                     |               | 052016                             |             |                 |     |                  |             |                     |             |              |
| 531018           | Cockpit Below Floor FS 189.375 - FS 223 Hirf/L - Detailed<br>Inspection                             |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                     |             | 0            |
|                  |                                                                                                     |               | AFL                                |             | 315             |     |                  | 802         |                     |             | 0            |
|                  |                                                                                                     |               | MOS                                |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031         | 31 Jan 2032 |              |
|                  |                                                                                                     |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                     |             |              |
| Airframe         |                                                                                                     |               | 052016                             |             |                 |     |                  |             |                     |             |              |
| 531019           | Cockpit Below Floor FS 223 - FS 243 Hirf/L - Detailed<br>Inspection                                 |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                     |             | 0            |
|                  |                                                                                                     |               | AFL                                |             | 315             |     |                  | 802         |                     |             | 0            |
|                  |                                                                                                     |               | MOS                                |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031         | 31 Jan 2032 |              |
|                  |                                                                                                     |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                     |             |              |
| Airframe         |                                                                                                     |               | 052016                             |             |                 |     |                  |             |                     |             |              |
| 531020           | Internal Below Pedestal - Zonal Inspection                                                          |               | HRS                                |             | 3046.1          |     |                  | 0           |                     |             | 0            |
|                  |                                                                                                     |               | AFL                                |             | 1117            |     |                  | 0           |                     |             | 0            |
|                  |                                                                                                     |               | MOS                                |             | 122             |     | 144              | 11 Mar 2016 | 31 Mar 2028         | 30 Apr 2028 |              |
|                  |                                                                                                     |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                     |             |              |
| Airframe         |                                                                                                     |               | 052019                             |             |                 |     |                  |             |                     |             |              |



| ATA<br>U=Custom  | Description                                                                  |               | UOM                                               | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------|------------------------------------------------------------------------------|---------------|---------------------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                  | Part Number                                                                  | Serial Number |                                                   |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position | HW                                                                           | SW            |                                                   |             |                 |     |                  |             |                    |             | Manufacturer |
|                  | MM Ref                                                                       |               |                                                   |             |                 |     |                  |             |                    |             | Date Type    |
|                  | Ops Number(s)                                                                |               |                                                   |             |                 |     |                  |             |                    |             |              |
| 531021           | Cockpit Below Floor Cleaning and Dust Removal -<br>Enhanced Zonal Inspection |               | HRS                                               |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                  |                                                                              |               | AFL                                               |             | 52              |     |                  | 1065        |                    |             | 0            |
|                  |                                                                              |               | MOS                                               |             | 5.1             | 42  | 24               | 09 Dec 2025 | 31 Jan 2028*       | 29 Feb 2028 |              |
|                  |                                                                              |               | [End Of Month Item] [MOS: +1m/-1m]                |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                              | 052011        |                                                   |             |                 |     |                  |             |                    |             |              |
| 531022           | Leer Hirf/L - Detailed Inspection                                            |               | HRS                                               |             | 1300.7          |     |                  | 1745.4      |                    |             | 0            |
|                  |                                                                              |               | AFL                                               |             | 507             |     |                  | 610         |                    |             | 0            |
|                  |                                                                              |               | MOS                                               |             | 51.7            |     | 72               | 19 Jan 2022 | 31 Jan 2028        | 29 Feb 2028 |              |
|                  |                                                                              |               | [End Of Month Item] [MOS: +1m/-1m]                |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                              | 052015        |                                                   |             |                 |     |                  |             |                    |             |              |
| 531023           | Reer Hirf/L - Detailed Inspection                                            |               | HRS                                               |             | 1300.7          |     |                  | 1745.4      |                    |             | 0            |
|                  |                                                                              |               | AFL                                               |             | 507             |     |                  | 610         |                    |             | 0            |
|                  |                                                                              |               | MOS                                               |             | 51.7            |     | 72               | 19 Jan 2022 | 31 Jan 2028        | 29 Feb 2028 |              |
|                  |                                                                              |               | [End Of Month Item] [MOS: +1m/-1m]                |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                              | 052015        |                                                   |             |                 |     |                  |             |                    |             |              |
| 531024           | Nose Landing Gear Wheel Well FS 148.5 - FS 223 - Zonal<br>Inspection         |               | HRS                                               |             | 137             |     | 600              | 2909.1      | 3509.1             | 3559.1      | 0            |
|                  |                                                                              |               | AFL                                               |             | 52              |     |                  | 1065        |                    |             | 0            |
|                  |                                                                              |               | MOS                                               |             | 5.5             |     | 24               | 27 Nov 2025 | 30 Nov 2027        | 31 Dec 2027 |              |
|                  |                                                                              |               | [End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                              | 052001,052011 |                                                   |             |                 |     |                  |             |                    |             |              |
| 531026           | Radome Assembly - General Visual Inspection                                  |               | HRS                                               |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                  |                                                                              |               | AFL                                               |             | 52              |     |                  | 1065        |                    |             | 0            |
|                  |                                                                              |               | MOS                                               |             | 4.8             |     | 120              | 18 Dec 2025 | 31 Dec 2035        | 31 Jan 2036 |              |
|                  |                                                                              |               | [End Of Month Item] [MOS: +1m/-1m]                |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                              | 052018        |                                                   |             |                 |     |                  |             |                    |             |              |
| 531036           | Radome to Structure Perimeter Steps - Detailed<br>Inspection                 |               | HRS                                               |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                  |                                                                              |               | AFL                                               |             | 52              |     |                  | 1065        |                    |             | 0            |
|                  |                                                                              |               | MOS                                               |             | 4.8             | 28  | 24               | 18 Dec 2025 | 31 Jan 2028*       | 29 Feb 2028 |              |
|                  |                                                                              |               | [End Of Month Item] [MOS: +1m/-1m]                |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                              | 052011        |                                                   |             |                 |     |                  |             |                    |             |              |
| 531037           | Internal Cockpit Below Floor FS 167 - FS 189 - Zonal<br>Inspection           |               | HRS                                               |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                              |               | AFL                                               |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                              |               | MOS                                               |             | 122             | 20  | 144              | 11 Mar 2016 | 31 Mar 2028*       | 30 Apr 2028 |              |
|                  |                                                                              |               | [End Of Month Item] [MOS: +1m/-1m]                |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                              | 052019        |                                                   |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom  | Description                                                                           |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------|---------------------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                  | Part Number                                                                           | Serial Number |                                    |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position | HW                                                                                    | SW            |                                    |             |                 |     |                  |             |                    |             | Manufacturer |
|                  | MM Ref                                                                                |               |                                    |             |                 |     |                  |             |                    |             | Date Type    |
|                  | Ops Number(s)                                                                         |               |                                    |             |                 |     |                  |             |                    |             |              |
| 531100           | Vestibule Internal Above Floor FS 245.50 - FS 324.50 -<br>Special Detailed Inspection |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                       |               | AFL                                |             | 1117            |     |                  | 0           |                    | 0           |              |
|                  |                                                                                       |               | MOS                                |             | 122             |     | 192              | 11 Mar 2016 | 31 Mar 2032        | 30 Apr 2032 |              |
|                  |                                                                                       |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                       | 052021        |                                    |             |                 |     |                  |             |                    |             |              |
| 531101           | Vestibule Internal Below Floor FS 245.5 - FS 324.5 -<br>Detailed Inspection           |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                                       |               | AFL                                |             | 315             |     |                  | 802         |                    | 0           |              |
|                  |                                                                                       |               | MOS                                |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031        | 31 Jan 2032 |              |
|                  |                                                                                       |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                       | 052016        |                                    |             |                 |     |                  |             |                    |             |              |
| 531105           | Nose Landing Gear Skin Cutout AT FS 220 - Visual<br>Inspection                        |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                       |               | AFL                                |             | 1117            |     | 6145**           | 0           | 6145               |             | 0            |
|                  |                                                                                       |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                       |               |                                    |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                       |               |                                    |             |                 |     |                  |             |                    |             |              |
| 531200           | Bulkhead Installation FS 148.5 - Detailed Inspection                                  |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                       |               | AFL                                |             | 1117            |     |                  | 0           |                    | 0           |              |
|                  |                                                                                       |               | MOS                                |             | 122             |     | 192              | 11 Mar 2016 | 31 Mar 2032        | 30 Apr 2032 |              |
|                  |                                                                                       |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                       | 052021        |                                    |             |                 |     |                  |             |                    |             |              |
| 531201           | Bulkhead Installation FS 167 - Detailed Inspection                                    |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                       |               | AFL                                |             | 1117            |     |                  | 0           |                    | 0           |              |
|                  |                                                                                       |               | MOS                                |             | 122             |     | 192              | 11 Mar 2016 | 31 Mar 2032        | 30 Apr 2032 |              |
|                  |                                                                                       |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                       | 052021        |                                    |             |                 |     |                  |             |                    |             |              |
| 531202           | Bulkhead Installation FS 189.375 - Detailed Inspection                                |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                       |               | AFL                                |             | 1117            |     |                  | 0           |                    | 0           |              |
|                  |                                                                                       |               | MOS                                |             | 122             |     | 192              | 11 Mar 2016 | 31 Mar 2032        | 30 Apr 2032 |              |
|                  |                                                                                       |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                       | 052021        |                                    |             |                 |     |                  |             |                    |             |              |
| 531203           | Bulkhead Installation FS 223 - Detailed Inspection                                    |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                       |               | AFL                                |             | 1117            |     |                  | 0           |                    | 0           |              |
|                  |                                                                                       |               | MOS                                |             | 122             |     | 192              | 11 Mar 2016 | 31 Mar 2032        | 30 Apr 2032 |              |
|                  |                                                                                       |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                       | 052021        |                                    |             |                 |     |                  |             |                    |             |              |
| 531204           | Bulkhead Installation FS 243 - Detailed Inspection                                    |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                       |               | AFL                                |             | 1117            |     |                  | 0           |                    | 0           |              |
|                  |                                                                                       |               | MOS                                |             | 122             |     | 192              | 11 Mar 2016 | 31 Mar 2032        | 30 Apr 2032 |              |
|                  |                                                                                       |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                       | 052021        |                                    |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom  | Description                                                                                         |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------|-----------------------------------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                  | Part Number                                                                                         | Serial Number |                                    |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position | HW                                                                                                  | SW            |                                    |             |                 |     |                  |             |                    |             | Manufacturer |
|                  | MM Ref                                                                                              |               |                                    |             |                 |     |                  |             |                    |             | Date Type    |
|                  | Ops Number(s)                                                                                       |               |                                    |             |                 |     |                  |             |                    |             |              |
| 531205           | Bulkhead Installation FS 148.5 - General Visual Inspection                                          |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                                                     |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                                                     |               | MOS                                |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031        | 31 Jan 2032 |              |
|                  | Airframe                                                                                            |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
|                  |                                                                                                     | 052016        |                                    |             |                 |     |                  |             |                    |             |              |
| 531210           | Forward Cabin Frame Splices - Ndt Inspection                                                        |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                     |               | AFL                                |             | 1117            |     | 14230**          | 0           | 14230              |             | 0            |
|                  |                                                                                                     |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  | Airframe                                                                                            |               |                                    |             |                 |     |                  |             |                    |             |              |
| 531300           | Forward Fuselage Below Floor FS 167 - FS 243 - Detailed Inspection                                  |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                     |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                     |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                                     |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                                     |               |                                    |             |                 |     |                  |             |                    |             |              |
| 531301           | Nose Wheel Well Trunnion and Drag Brace Fittings - Detailed Inspection                              |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                     |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                     |               | MOS                                |             | 122             |     | 144              | 11 Mar 2016 | 31 Mar 2028        | 30 Apr 2028 |              |
|                  |                                                                                                     |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                                     | 052019        |                                    |             |                 |     |                  |             |                    |             |              |
| 531302           | Forward Fuselage Above Floor FS 189.375 - FS 243 - Detailed Inspection                              |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                     |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                     |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                                     |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                                     |               |                                    |             |                 |     |                  |             |                    |             |              |
| 531303           | Forward Fuselage Splice Installations Above Floor FS 245.5 - FS 324.5 - Special Detailed Inspection |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                     |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                     |               | MOS                                |             | 122             |     | 192              | 11 Mar 2016 | 31 Mar 2032        | 30 Apr 2032 |              |
|                  |                                                                                                     |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                                     | 052021        |                                    |             |                 |     |                  |             |                    |             |              |
| 531304           | Splice Installations Below Floor Left Side FS 245.5 - FS 324.5 - Detailed Inspection                |               | HRS                                |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                  |                                                                                                     |               | AFL                                |             | 52              |     |                  | 1065        |                    |             | 0            |
|                  |                                                                                                     |               | MOS                                |             | 5               | 37  | 24               | 12 Dec 2025 | 31 Jan 2028*       | 29 Feb 2028 |              |
|                  |                                                                                                     |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                                     | 052011        |                                    |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom  | Description                                                                                       |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------|---------------------------------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                  | Part Number                                                                                       | Serial Number |                                    |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position | HW                                                                                                | SW            |                                    |             |                 |     |                  |             |                    |             | Manufacturer |
|                  | MM Ref                                                                                            |               |                                    |             |                 |     |                  |             |                    |             | Date Type    |
|                  | Ops Number(s)                                                                                     |               |                                    |             |                 |     |                  |             |                    |             |              |
| 531305           | Splice Installations Below Floor (Dry Areas) Right Side FS 245.5 - FS 324.5 - Detailed Inspection |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                   |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                   |               | MOS                                |             | 122             |     | 144              | 11 Mar 2016 | 31 Mar 2028        | 30 Apr 2028 |              |
|                  |                                                                                                   |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                                   |               | 052019                             |             |                 |     |                  |             |                    |             |              |
| 531310           | FS 273 and FS 309 Bulkhead Splices AT Stringers 3L and 19L - Ndt Inspection                       |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                   |               | AFL                                |             | 1117            |     | 15715**          | 0           | 15715              |             | 0            |
|                  |                                                                                                   |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                                   |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                                   |               | 052019                             |             |                 |     |                  |             |                    |             |              |
| 531502           | Floor Structure Left Side FS 245.5 - FS 324.5 - Detailed Inspection                               |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                   |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                   |               | MOS                                |             | 122             |     | 144              | 11 Mar 2016 | 31 Mar 2028        | 30 Apr 2028 |              |
|                  |                                                                                                   |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                                   |               | 052019                             |             |                 |     |                  |             |                    |             |              |
| 531503           | Floor Structure (Dry Areas) Right Side FS 245.5 - FS 324.5 - Detailed Inspection                  |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                   |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                   |               | MOS                                |             | 122             |     | 144              | 11 Mar 2016 | 31 Mar 2028        | 30 Apr 2028 |              |
|                  |                                                                                                   |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                                   |               | 052019                             |             |                 |     |                  |             |                    |             |              |
| 531600           | Cockpit Above Floor FS 167 - FS 189.375 - Detailed Inspection                                     |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                   |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                   |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                                   |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                                   |               | 052019                             |             |                 |     |                  |             |                    |             |              |
| 531601           | Cockpit Interior Above Floor FS 167 - FS 245.5 - Enhanced Zonal Inspection                        |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                                                   |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                                                   |               | MOS                                |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031        | 31 Jan 2032 |              |
|                  |                                                                                                   |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                                   |               | 052016                             |             |                 |     |                  |             |                    |             |              |
| 531602           | Cockpit Interior Cleaning and Dust Removal - Enhanced Zonal Inspection                            |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                                                   |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                                                   |               | MOS                                |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031        | 31 Jan 2032 |              |
|                  |                                                                                                   |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                                   |               | 052016                             |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom  | Description                                                        |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------|--------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                  | Part Number                                                        | Serial Number |                                    |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position | HW                                                                 | SW            |                                    |             |                 |     |                  |             |                    |             | Manufacturer |
|                  | MM Ref                                                             |               |                                    |             |                 |     |                  |             |                    |             | Date Type    |
|                  | Ops Number(s)                                                      |               |                                    |             |                 |     |                  |             |                    |             |              |
| 531605           | Cockpit Pressure Floor - Visual / Ndt Inspection                   |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                    |               | AFL                                |             | 1117            |     | 9820**           | 0           | 9820               |             | 0            |
|                  |                                                                    |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  | Airframe                                                           |               |                                    |             |                 |     |                  |             |                    |             |              |
| 531700           | Cockpit Center Post - Ndt Inspeiton                                |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                    |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                    |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  | Airframe                                                           |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| 531701           | Cockpit Side Post - Ndt Inspeiton                                  |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                    |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                    |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  | Airframe                                                           |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| 531702           | Cockpit Side Window Surround - Ndt Inspection                      |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                    |               | AFL                                |             |                 |     | 7000**           |             | 7000               |             | 0            |
|                  |                                                                    |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  | Airframe                                                           |               |                                    |             |                 |     |                  |             |                    |             |              |
| 531703           | Cockpit Lower RAIL - Detailed Inspection                           |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                    |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                    |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  | Airframe                                                           |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| 531704           | Cockpit Upper RAIL - Detailed Inspection                           |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                    |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                    |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  | Airframe                                                           |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| 531705           | Cockpit Internal Structure Headliner Removed - Detailed Inspection |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                    |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                    |               | MOS                                |             | 122             |     | 144              | 11 Mar 2016 | 31 Mar 2028        | 30 Apr 2028 |              |
|                  |                                                                    |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                    |               |                                    |             |                 |     |                  |             |                    |             |              |
| 531706           | Cockpit Splice and Crossbeam Internal - Detailed Inspection        |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                    |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                    |               | MOS                                |             | 122             |     | 144              | 11 Mar 2016 | 31 Mar 2028        | 30 Apr 2028 |              |
|                  |                                                                    |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                    |               |                                    |             |                 |     |                  |             |                    |             |              |
|                  |                                                                    | 052019        |                                    |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom  | Description                                                                                                            |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------|------------------------------------------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                  | Part Number                                                                                                            | Serial Number |     |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position | HW                                                                                                                     | SW            |     |             |                 |     |                  |             |                    |             | Manufacturer |
|                  | MM Ref                                                                                                                 |               |     |             |                 |     |                  |             |                    |             | Date Type    |
|                  | Ops Number(s)                                                                                                          |               |     |             |                 |     |                  |             |                    |             |              |
| 531707           | Side Window Rails and Posts Internal (Left) - Detailed Inspection                                                      |               | HRS |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                                        |               | AFL |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                                        |               | MOS |             | 122             |     | 144              | 11 Mar 2016 | 31 Mar 2028        | 30 Apr 2028 |              |
|                  | [End Of Month Item] [MOS: +1m/-1m]                                                                                     |               |     |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                                                        | 052019        |     |             |                 |     |                  |             |                    |             |              |
| 531708           | Side Window Rails and Posts Internal (Right) - Detailed Inspection                                                     |               | HRS |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                                        |               | AFL |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                                        |               | MOS |             | 122             |     | 144              | 11 Mar 2016 | 31 Mar 2028        | 30 Apr 2028 |              |
|                  | [End Of Month Item] [MOS: +1m/-1m]                                                                                     |               |     |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                                                        | 052019        |     |             |                 |     |                  |             |                    |             |              |
| 531709           | Windshield Rails and Posts Internal (Left) - Detailed Inspection                                                       |               | HRS |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                                        |               | AFL |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                                        |               | MOS |             | 122             |     | 144              | 11 Mar 2016 | 31 Mar 2028        | 30 Apr 2028 |              |
|                  | [End Of Month Item] [MOS: +1m/-1m]                                                                                     |               |     |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                                                        | 052019        |     |             |                 |     |                  |             |                    |             |              |
| 531710           | Windshield Rails and Posts Internal (Right) - Detailed Inspection                                                      |               | HRS |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                                        |               | AFL |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                                        |               | MOS |             | 122             |     | 144              | 11 Mar 2016 | 31 Mar 2028        | 30 Apr 2028 |              |
|                  | [End Of Month Item] [MOS: +1m/-1m]                                                                                     |               |     |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                                                        | 052019        |     |             |                 |     |                  |             |                    |             |              |
| 531711           | Cockpit Windshields, Side Windows and Cabin Windows Polished Exterior Surrounds - Detailed Inspection                  |               | HRS |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                  |                                                                                                                        |               | AFL |             | 52              |     |                  | 1065        |                    |             | 0            |
|                  |                                                                                                                        |               | MOS |             | 4.7             | -21 | 12               | 19 Dec 2025 | 30 Nov 2026*       | 31 Dec 2026 |              |
|                  | [End Of Month Item] [MOS: +1m/-1m]                                                                                     |               |     |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                                                        | 052010        |     |             |                 |     |                  |             |                    |             |              |
| 531712           | Cockpit Windshields, Side Windows and Cabin Windows Polished Exterior Surrounds Corrosion Inhibiting Coating - Restore |               | HRS |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                  |                                                                                                                        |               | AFL |             | 52              |     |                  | 1065        |                    |             | 0            |
|                  |                                                                                                                        |               | MOS |             | 4.7             | 2   | 12               | 19 Dec 2025 | 31 Dec 2026*       | 31 Jan 2027 |              |
|                  | [End Of Month Item] [MOS: +1m/-1m]                                                                                     |               |     |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                                                        | 052010        |     |             |                 |     |                  |             |                    |             |              |
| 531713           | Cockpit Side Window Surround Lower Corner (Right)- Ndt Inspection                                                      |               | HRS |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                                        |               | AFL |             | 1117            |     | 4080**           | 0           | 4080               |             | 0            |
|                  |                                                                                                                        |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
| Airframe         |                                                                                                                        |               |     |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom  | Description                                                                                                      |                                    | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------|------------------------------------------------------------------------------------------------------------------|------------------------------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                  | Part Number                                                                                                      | Serial Number                      |     |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position | HW                                                                                                               | SW                                 |     |             |                 |     |                  |             |                    |             | Manufacturer |
|                  | MM Ref                                                                                                           |                                    |     |             |                 |     |                  |             |                    |             | Date Type    |
|                  | Ops Number(s)                                                                                                    |                                    |     |             |                 |     |                  |             |                    |             |              |
| 531715           | Cockpit Side Window Surround Upper Corner (Left) - Ndt Inspection                                                |                                    | HRS |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                                  |                                    | AFL |             | 1117            |     | 8085**           | 0           | 8085               |             | 0            |
|                  |                                                                                                                  |                                    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
| Airframe         |                                                                                                                  |                                    |     |             |                 |     |                  |             |                    |             |              |
| 531716           | Cockpit Side Window Surround Upper Corner (Right) - Ndt Inspection                                               |                                    | HRS |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                                  |                                    | AFL |             | 1117            |     | 8085**           | 0           | 8085               |             | 0            |
|                  |                                                                                                                  |                                    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
| Airframe         |                                                                                                                  |                                    |     |             |                 |     |                  |             |                    |             |              |
| 532001           | Fuselage Drain Plug Assembly - Operational Check                                                                 |                                    | HRS |             | 3046.1          |     | 10000            | 0           | 10000              | 10050       | 0            |
|                  |                                                                                                                  |                                    | AFL |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                                  |                                    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
| Airframe         |                                                                                                                  | [HRS: +50/-50]                     |     |             |                 |     |                  |             |                    |             |              |
|                  |                                                                                                                  | 052027                             |     |             |                 |     |                  |             |                    |             |              |
| 532100           | Galley / Lavatory Below Floor (Wet Areas) FS 324.5 - FS 529 - Detailed Inspection                                |                                    | HRS |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                                                                  |                                    | AFL |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                                                                  |                                    | MOS |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031        | 31 Jan 2032 |              |
| Airframe         |                                                                                                                  | [End Of Month Item] [MOS: +1m/-1m] |     |             |                 |     |                  |             |                    |             |              |
|                  |                                                                                                                  | 052016                             |     |             |                 |     |                  |             |                    |             |              |
| 532101           | Interior Upper Forward Midcabin Panel Installation Headliner Removed FS 324.5 - FS 529 - Detailed Inspection     |                                    | HRS |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                                  |                                    | AFL |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                                  |                                    | MOS |             | 122             |     | 144              | 11 Mar 2016 | 31 Mar 2028        | 30 Apr 2028 |              |
| Airframe         |                                                                                                                  | [End Of Month Item] [MOS: +1m/-1m] |     |             |                 |     |                  |             |                    |             |              |
|                  |                                                                                                                  | 052019                             |     |             |                 |     |                  |             |                    |             |              |
| 532102           | Interior Left and Right Forward Midcabin Panel Installations Above Floor FS 324.5 - FS 529 - Detailed Inspection |                                    | HRS |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                                  |                                    | AFL |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                                  |                                    | MOS |             | 122             |     | 144              | 11 Mar 2016 | 31 Mar 2028        | 30 Apr 2028 |              |
| Airframe         |                                                                                                                  | [End Of Month Item] [MOS: +1m/-1m] |     |             |                 |     |                  |             |                    |             |              |
|                  |                                                                                                                  | 052019                             |     |             |                 |     |                  |             |                    |             |              |
| 532103           | Wing Link Fittings Interior to Wing to Body Fairing FS 470 - FS 511.5 - Detailed Inspection                      |                                    | HRS |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                                                                  |                                    | AFL |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                                                                  |                                    | MOS |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031        | 31 Jan 2032 |              |
| Airframe         |                                                                                                                  | [End Of Month Item] [MOS: +1m/-1m] |     |             |                 |     |                  |             |                    |             |              |
|                  |                                                                                                                  | 052016                             |     |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom  | Description                                                                                                                                  |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------|----------------------------------------------------------------------------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                  | Part Number                                                                                                                                  | Serial Number |                                    |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position | HW                                                                                                                                           | SW            |                                    |             |                 |     |                  |             |                    |             | Manufacturer |
|                  | MM Ref                                                                                                                                       |               |                                    |             |                 |     |                  |             |                    |             | Date Type    |
|                  | Ops Number(s)                                                                                                                                |               |                                    |             |                 |     |                  |             |                    |             |              |
| 532104           | Waste Penetration Installation Interior to Wing to Body<br>Fairing FS 470 - Detailed Inspection                                              |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                                                                                              |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                                                                                              |               | MOS                                |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031        | 31 Jan 2032 |              |
|                  |                                                                                                                                              |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                                                                              | 052016        |                                    |             |                 |     |                  |             |                    |             |              |
| 532105           | Forward Midcabin Below Floor (Dry Areas) FS 324.5 - FS<br>529 - Detailed Inspection                                                          |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                                                                                              |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                                                                                              |               | MOS                                |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031        | 31 Jan 2032 |              |
|                  |                                                                                                                                              |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                                                                              | 052016        |                                    |             |                 |     |                  |             |                    |             |              |
| 532201           | FS 511.5 Bulkhead - Ndt Inspection                                                                                                           |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                                                              |               | AFL                                |             | 1117            |     | 15870**          | 0           | 15870              |             | 0            |
|                  |                                                                                                                                              |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                                                                              |               |                                    |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                                                                              |               |                                    |             |                 |     |                  |             |                    |             |              |
| 532300           | Production Circle Splice, FS 805 (Upper Stringers 6L - 6<br>R) - Detailed Inspection                                                         |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                                                              |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                                                              |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                                                                              |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                                                                              |               |                                    |             |                 |     |                  |             |                    |             |              |
| 532301           | Left and Right Stringer 6 and Midbay Skin Splices (Above<br>Floor) FS 324.5 - FS 529 - Detailed Inspection                                   |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                                                              |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                                                              |               | MOS                                |             | 122             |     | 144              | 11 Mar 2016 | 31 Mar 2028        | 30 Apr 2028 |              |
|                  |                                                                                                                                              |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                                                                              | 052019        |                                    |             |                 |     |                  |             |                    |             |              |
| 532302           | Left and Right Stringer 19 and Midbay Skin Splices Below<br>Floor (Dry Areas) FS 324.5 - FS 529 - Detailed Inspection                        |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                                                                                              |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                                                                                              |               | MOS                                |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031        | 31 Jan 2032 |              |
|                  |                                                                                                                                              |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                                                                              | 052016        |                                    |             |                 |     |                  |             |                    |             |              |
| 532303           | Left and Right Stringer 19 and Midbay Skin Splices Below<br>Floor Galley / Lavatories (Wet Areas) FS 324.5 - FS 529 -<br>Detailed Inspection |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                                                                                              |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                                                                                              |               | MOS                                |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031        | 31 Jan 2032 |              |
|                  |                                                                                                                                              |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                                                                              | 052016        |                                    |             |                 |     |                  |             |                    |             |              |



| ATA<br>U=Custom  | Description                                                                                                        |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------|--------------------------------------------------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                  | Part Number                                                                                                        | Serial Number |                                    |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position | HW                                                                                                                 | SW            |                                    |             |                 |     |                  |             |                    |             | Manufacturer |
|                  | MM Ref                                                                                                             |               |                                    |             |                 |     |                  |             |                    |             | Date Type    |
|                  | Ops Number(s)                                                                                                      |               |                                    |             |                 |     |                  |             |                    |             |              |
| 532500           | Floor Beams and Tracks Above Floor (Dry Areas) FS 321<br>- FS 511.5 - Detailed Inspection                          |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                                    |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                                    |               | MOS                                |             | 122             |     | 192              | 11 Mar 2016 | 31 Mar 2032        | 30 Apr 2032 |              |
|                  |                                                                                                                    |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                                                    | 052021        |                                    |             |                 |     |                  |             |                    |             |              |
| 532501           | Floor Beams and Tracks Above Floor (Wet Areas) FS 321<br>- FS 511.5 - Detailed Inspection                          |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                                                                    |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                                                                    |               | MOS                                |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031        | 31 Jan 2032 |              |
|                  |                                                                                                                    |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                                                    | 052016        |                                    |             |                 |     |                  |             |                    |             |              |
| 532502           | Cabin Below Floor Seat Track Beams and Support<br>Structure (Dry Areas) FS 321 - FS 511.5 - Detailed<br>Inspection |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                                    |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                                    |               | MOS                                |             | 122             |     | 144              | 11 Mar 2016 | 31 Mar 2028        | 30 Apr 2028 |              |
|                  |                                                                                                                    |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                                                    | 052019        |                                    |             |                 |     |                  |             |                    |             |              |
| 532503           | Cabin Below Floor Seat Track Beams and Support<br>Structure (Wet Areas) FS 321 - FS 511.5 - Detailed<br>Inspection |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                                                                    |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                                                                    |               | MOS                                |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031        | 31 Jan 2032 |              |
|                  |                                                                                                                    |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                                                    | 052016        |                                    |             |                 |     |                  |             |                    |             |              |
| 532600           | Leer FS 246 - FS 270 - Zonal Inspection                                                                            |               | HRS                                |             | 663.7           |     |                  | 2382.4      |                    |             | 0            |
|                  |                                                                                                                    |               | AFL                                |             | 291             |     |                  | 826         |                    |             | 0            |
|                  |                                                                                                                    |               | MOS                                |             | 25.5            |     | 48               | 26 Mar 2024 | 31 Mar 2028        | 30 Apr 2028 |              |
|                  |                                                                                                                    |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                                                    | 052013        |                                    |             |                 |     |                  |             |                    |             |              |
| 532601           | Leer FS 246 - FS 270 - Enhanced Zonal Inspection                                                                   |               | HRS                                |             | 663.7           |     |                  | 2382.4      |                    |             | 0            |
|                  |                                                                                                                    |               | AFL                                |             | 291             |     |                  | 826         |                    |             | 0            |
|                  |                                                                                                                    |               | MOS                                |             | 25.5            |     | 48               | 26 Mar 2024 | 31 Mar 2028        | 30 Apr 2028 |              |
|                  |                                                                                                                    |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                                                    | 052013        |                                    |             |                 |     |                  |             |                    |             |              |
| 532602           | Reer FS 251.5 - FS 285 - Zonal Inspection                                                                          |               | HRS                                |             | 663.7           |     |                  | 2382.4      |                    |             | 0            |
|                  |                                                                                                                    |               | AFL                                |             | 291             |     |                  | 826         |                    |             | 0            |
|                  |                                                                                                                    |               | MOS                                |             | 25.5            |     | 48               | 26 Mar 2024 | 31 Mar 2028        | 30 Apr 2028 |              |
|                  |                                                                                                                    |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                                                    | 052013        |                                    |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom  | Description                                                                                |               | UOM | Times Since                                       | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------|--------------------------------------------------------------------------------------------|---------------|-----|---------------------------------------------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                  | Part Number                                                                                | Serial Number |     |                                                   |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position | HW                                                                                         | SW            |     |                                                   |                 |     |                  |             |                    |             | Manufacturer |
|                  | MM Ref                                                                                     |               |     |                                                   |                 |     |                  |             |                    |             | Date Type    |
|                  | Ops Number(s)                                                                              |               |     |                                                   |                 |     |                  |             |                    |             |              |
| 532603           | Reer FS 251.5 - FS 285 - Enhanced Zonal Inspection                                         |               | HRS |                                                   | 663.7           |     |                  | 2382.4      |                    |             | 0            |
|                  |                                                                                            |               | AFL |                                                   | 291             |     |                  | 826         |                    |             | 0            |
|                  |                                                                                            |               | MOS |                                                   | 25.5            |     | 48               | 26 Mar 2024 | 31 Mar 2028        | 30 Apr 2028 |              |
|                  | Airframe                                                                                   | 052013        |     | [End Of Month Item] [MOS: +1m/-1m]                |                 |     |                  |             |                    |             |              |
| 532604           | Leer Cleaning and Dust Removal - Enhanced Zonal Inspection                                 |               | HRS |                                                   | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                                            |               | AFL |                                                   | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                                            |               | MOS |                                                   | 28.7            |     | 48               | 21 Dec 2023 | 31 Dec 2027        | 31 Jan 2028 |              |
|                  | Airframe                                                                                   | 052013        |     | [End Of Month Item] [MOS: +1m/-1m]                |                 |     |                  |             |                    |             |              |
| 532605           | Reer Cleaning and Dust Removal - Enhanced Zonal Inspection                                 |               | HRS |                                                   | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                                            |               | AFL |                                                   | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                                            |               | MOS |                                                   | 28.7            |     | 48               | 21 Dec 2023 | 31 Dec 2027        | 31 Jan 2028 |              |
|                  | Airframe                                                                                   | 052013        |     | [End Of Month Item] [MOS: +1m/-1m]                |                 |     |                  |             |                    |             |              |
| 532701           | Forward Cabin Window Rings (Left) - Ndt Inspection                                         |               | HRS |                                                   | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                            |               | AFL |                                                   | 1117            |     | 8955**           | 0           | 8955               |             | 0            |
|                  |                                                                                            |               | MOS |                                                   | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  | Airframe                                                                                   |               |     |                                                   |                 |     |                  |             |                    |             |              |
| 532702           | Forward Cabin Window Rings (Right) - Ndt Inspection                                        |               | HRS |                                                   | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                            |               | AFL |                                                   | 1117            |     | 8955**           | 0           | 8955               |             | 0            |
|                  |                                                                                            |               | MOS |                                                   | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  | Airframe                                                                                   |               |     |                                                   |                 |     |                  |             |                    |             |              |
| 533000           | Main Landing Gear Wheel Well and Torque Box FS 671.411 - FS 739 (Left) - Zonal Inspection  |               | HRS |                                                   | 137             |     | 600              | 2909.1      | 3509.1             | 3559.1      | 0            |
|                  |                                                                                            |               | AFL |                                                   | 52              |     |                  | 1065        |                    |             | 0            |
|                  |                                                                                            |               | MOS |                                                   | 5.3             |     | 24               | 01 Dec 2025 | 31 Dec 2027        | 31 Jan 2028 |              |
|                  | Airframe                                                                                   |               |     | [End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50] |                 |     |                  |             |                    |             |              |
| 533001           | Main Landing Gear Wheel Well and Torque Box FS 671.411 - FS 739 (Right) - Zonal Inspection |               | HRS |                                                   | 137             |     | 600              | 2909.1      | 3509.1             | 3559.1      | 0            |
|                  |                                                                                            |               | AFL |                                                   | 52              |     |                  | 1065        |                    |             | 0            |
|                  |                                                                                            |               | MOS |                                                   | 5.3             |     | 24               | 01 Dec 2025 | 31 Dec 2027        | 31 Jan 2028 |              |
|                  | Airframe                                                                                   |               |     | [End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50] |                 |     |                  |             |                    |             |              |
|                  | 052001,052011                                                                              |               |     |                                                   |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom  | Description                                                |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------|------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                  | Part Number                                                | Serial Number |     |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position | HW                                                         | SW            |     |             |                 |     |                  |             |                    |             | Manufacturer |
|                  | MM Ref                                                     |               |     |             |                 |     |                  |             |                    |             | Date Type    |
|                  | Ops Number(s)                                              |               |     |             |                 |     |                  |             |                    |             |              |
| 533002           | Main Landing Gear Wheel Well and Torque Box FS             |               | HRS |             | 137             |     | 600              | 2909.1      | 3509.1             | 3559.1      | 0            |
|                  | 671.411 - FS 739 (Left) - Enhanced Zonal Inspection        |               | AFL |             | 52              |     |                  | 1065        |                    |             | 0            |
|                  |                                                            |               | MOS |             | 5.3             |     | 24               | 01 Dec 2025 | 31 Dec 2027        | 31 Jan 2028 |              |
|                  | [End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]          |               |     |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                            | 052001,052011 |     |             |                 |     |                  |             |                    |             |              |
| 533003           | Main Landing Gear Wheel Well and Torque Box FS             |               | HRS |             | 137             |     | 600              | 2909.1      | 3509.1             | 3559.1      | 0            |
|                  | 671.411 - FS 739 (Right) - Enhanced Zonal Inspection       |               | AFL |             | 52              |     |                  | 1065        |                    |             | 0            |
|                  |                                                            |               | MOS |             | 5.3             |     | 24               | 01 Dec 2025 | 31 Dec 2027        | 31 Jan 2028 |              |
|                  | [End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]          |               |     |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                            | 052001,052011 |     |             |                 |     |                  |             |                    |             |              |
| 533017           | Vertical Fin Skin Cutouts - Ndt Inspection                 |               | HRS |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                            |               | AFL |             | 1117            |     | 6705**           | 0           | 6705               |             | 0            |
|                  |                                                            |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  | [End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]          |               |     |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                            | 052001,052011 |     |             |                 |     |                  |             |                    |             |              |
| 533100           | Fuselage Skin Exterior - General Visual Inspection         |               | HRS |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                            |               | AFL |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                            |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  | [End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50]          |               |     |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                            | 052001,052011 |     |             |                 |     |                  |             |                    |             |              |
| 533101           | Interior Center Midcabin Side Panel Installation FS 529 -  |               | HRS |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  | FS 747.75 - Detailed Inspection                            |               | AFL |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                            |               | MOS |             | 122             |     | 144              | 11 Mar 2016 | 31 Mar 2028        | 30 Apr 2028 |              |
|                  | [End Of Month Item] [MOS: +1m/-1m]                         |               |     |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                            | 052019        |     |             |                 |     |                  |             |                    |             |              |
| 533102           | Interior Upper Center Midcabin Panel Installation FS 529 - |               | HRS |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  | FS 747.75 - Detailed Inspection                            |               | AFL |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                            |               | MOS |             | 122             |     | 144              | 11 Mar 2016 | 31 Mar 2028        | 30 Apr 2028 |              |
|                  | [End Of Month Item] [MOS: +1m/-1m]                         |               |     |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                            | 052019        |     |             |                 |     |                  |             |                    |             |              |
| 533103           | Center Midcabin Mainframe Installation FS 529 and FS       |               | HRS |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  | 686.5 - Detailed Inspection                                |               | AFL |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                            |               | MOS |             | 122             |     | 144              | 11 Mar 2016 | 31 Mar 2028        | 30 Apr 2028 |              |
|                  | [End Of Month Item] [MOS: +1m/-1m]                         |               |     |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                            | 052019        |     |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom  | Description                                                                            |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------|----------------------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                  | Part Number                                                                            | Serial Number |                                    |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position | HW                                                                                     | SW            |                                    |             |                 |     |                  |             |                    |             | Manufacturer |
|                  | MM Ref                                                                                 |               |                                    |             |                 |     |                  |             |                    |             | Date Type    |
|                  | Ops Number(s)                                                                          |               |                                    |             |                 |     |                  |             |                    |             |              |
| 533104           | Emergency Exit Door Internal Surround Structures - Detailed Inspection                 |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                        |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                        |               | MOS                                |             | 122             |     | 144              | 11 Mar 2016 | 31 Mar 2028        | 30 Apr 2028 |              |
|                  |                                                                                        |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                        | 052019        |                                    |             |                 |     |                  |             |                    |             |              |
| 533107           | Fuselage Skin AT Window 7 Cutout (Left) - Visual Inspection                            |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                        |               | AFL                                |             | 1117            |     | 6620**           | 0           | 6620               |             | 0            |
|                  |                                                                                        |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                        |               |                                    |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                        |               |                                    |             |                 |     |                  |             |                    |             |              |
| 533108           | Fuselage Skin AT Window 7 Cutout (Right) - Visual Inspection                           |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                        |               | AFL                                |             | 1117            |     | 6620**           | 0           | 6620               |             | 0            |
|                  |                                                                                        |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                        |               |                                    |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                        |               |                                    |             |                 |     |                  |             |                    |             |              |
| 533201           | Window Frame Splices (Cabin Windows 1 Thru 4) - Detailed Inspection                    |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                        |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                        |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                        |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                        |               |                                    |             |                 |     |                  |             |                    |             |              |
| 533202           | Mid-Bay Circumference Splice, FS747.75 (Upper Stringers 8L - 8R) - Detailed Inspection |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                        |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                        |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                        |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                        |               |                                    |             |                 |     |                  |             |                    |             |              |
| 533203           | Bulkhead Aft Face Below Floor FS 739 - Detailed Inspection                             |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                        |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                        |               | MOS                                |             | 122             |     | 144              | 11 Mar 2016 | 31 Mar 2028        | 30 Apr 2028 |              |
|                  |                                                                                        |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                        | 052019        |                                    |             |                 |     |                  |             |                    |             |              |
| 533204           | Bulkhead Aft Face Internal to Wtbf FS 739 - Detailed Inspection                        |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                                        |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                                        |               | MOS                                |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031        | 31 Jan 2032 |              |
|                  |                                                                                        |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                        | 052016        |                                    |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom  | Description                                                                     |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------|---------------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                  | Part Number                                                                     | Serial Number |                                    |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position | HW                                                                              | SW            |                                    |             |                 |     |                  |             |                    |             | Manufacturer |
|                  | MM Ref                                                                          |               |                                    |             |                 |     |                  |             |                    |             | Date Type    |
|                  | Ops Number(s)                                                                   |               |                                    |             |                 |     |                  |             |                    |             |              |
| 533205           | Interior Bulkhead Forward and Aft Face Above Floor FS 739 - Detailed Inspection |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                 |               | AFL                                |             | 1117            |     |                  | 0           |                    | 0           |              |
|                  |                                                                                 |               | MOS                                |             | 122             |     | 192              | 11 Mar 2016 | 31 Mar 2032        | 30 Apr 2032 |              |
|                  |                                                                                 |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                 | 052021        |                                    |             |                 |     |                  |             |                    |             |              |
| 533207           | FS 529 Main Frame - Ndt Inspection                                              |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                 |               | AFL                                |             | 1117            |     | 11120**          | 0           | 11120              |             | 0            |
|                  |                                                                                 |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                 |               |                                    |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                 |               |                                    |             |                 |     |                  |             |                    |             |              |
| 533209           | Mid Cabin Frame Splices AT Longerons 9 and 13 - Ndt Inspection                  |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                 |               | AFL                                |             | 1117            |     | 4880**           | 0           | 4880               |             | 0            |
|                  |                                                                                 |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                 |               |                                    |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                 |               |                                    |             |                 |     |                  |             |                    |             |              |
| 533211           | FS 739 Bulkhead AT Longeron 17 Splice - Ndt Inspection                          |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                 |               | AFL                                |             | 1117            |     | 15870**          | 0           | 15870              |             | 0            |
|                  |                                                                                 |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                 |               |                                    |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                 |               |                                    |             |                 |     |                  |             |                    |             |              |
| 533300           | Splice Installations Above Floor FS 529 - FS 747.75 - Detailed Inspection       |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                 |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                 |               | MOS                                |             | 122             |     | 192              | 11 Mar 2016 | 31 Mar 2032        | 30 Apr 2032 |              |
|                  |                                                                                 |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                 | 052021        |                                    |             |                 |     |                  |             |                    |             |              |
| 533301           | Splice Installations Below Floor FS 529 - FS 747.75 - Detailed Inspection       |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                                 |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                                 |               | MOS                                |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031        | 31 Jan 2032 |              |
|                  |                                                                                 |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                 | 052016        |                                    |             |                 |     |                  |             |                    |             |              |
| 533303           | Longeron 9 and 13 Splices AT FS 529 and FS 686.5 - Ndt Inspection               |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                 |               | AFL                                |             | 1117            |     | 9340**           | 0           | 9340               |             | 0            |
|                  |                                                                                 |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                 |               |                                    |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                 |               |                                    |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom                    | Description                                                       |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due     | Avg Man Hrs  |
|------------------------------------|-------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|---------------------|-------------|--------------|
|                                    | Part Number                                                       | Serial Number |     |             |                 |     |                  |             |                     |             | Approx Price |
| Logbook Position                   | HW                                                                | SW            |     |             |                 |     |                  |             |                     |             | Manufacturer |
|                                    | MM Ref                                                            |               |     |             |                 |     |                  |             |                     |             | Date Type    |
|                                    | Ops Number(s)                                                     |               |     |             |                 |     |                  |             |                     |             |              |
| 533305                             | Longeron 17 AT Frame Attachment - Ndt Inspection                  |               | HRS |             | 3046.1          |     |                  | 0           |                     |             | 0            |
|                                    |                                                                   |               | AFL |             | 1117            |     | 14545**          | 0           | 14545               |             | 0            |
|                                    |                                                                   |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |             |              |
| Airframe                           |                                                                   |               |     |             |                 |     |                  |             |                     |             |              |
| 533307                             | Longeron 17 AT FS 581.5 - Ndt Inspection                          |               | HRS |             | 3046.1          |     |                  | 0           |                     |             | 0            |
|                                    |                                                                   |               | AFL |             | 1117            |     | 3715**           | 0           | 3715                |             | 0            |
|                                    |                                                                   |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |             |              |
| Airframe                           |                                                                   |               |     |             |                 |     |                  |             |                     |             |              |
| 533309                             | Longeron 7 and 15 Splices AT FS 529 and FS 686.5 - Ndt Inspection |               | HRS |             | 3046.1          |     |                  | 0           |                     |             | 0            |
|                                    |                                                                   |               | AFL |             | 1117            |     | 9340**           | 0           | 9340                |             | 0            |
|                                    |                                                                   |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |             |              |
| Airframe                           |                                                                   |               |     |             |                 |     |                  |             |                     |             |              |
| 533400                             | Wing to Fuselage Attachment Links - Detailed Inspection           |               | HRS |             | 730.5           |     |                  | 2315.6      |                     |             | 0            |
|                                    |                                                                   |               | AFL |             | 315             |     |                  | 802         |                     |             | 0            |
|                                    |                                                                   |               | MOS |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031         | 31 Jan 2032 |              |
| Airframe                           |                                                                   |               |     |             |                 |     |                  |             |                     |             |              |
| [End Of Month Item] [MOS: +1m/-1m] |                                                                   |               |     |             |                 |     |                  |             |                     |             |              |
| 052016                             |                                                                   |               |     |             |                 |     |                  |             |                     |             |              |
| 533402                             | Main Frame Assy (Lh, FS 686)                                      |               | HRS |             | 3046.1          |     |                  | 0           |                     |             | 0            |
|                                    | 60P5334001A113                                                    | WM0158        | AFL |             | 1117            |     |                  | 0           |                     |             | 0            |
|                                    |                                                                   |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |             |              |
| Airframe                           |                                                                   |               |     |             |                 |     |                  |             |                     |             |              |
| MSC                                |                                                                   |               |     |             |                 |     |                  |             |                     |             |              |
| 533403                             | BI 49 Wing Attach Drag Link - Removal / Installation              |               | HRS |             | 3046.1          |     |                  | 0           |                     |             | 0            |
|                                    | 60P5334001A089                                                    | H18269-11-2-6 | AFL |             | 1117            |     |                  | 0           |                     |             | 0            |
|                                    |                                                                   |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |             |              |
| Airframe                           |                                                                   |               |     |             |                 |     |                  |             |                     |             |              |
| MSC                                |                                                                   |               |     |             |                 |     |                  |             |                     |             |              |
| 533405                             | BI 49 Wing Attach Drag Link - Ndt Inspection                      |               | HRS |             | 3046.1          |     |                  | 0           |                     |             | 0            |
|                                    |                                                                   |               | AFL |             | 1117            |     | 9760**           | 0           | 9760                |             | 0            |
|                                    |                                                                   |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |             |              |
| Airframe                           |                                                                   |               |     |             |                 |     |                  |             |                     |             |              |
| 533407                             | Wing to Fuselage Joints, Sleeves and Pins - Ndt Inspection        |               | HRS |             | 3046.1          |     |                  | 0           |                     |             | 0            |
|                                    |                                                                   |               | AFL |             | 1117            |     | 12445**          | 0           | 12445               |             | 0            |
|                                    |                                                                   |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |             |              |
| Airframe                           |                                                                   |               |     |             |                 |     |                  |             |                     |             |              |

| ATA<br>U=Custom  | Description                                                                                       |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------|---------------------------------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                  | Part Number                                                                                       | Serial Number |                                    |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position | HW                                                                                                | SW            |                                    |             |                 |     |                  |             |                    |             | Manufacturer |
|                  | MM Ref                                                                                            |               |                                    |             |                 |     |                  |             |                    |             | Date Type    |
|                  | Ops Number(s)                                                                                     |               |                                    |             |                 |     |                  |             |                    |             |              |
| 533500           | Pressure Floor Structure Below Floor FS 511.5 - FS 739 - Detailed Inspection                      |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                   |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                   |               | MOS                                |             | 122             |     | 144**            | 11 Mar 2016 | 31 Mar 2028        | 30 Apr 2028 |              |
|                  |                                                                                                   |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                                   |               | 052020                             |             |                 |     |                  |             |                    |             |              |
| 533501           | Pressure Floor Structure Panels Above Floor (Dry Areas) FS 511.5 - FS 739 - Detailed Inspection   |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                   |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                   |               | MOS                                |             | 122             |     | 192**            | 11 Mar 2016 | 31 Mar 2032        | 30 Apr 2032 |              |
|                  |                                                                                                   |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                                   |               | 052022                             |             |                 |     |                  |             |                    |             |              |
| 533502           | Pressure Floor Structure Panels Above Floor (Wet Areas) FS 511.5 - FS 739 - Detailed Inspection   |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                   |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                   |               | MOS                                |             | 122             |     | 192**            | 11 Mar 2016 | 31 Mar 2032        | 30 Apr 2032 |              |
|                  |                                                                                                   |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                                   |               | 052022                             |             |                 |     |                  |             |                    |             |              |
| 533503           | Pressure Floor Structure AT Wheel Wells Below Floor FS 511.5 - FS 669 - Detailed Inspection       |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                   |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                   |               | MOS                                |             | 122             |     | 144              | 11 Mar 2016 | 31 Mar 2028        | 30 Apr 2028 |              |
|                  |                                                                                                   |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                                   |               |                                    |             |                 |     |                  |             |                    |             |              |
| 533504           | Pressure Floor Structure Forward of Wheel Wells Below Floor FS 669 - FS 739 - Detailed Inspection |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                                                   |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                                                   |               | MOS                                |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031        | 31 Jan 2032 |              |
|                  |                                                                                                   |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                                   |               |                                    |             |                 |     |                  |             |                    |             |              |
| 533505           | Seat Track Beams Above Floor (Dry Areas) FS 511.5 - FS 739 - Detailed Inspection                  |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                   |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                   |               | MOS                                |             | 122             |     | 192              | 11 Mar 2016 | 31 Mar 2032        | 30 Apr 2032 |              |
|                  |                                                                                                   |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                                   |               | 052021                             |             |                 |     |                  |             |                    |             |              |
| 533506           | Seat Track Beams Above Floor (Wet Areas) FS 511.5 - FS 739 - Detailed Inspection                  |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                   |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                   |               | MOS                                |             | 122             |     | 192              | 11 Mar 2016 | 31 Mar 2032        | 30 Apr 2032 |              |
|                  |                                                                                                   |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                                   |               | 052021                             |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom                    | Description                                                         |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------------------------|---------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                                    | Part Number                                                         | Serial Number |     |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position                   | HW                                                                  | SW            |     |             |                 |     |                  |             |                    |             | Manufacturer |
|                                    | MM Ref                                                              |               |     |             |                 |     |                  |             |                    |             | Date Type    |
|                                    | Ops Number(s)                                                       |               |     |             |                 |     |                  |             |                    |             |              |
| 533510                             | FS 686.5 Floor Beam Connection - Ndt Inspection                     |               | HRS |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                                    |                                                                     |               | AFL |             | 1117            |     | 9145**           | 0           | 9145               |             | 0            |
|                                    |                                                                     |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
| Airframe                           |                                                                     |               |     |             |                 |     |                  |             |                    |             |              |
| 533511                             | FS 686.5 Floor Beam Lower CAP - Ndt Inspection                      |               | HRS |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                                    |                                                                     |               | AFL |             | 1117            |     | 3610**           | 0           | 3610               |             | 0            |
|                                    |                                                                     |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
| Airframe                           |                                                                     |               |     |             |                 |     |                  |             |                    |             |              |
| 533513                             | Mid Cabin Pressure Floor Structure - Ndt Inspection                 |               | HRS |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                                    |                                                                     |               | AFL |             | 1117            |     | 9410**           | 0           | 9410               |             | 0            |
|                                    |                                                                     |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
| Airframe                           |                                                                     |               |     |             |                 |     |                  |             |                    |             |              |
| 533515                             | FS 529 Floor Beam Connection - Ndt Inspection                       |               | HRS |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                                    |                                                                     |               | AFL |             | 1117            |     | 9145**           | 0           | 9145               |             | 0            |
|                                    |                                                                     |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
| Airframe                           |                                                                     |               |     |             |                 |     |                  |             |                    |             |              |
| 533800                             | Wing to Fuselage Drag Links FS 529 - FS 581.5 - Detailed Inspection |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                                    |                                                                     |               | AFL |             | 315             |     |                  | 802         |                    |             | 0            |
|                                    |                                                                     |               | MOS |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031        | 31 Jan 2032 |              |
| [End Of Month Item] [MOS: +1m/-1m] |                                                                     |               |     |             |                 |     |                  |             |                    |             |              |
| Airframe                           |                                                                     |               |     |             |                 |     |                  |             |                    |             |              |
| 052016                             |                                                                     |               |     |             |                 |     |                  |             |                    |             |              |
| 533900                             | Torque Box Interior - Detailed Inspection                           |               | HRS |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                                    |                                                                     |               | AFL |             | 1117            |     |                  | 0           |                    |             | 0            |
|                                    |                                                                     |               | MOS |             | 122             |     | 144              | 11 Mar 2016 | 31 Mar 2028        | 30 Apr 2028 |              |
| [End Of Month Item] [MOS: +1m/-1m] |                                                                     |               |     |             |                 |     |                  |             |                    |             |              |
| Airframe                           |                                                                     |               |     |             |                 |     |                  |             |                    |             |              |
| 052019                             |                                                                     |               |     |             |                 |     |                  |             |                    |             |              |
| 533901                             | Torque Box Exterior and Links - Detailed Inspection                 |               | HRS |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                                    |                                                                     |               | AFL |             | 1117            |     |                  | 0           |                    |             | 0            |
|                                    |                                                                     |               | MOS |             | 122             |     | 144              | 11 Mar 2016 | 31 Mar 2028        | 30 Apr 2028 |              |
| [End Of Month Item] [MOS: +1m/-1m] |                                                                     |               |     |             |                 |     |                  |             |                    |             |              |
| Airframe                           |                                                                     |               |     |             |                 |     |                  |             |                    |             |              |
| 052019                             |                                                                     |               |     |             |                 |     |                  |             |                    |             |              |
| 533902                             | Torque Box Assembly - Removal / Installation                        |               | HRS |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                                    | 60P5334001N003P09                                                   | A0297522101   | AFL |             | 1117            |     |                  | 0           |                    |             | 0            |
|                                    |                                                                     |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
| Airframe                           |                                                                     |               |     |             |                 |     |                  |             |                    |             |              |
| O/C                                |                                                                     |               |     |             |                 |     |                  |             |                    |             |              |



| ATA<br>U=Custom  | Description                                                                                                               |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------|---------------------------------------------------------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                  | Part Number                                                                                                               | Serial Number |                                    |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position | HW                                                                                                                        | SW            |                                    |             |                 |     |                  |             |                    |             | Manufacturer |
|                  | MM Ref                                                                                                                    |               |                                    |             |                 |     |                  |             |                    |             | Date Type    |
|                  | Ops Number(s)                                                                                                             |               |                                    |             |                 |     |                  |             |                    |             |              |
| 533903           | Torque Box Internal Side (FS 680 - FS 735) - Zonal<br>Inspection                                                          |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                                                                           |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                                                                           |               | MOS                                |             | 28.7            |     | 48               | 21 Dec 2023 | 21 Dec 2027        | 21 Jan 2028 |              |
|                  |                                                                                                                           |               | [MOS: +1m/-1m]                     |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                                                           |               | 052013                             |             |                 |     |                  |             |                    |             |              |
| 533904           | Wiring and Fuel Installations Located Inside Torque Box<br>Upper Portion (FS 680 - FS 735) - Enhanced Zonal<br>Inspection |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                                                                           |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                                                                           |               | MOS                                |             | 28.7            | -82 | 48               | 21 Dec 2023 | 30 Sep 2027*       | 31 Oct 2027 |              |
|                  |                                                                                                                           |               | [MOS: +1m/-1m]                     |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                                                           |               | 052013                             |             |                 |     |                  |             |                    |             |              |
| 533906           | Forward Torque Box Connection to Wing Rear Spar - Ndt<br>Inspection                                                       |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                                           |               | AFL                                |             | 1117            |     | 13550**          | 0           | 13550              |             | 0            |
|                  |                                                                                                                           |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                                                           |               |                                    |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                                                           |               |                                    |             |                 |     |                  |             |                    |             |              |
| 533908           | Aft Torque Box Connection to Longerons 24 - Ndt<br>Inspection                                                             |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                                           |               | AFL                                |             | 1117            |     | 13550**          | 0           | 13550              |             | 0            |
|                  |                                                                                                                           |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                                                           |               |                                    |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                                                           |               |                                    |             |                 |     |                  |             |                    |             |              |
| 534000           | Baggage Compartment Wiring Installation FS 805.5 - FS<br>886 - Enhanced Zonal Inspection                                  |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                                                                           |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                                                                           |               | MOS                                |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031        | 31 Jan 2032 |              |
|                  |                                                                                                                           |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                                                           |               | 052016                             |             |                 |     |                  |             |                    |             |              |
| 534001           | Baggage Compartment Below Floor Hirf/L - Detailed<br>Inspection                                                           |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                                                                           |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                                                                           |               | MOS                                |             | 28.7            |     | 48               | 21 Dec 2023 | 31 Dec 2027        | 31 Jan 2028 |              |
|                  |                                                                                                                           |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                                                           |               | 052013                             |             |                 |     |                  |             |                    |             |              |
| 534002           | Baggage Compartment Above Floor Hirf/L - Detailed<br>Inspection                                                           |               | HRS                                |             | 1300.7          |     |                  | 1745.4      |                    |             | 0            |
|                  |                                                                                                                           |               | AFL                                |             | 507             |     |                  | 610         |                    |             | 0            |
|                  |                                                                                                                           |               | MOS                                |             | 51.7            |     | 72               | 19 Jan 2022 | 31 Jan 2028        | 29 Feb 2028 |              |
|                  |                                                                                                                           |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                                                           |               | 052015                             |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom  | Description                                                                                 |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------|---------------------------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                  | Part Number                                                                                 | Serial Number |                                    |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position | HW                                                                                          | SW            |                                    |             |                 |     |                  |             |                    |             | Manufacturer |
|                  | MM Ref                                                                                      |               |                                    |             |                 |     |                  |             |                    |             | Date Type    |
|                  | Ops Number(s)                                                                               |               |                                    |             |                 |     |                  |             |                    |             |              |
| 534003           | Baggage Compartment Above Floor Hirf/L - General<br>Visual Inspection                       |               | HRS                                |             | 1300.7          |     |                  | 1745.4      |                    |             | 0            |
|                  |                                                                                             |               | AFL                                |             | 507             |     |                  | 610         |                    |             | 0            |
|                  |                                                                                             |               | MOS                                |             | 51.7            |     | 72               | 19 Jan 2022 | 31 Jan 2028        | 29 Feb 2028 |              |
|                  |                                                                                             |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                             | 052015        |                                    |             |                 |     |                  |             |                    |             |              |
| 534004           | Baggage Compartment Forward Electronic Equipment<br>Rack Hirf/L - Detailed Inspection       |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                                             |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                                             |               | MOS                                |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031        | 31 Jan 2032 |              |
|                  |                                                                                             |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                             | 052016        |                                    |             |                 |     |                  |             |                    |             |              |
| 534100           | Interior Upper Aft Mid Panel Installation FS 739 - FS 886 -<br>Detailed Inspection          |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                             |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                             |               | MOS                                |             | 122             |     | 144              | 11 Mar 2016 | 31 Mar 2028        | 30 Apr 2028 |              |
|                  |                                                                                             |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                             | 052019        |                                    |             |                 |     |                  |             |                    |             |              |
| 534101           | Interior Aft Mid Side Panel Installations FS 739 - FS 886 -<br>Detailed Inspection          |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                             |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                             |               | MOS                                |             | 122             |     | 144              | 11 Mar 2016 | 31 Mar 2028        | 30 Apr 2028 |              |
|                  |                                                                                             |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                             | 052019        |                                    |             |                 |     |                  |             |                    |             |              |
| 534102           | Aft Mid Internal Structure Below Floor (Wet Areas) FS 739<br>- FS 886 - Detailed Inspection |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                                             |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                                             |               | MOS                                |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031        | 31 Jan 2032 |              |
|                  |                                                                                             |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                             | 052016        |                                    |             |                 |     |                  |             |                    |             |              |
| 534103           | Aft Mid Internal Structure Below Floor (Dry Areas) FS 739<br>- FS 886 - Detailed Inspection |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                                             |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                                             |               | MOS                                |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031        | 31 Jan 2032 |              |
|                  |                                                                                             |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                             | 052016        |                                    |             |                 |     |                  |             |                    |             |              |
| 534104           | Aft Mid Splice Installations Above Floor FS 739 - FS 886 -<br>Detailed Inspection           |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                             |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                             |               | MOS                                |             | 122             |     | 144              | 11 Mar 2016 | 31 Mar 2028        | 30 Apr 2028 |              |
|                  |                                                                                             |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                             | 052019        |                                    |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom  | Description                                                                                |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------|--------------------------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                  | Part Number                                                                                | Serial Number |                                    |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position | HW                                                                                         | SW            |                                    |             |                 |     |                  |             |                    |             | Manufacturer |
|                  | MM Ref                                                                                     |               |                                    |             |                 |     |                  |             |                    |             | Date Type    |
|                  | Ops Number(s)                                                                              |               |                                    |             |                 |     |                  |             |                    |             |              |
| 534105           | Aft Mid Splice Installations FS 886 - FS 951.31 - Detailed Inspection                      |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                                            |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                                            |               | MOS                                |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031        | 31 Jan 2032 |              |
|                  |                                                                                            |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                            | 052016        |                                    |             |                 |     |                  |             |                    |             |              |
| 534106           | Aft Mid Splice Installations Below Floor (Dry Areas) FS 739 - FS 886 - Detailed Inspection |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                                            |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                                            |               | MOS                                |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031        | 31 Jan 2032 |              |
|                  |                                                                                            |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                            | 052016        |                                    |             |                 |     |                  |             |                    |             |              |
| 534107           | Aft Mid Splice Installations Below Floor (Wet Areas) FS 739 - FS 886 - Detailed Inspection |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                                            |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                                            |               | MOS                                |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031        | 31 Jan 2032 |              |
|                  |                                                                                            |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                            | 052016        |                                    |             |                 |     |                  |             |                    |             |              |
| 534110           | Baggage Door Surround Structure (Cutout Corners) - Visual Inspection                       |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                            |               | AFL                                |             | 1117            |     | 11945**          | 0           | 11945              |             | 0            |
|                  |                                                                                            |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                            |               |                                    |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                            |               |                                    |             |                 |     |                  |             |                    |             |              |
| 534112           | FS 805.5 Circumferential Skin Splice (Above Stringer 8) - Ndt Inspection                   |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                            |               | AFL                                |             | 1117            |     | 5380**           | 0           | 5380               |             | 0            |
|                  |                                                                                            |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                            |               |                                    |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                            |               |                                    |             |                 |     |                  |             |                    |             |              |
| 534115           | Pylon AREA Skin Cutouts (Left) - Visual Inspection                                         |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                            |               | AFL                                |             | 1117            |     | 11945**          | 0           | 11945              |             | 0            |
|                  |                                                                                            |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                            |               |                                    |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                            |               |                                    |             |                 |     |                  |             |                    |             |              |
| 534116           | Pylon AREA Skin Cutouts (Right) - Visual Inspection                                        |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                            |               | AFL                                |             | 1117            |     | 11945**          | 0           | 11945              |             | 0            |
|                  |                                                                                            |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                            |               |                                    |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                            |               |                                    |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom                    | Description                                                                       |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------------------------|-----------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                                    | Part Number                                                                       | Serial Number |     |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position                   | HW                                                                                | SW            |     |             |                 |     |                  |             |                    |             | Manufacturer |
|                                    | MM Ref                                                                            |               |     |             |                 |     |                  |             |                    |             | Date Type    |
|                                    | Ops Number(s)                                                                     |               |     |             |                 |     |                  |             |                    |             |              |
| 534119                             | Lower Access Cutouts - Visual Inspection                                          |               | HRS |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                                    |                                                                                   |               | AFL |             | 1117            |     | 11945**          | 0           | 11945              |             | 0            |
|                                    |                                                                                   |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
| Airframe                           |                                                                                   |               |     |             |                 |     |                  |             |                    |             |              |
| 534121                             | APU Access Door Surround Structure, Cutout Corners - Visual Inspection            |               | HRS |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                                    |                                                                                   |               | AFL |             | 1117            |     | 11945**          | 0           | 11945              |             | 0            |
|                                    |                                                                                   |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
| Airframe                           |                                                                                   |               |     |             |                 |     |                  |             |                    |             |              |
| 534200                             | Aft Engine Mount Frame Installation Above Floor FS 951.31 - Detailed Inspection   |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                                    |                                                                                   |               | AFL |             | 315             |     |                  | 802         |                    |             | 0            |
|                                    |                                                                                   |               | MOS |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031        | 31 Jan 2032 |              |
| [End Of Month Item] [MOS: +1m/-1m] |                                                                                   |               |     |             |                 |     |                  |             |                    |             |              |
| Airframe                           |                                                                                   |               |     |             |                 |     |                  |             |                    |             |              |
| 052016                             |                                                                                   |               |     |             |                 |     |                  |             |                    |             |              |
| 534201                             | Aft Engine Mount Frame Installation Below Floor FS 951.31 - Detailed Inspection   |               | HRS |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                                    |                                                                                   |               | AFL |             | 1117            |     |                  | 0           |                    |             | 0            |
|                                    |                                                                                   |               | MOS |             | 122             |     | 144              | 11 Mar 2016 | 31 Mar 2028        | 30 Apr 2028 |              |
| [End Of Month Item] [MOS: +1m/-1m] |                                                                                   |               |     |             |                 |     |                  |             |                    |             |              |
| Airframe                           |                                                                                   |               |     |             |                 |     |                  |             |                    |             |              |
| 052019                             |                                                                                   |               |     |             |                 |     |                  |             |                    |             |              |
| 534202                             | Aft Mid Frame Installations Above Floor FS 823 and FS 868.5 - Detailed Inspection |               | HRS |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                                    |                                                                                   |               | AFL |             | 1117            |     |                  | 0           |                    |             | 0            |
|                                    |                                                                                   |               | MOS |             | 122             |     | 144              | 11 Mar 2016 | 31 Mar 2028        | 30 Apr 2028 |              |
| [End Of Month Item] [MOS: +1m/-1m] |                                                                                   |               |     |             |                 |     |                  |             |                    |             |              |
| Airframe                           |                                                                                   |               |     |             |                 |     |                  |             |                    |             |              |
| 052019                             |                                                                                   |               |     |             |                 |     |                  |             |                    |             |              |
| 534203                             | Baggage Door Support Internal Structure - Detailed Inspection                     |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                                    |                                                                                   |               | AFL |             | 315             |     |                  | 802         |                    |             | 0            |
|                                    |                                                                                   |               | MOS |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031        | 31 Jan 2032 |              |
| [End Of Month Item] [MOS: +1m/-1m] |                                                                                   |               |     |             |                 |     |                  |             |                    |             |              |
| Airframe                           |                                                                                   |               |     |             |                 |     |                  |             |                    |             |              |
| 052016                             |                                                                                   |               |     |             |                 |     |                  |             |                    |             |              |
| 534204                             | Secondary Pressure Bulkhead Door FS 805.5 - Detailed Inspection                   |               | HRS |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                                    |                                                                                   |               | AFL |             | 1117            |     |                  | 0           |                    |             | 0            |
|                                    |                                                                                   |               | MOS |             | 122             |     | 144              | 11 Mar 2016 | 31 Mar 2028        | 30 Apr 2028 |              |
| [End Of Month Item] [MOS: +1m/-1m] |                                                                                   |               |     |             |                 |     |                  |             |                    |             |              |
| Airframe                           |                                                                                   |               |     |             |                 |     |                  |             |                    |             |              |
| 052019                             |                                                                                   |               |     |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom  | Description                                                                      |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due     | Avg Man Hrs  |
|------------------|----------------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|---------------------|-------------|--------------|
|                  | Part Number                                                                      | Serial Number |                                    |             |                 |     |                  |             |                     |             | Approx Price |
| Logbook Position | HW                                                                               | SW            |                                    |             |                 |     |                  |             |                     |             | Manufacturer |
|                  | MM Ref                                                                           |               |                                    |             |                 |     |                  |             |                     |             | Date Type    |
|                  | Ops Number(s)                                                                    |               |                                    |             |                 |     |                  |             |                     |             |              |
| 534205           | Secondary Pressure Bulkhead Above Floor FS 805.5 - Detailed Inspection           |               | HRS                                |             | 3046.1          |     |                  | 0           |                     |             | 0            |
|                  |                                                                                  |               | AFL                                |             | 1117            |     |                  | 0           |                     |             | 0            |
|                  |                                                                                  |               | MOS                                |             | 122             |     | 144              | 11 Mar 2016 | 31 Mar 2028         | 30 Apr 2028 |              |
|                  |                                                                                  |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                     |             |              |
| Airframe         |                                                                                  | 052019        |                                    |             |                 |     |                  |             |                     |             |              |
| 534206           | Secondary Pressure Bulkhead Below Floor FS 805.5 - Detailed Inspection           |               | HRS                                |             | 3046.1          |     |                  | 0           |                     |             | 0            |
|                  |                                                                                  |               | AFL                                |             | 1117            |     |                  | 0           |                     |             | 0            |
|                  |                                                                                  |               | MOS                                |             | 122             |     | 144              | 11 Mar 2016 | 31 Mar 2028         | 30 Apr 2028 |              |
|                  |                                                                                  |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                     |             |              |
| Airframe         |                                                                                  | 052019        |                                    |             |                 |     |                  |             |                     |             |              |
| 534207           | Primary Pressure Bulkhead - Detailed Inspection                                  |               | HRS                                |             | 3046.1          |     |                  | 0           |                     |             | 0            |
|                  |                                                                                  |               | AFL                                |             | 1117            |     |                  | 0           |                     |             | 0            |
|                  |                                                                                  |               | MOS                                |             | 122             |     | 144              | 11 Mar 2016 | 31 Mar 2028         | 30 Apr 2028 |              |
|                  |                                                                                  |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                     |             |              |
| Airframe         |                                                                                  | 052019        |                                    |             |                 |     |                  |             |                     |             |              |
| 534208           | Baggage Door Support External Structure - General Visual Inspection              |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                     |             | 0            |
|                  |                                                                                  |               | AFL                                |             | 315             |     |                  | 802         |                     |             | 0            |
|                  |                                                                                  |               | MOS                                |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031         | 31 Jan 2032 |              |
|                  |                                                                                  |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                     |             |              |
| Airframe         |                                                                                  | 052016        |                                    |             |                 |     |                  |             |                     |             |              |
| 534210           | Frames AT Floor Beam Connections, Left Side, FS 838 and FS 853 - Ndt Inspection  |               | HRS                                |             | 3046.1          |     |                  | 0           |                     |             | 0            |
|                  |                                                                                  |               | AFL                                |             | 1117            |     | 3745**           | 0           | 3745                |             | 0            |
|                  |                                                                                  |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                     |             |              |
|                  |                                                                                  |               |                                    |             |                 |     |                  |             |                     |             |              |
| Airframe         |                                                                                  |               |                                    |             |                 |     |                  |             |                     |             |              |
| 534211           | Frames AT Floor Beam Connections, Right Side, FS 838 and FS 853 - Ndt Inspection |               | HRS                                |             | 3046.1          |     |                  | 0           |                     |             | 0            |
|                  |                                                                                  |               | AFL                                |             | 1117            |     | 13710**          | 0           | 13710               |             | 0            |
|                  |                                                                                  |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                     |             |              |
|                  |                                                                                  |               |                                    |             |                 |     |                  |             |                     |             |              |
| Airframe         |                                                                                  |               |                                    |             |                 |     |                  |             |                     |             |              |
| 534213           | Composite Pressure Bulkhead FS 886 - Visual Inspection                           |               | HRS                                |             | 3046.1          |     |                  | 0           |                     |             | 0            |
|                  |                                                                                  |               | AFL                                |             | 1117            |     | 4000**           | 0           | 4000                |             | 0            |
|                  |                                                                                  |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                     |             |              |
|                  |                                                                                  |               |                                    |             |                 |     |                  |             |                     |             |              |
| Airframe         |                                                                                  |               |                                    |             |                 |     |                  |             |                     |             |              |

| ATA<br>U=Custom                    | Description                                                                                                 |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------------------------|-------------------------------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                                    | Part Number                                                                                                 | Serial Number |     |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position                   | HW                                                                                                          | SW            |     |             |                 |     |                  |             |                    |             | Manufacturer |
|                                    | MM Ref                                                                                                      |               |     |             |                 |     |                  |             |                    |             | Date Type    |
|                                    | Ops Number(s)                                                                                               |               |     |             |                 |     |                  |             |                    |             |              |
| 534214                             | Composite Pressure Bulkhead Attach FS 886 - Ndt Inspection                                                  |               | HRS |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                                    |                                                                                                             |               | AFL |             | 1117            |     | 11880**          | 0           | 11880              |             | 0            |
|                                    |                                                                                                             |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
| Airframe                           |                                                                                                             |               |     |             |                 |     |                  |             |                    |             |              |
| 052019                             |                                                                                                             |               |     |             |                 |     |                  |             |                    |             |              |
| 534500                             | Aft Mid Auxiliary Pressure Floor Structures Above Floor (Dry Areas) FS 739 - FS 805.5 - Detailed Inspection |               | HRS |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                                    |                                                                                                             |               | AFL |             | 1117            |     |                  | 0           |                    |             | 0            |
|                                    |                                                                                                             |               | MOS |             | 122             |     | 144              | 11 Mar 2016 | 31 Mar 2028        | 30 Apr 2028 |              |
| [End Of Month Item] [MOS: +1m/-1m] |                                                                                                             |               |     |             |                 |     |                  |             |                    |             |              |
| Airframe                           |                                                                                                             |               |     |             |                 |     |                  |             |                    |             |              |
| 052019                             |                                                                                                             |               |     |             |                 |     |                  |             |                    |             |              |
| 534501                             | Aft Mid Auxiliary Pressure Floor Structures Above Floor (Wet Areas) FS 739 - FS 805.5 - Detailed Inspection |               | HRS |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                                    |                                                                                                             |               | AFL |             | 1117            |     |                  | 0           |                    |             | 0            |
|                                    |                                                                                                             |               | MOS |             | 122             |     | 144              | 11 Mar 2016 | 31 Mar 2028        | 30 Apr 2028 |              |
| [End Of Month Item] [MOS: +1m/-1m] |                                                                                                             |               |     |             |                 |     |                  |             |                    |             |              |
| Airframe                           |                                                                                                             |               |     |             |                 |     |                  |             |                    |             |              |
| 052019                             |                                                                                                             |               |     |             |                 |     |                  |             |                    |             |              |
| 534502                             | Aft Mid Auxiliary Pressure Floor Structures Below Floor (Dry Areas) FS 739 - FS 805.5 - Detailed Inspection |               | HRS |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                                    |                                                                                                             |               | AFL |             | 1117            |     |                  | 0           |                    |             | 0            |
|                                    |                                                                                                             |               | MOS |             | 122             |     | 144              | 11 Mar 2016 | 31 Mar 2028        | 30 Apr 2028 |              |
| [End Of Month Item] [MOS: +1m/-1m] |                                                                                                             |               |     |             |                 |     |                  |             |                    |             |              |
| Airframe                           |                                                                                                             |               |     |             |                 |     |                  |             |                    |             |              |
| 052019                             |                                                                                                             |               |     |             |                 |     |                  |             |                    |             |              |
| 534503                             | Aft Mid Auxiliary Pressure Floor Structures Below Floor (Wet Areas) FS 739 - FS 805.5 - Detailed Inspection |               | HRS |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                                    |                                                                                                             |               | AFL |             | 1117            |     |                  | 0           |                    |             | 0            |
|                                    |                                                                                                             |               | MOS |             | 122             |     | 144              | 11 Mar 2016 | 31 Mar 2028        | 30 Apr 2028 |              |
| [End Of Month Item] [MOS: +1m/-1m] |                                                                                                             |               |     |             |                 |     |                  |             |                    |             |              |
| Airframe                           |                                                                                                             |               |     |             |                 |     |                  |             |                    |             |              |
| 052019                             |                                                                                                             |               |     |             |                 |     |                  |             |                    |             |              |
| 534504                             | Baggage Floor Structures Below Floor FS 805.5 - FS 886 - Detailed Inspection                                |               | HRS |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                                    |                                                                                                             |               | AFL |             | 1117            |     |                  | 0           |                    |             | 0            |
|                                    |                                                                                                             |               | MOS |             | 122             |     | 192              | 11 Mar 2016 | 31 Mar 2032        | 30 Apr 2032 |              |
| [End Of Month Item] [MOS: +1m/-1m] |                                                                                                             |               |     |             |                 |     |                  |             |                    |             |              |
| Airframe                           |                                                                                                             |               |     |             |                 |     |                  |             |                    |             |              |
| 052021                             |                                                                                                             |               |     |             |                 |     |                  |             |                    |             |              |
| 534600                             | APU Enclosure FS 886 - FS 951.3 - General Visual Inspection                                                 |               | HRS |             | 663.7           |     |                  | 2382.4      |                    |             | 0            |
|                                    |                                                                                                             |               | AFL |             | 291             |     |                  | 826         |                    |             | 0            |
|                                    |                                                                                                             |               | MOS |             | 25.5            |     | 48               | 26 Mar 2024 | 31 Mar 2028        | 30 Apr 2028 |              |
| [End Of Month Item] [MOS: +1m/-1m] |                                                                                                             |               |     |             |                 |     |                  |             |                    |             |              |
| Airframe                           |                                                                                                             |               |     |             |                 |     |                  |             |                    |             |              |
| 052013                             |                                                                                                             |               |     |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom  | Description                                                                                                 |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------|-------------------------------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                  | Part Number                                                                                                 | Serial Number |     |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position | HW                                                                                                          | SW            |     |             |                 |     |                  |             |                    |             | Manufacturer |
|                  | MM Ref                                                                                                      |               |     |             |                 |     |                  |             |                    |             | Date Type    |
|                  | Ops Number(s)                                                                                               |               |     |             |                 |     |                  |             |                    |             |              |
| 534700           | Engine Mount Installation FS 886 - FS 951.31 - Detailed Inspection                                          |               | HRS |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                             |               | AFL |             | 1117            |     |                  | 0           |                    | 0           |              |
|                  |                                                                                                             |               | MOS |             | 122             |     | 144              | 11 Mar 2016 | 31 Mar 2028        | 30 Apr 2028 |              |
|                  | [End Of Month Item] [MOS: +1m/-1m]                                                                          |               |     |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                                             | 052019        |     |             |                 |     |                  |             |                    |             |              |
| 534701           | FS 886 Upper Engine Mount Fittings (Left) - Ndt Inspection                                                  |               | HRS |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                             |               | AFL |             | 1117            |     | 5780**           | 0           | 5780               |             | 0            |
|                  |                                                                                                             |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  | Airframe                                                                                                    |               |     |             |                 |     |                  |             |                    |             |              |
| 534702           | FS 886 Upper Engine Mount Fittings (Right) - Ndt Inspection                                                 |               | HRS |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                             |               | AFL |             | 1117            |     | 5780**           | 0           | 5780               |             | 0            |
|                  |                                                                                                             |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  | Airframe                                                                                                    |               |     |             |                 |     |                  |             |                    |             |              |
| 534703           | FS 886 Upper Fuselage Link (Left) - Ndt Inspection                                                          |               | HRS |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                             |               | AFL |             | 1117            |     | 10000**          | 0           | 10000              |             | 0            |
|                  |                                                                                                             |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  | Airframe                                                                                                    |               |     |             |                 |     |                  |             |                    |             |              |
| 534704           | FS 886 Upper Fuselage Link (Right) - Ndt Inspection                                                         |               | HRS |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                             |               | AFL |             | 1117            |     | 10000**          | 0           | 10000              |             | 0            |
|                  |                                                                                                             |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  | Airframe                                                                                                    |               |     |             |                 |     |                  |             |                    |             |              |
| 534800           | Baggage Compartment Forward Electronic Equipment Rack Internal - Zonal Inspection                           |               | HRS |             | 663.7           |     |                  | 2382.4      |                    |             | 0            |
|                  |                                                                                                             |               | AFL |             | 291             |     |                  | 826         |                    |             | 0            |
|                  |                                                                                                             |               | MOS |             | 25.5            |     | 72               | 28 Mar 2024 | 31 Mar 2030        | 30 Apr 2030 |              |
|                  | [End Of Month Item] [MOS: +1m/-1m]                                                                          |               |     |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                                             | 052015        |     |             |                 |     |                  |             |                    |             |              |
| 534801           | Baggage Compartment Forward Electronic Equipment Rack Cleaning and Dust Removal - Enhanced Zonal Inspection |               | HRS |             | 1300.7          |     |                  | 1745.4      |                    |             | 0            |
|                  |                                                                                                             |               | AFL |             | 507             |     |                  | 610         |                    |             | 0            |
|                  |                                                                                                             |               | MOS |             | 51.1            | 32  | 72               | 08 Feb 2022 | 31 Mar 2028*       | 30 Apr 2028 |              |
|                  | [End Of Month Item] [MOS: +1m/-1m]                                                                          |               |     |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                                             | 052015        |     |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom  | Description                                                                                                |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(* =Adj) | Max Due     | Avg Man Hrs  |
|------------------|------------------------------------------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|----------------------|-------------|--------------|
|                  | Part Number                                                                                                | Serial Number |                                    |             |                 |     |                  |             |                      |             | Approx Price |
| Logbook Position | HW                                                                                                         | SW            |                                    |             |                 |     |                  |             |                      |             | Manufacturer |
|                  | MM Ref                                                                                                     |               |                                    |             |                 |     |                  |             |                      |             | Date Type    |
|                  | Ops Number(s)                                                                                              |               |                                    |             |                 |     |                  |             |                      |             |              |
| 534802           | Baggage Compartment Aft Electronic Equipment Rack<br>Internal - Zonal Inspection                           |               | HRS                                |             | 663.7           |     |                  | 2382.4      |                      |             | 0            |
|                  |                                                                                                            |               | AFL                                |             | 291             |     |                  | 826         |                      |             | 0            |
|                  |                                                                                                            |               | MOS                                |             | 25.5            |     | 72               | 28 Mar 2024 | 31 Mar 2030          | 30 Apr 2030 |              |
|                  |                                                                                                            |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                      |             |              |
| Airframe         |                                                                                                            |               | 052015                             |             |                 |     |                  |             |                      |             |              |
| 534803           | Baggage Compartment Aft Electronic Equipment Rack<br>Cleaning and Dust Removal - Enhanced Zonal Inspection |               | HRS                                |             | 1300.7          |     |                  | 1745.4      |                      |             | 0            |
|                  |                                                                                                            |               | AFL                                |             | 507             |     |                  | 610         |                      |             | 0            |
|                  |                                                                                                            |               | MOS                                |             | 51.7            |     | 72               | 19 Jan 2022 | 31 Jan 2028          | 29 Feb 2028 |              |
|                  |                                                                                                            |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                      |             |              |
| Airframe         |                                                                                                            |               | 052015                             |             |                 |     |                  |             |                      |             |              |
| 534804           | Water Supply Cabinet Internal - Zonal Inspection                                                           |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                      |             | 0            |
|                  |                                                                                                            |               | AFL                                |             | 315             |     |                  | 802         |                      |             | 0            |
|                  |                                                                                                            |               | MOS                                |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031          | 31 Jan 2032 |              |
|                  |                                                                                                            |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                      |             |              |
| Airframe         |                                                                                                            |               | 052016                             |             |                 |     |                  |             |                      |             |              |
| 535000           | APU and Aft Fuselage Below Floor - Zonal Inspection                                                        |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                      |             | 0            |
|                  |                                                                                                            |               | AFL                                |             | 315             |     |                  | 802         |                      |             | 0            |
|                  |                                                                                                            |               | MOS                                |             | 28.7            |     | 48               | 21 Dec 2023 | 31 Dec 2027          | 31 Jan 2028 |              |
|                  |                                                                                                            |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                      |             |              |
| Airframe         |                                                                                                            |               | 052013                             |             |                 |     |                  |             |                      |             |              |
| 535001           | APU Interior and Exterior Enclosure - Zonal Inspection                                                     |               | HRS                                |             | 137             |     |                  | 2909.1      |                      |             | 0            |
|                  |                                                                                                            |               | AFL                                |             | 52              |     |                  | 1065        |                      |             | 0            |
|                  |                                                                                                            |               | MOS                                |             | 5.4             |     | 24               | 29 Nov 2025 | 30 Nov 2027          | 31 Dec 2027 |              |
|                  |                                                                                                            |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                      |             |              |
| Airframe         |                                                                                                            |               | 052011                             |             |                 |     |                  |             |                      |             |              |
| 535002           | Aft Fuselage Below Floor FS 951.31 - FS 1071.75 - Zonal<br>Inspection                                      |               | HRS                                |             | 3046.1          |     |                  | 0           |                      |             | 0            |
|                  |                                                                                                            |               | AFL                                |             | 1117            |     |                  | 0           |                      |             | 0            |
|                  |                                                                                                            |               | MOS                                |             | 122             |     | 144              | 11 Mar 2016 | 31 Mar 2028          | 30 Apr 2028 |              |
|                  |                                                                                                            |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                      |             |              |
| Airframe         |                                                                                                            |               | 052019                             |             |                 |     |                  |             |                      |             |              |
| 535003           | Aft Fuselage Above Floor FS 886 - FS 1083.46 - Zonal<br>Inspection                                         |               | HRS                                |             | 137             |     |                  | 2909.1      |                      |             | 0            |
|                  |                                                                                                            |               | AFL                                |             | 52              |     |                  | 1065        |                      |             | 0            |
|                  |                                                                                                            |               | MOS                                |             | 5.2             |     | 24               | 05 Dec 2025 | 31 Dec 2027          | 31 Jan 2028 |              |
|                  |                                                                                                            |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                      |             |              |
| Airframe         |                                                                                                            |               | 052011                             |             |                 |     |                  |             |                      |             |              |



| ATA<br>U=Custom  | Description                                                                                       |               | UOM | Times Since                        | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------|---------------------------------------------------------------------------------------------------|---------------|-----|------------------------------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                  | Part Number                                                                                       | Serial Number |     |                                    |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position | HW                                                                                                | SW            |     |                                    |                 |     |                  |             |                    |             | Manufacturer |
|                  | MM Ref                                                                                            |               |     |                                    |                 |     |                  |             |                    |             | Date Type    |
|                  | Ops Number(s)                                                                                     |               |     |                                    |                 |     |                  |             |                    |             |              |
| 535004           | Aft Fuselage Internal Tail Cone - Zonal Inspection                                                |               | HRS |                                    | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                   |               | AFL |                                    | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                   |               | MOS |                                    | 122             |     | 192              | 11 Mar 2016 | 31 Mar 2032        | 30 Apr 2032 |              |
|                  | Airframe                                                                                          | 052021        |     | [End Of Month Item] [MOS: +1m/-1m] |                 |     |                  |             |                    |             |              |
| 535100           | Aft Fuselage Above Floor FS 951.31 - FS 1103.25 -<br>General Visual Inspection                    |               | HRS |                                    | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                   |               | AFL |                                    | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                   |               | MOS |                                    | 122             |     | 144              | 11 Mar 2016 | 31 Mar 2028        | 30 Apr 2028 |              |
|                  | Airframe                                                                                          | 052019        |     | [End Of Month Item] [MOS: +1m/-1m] |                 |     |                  |             |                    |             |              |
| 535101           | Aft Fuselage Interior Below Floor FS 951.31 - FS 1103.25<br>- General Visual Inspection           |               | HRS |                                    | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                   |               | AFL |                                    | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                   |               | MOS |                                    | 122             |     | 144              | 11 Mar 2016 | 31 Mar 2028        | 30 Apr 2028 |              |
|                  | Airframe                                                                                          | 052019        |     | [End Of Month Item] [MOS: +1m/-1m] |                 |     |                  |             |                    |             |              |
| 535102           | Tail Compartment Stringers 6 and 20 Splices FS 951.31 -<br>FS 1103.25 - General Visual Inspection |               | HRS |                                    | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                                                   |               | AFL |                                    | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                                                   |               | MOS |                                    | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031        | 31 Jan 2032 |              |
|                  | Airframe                                                                                          | 052016        |     | [End Of Month Item] [MOS: +1m/-1m] |                 |     |                  |             |                    |             |              |
| 535103           | Aft Fuselage Interior Above Floor FS 951.31 - FS 1103.25<br>- General Visual Inspection           |               | HRS |                                    | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                   |               | AFL |                                    | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                   |               | MOS |                                    | 122             |     | 144              | 11 Mar 2016 | 31 Mar 2028        | 30 Apr 2028 |              |
|                  | Airframe                                                                                          | 052019        |     | [End Of Month Item] [MOS: +1m/-1m] |                 |     |                  |             |                    |             |              |
| 535201           | FS 1003 Frame AT Fin Attachment - Ndt Inspection                                                  |               | HRS |                                    | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                   |               | AFL |                                    | 1117            |     | 4920**           | 0           | 4920               |             | 0            |
|                  |                                                                                                   |               | MOS |                                    | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
| Airframe         |                                                                                                   |               |     |                                    |                 |     |                  |             |                    |             |              |
| 535203           | FS 1083 Bulkhead AT Fin Attachment - Ndt Inspection                                               |               | HRS |                                    | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                   |               | AFL |                                    | 1117            |     | 9985**           | 0           | 9985               |             | 0            |
|                  |                                                                                                   |               | MOS |                                    | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
| Airframe         |                                                                                                   |               |     |                                    |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom  | Description                                                                 |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------|-----------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                  | Part Number                                                                 | Serial Number |                                    |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position | HW                                                                          | SW            |                                    |             |                 |     |                  |             |                    |             | Manufacturer |
|                  | MM Ref                                                                      |               |                                    |             |                 |     |                  |             |                    |             | Date Type    |
|                  | Ops Number(s)                                                               |               |                                    |             |                 |     |                  |             |                    |             |              |
| 539101           | Ram AIR Turbine Enclosure Internal - Zonal Inspection                       |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                             |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                             |               | MOS                                |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031        | 31 Jan 2032 |              |
|                  | Airframe                                                                    |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
|                  |                                                                             | 052016        |                                    |             |                 |     |                  |             |                    |             |              |
| 539102           | Forward Wtbf Internal - Zonal Inspection                                    |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                             |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                             |               | MOS                                |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031        | 31 Jan 2032 |              |
|                  | Airframe                                                                    |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
|                  |                                                                             | 052016        |                                    |             |                 |     |                  |             |                    |             |              |
| 539103           | Forward Wtbf Internal - Enhanced Zonal Inspection                           |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                             |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                             |               | MOS                                |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031        | 31 Jan 2032 |              |
|                  | Airframe                                                                    |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
|                  |                                                                             | 052016        |                                    |             |                 |     |                  |             |                    |             |              |
| 539104           | Forward Wtbf Drain Holes - Enhanced Zonal Inspection                        |               | HRS                                |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                  |                                                                             |               | AFL                                |             | 52              |     |                  | 1065        |                    |             | 0            |
|                  |                                                                             |               | MOS                                |             | 5.2             |     | 24               | 05 Dec 2025 | 31 Dec 2027        | 31 Jan 2028 |              |
|                  | Airframe                                                                    |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
|                  |                                                                             | 052011        |                                    |             |                 |     |                  |             |                    |             |              |
| 539301           | Mid Wtbf Internal - Zonal Inspection                                        |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                             |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                             |               | MOS                                |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031        | 31 Jan 2032 |              |
|                  | Airframe                                                                    |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
|                  |                                                                             | 052016        |                                    |             |                 |     |                  |             |                    |             |              |
| 539302           | Mid Wtbf Internal - Enhanced Zonal Inspection                               |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                             |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                             |               | MOS                                |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031        | 31 Jan 2032 |              |
|                  | Airframe                                                                    |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
|                  |                                                                             | 052016        |                                    |             |                 |     |                  |             |                    |             |              |
| 539303           | Lower Mid Wtbf Drain Holes - Enhanced Zonal Inspection                      |               | HRS                                |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                  |                                                                             |               | AFL                                |             | 52              |     |                  | 1065        |                    |             | 0            |
|                  |                                                                             |               | MOS                                |             | 5.2             |     | 24               | 05 Dec 2025 | 31 Dec 2027        | 31 Jan 2028 |              |
|                  | Airframe                                                                    |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
|                  |                                                                             | 052011        |                                    |             |                 |     |                  |             |                    |             |              |
| 539308           | Forward Wing to Body Fairing Panel 02 (FS. 406-50) - Removal / Installation |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                             |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  | 60P5391202A004                                                              | SN-UNKNOWN    | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                             |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                             |               |                                    |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom  | Description                                                                 |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------|-----------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                  | Part Number                                                                 | Serial Number |                                    |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position | HW                                                                          | SW            |                                    |             |                 |     |                  |             |                    |             | Manufacturer |
|                  | MM Ref                                                                      |               |                                    |             |                 |     |                  |             |                    |             | Date Type    |
|                  | Ops Number(s)                                                               |               |                                    |             |                 |     |                  |             |                    |             |              |
| 539309           | Forward Wing to Body Fairing Panel 04 (FS. 406-50) - Removal / Installation |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                             |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  | 60P5391204A005                                                              | SN-UNKNOWN    | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                             |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                             |               |                                    |             |                 |     |                  |             |                    |             |              |
| 539310           | Left Wtbf Panel 5 Fwd - Removal / Installation                              |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                             |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  | 60P5392205A008                                                              | 0001930121    | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                             |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                             |               |                                    |             |                 |     |                  |             |                    |             |              |
| 539311           | Left Wtbf Panel 5 Aft - Removal / Installation                              |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                             |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  | 60P5392205A009                                                              | 0001932168    | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                             |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                             |               |                                    |             |                 |     |                  |             |                    |             |              |
| 539312           | Right Wtbf Panel 6 Fwd - Removal / Installation                             |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                             |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  | 60P5392206A008                                                              | 0001805521    | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                             |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                             |               |                                    |             |                 |     |                  |             |                    |             |              |
| 539313           | Right Wtbf Panel 6 Aft - Removal / Installation                             |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                             |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  | 60P5392206A009                                                              | 0001932170    | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                             |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                             |               |                                    |             |                 |     |                  |             |                    |             |              |
| 539501           | Aft Wtbf Internal - Zonal Inspection                                        |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                             |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                             |               | MOS                                |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031        | 31 Jan 2032 |              |
|                  |                                                                             |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                             |               |                                    |             |                 |     |                  |             |                    |             |              |
| 539502           | Aft Wtbf Internal - Enhanced Zonal Inspection                               |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                             |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                             |               | MOS                                |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031        | 31 Jan 2032 |              |
|                  |                                                                             |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                             |               |                                    |             |                 |     |                  |             |                    |             |              |
| 539503           | Aft Wtbf Drain Holes - Enhanced Zonal Inspection                            |               | HRS                                |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                  |                                                                             |               | AFL                                |             | 52              |     |                  | 1065        |                    |             | 0            |
|                  |                                                                             |               | MOS                                |             | 5.2             | 41  | 24               | 05 Dec 2025 | 31 Jan 2028*       | 29 Feb 2028 |              |
|                  |                                                                             |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                             |               |                                    |             |                 |     |                  |             |                    |             |              |

54 - Nacelles/Pylons

| ATA<br>U=Custom  | Description                                                                           |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due     | Avg Man Hrs  |
|------------------|---------------------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|---------------------|-------------|--------------|
|                  | Part Number                                                                           | Serial Number |                                    |             |                 |     |                  |             |                     |             | Approx Price |
| Logbook Position | HW                                                                                    | SW            |                                    |             |                 |     |                  |             |                     |             | Manufacturer |
|                  | MM Ref                                                                                |               |                                    |             |                 |     |                  |             |                     |             | Date Type    |
|                  | Ops Number(s)                                                                         |               |                                    |             |                 |     |                  |             |                     |             |              |
| 540001           | Nacelle, Thrust Reverser and Exhaust External (Viewed from Ground) - Zonal Inspection |               | HRS                                |             | 3046.1          |     |                  | 0           |                     |             | 0            |
|                  |                                                                                       |               | AFL                                |             | 1117            |     |                  | 0           |                     | 0           |              |
|                  |                                                                                       |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                     |             |              |
|                  |                                                                                       |               | MSC                                |             |                 |     | O/C              |             |                     |             |              |
| Airframe         |                                                                                       |               |                                    |             |                 |     |                  |             |                     |             |              |
| 545000           | Pylons (External) - Zonal Inspection                                                  |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                     |             | 0            |
|                  |                                                                                       |               | AFL                                |             | 315             |     |                  | 802         |                     | 0           |              |
|                  |                                                                                       |               | MOS                                |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031         | 31 Jan 2032 |              |
|                  |                                                                                       |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                     |             |              |
| Airframe         | 052016                                                                                |               |                                    |             |                 |     |                  |             |                     |             |              |
| 545001           | Pylons (Internal) - Zonal Inspection                                                  |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                     |             | 0            |
|                  |                                                                                       |               | AFL                                |             | 315             |     |                  | 802         |                     | 0           |              |
|                  |                                                                                       |               | MOS                                |             | 28.7            |     | 48               | 21 Dec 2023 | 31 Dec 2027         | 31 Jan 2028 |              |
|                  |                                                                                       |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                     |             |              |
| Airframe         | 052013                                                                                |               |                                    |             |                 |     |                  |             |                     |             |              |
| 545002           | Pylon (External) (Left) - General Visual Inspection                                   |               | HRS                                |             | 663.7           |     |                  | 2382.4      |                     |             | 0            |
|                  |                                                                                       |               | AFL                                |             | 291             |     |                  | 826         |                     | 0           |              |
|                  |                                                                                       |               | MOS                                |             | 25.5            |     |                  | 28 Mar 2024 |                     |             |              |
|                  |                                                                                       |               | MSC                                |             |                 |     | O/C              |             |                     |             |              |
| Airframe         |                                                                                       |               |                                    |             |                 |     |                  |             |                     |             |              |
| 545003           | Pylon (External) (Right) - General Visual Inspection                                  |               | HRS                                |             | 663.7           |     |                  | 2382.4      |                     |             | 0            |
|                  |                                                                                       |               | AFL                                |             | 291             |     |                  | 826         |                     | 0           |              |
|                  |                                                                                       |               | MOS                                |             | 25.5            |     |                  | 28 Mar 2024 |                     |             |              |
|                  |                                                                                       |               | MSC                                |             |                 |     | O/C              |             |                     |             |              |
| Airframe         |                                                                                       |               |                                    |             |                 |     |                  |             |                     |             |              |
| 545004           | Idg Feeder Cables and Wiring Installations - Enhanced Zonal Inspection                |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                     |             | 0            |
|                  |                                                                                       |               | AFL                                |             | 315             |     |                  | 802         |                     | 0           |              |
|                  |                                                                                       |               | MOS                                |             | 28.7            |     | 48               | 21 Dec 2023 | 31 Dec 2027         | 31 Jan 2028 |              |
|                  |                                                                                       |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                     |             |              |
| Airframe         | 052013                                                                                |               |                                    |             |                 |     |                  |             |                     |             |              |
| 545005           | Pylon Leading Edge - Polishing                                                        |               | HRS                                |             | 137             |     |                  | 2909.1      |                     |             | 0            |
|                  |                                                                                       |               | AFL                                |             | 52              |     |                  | 1065        |                     | 0           |              |
|                  |                                                                                       |               | MOS                                |             | 4.7             | -23 | 6                | 19 Dec 2025 | 31 May 2026*        | 30 Jun 2026 |              |
|                  |                                                                                       |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                     |             |              |
| Airframe         |                                                                                       |               |                                    |             |                 |     |                  |             |                     |             |              |
| 545006           | Pylon Leading Edge (Right) - Polishing                                                |               | HRS                                |             | 137             |     |                  | 2909.1      |                     |             | 0            |
|                  |                                                                                       |               | AFL                                |             | 52              |     |                  | 1065        |                     | 0           |              |
|                  |                                                                                       |               | MOS                                |             | 4.7             | -23 | 6                | 19 Dec 2025 | 31 May 2026*        | 30 Jun 2026 |              |
|                  |                                                                                       |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                     |             |              |
| Airframe         |                                                                                       |               |                                    |             |                 |     |                  |             |                     |             |              |

| ATA<br>U=Custom  | Description                                                                 |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-----------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                 | Serial Number |                                    |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                          | SW            |                                    |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                      |               |                                    |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                               |               |                                    |             |                 |     |                  |             |                    |         |              |
| 55 - Stabilizers |                                                                             |               |                                    |             |                 |     |                  |             |                    |         |              |
| 551000           | Horizontal Stabilizer Rear Spar Splice Angles - Detailed Inspection         |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                             |               | AFL                                |             | 1117            |     |                  | 0           |                    | 0       |              |
|                  |                                                                             |               | MOS                                |             | 128.6           |     | 24 Aug 2015      |             |                    |         |              |
|                  |                                                                             |               | MSC                                |             |                 | O/C |                  |             |                    |         |              |
|                  | Airframe                                                                    |               |                                    |             |                 |     |                  |             |                    |         |              |
| 551001           | Horizontal Stabilizer Rub Block Adjustment - Adjustment                     |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                             |               | AFL                                |             | 1117            |     |                  | 0           |                    | 0       |              |
|                  |                                                                             |               | MOS                                |             | 128.6           |     | 24 Aug 2015      |             |                    |         |              |
|                  |                                                                             |               | MSC                                |             |                 | O/C |                  |             |                    |         |              |
|                  | Airframe                                                                    |               |                                    |             |                 |     |                  |             |                    |         |              |
| 551002           | Horizontal Stabilizer Assembly (External) Left - General Visual Inspection  |               | HRS                                |             | 663.7           |     |                  | 2382.4      |                    |         | 0            |
|                  |                                                                             |               | AFL                                |             | 291             |     |                  | 826         |                    | 0       |              |
|                  |                                                                             |               | MOS                                |             | 25.5            | 48  | 28 Mar 2024      | 31 Mar 2028 | 30 Apr 2028        |         |              |
|                  |                                                                             |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |         |              |
|                  | Airframe                                                                    |               |                                    |             |                 |     |                  |             |                    |         |              |
|                  |                                                                             | 052013        |                                    |             |                 |     |                  |             |                    |         |              |
| 551003           | Horizontal Stabilizer Assembly (External) Right - General Visual Inspection |               | HRS                                |             | 663.7           |     |                  | 2382.4      |                    |         | 0            |
|                  |                                                                             |               | AFL                                |             | 291             |     |                  | 826         |                    | 0       |              |
|                  |                                                                             |               | MOS                                |             | 25.5            | 48  | 28 Mar 2024      | 31 Mar 2028 | 30 Apr 2028        |         |              |
|                  |                                                                             |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |         |              |
|                  | Airframe                                                                    |               |                                    |             |                 |     |                  |             |                    |         |              |
|                  |                                                                             | 052013        |                                    |             |                 |     |                  |             |                    |         |              |
| 551004           | Horizontal Stabilizer Assembly (External) Left - Detailed Inspection        |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  |                                                                             |               | AFL                                |             | 315             |     |                  | 802         |                    | 0       |              |
|                  |                                                                             |               | MOS                                |             | 28.7            | 96  | 21 Dec 2023      | 31 Dec 2031 | 31 Jan 2032        |         |              |
|                  |                                                                             |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |         |              |
|                  | Airframe                                                                    |               |                                    |             |                 |     |                  |             |                    |         |              |
|                  |                                                                             | 052016        |                                    |             |                 |     |                  |             |                    |         |              |
| 551005           | Horizontal Stabilizer Assembly (External) Right - Detailed Inspection       |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  |                                                                             |               | AFL                                |             | 315             |     |                  | 802         |                    | 0       |              |
|                  |                                                                             |               | MOS                                |             | 28.7            | 96  | 21 Dec 2023      | 31 Dec 2031 | 31 Jan 2032        |         |              |
|                  |                                                                             |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |         |              |
|                  | Airframe                                                                    |               |                                    |             |                 |     |                  |             |                    |         |              |
|                  |                                                                             | 052016        |                                    |             |                 |     |                  |             |                    |         |              |
| 551006           | Horizontal Stabilizer Front Beam (Left) - Detailed Inspection               |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                             |               | AFL                                |             | 1117            |     |                  | 0           |                    | 0       |              |
|                  |                                                                             |               | MOS                                |             | 122             | 192 | 11 Mar 2016      | 31 Mar 2032 | 30 Apr 2032        |         |              |
|                  |                                                                             |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |         |              |
|                  | Airframe                                                                    |               |                                    |             |                 |     |                  |             |                    |         |              |
|                  |                                                                             | 052021        |                                    |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                          |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------|----------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                  | Part Number                                                          | Serial Number |     |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position | HW                                                                   | SW            |     |             |                 |     |                  |             |                    |             | Manufacturer |
|                  | MM Ref                                                               |               |     |             |                 |     |                  |             |                    |             | Date Type    |
|                  | Ops Number(s)                                                        |               |     |             |                 |     |                  |             |                    |             |              |
| 551007           | Horizontal Stabilizer Front Beam (Right) - Detailed Inspection       |               | HRS |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                      |               | AFL |             | 1117            |     | 0                |             |                    | 0           |              |
|                  |                                                                      |               | MOS |             | 122             |     | 192              | 11 Mar 2016 | 31 Mar 2032        | 30 Apr 2032 |              |
|                  | [End Of Month Item] [MOS: +1m/-1m]                                   |               |     |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                      | 052021        |     |             |                 |     |                  |             |                    |             |              |
| 551008           | Horizontal Stabilizer Rear Beam (Left) - Detailed Inspection         |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                      |               | AFL |             | 315             |     | 802              |             |                    | 0           |              |
|                  |                                                                      |               | MOS |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031        | 31 Jan 2032 |              |
|                  | [End Of Month Item] [MOS: +1m/-1m]                                   |               |     |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                      | 052016        |     |             |                 |     |                  |             |                    |             |              |
| 551009           | Horizontal Stabilizer Rear Beam (Right) - Detailed Inspection        |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                      |               | AFL |             | 315             |     | 802              |             |                    | 0           |              |
|                  |                                                                      |               | MOS |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031        | 31 Jan 2032 |              |
|                  | [End Of Month Item] [MOS: +1m/-1m]                                   |               |     |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                      | 052016        |     |             |                 |     |                  |             |                    |             |              |
| 551010           | Horizontal Stabilizer Rub Blocks (Left) - General Visual Inspection  |               | HRS |             | 137             |     | 3000             | 2909.1      | 5909.1             | 5959.1      | 0            |
|                  |                                                                      |               | AFL |             | 52              |     | 1065             |             |                    | 0           |              |
|                  |                                                                      |               | MOS |             | 5.2             |     | 04 Dec 2025      |             |                    |             |              |
|                  | [HRS: +50/-50]                                                       |               |     |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                      | 052005        |     |             |                 |     |                  |             |                    |             |              |
| 551011           | Horizontal Stabilizer Rub Blocks (Right) - General Visual Inspection |               | HRS |             | 137             |     | 3000             | 2909.1      | 5909.1             |             | 0            |
|                  |                                                                      |               | AFL |             | 52              |     | 1065             |             |                    | 0           |              |
|                  |                                                                      |               | MOS |             | 5.2             |     | 04 Dec 2025      |             |                    |             |              |
|                  | [HRS: -50]                                                           |               |     |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                      | 052005        |     |             |                 |     |                  |             |                    |             |              |
| 551012           | Horizontal Stabilizer Hirf/L (Left) - Detailed Inspection            |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                      |               | AFL |             | 315             |     | 802              |             |                    | 0           |              |
|                  |                                                                      |               | MOS |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031        | 31 Jan 2032 |              |
|                  | [End Of Month Item] [MOS: +1m/-1m]                                   |               |     |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                      | 052016        |     |             |                 |     |                  |             |                    |             |              |
| 551013           | Horizontal Stabilizer Hirf/L (Right) - Detailed Inspection           |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                      |               | AFL |             | 315             |     | 802              |             |                    | 0           |              |
|                  |                                                                      |               | MOS |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031        | 31 Jan 2032 |              |
|                  | [End Of Month Item] [MOS: +1m/-1m]                                   |               |     |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                      | 052016        |     |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom  | Description                                                                      |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(* =Adj) | Max Due     | Avg Man Hrs  |
|------------------|----------------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|----------------------|-------------|--------------|
|                  | Part Number                                                                      | Serial Number |                                    |             |                 |     |                  |             |                      |             | Approx Price |
| Logbook Position | HW                                                                               | SW            |                                    |             |                 |     |                  |             |                      |             | Manufacturer |
|                  | MM Ref                                                                           |               |                                    |             |                 |     |                  |             |                      |             | Date Type    |
|                  | Ops Number(s)                                                                    |               |                                    |             |                 |     |                  |             |                      |             |              |
| 551014           | Horizontal Stabilizer Rear Beam Hirf/L (Left) - Detailed Inspection              |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                      |             | 0            |
|                  |                                                                                  |               | AFL                                |             | 315             |     |                  | 802         |                      |             | 0            |
|                  |                                                                                  |               | MOS                                |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031          | 31 Jan 2032 |              |
|                  |                                                                                  |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                      |             |              |
| Airframe         |                                                                                  |               |                                    |             |                 |     |                  |             |                      |             |              |
|                  |                                                                                  |               | 052016                             |             |                 |     |                  |             |                      |             |              |
| 551015           | Horizontal Stabilizer Rear Beam Hirf/L (Right) - Detailed Inspection             |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                      |             | 0            |
|                  |                                                                                  |               | AFL                                |             | 315             |     |                  | 802         |                      |             | 0            |
|                  |                                                                                  |               | MOS                                |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031          | 31 Jan 2032 |              |
|                  |                                                                                  |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                      |             |              |
| Airframe         |                                                                                  |               |                                    |             |                 |     |                  |             |                      |             |              |
|                  |                                                                                  |               | 052016                             |             |                 |     |                  |             |                      |             |              |
| 551016           | Horizontal Stabilizer Rub Block / Vertical Fin Rub Strip Gaps - Functional Check |               | HRS                                |             | 137             |     | 3000             | 2909.1      | 5909.1               | 5959.1      | 0            |
|                  |                                                                                  |               | AFL                                |             | 52              |     |                  | 1065        |                      |             | 0            |
|                  |                                                                                  |               | MOS                                |             | 5.2             |     |                  | 04 Dec 2025 |                      |             |              |
|                  |                                                                                  |               | [HRS: +50/-50]                     |             |                 |     |                  |             |                      |             |              |
| Airframe         |                                                                                  |               |                                    |             |                 |     |                  |             |                      |             |              |
|                  |                                                                                  |               | 052005                             |             |                 |     |                  |             |                      |             |              |
| 551017           | Horizontal Stabilizer Assembly (Internal) Left - Zonal Inspection                |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                      |             | 0            |
|                  |                                                                                  |               | AFL                                |             | 315             |     |                  | 802         |                      |             | 0            |
|                  |                                                                                  |               | MOS                                |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031          | 31 Jan 2032 |              |
|                  |                                                                                  |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                      |             |              |
| Airframe         |                                                                                  |               |                                    |             |                 |     |                  |             |                      |             |              |
|                  |                                                                                  |               | 052016                             |             |                 |     |                  |             |                      |             |              |
| 551018           | Horizontal Stabilizer Assembly (Internal) Right - Zonal Inspection               |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                      |             | 0            |
|                  |                                                                                  |               | AFL                                |             | 315             |     |                  | 802         |                      |             | 0            |
|                  |                                                                                  |               | MOS                                |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031          | 31 Jan 2032 |              |
|                  |                                                                                  |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                      |             |              |
| Airframe         |                                                                                  |               |                                    |             |                 |     |                  |             |                      |             |              |
|                  |                                                                                  |               | 052016                             |             |                 |     |                  |             |                      |             |              |
| 551019           | Horizontal Stabilizer - Removal / Installation<br>60P5510000-0016160             |               | HRS                                |             | 3046.1          |     |                  | 0           |                      |             | 0            |
|                  |                                                                                  |               | AFL                                |             | 1117            |     |                  | 0           |                      |             | 0            |
|                  |                                                                                  |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                      |             |              |
|                  |                                                                                  |               | MSC                                |             |                 |     | O/C              |             |                      |             |              |
| Airframe         |                                                                                  |               |                                    |             |                 |     |                  |             |                      |             |              |
| 551021           | Left Horizontal Stabilizer Rub Block - Removal / Installation<br>N/A NSN         |               | HRS                                |             | 3046.1          |     |                  | 0           |                      |             | 0            |
|                  |                                                                                  |               | AFL                                |             | 1117            |     |                  | 0           |                      |             | 0            |
|                  |                                                                                  |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                      |             |              |
|                  |                                                                                  |               | MSC                                |             |                 |     | O/C              |             |                      |             |              |
| Airframe         |                                                                                  |               |                                    |             |                 |     |                  |             |                      |             |              |

| ATA<br>U=Custom  | Description                                                                     |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W                            | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|---------------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------------------------------|--------------------|---------|--------------|
|                  | Part Number                                                                     | Serial Number |                                    |             |                 |     |                  |                                     |                    |         | Approx Price |
| Logbook Position | HW                                                                              | SW            |                                    |             |                 |     |                  |                                     |                    |         | Manufacturer |
|                  | MM Ref                                                                          |               |                                    |             |                 |     |                  |                                     |                    |         | Date Type    |
|                  | Ops Number(s)                                                                   |               |                                    |             |                 |     |                  |                                     |                    |         |              |
| 551022           | Right Horizontal Stabilizer Rub Block - Removal / Installation                  |               | HRS                                |             | 3046.1          |     |                  | 0                                   |                    |         | 0            |
|                  |                                                                                 |               | AFL                                |             | 1117            |     |                  | 0                                   |                    |         | 0            |
|                  | N/A                                                                             | NSN           | MOS                                |             | 128.6           |     |                  | 24 Aug 2015                         |                    |         |              |
|                  |                                                                                 |               | MSC                                |             |                 |     | O/C              |                                     |                    |         |              |
| Airframe         |                                                                                 |               |                                    |             |                 |     |                  |                                     |                    |         |              |
| 551100           | Horizontal Stabilizer Inboard Leading Edge (Left) - Removal / Installation      |               | HRS                                |             | 730.5           |     |                  | 2315.6                              |                    |         | 0            |
|                  |                                                                                 |               | AFL                                |             | 315             |     |                  | 802                                 |                    |         | 0            |
|                  | 60P5511601A004                                                                  | NSN           | MOS                                |             | 28.7            |     |                  | 21 Dec 2023                         |                    |         |              |
|                  |                                                                                 |               | MSC                                |             |                 |     | O/C              |                                     |                    |         |              |
| Airframe         |                                                                                 |               |                                    |             |                 |     |                  |                                     |                    |         |              |
| 551101           | Horizontal Stabilizer Inboard Leading Edge (Right) - Removal / Installation     |               | HRS                                |             | 730.5           |     |                  | 2315.6                              |                    |         | 0            |
|                  |                                                                                 |               | AFL                                |             | 315             |     |                  | 802                                 |                    |         | 0            |
|                  | 60P5511602A004                                                                  | NSN           | MOS                                |             | 28.7            |     |                  | 21 Dec 2023                         |                    |         |              |
|                  |                                                                                 |               | MSC                                |             |                 |     | O/C              |                                     |                    |         |              |
| Airframe         |                                                                                 |               |                                    |             |                 |     |                  |                                     |                    |         |              |
| 551108           | Horizontal Stabilizer Leading Edge (Left) - Polishing                           |               | HRS                                |             | 137             |     |                  | 2909.1                              |                    |         | 0            |
|                  |                                                                                 |               | AFL                                |             | 52              |     |                  | 1065                                |                    |         | 0            |
|                  |                                                                                 |               | MOS                                |             | 4.7             | -23 | 6                | 19 Dec 2025 31 May 2026*            | 30 Jun 2026        |         |              |
|                  |                                                                                 |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |                                     |                    |         |              |
| Airframe         |                                                                                 |               |                                    |             |                 |     |                  |                                     |                    |         |              |
| 551200           | Horizontal Stabilizer Center Box and Actuator Attachments - Detailed Inspection |               | HRS                                |             | 3046.1          |     |                  | 0                                   |                    |         | 0            |
|                  |                                                                                 |               | AFL                                |             | 1117            |     |                  | 0                                   |                    |         | 0            |
|                  |                                                                                 |               | MOS                                |             | 122             |     | 144              | 11 Mar 2016 31 Mar 2028 30 Apr 2028 |                    |         |              |
|                  |                                                                                 |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |                                     |                    |         |              |
| Airframe         |                                                                                 |               |                                    |             |                 |     |                  |                                     |                    |         |              |
| 052019           |                                                                                 |               |                                    |             |                 |     |                  |                                     |                    |         |              |
| 551400           | Elevator Exterior - Zonal Inspection                                            |               | HRS                                |             | 3046.1          |     |                  | 0                                   |                    |         | 0            |
|                  |                                                                                 |               | AFL                                |             | 1117            |     |                  | 0                                   |                    |         | 0            |
|                  |                                                                                 |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015                         |                    |         |              |
|                  |                                                                                 |               | MSC                                |             |                 |     | O/C              |                                     |                    |         |              |
| Airframe         |                                                                                 |               |                                    |             |                 |     |                  |                                     |                    |         |              |
| 551401           | Elevator Attachments - Zonal Inspection                                         |               | HRS                                |             | 3046.1          |     |                  | 0                                   |                    |         | 0            |
|                  |                                                                                 |               | AFL                                |             | 1117            |     |                  | 0                                   |                    |         | 0            |
|                  |                                                                                 |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015                         |                    |         |              |
|                  |                                                                                 |               | MSC                                |             |                 |     | O/C              |                                     |                    |         |              |
| Airframe         |                                                                                 |               |                                    |             |                 |     |                  |                                     |                    |         |              |



| ATA<br>U=Custom  | Description                                                                 |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due     | Avg Man Hrs  |
|------------------|-----------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|---------------------|-------------|--------------|
|                  | Part Number                                                                 | Serial Number |                                    |             |                 |     |                  |             |                     |             | Approx Price |
| Logbook Position | HW                                                                          | SW            |                                    |             |                 |     |                  |             |                     |             | Manufacturer |
|                  | MM Ref                                                                      |               |                                    |             |                 |     |                  |             |                     |             | Date Type    |
|                  | Ops Number(s)                                                               |               |                                    |             |                 |     |                  |             |                     |             |              |
| 551403           | Horizontal Stabilizer Trailing Edge (Left) - Zonal Inspection               |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                     |             | 0            |
|                  |                                                                             |               | AFL                                |             | 315             |     |                  | 802         |                     |             | 0            |
|                  |                                                                             |               | MOS                                |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031         | 31 Jan 2032 |              |
|                  |                                                                             |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                     |             |              |
| Airframe         |                                                                             | 052016        |                                    |             |                 |     |                  |             |                     |             |              |
| 551404           | Horizontal Stabilizer Trailing Edge (Right) - Zonal Inspection              |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                     |             | 0            |
|                  |                                                                             |               | AFL                                |             | 315             |     |                  | 802         |                     |             | 0            |
|                  |                                                                             |               | MOS                                |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031         | 31 Jan 2032 |              |
|                  |                                                                             |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                     |             |              |
| Airframe         |                                                                             | 052016        |                                    |             |                 |     |                  |             |                     |             |              |
| 551500           | Horizontal Stabilizer Elevator Hinge Brackets (Left) - Detailed Inspection  |               | HRS                                |             | 3046.1          |     |                  | 0           |                     |             | 0            |
|                  |                                                                             |               | AFL                                |             | 1117            |     |                  | 0           |                     |             | 0            |
|                  |                                                                             |               | MOS                                |             | 122             |     | 144              | 11 Mar 2016 | 31 Mar 2028         | 30 Apr 2028 |              |
|                  |                                                                             |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                     |             |              |
| Airframe         |                                                                             | 052019        |                                    |             |                 |     |                  |             |                     |             |              |
| 551501           | Horizontal Stabilizer Elevator Hinge Brackets (Right) - Detailed Inspection |               | HRS                                |             | 3046.1          |     |                  | 0           |                     |             | 0            |
|                  |                                                                             |               | AFL                                |             | 1117            |     |                  | 0           |                     |             | 0            |
|                  |                                                                             |               | MOS                                |             | 122             |     | 144              | 11 Mar 2016 | 31 Mar 2028         | 30 Apr 2028 |              |
|                  |                                                                             |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                     |             |              |
| Airframe         |                                                                             | 052019        |                                    |             |                 |     |                  |             |                     |             |              |
| 551502           | Horizontal Stabilizer Pivot Fitting - Detailed Inspection                   |               | HRS                                |             | 562.4           |     |                  | 2483.7      |                     |             | 0            |
|                  |                                                                             |               | AFL                                |             | 217             |     |                  | 900         |                     |             | 0            |
|                  |                                                                             |               | MOS                                |             | 17.5            |     | 96               | 27 Nov 2024 | 30 Nov 2032         | 31 Dec 2032 |              |
|                  |                                                                             |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                     |             |              |
| Airframe         |                                                                             | 052019        |                                    |             |                 |     |                  |             |                     |             |              |
| 551700           | Horizontal Stabilizer Actuator Structural Attachments - Visual Inspection   |               | HRS                                |             | 3046.1          |     |                  | 0           |                     |             | 0            |
|                  |                                                                             |               | AFL                                |             | 1117            |     |                  | 0           |                     |             | 0            |
|                  |                                                                             |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                     |             |              |
|                  |                                                                             |               | MSC                                |             |                 |     | O/C              |             |                     |             |              |
| Airframe         |                                                                             |               |                                    |             |                 |     |                  |             |                     |             |              |
| 551701           | Horizontal Stabilizer Actuator Connectors - Seating Check                   |               | HRS                                |             | 3046.1          |     |                  | 0           |                     |             | 0            |
|                  |                                                                             |               | AFL                                |             | 1117            |     |                  | 0           |                     |             | 0            |
|                  |                                                                             |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                     |             |              |
|                  |                                                                             |               | MSC                                |             |                 |     | O/C              |             |                     |             |              |
| Airframe         |                                                                             |               |                                    |             |                 |     |                  |             |                     |             |              |

| ATA<br>U=Custom  | Description                                                                   |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------|-------------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                  | Part Number                                                                   | Serial Number |                                    |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position | HW                                                                            | SW            |                                    |             |                 |     |                  |             |                    |             | Manufacturer |
|                  | MM Ref                                                                        |               |                                    |             |                 |     |                  |             |                    |             | Date Type    |
|                  | Ops Number(s)                                                                 |               |                                    |             |                 |     |                  |             |                    |             |              |
| 552006           | Elevator Hinge Brackets AT Interior of Elevator (Left) - Detailed Inspection  |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                               |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                               |               | MOS                                |             | 122             |     | 192              | 11 Mar 2016 | 31 Mar 2032        | 30 Apr 2032 |              |
|                  |                                                                               |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                               | 052021        |                                    |             |                 |     |                  |             |                    |             |              |
| 552007           | Elevator Hinge Brackets AT Interior of Elevator (Right) - Detailed Inspection |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                               |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                               |               | MOS                                |             | 122             |     | 192              | 11 Mar 2016 | 31 Mar 2032        | 30 Apr 2032 |              |
|                  |                                                                               |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                               | 052021        |                                    |             |                 |     |                  |             |                    |             |              |
| 552008           | Elevator (External) Left - Detailed Inspection                                |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                               |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                               |               | MOS                                |             | 28.7            |     | 48               | 21 Dec 2023 | 31 Dec 2027        | 31 Jan 2028 |              |
|                  |                                                                               |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                               | 052013        |                                    |             |                 |     |                  |             |                    |             |              |
| 552009           | Elevator (External) Right - Detailed Inspection                               |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                               |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                               |               | MOS                                |             | 28.7            |     | 48               | 21 Dec 2023 | 31 Dec 2027        | 31 Jan 2028 |              |
|                  |                                                                               |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                               | 052013        |                                    |             |                 |     |                  |             |                    |             |              |
| 552010           | Elevator (Internal) Nonmetal Parts (Left) - Detailed Inspection               |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                               |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                               |               | MOS                                |             | 122             |     | 192              | 11 Mar 2016 | 31 Mar 2032        | 30 Apr 2032 |              |
|                  |                                                                               |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                               | 052021        |                                    |             |                 |     |                  |             |                    |             |              |
| 552011           | Elevator (Internal) Nonmetal Parts (Right) - Detailed Inspection              |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                               |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                               |               | MOS                                |             | 122             |     | 192              | 11 Mar 2016 | 31 Mar 2032        | 30 Apr 2032 |              |
|                  |                                                                               |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                               | 052021        |                                    |             |                 |     |                  |             |                    |             |              |
| 552300           | Elevator Hinge (Left) - Detailed Inspection                                   |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                               |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                               |               | MOS                                |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031        | 31 Jan 2032 |              |
|                  |                                                                               |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                               | 052016        |                                    |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom  | Description                                                                          |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------|--------------------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                  | Part Number                                                                          | Serial Number |                                    |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position | HW                                                                                   | SW            |                                    |             |                 |     |                  |             |                    |             | Manufacturer |
|                  | MM Ref                                                                               |               |                                    |             |                 |     |                  |             |                    |             | Date Type    |
|                  | Ops Number(s)                                                                        |               |                                    |             |                 |     |                  |             |                    |             |              |
| 552301           | Elevator Hinge (Right) - Detailed Inspection                                         |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                                      |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                                      |               | MOS                                |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031        | 31 Jan 2032 |              |
| Airframe         | 052016                                                                               |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| 553000           | Vertical Stabilizer Exterior - Zonal Inspection                                      |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                      |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                      |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
| Airframe         |                                                                                      |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| 553001           | Rudder Exterior - Zonal Inspection                                                   |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                      |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                      |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
| Airframe         |                                                                                      |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| 553003           | Vertical Stabilizer Interior of Fin CAP / Rear Bullet Fairings<br>- Zonal Inspection |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                                      |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                                      |               | MOS                                |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031        | 31 Jan 2032 |              |
| Airframe         | 052016                                                                               |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| 553005           | Vertical Stabilizer Rear Spar Aft Face - Zonal Inspection                            |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                                      |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                                      |               | MOS                                |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031        | 31 Jan 2032 |              |
| Airframe         | 052016                                                                               |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| 553006           | Vertical Stabilizer (External) - General Visual Inspection                           |               | HRS                                |             | 663.7           |     |                  | 2382.4      |                    |             | 0            |
|                  |                                                                                      |               | AFL                                |             | 291             |     |                  | 826         |                    |             | 0            |
|                  |                                                                                      |               | MOS                                |             | 25.5            |     | 48               | 28 Mar 2024 | 31 Mar 2028        | 30 Apr 2028 |              |
| Airframe         | 052013                                                                               |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| 553007           | Vertical Stabilizer Assembly (Internal) - Detailed<br>Inspection                     |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                      |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                      |               | MOS                                |             | 122             |     | 144              | 11 Mar 2016 | 31 Mar 2028        | 30 Apr 2028 |              |
| Airframe         | 052019                                                                               |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| 553008           | Vertical Stabilizer Hirf/L - Detailed Inspection                                     |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                                      |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                                      |               | MOS                                |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031        | 31 Jan 2032 |              |
| Airframe         | 052016                                                                               |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom  | Description                                                                   |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due     | Avg Man Hrs  |
|------------------|-------------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|---------------------|-------------|--------------|
|                  | Part Number                                                                   | Serial Number |                                    |             |                 |     |                  |             |                     |             | Approx Price |
| Logbook Position | HW                                                                            | SW            |                                    |             |                 |     |                  |             |                     |             | Manufacturer |
|                  | MM Ref                                                                        |               |                                    |             |                 |     |                  |             |                     |             | Date Type    |
|                  | Ops Number(s)                                                                 |               |                                    |             |                 |     |                  |             |                     |             |              |
| 553009           | Vertical Stabilizer Rear Beam Hirf/L - Detailed Inspection                    |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                     |             | 0            |
|                  |                                                                               |               | AFL                                |             | 315             |     |                  | 802         |                     |             | 0            |
|                  |                                                                               |               | MOS                                |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031         | 31 Jan 2032 |              |
|                  |                                                                               |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                     |             |              |
| Airframe         |                                                                               | 052016        |                                    |             |                 |     |                  |             |                     |             |              |
| 553010           | Vertical Stabilizer - Removal / Installation                                  |               | HRS                                |             | 3046.1          |     |                  | 0           |                     |             | 0            |
|                  | 60P5530000-001                                                                | 6160          | AFL                                |             | 1117            |     |                  | 0           |                     |             | 0            |
|                  |                                                                               |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                     |             |              |
|                  |                                                                               |               | MSC                                |             |                 |     | O/C              |             |                     |             |              |
| Airframe         |                                                                               |               |                                    |             |                 |     |                  |             |                     |             |              |
| 553011           | Vertical Stabilizer Leading Edge - Polishing                                  |               | HRS                                |             | 137             |     |                  | 2909.1      |                     |             | 0            |
|                  |                                                                               |               | AFL                                |             | 52              |     |                  | 1065        |                     |             | 0            |
|                  |                                                                               |               | MOS                                |             | 4.7             | -23 | 6                | 19 Dec 2025 | 31 May 2026*        | 30 Jun 2026 |              |
|                  |                                                                               |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                     |             |              |
| Airframe         |                                                                               |               |                                    |             |                 |     |                  |             |                     |             |              |
| 553100           | Vertical Stabilizer Interior of Leading Edge - Zonal Inspection               |               | HRS                                |             | 3046.1          |     |                  | 0           |                     |             | 0            |
|                  |                                                                               |               | AFL                                |             | 1117            |     |                  | 0           |                     |             | 0            |
|                  |                                                                               |               | MOS                                |             | 122             |     | 192              | 11 Mar 2016 | 31 Mar 2032         | 30 Apr 2032 |              |
|                  |                                                                               |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                     |             |              |
| Airframe         |                                                                               | 052021        |                                    |             |                 |     |                  |             |                     |             |              |
| 553200           | Vertical Stabilizer Box Section Internal Structure - Zonal Inspection         |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                     |             | 0            |
|                  |                                                                               |               | AFL                                |             | 315             |     |                  | 802         |                     |             | 0            |
|                  |                                                                               |               | MOS                                |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031         | 31 Jan 2032 |              |
|                  |                                                                               |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                     |             |              |
| Airframe         |                                                                               | 052016        |                                    |             |                 |     |                  |             |                     |             |              |
| 553201           | Vertical Stabilizer Box Section (Internal) Flight Controls - Zonal Inspection |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                     |             | 0            |
|                  |                                                                               |               | AFL                                |             | 315             |     |                  | 802         |                     |             | 0            |
|                  |                                                                               |               | MOS                                |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031         | 31 Jan 2032 |              |
|                  |                                                                               |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                     |             |              |
| Airframe         |                                                                               | 052016        |                                    |             |                 |     |                  |             |                     |             |              |
| 553500           | Vertical Stabilizer Pivot Lugs and Interface - Detailed Inspection            |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                     |             | 0            |
|                  |                                                                               |               | AFL                                |             | 315             |     |                  | 802         |                     |             | 0            |
|                  |                                                                               |               | MOS                                |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031         | 31 Jan 2032 |              |
|                  |                                                                               |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                     |             |              |
| Airframe         |                                                                               | 052016        |                                    |             |                 |     |                  |             |                     |             |              |

| ATA<br>U=Custom  | Description                                                                  |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due     | Avg Man Hrs  |
|------------------|------------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|---------------------|-------------|--------------|
|                  | Part Number                                                                  | Serial Number |                                    |             |                 |     |                  |             |                     |             | Approx Price |
| Logbook Position | HW                                                                           | SW            |                                    |             |                 |     |                  |             |                     |             | Manufacturer |
|                  | MM Ref                                                                       |               |                                    |             |                 |     |                  |             |                     |             | Date Type    |
|                  | Ops Number(s)                                                                |               |                                    |             |                 |     |                  |             |                     |             |              |
| 553501           | Vertical Stabilizer (Internal) Boomerang Fittings - Detailed Inspection      |               | HRS                                |             | 3046.1          |     |                  | 0           |                     |             | 0            |
|                  |                                                                              |               | AFL                                |             | 1117            |     |                  | 0           |                     |             | 0            |
|                  |                                                                              |               | MOS                                |             | 122             |     | 144              | 11 Mar 2016 | 31 Mar 2028         | 30 Apr 2028 |              |
|                  |                                                                              |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                     |             |              |
| Airframe         |                                                                              |               | 052019                             |             |                 |     |                  |             |                     |             |              |
| 554000           | Vertical Stabilizer Rudder Hinges and Support Fittings - Detailed Inspection |               | HRS                                |             | 3046.1          |     |                  | 0           |                     |             | 0            |
|                  |                                                                              |               | AFL                                |             | 1117            |     |                  | 0           |                     |             | 0            |
|                  |                                                                              |               | MOS                                |             | 122             |     | 144              | 11 Mar 2016 | 31 Mar 2028         | 30 Apr 2028 |              |
|                  |                                                                              |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                     |             |              |
| Airframe         |                                                                              |               | 052019                             |             |                 |     |                  |             |                     |             |              |
| 554001           | Rudder Assembly Hinge Brackets and Swivel Links - Detailed Inspection        |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                     |             | 0            |
|                  |                                                                              |               | AFL                                |             | 315             |     |                  | 802         |                     |             | 0            |
|                  |                                                                              |               | MOS                                |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031         | 31 Jan 2032 |              |
|                  |                                                                              |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                     |             |              |
| Airframe         |                                                                              |               | 052016                             |             |                 |     |                  |             |                     |             |              |
| 554002           | Rudder (External) - Detailed Inspection                                      |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                     |             | 0            |
|                  |                                                                              |               | AFL                                |             | 315             |     |                  | 802         |                     |             | 0            |
|                  |                                                                              |               | MOS                                |             | 28.7            |     | 48               | 21 Dec 2023 | 31 Dec 2027         | 31 Jan 2028 |              |
|                  |                                                                              |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                     |             |              |
| Airframe         |                                                                              |               | 052013                             |             |                 |     |                  |             |                     |             |              |
| 554003           | Rudder Assembly Front Beam (Internal) - Detailed Inspection                  |               | HRS                                |             | 3046.1          |     |                  | 0           |                     |             | 0            |
|                  |                                                                              |               | AFL                                |             | 1117            |     |                  | 0           |                     |             | 0            |
|                  |                                                                              |               | MOS                                |             | 122             |     | 192              | 11 Mar 2016 | 31 Mar 2032         | 30 Apr 2032 |              |
|                  |                                                                              |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                     |             |              |
| Airframe         |                                                                              |               | 052021                             |             |                 |     |                  |             |                     |             |              |
| 56 - Windows     |                                                                              |               |                                    |             |                 |     |                  |             |                     |             |              |
| 561100           | Windshield (Left) - Removal / Installation<br>1159SCB5102-1315041H3405       |               | HRS                                |             | 3046.1          |     |                  | 0           |                     |             | 0            |
|                  |                                                                              |               | AFL                                |             | 1117            |     |                  | 0           |                     |             | 0            |
|                  |                                                                              |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                     |             |              |
|                  |                                                                              |               | MSC                                |             |                 |     | O/C              |             |                     |             |              |
| Airframe         |                                                                              |               |                                    |             |                 |     |                  |             |                     |             |              |
| 561101           | Windshield (Right) - Removal / Installation<br>1159SCB5102-1524293H5028      |               | HRS                                |             | 564.8           |     |                  | 2481.3      |                     |             | 0            |
|                  |                                                                              |               | AFL                                |             | 219             |     |                  | 898         |                     |             | 0            |
|                  |                                                                              |               | MOS                                | TSN:96      | 17.8            |     |                  | 17 Nov 2024 |                     |             |              |
|                  |                                                                              |               | MSC                                |             |                 |     | O/C              |             |                     |             |              |
| Airframe         |                                                                              |               |                                    |             |                 |     |                  |             |                     |             |              |

| ATA<br>U=Custom  | Description                                                                      |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------|----------------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                  | Part Number                                                                      | Serial Number |                                    |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position | HW                                                                               | SW            |                                    |             |                 |     |                  |             |                    |             | Manufacturer |
|                  | MM Ref                                                                           |               |                                    |             |                 |     |                  |             |                    |             | Date Type    |
|                  | Ops Number(s)                                                                    |               |                                    |             |                 |     |                  |             |                    |             |              |
| 561102           | Side Window (Left) - Removal / Installation                                      |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  | 60P5612001Z003                                                                   | 15005H9542    | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                  |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  | Airframe                                                                         |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| 561103           | Side Window (Right) - Removal / Installation                                     |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  | 60P5612002Z003                                                                   | 15069H5864    | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                  |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  | Airframe                                                                         |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| 561106           | Cockpit Windshield Nonmetallic Interior Structures (Left) - Detailed Inspection  |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                  |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                  |               | MOS                                |             | 122             | 19  | 200              | 11 Mar 2016 | 30 Nov 2032*       | 31 Dec 2032 |              |
|                  | Airframe                                                                         |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| 561107           | Cockpit Windshield Nonmetallic Interior Structures (Right) - Detailed Inspection |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                  |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                  |               | MOS                                |             | 122             | 19  | 200              | 11 Mar 2016 | 30 Nov 2032*       | 31 Dec 2032 |              |
|                  | Airframe                                                                         |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| 561108           | Cockpit Windshield Metallic Interior Structures (Left) - Detailed Inspection     |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                  |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                  |               | MOS                                |             | 122             | 19  | 200              | 11 Mar 2016 | 30 Nov 2032*       | 31 Dec 2032 |              |
|                  | Airframe                                                                         |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| 561109           | Cockpit Windshield Metallic Interior Structures (Right) - Detailed Inspection    |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                  |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                  |               | MOS                                |             | 122             | 19  | 200              | 11 Mar 2016 | 30 Nov 2032*       | 31 Dec 2032 |              |
|                  | Airframe                                                                         |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| 561111           | Windshield Weather Seals (Humpseal) (Left) - Detailed Inspection                 |               | HRS                                |             | 137             |     | 600              | 2909.1      | 3509.1             | 3559.1      | 0            |
|                  |                                                                                  |               | AFL                                |             | 52              |     |                  | 1065        |                    |             | 0            |
|                  |                                                                                  |               | MOS                                |             | 5.5             |     | 24               | 27 Nov 2025 | 27 Nov 2027        | 27 Dec 2027 |              |
|                  | Airframe                                                                         |               | [MOS: +1m/-1m] [HRS: +50/-50]      |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom  | Description                                                                       |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due     | Avg Man Hrs  |
|------------------|-----------------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|---------------------|-------------|--------------|
|                  | Part Number                                                                       | Serial Number |                                    |             |                 |     |                  |             |                     |             | Approx Price |
| Logbook Position | HW                                                                                | SW            |                                    |             |                 |     |                  |             |                     |             | Manufacturer |
|                  | MM Ref                                                                            |               |                                    |             |                 |     |                  |             |                     |             | Date Type    |
|                  | Ops Number(s)                                                                     |               |                                    |             |                 |     |                  |             |                     |             |              |
| 561112           | Windshield Weather Seals (Humpseal) (Right) - Detailed Inspection                 |               | HRS                                |             | 137             |     | 600              | 2909.1      | 3509.1              | 3559.1      | 0            |
|                  |                                                                                   |               | AFL                                |             | 52              |     |                  | 1065        |                     |             | 0            |
|                  |                                                                                   |               | MOS                                |             | 5.5             |     | 24               | 27 Nov 2025 | 27 Nov 2027         | 27 Dec 2027 |              |
|                  |                                                                                   |               | [MOS: +1m/-1m] [HRS: +50/-50]      |             |                 |     |                  |             |                     |             |              |
| Airframe         |                                                                                   |               |                                    |             |                 |     |                  |             |                     |             |              |
| 561200           | Cockpit Side Window Nonmetallic Interior Structures (Left) - Detailed Inspection  |               | HRS                                |             | 3046.1          |     |                  | 0           |                     |             | 0            |
|                  |                                                                                   |               | AFL                                |             | 1117            |     |                  | 0           |                     |             | 0            |
|                  |                                                                                   |               | MOS                                |             | 122             | 19  | 200              | 11 Mar 2016 | 30 Nov 2032*        | 31 Dec 2032 |              |
|                  |                                                                                   |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                     |             |              |
| Airframe         |                                                                                   |               |                                    |             |                 |     |                  |             |                     |             |              |
| 561201           | Cockpit Side Window Nonmetallic Interior Structures (Right) - Detailed Inspection |               | HRS                                |             | 3046.1          |     |                  | 0           |                     |             | 0            |
|                  |                                                                                   |               | AFL                                |             | 1117            |     |                  | 0           |                     |             | 0            |
|                  |                                                                                   |               | MOS                                |             | 122             | 19  | 200              | 11 Mar 2016 | 30 Nov 2032*        | 31 Dec 2032 |              |
|                  |                                                                                   |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                     |             |              |
| Airframe         |                                                                                   |               |                                    |             |                 |     |                  |             |                     |             |              |
| 561202           | Cockpit Side Window Metallic Interior Structures (Left) - Detailed Inspection     |               | HRS                                |             | 3046.1          |     |                  | 0           |                     |             | 0            |
|                  |                                                                                   |               | AFL                                |             | 1117            |     |                  | 0           |                     |             | 0            |
|                  |                                                                                   |               | MOS                                |             | 122             | 19  | 200              | 11 Mar 2016 | 30 Nov 2032*        | 31 Dec 2032 |              |
|                  |                                                                                   |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                     |             |              |
| Airframe         |                                                                                   |               |                                    |             |                 |     |                  |             |                     |             |              |
| 561203           | Cockpit Side Window Metallic Interior Structures (Right) - Detailed Inspection    |               | HRS                                |             | 3046.1          |     |                  | 0           |                     |             | 0            |
|                  |                                                                                   |               | AFL                                |             | 1117            |     |                  | 0           |                     |             | 0            |
|                  |                                                                                   |               | MOS                                |             | 122             | 19  | 200              | 11 Mar 2016 | 30 Nov 2032*        | 31 Dec 2032 |              |
|                  |                                                                                   |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                     |             |              |
| Airframe         |                                                                                   |               |                                    |             |                 |     |                  |             |                     |             |              |
| 562100           | Cabin Window (Left No. 1) - Removal / Installation<br>60P5621001Z00415138H3013    |               | HRS                                |             | 3046.1          |     |                  | 0           |                     |             | 0            |
|                  |                                                                                   |               | AFL                                |             | 1117            |     |                  | 0           |                     |             | 0            |
|                  |                                                                                   |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                     |             |              |
|                  |                                                                                   |               | MSC                                |             |                 |     | O/C              |             |                     |             |              |
| Airframe         |                                                                                   |               |                                    |             |                 |     |                  |             |                     |             |              |
| 562101           | Cabin Window (Left No. 2) - Removal / Installation<br>60P5621001Z00415131H2313    |               | HRS                                |             | 3046.1          |     |                  | 0           |                     |             | 0            |
|                  |                                                                                   |               | AFL                                |             | 1117            |     |                  | 0           |                     |             | 0            |
|                  |                                                                                   |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                     |             |              |
|                  |                                                                                   |               | MSC                                |             |                 |     | O/C              |             |                     |             |              |
| Airframe         |                                                                                   |               |                                    |             |                 |     |                  |             |                     |             |              |

| ATA<br>U=Custom  | Description                                         |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-----------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                         | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                  | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                              |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                       |               |     |             |                 |     |                  |             |                    |         |              |
| 562102           | Cabin Window (Left No. 3) - Removal / Installation  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P5621001Z004                                      | 15134H2747    | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                     |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                            |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 562103           | Cabin Window (Left No. 4) - Removal / Installation  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P5621001Z004                                      | 15131H2387    | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                     |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                            |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 562104           | Cabin Window (Left No. 5) - Removal / Installation  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P5621001Z004                                      | 15138H3010    | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                     |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                            |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 562105           | Cabin Window (Left No. 6) - Removal / Installation  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P5621001Z004                                      | 14288H1819    | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                     |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                            |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 562106           | Cabin Window (Left No. 7) - Removal / Installation  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P5621001Z004                                      | 15138H3009    | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                     |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                            |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 562107           | Cabin Window (Left No. 8) - Removal / Installation  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P5621001Z004                                      | 15131H2309    | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                     |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                            |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 562108           | Cabin Window (Right No. 1) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P5621001Z004                                      | 15131H2388    | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                     |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                            |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 562109           | Cabin Window (Right No. 2) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P5621001Z004                                      | 15138H3015    | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                     |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                            |               | MSC |             |                 |     | O/C              |             |                    |         |              |



| ATA<br>U=Custom                      | Description                                          |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|--------------------------------------|------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                      | Part Number                                          | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position                     | HW                                                   | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                      | MM Ref                                               |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                                      | Ops Number(s)                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 562110                               | Cabin Window (Right No. 3) - Removal / Installation  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                      | 60P5621001Z004                                       | 15134H2867    | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                      |                                                      |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                      | Airframe                                             |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 562111                               | Cabin Window (Right No. 4) - Removal / Installation  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                      | 60P5621001Z004                                       | 15138H3014    | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                      |                                                      |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                      | Airframe                                             |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 562112                               | Cabin Windows (Right No. 5) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                      | 60P5621001Z004                                       | 14295H2600    | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                      |                                                      |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                      | Airframe                                             |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 562113                               | Cabin Window (Right No. 6) - Removal / Installation  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                      | 60P5621001Z004                                       | 14247H7691    | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                      |                                                      |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                      | Airframe                                             |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 562114                               | Cabin Window (Right No. 7) - Removal / Installation  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                      | 60P5621001Z004                                       | 15138H3016    | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                      |                                                      |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                      | Airframe                                             |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 562115                               | Cabin Window (Right No. 8) - Removal / Installation  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                      | 60P5621001Z004                                       | 15132H2541    | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                      |                                                      |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                      | Airframe                                             |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 562164                               | Cabin Windows - Detailed Inspection                  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                      |                                                      |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                      |                                                      |               | MOS |             | 122             |     |                  | 11 Mar 2016 |                    |         |              |
|                                      | Airframe                                             |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| 562165                               | Cabin Windows - Leak Check                           |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                                      |                                                      |               | AFL |             | 315             |     |                  | 802         |                    |         | 0            |
|                                      |                                                      |               | MOS |             | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
|                                      | Airframe                                             |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Notes: PN: 60P562100Z004 SN: <NONE>. |                                                      |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                           |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------|---------------------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                  | Part Number                                                                           | Serial Number |                                    |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position | HW                                                                                    | SW            |                                    |             |                 |     |                  |             |                    |             | Manufacturer |
|                  | MM Ref                                                                                |               |                                    |             |                 |     |                  |             |                    |             | Date Type    |
|                  | Ops Number(s)                                                                         |               |                                    |             |                 |     |                  |             |                    |             |              |
| 562166           | Cabin Fixed Window Nonmetallic Interior Structures (Left No. 1) - Detailed Inspection |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                       |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                       |               | MOS                                |             | 122             | 19  | 200              | 11 Mar 2016 | 30 Nov 2032*       | 31 Dec 2032 |              |
|                  |                                                                                       |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                       |               |                                    |             |                 |     |                  |             |                    |             |              |
| 562167           | Cabin Fixed Window Nonmetallic Interior Structures (Left No. 2) - Detailed Inspection |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                       |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                       |               | MOS                                |             | 122             | 19  | 200              | 11 Mar 2016 | 30 Nov 2032*       | 31 Dec 2032 |              |
|                  |                                                                                       |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                       |               |                                    |             |                 |     |                  |             |                    |             |              |
| 562168           | Cabin Fixed Window Nonmetallic Interior Structures (Left No. 3) - Detailed Inspection |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                       |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                       |               | MOS                                |             | 122             | 19  | 200              | 11 Mar 2016 | 30 Nov 2032*       | 31 Dec 2032 |              |
|                  |                                                                                       |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                       |               |                                    |             |                 |     |                  |             |                    |             |              |
| 562169           | Cabin Fixed Window Nonmetallic Interior Structures (Left No. 4) - Detailed Inspection |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                       |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                       |               | MOS                                |             | 122             | 19  | 200              | 11 Mar 2016 | 30 Nov 2032*       | 31 Dec 2032 |              |
|                  |                                                                                       |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                       |               |                                    |             |                 |     |                  |             |                    |             |              |
| 562170           | Cabin Fixed Window Nonmetallic Interior Structures (Left No. 5) - Detailed Inspection |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                       |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                       |               | MOS                                |             | 122             | 19  | 200              | 11 Mar 2016 | 30 Nov 2032*       | 31 Dec 2032 |              |
|                  |                                                                                       |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                       |               |                                    |             |                 |     |                  |             |                    |             |              |
| 562171           | Cabin Fixed Window Nonmetallic Interior Structures (Left No. 6) - Detailed Inspection |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                       |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                       |               | MOS                                |             | 122             | 19  | 200              | 11 Mar 2016 | 30 Nov 2032*       | 31 Dec 2032 |              |
|                  |                                                                                       |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                       |               |                                    |             |                 |     |                  |             |                    |             |              |
| 562172           | Cabin Fixed Window Nonmetallic Interior Structures (Left No. 7) - Detailed Inspection |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                       |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                       |               | MOS                                |             | 122             | 19  | 200              | 11 Mar 2016 | 30 Nov 2032*       | 31 Dec 2032 |              |
|                  |                                                                                       |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                       |               |                                    |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom  | Description                                                                            |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------|----------------------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                  | Part Number                                                                            | Serial Number |                                    |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position | HW                                                                                     | SW            |                                    |             |                 |     |                  |             |                    |             | Manufacturer |
|                  | MM Ref                                                                                 |               |                                    |             |                 |     |                  |             |                    |             | Date Type    |
|                  | Ops Number(s)                                                                          |               |                                    |             |                 |     |                  |             |                    |             |              |
| 562173           | Cabin Fixed Window Nonmetallic Interior Structures (Left No. 8) - Detailed Inspection  |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                        |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                        |               | MOS                                |             | 122             | 19  | 200              | 11 Mar 2016 | 30 Nov 2032*       | 31 Dec 2032 |              |
|                  |                                                                                        |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                        |               |                                    |             |                 |     |                  |             |                    |             |              |
| 562174           | Cabin Fixed Window Nonmetallic Interior Structures (Right No. 1) - Detailed Inspection |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                        |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                        |               | MOS                                |             | 122             | 19  | 200              | 11 Mar 2016 | 30 Nov 2032*       | 31 Dec 2032 |              |
|                  |                                                                                        |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                        |               |                                    |             |                 |     |                  |             |                    |             |              |
| 562175           | Cabin Fixed Window Nonmetallic Interior Structures (Right No. 2) - Detailed Inspection |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                        |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                        |               | MOS                                |             | 122             | 19  | 200              | 11 Mar 2016 | 30 Nov 2032*       | 31 Dec 2032 |              |
|                  |                                                                                        |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                        |               |                                    |             |                 |     |                  |             |                    |             |              |
| 562176           | Cabin Fixed Window Nonmetallic Interior Structures (Right No. 3) - Detailed Inspection |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                        |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                        |               | MOS                                |             | 122             | 19  | 200              | 11 Mar 2016 | 30 Nov 2032*       | 31 Dec 2032 |              |
|                  |                                                                                        |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                        |               |                                    |             |                 |     |                  |             |                    |             |              |
| 562177           | Cabin Fixed Window Nonmetallic Interior Structures (Right No. 4) - Detailed Inspection |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                        |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                        |               | MOS                                |             | 122             | 19  | 200              | 11 Mar 2016 | 30 Nov 2032*       | 31 Dec 2032 |              |
|                  |                                                                                        |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                        |               |                                    |             |                 |     |                  |             |                    |             |              |
| 562178           | Cabin Fixed Window Nonmetallic Interior Structures (Right No. 5) - Detailed Inspection |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                        |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                        |               | MOS                                |             | 122             | 19  | 200              | 11 Mar 2016 | 30 Nov 2032*       | 31 Dec 2032 |              |
|                  |                                                                                        |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                        |               |                                    |             |                 |     |                  |             |                    |             |              |
| 562179           | Cabin Fixed Window Nonmetallic Interior Structures (Right No. 6) - Detailed Inspection |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                        |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                        |               | MOS                                |             | 122             | 19  | 200              | 11 Mar 2016 | 30 Nov 2032*       | 31 Dec 2032 |              |
|                  |                                                                                        |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                        |               |                                    |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom  | Description                                                                               |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------|-------------------------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                  | Part Number                                                                               | Serial Number |                                    |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position | HW                                                                                        | SW            |                                    |             |                 |     |                  |             |                    |             | Manufacturer |
|                  | MM Ref                                                                                    |               |                                    |             |                 |     |                  |             |                    |             | Date Type    |
|                  | Ops Number(s)                                                                             |               |                                    |             |                 |     |                  |             |                    |             |              |
| 562180           | Cabin Fixed Window Nonmetallic Interior Structures<br>(Right No. 7) - Detailed Inspection |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                           |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                           |               | MOS                                |             | 122             | 19  | 200              | 11 Mar 2016 | 30 Nov 2032*       | 31 Dec 2032 |              |
|                  |                                                                                           |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                           |               |                                    |             |                 |     |                  |             |                    |             |              |
| 562181           | Cabin Fixed Window Nonmetallic Interior Structures<br>(Right No. 8) - Detailed Inspection |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                           |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                           |               | MOS                                |             | 122             | 19  | 200              | 11 Mar 2016 | 30 Nov 2032*       | 31 Dec 2032 |              |
|                  |                                                                                           |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                           |               |                                    |             |                 |     |                  |             |                    |             |              |
| 562182           | Cabin Fixed Window Metallic Interior Structures (Left No.<br>1) - Detailed Inspection     |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                           |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                           |               | MOS                                |             | 122             | 19  | 200              | 11 Mar 2016 | 30 Nov 2032*       | 31 Dec 2032 |              |
|                  |                                                                                           |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                           |               |                                    |             |                 |     |                  |             |                    |             |              |
| 562183           | Cabin Fixed Window Metallic Interior Structures (Left No.<br>2) - Detailed Inspection     |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                           |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                           |               | MOS                                |             | 122             | 19  | 200              | 11 Mar 2016 | 30 Nov 2032*       | 31 Dec 2032 |              |
|                  |                                                                                           |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                           |               |                                    |             |                 |     |                  |             |                    |             |              |
| 562184           | Cabin Fixed Window Metallic Interior Structures (Left No.<br>3) - Detailed Inspection     |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                           |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                           |               | MOS                                |             | 122             | 19  | 200              | 11 Mar 2016 | 30 Nov 2032*       | 31 Dec 2032 |              |
|                  |                                                                                           |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                           |               |                                    |             |                 |     |                  |             |                    |             |              |
| 562185           | Cabin Fixed Window Metallic Interior Structures (Left No.<br>4) - Detailed Inspection     |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                           |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                           |               | MOS                                |             | 122             | 19  | 200              | 11 Mar 2016 | 30 Nov 2032*       | 31 Dec 2032 |              |
|                  |                                                                                           |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                           |               |                                    |             |                 |     |                  |             |                    |             |              |
| 562186           | Cabin Fixed Window Metallic Interior Structures (Left No.<br>5) - Detailed Inspection     |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                           |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                           |               | MOS                                |             | 122             | 19  | 200              | 11 Mar 2016 | 30 Nov 2032*       | 31 Dec 2032 |              |
|                  |                                                                                           |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                           |               |                                    |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom  | Description                                                                         |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------|-------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                  | Part Number                                                                         | Serial Number |     |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position | HW                                                                                  | SW            |     |             |                 |     |                  |             |                    |             | Manufacturer |
|                  | MM Ref                                                                              |               |     |             |                 |     |                  |             |                    |             | Date Type    |
|                  | Ops Number(s)                                                                       |               |     |             |                 |     |                  |             |                    |             |              |
| 562187           | Cabin Fixed Window Metallic Interior Structures (Left No. 6) - Detailed Inspection  |               | HRS |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                     |               | AFL |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                     |               | MOS |             | 122             | 19  | 200              | 11 Mar 2016 | 30 Nov 2032*       | 31 Dec 2032 |              |
|                  | [End Of Month Item] [MOS: +1m/-1m]                                                  |               |     |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                     |               |     |             |                 |     |                  |             |                    |             |              |
| 562188           | Cabin Fixed Window Metallic Interior Structures (Left No. 7) - Detailed Inspection  |               | HRS |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                     |               | AFL |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                     |               | MOS |             | 122             | 19  | 200              | 11 Mar 2016 | 30 Nov 2032*       | 31 Dec 2032 |              |
|                  | [End Of Month Item] [MOS: +1m/-1m]                                                  |               |     |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                     |               |     |             |                 |     |                  |             |                    |             |              |
| 562189           | Cabin Fixed Window Metallic Interior Structures (Left No. 8) - Detailed Inspection  |               | HRS |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                     |               | AFL |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                     |               | MOS |             | 122             | 19  | 200              | 11 Mar 2016 | 30 Nov 2032*       | 31 Dec 2032 |              |
|                  | [End Of Month Item] [MOS: +1m/-1m]                                                  |               |     |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                     |               |     |             |                 |     |                  |             |                    |             |              |
| 562190           | Cabin Fixed Window Metallic Interior Structures (Right No. 1) - Detailed Inspection |               | HRS |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                     |               | AFL |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                     |               | MOS |             | 122             | 19  | 200              | 11 Mar 2016 | 30 Nov 2032*       | 31 Dec 2032 |              |
|                  | [End Of Month Item] [MOS: +1m/-1m]                                                  |               |     |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                     |               |     |             |                 |     |                  |             |                    |             |              |
| 562191           | Cabin Fixed Window Metallic Interior Structures (Right No. 2) - Detailed Inspection |               | HRS |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                     |               | AFL |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                     |               | MOS |             | 122             |     | 200              | 11 Mar 2016 | 30 Nov 2032        | 31 Dec 2032 |              |
|                  | [End Of Month Item] [MOS: +1m/-1m]                                                  |               |     |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                     |               |     |             |                 |     |                  |             |                    |             |              |
| 562192           | Cabin Fixed Window Metallic Interior Structures (Right No. 3) - Detailed Inspection |               | HRS |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                     |               | AFL |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                     |               | MOS |             | 122             | 19  | 200              | 11 Mar 2016 | 30 Nov 2032*       | 31 Dec 2032 |              |
|                  | [End Of Month Item] [MOS: +1m/-1m]                                                  |               |     |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                     |               |     |             |                 |     |                  |             |                    |             |              |
| 562193           | Cabin Fixed Window Metallic Interior Structures (Right No. 4) - Detailed Inspection |               | HRS |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                     |               | AFL |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                     |               | MOS |             | 122             | 19  | 200              | 11 Mar 2016 | 30 Nov 2032*       | 31 Dec 2032 |              |
|                  | [End Of Month Item] [MOS: +1m/-1m]                                                  |               |     |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                     |               |     |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom  | Description                                                                         |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------|-------------------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                  | Part Number                                                                         | Serial Number |                                    |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position | HW                                                                                  | SW            |                                    |             |                 |     |                  |             |                    |             | Manufacturer |
|                  | MM Ref                                                                              |               |                                    |             |                 |     |                  |             |                    |             | Date Type    |
|                  | Ops Number(s)                                                                       |               |                                    |             |                 |     |                  |             |                    |             |              |
| 562194           | Cabin Fixed Window Metallic Interior Structures (Right No. 5) - Detailed Inspection |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                     |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                     |               | MOS                                |             | 122             | 19  | 200              | 11 Mar 2016 | 30 Nov 2032*       | 31 Dec 2032 |              |
|                  |                                                                                     |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                     |               |                                    |             |                 |     |                  |             |                    |             |              |
| 562195           | Cabin Fixed Window Metallic Interior Structures (Right No. 6) - Detailed Inspection |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                     |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                     |               | MOS                                |             | 122             | 19  | 200              | 11 Mar 2016 | 30 Nov 2032*       | 31 Dec 2032 |              |
|                  |                                                                                     |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                     |               |                                    |             |                 |     |                  |             |                    |             |              |
| 562196           | Cabin Fixed Window Metallic Interior Structures (Right No. 7) - Detailed Inspection |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                     |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                     |               | MOS                                |             | 122             | 19  | 200              | 11 Mar 2016 | 30 Nov 2032*       | 31 Dec 2032 |              |
|                  |                                                                                     |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                     |               |                                    |             |                 |     |                  |             |                    |             |              |
| 562197           | Cabin Fixed Window Metallic Interior Structures (Right No. 8) - Detailed Inspection |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                     |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                     |               | MOS                                |             | 122             | 19  | 200              | 11 Mar 2016 | 30 Nov 2032*       | 31 Dec 2032 |              |
|                  |                                                                                     |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                     |               |                                    |             |                 |     |                  |             |                    |             |              |
| 564000           | Primary and Auxiliary Pressure Bulkhead Viewport - Operational Check                |               | HRS                                |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                  |                                                                                     |               | AFL                                |             | 52              |     |                  | 1065        |                    |             | 0            |
|                  |                                                                                     |               | MOS                                |             | 5.3             | 51  | 24               | 01 Dec 2025 | 31 Jan 2028*       | 29 Feb 2028 |              |
|                  |                                                                                     |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                     |               |                                    |             |                 |     |                  |             |                    |             |              |
| 052011           |                                                                                     |               |                                    |             |                 |     |                  |             |                    |             |              |
| 57 - Wings       |                                                                                     |               |                                    |             |                 |     |                  |             |                    |             |              |
| 570001           | Wing Lower Cover Skins - Zonal Inspection                                           |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                     |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                     |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                     |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                     |               |                                    |             |                 |     |                  |             |                    |             |              |
| 570003           | Wing (Internal) (Left) - Zonal Inspection                                           |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                                     |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                                     |               | MOS                                |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031        | 31 Jan 2032 |              |
|                  |                                                                                     |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                     |               |                                    |             |                 |     |                  |             |                    |             |              |
| 052016           |                                                                                     |               |                                    |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom  | Description                                                                   |                                    | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(* =Adj) | Max Due     | Avg Man Hrs  |
|------------------|-------------------------------------------------------------------------------|------------------------------------|-----|-------------|-----------------|-----|------------------|-------------|----------------------|-------------|--------------|
|                  | Part Number                                                                   | Serial Number                      |     |             |                 |     |                  |             |                      |             | Approx Price |
| Logbook Position | HW                                                                            | SW                                 |     |             |                 |     |                  |             |                      |             | Manufacturer |
|                  | MM Ref                                                                        |                                    |     |             |                 |     |                  |             |                      |             | Date Type    |
|                  | Ops Number(s)                                                                 |                                    |     |             |                 |     |                  |             |                      |             |              |
| 570004           | Wing (Internal) (Right) - Zonal Inspection                                    |                                    | HRS |             | 730.5           |     |                  | 2315.6      |                      |             | 0            |
|                  |                                                                               |                                    | AFL |             | 315             |     |                  | 802         |                      |             | 0            |
|                  |                                                                               |                                    | MOS |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031          | 31 Jan 2032 |              |
| Airframe         |                                                                               | [End Of Month Item] [MOS: +1m/-1m] |     |             |                 |     |                  |             |                      |             |              |
|                  |                                                                               | 052016                             |     |             |                 |     |                  |             |                      |             |              |
| 570005           | Wing (Internal) Wiring Installations (Left) - Enhanced Zonal Inspection       |                                    | HRS |             | 730.5           |     |                  | 2315.6      |                      |             | 0            |
|                  |                                                                               |                                    | AFL |             | 315             |     |                  | 802         |                      |             | 0            |
|                  |                                                                               |                                    | MOS |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031          | 31 Jan 2032 |              |
| Airframe         |                                                                               | [End Of Month Item] [MOS: +1m/-1m] |     |             |                 |     |                  |             |                      |             |              |
|                  |                                                                               | 052016                             |     |             |                 |     |                  |             |                      |             |              |
| 570006           | Wing (Internal) Wiring Installations (Right) - Enhanced Zonal Inspection      |                                    | HRS |             | 730.5           |     |                  | 2315.6      |                      |             | 0            |
|                  |                                                                               |                                    | AFL |             | 315             |     |                  | 802         |                      |             | 0            |
|                  |                                                                               |                                    | MOS |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031          | 31 Jan 2032 |              |
| Airframe         |                                                                               | [End Of Month Item] [MOS: +1m/-1m] |     |             |                 |     |                  |             |                      |             |              |
|                  |                                                                               | 052016                             |     |             |                 |     |                  |             |                      |             |              |
| 570007           | Wing (Upper Surface External) from Wtbf to Winglet (Left) - Zonal Inspection  |                                    | HRS |             | 663.7           |     |                  | 2382.4      |                      |             | 0            |
|                  |                                                                               |                                    | AFL |             | 291             |     |                  | 826         |                      |             | 0            |
|                  |                                                                               |                                    | MOS |             | 25.5            |     | 72               | 26 Mar 2024 | 31 Mar 2030          | 30 Apr 2030 |              |
| Airframe         |                                                                               | [End Of Month Item] [MOS: +1m/-1m] |     |             |                 |     |                  |             |                      |             |              |
|                  |                                                                               | 052015                             |     |             |                 |     |                  |             |                      |             |              |
| 570008           | Wing (Upper Surface External) from Wtbf to Winglet (Right) - Zonal Inspection |                                    | HRS |             | 663.7           |     |                  | 2382.4      |                      |             | 0            |
|                  |                                                                               |                                    | AFL |             | 291             |     |                  | 826         |                      |             | 0            |
|                  |                                                                               |                                    | MOS |             | 25.5            |     | 72               | 26 Mar 2024 | 31 Mar 2030          | 30 Apr 2030 |              |
| Airframe         |                                                                               | [End Of Month Item] [MOS: +1m/-1m] |     |             |                 |     |                  |             |                      |             |              |
|                  |                                                                               | 052015                             |     |             |                 |     |                  |             |                      |             |              |
| 570009           | Wing (Lower Surface External) from Wtbf to Winglet (Left) - Zonal Inspection  |                                    | HRS |             | 137             |     |                  | 2909.1      |                      |             | 0            |
|                  |                                                                               |                                    | AFL |             | 52              |     |                  | 1065        |                      |             | 0            |
|                  |                                                                               |                                    | MOS |             | 5.2             |     | 24               | 05 Dec 2025 | 31 Dec 2027          | 31 Jan 2028 |              |
| Airframe         |                                                                               | [End Of Month Item] [MOS: +1m/-1m] |     |             |                 |     |                  |             |                      |             |              |
|                  |                                                                               | 052011                             |     |             |                 |     |                  |             |                      |             |              |
| 570010           | Wing (Lower Surface External) from Wtbf to Winglet (Right) - Zonal Inspection |                                    | HRS |             | 137             |     |                  | 2909.1      |                      |             | 0            |
|                  |                                                                               |                                    | AFL |             | 52              |     |                  | 1065        |                      |             | 0            |
|                  |                                                                               |                                    | MOS |             | 5.2             |     | 24               | 05 Dec 2025 | 31 Dec 2027          | 31 Jan 2028 |              |
| Airframe         |                                                                               | [End Of Month Item] [MOS: +1m/-1m] |     |             |                 |     |                  |             |                      |             |              |
|                  |                                                                               | 052011                             |     |             |                 |     |                  |             |                      |             |              |

| ATA<br>U=Custom  | Description                                                                              |               | UOM    | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------|------------------------------------------------------------------------------------------|---------------|--------|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                  | Part Number                                                                              | Serial Number |        |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position | HW                                                                                       | SW            |        |             |                 |     |                  |             |                    |             | Manufacturer |
|                  | MM Ref                                                                                   |               |        |             |                 |     |                  |             |                    |             | Date Type    |
|                  | Ops Number(s)                                                                            |               |        |             |                 |     |                  |             |                    |             |              |
| 570011           | Wing (External) Flaps, Spoilers and Ailerons (Left) - Zonal Inspection                   |               | HRS    |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                  |                                                                                          |               | AFL    |             | 52              |     |                  | 1065        |                    |             | 0            |
|                  |                                                                                          |               | MOS    |             | 5.2             |     | 24               | 05 Dec 2025 | 31 Dec 2027        | 31 Jan 2028 |              |
|                  | [End Of Month Item] [MOS: +1m/-1m]                                                       |               |        |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                          |               | 052011 |             |                 |     |                  |             |                    |             |              |
| 570012           | Wing (External) Flaps, Spoilers and Ailerons (Right) - Zonal Inspection                  |               | HRS    |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                  |                                                                                          |               | AFL    |             | 52              |     |                  | 1065        |                    |             | 0            |
|                  |                                                                                          |               | MOS    |             | 5.2             |     | 24               | 05 Dec 2025 | 31 Dec 2027        | 31 Jan 2028 |              |
|                  | [End Of Month Item] [MOS: +1m/-1m]                                                       |               |        |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                          |               | 052011 |             |                 |     |                  |             |                    |             |              |
| 571016           | Wing - Removal / Installation<br>60P5700000A001                                          |               | HRS    |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                          |               | AFL    |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                          |               | MOS    |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  | Airframe                                                                                 |               |        | MSC<br>O/C  |                 |     |                  |             |                    |             |              |
| 571021           | Wing Forward Spar Splices (External) Surfaces (Left) - Detailed Inspection               |               | HRS    |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                          |               | AFL    |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                          |               | MOS    |             | 122             |     | 192              | 11 Mar 2016 | 31 Mar 2032        | 30 Apr 2032 |              |
|                  | [End Of Month Item] [MOS: +1m/-1m]                                                       |               |        |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                          |               | 052021 |             |                 |     |                  |             |                    |             |              |
| 571022           | Wing Forward Spar Splices (External) Surfaces (Right) - Detailed Inspection              |               | HRS    |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                          |               | AFL    |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                          |               | MOS    |             | 122             |     | 192              | 11 Mar 2016 | 31 Mar 2032        | 30 Apr 2032 |              |
|                  | [End Of Month Item] [MOS: +1m/-1m]                                                       |               |        |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                          |               | 052021 |             |                 |     |                  |             |                    |             |              |
| 571023           | Wing Aft, Spars, Splices and Spar Cans (External) Surfaces (Left) - Detailed Inspection  |               | HRS    |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                          |               | AFL    |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                          |               | MOS    |             | 122             |     | 144              | 11 Mar 2016 | 31 Mar 2028        | 30 Apr 2028 |              |
|                  | [End Of Month Item] [MOS: +1m/-1m]                                                       |               |        |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                          |               | 052019 |             |                 |     |                  |             |                    |             |              |
| 571024           | Wing Aft, Spars, Splices and Spar Cans (External) Surfaces (Right) - Detailed Inspection |               | HRS    |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                          |               | AFL    |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                          |               | MOS    |             | 122             |     | 144              | 11 Mar 2016 | 31 Mar 2028        | 30 Apr 2028 |              |
|                  | [End Of Month Item] [MOS: +1m/-1m]                                                       |               |        |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                          |               | 052019 |             |                 |     |                  |             |                    |             |              |



| ATA<br>U=Custom  | Description                                                                  |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------|------------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                  | Part Number                                                                  | Serial Number |                                    |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position | HW                                                                           | SW            |                                    |             |                 |     |                  |             |                    |             | Manufacturer |
|                  | MM Ref                                                                       |               |                                    |             |                 |     |                  |             |                    |             | Date Type    |
|                  | Ops Number(s)                                                                |               |                                    |             |                 |     |                  |             |                    |             |              |
| 571025           | Wing Aft Spar Splices (External) Surfaces (Left) - Detailed Inspection       |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                              |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                              |               | MOS                                |             | 122             |     | 144              | 11 Mar 2016 | 31 Mar 2028        | 30 Apr 2028 |              |
|                  |                                                                              |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                              | 052019        |                                    |             |                 |     |                  |             |                    |             |              |
| 571026           | Wing Aft Spar Splices (External) Surfaces (Right) - Detailed Inspection      |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                              |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                              |               | MOS                                |             | 122             |     | 144              | 11 Mar 2016 | 31 Mar 2028        | 30 Apr 2028 |              |
|                  |                                                                              |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                              | 052019        |                                    |             |                 |     |                  |             |                    |             |              |
| 571027           | Wing Tank (Internal) BI 0 - Rbs 135 (Left) - Detailed Inspection             |               | HRS                                |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                  |                                                                              |               | AFL                                |             | 52              |     |                  | 1065        |                    |             | 0            |
|                  |                                                                              |               | MOS                                |             | 5               | 44  | 24               | 12 Dec 2025 | 31 Jan 2028*       | 29 Feb 2028 |              |
|                  |                                                                              |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                              | 052011        |                                    |             |                 |     |                  |             |                    |             |              |
| 571028           | Wing Tank (Internal) BI 0 - Rbs 135 (Right) - Detailed Inspection            |               | HRS                                |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                  |                                                                              |               | AFL                                |             | 52              |     |                  | 1065        |                    |             | 0            |
|                  |                                                                              |               | MOS                                |             | 5               | 45  | 24               | 12 Dec 2025 | 31 Jan 2028*       | 29 Feb 2028 |              |
|                  |                                                                              |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                              | 052011        |                                    |             |                 |     |                  |             |                    |             |              |
| 571029           | Wing Tank Internal Rbs 135 - Ws 551 (Left) - Detailed Inspection             |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                              |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                              |               | MOS                                |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031        | 31 Jan 2032 |              |
|                  |                                                                              |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                              | 052016        |                                    |             |                 |     |                  |             |                    |             |              |
| 571030           | Wing Tank Internal Rbs 135 - Ws 551 (Right) - Detailed Inspection            |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                              |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                              |               | MOS                                |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031        | 31 Jan 2032 |              |
|                  |                                                                              |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                              | 052016        |                                    |             |                 |     |                  |             |                    |             |              |
| 571031           | Main Landing Gear Sponsons and Support Fittings (Left) - Detailed Inspection |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                              |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                              |               | MOS                                |             | 28.7            |     | 48               | 21 Dec 2023 | 31 Dec 2027        | 31 Jan 2028 |              |
|                  |                                                                              |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                              | 052013        |                                    |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom  | Description                                                                                       |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------|---------------------------------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                  | Part Number                                                                                       | Serial Number |                                    |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position | HW                                                                                                | SW            |                                    |             |                 |     |                  |             |                    |             | Manufacturer |
|                  | MM Ref                                                                                            |               |                                    |             |                 |     |                  |             |                    |             | Date Type    |
|                  | Ops Number(s)                                                                                     |               |                                    |             |                 |     |                  |             |                    |             |              |
| 571032           | Main Landing Gear Sponsons and Support Fittings (Right)<br>- Detailed Inspection                  |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                                                   |               | AFL                                |             | 315             |     |                  | 802         |                    | 0           |              |
|                  |                                                                                                   |               | MOS                                |             | 28.7            |     | 48               | 21 Dec 2023 | 31 Dec 2027        | 31 Jan 2028 |              |
|                  |                                                                                                   |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                                   |               | 052013                             |             |                 |     |                  |             |                    |             |              |
| 571033           | Sponson Beam, Main Landing Gear (Left) - Removal /<br>Installation<br>60P3215105M006-01A000124    |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                   |               | AFL                                |             | 1117            |     |                  | 0           |                    | 0           |              |
|                  |                                                                                                   |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                                   |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                                   |               |                                    |             |                 |     |                  |             |                    |             |              |
| 571034           | Sponson Beam, Main Landing Gear (Right) - Removal /<br>Installation<br>60P3215106M008-02A000140   |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                   |               | AFL                                |             | 1117            |     |                  | 0           |                    | 0           |              |
|                  |                                                                                                   |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                                   |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                                   |               |                                    |             |                 |     |                  |             |                    |             |              |
| 571035           | Main Landing Gear Sponson Bores (With Main Landing<br>Gear Removed) (Left) - Detailed Inspection  |               | HRS                                |             | 1735.8          |     |                  | 1310.3      |                    |             | 0            |
|                  |                                                                                                   |               | AFL                                |             | 729             |     |                  | 388         |                    | 0           |              |
|                  |                                                                                                   |               | MOS                                |             | 75.2            |     | 144              | 05 Feb 2020 | 29 Feb 2032        | 31 Mar 2032 |              |
|                  |                                                                                                   |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                                   |               | 052019                             |             |                 |     |                  |             |                    |             |              |
| 571036           | Main Landing Gear Sponson Bores (With Main Landing<br>Gear Removed) (Right) - Detailed Inspection |               | HRS                                |             | 1735.8          |     |                  | 1310.3      |                    |             | 0            |
|                  |                                                                                                   |               | AFL                                |             | 729             |     |                  | 388         |                    | 0           |              |
|                  |                                                                                                   |               | MOS                                |             | 75.2            |     | 144              | 05 Feb 2020 | 29 Feb 2032        | 31 Mar 2032 |              |
|                  |                                                                                                   |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                                   |               | 052019                             |             |                 |     |                  |             |                    |             |              |
| 571040           | BI 34 Rib (Left) - Ndt Inspection                                                                 |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                   |               | AFL                                |             | 1117            |     | 13510**          | 0           | 13510              |             | 0            |
|                  |                                                                                                   |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                                   |               |                                    |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                                   |               |                                    |             |                 |     |                  |             |                    |             |              |
| 571041           | BI 34 Rib (Right) - Ndt Inspection                                                                |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                   |               | AFL                                |             | 1117            |     | 13510**          | 0           | 13510              |             | 0            |
|                  |                                                                                                   |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                                   |               |                                    |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                                   |               |                                    |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom                    | Description                                                                       |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------------------------|-----------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                                    | Part Number                                                                       | Serial Number |     |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position                   | HW                                                                                | SW            |     |             |                 |     |                  |             |                    |             | Manufacturer |
|                                    | MM Ref                                                                            |               |     |             |                 |     |                  |             |                    |             | Date Type    |
|                                    | Ops Number(s)                                                                     |               |     |             |                 |     |                  |             |                    |             |              |
| 571044                             | Sponson Outboard Beam (Left) - Ndt Inspection                                     |               | HRS |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                                    |                                                                                   |               | AFL |             | 1117            |     | 12710**          | 0           | 12710              |             | 0            |
|                                    |                                                                                   |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
| Airframe                           |                                                                                   |               |     |             |                 |     |                  |             |                    |             |              |
| 571045                             | Sponson Outboard Beam (Right) - Ndt Inspection                                    |               | HRS |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                                    |                                                                                   |               | AFL |             | 1117            |     | 12710**          | 0           | 12710              |             | 0            |
|                                    |                                                                                   |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
| Airframe                           |                                                                                   |               |     |             |                 |     |                  |             |                    |             |              |
| 571200                             | Wing Rear Beam Wiring Harness Installation (Left) -<br>Enhanced Zonal Inspection  |               | HRS |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                                    |                                                                                   |               | AFL |             | 52              |     |                  | 1065        |                    |             | 0            |
|                                    |                                                                                   |               | MOS |             | 5.3             |     | 24               | 01 Dec 2025 | 31 Dec 2027        | 31 Jan 2028 |              |
| [End Of Month Item] [MOS: +1m/-1m] |                                                                                   |               |     |             |                 |     |                  |             |                    |             |              |
| Airframe                           |                                                                                   |               |     |             |                 |     |                  |             |                    |             |              |
| 052011                             |                                                                                   |               |     |             |                 |     |                  |             |                    |             |              |
| 571201                             | Wing Rear Beam Wiring Harness Installation (Right) -<br>Enhanced Zonal Inspection |               | HRS |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                                    |                                                                                   |               | AFL |             | 52              |     |                  | 1065        |                    |             | 0            |
|                                    |                                                                                   |               | MOS |             | 5.3             |     | 24               | 01 Dec 2025 | 31 Dec 2027        | 31 Jan 2028 |              |
| [End Of Month Item] [MOS: +1m/-1m] |                                                                                   |               |     |             |                 |     |                  |             |                    |             |              |
| Airframe                           |                                                                                   |               |     |             |                 |     |                  |             |                    |             |              |
| 052011                             |                                                                                   |               |     |             |                 |     |                  |             |                    |             |              |
| 571202                             | Wing Drain Holes (Left) - Enhanced Zonal Inspection                               |               | HRS |             | 663.7           |     |                  | 2382.4      |                    |             | 0            |
|                                    |                                                                                   |               | AFL |             | 291             |     |                  | 826         |                    |             | 0            |
|                                    |                                                                                   |               | MOS |             | 25.5            |     |                  | 26 Mar 2024 |                    |             |              |
| Airframe                           |                                                                                   |               |     |             |                 |     |                  |             |                    |             |              |
| O/C                                |                                                                                   |               |     |             |                 |     |                  |             |                    |             |              |
| 571203                             | Wing Drain Holes (Right) - Enhanced Zonal Inspection                              |               | HRS |             | 663.7           |     |                  | 2382.4      |                    |             | 0            |
|                                    |                                                                                   |               | AFL |             | 291             |     |                  | 826         |                    |             | 0            |
|                                    |                                                                                   |               | MOS |             | 25.5            |     |                  | 26 Mar 2024 |                    |             |              |
| Airframe                           |                                                                                   |               |     |             |                 |     |                  |             |                    |             |              |
| O/C                                |                                                                                   |               |     |             |                 |     |                  |             |                    |             |              |
| 571204                             | Wing Rear Beam Spar and Aileron (Left) - Zonal<br>Inspection                      |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                                    |                                                                                   |               | AFL |             | 315             |     |                  | 802         |                    |             | 0            |
|                                    |                                                                                   |               | MOS |             | 28.7            |     | 48               | 21 Dec 2023 | 31 Dec 2027        | 31 Jan 2028 |              |
| [End Of Month Item] [MOS: +1m/-1m] |                                                                                   |               |     |             |                 |     |                  |             |                    |             |              |
| Airframe                           |                                                                                   |               |     |             |                 |     |                  |             |                    |             |              |
| 052013                             |                                                                                   |               |     |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom  | Description                                                              |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------|--------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                  | Part Number                                                              | Serial Number |                                    |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position | HW                                                                       | SW            |                                    |             |                 |     |                  |             |                    |             | Manufacturer |
|                  | MM Ref                                                                   |               |                                    |             |                 |     |                  |             |                    |             | Date Type    |
|                  | Ops Number(s)                                                            |               |                                    |             |                 |     |                  |             |                    |             |              |
| 571205           | Wing Rear Beam Spar and Aileron (Right) - Zonal Inspection               |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                          |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                          |               | MOS                                |             | 28.7            |     | 48               | 21 Dec 2023 | 31 Dec 2027        | 31 Jan 2028 |              |
|                  |                                                                          |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                          | 052013        |                                    |             |                 |     |                  |             |                    |             |              |
| 571206           | Wing Rear Spar / Flap / Spoiler (Left) - Zonal Inspection                |               | HRS                                |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                  |                                                                          |               | AFL                                |             | 52              |     |                  | 1065        |                    |             | 0            |
|                  |                                                                          |               | MOS                                |             | 5.3             |     | 24               | 01 Dec 2025 | 31 Dec 2027        | 31 Jan 2028 |              |
|                  |                                                                          |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                          | 052011        |                                    |             |                 |     |                  |             |                    |             |              |
| 571207           | Wing Rear Spar / Flap / Spoiler (Right) - Zonal Inspection               |               | HRS                                |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                  |                                                                          |               | AFL                                |             | 52              |     |                  | 1065        |                    |             | 0            |
|                  |                                                                          |               | MOS                                |             | 5.3             |     | 24               | 01 Dec 2025 | 31 Dec 2027        | 31 Jan 2028 |              |
|                  |                                                                          |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                          | 052011        |                                    |             |                 |     |                  |             |                    |             |              |
| 571208           | Wing Rear Beam Rbs 135.66 - Rbs 441 Hirf/L (Left) - Detailed Inspection  |               | HRS                                |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                  |                                                                          |               | AFL                                |             | 52              |     |                  | 1065        |                    |             | 0            |
|                  |                                                                          |               | MOS                                |             | 5.3             |     | 24               | 02 Dec 2025 | 31 Dec 2027        | 31 Jan 2028 |              |
|                  |                                                                          |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                          | 052011        |                                    |             |                 |     |                  |             |                    |             |              |
| 571209           | Wing Rear Beam Rbs 135.66 - Rbs 441 Hirf/L (Right) - Detailed Inspection |               | HRS                                |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                  |                                                                          |               | AFL                                |             | 52              |     |                  | 1065        |                    |             | 0            |
|                  |                                                                          |               | MOS                                |             | 5.3             |     | 24               | 02 Dec 2025 | 31 Dec 2027        | 31 Jan 2028 |              |
|                  |                                                                          |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                          | 052011        |                                    |             |                 |     |                  |             |                    |             |              |
| 571210           | Wing Rear Beam Rbs 441 - Rbs 534 Hirf/L (Left) - Detailed Inspection     |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                          |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                          |               | MOS                                |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031        | 31 Jan 2032 |              |
|                  |                                                                          |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                          | 052016        |                                    |             |                 |     |                  |             |                    |             |              |
| 571211           | Wing Rear Beam Rbs 441 - Rbs 534 Hirf/L (Right) - Detailed Inspection    |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                          |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                          |               | MOS                                |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031        | 31 Jan 2032 |              |
|                  |                                                                          |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                          | 052016        |                                    |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom  | Description                                                                |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                         | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                     |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                              |               |     |             |                 |     |                  |             |                    |         |              |
| 571214           | Rear Spar AT Sponson Attachment (Left) - Ndt Inspection                    |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                            |               | AFL |             | 1117            |     | 3655**           | 0           | 3655               |         | 0            |
|                  |                                                                            |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe         |                                                                            |               |     |             |                 |     |                  |             |                    |         |              |
| 571215           | Rear Spar AT Sponson Attachment (Right) - Ndt Inspection                   |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                            |               | AFL |             | 1117            |     | 3655**           | 0           | 3655               |         | 0            |
|                  |                                                                            |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe         |                                                                            |               |     |             |                 |     |                  |             |                    |         |              |
| 571218           | Rear Spar AT BI 49 Attachment Fitting (Left) - Ndt Inspection              |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                            |               | AFL |             | 1117            |     | 14325**          | 0           | 14325              |         | 0            |
|                  |                                                                            |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe         |                                                                            |               |     |             |                 |     |                  |             |                    |         |              |
| 571219           | Rear Spar AT BI 49 Attachment Fitting (Right) - Ndt Inspection             |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                            |               | AFL |             | 1117            |     | 14325**          | 0           | 14325              |         | 0            |
|                  |                                                                            |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe         |                                                                            |               |     |             |                 |     |                  |             |                    |         |              |
| 571222           | Rear Spar AT Main Landing Gear Side Brace Fitting (Left) - Ndt Inspection  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                            |               | AFL |             | 1117            |     | 14325**          | 0           | 14325              |         | 0            |
|                  |                                                                            |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe         |                                                                            |               |     |             |                 |     |                  |             |                    |         |              |
| 571223           | Rear Spar AT Main Landing Gear Side Brace Fitting (Right) - Ndt Inspection |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                            |               | AFL |             | 1117            |     | 14325**          | 0           | 14325              |         | 0            |
|                  |                                                                            |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe         |                                                                            |               |     |             |                 |     |                  |             |                    |         |              |
| 571307           | Sponson Lower Skin AT Rear Spar Attach (Left) - Ndt Inspection             |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                            |               | AFL |             | 1117            |     | 14450**          | 0           | 14450              |         | 0            |
|                  |                                                                            |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe         |                                                                            |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom                    | Description                                                                                                         |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------------------------|---------------------------------------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                                    | Part Number                                                                                                         | Serial Number |     |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position                   | HW                                                                                                                  | SW            |     |             |                 |     |                  |             |                    |             | Manufacturer |
|                                    | MM Ref                                                                                                              |               |     |             |                 |     |                  |             |                    |             | Date Type    |
|                                    | Ops Number(s)                                                                                                       |               |     |             |                 |     |                  |             |                    |             |              |
| 571308                             | Sponson Lower Skin AT Rear Spar Attach (Right) - Ndt Inspection                                                     |               | HRS |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                                    |                                                                                                                     |               | AFL |             | 1117            |     | 14450**          | 0           | 14450              |             | 0            |
|                                    |                                                                                                                     |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
| Airframe                           |                                                                                                                     |               |     |             |                 |     |                  |             |                    |             |              |
| 052015                             |                                                                                                                     |               |     |             |                 |     |                  |             |                    |             |              |
| 571600                             | Wing to Fuselage, Floor Support and Wtbf Fittings (Left) - Detailed Inspection                                      |               | HRS |             | 1300.7          |     |                  | 1745.4      |                    |             | 0            |
|                                    |                                                                                                                     |               | AFL |             | 507             |     |                  | 610         |                    |             | 0            |
|                                    |                                                                                                                     |               | MOS |             | 51.7            |     | 72               | 21 Jan 2022 | 31 Jan 2028        | 29 Feb 2028 |              |
| [End Of Month Item] [MOS: +1m/-1m] |                                                                                                                     |               |     |             |                 |     |                  |             |                    |             |              |
| Airframe                           |                                                                                                                     |               |     |             |                 |     |                  |             |                    |             |              |
| 052015                             |                                                                                                                     |               |     |             |                 |     |                  |             |                    |             |              |
| 571601                             | Wing to Fuselage, Floor Support and Wtbf Fittings (Right) - Detailed Inspection                                     |               | HRS |             | 1300.7          |     |                  | 1745.4      |                    |             | 0            |
|                                    |                                                                                                                     |               | AFL |             | 507             |     |                  | 610         |                    |             | 0            |
|                                    |                                                                                                                     |               | MOS |             | 51.7            |     | 72               | 21 Jan 2022 | 31 Jan 2028        | 29 Feb 2028 |              |
| [End Of Month Item] [MOS: +1m/-1m] |                                                                                                                     |               |     |             |                 |     |                  |             |                    |             |              |
| Airframe                           |                                                                                                                     |               |     |             |                 |     |                  |             |                    |             |              |
| 052015                             |                                                                                                                     |               |     |             |                 |     |                  |             |                    |             |              |
| 571602                             | Fitting, Wing to Fuselage-Aft Torque Box (Left) - Removal / Installation<br>60P5700131M008-01A      09534DD-12-1-10 |               | HRS |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                                    |                                                                                                                     |               | AFL |             | 1117            |     |                  | 0           |                    |             | 0            |
|                                    |                                                                                                                     |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
| MSC<br>O/C                         |                                                                                                                     |               |     |             |                 |     |                  |             |                    |             |              |
| Airframe                           |                                                                                                                     |               |     |             |                 |     |                  |             |                    |             |              |
| 571603                             | Fitting, Wing to Fuselage-Aft Torque Box (Right) - Removal / Installation<br>60P5700132M006-02A      10036DD-12-2-2 |               | HRS |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                                    |                                                                                                                     |               | AFL |             | 1117            |     |                  | 0           |                    |             | 0            |
|                                    |                                                                                                                     |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
| MSC<br>O/C                         |                                                                                                                     |               |     |             |                 |     |                  |             |                    |             |              |
| Airframe                           |                                                                                                                     |               |     |             |                 |     |                  |             |                    |             |              |
| 571606                             | FS 529 Vertical Fitting - Ndt Inspection                                                                            |               | HRS |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                                    |                                                                                                                     |               | AFL |             | 1117            |     | 14410**          | 0           | 14410              |             | 0            |
|                                    |                                                                                                                     |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
| Airframe                           |                                                                                                                     |               |     |             |                 |     |                  |             |                    |             |              |
| 571607                             | BI 49 Drag Fitting - Ndt Inspection                                                                                 |               | HRS |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                                    |                                                                                                                     |               | AFL |             | 1117            |     | 6205**           | 0           | 6205               |             | 0            |
|                                    |                                                                                                                     |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
| Airframe                           |                                                                                                                     |               |     |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom  | Description                                                                  |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------|------------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                  | Part Number                                                                  | Serial Number |                                    |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position | HW                                                                           | SW            |                                    |             |                 |     |                  |             |                    |             | Manufacturer |
|                  | MM Ref                                                                       |               |                                    |             |                 |     |                  |             |                    |             | Date Type    |
|                  | Ops Number(s)                                                                |               |                                    |             |                 |     |                  |             |                    |             |              |
| 571900           | Wing to Wing Mate (External) Splices and Skegs (Left) - Detailed Inspection  |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                              |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                              |               | MOS                                |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031        | 31 Jan 2032 |              |
|                  |                                                                              |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                              |               | 052016                             |             |                 |     |                  |             |                    |             |              |
| 571901           | Wing to Wing Mate (External) Splices and Skegs (Right) - Detailed Inspection |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                              |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                              |               | MOS                                |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031        | 31 Jan 2032 |              |
|                  |                                                                              |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                              |               | 052016                             |             |                 |     |                  |             |                    |             |              |
| 571904           | Front Spar Splice AT BI 103 (Left) - Ndt Inspection                          |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                              |               | AFL                                |             | 1117            |     | 15250**          | 0           | 15250              |             | 0            |
|                  |                                                                              |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                              |               |                                    |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                              |               |                                    |             |                 |     |                  |             |                    |             |              |
| 571905           | Front Spar Splice AT BI 103 (Right) - Ndt Inspection                         |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                              |               | AFL                                |             | 1117            |     | 15250**          | 0           | 15250              |             | 0            |
|                  |                                                                              |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                              |               |                                    |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                              |               |                                    |             |                 |     |                  |             |                    |             |              |
| 571907           | Rear Spar Rbs 150 Splice (Left) - Ndt Inspection                             |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                              |               | AFL                                |             | 1117            |     | 8610**           | 0           | 8610               |             | 0            |
|                  |                                                                              |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                              |               |                                    |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                              |               |                                    |             |                 |     |                  |             |                    |             |              |
| 571908           | Rear Spar Rbs 150 Splice (Right) - Ndt Inspection                            |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                              |               | AFL                                |             | 1117            |     | 8610**           | 0           | 8610               |             | 0            |
|                  |                                                                              |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                              |               |                                    |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                              |               |                                    |             |                 |     |                  |             |                    |             |              |
| 571910           | Lower Cover Splice Stringers (Left) - Visual Inspection                      |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                              |               | AFL                                |             | 1117            |     | 10200**          | 0           | 10200              |             | 0            |
|                  |                                                                              |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                              |               |                                    |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                              |               |                                    |             |                 |     |                  |             |                    |             |              |
| 571911           | Lower Cover Splice Stringers (Right) - Visual Inspection                     |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                              |               | AFL                                |             | 1117            |     | 10200**          | 0           | 10200              |             | 0            |
|                  |                                                                              |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                              |               |                                    |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                              |               |                                    |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom                    | Description                                                                                 |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------------------------|---------------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                                    | Part Number                                                                                 | Serial Number |     |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position                   | HW                                                                                          | SW            |     |             |                 |     |                  |             |                    |             | Manufacturer |
|                                    | MM Ref                                                                                      |               |     |             |                 |     |                  |             |                    |             | Date Type    |
|                                    | Ops Number(s)                                                                               |               |     |             |                 |     |                  |             |                    |             |              |
| 571912                             | Lower Cover Coaming Stringers (Left) - Visual Inspection                                    |               | HRS |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                                    |                                                                                             |               | AFL |             | 1117            |     | 16870**          | 0           | 16870              |             | 0            |
|                                    |                                                                                             |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
| Airframe                           |                                                                                             |               |     |             |                 |     |                  |             |                    |             |              |
| 571913                             | Lower Cover Coaming Stringers (Right) - Visual Inspection                                   |               | HRS |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                                    |                                                                                             |               | AFL |             | 1117            |     | 16870**          | 0           | 16870              |             | 0            |
|                                    |                                                                                             |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
| Airframe                           |                                                                                             |               |     |             |                 |     |                  |             |                    |             |              |
| 571915                             | BI 0 Splice AT Front Spar - Ndt Inspecton                                                   |               | HRS |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                                    |                                                                                             |               | AFL |             | 1117            |     | 15250**          | 0           | 15250              |             | 0            |
|                                    |                                                                                             |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
| Airframe                           |                                                                                             |               |     |             |                 |     |                  |             |                    |             |              |
| 571917                             | BI 0 Splice AT Rear Spar - Ndt Inspecton                                                    |               | HRS |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                                    |                                                                                             |               | AFL |             | 1117            |     | 8610**           | 0           | 8610               |             | 0            |
|                                    |                                                                                             |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
| Airframe                           |                                                                                             |               |     |             |                 |     |                  |             |                    |             |              |
| 572000                             | Lightning Ignition Source Protection Feature - Detailed Inspection                          |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                                    |                                                                                             |               | AFL |             | 315             |     |                  | 802         |                    |             | 0            |
|                                    |                                                                                             |               | MOS |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031        | 31 Jan 2032 |              |
| [End Of Month Item] [MOS: +1m/-1m] |                                                                                             |               |     |             |                 |     |                  |             |                    |             |              |
| Airframe                           |                                                                                             |               |     |             |                 |     |                  |             |                    |             |              |
| 573200                             | Winglet (Left) - Removal / Installation<br>60P5730011A009-01A                      TIG130L  |               | HRS |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                                    |                                                                                             |               | AFL |             | 1117            |     |                  | 0           |                    |             | 0            |
|                                    |                                                                                             |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
| Airframe                           |                                                                                             |               |     |             |                 |     |                  |             |                    |             |              |
| 573201                             | Winglet (Right) - Removal / Installation<br>60P5730012A010-02A                      TIG133R |               | HRS |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                                    |                                                                                             |               | AFL |             | 1117            |     |                  | 0           |                    |             | 0            |
|                                    |                                                                                             |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
| Airframe                           |                                                                                             |               |     |             |                 |     |                  |             |                    |             |              |
| 573203                             | Winglet Leading Edge (Right) - Polishing                                                    |               | HRS |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                                    |                                                                                             |               | AFL |             | 52              |     |                  | 1065        |                    |             | 0            |
|                                    |                                                                                             |               | MOS |             | 4.7             | -23 | 6                | 19 Dec 2025 | 27 May 2026*       | 27 Jun 2026 |              |
| Airframe                           |                                                                                             |               |     |             |                 |     |                  |             |                    |             |              |
| [MOS: +1m/-1m]                     |                                                                                             |               |     |             |                 |     |                  |             |                    |             |              |



| ATA<br>U=Custom  | Description                                                                                             |               | UOM | Times Since                        | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------|---------------------------------------------------------------------------------------------------------|---------------|-----|------------------------------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                  | Part Number                                                                                             | Serial Number |     |                                    |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position | HW                                                                                                      | SW            |     |                                    |                 |     |                  |             |                    |             | Manufacturer |
|                  | MM Ref                                                                                                  |               |     |                                    |                 |     |                  |             |                    |             | Date Type    |
|                  | Ops Number(s)                                                                                           |               |     |                                    |                 |     |                  |             |                    |             |              |
| 573204           | Winglet (Internal) (Left) - Zonal Inspection                                                            |               | HRS |                                    | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                         |               | AFL |                                    | 1117            |     |                  | 0           |                    | 0           |              |
|                  |                                                                                                         |               | MOS |                                    | 122             |     | 192              | 11 Mar 2016 | 31 Mar 2032        | 30 Apr 2032 |              |
|                  | Airframe                                                                                                | 052021        |     | [End Of Month Item] [MOS: +1m/-1m] |                 |     |                  |             |                    |             |              |
| 573205           | Winglet (Internal) (Right) - Zonal Inspection                                                           |               | HRS |                                    | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                         |               | AFL |                                    | 1117            |     |                  | 0           |                    | 0           |              |
|                  |                                                                                                         |               | MOS |                                    | 122             |     | 192              | 11 Mar 2016 | 31 Mar 2032        | 30 Apr 2032 |              |
|                  | Airframe                                                                                                | 052021        |     | [End Of Month Item] [MOS: +1m/-1m] |                 |     |                  |             |                    |             |              |
| 573206           | Winglet Exterior Surfaces (Left) - Zonal Inspection                                                     |               | HRS |                                    | 663.7           |     |                  | 2382.4      |                    |             | 0            |
|                  |                                                                                                         |               | AFL |                                    | 291             |     |                  | 826         |                    | 0           |              |
|                  |                                                                                                         |               | MOS |                                    | 25.5            |     | 72               | 26 Mar 2024 | 31 Mar 2030        | 30 Apr 2030 |              |
|                  | Airframe                                                                                                | 052015        |     | [End Of Month Item] [MOS: +1m/-1m] |                 |     |                  |             |                    |             |              |
| 573207           | Winglet Exterior Surfaces (Right) - Zonal Inspection                                                    |               | HRS |                                    | 663.7           |     |                  | 2382.4      |                    |             | 0            |
|                  |                                                                                                         |               | AFL |                                    | 291             |     |                  | 826         |                    | 0           |              |
|                  |                                                                                                         |               | MOS |                                    | 25.5            |     | 72               | 26 Mar 2024 | 31 Mar 2030        | 30 Apr 2030 |              |
|                  | Airframe                                                                                                | 052015        |     | [End Of Month Item] [MOS: +1m/-1m] |                 |     |                  |             |                    |             |              |
| 573212           | Wing Kit (Left) - Removal / Installation<br>1007-3342N001-005      SN-UNKNOWN                           |               | HRS |                                    | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                         |               | AFL |                                    | 1117            |     |                  | 0           |                    | 0           |              |
|                  |                                                                                                         |               | MOS |                                    | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                                         |               | MSC |                                    |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                                         |               |     |                                    |                 |     |                  |             |                    |             |              |
| 573213           | Wing Kit (Right) - Removal / Installation<br>1007-3342N001-006      SN-UNKNOWN                          |               | HRS |                                    | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                         |               | AFL |                                    | 1117            |     |                  | 0           |                    | 0           |              |
|                  |                                                                                                         |               | MOS |                                    | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                                         |               | MSC |                                    |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                                         |               |     |                                    |                 |     |                  |             |                    |             |              |
| 574000           | Wing Inboard Leading Edge Assembly (Left) - Removal /<br>Installation<br>60P5740031-001      177        |               | HRS |                                    | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                                                         |               | AFL |                                    | 315             |     |                  | 802         |                    | 0           |              |
|                  |                                                                                                         |               | MOS |                                    | 29.1            |     |                  | 07 Dec 2023 |                    |             |              |
|                  |                                                                                                         |               | MSC |                                    |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                                         |               |     |                                    |                 |     |                  |             |                    |             |              |
| 574001           | Wing Inboard Center Leading Edge Assembly (Left) -<br>Removal / Installation<br>60P5740033-001      159 |               | HRS |                                    | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                                                         |               | AFL |                                    | 315             |     |                  | 802         |                    | 0           |              |
|                  |                                                                                                         |               | MOS | TSN:7                              | 28.7            |     |                  | 21 Dec 2023 |                    |             |              |
|                  |                                                                                                         |               | MSC |                                    |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                                         |               |     |                                    |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom  | Description                                                                    |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|--------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                    | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                             | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                         |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                                  |               |     |             |                 |     |                  |             |                    |         |              |
| 574002           | Wing Inboard Center Mid Leading Edge Assembly (Left) - Removal / Installation  |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  |                                                                                |               | AFL |             | 315             |     |                  | 802         |                    |         | 0            |
|                  | 60P5740035-001                                                                 | 641           | MOS | TSN:1       | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
|                  |                                                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| 574003           | Wing Outboard Center Leading Edge Assembly (Left) - Removal / Installation     |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  |                                                                                |               | AFL |             | 315             |     |                  | 802         |                    |         | 0            |
|                  | 60P5740037-001                                                                 | 095           | MOS | TSN:8       | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
|                  |                                                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| 574004           | Wing Outboard Leading Edge Assembly (Left) - Removal / Installation            |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  |                                                                                |               | AFL |             | 315             |     |                  | 802         |                    |         | 0            |
|                  | 60P5740039-001                                                                 | 182           | MOS |             | 29.6            |     |                  | 23 Nov 2023 |                    |         |              |
|                  |                                                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| 574005           | Wing Inboard Leading Edge Assembly (Right) - Removal / Installation            |               | HRS | TSN:2315.58 | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  |                                                                                |               | AFL | TSN:802     | 315             |     |                  | 802         |                    |         | 0            |
|                  | 60P5740032-001                                                                 | 177           | MOS | TSN:100     | 29.1            |     |                  | 07 Dec 2023 |                    |         |              |
|                  |                                                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| 574006           | Wing Inboard Center Leading Edge Assembly (Right) - Removal / Installation     |               | HRS | TSN:2315.58 | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  |                                                                                |               | AFL | TSN:802     | 315             |     |                  | 802         |                    |         | 0            |
|                  | 60P5740034-001                                                                 | 190           | MOS | TSN:100     | 29.1            |     |                  | 07 Dec 2023 |                    |         |              |
|                  |                                                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| 574007           | Wing Inboard Center Mid Leading Edge Assembly (Right) - Removal / Installation |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  |                                                                                |               | AFL |             | 315             |     |                  | 802         |                    |         | 0            |
|                  | 60P5740036-001                                                                 | 201           | MOS |             | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
|                  |                                                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| 574008           | Wing Outboard Center Leading Edge Assembly (Right) - Removal / Installation    |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  |                                                                                |               | AFL |             | 315             |     |                  | 802         |                    |         | 0            |
|                  | 60P5740038-001                                                                 | 653           | MOS |             | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
|                  |                                                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------|----------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                  | Part Number                                                                | Serial Number |                                    |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position | HW                                                                         | SW            |                                    |             |                 |     |                  |             |                    |             | Manufacturer |
|                  | MM Ref                                                                     |               |                                    |             |                 |     |                  |             |                    |             | Date Type    |
|                  | Ops Number(s)                                                              |               |                                    |             |                 |     |                  |             |                    |             |              |
| 574009           | Wing Outboard Leading Edge Assembly (Right) - Removal / Installation       |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                            |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  | 60P5740040-001                                                             | 458           | MOS                                |             | 28.7            |     |                  | 21 Dec 2023 |                    |             |              |
|                  |                                                                            |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                            |               |                                    |             |                 |     |                  |             |                    |             |              |
| 574010           | Wing Leading Edge - Polishing                                              |               | HRS                                |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                  |                                                                            |               | AFL                                |             | 52              |     |                  | 1065        |                    |             | 0            |
|                  |                                                                            |               | MOS                                |             | 4.7             | -23 | 6                | 19 Dec 2025 | 31 May 2026*       | 30 Jun 2026 |              |
|                  |                                                                            |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                            |               |                                    |             |                 |     |                  |             |                    |             |              |
| 574011           | Wing Leading Edge (Right) - Polishing                                      |               | HRS                                |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                  |                                                                            |               | AFL                                |             | 52              |     |                  | 1065        |                    |             | 0            |
|                  |                                                                            |               | MOS                                |             | 4.7             | -23 | 6                | 19 Dec 2025 | 31 May 2026*       | 30 Jun 2026 |              |
|                  |                                                                            |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                            |               |                                    |             |                 |     |                  |             |                    |             |              |
| 574020           | Wing Leading Edge Wiring Installations (Left) - Enhanced Zonal Inspection  |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                            |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                            |               | MOS                                |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031        | 31 Jan 2032 |              |
|                  |                                                                            |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                            |               |                                    |             |                 |     |                  |             |                    |             |              |
| 052016           |                                                                            |               |                                    |             |                 |     |                  |             |                    |             |              |
| 574021           | Wing Leading Edge Wiring Installations (Right) - Enhanced Zonal Inspection |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                            |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                            |               | MOS                                |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031        | 31 Jan 2032 |              |
|                  |                                                                            |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                            |               |                                    |             |                 |     |                  |             |                    |             |              |
| 052016           |                                                                            |               |                                    |             |                 |     |                  |             |                    |             |              |
| 574022           | Wing Leading Edge (Internal) (Left) - Zonal Inspection                     |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                            |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                            |               | MOS                                |             | 122             |     | 192              | 11 Mar 2016 | 31 Mar 2032        | 30 Apr 2032 |              |
|                  |                                                                            |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                            |               |                                    |             |                 |     |                  |             |                    |             |              |
| 052021           |                                                                            |               |                                    |             |                 |     |                  |             |                    |             |              |
| 574023           | Wing Leading Edge (Internal) (Right) - Zonal Inspection                    |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                            |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                            |               | MOS                                |             | 122             |     | 192              | 11 Mar 2016 | 31 Mar 2032        | 30 Apr 2032 |              |
|                  |                                                                            |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                            |               |                                    |             |                 |     |                  |             |                    |             |              |
| 052021           |                                                                            |               |                                    |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom  | Description                                                                                              |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------|----------------------------------------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                  | Part Number                                                                                              | Serial Number |                                    |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position | HW                                                                                                       | SW            |                                    |             |                 |     |                  |             |                    |             | Manufacturer |
|                  | MM Ref                                                                                                   |               |                                    |             |                 |     |                  |             |                    |             | Date Type    |
|                  | Ops Number(s)                                                                                            |               |                                    |             |                 |     |                  |             |                    |             |              |
| 574024           | Wing Leading Edge With Gap Bands Removed (Left) -<br>Zonal Inspection                                    |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                                                          |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                                                          |               | MOS                                |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031        | 31 Jan 2032 |              |
|                  |                                                                                                          |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                                          | 052016        |                                    |             |                 |     |                  |             |                    |             |              |
| 574025           | Wing Leading Edge With Gap Bands Removed (Right) -<br>Zonal Inspection                                   |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                                                          |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                                                          |               | MOS                                |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031        | 31 Jan 2032 |              |
|                  |                                                                                                          |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                                          | 052016        |                                    |             |                 |     |                  |             |                    |             |              |
| 574026           | Wing Leading Edge and Gap Bands (External) (Left) -<br>Zonal Inspection                                  |               | HRS                                |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                  |                                                                                                          |               | AFL                                |             | 52              |     |                  | 1065        |                    |             | 0            |
|                  |                                                                                                          |               | MOS                                |             | 5.2             |     | 24               | 05 Dec 2025 | 31 Dec 2027        | 31 Jan 2028 |              |
|                  |                                                                                                          |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                                          | 052011        |                                    |             |                 |     |                  |             |                    |             |              |
| 574027           | Wing Leading Edge and Gap Bands (External) (Right) -<br>Zonal Inspection                                 |               | HRS                                |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                  |                                                                                                          |               | AFL                                |             | 52              |     |                  | 1065        |                    |             | 0            |
|                  |                                                                                                          |               | MOS                                |             | 5.2             |     | 24               | 05 Dec 2025 | 31 Dec 2027        | 31 Jan 2028 |              |
|                  |                                                                                                          |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                                          | 052011        |                                    |             |                 |     |                  |             |                    |             |              |
| 574032           | Blend Plenum Panel (Left) - Removal / Installation<br>60P5740417A001L01                      SN-UNKNOWN  |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                          |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                          |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                                          |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                                          |               |                                    |             |                 |     |                  |             |                    |             |              |
| 574033           | Blend Plenum Panel (Right) - Removal / Installation<br>60P5740418A003L01                      SN-UNKNOWN |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                          |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                          |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                                          |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                                          |               |                                    |             |                 |     |                  |             |                    |             |              |
| 574036           | Gap Band 01 (Left) - Removal / Installation<br>60P5740471A005-01A                      NSN               |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                                                          |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                                                          |               | MOS                                |             | 30.6            |     |                  | 22 Oct 2023 |                    |             |              |
|                  |                                                                                                          |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                                          |               |                                    |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom  | Description                                  |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                  | Serial Number |     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                           | SW            |     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                       |               |     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                |               |     |             |                 |     |                  |             |                     |         |              |
| 574037           | Gap Band 01 (Right) - Removal / Installation |               | HRS |             | 730.5           |     |                  | 2315.6      |                     |         | 0            |
|                  | 60P5740475A005-02A                           | SN-UNKNOWN    | AFL |             | 315             |     |                  | 802         |                     |         | 0            |
|                  |                                              |               | MOS |             | 30.6            |     |                  | 22 Oct 2023 |                     |         |              |
|                  | Airframe                                     |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| 574038           | Gap Band 02 (Left) - Removal / Installation  |               | HRS |             | 730.5           |     |                  | 2315.6      |                     |         | 0            |
|                  | 60P5740471A005-01A                           | NSN           | AFL |             | 315             |     |                  | 802         |                     |         | 0            |
|                  |                                              |               | MOS |             | 30.6            |     |                  | 22 Oct 2023 |                     |         |              |
|                  | Airframe                                     |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| 574039           | Gap Band 02 (Right) - Removal / Installation |               | HRS |             | 730.5           |     |                  | 2315.6      |                     |         | 0            |
|                  | 60P5740474A005-02A                           | SN-UNKNOWN    | AFL |             | 315             |     |                  | 802         |                     |         | 0            |
|                  |                                              |               | MOS |             | 30.6            |     |                  | 22 Oct 2023 |                     |         |              |
|                  | Airframe                                     |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| 574040           | Gap Band 03 (Left) - Removal / Installation  |               | HRS |             | 730.5           |     |                  | 2315.6      |                     |         | 0            |
|                  | 60P5740475A006-01A                           | NSN           | AFL |             | 315             |     |                  | 802         |                     |         | 0            |
|                  |                                              |               | MOS |             | 30.6            |     |                  | 22 Oct 2023 |                     |         |              |
|                  | Airframe                                     |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| 574041           | Gap Band 03 (Right) - Removal / Installation |               | HRS |             | 730.5           |     |                  | 2315.6      |                     |         | 0            |
|                  | 60P5740476A005-02A                           | SN-UNKNOWN    | AFL |             | 315             |     |                  | 802         |                     |         | 0            |
|                  |                                              |               | MOS |             | 30.6            |     |                  | 22 Oct 2023 |                     |         |              |
|                  | Airframe                                     |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| 574042           | Gap Band 04 (Left) - Removal / Installation  |               | HRS |             | 730.5           |     |                  | 2315.6      |                     |         | 0            |
|                  | 60P5740477A006-01A                           | NSN           | AFL |             | 315             |     |                  | 802         |                     |         | 0            |
|                  |                                              |               | MOS |             | 30.6            |     |                  | 22 Oct 2023 |                     |         |              |
|                  | Airframe                                     |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| 574043           | Gap Band 04 (Right) - Removal / Installation |               | HRS |             | 730.5           |     |                  | 2315.6      |                     |         | 0            |
|                  | 60P5740478A008-02A                           | SN-UNKNOWN    | AFL |             | 315             |     |                  | 802         |                     |         | 0            |
|                  |                                              |               | MOS |             | 30.6            |     |                  | 22 Oct 2023 |                     |         |              |
|                  | Airframe                                     |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| 574044           | Gap Band 05 (Left) - Removal / Installation  |               | HRS |             | 730.5           |     |                  | 2315.6      |                     |         | 0            |
|                  | 60P5740481A003-01A                           | NSN           | AFL |             | 315             |     |                  | 802         |                     |         | 0            |
|                  |                                              |               | MOS |             | 30.6            |     |                  | 22 Oct 2023 |                     |         |              |
|                  | Airframe                                     |               | MSC |             |                 |     | O/C              |             |                     |         |              |

| ATA<br>U=Custom  | Description                                                                           |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------|---------------------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                  | Part Number                                                                           | Serial Number |                                    |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position | HW                                                                                    | SW            |                                    |             |                 |     |                  |             |                    |             | Manufacturer |
|                  | MM Ref                                                                                |               |                                    |             |                 |     |                  |             |                    |             | Date Type    |
|                  | Ops Number(s)                                                                         |               |                                    |             |                 |     |                  |             |                    |             |              |
| 574045           | Gap Band 05 (Right) - Removal / Installation                                          |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  | 60P5740482A003-02A                                                                    | SN-UNKNOWN    | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                                       |               | MOS                                |             | 30.6            |     |                  | 22 Oct 2023 |                    |             |              |
|                  | Airframe                                                                              |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| 575006           | Wing Trailing Edge Box (Interior) (Left) - Zonal Inspection                           |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                                       |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                                       |               | MOS                                |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031        | 31 Jan 2032 |              |
|                  | Airframe                                                                              |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
|                  | 052016                                                                                |               |                                    |             |                 |     |                  |             |                    |             |              |
| 575007           | Wing Trailing Edge Box (Interior) (Right) - Zonal Inspection                          |               | HRS                                |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                  |                                                                                       |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                                       |               | MOS                                |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031        | 31 Jan 2032 |              |
|                  | Airframe                                                                              |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
|                  | 052016                                                                                |               |                                    |             |                 |     |                  |             |                    |             |              |
| 575008           | Wing Flight Control Attach Fittings (Left) - Detailed Inspection                      |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                       |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                       |               | MOS                                |             | 122             |     | 144              | 11 Mar 2016 | 31 Mar 2028        | 30 Apr 2028 |              |
|                  | Airframe                                                                              |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
|                  | 052019                                                                                |               |                                    |             |                 |     |                  |             |                    |             |              |
| 575009           | Wing Flight Control Attach Fittings (Right) - Detailed Inspection                     |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                       |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                       |               | MOS                                |             | 122             |     | 144              | 11 Mar 2016 | 31 Mar 2028        | 30 Apr 2028 |              |
|                  | Airframe                                                                              |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
|                  | 052019                                                                                |               |                                    |             |                 |     |                  |             |                    |             |              |
| 575010           | Inboard / Outboard Fixed Trailing Edges and Cove Panels (Left) - Detailed Inspection  |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                       |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                       |               | MOS                                |             | 122             |     | 144              | 11 Mar 2016 | 31 Mar 2028        | 30 Apr 2028 |              |
|                  | Airframe                                                                              |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
|                  | 052019                                                                                |               |                                    |             |                 |     |                  |             |                    |             |              |
| 575011           | Inboard / Outboard Fixed Trailing Edges and Cove Panels (Right) - Detailed Inspection |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                       |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                       |               | MOS                                |             | 122             |     | 144              | 11 Mar 2016 | 31 Mar 2028        | 30 Apr 2028 |              |
|                  | Airframe                                                                              |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
|                  | 052019                                                                                |               |                                    |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom  | Description                                                                                            |               | UOM | Times Since                        | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------|--------------------------------------------------------------------------------------------------------|---------------|-----|------------------------------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                  | Part Number                                                                                            | Serial Number |     |                                    |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position | HW                                                                                                     | SW            |     |                                    |                 |     |                  |             |                    |             | Manufacturer |
|                  | MM Ref                                                                                                 |               |     |                                    |                 |     |                  |             |                    |             | Date Type    |
|                  | Ops Number(s)                                                                                          |               |     |                                    |                 |     |                  |             |                    |             |              |
| 575301           | Flap Upper Surface (Left) - Detailed Inspection                                                        |               | HRS |                                    | 137             |     |                  | 2909.1      |                    |             | 0            |
|                  |                                                                                                        |               | AFL |                                    | 52              |     |                  | 1065        |                    |             | 0            |
|                  |                                                                                                        |               | MOS |                                    | 5.2             |     | 24               | 05 Dec 2025 | 31 Dec 2027        | 31 Jan 2028 |              |
|                  | Airframe                                                                                               | 052011        |     | [End Of Month Item] [MOS: +1m/-1m] |                 |     |                  |             |                    |             |              |
| 575302           | Flap Upper Surface (Right) - Detailed Inspection                                                       |               | HRS |                                    | 137             |     |                  | 2909.1      |                    |             | 0            |
|                  |                                                                                                        |               | AFL |                                    | 52              |     |                  | 1065        |                    |             | 0            |
|                  |                                                                                                        |               | MOS |                                    | 5.2             |     | 24               | 05 Dec 2025 | 31 Dec 2027        | 31 Jan 2028 |              |
|                  | Airframe                                                                                               | 052011        |     | [End Of Month Item] [MOS: +1m/-1m] |                 |     |                  |             |                    |             |              |
| 575307           | Flap Fittings (Left) - Detailed Inspection                                                             |               | HRS |                                    | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                        |               | AFL |                                    | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                        |               | MOS |                                    | 122             |     | 144              | 11 Mar 2016 | 31 Mar 2028        | 30 Apr 2028 |              |
|                  | Airframe                                                                                               | 052019        |     | [End Of Month Item] [MOS: +1m/-1m] |                 |     |                  |             |                    |             |              |
| 575308           | Flap Fittings (Right) - Detailed Inspection                                                            |               | HRS |                                    | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                        |               | AFL |                                    | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                        |               | MOS |                                    | 122             |     | 144              | 11 Mar 2016 | 31 Mar 2028        | 30 Apr 2028 |              |
|                  | Airframe                                                                                               | 052019        |     | [End Of Month Item] [MOS: +1m/-1m] |                 |     |                  |             |                    |             |              |
| 575309           | Flap Track Fitting A (Left Upper) - Removal / Installation<br>60P5755231M003-01A      A0936-1-11 0134  |               | HRS |                                    | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                        |               | AFL |                                    | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                        |               | MOS |                                    | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                                        |               | MSC |                                    |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                                        |               |     |                                    |                 |     |                  |             |                    |             |              |
| 575310           | Flap Track Fitting A (Left Lower) - Removal / Installation<br>60P5755233M005-01A      229152-2-29 0159 |               | HRS |                                    | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                        |               | AFL |                                    | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                        |               | MOS |                                    | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                                        |               | MSC |                                    |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                                        |               |     |                                    |                 |     |                  |             |                    |             |              |
| 575311           | Flap Track Fitting B (Left Upper) - Removal / Installation<br>60P5755235M001-01A      M19062-02        |               | HRS |                                    | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                        |               | AFL |                                    | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                        |               | MOS |                                    | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                                        |               | MSC |                                    |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                                        |               |     |                                    |                 |     |                  |             |                    |             |              |
| 575312           | Flap Track Fitting B (Left Lower) - Removal / Installation<br>60P5755237M003-01A      229197-1-35 0155 |               | HRS |                                    | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                        |               | AFL |                                    | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                        |               | MOS |                                    | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                                        |               | MSC |                                    |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                                        |               |     |                                    |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom  | Description                                                 |                  | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-------------------------------------------------------------|------------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                 | Serial Number    |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                          | SW               |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                      |                  |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                               |                  |     |             |                 |     |                  |             |                    |         |              |
| 575313           | Flap Track Fitting C (Left Upper) - Removal / Installation  |                  | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P5755239M001-01A                                          | 229197-1-44 0142 | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                             |                  | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                    |                  | MSC |             |                 |     | O/C              |             |                    |         |              |
| 575314           | Flap Track Fitting C (Left Lower) - Removal / Installation  |                  | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P5755241M003-01A                                          | A0936-1-61 0133  | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                             |                  | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                    |                  | MSC |             |                 |     | O/C              |             |                    |         |              |
| 575315           | Flap Track Fitting D (Left Upper) - Removal / Installation  |                  | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P5755243M001-01A                                          | H18646-0011      | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                             |                  | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                    |                  | MSC |             |                 |     | O/C              |             |                    |         |              |
| 575317           | Flap Track Fitting A (Right Upper) - Removal / Installation |                  | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P5755232M001-02A                                          | A0936-1-80 0125  | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                             |                  | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                    |                  | MSC |             |                 |     | O/C              |             |                    |         |              |
| 575318           | Flap Track Fitting A (Right Lower) - Removal / Installation |                  | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P5755234M003-02A                                          | M19061-03        | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                             |                  | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                    |                  | MSC |             |                 |     | O/C              |             |                    |         |              |
| 575319           | Flap Track Fitting B (Right Upper) - Removal / Installation |                  | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P5755236M002-02A                                          | M20214-03        | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                             |                  | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                    |                  | MSC |             |                 |     | O/C              |             |                    |         |              |
| 575320           | Flap Track Fitting B (Right Lower) - Removal / Installation |                  | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P5755238M003-02A                                          | M19065-04        | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                             |                  | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                    |                  | MSC |             |                 |     | O/C              |             |                    |         |              |
| 575321           | Flap Track Fitting C (Right Upper) - Removal / Installation |                  | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P5755240M001-02A                                          | 229197-1-51 0152 | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                             |                  | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                    |                  | MSC |             |                 |     | O/C              |             |                    |         |              |



| ATA<br>U=Custom  | Description                                                 |                         | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-------------------------------------------------------------|-------------------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                 | Serial Number           |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                          | SW                      |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                      |                         |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                               |                         |     |             |                 |     |                  |             |                    |         |              |
| 575322           | Flap Track Fitting C (Right Lower) - Removal / Installation |                         | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P5755242M001-02A                                          | 229097-1-24 0115        | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                             |                         | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                    |                         | MSC |             |                 |     | O/C              |             |                    |         |              |
| 575323           | Flap Track Fitting D (Right Upper) - Removal / Installation |                         | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P5755244M001-02A                                          | H18646-0009             | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                             |                         | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                    |                         | MSC |             |                 |     | O/C              |             |                    |         |              |
| 575340           | Flaptrack A (Left) - Removal / Installation                 |                         | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P5755211M005-900                                          | J064620-229590-3-1-1-1  | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                             |                         | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                    |                         | MSC |             |                 |     | O/C              |             |                    |         |              |
| 575341           | Flaptrack A (Right) - Removal / Installation                |                         | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P5755212M003-900                                          | J056248-09 K L-1-13-1-2 | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                             |                         | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                    |                         | MSC |             |                 |     | O/C              |             |                    |         |              |
| 575342           | Flaptrack B (Left) - Removal / Installation                 |                         | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P5755213M007-900                                          | J064806-229709-2-7-1-2  | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                             |                         | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                    |                         | MSC |             |                 |     | O/C              |             |                    |         |              |
| 575343           | Flaptrack B (Right) - Removal / Installation                |                         | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P5755214M005-900                                          | J064790-229199-1-4-1-2  | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                             |                         | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                    |                         | MSC |             |                 |     | O/C              |             |                    |         |              |
| 575344           | Flaptrack C (Left) - Removal / Installation                 |                         | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P5755215M007-900                                          | M18284-01               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                             |                         | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                    |                         | MSC |             |                 |     | O/C              |             |                    |         |              |
| 575345           | Flaptrack C (Right) - Removal / Installation                |                         | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P5755216M005-900                                          | M18288--31-04           | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                             |                         | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                    |                         | MSC |             |                 |     | O/C              |             |                    |         |              |

| ATA<br>U=Custom  | Description                                           |                        | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-------------------------------------------------------|------------------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                           | Serial Number          |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                    | SW                     |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                |                        |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                         |                        |     |             |                 |     |                  |             |                    |         |              |
| 575346           | Flaptrack D (Left) - Removal / Installation           |                        | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P5755217M005-900                                    | J062385-229149-3-9-1-1 | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                       |                        | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                              |                        | MSC |             |                 |     | O/C              |             |                    |         |              |
| 575347           | Flaptrack D (Right) - Removal / Installation          |                        | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P5755218M003-900                                    | J065056-229408-1-2-1-1 | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                       |                        | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                              |                        | MSC |             |                 |     | O/C              |             |                    |         |              |
| 575360           | Flap Track A (Left) - Ndt Inspection                  |                        | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                       |                        | AFL |             | 1117            |     | 5050**           | 0           | 5050               |         | 0            |
|                  |                                                       |                        | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                              |                        |     |             |                 |     |                  |             |                    |         |              |
| 575361           | Flap Track A (Right) - Ndt Inspection                 |                        | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                       |                        | AFL |             | 1117            |     | 5050**           | 0           | 5050               |         | 0            |
|                  |                                                       |                        | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                              |                        |     |             |                 |     |                  |             |                    |         |              |
| 575364           | Flap Track A Attach Fittings (Left) - Ndt Inspection  |                        | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                       |                        | AFL |             | 1117            |     | 11680**          | 0           | 11680              |         | 0            |
|                  |                                                       |                        | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                              |                        |     |             |                 |     |                  |             |                    |         |              |
| 575365           | Flap Track A Attach Fittings (Right) - Ndt Inspection |                        | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                       |                        | AFL |             | 1117            |     | 11680**          | 0           | 11680              |         | 0            |
|                  |                                                       |                        | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                              |                        |     |             |                 |     |                  |             |                    |         |              |
| 575367           | Flap Track B (Left) - Ndt Inspection                  |                        | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                       |                        | AFL |             | 1117            |     | 7355**           | 0           | 7355               |         | 0            |
|                  |                                                       |                        | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                              |                        |     |             |                 |     |                  |             |                    |         |              |
| 575368           | Flap Track B (Right) - Ndt Inspection                 |                        | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                       |                        | AFL |             | 1117            |     | 7355**           | 0           | 7355               |         | 0            |
|                  |                                                       |                        | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                              |                        |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                           |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                           | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                    | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                         |               |     |             |                 |     |                  |             |                    |         |              |
| 575369           | Flap Track B Lugs (Left) - Ndt Inspection             |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                       |               | AFL |             | 1117            |     | 5505**           | 0           | 5505               | 0       |              |
|                  |                                                       |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe         |                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| 575370           | Flap Track B Lugs (Right) - Ndt Inspection            |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                       |               | AFL |             | 1117            |     | 5505**           | 0           | 5505               | 0       |              |
|                  |                                                       |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe         |                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| 575371           | Flap Track B Attach Fittings (Left) - Ndt Inspection  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                       |               | AFL |             | 1117            |     | 5410**           | 0           | 5410               | 0       |              |
|                  |                                                       |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe         |                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| 575372           | Flap Track B Attach Fittings (Right) - Ndt Inspection |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                       |               | AFL |             | 1117            |     | 5410**           | 0           | 5410               | 0       |              |
|                  |                                                       |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe         |                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| 575374           | Flap Track C (Left) - Ndt Inspection                  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                       |               | AFL |             | 1117            |     | 4815**           | 0           | 4815               | 0       |              |
|                  |                                                       |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe         |                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| 575375           | Flap Track C (Right) - Ndt Inspection                 |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                       |               | AFL |             | 1117            |     | 4815**           | 0           | 4815               | 0       |              |
|                  |                                                       |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe         |                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| 575376           | Flap Track C Lugs (Left) - Ndt Inspection             |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                       |               | AFL |             | 1117            |     | 5905**           | 0           | 5905               | 0       |              |
|                  |                                                       |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe         |                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| 575377           | Flap Track C Lugs (Right) - Ndt Inspection            |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                       |               | AFL |             | 1117            |     | 5905**           | 0           | 5905               | 0       |              |
|                  |                                                       |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
| Airframe         |                                                       |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom                    | Description                                                           |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------------------------|-----------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                                    | Part Number                                                           | Serial Number |     |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position                   | HW                                                                    | SW            |     |             |                 |     |                  |             |                    |             | Manufacturer |
|                                    | MM Ref                                                                |               |     |             |                 |     |                  |             |                    |             | Date Type    |
|                                    | Ops Number(s)                                                         |               |     |             |                 |     |                  |             |                    |             |              |
| 575378                             | Flap Track C Attach Fittings (Left) - Ndt Inspection                  |               | HRS |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                                    |                                                                       |               | AFL |             | 1117            |     | 6835**           | 0           | 6835               |             | 0            |
|                                    |                                                                       |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
| Airframe                           |                                                                       |               |     |             |                 |     |                  |             |                    |             |              |
| 575379                             | Flap Track C Attach Fittings (Right) - Ndt Inspection                 |               | HRS |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                                    |                                                                       |               | AFL |             | 1117            |     | 6835**           | 0           | 6835               |             | 0            |
|                                    |                                                                       |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
| Airframe                           |                                                                       |               |     |             |                 |     |                  |             |                    |             |              |
| 575381                             | Flap Track D (Left) - Ndt Inspection                                  |               | HRS |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                                    |                                                                       |               | AFL |             | 1117            |     | 6495**           | 0           | 6495               |             | 0            |
|                                    |                                                                       |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
| Airframe                           |                                                                       |               |     |             |                 |     |                  |             |                    |             |              |
| 575382                             | Flap Track D (Right) - Ndt Inspection                                 |               | HRS |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                                    |                                                                       |               | AFL |             | 1117            |     | 6495**           | 0           | 6495               |             | 0            |
|                                    |                                                                       |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
| Airframe                           |                                                                       |               |     |             |                 |     |                  |             |                    |             |              |
| 575383                             | Flap Track D Attach Fittings (Left) - Ndt Inspection                  |               | HRS |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                                    |                                                                       |               | AFL |             | 1117            |     | 12315**          | 0           | 12315              |             | 0            |
|                                    |                                                                       |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
| Airframe                           |                                                                       |               |     |             |                 |     |                  |             |                    |             |              |
| 575384                             | Flap Track D Attach Fittings (Right) - Ndt Inspection                 |               | HRS |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                                    |                                                                       |               | AFL |             | 1117            |     | 12315**          | 0           | 12315              |             | 0            |
|                                    |                                                                       |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
| Airframe                           |                                                                       |               |     |             |                 |     |                  |             |                    |             |              |
| 576000                             | Aileron Hinge Fittings and Forward Spar (Left) - Detailed Inspection  |               | HRS |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                                    |                                                                       |               | AFL |             | 1117            |     |                  | 0           |                    |             | 0            |
|                                    |                                                                       |               | MOS |             | 122             |     | 144              | 11 Mar 2016 | 31 Mar 2028        | 30 Apr 2028 |              |
| [End Of Month Item] [MOS: +1m/-1m] |                                                                       |               |     |             |                 |     |                  |             |                    |             |              |
| Airframe                           |                                                                       |               |     |             |                 |     |                  |             |                    |             |              |
| 052019                             |                                                                       |               |     |             |                 |     |                  |             |                    |             |              |
| 576001                             | Aileron Hinge Fittings and Forward Spar (Right) - Detailed Inspection |               | HRS |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                                    |                                                                       |               | AFL |             | 1117            |     |                  | 0           |                    |             | 0            |
|                                    |                                                                       |               | MOS |             | 122             |     | 144              | 11 Mar 2016 | 31 Mar 2028        | 30 Apr 2028 |              |
| [End Of Month Item] [MOS: +1m/-1m] |                                                                       |               |     |             |                 |     |                  |             |                    |             |              |
| Airframe                           |                                                                       |               |     |             |                 |     |                  |             |                    |             |              |
| 052019                             |                                                                       |               |     |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom                      | Description                                               |                                    | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|--------------------------------------|-----------------------------------------------------------|------------------------------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                                      | Part Number                                               | Serial Number                      |     |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position                     | HW                                                        | SW                                 |     |             |                 |     |                  |             |                    |             | Manufacturer |
|                                      | MM Ref                                                    |                                    |     |             |                 |     |                  |             |                    |             | Date Type    |
|                                      | Ops Number(s)                                             |                                    |     |             |                 |     |                  |             |                    |             |              |
| 577000                               | Spoiler Hinge Fittings (Left) - Detailed Inspection       |                                    | HRS |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                                      |                                                           |                                    | AFL |             | 1117            |     |                  | 0           |                    | 0           |              |
|                                      |                                                           |                                    | MOS |             | 122             |     | 144              | 11 Mar 2016 | 31 Mar 2028        | 30 Apr 2028 |              |
|                                      | Airframe                                                  | [End Of Month Item] [MOS: +1m/-1m] |     |             |                 |     |                  |             |                    |             |              |
|                                      | 052019                                                    |                                    |     |             |                 |     |                  |             |                    |             |              |
| 577001                               | Spoiler Hinge Fittings (Right) - Detailed Inspection      |                                    | HRS |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                                      |                                                           |                                    | AFL |             | 1117            |     |                  | 0           |                    | 0           |              |
|                                      |                                                           |                                    | MOS |             | 122             |     | 144              | 11 Mar 2016 | 31 Mar 2028        | 30 Apr 2028 |              |
|                                      | Airframe                                                  | [End Of Month Item] [MOS: +1m/-1m] |     |             |                 |     |                  |             |                    |             |              |
|                                      | 052019                                                    |                                    |     |             |                 |     |                  |             |                    |             |              |
| 577002                               | Spoiler Panels (Left) - Detailed Inspection               |                                    | HRS |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                                      |                                                           |                                    | AFL |             | 315             |     |                  | 802         |                    | 0           |              |
|                                      |                                                           |                                    | MOS |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031        | 31 Jan 2032 |              |
|                                      | Airframe                                                  | [End Of Month Item] [MOS: +1m/-1m] |     |             |                 |     |                  |             |                    |             |              |
|                                      | 052016                                                    |                                    |     |             |                 |     |                  |             |                    |             |              |
| 577003                               | Spoiler Panels (Right) - Detailed Inspection              |                                    | HRS |             | 730.5           |     |                  | 2315.6      |                    |             | 0            |
|                                      |                                                           |                                    | AFL |             | 315             |     |                  | 802         |                    | 0           |              |
|                                      |                                                           |                                    | MOS |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031        | 31 Jan 2032 |              |
|                                      | Airframe                                                  | [End Of Month Item] [MOS: +1m/-1m] |     |             |                 |     |                  |             |                    |             |              |
|                                      | 052016                                                    |                                    |     |             |                 |     |                  |             |                    |             |              |
| 71 - Power Plant                     |                                                           |                                    |     |             |                 |     |                  |             |                    |             |              |
| 710001                               | Engine (Left) - Removal / Installation<br>BR700-725A1-12  |                                    | HRS |             | 994.4           |     |                  | 2051.7      |                    |             | 0            |
|                                      |                                                           |                                    | AFL | 26163       | 392             |     |                  | 725         |                    | 0           |              |
|                                      |                                                           |                                    | MOS |             | 40.9            |     |                  | 15 Dec 2022 |                    |             |              |
|                                      | Airframe                                                  | MSC                                |     |             |                 |     | O/C              |             |                    |             |              |
| Notes: ENGINE DECLARED TASK ORIENTED |                                                           |                                    |     |             |                 |     |                  |             |                    |             |              |
| 710002                               | Engine (Right) - Removal / Installation<br>BR700-725A1-12 |                                    | HRS |             | 994.4           |     |                  | 2051.7      |                    |             | 0            |
|                                      |                                                           |                                    | AFL | 26162       | 392             |     |                  | 725         |                    | 0           |              |
|                                      |                                                           |                                    | MOS |             | 40.9            |     |                  | 15 Dec 2022 |                    |             |              |
|                                      | Airframe                                                  | MSC                                |     |             |                 |     | O/C              |             |                    |             |              |
| Notes: ENGINE DECLARED TASK ORIENTED |                                                           |                                    |     |             |                 |     |                  |             |                    |             |              |
| 710005                               | No. 1 Engine - Powerplant - N2 Overspeed                  |                                    | HRS |             | 994.4           |     |                  | 0           |                    |             | 0            |
|                                      |                                                           |                                    | ENC |             | 392             |     |                  | 0           |                    | 0           |              |
|                                      |                                                           |                                    | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |             |              |
|                                      | Engine                                                    | MSC                                |     |             |                 |     | O/C              |             |                    |             |              |
| [End Of Month Item]                  |                                                           |                                    |     |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom  | Description                                                      |                     | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------------------------------|---------------------|-----|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                                      | Serial Number       |     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                               | SW                  |     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                           |                     |     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                                    |                     |     |             |                 |     |                  |             |                     |         |              |
| 710005           | No. 2 Engine - Powerplant - N2 Overspeed                         |                     | HRS |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                  |                     | ENC |             | 392             |     |                  | 0           |                     | 0       |              |
|                  |                                                                  |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                  |                     | MSC |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                           | [End Of Month Item] |     |             |                 |     |                  |             |                     |         |              |
| 710006           | No. 1 Engine - Powerplant - N1 Overspeed In Forward Thrust       |                     | HRS |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                  |                     | ENC |             | 392             |     |                  | 0           |                     | 0       |              |
|                  |                                                                  |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                  |                     | MSC |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                           | [End Of Month Item] |     |             |                 |     |                  |             |                     |         |              |
| 710006           | No. 2 Engine - Powerplant - N1 Overspeed In Forward Thrust       |                     | HRS |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                  |                     | ENC |             | 392             |     |                  | 0           |                     | 0       |              |
|                  |                                                                  |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                  |                     | MSC |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                           | [End Of Month Item] |     |             |                 |     |                  |             |                     |         |              |
| 710007           | No. 1 Engine - Powerplant - N1 Overspeed In Reverse Thrust       |                     | HRS |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                  |                     | ENC |             | 392             |     |                  | 0           |                     | 0       |              |
|                  |                                                                  |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                  |                     | MSC |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                           | [End Of Month Item] |     |             |                 |     |                  |             |                     |         |              |
| 710007           | No. 2 Engine - Powerplant - N1 Overspeed In Reverse Thrust       |                     | HRS |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                  |                     | ENC |             | 392             |     |                  | 0           |                     | 0       |              |
|                  |                                                                  |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                  |                     | MSC |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                           | [End Of Month Item] |     |             |                 |     |                  |             |                     |         |              |
| 710008           | No. 1 Engine - Powerplant - Engine Overtemperature AT High Power |                     | HRS |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                  |                     | ENC |             | 392             |     |                  | 0           |                     | 0       |              |
|                  |                                                                  |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                  |                     | MSC |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                           | [End Of Month Item] |     |             |                 |     |                  |             |                     |         |              |
| 710008           | No. 2 Engine - Powerplant - Engine Overtemperature AT High Power |                     | HRS |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                  |                     | ENC |             | 392             |     |                  | 0           |                     | 0       |              |
|                  |                                                                  |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                  |                     | MSC |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                           | [End Of Month Item] |     |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom  | Description                                                                                                                          |               | UOM    | Times Since         | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|--------------------------------------------------------------------------------------------------------------------------------------|---------------|--------|---------------------|-----------------|-----|------------------|----------|---------------------|---------|--------------|
|                  | Part Number                                                                                                                          | Serial Number |        |                     |                 |     |                  |          |                     |         | Approx Price |
| Logbook Position | HW                                                                                                                                   | SW            |        |                     |                 |     |                  |          |                     |         | Manufacturer |
|                  | MM Ref                                                                                                                               |               |        |                     |                 |     |                  |          |                     |         | Date Type    |
|                  | Ops Number(s)                                                                                                                        |               |        |                     |                 |     |                  |          |                     |         |              |
| 710009           | No. 1 Engine - Powerplant - Engine Overtemperature<br>During Engine Start and Relight                                                |               | HRS    |                     | 994.4           |     |                  | 0        |                     | 0       |              |
|                  |                                                                                                                                      |               | ENC    |                     | 392             |     | 0                |          | 0                   |         |              |
|                  |                                                                                                                                      |               | MOS    |                     | 41.8            |     | 17 Nov 2022      |          |                     |         |              |
|                  |                                                                                                                                      |               | MSC    |                     |                 | O/C |                  |          |                     |         |              |
|                  |                                                                                                                                      |               | Engine | [End Of Month Item] |                 |     |                  |          |                     |         |              |
| 710009           | No. 2 Engine - Powerplant - Engine Overtemperature<br>During Engine Start and Relight                                                |               | HRS    |                     | 994.4           |     |                  | 0        |                     | 0       |              |
|                  |                                                                                                                                      |               | ENC    |                     | 392             |     | 0                |          | 0                   |         |              |
|                  |                                                                                                                                      |               | MOS    |                     | 41.9            |     | 15 Nov 2022      |          |                     |         |              |
|                  |                                                                                                                                      |               | MSC    |                     |                 | O/C |                  |          |                     |         |              |
|                  |                                                                                                                                      |               | Engine | [End Of Month Item] |                 |     |                  |          |                     |         |              |
| 710010           | No. 1 Engine - Powerplant - Combined Engine<br>Overtemperature AT High Power and N2 Overspeed or N1<br>Overspeed (In Forward Thrust) |               | HRS    |                     | 994.4           |     |                  | 0        |                     | 0       |              |
|                  |                                                                                                                                      |               | ENC    |                     | 392             |     | 0                |          | 0                   |         |              |
|                  |                                                                                                                                      |               | MOS    |                     | 41.8            |     | 17 Nov 2022      |          |                     |         |              |
|                  |                                                                                                                                      |               | MSC    |                     |                 | O/C |                  |          |                     |         |              |
|                  |                                                                                                                                      |               | Engine | [End Of Month Item] |                 |     |                  |          |                     |         |              |
| 710010           | No. 2 Engine - Powerplant - Combined Engine<br>Overtemperature AT High Power and N2 Overspeed or N1<br>Overspeed (In Forward Thrust) |               | HRS    |                     | 994.4           |     |                  | 0        |                     | 0       |              |
|                  |                                                                                                                                      |               | ENC    |                     | 392             |     | 0                |          | 0                   |         |              |
|                  |                                                                                                                                      |               | MOS    |                     | 41.9            |     | 15 Nov 2022      |          |                     |         |              |
|                  |                                                                                                                                      |               | MSC    |                     |                 | O/C |                  |          |                     |         |              |
|                  |                                                                                                                                      |               | Engine | [End Of Month Item] |                 |     |                  |          |                     |         |              |
| 710011           | No. 1 Engine - Powerplant - Uncommand Engine<br>Shutdown Following Ground Start of Both Engines                                      |               | HRS    |                     | 994.4           |     |                  | 0        |                     | 0       |              |
|                  |                                                                                                                                      |               | ENC    |                     | 392             |     | 0                |          | 0                   |         |              |
|                  |                                                                                                                                      |               | MOS    |                     | 41.8            |     | 17 Nov 2022      |          |                     |         |              |
|                  |                                                                                                                                      |               | MSC    |                     |                 | O/C |                  |          |                     |         |              |
|                  |                                                                                                                                      |               | Engine | [End Of Month Item] |                 |     |                  |          |                     |         |              |
| 710011           | No. 2 Engine - Powerplant - Uncommand Engine<br>Shutdown Following Ground Start of Both Engines                                      |               | HRS    |                     | 994.4           |     |                  | 0        |                     | 0       |              |
|                  |                                                                                                                                      |               | ENC    |                     | 392             |     | 0                |          | 0                   |         |              |
|                  |                                                                                                                                      |               | MOS    |                     | 41.9            |     | 15 Nov 2022      |          |                     |         |              |
|                  |                                                                                                                                      |               | MSC    |                     |                 | O/C |                  |          |                     |         |              |
|                  |                                                                                                                                      |               | Engine | [End Of Month Item] |                 |     |                  |          |                     |         |              |
| 710012           | No. 1 Engine - Procedure after Lp Vibration Exceedance                                                                               |               | HRS    |                     | 994.4           |     |                  | 0        |                     | 0       |              |
|                  |                                                                                                                                      |               | ENC    |                     | 392             |     | 0                |          | 0                   |         |              |
|                  |                                                                                                                                      |               | MOS    |                     | 41.8            |     | 17 Nov 2022      |          |                     |         |              |
|                  |                                                                                                                                      |               | MSC    |                     |                 | O/C |                  |          |                     |         |              |
|                  |                                                                                                                                      |               | Engine | [End Of Month Item] |                 |     |                  |          |                     |         |              |

| ATA<br>U=Custom  | Description                                                                                                   |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|---------------------------------------------------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                                                                                   | Serial Number |                     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                                                                            | SW            |                     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                                                                        |               |                     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                                                                                 |               |                     |             |                 |     |                  |             |                     |         |              |
| 710012           | No. 2 Engine - Procedure after Lp Vibration Exceedance                                                        |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                                                               |               | ENC                 |             | 392             |     |                  | 0           |                     | 0       |              |
|                  |                                                                                                               |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                                                               |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  |                                                                                                               |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 710013           | No. 1 Engine - Procedure after Hp Vibration Exceedance                                                        |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                                                               |               | ENC                 |             | 392             |     |                  | 0           |                     | 0       |              |
|                  |                                                                                                               |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                                                               |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  |                                                                                                               |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 710013           | No. 2 Engine - Procedure after Hp Vibration Exceedance                                                        |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                                                               |               | ENC                 |             | 392             |     |                  | 0           |                     | 0       |              |
|                  |                                                                                                               |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                                                               |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  |                                                                                                               |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 710015           | No. 1 Engine - Engine (Test 1) - Wet Motor Operation<br>Leak Check                                            |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                                                               |               | ENC                 |             | 392             |     |                  | 0           |                     | 0       |              |
|                  |                                                                                                               |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                                                               |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  |                                                                                                               |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 710015           | No. 2 Engine - Engine (Test 1) - Wet Motor Operation<br>Leak Check                                            |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                                                               |               | ENC                 |             | 392             |     |                  | 0           |                     | 0       |              |
|                  |                                                                                                               |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                                                               |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  |                                                                                                               |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 710016           | No. 1 Engine - Engine Run Leak Check (Test 2A) - Lp and<br>Bypass Duct Mounted Hp Fuel Systems and Oil System |               | HRS                 |             | 327.2           |     |                  | 667.2       |                     |         | 0            |
|                  |                                                                                                               |               | ENC                 |             | 128             |     |                  | 264         |                     | 0       |              |
|                  |                                                                                                               |               | MOS                 |             | 9.9             |     |                  | 15 Jul 2025 |                     |         |              |
|                  |                                                                                                               |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  |                                                                                                               |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 710016           | No. 2 Engine - Engine Run Leak Check (Test 2A) - Lp and<br>Bypass Duct Mounted Hp Fuel Systems and Oil System |               | HRS                 |             | 327.2           |     |                  | 667.2       |                     |         | 0            |
|                  |                                                                                                               |               | ENC                 |             | 128             |     |                  | 264         |                     | 0       |              |
|                  |                                                                                                               |               | MOS                 |             | 9.9             |     |                  | 15 Jul 2025 |                     |         |              |
|                  |                                                                                                               |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  |                                                                                                               |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| Engine           |                                                                                                               |               |                     |             |                 |     |                  |             |                     |         |              |



| ATA<br>U=Custom  | Description                                                           |               | UOM      | Times Since         | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-----------------------------------------------------------------------|---------------|----------|---------------------|-----------------|-----|------------------|----------|--------------------|---------|--------------|
|                  | Part Number                                                           | Serial Number |          |                     |                 |     |                  |          |                    |         | Approx Price |
| Logbook Position | HW                                                                    | SW            |          |                     |                 |     |                  |          |                    |         | Manufacturer |
|                  | MM Ref                                                                |               |          |                     |                 |     |                  |          |                    |         | Date Type    |
|                  | Ops Number(s)                                                         |               |          |                     |                 |     |                  |          |                    |         |              |
| 710017           | No. 1 Engine - Engine Run Leak Check (Test 2B) - Hp<br>Fuel System    |               | HRS      |                     | 994.4           |     |                  | 0        |                    | 0       |              |
|                  |                                                                       |               | ENC      |                     | 392             |     | 0                |          | 0                  |         |              |
|                  |                                                                       |               | MOS      |                     | 41.8            |     | 17 Nov 2022      |          |                    |         |              |
|                  |                                                                       |               | MSC      |                     |                 | O/C |                  |          |                    |         |              |
|                  |                                                                       |               | Engine   | [End Of Month Item] |                 |     |                  |          |                    |         |              |
| 710017           | No. 2 Engine - Engine Run Leak Check (Test 2B) - Hp<br>Fuel System    |               | HRS      |                     | 994.4           |     |                  | 0        |                    | 0       |              |
|                  |                                                                       |               | ENC      |                     | 392             |     | 0                |          | 0                  |         |              |
|                  |                                                                       |               | MOS      |                     | 41.9            |     | 15 Nov 2022      |          |                    |         |              |
|                  |                                                                       |               | MSC      |                     |                 | O/C |                  |          |                    |         |              |
|                  |                                                                       |               | Engine   | [End Of Month Item] |                 |     |                  |          |                    |         |              |
| 710018           | Engine (Test 3A, Left) - T/Rev Check                                  |               | HRS      |                     | 137             |     |                  | 2909.1   |                    | 0       |              |
|                  |                                                                       |               | AFL      |                     | 52              |     | 1065             |          | 0                  |         |              |
|                  |                                                                       |               | MOS      |                     | 5               |     | 12 Dec 2025      |          |                    |         |              |
|                  |                                                                       |               | MSC      |                     |                 | O/C |                  |          |                    |         |              |
|                  |                                                                       |               | Airframe |                     |                 |     |                  |          |                    |         |              |
| 710019           | Engine (Test 3A, Right) - T/Rev Check                                 |               | HRS      |                     | 730.5           |     |                  | 2315.6   |                    | 0       |              |
|                  |                                                                       |               | AFL      |                     | 315             |     | 802              |          | 0                  |         |              |
|                  |                                                                       |               | MOS      |                     | 28.7            |     | 21 Dec 2023      |          |                    |         |              |
|                  |                                                                       |               | MSC      |                     |                 | O/C |                  |          |                    |         |              |
|                  |                                                                       |               | Airframe |                     |                 |     |                  |          |                    |         |              |
| 710020           | Engine (Test 3B, Left) - T/Rev / Line Replaceable Unit<br>Leak Check  |               | HRS      |                     | 137             |     |                  | 2909.1   |                    | 0       |              |
|                  |                                                                       |               | AFL      |                     | 52              |     | 1065             |          | 0                  |         |              |
|                  |                                                                       |               | MOS      |                     | 5               |     | 12 Dec 2025      |          |                    |         |              |
|                  |                                                                       |               | MSC      |                     |                 | O/C |                  |          |                    |         |              |
|                  |                                                                       |               | Airframe |                     |                 |     |                  |          |                    |         |              |
| 710021           | Engine (Test 3B, Right) - T/Rev / Line Replaceable Unit<br>Leak Check |               | HRS      |                     | 3046.1          |     |                  | 0        |                    | 0       |              |
|                  |                                                                       |               | AFL      |                     | 1117            |     | 0                |          | 0                  |         |              |
|                  |                                                                       |               | MOS      |                     | 128.6           |     | 24 Aug 2015      |          |                    |         |              |
|                  |                                                                       |               | MSC      |                     |                 | O/C |                  |          |                    |         |              |
|                  |                                                                       |               | Airframe |                     |                 |     |                  |          |                    |         |              |
| 710022           | No. 1 Engine - Engine (Test 4) - Engine Power Assurance<br>Check      |               | HRS      |                     | 994.4           |     |                  | 0        |                    | 0       |              |
|                  |                                                                       |               | ENC      |                     | 392             |     | 0                |          | 0                  |         |              |
|                  |                                                                       |               | MOS      |                     | 41.8            |     | 17 Nov 2022      |          |                    |         |              |
|                  |                                                                       |               | MSC      |                     |                 | O/C |                  |          |                    |         |              |
|                  |                                                                       |               | Engine   | [End Of Month Item] |                 |     |                  |          |                    |         |              |

| ATA<br>U=Custom  | Description                                                        |                     | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|--------------------------------------------------------------------|---------------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                        | Serial Number       |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                 | SW                  |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                             |                     |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                      |                     |     |             |                 |     |                  |             |                    |         |              |
| 710022           | No. 2 Engine - Engine (Test 4) - Engine Power Assurance Check      |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                    |                     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                                    |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                    |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                             | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 710023           | No. 1 Engine - Engine (Test 5) - Pretested Replacement Engine Test |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                    |                     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                                    |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                    |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                             | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 710023           | No. 2 Engine - Engine (Test 5) - Pretested Replacement Engine Test |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                    |                     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                                    |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                    |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                             | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 710024           | No. 1 Engine - Engine (Test 6) - Vibration Survey                  |                     | HRS |             | 663.7           |     |                  | 330.7       |                    |         | 0            |
|                  |                                                                    |                     | ENC |             | 291             |     |                  | 101         |                    |         | 0            |
|                  |                                                                    |                     | MOS |             | 25.5            |     |                  | 27 Mar 2024 |                    |         |              |
|                  |                                                                    |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                             | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 710024           | No. 2 Engine - Engine (Test 6) - Vibration Survey                  |                     | HRS |             | 663.7           |     |                  | 330.7       |                    |         | 0            |
|                  |                                                                    |                     | ENC |             | 291             |     |                  | 101         |                    |         | 0            |
|                  |                                                                    |                     | MOS |             | 25.5            |     |                  | 27 Mar 2024 |                    |         |              |
|                  |                                                                    |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                             | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 710025           | No. 1 Engine - Engine (Test 7) - Lp Compressor (Fan) Trim Balance  |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                    |                     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                                    |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                    |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                             | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 710025           | No. 2 Engine - Engine (Test 7) - Lp Compressor (Fan) Trim Balance  |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                    |                     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                                    |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                    |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                             | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                              |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                              | Serial Number |                     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                       | SW            |                     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                   |               |                     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                            |               |                     |             |                 |     |                  |             |                     |         |              |
| 710026           | No. 1 Engine - Engine (Test 7A) - Fan Trim Balance       |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | Check (Using One-Shot Method With External Vibration     |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | Analyzer - 1ST Alternate Method)                         |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                          |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  |                                                          |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| Engine           |                                                          |               |                     |             |                 |     |                  |             |                     |         |              |
| 710026           | No. 2 Engine - Engine (Test 7A) - Fan Trim Balance       |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | Check (Using One-Shot Method With External Vibration     |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | Analyzer - 1ST Alternate Method)                         |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                          |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  |                                                          |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| Engine           |                                                          |               |                     |             |                 |     |                  |             |                     |         |              |
| 710027           | No. 1 Engine - Engine (Test 7B) - Fan Trim Balance       |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | Check (Using Trial Weight Method With External Vibration |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | Analyzer - 2ND Alternate Method)                         |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                          |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  |                                                          |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| Engine           |                                                          |               |                     |             |                 |     |                  |             |                     |         |              |
| 710027           | No. 2 Engine - Engine (Test 7B) - Fan Trim Balance       |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | Check (Using Trial Weight Method With External Vibration |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | Analyzer - 2ND Alternate Method)                         |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                          |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  |                                                          |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| Engine           |                                                          |               |                     |             |                 |     |                  |             |                     |         |              |
| 710028           | No. 1 Engine - Engine (Test 8) - Oil Consumption Test    |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                          |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                                          |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                          |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  |                                                          |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| Engine           |                                                          |               |                     |             |                 |     |                  |             |                     |         |              |
| 710028           | No. 2 Engine - Engine (Test 8) - Oil Consumption Test    |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                          |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                                          |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                          |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  |                                                          |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| Engine           |                                                          |               |                     |             |                 |     |                  |             |                     |         |              |
| 710029           | No. 1 Engine - Engine (Test 9) - Fadec Operational Test  |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                          |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                                          |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                          |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  |                                                          |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| Engine           |                                                          |               |                     |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom  | Description                                                            |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                            | Serial Number |                     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                     | SW            |                     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                 |               |                     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                          |               |                     |             |                 |     |                  |             |                    |         |              |
| 710029           | No. 2 Engine - Engine (Test 9) - Fadec Operational Test                |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                        |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                                        |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                        |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                 |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 710030           | No. 1 Engine - Lp Compressor (Fan) Blade SET - RE-Index                |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                        |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                                        |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                        |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                 |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 710030           | No. 2 Engine - Lp Compressor (Fan) Blade SET - RE-Index                |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                        |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                                        |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                        |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                 |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 710031           | No. 1 Engine - Lp Compressor (Fan) Blade SET - RE-Distribute (Shuffle) |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                        |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                                        |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                        |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                 |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 710031           | No. 2 Engine - Lp Compressor (Fan) Blade SET - RE-Distribute (Shuffle) |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                        |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                                        |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                        |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                 |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 710032           | No. 1 Engine - Inspection for Internal Oil Leaks - Inspection / Check  |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                        |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                                        |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                        |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                 |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 710032           | No. 2 Engine - Inspection for Internal Oil Leaks - Inspection / Check  |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                        |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                                        |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                        |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                 |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                          |               | UOM                                               | Times Since         | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------|--------------------------------------------------------------------------------------|---------------|---------------------------------------------------|---------------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                  | Part Number                                                                          | Serial Number |                                                   |                     |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position | HW                                                                                   | SW            |                                                   |                     |                 |     |                  |             |                    |             | Manufacturer |
|                  | MM Ref                                                                               |               |                                                   |                     |                 |     |                  |             |                    |             | Date Type    |
|                  | Ops Number(s)                                                                        |               |                                                   |                     |                 |     |                  |             |                    |             |              |
| 710033           | No. 1 Engine - High Oil Consumption - Troubleshooting / Inspection                   |               | HRS                                               |                     | 994.4           |     |                  | 0           |                    |             | 0            |
|                  |                                                                                      |               | ENC                                               |                     | 392             |     |                  | 0           |                    | 0           |              |
|                  |                                                                                      |               | MOS                                               |                     | 41.8            |     |                  | 17 Nov 2022 |                    |             |              |
|                  |                                                                                      |               | MSC                                               |                     |                 |     | O/C              |             |                    |             |              |
|                  |                                                                                      |               | Engine                                            | [End Of Month Item] |                 |     |                  |             |                    |             |              |
| 710033           | No. 2 Engine - High Oil Consumption - Troubleshooting / Inspection                   |               | HRS                                               |                     | 994.4           |     |                  | 0           |                    |             | 0            |
|                  |                                                                                      |               | ENC                                               |                     | 392             |     |                  | 0           |                    | 0           |              |
|                  |                                                                                      |               | MOS                                               |                     | 41.9            |     |                  | 15 Nov 2022 |                    |             |              |
|                  |                                                                                      |               | MSC                                               |                     |                 |     | O/C              |             |                    |             |              |
|                  |                                                                                      |               | Engine                                            | [End Of Month Item] |                 |     |                  |             |                    |             |              |
| 710034           | No. 1 Engine - Powerplant - Inspection after Activation of Pressure Relief Door(S)   |               | HRS                                               |                     | 994.4           |     |                  | 0           |                    |             | 0            |
|                  |                                                                                      |               | ENC                                               |                     | 392             |     |                  | 0           |                    | 0           |              |
|                  |                                                                                      |               | MOS                                               |                     | 41.8            |     |                  | 17 Nov 2022 |                    |             |              |
|                  |                                                                                      |               | MSC                                               |                     |                 |     | O/C              |             |                    |             |              |
|                  |                                                                                      |               | Engine                                            | [End Of Month Item] |                 |     |                  |             |                    |             |              |
| 710034           | No. 2 Engine - Powerplant - Inspection after Activation of Pressure Relief Door(S)   |               | HRS                                               |                     | 994.4           |     |                  | 0           |                    |             | 0            |
|                  |                                                                                      |               | ENC                                               |                     | 392             |     |                  | 0           |                    | 0           |              |
|                  |                                                                                      |               | MOS                                               |                     | 41.9            |     |                  | 15 Nov 2022 |                    |             |              |
|                  |                                                                                      |               | MSC                                               |                     |                 |     | O/C              |             |                    |             |              |
|                  |                                                                                      |               | Engine                                            | [End Of Month Item] |                 |     |                  |             |                    |             |              |
| 710035           | Nacelle, T/Rev and Exhaust External (Left, Viewed from Platform) - Zonal Inspection  |               | HRS                                               |                     | 663.7           |     | 2400             | 2382.4      | 4782.4             | 4832.4      | 0            |
|                  |                                                                                      |               | AFL                                               |                     | 291             |     |                  | 826         |                    |             | 0            |
|                  |                                                                                      |               | MOS                                               |                     | 25.5            |     | 48               | 28 Mar 2024 | 31 Mar 2028        | 30 Apr 2028 |              |
|                  |                                                                                      |               | [End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50] |                     |                 |     |                  |             |                    |             |              |
|                  |                                                                                      |               | Airframe                                          | 052004,052013       |                 |     |                  |             |                    |             |              |
| 710036           | Nacelle, T/Rev and Exhaust External (Right, Viewed from Platform) - Zonal Inspection |               | HRS                                               |                     | 663.7           |     | 2400             | 2382.4      | 4782.4             | 4832.4      | 0            |
|                  |                                                                                      |               | AFL                                               |                     | 291             |     |                  | 826         |                    |             | 0            |
|                  |                                                                                      |               | MOS                                               |                     | 25.5            |     | 48               | 28 Mar 2024 | 31 Mar 2028        | 30 Apr 2028 |              |
|                  |                                                                                      |               | [End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50] |                     |                 |     |                  |             |                    |             |              |
|                  |                                                                                      |               | Airframe                                          | 052004,052013       |                 |     |                  |             |                    |             |              |
| 710037           | No. 1 Engine - Engine - Core Wash                                                    |               | HRS                                               |                     | 994.4           |     |                  | 0           |                    |             | 0            |
|                  |                                                                                      |               | ENC                                               |                     | 392             |     |                  | 0           |                    | 0           |              |
|                  |                                                                                      |               | MOS                                               |                     | 41.8            |     |                  | 17 Nov 2022 |                    |             |              |
|                  |                                                                                      |               | MSC                                               |                     |                 |     | O/C              |             |                    |             |              |
|                  |                                                                                      |               | Engine                                            | [End Of Month Item] |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom  | Description                                                                    |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|--------------------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                    | Serial Number |                     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                             | SW            |                     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                         |               |                     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                                  |               |                     |             |                 |     |                  |             |                    |         |              |
| 710037           | No. 2 Engine - Engine - Core Wash                                              |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                                                |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                                                         |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  |                                                                                |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 710038           | No. 1 Engine - Engine - Cleaning (after Contamination With FIRE Extinguishant) |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                                                |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                                                         |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  |                                                                                |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 710038           | No. 2 Engine - Engine - Cleaning (after Contamination With FIRE Extinguishant) |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                                                |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                                                         |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  |                                                                                |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 710039           | No. 1 Engine - Engine Maintenance Program Declaration                          |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                                                |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                                                         |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | 052001                                                                         |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 710039           | No. 2 Engine - Engine Maintenance Program Declaration                          |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                                                |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                                                         |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | 052001                                                                         |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 710040           | No. 1 Engine - Lease Engine Inspection Requirements - Inspection               |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                                                |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                                                         |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  |                                                                                |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 710040           | No. 2 Engine - Lease Engine Inspection Requirements - Inspection               |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                                                |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                                                         |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  |                                                                                |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                           |               | UOM                                               | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------|-------------------------------------------------------|---------------|---------------------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                  | Part Number                                           | Serial Number |                                                   |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position | HW                                                    | SW            |                                                   |             |                 |     |                  |             |                    |             | Manufacturer |
|                  | MM Ref                                                |               |                                                   |             |                 |     |                  |             |                    |             | Date Type    |
|                  | Ops Number(s)                                         |               |                                                   |             |                 |     |                  |             |                    |             |              |
| 710041           | No. 1 Engine - Engine Overhaul - Hard Time Operated   |               | HRS                                               |             | 994.4           |     | 10000            | 0           | 10000              | 10250       | 0            |
|                  | PN SN-UNKNOWN                                         |               | ENC                                               |             | 392             |     |                  | 0           |                    |             | 0            |
|                  |                                                       |               | MOS                                               |             | 41.8            |     |                  | 17 Nov 2022 |                    |             |              |
|                  | Engine                                                |               | [End Of Month Item] [HRS: +250/-250]              |             |                 |     |                  |             |                    |             |              |
| 710041           | No. 2 Engine - Engine Overhaul - Hard Time Operated   |               | HRS                                               |             | 994.4           |     | 10000            | 0           | 10000              | 10250       | 0            |
|                  | PN SN-UNKNOWN                                         |               | ENC                                               |             | 392             |     |                  | 0           |                    |             | 0            |
|                  |                                                       |               | MOS                                               |             | 41.9            |     |                  | 15 Nov 2022 |                    |             |              |
|                  | Engine                                                |               | [End Of Month Item] [HRS: +250/-250]              |             |                 |     |                  |             |                    |             |              |
| 710042           | No. 1 Engine - Engine Calendar Life - Task Orientated |               | HRS                                               |             | 994.4           |     |                  | 0           |                    |             | 0            |
|                  | PN SN-UNKNOWN                                         |               | ENC                                               |             | 392             |     |                  | 0           |                    |             | 0            |
|                  |                                                       |               | MOS                                               |             | 41.8            |     |                  | 17 Nov 2022 |                    |             |              |
|                  | Engine                                                |               | MSC                                               |             |                 |     | O/C              |             |                    |             |              |
|                  |                                                       |               | [End Of Month Item]                               |             |                 |     |                  |             |                    |             |              |
| 710042           | No. 2 Engine - Engine Calendar Life - Task Orientated |               | HRS                                               |             | 994.4           |     |                  | 0           |                    |             | 0            |
|                  | PN SN-UNKNOWN                                         |               | ENC                                               |             | 392             |     |                  | 0           |                    |             | 0            |
|                  |                                                       |               | MOS                                               |             | 41.9            |     |                  | 15 Nov 2022 |                    |             |              |
|                  | Engine                                                |               | MSC                                               |             |                 |     | O/C              |             |                    |             |              |
|                  |                                                       |               | [End Of Month Item]                               |             |                 |     |                  |             |                    |             |              |
| 711000           | Engine Upper and Lower Cowl Doors (Left) - General    |               | HRS                                               |             | 730.5           |     | 1200             | 2315.6      | 3515.6             | 3565.6      | 0            |
|                  | Visual Inspection                                     |               | AFL                                               |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                       |               | MOS                                               |             | 28.7            |     |                  | 21 Dec 2023 |                    |             |              |
|                  | Airframe                                              |               | [HRS: +50/-50]                                    |             |                 |     |                  |             |                    |             |              |
|                  |                                                       |               | 052002                                            |             |                 |     |                  |             |                    |             |              |
| 711001           | Engine Upper and Lower Cowl Doors (Right) - General   |               | HRS                                               |             | 730.5           |     | 1200             | 2315.6      | 3515.6             | 3565.6      | 0            |
|                  | Visual Inspection                                     |               | AFL                                               |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                       |               | MOS                                               |             | 28.7            |     |                  | 21 Dec 2023 |                    |             |              |
|                  | Airframe                                              |               | [HRS: +50/-50]                                    |             |                 |     |                  |             |                    |             |              |
|                  |                                                       |               | 052002                                            |             |                 |     |                  |             |                    |             |              |
| 711002           | Engine Internal (Left) - Zonal Inspection             |               | HRS                                               |             | 663.7           |     | 1200             | 2382.4      | 3582.4             | 3632.4      | 0            |
|                  |                                                       |               | AFL                                               |             | 291             |     |                  | 826         |                    |             | 0            |
|                  |                                                       |               | MOS                                               |             | 25.5            |     | 48               | 28 Mar 2024 | 31 Mar 2028        | 30 Apr 2028 |              |
|                  | Airframe                                              |               | [End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50] |             |                 |     |                  |             |                    |             |              |
|                  |                                                       |               | 052002,052013                                     |             |                 |     |                  |             |                    |             |              |
| 711003           | Engine Internal (Right) - Zonal Inspection            |               | HRS                                               |             | 663.7           |     | 1200             | 2382.4      | 3582.4             | 3632.4      | 0            |
|                  |                                                       |               | AFL                                               |             | 291             |     |                  | 826         |                    |             | 0            |
|                  |                                                       |               | MOS                                               |             | 25.5            |     | 48               | 28 Mar 2024 | 31 Mar 2028        | 30 Apr 2028 |              |
|                  | Airframe                                              |               | [End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50] |             |                 |     |                  |             |                    |             |              |
|                  |                                                       |               | 052002,052013                                     |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom  | Description                                                                   |               | UOM                                               | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(* =Adj) | Max Due     | Avg Man Hrs  |
|------------------|-------------------------------------------------------------------------------|---------------|---------------------------------------------------|-------------|-----------------|-----|------------------|-------------|----------------------|-------------|--------------|
|                  | Part Number                                                                   | Serial Number |                                                   |             |                 |     |                  |             |                      |             | Approx Price |
| Logbook Position | HW                                                                            | SW            |                                                   |             |                 |     |                  |             |                      |             | Manufacturer |
|                  | MM Ref                                                                        |               |                                                   |             |                 |     |                  |             |                      |             | Date Type    |
|                  | Ops Number(s)                                                                 |               |                                                   |             |                 |     |                  |             |                      |             |              |
| 711004           | Engine Lower Fan Cowl Door (Left) - Enhanced Zonal Inspection                 |               | HRS                                               |             | 730.5           |     | 1200             | 2315.6      | 3515.6               | 3565.6      | 0            |
|                  |                                                                               |               | AFL                                               |             | 315             |     |                  | 802         |                      |             | 0            |
|                  |                                                                               |               | MOS                                               |             | 28.7            | -83 | 48               | 21 Dec 2023 | 30 Sep 2027*         | 31 Oct 2027 |              |
|                  |                                                                               |               | [End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50] |             |                 |     |                  |             |                      |             |              |
| Airframe         |                                                                               | 052002,052013 |                                                   |             |                 |     |                  |             |                      |             |              |
| 711005           | Engine Lower Fan Cowl Door (Right) - Enhanced Zonal Inspection                |               | HRS                                               |             | 730.5           |     | 1200             | 2315.6      | 3515.6               | 3565.6      | 0            |
|                  |                                                                               |               | AFL                                               |             | 315             |     |                  | 802         |                      |             | 0            |
|                  |                                                                               |               | MOS                                               |             | 28.7            | -84 | 48               | 21 Dec 2023 | 30 Sep 2027*         | 31 Oct 2027 |              |
|                  |                                                                               |               | [End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50] |             |                 |     |                  |             |                      |             |              |
| Airframe         |                                                                               | 052002,052013 |                                                   |             |                 |     |                  |             |                      |             |              |
| 711006           | Lower and Upper Cowl Door Latches (Upper Left) - Adjustment                   |               | HRS                                               |             | 3046.1          |     |                  | 0           |                      |             | 0            |
|                  |                                                                               |               | AFL                                               |             | 1117            |     |                  | 0           |                      |             | 0            |
|                  |                                                                               |               | MOS                                               |             | 128.6           |     |                  | 24 Aug 2015 |                      |             |              |
|                  |                                                                               |               | MSC                                               |             |                 |     | O/C              |             |                      |             |              |
| Airframe         |                                                                               |               |                                                   |             |                 |     |                  |             |                      |             |              |
| 711007           | Lower and Upper Cowl Door Latches (Upper Right) - Adjustment                  |               | HRS                                               |             | 3046.1          |     |                  | 0           |                      |             | 0            |
|                  |                                                                               |               | AFL                                               |             | 1117            |     |                  | 0           |                      |             | 0            |
|                  |                                                                               |               | MOS                                               |             | 128.6           |     |                  | 24 Aug 2015 |                      |             |              |
|                  |                                                                               |               | MSC                                               |             |                 |     | O/C              |             |                      |             |              |
| Airframe         |                                                                               |               |                                                   |             |                 |     |                  |             |                      |             |              |
| 711008           | Lower and Upper Cowl Door Latches (Lower Left) - Adjustment                   |               | HRS                                               |             | 3046.1          |     |                  | 0           |                      |             | 0            |
|                  |                                                                               |               | AFL                                               |             | 1117            |     |                  | 0           |                      |             | 0            |
|                  |                                                                               |               | MOS                                               |             | 128.6           |     |                  | 24 Aug 2015 |                      |             |              |
|                  |                                                                               |               | MSC                                               |             |                 |     | O/C              |             |                      |             |              |
| Airframe         |                                                                               |               |                                                   |             |                 |     |                  |             |                      |             |              |
| 711009           | Lower and Upper Cowl Door Latches (Lower Right) - Adjustment                  |               | HRS                                               |             | 3046.1          |     |                  | 0           |                      |             | 0            |
|                  |                                                                               |               | AFL                                               |             | 1117            |     |                  | 0           |                      |             | 0            |
|                  |                                                                               |               | MOS                                               |             | 128.6           |     |                  | 24 Aug 2015 |                      |             |              |
|                  |                                                                               |               | MSC                                               |             |                 |     | O/C              |             |                      |             |              |
| Airframe         |                                                                               |               |                                                   |             |                 |     |                  |             |                      |             |              |
| 711100           | Engine Inlet Cowl (Left) - Removal / Installation<br>RD00101001-1 RD1001L0170 |               | HRS                                               | TSN:2051.9  | 994.2           |     |                  | 2051.9      |                      |             | 0            |
|                  |                                                                               |               | AFL                                               | TSN:725     | 392             |     |                  | 725         |                      |             | 0            |
|                  |                                                                               |               | MOS                                               | TSN:88      | 41.2            |     |                  | 05 Dec 2022 |                      |             |              |
|                  |                                                                               |               | MSC                                               |             |                 |     | O/C              |             |                      |             |              |
| Airframe         |                                                                               |               |                                                   |             |                 |     |                  |             |                      |             |              |



| ATA<br>U=Custom  | Description                                                         |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------|---------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                  | Part Number                                                         | Serial Number |                                    |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position | HW                                                                  | SW            |                                    |             |                 |     |                  |             |                    |             | Manufacturer |
|                  | MM Ref                                                              |               |                                    |             |                 |     |                  |             |                    |             | Date Type    |
|                  | Ops Number(s)                                                       |               |                                    |             |                 |     |                  |             |                    |             |              |
| 711101           | Engine Inlet Cowl (Right) - Removal / Installation                  |               | HRS                                | TSN:2051.9  | 994.2           |     |                  | 2051.9      |                    |             | 0            |
|                  | RD00101001-2                                                        | RD1001R0171   | AFL                                | TSN:725     | 392             |     |                  | 725         |                    |             | 0            |
|                  |                                                                     |               | MOS                                | TSN:88      | 41.1            |     |                  | 09 Dec 2022 |                    |             |              |
|                  | Airframe                                                            |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| 711104           | Inlet Cowl (Left) - General Visual Inspection                       |               | HRS                                |             | 730.5           |     | 1200             | 2315.6      | 3515.6             | 3565.6      | 0            |
|                  |                                                                     |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                     |               | MOS                                |             | 28.7            |     |                  | 21 Dec 2023 |                    |             |              |
|                  | Airframe                                                            |               | [HRS: +50/-50]                     |             |                 |     |                  |             |                    |             |              |
|                  | 052002                                                              |               |                                    |             |                 |     |                  |             |                    |             |              |
| 711105           | Inlet Cowl (Right) - General Visual Inspection                      |               | HRS                                |             | 730.5           |     | 1200             | 2315.6      | 3515.6             | 3565.6      | 0            |
|                  |                                                                     |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                  |                                                                     |               | MOS                                |             | 28.7            |     |                  | 21 Dec 2023 |                    |             |              |
|                  | Airframe                                                            |               | [HRS: +50/-50]                     |             |                 |     |                  |             |                    |             |              |
|                  | 052002                                                              |               |                                    |             |                 |     |                  |             |                    |             |              |
| 711106           | Nose Cowl Structure FS 828.3 - FS 860.08 (Left) - Zonal Inspection  |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                     |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                     |               | MOS                                |             | 122             |     | 192              | 11 Mar 2016 | 31 Mar 2032        | 30 Apr 2032 |              |
|                  | Airframe                                                            |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
|                  | 052021                                                              |               |                                    |             |                 |     |                  |             |                    |             |              |
| 711107           | Nose Cowl Structure FS 828.3 - FS 860.08 (Right) - Zonal Inspection |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                     |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                     |               | MOS                                |             | 122             |     | 192              | 11 Mar 2016 | 31 Mar 2032        | 30 Apr 2032 |              |
|                  | Airframe                                                            |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
|                  | 052021                                                              |               |                                    |             |                 |     |                  |             |                    |             |              |
| 711108           | Inlet Cowl Lipskin (Left) - Nonabrasive Polish                      |               | HRS                                |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                  |                                                                     |               | AFL                                |             | 52              |     |                  | 1065        |                    |             | 0            |
|                  |                                                                     |               | MOS                                |             | 4.7             | -23 | 6                | 19 Dec 2025 | 31 May 2026*       | 30 Jun 2026 |              |
|                  | Airframe                                                            |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| 711109           | Inlet Cowl Lipskin (Right) - Nonabrasive Polish                     |               | HRS                                |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                  |                                                                     |               | AFL                                |             | 52              |     |                  | 1065        |                    |             | 0            |
|                  |                                                                     |               | MOS                                |             | 4.7             | -23 | 6                | 19 Dec 2025 | 31 May 2026*       | 30 Jun 2026 |              |
|                  | Airframe                                                            |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| 711110           | Inlet Cowl Lipskin (Left) - Cleaning                                |               | HRS                                |             | 137             |     |                  | 2909.1      |                    |             | 0            |
|                  |                                                                     |               | AFL                                |             | 52              |     |                  | 1065        |                    |             | 0            |
|                  |                                                                     |               | MOS                                |             | 4.7             |     |                  | 19 Dec 2025 |                    |             |              |
|                  | Airframe                                                            |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |

| ATA<br>U=Custom  | Description                          |                                                                                | UOM | Times Since | Time<br>Accrued | Adj    | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |   |
|------------------|--------------------------------------|--------------------------------------------------------------------------------|-----|-------------|-----------------|--------|------------------|-------------|--------------------|---------|--------------|---|
|                  | Part Number                          | Serial Number                                                                  |     |             |                 |        |                  |             |                    |         | Approx Price |   |
| Logbook Position | HW                                   | SW                                                                             |     |             |                 |        |                  |             |                    |         | Manufacturer |   |
|                  | MM Ref                               |                                                                                |     |             |                 |        |                  |             |                    |         | Date Type    |   |
|                  | Ops Number(s)                        |                                                                                |     |             |                 |        |                  |             |                    |         |              |   |
| 711111           | Inlet Cowl Lipskin (Right)- Cleaning |                                                                                | HRS |             | 137             |        |                  | 2909.1      |                    |         | 0            |   |
|                  |                                      |                                                                                | AFL |             | 52              |        |                  | 1065        |                    |         | 0            |   |
|                  |                                      |                                                                                | MOS |             | 4.7             |        |                  | 19 Dec 2025 |                    |         |              |   |
|                  |                                      |                                                                                | MSC |             |                 |        | O/C              |             |                    |         |              |   |
| Airframe         |                                      |                                                                                |     |             |                 |        |                  |             |                    |         |              |   |
|                  | 711200                               | Upper Cowl Door (Left) - Removal / Installation<br>RD00102006-9RD2006L0162     |     | HRS         | TSN:2051.9      | 994.2  |                  |             | 2051.9             |         |              | 0 |
|                  |                                      |                                                                                |     | AFL         | TSN:725         | 392    |                  |             | 725                |         |              | 0 |
|                  |                                      |                                                                                |     | MOS         | TSN:88          | 41.1   |                  |             | 09 Dec 2022        |         |              |   |
| MSC              |                                      |                                                                                |     |             |                 |        | O/C              |             |                    |         |              |   |
| Airframe         |                                      |                                                                                |     |             |                 |        |                  |             |                    |         |              |   |
|                  | 711201                               | Upper Cowl Door (Right) - Removal / Installation<br>RD00102006-10RD2006R0162   |     | HRS         | TSN:2051.9      | 994.2  |                  |             | 2051.9             |         |              | 0 |
|                  |                                      |                                                                                |     | AFL         | TSN:725         | 392    |                  |             | 725                |         |              | 0 |
|                  |                                      |                                                                                |     | MOS         | TSN:88          | 40.9   |                  |             | 13 Dec 2022        |         |              |   |
| MSC              |                                      |                                                                                |     |             |                 |        | O/C              |             |                    |         |              |   |
| Airframe         |                                      |                                                                                |     |             |                 |        |                  |             |                    |         |              |   |
|                  | 711300                               | Lower Cowl Door (Left) - Removal / Installation<br>RD00102005-9RD2005L0162     |     | HRS         | TSN:2051.9      | 994.2  |                  |             | 2051.9             |         |              | 0 |
|                  |                                      |                                                                                |     | AFL         | TSN:725         | 392    |                  |             | 725                |         |              | 0 |
|                  |                                      |                                                                                |     | MOS         | TSN:88          | 41.1   |                  |             | 09 Dec 2022        |         |              |   |
| MSC              |                                      |                                                                                |     |             |                 |        | O/C              |             |                    |         |              |   |
| Airframe         |                                      |                                                                                |     |             |                 |        |                  |             |                    |         |              |   |
|                  | 711301                               | Lower Cowl Door (Right) - Removal / Installation<br>RD00102005-10RD2005R0162   |     | HRS         | TSN:1419.1      | 994.2  |                  |             | 2051.9             |         |              | 0 |
|                  |                                      |                                                                                |     | AFL         | TSN:557         | 392    |                  |             | 725                |         |              | 0 |
|                  |                                      |                                                                                |     | MOS         | TSN:88          | 40.9   |                  |             | 13 Dec 2022        |         |              |   |
| MSC              |                                      |                                                                                |     |             |                 |        | O/C              |             |                    |         |              |   |
| Airframe         |                                      |                                                                                |     |             |                 |        |                  |             |                    |         |              |   |
|                  | 711400                               | Engine Fixed Cowl (Left) - Removal / Installation<br>RD00102007-9RD2007L0163   |     | HRS         |                 | 3046.1 |                  |             | 0                  |         |              | 0 |
|                  |                                      |                                                                                |     | AFL         |                 | 1117   |                  |             | 0                  |         |              | 0 |
|                  |                                      |                                                                                |     | MOS         |                 | 128.6  |                  |             | 24 Aug 2015        |         |              |   |
| MSC              |                                      |                                                                                |     |             |                 |        | O/C              |             |                    |         |              |   |
| Airframe         |                                      |                                                                                |     |             |                 |        |                  |             |                    |         |              |   |
|                  | 711401                               | Engine Fixed Cowl (Right) - Removal / Installation<br>RD00102007-10RD2007R0162 |     | HRS         |                 | 3046.1 |                  |             | 0                  |         |              | 0 |
|                  |                                      |                                                                                |     | AFL         |                 | 1117   |                  |             | 0                  |         |              | 0 |
|                  |                                      |                                                                                |     | MOS         |                 | 128.6  |                  |             | 24 Aug 2015        |         |              |   |
| MSC              |                                      |                                                                                |     |             |                 |        | O/C              |             |                    |         |              |   |
| Airframe         |                                      |                                                                                |     |             |                 |        |                  |             |                    |         |              |   |
|                  | 711404                               | Engine Fixed Cowl (Left) - Inspection                                          |     | HRS         |                 | 994.2  |                  |             | 2051.9             |         |              | 0 |
|                  |                                      |                                                                                |     | AFL         |                 | 392    |                  |             | 725                |         |              | 0 |
|                  |                                      |                                                                                |     | MOS         |                 | 41.1   |                  |             | 08 Dec 2022        |         |              |   |
| MSC              |                                      |                                                                                |     |             |                 |        | O/C              |             |                    |         |              |   |
| Airframe         |                                      |                                                                                |     |             |                 |        |                  |             |                    |         |              |   |

| ATA<br>U=Custom                    | Description                                                |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------------------------|------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                                    | Part Number                                                | Serial Number |                                    |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position                   | HW                                                         | SW            |                                    |             |                 |     |                  |             |                    |             | Manufacturer |
|                                    | MM Ref                                                     |               |                                    |             |                 |     |                  |             |                    |             | Date Type    |
|                                    | Ops Number(s)                                              |               |                                    |             |                 |     |                  |             |                    |             |              |
| 711405                             | Engine Fixed Cowl (Right) - Inspection                     |               | HRS                                |             | 994.2           |     |                  | 2051.9      |                    |             | 0            |
|                                    |                                                            |               | AFL                                |             | 392             |     |                  | 725         |                    |             | 0            |
|                                    |                                                            |               | MOS                                |             | 41.1            |     |                  | 09 Dec 2022 |                    |             |              |
|                                    | Airframe                                                   |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| 711406                             | Engine Fixed Cowl (Left) - Detailed Inspection             |               | HRS                                |             | 730.5           |     | 1200             | 2315.6      | 3515.6             |             | 0            |
|                                    |                                                            |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                                    |                                                            |               | MOS                                |             | 28.7            |     |                  | 21 Dec 2023 |                    |             |              |
|                                    | Airframe                                                   |               | [HRS: -50]                         |             |                 |     |                  |             |                    |             |              |
|                                    | 052002                                                     |               |                                    |             |                 |     |                  |             |                    |             |              |
| 711407                             | Engine Fixed Cowl (Right) - Detailed Inspection            |               | HRS                                |             | 730.5           |     | 1200             | 2315.6      | 3515.6             |             | 0            |
|                                    |                                                            |               | AFL                                |             | 315             |     |                  | 802         |                    |             | 0            |
|                                    |                                                            |               | MOS                                |             | 28.7            |     |                  | 21 Dec 2023 |                    |             |              |
|                                    | Airframe                                                   |               | [HRS: -50]                         |             |                 |     |                  |             |                    |             |              |
|                                    | 052002                                                     |               |                                    |             |                 |     |                  |             |                    |             |              |
| 712000                             | Engine Attach Pins and Bolts (Left) - Detailed Inspection  |               | HRS                                |             | 994.2           |     |                  | 2051.9      |                    |             | 0            |
|                                    |                                                            |               | AFL                                |             | 392             |     |                  | 725         |                    |             | 0            |
|                                    |                                                            |               | MOS                                |             | 41.3            |     | 192              | 02 Dec 2022 | 31 Dec 2038        | 31 Jan 2039 |              |
|                                    | Airframe                                                   |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Notes: PN: 50028001-11 SN: <NONE>. |                                                            |               |                                    |             |                 |     |                  |             |                    |             |              |
| 712001                             | Engine Attach Pins and Bolts (Right) - Detailed Inspection |               | HRS                                |             | 994.2           |     |                  | 2051.9      |                    |             | 0            |
|                                    |                                                            |               | AFL                                |             | 392             |     |                  | 725         |                    |             | 0            |
|                                    |                                                            |               | MOS                                |             | 41.1            |     | 192              | 09 Dec 2022 | 31 Dec 2038        | 31 Jan 2039 |              |
|                                    | Airframe                                                   |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Notes: PN: 50028001-11 SN: <NONE>. |                                                            |               |                                    |             |                 |     |                  |             |                    |             |              |
| 712004                             | Engine Mount Attach Pins (Left) - Ndt Inspection           |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                                    |                                                            |               | AFL                                |             | 1117            |     | 6130**           | 0           | 6130               |             | 0            |
|                                    |                                                            |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                                    | Airframe                                                   |               |                                    |             |                 |     |                  |             |                    |             |              |
| 712005                             | Engine Mount Attach Pins (Right) - Ndt Inspection          |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                                    |                                                            |               | AFL                                |             | 1117            |     | 6130**           | 0           | 6130               |             | 0            |
|                                    |                                                            |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                                    | Airframe                                                   |               |                                    |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom  | Description                                              |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                              | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                       | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                   |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                            |               |     |             |                 |     |                  |             |                    |         |              |
| 712100           | Chatterproof Bolt Assembly (Left Engine) Forward Inboard |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | Upper - Removal / Installation                           |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | JR29859A                                                 | SN-UNKNOWN    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                          |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| 712101           | Chatterproof Bolt Assembly (Left Engine) Forward Inboard |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | Lower - Removal / Installation                           |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | JR29859A                                                 | SN-UNKNOWN    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                          |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| 712102           | Chatterproof Bolt Assembly (Right Engine) Forward        |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | Inboard Upper - Removal / Installation                   |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | JR29859A                                                 | SN-UNKNOWN    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                          |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| 712103           | Chatterproof Bolt Assembly (Right Engine) Forward        |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | Inboard Lower - Removal / Installation                   |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | JR29859A                                                 | SN-UNKNOWN    | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                          |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| 712104           | Engine Mount Fitting (Left Forward, FS 886) - Removal /  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | Installation                                             |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P7121001A001                                           | 0348          | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                          |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| 712105           | Engine Mount Fitting (Right Forward, FS 886) - Removal / |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | Installation                                             |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P7121002A001                                           | 0354          | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                          |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| 712112           | Engine Mount Attach Pins (Left Upper Forward) -          |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | Removal / Installation                                   |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P5344001A073                                           | PMS0395       | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                          |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                          |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                             |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                             | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                      | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                  |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| 712113           | Engine Mount Attach Pins (Left Upper Aft) - Removal / Installation      |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                         |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P5344001A075                                                          | PMS0400       | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                         |               | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Airframe                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| 712114           | Engine Mount Attach Pins (Left Lower Forward) - Removal / Installation  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                         |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P5344001A072                                                          | PMS0394       | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                         |               | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Airframe                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| 712115           | Engine Mount Attach Pins (Left Lower Aft) - Removal / Installation      |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                         |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P5344001A074                                                          | PMS0423       | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                         |               | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Airframe                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| 712116           | Engine Mount Attach Pins (Right Upper Forward) - Removal / Installation |               | HRS | TSN:1867.2  | 1178.9          |     |                  | 1867.2      |                    |         | 0            |
|                  |                                                                         |               | AFL | TSN:630     | 487             |     |                  | 630         |                    |         | 0            |
|                  | 60P5344001A073                                                          | PMS0396       | MOS | TSN:81      | 48.2            |     |                  | 04 May 2022 |                    |         |              |
|                  |                                                                         |               | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Airframe                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| 712117           | Engine Mount Attach Pins (Right Upper Aft) - Removal / Installation     |               | HRS | TSN:1867.2  | 1178.9          |     |                  | 1867.2      |                    |         | 0            |
|                  |                                                                         |               | AFL | TSN:630     | 487             |     |                  | 630         |                    |         | 0            |
|                  | 60P5344001A075                                                          | PMS0401       | MOS | TSN:81      | 48.2            |     |                  | 04 May 2022 |                    |         |              |
|                  |                                                                         |               | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Airframe                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| 712118           | Engine Mount Attach Pins (Right Lower Forward) - Removal / Installation |               | HRS | TSN:1867.2  | 1178.9          |     |                  | 1867.2      |                    |         | 0            |
|                  |                                                                         |               | AFL | TSN:630     | 487             |     |                  | 630         |                    |         | 0            |
|                  | 60P5344001A072                                                          | PMS0400       | MOS | TSN:81      | 48.2            |     |                  | 04 May 2022 |                    |         |              |
|                  |                                                                         |               | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Airframe                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| 712119           | Engine Mount Attach Pins (Right Lower Aft) - Removal / Installation     |               | HRS | TSN:1867.2  | 1178.9          |     |                  | 1867.2      |                    |         | 0            |
|                  |                                                                         |               | AFL | TSN:630     | 487             |     |                  | 630         |                    |         | 0            |
|                  | 60P5344001A074                                                          | PMS0431       | MOS | TSN:81      | 48.2            |     |                  | 04 May 2022 |                    |         |              |
|                  |                                                                         |               | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Airframe                                                                |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom                                                | Description                                                                  |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due     | Avg Man Hrs  |
|----------------------------------------------------------------|------------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|---------------------|-------------|--------------|
|                                                                | Part Number                                                                  | Serial Number |                                    |             |                 |     |                  |             |                     |             | Approx Price |
| Logbook Position                                               | HW                                                                           | SW            |                                    |             |                 |     |                  |             |                     |             | Manufacturer |
|                                                                | MM Ref                                                                       |               |                                    |             |                 |     |                  |             |                     |             | Date Type    |
|                                                                | Ops Number(s)                                                                |               |                                    |             |                 |     |                  |             |                     |             |              |
| 712126                                                         | Engine Mount Attach Pins (Right Lower Forward) - Replacement                 |               | HRS                                |             | 3046.1          |     |                  | 0           |                     |             | 0            |
|                                                                |                                                                              |               | AFL                                |             | 1117            |     |                  | 0           |                     | 0           |              |
|                                                                |                                                                              |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                     |             |              |
|                                                                |                                                                              |               | MSC                                |             |                 |     | O/C              |             |                     |             |              |
| Airframe                                                       |                                                                              |               |                                    |             |                 |     |                  |             |                     |             |              |
| Notes: PN: 60P5344001A072 SN: PMS0400. MRI PARENT CODE: 712118 |                                                                              |               |                                    |             |                 |     |                  |             |                     |             |              |
| 712128                                                         | Forward Engine Mount (Left) - Detailed Inspection                            |               | HRS                                |             | 3046.1          |     |                  | 0           |                     |             | 0            |
|                                                                |                                                                              |               | AFL                                |             | 1117            |     |                  | 0           |                     | 0           |              |
|                                                                |                                                                              |               | MOS                                |             | 122             |     | 192              | 11 Mar 2016 | 31 Mar 2032         | 30 Apr 2032 |              |
|                                                                |                                                                              |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                     |             |              |
| Airframe                                                       |                                                                              |               |                                    |             |                 |     |                  |             |                     |             |              |
| 052021                                                         |                                                                              |               |                                    |             |                 |     |                  |             |                     |             |              |
| 712129                                                         | Forward Engine Mount (Right) - Detailed Inspection                           |               | HRS                                |             | 3046.1          |     |                  | 0           |                     |             | 0            |
|                                                                |                                                                              |               | AFL                                |             | 1117            |     |                  | 0           |                     | 0           |              |
|                                                                |                                                                              |               | MOS                                |             | 122             |     | 192              | 11 Mar 2016 | 31 Mar 2032         | 30 Apr 2032 |              |
|                                                                |                                                                              |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                     |             |              |
| Airframe                                                       |                                                                              |               |                                    |             |                 |     |                  |             |                     |             |              |
| 052021                                                         |                                                                              |               |                                    |             |                 |     |                  |             |                     |             |              |
| 712130                                                         | Forward Engine Mount Thrust Pin and Sleeve (Left) - Detailed Inspection      |               | HRS                                |             | 994.2           |     |                  | 2051.9      |                     |             | 0            |
|                                                                |                                                                              |               | AFL                                |             | 392             |     |                  | 725         |                     | 0           |              |
|                                                                |                                                                              |               | MOS                                |             | 41.3            |     | 192              | 02 Dec 2022 | 31 Dec 2038         | 31 Jan 2039 |              |
|                                                                |                                                                              |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                     |             |              |
| Airframe                                                       |                                                                              |               |                                    |             |                 |     |                  |             |                     |             |              |
| 712131                                                         | Forward Engine Mount Thrust Pin and Sleeve (Right) - Detailed Inspection     |               | HRS                                |             | 994.2           |     |                  | 2051.9      |                     |             | 0            |
|                                                                |                                                                              |               | AFL                                |             | 392             |     |                  | 725         |                     | 0           |              |
|                                                                |                                                                              |               | MOS                                |             | 41.1            |     | 192              | 09 Dec 2022 | 31 Dec 2038         | 31 Jan 2039 |              |
|                                                                |                                                                              |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                     |             |              |
| Airframe                                                       |                                                                              |               |                                    |             |                 |     |                  |             |                     |             |              |
| 712132                                                         | Thrust and Alignment Strut Assemblies External (Left) - Detailed Inspection  |               | HRS                                |             | 3046.1          |     |                  | 0           |                     |             | 0            |
|                                                                |                                                                              |               | AFL                                |             | 1117            |     |                  | 0           |                     | 0           |              |
|                                                                |                                                                              |               | MOS                                |             | 122             |     | 192              | 11 Mar 2016 | 31 Mar 2032         | 30 Apr 2032 |              |
|                                                                |                                                                              |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                     |             |              |
| Airframe                                                       |                                                                              |               |                                    |             |                 |     |                  |             |                     |             |              |
| 052021                                                         |                                                                              |               |                                    |             |                 |     |                  |             |                     |             |              |
| 712133                                                         | Thrust and Alignment Strut Assemblies External (Right) - Detailed Inspection |               | HRS                                |             | 3046.1          |     |                  | 0           |                     |             | 0            |
|                                                                |                                                                              |               | AFL                                |             | 1117            |     |                  | 0           |                     | 0           |              |
|                                                                |                                                                              |               | MOS                                |             | 122             |     | 192              | 11 Mar 2016 | 31 Mar 2032         | 30 Apr 2032 |              |
|                                                                |                                                                              |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                     |             |              |
| Airframe                                                       |                                                                              |               |                                    |             |                 |     |                  |             |                     |             |              |
| 052021                                                         |                                                                              |               |                                    |             |                 |     |                  |             |                     |             |              |

| ATA<br>U=Custom  | Description                                                                                    |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------|------------------------------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                  | Part Number                                                                                    | Serial Number |                                    |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position | HW                                                                                             | SW            |                                    |             |                 |     |                  |             |                    |             | Manufacturer |
|                  | MM Ref                                                                                         |               |                                    |             |                 |     |                  |             |                    |             | Date Type    |
|                  | Ops Number(s)                                                                                  |               |                                    |             |                 |     |                  |             |                    |             |              |
| 712134           | Thrust and Alignment Strut Assemblies Internal (Left) -<br>Special Detailed Inspection         |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                |               | MOS                                |             | 122             |     | 192              | 11 Mar 2016 | 31 Mar 2032        | 30 Apr 2032 |              |
|                  |                                                                                                |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                                |               | 052021                             |             |                 |     |                  |             |                    |             |              |
| 712135           | Thrust and Alignment Strut Assemblies Internal (Right) -<br>Special Detailed Inspection        |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                |               | MOS                                |             | 122             |     | 192              | 11 Mar 2016 | 31 Mar 2032        | 30 Apr 2032 |              |
|                  |                                                                                                |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                                |               | 052021                             |             |                 |     |                  |             |                    |             |              |
| 712136           | Forward Engine Mount Fitting Left Lower Forward -<br>Removal / Installation<br>60P5344001M005  |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                |               | MOS                                | NSN         | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                                |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                                |               |                                    |             |                 |     |                  |             |                    |             |              |
| 712137           | Forward Engine Mount Fitting Right Lower Forward-<br>Removal / Installation<br>60P5344001M005  |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                |               | MOS                                | NSN         | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                                |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                                |               |                                    |             |                 |     |                  |             |                    |             |              |
| 712138           | Forward Engine Mount Fitting Left Upper Forward -<br>Removal / Installation<br>60P5344001M004  |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                |               | MOS                                | NSN         | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                                |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                                |               |                                    |             |                 |     |                  |             |                    |             |              |
| 712139           | Forward Engine Mount Fitting Right Upper Forward -<br>Removal / Installation<br>60P5344001M004 |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                |               | MOS                                | NSN         | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                                |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                                |               |                                    |             |                 |     |                  |             |                    |             |              |
| 712140           | Forward Engine Mount Fitting Left Lower Aft - Removal /<br>Installation<br>60P5344001M110      |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                |               | MOS                                | NSN         | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                                |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                                |               |                                    |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom  | Description                                                            |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(* =Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|----------------------|---------|--------------|
|                  | Part Number                                                            | Serial Number |     |             |                 |     |                  |             |                      |         | Approx Price |
| Logbook Position | HW                                                                     | SW            |     |             |                 |     |                  |             |                      |         | Manufacturer |
|                  | MM Ref                                                                 |               |     |             |                 |     |                  |             |                      |         | Date Type    |
|                  | Ops Number(s)                                                          |               |     |             |                 |     |                  |             |                      |         |              |
| 712141           | Forward Engine Mount Fitting Right Lower Aft - Removal / Installation  |               | HRS |             | 3046.1          |     |                  | 0           |                      |         | 0            |
|                  |                                                                        |               | AFL |             | 1117            |     |                  | 0           |                      |         | 0            |
|                  | 60P5344001M110                                                         | NSN           | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                      |         |              |
|                  |                                                                        |               | MSC |             |                 |     | O/C              |             |                      |         |              |
| Airframe         |                                                                        |               |     |             |                 |     |                  |             |                      |         |              |
| 712142           | Forward Engine Mount Fitting Right Upper Aft - Removal / Installation  |               | HRS |             | 3046.1          |     |                  | 0           |                      |         | 0            |
|                  |                                                                        |               | AFL |             | 1117            |     |                  | 0           |                      |         | 0            |
|                  | 60P5344001M111                                                         | NSN           | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                      |         |              |
|                  |                                                                        |               | MSC |             |                 |     | O/C              |             |                      |         |              |
| Airframe         |                                                                        |               |     |             |                 |     |                  |             |                      |         |              |
| 712143           | Forward Engine Mount Fitting Left Upper Aft - Removal / Installation   |               | HRS |             | 3046.1          |     |                  | 0           |                      |         | 0            |
|                  |                                                                        |               | AFL |             | 1117            |     |                  | 0           |                      |         | 0            |
|                  | 60P5344001M111                                                         | NSN           | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                      |         |              |
|                  |                                                                        |               | MSC |             |                 |     | O/C              |             |                      |         |              |
| Airframe         |                                                                        |               |     |             |                 |     |                  |             |                      |         |              |
| 712200           | Engine Mount (Left Aft, FS 951) - Removal / Installation               |               | HRS |             | 3046.1          |     |                  | 0           |                      |         | 0            |
|                  |                                                                        |               | AFL |             | 1117            |     |                  | 0           |                      |         | 0            |
|                  | 60P7122601Z001                                                         | TY-316        | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                      |         |              |
|                  |                                                                        |               | MSC |             |                 |     | O/C              |             |                      |         |              |
| Airframe         |                                                                        |               |     |             |                 |     |                  |             |                      |         |              |
| 712201           | Engine Mount (Right Aft, FS 951) - Removal / Installation              |               | HRS |             | 3046.1          |     |                  | 0           |                      |         | 0            |
|                  |                                                                        |               | AFL |             | 1117            |     |                  | 0           |                      |         | 0            |
|                  | 60P7122601Z001                                                         | TY-314        | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                      |         |              |
|                  |                                                                        |               | MSC |             |                 |     | O/C              |             |                      |         |              |
| Airframe         |                                                                        |               |     |             |                 |     |                  |             |                      |         |              |
| 712206           | Aft Engine Mount Fitting - Left Upper Forward - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                      |         | 0            |
|                  |                                                                        |               | AFL |             | 1117            |     |                  | 0           |                      |         | 0            |
|                  | 60P5342001A047                                                         | CII0301       | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                      |         |              |
|                  |                                                                        |               | MSC |             |                 |     | O/C              |             |                      |         |              |
| Airframe         |                                                                        |               |     |             |                 |     |                  |             |                      |         |              |
| 712207           | Aft Engine Mount Fitting - Left Upper Aft - Removal / Installation     |               | HRS |             | 3046.1          |     |                  | 0           |                      |         | 0            |
|                  |                                                                        |               | AFL |             | 1117            |     |                  | 0           |                      |         | 0            |
|                  | 60P5342001A048                                                         | CII0309       | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                      |         |              |
|                  |                                                                        |               | MSC |             |                 |     | O/C              |             |                      |         |              |
| Airframe         |                                                                        |               |     |             |                 |     |                  |             |                      |         |              |



| ATA<br>U=Custom  | Description                                                             |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|-------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                                             | Serial Number |     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                                      | SW            |     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                                  |               |     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                                           |               |     |             |                 |     |                  |             |                     |         |              |
| 712208           | Aft Engine Mount Fitting - Left Lower Forward - Removal / Installation  |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                         |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 60P5342001A045                                                          | CII0313       | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                         |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                         |               |     |             |                 |     |                  |             |                     |         |              |
| 712209           | Aft Engine Mount Fitting - Left Lower Aft - Removal / Installation      |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                         |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 60P5342001A046                                                          | CII0293       | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                         |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                         |               |     |             |                 |     |                  |             |                     |         |              |
| 712210           | Aft Engine Mount Fitting - Right Upper Forward - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                         |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 60P5342001A047                                                          | CII0308       | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                         |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                         |               |     |             |                 |     |                  |             |                     |         |              |
| 712211           | Aft Engine Mount Fitting - Right Upper Aft - Removal / Installation     |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                         |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 60P5342001A048                                                          | CII0310       | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                         |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                         |               |     |             |                 |     |                  |             |                     |         |              |
| 712212           | Aft Engine Mount Fitting - Right Lower Forward - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                         |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 60P5342001A045                                                          | CII0314       | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                         |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                         |               |     |             |                 |     |                  |             |                     |         |              |
| 712213           | Aft Engine Mount Fitting - Right Lower Aft - Removal / Installation     |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                         |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 60P5342001A046                                                          | CII0310       | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                         |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                         |               |     |             |                 |     |                  |             |                     |         |              |
| 712214           | Aft Engine Mount Fitting, Lh/Lwr/Fwd - Removal / Installation           |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                         |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 60P5342001M113                                                          | CII0313       | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                         |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                         |               |     |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom  | Description                                      |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|--------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                      | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                               | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                           |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                    |               |     |             |                 |     |                  |             |                    |         |              |
| 712215           | Aft Engine Mount Fitting, Rh/Lwr/Fwd - Removal / |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | Installation                                     |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P5342001M113                                   | CII0314       | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                  |               |     |             |                 |     |                  |             |                    |         |              |
| 712216           | Aft Engine Mount Fitting, Lh/Lwr/Aft - Removal / |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | Installation                                     |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P5342001M265                                   | CII0293       | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                  |               |     |             |                 |     |                  |             |                    |         |              |
| 712217           | Aft Engine Mount Fitting, Rh/Lwr/Aft - Removal / |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | Installation                                     |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P5342001M265                                   | CII0310       | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                  |               |     |             |                 |     |                  |             |                    |         |              |
| 712218           | Aft Engine Mount Fitting, Lh/UPR/Fwd - Removal / |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | Installation                                     |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P5342001M264                                   | CII0301       | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                  |               |     |             |                 |     |                  |             |                    |         |              |
| 712219           | Aft Engine Mount Fitting, Rh/UPR/Fwd - Removal / |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | Installation                                     |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P5342001M264                                   | CII0308       | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                  |               |     |             |                 |     |                  |             |                    |         |              |
| 712220           | Aft Engine Mount Fitting, Lh/UPR/Aft - Removal / |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | Installation                                     |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P5342001M263                                   | CII0309       | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                  |               |     |             |                 |     |                  |             |                    |         |              |
| 712221           | Aft Engine Mount Fitting, Rh/UPR/Aft - Removal / |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | Installation                                     |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P5342001M263                                   | CII0310       | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                  |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                  |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                                 |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------|---------------------------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                  | Part Number                                                                                 | Serial Number |                                    |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position | HW                                                                                          | SW            |                                    |             |                 |     |                  |             |                    |             | Manufacturer |
|                  | MM Ref                                                                                      |               |                                    |             |                 |     |                  |             |                    |             | Date Type    |
|                  | Ops Number(s)                                                                               |               |                                    |             |                 |     |                  |             |                    |             |              |
| 712226           | Aft Engine Mount Strut Assemblies External (Left) - Detailed Inspection                     |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                             |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                             |               | MOS                                |             | 122             |     | 192              | 11 Mar 2016 | 31 Mar 2032        | 30 Apr 2032 |              |
|                  |                                                                                             |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                             | 052021        |                                    |             |                 |     |                  |             |                    |             |              |
| 712227           | Aft Engine Mount Strut Assemblies External (Right) - Detailed Inspection                    |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                             |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                             |               | MOS                                |             | 122             |     | 192              | 11 Mar 2016 | 31 Mar 2032        | 30 Apr 2032 |              |
|                  |                                                                                             |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                             | 052021        |                                    |             |                 |     |                  |             |                    |             |              |
| 712228           | Aft Engine Mount Strut Assemblies Internal (Left) - Special Detailed Inspection             |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                             |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                             |               | MOS                                |             | 122             |     | 192              | 11 Mar 2016 | 31 Mar 2032        | 30 Apr 2032 |              |
|                  |                                                                                             |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                             | 052021        |                                    |             |                 |     |                  |             |                    |             |              |
| 712229           | Aft Engine Mount Strut Assemblies Internal (Right) - Special Detailed Inspection            |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                             |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                             |               | MOS                                |             | 122             |     | 192              | 11 Mar 2016 | 31 Mar 2032        | 30 Apr 2032 |              |
|                  |                                                                                             |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Airframe         |                                                                                             | 052021        |                                    |             |                 |     |                  |             |                    |             |              |
| 712230           | Engine Aft Upper Suspension Strut (Left) - Removal / Installation<br>60P7122201Z001TY-0346  |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                             |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                             |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                             |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                             |               |                                    |             |                 |     |                  |             |                    |             |              |
| 712231           | Engine Aft Upper Suspension Strut (Right) - Removal / Installation<br>60P7122201Z001TY-0343 |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                             |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                             |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                             |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                             |               |                                    |             |                 |     |                  |             |                    |             |              |
| 712232           | Engine Aft Lower Suspension Strut (Left) - Removal / Installation<br>60P7122301Z001TY-0342  |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |             | 0            |
|                  |                                                                                             |               | AFL                                |             | 1117            |     |                  | 0           |                    |             | 0            |
|                  |                                                                                             |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |             |              |
|                  |                                                                                             |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Airframe         |                                                                                             |               |                                    |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom  | Description                                                         |                 | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|---------------------------------------------------------------------|-----------------|-----|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                                         | Serial Number   |     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                                  | SW              |     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                              |                 |     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                                       |                 |     |             |                 |     |                  |             |                     |         |              |
| 712233           | Engine Aft Lower Suspension Strut (Right) - Removal / Installation  |                 | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                     |                 | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 60P7122301Z001                                                      | TY-0349         | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                     |                 | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                     |                 |     |             |                 |     |                  |             |                     |         |              |
| 712300           | Forward Upper Inboard Link (Left Engine) - Removal / Installation   |                 | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                     |                 | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 60P7123101Z001                                                      | 0673            | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                     |                 | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                     |                 |     |             |                 |     |                  |             |                     |         |              |
| 712301           | Forward Lower Engine Link (Left) - Removal / Installation           |                 | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                     |                 | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 60P7123101Z001                                                      | 0664            | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                     |                 | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                     |                 |     |             |                 |     |                  |             |                     |         |              |
| 712302           | Forward Upper Inboard Link (Right Engine) - Removal / Installation  |                 | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                     |                 | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 60P7123101Z001                                                      | 0672            | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                     |                 | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                     |                 |     |             |                 |     |                  |             |                     |         |              |
| 712303           | Forward Lower Engine Link (Right) - Removal / Installation          |                 | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                     |                 | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 60P7123101Z001                                                      | 0674            | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                     |                 | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                     |                 |     |             |                 |     |                  |             |                     |         |              |
| 712304           | Fuselage Engine Mount Link (Left Forward) - Removal / Installation  |                 | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                     |                 | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 60P7123001A010                                                      | J095031-000-004 | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                     |                 | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                     |                 |     |             |                 |     |                  |             |                     |         |              |
| 712305           | Fuselage Engine Mount Link (Right Forward) - Removal / Installation |                 | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                     |                 | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 60P7123001A010                                                      | J095031-000-010 | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                     |                 | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                     |                 |     |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom  | Description                                                                       |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(* =Adj) | Max Due | Avg Man Hrs  |
|------------------|-----------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|----------------------|---------|--------------|
|                  | Part Number                                                                       | Serial Number |     |             |                 |     |                  |             |                      |         | Approx Price |
| Logbook Position | HW                                                                                | SW            |     |             |                 |     |                  |             |                      |         | Manufacturer |
|                  | MM Ref                                                                            |               |     |             |                 |     |                  |             |                      |         | Date Type    |
|                  | Ops Number(s)                                                                     |               |     |             |                 |     |                  |             |                      |         |              |
| 712306           | Engine Mount Retaining CAP (Left Aft Upper) - Removal / Installation              |               | HRS |             | 3046.1          |     |                  | 0           |                      |         | 0            |
|                  |                                                                                   |               | AFL |             | 1117            |     |                  | 0           |                      |         | 0            |
|                  | 60P7123001M004                                                                    | 2231          | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                      |         |              |
|                  |                                                                                   |               | MSC |             |                 |     | O/C              |             |                      |         |              |
| Airframe         |                                                                                   |               |     |             |                 |     |                  |             |                      |         |              |
| 712307           | Engine Mount Retaining CAP (Right Aft Upper) - Removal / Installation             |               | HRS |             | 3046.1          |     |                  | 0           |                      |         | 0            |
|                  |                                                                                   |               | AFL |             | 1117            |     |                  | 0           |                      |         | 0            |
|                  | 60P7123001M004                                                                    | 2321          | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                      |         |              |
|                  |                                                                                   |               | MSC |             |                 |     | O/C              |             |                      |         |              |
| Airframe         |                                                                                   |               |     |             |                 |     |                  |             |                      |         |              |
| 712308           | Engine Mount Retaining CAP (Left Aft Lower) - Removal / Installation              |               | HRS |             | 3046.1          |     |                  | 0           |                      |         | 0            |
|                  |                                                                                   |               | AFL |             | 1117            |     |                  | 0           |                      |         | 0            |
|                  | 60P7123001M004                                                                    | 2245          | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                      |         |              |
|                  |                                                                                   |               | MSC |             |                 |     | O/C              |             |                      |         |              |
| Airframe         |                                                                                   |               |     |             |                 |     |                  |             |                      |         |              |
| 712309           | Engine Mount Retaining CAP (Right Aft Lower) - Removal / Installation             |               | HRS |             | 3046.1          |     |                  | 0           |                      |         | 0            |
|                  |                                                                                   |               | AFL |             | 1117            |     |                  | 0           |                      |         | 0            |
|                  | 60P7123001M004                                                                    | 2214          | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                      |         |              |
|                  |                                                                                   |               | MSC |             |                 |     | O/C              |             |                      |         |              |
| Airframe         |                                                                                   |               |     |             |                 |     |                  |             |                      |         |              |
| 712310           | Engine Mount Retaining CAP (Left Forward Inboard Upper) - Removal / Installation  |               | HRS |             | 3046.1          |     |                  | 0           |                      |         | 0            |
|                  |                                                                                   |               | AFL |             | 1117            |     |                  | 0           |                      |         | 0            |
|                  | 60P7123001M005                                                                    | 1058          | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                      |         |              |
|                  |                                                                                   |               | MSC |             |                 |     | O/C              |             |                      |         |              |
| Airframe         |                                                                                   |               |     |             |                 |     |                  |             |                      |         |              |
| 712311           | Engine Mount Retaining CAP (Right Forward Inboard Upper) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                      |         | 0            |
|                  |                                                                                   |               | AFL |             | 1117            |     |                  | 0           |                      |         | 0            |
|                  | 60P7123001M005                                                                    | 1101          | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                      |         |              |
|                  |                                                                                   |               | MSC |             |                 |     | O/C              |             |                      |         |              |
| Airframe         |                                                                                   |               |     |             |                 |     |                  |             |                      |         |              |
| 712312           | Engine Mount Retaining CAP (Left Forward Inboard Lower) - Removal / Installation  |               | HRS |             | 3046.1          |     |                  | 0           |                      |         | 0            |
|                  |                                                                                   |               | AFL |             | 1117            |     |                  | 0           |                      |         | 0            |
|                  | 60P7123001M005                                                                    | 1056          | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                      |         |              |
|                  |                                                                                   |               | MSC |             |                 |     | O/C              |             |                      |         |              |
| Airframe         |                                                                                   |               |     |             |                 |     |                  |             |                      |         |              |

| ATA<br>U=Custom  | Description                                                                        |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                        | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                                 | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                             |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                                      |               |     |             |                 |     |                  |             |                    |         |              |
| 712313           | Engine Mount Retaining CAP (Right Forward Inboard Lower) - Removal / Installation  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                    |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P7123001M005                                                                     | 1102          | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                    |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                    |               |     |             |                 |     |                  |             |                    |         |              |
| 712314           | Engine Mount Retaining CAP (Left Forward Outboard Upper) - Removal / Installation  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                    |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P7123001M005                                                                     | 1057          | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                    |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                    |               |     |             |                 |     |                  |             |                    |         |              |
| 712315           | Engine Mount Retaining CAP (Right Forward Outboard Upper) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                    |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P7123001M005                                                                     | 1100          | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                    |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                    |               |     |             |                 |     |                  |             |                    |         |              |
| 712316           | Engine Mount Thrust Strut Retaining CAP (Left Forward) - Removal / Installation    |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                    |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P7123001M004                                                                     | 2226          | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                    |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                    |               |     |             |                 |     |                  |             |                    |         |              |
| 712317           | Engine Mount Thrust Strut Retaining CAP (Right Forward) - Removal / Installation   |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                    |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P7123001M004                                                                     | 2218          | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                    |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                    |               |     |             |                 |     |                  |             |                    |         |              |
| 712318           | Engine Mount Thrust Strut Retaining CAP (Left Aft) - Removal / Installation        |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                    |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P7123001M004                                                                     | 2247          | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                    |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                    |               |     |             |                 |     |                  |             |                    |         |              |
| 712319           | Engine Mount Thrust Strut Retaining CAP (Right Aft) - Removal / Installation       |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                    |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P7123001M004                                                                     | 2209          | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                    |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                    |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                         |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                         | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                                  | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                              |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| 712320           | Engine Mount Alignment Strut Retaining CAP (Left Forward) - Removal / Installation  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                     |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P7123001M006                                                                      | 369           | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                     |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| 712321           | Engine Mount Alignment Strut Retaining CAP (Right Forward) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                     |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P7123001M006                                                                      | 401           | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                     |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| 712322           | Engine Mount Thrust Strut (Left) - Removal / Installation                           |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P7123401Z001 TY-0378                                                              |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                     |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                     |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| 712323           | Engine Mount Thrust Strut (Right) - Removal / Installation                          |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 60P7123401Z002 TY-0359                                                              |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                                     |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                     |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| 712324           | Engine Mount Alignment Strut (Left) - Removal / Installation                        |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                     |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P7123501Z001                                                                      | TY-0381       | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                     |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| 712325           | Engine Mount Alignment Strut (Right) - Removal / Installation                       |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                     |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P7123501Z002                                                                      | TY-0388       | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                     |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| 712326           | Engine Mount Link Attach Pin (Left Forward Inboard) - Removal / Installation        |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                     |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P7123001M025                                                                      | 356           | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                     |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                     |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                    |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|--------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                    | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                             | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                         |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                                  |               |     |             |                 |     |                  |             |                    |         |              |
| 712327           | Engine Mount Link Attach Pin (Right Forward Inboard) - Removal / Installation  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P7123001M025                                                                 | 358           | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| 712328           | Engine Mount Link Attach Pin (Left Forward Outboard) - Removal / Installation  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P7123001M024                                                                 | 337           | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| 712329           | Engine Mount Link Attach Pin (Right Forward Outboard) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P7123001M024                                                                 | 418           | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| 712330           | Engine Mount Attach Pin (Left Forward Lower) - Removal / Installation          |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P7123001M030                                                                 | 369           | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| 712331           | Engine Mount Attach Pin (Right Forward Lower) - Removal / Installation         |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P7123001M030                                                                 | 376           | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| 712332           | Engine Mount Attach Pin (Left Aft Lower) - Removal / Installation              |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P7123001M034                                                                 | 390           | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| 712333           | Engine Mount Attach Pin (Right Aft Lower) - Removal / Installation             |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P7123001M034                                                                 | 398           | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                |               |     |             |                 |     |                  |             |                    |         |              |



| ATA<br>U=Custom  | Description                                               |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-----------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                               | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                        | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                    |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                             |               |     |             |                 |     |                  |             |                    |         |              |
| 712334           | Engine Mount Attach Pin (Left Aft Inboard Upper) -        |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | Removal / Installation                                    |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P7123001M026                                            | 395           | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                           |               | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Airframe                                                  |               |     |             |                 |     |                  |             |                    |         |              |
| 712335           | Engine Mount Attach Pin (Right Aft Inboard Upper) -       |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | Removal / Installation                                    |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P7123001M026                                            | 362           | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                           |               | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Airframe                                                  |               |     |             |                 |     |                  |             |                    |         |              |
| 712336           | Engine Mount Thrust Strut Attach Pin (Left Forward) -     |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | Removal / Installation                                    |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P7123001M027                                            | 396           | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                           |               | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Airframe                                                  |               |     |             |                 |     |                  |             |                    |         |              |
| 712337           | Engine Mount Thrust Strut Attach Pin (Right Forward) -    |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | Removal / Installation                                    |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P7123001M027                                            | 406           | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                           |               | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Airframe                                                  |               |     |             |                 |     |                  |             |                    |         |              |
| 712338           | Engine Mount Thrust Strut Attach Pin (Left Aft) - Removal |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | / Installation                                            |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P7123001M029                                            | 432           | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                           |               | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Airframe                                                  |               |     |             |                 |     |                  |             |                    |         |              |
| 712339           | Engine Mount Thrust Strut Attach Pin (Right Aft) -        |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | Removal / Installation                                    |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P7123001M029                                            | 396           | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                           |               | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Airframe                                                  |               |     |             |                 |     |                  |             |                    |         |              |
| 712340           | Engine Mount Alignment Strut Attach Pin (Left Forward) -  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | Removal / Installation                                    |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P7123001M028                                            | 445           | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                           |               | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Airframe                                                  |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                              |                 | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------------|-----------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                              | Serial Number   |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                       | SW              |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                   |                 |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                            |                 |     |             |                 |     |                  |             |                    |         |              |
| 712341           | Engine Mount Alignment Strut Attach Pin (Right Forward)  |                 | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | - Removal / Installation                                 |                 | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P7123001M028                                           | 454             | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                          |                 | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                          |                 |     |             |                 |     |                  |             |                    |         |              |
| 712342           | Pin, - Engine to Engine Mount, Right Engine Forward      |                 | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | Inboard Lower - Removal / Installation                   |                 | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P7123001M022                                           | 813             | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                          |                 | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                          |                 |     |             |                 |     |                  |             |                    |         |              |
| 712343           | Pin, - Engine to Engine Mount, Left Engine Forward       |                 | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | Inboard Upper - Removal / Installation                   |                 | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P7123001M022                                           | 786             | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                          |                 | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                          |                 |     |             |                 |     |                  |             |                    |         |              |
| 712344           | Pin, - Engine to Engine Mount, Aft - Left - Removal /    |                 | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | Installation                                             |                 | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P7123001M023                                           | 357             | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                          |                 | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                          |                 |     |             |                 |     |                  |             |                    |         |              |
| 712345           | Pin, Thrust - Engine Mount, Forward - Left Engine -      |                 | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | Removal / Installation                                   |                 | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P7123001A001                                           | J092791-000-021 | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                          |                 | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                          |                 |     |             |                 |     |                  |             |                    |         |              |
| 712346           | Pin, Hollow - Engine to Engine Mount, Fwd - Removal /    |                 | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | Installation                                             |                 | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P7123001M022                                           | 810             | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                          |                 | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                          |                 |     |             |                 |     |                  |             |                    |         |              |
| 712347           | Pin, - Engine to Engine Mount, Forward - Right - Removal |                 | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | / Installation                                           |                 | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | 60P7123001M022                                           | 787             | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                          |                 | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                          |                 |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                             |                 | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|-----------------------------------------------------------------------------------------|-----------------|-----|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                                                             | Serial Number   |     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                                                      | SW              |     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                                                  |                 |     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                                                           |                 |     |             |                 |     |                  |             |                     |         |              |
| 712348           | Pin, - Engine to Engine Mount, Aft - Right - Removal / Installation                     |                 | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                                         |                 | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 60P7123001M023                                                                          | 365             | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                                         |                 | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                         |                 |     |             |                 |     |                  |             |                     |         |              |
| 712349           | Pin, Thrust - Engine Mount, Forward - Right Engine - Removal / Installation             |                 | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                                         |                 | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 60P7123001A001                                                                          | J092791-000-016 | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                                         |                 | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                         |                 |     |             |                 |     |                  |             |                     |         |              |
| 712352           | Retaining CAP - Forward Engine Mount Link Upper (Left Engine) - Removal / Installation  |                 | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                                         |                 | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 60P7123001M004                                                                          | 2246            | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                                         |                 | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                         |                 |     |             |                 |     |                  |             |                     |         |              |
| 712353           | Retaining CAP - Forward Engine Mount Link Upper (Right Engine) - Removal / Installation |                 | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                                         |                 | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 60P7123001M004                                                                          | 2115            | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                                         |                 | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                         |                 |     |             |                 |     |                  |             |                     |         |              |
| 712354           | Retaining CAP - Forward Engine Mount Link Lower (Left Engine) - Removal / Installation  |                 | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                                         |                 | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 60P7123001M004                                                                          | 2221            | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                                         |                 | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                         |                 |     |             |                 |     |                  |             |                     |         |              |
| 712355           | Retaining CAP - Forward Engine Mount Link Lower (Right Engine) - Removal / Installation |                 | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                                         |                 | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 60P7123001M004                                                                          | 2276            | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                                         |                 | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                         |                 |     |             |                 |     |                  |             |                     |         |              |
| 712394           | Left Thrust Strut Fitting Assembly - Removal / Installation                             |                 | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                                         |                 | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 60P5347001A006                                                                          | PMS0118         | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                                                         |                 | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                                                         |                 |     |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom  | Description                                                       |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due     | Avg Man Hrs  |
|------------------|-------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|---------------------|-------------|--------------|
|                  | Part Number                                                       | Serial Number |                                    |             |                 |     |                  |             |                     |             | Approx Price |
| Logbook Position | HW                                                                | SW            |                                    |             |                 |     |                  |             |                     |             | Manufacturer |
|                  | MM Ref                                                            |               |                                    |             |                 |     |                  |             |                     |             | Date Type    |
|                  | Ops Number(s)                                                     |               |                                    |             |                 |     |                  |             |                     |             |              |
| 712396           | Right Thrust Strut Fitting Assembly - Removal / Installation      |               | HRS                                |             | 3046.1          |     |                  | 0           |                     |             | 0            |
|                  | 60P5347002A005                                                    |               | AFL                                |             | 1117            |     |                  | 0           |                     |             | 0            |
|                  |                                                                   |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                     |             |              |
|                  |                                                                   |               | MSC                                |             |                 |     | O/C              |             |                     |             |              |
| Airframe         |                                                                   |               |                                    |             |                 |     |                  |             |                     |             |              |
| 712398           | Link Assemblies (Left) - Detailed Inspection                      |               | HRS                                |             | 3046.1          |     |                  | 0           |                     |             | 0            |
|                  |                                                                   |               | AFL                                |             | 1117            |     |                  | 0           |                     |             | 0            |
|                  |                                                                   |               | MOS                                |             | 122             |     | 192              | 11 Mar 2016 | 31 Mar 2032         | 30 Apr 2032 |              |
|                  |                                                                   |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                     |             |              |
| Airframe         | 052021                                                            |               |                                    |             |                 |     |                  |             |                     |             |              |
| 712399           | Link Assemblies (Right) - Detailed Inspection                     |               | HRS                                |             | 3046.1          |     |                  | 0           |                     |             | 0            |
|                  |                                                                   |               | AFL                                |             | 1117            |     |                  | 0           |                     |             | 0            |
|                  |                                                                   |               | MOS                                |             | 122             |     | 192              | 11 Mar 2016 | 31 Mar 2032         | 30 Apr 2032 |              |
|                  |                                                                   |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                     |             |              |
| Airframe         | 052021                                                            |               |                                    |             |                 |     |                  |             |                     |             |              |
| 715000           | No. 1 Engine - Electrical Harnesses - Inspection                  |               | HRS                                |             | 994.4           |     |                  | 0           |                     |             | 0            |
|                  |                                                                   |               | ENC                                |             | 392             |     |                  | 0           |                     |             | 0            |
|                  |                                                                   |               | MOS                                |             | 41.8            |     |                  | 17 Nov 2022 |                     |             |              |
|                  |                                                                   |               | MSC                                |             |                 |     | O/C              |             |                     |             |              |
| Engine           |                                                                   |               | [End Of Month Item]                |             |                 |     |                  |             |                     |             |              |
| 715000           | No. 2 Engine - Electrical Harnesses - Inspection                  |               | HRS                                |             | 994.4           |     |                  | 0           |                     |             | 0            |
|                  |                                                                   |               | ENC                                |             | 392             |     |                  | 0           |                     |             | 0            |
|                  |                                                                   |               | MOS                                |             | 41.9            |     |                  | 15 Nov 2022 |                     |             |              |
|                  |                                                                   |               | MSC                                |             |                 |     | O/C              |             |                     |             |              |
| Engine           |                                                                   |               | [End Of Month Item]                |             |                 |     |                  |             |                     |             |              |
| 715001           | No. 1 Engine - Electrical Harnesses - Insulation Resistance Check |               | HRS                                |             | 994.4           |     |                  | 0           |                     |             | 0            |
|                  |                                                                   |               | ENC                                |             | 392             |     |                  | 0           |                     |             | 0            |
|                  |                                                                   |               | MOS                                |             | 41.8            |     |                  | 17 Nov 2022 |                     |             |              |
|                  |                                                                   |               | MSC                                |             |                 |     | O/C              |             |                     |             |              |
| Engine           |                                                                   |               | [End Of Month Item]                |             |                 |     |                  |             |                     |             |              |
| 715001           | No. 2 Engine - Electrical Harnesses - Insulation Resistance Check |               | HRS                                |             | 994.4           |     |                  | 0           |                     |             | 0            |
|                  |                                                                   |               | ENC                                |             | 392             |     |                  | 0           |                     |             | 0            |
|                  |                                                                   |               | MOS                                |             | 41.9            |     |                  | 15 Nov 2022 |                     |             |              |
|                  |                                                                   |               | MSC                                |             |                 |     | O/C              |             |                     |             |              |
| Engine           |                                                                   |               | [End Of Month Item]                |             |                 |     |                  |             |                     |             |              |
| 715002           | No. 1 Engine - Electrical Harnesses - Continuity Check            |               | HRS                                |             | 994.4           |     |                  | 0           |                     |             | 0            |
|                  |                                                                   |               | ENC                                |             | 392             |     |                  | 0           |                     |             | 0            |
|                  |                                                                   |               | MOS                                |             | 41.8            |     |                  | 17 Nov 2022 |                     |             |              |
|                  |                                                                   |               | MSC                                |             |                 |     | O/C              |             |                     |             |              |
| Engine           |                                                                   |               | [End Of Month Item]                |             |                 |     |                  |             |                     |             |              |

| ATA<br>U=Custom  | Description                                                   |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|---------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                                   | Serial Number |                     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                            | SW            |                     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                        |               |                     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                                 |               |                     |             |                 |     |                  |             |                     |         |              |
| 715002           | No. 2 Engine - Electrical Harnesses - Continuity Check        |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                               |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                                               |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  | Engine                                                        |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  |                                                               |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 715003           | No. 1 Engine - Harnesses - Cleaning                           |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                               |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                                               |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  | Engine                                                        |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  |                                                               |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 715003           | No. 2 Engine - Harnesses - Cleaning                           |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                               |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                                               |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  | Engine                                                        |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  |                                                               |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 715100           | No. 1 Engine - Eec Lane A Harness 1A - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                               |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | PN                                                            | SN-UNKNOWN    | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  | Engine                                                        |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  |                                                               |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 715100           | No. 2 Engine - Eec Lane A Harness 1A - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                               |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | PN                                                            | SN-UNKNOWN    | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  | Engine                                                        |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  |                                                               |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 715102           | No. 1 Engine - Eec Lane B Harness 1B - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                               |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | PN                                                            | SN-UNKNOWN    | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  | Engine                                                        |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  |                                                               |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 715102           | No. 2 Engine - Eec Lane B Harness 1B - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                               |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | PN                                                            | SN-UNKNOWN    | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  | Engine                                                        |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  |                                                               |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom  | Description                                                   |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|---------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                   | Serial Number |                     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                            | SW            |                     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                        |               |                     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                 |               |                     |             |                 |     |                  |             |                    |         |              |
| 715104           | No. 1 Engine - Eec Lane A Harness 1C - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                               |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | PN                                                            | SN-UNKNOWN    | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                               |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                        |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 715104           | No. 2 Engine - Eec Lane A Harness 1C - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                               |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | PN                                                            | SN-UNKNOWN    | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                               |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                        |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 715106           | No. 1 Engine - Eec Lane B Harness 1D - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                               |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | PN                                                            | SN-UNKNOWN    | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                               |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                        |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 715106           | No. 2 Engine - Eec Lane B Harness 1D - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                               |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | PN                                                            | SN-UNKNOWN    | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                               |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                        |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 715108           | No. 1 Engine - Eec Lane A Harness 1E - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                               |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | PN                                                            | SN-UNKNOWN    | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                               |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                        |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 715108           | No. 2 Engine - Eec Lane A Harness 1E - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                               |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | PN                                                            | SN-UNKNOWN    | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                               |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                        |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 715110           | No. 1 Engine - Eec Lane B Harness 1F - Removal /Installation  |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                               |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | PN                                                            | SN-UNKNOWN    | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                               |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                        |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                  |                     | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------------------------------------------|---------------------|-----|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                                                  | Serial Number       |     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                                           | SW                  |     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                                       |                     |     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                                                |                     |     |             |                 |     |                  |             |                     |         |              |
| 715110           | No. 2 Engine - Eec Lane B Harness 1F - Removal /Installation                 |                     | HRS |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                              |                     | ENC |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | PN                                                                           | SN-UNKNOWN          | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                              |                     | MSC |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                       | [End Of Month Item] |     |             |                 |     |                  |             |                     |         |              |
| 717100           | No. 1 Engine - Drains Tank Ejector - Removal / Installation                  |                     | HRS |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | CV41-14-2                                                                    |                     | ENC |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | 2501298-6                                                                    |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                              |                     | MSC |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                       | [End Of Month Item] |     |             |                 |     |                  |             |                     |         |              |
| 717100           | No. 2 Engine - Drains Tank Ejector - Removal / Installation                  |                     | HRS |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | CV41-14-2                                                                    |                     | ENC |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | 2501298-8                                                                    |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                              |                     | MSC |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                       | [End Of Month Item] |     |             |                 |     |                  |             |                     |         |              |
| 717102           | No. 1 Engine - Drains Tank Ejector Filter (Conical) - Removal / Installation |                     | HRS |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                              |                     | ENC |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | PN                                                                           | SN-UNKNOWN          | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                              |                     | MSC |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                       | [End Of Month Item] |     |             |                 |     |                  |             |                     |         |              |
| 717102           | No. 2 Engine - Drains Tank Ejector Filter (Conical) - Removal / Installation |                     | HRS |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                              |                     | ENC |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | PN                                                                           | SN-UNKNOWN          | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                              |                     | MSC |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                       | [End Of Month Item] |     |             |                 |     |                  |             |                     |         |              |
| 717104           | No. 1 Engine - Drains Tank Ejector Filter (Conical) - Inspection             |                     | HRS |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                              |                     | ENC |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                                                              |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                              |                     | MSC |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                       | [End Of Month Item] |     |             |                 |     |                  |             |                     |         |              |
| 717104           | No. 2 Engine - Drains Tank Ejector Filter (Conical) - Inspection             |                     | HRS |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                              |                     | ENC |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                                                              |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                              |                     | MSC |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                       | [End Of Month Item] |     |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom  | Description                                                       |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                       | Serial Number |                                    |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                | SW            |                                    |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                            |               |                                    |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                     |               |                                    |             |                 |     |                  |             |                    |         |              |
| 717105           | No. 1 Engine - Drains Collection Tank - Removal / Installation    |               | HRS                                |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                   |               | ENC                                |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | PN                                                                | SN-UNKNOWN    | MOS                                |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                   |               | MSC                                |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                            |               | [End Of Month Item]                |             |                 |     |                  |             |                    |         |              |
| 717105           | No. 2 Engine - Drains Collection Tank - Removal / Installation    |               | HRS                                |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                   |               | ENC                                |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | PN                                                                | SN-UNKNOWN    | MOS                                |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                   |               | MSC                                |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                            |               | [End Of Month Item]                |             |                 |     |                  |             |                    |         |              |
| 717107           | No. 1 Engine - Drains Collection Tank - General Visual Inspection |               | HRS                                |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                   |               | ENC                                |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                                   |               | MOS                                |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                   |               | MSC                                |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                            |               | [End Of Month Item]                |             |                 |     |                  |             |                    |         |              |
| 717107           | No. 2 Engine - Drains Collection Tank - General Visual Inspection |               | HRS                                |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                   |               | ENC                                |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                                   |               | MOS                                |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                   |               | MSC                                |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                            |               | [End Of Month Item]                |             |                 |     |                  |             |                    |         |              |
| 717108           | No. 1 Engine - Drains Tubes and Fittings - Detailed Inspection    |               | HRS                                |             | 663.7           |     | 1200             | 330.7       | 1530.7             | 1580.7  | 0            |
|                  |                                                                   |               | ENC                                |             | 291             |     |                  | 101         |                    |         | 0            |
|                  |                                                                   |               | MOS                                |             | 25.5            |     |                  | 28 Mar 2024 |                    |         |              |
|                  |                                                                   |               | [End Of Month Item] [HRS: +50/-50] |             |                 |     |                  |             |                    |         |              |
|                  | Engine                                                            |               | 052002                             |             |                 |     |                  |             |                    |         |              |
| 717108           | No. 2 Engine - Drains Tubes and Fittings - Detailed Inspection    |               | HRS                                |             | 663.7           |     | 1200             | 330.7       | 1530.7             | 1580.7  | 0            |
|                  |                                                                   |               | ENC                                |             | 291             |     |                  | 101         |                    |         | 0            |
|                  |                                                                   |               | MOS                                |             | 25.5            |     |                  | 25 Mar 2024 |                    |         |              |
|                  |                                                                   |               | [End Of Month Item] [HRS: +50/-50] |             |                 |     |                  |             |                    |         |              |
|                  | Engine                                                            |               | 052002                             |             |                 |     |                  |             |                    |         |              |
| 717109           | No. 1 Engine - Engine Drain System - Leakage Rate Test            |               | HRS                                |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                   |               | ENC                                |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                                   |               | MOS                                |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                   |               | MSC                                |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                            |               | [End Of Month Item]                |             |                 |     |                  |             |                    |         |              |



| ATA<br>U=Custom       | Description                                                                                             |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|-----------------------|---------------------------------------------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                       | Part Number                                                                                             | Serial Number |                     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position      | HW                                                                                                      | SW            |                     |             |                 |     |                  |             |                    |         | Manufacturer |
|                       | MM Ref                                                                                                  |               |                     |             |                 |     |                  |             |                    |         | Date Type    |
|                       | Ops Number(s)                                                                                           |               |                     |             |                 |     |                  |             |                    |         |              |
| 717109<br><br>Engine  | No. 2 Engine - Engine Drain System - Leakage Rate Test                                                  |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                       |                                                                                                         |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                       |                                                                                                         |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                       |                                                                                                         |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                       |                                                                                                         |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 71EN1<br><br>Airframe | No. 1 Engine                                                                                            |               | HRS                 |             | 994.4           |     |                  | 2051.7      |                    |         | 0            |
|                       | DEL116                                                                                                  | 26163         | AFL                 |             | 392             |     |                  | 725         |                    |         | 0            |
|                       |                                                                                                         |               | MOS                 |             | 41.5            |     |                  | 28 Nov 2022 |                    |         |              |
|                       |                                                                                                         |               | MSC                 |             |                 |     | E/C              |             |                    |         |              |
|                       |                                                                                                         |               |                     |             |                 |     |                  |             |                    |         |              |
| 71EN2<br><br>Airframe | No. 2 Engine                                                                                            |               | HRS                 |             | 994.4           |     |                  | 2051.7      |                    |         | 0            |
|                       | DER116                                                                                                  | 26162         | AFL                 |             | 392             |     |                  | 725         |                    |         | 0            |
|                       |                                                                                                         |               | MOS                 |             | 41.5            |     |                  | 28 Nov 2022 |                    |         |              |
|                       |                                                                                                         |               | MSC                 |             |                 |     | E/C              |             |                    |         |              |
|                       |                                                                                                         |               |                     |             |                 |     |                  |             |                    |         |              |
| 72 - Engine           |                                                                                                         |               |                     |             |                 |     |                  |             |                    |         |              |
| 720000<br><br>Engine  | No. 1 Engine - Engine Turbine / Ducted Fan - Chapter 72                                                 |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                       |                                                                                                         |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                       |                                                                                                         |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                       |                                                                                                         |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                       |                                                                                                         |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 720000<br><br>Engine  | No. 2 Engine - Engine Turbine / Ducted Fan - Chapter 72                                                 |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                       |                                                                                                         |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                       |                                                                                                         |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                       |                                                                                                         |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                       |                                                                                                         |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 720001<br><br>Engine  | No. 1 Engine - Lp Compressor Module (Bladed and Unbladed) - Removal / Installation - Inlet Cowl Removed |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                       | PN                                                                                                      | SN-UNKNOWN    | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                       |                                                                                                         |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                       |                                                                                                         |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                       |                                                                                                         |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 720001<br><br>Engine  | No. 2 Engine - Lp Compressor Module (Bladed and Unbladed) - Removal / Installation - Inlet Cowl Removed |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                       | PN                                                                                                      | SN-UNKNOWN    | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                       |                                                                                                         |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                       |                                                                                                         |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                       |                                                                                                         |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                                                                                                   |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                                                                                                                                   | Serial Number |                                    |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                                                                                                                            | SW            |                                    |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                                                                                                                        |               |                                    |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                                                                                                                                 |               |                                    |             |                 |     |                  |             |                     |         |              |
| 720002           | No. 1 Engine - Lp Compressor Module (Bladed and Unbladed) - Removal / Installation - Inlet Cowl Removed (Alternate)<br><br>PN                      SN-UNKNOWN |               | HRS                                |             | 994.4           |     |                  | 0           |                     | 0       |              |
|                  |                                                                                                                                                               |               | ENC                                |             | 392             |     |                  | 0           |                     | 0       |              |
|                  |                                                                                                                                                               |               | MOS                                |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                                                                                                               |               | MSC                                |             |                 | O/C |                  |             |                     |         |              |
| Engine           | [End Of Month Item]                                                                                                                                           |               |                                    |             |                 |     |                  |             |                     |         |              |
| 720002           | No. 2 Engine - Lp Compressor Module (Bladed and Unbladed) - Removal / Installation - Inlet Cowl Removed (Alternate)<br><br>PN                      SN-UNKNOWN |               | HRS                                |             | 994.4           |     |                  | 0           |                     | 0       |              |
|                  |                                                                                                                                                               |               | ENC                                |             | 392             |     |                  | 0           |                     | 0       |              |
|                  |                                                                                                                                                               |               | MOS                                |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                                                                                                               |               | MSC                                |             |                 | O/C |                  |             |                     |         |              |
| Engine           | [End Of Month Item]                                                                                                                                           |               |                                    |             |                 |     |                  |             |                     |         |              |
| 720003           | No. 1 Engine - Lp Compressor Module (Unbladed) - Removal / Installation - Inlet Cowl Installed<br><br>PN                      SN-UNKNOWN                      |               | HRS                                |             | 994.4           |     |                  | 0           |                     | 0       |              |
|                  |                                                                                                                                                               |               | ENC                                |             | 392             |     |                  | 0           |                     | 0       |              |
|                  |                                                                                                                                                               |               | MOS                                |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                                                                                                               |               | MSC                                |             |                 | O/C |                  |             |                     |         |              |
| Engine           | [End Of Month Item]                                                                                                                                           |               |                                    |             |                 |     |                  |             |                     |         |              |
| 720003           | No. 2 Engine - Lp Compressor Module (Unbladed) - Removal / Installation - Inlet Cowl Installed<br><br>PN                      SN-UNKNOWN                      |               | HRS                                |             | 994.4           |     |                  | 0           |                     | 0       |              |
|                  |                                                                                                                                                               |               | ENC                                |             | 392             |     |                  | 0           |                     | 0       |              |
|                  |                                                                                                                                                               |               | MOS                                |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                                                                                                               |               | MSC                                |             |                 | O/C |                  |             |                     |         |              |
| Engine           | [End Of Month Item]                                                                                                                                           |               |                                    |             |                 |     |                  |             |                     |         |              |
| 720005           | No. 1 Engine - Hp Compressor - Inspection                                                                                                                     |               | HRS                                |             | 994.4           |     |                  | 0           |                     | 0       |              |
|                  |                                                                                                                                                               |               | ENC                                |             | 392             |     |                  | 0           |                     | 0       |              |
|                  |                                                                                                                                                               |               | MOS                                |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                                                                                                               |               | MSC                                |             |                 | O/C |                  |             |                     |         |              |
| Engine           | [End Of Month Item]                                                                                                                                           |               |                                    |             |                 |     |                  |             |                     |         |              |
| 720005           | No. 2 Engine - Hp Compressor - Inspection                                                                                                                     |               | HRS                                |             | 994.4           |     |                  | 0           |                     | 0       |              |
|                  |                                                                                                                                                               |               | ENC                                |             | 392             |     |                  | 0           |                     | 0       |              |
|                  |                                                                                                                                                               |               | MOS                                |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                                                                                                               |               | MSC                                |             |                 | O/C |                  |             |                     |         |              |
| Engine           | [End Of Month Item]                                                                                                                                           |               |                                    |             |                 |     |                  |             |                     |         |              |
| 720006           | No. 1 Engine - Combustion Section - Special Detailed Inspection                                                                                               |               | HRS                                |             | 663.7           |     | 1200             | 330.7       | 1530.7              | 1580.7  | 0            |
|                  |                                                                                                                                                               |               | ENC                                |             | 291             |     |                  | 101         |                     |         | 0            |
|                  |                                                                                                                                                               |               | MOS                                |             | 25.5            |     |                  | 28 Mar 2024 |                     |         |              |
|                  |                                                                                                                                                               |               | [End Of Month Item] [HRS: +50/-50] |             |                 |     |                  |             |                     |         |              |
| Engine           |                                                                                                                                                               |               |                                    |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom     | Description                                                     |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|---------------------|-----------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                     | Part Number                                                     | Serial Number |                                    |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position    | HW                                                              | SW            |                                    |             |                 |     |                  |             |                    |         | Manufacturer |
|                     | MM Ref                                                          |               |                                    |             |                 |     |                  |             |                    |         | Date Type    |
|                     | Ops Number(s)                                                   |               |                                    |             |                 |     |                  |             |                    |         |              |
| 720006              | No. 2 Engine - Combustion Section - Special Detailed Inspection |               | HRS                                |             | 663.7           |     | 1200             | 330.7       | 1530.7             | 1580.7  | 0            |
|                     |                                                                 |               | ENC                                |             | 291             |     |                  | 101         |                    | 0       |              |
|                     |                                                                 |               | MOS                                |             | 25.5            |     |                  | 27 Mar 2024 |                    |         |              |
|                     |                                                                 |               | [End Of Month Item] [HRS: +50/-50] |             |                 |     |                  |             |                    |         |              |
| Engine              |                                                                 |               |                                    |             |                 |     |                  |             |                    |         |              |
| 720007              | No. 1 Engine - Hp Turbine - Special Detailed Inspection         |               | HRS                                |             | 663.7           |     | 1200             | 330.7       | 1530.7             | 1580.7  | 0            |
|                     |                                                                 |               | ENC                                |             | 291             |     |                  | 101         |                    | 0       |              |
|                     |                                                                 |               | MOS                                |             | 25.5            |     |                  | 28 Mar 2024 |                    |         |              |
|                     |                                                                 |               | [End Of Month Item] [HRS: +50/-50] |             |                 |     |                  |             |                    |         |              |
| Engine              |                                                                 |               |                                    |             |                 |     |                  |             |                    |         |              |
| 720007              | No. 2 Engine - Hp Turbine - Special Detailed Inspection         |               | HRS                                |             | 663.7           |     | 1200             | 330.7       | 1530.7             | 1580.7  | 0            |
|                     |                                                                 |               | ENC                                |             | 291             |     |                  | 101         |                    | 0       |              |
|                     |                                                                 |               | MOS                                |             | 25.5            |     |                  | 28 Mar 2024 |                    |         |              |
|                     |                                                                 |               | [End Of Month Item] [HRS: +50/-50] |             |                 |     |                  |             |                    |         |              |
| Engine              |                                                                 |               |                                    |             |                 |     |                  |             |                    |         |              |
| 720008              | No. 1 Engine - Lp Turbine - Inspection                          |               | HRS                                |             | 663.7           |     |                  | 330.7       |                    |         | 0            |
|                     |                                                                 |               | ENC                                |             | 291             |     |                  | 101         |                    | 0       |              |
|                     |                                                                 |               | MOS                                |             | 25.5            |     |                  | 28 Mar 2024 |                    |         |              |
|                     |                                                                 |               | MSC                                |             |                 |     | O/C              |             |                    |         |              |
| Engine              |                                                                 |               |                                    |             |                 |     |                  |             |                    |         |              |
| [End Of Month Item] |                                                                 |               |                                    |             |                 |     |                  |             |                    |         |              |
| 720008              | No. 2 Engine - Lp Turbine - Inspection                          |               | HRS                                |             | 663.7           |     |                  | 330.7       |                    |         | 0            |
|                     |                                                                 |               | ENC                                |             | 291             |     |                  | 101         |                    | 0       |              |
|                     |                                                                 |               | MOS                                |             | 25.5            |     |                  | 28 Mar 2024 |                    |         |              |
|                     |                                                                 |               | MSC                                |             |                 |     | O/C              |             |                    |         |              |
| Engine              |                                                                 |               |                                    |             |                 |     |                  |             |                    |         |              |
| [End Of Month Item] |                                                                 |               |                                    |             |                 |     |                  |             |                    |         |              |
| 720009              | No. 1 Engine - Engine after Surge - Inspection                  |               | HRS                                |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                     |                                                                 |               | ENC                                |             | 392             |     |                  | 0           |                    | 0       |              |
|                     |                                                                 |               | MOS                                |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                     |                                                                 |               | MSC                                |             |                 |     | O/C              |             |                    |         |              |
| Engine              |                                                                 |               |                                    |             |                 |     |                  |             |                    |         |              |
| [End Of Month Item] |                                                                 |               |                                    |             |                 |     |                  |             |                    |         |              |
| 720009              | No. 2 Engine - Engine after Surge - Inspection                  |               | HRS                                |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                     |                                                                 |               | ENC                                |             | 392             |     |                  | 0           |                    | 0       |              |
|                     |                                                                 |               | MOS                                |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                     |                                                                 |               | MSC                                |             |                 |     | O/C              |             |                    |         |              |
| Engine              |                                                                 |               |                                    |             |                 |     |                  |             |                    |         |              |
| [End Of Month Item] |                                                                 |               |                                    |             |                 |     |                  |             |                    |         |              |
| 720010              | No. 1 Engine - Engine Lightning Strike - Inspection             |               | HRS                                |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                     |                                                                 |               | ENC                                |             | 392             |     |                  | 0           |                    | 0       |              |
|                     |                                                                 |               | MOS                                |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                     |                                                                 |               | MSC                                |             |                 |     | O/C              |             |                    |         |              |
| Engine              |                                                                 |               |                                    |             |                 |     |                  |             |                    |         |              |
| [End Of Month Item] |                                                                 |               |                                    |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                 |                     | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-----------------------------------------------------------------------------|---------------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                 | Serial Number       |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                          | SW                  |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                      |                     |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                               |                     |     |             |                 |     |                  |             |                    |         |              |
| 720010           | No. 2 Engine - Engine Lightning Strike - Inspection                         |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                             |                     | ENC |             | 392             |     |                  | 0           |                    | 0       |              |
|                  |                                                                             |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                             |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                      | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 720011           | No. 1 Engine - Engine after Contamination With Volcanic<br>ASH - Inspection |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                             |                     | ENC |             | 392             |     |                  | 0           |                    | 0       |              |
|                  |                                                                             |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                             |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                      | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 720011           | No. 2 Engine - Engine after Contamination With Volcanic<br>ASH - Inspection |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                             |                     | ENC |             | 392             |     |                  | 0           |                    | 0       |              |
|                  |                                                                             |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                             |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                      | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 720012           | No. 1 Engine - Engine after Birdstrike or Slush Ingestion -<br>Inspection   |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                             |                     | ENC |             | 392             |     |                  | 0           |                    | 0       |              |
|                  |                                                                             |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                             |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                      | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 720012           | No. 2 Engine - Engine after Birdstrike or Slush Ingestion -<br>Inspection   |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                             |                     | ENC |             | 392             |     |                  | 0           |                    | 0       |              |
|                  |                                                                             |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                             |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                      | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 720013           | No. 1 Engine - Engine after Shock Loading - Inspection                      |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                             |                     | ENC |             | 392             |     |                  | 0           |                    | 0       |              |
|                  |                                                                             |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                             |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                      | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 720013           | No. 2 Engine - Engine after Shock Loading - Inspection                      |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                             |                     | ENC |             | 392             |     |                  | 0           |                    | 0       |              |
|                  |                                                                             |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                             |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                      | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                                                                                           |                     | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------|---------------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                                                                                           | Serial Number       |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                                                                                                    | SW                  |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                                                                                                |                     |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                                                                                                         |                     |     |             |                 |     |                  |             |                    |         |              |
| 720014           | No. 1 Engine - Engine after In-Flight Shutdown -<br>Inspection                                                                                        |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                                                                       |                     | ENC |             | 392             |     |                  | 0           |                    | 0       |              |
|                  |                                                                                                                                                       |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                                                                                                       |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                                                                                                | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 720014           | No. 2 Engine - Engine after In-Flight Shutdown -<br>Inspection                                                                                        |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                                                                       |                     | ENC |             | 392             |     |                  | 0           |                    | 0       |              |
|                  |                                                                                                                                                       |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                                                                                                       |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                                                                                                | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 720015           | No. 1 Engine - Reverse Thrust Use In Emergency Aborted<br>Take-Off, Emergency Stop or Above Idle With 60 Knots or<br>Less Aircraft Speed - Inspection |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                                                                       |                     | ENC |             | 392             |     |                  | 0           |                    | 0       |              |
|                  |                                                                                                                                                       |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                                                                                                       |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                                                                                                | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 720015           | No. 2 Engine - Reverse Thrust Use In Emergency Aborted<br>Take-Off, Emergency Stop or Above Idle With 60 Knots or<br>Less Aircraft Speed - Inspection |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                                                                       |                     | ENC |             | 392             |     |                  | 0           |                    | 0       |              |
|                  |                                                                                                                                                       |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                                                                                                       |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                                                                                                | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 720016           | No. 1 Engine - Engine after Shedding / Ingestion of Ice -<br>Inspection                                                                               |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                                                                       |                     | ENC |             | 392             |     |                  | 0           |                    | 0       |              |
|                  |                                                                                                                                                       |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                                                                                                       |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                                                                                                | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 720016           | No. 2 Engine - Engine after Shedding / Ingestion of Ice -<br>Inspection                                                                               |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                                                                       |                     | ENC |             | 392             |     |                  | 0           |                    | 0       |              |
|                  |                                                                                                                                                       |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                                                                                                       |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                                                                                                | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 720017           | No. 1 Engine - Engine after Foreign Object Ingestion -<br>Inspection                                                                                  |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                                                                       |                     | ENC |             | 392             |     |                  | 0           |                    | 0       |              |
|                  |                                                                                                                                                       |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                                                                                                       |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                                                                                                | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                                                    |                     | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------------------------------------------------------------------|---------------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                                                    | Serial Number       |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                                                             | SW                  |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                                                         |                     |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                                                                  |                     |     |             |                 |     |                  |             |                    |         |              |
| 720017           | No. 2 Engine - Engine after Foreign Object Ingestion -<br>Inspection                                           |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                                |                     | ENC |             | 392             |     |                  | 0           |                    | 0       |              |
|                  |                                                                                                                |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                                                                |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                                                         | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 720018           | No. 1 Engine - Engine after Bypass Duct Blockage -<br>Inspection                                               |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                                |                     | ENC |             | 392             |     |                  | 0           |                    | 0       |              |
|                  |                                                                                                                |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                                                                |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                                                         | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 720018           | No. 2 Engine - Engine after Bypass Duct Blockage -<br>Inspection                                               |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                                |                     | ENC |             | 392             |     |                  | 0           |                    | 0       |              |
|                  |                                                                                                                |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                                                                |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                                                         | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 720020           | No. 1 Engine - Lp Compressor Outlet Guide Vanes (No. 1)<br>- Removal / Installation<br>FW83896 210067014024998 |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                                |                     | ENC |             | 392             |     |                  | 0           |                    | 0       |              |
|                  |                                                                                                                |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                                                                |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                                                         | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 720020           | No. 2 Engine - Lp Compressor Outlet Guide Vanes (No. 1)<br>- Removal / Installation<br>FW83896 210067014024866 |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                                |                     | ENC |             | 392             |     |                  | 0           |                    | 0       |              |
|                  |                                                                                                                |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                                                                |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                                                         | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 720021           | No. 1 Engine - Lp Compressor Outlet Guide Vanes (No. 2)<br>- Removal / Installation<br>FW83896 210067014025018 |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                                |                     | ENC |             | 392             |     |                  | 0           |                    | 0       |              |
|                  |                                                                                                                |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                                                                |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                                                         | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 720021           | No. 2 Engine - Lp Compressor Outlet Guide Vanes (No. 2)<br>- Removal / Installation<br>FW83896 210067014024922 |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                                |                     | ENC |             | 392             |     |                  | 0           |                    | 0       |              |
|                  |                                                                                                                |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                                                                |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                                                         | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                             |                 | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|---------------------------------------------------------|-----------------|---------------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                             | Serial Number   |                     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                      | SW              |                     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                  |                 |                     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                           |                 |                     |             |                 |     |                  |             |                    |         |              |
| 720022           | No. 1 Engine - Lp Compressor Outlet Guide Vanes (No. 3) |                 | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | - Removal / Installation                                |                 | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | FW83896                                                 | 210067014025021 | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                         |                 | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                  |                 | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 720022           | No. 2 Engine - Lp Compressor Outlet Guide Vanes (No. 3) |                 | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | - Removal / Installation                                |                 | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | FW83896                                                 | 210067014024923 | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                         |                 | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                  |                 | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 720023           | No. 1 Engine - Lp Compressor Outlet Guide Vanes (No. 4) |                 | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | - Removal / Installation                                |                 | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | FW83896                                                 | 210067014025024 | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                         |                 | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                  |                 | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 720023           | No. 2 Engine - Lp Compressor Outlet Guide Vanes (No. 4) |                 | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | - Removal / Installation                                |                 | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | FW83896                                                 | 210067014024924 | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                         |                 | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                  |                 | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 720024           | No. 1 Engine - Lp Compressor Outlet Guide Vanes (No. 5) |                 | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | - Removal / Installation                                |                 | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | FW83896                                                 | 210067014025025 | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                         |                 | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                  |                 | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 720024           | No. 2 Engine - Lp Compressor Outlet Guide Vanes (No. 5) |                 | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | - Removal / Installation                                |                 | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | FW83896                                                 | 210067014024925 | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                         |                 | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                  |                 | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 720025           | No. 1 Engine - Lp Compressor Outlet Guide Vanes (No. 6) |                 | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | - Removal / Installation                                |                 | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | FW83896                                                 | 210067014025026 | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                         |                 | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                  |                 | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                             |                 | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|---------------------------------------------------------|-----------------|---------------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                             | Serial Number   |                     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                      | SW              |                     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                  |                 |                     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                           |                 |                     |             |                 |     |                  |             |                    |         |              |
| 720025           | No. 2 Engine - Lp Compressor Outlet Guide Vanes (No. 6) |                 | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | - Removal / Installation                                |                 | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | FW83896                                                 | 210067014024926 | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                         |                 | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                  |                 | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 720026           | No. 1 Engine - Lp Compressor Outlet Guide Vanes (No. 7) |                 | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | - Removal / Installation                                |                 | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | FW83896                                                 | 210067014025027 | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                         |                 | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                  |                 | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 720026           | No. 2 Engine - Lp Compressor Outlet Guide Vanes (No. 7) |                 | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | - Removal / Installation                                |                 | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | FW83896                                                 | 210067014024927 | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                         |                 | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                  |                 | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 720027           | No. 1 Engine - Lp Compressor Outlet Guide Vanes (No. 8) |                 | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | - Removal / Installation                                |                 | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | FW83896                                                 | 210067014025028 | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                         |                 | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                  |                 | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 720027           | No. 2 Engine - Lp Compressor Outlet Guide Vanes (No. 8) |                 | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | - Removal / Installation                                |                 | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | FW83896                                                 | 210067014024928 | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                         |                 | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                  |                 | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 720028           | No. 1 Engine - Lp Compressor Outlet Guide Vanes (No. 9) |                 | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | - Removal / Installation                                |                 | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | FW83896                                                 | 210067014025043 | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                         |                 | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                  |                 | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 720028           | No. 2 Engine - Lp Compressor Outlet Guide Vanes (No. 9) |                 | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | - Removal / Installation                                |                 | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | FW83896                                                 | 210067014024931 | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                         |                 | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                  |                 | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |



| ATA<br>U=Custom  | Description                                                                       |                 | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|-----------------------------------------------------------------------------------|-----------------|---------------------|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                                                       | Serial Number   |                     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                                                | SW              |                     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                                            |                 |                     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                                                     |                 |                     |             |                 |     |                  |             |                     |         |              |
| 720029           | No. 1 Engine - Lp Compressor Outlet Guide Vanes (No. 10) - Removal / Installation |                 | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                                   |                 | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | FW83896                                                                           | 210067014025099 | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                                   |                 | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                            |                 | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 720029           | No. 2 Engine - Lp Compressor Outlet Guide Vanes (No. 10) - Removal / Installation |                 | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                                   |                 | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | FW83896                                                                           | 210067014024933 | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                                   |                 | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                            |                 | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 720030           | No. 1 Engine - Lp Compressor Outlet Guide Vanes (No. 11) - Removal / Installation |                 | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                                   |                 | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | FW83896                                                                           | 210067014025102 | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                                   |                 | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                            |                 | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 720030           | No. 2 Engine - Lp Compressor Outlet Guide Vanes (No. 11) - Removal / Installation |                 | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                                   |                 | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | FW83896                                                                           | 210067014024962 | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                                   |                 | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                            |                 | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 720031           | No. 1 Engine - Lp Compressor Outlet Guide Vanes (No. 12) - Removal / Installation |                 | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                                   |                 | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | FW83896                                                                           | 210067014025103 | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                                   |                 | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                            |                 | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 720031           | No. 2 Engine - Lp Compressor Outlet Guide Vanes (No. 12) - Removal / Installation |                 | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                                   |                 | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | FW83896                                                                           | 210067014024963 | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                                   |                 | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                            |                 | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 720032           | No. 1 Engine - Lp Compressor Outlet Guide Vanes (No. 13) - Removal / Installation |                 | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                                   |                 | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | FW83896                                                                           | 210067014025105 | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                                   |                 | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                            |                 | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom  | Description                                                                       |                 | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(* =Adj) | Max Due | Avg Man Hrs  |
|------------------|-----------------------------------------------------------------------------------|-----------------|---------------------|-------------|-----------------|-----|------------------|-------------|----------------------|---------|--------------|
|                  | Part Number                                                                       | Serial Number   |                     |             |                 |     |                  |             |                      |         | Approx Price |
| Logbook Position | HW                                                                                | SW              |                     |             |                 |     |                  |             |                      |         | Manufacturer |
|                  | MM Ref                                                                            |                 |                     |             |                 |     |                  |             |                      |         | Date Type    |
|                  | Ops Number(s)                                                                     |                 |                     |             |                 |     |                  |             |                      |         |              |
| 720032           | No. 2 Engine - Lp Compressor Outlet Guide Vanes (No. 13) - Removal / Installation |                 | HRS                 |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                  |                                                                                   |                 | ENC                 |             | 392             |     |                  | 0           |                      |         | 0            |
|                  | FW83896                                                                           | 210067014024964 | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                      |         |              |
|                  |                                                                                   |                 | MSC                 |             |                 |     | O/C              |             |                      |         |              |
|                  | Engine                                                                            |                 | [End Of Month Item] |             |                 |     |                  |             |                      |         |              |
| 720033           | No. 1 Engine - Lp Compressor Outlet Guide Vanes (No. 14) - Removal / Installation |                 | HRS                 |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                  |                                                                                   |                 | ENC                 |             | 392             |     |                  | 0           |                      |         | 0            |
|                  | FW83896                                                                           | 210067014025106 | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                      |         |              |
|                  |                                                                                   |                 | MSC                 |             |                 |     | O/C              |             |                      |         |              |
|                  | Engine                                                                            |                 | [End Of Month Item] |             |                 |     |                  |             |                      |         |              |
| 720033           | No. 2 Engine - Lp Compressor Outlet Guide Vanes (No. 14) - Removal / Installation |                 | HRS                 |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                  |                                                                                   |                 | ENC                 |             | 392             |     |                  | 0           |                      |         | 0            |
|                  | FW83896                                                                           | 210067014024965 | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                      |         |              |
|                  |                                                                                   |                 | MSC                 |             |                 |     | O/C              |             |                      |         |              |
|                  | Engine                                                                            |                 | [End Of Month Item] |             |                 |     |                  |             |                      |         |              |
| 720034           | No. 1 Engine - Lp Compressor Outlet Guide Vanes (No. 15) - Removal / Installation |                 | HRS                 |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                  |                                                                                   |                 | ENC                 |             | 392             |     |                  | 0           |                      |         | 0            |
|                  | FW83896                                                                           | 210067014025109 | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                      |         |              |
|                  |                                                                                   |                 | MSC                 |             |                 |     | O/C              |             |                      |         |              |
|                  | Engine                                                                            |                 | [End Of Month Item] |             |                 |     |                  |             |                      |         |              |
| 720034           | No. 2 Engine - Lp Compressor Outlet Guide Vanes (No. 15) - Removal / Installation |                 | HRS                 |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                  |                                                                                   |                 | ENC                 |             | 392             |     |                  | 0           |                      |         | 0            |
|                  | FW83896                                                                           | 210067014024966 | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                      |         |              |
|                  |                                                                                   |                 | MSC                 |             |                 |     | O/C              |             |                      |         |              |
|                  | Engine                                                                            |                 | [End Of Month Item] |             |                 |     |                  |             |                      |         |              |
| 720035           | No. 1 Engine - Lp Compressor Outlet Guide Vanes (No. 16) - Removal / Installation |                 | HRS                 |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                  |                                                                                   |                 | ENC                 |             | 392             |     |                  | 0           |                      |         | 0            |
|                  | FW83896                                                                           | 210067014025111 | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                      |         |              |
|                  |                                                                                   |                 | MSC                 |             |                 |     | O/C              |             |                      |         |              |
|                  | Engine                                                                            |                 | [End Of Month Item] |             |                 |     |                  |             |                      |         |              |
| 720035           | No. 2 Engine - Lp Compressor Outlet Guide Vanes (No. 16) - Removal / Installation |                 | HRS                 |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                  |                                                                                   |                 | ENC                 |             | 392             |     |                  | 0           |                      |         | 0            |
|                  | FW83896                                                                           | 210067014024968 | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                      |         |              |
|                  |                                                                                   |                 | MSC                 |             |                 |     | O/C              |             |                      |         |              |
|                  | Engine                                                                            |                 | [End Of Month Item] |             |                 |     |                  |             |                      |         |              |

| ATA<br>U=Custom  | Description                                                                       |                 | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-----------------------------------------------------------------------------------|-----------------|---------------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                       | Serial Number   |                     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                                | SW              |                     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                            |                 |                     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                                     |                 |                     |             |                 |     |                  |             |                    |         |              |
| 720036           | No. 1 Engine - Lp Compressor Outlet Guide Vanes (No. 17) - Removal / Installation |                 | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                   |                 | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | FW83896                                                                           | 210067014025112 | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                                   |                 | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                            |                 | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 720036           | No. 2 Engine - Lp Compressor Outlet Guide Vanes (No. 17) - Removal / Installation |                 | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                   |                 | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | FW83896                                                                           | 210067014024969 | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                                   |                 | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                            |                 | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 720037           | No. 1 Engine - Lp Compressor Outlet Guide Vanes (No. 18) - Removal / Installation |                 | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                   |                 | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | FW83896                                                                           | 210067014025120 | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                                   |                 | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                            |                 | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 720037           | No. 2 Engine - Lp Compressor Outlet Guide Vanes (No. 18) - Removal / Installation |                 | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                   |                 | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | FW83896                                                                           | 210067014024970 | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                                   |                 | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                            |                 | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 720038           | No. 1 Engine - Lp Compressor Outlet Guide Vanes (No. 19) - Removal / Installation |                 | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                   |                 | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | FW83896                                                                           | 210067014025124 | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                                   |                 | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                            |                 | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 720038           | No. 2 Engine - Lp Compressor Outlet Guide Vanes (No. 19) - Removal / Installation |                 | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                   |                 | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | FW83896                                                                           | 210067014025012 | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                                   |                 | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                            |                 | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 720039           | No. 1 Engine - Lp Compressor Outlet Guide Vanes (No. 20) - Removal / Installation |                 | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                   |                 | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | FW83896                                                                           | 210067014025125 | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                                   |                 | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                            |                 | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                       |                 | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-----------------------------------------------------------------------------------|-----------------|---------------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                       | Serial Number   |                     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                                | SW              |                     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                            |                 |                     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                                     |                 |                     |             |                 |     |                  |             |                    |         |              |
| 720039           | No. 2 Engine - Lp Compressor Outlet Guide Vanes (No. 20) - Removal / Installation |                 | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                   |                 | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | FW83896                                                                           | 210067014025013 | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                                   |                 | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                            |                 | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 720040           | No. 1 Engine - Lp Compressor Outlet Guide Vanes (No. 21) - Removal / Installation |                 | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                   |                 | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | FW83896                                                                           | 210067014025127 | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                                   |                 | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                            |                 | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 720040           | No. 2 Engine - Lp Compressor Outlet Guide Vanes (No. 21) - Removal / Installation |                 | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                   |                 | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | FW83896                                                                           | 210067014025014 | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                                   |                 | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                            |                 | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 720041           | No. 1 Engine - Lp Compressor Outlet Guide Vanes (No. 22) - Removal / Installation |                 | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                   |                 | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | FW83896                                                                           | 210067014025140 | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                                   |                 | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                            |                 | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 720041           | No. 2 Engine - Lp Compressor Outlet Guide Vanes (No. 22) - Removal / Installation |                 | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                   |                 | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | FW83896                                                                           | 210067014025015 | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                                   |                 | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                            |                 | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 720042           | No. 1 Engine - Lp Compressor Outlet Guide Vanes (No. 23) - Removal / Installation |                 | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                   |                 | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | FW83896                                                                           | 210067014025142 | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                                   |                 | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                            |                 | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 720042           | No. 2 Engine - Lp Compressor Outlet Guide Vanes (No. 23) - Removal / Installation |                 | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                   |                 | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | FW83896                                                                           | 210067014025016 | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                                   |                 | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                            |                 | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                       |                 | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|-----------------------------------------------------------------------------------|-----------------|---------------------|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                                                       | Serial Number   |                     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                                                | SW              |                     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                                            |                 |                     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                                                     |                 |                     |             |                 |     |                  |             |                     |         |              |
| 720043           | No. 1 Engine - Lp Compressor Outlet Guide Vanes (No. 24) - Removal / Installation |                 | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                                   |                 | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | FW83896                                                                           | 210067014025143 | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                                   |                 | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                            |                 | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 720043           | No. 2 Engine - Lp Compressor Outlet Guide Vanes (No. 24) - Removal / Installation |                 | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                                   |                 | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | FW83896                                                                           | 210067014025017 | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                                   |                 | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                            |                 | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 720044           | No. 1 Engine - Lp Compressor Outlet Guide Vanes (No. 25) - Removal / Installation |                 | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                                   |                 | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | FW83896                                                                           | 210067014025144 | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                                   |                 | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                            |                 | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 720044           | No. 2 Engine - Lp Compressor Outlet Guide Vanes (No. 25) - Removal / Installation |                 | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                                   |                 | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | FW83896                                                                           | 210067014025020 | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                                   |                 | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                            |                 | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 720045           | No. 1 Engine - Lp Compressor Outlet Guide Vanes (No. 26) - Removal / Installation |                 | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                                   |                 | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | FW83896                                                                           | 210067014025145 | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                                   |                 | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                            |                 | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 720045           | No. 2 Engine - Lp Compressor Outlet Guide Vanes (No. 26) - Removal / Installation |                 | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                                   |                 | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | FW83896                                                                           | 210067014025022 | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                                   |                 | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                            |                 | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 720046           | No. 1 Engine - Lp Compressor Outlet Guide Vanes (No. 27) - Removal / Installation |                 | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                                   |                 | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | FW83896                                                                           | 210067014025155 | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                                   |                 | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                            |                 | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom  | Description                                                                       |                 | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(* =Adj) | Max Due | Avg Man Hrs  |
|------------------|-----------------------------------------------------------------------------------|-----------------|---------------------|-------------|-----------------|-----|------------------|-------------|----------------------|---------|--------------|
|                  | Part Number                                                                       | Serial Number   |                     |             |                 |     |                  |             |                      |         | Approx Price |
| Logbook Position | HW                                                                                | SW              |                     |             |                 |     |                  |             |                      |         | Manufacturer |
|                  | MM Ref                                                                            |                 |                     |             |                 |     |                  |             |                      |         | Date Type    |
|                  | Ops Number(s)                                                                     |                 |                     |             |                 |     |                  |             |                      |         |              |
| 720046           | No. 2 Engine - Lp Compressor Outlet Guide Vanes (No. 27) - Removal / Installation |                 | HRS                 |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                  |                                                                                   |                 | ENC                 |             | 392             |     |                  | 0           |                      |         | 0            |
|                  | FW83896                                                                           | 210067014025023 | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                      |         |              |
|                  |                                                                                   |                 | MSC                 |             |                 |     | O/C              |             |                      |         |              |
|                  | Engine                                                                            |                 | [End Of Month Item] |             |                 |     |                  |             |                      |         |              |
| 720300           | No. 1 Engine - Core Fairing Fireseals - General Visual Inspection                 |                 | HRS                 |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                  |                                                                                   |                 | ENC                 |             | 392             |     |                  | 0           |                      |         | 0            |
|                  |                                                                                   |                 | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                      |         |              |
|                  |                                                                                   |                 | MSC                 |             |                 |     | C/C              |             |                      |         |              |
|                  | Engine                                                                            |                 | [End Of Month Item] |             |                 |     |                  |             |                      |         |              |
| 720300           | No. 2 Engine - Core Fairing Fireseals - General Visual Inspection                 |                 | HRS                 |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                  |                                                                                   |                 | ENC                 |             | 392             |     |                  | 0           |                      |         | 0            |
|                  |                                                                                   |                 | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                      |         |              |
|                  |                                                                                   |                 | MSC                 |             |                 |     | C/C              |             |                      |         |              |
|                  | Engine                                                                            |                 | [End Of Month Item] |             |                 |     |                  |             |                      |         |              |
| 720301           | No. 1 Engine - Core Fairings - Replace Fasteners (BRG3134)                        |                 | HRS                 |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                  |                                                                                   |                 | ENC                 |             | 392             |     |                  | 0           |                      |         | 0            |
|                  |                                                                                   |                 | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                      |         |              |
|                  |                                                                                   |                 | MSC                 |             |                 |     | O/C              |             |                      |         |              |
|                  | Engine                                                                            |                 | [End Of Month Item] |             |                 |     |                  |             |                      |         |              |
| 720301           | No. 2 Engine - Core Fairings - Replace Fasteners (BRG3134)                        |                 | HRS                 |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                  |                                                                                   |                 | ENC                 |             | 392             |     |                  | 0           |                      |         | 0            |
|                  |                                                                                   |                 | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                      |         |              |
|                  |                                                                                   |                 | MSC                 |             |                 |     | O/C              |             |                      |         |              |
|                  | Engine                                                                            |                 | [End Of Month Item] |             |                 |     |                  |             |                      |         |              |
| 720302           | No. 1 Engine - Hp Compressor Fairings (Upper) - Removal / Installation            |                 | HRS                 |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                  |                                                                                   |                 | ENC                 |             | 392             |     |                  | 0           |                      |         | 0            |
|                  | PN                                                                                | SN-UNKNOWN      | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                      |         |              |
|                  |                                                                                   |                 | MSC                 |             |                 |     | O/C              |             |                      |         |              |
|                  | Engine                                                                            |                 | [End Of Month Item] |             |                 |     |                  |             |                      |         |              |
| 720302           | No. 2 Engine - Hp Compressor Fairings (Upper) - Removal / Installation            |                 | HRS                 |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                  |                                                                                   |                 | ENC                 |             | 392             |     |                  | 0           |                      |         | 0            |
|                  | PN                                                                                | SN-UNKNOWN      | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                      |         |              |
|                  |                                                                                   |                 | MSC                 |             |                 |     | O/C              |             |                      |         |              |
|                  | Engine                                                                            |                 | [End Of Month Item] |             |                 |     |                  |             |                      |         |              |

| ATA<br>U=Custom  | Description                                                            |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                            | Serial Number |                     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                     | SW            |                     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                 |               |                     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                          |               |                     |             |                 |     |                  |             |                    |         |              |
| 720303           | No. 1 Engine - Hp Compressor Fairings (Lower) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                        |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | PN                                                                     | SN-UNKNOWN    | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                        |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                 |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 720303           | No. 2 Engine - Hp Compressor Fairings (Lower) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                        |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | PN                                                                     | SN-UNKNOWN    | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                        |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                 |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 720306           | No. 1 Engine - Combustion Fairings (Upper) - Removal / Installation    |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                        |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | PN                                                                     | SN-UNKNOWN    | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                        |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                 |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 720306           | No. 2 Engine - Combustion Fairings (Upper) - Removal / Installation    |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                        |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | PN                                                                     | SN-UNKNOWN    | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                        |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                 |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 720307           | No. 1 Engine - Combustion Fairings (Lower) - Removal / Installation    |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                        |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | PN                                                                     | SN-UNKNOWN    | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                        |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                 |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 720307           | No. 2 Engine - Combustion Fairings (Lower) - Removal / Installation    |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                        |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | PN                                                                     | SN-UNKNOWN    | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                        |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                 |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 720310           | No. 1 Engine - Lp Turbine Fairings (Left) - Removal / Installation     |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                        |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | PN                                                                     | SN-UNKNOWN    | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                        |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                 |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                         |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|---------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                         | Serial Number |                     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                  | SW            |                     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                              |               |                     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                       |               |                     |             |                 |     |                  |             |                    |         |              |
| 720310           | No. 2 Engine - Lp Turbine Fairings (Left) - Removal / Installation  |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                     |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | PN                                                                  | SN-UNKNOWN    | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                     |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                              |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 720311           | No. 1 Engine - Lp Turbine Fairings (Right) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                     |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | PN                                                                  | SN-UNKNOWN    | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                     |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                              |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 720311           | No. 2 Engine - Lp Turbine Fairings (Right) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                     |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | PN                                                                  | SN-UNKNOWN    | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                     |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                              |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 720312           | No. 1 Engine - Lp Turbine Fairings (Upper) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                     |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | PN                                                                  | SN-UNKNOWN    | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                     |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                              |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 720312           | No. 2 Engine - Lp Turbine Fairings (Upper) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                     |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | PN                                                                  | SN-UNKNOWN    | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                     |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                              |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 720316           | No. 1 Engine - Lp Turbine Fairings - Inspection                     |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                     |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                                     |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                     |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                              |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 720316           | No. 2 Engine - Lp Turbine Fairings - Inspection                     |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                     |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                                     |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                     |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                              |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |



| ATA<br>U=Custom  | Description                                                                                      |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|--------------------------------------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                                      | Serial Number |                     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                                               | SW            |                     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                                           |               |                     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                                                    |               |                     |             |                 |     |                  |             |                    |         |              |
| 720321           | No. 1 Engine - Left Engine Flow Plates - Removal / Installation                                  |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                  |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | PN                                                                                               | SN-UNKNOWN    | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                                                  |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                                           |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 720321           | No. 2 Engine - Left Engine Flow Plates - Removal / Installation                                  |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                  |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | PN                                                                                               | SN-UNKNOWN    | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                                                  |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                                           |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 720322           | No. 1 Engine - Right Engine Flow Plates - Removal / Installation                                 |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                  |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | PN                                                                                               | SN-UNKNOWN    | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                                                  |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                                           |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 720322           | No. 2 Engine - Right Engine Flow Plates - Removal / Installation                                 |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                  |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | PN                                                                                               | SN-UNKNOWN    | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                                                  |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                                           |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 720325           | No. 1 Engine - Left Engine Core FIRE Detection Sensor Assembly Grommet - Removal / Installation  |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                  |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | PN                                                                                               | SN-UNKNOWN    | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                                                  |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                                           |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 720325           | No. 2 Engine - Left Engine Core FIRE Detection Sensor Assembly Grommet - Removal / Installation  |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                  |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | PN                                                                                               | SN-UNKNOWN    | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                                                  |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                                           |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 720326           | No. 1 Engine - Right Engine Core FIRE Detection Sensor Assembly Grommet - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                  |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | PN                                                                                               | SN-UNKNOWN    | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                                                  |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                                           |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                               |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-----------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                               | Serial Number |                     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                        | SW            |                     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                    |               |                     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                             |               |                     |             |                 |     |                  |             |                    |         |              |
| 720326           | No. 2 Engine - Right Engine Core FIRE Detection Sensor    |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | Assembly Grommet - Removal / Installation                 |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | PN                                                        | SN-UNKNOWN    | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                           |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 720329           | No. 1 Engine - Left Engine Core FIRE Detection Sensor     |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | Assembly Grommet - Inspection                             |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                           |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                           |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 720329           | No. 2 Engine - Left Engine Core FIRE Detection Sensor     |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | Assembly Grommet - Inspection                             |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                           |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                           |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 720330           | No. 1 Engine - Right Engine Core FIRE Detection Sensor    |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | Assembly Grommet - Inspection                             |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                           |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                           |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 720330           | No. 2 Engine - Right Engine Core FIRE Detection Sensor    |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | Assembly Grommet - Inspection                             |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                           |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                           |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 721600           | No. 1 Engine - Accessory Gearbox - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | PN                                                        | SN-UNKNOWN    | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                           |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                           |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 721600           | No. 2 Engine - Accessory Gearbox - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | PN                                                        | SN-UNKNOWN    | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                           |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                           |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom                     | Description                                                                   |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|-------------------------------------|-------------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                     | Part Number                                                                   | Serial Number |                                    |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position                    | HW                                                                            | SW            |                                    |             |                 |     |                  |             |                    |         | Manufacturer |
|                                     | MM Ref                                                                        |               |                                    |             |                 |     |                  |             |                    |         | Date Type    |
|                                     | Ops Number(s)                                                                 |               |                                    |             |                 |     |                  |             |                    |         |              |
| <b>723000</b><br>(723000)<br>Engine | No. 1 Engine - Lp Compressor Fan                                              |               | HRS                                |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                                     | PN                                                                            | SN-UNKNOWN    | ENC                                |             | 392             |     |                  | 0           |                    |         | 0            |
|                                     |                                                                               |               | MOS                                |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                                     |                                                                               |               | MSC                                |             |                 |     | O/C              |             |                    |         |              |
| [End Of Month Item]                 |                                                                               |               |                                    |             |                 |     |                  |             |                    |         |              |
| <b>723000</b><br>(723000)<br>Engine | No. 2 Engine - Lp Compressor Fan                                              |               | HRS                                |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                                     | PN                                                                            | SN-UNKNOWN    | ENC                                |             | 392             |     |                  | 0           |                    |         | 0            |
|                                     |                                                                               |               | MOS                                |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                                     |                                                                               |               | MSC                                |             |                 |     | O/C              |             |                    |         |              |
| [End Of Month Item]                 |                                                                               |               |                                    |             |                 |     |                  |             |                    |         |              |
| <b>723100</b><br><br>Engine         | No. 1 Engine - Lp Compressor (Fan) Disc - Inspection                          |               | HRS                                |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                                     |                                                                               |               | ENC                                |             | 392             |     |                  | 0           |                    |         | 0            |
|                                     |                                                                               |               | MOS                                |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                                     |                                                                               |               | MSC                                |             |                 |     | O/C              |             |                    |         |              |
| [End Of Month Item]                 |                                                                               |               |                                    |             |                 |     |                  |             |                    |         |              |
| <b>723100</b><br><br>Engine         | No. 2 Engine - Lp Compressor (Fan) Disc - Inspection                          |               | HRS                                |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                                     |                                                                               |               | ENC                                |             | 392             |     |                  | 0           |                    |         | 0            |
|                                     |                                                                               |               | MOS                                |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                                     |                                                                               |               | MSC                                |             |                 |     | O/C              |             |                    |         |              |
| [End Of Month Item]                 |                                                                               |               |                                    |             |                 |     |                  |             |                    |         |              |
| <b>723101</b><br><br>Engine         | No. 1 Engine - Lp Compressor Fan Blades - Detailed Inspection                 |               | HRS                                |             | 137             | 6.5 | 600              | 857.4       | 1463.9*            | 1513.9  | 0            |
|                                     |                                                                               |               | ENC                                |             | 52              |     |                  | 340         |                    |         | 0            |
|                                     |                                                                               |               | MOS                                |             | 5.3             |     |                  | 02 Dec 2025 |                    |         |              |
|                                     |                                                                               |               | [End Of Month Item] [HRS: +50/-50] |             |                 |     |                  |             |                    |         |              |
| 052001                              |                                                                               |               |                                    |             |                 |     |                  |             |                    |         |              |
| <b>723101</b><br><br>Engine         | No. 2 Engine - Lp Compressor Fan Blades - Detailed Inspection                 |               | HRS                                |             | 137             | 6.5 | 600              | 857.4       | 1463.9*            | 1513.9  | 0            |
|                                     |                                                                               |               | ENC                                |             | 52              |     |                  | 340         |                    |         | 0            |
|                                     |                                                                               |               | MOS                                |             | 5.3             |     |                  | 02 Dec 2025 |                    |         |              |
|                                     |                                                                               |               | [End Of Month Item] [HRS: +50/-50] |             |                 |     |                  |             |                    |         |              |
| 052001                              |                                                                               |               |                                    |             |                 |     |                  |             |                    |         |              |
| <b>723102</b><br><br>Engine         | No. 1 Engine - Lp Compressor Disc and Fan Shaft Curvic Couplings - Inspection |               | HRS                                |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                                     |                                                                               |               | ENC                                |             | 392             |     |                  | 0           |                    |         | 0            |
|                                     |                                                                               |               | MOS                                |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                                     |                                                                               |               | MSC                                |             |                 |     | O/C              |             |                    |         |              |
| [End Of Month Item]                 |                                                                               |               |                                    |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                   |                     | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|-------------------------------------------------------------------------------|---------------------|-----|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                                                   | Serial Number       |     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                                            | SW                  |     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                                        |                     |     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                                                 |                     |     |             |                 |     |                  |             |                     |         |              |
| 723102           | No. 2 Engine - Lp Compressor Disc and Fan Shaft Curvic Couplings - Inspection |                     | HRS |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                               |                     | ENC |             | 392             |     |                  | 0           |                     | 0       |              |
|                  |                                                                               |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                               |                     | MSC |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                        | [End Of Month Item] |     |             |                 |     |                  |             |                     |         |              |
| 723103           | No. 1 Engine - Lp Compressor Anti-Score Ring - Inspection                     |                     | HRS |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                               |                     | ENC |             | 392             |     |                  | 0           |                     | 0       |              |
|                  |                                                                               |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                               |                     | MSC |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                        | [End Of Month Item] |     |             |                 |     |                  |             |                     |         |              |
| 723103           | No. 2 Engine - Lp Compressor Anti-Score Ring - Inspection                     |                     | HRS |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                               |                     | ENC |             | 392             |     |                  | 0           |                     | 0       |              |
|                  |                                                                               |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                               |                     | MSC |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                        | [End Of Month Item] |     |             |                 |     |                  |             |                     |         |              |
| 723104           | No. 1 Engine - Lp Compressor Rear Retaining Ring - Inspection                 |                     | HRS |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                               |                     | ENC |             | 392             |     |                  | 0           |                     | 0       |              |
|                  |                                                                               |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                               |                     | MSC |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                        | [End Of Month Item] |     |             |                 |     |                  |             |                     |         |              |
| 723104           | No. 2 Engine - Lp Compressor Rear Retaining Ring - Inspection                 |                     | HRS |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                               |                     | ENC |             | 392             |     |                  | 0           |                     | 0       |              |
|                  |                                                                               |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                               |                     | MSC |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                        | [End Of Month Item] |     |             |                 |     |                  |             |                     |         |              |
| 723106           | No. 1 Engine - Lp Compressor Blades (Installed) - Cleaning                    |                     | HRS |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                               |                     | ENC |             | 392             |     |                  | 0           |                     | 0       |              |
|                  |                                                                               |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                               |                     | MSC |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                        | [End Of Month Item] |     |             |                 |     |                  |             |                     |         |              |
| 723106           | No. 2 Engine - Lp Compressor Blades (Installed) - Cleaning                    |                     | HRS |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                               |                     | ENC |             | 392             |     |                  | 0           |                     | 0       |              |
|                  |                                                                               |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                               |                     | MSC |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                        | [End Of Month Item] |     |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom  | Description                                                                |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                                                | Serial Number |                     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                                         | SW            |                     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                                     |               |                     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                                              |               |                     |             |                 |     |                  |             |                     |         |              |
| 723107           | No. 1 Engine - Lp Compressor Front Retaining Ring - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                            |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | PN                                                                         | SN-UNKNOWN    | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                            |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                     |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 723107           | No. 2 Engine - Lp Compressor Front Retaining Ring - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                            |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | PN                                                                         | SN-UNKNOWN    | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                            |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                     |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 723109           | No. 1 Engine - Lp Compressor Front Retaining Ring - Inspection             |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                            |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                                                            |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                            |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                     |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 723109           | No. 2 Engine - Lp Compressor Front Retaining Ring - Inspection             |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                            |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                                                            |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                            |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                     |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 723110           | No. 1 Engine - Lp Compressor Fan Blades (No. 1) - Removal / Installation   |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                            |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | PN                                                                         | SN-UNKNOWN    | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                            |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                     |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 723110           | No. 2 Engine - Lp Compressor Fan Blades (No. 1) - Removal / Installation   |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                            |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | PN                                                                         | SN-UNKNOWN    | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                            |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                     |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 723111           | No. 1 Engine - Lp Compressor Fan Blades (No. 2) - Removal / Installation   |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                            |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | PN                                                                         | SN-UNKNOWN    | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                            |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                     |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom  | Description                                                              |                     | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|--------------------------------------------------------------------------|---------------------|-----|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                                              | Serial Number       |     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                                       | SW                  |     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                                   |                     |     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                                            |                     |     |             |                 |     |                  |             |                     |         |              |
| 723111           | No. 2 Engine - Lp Compressor Fan Blades (No. 2) - Removal / Installation |                     | HRS |             | 994.4           |     |                  | 0           |                     | 0       |              |
|                  |                                                                          |                     | ENC |             | 392             |     |                  | 0           |                     | 0       |              |
|                  | PN                                                                       | SN-UNKNOWN          | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                          |                     | MSC |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                   | [End Of Month Item] |     |             |                 |     |                  |             |                     |         |              |
| 723112           | No. 1 Engine - Lp Compressor Fan Blades (No. 3) - Removal / Installation |                     | HRS |             | 994.4           |     |                  | 0           |                     | 0       |              |
|                  |                                                                          |                     | ENC |             | 392             |     |                  | 0           |                     | 0       |              |
|                  | PN                                                                       | SN-UNKNOWN          | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                          |                     | MSC |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                   | [End Of Month Item] |     |             |                 |     |                  |             |                     |         |              |
| 723112           | No. 2 Engine - Lp Compressor Fan Blades (No. 3) - Removal / Installation |                     | HRS |             | 994.4           |     |                  | 0           |                     | 0       |              |
|                  |                                                                          |                     | ENC |             | 392             |     |                  | 0           |                     | 0       |              |
|                  | PN                                                                       | SN-UNKNOWN          | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                          |                     | MSC |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                   | [End Of Month Item] |     |             |                 |     |                  |             |                     |         |              |
| 723113           | No. 1 Engine - Lp Compressor Fan Blades (No. 4) - Removal / Installation |                     | HRS |             | 994.4           |     |                  | 0           |                     | 0       |              |
|                  |                                                                          |                     | ENC |             | 392             |     |                  | 0           |                     | 0       |              |
|                  | PN                                                                       | SN-UNKNOWN          | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                          |                     | MSC |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                   | [End Of Month Item] |     |             |                 |     |                  |             |                     |         |              |
| 723113           | No. 2 Engine - Lp Compressor Fan Blades (No. 4) - Removal / Installation |                     | HRS |             | 994.4           |     |                  | 0           |                     | 0       |              |
|                  |                                                                          |                     | ENC |             | 392             |     |                  | 0           |                     | 0       |              |
|                  | PN                                                                       | SN-UNKNOWN          | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                          |                     | MSC |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                   | [End Of Month Item] |     |             |                 |     |                  |             |                     |         |              |
| 723114           | No. 1 Engine - Lp Compressor Fan Blades (No. 5) - Removal / Installation |                     | HRS |             | 994.4           |     |                  | 0           |                     | 0       |              |
|                  |                                                                          |                     | ENC |             | 392             |     |                  | 0           |                     | 0       |              |
|                  | PN                                                                       | SN-UNKNOWN          | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                          |                     | MSC |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                   | [End Of Month Item] |     |             |                 |     |                  |             |                     |         |              |
| 723114           | No. 2 Engine - Lp Compressor Fan Blades (No. 5) - Removal / Installation |                     | HRS |             | 994.4           |     |                  | 0           |                     | 0       |              |
|                  |                                                                          |                     | ENC |             | 392             |     |                  | 0           |                     | 0       |              |
|                  | PN                                                                       | SN-UNKNOWN          | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                          |                     | MSC |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                   | [End Of Month Item] |     |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom  | Description                                                              |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(* =Adj) | Max Due | Avg Man Hrs  |
|------------------|--------------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|----------------------|---------|--------------|
|                  | Part Number                                                              | Serial Number |                     |             |                 |     |                  |             |                      |         | Approx Price |
| Logbook Position | HW                                                                       | SW            |                     |             |                 |     |                  |             |                      |         | Manufacturer |
|                  | MM Ref                                                                   |               |                     |             |                 |     |                  |             |                      |         | Date Type    |
|                  | Ops Number(s)                                                            |               |                     |             |                 |     |                  |             |                      |         |              |
| 723115           | No. 1 Engine - Lp Compressor Fan Blades (No. 6) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                  |                                                                          |               | ENC                 |             | 392             |     |                  | 0           |                      |         | 0            |
|                  | PN                                                                       | SN-UNKNOWN    | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                      |         |              |
|                  |                                                                          |               | MSC                 |             |                 |     | O/C              |             |                      |         |              |
|                  | Engine                                                                   |               | [End Of Month Item] |             |                 |     |                  |             |                      |         |              |
| 723115           | No. 2 Engine - Lp Compressor Fan Blades (No. 6) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                  |                                                                          |               | ENC                 |             | 392             |     |                  | 0           |                      |         | 0            |
|                  | PN                                                                       | SN-UNKNOWN    | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                      |         |              |
|                  |                                                                          |               | MSC                 |             |                 |     | O/C              |             |                      |         |              |
|                  | Engine                                                                   |               | [End Of Month Item] |             |                 |     |                  |             |                      |         |              |
| 723116           | No. 1 Engine - Lp Compressor Fan Blades (No. 7) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                  |                                                                          |               | ENC                 |             | 392             |     |                  | 0           |                      |         | 0            |
|                  | PN                                                                       | SN-UNKNOWN    | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                      |         |              |
|                  |                                                                          |               | MSC                 |             |                 |     | O/C              |             |                      |         |              |
|                  | Engine                                                                   |               | [End Of Month Item] |             |                 |     |                  |             |                      |         |              |
| 723116           | No. 2 Engine - Lp Compressor Fan Blades (No. 7) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                  |                                                                          |               | ENC                 |             | 392             |     |                  | 0           |                      |         | 0            |
|                  | PN                                                                       | SN-UNKNOWN    | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                      |         |              |
|                  |                                                                          |               | MSC                 |             |                 |     | O/C              |             |                      |         |              |
|                  | Engine                                                                   |               | [End Of Month Item] |             |                 |     |                  |             |                      |         |              |
| 723117           | No. 1 Engine - Lp Compressor Fan Blades (No. 8) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                  |                                                                          |               | ENC                 |             | 392             |     |                  | 0           |                      |         | 0            |
|                  | PN                                                                       | SN-UNKNOWN    | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                      |         |              |
|                  |                                                                          |               | MSC                 |             |                 |     | O/C              |             |                      |         |              |
|                  | Engine                                                                   |               | [End Of Month Item] |             |                 |     |                  |             |                      |         |              |
| 723117           | No. 2 Engine - Lp Compressor Fan Blades (No. 8) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                  |                                                                          |               | ENC                 |             | 392             |     |                  | 0           |                      |         | 0            |
|                  | PN                                                                       | SN-UNKNOWN    | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                      |         |              |
|                  |                                                                          |               | MSC                 |             |                 |     | O/C              |             |                      |         |              |
|                  | Engine                                                                   |               | [End Of Month Item] |             |                 |     |                  |             |                      |         |              |
| 723118           | No. 1 Engine - Lp Compressor Fan Blades (No. 9) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                  |                                                                          |               | ENC                 |             | 392             |     |                  | 0           |                      |         | 0            |
|                  | PN                                                                       | SN-UNKNOWN    | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                      |         |              |
|                  |                                                                          |               | MSC                 |             |                 |     | O/C              |             |                      |         |              |
|                  | Engine                                                                   |               | [End Of Month Item] |             |                 |     |                  |             |                      |         |              |

| ATA<br>U=Custom  | Description                                                               |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|---------------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                                               | Serial Number |                     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                                        | SW            |                     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                                    |               |                     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                                             |               |                     |             |                 |     |                  |             |                     |         |              |
| 723118           | No. 2 Engine - Lp Compressor Fan Blades (No. 9) - Removal / Installation  |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                           |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | PN                                                                        | SN-UNKNOWN    | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                           |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 723119           | No. 1 Engine - Lp Compressor Fan Blades (No. 10) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                           |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | PN                                                                        | SN-UNKNOWN    | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                           |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 723119           | No. 2 Engine - Lp Compressor Fan Blades (No. 10) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                           |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | PN                                                                        | SN-UNKNOWN    | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                           |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 723120           | No. 1 Engine - Lp Compressor Fan Blades (No. 11) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                           |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | PN                                                                        | SN-UNKNOWN    | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                           |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 723120           | No. 2 Engine - Lp Compressor Fan Blades (No. 11) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                           |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | PN                                                                        | SN-UNKNOWN    | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                           |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 723121           | No. 1 Engine - Lp Compressor Fan Blades (No. 12) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                           |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | PN                                                                        | SN-UNKNOWN    | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                           |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 723121           | No. 2 Engine - Lp Compressor Fan Blades (No. 12) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                           |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | PN                                                                        | SN-UNKNOWN    | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                           |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |



| ATA<br>U=Custom  | Description                                                               |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|---------------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                                               | Serial Number |                     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                                        | SW            |                     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                                    |               |                     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                                             |               |                     |             |                 |     |                  |             |                     |         |              |
| 723122           | No. 1 Engine - Lp Compressor Fan Blades (No. 13) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                           |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | PN                                                                        | SN-UNKNOWN    | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                           |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 723122           | No. 2 Engine - Lp Compressor Fan Blades (No. 13) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                           |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | PN                                                                        | SN-UNKNOWN    | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                           |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 723123           | No. 1 Engine - Lp Compressor Fan Blades (No. 14) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                           |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | PN                                                                        | SN-UNKNOWN    | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                           |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 723123           | No. 2 Engine - Lp Compressor Fan Blades (No. 14) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                           |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | PN                                                                        | SN-UNKNOWN    | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                           |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 723124           | No. 1 Engine - Lp Compressor Fan Blades (No. 15) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                           |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | PN                                                                        | SN-UNKNOWN    | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                           |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 723124           | No. 2 Engine - Lp Compressor Fan Blades (No. 15) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                           |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | PN                                                                        | SN-UNKNOWN    | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                           |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 723125           | No. 1 Engine - Lp Compressor Fan Blades (No. 16) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                           |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | PN                                                                        | SN-UNKNOWN    | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                           |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom  | Description                                                               |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(* =Adj) | Max Due | Avg Man Hrs  |
|------------------|---------------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|----------------------|---------|--------------|
|                  | Part Number                                                               | Serial Number |                     |             |                 |     |                  |             |                      |         | Approx Price |
| Logbook Position | HW                                                                        | SW            |                     |             |                 |     |                  |             |                      |         | Manufacturer |
|                  | MM Ref                                                                    |               |                     |             |                 |     |                  |             |                      |         | Date Type    |
|                  | Ops Number(s)                                                             |               |                     |             |                 |     |                  |             |                      |         |              |
| 723125           | No. 2 Engine - Lp Compressor Fan Blades (No. 16) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                  |                                                                           |               | ENC                 |             | 392             |     |                  | 0           |                      |         | 0            |
|                  | PN                                                                        | SN-UNKNOWN    | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                      |         |              |
|                  |                                                                           |               | MSC                 |             |                 |     | O/C              |             |                      |         |              |
|                  | Engine                                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                      |         |              |
| 723126           | No. 1 Engine - Lp Compressor Fan Blades (No. 17) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                  |                                                                           |               | ENC                 |             | 392             |     |                  | 0           |                      |         | 0            |
|                  | PN                                                                        | SN-UNKNOWN    | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                      |         |              |
|                  |                                                                           |               | MSC                 |             |                 |     | O/C              |             |                      |         |              |
|                  | Engine                                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                      |         |              |
| 723126           | No. 2 Engine - Lp Compressor Fan Blades (No. 17) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                  |                                                                           |               | ENC                 |             | 392             |     |                  | 0           |                      |         | 0            |
|                  | PN                                                                        | SN-UNKNOWN    | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                      |         |              |
|                  |                                                                           |               | MSC                 |             |                 |     | O/C              |             |                      |         |              |
|                  | Engine                                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                      |         |              |
| 723127           | No. 1 Engine - Lp Compressor Fan Blades (No. 18) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                  |                                                                           |               | ENC                 |             | 392             |     |                  | 0           |                      |         | 0            |
|                  | PN                                                                        | SN-UNKNOWN    | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                      |         |              |
|                  |                                                                           |               | MSC                 |             |                 |     | O/C              |             |                      |         |              |
|                  | Engine                                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                      |         |              |
| 723127           | No. 2 Engine - Lp Compressor Fan Blades (No. 18) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                  |                                                                           |               | ENC                 |             | 392             |     |                  | 0           |                      |         | 0            |
|                  | PN                                                                        | SN-UNKNOWN    | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                      |         |              |
|                  |                                                                           |               | MSC                 |             |                 |     | O/C              |             |                      |         |              |
|                  | Engine                                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                      |         |              |
| 723128           | No. 1 Engine - Lp Compressor Fan Blades (No. 19) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                  |                                                                           |               | ENC                 |             | 392             |     |                  | 0           |                      |         | 0            |
|                  | PN                                                                        | SN-UNKNOWN    | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                      |         |              |
|                  |                                                                           |               | MSC                 |             |                 |     | O/C              |             |                      |         |              |
|                  | Engine                                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                      |         |              |
| 723128           | No. 2 Engine - Lp Compressor Fan Blades (No. 19) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                  |                                                                           |               | ENC                 |             | 392             |     |                  | 0           |                      |         | 0            |
|                  | PN                                                                        | SN-UNKNOWN    | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                      |         |              |
|                  |                                                                           |               | MSC                 |             |                 |     | O/C              |             |                      |         |              |
|                  | Engine                                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                      |         |              |

| ATA<br>U=Custom  | Description                                                               |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|---------------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                               | Serial Number |                     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                        | SW            |                     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                    |               |                     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                             |               |                     |             |                 |     |                  |             |                    |         |              |
| 723129           | No. 1 Engine - Lp Compressor Fan Blades (No. 20) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                           |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | PN                                                                        | SN-UNKNOWN    | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                           |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 723129           | No. 2 Engine - Lp Compressor Fan Blades (No. 20) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                           |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | PN                                                                        | SN-UNKNOWN    | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                           |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 723130           | No. 1 Engine - Lp Compressor Fan Blades (No. 21) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                           |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | PN                                                                        | SN-UNKNOWN    | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                           |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 723130           | No. 2 Engine - Lp Compressor Fan Blades (No. 21) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                           |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | PN                                                                        | SN-UNKNOWN    | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                           |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 723131           | No. 1 Engine - Lp Compressor Fan Blades (No. 22) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                           |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | PN                                                                        | SN-UNKNOWN    | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                           |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 723131           | No. 2 Engine - Lp Compressor Fan Blades (No. 22) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                           |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | PN                                                                        | SN-UNKNOWN    | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                           |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 723132           | No. 1 Engine - Lp Compressor Fan Blades (No. 23) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                           |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | PN                                                                        | SN-UNKNOWN    | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                           |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                                                   |                     | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|---------------------------------------------------------------------------------------------------------------|---------------------|-----|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                                                                                   | Serial Number       |     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                                                                            | SW                  |     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                                                                        |                     |     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                                                                                 |                     |     |             |                 |     |                  |             |                     |         |              |
| 723132           | No. 2 Engine - Lp Compressor Fan Blades (No. 23) - Removal / Installation                                     |                     | HRS |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                                                               |                     | ENC |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | PN                                                                                                            | SN-UNKNOWN          | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                                                               |                     | MSC |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                                                        | [End Of Month Item] |     |             |                 |     |                  |             |                     |         |              |
| 723133           | No. 1 Engine - Lp Compressor Fan Blades (No. 24) - Removal / Installation                                     |                     | HRS |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                                                               |                     | ENC |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | PN                                                                                                            | SN-UNKNOWN          | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                                                               |                     | MSC |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                                                        | [End Of Month Item] |     |             |                 |     |                  |             |                     |         |              |
| 723133           | No. 2 Engine - Lp Compressor Fan Blades (No. 24) - Removal / Installation                                     |                     | HRS |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                                                               |                     | ENC |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | PN                                                                                                            | SN-UNKNOWN          | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                                                               |                     | MSC |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                                                        | [End Of Month Item] |     |             |                 |     |                  |             |                     |         |              |
| 723158           | No. 1 Engine - Lp Compressor (Fan) Disc Assembly - Touch-Up Dry Film Lubricant (BRG3183)                      |                     | HRS |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                                                               |                     | ENC |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                                                                                               |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                                                               |                     | MSC |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                                                        | [End Of Month Item] |     |             |                 |     |                  |             |                     |         |              |
| 723158           | No. 2 Engine - Lp Compressor (Fan) Disc Assembly - Touch-Up Dry Film Lubricant (BRG3183)                      |                     | HRS |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                                                               |                     | ENC |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                                                                                               |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                                                               |                     | MSC |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                                                        | [End Of Month Item] |     |             |                 |     |                  |             |                     |         |              |
| 723159           | No. 1 Engine - Lp Compressor Rotor Blade Assembly - Repair Leading and Trailing Edges By Scalloping (BRG3137) |                     | HRS |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                                                               |                     | ENC |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                                                                                               |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                                                               |                     | MSC |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                                                        | [End Of Month Item] |     |             |                 |     |                  |             |                     |         |              |
| 723159           | No. 2 Engine - Lp Compressor Rotor Blade Assembly - Repair Leading and Trailing Edges By Scalloping (BRG3137) |                     | HRS |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                                                               |                     | ENC |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                                                                                               |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                                                               |                     | MSC |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                                                        | [End Of Month Item] |     |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom  | Description                                                                                  |                     | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------------------------------------------------|---------------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                                  | Serial Number       |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                                           | SW                  |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                                       |                     |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                                                |                     |     |             |                 |     |                  |             |                    |         |              |
| 723160           | No. 1 Engine - Lp Compressor Fan Blade Assembly -<br>Replace Chocking PAD (BRG3138)          |                     | HRS |             | 994.4           |     |                  | 0           |                    | 0       |              |
|                  |                                                                                              |                     | ENC |             | 392             |     |                  | 0           |                    | 0       |              |
|                  |                                                                                              |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                                              |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                                       | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 723160           | No. 2 Engine - Lp Compressor Fan Blade Assembly -<br>Replace Chocking PAD (BRG3138)          |                     | HRS |             | 994.4           |     |                  | 0           |                    | 0       |              |
|                  |                                                                                              |                     | ENC |             | 392             |     |                  | 0           |                    | 0       |              |
|                  |                                                                                              |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                                              |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                                       | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 723161           | No. 1 Engine - Lp Compressor Fan Blade Assembly -<br>Repair Airfoil Surface Damage (BRG3181) |                     | HRS |             | 994.4           |     |                  | 0           |                    | 0       |              |
|                  |                                                                                              |                     | ENC |             | 392             |     |                  | 0           |                    | 0       |              |
|                  |                                                                                              |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                                              |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                                       | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 723161           | No. 2 Engine - Lp Compressor Fan Blade Assembly -<br>Repair Airfoil Surface Damage (BRG3181) |                     | HRS |             | 994.4           |     |                  | 0           |                    | 0       |              |
|                  |                                                                                              |                     | ENC |             | 392             |     |                  | 0           |                    | 0       |              |
|                  |                                                                                              |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                                              |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                                       | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 723162           | No. 1 Engine - Lp Compressor Fan Blade Assembly -<br>Touch-Up Dry Film Lubricant (BRG3184)   |                     | HRS |             | 994.4           |     |                  | 0           |                    | 0       |              |
|                  |                                                                                              |                     | ENC |             | 392             |     |                  | 0           |                    | 0       |              |
|                  |                                                                                              |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                                              |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                                       | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 723162           | No. 2 Engine - Lp Compressor Fan Blade Assembly -<br>Touch-Up Dry Film Lubricant (BRG3184)   |                     | HRS |             | 994.4           |     |                  | 0           |                    | 0       |              |
|                  |                                                                                              |                     | ENC |             | 392             |     |                  | 0           |                    | 0       |              |
|                  |                                                                                              |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                                              |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                                       | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 723174           | No. 1 Engine - Fan Disc - Removal / Installation<br>PN SN-UNKNOWN                            |                     | HRS |             | 994.4           |     |                  | 0           |                    | 0       |              |
|                  |                                                                                              |                     | ENC |             | 392             |     |                  | 0           |                    | 0       |              |
|                  |                                                                                              |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                                              |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                                       | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                        |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                        | Serial Number |                     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                 | SW            |                     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                             |               |                     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                      |               |                     |             |                 |     |                  |             |                    |         |              |
| 723174           | No. 2 Engine - Fan Disc - Removal / Installation   |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | PN                                                 | SN-UNKNOWN    | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                    |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                    |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
| Engine           | [End Of Month Item]                                |               |                     |             |                 |     |                  |             |                    |         |              |
| 723175           | No. 1 Engine - Fan Disc - Discard                  |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | PN                                                 | SN-UNKNOWN    | ENC                 |             | 392             |     | 5000             | 0           | 5000               |         | 0            |
|                  |                                                    |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                    |         |              |
| 723175           | No. 2 Engine - Fan Disc - Discard                  |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | PN                                                 | SN-UNKNOWN    | ENC                 |             | 392             |     | 5000             | 0           | 5000               |         | 0            |
|                  |                                                    |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                    |         |              |
| 723176           | No. 1 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | No. 1 - Discard                                    | 222977SAP110  | ENC                 |             | 392             |     | 5000             | 0           | 5000               |         | 0            |
|                  |                                                    |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                    |         |              |
| 723176           | No. 2 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | No. 1 - Discard                                    | 222977SAS061  | ENC                 |             | 392             |     | 5000             | 0           | 5000               |         | 0            |
|                  |                                                    |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                    |         |              |
| 723177           | No. 1 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | No. 2 - Discard                                    | 222977SAP135  | ENC                 |             | 392             |     | 5000             | 0           | 5000               |         | 0            |
|                  |                                                    |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                    |         |              |
| 723177           | No. 2 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | No. 2 - Discard                                    | 222977SAS121  | ENC                 |             | 392             |     | 5000             | 0           | 5000               |         | 0            |
|                  |                                                    |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom     | Description                                        |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|---------------------|----------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                     | Part Number                                        | Serial Number |     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position    | HW                                                 | SW            |     |             |                 |     |                  |             |                     |         | Manufacturer |
|                     | MM Ref                                             |               |     |             |                 |     |                  |             |                     |         | Date Type    |
|                     | Ops Number(s)                                      |               |     |             |                 |     |                  |             |                     |         |              |
| 723178              | No. 1 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                     | No. 3 - Discard                                    |               | ENC |             | 392             |     | 5000             | 0           | 5000                |         | 0            |
|                     | FW86142                                            | 222977SAP061  | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
| [End Of Month Item] |                                                    |               |     |             |                 |     |                  |             |                     |         |              |
| Engine              |                                                    |               |     |             |                 |     |                  |             |                     |         |              |
| 723178              | No. 2 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                     | No. 3 - Discard                                    |               | ENC |             | 392             |     | 5000             | 0           | 5000                |         | 0            |
|                     | FW86142                                            | 222977SAM129  | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
| [End Of Month Item] |                                                    |               |     |             |                 |     |                  |             |                     |         |              |
| Engine              |                                                    |               |     |             |                 |     |                  |             |                     |         |              |
| 723179              | No. 1 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                     | No. 4 - Discard                                    |               | ENC |             | 392             |     | 5000             | 0           | 5000                |         | 0            |
|                     | FW86142                                            | 222977SAN069  | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
| [End Of Month Item] |                                                    |               |     |             |                 |     |                  |             |                     |         |              |
| Engine              |                                                    |               |     |             |                 |     |                  |             |                     |         |              |
| 723179              | No. 2 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                     | No. 4 - Discard                                    |               | ENC |             | 392             |     | 5000             | 0           | 5000                |         | 0            |
|                     | FW86142                                            | 222977SAN107  | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
| [End Of Month Item] |                                                    |               |     |             |                 |     |                  |             |                     |         |              |
| Engine              |                                                    |               |     |             |                 |     |                  |             |                     |         |              |
| 723180              | No. 1 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                     | No. 5 - Discard                                    |               | ENC |             | 392             |     | 5000             | 0           | 5000                |         | 0            |
|                     | FW86142                                            | 222977SAS187  | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
| [End Of Month Item] |                                                    |               |     |             |                 |     |                  |             |                     |         |              |
| Engine              |                                                    |               |     |             |                 |     |                  |             |                     |         |              |
| 723180              | No. 2 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                     | No. 5 - Discard                                    |               | ENC |             | 392             |     | 5000             | 0           | 5000                |         | 0            |
|                     | FW86142                                            | 222977SAM135  | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
| [End Of Month Item] |                                                    |               |     |             |                 |     |                  |             |                     |         |              |
| Engine              |                                                    |               |     |             |                 |     |                  |             |                     |         |              |
| 723181              | No. 1 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                     | No. 6 - Discard                                    |               | ENC |             | 392             |     | 5000             | 0           | 5000                |         | 0            |
|                     | FW86142                                            | 222977SAP067  | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
| [End Of Month Item] |                                                    |               |     |             |                 |     |                  |             |                     |         |              |
| Engine              |                                                    |               |     |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom  | Description                                        |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                        | Serial Number |                     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                 | SW            |                     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                             |               |                     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                      |               |                     |             |                 |     |                  |             |                    |         |              |
| 723181           | No. 2 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | No. 6 - Discard                                    |               | ENC                 |             | 392             |     | 5000             | 0           | 5000               |         | 0            |
|                  | FW86142                                            | 222977SAP075  | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                    |         |              |
| 723182           | No. 1 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | No. 7 - Discard                                    |               | ENC                 |             | 392             |     | 5000             | 0           | 5000               |         | 0            |
|                  | FW86142                                            | 222977SAM043  | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                    |         |              |
| 723182           | No. 2 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | No. 7 - Discard                                    |               | ENC                 |             | 392             |     | 5000             | 0           | 5000               |         | 0            |
|                  | FW86142                                            | 222977SAN034  | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                    |         |              |
| 723183           | No. 1 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | No. 8 - Discard                                    |               | ENC                 |             | 392             |     | 5000             | 0           | 5000               |         | 0            |
|                  | FW86142                                            | 222977SAP029  | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                    |         |              |
| 723183           | No. 2 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | No. 8 - Discard                                    |               | ENC                 |             | 392             |     | 5000             | 0           | 5000               |         | 0            |
|                  | FW86142                                            | 222977SAN199  | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                    |         |              |
| 723184           | No. 1 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | No. 9 - Discard                                    |               | ENC                 |             | 392             |     | 5000             | 0           | 5000               |         | 0            |
|                  | FW86142                                            | 222977SAS183  | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                    |         |              |
| 723184           | No. 2 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | No. 9 - Discard                                    |               | ENC                 |             | 392             |     | 5000             | 0           | 5000               |         | 0            |
|                  | FW86142                                            | 222977SAS186  | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                    |         |              |



| ATA<br>U=Custom  | Description                                        |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                        | Serial Number |                     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                 | SW            |                     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                             |               |                     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                      |               |                     |             |                 |     |                  |             |                    |         |              |
| 723185           | No. 1 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | No. 10 - Discard                                   |               | ENC                 |             | 392             |     | 5000             | 0           | 5000               |         | 0            |
|                  | FW86142                                            | 222977SAP050  | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                    |         |              |
| 723185           | No. 2 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | No. 10 - Discard                                   |               | ENC                 |             | 392             |     | 5000             | 0           | 5000               |         | 0            |
|                  | FW86142                                            | 222977SAP122  | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                    |         |              |
| 723186           | No. 1 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | No. 11 - Discard                                   |               | ENC                 |             | 392             |     | 5000             | 0           | 5000               |         | 0            |
|                  | FW86142                                            | 222977SAP121  | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                    |         |              |
| 723186           | No. 2 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | No. 11 - Discard                                   |               | ENC                 |             | 392             |     | 5000             | 0           | 5000               |         | 0            |
|                  | FW86142                                            | 222977SAS114  | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                    |         |              |
| 723187           | No. 1 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | No. 12 - Discard                                   |               | ENC                 |             | 392             |     | 5000             | 0           | 5000               |         | 0            |
|                  | FW86142                                            | 222977SAS065  | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                    |         |              |
| 723187           | No. 2 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | No. 12 - Discard                                   |               | ENC                 |             | 392             |     | 5000             | 0           | 5000               |         | 0            |
|                  | FW86142                                            | 222977SAN187  | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                    |         |              |
| 723188           | No. 1 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | No. 13 - Discard                                   |               | ENC                 |             | 392             |     | 5000             | 0           | 5000               |         | 0            |
|                  | FW86142                                            | 222977SAS034  | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                        |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(* =Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|----------------------|---------|--------------|
|                  | Part Number                                        | Serial Number |                     |             |                 |     |                  |             |                      |         | Approx Price |
| Logbook Position | HW                                                 | SW            |                     |             |                 |     |                  |             |                      |         | Manufacturer |
|                  | MM Ref                                             |               |                     |             |                 |     |                  |             |                      |         | Date Type    |
|                  | Ops Number(s)                                      |               |                     |             |                 |     |                  |             |                      |         |              |
| 723188           | No. 2 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                  | No. 13 - Discard                                   |               | ENC                 |             | 392             |     | 5000             | 0           | 5000                 |         | 0            |
|                  | FW86142                                            | 222977SAP109  | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                      |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                      |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                      |         |              |
| 723189           | No. 1 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                  | No. 14 - Discard                                   |               | ENC                 |             | 392             |     | 5000             | 0           | 5000                 |         | 0            |
|                  | FW86142                                            | 222977SAP124  | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                      |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                      |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                      |         |              |
| 723189           | No. 2 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                  | No. 14 - Discard                                   |               | ENC                 |             | 392             |     | 5000             | 0           | 5000                 |         | 0            |
|                  | FW86142                                            | 222977SAS126  | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                      |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                      |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                      |         |              |
| 723190           | No. 1 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                  | No. 15 - Discard                                   |               | ENC                 |             | 392             |     | 5000             | 0           | 5000                 |         | 0            |
|                  | FW86142                                            | 222977SAN066  | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                      |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                      |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                      |         |              |
| 723190           | No. 2 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                  | No. 15 - Discard                                   |               | ENC                 |             | 392             |     | 5000             | 0           | 5000                 |         | 0            |
|                  | FW86142                                            | 222977SAN142  | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                      |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                      |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                      |         |              |
| 723191           | No. 1 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                  | No. 16 - Discard                                   |               | ENC                 |             | 392             |     | 5000             | 0           | 5000                 |         | 0            |
|                  | FW86142                                            | 222977SAS033  | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                      |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                      |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                      |         |              |
| 723191           | No. 2 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                  | No. 16 - Discard                                   |               | ENC                 |             | 392             |     | 5000             | 0           | 5000                 |         | 0            |
|                  | FW86142                                            | 222977SAS135  | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                      |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                      |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                      |         |              |

| ATA<br>U=Custom  | Description                                        |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                        | Serial Number |                     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                 | SW            |                     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                             |               |                     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                      |               |                     |             |                 |     |                  |             |                    |         |              |
| 723192           | No. 1 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | No. 17 - Discard                                   |               | ENC                 |             | 392             |     | 5000             | 0           | 5000               |         | 0            |
|                  | FW86142                                            | 222977SAN008  | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                    |         |              |
| 723192           | No. 2 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | No. 17 - Discard                                   |               | ENC                 |             | 392             |     | 5000             | 0           | 5000               |         | 0            |
|                  | FW86142                                            | 222977SAN053  | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                    |         |              |
| 723193           | No. 1 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | No. 18 - Discard                                   |               | ENC                 |             | 392             |     | 5000             | 0           | 5000               |         | 0            |
|                  | FW86142                                            | 222977SAP106  | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                    |         |              |
| 723193           | No. 2 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | No. 18 - Discard                                   |               | ENC                 |             | 392             |     | 5000             | 0           | 5000               |         | 0            |
|                  | FW86142                                            | 222977SAP136  | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                    |         |              |
| 723194           | No. 1 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | No. 19 - Discard                                   |               | ENC                 |             | 392             |     | 5000             | 0           | 5000               |         | 0            |
|                  | FW86142                                            | 222977SAN009  | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                    |         |              |
| 723194           | No. 2 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | No. 19 - Discard                                   |               | ENC                 |             | 392             |     | 5000             | 0           | 5000               |         | 0            |
|                  | FW86142                                            | 222977SAP117  | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                    |         |              |
| 723195           | No. 1 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | No. 20 - Discard                                   |               | ENC                 |             | 392             |     | 5000             | 0           | 5000               |         | 0            |
|                  | FW86142                                            | 222977SAP066  | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                        |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                        | Serial Number |                     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                 | SW            |                     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                             |               |                     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                      |               |                     |             |                 |     |                  |             |                    |         |              |
| 723195           | No. 2 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | No. 20 - Discard                                   |               | ENC                 |             | 392             |     | 5000             | 0           | 5000               |         | 0            |
|                  | FW86142                                            | 222977SAP077  | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                    |         |              |
| 723196           | No. 1 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | No. 21 - Discard                                   |               | ENC                 |             | 392             |     | 5000             | 0           | 5000               |         | 0            |
|                  | FW86142                                            | 222977SAN007  | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                    |         |              |
| 723196           | No. 2 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | No. 21 - Discard                                   |               | ENC                 |             | 392             |     | 5000             | 0           | 5000               |         | 0            |
|                  | FW86142                                            | 222977SAN045  | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                    |         |              |
| 723197           | No. 1 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | No. 22 - Discard                                   |               | ENC                 |             | 392             |     | 5000             | 0           | 5000               |         | 0            |
|                  | FW86142                                            | 222977SAN071  | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                    |         |              |
| 723197           | No. 2 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | No. 22 - Discard                                   |               | ENC                 |             | 392             |     | 5000             | 0           | 5000               |         | 0            |
|                  | FW86142                                            | 222977SAM048  | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                    |         |              |
| 723198           | No. 1 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | No. 23 - Discard                                   |               | ENC                 |             | 392             |     | 5000             | 0           | 5000               |         | 0            |
|                  | FW86142                                            | 222977SAP060  | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                    |         |              |
| 723198           | No. 2 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | No. 23 - Discard                                   |               | ENC                 |             | 392             |     | 5000             | 0           | 5000               |         | 0            |
|                  | FW86142                                            | 222977SAM053  | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom     | Description                                                           |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|---------------------|-----------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                     | Part Number                                                           | Serial Number |     |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position    | HW                                                                    | SW            |     |             |                 |     |                  |             |                    |             | Manufacturer |
|                     | MM Ref                                                                |               |     |             |                 |     |                  |             |                    |             | Date Type    |
|                     | Ops Number(s)                                                         |               |     |             |                 |     |                  |             |                    |             |              |
| 723199              | No. 1 Engine - Low-Pressure Compressor (Fan) Blade                    |               | HRS |             | 994.4           |     |                  | 0           |                    |             | 0            |
|                     | No. 24 - Discard                                                      |               | ENC |             | 392             |     | 5000             | 0           | 5000               |             | 0            |
|                     | FW86142                                                               | 222977SAN043  | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |             |              |
|                     | [End Of Month Item]                                                   |               |     |             |                 |     |                  |             |                    |             |              |
| Engine              |                                                                       |               |     |             |                 |     |                  |             |                    |             |              |
| 723199              | No. 2 Engine - Low-Pressure Compressor (Fan) Blade                    |               | HRS |             | 994.4           |     |                  | 0           |                    |             | 0            |
|                     | No. 24 - Discard                                                      |               | ENC |             | 392             |     | 5000             | 0           | 5000               |             | 0            |
|                     | FW86142                                                               | 222977SAN185  | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |             |              |
|                     | [End Of Month Item]                                                   |               |     |             |                 |     |                  |             |                    |             |              |
| Engine              |                                                                       |               |     |             |                 |     |                  |             |                    |             |              |
| 723200              | No. 1 Engine - Lp Compressor Outlet Guide Vanes - Detailed Inspection |               | HRS |             | 994.4           |     | 4800             | 0           | 4800               | 4850        | 0            |
|                     |                                                                       |               | ENC |             | 392             |     |                  | 0           |                    |             | 0            |
|                     |                                                                       |               | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |             |              |
|                     | [End Of Month Item] [HRS: +50/-50]                                    |               |     |             |                 |     |                  |             |                    |             |              |
| Engine              |                                                                       |               |     |             |                 |     |                  |             |                    |             |              |
| 052006              |                                                                       |               |     |             |                 |     |                  |             |                    |             |              |
| 723200              | No. 2 Engine - Lp Compressor Outlet Guide Vanes - Detailed Inspection |               | HRS |             | 994.4           |     | 4800             | 0           | 4800               | 4850        | 0            |
|                     |                                                                       |               | ENC |             | 392             |     |                  | 0           |                    |             | 0            |
|                     |                                                                       |               | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |             |              |
|                     | [End Of Month Item] [HRS: +50/-50]                                    |               |     |             |                 |     |                  |             |                    |             |              |
| Engine              |                                                                       |               |     |             |                 |     |                  |             |                    |             |              |
| 052006              |                                                                       |               |     |             |                 |     |                  |             |                    |             |              |
| 723201              | No. 1 Engine - Intermediate Case - Detailed Inspection                |               | HRS |             | 994.4           |     |                  | 0           |                    |             | 0            |
|                     |                                                                       |               | ENC |             | 392             |     |                  | 0           |                    |             | 0            |
|                     |                                                                       |               | MOS |             | 41.8            |     | 240              | 17 Nov 2022 | 30 Nov 2042        | 31 Dec 2042 |              |
|                     | [End Of Month Item] [MOS: +1m/-1m]                                    |               |     |             |                 |     |                  |             |                    |             |              |
| Engine              |                                                                       |               |     |             |                 |     |                  |             |                    |             |              |
| 723201              | No. 2 Engine - Intermediate Case - Detailed Inspection                |               | HRS |             | 994.4           |     |                  | 0           |                    |             | 0            |
|                     |                                                                       |               | ENC |             | 392             |     |                  | 0           |                    |             | 0            |
|                     |                                                                       |               | MOS |             | 41.9            |     | 240              | 15 Nov 2022 | 30 Nov 2042        | 31 Dec 2042 |              |
|                     | [End Of Month Item] [MOS: +1m/-1m]                                    |               |     |             |                 |     |                  |             |                    |             |              |
| Engine              |                                                                       |               |     |             |                 |     |                  |             |                    |             |              |
| 723202              | No. 1 Engine - Intermediate Case Struts - Inspection                  |               | HRS |             | 994.4           |     |                  | 0           |                    |             | 0            |
|                     |                                                                       |               | ENC |             | 392             |     |                  | 0           |                    |             | 0            |
|                     |                                                                       |               | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |             |              |
|                     |                                                                       |               | MSC |             |                 |     | O/C              |             |                    |             |              |
| Engine              |                                                                       |               |     |             |                 |     |                  |             |                    |             |              |
| [End Of Month Item] |                                                                       |               |     |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom  | Description                                                     |                     | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-----------------------------------------------------------------|---------------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                     | Serial Number       |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                              | SW                  |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                          |                     |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                   |                     |     |             |                 |     |                  |             |                    |         |              |
| 723202           | No. 2 Engine - Intermediate Case Struts - Inspection            |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                 |                     | ENC |             | 392             |     |                  | 0           |                    | 0       |              |
|                  |                                                                 |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                 |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 723203           | No. 1 Engine - Lp Compressor Static Seal Housing - Inspection   |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                 |                     | ENC |             | 392             |     |                  | 0           |                    | 0       |              |
|                  |                                                                 |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                 |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 723203           | No. 2 Engine - Lp Compressor Static Seal Housing - Inspection   |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                 |                     | ENC |             | 392             |     |                  | 0           |                    | 0       |              |
|                  |                                                                 |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                 |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 723204           | No. 1 Engine - NI Speed Probe Plugs (N1-1 to Eec) - Interchange |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                 |                     | ENC |             | 392             |     |                  | 0           |                    | 0       |              |
|                  |                                                                 |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                 |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 723204           | No. 2 Engine - NI Speed Probe Plugs (N1-1 to Eec) - Interchange |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                 |                     | ENC |             | 392             |     |                  | 0           |                    | 0       |              |
|                  |                                                                 |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                 |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 723205           | No. 1 Engine - NI Speed Probe Plugs (N1-2 to Eec) - Interchange |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                 |                     | ENC |             | 392             |     |                  | 0           |                    | 0       |              |
|                  |                                                                 |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                 |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 723205           | No. 2 Engine - NI Speed Probe Plugs (N1-2 to Eec) - Interchange |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                 |                     | ENC |             | 392             |     |                  | 0           |                    | 0       |              |
|                  |                                                                 |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                 |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                                                      |                     | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------------------------------------------------------------------------------|---------------------|-----|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                                                                                      | Serial Number       |     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                                                                               | SW                  |     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                                                                           |                     |     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                                                                                    |                     |     |             |                 |     |                  |             |                     |         |              |
| 723206           | No. 1 Engine - NI Speed Probe Plugs (N1 OPR Harness to Airframe) - Interchange                                   |                     | HRS |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                                                                  |                     | ENC |             | 392             |     |                  | 0           |                     | 0       |              |
|                  |                                                                                                                  |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                                                                  |                     | MSC |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                                                           | [End Of Month Item] |     |             |                 |     |                  |             |                     |         |              |
| 723206           | No. 2 Engine - NI Speed Probe Plugs (N1 OPR Harness to Airframe) - Interchange                                   |                     | HRS |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                                                                  |                     | ENC |             | 392             |     |                  | 0           |                     | 0       |              |
|                  |                                                                                                                  |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                                                                  |                     | MSC |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                                                           | [End Of Month Item] |     |             |                 |     |                  |             |                     |         |              |
| 723207           | No. 1 Engine - NI Speed Probe Plugs (N2 OPR Harness to Airframe) - Interchange                                   |                     | HRS |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                                                                  |                     | ENC |             | 392             |     |                  | 0           |                     | 0       |              |
|                  |                                                                                                                  |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                                                                  |                     | MSC |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                                                           | [End Of Month Item] |     |             |                 |     |                  |             |                     |         |              |
| 723207           | No. 2 Engine - NI Speed Probe Plugs (N2 OPR Harness to Airframe) - Interchange                                   |                     | HRS |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                                                                  |                     | ENC |             | 392             |     |                  | 0           |                     | 0       |              |
|                  |                                                                                                                  |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                                                                  |                     | MSC |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                                                           | [End Of Month Item] |     |             |                 |     |                  |             |                     |         |              |
| 723208           | No. 1 Engine - Lp Compressor Outlet Guide Vanes - Repair By Damage Dressing and Restoration of Airfoil (BRG3144) |                     | HRS |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                                                                  |                     | ENC |             | 392             |     |                  | 0           |                     | 0       |              |
|                  |                                                                                                                  |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                                                                  |                     | MSC |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                                                           | [End Of Month Item] |     |             |                 |     |                  |             |                     |         |              |
| 723208           | No. 2 Engine - Lp Compressor Outlet Guide Vanes - Repair By Damage Dressing and Restoration of Airfoil (BRG3144) |                     | HRS |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                                                                  |                     | ENC |             | 392             |     |                  | 0           |                     | 0       |              |
|                  |                                                                                                                  |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                                                                  |                     | MSC |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                                                           | [End Of Month Item] |     |             |                 |     |                  |             |                     |         |              |
| 723209           | No. 1 Engine - Lp Compressor Outlet Guide Vanes - Repair Leading Edge Using Doubler (BRG3139)                    |                     | HRS |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                                                                  |                     | ENC |             | 392             |     |                  | 0           |                     | 0       |              |
|                  |                                                                                                                  |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                                                                  |                     | MSC |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                                                           | [End Of Month Item] |     |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom  | Description                                                                                      |                     | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|--------------------------------------------------------------------------------------------------|---------------------|---------------------|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                                                                      | Serial Number       |                     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                                                               | SW                  |                     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                                                           |                     |                     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                                                                    |                     |                     |             |                 |     |                  |             |                     |         |              |
| 723209           | No. 2 Engine - Lp Compressor Outlet Guide Vanes -<br>Repair Leading Edge Using Doubler (BRG3139) |                     | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                                                  |                     | ENC                 |             | 392             |     |                  | 0           |                     | 0       |              |
|                  |                                                                                                  |                     | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                                                  |                     | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                                           | [End Of Month Item] |                     |             |                 |     |                  |             |                     |         |              |
| 723210           | No. 1 Engine - Lp Compressor Outlet Guide Vanes -<br>Inspection                                  |                     | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                                                  |                     | ENC                 |             | 392             |     |                  | 0           |                     | 0       |              |
|                  |                                                                                                  |                     | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                                                  |                     | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                                           | [End Of Month Item] |                     |             |                 |     |                  |             |                     |         |              |
| 723210           | No. 2 Engine - Lp Compressor Outlet Guide Vanes -<br>Inspection                                  |                     | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                                                  |                     | ENC                 |             | 392             |     |                  | 0           |                     | 0       |              |
|                  |                                                                                                  |                     | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                                                  |                     | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                                           | [End Of Month Item] |                     |             |                 |     |                  |             |                     |         |              |
| 723211           | No. 1 Engine - Fan Shaft - Removal / Installation<br>PN SN-UNKNOWN                               |                     | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                                                  |                     | ENC                 |             | 392             |     |                  | 0           |                     | 0       |              |
|                  |                                                                                                  |                     | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                                                  |                     | MSC                 |             |                 |     | H/T              |             |                     |         |              |
|                  | Engine                                                                                           | [End Of Month Item] |                     |             |                 |     |                  |             |                     |         |              |
| 723211           | No. 2 Engine - Fan Shaft - Removal / Installation<br>PN SN-UNKNOWN                               |                     | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                                                  |                     | ENC                 |             | 392             |     |                  | 0           |                     | 0       |              |
|                  |                                                                                                  |                     | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                                                  |                     | MSC                 |             |                 |     | H/T              |             |                     |         |              |
|                  | Engine                                                                                           | [End Of Month Item] |                     |             |                 |     |                  |             |                     |         |              |
| 723212           | No. 1 Engine - Fan Shaft - Discard<br>PN SN-UNKNOWN                                              |                     | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                                                  |                     | ENC                 |             | 392             |     | 5000             | 0           | 5000                |         | 0            |
|                  |                                                                                                  |                     | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                                                  |                     | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
|                  | Engine                                                                                           |                     |                     |             |                 |     |                  |             |                     |         |              |
| 723212           | No. 2 Engine - Fan Shaft - Discard<br>PN SN-UNKNOWN                                              |                     | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                                                  |                     | ENC                 |             | 392             |     | 5000             | 0           | 5000                |         | 0            |
|                  |                                                                                                  |                     | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                                                  |                     | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
|                  | Engine                                                                                           |                     |                     |             |                 |     |                  |             |                     |         |              |
| 723213           | No. 1 Engine - Intermediate Case - Removal / Installation<br>PN SN-UNKNOWN                       |                     | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                                                  |                     | ENC                 |             | 392             |     |                  | 0           |                     | 0       |              |
|                  |                                                                                                  |                     | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                                                  |                     | MSC                 |             |                 |     | H/T              |             |                     |         |              |
|                  | Engine                                                                                           | [End Of Month Item] |                     |             |                 |     |                  |             |                     |         |              |



| ATA<br>U=Custom  | Description                                                                                        |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                                        | Serial Number |                     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                                                 | SW            |                     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                                             |               |                     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                                                      |               |                     |             |                 |     |                  |             |                    |         |              |
| 723213           | No. 2 Engine - Intermediate Case - Removal / Installation                                          |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | PN SN-UNKNOWN                                                                                      |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                    |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                                                                             |               | MSC                 |             |                 |     | H/T              |             |                    |         |              |
|                  |                                                                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 723214           | No. 1 Engine - Intermediate Case - Discard                                                         |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | PN SN-UNKNOWN                                                                                      |               | ENC                 |             | 392             |     | 15000            | 0           | 15000              |         | 0            |
|                  |                                                                                                    |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                                                                             |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
|                  |                                                                                                    |               |                     |             |                 |     |                  |             |                    |         |              |
| 723214           | No. 2 Engine - Intermediate Case - Discard                                                         |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | PN SN-UNKNOWN                                                                                      |               | ENC                 |             | 392             |     | 15000            | 0           | 15000              |         | 0            |
|                  |                                                                                                    |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                                                                             |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
|                  |                                                                                                    |               |                     |             |                 |     |                  |             |                    |         |              |
| 723300           | No. 1 Engine - Hp Compressor Front Drum (Stage 1 Disc, Stages 2-6 Blisks) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | PN SN-UNKNOWN                                                                                      |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                    |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                                                                             |               | MSC                 |             |                 |     | H/T              |             |                    |         |              |
|                  |                                                                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 723300           | No. 2 Engine - Hp Compressor Front Drum (Stage 1 Disc, Stages 2-6 Blisks) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | PN SN-UNKNOWN                                                                                      |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                    |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                                                                             |               | MSC                 |             |                 |     | H/T              |             |                    |         |              |
|                  |                                                                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 723301           | No. 1 Engine - Hp Compressor Front Drum (Stage 1 Disc, Stages 2-6 Blisks) - Discard                |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | PN SN-UNKNOWN                                                                                      |               | ENC                 |             | 392             |     | 10000            | 0           | 10000              |         | 0            |
|                  |                                                                                                    |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                                                                             |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
|                  |                                                                                                    |               |                     |             |                 |     |                  |             |                    |         |              |
| 723301           | No. 2 Engine - Hp Compressor Front Drum (Stage 1 Disc, Stages 2-6 Blisks) - Discard                |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | PN SN-UNKNOWN                                                                                      |               | ENC                 |             | 392             |     | 10000            | 0           | 10000              |         | 0            |
|                  |                                                                                                    |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                                                                             |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
|                  |                                                                                                    |               |                     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                        |                                                   | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------|------------------------------------------------------------------------------------|---------------------------------------------------|---------------------|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                  | Part Number                                                                        | Serial Number                                     |                     |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position | HW                                                                                 | SW                                                |                     |             |                 |     |                  |             |                    |             | Manufacturer |
|                  | MM Ref                                                                             |                                                   |                     |             |                 |     |                  |             |                    |             | Date Type    |
|                  | Ops Number(s)                                                                      |                                                   |                     |             |                 |     |                  |             |                    |             |              |
| 723302           | No. 1 Engine - Hp Compressor Rear Drum (Stages 7-10 Disc) - Removal / Installation |                                                   | HRS                 |             | 994.4           |     |                  | 0           |                    |             | 0            |
|                  |                                                                                    |                                                   | ENC                 |             | 392             |     |                  | 0           |                    |             | 0            |
|                  | PN                                                                                 | SN-UNKNOWN                                        | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |             |              |
|                  |                                                                                    |                                                   | MSC                 |             |                 |     | H/T              |             |                    |             |              |
|                  | Engine                                                                             | [End Of Month Item]                               |                     |             |                 |     |                  |             |                    |             |              |
| 723302           | No. 2 Engine - Hp Compressor Rear Drum (Stages 7-10 Disc) - Removal / Installation |                                                   | HRS                 |             | 994.4           |     |                  | 0           |                    |             | 0            |
|                  |                                                                                    |                                                   | ENC                 |             | 392             |     |                  | 0           |                    |             | 0            |
|                  | PN                                                                                 | SN-UNKNOWN                                        | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |             |              |
|                  |                                                                                    |                                                   | MSC                 |             |                 |     | H/T              |             |                    |             |              |
|                  | Engine                                                                             | [End Of Month Item]                               |                     |             |                 |     |                  |             |                    |             |              |
| 723303           | No. 1 Engine - Hp Compressor Rear Drum (Stages 7-10 Discs) - Discard               |                                                   | HRS                 |             | 994.4           |     |                  | 0           |                    |             | 0            |
|                  |                                                                                    |                                                   | ENC                 |             | 392             |     | 10000            | 0           | 10000              |             | 0            |
|                  | PN                                                                                 | SN-UNKNOWN                                        | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |             |              |
|                  |                                                                                    |                                                   | [End Of Month Item] |             |                 |     |                  |             |                    |             |              |
|                  | Engine                                                                             |                                                   |                     |             |                 |     |                  |             |                    |             |              |
| 723303           | No. 2 Engine - Hp Compressor Rear Drum (Stages 7-10 Discs) - Discard               |                                                   | HRS                 |             | 994.4           |     |                  | 0           |                    |             | 0            |
|                  |                                                                                    |                                                   | ENC                 |             | 392             |     | 10000            | 0           | 10000              |             | 0            |
|                  | PN                                                                                 | SN-UNKNOWN                                        | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |             |              |
|                  |                                                                                    |                                                   | [End Of Month Item] |             |                 |     |                  |             |                    |             |              |
|                  | Engine                                                                             |                                                   |                     |             |                 |     |                  |             |                    |             |              |
| 723334           | No. 1 Engine - Variable Stator Vane Actuating Mechanism - Functional Check         |                                                   | HRS                 |             | 730.5           |     | 1200             | 263.9       | 1463.9             | 1513.9      | 0            |
|                  |                                                                                    |                                                   | ENC                 |             | 315             |     |                  | 77          |                    |             | 0            |
|                  |                                                                                    |                                                   | MOS                 |             | 28.7            |     | 48               | 21 Dec 2023 | 31 Dec 2027        | 31 Jan 2028 |              |
|                  | (723334)                                                                           | [End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50] |                     |             |                 |     |                  |             |                    |             |              |
|                  | Engine                                                                             | 052002,052013                                     |                     |             |                 |     |                  |             |                    |             |              |
| 723334           | No. 2 Engine - Variable Stator Vane Actuating Mechanism - Functional Check         |                                                   | HRS                 |             | 730.5           |     | 1200             | 263.9       | 1463.9             | 1513.9      | 0            |
|                  |                                                                                    |                                                   | ENC                 |             | 315             |     |                  | 77          |                    |             | 0            |
|                  |                                                                                    |                                                   | MOS                 |             | 28.7            |     | 48               | 21 Dec 2023 | 31 Dec 2027        | 31 Jan 2028 |              |
|                  | (723334)                                                                           | [End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50] |                     |             |                 |     |                  |             |                    |             |              |
|                  | Engine                                                                             | 052002,052013                                     |                     |             |                 |     |                  |             |                    |             |              |
| 723335           | No. 1 Engine - Variable Stator Vane Actuation Mechanism - Lubrication              |                                                   | HRS                 |             | 730.5           |     | 1200             | 263.9       | 1463.9             | 1513.9      | 0            |
|                  |                                                                                    |                                                   | ENC                 |             | 315             |     |                  | 77          |                    |             | 0            |
|                  |                                                                                    |                                                   | MOS                 |             | 28.7            |     | 48               | 21 Dec 2023 | 31 Dec 2027        | 31 Jan 2028 |              |
|                  | (723335)                                                                           | [End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50] |                     |             |                 |     |                  |             |                    |             |              |
|                  | Engine                                                                             | 052002,052013                                     |                     |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom  | Description                                                                                                                                |                                                   | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------|--------------------------------------------------------------------------------------------------------------------------------------------|---------------------------------------------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                  | Part Number                                                                                                                                | Serial Number                                     |     |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position | HW                                                                                                                                         | SW                                                |     |             |                 |     |                  |             |                    |             | Manufacturer |
|                  | MM Ref                                                                                                                                     |                                                   |     |             |                 |     |                  |             |                    |             | Date Type    |
|                  | Ops Number(s)                                                                                                                              |                                                   |     |             |                 |     |                  |             |                    |             |              |
| 723335           | No. 2 Engine - Variable Stator Vane Actuation Mechanism<br>- Lubrication                                                                   |                                                   | HRS |             | 730.5           |     | 1200             | 263.9       | 1463.9             | 1513.9      | 0            |
|                  |                                                                                                                                            |                                                   | ENC |             | 315             |     |                  | 77          |                    |             | 0            |
|                  |                                                                                                                                            |                                                   | MOS |             | 28.7            |     | 48               | 21 Dec 2023 | 31 Dec 2027        | 31 Jan 2028 |              |
|                  | (723335)                                                                                                                                   | [End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50] |     |             |                 |     |                  |             |                    |             |              |
| Engine           | 052002,052013                                                                                                                              |                                                   |     |             |                 |     |                  |             |                    |             |              |
| 723400           | No. 1 Engine - Lp Compressor Case Outer Surface -<br>Detailed Inspection                                                                   |                                                   | HRS |             | 137             |     |                  | 857.4       |                    |             | 0            |
|                  |                                                                                                                                            |                                                   | ENC |             | 52              |     |                  | 340         |                    |             | 0            |
|                  |                                                                                                                                            |                                                   | MOS |             | 5.2             |     | 120              | 04 Dec 2025 | 31 Dec 2035        | 31 Jan 2036 |              |
|                  | Engine                                                                                                                                     | [End Of Month Item] [MOS: +1m/-1m]                |     |             |                 |     |                  |             |                    |             |              |
|                  | 052018                                                                                                                                     |                                                   |     |             |                 |     |                  |             |                    |             |              |
| 723400           | No. 2 Engine - Lp Compressor Case Outer Surface -<br>Detailed Inspection                                                                   |                                                   | HRS |             | 137             |     |                  | 857.4       |                    |             | 0            |
|                  |                                                                                                                                            |                                                   | ENC |             | 52              |     |                  | 340         |                    |             | 0            |
|                  |                                                                                                                                            |                                                   | MOS |             | 5.2             |     | 120              | 04 Dec 2025 | 31 Dec 2035        | 31 Jan 2036 |              |
|                  | Engine                                                                                                                                     | [End Of Month Item] [MOS: +1m/-1m]                |     |             |                 |     |                  |             |                    |             |              |
|                  | 052018                                                                                                                                     |                                                   |     |             |                 |     |                  |             |                    |             |              |
| 723401           | No. 1 Engine - Lp Compressor Case Inner Surface -<br>General Visual Inspection                                                             |                                                   | HRS |             | 137             | 6.5 | 600              | 857.4       | 1463.9*            | 1513.9      | 0            |
|                  |                                                                                                                                            |                                                   | ENC |             | 52              |     |                  | 340         |                    |             | 0            |
|                  |                                                                                                                                            |                                                   | MOS |             | 5.3             |     |                  | 02 Dec 2025 |                    |             |              |
|                  | Engine                                                                                                                                     | [End Of Month Item] [HRS: +50/-50]                |     |             |                 |     |                  |             |                    |             |              |
|                  | 052001                                                                                                                                     |                                                   |     |             |                 |     |                  |             |                    |             |              |
| 723401           | No. 2 Engine - Lp Compressor Case Inner Surface -<br>General Visual Inspection                                                             |                                                   | HRS |             | 137             | 6.5 | 600              | 857.4       | 1463.9*            | 1513.9      | 0            |
|                  |                                                                                                                                            |                                                   | ENC |             | 52              |     |                  | 340         |                    |             | 0            |
|                  |                                                                                                                                            |                                                   | MOS |             | 5.3             |     |                  | 02 Dec 2025 |                    |             |              |
|                  | Engine                                                                                                                                     | [End Of Month Item] [HRS: +50/-50]                |     |             |                 |     |                  |             |                    |             |              |
|                  | 052001                                                                                                                                     |                                                   |     |             |                 |     |                  |             |                    |             |              |
| 723402           | No. 1 Engine - Lp Compressor Case Assembly - Repair<br>Fan Track Liner Without Damaged Honeycomb Above<br>Grp Layer Using Filler (BRG3140) |                                                   | HRS |             | 994.4           |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                                                            |                                                   | ENC |             | 392             |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                                                            |                                                   | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |             |              |
|                  |                                                                                                                                            |                                                   | MSC |             |                 |     | O/C              |             |                    |             |              |
|                  | Engine                                                                                                                                     | [End Of Month Item]                               |     |             |                 |     |                  |             |                    |             |              |
| 723402           | No. 2 Engine - Lp Compressor Case Assembly - Repair<br>Fan Track Liner Without Damaged Honeycomb Above<br>Grp Layer Using Filler (BRG3140) |                                                   | HRS |             | 994.4           |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                                                            |                                                   | ENC |             | 392             |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                                                            |                                                   | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |             |              |
|                  |                                                                                                                                            |                                                   | MSC |             |                 |     | O/C              |             |                    |             |              |
|                  | Engine                                                                                                                                     | [End Of Month Item]                               |     |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom  | Description                                                                                                                             |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|-----------------------------------------------------------------------------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                                                                                                             | Serial Number |                     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                                                                                                      | SW            |                     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                                                                                                  |               |                     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                                                                                                           |               |                     |             |                 |     |                  |             |                     |         |              |
| 723403           | No. 1 Engine - Lp Compressor Case Assembly - Repair<br>Fan Track Liner With Damaged Honeycomb Above Grp<br>Layer Using Filler (BRG3141) |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                                                                                         |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                                                                                                                         |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                                                                                         |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  |                                                                                                                                         |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| Engine           |                                                                                                                                         |               |                     |             |                 |     |                  |             |                     |         |              |
| 723403           | No. 2 Engine - Lp Compressor Case Assembly - Repair<br>Fan Track Liner With Damaged Honeycomb Above Grp<br>Layer Using Filler (BRG3141) |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                                                                                         |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                                                                                                                         |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                                                                                         |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  |                                                                                                                                         |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| Engine           |                                                                                                                                         |               |                     |             |                 |     |                  |             |                     |         |              |
| 723404           | No. 1 Engine - Lp Compressor Case Assembly - Repair<br>Rear Lining Panel Using Polysulphide Compound<br>(BRG3142)                       |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                                                                                         |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                                                                                                                         |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                                                                                         |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  |                                                                                                                                         |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| Engine           |                                                                                                                                         |               |                     |             |                 |     |                  |             |                     |         |              |
| 723404           | No. 2 Engine - Lp Compressor Case Assembly - Repair<br>Rear Lining Panel Using Polysulphide Compound<br>(BRG3142)                       |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                                                                                         |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                                                                                                                         |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                                                                                         |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  |                                                                                                                                         |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| Engine           |                                                                                                                                         |               |                     |             |                 |     |                  |             |                     |         |              |
| 723405           | No. 1 Engine - Lp Compressor Case Fan Track Liner -<br>Removal / Installation<br>PN SN-UNKNOWN                                          |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                                                                                         |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                                                                                                                         |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                                                                                         |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  |                                                                                                                                         |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| Engine           |                                                                                                                                         |               |                     |             |                 |     |                  |             |                     |         |              |
| 723405           | No. 2 Engine - Lp Compressor Case Fan Track Liner -<br>Removal / Installation<br>PN SN-UNKNOWN                                          |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                                                                                         |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                                                                                                                         |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                                                                                         |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  |                                                                                                                                         |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| Engine           |                                                                                                                                         |               |                     |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom  | Description                                                       |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                       | Serial Number |                     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                | SW            |                     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                            |               |                     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                     |               |                     |             |                 |     |                  |             |                    |         |              |
| 723407           | No. 1 Engine - Rear Acoustic Panels - Removal / Installation      |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                   |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | PN                                                                | SN-UNKNOWN    | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                   |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                            |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 723407           | No. 2 Engine - Rear Acoustic Panels - Removal / Installation      |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                   |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | PN                                                                | SN-UNKNOWN    | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                   |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                            |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 723409           | No. 1 Engine - Case Assembly - Removal / Installation             |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | PN                                                                |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                                   |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                   |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                            |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 723409           | No. 2 Engine - Case Assembly - Removal / Installation             |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | PN                                                                |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                                   |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                   |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                            |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 723410           | No. 1 Engine - Lp Compressor Case Module - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | PN                                                                |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                                   |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                   |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                            |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 723410           | No. 2 Engine - Lp Compressor Case Module - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | PN                                                                |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                                   |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                   |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                            |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 723500           | No. 1 Engine - Low-Pressure Compressor (Fan) Blade                |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | No. 1- Blade Root Copper Nickel Indium Coating - Refurbishment    |               | ENC                 |             | 392             |     | 5000             | 0           | 5000               |         | 0            |
|                  |                                                                   |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                   |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
|                  | Engine                                                            |               |                     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                        |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                        | Serial Number |                     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                 | SW            |                     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                             |               |                     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                      |               |                     |             |                 |     |                  |             |                     |         |              |
| 723500           | No. 2 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | No. 1- Blade Root Copper Nickel Indium Coating -   |               | ENC                 |             | 392             |     | 5000             | 0           | 5000                |         | 0            |
|                  | Refurbishment                                      |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                     |         |              |
| 723501           | No. 1 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | No. 2 - Blade Root Copper Nickel Indium Coating -  |               | ENC                 |             | 392             |     | 5000             | 0           | 5000                |         | 0            |
|                  | Refurbishment                                      |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                     |         |              |
| 723501           | No. 2 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | No. 2 - Blade Root Copper Nickel Indium Coating -  |               | ENC                 |             | 392             |     | 5000             | 0           | 5000                |         | 0            |
|                  | Refurbishment                                      |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                     |         |              |
| 723502           | No. 1 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | No. 3 - Blade Root Copper Nickel Indium Coating -  |               | ENC                 |             | 392             |     | 5000             | 0           | 5000                |         | 0            |
|                  | Refurbishment                                      |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                     |         |              |
| 723502           | No. 2 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | No. 3 - Blade Root Copper Nickel Indium Coating -  |               | ENC                 |             | 392             |     | 5000             | 0           | 5000                |         | 0            |
|                  | Refurbishment                                      |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                     |         |              |
| 723503           | No. 1 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | No. 4 - Blade Root Copper Nickel Indium Coating -  |               | ENC                 |             | 392             |     | 5000             | 0           | 5000                |         | 0            |
|                  | Refurbishment                                      |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom  | Description                                        |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                        | Serial Number |                     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                 | SW            |                     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                             |               |                     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                      |               |                     |             |                 |     |                  |             |                    |         |              |
| 723503           | No. 2 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | No. 4 - Blade Root Copper Nickel Indium Coating -  |               | ENC                 |             | 392             |     | 5000             | 0           | 5000               |         | 0            |
|                  | Refurbishment                                      |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                    |         |              |
| 723504           | No. 1 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | No. 5 - Blade Root Copper Nickel Indium Coating -  |               | ENC                 |             | 392             |     | 5000             | 0           | 5000               |         | 0            |
|                  | Refurbishment                                      |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                    |         |              |
| 723504           | No. 2 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | No. 5 - Blade Root Copper Nickel Indium Coating -  |               | ENC                 |             | 392             |     | 5000             | 0           | 5000               |         | 0            |
|                  | Refurbishment                                      |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                    |         |              |
| 723505           | No. 1 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | No. 6 - Blade Root Copper Nickel Indium Coating -  |               | ENC                 |             | 392             |     | 5000             | 0           | 5000               |         | 0            |
|                  | Refurbishment                                      |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                    |         |              |
| 723505           | No. 2 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | No. 6 - Blade Root Copper Nickel Indium Coating -  |               | ENC                 |             | 392             |     | 5000             | 0           | 5000               |         | 0            |
|                  | Refurbishment                                      |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                    |         |              |
| 723506           | No. 1 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | No. 7 - Blade Root Copper Nickel Indium Coating -  |               | ENC                 |             | 392             |     | 5000             | 0           | 5000               |         | 0            |
|                  | Refurbishment                                      |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                        |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                        | Serial Number |                     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                 | SW            |                     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                             |               |                     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                      |               |                     |             |                 |     |                  |             |                    |         |              |
| 723506           | No. 2 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | No. 7 - Blade Root Copper Nickel Indium Coating -  |               | ENC                 |             | 392             |     | 5000             | 0           | 5000               |         | 0            |
|                  | Refurbishment                                      |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                    |         |              |
| 723507           | No. 1 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | No. 8 - Blade Root Copper Nickel Indium Coating -  |               | ENC                 |             | 392             |     | 5000             | 0           | 5000               |         | 0            |
|                  | Refurbishment                                      |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                    |         |              |
| 723507           | No. 2 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | No. 8 - Blade Root Copper Nickel Indium Coating -  |               | ENC                 |             | 392             |     | 5000             | 0           | 5000               |         | 0            |
|                  | Refurbishment                                      |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                    |         |              |
| 723508           | No. 1 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | No. 9 - Blade Root Copper Nickel Indium Coating -  |               | ENC                 |             | 392             |     | 5000             | 0           | 5000               |         | 0            |
|                  | Refurbishment                                      |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                    |         |              |
| 723508           | No. 2 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | No. 9 - Blade Root Copper Nickel Indium Coating -  |               | ENC                 |             | 392             |     | 5000             | 0           | 5000               |         | 0            |
|                  | Refurbishment                                      |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                    |         |              |
| 723509           | No. 1 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | No. 10 - Blade Root Copper Nickel Indium Coating - |               | ENC                 |             | 392             |     | 5000             | 0           | 5000               |         | 0            |
|                  | Refurbishment                                      |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                    |         |              |



| ATA<br>U=Custom  | Description                                        |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                        | Serial Number |                     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                 | SW            |                     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                             |               |                     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                      |               |                     |             |                 |     |                  |             |                    |         |              |
| 723509           | No. 2 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | No. 10 - Blade Root Copper Nickel Indium Coating - |               | ENC                 |             | 392             |     | 5000             | 0           | 5000               |         | 0            |
|                  | Refurbishment                                      |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                    |         |              |
| 723510           | No. 1 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | No. 11- Blade Root Copper Nickel Indium Coating -  |               | ENC                 |             | 392             |     | 5000             | 0           | 5000               |         | 0            |
|                  | Refurbishment                                      |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                    |         |              |
| 723510           | No. 2 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | No. 11- Blade Root Copper Nickel Indium Coating -  |               | ENC                 |             | 392             |     | 5000             | 0           | 5000               |         | 0            |
|                  | Refurbishment                                      |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                    |         |              |
| 723511           | No. 1 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | No. 12 - Blade Root Copper Nickel Indium Coating - |               | ENC                 |             | 392             |     | 5000             | 0           | 5000               |         | 0            |
|                  | Refurbishment                                      |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                    |         |              |
| 723511           | No. 2 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | No. 12 - Blade Root Copper Nickel Indium Coating - |               | ENC                 |             | 392             |     | 5000             | 0           | 5000               |         | 0            |
|                  | Refurbishment                                      |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                    |         |              |
| 723512           | No. 1 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | No. 13 - Blade Root Copper Nickel Indium Coating - |               | ENC                 |             | 392             |     | 5000             | 0           | 5000               |         | 0            |
|                  | Refurbishment                                      |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                        |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                        | Serial Number |                     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                 | SW            |                     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                             |               |                     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                      |               |                     |             |                 |     |                  |             |                     |         |              |
| 723512           | No. 2 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | No. 13 - Blade Root Copper Nickel Indium Coating - |               | ENC                 |             | 392             |     | 5000             | 0           | 5000                |         | 0            |
|                  | Refurbishment                                      |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                     |         |              |
| 723513           | No. 1 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | No. 14 - Blade Root Copper Nickel Indium Coating - |               | ENC                 |             | 392             |     | 5000             | 0           | 5000                |         | 0            |
|                  | Refurbishment                                      |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                     |         |              |
| 723513           | No. 2 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | No. 14 - Blade Root Copper Nickel Indium Coating - |               | ENC                 |             | 392             |     | 5000             | 0           | 5000                |         | 0            |
|                  | Refurbishment                                      |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                     |         |              |
| 723514           | No. 1 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | No. 15 - Blade Root Copper Nickel Indium Coating - |               | ENC                 |             | 392             |     | 5000             | 0           | 5000                |         | 0            |
|                  | Refurbishment                                      |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                     |         |              |
| 723514           | No. 2 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | No. 15 - Blade Root Copper Nickel Indium Coating - |               | ENC                 |             | 392             |     | 5000             | 0           | 5000                |         | 0            |
|                  | Refurbishment                                      |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                     |         |              |
| 723515           | No. 1 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | No. 16 - Blade Root Copper Nickel Indium Coating - |               | ENC                 |             | 392             |     | 5000             | 0           | 5000                |         | 0            |
|                  | Refurbishment                                      |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom  | Description                                        |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                        | Serial Number |                     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                 | SW            |                     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                             |               |                     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                      |               |                     |             |                 |     |                  |             |                    |         |              |
| 723515           | No. 2 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | No. 16 - Blade Root Copper Nickel Indium Coating - |               | ENC                 |             | 392             |     | 5000             | 0           | 5000               |         | 0            |
|                  | Refurbishment                                      |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                    |         |              |
| 723516           | No. 1 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | No. 17 - Blade Root Copper Nickel Indium Coating - |               | ENC                 |             | 392             |     | 5000             | 0           | 5000               |         | 0            |
|                  | Refurbishment                                      |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                    |         |              |
| 723516           | No. 2 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | No. 17 - Blade Root Copper Nickel Indium Coating - |               | ENC                 |             | 392             |     | 5000             | 0           | 5000               |         | 0            |
|                  | Refurbishment                                      |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                    |         |              |
| 723517           | No. 1 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | No. 18 - Blade Root Copper Nickel Indium Coating - |               | ENC                 |             | 392             |     | 5000             | 0           | 5000               |         | 0            |
|                  | Refurbishment                                      |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                    |         |              |
| 723517           | No. 2 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | No. 18 - Blade Root Copper Nickel Indium Coating - |               | ENC                 |             | 392             |     | 5000             | 0           | 5000               |         | 0            |
|                  | Refurbishment                                      |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                    |         |              |
| 723518           | No. 1 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | No. 19 - Blade Root Copper Nickel Indium Coating - |               | ENC                 |             | 392             |     | 5000             | 0           | 5000               |         | 0            |
|                  | Refurbishment                                      |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                        |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                        | Serial Number |                     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                 | SW            |                     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                             |               |                     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                      |               |                     |             |                 |     |                  |             |                    |         |              |
| 723518           | No. 2 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | No. 19 - Blade Root Copper Nickel Indium Coating - |               | ENC                 |             | 392             |     | 5000             | 0           | 5000               |         | 0            |
|                  | Refurbishment                                      |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                    |         |              |
| 723519           | No. 1 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | No. 20 - Blade Root Copper Indium Coating -        |               | ENC                 |             | 392             |     | 5000             | 0           | 5000               |         | 0            |
|                  | Refurbishment                                      |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                    |         |              |
| 723519           | No. 2 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | No. 20 - Blade Root Copper Indium Coating -        |               | ENC                 |             | 392             |     | 5000             | 0           | 5000               |         | 0            |
|                  | Refurbishment                                      |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                    |         |              |
| 723520           | No. 1 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | No. 21- Blade Root Copper Nickel Indium Coating -  |               | ENC                 |             | 392             |     | 5000             | 0           | 5000               |         | 0            |
|                  | Refurbishment                                      |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                    |         |              |
| 723520           | No. 2 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | No. 21- Blade Root Copper Nickel Indium Coating -  |               | ENC                 |             | 392             |     | 5000             | 0           | 5000               |         | 0            |
|                  | Refurbishment                                      |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                    |         |              |
| 723521           | No. 1 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | No. 22 - Blade Root Copper Nickel Indium Coating - |               | ENC                 |             | 392             |     | 5000             | 0           | 5000               |         | 0            |
|                  | Refurbishment                                      |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                        |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                        | Serial Number |                     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                 | SW            |                     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                             |               |                     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                      |               |                     |             |                 |     |                  |             |                    |         |              |
| 723521           | No. 2 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | No. 22 - Blade Root Copper Nickel Indium Coating - |               | ENC                 |             | 392             |     | 5000             | 0           | 5000               |         | 0            |
|                  | Refurbishment                                      |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                    |         |              |
| 723522           | No. 1 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | No. 23 - Blade Root Copper Nickel Indium Coating - |               | ENC                 |             | 392             |     | 5000             | 0           | 5000               |         | 0            |
|                  | Refurbishment                                      |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                    |         |              |
| 723522           | No. 2 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | No. 23 - Blade Root Copper Nickel Indium Coating - |               | ENC                 |             | 392             |     | 5000             | 0           | 5000               |         | 0            |
|                  | Refurbishment                                      |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                    |         |              |
| 723523           | No. 1 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | No. 24 - Blade Root Copper Nickel Indium Coating - |               | ENC                 |             | 392             |     | 5000             | 0           | 5000               |         | 0            |
|                  | Refurbishment                                      |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                    |         |              |
| 723523           | No. 2 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | No. 24 - Blade Root Copper Nickel Indium Coating - |               | ENC                 |             | 392             |     | 5000             | 0           | 5000               |         | 0            |
|                  | Refurbishment                                      |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                    |         |              |
| 723524           | No. 1 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | No. 1- Dry Film Coating - Refurbishment            |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                    |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                    |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  |                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                    |               |                     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                        |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                        | Serial Number |                     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                 | SW            |                     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                             |               |                     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                      |               |                     |             |                 |     |                  |             |                     |         |              |
| 723524           | No. 2 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | No. 1- Dry Film Coating - Refurbishment            |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                                    |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                    |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                             |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 723525           | No. 1 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | No. 2 - Dry Film Coating - Refurbishment           |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                                    |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                    |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                             |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 723525           | No. 2 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | No. 2 - Dry Film Coating - Refurbishment           |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                                    |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                    |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                             |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 723526           | No. 1 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | No. 3 - Dry Film Coating - Refurbishment           |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                                    |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                    |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                             |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 723526           | No. 2 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | No. 3 - Dry Film Coating - Refurbishment           |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                                    |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                    |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                             |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 723527           | No. 1 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | No. 4 - Dry Film Coating - Refurbishment           |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                                    |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                    |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                             |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 723527           | No. 2 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | No. 4 - Dry Film Coating - Refurbishment           |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                                    |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                    |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                             |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom  | Description                                        |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                        | Serial Number |                     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                 | SW            |                     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                             |               |                     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                      |               |                     |             |                 |     |                  |             |                     |         |              |
| 723528           | No. 1 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | No. 5 - Dry Film Coating - Refurbishment           |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                                    |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                    |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                             |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 723528           | No. 2 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | No. 5 - Dry Film Coating - Refurbishment           |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                                    |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                    |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                             |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 723529           | No. 1 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | No. 6 - Dry Film Coating - Refurbishment           |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                                    |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                    |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                             |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 723529           | No. 2 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | No. 6 - Dry Film Coating - Refurbishment           |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                                    |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                    |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                             |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 723530           | No. 1 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | No. 7 - Dry Film Coating - Refurbishment           |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                                    |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                    |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                             |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 723530           | No. 2 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | No. 7 - Dry Film Coating - Refurbishment           |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                                    |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                    |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                             |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 723531           | No. 1 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | No. 8 - Dry Film Coating - Refurbishment           |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                                    |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                    |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                             |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom  | Description                                        |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                        | Serial Number |                     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                 | SW            |                     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                             |               |                     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                      |               |                     |             |                 |     |                  |             |                     |         |              |
| 723531           | No. 2 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | No. 8 - Dry Film Coating - Refurbishment           |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                                    |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                    |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                             |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 723532           | No. 1 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | No. 9 - Dry Film Coating - Refurbishment           |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                                    |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                    |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                             |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 723532           | No. 2 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | No. 9 - Dry Film Coating - Refurbishment           |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                                    |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                    |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                             |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 723533           | No. 1 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | No. 10 - Dry Film Coating - Refurbishment          |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                                    |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                    |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                             |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 723533           | No. 2 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | No. 10 - Dry Film Coating - Refurbishment          |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                                    |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                    |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                             |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 723534           | No. 1 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | No. 11 - Dry Film Coating - Refurbishment          |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                                    |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                    |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                             |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 723534           | No. 2 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | No. 11 - Dry Film Coating - Refurbishment          |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                                    |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                    |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                             |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |



| ATA<br>U=Custom  | Description                                        |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(* =Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|----------------------|---------|--------------|
|                  | Part Number                                        | Serial Number |                     |             |                 |     |                  |             |                      |         | Approx Price |
| Logbook Position | HW                                                 | SW            |                     |             |                 |     |                  |             |                      |         | Manufacturer |
|                  | MM Ref                                             |               |                     |             |                 |     |                  |             |                      |         | Date Type    |
|                  | Ops Number(s)                                      |               |                     |             |                 |     |                  |             |                      |         |              |
| 723535           | No. 1 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                  | No. 12 - Dry Film Coating - Refurbishment          |               | ENC                 |             | 392             |     |                  | 0           |                      |         | 0            |
|                  |                                                    |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                      |         |              |
|                  |                                                    |               | MSC                 |             |                 |     | O/C              |             |                      |         |              |
|                  | Engine                                             |               | [End Of Month Item] |             |                 |     |                  |             |                      |         |              |
| 723535           | No. 2 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                  | No. 12 - Dry Film Coating - Refurbishment          |               | ENC                 |             | 392             |     |                  | 0           |                      |         | 0            |
|                  |                                                    |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                      |         |              |
|                  |                                                    |               | MSC                 |             |                 |     | O/C              |             |                      |         |              |
|                  | Engine                                             |               | [End Of Month Item] |             |                 |     |                  |             |                      |         |              |
| 723536           | No. 1 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                  | No. 13 - Dry Film Coating - Refurbishment          |               | ENC                 |             | 392             |     |                  | 0           |                      |         | 0            |
|                  |                                                    |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                      |         |              |
|                  |                                                    |               | MSC                 |             |                 |     | O/C              |             |                      |         |              |
|                  | Engine                                             |               | [End Of Month Item] |             |                 |     |                  |             |                      |         |              |
| 723536           | No. 2 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                  | No. 13 - Dry Film Coating - Refurbishment          |               | ENC                 |             | 392             |     |                  | 0           |                      |         | 0            |
|                  |                                                    |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                      |         |              |
|                  |                                                    |               | MSC                 |             |                 |     | O/C              |             |                      |         |              |
|                  | Engine                                             |               | [End Of Month Item] |             |                 |     |                  |             |                      |         |              |
| 723537           | No. 1 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                  | No. 14 - Dry Film Coating - Refurbishment          |               | ENC                 |             | 392             |     |                  | 0           |                      |         | 0            |
|                  |                                                    |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                      |         |              |
|                  |                                                    |               | MSC                 |             |                 |     | O/C              |             |                      |         |              |
|                  | Engine                                             |               | [End Of Month Item] |             |                 |     |                  |             |                      |         |              |
| 723537           | No. 2 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                  | No. 14 - Dry Film Coating - Refurbishment          |               | ENC                 |             | 392             |     |                  | 0           |                      |         | 0            |
|                  |                                                    |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                      |         |              |
|                  |                                                    |               | MSC                 |             |                 |     | O/C              |             |                      |         |              |
|                  | Engine                                             |               | [End Of Month Item] |             |                 |     |                  |             |                      |         |              |
| 723538           | No. 1 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                  | No. 15 - Dry Film Coating - Refurbishment          |               | ENC                 |             | 392             |     |                  | 0           |                      |         | 0            |
|                  |                                                    |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                      |         |              |
|                  |                                                    |               | MSC                 |             |                 |     | O/C              |             |                      |         |              |
|                  | Engine                                             |               | [End Of Month Item] |             |                 |     |                  |             |                      |         |              |

| ATA<br>U=Custom  | Description                                        |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(* =Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|----------------------|---------|--------------|
|                  | Part Number                                        | Serial Number |                     |             |                 |     |                  |             |                      |         | Approx Price |
| Logbook Position | HW                                                 | SW            |                     |             |                 |     |                  |             |                      |         | Manufacturer |
|                  | MM Ref                                             |               |                     |             |                 |     |                  |             |                      |         | Date Type    |
|                  | Ops Number(s)                                      |               |                     |             |                 |     |                  |             |                      |         |              |
| 723538           | No. 2 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                  | No. 15 - Dry Film Coating - Refurbishment          |               | ENC                 |             | 392             |     |                  | 0           |                      |         | 0            |
|                  |                                                    |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                      |         |              |
|                  |                                                    |               | MSC                 |             |                 |     | O/C              |             |                      |         |              |
|                  | Engine                                             |               | [End Of Month Item] |             |                 |     |                  |             |                      |         |              |
| 723539           | No. 1 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                  | No. 16 - Dry Film Coating - Refurbishment          |               | ENC                 |             | 392             |     |                  | 0           |                      |         | 0            |
|                  |                                                    |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                      |         |              |
|                  |                                                    |               | MSC                 |             |                 |     | O/C              |             |                      |         |              |
|                  | Engine                                             |               | [End Of Month Item] |             |                 |     |                  |             |                      |         |              |
| 723539           | No. 2 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                  | No. 16 - Dry Film Coating - Refurbishment          |               | ENC                 |             | 392             |     |                  | 0           |                      |         | 0            |
|                  |                                                    |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                      |         |              |
|                  |                                                    |               | MSC                 |             |                 |     | O/C              |             |                      |         |              |
|                  | Engine                                             |               | [End Of Month Item] |             |                 |     |                  |             |                      |         |              |
| 723540           | No. 1 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                  | No. 17 - Dry Film Coating - Refurbishment          |               | ENC                 |             | 392             |     |                  | 0           |                      |         | 0            |
|                  |                                                    |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                      |         |              |
|                  |                                                    |               | MSC                 |             |                 |     | O/C              |             |                      |         |              |
|                  | Engine                                             |               | [End Of Month Item] |             |                 |     |                  |             |                      |         |              |
| 723540           | No. 2 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                  | No. 17 - Dry Film Coating - Refurbishment          |               | ENC                 |             | 392             |     |                  | 0           |                      |         | 0            |
|                  |                                                    |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                      |         |              |
|                  |                                                    |               | MSC                 |             |                 |     | O/C              |             |                      |         |              |
|                  | Engine                                             |               | [End Of Month Item] |             |                 |     |                  |             |                      |         |              |
| 723541           | No. 1 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                  | No. 18 - Dry Film Coating - Refurbishment          |               | ENC                 |             | 392             |     |                  | 0           |                      |         | 0            |
|                  |                                                    |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                      |         |              |
|                  |                                                    |               | MSC                 |             |                 |     | O/C              |             |                      |         |              |
|                  | Engine                                             |               | [End Of Month Item] |             |                 |     |                  |             |                      |         |              |
| 723541           | No. 2 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                  | No. 18 - Dry Film Coating - Refurbishment          |               | ENC                 |             | 392             |     |                  | 0           |                      |         | 0            |
|                  |                                                    |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                      |         |              |
|                  |                                                    |               | MSC                 |             |                 |     | O/C              |             |                      |         |              |
|                  | Engine                                             |               | [End Of Month Item] |             |                 |     |                  |             |                      |         |              |

| ATA<br>U=Custom  | Description                                        |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(* =Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|----------------------|---------|--------------|
|                  | Part Number                                        | Serial Number |                     |             |                 |     |                  |             |                      |         | Approx Price |
| Logbook Position | HW                                                 | SW            |                     |             |                 |     |                  |             |                      |         | Manufacturer |
|                  | MM Ref                                             |               |                     |             |                 |     |                  |             |                      |         | Date Type    |
|                  | Ops Number(s)                                      |               |                     |             |                 |     |                  |             |                      |         |              |
| 723542           | No. 1 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                  | No. 19 - Dry Film Coating - Refurbishment          |               | ENC                 |             | 392             |     |                  | 0           |                      |         | 0            |
|                  |                                                    |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                      |         |              |
|                  |                                                    |               | MSC                 |             |                 |     | O/C              |             |                      |         |              |
|                  | Engine                                             |               | [End Of Month Item] |             |                 |     |                  |             |                      |         |              |
| 723542           | No. 2 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                  | No. 19 - Dry Film Coating - Refurbishment          |               | ENC                 |             | 392             |     |                  | 0           |                      |         | 0            |
|                  |                                                    |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                      |         |              |
|                  |                                                    |               | MSC                 |             |                 |     | O/C              |             |                      |         |              |
|                  | Engine                                             |               | [End Of Month Item] |             |                 |     |                  |             |                      |         |              |
| 723543           | No. 1 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                  | No. 20 - Dry Film Coating - Refurbishment          |               | ENC                 |             | 392             |     |                  | 0           |                      |         | 0            |
|                  |                                                    |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                      |         |              |
|                  |                                                    |               | MSC                 |             |                 |     | O/C              |             |                      |         |              |
|                  | Engine                                             |               | [End Of Month Item] |             |                 |     |                  |             |                      |         |              |
| 723543           | No. 2 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                  | No. 20 - Dry Film Coating - Refurbishment          |               | ENC                 |             | 392             |     |                  | 0           |                      |         | 0            |
|                  |                                                    |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                      |         |              |
|                  |                                                    |               | MSC                 |             |                 |     | O/C              |             |                      |         |              |
|                  | Engine                                             |               | [End Of Month Item] |             |                 |     |                  |             |                      |         |              |
| 723544           | No. 1 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                  | No. 21- Dry Film Coating - Refurbishment           |               | ENC                 |             | 392             |     |                  | 0           |                      |         | 0            |
|                  |                                                    |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                      |         |              |
|                  |                                                    |               | MSC                 |             |                 |     | O/C              |             |                      |         |              |
|                  | Engine                                             |               | [End Of Month Item] |             |                 |     |                  |             |                      |         |              |
| 723544           | No. 2 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                  | No. 21- Dry Film Coating - Refurbishment           |               | ENC                 |             | 392             |     |                  | 0           |                      |         | 0            |
|                  |                                                    |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                      |         |              |
|                  |                                                    |               | MSC                 |             |                 |     | O/C              |             |                      |         |              |
|                  | Engine                                             |               | [End Of Month Item] |             |                 |     |                  |             |                      |         |              |
| 723545           | No. 1 Engine - Low-Pressure Compressor (Fan) Blade |               | HRS                 |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                  | No. 22 - Dry Film Coating - Refurbishment          |               | ENC                 |             | 392             |     |                  | 0           |                      |         | 0            |
|                  |                                                    |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                      |         |              |
|                  |                                                    |               | MSC                 |             |                 |     | O/C              |             |                      |         |              |
|                  | Engine                                             |               | [End Of Month Item] |             |                 |     |                  |             |                      |         |              |

| ATA<br>U=Custom  | Description                                            |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|--------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                            | Serial Number |                     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                     | SW            |                     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                 |               |                     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                          |               |                     |             |                 |     |                  |             |                     |         |              |
| 723545           | No. 2 Engine - Low-Pressure Compressor (Fan) Blade     |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | No. 22 - Dry Film Coating - Refurbishment              |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                                        |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                        |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                 |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 723546           | No. 1 Engine - Low-Pressure Compressor (Fan) Blade     |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | No. 23 - Dry Film Coating - Refurbishment              |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                                        |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                        |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                 |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 723546           | No. 2 Engine - Low-Pressure Compressor (Fan) Blade     |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | No. 23 - Dry Film Coating - Refurbishment              |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                                        |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                        |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                 |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 723547           | No. 1 Engine - Low-Pressure Compressor (Fan) Blade     |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | No. 24 - Dry Film Coating - Refurbishment              |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                                        |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                        |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                 |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 723547           | No. 2 Engine - Low-Pressure Compressor (Fan) Blade     |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | No. 24 - Dry Film Coating - Refurbishment              |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                                        |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                        |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                 |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 723800           | No. 1 Engine - Lp Compressor Intake Rotating Fairing - |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | Replace Nose Cone CAP (BRG3135)                        |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | PN                                                     | SN-UNKNOWN    | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                        |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                 |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 723800           | No. 2 Engine - Lp Compressor Intake Rotating Fairing - |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | Replace Nose Cone CAP (BRG3135)                        |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | PN                                                     | SN-UNKNOWN    | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                        |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                 |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom  | Description                                                                                                                                |                     | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|--------------------------------------------------------------------------------------------------------------------------------------------|---------------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                                                                                | Serial Number       |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                                                                                         | SW                  |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                                                                                     |                     |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                                                                                              |                     |     |             |                 |     |                  |             |                    |         |              |
| 723801           | No. 1 Engine - Lp Compressor Intake Rotating Fairing -<br>Touch-Up Surface Protection (BRG3136)                                            |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                                                            |                     | ENC |             | 392             |     |                  | 0           |                    | 0       |              |
|                  |                                                                                                                                            |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                                                                                            |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                                                                                     | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 723801           | No. 2 Engine - Lp Compressor Intake Rotating Fairing -<br>Touch-Up Surface Protection (BRG3136)                                            |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                                                            |                     | ENC |             | 392             |     |                  | 0           |                    | 0       |              |
|                  |                                                                                                                                            |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                                                                                            |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                                                                                     | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 723802           | No. 1 Engine - Lp Compressor Intake Rotating Fairing -<br>Apply Filler Compound to Eroded Seal Between Nose<br>Cone and Cone CAP (BRG3169) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                                                            |                     | ENC |             | 392             |     |                  | 0           |                    | 0       |              |
|                  |                                                                                                                                            |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                                                                                            |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                                                                                     | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 723802           | No. 2 Engine - Lp Compressor Intake Rotating Fairing -<br>Apply Filler Compound to Eroded Seal Between Nose<br>Cone and Cone CAP (BRG3169) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                                                            |                     | ENC |             | 392             |     |                  | 0           |                    | 0       |              |
|                  |                                                                                                                                            |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                                                                                            |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                                                                                     | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 723803           | No. 1 Engine - Lp Compressor Intake Rotating Fairing -<br>Replace Location Pins (BRG3185)<br>PN SN-UNKNOWN                                 |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                                                            |                     | ENC |             | 392             |     |                  | 0           |                    | 0       |              |
|                  |                                                                                                                                            |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                                                                                            |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                                                                                     | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 723803           | No. 2 Engine - Lp Compressor Intake Rotating Fairing -<br>Replace Location Pins (BRG3185)<br>PN SN-UNKNOWN                                 |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                                                            |                     | ENC |             | 392             |     |                  | 0           |                    | 0       |              |
|                  |                                                                                                                                            |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                                                                                            |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                                                                                     | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 723804           | No. 1 Engine - Lp Compressor Intake Rotating Fairing -<br>Touch-Up Timing Mark (BRG3187)                                                   |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                                                            |                     | ENC |             | 392             |     |                  | 0           |                    | 0       |              |
|                  |                                                                                                                                            |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                                                                                            |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                                                                                     | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                                       |                     | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|---------------------------------------------------------------------------------------------------|---------------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                                       | Serial Number       |                                    |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                                                | SW                  |                                    |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                                            |                     |                                    |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                                                     |                     |                                    |             |                 |     |                  |             |                    |         |              |
| 723804           | No. 2 Engine - Lp Compressor Intake Rotating Fairing -<br>Touch-Up Timing Mark (BRG3187)          |                     | HRS                                |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                   |                     | ENC                                |             | 392             |     |                  | 0           |                    | 0       |              |
|                  |                                                                                                   |                     | MOS                                |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                                                   |                     | MSC                                |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                                            | [End Of Month Item] |                                    |             |                 |     |                  |             |                    |         |              |
| 723805           | No. 1 Engine - Lp Compressor Fan Retention Shaft and<br>Locking Ring Nut - Inspection             |                     | HRS                                |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                   |                     | ENC                                |             | 392             |     |                  | 0           |                    | 0       |              |
|                  |                                                                                                   |                     | MOS                                |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                                                   |                     | MSC                                |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                                            | [End Of Month Item] |                                    |             |                 |     |                  |             |                    |         |              |
| 723805           | No. 2 Engine - Lp Compressor Fan Retention Shaft and<br>Locking Ring Nut - Inspection             |                     | HRS                                |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                   |                     | ENC                                |             | 392             |     |                  | 0           |                    | 0       |              |
|                  |                                                                                                   |                     | MOS                                |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                                                   |                     | MSC                                |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                                            | [End Of Month Item] |                                    |             |                 |     |                  |             |                    |         |              |
| 723806           | No. 1 Engine - Lp Compressor Intake Rotating Fairing -<br>General Visual Inspection               |                     | HRS                                |             | 137             | 6.5 | 600              | 857.4       | 1463.9*            | 1513.9  | 0            |
|                  |                                                                                                   |                     | ENC                                |             | 52              |     |                  | 340         |                    | 0       |              |
|                  |                                                                                                   |                     | MOS                                |             | 5.3             |     |                  | 02 Dec 2025 |                    |         |              |
|                  |                                                                                                   |                     | [End Of Month Item] [HRS: +50/-50] |             |                 |     |                  |             |                    |         |              |
|                  | Engine                                                                                            | 052001              |                                    |             |                 |     |                  |             |                    |         |              |
| 723806           | No. 2 Engine - Lp Compressor Intake Rotating Fairing -<br>General Visual Inspection               |                     | HRS                                |             | 137             | 6.5 | 600              | 857.4       | 1463.9*            | 1513.9  | 0            |
|                  |                                                                                                   |                     | ENC                                |             | 52              |     |                  | 340         |                    | 0       |              |
|                  |                                                                                                   |                     | MOS                                |             | 5.3             |     |                  | 02 Dec 2025 |                    |         |              |
|                  |                                                                                                   |                     | [End Of Month Item] [HRS: +50/-50] |             |                 |     |                  |             |                    |         |              |
|                  | Engine                                                                                            | 052001              |                                    |             |                 |     |                  |             |                    |         |              |
| 723807           | No. 1 Engine - Lp Compressor Intake Rotating Fairing -<br>Removal / Installation<br>PN SN-UNKNOWN |                     | HRS                                |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                   |                     | ENC                                |             | 392             |     |                  | 0           |                    | 0       |              |
|                  |                                                                                                   |                     | MOS                                |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                                                   |                     | MSC                                |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                                            | [End Of Month Item] |                                    |             |                 |     |                  |             |                    |         |              |
| 723807           | No. 2 Engine - Lp Compressor Intake Rotating Fairing -<br>Removal / Installation<br>PN SN-UNKNOWN |                     | HRS                                |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                   |                     | ENC                                |             | 392             |     |                  | 0           |                    | 0       |              |
|                  |                                                                                                   |                     | MOS                                |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                                                   |                     | MSC                                |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                                            | [End Of Month Item] |                                    |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                              |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|--------------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                              | Serial Number |                     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                       | SW            |                     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                   |               |                     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                            |               |                     |             |                 |     |                  |             |                    |         |              |
| 723809           | No. 1 Engine - Lp Compressor Nose Cone Assembly - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                          |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | PN                                                                       | SN-UNKNOWN    | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                          |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                   |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 723809           | No. 2 Engine - Lp Compressor Nose Cone Assembly - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                          |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | PN                                                                       | SN-UNKNOWN    | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                          |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                   |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 724100           | No. 1 Engine - Curvic Ring - Removal / Installation                      |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                          |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | PN                                                                       | SN-UNKNOWN    | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                          |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                   |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 724100           | No. 2 Engine - Curvic Ring - Removal / Installation                      |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                          |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | PN                                                                       | SN-UNKNOWN    | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                          |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                   |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 724101           | No. 1 Engine - Curvic Ring - Discard                                     |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                          |               | ENC                 |             | 392             |     | 10000            | 0           | 10000              |         | 0            |
|                  | PN                                                                       | SN-UNKNOWN    | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                          |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
|                  | Engine                                                                   |               |                     |             |                 |     |                  |             |                    |         |              |
| 724101           | No. 2 Engine - Curvic Ring - Discard                                     |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                          |               | ENC                 |             | 392             |     | 10000            | 0           | 10000              |         | 0            |
|                  | PN                                                                       | SN-UNKNOWN    | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                          |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
|                  | Engine                                                                   |               |                     |             |                 |     |                  |             |                    |         |              |
| 724102           | No. 1 Engine - Hp Turbine Stage 1 Disc - Removal / Installation          |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                          |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | PN                                                                       | SN-UNKNOWN    | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                          |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                   |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                     |                 | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-----------------------------------------------------------------|-----------------|---------------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                     | Serial Number   |                     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                              | SW              |                     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                          |                 |                     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                   |                 |                     |             |                 |     |                  |             |                    |         |              |
| 724102           | No. 2 Engine - Hp Turbine Stage 1 Disc - Removal / Installation |                 | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                 |                 | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | PN                                                              | SN-UNKNOWN      | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                 |                 | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                          |                 | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 724103           | No. 1 Engine - Hp Turbine Stage 1 Disc - Discard                |                 | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | PN                                                              |                 | ENC                 |             | 392             |     | 5000             | 0           | 5000               |         | 0            |
|                  |                                                                 |                 | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                 |                 | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
|                  | Engine                                                          |                 |                     |             |                 |     |                  |             |                    |         |              |
| 724103           | No. 2 Engine - Hp Turbine Stage 1 Disc - Discard                |                 | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | PN                                                              |                 | ENC                 |             | 392             |     | 5000             | 0           | 5000               |         | 0            |
|                  |                                                                 |                 | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                 |                 | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
|                  | Engine                                                          |                 |                     |             |                 |     |                  |             |                    |         |              |
| 724104           | No. 1 Engine - Hp Turbine Stage 2 Disc - Removal / Installation |                 | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | PN                                                              |                 | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                                 |                 | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                 |                 | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                          |                 | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 724104           | No. 2 Engine - Hp Turbine Stage 2 Disc - Removal / Installation |                 | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | PN                                                              |                 | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                                 |                 | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                 |                 | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                          |                 | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 724105           | No. 1 Engine - Hp Turbine Stage 2 Disc - Discard                |                 | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | PN                                                              |                 | ENC                 |             | 392             |     | 5000             | 0           | 5000               |         | 0            |
|                  |                                                                 |                 | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                 |                 | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
|                  | Engine                                                          |                 |                     |             |                 |     |                  |             |                    |         |              |
| 724105           | No. 2 Engine - Hp Turbine Stage 2 Disc - Discard                |                 | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | PN                                                              |                 | ENC                 |             | 392             |     | 5000             | 0           | 5000               |         | 0            |
|                  |                                                                 |                 | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                 |                 | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
|                  | Engine                                                          |                 |                     |             |                 |     |                  |             |                    |         |              |
| 724125           | No. 1 Engine - Hpt Stage 1 Blade (No.1)                         |                 | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                                         | RRHPMC600055007 | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                                 |                 | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                 |                 | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                          |                 | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |



| ATA<br>U=Custom  | Description                             |                     | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-----------------------------------------|---------------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                             | Serial Number       |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                      | SW                  |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                  |                     |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                           |                     |     |             |                 |     |                  |             |                    |         |              |
| 724125           | No. 2 Engine - Hpt Stage 1 Blade (No.1) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                 | RRHPMCAB028960      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                         |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                  |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                         | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724126           | No. 1 Engine - Hpt Stage 1 Blade (No.2) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                 | RRHPMC600053721     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                         |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                  |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                         | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724126           | No. 2 Engine - Hpt Stage 1 Blade (No.2) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                 | RRHPMCAB030009      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                         |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                  |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                         | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724127           | No. 1 Engine - Hpt Stage 1 Blade (No.3) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                 | RRHPMCAB030002      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                         |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                  |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                         | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724127           | No. 2 Engine - Hpt Stage 1 Blade (No.3) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                 | RRHPC600054321      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                         |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                  |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                         | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724128           | No. 1 Engine - Hpt Stage 1 Blade (No.4) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                 | RRHPMCAB030017      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                         |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                  |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                         | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724128           | No. 2 Engine - Hpt Stage 1 Blade (No.4) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                 | RRHPMCAB030126      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                         |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                  |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                         | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724129           | No. 1 Engine - Hpt Stage 1 Blade (No.5) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                 | RRHPMCAB028997      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                         |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                  |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                         | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                             |                     | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-----------------------------------------|---------------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                             | Serial Number       |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                      | SW                  |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                  |                     |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                           |                     |     |             |                 |     |                  |             |                    |         |              |
| 724129           | No. 2 Engine - Hpt Stage 1 Blade (No.5) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                 | RRHPMC600054607     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                         |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                  |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                         | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724130           | No. 1 Engine - Hpt Stage 1 Blade (No.6) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                 | RRHPMC600055131     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                         |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                  |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                         | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724130           | No. 2 Engine - Hpt Stage 1 Blade (No.6) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                 | RRHPMC600053847     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                         |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                  |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                         | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724131           | No. 1 Engine - Hpt Stage 1 Blade (No.7) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                 | RRHPMCAB028962      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                         |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                  |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                         | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724131           | No. 2 Engine - Hpt Stage 1 Blade (No.7) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                 | RRHPMCAB028939      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                         |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                  |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                         | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724132           | No. 1 Engine - Hpt Stage 1 Blade (No.8) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                 | RRHPMCAB030146      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                         |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                  |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                         | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724132           | No. 2 Engine - Hpt Stage 1 Blade (No.8) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                 | RRHPMCAB028967      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                         |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                  |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                         | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724133           | No. 1 Engine - Hpt Stage 1 Blade (No.9) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                 | RRHPMCAB029026      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                         |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                  |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                         | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                              |                     | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------|---------------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                              | Serial Number       |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                       | SW                  |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                   |                     |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                            |                     |     |             |                 |     |                  |             |                    |         |              |
| 724133           | No. 2 Engine - Hpt Stage 1 Blade (No.9)  |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMCAB028258      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724134           | No. 1 Engine - Hpt Stage 1 Blade (No.10) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMCAB030072      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724134           | No. 2 Engine - Hpt Stage 1 Blade (No.10) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMC600054880     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724135           | No. 1 Engine - Hpt Stage 1 Blade (No.11) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMC600054292     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724135           | No. 2 Engine - Hpt Stage 1 Blade (No.11) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMCAB030153      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724136           | No. 1 Engine - Hpt Stage 1 Blade (No.12) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMC600054306     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724136           | No. 2 Engine - Hpt Stage 1 Blade (No.12) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMCAB028956      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724137           | No. 1 Engine - Hpt Stage 1 Blade (No.13) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMC600054839     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                              |                     | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------|---------------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                              | Serial Number       |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                       | SW                  |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                   |                     |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                            |                     |     |             |                 |     |                  |             |                    |         |              |
| 724137           | No. 2 Engine - Hpt Stage 1 Blade (No.13) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMCAB030051      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724138           | No. 1 Engine - Hpt Stage 1 Blade (No.14) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMCAB030135      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724138           | No. 2 Engine - Hpt Stage 1 Blade (No.14) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMCAB028980      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724139           | No. 1 Engine - Hpt Stage 1 Blade (No.15) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMC600054056     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724139           | No. 2 Engine - Hpt Stage 1 Blade (No.15) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMCAB029999      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724140           | No. 1 Engine - Hpt Stage 1 Blade (No.16) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMCAB030185      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724140           | No. 2 Engine - Hpt Stage 1 Blade (No.16) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMCAB030156      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724141           | No. 1 Engine - Hpt Stage 1 Blade (No.17) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMCAB030047      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                              |                     | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------|---------------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                              | Serial Number       |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                       | SW                  |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                   |                     |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                            |                     |     |             |                 |     |                  |             |                    |         |              |
| 724141           | No. 2 Engine - Hpt Stage 1 Blade (No.17) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMCAB029052      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724142           | No. 1 Engine - Hpt Stage 1 Blade (No.18) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMC600054047     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724142           | No. 2 Engine - Hpt Stage 1 Blade (No.18) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMC600055004     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724143           | No. 1 Engine - Hpt Stage 1 Blade (No.19) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMCAB029062      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724143           | No. 2 Engine - Hpt Stage 1 Blade (No.19) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMCAB026959      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724144           | No. 1 Engine - Hpt Stage 1 Blade (No.20) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMC600054884     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724144           | No. 2 Engine - Hpt Stage 1 Blade (No.20) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMC600054503     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724145           | No. 1 Engine - Hpt Stage 1 Blade (No.21) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMCAB029094      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                              |                     | UOM             | Times Since | Time<br>Accrued | Adj  | Required<br>Freq | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------|---------------------|-----------------|-------------|-----------------|------|------------------|----------|--------------------|---------|--------------|
|                  | Part Number                              | Serial Number       |                 |             |                 |      |                  |          |                    |         | Approx Price |
| Logbook Position | HW                                       | SW                  |                 |             |                 |      |                  |          |                    |         | Manufacturer |
|                  | MM Ref                                   |                     |                 |             |                 |      |                  |          |                    |         | Date Type    |
|                  | Ops Number(s)                            |                     |                 |             |                 |      |                  |          |                    |         |              |
| 724145           | No. 2 Engine - Hpt Stage 1 Blade (No.21) |                     | HRS             |             | 994.4           |      |                  | 0        |                    |         | 0            |
|                  | Engine                                   | FW85681             | RRHPMCAB028982  | ENC         |                 | 392  |                  |          | 0                  |         | 0            |
|                  |                                          |                     |                 | MOS         |                 | 41.9 |                  |          | 15 Nov 2022        |         |              |
|                  |                                          |                     |                 | MSC         |                 |      |                  | O/C      |                    |         |              |
|                  |                                          | [End Of Month Item] |                 |             |                 |      |                  |          |                    |         |              |
| 724146           | No. 1 Engine - Hpt Stage 1 Blade (No.22) |                     | HRS             |             | 994.4           |      |                  | 0        |                    |         | 0            |
|                  | Engine                                   | FW85681             | RRHPMC600054440 | ENC         |                 | 392  |                  |          | 0                  |         | 0            |
|                  |                                          |                     |                 | MOS         |                 | 41.8 |                  |          | 17 Nov 2022        |         |              |
|                  |                                          |                     |                 | MSC         |                 |      |                  | O/C      |                    |         |              |
|                  |                                          | [End Of Month Item] |                 |             |                 |      |                  |          |                    |         |              |
| 724146           | No. 2 Engine - Hpt Stage 1 Blade (No.22) |                     | HRS             |             | 994.4           |      |                  | 0        |                    |         | 0            |
|                  | Engine                                   | FW85681             | RRHPMCAB028235  | ENC         |                 | 392  |                  |          | 0                  |         | 0            |
|                  |                                          |                     |                 | MOS         |                 | 41.9 |                  |          | 15 Nov 2022        |         |              |
|                  |                                          |                     |                 | MSC         |                 |      |                  | O/C      |                    |         |              |
|                  |                                          | [End Of Month Item] |                 |             |                 |      |                  |          |                    |         |              |
| 724147           | No. 1 Engine - Hpt Stage 1 Blade (No.23) |                     | HRS             |             | 994.4           |      |                  | 0        |                    |         | 0            |
|                  | Engine                                   | FW85681             | RRHPMC600055195 | ENC         |                 | 392  |                  |          | 0                  |         | 0            |
|                  |                                          |                     |                 | MOS         |                 | 41.8 |                  |          | 17 Nov 2022        |         |              |
|                  |                                          |                     |                 | MSC         |                 |      |                  | O/C      |                    |         |              |
|                  |                                          | [End Of Month Item] |                 |             |                 |      |                  |          |                    |         |              |
| 724147           | No. 2 Engine - Hpt Stage 1 Blade (No.23) |                     | HRS             |             | 994.4           |      |                  | 0        |                    |         | 0            |
|                  | Engine                                   | FW85681             | RRHPCAB028986   | ENC         |                 | 392  |                  |          | 0                  |         | 0            |
|                  |                                          |                     |                 | MOS         |                 | 41.9 |                  |          | 15 Nov 2022        |         |              |
|                  |                                          |                     |                 | MSC         |                 |      |                  | O/C      |                    |         |              |
|                  |                                          | [End Of Month Item] |                 |             |                 |      |                  |          |                    |         |              |
| 724148           | No. 1 Engine - Hpt Stage 1 Blade (No.24) |                     | HRS             |             | 994.4           |      |                  | 0        |                    |         | 0            |
|                  | Engine                                   | FW85681             | RRHPMC600054110 | ENC         |                 | 392  |                  |          | 0                  |         | 0            |
|                  |                                          |                     |                 | MOS         |                 | 41.8 |                  |          | 17 Nov 2022        |         |              |
|                  |                                          |                     |                 | MSC         |                 |      |                  | O/C      |                    |         |              |
|                  |                                          | [End Of Month Item] |                 |             |                 |      |                  |          |                    |         |              |
| 724148           | No. 2 Engine - Hpt Stage 1 Blade (No.24) |                     | HRS             |             | 994.4           |      |                  | 0        |                    |         | 0            |
|                  | Engine                                   | FW85681             | RRHPMCAB030134  | ENC         |                 | 392  |                  |          | 0                  |         | 0            |
|                  |                                          |                     |                 | MOS         |                 | 41.9 |                  |          | 15 Nov 2022        |         |              |
|                  |                                          |                     |                 | MSC         |                 |      |                  | O/C      |                    |         |              |
|                  |                                          | [End Of Month Item] |                 |             |                 |      |                  |          |                    |         |              |
| 724149           | No. 1 Engine - Hpt Stage 1 Blade (No.25) |                     | HRS             |             | 994.4           |      |                  | 0        |                    |         | 0            |
|                  | Engine                                   | FW85681             | RRHPMCAB030086  | ENC         |                 | 392  |                  |          | 0                  |         | 0            |
|                  |                                          |                     |                 | MOS         |                 | 41.8 |                  |          | 17 Nov 2022        |         |              |
|                  |                                          |                     |                 | MSC         |                 |      |                  | O/C      |                    |         |              |
|                  |                                          | [End Of Month Item] |                 |             |                 |      |                  |          |                    |         |              |

| ATA<br>U=Custom  | Description                              |                     | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------|---------------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                              | Serial Number       |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                       | SW                  |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                   |                     |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                            |                     |     |             |                 |     |                  |             |                    |         |              |
| 724149           | No. 2 Engine - Hpt Stage 1 Blade (No.25) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMCAB028277      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724150           | No. 1 Engine - Hpt Stage 1 Blade (No.26) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMC600055018     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724150           | No. 2 Engine - Hpt Stage 1 Blade (No.26) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMC600054528     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724151           | No. 1 Engine - Hpt Stage 1 Blade (No.27) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMC600053872     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724151           | No. 2 Engine - Hpt Stage 1 Blade (No.27) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMCAB028203      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724152           | No. 1 Engine - Hpt Stage 1 Blade (No.28) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMCAB030053      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724152           | No. 2 Engine - Hpt Stage 1 Blade (No.28) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMCAB030045      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724153           | No. 1 Engine - Hpt Stage 1 Blade (No.29) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMCAB025921      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                              |                     | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------|---------------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                              | Serial Number       |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                       | SW                  |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                   |                     |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                            |                     |     |             |                 |     |                  |             |                    |         |              |
| 724153           | No. 2 Engine - Hpt Stage 1 Blade (No.29) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMCAB026956      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724154           | No. 1 Engine - Hpt Stage 1 Blade (No.30) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMCAB030093      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724154           | No. 2 Engine - Hpt Stage 1 Blade (No.30) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMCAB028943      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724155           | No. 1 Engine - Hpt Stage 1 Blade (No.31) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMCAB030026      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724155           | No. 2 Engine - Hpt Stage 1 Blade (No.31) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMCAB026073      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724156           | No. 1 Engine - Hpt Stage 1 Blade (No.32) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMCAB029079      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724156           | No. 2 Engine - Hpt Stage 1 Blade (No.32) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMCAB029019      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724157           | No. 1 Engine - Hpt Stage 1 Blade (No.33) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMC600054399     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |



| ATA<br>U=Custom  | Description                              |                     | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------|---------------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                              | Serial Number       |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                       | SW                  |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                   |                     |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                            |                     |     |             |                 |     |                  |             |                    |         |              |
| 724157           | No. 2 Engine - Hpt Stage 1 Blade (No.33) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMCAB026980      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724158           | No. 1 Engine - Hpt Stage 1 Blade (No.34) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMC600055065     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724158           | No. 2 Engine - Hpt Stage 1 Blade (No.34) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMCAB029090      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724159           | No. 1 Engine - Hpt Stage 1 Blade (No.35) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMC600054704     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724159           | No. 2 Engine - Hpt Stage 1 Blade (No.35) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMCAB028949      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724160           | No. 1 Engine - Hpt Stage 1 Blade (No.36) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMC600054979     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724160           | No. 2 Engine - Hpt Stage 1 Blade (No.36) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMCAB029117      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724161           | No. 1 Engine - Hpt Stage 1 Blade (No.37) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMC600053989     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                              |                     | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------|---------------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                              | Serial Number       |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                       | SW                  |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                   |                     |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                            |                     |     |             |                 |     |                  |             |                    |         |              |
| 724161           | No. 2 Engine - Hpt Stage 1 Blade (No.37) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMCAB028261      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724162           | No. 1 Engine - Hpt Stage 1 Blade (No.38) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMC600054063     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724162           | No. 2 Engine - Hpt Stage 1 Blade (No.38) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMCAB028983      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724163           | No. 1 Engine - Hpt Stage 1 Blade (No.39) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMCAB030090      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724163           | No. 2 Engine - Hpt Stage 1 Blade (No.39) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMCAB030147      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724164           | No. 1 Engine - Hpt Stage 1 Blade (No.40) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMCAB030177      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724164           | No. 2 Engine - Hpt Stage 1 Blade (No.40) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMCAB026041      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724165           | No. 1 Engine - Hpt Stage 1 Blade (No.41) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMC600055230     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                              |                     | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------|---------------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                              | Serial Number       |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                       | SW                  |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                   |                     |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                            |                     |     |             |                 |     |                  |             |                    |         |              |
| 724165           | No. 2 Engine - Hpt Stage 1 Blade (No.41) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMCAB028954      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724166           | No. 1 Engine - Hpt Stage 1 Blade (No.42) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMC600055076     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724166           | No. 2 Engine - Hpt Stage 1 Blade (No.42) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMCAB029063      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724167           | No. 1 Engine - Hpt Stage 1 Blade (No.43) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMCAB028947      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724167           | No. 2 Engine - Hpt Stage 1 Blade (No.43) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMCAB028273      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724168           | No. 1 Engine - Hpt Stage 1 Blade (No.44) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMCAB025913      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724168           | No. 2 Engine - Hpt Stage 1 Blade (No.44) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMCAB029039      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724169           | No. 1 Engine - Hpt Stage 1 Blade (No.45) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMC600054974     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                              |                     | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------|---------------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                              | Serial Number       |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                       | SW                  |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                   |                     |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                            |                     |     |             |                 |     |                  |             |                    |         |              |
| 724169           | No. 2 Engine - Hpt Stage 1 Blade (No.45) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMCAB029001      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724170           | No. 1 Engine - Hpt Stage 1 Blade (No.46) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMCAB030012      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724170           | No. 2 Engine - Hpt Stage 1 Blade (No.46) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMCAB030039      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724171           | No. 1 Engine - Hpt Stage 1 Blade (No.47) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMC600054020     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724171           | No. 2 Engine - Hpt Stage 1 Blade (No.47) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMCAB030038      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724172           | No. 1 Engine - Hpt Stage 1 Blade (No.48) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMCAB029022      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724172           | No. 2 Engine - Hpt Stage 1 Blade (No.48) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMCAB028979      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724173           | No. 1 Engine - Hpt Stage 1 Blade (No.49) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMC600054842     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                              |                     | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------|---------------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                              | Serial Number       |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                       | SW                  |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                   |                     |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                            |                     |     |             |                 |     |                  |             |                    |         |              |
| 724173           | No. 2 Engine - Hpt Stage 1 Blade (No.49) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMC600054567     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724174           | No. 1 Engine - Hpt Stage 1 Blade (No.50) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMC600054083     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724174           | No. 2 Engine - Hpt Stage 1 Blade (No.50) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMCAB030050      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724175           | No. 1 Engine - Hpt Stage 1 Blade (No.51) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMCAB028981      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724175           | No. 2 Engine - Hpt Stage 1 Blade (No.51) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMCAB029054      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724176           | No. 1 Engine - Hpt Stage 1 Blade (No.52) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMC600054792     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724176           | No. 2 Engine - Hpt Stage 1 Blade (No.52) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMCAB0229028     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724177           | No. 1 Engine - Hpt Stage 1 Blade (No.53) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMCAB030166      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                              |                     | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------|---------------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                              | Serial Number       |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                       | SW                  |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                   |                     |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                            |                     |     |             |                 |     |                  |             |                    |         |              |
| 724177           | No. 2 Engine - Hpt Stage 1 Blade (No.53) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RHPMCAB025775       | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724178           | No. 1 Engine - Hpt Stage 1 Blade (No.54) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMC600054883     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724178           | No. 2 Engine - Hpt Stage 1 Blade (No.54) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMCAB029125      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724179           | No. 1 Engine - Hpt Stage 1 Blade (No.55) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMCAB030150      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724179           | No. 2 Engine - Hpt Stage 1 Blade (No.55) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMCAB028199      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724180           | No. 1 Engine - Hpt Stage 1 Blade (No.56) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMCAB026024      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724180           | No. 2 Engine - Hpt Stage 1 Blade (No.56) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMCAB029065      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724181           | No. 1 Engine - Hpt Stage 1 Blade (No.57) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMCAB030181      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                              |               | UOM             | Times Since         | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------|---------------|-----------------|---------------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                              | Serial Number |                 |                     |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                       | SW            |                 |                     |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                   |               |                 |                     |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                            |               |                 |                     |                 |     |                  |             |                    |         |              |
| 724181           | No. 2 Engine - Hpt Stage 1 Blade (No.57) |               | HRS             |                     | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | Engine                                   | FW85681       | RRHPMCAB028977  | ENC                 | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |               |                 | MOS                 | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                          |               |                 | MSC                 |                 |     | O/C              |             |                    |         |              |
|                  |                                          |               |                 | [End Of Month Item] |                 |     |                  |             |                    |         |              |
| 724182           | No. 1 Engine - Hpt Stage 1 Blade (No.58) |               | HRS             |                     | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | Engine                                   | FW85681       | RRHPMCAB030076  | ENC                 | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |               |                 | MOS                 | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                          |               |                 | MSC                 |                 |     | O/C              |             |                    |         |              |
|                  |                                          |               |                 | [End Of Month Item] |                 |     |                  |             |                    |         |              |
| 724182           | No. 2 Engine - Hpt Stage 1 Blade (No.58) |               | HRS             |                     | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | Engine                                   | FW85681       | RRHPMCAB026982  | ENC                 | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |               |                 | MOS                 | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                          |               |                 | MSC                 |                 |     | O/C              |             |                    |         |              |
|                  |                                          |               |                 | [End Of Month Item] |                 |     |                  |             |                    |         |              |
| 724183           | No. 1 Engine - Hpt Stage 1 Blade (No.59) |               | HRS             |                     | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | Engine                                   | FW85681       | RRHPMCAB030069  | ENC                 | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |               |                 | MOS                 | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                          |               |                 | MSC                 |                 |     | O/C              |             |                    |         |              |
|                  |                                          |               |                 | [End Of Month Item] |                 |     |                  |             |                    |         |              |
| 724183           | No. 2 Engine - Hpt Stage 1 Blade (No.59) |               | HRS             |                     | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | Engine                                   | FW85681       | RRHPMCAB028966  | ENC                 | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |               |                 | MOS                 | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                          |               |                 | MSC                 |                 |     | O/C              |             |                    |         |              |
|                  |                                          |               |                 | [End Of Month Item] |                 |     |                  |             |                    |         |              |
| 724184           | No. 1 Engine - Hpt Stage 1 Blade (No.60) |               | HRS             |                     | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | Engine                                   | FW85681       | RRHPMCAB029043  | ENC                 | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |               |                 | MOS                 | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                          |               |                 | MSC                 |                 |     | O/C              |             |                    |         |              |
|                  |                                          |               |                 | [End Of Month Item] |                 |     |                  |             |                    |         |              |
| 724184           | No. 2 Engine - Hpt Stage 1 Blade (No.60) |               | HRS             |                     | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | Engine                                   | FW85681       | RRHPMCAB029089  | ENC                 | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |               |                 | MOS                 | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                          |               |                 | MSC                 |                 |     | O/C              |             |                    |         |              |
|                  |                                          |               |                 | [End Of Month Item] |                 |     |                  |             |                    |         |              |
| 724185           | No. 1 Engine - Hpt Stage 1 Blade (No.61) |               | HRS             |                     | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | Engine                                   | FW85681       | RRHPMC600054971 | ENC                 | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |               |                 | MOS                 | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                          |               |                 | MSC                 |                 |     | O/C              |             |                    |         |              |
|                  |                                          |               |                 | [End Of Month Item] |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                              |                     | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------|---------------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                              | Serial Number       |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                       | SW                  |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                   |                     |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                            |                     |     |             |                 |     |                  |             |                    |         |              |
| 724185           | No. 2 Engine - Hpt Stage 1 Blade (No.61) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMCAB029044      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724186           | No. 1 Engine - Hpt Stage 1 Blade (No.62) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMCAB029121      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724186           | No. 2 Engine - Hpt Stage 1 Blade (No.62) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMCAB029082      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724187           | No. 1 Engine - Hpt Stage 1 Blade (No.63) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMCAB029123      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724187           | No. 2 Engine - Hpt Stage 1 Blade (No.63) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMCAB029032      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724188           | No. 1 Engine - Hpt Stage 1 Blade (No.64) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMC600054013     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724188           | No. 2 Engine - Hpt Stage 1 Blade (No.64) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMCAB028265      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724189           | No. 1 Engine - Hpt Stage 1 Blade (No.65) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMCAB028219      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |



| ATA<br>U=Custom  | Description                              |                     | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------|---------------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                              | Serial Number       |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                       | SW                  |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                   |                     |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                            |                     |     |             |                 |     |                  |             |                    |         |              |
| 724189           | No. 2 Engine - Hpt Stage 1 Blade (No.65) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMCAB026952      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724190           | No. 1 Engine - Hpt Stage 1 Blade (No.66) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMCAB030154      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724190           | No. 2 Engine - Hpt Stage 1 Blade (No.66) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMC600053722     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724191           | No. 1 Engine - Hpt Stage 1 Blade (No.67) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMCAB030071      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724191           | No. 2 Engine - Hpt Stage 1 Blade (No.67) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMCAB029016      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724192           | No. 1 Engine - Hpt Stage 1 Blade (No.68) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMC600054333     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724192           | No. 2 Engine - Hpt Stage 1 Blade (No.68) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMCAB028996      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724193           | No. 1 Engine - Hpt Stage 1 Blade (No.69) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMCAB029008      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                              |                     | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------|---------------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                              | Serial Number       |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                       | SW                  |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                   |                     |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                            |                     |     |             |                 |     |                  |             |                    |         |              |
| 724193           | No. 2 Engine - Hpt Stage 1 Blade (No.69) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMCAB029996      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724194           | No. 1 Engine - Hpt Stage 1 Blade (No.70) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMC600055244     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724194           | No. 2 Engine - Hpt Stage 1 Blade (No.70) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMCAB029034      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724195           | No. 1 Engine - Hpt Stage 1 Blade (No.71) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMCAB030037      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724195           | No. 2 Engine - Hpt Stage 1 Blade (No.71) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMCAB028192      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724196           | No. 1 Engine - Hpt Stage 1 Blade (No.72) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMC600055019     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724196           | No. 2 Engine - Hpt Stage 1 Blade (No.72) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMCAB029133      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724197           | No. 1 Engine - Hpt Stage 1 Blade (No.73) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMCAB030124      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                              |                     | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------|---------------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                              | Serial Number       |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                       | SW                  |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                   |                     |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                            |                     |     |             |                 |     |                  |             |                    |         |              |
| 724197           | No. 2 Engine - Hpt Stage 1 Blade (No.73) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMC600053742     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724198           | No. 1 Engine - Hpt Stage 1 Blade (No.74) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMCAB030088      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724198           | No. 2 Engine - Hpt Stage 1 Blade (No.74) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85681                                  | RRHPMCAB029030      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724200           | No. 1 Engine - Hpt Stage 2 Blade (No.1)  |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMCAB000318      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724200           | No. 2 Engine - Hpt Stage 2 Blade (No.1)  |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMC502396901     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724201           | No. 1 Engine - Hpt Stage 2 Blade (No.2)  |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMC502365404     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724201           | No. 2 Engine - Hpt Stage 2 Blade (No.2)  |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMC502396804     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724202           | No. 1 Engine - Hpt Stage 2 Blade (No.3)  |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMCAB042861      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                             |                     | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-----------------------------------------|---------------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                             | Serial Number       |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                      | SW                  |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                  |                     |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                           |                     |     |             |                 |     |                  |             |                    |         |              |
| 724202           | No. 2 Engine - Hpt Stage 2 Blade (No.3) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                 | RRHPMC502405002     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                         |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                  |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                         | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724203           | No. 1 Engine - Hpt Stage 2 Blade (No.4) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                 | RRHPMCAB040747      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                         |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                  |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                         | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724203           | No. 2 Engine - Hpt Stage 2 Blade (No.4) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                 | RRHPMC502405903     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                         |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                  |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                         | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724204           | No. 1 Engine - Hpt Stage 2 Blade (No.5) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                 | RRHPMCAB044669      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                         |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                  |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                         | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724204           | No. 2 Engine - Hpt Stage 2 Blade (No.5) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                 | RRHPMCAB000299      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                         |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                  |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                         | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724205           | No. 1 Engine - Hpt Stage 2 Blade (No.6) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                 | RRHPMCAB042799      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                         |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                  |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                         | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724205           | No. 2 Engine - Hpt Stage 2 Blade (No.6) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                 | RRHPMC502364204     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                         |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                  |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                         | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724206           | No. 1 Engine - Hpt Stage 2 Blade (No.7) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                 | RRHPMCAB043845      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                         |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                  |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                         | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                              |                     | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------|---------------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                              | Serial Number       |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                       | SW                  |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                   |                     |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                            |                     |     |             |                 |     |                  |             |                    |         |              |
| 724206           | No. 2 Engine - Hpt Stage 2 Blade (No.7)  |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMC502409401     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724207           | No. 1 Engine - Hpt Stage 2 Blade (No.8)  |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMC502377107     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724207           | No. 2 Engine - Hpt Stage 2 Blade (No.8)  |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMC502391803     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724208           | No. 1 Engine - Hpt Stage 2 Blade (No.9)  |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMC502390407     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724208           | No. 2 Engine - Hpt Stage 2 Blade (No.9)  |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMC502386804     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724209           | No. 1 Engine - Hpt Stage 2 Blade (No.10) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMCAB042859      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724209           | No. 2 Engine - Hpt Stage 2 Blade (No.10) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMCAB000347      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724210           | No. 1 Engine - Hpt Stage 2 Blade (No.11) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMCAB043851      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                              |                     | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------|---------------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                              | Serial Number       |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                       | SW                  |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                   |                     |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                            |                     |     |             |                 |     |                  |             |                    |         |              |
| 724210           | No. 2 Engine - Hpt Stage 2 Blade (No.11) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMC502392203     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724211           | No. 1 Engine - Hpt Stage 2 Blade (No.12) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMCAB044720      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724211           | No. 2 Engine - Hpt Stage 2 Blade (No.12) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMCAB000363      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724212           | No. 1 Engine - Hpt Stage 2 Blade (No.13) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMC502397605     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724212           | No. 2 Engine - Hpt Stage 2 Blade (No.13) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMC502386801     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724213           | No. 1 Engine - Hpt Stage 2 Blade (No.14) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMCAB040923      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724213           | No. 2 Engine - Hpt Stage 2 Blade (No.14) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMC502370801     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724214           | No. 1 Engine - Hpt Stage 2 Blade (No.15) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMCAB040863      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                              |                     | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------|---------------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                              | Serial Number       |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                       | SW                  |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                   |                     |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                            |                     |     |             |                 |     |                  |             |                    |         |              |
| 724214           | No. 2 Engine - Hpt Stage 2 Blade (No.15) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMCAB000319      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724215           | No. 1 Engine - Hpt Stage 2 Blade (No.16) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMCAB043815      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724215           | No. 2 Engine - Hpt Stage 2 Blade (No.16) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMCAB000317      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724216           | No. 1 Engine - Hpt Stage 2 Blade (No.17) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMCAB040909      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724216           | No. 2 Engine - Hpt Stage 2 Blade (No.17) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMC502401806     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724217           | No. 1 Engine - Hpt Stage 2 Blade (No.18) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMC502399001     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724217           | No. 2 Engine - Hpt Stage 2 Blade (No.18) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMC502384301     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724218           | No. 1 Engine - Hpt Stage 2 Blade (No.19) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMCAB043883      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                              |                     | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------|---------------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                              | Serial Number       |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                       | SW                  |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                   |                     |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                            |                     |     |             |                 |     |                  |             |                    |         |              |
| 724218           | No. 2 Engine - Hpt Stage 2 Blade (No.19) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMC502410601     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724219           | No. 1 Engine - Hpt Stage 2 Blade (No.20) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMC502362504     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724219           | No. 2 Engine - Hpt Stage 2 Blade (No.20) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMCAB040852      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724220           | No. 1 Engine - Hpt Stage 2 Blade (No.21) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMCAB040870      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724220           | No. 2 Engine - Hpt Stage 2 Blade (No.21) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMC502380002     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724221           | No. 1 Engine - Hpt Stage 2 Blade (No.22) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMC502399004     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724221           | No. 2 Engine - Hpt Stage 2 Blade (No.22) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMC502386301     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724222           | No. 1 Engine - Hpt Stage 2 Blade (No.23) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMCAB042388      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |



| ATA<br>U=Custom  | Description                              |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                              | Serial Number |                     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                       | SW            |                     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                   |               |                     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                            |               |                     |             |                 |     |                  |             |                    |         |              |
| 724222           | No. 2 Engine - Hpt Stage 2 Blade (No.23) |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439 RRHPMC502406305                  |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 724223           | No. 1 Engine - Hpt Stage 2 Blade (No.24) |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439 RRHPMCAB043828                   |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 724223           | No. 2 Engine - Hpt Stage 2 Blade (No.24) |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439 RRHPMC502389703                  |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 724224           | No. 1 Engine - Hpt Stage 2 Blade (No.25) |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439 RRHPMCAB040796                   |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 724224           | No. 2 Engine - Hpt Stage 2 Blade (No.25) |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439 RRHPMC502370908                  |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 724225           | No. 1 Engine - Hpt Stage 2 Blade (No.26) |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439 RRHPMC502397307                  |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 724225           | No. 2 Engine - Hpt Stage 2 Blade (No.26) |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439 RRHPMC502410501                  |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 724226           | No. 1 Engine - Hpt Stage 2 Blade (No.27) |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439 RRHPMCAB043800                   |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                              |                     | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------|---------------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                              | Serial Number       |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                       | SW                  |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                   |                     |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                            |                     |     |             |                 |     |                  |             |                    |         |              |
| 724226           | No. 2 Engine - Hpt Stage 2 Blade (No.27) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMC502410907     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724227           | No. 1 Engine - Hpt Stage 2 Blade (No.28) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMC502384808     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724227           | No. 2 Engine - Hpt Stage 2 Blade (No.28) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMCAB040851      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724228           | No. 1 Engine - Hpt Stage 2 Blade (No.29) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMCAB043844      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724228           | No. 2 Engine - Hpt Stage 2 Blade (No.29) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMC502376807     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724229           | No. 1 Engine - Hpt Stage 2 Blade (No.30) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMCAB040799      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724229           | No. 2 Engine - Hpt Stage 2 Blade (No.30) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMC502406702     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724230           | No. 1 Engine - Hpt Stage 2 Blade (No.31) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMCAB040783      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                              |                     | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------|---------------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                              | Serial Number       |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                       | SW                  |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                   |                     |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                            |                     |     |             |                 |     |                  |             |                    |         |              |
| 724230           | No. 2 Engine - Hpt Stage 2 Blade (No.31) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMC502406506     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724231           | No. 1 Engine - Hpt Stage 2 Blade (No.32) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMCAB040838      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724231           | No. 2 Engine - Hpt Stage 2 Blade (No.32) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMCAB044666      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724232           | No. 1 Engine - Hpt Stage 2 Blade (No.33) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMCAB042803      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724232           | No. 2 Engine - Hpt Stage 2 Blade (No.33) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMC502395105     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724233           | No. 1 Engine - Hpt Stage 2 Blade (No.34) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMCAB043849      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724233           | No. 2 Engine - Hpt Stage 2 Blade (No.34) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMC502376808     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724234           | No. 1 Engine - Hpt Stage 2 Blade (No.35) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMCAB040765      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                              |                     | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------|---------------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                              | Serial Number       |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                       | SW                  |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                   |                     |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                            |                     |     |             |                 |     |                  |             |                    |         |              |
| 724234           | No. 2 Engine - Hpt Stage 2 Blade (No.35) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMC502312301     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724235           | No. 1 Engine - Hpt Stage 2 Blade (No.36) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMC502372601     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724235           | No. 2 Engine - Hpt Stage 2 Blade (No.36) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMC502387604     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724236           | No. 1 Engine - Hpt Stage 2 Blade (No.37) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMCAB043831      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724236           | No. 2 Engine - Hpt Stage 2 Blade (No.37) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMC502312007     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724237           | No. 1 Engine - Hpt Stage 2 Blade (No.38) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMCAB043850      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724237           | No. 2 Engine - Hpt Stage 2 Blade (No.38) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMC502405605     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724238           | No. 1 Engine - Hpt Stage 2 Blade (No.39) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMCAB040862      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                              |                     | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------|---------------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                              | Serial Number       |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                       | SW                  |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                   |                     |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                            |                     |     |             |                 |     |                  |             |                    |         |              |
| 724238           | No. 2 Engine - Hpt Stage 2 Blade (No.39) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMCAB042768      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724239           | No. 1 Engine - Hpt Stage 2 Blade (No.40) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPNCAB042396      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724239           | No. 2 Engine - Hpt Stage 2 Blade (No.40) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMC502404401     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724240           | No. 1 Engine - Hpt Stage 2 Blade (No.41) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMCAB040759      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724240           | No. 2 Engine - Hpt Stage 2 Blade (No.41) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMC502407002     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724241           | No. 1 Engine - Hpt Stage 2 Blade (No.42) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMC502377002     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724241           | No. 2 Engine - Hpt Stage 2 Blade (No.42) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMC502181504     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724242           | No. 1 Engine - Hpt Stage 2 Blade (No.43) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMCAB042389      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                              |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                              | Serial Number |                     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                       | SW            |                     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                   |               |                     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                            |               |                     |             |                 |     |                  |             |                    |         |              |
| 724242           | No. 2 Engine - Hpt Stage 2 Blade (No.43) |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439 RRHPMC502407601                  |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 724243           | No. 1 Engine - Hpt Stage 2 Blade (No.44) |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439 RRHPMC502397407                  |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 724243           | No. 2 Engine - Hpt Stage 2 Blade (No.44) |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FR85439 RRHPMC502411102                  |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 724244           | No. 1 Engine - Hpt Stage 2 Blade (No.45) |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439 RRHPMCAB040792                   |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 724244           | No. 2 Engine - Hpt Stage 2 Blade (No.45) |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439 RRHPMCAB043853                   |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 724245           | No. 1 Engine - Hpt Stage 2 Blade (No.46) |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439 RRHPMCAB044727                   |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 724245           | No. 2 Engine - Hpt Stage 2 Blade (No.46) |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439 RRHPMC502412004                  |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 724246           | No. 1 Engine - Hpt Stage 2 Blade (No.47) |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439 RRHPMC502400301                  |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                              |                     | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------|---------------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                              | Serial Number       |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                       | SW                  |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                   |                     |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                            |                     |     |             |                 |     |                  |             |                    |         |              |
| 724246           | No. 2 Engine - Hpt Stage 2 Blade (No.47) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMC502397206     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724247           | No. 1 Engine - Hpt Stage 2 Blade (No.48) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMCAB043796      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724247           | No. 2 Engine - Hpt Stage 2 Blade (No.48) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMC502406306     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724248           | No. 1 Engine - Hpt Stage 2 Blade (No.49) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMC502406501     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724248           | No. 2 Engine - Hpt Stage 2 Blade (No.49) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMCAB000356      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724249           | No. 1 Engine - Hpt Stage 2 Blade (No.50) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMC502370904     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724249           | No. 2 Engine - Hpt Stage 2 Blade (No.50) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMC502390008     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724250           | No. 1 Engine - Hpt Stage 2 Blade (No.51) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMCAB040815      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                              |                     | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------|---------------------|-----|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                              | Serial Number       |     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                       | SW                  |     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                   |                     |     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                            |                     |     |             |                 |     |                  |             |                     |         |              |
| 724250           | No. 2 Engine - Hpt Stage 2 Blade (No.51) |                     | HRS |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | FW85439                                  | RRHPMC502409105     | ENC |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                     |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                     |         |              |
| 724251           | No. 1 Engine - Hpt Stage 2 Blade (No.52) |                     | HRS |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | FW85439                                  | RRHPMCAB042774      | ENC |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                     |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                     |         |              |
| 724251           | No. 2 Engine - Hpt Stage 2 Blade (No.52) |                     | HRS |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | FW85439                                  | RRHPMC502406303     | ENC |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                     |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                     |         |              |
| 724252           | No. 1 Engine - Hpt Stage 2 Blade (No.53) |                     | HRS |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | FW85439                                  | RRHPMCAB040758      | ENC |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                     |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                     |         |              |
| 724252           | No. 2 Engine - Hpt Stage 2 Blade (No.53) |                     | HRS |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | FW85439                                  | RRHPMC502391303     | ENC |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                     |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                     |         |              |
| 724253           | No. 1 Engine - Hpt Stage 2 Blade (No.54) |                     | HRS |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | FW85439                                  | RRHPMC502256107     | ENC |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                     |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                     |         |              |
| 724253           | No. 2 Engine - Hpt Stage 2 Blade (No.54) |                     | HRS |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | FR85439                                  | RRHPMC502376802     | ENC |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                     |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                     |         |              |
| 724254           | No. 1 Engine - Hpt Stage 2 Blade (No.55) |                     | HRS |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | FW85439                                  | RRHPMCAB042791      | ENC |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                     |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                     |         |              |



| ATA<br>U=Custom  | Description                              |                     | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------|---------------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                              | Serial Number       |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                       | SW                  |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                   |                     |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                            |                     |     |             |                 |     |                  |             |                    |         |              |
| 724254           | No. 2 Engine - Hpt Stage 2 Blade (No.55) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMC502406808     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724255           | No. 1 Engine - Hpt Stage 2 Blade (No.56) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMCAB042821      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724255           | No. 2 Engine - Hpt Stage 2 Blade (No.56) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMC502411605     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724256           | No. 1 Engine - Hpt Stage 2 Blade (No.57) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMCAB042804      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724256           | No. 2 Engine - Hpt Stage 2 Blade (No.57) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMCAB042835      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724257           | No. 1 Engine - Hpt Stage 2 Blade (No.58) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMCAB042858      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724257           | No. 2 Engine - Hpt Stage 2 Blade (No.58) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMC502395407     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724258           | No. 1 Engine - Hpt Stage 2 Blade (No.59) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMC502361901     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                              |                     | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------|---------------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                              | Serial Number       |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                       | SW                  |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                   |                     |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                            |                     |     |             |                 |     |                  |             |                    |         |              |
| 724258           | No. 2 Engine - Hpt Stage 2 Blade (No.59) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMC502364701     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724259           | No. 1 Engine - Hpt Stage 2 Blade (No.60) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMCAB040785      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724259           | No. 2 Engine - Hpt Stage 2 Blade (No.60) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMC502314602     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724260           | No. 1 Engine - Hpt Stage 2 Blade (No.61) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMC502391808     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724260           | No. 2 Engine - Hpt Stage 2 Blade (No.61) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMC502386807     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724261           | No. 1 Engine - Hpt Stage 2 Blade (No.62) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMCAB043881      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724261           | No. 2 Engine - Hpt Stage 2 Blade (No.62) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMCAB000288      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724262           | No. 1 Engine - Hpt Stage 2 Blade (No.63) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMC502362506     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                              |                     | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------|---------------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                              | Serial Number       |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                       | SW                  |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                   |                     |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                            |                     |     |             |                 |     |                  |             |                    |         |              |
| 724262           | No. 2 Engine - Hpt Stage 2 Blade (No.63) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMC502398601     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724263           | No. 1 Engine - Hpt Stage 2 Blade (No.64) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMC502392805     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724263           | No. 2 Engine - Hpt Stage 2 Blade (No.64) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMC502400308     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724264           | No. 1 Engine - Hpt Stage 2 Blade (No.65) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMCAB043882      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724264           | No. 2 Engine - Hpt Stage 2 Blade (No.65) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMC502387202     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724265           | No. 1 Engine - Hpt Stage 2 Blade (No.66) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMCAB043798      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724265           | No. 2 Engine - Hpt Stage 2 Blade (No.66) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMC502406706     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724266           | No. 1 Engine - Hpt Stage 2 Blade (No.67) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMCAB040873      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                              |                     | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------|---------------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                              | Serial Number       |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                       | SW                  |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                   |                     |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                            |                     |     |             |                 |     |                  |             |                    |         |              |
| 724266           | No. 2 Engine - Hpt Stage 2 Blade (No.67) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMC502388101     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724267           | No. 1 Engine - Hpt Stage 2 Blade (No.68) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMCAB040921      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724267           | No. 2 Engine - Hpt Stage 2 Blade (No.68) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMC502405208     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724268           | No. 1 Engine - Hpt Stage 2 Blade (No.69) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMCAB040738      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724268           | No. 2 Engine - Hpt Stage 2 Blade (No.69) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMC502395308     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724269           | No. 1 Engine - Hpt Stage 2 Blade (No.70) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMCAB044671      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724269           | No. 2 Engine - Hpt Stage 2 Blade (No.70) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMC502399608     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724270           | No. 1 Engine - Hpt Stage 2 Blade (No.71) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMCAB044689      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                              |                     | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------|---------------------|-----|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                              | Serial Number       |     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                       | SW                  |     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                   |                     |     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                            |                     |     |             |                 |     |                  |             |                     |         |              |
| 724270           | No. 2 Engine - Hpt Stage 2 Blade (No.71) |                     | HRS |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | FW85439                                  | RRHPMC502365706     | ENC |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                     |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                     |         |              |
| 724271           | No. 1 Engine - Hpt Stage 2 Blade (No.72) |                     | HRS |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | FW85439                                  | RRHPMC502406001     | ENC |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                     |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                     |         |              |
| 724271           | No. 2 Engine - Hpt Stage 2 Blade (No.72) |                     | HRS |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | FW85439                                  | RRHPMC502397707     | ENC |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                     |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                     |         |              |
| 724272           | No. 1 Engine - Hpt Stage 2 Blade (No.73) |                     | HRS |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | FW85439                                  | RRHPMCAB043847      | ENC |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                     |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                     |         |              |
| 724272           | No. 2 Engine - Hpt Stage 2 Blade (No.73) |                     | HRS |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | FW85439                                  | RRHPMC502406504     | ENC |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                     |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                     |         |              |
| 724273           | No. 1 Engine - Hpt Stage 2 Blade (No.74) |                     | HRS |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | FW85439                                  | RRHPMC502384803     | ENC |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                     |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                     |         |              |
| 724273           | No. 2 Engine - Hpt Stage 2 Blade (No.74) |                     | HRS |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | FW85439                                  | RRHPMC502390007     | ENC |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                     |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                     |         |              |
| 724274           | No. 1 Engine - Hpt Stage 2 Blade (No.75) |                     | HRS |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | FW85439                                  | RRHPMCAB044691      | ENC |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                     |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom  | Description                              |                     | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------|---------------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                              | Serial Number       |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                       | SW                  |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                   |                     |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                            |                     |     |             |                 |     |                  |             |                    |         |              |
| 724274           | No. 2 Engine - Hpt Stage 2 Blade (No.75) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMCAB040881      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724275           | No. 1 Engine - Hpt Stage 2 Blade (No.76) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMCAB040905      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724275           | No. 2 Engine - Hpt Stage 2 Blade (No.76) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMC502396507     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724276           | No. 1 Engine - Hpt Stage 2 Blade (No.77) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMCAB044752      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724276           | No. 2 Engine - Hpt Stage 2 Blade (No.77) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMC502280307     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724277           | No. 1 Engine - Hpt Stage 2 Blade (No.78) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMCAB040746      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724277           | No. 2 Engine - Hpt Stage 2 Blade (No.78) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMC502308601     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724278           | No. 1 Engine - Hpt Stage 2 Blade (No.79) |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                  | RRHPMCAB040745      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                   |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                     |                     | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-----------------------------------------------------------------|---------------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                     | Serial Number       |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                              | SW                  |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                          |                     |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                   |                     |     |             |                 |     |                  |             |                    |         |              |
| 724278           | No. 2 Engine - Hpt Stage 2 Blade (No.79)                        |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                                         | RRHPMCAB042304      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                                 |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                                          |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                                                 | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724279           | No. 1 Engine - Hpt Stage 2 Blade (No.80)                        |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                                         | RRHPMCAB040835      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                                 |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                                          |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                                                 | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724279           | No. 2 Engine - Hpt Stage 2 Blade (No.80)                        |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                                         | RRHPMCAB042306      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                                 |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                                          |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                                                 | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724280           | No. 1 Engine - Hpt Stage 2 Blade (No.81)                        |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                                         | RRHPMCAB044713      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                                 |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                                          |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                                                 | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724280           | No. 2 Engine - Hpt Stage 2 Blade (No.81)                        |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                                         | RRHPMC502365402     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                                 |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                                          |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                                                 | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724281           | No. 1 Engine - Hpt Stage 2 Blade (No.82)                        |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                                         | RRHPMC502370505     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                                 |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                                          |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                                                 | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 724281           | No. 2 Engine - Hpt Stage 2 Blade (No.82)                        |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | FW85439                                                         | RRHPMC502396907     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                                 |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                                          |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  |                                                                 | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 725100           | No. 1 Engine - Lp Turbine Stage 1 Disc - Removal / Installation |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                 |                     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | PN                                                              | SN-UNKNOWN          | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                 |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                          | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                     |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|-----------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                                     | Serial Number |                     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                              | SW            |                     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                          |               |                     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                                   |               |                     |             |                 |     |                  |             |                     |         |              |
| 725100           | No. 2 Engine - Lp Turbine Stage 1 Disc - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                 |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | PN                                                              | SN-UNKNOWN    | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                 |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                          |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 725101           | No. 1 Engine - Lp Turbine Stage 1 Disc - Discard                |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | PN                                                              | SN-UNKNOWN    | ENC                 |             | 392             |     | 10000            | 0           | 10000               |         | 0            |
|                  |                                                                 |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                 |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
|                  | Engine                                                          |               |                     |             |                 |     |                  |             |                     |         |              |
| 725101           | No. 2 Engine - Lp Turbine Stage 1 Disc - Discard                |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | PN                                                              | SN-UNKNOWN    | ENC                 |             | 392             |     | 10000            | 0           | 10000               |         | 0            |
|                  |                                                                 |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                 |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
|                  | Engine                                                          |               |                     |             |                 |     |                  |             |                     |         |              |
| 725102           | No. 1 Engine - Lp Turbine Stage 2 Disc - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | PN                                                              | SN-UNKNOWN    | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                                                 |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                 |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                          |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 725102           | No. 2 Engine - Lp Turbine Stage 2 Disc - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | PN                                                              | SN-UNKNOWN    | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                                                 |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                 |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                          |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 725103           | No. 1 Engine - Lp Turbine Stage 2 Disc - Discard                |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | PN                                                              | SN-UNKNOWN    | ENC                 |             | 392             |     | 10000            | 0           | 10000               |         | 0            |
|                  |                                                                 |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                 |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
|                  | Engine                                                          |               |                     |             |                 |     |                  |             |                     |         |              |
| 725103           | No. 2 Engine - Lp Turbine Stage 2 Disc - Discard                |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | PN                                                              | SN-UNKNOWN    | ENC                 |             | 392             |     | 10000            | 0           | 10000               |         | 0            |
|                  |                                                                 |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                 |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
|                  | Engine                                                          |               |                     |             |                 |     |                  |             |                     |         |              |



| ATA<br>U=Custom  | Description                                                     |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|-----------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                                     | Serial Number |                     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                              | SW            |                     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                          |               |                     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                                   |               |                     |             |                 |     |                  |             |                     |         |              |
| 725104           | No. 1 Engine - Lp Turbine Stage 3 Disc - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                 |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | PN                                                              | SN-UNKNOWN    | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                 |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                          |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 725104           | No. 2 Engine - Lp Turbine Stage 3 Disc - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                 |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | PN                                                              | SN-UNKNOWN    | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                 |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                          |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 725105           | No. 1 Engine - Lp Turbine Stage 3 Disc - Discard                |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | PN                                                              | SN-UNKNOWN    | ENC                 |             | 392             |     | 10000            | 0           | 10000               |         | 0            |
|                  |                                                                 |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                 |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
|                  | Engine                                                          |               |                     |             |                 |     |                  |             |                     |         |              |
| 725105           | No. 2 Engine - Lp Turbine Stage 3 Disc - Discard                |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | PN                                                              | SN-UNKNOWN    | ENC                 |             | 392             |     | 10000            | 0           | 10000               |         | 0            |
|                  |                                                                 |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                 |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
|                  | Engine                                                          |               |                     |             |                 |     |                  |             |                     |         |              |
| 725106           | No. 1 Engine - Lp Turbine Shaft - Removal / Installation        |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | PN                                                              | SN-UNKNOWN    | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                                                 |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                 |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                          |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 725106           | No. 2 Engine - Lp Turbine Shaft - Removal / Installation        |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | PN                                                              | SN-UNKNOWN    | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                                                 |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                 |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                          |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 725107           | No. 1 Engine - Lp Turbine Shaft - Discard                       |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | PN                                                              | SN-UNKNOWN    | ENC                 |             | 392             |     | 5000             | 0           | 5000                |         | 0            |
|                  |                                                                 |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                 |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
|                  | Engine                                                          |               |                     |             |                 |     |                  |             |                     |         |              |
| 725107           | No. 2 Engine - Lp Turbine Shaft - Discard                       |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | PN                                                              | SN-UNKNOWN    | ENC                 |             | 392             |     | 5000             | 0           | 5000                |         | 0            |
|                  |                                                                 |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                 |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
|                  | Engine                                                          |               |                     |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom  | Description                                                                    |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------|--------------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                  | Part Number                                                                    | Serial Number |                                    |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position | HW                                                                             | SW            |                                    |             |                 |     |                  |             |                    |             | Manufacturer |
|                  | MM Ref                                                                         |               |                                    |             |                 |     |                  |             |                    |             | Date Type    |
|                  | Ops Number(s)                                                                  |               |                                    |             |                 |     |                  |             |                    |             |              |
| 725600           | No. 1 Engine - Turbine Exhaust Support Strut Assembly - Removal / Installation |               | HRS                                |             | 994.4           |     |                  | 0           |                    |             | 0            |
|                  |                                                                                |               | ENC                                |             | 392             |     |                  | 0           |                    |             | 0            |
|                  | PN                                                                             | SN-UNKNOWN    | MOS                                |             | 41.8            |     |                  | 17 Nov 2022 |                    |             |              |
|                  |                                                                                |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Engine           |                                                                                |               | [End Of Month Item]                |             |                 |     |                  |             |                    |             |              |
| 725600           | No. 2 Engine - Turbine Exhaust Support Strut Assembly - Removal / Installation |               | HRS                                |             | 994.4           |     |                  | 0           |                    |             | 0            |
|                  |                                                                                |               | ENC                                |             | 392             |     |                  | 0           |                    |             | 0            |
|                  | PN                                                                             | SN-UNKNOWN    | MOS                                |             | 41.9            |     |                  | 15 Nov 2022 |                    |             |              |
|                  |                                                                                |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Engine           |                                                                                |               | [End Of Month Item]                |             |                 |     |                  |             |                    |             |              |
| 725602           | No. 1 Engine - Turbine Exhaust Support Strut Assembly - Inspection             |               | HRS                                |             | 994.4           |     |                  | 0           |                    |             | 0            |
|                  |                                                                                |               | ENC                                |             | 392             |     |                  | 0           |                    |             | 0            |
|                  |                                                                                |               | MOS                                |             | 41.8            |     |                  | 17 Nov 2022 |                    |             |              |
|                  |                                                                                |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Engine           |                                                                                |               | [End Of Month Item]                |             |                 |     |                  |             |                    |             |              |
| 725602           | No. 2 Engine - Turbine Exhaust Support Strut Assembly - Inspection             |               | HRS                                |             | 994.4           |     |                  | 0           |                    |             | 0            |
|                  |                                                                                |               | ENC                                |             | 392             |     |                  | 0           |                    |             | 0            |
|                  |                                                                                |               | MOS                                |             | 41.9            |     |                  | 15 Nov 2022 |                    |             |              |
|                  |                                                                                |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Engine           |                                                                                |               | [End Of Month Item]                |             |                 |     |                  |             |                    |             |              |
| 725603           | No. 1 Engine - Rear Mount Ring - Detailed Inspection                           |               | HRS                                |             | 994.4           |     |                  | 0           |                    |             | 0            |
|                  |                                                                                |               | ENC                                |             | 392             |     |                  | 0           |                    |             | 0            |
|                  |                                                                                |               | MOS                                |             | 41.8            |     | 240              | 17 Nov 2022 | 30 Nov 2042        | 31 Dec 2042 |              |
|                  |                                                                                |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Engine           | 052023                                                                         |               |                                    |             |                 |     |                  |             |                    |             |              |
| 725603           | No. 2 Engine - Rear Mount Ring - Detailed Inspection                           |               | HRS                                |             | 994.4           |     |                  | 0           |                    |             | 0            |
|                  |                                                                                |               | ENC                                |             | 392             |     |                  | 0           |                    |             | 0            |
|                  |                                                                                |               | MOS                                |             | 41.9            |     | 240              | 15 Nov 2022 | 30 Nov 2042        | 31 Dec 2042 |              |
|                  |                                                                                |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Engine           | 052023                                                                         |               |                                    |             |                 |     |                  |             |                    |             |              |
| 725604           | No. 1 Engine - Lp Turbine Fuel Shut-Off Cable - Removal / Installation         |               | HRS                                |             | 994.4           |     |                  | 0           |                    |             | 0            |
|                  |                                                                                |               | ENC                                |             | 392             |     |                  | 0           |                    |             | 0            |
|                  | PN                                                                             | SN-UNKNOWN    | MOS                                |             | 41.8            |     |                  | 17 Nov 2022 |                    |             |              |
|                  |                                                                                |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Engine           |                                                                                |               | [End Of Month Item]                |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom  | Description                                                                 |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------|-----------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                  | Part Number                                                                 | Serial Number |                                    |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position | HW                                                                          | SW            |                                    |             |                 |     |                  |             |                    |             | Manufacturer |
|                  | MM Ref                                                                      |               |                                    |             |                 |     |                  |             |                    |             | Date Type    |
|                  | Ops Number(s)                                                               |               |                                    |             |                 |     |                  |             |                    |             |              |
| 725604           | No. 2 Engine - Lp Turbine Fuel Shut-Off Cable - Removal / Installation      |               | HRS                                |             | 994.4           |     |                  | 0           |                    |             | 0            |
|                  |                                                                             |               | ENC                                |             | 392             |     |                  | 0           |                    |             | 0            |
|                  | PN                                                                          | SN-UNKNOWN    | MOS                                |             | 41.9            |     |                  | 15 Nov 2022 |                    |             |              |
|                  |                                                                             |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Engine           |                                                                             |               | [End Of Month Item]                |             |                 |     |                  |             |                    |             |              |
| 725606           | No. 1 Engine - Lp Turbine Fuel Shut-Off Cable - Special Detailed Inspection |               | HRS                                |             | 994.4           |     |                  | 0           |                    |             | 0            |
|                  |                                                                             |               | ENC                                |             | 392             |     |                  | 0           |                    |             | 0            |
|                  |                                                                             |               | MOS                                |             | 41.8            |     | 240              | 17 Nov 2022 | 30 Nov 2042        | 31 Dec 2042 |              |
|                  |                                                                             |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Engine           | 052023                                                                      |               |                                    |             |                 |     |                  |             |                    |             |              |
| 725606           | No. 2 Engine - Lp Turbine Fuel Shut-Off Cable - Special Detailed Inspection |               | HRS                                |             | 994.4           |     |                  | 0           |                    |             | 0            |
|                  |                                                                             |               | ENC                                |             | 392             |     |                  | 0           |                    |             | 0            |
|                  |                                                                             |               | MOS                                |             | 41.9            |     | 240              | 15 Nov 2022 | 30 Nov 2042        | 31 Dec 2042 |              |
|                  |                                                                             |               | [End Of Month Item] [MOS: +1m/-1m] |             |                 |     |                  |             |                    |             |              |
| Engine           | 052023                                                                      |               |                                    |             |                 |     |                  |             |                    |             |              |
| 725607           | No. 1 Engine - Turbine Exhaust AIR Baffle - Removal / Installation          |               | HRS                                |             | 994.4           |     |                  | 0           |                    |             | 0            |
|                  |                                                                             |               | ENC                                |             | 392             |     |                  | 0           |                    |             | 0            |
|                  | PN                                                                          | SN-UNKNOWN    | MOS                                |             | 41.8            |     |                  | 17 Nov 2022 |                    |             |              |
|                  |                                                                             |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Engine           |                                                                             |               | [End Of Month Item]                |             |                 |     |                  |             |                    |             |              |
| 725607           | No. 2 Engine - Turbine Exhaust AIR Baffle - Removal / Installation          |               | HRS                                |             | 994.4           |     |                  | 0           |                    |             | 0            |
|                  |                                                                             |               | ENC                                |             | 392             |     |                  | 0           |                    |             | 0            |
|                  | PN                                                                          | SN-UNKNOWN    | MOS                                |             | 41.9            |     |                  | 15 Nov 2022 |                    |             |              |
|                  |                                                                             |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Engine           |                                                                             |               | [End Of Month Item]                |             |                 |     |                  |             |                    |             |              |
| 725609           | No. 1 Engine - Turbine Exhaust AIR Baffles - Inspection / Check             |               | HRS                                |             | 994.4           |     |                  | 0           |                    |             | 0            |
|                  |                                                                             |               | ENC                                |             | 392             |     |                  | 0           |                    |             | 0            |
|                  |                                                                             |               | MOS                                |             | 41.8            |     |                  | 17 Nov 2022 |                    |             |              |
|                  |                                                                             |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Engine           |                                                                             |               | [End Of Month Item]                |             |                 |     |                  |             |                    |             |              |
| 725609           | No. 2 Engine - Turbine Exhaust AIR Baffles - Inspection / Check             |               | HRS                                |             | 994.4           |     |                  | 0           |                    |             | 0            |
|                  |                                                                             |               | ENC                                |             | 392             |     |                  | 0           |                    |             | 0            |
|                  |                                                                             |               | MOS                                |             | 41.9            |     |                  | 15 Nov 2022 |                    |             |              |
|                  |                                                                             |               | MSC                                |             |                 |     | O/C              |             |                    |             |              |
| Engine           |                                                                             |               | [End Of Month Item]                |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom  | Description                                                                  |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                  | Serial Number |                     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                           | SW            |                     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                       |               |                     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                                |               |                     |             |                 |     |                  |             |                    |         |              |
| 725610           | No. 1 Engine - Rear Mount Ring - Removal / Installation                      |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | PN                                                                           | SN-UNKNOWN    | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                                              |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                                                       |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  |                                                                              |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 725610           | No. 2 Engine - Rear Mount Ring - Removal / Installation                      |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | PN                                                                           | SN-UNKNOWN    | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                                              |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                                                       |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  |                                                                              |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 725611           | No. 1 Engine - Rear Mount Ring - Discard                                     |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | PN                                                                           | SN-UNKNOWN    | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                                              |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                                                       |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  |                                                                              |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 725611           | No. 2 Engine - Rear Mount Ring - Discard                                     |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | PN                                                                           | SN-UNKNOWN    | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                                              |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                                                       |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  |                                                                              |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 726100           | No. 1 Engine - Accessory Gearbox Pressurizing Valve - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | PN                                                                           | SN-UNKNOWN    | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                                              |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                                                       |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  |                                                                              |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 726100           | No. 2 Engine - Accessory Gearbox Pressurizing Valve - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | PN                                                                           | SN-UNKNOWN    | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                                              |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                                                       |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  |                                                                              |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 726102           | No. 1 Engine - Accessory Gearbox Pressurizing Valve - Inspection             |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                              |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                                              |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                                                       |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  |                                                                              |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                    |                     | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|--------------------------------------------------------------------------------|---------------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                    | Serial Number       |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                             | SW                  |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                         |                     |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                                  |                     |     |             |                 |     |                  |             |                    |         |              |
| 726102           | No. 2 Engine - Accessory Gearbox Pressurizing Valve - Inspection               |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                |                     | ENC |             | 392             |     |                  | 0           |                    | 0       |              |
|                  |                                                                                |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                                |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                         | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 726103           | No. 1 Engine - Accessory Gearbox Oil Tank Sight Glass - Removal / Installation |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                |                     | ENC |             | 392             |     |                  | 0           |                    | 0       |              |
|                  |                                                                                |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                                |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                         | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 726103           | No. 2 Engine - Accessory Gearbox Oil Tank Sight Glass - Removal / Installation |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                |                     | ENC |             | 392             |     |                  | 0           |                    | 0       |              |
|                  |                                                                                |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                                |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                         | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 726105           | No. 1 Engine - Remote Oil Filler Assembly - Removal / Installation             |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                |                     | ENC |             | 392             |     |                  | 0           |                    | 0       |              |
|                  |                                                                                |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                                |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                         | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 726105           | No. 2 Engine - Remote Oil Filler Assembly - Removal / Installation             |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                |                     | ENC |             | 392             |     |                  | 0           |                    | 0       |              |
|                  |                                                                                |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                                |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                         | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 726107           | No. 1 Engine - Accessory Gearbox - Inspection                                  |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                |                     | ENC |             | 392             |     |                  | 0           |                    | 0       |              |
|                  |                                                                                |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                                |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                         | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 726107           | No. 2 Engine - Accessory Gearbox - Inspection                                  |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                |                     | ENC |             | 392             |     |                  | 0           |                    | 0       |              |
|                  |                                                                                |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                                |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                         | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                        |                     | UOM                                               | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------|------------------------------------------------------------------------------------|---------------------|---------------------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                  | Part Number                                                                        | Serial Number       |                                                   |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position | HW                                                                                 | SW                  |                                                   |             |                 |     |                  |             |                    |             | Manufacturer |
|                  | MM Ref                                                                             |                     |                                                   |             |                 |     |                  |             |                    |             | Date Type    |
|                  | Ops Number(s)                                                                      |                     |                                                   |             |                 |     |                  |             |                    |             |              |
| 726113           | No. 1 Engine - Accessory Gearbox - Replacement of Inserts (BRG3318)                |                     | HRS                                               |             | 994.4           |     |                  | 0           |                    |             | 0            |
|                  |                                                                                    |                     | ENC                                               |             | 392             |     |                  | 0           |                    | 0           |              |
|                  |                                                                                    |                     | MOS                                               |             | 41.8            |     |                  | 17 Nov 2022 |                    |             |              |
|                  |                                                                                    |                     | MSC                                               |             |                 |     | O/C              |             |                    |             |              |
|                  | Engine                                                                             | [End Of Month Item] |                                                   |             |                 |     |                  |             |                    |             |              |
| 726113           | No. 2 Engine - Accessory Gearbox - Replacement of Inserts (BRG3318)                |                     | HRS                                               |             | 994.4           |     |                  | 0           |                    |             | 0            |
|                  |                                                                                    |                     | ENC                                               |             | 392             |     |                  | 0           |                    | 0           |              |
|                  |                                                                                    |                     | MOS                                               |             | 41.9            |     |                  | 15 Nov 2022 |                    |             |              |
|                  |                                                                                    |                     | MSC                                               |             |                 |     | O/C              |             |                    |             |              |
|                  | Engine                                                                             | [End Of Month Item] |                                                   |             |                 |     |                  |             |                    |             |              |
| 727100           | No. 1 Engine - Bypass Duct Access Panels - Removal / Installation<br>PN SN-UNKNOWN |                     | HRS                                               |             | 994.4           |     |                  | 0           |                    |             | 0            |
|                  |                                                                                    |                     | ENC                                               |             | 392             |     |                  | 0           |                    | 0           |              |
|                  |                                                                                    |                     | MOS                                               |             | 41.8            |     |                  | 17 Nov 2022 |                    |             |              |
|                  |                                                                                    |                     | MSC                                               |             |                 |     | O/C              |             |                    |             |              |
|                  | Engine                                                                             | [End Of Month Item] |                                                   |             |                 |     |                  |             |                    |             |              |
| 727100           | No. 2 Engine - Bypass Duct Access Panels - Removal / Installation<br>PN SN-UNKNOWN |                     | HRS                                               |             | 994.4           |     |                  | 0           |                    |             | 0            |
|                  |                                                                                    |                     | ENC                                               |             | 392             |     |                  | 0           |                    | 0           |              |
|                  |                                                                                    |                     | MOS                                               |             | 41.9            |     |                  | 15 Nov 2022 |                    |             |              |
|                  |                                                                                    |                     | MSC                                               |             |                 |     | O/C              |             |                    |             |              |
|                  | Engine                                                                             | [End Of Month Item] |                                                   |             |                 |     |                  |             |                    |             |              |
| 727102           | No. 1 Engine - Bypass Duct - General Visual Inspection<br>052006                   |                     | HRS                                               |             | 994.4           |     | 4800             | 0           | 4800               | 4850        | 0            |
|                  |                                                                                    |                     | ENC                                               |             | 392             |     |                  | 0           |                    |             | 0            |
|                  |                                                                                    |                     | MOS                                               |             | 41.8            |     |                  | 17 Nov 2022 |                    |             |              |
|                  |                                                                                    |                     | [End Of Month Item] [HRS: +50/-50]                |             |                 |     |                  |             |                    |             |              |
|                  | Engine                                                                             |                     |                                                   |             |                 |     |                  |             |                    |             |              |
| 727102           | No. 2 Engine - Bypass Duct - General Visual Inspection<br>052006                   |                     | HRS                                               |             | 994.4           |     | 4800             | 0           | 4800               | 4850        | 0            |
|                  |                                                                                    |                     | ENC                                               |             | 392             |     |                  | 0           |                    |             | 0            |
|                  |                                                                                    |                     | MOS                                               |             | 41.9            |     |                  | 15 Nov 2022 |                    |             |              |
|                  |                                                                                    |                     | [End Of Month Item] [HRS: +50/-50]                |             |                 |     |                  |             |                    |             |              |
|                  | Engine                                                                             |                     |                                                   |             |                 |     |                  |             |                    |             |              |
| 727103           | No. 1 Engine - Engine Bypass Duct Internal FS 894.6 - FS 950.3 - Zonal Inspection  |                     | HRS                                               |             | 994.4           |     | 4800             | 0           | 4800               | 4850        | 0            |
|                  |                                                                                    |                     | ENC                                               |             | 392             |     |                  | 0           |                    |             | 0            |
|                  |                                                                                    |                     | MOS                                               |             | 41.8            |     | 192              | 17 Nov 2022 | 30 Nov 2038        | 31 Dec 2038 |              |
|                  |                                                                                    |                     | [End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50] |             |                 |     |                  |             |                    |             |              |
|                  | Engine                                                                             |                     |                                                   |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom  | Description                                                                                               |               | UOM                                               | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |
|------------------|-----------------------------------------------------------------------------------------------------------|---------------|---------------------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|
|                  | Part Number                                                                                               | Serial Number |                                                   |             |                 |     |                  |             |                    |             | Approx Price |
| Logbook Position | HW                                                                                                        | SW            |                                                   |             |                 |     |                  |             |                    |             | Manufacturer |
|                  | MM Ref                                                                                                    |               |                                                   |             |                 |     |                  |             |                    |             | Date Type    |
|                  | Ops Number(s)                                                                                             |               |                                                   |             |                 |     |                  |             |                    |             |              |
| 727103           | No. 2 Engine - Engine Bypass Duct Internal FS 894.6 - FS 950.3 - Zonal Inspection                         |               | HRS                                               |             | 994.4           |     | 4800             | 0           | 4800               | 4850        | 0            |
|                  |                                                                                                           |               | ENC                                               |             | 392             |     |                  | 0           |                    | 0           |              |
|                  |                                                                                                           |               | MOS                                               |             | 41.9            |     | 192              | 15 Nov 2022 | 30 Nov 2038        | 31 Dec 2038 |              |
|                  |                                                                                                           |               | [End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50] |             |                 |     |                  |             |                    |             |              |
| Engine           |                                                                                                           |               |                                                   |             |                 |     |                  |             |                    |             |              |
| 727104           | No. 1 Engine - Bypass Duct Access Panels - Repair Damage to Perforate Skin Using Filler (BRG3145)         |               | HRS                                               |             | 994.4           |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                           |               | ENC                                               |             | 392             |     |                  | 0           |                    | 0           |              |
|                  |                                                                                                           |               | MOS                                               |             | 41.8            |     |                  | 17 Nov 2022 |                    |             |              |
|                  |                                                                                                           |               | MSC                                               |             |                 |     | O/C              |             |                    |             |              |
| Engine           |                                                                                                           |               |                                                   |             |                 |     |                  |             |                    |             |              |
| 727104           | No. 2 Engine - Bypass Duct Access Panels - Repair Damage to Perforate Skin Using Filler (BRG3145)         |               | HRS                                               |             | 994.4           |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                           |               | ENC                                               |             | 392             |     |                  | 0           |                    | 0           |              |
|                  |                                                                                                           |               | MOS                                               |             | 41.9            |     |                  | 15 Nov 2022 |                    |             |              |
|                  |                                                                                                           |               | MSC                                               |             |                 |     | O/C              |             |                    |             |              |
| Engine           |                                                                                                           |               |                                                   |             |                 |     |                  |             |                    |             |              |
| 727105           | No. 1 Engine - Bypass Duct Access Assembly - Repair Damage to Perforate Skin Using Filler (BRG3147)       |               | HRS                                               |             | 994.4           |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                           |               | ENC                                               |             | 392             |     |                  | 0           |                    | 0           |              |
|                  |                                                                                                           |               | MOS                                               |             | 41.8            |     |                  | 17 Nov 2022 |                    |             |              |
|                  |                                                                                                           |               | MSC                                               |             |                 |     | O/C              |             |                    |             |              |
| Engine           |                                                                                                           |               |                                                   |             |                 |     |                  |             |                    |             |              |
| 727105           | No. 2 Engine - Bypass Duct Access Assembly - Repair Damage to Perforate Skin Using Filler (BRG3147)       |               | HRS                                               |             | 994.4           |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                           |               | ENC                                               |             | 392             |     |                  | 0           |                    | 0           |              |
|                  |                                                                                                           |               | MOS                                               |             | 41.9            |     |                  | 15 Nov 2022 |                    |             |              |
|                  |                                                                                                           |               | MSC                                               |             |                 |     | O/C              |             |                    |             |              |
| Engine           |                                                                                                           |               |                                                   |             |                 |     |                  |             |                    |             |              |
| 727106           | No. 1 Engine - Bypass Duct Assembly - Touch-Up Pressure Skin (Outer Surface) Surface Protection (BRG3146) |               | HRS                                               |             | 994.4           |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                           |               | ENC                                               |             | 392             |     |                  | 0           |                    | 0           |              |
|                  |                                                                                                           |               | MOS                                               |             | 41.8            |     |                  | 17 Nov 2022 |                    |             |              |
|                  |                                                                                                           |               | MSC                                               |             |                 |     | O/C              |             |                    |             |              |
| Engine           |                                                                                                           |               |                                                   |             |                 |     |                  |             |                    |             |              |
| 727106           | No. 2 Engine - Bypass Duct Assembly - Touch-Up Pressure Skin (Outer Surface) Surface Protection (BRG3146) |               | HRS                                               |             | 994.4           |     |                  | 0           |                    |             | 0            |
|                  |                                                                                                           |               | ENC                                               |             | 392             |     |                  | 0           |                    | 0           |              |
|                  |                                                                                                           |               | MOS                                               |             | 41.9            |     |                  | 15 Nov 2022 |                    |             |              |
|                  |                                                                                                           |               | MSC                                               |             |                 |     | O/C              |             |                    |             |              |
| Engine           |                                                                                                           |               |                                                   |             |                 |     |                  |             |                    |             |              |

| ATA<br>U=Custom  | Description                                                                              |                     | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------------------------------------------------------|---------------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                              | Serial Number       |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                                       | SW                  |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                                   |                     |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                                            |                     |     |             |                 |     |                  |             |                    |         |              |
| 727107           | No. 1 Engine - Bypass Duct - Replace Insert Carrier(S)<br>and Bushing(S) (BRG3186)       |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                          |                     | ENC |             | 392             |     |                  | 0           |                    | 0       |              |
|                  |                                                                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                                          |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                                   | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 727107           | No. 2 Engine - Bypass Duct - Replace Insert Carrier(S)<br>and Bushing(S) (BRG3186)       |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                          |                     | ENC |             | 392             |     |                  | 0           |                    | 0       |              |
|                  |                                                                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                                          |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                                   | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 729228           | No. 1 Engine - G650 Ring Bearing Outer Removal /<br>Installation<br>PN SN-UNKNOWN        |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                          |                     | ENC |             | 392             |     |                  | 0           |                    | 0       |              |
|                  |                                                                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                                          |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                                   | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 729228           | No. 2 Engine - G650 Ring Bearing Outer Removal /<br>Installation<br>PN SN-UNKNOWN        |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                          |                     | ENC |             | 392             |     |                  | 0           |                    | 0       |              |
|                  |                                                                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                                          |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                                   | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 729229           | No. 1 Engine - G650 Bearing Assy Intermediate Removal<br>/ Installation<br>PN SN-UNKNOWN |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                          |                     | ENC |             | 392             |     |                  | 0           |                    | 0       |              |
|                  |                                                                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                                          |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                                   | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 729229           | No. 2 Engine - G650 Bearing Assy Intermediate Removal<br>/ Installation<br>PN SN-UNKNOWN |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                          |                     | ENC |             | 392             |     |                  | 0           |                    | 0       |              |
|                  |                                                                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                                          |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                                   | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 729231           | No. 1 Engine - G650 Bearing 3/4Hp Thrust Assy Removal /<br>Installation<br>PN SN-UNKNOWN |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                          |                     | ENC |             | 392             |     |                  | 0           |                    | 0       |              |
|                  |                                                                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                                          |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                                   | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |



| ATA<br>U=Custom              | Description                                                          |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------------------|----------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                              | Part Number                                                          | Serial Number |                     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position             | HW                                                                   | SW            |                     |             |                 |     |                  |             |                     |         | Manufacturer |
|                              | MM Ref                                                               |               |                     |             |                 |     |                  |             |                     |         | Date Type    |
|                              | Ops Number(s)                                                        |               |                     |             |                 |     |                  |             |                     |         |              |
| 729231                       | No. 2 Engine - G650 Bearing 3/Hp Thrust Assy Removal / Installation  |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                              |                                                                      |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                              | PN                                                                   | SN-UNKNOWN    | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                              |                                                                      |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                              | Engine                                                               |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 729235                       | No. 1 Engine - G650 Bearing Assy of Removal / Installation           |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                              |                                                                      |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                              | PN                                                                   | SN-UNKNOWN    | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                              |                                                                      |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                              | Engine                                                               |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 729235                       | No. 2 Engine - G650 Bearing Assy of Removal / Installation           |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                              |                                                                      |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                              | PN                                                                   | SN-UNKNOWN    | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                              |                                                                      |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                              | Engine                                                               |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 729240                       | No. 1 Engine - G650 Nozzle Assy of Vortex Hpc Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                              |                                                                      |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                              | PN                                                                   | SN-UNKNOWN    | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                              |                                                                      |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                              | Engine                                                               |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 729240                       | No. 2 Engine - G650 Nozzle Assy of Vortex Hpc Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                              |                                                                      |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                              | PN                                                                   | SN-UNKNOWN    | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                              |                                                                      |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                              | Engine                                                               |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 729265                       | No. 1 Engine - G650 Ring Retainer Removal / Installation             |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                              |                                                                      |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                              | PN                                                                   | SN-UNKNOWN    | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                              |                                                                      |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                              | Engine                                                               |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 729265                       | No. 2 Engine - G650 Ring Retainer Removal / Installation             |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                              |                                                                      |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                              | PN                                                                   | SN-UNKNOWN    | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                              |                                                                      |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                              | Engine                                                               |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 73 - Engine Fuel and Control |                                                                      |               |                     |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom  | Description                                                                                             |                     | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|---------------------------------------------------------------------------------------------------------|---------------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                                             | Serial Number       |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                                                      | SW                  |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                                                  |                     |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                                                           |                     |     |             |                 |     |                  |             |                    |         |              |
| 730000           | No. 1 Engine - Engine Fuel and Control - Chapter 73                                                     |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                         |                     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                         |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                                                         |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                                                  | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 730000           | No. 2 Engine - Engine Fuel and Control - Chapter 73                                                     |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                         |                     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                         |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                                                         |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                                                  | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 731100           | No. 1 Engine - Fuel Pump - Removal / Installation<br>G3000FPU03                      SPX22-059          |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                         |                     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                         |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                                                         |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                                                  | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 731100           | No. 2 Engine - Fuel Pump - Removal / Installation<br>G3000FPU03                      SPX22-061          |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                         |                     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                         |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                                                         |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                                                  | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 731200           | No. 1 Engine - Lp Fuel Filter Element - Removal /<br>Installation<br>QA07865                      NSN   |                     | HRS |             | 327.2           |     |                  | 667.2       |                    |         | 0            |
|                  |                                                                                                         |                     | ENC |             | 128             |     |                  | 264         |                    |         | 0            |
|                  |                                                                                                         |                     | MOS |             | 9.9             |     |                  | 15 Jul 2025 |                    |         |              |
|                  |                                                                                                         |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                                                  | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 731200           | No. 2 Engine - Lp Fuel Filter Element - Removal /<br>Installation<br>QA07865                      NSN   |                     | HRS |             | 327.2           |     |                  | 667.2       |                    |         | 0            |
|                  |                                                                                                         |                     | ENC |             | 128             |     |                  | 264         |                    |         | 0            |
|                  |                                                                                                         |                     | MOS |             | 9.9             |     |                  | 15 Jul 2025 |                    |         |              |
|                  |                                                                                                         |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                                                  | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 731201           | No. 1 Engine - Hp Fuel Filter Element - Removal /<br>Installation<br>PN                      SN-UNKNOWN |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                         |                     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                         |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                                                         |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                                                  | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                    |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                                    | Serial Number |                     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                             | SW            |                     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                         |               |                     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                                  |               |                     |             |                 |     |                  |             |                     |         |              |
| 731201           | No. 2 Engine - Hp Fuel Filter Element - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | PN                                                             | SN-UNKNOWN    | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                         |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 731204           | No. 1 Engine - Hp Fuel Filter Housing - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | PN                                                             | SN-UNKNOWN    | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                         |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 731204           | No. 2 Engine - Hp Fuel Filter Housing - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | PN                                                             | SN-UNKNOWN    | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                         |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 731206           | No. 1 Engine - Lp Fuel Filter Element - Inspection             |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                                                |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                         |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 731206           | No. 2 Engine - Lp Fuel Filter Element - Inspection             |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                                                |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                         |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 731207           | No. 1 Engine - Hp Fuel Filter Element - Inspection             |               | HRS                 |             | 327.2           |     |                  | 667.2       |                     |         | 0            |
|                  |                                                                |               | ENC                 |             | 128             |     |                  | 264         |                     |         | 0            |
|                  |                                                                |               | MOS                 |             | 9.9             |     |                  | 15 Jul 2025 |                     |         |              |
|                  |                                                                |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                         |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 731207           | No. 2 Engine - Hp Fuel Filter Element - Inspection             |               | HRS                 |             | 327.2           |     |                  | 667.2       |                     |         | 0            |
|                  |                                                                |               | ENC                 |             | 128             |     |                  | 264         |                     |         | 0            |
|                  |                                                                |               | MOS                 |             | 9.9             |     |                  | 15 Jul 2025 |                     |         |              |
|                  |                                                                |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                         |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 731208           | No. 1 Engine - Hp Fuel Filter Element - Cleaning               |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                                                |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                         |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom  | Description                                                        |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due     | Avg Man Hrs  |  |
|------------------|--------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|--------------------|-------------|--------------|--|
|                  | Part Number                                                        | Serial Number |                     |             |                 |     |                  |             |                    |             | Approx Price |  |
| Logbook Position | HW                                                                 | SW            |                     |             |                 |     |                  |             |                    |             | Manufacturer |  |
|                  | MM Ref                                                             |               |                     |             |                 |     |                  |             |                    |             | Date Type    |  |
|                  | Ops Number(s)                                                      |               |                     |             |                 |     |                  |             |                    |             |              |  |
| 731208           | No. 2 Engine - Hp Fuel Filter Element - Cleaning                   |               | HRS                 |             | 994.4           |     |                  | 0           |                    |             | 0            |  |
|                  |                                                                    |               | ENC                 |             | 392             |     |                  | 0           |                    | 0           |              |  |
|                  |                                                                    |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |             |              |  |
|                  |                                                                    |               | MSC                 |             |                 |     | O/C              |             |                    |             |              |  |
| Engine           |                                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |             |              |  |
| 731209           | No. 1 Engine - Fuel Manifold and Pigtails - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                    |             | 0            |  |
|                  |                                                                    |               | ENC                 |             | 392             |     |                  | 0           |                    | 0           |              |  |
|                  |                                                                    |               | PN                  | SN-UNKNOWN  | MOS             |     | 41.8             |             |                    | 17 Nov 2022 |              |  |
|                  |                                                                    |               | MSC                 |             |                 |     | O/C              |             |                    |             |              |  |
| Engine           |                                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |             |              |  |
| 731209           | No. 2 Engine - Fuel Manifold and Pigtails - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                    |             | 0            |  |
|                  |                                                                    |               | ENC                 |             | 392             |     |                  | 0           |                    | 0           |              |  |
|                  |                                                                    |               | PN                  | SN-UNKNOWN  | MOS             |     | 41.9             |             |                    | 15 Nov 2022 |              |  |
|                  |                                                                    |               | MSC                 |             |                 |     | O/C              |             |                    |             |              |  |
| Engine           |                                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |             |              |  |
| 731211           | No. 1 Engine - Fuel Manifold and Pigtails - Inspection             |               | HRS                 |             | 994.4           |     |                  | 0           |                    |             | 0            |  |
|                  |                                                                    |               | ENC                 |             | 392             |     |                  | 0           |                    | 0           |              |  |
|                  |                                                                    |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |             |              |  |
|                  |                                                                    |               | MSC                 |             |                 |     | O/C              |             |                    |             |              |  |
| Engine           |                                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |             |              |  |
| 731211           | No. 2 Engine - Fuel Manifold and Pigtails - Inspection             |               | HRS                 |             | 994.4           |     |                  | 0           |                    |             | 0            |  |
|                  |                                                                    |               | ENC                 |             | 392             |     |                  | 0           |                    | 0           |              |  |
|                  |                                                                    |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |             |              |  |
|                  |                                                                    |               | MSC                 |             |                 |     | O/C              |             |                    |             |              |  |
| Engine           |                                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |             |              |  |
| 731212           | No. 1 Engine - Fuel Distribution Tubes and Fittings - Inspection   |               | HRS                 |             | 994.4           |     |                  | 0           |                    |             | 0            |  |
|                  |                                                                    |               | ENC                 |             | 392             |     |                  | 0           |                    | 0           |              |  |
|                  |                                                                    |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |             |              |  |
|                  |                                                                    |               | MSC                 |             |                 |     | O/C              |             |                    |             |              |  |
| Engine           |                                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |             |              |  |
| 731212           | No. 2 Engine - Fuel Distribution Tubes and Fittings - Inspection   |               | HRS                 |             | 994.4           |     |                  | 0           |                    |             | 0            |  |
|                  |                                                                    |               | ENC                 |             | 392             |     |                  | 0           |                    | 0           |              |  |
|                  |                                                                    |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |             |              |  |
|                  |                                                                    |               | MSC                 |             |                 |     | O/C              |             |                    |             |              |  |
| Engine           |                                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                    |             |              |  |

| ATA<br>U=Custom  | Description                                                       |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|----------|--------------------|---------|--------------|
|                  | Part Number                                                       | Serial Number |                     |             |                 |     |                  |          |                    |         | Approx Price |
| Logbook Position | HW                                                                | SW            |                     |             |                 |     |                  |          |                    |         | Manufacturer |
|                  | MM Ref                                                            |               |                     |             |                 |     |                  |          |                    |         | Date Type    |
|                  | Ops Number(s)                                                     |               |                     |             |                 |     |                  |          |                    |         |              |
| 731300           | No. 1 Engine - Fuel Spray Nozzle (No. 1) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0        |                    | 0       |              |
|                  |                                                                   |               | ENC                 |             | 392             |     |                  | 0        |                    | 0       |              |
|                  | 6080016E01                                                        | AH1829        | MOS                 |             | 41.8            |     | 17 Nov 2022      |          |                    |         |              |
|                  |                                                                   |               | MSC                 |             |                 |     | O/C              |          |                    |         |              |
|                  | Engine                                                            |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| 731300           | No. 2 Engine - Fuel Spray Nozzle (No. 1) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0        |                    | 0       |              |
|                  |                                                                   |               | ENC                 |             | 392             |     |                  | 0        |                    | 0       |              |
|                  | 6080016E01                                                        | AF9772        | MOS                 |             | 41.9            |     | 15 Nov 2022      |          |                    |         |              |
|                  |                                                                   |               | MSC                 |             |                 |     | O/C              |          |                    |         |              |
|                  | Engine                                                            |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| 731301           | No. 1 Engine - Fuel Spray Nozzle (No. 2) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0        |                    | 0       |              |
|                  |                                                                   |               | ENC                 |             | 392             |     |                  | 0        |                    | 0       |              |
|                  | 6080016E01                                                        | AH1830        | MOS                 |             | 41.8            |     | 17 Nov 2022      |          |                    |         |              |
|                  |                                                                   |               | MSC                 |             |                 |     | O/C              |          |                    |         |              |
|                  | Engine                                                            |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| 731301           | No. 2 Engine - Fuel Spray Nozzle (No. 2) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0        |                    | 0       |              |
|                  |                                                                   |               | ENC                 |             | 392             |     |                  | 0        |                    | 0       |              |
|                  | 6080016E01                                                        | AH1290        | MOS                 |             | 41.9            |     | 15 Nov 2022      |          |                    |         |              |
|                  |                                                                   |               | MSC                 |             |                 |     | O/C              |          |                    |         |              |
|                  | Engine                                                            |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| 731302           | No. 1 Engine - Fuel Spray Nozzle (No. 3) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0        |                    | 0       |              |
|                  |                                                                   |               | ENC                 |             | 392             |     |                  | 0        |                    | 0       |              |
|                  | 6080016E01                                                        | AH1831        | MOS                 |             | 41.8            |     | 17 Nov 2022      |          |                    |         |              |
|                  |                                                                   |               | MSC                 |             |                 |     | O/C              |          |                    |         |              |
|                  | Engine                                                            |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| 731302           | No. 2 Engine - Fuel Spray Nozzle (No. 3) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0        |                    | 0       |              |
|                  |                                                                   |               | ENC                 |             | 392             |     |                  | 0        |                    | 0       |              |
|                  | 6080016E01                                                        | AH1291        | MOS                 |             | 41.9            |     | 15 Nov 2022      |          |                    |         |              |
|                  |                                                                   |               | MSC                 |             |                 |     | O/C              |          |                    |         |              |
|                  | Engine                                                            |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| 731303           | No. 1 Engine - Fuel Spray Nozzle (No. 4) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0        |                    | 0       |              |
|                  |                                                                   |               | ENC                 |             | 392             |     |                  | 0        |                    | 0       |              |
|                  | 6080016E01                                                        | AH1832        | MOS                 |             | 41.8            |     | 17 Nov 2022      |          |                    |         |              |
|                  |                                                                   |               | MSC                 |             |                 |     | O/C              |          |                    |         |              |
|                  | Engine                                                            |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |

| ATA<br>U=Custom  | Description                                                       |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|-------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                                       | Serial Number |                     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                                | SW            |                     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                            |               |                     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                                     |               |                     |             |                 |     |                  |             |                     |         |              |
| 731303           | No. 2 Engine - Fuel Spray Nozzle (No. 4) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                   |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | 6080016E01                                                        | AH1292        | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                   |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                            |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 731304           | No. 1 Engine - Fuel Spray Nozzle (No. 5) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                   |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | 6080016E01                                                        | AH1833        | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                   |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                            |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 731304           | No. 2 Engine - Fuel Spray Nozzle (No. 5) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                   |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | 6080016E01                                                        | AH1293        | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                   |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                            |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 731305           | No. 1 Engine - Fuel Spray Nozzle (No. 6) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                   |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | 6080016E01                                                        | AH1834        | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                   |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                            |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 731305           | No. 2 Engine - Fuel Spray Nozzle (No. 6) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                   |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | 6080016E01                                                        | AH1294        | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                   |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                            |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 731306           | No. 1 Engine - Fuel Spray Nozzle (No. 7) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                   |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | 6080016E01                                                        | AH1835        | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                   |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                            |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 731306           | No. 2 Engine - Fuel Spray Nozzle (No. 7) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                   |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | 6080016E01                                                        | AH1295        | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                   |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                            |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom  | Description                                                        |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|--------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                        | Serial Number |                     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                 | SW            |                     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                             |               |                     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                      |               |                     |             |                 |     |                  |             |                    |         |              |
| 731307           | No. 1 Engine - Fuel Spray Nozzle (No. 8) - Removal / Installation  |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                    |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | 6080016E01                                                         | AH1836        | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                    |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                             |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 731307           | No. 2 Engine - Fuel Spray Nozzle (No. 8) - Removal / Installation  |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                    |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | 6080016E01                                                         | AH1296        | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                    |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                             |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 731308           | No. 1 Engine - Fuel Spray Nozzle (No. 9) - Removal / Installation  |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                    |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | 6080016E01                                                         | AH1837        | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                    |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                             |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 731308           | No. 2 Engine - Fuel Spray Nozzle (No. 9) - Removal / Installation  |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                    |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | 6080016E01                                                         | AH1297        | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                    |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                             |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 731309           | No. 1 Engine - Fuel Spray Nozzle (No. 10) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                    |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | 6080016E01                                                         | AH1838        | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                    |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                             |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 731309           | No. 2 Engine - Fuel Spray Nozzle (No. 10) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                    |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | 6080016E01                                                         | AH1298        | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                    |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                             |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 731310           | No. 1 Engine - Fuel Spray Nozzle (No. 11) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                    |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | 6080016E01                                                         | AH1839        | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                    |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                             |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                        |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|--------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                                        | Serial Number |                     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                                 | SW            |                     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                             |               |                     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                                      |               |                     |             |                 |     |                  |             |                     |         |              |
| 731310           | No. 2 Engine - Fuel Spray Nozzle (No. 11) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                    |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | 6080016E01                                                         | AH1299        | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                    |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                             |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 731311           | No. 1 Engine - Fuel Spray Nozzle (No. 12) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                    |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | 6080016E01                                                         | AH1840        | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                    |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                             |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 731311           | No. 2 Engine - Fuel Spray Nozzle (No. 12) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                    |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | 6080016E01                                                         | AH12300       | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                    |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                             |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 731312           | No. 1 Engine - Fuel Spray Nozzle (No. 13) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                    |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | 6080016E01                                                         | AH1841        | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                    |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                             |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 731312           | No. 2 Engine - Fuel Spray Nozzle (No. 13) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                    |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | 6080016E01                                                         | AH12301       | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                    |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                             |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 731313           | No. 1 Engine - Fuel Spray Nozzle (No. 14) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                    |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | 6080016E01                                                         | AH1842        | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                    |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                             |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 731313           | No. 2 Engine - Fuel Spray Nozzle (No. 14) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                    |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | 6080016E01                                                         | AH12302       | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                    |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                             |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |



| ATA<br>U=Custom  | Description                                                        |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|--------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                                        | Serial Number |                     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                                 | SW            |                     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                             |               |                     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                                      |               |                     |             |                 |     |                  |             |                     |         |              |
| 731314           | No. 1 Engine - Fuel Spray Nozzle (No. 15) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                    |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | 6080016E01                                                         | AH1843        | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                    |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                             |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 731314           | No. 2 Engine - Fuel Spray Nozzle (No. 15) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                    |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | 6080016E01                                                         | AH12303       | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                    |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                             |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 731315           | No. 1 Engine - Fuel Spray Nozzle (No. 16) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                    |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | 6080016E01                                                         | AH1844        | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                    |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                             |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 731315           | No. 2 Engine - Fuel Spray Nozzle (No. 16) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                    |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | 6080016E01                                                         | AH12304       | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                    |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                             |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 731316           | No. 1 Engine - Fuel Spray Nozzle (No. 17) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                    |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | 6080016E01                                                         | AH1845        | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                    |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                             |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 731316           | No. 2 Engine - Fuel Spray Nozzle (No. 17) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                    |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | 6080016E01                                                         | AH12305       | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                    |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                             |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 731317           | No. 1 Engine - Fuel Spray Nozzle (No. 18) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                    |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | 6080016E01                                                         | AH1846        | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                    |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                             |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom  | Description                                                                             |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-----------------------------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                             | Serial Number |                     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                                      | SW            |                     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                                  |               |                     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                                           |               |                     |             |                 |     |                  |             |                    |         |              |
| 731317           | No. 2 Engine - Fuel Spray Nozzle (No. 18) - Removal / Installation                      |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                         |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | 6080016E01                                                                              | AH12306       | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                                         |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                                  |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 731318           | No. 1 Engine - Fuel Spray Nozzle (No. 19) - Removal / Installation                      |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                         |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | 6080016E01                                                                              | AH1847        | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                                         |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                                  |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 731318           | No. 2 Engine - Fuel Spray Nozzle (No. 19) - Removal / Installation                      |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                         |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | 6080016E01                                                                              | AH12307       | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                                         |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                                  |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 731319           | No. 1 Engine - Fuel Spray Nozzle (No. 20) - Removal / Installation                      |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                         |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | 6080016E01                                                                              | AH1848        | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                                         |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                                  |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 731319           | No. 2 Engine - Fuel Spray Nozzle (No. 20) - Removal / Installation                      |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                         |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | 6080016E01                                                                              | AH12308       | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                                         |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                                  |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 731340           | No. 1 Engine - Lp Turbine Overspeed and Manifold Splitter Unit - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                         |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | 1014205-2                                                                               | F87187        | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                                         |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                                  |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 731340           | No. 2 Engine - Lp Turbine Overspeed and Manifold Splitter Unit - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                         |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | 1014205-2                                                                               | F87205        | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                                         |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                                  |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                              |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                              | Serial Number |                     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                       | SW            |                     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                   |               |                     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                            |               |                     |             |                 |     |                  |             |                     |         |              |
| 732000           | No. 1 Engine - Left Engine Electronic Control Attaching  |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | Parts and Fittings - Removal / Installation              |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | PN                                                       | SN-UNKNOWN    | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                          |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                   |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 732000           | No. 2 Engine - Left Engine Electronic Control Attaching  |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | Parts and Fittings - Removal / Installation              |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | PN                                                       | SN-UNKNOWN    | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                          |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                   |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 732001           | No. 1 Engine - Right Engine Electronic Control Attaching |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | Parts and Fittings - Removal / Installation              |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | PN                                                       | SN-UNKNOWN    | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                          |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                   |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 732001           | No. 2 Engine - Right Engine Electronic Control Attaching |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | Parts and Fittings - Removal / Installation              |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | PN                                                       | SN-UNKNOWN    | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                          |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                   |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 732100           | No. 1 Engine - Permanent Magnetic Alternator Rotor -     |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | Removal / Installation                                   |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | G3000DGR01                                               | 2384          | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                          |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                   |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 732100           | No. 2 Engine - Permanent Magnetic Alternator Rotor -     |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | Removal / Installation                                   |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | G3000DGR01                                               | 2374          | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                          |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                   |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 732102           | No. 1 Engine - Permanent Magnetic Alternator Stator -    |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | Removal / Installation                                   |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | G3000DGS02                                               | 1939          | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                          |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                   |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom  | Description                                                                  |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                                                  | Serial Number |                     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                                           | SW            |                     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                                       |               |                     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                                                |               |                     |             |                 |     |                  |             |                     |         |              |
| 732102           | No. 2 Engine - Permanent Magnetic Alternator Stator - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                              |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | G3000DGS02                                                                   | 1943          | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                              |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                       |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 732104           | No. 1 Engine - T30 Thermocouple (Right) - Removal / Installation             |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                              |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | PN                                                                           | SN-UNKNOWN    | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                              |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                       |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 732104           | No. 2 Engine - T30 Thermocouple (Right) - Removal / Installation             |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                              |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | PN                                                                           | SN-UNKNOWN    | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                              |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                       |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 732105           | No. 1 Engine - T30 Thermocouple (Left) - Removal / Installation              |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                              |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | PN                                                                           | SN-UNKNOWN    | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                              |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                       |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 732105           | No. 2 Engine - T30 Thermocouple (Left) - Removal / Installation              |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                              |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | PN                                                                           | SN-UNKNOWN    | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                              |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                       |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 732108           | No. 1 Engine - Fuel Metering Unit - Removal / Installation                   |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | G3000FMU04                                                                   | SFX22-059     | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                                                              |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                              |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                       |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 732108           | No. 2 Engine - Fuel Metering Unit - Removal / Installation                   |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | G3000FMU04                                                                   | SFX22-057     | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                                                              |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                              |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                       |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom  | Description                                              |                     | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(* =Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------------|---------------------|-----|-------------|-----------------|-----|------------------|-------------|----------------------|---------|--------------|
|                  | Part Number                                              | Serial Number       |     |             |                 |     |                  |             |                      |         | Approx Price |
| Logbook Position | HW                                                       | SW                  |     |             |                 |     |                  |             |                      |         | Manufacturer |
|                  | MM Ref                                                   |                     |     |             |                 |     |                  |             |                      |         | Date Type    |
|                  | Ops Number(s)                                            |                     |     |             |                 |     |                  |             |                      |         |              |
| 732110           | No. 1 Engine - Data Entry Plug - Removal / Installation  |                     | HRS |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                  | G3000DEP01                                               | 00001218            | ENC |             | 392             |     |                  | 0           |                      |         | 0            |
|                  |                                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                      |         |              |
|                  | Engine                                                   |                     | MSC |             |                 |     | O/C              |             |                      |         |              |
|                  |                                                          | [End Of Month Item] |     |             |                 |     |                  |             |                      |         |              |
| 732110           | No. 2 Engine - Data Entry Plug - Removal / Installation  |                     | HRS |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                  | G3000DEP01                                               | 00001223            | ENC |             | 392             |     |                  | 0           |                      |         | 0            |
|                  |                                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                      |         |              |
|                  | Engine                                                   |                     | MSC |             |                 |     | O/C              |             |                      |         |              |
|                  |                                                          | [End Of Month Item] |     |             |                 |     |                  |             |                      |         |              |
| 732112           | No. 1 Engine - Data Entry Plug Program Trims Using       |                     | HRS |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                  | External Loader - Adjustment / Test                      |                     | ENC |             | 392             |     |                  | 0           |                      |         | 0            |
|                  |                                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                      |         |              |
|                  | Engine                                                   |                     | MSC |             |                 |     | O/C              |             |                      |         |              |
|                  |                                                          | [End Of Month Item] |     |             |                 |     |                  |             |                      |         |              |
| 732112           | No. 2 Engine - Data Entry Plug Program Trims Using       |                     | HRS |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                  | External Loader - Adjustment / Test                      |                     | ENC |             | 392             |     |                  | 0           |                      |         | 0            |
|                  |                                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                      |         |              |
|                  | Engine                                                   |                     | MSC |             |                 |     | O/C              |             |                      |         |              |
|                  |                                                          | [End Of Month Item] |     |             |                 |     |                  |             |                      |         |              |
| 732113           | No. 1 Engine - Engine Electronic Controller (Eec) - Life |                     | HRS |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                  | Limit                                                    |                     | ENC |             | 392             |     |                  | 0           |                      |         | 0            |
|                  | PN                                                       | SN-UNKNOWN          | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                      |         |              |
|                  | Engine                                                   |                     | MSC |             |                 |     | O/C              |             |                      |         |              |
|                  |                                                          | [End Of Month Item] |     |             |                 |     |                  |             |                      |         |              |
| 732113           | No. 2 Engine - Engine Electronic Controller (Eec) - Life |                     | HRS |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                  | Limit                                                    |                     | ENC |             | 392             |     |                  | 0           |                      |         | 0            |
|                  | PN                                                       | SN-UNKNOWN          | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                      |         |              |
|                  | Engine                                                   |                     | MSC |             |                 |     | O/C              |             |                      |         |              |
|                  |                                                          | [End Of Month Item] |     |             |                 |     |                  |             |                      |         |              |
| 732114           | No. 1 Engine - Eec - Removal / Installation              |                     | HRS |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                  | G3010ECU01BC                                             | BX261155            | ENC |             | 392             |     |                  | 0           |                      |         | 0            |
|                  |                                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                      |         |              |
|                  | Engine                                                   |                     | MSC |             |                 |     | O/C              |             |                      |         |              |
|                  |                                                          | [End Of Month Item] |     |             |                 |     |                  |             |                      |         |              |

| ATA<br>U=Custom  | Description                                                              |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|--------------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                              | Serial Number |                     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                       | SW            |                     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                   |               |                     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                            |               |                     |             |                 |     |                  |             |                    |         |              |
| 732114           | No. 2 Engine - Eec - Removal / Installation                              |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | G3010ECU01BC BX261163                                                    |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                                          |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                          |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                   |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 732116           | No. 1 Engine - Fuel Metering Unit Support Plate - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                          |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | PN SN-UNKNOWN                                                            |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                          |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                   |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 732116           | No. 2 Engine - Fuel Metering Unit Support Plate - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                          |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | PN SN-UNKNOWN                                                            |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                          |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                   |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 732118           | No. 1 Engine - Fuel System AIR Tubes and Fittings - Inspection           |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                          |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                                          |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                          |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                   |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 732118           | No. 2 Engine - Fuel System AIR Tubes and Fittings - Inspection           |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                          |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                                          |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                          |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                   |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 732119           | No. 1 Engine - T30 Thermocouple Blocks - Removal / Installation          |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                          |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | PN SN-UNKNOWN                                                            |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                          |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                   |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 732119           | No. 2 Engine - T30 Thermocouple Blocks - Removal / Installation          |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                          |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | PN SN-UNKNOWN                                                            |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                          |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                   |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                            |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|--------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                            | Serial Number |                     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                     | SW            |                     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                 |               |                     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                          |               |                     |             |                 |     |                  |             |                    |         |              |
| 732121           | No. 1 Engine - Fuel Metering Unit (Fmu) - Life Limit   |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | G3000FMU04                                             |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                        |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                        |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                 |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 732121           | No. 2 Engine - Fuel Metering Unit (Fmu) - Life Limit   |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | G3000FMU04                                             |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                        |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                        |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                 |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 733100           | No. 1 Engine - Fuel Flow Transmitter - Removal /       |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | Installation                                           |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | 9-217-49                                               | 170436-3632   | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                        |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                 |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 733100           | No. 2 Engine - Fuel Flow Transmitter - Removal /       |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | Installation                                           |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | 9-217-49                                               | 170436-03718  | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                        |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                 |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 733200           | No. 1 Engine - Fuel Temperature Transducer (Channel A  |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | and B) - Removal / Installation                        |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | PN                                                     | SN-UNKNOWN    | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                        |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                 |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 733200           | No. 2 Engine - Fuel Temperature Transducer (Channel A  |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | and B) - Removal / Installation                        |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | PN                                                     | SN-UNKNOWN    | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                        |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                 |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 733201           | No. 1 Engine - Fuel Temperature Transducer (Channel B) |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | - Removal / Installation                               |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | PN                                                     | SN-UNKNOWN    | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                        |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                 |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                                | Serial Number |                     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                         | SW            |                     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                     |               |                     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                              |               |                     |             |                 |     |                  |             |                     |         |              |
| 733201           | No. 2 Engine - Fuel Temperature Transducer (Channel B)     |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | - Removal / Installation                                   |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | PN                                                         | SN-UNKNOWN    | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                            |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                     |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 733300           | No. 1 Engine - Low Fuel Pressure Switch - Removal /        |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | Installation                                               |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | 8H0134-1G                                                  | 2318          | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                            |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                     |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 733300           | No. 2 Engine - Low Fuel Pressure Switch - Removal /        |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | Installation                                               |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | 8H0134-1G                                                  | 2324          | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                            |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                     |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 733302           | No. 1 Engine - Fuel Differential Lp Transducer - Removal / |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | Installation                                               |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | PN                                                         | SN-UNKNOWN    | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                            |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                     |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 733302           | No. 2 Engine - Fuel Differential Lp Transducer - Removal / |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | Installation                                               |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | PN                                                         | SN-UNKNOWN    | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                            |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                     |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 733500           | No. 1 Engine - Fuel Return to Tank Differential Pressure   |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | Transducer - Removal / Installation                        |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | PN                                                         | SN-UNKNOWN    | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                            |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                     |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 733500           | No. 2 Engine - Fuel Return to Tank Differential Pressure   |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | Transducer - Removal / Installation                        |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | PN                                                         | SN-UNKNOWN    | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                            |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                     |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 74 - Ignition    |                                                            |               |                     |             |                 |     |                  |             |                     |         |              |



| ATA<br>U=Custom  | Description                                                               |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|---------------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                                               | Serial Number |                     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                                        | SW            |                     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                                    |               |                     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                                             |               |                     |             |                 |     |                  |             |                     |         |              |
| 741000           | No. 1 Engine - High Energy Ignition Unit (No. 1) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                           |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | HE3392                                                                    | 02884         | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                           |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 741000           | No. 2 Engine - High Energy Ignition Unit (No. 1) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                           |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | HE3392                                                                    | 02879         | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                           |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 741001           | No. 1 Engine - High Energy Ignition Unit (No. 2) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                           |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | HE3392                                                                    | 02887         | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                           |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 741001           | No. 2 Engine - High Energy Ignition Unit (No. 2) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                           |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | HE3392                                                                    | 02881         | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                           |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 742000           | No. 1 Engine - Igniter Plug (No. 1) - Removal / Installation              |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | CH34760-2                                                                 |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | 22044962                                                                  |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                           |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 742000           | No. 2 Engine - Igniter Plug (No. 1) - Removal / Installation              |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | CH34760-2                                                                 |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | 22031294                                                                  |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                           |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 742001           | No. 1 Engine - Igniter Plug (No. 2) - Removal / Installation              |               | HRS                 | TSN:330.7   | 663.7           |     |                  | 330.7       |                     |         | 0            |
|                  | CH34760-2                                                                 |               | ENC                 | TSN:101     | 291             |     |                  | 101         |                     |         | 0            |
|                  | 22044974                                                                  |               | MOS                 | TSN:16      | 25.5            |     |                  | 28 Mar 2024 |                     |         |              |
|                  |                                                                           |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom  | Description                                                  |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|--------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                  | Serial Number |                     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                           | SW            |                     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                       |               |                     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                |               |                     |             |                 |     |                  |             |                    |         |              |
| 742001           | No. 2 Engine - Igniter Plug (No. 2) - Removal / Installation |               | HRS                 | TSN:330.7   | 663.7           |     |                  | 330.7       |                    |         | 0            |
|                  | CH34760-2                                                    | 22044979      | ENC                 | TSN:101     | 291             |     |                  | 101         |                    |         | 0            |
|                  |                                                              |               | MOS                 | TSN:16      | 25.5            |     |                  | 28 Mar 2024 |                    |         |              |
|                  | Engine                                                       |               | MSC                 |             |                 |     |                  | O/C         |                    |         |              |
|                  |                                                              |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 742004           | No. 1 Engine - Igniter Plug (No.1) - Discard                 |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | CH34760-2                                                    | 22044962      | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                              |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                                       |               | MSC                 |             |                 |     |                  | O/C         |                    |         |              |
|                  |                                                              |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 742004           | No. 2 Engine - Igniter Plug (No.1) - Discard                 |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | CH34760-2                                                    | 22031294      | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                              |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                                       |               | MSC                 |             |                 |     |                  | O/C         |                    |         |              |
|                  |                                                              |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 742005           | No. 1 Engine - Igniter Plug (No.2) - Discard                 |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | CH34760-2                                                    | 22044974      | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                              |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                                       |               | MSC                 |             |                 |     |                  | O/C         |                    |         |              |
|                  |                                                              |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 742005           | No. 2 Engine - Igniter Plug (No.2) - Discard                 |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | CH34760-2                                                    | 22044979      | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                              |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                                       |               | MSC                 |             |                 |     |                  | O/C         |                    |         |              |
|                  |                                                              |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 742006           | No. 1 Engine - Igniter Plug (No. 1) - Inspection             |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                              |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                              |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                                       |               | MSC                 |             |                 |     |                  | O/C         |                    |         |              |
|                  |                                                              |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 742006           | No. 2 Engine - Igniter Plug (No. 1) - Inspection             |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                              |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                              |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                                       |               | MSC                 |             |                 |     |                  | O/C         |                    |         |              |
|                  |                                                              |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 742007           | No. 1 Engine - Igniter Plug (No. 2) - Inspection             |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                              |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                              |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                                       |               | MSC                 |             |                 |     |                  | O/C         |                    |         |              |
|                  |                                                              |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                          |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                                          | Serial Number |                     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                                   | SW            |                     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                               |               |                     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                                        |               |                     |             |                 |     |                  |             |                     |         |              |
| 742007           | No. 2 Engine - Igniter Plug (No. 2) - Inspection                     |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                      |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                                                      |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  | Engine                                                               |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  |                                                                      |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 742008           | No. 1 Engine - Ignition Lead (No. 1) - Removal / Installation        |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                      |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | CLB3032                                                              | 02318         | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  | Engine                                                               |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  |                                                                      |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 742008           | No. 2 Engine - Ignition Lead (No. 1) - Removal / Installation        |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                      |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | CLB3032                                                              | 02288         | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  | Engine                                                               |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  |                                                                      |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 742009           | No. 1 Engine - Ignition Lead (No. 2) - Removal / Installation        |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                      |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | CLB3032                                                              | 02386         | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  | Engine                                                               |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  |                                                                      |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 742009           | No. 2 Engine - Ignition Lead (No. 2) - Removal / Installation        |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                      |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | CLB3032                                                              | 02431         | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  | Engine                                                               |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  |                                                                      |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 742012           | No. 1 Engine - Igniter Plug Adapter (No. 1) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                      |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | PN                                                                   | SN-UNKNOWN    | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  | Engine                                                               |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  |                                                                      |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 742012           | No. 2 Engine - Igniter Plug Adapter (No. 1) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                      |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | PN                                                                   | SN-UNKNOWN    | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  | Engine                                                               |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  |                                                                      |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom  | Description                                                                    |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|--------------------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                                                    | Serial Number |                     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                                             | SW            |                     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                                         |               |                     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                                                  |               |                     |             |                 |     |                  |             |                     |         |              |
| 742013           | No. 1 Engine - Igniter Plug Adapter (No. 2) - Removal / Installation           |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                                |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | PN                                                                             | SN-UNKNOWN    | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                                |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                         |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 742013           | No. 2 Engine - Igniter Plug Adapter (No. 2) - Removal / Installation           |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                                |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | PN                                                                             | SN-UNKNOWN    | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                                |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                         |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 742016           | No. 1 Engine - Ignition Lead Ceramic Insulator (No.1) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                                |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | PN                                                                             | SN-UNKNOWN    | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                                |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                         |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 742016           | No. 2 Engine - Ignition Lead Ceramic Insulator (No.1) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                                |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | PN                                                                             | SN-UNKNOWN    | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                                |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                         |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 742017           | No. 1 Engine - Ignition Lead Ceramic Insulator (No.2) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                                |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | PN                                                                             | SN-UNKNOWN    | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                                |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                         |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 742017           | No. 2 Engine - Ignition Lead Ceramic Insulator (No.2) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                                |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | PN                                                                             | SN-UNKNOWN    | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                                |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                         |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 742018           | No. 1 Engine - Ignition Lead Ceramic Insulator (No. 1) - Repair                |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                                |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                                                                |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                                |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                         |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom  | Description                                                                                 |                     | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(* =Adj) | Max Due | Avg Man Hrs  |
|------------------|---------------------------------------------------------------------------------------------|---------------------|-----|-------------|-----------------|-----|------------------|-------------|----------------------|---------|--------------|
|                  | Part Number                                                                                 | Serial Number       |     |             |                 |     |                  |             |                      |         | Approx Price |
| Logbook Position | HW                                                                                          | SW                  |     |             |                 |     |                  |             |                      |         | Manufacturer |
|                  | MM Ref                                                                                      |                     |     |             |                 |     |                  |             |                      |         | Date Type    |
|                  | Ops Number(s)                                                                               |                     |     |             |                 |     |                  |             |                      |         |              |
| 742018           | No. 2 Engine - Ignition Lead Ceramic Insulator (No. 1) - Repair                             |                     | HRS |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                  |                                                                                             |                     | ENC |             | 392             |     |                  | 0           |                      | 0       |              |
|                  |                                                                                             |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                      |         |              |
|                  |                                                                                             |                     | MSC |             |                 |     | O/C              |             |                      |         |              |
|                  | Engine                                                                                      | [End Of Month Item] |     |             |                 |     |                  |             |                      |         |              |
| 742019           | No. 1 Engine - Ignition Lead Ceramic Insulator (No. 2) - Repair                             |                     | HRS |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                  |                                                                                             |                     | ENC |             | 392             |     |                  | 0           |                      | 0       |              |
|                  |                                                                                             |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                      |         |              |
|                  |                                                                                             |                     | MSC |             |                 |     | O/C              |             |                      |         |              |
|                  | Engine                                                                                      | [End Of Month Item] |     |             |                 |     |                  |             |                      |         |              |
| 742019           | No. 2 Engine - Ignition Lead Ceramic Insulator (No. 2) - Repair                             |                     | HRS |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                  |                                                                                             |                     | ENC |             | 392             |     |                  | 0           |                      | 0       |              |
|                  |                                                                                             |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                      |         |              |
|                  |                                                                                             |                     | MSC |             |                 |     | O/C              |             |                      |         |              |
|                  | Engine                                                                                      | [End Of Month Item] |     |             |                 |     |                  |             |                      |         |              |
| 742020           | No. 1 Engine - Ignition Lead End Contactor (No.1) - Removal / Installation<br>PN SN-UNKNOWN |                     | HRS |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                  |                                                                                             |                     | ENC |             | 392             |     |                  | 0           |                      | 0       |              |
|                  |                                                                                             |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                      |         |              |
|                  |                                                                                             |                     | MSC |             |                 |     | O/C              |             |                      |         |              |
|                  | Engine                                                                                      | [End Of Month Item] |     |             |                 |     |                  |             |                      |         |              |
| 742020           | No. 2 Engine - Ignition Lead End Contactor (No.1) - Removal / Installation<br>PN SN-UNKNOWN |                     | HRS |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                  |                                                                                             |                     | ENC |             | 392             |     |                  | 0           |                      | 0       |              |
|                  |                                                                                             |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                      |         |              |
|                  |                                                                                             |                     | MSC |             |                 |     | O/C              |             |                      |         |              |
|                  | Engine                                                                                      | [End Of Month Item] |     |             |                 |     |                  |             |                      |         |              |
| 742021           | No. 1 Engine - Ignition Lead End Contactor (No.2) - Removal / Installation<br>PN SN-UNKNOWN |                     | HRS |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                  |                                                                                             |                     | ENC |             | 392             |     |                  | 0           |                      | 0       |              |
|                  |                                                                                             |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                      |         |              |
|                  |                                                                                             |                     | MSC |             |                 |     | O/C              |             |                      |         |              |
|                  | Engine                                                                                      | [End Of Month Item] |     |             |                 |     |                  |             |                      |         |              |
| 742021           | No. 2 Engine - Ignition Lead End Contactor (No.2) - Removal / Installation<br>PN SN-UNKNOWN |                     | HRS |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                  |                                                                                             |                     | ENC |             | 392             |     |                  | 0           |                      | 0       |              |
|                  |                                                                                             |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                      |         |              |
|                  |                                                                                             |                     | MSC |             |                 |     | O/C              |             |                      |         |              |
|                  | Engine                                                                                      | [End Of Month Item] |     |             |                 |     |                  |             |                      |         |              |

| ATA<br>U=Custom  | Description                                                      |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                      | Serial Number |                     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                               | SW            |                     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                           |               |                     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                    |               |                     |             |                 |     |                  |             |                    |         |              |
| 742022           | No. 1 Engine - Ignition Lead End Contactor (No. 1) - Replacement |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                  |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | PN                                                               | SN-UNKNOWN    | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                  |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                           |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 742022           | No. 2 Engine - Ignition Lead End Contactor (No. 1) - Replacement |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                  |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | PN                                                               | SN-UNKNOWN    | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                  |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                           |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 742023           | No. 1 Engine - Ignition Lead End Contactor (No. 2) - Replacement |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                  |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | PN                                                               | SN-UNKNOWN    | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                  |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                           |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 742023           | No. 2 Engine - Ignition Lead End Contactor (No. 2) - Replacement |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                  |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | PN                                                               | SN-UNKNOWN    | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                  |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                           |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 742026           | No. 1 Engine - Ignition Lead (No. 1) - Inspection                |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                  |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                                  |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                  |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                           |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 742026           | No. 2 Engine - Ignition Lead (No. 1) - Inspection                |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                  |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                                  |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                  |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                           |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 742027           | No. 1 Engine - Ignition Lead (No. 2) - Inspection                |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                  |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                                  |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                  |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                           |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                              |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|----------|--------------------|---------|--------------|
|                  | Part Number                                              | Serial Number |                     |             |                 |     |                  |          |                    |         | Approx Price |
| Logbook Position | HW                                                       | SW            |                     |             |                 |     |                  |          |                    |         | Manufacturer |
|                  | MM Ref                                                   |               |                     |             |                 |     |                  |          |                    |         | Date Type    |
|                  | Ops Number(s)                                            |               |                     |             |                 |     |                  |          |                    |         |              |
| 742027           | No. 2 Engine - Ignition Lead (No. 2) - Inspection        |               | HRS                 |             | 994.4           |     |                  | 0        |                    |         | 0            |
|                  |                                                          |               | ENC                 |             | 392             |     |                  | 0        |                    | 0       |              |
|                  |                                                          |               | MOS                 |             | 41.9            |     | 15 Nov 2022      |          |                    |         |              |
|                  |                                                          |               | MSC                 |             |                 | O/C |                  |          |                    |         |              |
|                  |                                                          |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| 742028           | No. 1 Engine - Ignition System - Operational Check       |               | HRS                 |             | 994.4           |     |                  | 0        |                    |         | 0            |
|                  |                                                          |               | ENC                 |             | 392             |     |                  | 0        |                    | 0       |              |
|                  |                                                          |               | MOS                 |             | 41.8            |     | 17 Nov 2022      |          |                    |         |              |
|                  |                                                          |               | MSC                 |             |                 | O/C |                  |          |                    |         |              |
|                  |                                                          |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| 742028           | No. 2 Engine - Ignition System - Operational Check       |               | HRS                 |             | 994.4           |     |                  | 0        |                    |         | 0            |
|                  |                                                          |               | ENC                 |             | 392             |     |                  | 0        |                    | 0       |              |
|                  |                                                          |               | MOS                 |             | 41.9            |     | 15 Nov 2022      |          |                    |         |              |
|                  |                                                          |               | MSC                 |             |                 | O/C |                  |          |                    |         |              |
|                  |                                                          |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| 742029           | No. 1 Engine - Igniter Plug (No. 1) - Cleaning           |               | HRS                 |             | 994.4           |     |                  | 0        |                    |         | 0            |
|                  |                                                          |               | ENC                 |             | 392             |     |                  | 0        |                    | 0       |              |
|                  |                                                          |               | MOS                 |             | 41.8            |     | 17 Nov 2022      |          |                    |         |              |
|                  |                                                          |               | MSC                 |             |                 | O/C |                  |          |                    |         |              |
|                  |                                                          |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| 742029           | No. 2 Engine - Igniter Plug (No. 1) - Cleaning           |               | HRS                 |             | 994.4           |     |                  | 0        |                    |         | 0            |
|                  |                                                          |               | ENC                 |             | 392             |     |                  | 0        |                    | 0       |              |
|                  |                                                          |               | MOS                 |             | 41.9            |     | 15 Nov 2022      |          |                    |         |              |
|                  |                                                          |               | MSC                 |             |                 | O/C |                  |          |                    |         |              |
|                  |                                                          |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| 742030           | No. 1 Engine - Igniter Plug (No. 2) - Cleaning           |               | HRS                 |             | 994.4           |     |                  | 0        |                    |         | 0            |
|                  |                                                          |               | ENC                 |             | 392             |     |                  | 0        |                    | 0       |              |
|                  |                                                          |               | MOS                 |             | 41.8            |     | 17 Nov 2022      |          |                    |         |              |
|                  |                                                          |               | MSC                 |             |                 | O/C |                  |          |                    |         |              |
|                  |                                                          |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| 742030           | No. 2 Engine - Igniter Plug (No. 2) - Cleaning           |               | HRS                 |             | 994.4           |     |                  | 0        |                    |         | 0            |
|                  |                                                          |               | ENC                 |             | 392             |     |                  | 0        |                    | 0       |              |
|                  |                                                          |               | MOS                 |             | 41.9            |     | 15 Nov 2022      |          |                    |         |              |
|                  |                                                          |               | MSC                 |             |                 | O/C |                  |          |                    |         |              |
|                  |                                                          |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| 742031           | No. 1 Engine - Ignition Lead Core Cable (No. 1) - Repair |               | HRS                 |             | 994.4           |     |                  | 0        |                    |         | 0            |
|                  |                                                          |               | ENC                 |             | 392             |     |                  | 0        |                    | 0       |              |
|                  |                                                          |               | MOS                 |             | 41.8            |     | 17 Nov 2022      |          |                    |         |              |
|                  |                                                          |               | MSC                 |             |                 | O/C |                  |          |                    |         |              |
|                  |                                                          |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |

| ATA<br>U=Custom  | Description                                                   |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|---------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                   | Serial Number |                     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                            | SW            |                     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                        |               |                     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                 |               |                     |             |                 |     |                  |             |                    |         |              |
| 742031           | No. 2 Engine - Ignition Lead Core Cable (No. 1) - Repair      |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                               |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                               |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                               |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  |                                                               |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 742032           | No. 1 Engine - Ignition Lead Core Cable (No. 2) - Repair      |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                               |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                               |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                               |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  |                                                               |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 742032           | No. 2 Engine - Ignition Lead Core Cable (No. 2) - Repair      |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                               |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                               |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                               |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  |                                                               |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 742033           | No. 1 Engine - Ignition Lead Spiral Lock Nut (No. 1) - Repair |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                               |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                               |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                               |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  |                                                               |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 742033           | No. 2 Engine - Ignition Lead Spiral Lock Nut (No. 1) - Repair |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                               |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                               |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                               |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  |                                                               |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 742034           | No. 1 Engine - Ignition Lead Spiral Lock Nut (No. 2) - Repair |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                               |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                               |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                               |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  |                                                               |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 742034           | No. 2 Engine - Ignition Lead Spiral Lock Nut (No. 2) - Repair |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                               |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                               |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                               |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  |                                                               |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 75 - AIR         |                                                               |               |                     |             |                 |     |                  |             |                    |         |              |



| ATA<br>U=Custom  | Description                                              |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                              | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                       | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                   |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                            |               |     |             |                 |     |                  |             |                    |         |              |
| 752200           | No. 1 Engine - Turbine Case Cooling Control Valve        |               | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | Thermocouple (Pre-Sb 71-101987, Clock 2 Position) -      |               | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | Removal / Installation                                   |               | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | PN                                                       | SN-UNKNOWN    | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | [End Of Month Item]                                      |               |     |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| 752200           | No. 2 Engine - Turbine Case Cooling Control Valve        |               | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | Thermocouple (Pre-Sb 71-101987, Clock 2 Position) -      |               | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | Removal / Installation                                   |               | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | PN                                                       | SN-UNKNOWN    | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | [End Of Month Item]                                      |               |     |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| 752201           | No. 1 Engine - Turbine Case Cooling Control Valve        |               | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | Thermocouple (Pre-Sb 71-101987, Clock 10 Position) -     |               | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | Removal / Installation                                   |               | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | PN                                                       | SN-UNKNOWN    | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | [End Of Month Item]                                      |               |     |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| 752201           | No. 2 Engine - Turbine Case Cooling Control Valve        |               | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | Thermocouple (Pre-Sb 71-101987, Clock 10 Position) -     |               | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | Removal / Installation                                   |               | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | PN                                                       | SN-UNKNOWN    | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | [End Of Month Item]                                      |               |     |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| 752204           | No. 1 Engine - Buffer AIR Valve - Removal / Installation |               | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | 8910-513                                                 | 22978770      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                          |               | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                          |               | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | [End Of Month Item]                                      |               |     |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| 752204           | No. 2 Engine - Buffer AIR Valve - Removal / Installation |               | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | 8910-513                                                 | 22947844      | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                          |               | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                          |               | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | [End Of Month Item]                                      |               |     |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| 752206           | No. 1 Engine - Turbine Case Cooling Valve (Clock 2       |               | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | Position) - Removal / Installation                       |               | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | PN                                                       | SN-UNKNOWN    | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                          |               | MSC |             |                 |     | O/C              |             |                    |         |              |
|                  | [End Of Month Item]                                      |               |     |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                          |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                            |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                            | Serial Number |                     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                                     | SW            |                     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                                 |               |                     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                                          |               |                     |             |                 |     |                  |             |                    |         |              |
| 752206           | No. 2 Engine - Turbine Case Cooling Valve (Clock 2 Position) - Removal / Installation  |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                        |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | PN                                                                                     | SN-UNKNOWN    | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                                        |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                                 |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 752207           | No. 1 Engine - Turbine Case Cooling Valve (Clock 7 Position) - Removal / Installation  |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                        |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | PN                                                                                     | SN-UNKNOWN    | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                                        |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                                 |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 752207           | No. 2 Engine - Turbine Case Cooling Valve (Clock 7 Position) - Removal / Installation  |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                        |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | PN                                                                                     | SN-UNKNOWN    | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                                        |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                                 |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 752208           | No. 1 Engine - Turbine Case Cooling Valve (Clock 11 Position) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                        |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | PN                                                                                     | SN-UNKNOWN    | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                                        |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                                 |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 752208           | No. 2 Engine - Turbine Case Cooling Valve (Clock 11 Position) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                        |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | PN                                                                                     | SN-UNKNOWN    | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                                        |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                                 |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 752212           | No. 1 Engine - Turbine Case Cooling Valve (Clock 2 Position) - Inspection              |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                        |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                                                        |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                                        |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                                 |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 752212           | No. 2 Engine - Turbine Case Cooling Valve (Clock 2 Position) - Inspection              |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                        |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                                                        |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                                        |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                                 |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                                                         |               | UOM    | Times Since         | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|---------------------------------------------------------------------------------------------------------------------|---------------|--------|---------------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                                                         | Serial Number |        |                     |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                                                                  | SW            |        |                     |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                                                              |               |        |                     |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                                                                       |               |        |                     |                 |     |                  |             |                    |         |              |
| 752213           | No. 1 Engine - Turbine Case Cooling Valve (Clock 7 Position) - Inspection                                           |               | HRS    |                     | 994.4           |     |                  | 0           |                    | 0       |              |
|                  |                                                                                                                     |               | ENC    |                     | 392             |     |                  | 0           |                    | 0       |              |
|                  |                                                                                                                     |               | MOS    |                     | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                                                                     |               | MSC    |                     |                 |     | O/C              |             |                    |         |              |
|                  |                                                                                                                     |               | Engine | [End Of Month Item] |                 |     |                  |             |                    |         |              |
| 752213           | No. 2 Engine - Turbine Case Cooling Valve (Clock 7 Position) - Inspection                                           |               | HRS    |                     | 994.4           |     |                  | 0           |                    | 0       |              |
|                  |                                                                                                                     |               | ENC    |                     | 392             |     |                  | 0           |                    | 0       |              |
|                  |                                                                                                                     |               | MOS    |                     | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                                                                     |               | MSC    |                     |                 |     | O/C              |             |                    |         |              |
|                  |                                                                                                                     |               | Engine | [End Of Month Item] |                 |     |                  |             |                    |         |              |
| 752214           | No. 1 Engine - Turbine Case Cooling Valve (Clock 11 Position) - Inspection                                          |               | HRS    |                     | 994.4           |     |                  | 0           |                    | 0       |              |
|                  |                                                                                                                     |               | ENC    |                     | 392             |     |                  | 0           |                    | 0       |              |
|                  |                                                                                                                     |               | MOS    |                     | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                                                                     |               | MSC    |                     |                 |     | O/C              |             |                    |         |              |
|                  |                                                                                                                     |               | Engine | [End Of Month Item] |                 |     |                  |             |                    |         |              |
| 752214           | No. 2 Engine - Turbine Case Cooling Valve (Clock 11 Position) - Inspection                                          |               | HRS    |                     | 994.4           |     |                  | 0           |                    | 0       |              |
|                  |                                                                                                                     |               | ENC    |                     | 392             |     |                  | 0           |                    | 0       |              |
|                  |                                                                                                                     |               | MOS    |                     | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                                                                     |               | MSC    |                     |                 |     | O/C              |             |                    |         |              |
|                  |                                                                                                                     |               | Engine | [End Of Month Item] |                 |     |                  |             |                    |         |              |
| 753100           | No. 1 Engine - Variable Stator Vane Actuator - Removal / Installation<br>G3000VSVA01                      SAX22-057 |               | HRS    |                     | 994.4           |     |                  | 0           |                    | 0       |              |
|                  |                                                                                                                     |               | ENC    |                     | 392             |     |                  | 0           |                    | 0       |              |
|                  |                                                                                                                     |               | MOS    |                     | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                                                                     |               | MSC    |                     |                 |     | O/C              |             |                    |         |              |
|                  |                                                                                                                     |               | Engine | [End Of Month Item] |                 |     |                  |             |                    |         |              |
| 753100           | No. 2 Engine - Variable Stator Vane Actuator - Removal / Installation<br>G3000VSVA01                      SAX22-061 |               | HRS    |                     | 994.4           |     |                  | 0           |                    | 0       |              |
|                  |                                                                                                                     |               | ENC    |                     | 392             |     |                  | 0           |                    | 0       |              |
|                  |                                                                                                                     |               | MOS    |                     | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                                                                     |               | MSC    |                     |                 |     | O/C              |             |                    |         |              |
|                  |                                                                                                                     |               | Engine | [End Of Month Item] |                 |     |                  |             |                    |         |              |
| 753102           | No. 1 Engine - AIR Bleed Control Solenoid Block - Removal / Installation<br>PN                      SN-UNKNOWN      |               | HRS    |                     | 994.4           |     |                  | 0           |                    | 0       |              |
|                  |                                                                                                                     |               | ENC    |                     | 392             |     |                  | 0           |                    | 0       |              |
|                  |                                                                                                                     |               | MOS    |                     | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                                                                     |               | MSC    |                     |                 |     | O/C              |             |                    |         |              |
|                  |                                                                                                                     |               | Engine | [End Of Month Item] |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                      |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                                                      | Serial Number |                     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                                               | SW            |                     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                                           |               |                     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                                                    |               |                     |             |                 |     |                  |             |                     |         |              |
| 753102           | No. 2 Engine - AIR Bleed Control Solenoid Block - Removal / Installation         |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | PN                                                                               |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | SN-UNKNOWN                                                                       |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                                  |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                           |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 753104           | No. 1 Engine - Lower Left Handling Bleed Valve (HP5.3) - Removal / Installation  |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | PN                                                                               |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | SN-UNKNOWN                                                                       |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                                  |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                           |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 753104           | No. 2 Engine - Lower Left Handling Bleed Valve (HP5.3) - Removal / Installation  |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | PN                                                                               |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | SN-UNKNOWN                                                                       |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                                  |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                           |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 753105           | No. 1 Engine - Lower Right Handling Bleed Valve (HP5.2) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | PN                                                                               |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | SN-UNKNOWN                                                                       |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                                  |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                           |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 753105           | No. 2 Engine - Lower Right Handling Bleed Valve (HP5.2) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | PN                                                                               |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | SN-UNKNOWN                                                                       |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                                  |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                           |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 753106           | No. 1 Engine - Upper Right Handling Bleed Valve (HP5.1) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | PN                                                                               |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | SN-UNKNOWN                                                                       |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                                  |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                           |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 753106           | No. 2 Engine - Upper Right Handling Bleed Valve (HP5.1) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | PN                                                                               |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | SN-UNKNOWN                                                                       |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                                  |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                           |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom  | Description                                                                   |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|-------------------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                                                   | Serial Number |                     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                                            | SW            |                     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                                        |               |                     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                                                 |               |                     |             |                 |     |                  |             |                     |         |              |
| 753107           | No. 1 Engine - Upper Left Handling Bleed Valve (HP8) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                               |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | PN                                                                            | SN-UNKNOWN    | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                               |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                        |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 753107           | No. 2 Engine - Upper Left Handling Bleed Valve (HP8) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                               |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | PN                                                                            | SN-UNKNOWN    | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                               |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                        |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 753112           | No. 1 Engine - Bleed Valve Standpipe (Upper HP5) - Removal / Installation     |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                               |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | PN                                                                            | SN-UNKNOWN    | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                               |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                        |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 753112           | No. 2 Engine - Bleed Valve Standpipe (Upper HP5) - Removal / Installation     |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                               |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | PN                                                                            | SN-UNKNOWN    | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                               |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                        |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 753113           | No. 1 Engine - Bleed Valve Standpipe (Lower HP5) - Removal / Installation     |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                               |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | PN                                                                            | SN-UNKNOWN    | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                               |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                        |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 753113           | No. 2 Engine - Bleed Valve Standpipe (Lower HP5) - Removal / Installation     |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                               |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | PN                                                                            | SN-UNKNOWN    | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                               |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                        |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 753114           | No. 1 Engine - Bleed Valve Standpipe (HP8) - Removal / Installation           |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                               |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | PN                                                                            | SN-UNKNOWN    | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                               |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                        |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom  | Description                                                                 |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-----------------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                 | Serial Number |                     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                          | SW            |                     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                      |               |                     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                               |               |                     |             |                 |     |                  |             |                    |         |              |
| 753114           | No. 2 Engine - Bleed Valve Standpipe (HP8) - Removal / Installation         |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                             |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | PN                                                                          | SN-UNKNOWN    | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                             |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                      |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 753118           | No. 1 Engine - Bleed Valve HP5 Attenuator S-Seal (Lower Left) - Inspection  |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                             |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                                             |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                             |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                      |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 753118           | No. 2 Engine - Bleed Valve HP5 Attenuator S-Seal (Lower Left) - Inspection  |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                             |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                                             |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                             |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                      |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 753119           | No. 1 Engine - Bleed Valve HP5 Attenuator S-Seal (Lower Right) - Inspection |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                             |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                                             |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                             |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                      |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 753119           | No. 2 Engine - Bleed Valve HP5 Attenuator S-Seal (Lower Right) - Inspection |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                             |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                                             |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                             |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                      |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 753120           | No. 1 Engine - Bleed Valve HP5 Attenuator S-Seal (Upper Left) - Inspection  |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                             |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                                             |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                             |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                      |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 753120           | No. 2 Engine - Bleed Valve HP5 Attenuator S-Seal (Upper Left) - Inspection  |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                             |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                                             |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                             |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                      |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom      | Description                                                                 |               | UOM      | Times Since         | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|----------------------|-----------------------------------------------------------------------------|---------------|----------|---------------------|-----------------|-----|------------------|----------|--------------------|---------|--------------|
|                      | Part Number                                                                 | Serial Number |          |                     |                 |     |                  |          |                    |         | Approx Price |
| Logbook Position     | HW                                                                          | SW            |          |                     |                 |     |                  |          |                    |         | Manufacturer |
|                      | MM Ref                                                                      |               |          |                     |                 |     |                  |          |                    |         | Date Type    |
|                      | Ops Number(s)                                                               |               |          |                     |                 |     |                  |          |                    |         |              |
| 753121               | No. 1 Engine - Bleed Valve HP5 Attenuator S-Seal (Upper Right) - Inspection |               | HRS      |                     | 994.4           |     |                  | 0        |                    |         | 0            |
|                      |                                                                             |               | ENC      |                     | 392             |     |                  | 0        |                    | 0       |              |
|                      |                                                                             |               | MOS      |                     | 41.8            |     | 17 Nov 2022      |          |                    |         |              |
|                      |                                                                             |               | MSC      |                     |                 | O/C |                  |          |                    |         |              |
|                      |                                                                             |               | Engine   | [End Of Month Item] |                 |     |                  |          |                    |         |              |
| 753121               | No. 2 Engine - Bleed Valve HP5 Attenuator S-Seal (Upper Right) - Inspection |               | HRS      |                     | 994.4           |     |                  | 0        |                    |         | 0            |
|                      |                                                                             |               | ENC      |                     | 392             |     |                  | 0        |                    | 0       |              |
|                      |                                                                             |               | MOS      |                     | 41.9            |     | 15 Nov 2022      |          |                    |         |              |
|                      |                                                                             |               | MSC      |                     |                 | O/C |                  |          |                    |         |              |
|                      |                                                                             |               | Engine   | [End Of Month Item] |                 |     |                  |          |                    |         |              |
| 753122               | No. 1 Engine - AIR Tubes and Fittings - Inspection                          |               | HRS      |                     | 994.4           |     |                  | 0        |                    |         | 0            |
|                      |                                                                             |               | ENC      |                     | 392             |     |                  | 0        |                    | 0       |              |
|                      |                                                                             |               | MOS      |                     | 41.8            |     | 17 Nov 2022      |          |                    |         |              |
|                      |                                                                             |               | MSC      |                     |                 | O/C |                  |          |                    |         |              |
|                      |                                                                             |               | Engine   | [End Of Month Item] |                 |     |                  |          |                    |         |              |
| 753122               | No. 2 Engine - AIR Tubes and Fittings - Inspection                          |               | HRS      |                     | 994.4           |     |                  | 0        |                    |         | 0            |
|                      |                                                                             |               | ENC      |                     | 392             |     |                  | 0        |                    | 0       |              |
|                      |                                                                             |               | MOS      |                     | 41.9            |     | 15 Nov 2022      |          |                    |         |              |
|                      |                                                                             |               | MSC      |                     |                 | O/C |                  |          |                    |         |              |
|                      |                                                                             |               | Engine   | [End Of Month Item] |                 |     |                  |          |                    |         |              |
| 753123               | No. 1 Engine - Bleed Valve Standpipe (Lower HP8) - Removal / Installation   |               | HRS      |                     | 994.4           |     |                  | 0        |                    |         | 0            |
|                      |                                                                             |               | ENC      |                     | 392             |     |                  | 0        |                    | 0       |              |
|                      |                                                                             |               | MOS      |                     | 41.8            |     | 17 Nov 2022      |          |                    |         |              |
|                      |                                                                             |               | MSC      |                     |                 | O/C |                  |          |                    |         |              |
|                      |                                                                             |               | Engine   | [End Of Month Item] |                 |     |                  |          |                    |         |              |
| 753123               | No. 2 Engine - Bleed Valve Standpipe (Lower HP8) - Removal / Installation   |               | HRS      |                     | 994.4           |     |                  | 0        |                    |         | 0            |
|                      |                                                                             |               | ENC      |                     | 392             |     |                  | 0        |                    | 0       |              |
|                      |                                                                             |               | MOS      |                     | 41.9            |     | 15 Nov 2022      |          |                    |         |              |
|                      |                                                                             |               | MSC      |                     |                 | O/C |                  |          |                    |         |              |
|                      |                                                                             |               | Engine   | [End Of Month Item] |                 |     |                  |          |                    |         |              |
| 76 - Engine Controls |                                                                             |               |          |                     |                 |     |                  |          |                    |         |              |
| 761000               | Throttle Quadrant - Removal / Installation                                  |               | HRS      |                     | 3046.1          |     |                  | 0        |                    |         | 0            |
|                      |                                                                             |               | AFL      |                     | 1117            |     |                  | 0        |                    | 0       |              |
|                      |                                                                             |               | MOS      |                     | 128.6           |     | 24 Aug 2015      |          |                    |         |              |
|                      |                                                                             |               | MSC      |                     |                 | O/C |                  |          |                    |         |              |
|                      |                                                                             |               | Airframe | [End Of Month Item] |                 |     |                  |          |                    |         |              |
| 60P7610001Z0110185   |                                                                             |               |          |                     |                 |     |                  |          |                    |         |              |

| ATA<br>U=Custom                       | Description                                                          |                     | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|---------------------------------------|----------------------------------------------------------------------|---------------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                       | Part Number                                                          | Serial Number       |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position                      | HW                                                                   | SW                  |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                       | MM Ref                                                               |                     |     |             |                 |     |                  |             |                    |         | Date Type    |
|                                       | Ops Number(s)                                                        |                     |     |             |                 |     |                  |             |                    |         |              |
| 761002                                | Throttle Quadrant - Functional Test                                  |                     | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                       |                                                                      |                     | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                       |                                                                      |                     | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                       | Airframe                                                             |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
| Notes: PN: 60P2510001A005 SN: <NONE>. |                                                                      |                     |     |             |                 |     |                  |             |                    |         |              |
| 762301                                | Engine Fuel Control Switch Panel - Removal / Installation            |                     | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                       | 60P3110909A007                                                       | SN-UNKNOWN          | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                       |                                                                      |                     | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                       | Airframe                                                             |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
| 77 - Engine Indicating                |                                                                      |                     |     |             |                 |     |                  |             |                    |         |              |
| 770001                                | No. 1 Engine - Thermocouple, #2 Turbine O/H - Removal / Installation |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                                       |                                                                      |                     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                                       | PN                                                                   | SN-UNKNOWN          | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                                       |                                                                      |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
| Engine                                |                                                                      | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 770001                                | No. 2 Engine - Thermocouple, #2 Turbine O/H - Removal / Installation |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                                       |                                                                      |                     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                                       | PN                                                                   | SN-UNKNOWN          | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                                       |                                                                      |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
| Engine                                |                                                                      | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 771200                                | No. 1 Engine - #1 Lp Speed Probe - Removal / Installation            |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                                       |                                                                      |                     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                                       | PN                                                                   | SN-UNKNOWN          | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                                       |                                                                      |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
| Engine                                |                                                                      | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 771200                                | No. 2 Engine - #1 Lp Speed Probe - Removal / Installation            |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                                       |                                                                      |                     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                                       | PN                                                                   | SN-UNKNOWN          | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                                       |                                                                      |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
| Engine                                |                                                                      | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |
| 771201                                | No. 1 Engine - #2 Lp Speed Probe - Removal / Installation            |                     | HRS |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                                       |                                                                      |                     | ENC |             | 392             |     |                  | 0           |                    |         | 0            |
|                                       | PN                                                                   | SN-UNKNOWN          | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                                       |                                                                      |                     | MSC |             |                 |     | O/C              |             |                    |         |              |
| Engine                                |                                                                      | [End Of Month Item] |     |             |                 |     |                  |             |                    |         |              |



| ATA<br>U=Custom  | Description                                                           |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|-----------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                                           | Serial Number |                     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                                    | SW            |                     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                                |               |                     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                                         |               |                     |             |                 |     |                  |             |                     |         |              |
| 771201           | No. 2 Engine - #2 Lp Speed Probe - Removal / Installation             |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | PN                                                                    | SN-UNKNOWN    | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                                                       |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  | Engine                                                                |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  |                                                                       |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 771202           | No. 1 Engine - #3 Lp Speed Probe - Removal / Installation             |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | PN                                                                    | SN-UNKNOWN    | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                                                       |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  | Engine                                                                |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  |                                                                       |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 771202           | No. 2 Engine - #3 Lp Speed Probe - Removal / Installation             |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | PN                                                                    | SN-UNKNOWN    | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                                                       |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  | Engine                                                                |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  |                                                                       |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 771203           | No. 1 Engine - #4 Lp Speed Probe - Removal / Installation             |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | PN                                                                    | SN-UNKNOWN    | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                                                       |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  | Engine                                                                |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  |                                                                       |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 771203           | No. 2 Engine - #4 Lp Speed Probe - Removal / Installation             |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | PN                                                                    | SN-UNKNOWN    | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                                                       |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  | Engine                                                                |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  |                                                                       |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 771208           | No. 1 Engine - Engine N2 Speed Probe (No. 1) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | 7001KGB01                                                             | 2202563       | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                                                       |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  | Engine                                                                |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  |                                                                       |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 771208           | No. 2 Engine - Engine N2 Speed Probe (No. 1) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | 7001KGB01                                                             | 2202560       | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                                                       |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  | Engine                                                                |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  |                                                                       |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 771209           | No. 1 Engine - Engine N2 Speed Probe (No. 2) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | 7001KGB01                                                             | 2202566       | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                                                       |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  | Engine                                                                |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  |                                                                       |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom  | Description                                                                   |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-------------------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                   | Serial Number |                     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                            | SW            |                     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                        |               |                     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                                 |               |                     |             |                 |     |                  |             |                    |         |              |
| 771209           | No. 2 Engine - Engine N2 Speed Probe (No. 2) - Removal / Installation         |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                               |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | 7001KGB01                                                                     | 2202573       | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                               |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                        |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 771210           | No. 1 Engine - Generator Control Unit N2 Speed Probe - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                               |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | 7030KGB01                                                                     | 2202268       | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                               |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                        |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 771210           | No. 2 Engine - Generator Control Unit N2 Speed Probe - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                               |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | 7030KGB01                                                                     | 2202270       | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                               |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                        |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 771214           | No. 1 Engine - #5 Lp Speed Probe - Removal / Installation                     |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | PN                                                                            | SN-UNKNOWN    | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                                               |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                               |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                        |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 771214           | No. 2 Engine - #5 Lp Speed Probe - Removal / Installation                     |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | PN                                                                            | SN-UNKNOWN    | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                                               |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                               |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                        |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 771220           | No. 1 Engine - Nh 1/Rev Signal Attenuating Plug - Removal / Installation      |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | PN                                                                            | SN-UNKNOWN    | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                                               |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                               |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                        |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 771220           | No. 2 Engine - Nh 1/Rev Signal Attenuating Plug - Removal / Installation      |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | PN                                                                            | SN-UNKNOWN    | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                                               |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                               |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                        |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                             |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-------------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                             | Serial Number |                     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                      | SW            |                     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                  |               |                     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                           |               |                     |             |                 |     |                  |             |                    |         |              |
| 772100           | No. 1 Engine - Engine Tgt Thermocouple Harness - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                         |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | 0301KHS01                                                               | 2250034       | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                         |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                  |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 772100           | No. 2 Engine - Engine Tgt Thermocouple Harness - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                         |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | PN                                                                      | SN-UNKNOWN    | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                         |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                  |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 772102           | No. 1 Engine - Engine Tgt Thermocouple (No. 1) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                         |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | 6001KTC04                                                               | 2202736       | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                         |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                  |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 772102           | No. 2 Engine - Engine Tgt Thermocouple (No. 1) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                         |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | 6001KTC04                                                               | 2202735       | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                         |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                  |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 772103           | No. 1 Engine - Engine Tgt Thermocouple (No. 2) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                         |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | 6001KTC04                                                               | 2202741       | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                         |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                  |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 772103           | No. 2 Engine - Engine Tgt Thermocouple (No. 2) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                         |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | 6001KTC04                                                               | 2202737       | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                         |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                  |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 772104           | No. 1 Engine - Engine Tgt Thermocouple (No. 3) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                         |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | 6001KTC04                                                               | 2202753       | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                         |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                  |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                      |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|--------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                      | Serial Number |                     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                               | SW            |                     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                           |               |                     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                    |               |                     |             |                 |     |                  |             |                    |         |              |
| 772104           | No. 2 Engine - Engine Tgt Thermocouple (No. 3) - |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | Removal / Installation                           |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | 6001KTC04                                        | 2202742       | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                  |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                           |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 772105           | No. 1 Engine - Engine Tgt Thermocouple (No. 4) - |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | Removal / Installation                           |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | 6001KTC04                                        | 2202756       | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                  |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                           |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 772105           | No. 2 Engine - Engine Tgt Thermocouple (No. 4) - |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | Removal / Installation                           |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | 6001KTC04                                        | 2202743       | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                  |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                           |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 772106           | No. 1 Engine - Engine Tgt Thermocouple (No. 5) - |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | Removal / Installation                           |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | 6001KTC04                                        | 2202758       | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                  |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                           |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 772106           | No. 2 Engine - Engine Tgt Thermocouple (No. 5) - |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | Removal / Installation                           |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | 6001KTC04                                        | 2202744       | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                  |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                           |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 772107           | No. 1 Engine - Engine Tgt Thermocouple (No. 6) - |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | Removal / Installation                           |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | 6001KTC04                                        | 2202761       | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                  |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                           |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 772107           | No. 2 Engine - Engine Tgt Thermocouple (No. 6) - |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | Removal / Installation                           |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | 6001KTC04                                        | 2202750       | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                  |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                           |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                               |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(* = Adj) | Max Due | Avg Man Hrs  |
|------------------|-----------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|-----------------------|---------|--------------|
|                  | Part Number                                               | Serial Number |                     |             |                 |     |                  |             |                       |         | Approx Price |
| Logbook Position | HW                                                        | SW            |                     |             |                 |     |                  |             |                       |         | Manufacturer |
|                  | MM Ref                                                    |               |                     |             |                 |     |                  |             |                       |         | Date Type    |
|                  | Ops Number(s)                                             |               |                     |             |                 |     |                  |             |                       |         |              |
| 772108           | No. 1 Engine - Engine Tgt Thermocouple (No. 7) -          |               | HRS                 |             | 994.4           |     |                  | 0           |                       |         | 0            |
|                  | Removal / Installation                                    |               | ENC                 |             | 392             |     |                  | 0           |                       |         | 0            |
|                  | 6001KTC04                                                 | 2202763       | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                       |         |              |
|                  |                                                           |               | MSC                 |             |                 |     | O/C              |             |                       |         |              |
|                  | Engine                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                       |         |              |
| 772108           | No. 2 Engine - Engine Tgt Thermocouple (No. 7) -          |               | HRS                 |             | 994.4           |     |                  | 0           |                       |         | 0            |
|                  | Removal / Installation                                    |               | ENC                 |             | 392             |     |                  | 0           |                       |         | 0            |
|                  | 6001KTC04                                                 | 2202762       | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                       |         |              |
|                  |                                                           |               | MSC                 |             |                 |     | O/C              |             |                       |         |              |
|                  | Engine                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                       |         |              |
| 772200           | No. 1 Engine - Oil FIRE Detection Thermocouple -          |               | HRS                 |             | 994.4           |     |                  | 0           |                       |         | 0            |
|                  | Removal / Installation                                    |               | ENC                 |             | 392             |     |                  | 0           |                       |         | 0            |
|                  | PN                                                        | SN-UNKNOWN    | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                       |         |              |
|                  |                                                           |               | MSC                 |             |                 |     | O/C              |             |                       |         |              |
|                  | Engine                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                       |         |              |
| 772200           | No. 2 Engine - Oil FIRE Detection Thermocouple -          |               | HRS                 |             | 994.4           |     |                  | 0           |                       |         | 0            |
|                  | Removal / Installation                                    |               | ENC                 |             | 392             |     |                  | 0           |                       |         | 0            |
|                  | PN                                                        | SN-UNKNOWN    | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                       |         |              |
|                  |                                                           |               | MSC                 |             |                 |     | O/C              |             |                       |         |              |
|                  | Engine                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                       |         |              |
| 772202           | No. 1 Engine - Engine Thermocouple Harness - Removal /    |               | HRS                 |             | 994.4           |     |                  | 0           |                       |         | 0            |
|                  | Installation                                              |               | ENC                 |             | 392             |     |                  | 0           |                       |         | 0            |
|                  | PN                                                        | SN-UNKNOWN    | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                       |         |              |
|                  |                                                           |               | MSC                 |             |                 |     | O/C              |             |                       |         |              |
|                  | Engine                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                       |         |              |
| 772202           | No. 2 Engine - Engine Thermocouple Harness - Removal /    |               | HRS                 |             | 994.4           |     |                  | 0           |                       |         | 0            |
|                  | Installation                                              |               | ENC                 |             | 392             |     |                  | 0           |                       |         | 0            |
|                  | PN                                                        | SN-UNKNOWN    | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                       |         |              |
|                  |                                                           |               | MSC                 |             |                 |     | O/C              |             |                       |         |              |
|                  | Engine                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                       |         |              |
| 773100           | Integrated Engine Vibration Monitor System - Adjustment / |               | HRS                 |             | 3046.1          |     |                  | 0           |                       |         | 0            |
|                  | Test                                                      |               | AFL                 |             | 1117            |     |                  | 0           |                       |         | 0            |
|                  |                                                           |               | MOS                 |             | 128.6           |     |                  | 24 Aug 2015 |                       |         |              |
|                  |                                                           |               | MSC                 |             |                 |     | O/C              |             |                       |         |              |
|                  | Airframe                                                  |               |                     |             |                 |     |                  |             |                       |         |              |

| ATA<br>U=Custom  | Description                                              |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                              | Serial Number |                                    |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                       | SW            |                                    |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                   |               |                                    |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                            |               |                                    |             |                 |     |                  |             |                     |         |              |
| 773101           | Engine Vibration Monitor Secondary Pickup Selector       |               | HRS                                |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  | Switch - Removal / Installation                          |               | AFL                                |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 318VL23AAARY00                                           | SN-UNKNOWN    | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                          |               | MSC                                |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                          |               |                                    |             |                 |     |                  |             |                     |         |              |
| 773102           | No. 1 Engine - Engine Vibration Transducer A (Primary) - |               | HRS                                |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | Removal / Installation                                   |               | ENC                                |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | PN                                                       | SN-UNKNOWN    | MOS                                |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                          |               | MSC                                |             |                 |     | O/C              |             |                     |         |              |
| Engine           |                                                          |               | [End Of Month Item]                |             |                 |     |                  |             |                     |         |              |
| 773102           | No. 2 Engine - Engine Vibration Transducer A (Primary) - |               | HRS                                |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | Removal / Installation                                   |               | ENC                                |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | PN                                                       | SN-UNKNOWN    | MOS                                |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                          |               | MSC                                |             |                 |     | O/C              |             |                     |         |              |
| Engine           |                                                          |               | [End Of Month Item]                |             |                 |     |                  |             |                     |         |              |
| 773103           | No. 1 Engine - Engine Vibration Transducer B             |               | HRS                                |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | (Secondary) - Removal / Installation                     |               | ENC                                |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | PN                                                       | SN-UNKNOWN    | MOS                                |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                          |               | MSC                                |             |                 |     | O/C              |             |                     |         |              |
| Engine           |                                                          |               | [End Of Month Item]                |             |                 |     |                  |             |                     |         |              |
| 773103           | No. 2 Engine - Engine Vibration Transducer B             |               | HRS                                |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | (Secondary) - Removal / Installation                     |               | ENC                                |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | PN                                                       | SN-UNKNOWN    | MOS                                |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                          |               | MSC                                |             |                 |     | O/C              |             |                     |         |              |
| Engine           |                                                          |               | [End Of Month Item]                |             |                 |     |                  |             |                     |         |              |
| 78 - Exhaust     |                                                          |               |                                    |             |                 |     |                  |             |                     |         |              |
| 780001           | No. 1 Engine - Engine Exhaust - General Visual           |               | HRS                                |             | 137             | 6.5 | 600              | 857.4       | 1463.9*             | 1513.9  | 0            |
|                  | Inspection                                               |               | ENC                                |             | 52              |     |                  | 340         |                     |         | 0            |
|                  |                                                          |               | MOS                                |             | 5.2             |     |                  | 04 Dec 2025 |                     |         |              |
|                  |                                                          |               | [End Of Month Item] [HRS: +50/-50] |             |                 |     |                  |             |                     |         |              |
| Engine           | 052001                                                   |               |                                    |             |                 |     |                  |             |                     |         |              |
| 780001           | No. 2 Engine - Engine Exhaust - General Visual           |               | HRS                                |             | 137             | 6.5 | 600              | 857.4       | 1463.9*             | 1513.9  | 0            |
|                  | Inspection                                               |               | ENC                                |             | 52              |     |                  | 340         |                     |         | 0            |
|                  |                                                          |               | MOS                                |             | 5.2             |     |                  | 04 Dec 2025 |                     |         |              |
|                  |                                                          |               | [End Of Month Item] [HRS: +50/-50] |             |                 |     |                  |             |                     |         |              |
| Engine           | 052001                                                   |               |                                    |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom  | Description                                                                                                       |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|-------------------------------------------------------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                                                                                       | Serial Number |                     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                                                                                | SW            |                     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                                                                            |               |                     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                                                                                     |               |                     |             |                 |     |                  |             |                     |         |              |
| 781000           | Exhaust Cone Assembly (Left) - Removal / Installation                                                             |               | HRS                 |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  | FW71895                                                                                                           | SN-UNKNOWN    | AFL                 |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  |                                                                                                                   |               | MOS                 |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  | Airframe                                                                                                          |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
| 781001           | Exhaust Cone Assembly (Right) - Removal / Installation                                                            |               | HRS                 |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  | FW71895                                                                                                           | SN-UNKNOWN    | AFL                 |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  |                                                                                                                   |               | MOS                 |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  | Airframe                                                                                                          |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
| 781004           | Exhaust Cone Assembly (Left) - Inspection                                                                         |               | HRS                 |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                                                                   |               | AFL                 |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  |                                                                                                                   |               | MOS                 |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  | Airframe                                                                                                          |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
| 781005           | Exhaust Cone Assembly (Right) - Inspection                                                                        |               | HRS                 |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                                                                   |               | AFL                 |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  |                                                                                                                   |               | MOS                 |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  | Airframe                                                                                                          |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
| 781050           | No. 1 Engine - Engine Exhaust Outlet Guide Vane,<br>Exhaust Mixer and Exhaust Cone - General Visual<br>Inspection |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                                                                   |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                                                                                                   |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                                                                   |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                                                            |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 781050           | No. 2 Engine - Engine Exhaust Outlet Guide Vane,<br>Exhaust Mixer and Exhaust Cone - General Visual<br>Inspection |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                                                                   |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                                                                                                   |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                                                                   |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                                                            |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 783100           | Engine T/Rev (Left) - Removal / Installation                                                                      |               | HRS                 | TSN:2051.9  | 994.2           |     |                  | 2051.9      |                     |         | 0            |
|                  | RD00103001-1                                                                                                      | RD3001L0170   | AFL                 | TSN:725     | 392             |     |                  | 725         |                     |         | 0            |
|                  |                                                                                                                   |               | MOS                 | TSN:88      | 41.2            |     |                  | 05 Dec 2022 |                     |         |              |
|                  | Airframe                                                                                                          |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |

| ATA<br>U=Custom  | Description                                                       |               | UOM            | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-------------------------------------------------------------------|---------------|----------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                       | Serial Number |                |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                | SW            |                |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                            |               |                |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                     |               |                |             |                 |     |                  |             |                    |         |              |
| 783101           | Engine T/Rev (Right) - Removal / Installation                     |               | HRS            | TSN:2051.9  | 994.2           |     |                  | 2051.9      |                    |         | 0            |
|                  | RD00103001-2                                                      | RD3001R0169   | AFL            | TSN:725     | 392             |     |                  | 725         |                    |         | 0            |
|                  |                                                                   |               | MOS            | TSN:88      | 41.1            |     |                  | 09 Dec 2022 |                    |         |              |
|                  | Airframe                                                          |               | MSC            |             |                 |     | O/C              |             |                    |         |              |
| 783104           | T/Rev Deactivate / Activate (Left) - Procedure                    |               | HRS            |             | 994.4           |     |                  | 2051.7      |                    |         | 0            |
|                  |                                                                   |               | AFL            |             | 392             |     |                  | 725         |                    |         | 0            |
|                  |                                                                   |               | MOS            |             | 40.9            |     |                  | 15 Dec 2022 |                    |         |              |
|                  | Airframe                                                          |               | MSC            |             |                 |     | O/C              |             |                    |         |              |
| 783105           | T/Rev Deactivate / Activate (Right) - Procedure                   |               | HRS            |             | 994.4           |     |                  | 2051.7      |                    |         | 0            |
|                  |                                                                   |               | AFL            |             | 392             |     |                  | 725         |                    |         | 0            |
|                  |                                                                   |               | MOS            |             | 40.9            |     |                  | 15 Dec 2022 |                    |         |              |
|                  | Airframe                                                          |               | MSC            |             |                 |     | O/C              |             |                    |         |              |
| 783106           | T/Rev Pivoting Doors Lockout (Left) - Procedure                   |               | HRS            |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                   |               | AFL            |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                   |               | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                          |               | MSC            |             |                 |     | O/C              |             |                    |         |              |
| 783107           | T/Rev Pivoting Doors Lockout (Right) - Procedure                  |               | HRS            |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                   |               | AFL            |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                   |               | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                          |               | MSC            |             |                 |     | O/C              |             |                    |         |              |
| 783108           | Pivoting Doors Actuator Locking Sleeve (Left) - Safety Procedure  |               | HRS            |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                   |               | AFL            |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                   |               | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                          |               | MSC            |             |                 |     | O/C              |             |                    |         |              |
| 783109           | Pivoting Doors Actuator Locking Sleeve (Right) - Safety Procedure |               | HRS            |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                   |               | AFL            |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                   |               | MOS            |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                          |               | MSC            |             |                 |     | O/C              |             |                    |         |              |
| 783110           | T/Rev (Left) - General Visual Inspection                          |               | HRS            |             | 730.5           |     | 2400             | 2315.6      | 4715.6             | 4765.6  | 0            |
|                  |                                                                   |               | AFL            |             | 315             |     |                  | 802         |                    |         | 0            |
|                  |                                                                   |               | MOS            |             | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
|                  | Airframe                                                          |               | [HRS: +50/-50] |             |                 |     |                  |             |                    |         |              |
|                  | 052004                                                            |               |                |             |                 |     |                  |             |                    |         |              |



| ATA<br>U=Custom  | Description                                           |               | UOM                                               | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due     | Avg Man Hrs  |
|------------------|-------------------------------------------------------|---------------|---------------------------------------------------|-------------|-----------------|-----|------------------|-------------|---------------------|-------------|--------------|
|                  | Part Number                                           | Serial Number |                                                   |             |                 |     |                  |             |                     |             | Approx Price |
| Logbook Position | HW                                                    | SW            |                                                   |             |                 |     |                  |             |                     |             | Manufacturer |
|                  | MM Ref                                                |               |                                                   |             |                 |     |                  |             |                     |             | Date Type    |
|                  | Ops Number(s)                                         |               |                                                   |             |                 |     |                  |             |                     |             |              |
| 783111           | T/Rev (Right) - General Visual Inspection             |               | HRS                                               |             | 730.5           |     | 2400             | 2315.6      | 4715.6              | 4765.6      | 0            |
|                  |                                                       |               | AFL                                               |             | 315             |     |                  | 802         |                     |             | 0            |
|                  |                                                       |               | MOS                                               |             | 28.7            |     |                  | 21 Dec 2023 |                     |             |              |
|                  | Airframe                                              |               | [HRS: +50/-50]                                    |             |                 |     |                  |             |                     |             |              |
|                  |                                                       | 052004        |                                                   |             |                 |     |                  |             |                     |             |              |
| 783112           | T/Rev and Exhaust Internal (Left) - Zonal Inspection  |               | HRS                                               |             | 730.5           |     | 2400             | 2315.6      | 4715.6              | 4765.6      | 0            |
|                  |                                                       |               | AFL                                               |             | 315             |     |                  | 802         |                     |             | 0            |
|                  |                                                       |               | MOS                                               |             | 28.7            |     | 48               | 21 Dec 2023 | 31 Dec 2027         | 31 Jan 2028 |              |
|                  | Airframe                                              |               | [End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50] |             |                 |     |                  |             |                     |             |              |
|                  |                                                       | 052004,052013 |                                                   |             |                 |     |                  |             |                     |             |              |
| 783113           | T/Rev and Exhaust Internal (Right) - Zonal Inspection |               | HRS                                               |             | 730.5           |     | 2400             | 2315.6      | 4715.6              | 4765.6      | 0            |
|                  |                                                       |               | AFL                                               |             | 315             |     |                  | 802         |                     |             | 0            |
|                  |                                                       |               | MOS                                               |             | 28.7            |     | 48               | 21 Dec 2023 | 31 Dec 2027         | 31 Jan 2028 |              |
|                  | Airframe                                              |               | [End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50] |             |                 |     |                  |             |                     |             |              |
|                  |                                                       | 052004,052013 |                                                   |             |                 |     |                  |             |                     |             |              |
| 783114           | T/Rev Hirf/L (Left) - Detailed Inspection             |               | HRS                                               |             | 730.5           |     | 2400             | 2315.6      | 4715.6              | 4765.6      | 0            |
|                  |                                                       |               | AFL                                               |             | 315             |     |                  | 802         |                     |             | 0            |
|                  |                                                       |               | MOS                                               |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031         | 31 Jan 2032 |              |
|                  | Airframe                                              |               | [End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50] |             |                 |     |                  |             |                     |             |              |
|                  |                                                       | 052004        |                                                   |             |                 |     |                  |             |                     |             |              |
| 783115           | T/Rev Hirf/L (Right) - Detailed Inspection            |               | HRS                                               |             | 730.5           |     | 2400             | 2315.6      | 4715.6              | 4765.6      | 0            |
|                  |                                                       |               | AFL                                               |             | 315             |     |                  | 802         |                     |             | 0            |
|                  |                                                       |               | MOS                                               |             | 28.7            |     | 96               | 21 Dec 2023 | 31 Dec 2031         | 31 Jan 2032 |              |
|                  | Airframe                                              |               | [End Of Month Item] [MOS: +1m/-1m] [HRS: +50/-50] |             |                 |     |                  |             |                     |             |              |
|                  |                                                       | 052004        |                                                   |             |                 |     |                  |             |                     |             |              |
| 783116           | T/Rev (Left) - Bleed Procedure                        |               | HRS                                               |             | 137             |     |                  | 2909.1      |                     |             | 0            |
|                  |                                                       |               | AFL                                               |             | 52              |     |                  | 1065        |                     |             | 0            |
|                  |                                                       |               | MOS                                               |             | 5               |     |                  | 12 Dec 2025 |                     |             |              |
|                  | Airframe                                              |               | MSC                                               |             |                 |     | O/C              |             |                     |             |              |
| 783117           | T/Rev (Right) - Bleed Procedure                       |               | HRS                                               |             | 994.2           |     |                  | 2051.9      |                     |             | 0            |
|                  |                                                       |               | AFL                                               |             | 392             |     |                  | 725         |                     |             | 0            |
|                  |                                                       |               | MOS                                               |             | 41              |     |                  | 12 Dec 2022 |                     |             |              |
|                  | Airframe                                              |               | MSC                                               |             |                 |     | O/C              |             |                     |             |              |
| 783130           | Batwing (Left) - Adjustment                           |               | HRS                                               |             | 3046.1          |     |                  | 0           |                     |             | 0            |
|                  |                                                       |               | AFL                                               |             | 1117            |     |                  | 0           |                     |             | 0            |
|                  |                                                       |               | MOS                                               |             | 128.6           |     |                  | 24 Aug 2015 |                     |             |              |
|                  | Airframe                                              |               | MSC                                               |             |                 |     | O/C              |             |                     |             |              |

| ATA<br>U=Custom  | Description                                                  |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|--------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                  | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                           | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                       |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                |               |     |             |                 |     |                  |             |                    |         |              |
| 783131           | Batwing (Right) - Adjustment                                 |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                              |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                              |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                              |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                              |               |     |             |                 |     |                  |             |                    |         |              |
| 783200           | Primary Lock Assembly Gap (Left) - Inspection                |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                              |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                              |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                              |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                              |               |     |             |                 |     |                  |             |                    |         |              |
| 783201           | Primary Lock Assembly Gap (Right) - Inspection               |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                              |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                              |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                              |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                              |               |     |             |                 |     |                  |             |                    |         |              |
| 783300           | T/Rev Upper Pivoting Door (Left) - Removal / Installation    |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | RD00103040-5                                                 | SN-UNKNOWN    | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                              |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                              |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                              |               |     |             |                 |     |                  |             |                    |         |              |
| 783301           | T/Rev Upper Pivoting Door (Right) - Removal / Installation   |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | RD00103040-5                                                 | SN-UNKNOWN    | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                              |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                              |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                              |               |     |             |                 |     |                  |             |                    |         |              |
| 783302           | T/Rev Lower Pivoting Door (Left) - Removal / Installation    |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | RD00103040-7                                                 | SN-UNKNOWN    | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                              |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                              |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                              |               |     |             |                 |     |                  |             |                    |         |              |
| 783303           | T/Rev Lower Pivoting Door (Right) - Removal / Installation   |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | RD00103040-7                                                 | SN-UNKNOWN    | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                              |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                              |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                              |               |     |             |                 |     |                  |             |                    |         |              |
| 783308           | Pivoting Door Actuator (Left Upper) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                              |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | RD001C0001-20                                                | 19997487      | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                              |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                              |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                   |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|---------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                                   | Serial Number |     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                            | SW            |     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                        |               |     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                                 |               |     |             |                 |     |                  |             |                     |         |              |
| 783309           | Pivoting Door Actuator (Right Upper) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                               |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | RD001C0001-20                                                 | 19979142      | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                               |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                               |               |     |             |                 |     |                  |             |                     |         |              |
| 783310           | Pivoting Door Actuator (Left Lower) - Removal / Installation  |               | HRS |             | 137             |     |                  | 2909.1      |                     |         | 0            |
|                  |                                                               |               | AFL |             | 52              |     |                  | 1065        |                     |         | 0            |
|                  | RD001C0001-20                                                 | A0112914      | MOS |             | 5               |     |                  | 10 Dec 2025 |                     |         |              |
|                  |                                                               |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                               |               |     |             |                 |     |                  |             |                     |         |              |
| 783311           | Pivoting Door Actuator (Right Lower) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                               |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | RD001C0001-20                                                 | 19997490      | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                               |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                               |               |     |             |                 |     |                  |             |                     |         |              |
| 783316           | Direction Control Unit (Left) - Removal / Installation        |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                               |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | RD001C0001-34                                                 | 19997483      | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                               |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                               |               |     |             |                 |     |                  |             |                     |         |              |
| 783317           | Direction Control Unit (Right) - Removal / Installation       |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                               |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | RD001C0001-34                                                 | 19997480      | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                               |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                               |               |     |             |                 |     |                  |             |                     |         |              |
| 783320           | Isolation Control Unit Filter Element - Replacement           |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                               |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | RD001C0001-27                                                 | 19988237      | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                               |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                               |               |     |             |                 |     |                  |             |                     |         |              |
| 783321           | Isolation Control Unit Filter Element - Replacement           |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                               |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | RD001C0001-27                                                 | 20011556      | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                               |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                               |               |     |             |                 |     |                  |             |                     |         |              |
| 783324           | Tertiary Lock Actuator (Left Upper) - Removal / Installation  |               | HRS |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                               |               | AFL |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | RD001C0001-29                                                 | 20011580      | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  |                                                               |               | MSC |             |                 |     | O/C              |             |                     |         |              |
| Airframe         |                                                               |               |     |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom  | Description                                                            |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                            | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                     | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                 |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| 783325           | Tertiary Lock Actuator (Right Upper) - Removal / Installation          |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                        |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | RD001C0001-29                                                          | 19988250      | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 783326           | Tertiary Lock Actuator (Left Lower) - Removal / Installation           |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                        |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | RD001C0001-29                                                          | 20011576      | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 783327           | Tertiary Lock Actuator (Right Lower) - Removal / Installation          |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                        |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | RD001C0001-29                                                          | 19988251      | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 783332           | Primary Lock Actuator (Left Engine Outboard) - Removal / Installation  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                        |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | RD001C0001-4                                                           | 20030358      | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 783333           | Primary Lock Actuator (Right Engine Outboard) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                        |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | RD001C0001-4                                                           | 19978974      | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 783334           | Primary Lock Actuator (Left Engine Inboard) - Removal / Installation   |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                        |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | RD001C0001-4                                                           | 19988308      | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 783335           | Primary Lock Actuator (Right Engine Inboard) - Removal / Installation  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                        |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | RD001C0001-4                                                           | 19978975      | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                        |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                              |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                              | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                                       | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                                   |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                                            |               |     |             |                 |     |                  |             |                    |         |              |
| 783376           | Primary Lock Assembly (Left Outboard) - Adjustment                                       |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                          |               | AFL |             | 1117            |     |                  | 0           |                    | 0       |              |
|                  |                                                                                          |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                          |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| 783377           | Primary Lock Assembly (Right Outboard) - Adjustment                                      |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                          |               | AFL |             | 1117            |     |                  | 0           |                    | 0       |              |
|                  |                                                                                          |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                          |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| 783378           | Primary Lock Assembly (Left Inboard) - Adjustment                                        |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                          |               | AFL |             | 1117            |     |                  | 0           |                    | 0       |              |
|                  |                                                                                          |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                          |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| 783379           | Primary Lock Assembly (Right Inboard) - Adjustment                                       |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                                          |               | AFL |             | 1117            |     |                  | 0           |                    | 0       |              |
|                  |                                                                                          |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                                          |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| 783400           | Door Stow Switch (Left Inboard Upper) - Removal /<br>Installation<br>RD001C0001-3201718  |               | HRS | TSN:2315.6  | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  |                                                                                          |               | AFL | TSN:802     | 315             |     |                  | 802         |                    | 0       |              |
|                  |                                                                                          |               | MOS | TSN:99      | 29.9            |     |                  | 13 Nov 2023 |                    |         |              |
|                  |                                                                                          |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| 783401           | Door Stow Switch (Right Inboard Upper) - Removal /<br>Installation<br>RD001C0001-3201409 |               | HRS | TSN:2315.6  | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  |                                                                                          |               | AFL | TSN:802     | 315             |     |                  | 802         |                    | 0       |              |
|                  |                                                                                          |               | MOS | TSN:99      | 29.9            |     |                  | 13 Nov 2023 |                    |         |              |
|                  |                                                                                          |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| 783402           | Door Stow Switch (Left Outboard Upper) - Removal /<br>Installation<br>RD001C0001-3201712 |               | HRS | TSN:2315.6  | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  |                                                                                          |               | AFL | TSN:802     | 315             |     |                  | 802         |                    | 0       |              |
|                  |                                                                                          |               | MOS | TSN:99      | 29.9            |     |                  | 13 Nov 2023 |                    |         |              |
|                  |                                                                                          |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                                          |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                            |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                            | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                     | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                 |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| 783403           | Door Stow Switch (Right Outboard Upper) - Removal / Installation       |               | HRS | TSN:2315.6  | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  |                                                                        |               | AFL | TSN:802     | 315             |     |                  | 802         |                    |         | 0            |
|                  | RD001C0001-32                                                          | 01462         | MOS | TSN:99      | 29.9            |     |                  | 13 Nov 2023 |                    |         |              |
|                  |                                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 783404           | Door Stow Switch (Left Inboard Lower) - Removal / Installation         |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                        |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | RD001C0001-32                                                          | 01731         | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 783405           | Door Stow Switch (Right Inboard Lower) - Removal / Installation        |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                        |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | RD001C0001-32                                                          | 01626         | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 783406           | Door Stow Switch (Left Outboard Lower) - Removal / Installation        |               | HRS | TSN:2315.6  | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  |                                                                        |               | AFL | TSN:802     | 315             |     |                  | 802         |                    |         | 0            |
|                  | RD001C0001-32                                                          | 01714         | MOS | TSN:99      | 29.9            |     |                  | 13 Nov 2023 |                    |         |              |
|                  |                                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 783407           | Door Stow Switch (Right Outboard Lower) - Removal / Installation       |               | HRS | TSN:2315.6  | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  |                                                                        |               | AFL | TSN:802     | 315             |     |                  | 802         |                    |         | 0            |
|                  | RD001C0001-32                                                          | 01423         | MOS | TSN:99      | 29.9            |     |                  | 13 Nov 2023 |                    |         |              |
|                  |                                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 783416           | Door Position Transducer (Left Engine Upper) - Removal / Installation  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                        |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | RD001C0001-24                                                          | ET2244-10753  | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 783417           | Door Position Transducer (Right Engine Upper) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                        |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | RD001C0001-24                                                          | ET2244-10744  | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                        |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                            |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                            | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                     | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                 |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| 783418           | Door Position Transducer (Left Engine Lower) - Removal / Installation  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                        |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | RD001C0001-24                                                          | ET2244-10756  | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 783419           | Door Position Transducer (Right Engine Lower) - Removal / Installation |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                        |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  | RD001C0001-24                                                          | ET2244-10699  | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 783424           | Door Position Transducer (Lvdt, Left Engine Upper) - Adjustment        |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                        |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                        |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 783425           | Door Position Transducer (Lvdt, Right Engine Upper) - Adjustment       |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                        |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                        |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 783426           | Door Position Transducer (Lvdt, Left Engine Lower) - Adjustment        |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                        |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                        |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 783427           | Door Position Transducer (Lvdt, Right Engine Lower) - Adjustment       |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                        |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                        |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| 783436           | Tertiary Lock (Left) - Functional Test                                 |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                                        |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                                        |               | MOS |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  |                                                                        |               | MSC |             |                 |     | O/C              |             |                    |         |              |
| Airframe         |                                                                        |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                | Serial Number |                     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                         | SW            |                     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                     |               |                     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                              |               |                     |             |                 |     |                  |             |                    |         |              |
| 783437           | Tertiary Lock (Right) - Functional Test                    |               | HRS                 |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  |                                                            |               | AFL                 |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                            |               | MOS                 |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                  | Airframe                                                   |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
| 789999           | No. 1 Engine - Available Code                              |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | PN                                                         | SN-UNKNOWN    | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                            |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                                     |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  |                                                            |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 789999           | No. 2 Engine - Available Code                              |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | PN                                                         | SN-UNKNOWN    | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                            |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                                     |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  |                                                            |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 79 - Oil         |                                                            |               |                     |             |                 |     |                  |             |                    |         |              |
| 790001           | No. 1 Engine - Oil Filter POP-Up Indicator - Removal /     |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | Installation                                               |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | QA07508                                                    | RJ7-1012      | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                                     |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  |                                                            |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 790001           | No. 2 Engine - Oil Filter POP-Up Indicator - Removal /     |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | Installation                                               |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | QA07508                                                    | RJ7-1015      | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                                     |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  |                                                            |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 790003           | No. 1 Engine - Oil Pressure Differential Pressure Switch - |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | Removal / Installation                                     |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | PN                                                         | SN-UNKNOWN    | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                                     |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  |                                                            |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 790003           | No. 2 Engine - Oil Pressure Differential Pressure Switch - |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | Removal / Installation                                     |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | PN                                                         | SN-UNKNOWN    | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                                     |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  |                                                            |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |



| ATA<br>U=Custom  | Description                                                             |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(* =Adj) | Max Due | Avg Man Hrs  |
|------------------|-------------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|----------------------|---------|--------------|
|                  | Part Number                                                             | Serial Number |                     |             |                 |     |                  |             |                      |         | Approx Price |
| Logbook Position | HW                                                                      | SW            |                     |             |                 |     |                  |             |                      |         | Manufacturer |
|                  | MM Ref                                                                  |               |                     |             |                 |     |                  |             |                      |         | Date Type    |
|                  | Ops Number(s)                                                           |               |                     |             |                 |     |                  |             |                      |         |              |
| 790005           | No. 1 Engine - Restrictor Check Valve - Removal / Installation          |               | HRS                 |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                  |                                                                         |               | ENC                 |             | 392             |     |                  | 0           |                      |         | 0            |
|                  | PN                                                                      | SN-UNKNOWN    | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                      |         |              |
|                  |                                                                         |               | MSC                 |             |                 |     | O/C              |             |                      |         |              |
|                  | Engine                                                                  |               | [End Of Month Item] |             |                 |     |                  |             |                      |         |              |
| 790005           | No. 2 Engine - Restrictor Check Valve - Removal / Installation          |               | HRS                 |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                  |                                                                         |               | ENC                 |             | 392             |     |                  | 0           |                      |         | 0            |
|                  | PN                                                                      | SN-UNKNOWN    | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                      |         |              |
|                  |                                                                         |               | MSC                 |             |                 |     | O/C              |             |                      |         |              |
|                  | Engine                                                                  |               | [End Of Month Item] |             |                 |     |                  |             |                      |         |              |
| 790007           | No. 1 Engine - Engine Oil System Check for Contamination                |               | HRS                 |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                  |                                                                         |               | ENC                 |             | 392             |     |                  | 0           |                      |         | 0            |
|                  |                                                                         |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                      |         |              |
|                  |                                                                         |               | MSC                 |             |                 |     | O/C              |             |                      |         |              |
|                  | Engine                                                                  |               | [End Of Month Item] |             |                 |     |                  |             |                      |         |              |
| 790007           | No. 2 Engine - Engine Oil System Check for Contamination                |               | HRS                 |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                  |                                                                         |               | ENC                 |             | 392             |     |                  | 0           |                      |         | 0            |
|                  |                                                                         |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                      |         |              |
|                  |                                                                         |               | MSC                 |             |                 |     | O/C              |             |                      |         |              |
|                  | Engine                                                                  |               | [End Of Month Item] |             |                 |     |                  |             |                      |         |              |
| 790008           | No. 1 Engine - Oil System Pressure Filter POP-Up Indicator - Inspection |               | HRS                 |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                  |                                                                         |               | ENC                 |             | 392             |     |                  | 0           |                      |         | 0            |
|                  |                                                                         |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                      |         |              |
|                  |                                                                         |               | MSC                 |             |                 |     | O/C              |             |                      |         |              |
|                  | Engine                                                                  |               | [End Of Month Item] |             |                 |     |                  |             |                      |         |              |
| 790008           | No. 2 Engine - Oil System Pressure Filter POP-Up Indicator - Inspection |               | HRS                 |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                  |                                                                         |               | ENC                 |             | 392             |     |                  | 0           |                      |         | 0            |
|                  |                                                                         |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                      |         |              |
|                  |                                                                         |               | MSC                 |             |                 |     | O/C              |             |                      |         |              |
|                  | Engine                                                                  |               | [End Of Month Item] |             |                 |     |                  |             |                      |         |              |
| 791000           | No. 1 Engine - Engine Oil System - Draining                             |               | HRS                 |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                  |                                                                         |               | ENC                 |             | 392             |     |                  | 0           |                      |         | 0            |
|                  |                                                                         |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                      |         |              |
|                  |                                                                         |               | MSC                 |             |                 |     | O/C              |             |                      |         |              |
|                  | Engine                                                                  |               | [End Of Month Item] |             |                 |     |                  |             |                      |         |              |

| ATA<br>U=Custom  | Description                                                      |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                                      | Serial Number |                     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                               | SW            |                     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                           |               |                     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                                    |               |                     |             |                 |     |                  |             |                     |         |              |
| 791000           | No. 2 Engine - Engine Oil System - Draining                      |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                  |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                                                  |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  | Engine                                                           |               |                     | MSC         |                 |     | O/C              |             |                     |         |              |
|                  |                                                                  |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 791300           | Oil Servicing Reservoir - Removal / Installation                 |               | HRS                 |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  | 1159SCP565-3                                                     | 1211          | AFL                 |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  |                                                                  |               | MOS                 |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  | Airframe                                                         |               |                     | MSC         |                 |     | O/C              |             |                     |         |              |
|                  |                                                                  |               |                     |             |                 |     |                  |             |                     |         |              |
| 791301           | Oil Servicing Selector Valve - Removal / Installation            |               | HRS                 |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  | 1159SCP105-1                                                     | 1354          | AFL                 |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  |                                                                  |               | MOS                 |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  | Airframe                                                         |               |                     | MSC         |                 |     | O/C              |             |                     |         |              |
|                  |                                                                  |               |                     |             |                 |     |                  |             |                     |         |              |
| 791314           | Engine and APU Oil Servicing System - Test and Operational Check |               | HRS                 |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                  |               | AFL                 |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  |                                                                  |               | MOS                 |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  | Airframe                                                         |               |                     | MSC         |                 |     | O/C              |             |                     |         |              |
|                  |                                                                  |               |                     |             |                 |     |                  |             |                     |         |              |
| 791315           | Engine and APU Oil Servicing Pump - Removal / Installation       |               | HRS                 |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  |                                                                  |               | AFL                 |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | 1B5-17                                                           | 4BM27         | MOS                 |             | 128.6           |     |                  | 24 Aug 2015 |                     |         |              |
|                  | Airframe                                                         |               |                     | MSC         |                 |     | O/C              |             |                     |         |              |
|                  |                                                                  |               |                     |             |                 |     |                  |             |                     |         |              |
| 792100           | No. 1 Engine - Oil Pump - Removal / Installation                 |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | LR47980A                                                         | C1197         | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                                                  |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  | Engine                                                           |               |                     | MSC         |                 |     | O/C              |             |                     |         |              |
|                  |                                                                  |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 792100           | No. 2 Engine - Oil Pump - Removal / Installation                 |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  | LR47980B                                                         | C1201         | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                                                  |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  | Engine                                                           |               |                     | MSC         |                 |     | O/C              |             |                     |         |              |
|                  |                                                                  |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 792102           | No. 1 Engine - Oil Pump Spline Coupling - Inspection             |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                  |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                                                  |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  | Engine                                                           |               |                     | MSC         |                 |     | O/C              |             |                     |         |              |
|                  |                                                                  |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom  | Description                                                                   |                     | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due     | Avg Man Hrs  |  |
|------------------|-------------------------------------------------------------------------------|---------------------|-----|-------------|-----------------|-----|------------------|-------------|---------------------|-------------|--------------|--|
|                  | Part Number                                                                   | Serial Number       |     |             |                 |     |                  |             |                     |             | Approx Price |  |
| Logbook Position | HW                                                                            | SW                  |     |             |                 |     |                  |             |                     |             | Manufacturer |  |
|                  | MM Ref                                                                        |                     |     |             |                 |     |                  |             |                     |             | Date Type    |  |
|                  | Ops Number(s)                                                                 |                     |     |             |                 |     |                  |             |                     |             |              |  |
| 792102           | No. 2 Engine - Oil Pump Spline Coupling - Inspection                          |                     | HRS |             | 994.4           |     |                  | 0           |                     |             | 0            |  |
|                  |                                                                               |                     | ENC |             | 392             |     |                  | 0           |                     | 0           |              |  |
|                  |                                                                               |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                     |             |              |  |
|                  |                                                                               |                     | MSC |             |                 |     | O/C              |             |                     |             |              |  |
|                  | Engine                                                                        | [End Of Month Item] |     |             |                 |     |                  |             |                     |             |              |  |
| 792103           | No. 1 Engine - Oil Pump Seal Plate - Inspection                               |                     | HRS |             | 994.4           |     |                  | 0           |                     |             | 0            |  |
|                  |                                                                               |                     | ENC |             | 392             |     |                  | 0           |                     | 0           |              |  |
|                  |                                                                               |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                     |             |              |  |
|                  |                                                                               |                     | MSC |             |                 |     | O/C              |             |                     |             |              |  |
|                  | Engine                                                                        | [End Of Month Item] |     |             |                 |     |                  |             |                     |             |              |  |
| 792103           | No. 2 Engine - Oil Pump Seal Plate - Inspection                               |                     | HRS |             | 994.4           |     |                  | 0           |                     |             | 0            |  |
|                  |                                                                               |                     | ENC |             | 392             |     |                  | 0           |                     | 0           |              |  |
|                  |                                                                               |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                     |             |              |  |
|                  |                                                                               |                     | MSC |             |                 |     | O/C              |             |                     |             |              |  |
|                  | Engine                                                                        | [End Of Month Item] |     |             |                 |     |                  |             |                     |             |              |  |
| 792104           | No. 1 Engine - Oil System Pressure Filter Element -<br>Removal / Installation |                     | HRS |             | 994.4           |     |                  | 0           |                     |             | 0            |  |
|                  |                                                                               |                     | ENC |             | 392             |     |                  | 0           |                     | 0           |              |  |
|                  |                                                                               |                     | PN  | SN-UNKNOWN  | MOS             |     | 41.8             |             |                     | 17 Nov 2022 |              |  |
|                  |                                                                               |                     | MSC |             |                 |     | O/C              |             |                     |             |              |  |
|                  | Engine                                                                        | [End Of Month Item] |     |             |                 |     |                  |             |                     |             |              |  |
| 792104           | No. 2 Engine - Oil System Pressure Filter Element -<br>Removal / Installation |                     | HRS |             | 994.4           |     |                  | 0           |                     |             | 0            |  |
|                  |                                                                               |                     | ENC |             | 392             |     |                  | 0           |                     | 0           |              |  |
|                  |                                                                               |                     | PN  | SN-UNKNOWN  | MOS             |     | 41.9             |             |                     | 15 Nov 2022 |              |  |
|                  |                                                                               |                     | MSC |             |                 |     | O/C              |             |                     |             |              |  |
|                  | Engine                                                                        | [End Of Month Item] |     |             |                 |     |                  |             |                     |             |              |  |
| 792105           | No. 1 Engine - Oil System Pressure Filter Element -<br>Replacement            |                     | HRS |             | 994.4           |     |                  | 0           |                     |             | 0            |  |
|                  |                                                                               |                     | ENC |             | 392             |     |                  | 0           |                     | 0           |              |  |
|                  |                                                                               |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                     |             |              |  |
|                  |                                                                               |                     | MSC |             |                 |     | O/C              |             |                     |             |              |  |
|                  | Engine                                                                        | [End Of Month Item] |     |             |                 |     |                  |             |                     |             |              |  |
| 792105           | No. 2 Engine - Oil System Pressure Filter Element -<br>Replacement            |                     | HRS |             | 994.4           |     |                  | 0           |                     |             | 0            |  |
|                  |                                                                               |                     | ENC |             | 392             |     |                  | 0           |                     | 0           |              |  |
|                  |                                                                               |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                     |             |              |  |
|                  |                                                                               |                     | MSC |             |                 |     | O/C              |             |                     |             |              |  |
|                  | Engine                                                                        | [End Of Month Item] |     |             |                 |     |                  |             |                     |             |              |  |

| ATA<br>U=Custom     | Description                                                                          |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(* =Adj) | Max Due | Avg Man Hrs  |
|---------------------|--------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|----------------------|---------|--------------|
|                     | Part Number                                                                          | Serial Number |     |             |                 |     |                  |             |                      |         | Approx Price |
| Logbook Position    | HW                                                                                   | SW            |     |             |                 |     |                  |             |                      |         | Manufacturer |
|                     | MM Ref                                                                               |               |     |             |                 |     |                  |             |                      |         | Date Type    |
|                     | Ops Number(s)                                                                        |               |     |             |                 |     |                  |             |                      |         |              |
| 792106              | No. 1 Engine - Oil System Pressure Filter Element - Discard                          |               | HRS |             | 994.4           |     | 1200             | 0           | 1200                 | 1250    | 0            |
|                     |                                                                                      |               | ENC |             | 392             |     |                  | 0           |                      |         | 0            |
|                     | PN                                                                                   | SN-UNKNOWN    | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                      |         |              |
|                     | [End Of Month Item] [HRS: +50/-50]                                                   |               |     |             |                 |     |                  |             |                      |         |              |
| Engine              |                                                                                      |               |     |             |                 |     |                  |             |                      |         |              |
| 792106              | No. 2 Engine - Oil System Pressure Filter Element - Discard                          |               | HRS |             | 994.4           |     | 1200             | 0           | 1200                 | 1250    | 0            |
|                     |                                                                                      |               | ENC |             | 392             |     |                  | 0           |                      |         | 0            |
|                     | PN                                                                                   | SN-UNKNOWN    | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                      |         |              |
|                     | [End Of Month Item] [HRS: +50/-50]                                                   |               |     |             |                 |     |                  |             |                      |         |              |
| Engine              |                                                                                      |               |     |             |                 |     |                  |             |                      |         |              |
| 792107              | No. 1 Engine - Oil System Pressure Filter Element - Inspection                       |               | HRS |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                     |                                                                                      |               | ENC |             | 392             |     |                  | 0           |                      |         | 0            |
|                     |                                                                                      |               | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                      |         |              |
|                     |                                                                                      |               | MSC |             |                 |     | O/C              |             |                      |         |              |
| [End Of Month Item] |                                                                                      |               |     |             |                 |     |                  |             |                      |         |              |
| Engine              |                                                                                      |               |     |             |                 |     |                  |             |                      |         |              |
| 792107              | No. 2 Engine - Oil System Pressure Filter Element - Inspection                       |               | HRS |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                     |                                                                                      |               | ENC |             | 392             |     |                  | 0           |                      |         | 0            |
|                     |                                                                                      |               | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                      |         |              |
|                     |                                                                                      |               | MSC |             |                 |     | O/C              |             |                      |         |              |
| [End Of Month Item] |                                                                                      |               |     |             |                 |     |                  |             |                      |         |              |
| Engine              |                                                                                      |               |     |             |                 |     |                  |             |                      |         |              |
| 792108              | No. 1 Engine - Oil Tubes and Fittings - Inspection                                   |               | HRS |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                     |                                                                                      |               | ENC |             | 392             |     |                  | 0           |                      |         | 0            |
|                     |                                                                                      |               | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                      |         |              |
|                     |                                                                                      |               | MSC |             |                 |     | O/C              |             |                      |         |              |
| [End Of Month Item] |                                                                                      |               |     |             |                 |     |                  |             |                      |         |              |
| Engine              |                                                                                      |               |     |             |                 |     |                  |             |                      |         |              |
| 792108              | No. 2 Engine - Oil Tubes and Fittings - Inspection                                   |               | HRS |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                     |                                                                                      |               | ENC |             | 392             |     |                  | 0           |                      |         | 0            |
|                     |                                                                                      |               | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                      |         |              |
|                     |                                                                                      |               | MSC |             |                 |     | O/C              |             |                      |         |              |
| [End Of Month Item] |                                                                                      |               |     |             |                 |     |                  |             |                      |         |              |
| Engine              |                                                                                      |               |     |             |                 |     |                  |             |                      |         |              |
| 792109              | No. 1 Engine - Magnetic Chip Detectors (Front Bearing Chamber) - Detailed Inspection |               | HRS |             | 137             | 6.5 | 600              | 857.4       | 1463.9*              | 1513.9  | 0            |
|                     |                                                                                      |               | ENC |             | 52              |     |                  | 340         |                      |         | 0            |
|                     |                                                                                      |               | MOS |             | 5.4             |     |                  | 29 Nov 2025 |                      |         |              |
|                     | [End Of Month Item] [HRS: +50/-50]                                                   |               |     |             |                 |     |                  |             |                      |         |              |
| Engine              |                                                                                      |               |     |             |                 |     |                  |             |                      |         |              |
| 052001              |                                                                                      |               |     |             |                 |     |                  |             |                      |         |              |

| ATA<br>U=Custom  | Description                                                                                              |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                                              | Serial Number |                                    |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                                                       | SW            |                                    |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                                                   |               |                                    |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                                                            |               |                                    |             |                 |     |                  |             |                    |         |              |
| 792109           | No. 2 Engine - Magnetic Chip Detectors (Front Bearing Chamber) - Detailed Inspection                     |               | HRS                                |             | 137             | 6.5 | 600              | 857.4       | 1463.9*            | 1513.9  | 0            |
|                  |                                                                                                          |               | ENC                                |             | 52              |     |                  | 340         |                    |         | 0            |
|                  |                                                                                                          |               | MOS                                |             | 5.4             |     |                  | 29 Nov 2025 |                    |         |              |
|                  |                                                                                                          |               | [End Of Month Item] [HRS: +50/-50] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                                                                          |               | 052001                             |             |                 |     |                  |             |                    |         |              |
| 792110           | No. 1 Engine - Magnetic Chip Detectors (Rear Bearing Chamber) - Detailed Inspection                      |               | HRS                                |             | 137             | 6.5 | 600              | 857.4       | 1463.9*            | 1513.9  | 0            |
|                  |                                                                                                          |               | ENC                                |             | 52              |     |                  | 340         |                    |         | 0            |
|                  |                                                                                                          |               | MOS                                |             | 5.5             |     |                  | 27 Nov 2025 |                    |         |              |
|                  |                                                                                                          |               | [End Of Month Item] [HRS: +50/-50] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                                                                          |               | 052001                             |             |                 |     |                  |             |                    |         |              |
| 792110           | No. 2 Engine - Magnetic Chip Detectors (Rear Bearing Chamber) - Detailed Inspection                      |               | HRS                                |             | 137             | 6.5 | 600              | 857.4       | 1463.9*            | 1513.9  | 0            |
|                  |                                                                                                          |               | ENC                                |             | 52              |     |                  | 340         |                    |         | 0            |
|                  |                                                                                                          |               | MOS                                |             | 5.5             |     |                  | 27 Nov 2025 |                    |         |              |
|                  |                                                                                                          |               | [End Of Month Item] [HRS: +50/-50] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                                                                          |               | 052001                             |             |                 |     |                  |             |                    |         |              |
| 792111           | No. 1 Engine - Magnetic Chip Detectors (Accessory Gearbox) - Detailed Inspection                         |               | HRS                                |             | 137             | 6.5 | 600              | 857.4       | 1463.9*            | 1513.9  | 0            |
|                  |                                                                                                          |               | ENC                                |             | 52              |     |                  | 340         |                    |         | 0            |
|                  |                                                                                                          |               | MOS                                |             | 5.5             |     |                  | 27 Nov 2025 |                    |         |              |
|                  |                                                                                                          |               | [End Of Month Item] [HRS: +50/-50] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                                                                          |               | 052001                             |             |                 |     |                  |             |                    |         |              |
| 792111           | No. 2 Engine - Magnetic Chip Detectors (Accessory Gearbox) - Detailed Inspection                         |               | HRS                                |             | 137             | 6.5 | 600              | 857.4       | 1463.9*            | 1513.9  | 0            |
|                  |                                                                                                          |               | ENC                                |             | 52              |     |                  | 340         |                    |         | 0            |
|                  |                                                                                                          |               | MOS                                |             | 5.5             |     |                  | 27 Nov 2025 |                    |         |              |
|                  |                                                                                                          |               | [End Of Month Item] [HRS: +50/-50] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                                                                          |               | 052001                             |             |                 |     |                  |             |                    |         |              |
| 792112           | No. 1 Engine - Transfer of Electromagnetic Chip Detector (Front Bearing Chamber to Rear Bearing Chamber) |               | HRS                                |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                          |               | ENC                                |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                          |               | MOS                                |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                                                          |               | MSC                                |             |                 |     | O/C              |             |                    |         |              |
| Engine           |                                                                                                          |               | [End Of Month Item]                |             |                 |     |                  |             |                    |         |              |
| 792112           | No. 2 Engine - Transfer of Electromagnetic Chip Detector (Front Bearing Chamber to Rear Bearing Chamber) |               | HRS                                |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                          |               | ENC                                |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                          |               | MOS                                |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                                                          |               | MSC                                |             |                 |     | O/C              |             |                    |         |              |
| Engine           |                                                                                                          |               | [End Of Month Item]                |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                                                                     |               | UOM        | Times Since         | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(* = Adj) | Max Due | Avg Man Hrs  |
|------------------|---------------------------------------------------------------------------------------------------------------------------------|---------------|------------|---------------------|-----------------|-----|------------------|----------|-----------------------|---------|--------------|
|                  | Part Number                                                                                                                     | Serial Number |            |                     |                 |     |                  |          |                       |         | Approx Price |
| Logbook Position | HW                                                                                                                              | SW            |            |                     |                 |     |                  |          |                       |         | Manufacturer |
|                  | MM Ref                                                                                                                          |               |            |                     |                 |     |                  |          |                       |         | Date Type    |
|                  | Ops Number(s)                                                                                                                   |               |            |                     |                 |     |                  |          |                       |         |              |
| 792113           | No. 1 Engine - Transfer of Electromagnetic Chip Detector<br>(Front Bearing Chamber to Accessory Gearbox)                        |               | HRS        |                     | 994.4           |     |                  | 0        |                       | 0       |              |
|                  |                                                                                                                                 |               | ENC        |                     | 392             |     |                  | 0        |                       | 0       |              |
|                  |                                                                                                                                 |               | MOS        |                     | 41.8            |     | 17 Nov 2022      |          |                       |         |              |
|                  |                                                                                                                                 |               | MSC        |                     |                 | O/C |                  |          |                       |         |              |
|                  | Engine                                                                                                                          |               |            | [End Of Month Item] |                 |     |                  |          |                       |         |              |
| 792113           | No. 2 Engine - Transfer of Electromagnetic Chip Detector<br>(Front Bearing Chamber to Accessory Gearbox)                        |               | HRS        |                     | 994.4           |     |                  | 0        |                       | 0       |              |
|                  |                                                                                                                                 |               | ENC        |                     | 392             |     |                  | 0        |                       | 0       |              |
|                  |                                                                                                                                 |               | MOS        |                     | 41.9            |     | 15 Nov 2022      |          |                       |         |              |
|                  |                                                                                                                                 |               | MSC        |                     |                 | O/C |                  |          |                       |         |              |
|                  | Engine                                                                                                                          |               |            | [End Of Month Item] |                 |     |                  |          |                       |         |              |
| 792114           | No. 1 Engine - Transfer of Electromagnetic Chip Detector<br>(Rear Bearing Chamber to Front Bearing Chamber)                     |               | HRS        |                     | 994.4           |     |                  | 0        |                       | 0       |              |
|                  |                                                                                                                                 |               | ENC        |                     | 392             |     |                  | 0        |                       | 0       |              |
|                  |                                                                                                                                 |               | MOS        |                     | 41.8            |     | 17 Nov 2022      |          |                       |         |              |
|                  |                                                                                                                                 |               | MSC        |                     |                 | O/C |                  |          |                       |         |              |
|                  | Engine                                                                                                                          |               |            | [End Of Month Item] |                 |     |                  |          |                       |         |              |
| 792114           | No. 2 Engine - Transfer of Electromagnetic Chip Detector<br>(Rear Bearing Chamber to Front Bearing Chamber)                     |               | HRS        |                     | 994.4           |     |                  | 0        |                       | 0       |              |
|                  |                                                                                                                                 |               | ENC        |                     | 392             |     |                  | 0        |                       | 0       |              |
|                  |                                                                                                                                 |               | MOS        |                     | 41.9            |     | 15 Nov 2022      |          |                       |         |              |
|                  |                                                                                                                                 |               | MSC        |                     |                 | O/C |                  |          |                       |         |              |
|                  | Engine                                                                                                                          |               |            | [End Of Month Item] |                 |     |                  |          |                       |         |              |
| 792115           | No. 1 Engine - Transfer of Electromagnetic Chip Detector<br>(Accessory Gearbox to Front Bearing Chamber)                        |               | HRS        |                     | 994.4           |     |                  | 0        |                       | 0       |              |
|                  |                                                                                                                                 |               | ENC        |                     | 392             |     |                  | 0        |                       | 0       |              |
|                  |                                                                                                                                 |               | MOS        |                     | 41.8            |     | 17 Nov 2022      |          |                       |         |              |
|                  |                                                                                                                                 |               | MSC        |                     |                 | O/C |                  |          |                       |         |              |
|                  | Engine                                                                                                                          |               |            | [End Of Month Item] |                 |     |                  |          |                       |         |              |
| 792115           | No. 2 Engine - Transfer of Electromagnetic Chip Detector<br>(Accessory Gearbox to Front Bearing Chamber)                        |               | HRS        |                     | 994.4           |     |                  | 0        |                       | 0       |              |
|                  |                                                                                                                                 |               | ENC        |                     | 392             |     |                  | 0        |                       | 0       |              |
|                  |                                                                                                                                 |               | MOS        |                     | 41.9            |     | 15 Nov 2022      |          |                       |         |              |
|                  |                                                                                                                                 |               | MSC        |                     |                 | O/C |                  |          |                       |         |              |
|                  | Engine                                                                                                                          |               |            | [End Of Month Item] |                 |     |                  |          |                       |         |              |
| 792116           | No. 1 Engine - Magnetic Chip Detector (Magnetic Chip<br>Detector on Front Bearing Chamber Position) - Removal /<br>Installation |               | HRS        |                     | 994.4           |     |                  | 0        |                       | 0       |              |
|                  |                                                                                                                                 |               | ENC        |                     | 392             |     |                  | 0        |                       | 0       |              |
|                  |                                                                                                                                 |               | MOS        |                     | 41.8            |     | 17 Nov 2022      |          |                       |         |              |
|                  |                                                                                                                                 |               | MSC        |                     |                 | O/C |                  |          |                       |         |              |
|                  | Engine                                                                                                                          | PN            | SN-UNKNOWN | [End Of Month Item] |                 |     |                  |          |                       |         |              |

| ATA<br>U=Custom  | Description                                                                                                                             |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-----------------------------------------------------------------------------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                                                                             | Serial Number |                     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                                                                                      | SW            |                     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                                                                                  |               |                     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                                                                                           |               |                     |             |                 |     |                  |             |                    |         |              |
| 792116           | No. 2 Engine - Magnetic Chip Detector (Magnetic Chip Detector on Front Bearing Chamber Position) - Removal / Installation               |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                                                         |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                                                         |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | PN                                                                                                                                      | SN-UNKNOWN    | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  |                                                                                                                                         |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                                                                                                         |               |                     |             |                 |     |                  |             |                    |         |              |
| 792117           | No. 1 Engine - Magnetic Chip Detector (Magnetic Chip Detector on Rear Bearing Chamber Position) - Removal / Installation                |               | HRS                 |             | 730.5           |     |                  | 263.9       |                    |         | 0            |
|                  |                                                                                                                                         |               | ENC                 |             | 315             |     |                  | 77          |                    |         | 0            |
|                  |                                                                                                                                         |               | MOS                 |             | 30.4            |     |                  | 31 Oct 2023 |                    |         |              |
|                  | 3002261                                                                                                                                 | 02366         | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  |                                                                                                                                         |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                                                                                                         |               |                     |             |                 |     |                  |             |                    |         |              |
| 792117           | No. 2 Engine - Magnetic Chip Detector (Magnetic Chip Detector on Rear Bearing Chamber Position) - Removal / Installation                |               | HRS                 |             | 730.5           |     |                  | 263.9       |                    |         | 0            |
|                  |                                                                                                                                         |               | ENC                 |             | 315             |     |                  | 77          |                    |         | 0            |
|                  |                                                                                                                                         |               | MOS                 |             | 30.4            |     |                  | 31 Oct 2023 |                    |         |              |
|                  | 3002261                                                                                                                                 | 02372         | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  |                                                                                                                                         |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                                                                                                         |               |                     |             |                 |     |                  |             |                    |         |              |
| 792118           | No. 1 Engine - Magnetic Chip Detector (Magnetic Chip Detector on Accessory Gearbox Position) - Removal / Installation                   |               | HRS                 |             | 730.5           |     |                  | 263.9       |                    |         | 0            |
|                  |                                                                                                                                         |               | ENC                 |             | 315             |     |                  | 77          |                    |         | 0            |
|                  |                                                                                                                                         |               | MOS                 |             | 30.4            |     |                  | 31 Oct 2023 |                    |         |              |
|                  | 3002261                                                                                                                                 | 02373         | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  |                                                                                                                                         |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                                                                                                         |               |                     |             |                 |     |                  |             |                    |         |              |
| 792118           | No. 2 Engine - Magnetic Chip Detector (Magnetic Chip Detector on Accessory Gearbox Position) - Removal / Installation                   |               | HRS                 |             | 730.5           |     |                  | 263.9       |                    |         | 0            |
|                  |                                                                                                                                         |               | ENC                 |             | 315             |     |                  | 77          |                    |         | 0            |
|                  |                                                                                                                                         |               | MOS                 |             | 29.9            |     |                  | 15 Nov 2023 |                    |         |              |
|                  | 3002261                                                                                                                                 | 02387         | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  |                                                                                                                                         |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                                                                                                         |               |                     |             |                 |     |                  |             |                    |         |              |
| 792122           | No. 1 Engine - Electromagnetic Chip Detector (Electromagnetic Chip Detector on Front Bearing Chamber Position) - Removal / Installation |               | HRS                 |             | 730.5           |     |                  | 263.9       |                    |         | 0            |
|                  |                                                                                                                                         |               | ENC                 |             | 315             |     |                  | 77          |                    |         | 0            |
|                  |                                                                                                                                         |               | MOS                 |             | 30.4            |     |                  | 31 Oct 2023 |                    |         |              |
|                  | 3002251                                                                                                                                 | 01223         | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  |                                                                                                                                         |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                                                                                                         |               |                     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                          |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                          | Serial Number |                     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                   | SW            |                     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                               |               |                     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                        |               |                     |             |                 |     |                  |             |                    |         |              |
| 792122           | No. 2 Engine - Electromagnetic Chip Detector         |               | HRS                 |             | 730.5           |     |                  | 263.9       |                    |         | 0            |
|                  | (Electromagnetic Chip Detector on Front Bearing      |               | ENC                 |             | 315             |     |                  | 77          |                    |         | 0            |
|                  | Chamber Position) - Removal / Installation           |               | MOS                 |             | 30.4            |     |                  | 31 Oct 2023 |                    |         |              |
|                  | PN                                                   | SN-UNKNOWN    | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  |                                                      |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                      |               |                     |             |                 |     |                  |             |                    |         |              |
| 792123           | No. 1 Engine - Electromagnetic Chip Detector         |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | (Electromagnetic Chip Detector on Rear Bearing       |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | Chamber Position) - Removal / Installation           |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | PN                                                   | SN-UNKNOWN    | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  |                                                      |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                      |               |                     |             |                 |     |                  |             |                    |         |              |
| 792123           | No. 2 Engine - Electromagnetic Chip Detector         |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | (Electromagnetic Chip Detector on Rear Bearing       |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | Chamber Position) - Removal / Installation           |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | PN                                                   | SN-UNKNOWN    | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  |                                                      |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                      |               |                     |             |                 |     |                  |             |                    |         |              |
| 792124           | No. 1 Engine - Electromagnetic Chip Detector         |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | (Electromagnetic Chip Detector on Accessory Gearbox  |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | Position) - Removal / Installation                   |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | PN                                                   | SN-UNKNOWN    | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  |                                                      |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                      |               |                     |             |                 |     |                  |             |                    |         |              |
| 792124           | No. 2 Engine - Electromagnetic Chip Detector         |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | (Electromagnetic Chip Detector on Accessory Gearbox  |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | Position) - Removal / Installation                   |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | PN                                                   | SN-UNKNOWN    | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  |                                                      |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                      |               |                     |             |                 |     |                  |             |                    |         |              |
| 792128           | No. 1 Engine - Magnetic Chip Detector Housing (Front |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | Bearing Chamber) - Removal / Installation            |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | PN                                                   | SN-UNKNOWN    | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                      |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  |                                                      |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine           |                                                      |               |                     |             |                 |     |                  |             |                    |         |              |



| ATA<br>U=Custom  | Description                                                                                    |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                                                                    | Serial Number |                     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                                                             | SW            |                     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                                                         |               |                     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                                                                  |               |                     |             |                 |     |                  |             |                     |         |              |
| 792128           | No. 2 Engine - Magnetic Chip Detector Housing (Front Bearing Chamber) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                                                |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | PN                                                                                             | SN-UNKNOWN    | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                                                |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                                         |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 792129           | No. 1 Engine - Magnetic Chip Detector Housing (Rear Bearing Chamber) - Removal / Installation  |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                                                |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | PN                                                                                             | SN-UNKNOWN    | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                                                |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                                         |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 792129           | No. 2 Engine - Magnetic Chip Detector Housing (Rear Bearing Chamber) - Removal / Installation  |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                                                |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | PN                                                                                             | SN-UNKNOWN    | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                                                |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                                         |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 792130           | No. 1 Engine - Magnetic Chip Detector Housing (Accessory Gearbox) - Removal / Installation     |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                                                |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | PN                                                                                             | SN-UNKNOWN    | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                                                |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                                         |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 792130           | No. 2 Engine - Magnetic Chip Detector Housing (Accessory Gearbox) - Removal / Installation     |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                                                |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | PN                                                                                             | SN-UNKNOWN    | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                                                |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                                         |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 792134           | No. 1 Engine - Scavenge Strainer (Front Gearbox) - Removal / Installation                      |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                                                |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | PN                                                                                             | SN-UNKNOWN    | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                                                |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                                         |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 792134           | No. 2 Engine - Scavenge Strainer (Front Gearbox) - Removal / Installation                      |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                                                |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | PN                                                                                             | SN-UNKNOWN    | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                                                |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                                         |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom  | Description                                                                       |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-----------------------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                       | Serial Number |                     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                                | SW            |                     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                            |               |                     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                                     |               |                     |             |                 |     |                  |             |                    |         |              |
| 792135           | No. 1 Engine - Scavenge Strainer (Aft Gearbox, Left) - Removal / Installation     |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                   |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | PN                                                                                | SN-UNKNOWN    | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                                   |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                            |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 792135           | No. 2 Engine - Scavenge Strainer (Aft Gearbox, Left) - Removal / Installation     |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                   |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | PN                                                                                | SN-UNKNOWN    | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                                   |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                            |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 792136           | No. 1 Engine - Scavenge Strainer (Aft Gearbox, Right) - Removal / Installation    |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                   |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | PN                                                                                | SN-UNKNOWN    | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                                   |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                            |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 792136           | No. 2 Engine - Scavenge Strainer (Aft Gearbox, Right) - Removal / Installation    |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                   |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | PN                                                                                | SN-UNKNOWN    | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                                   |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                            |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 792137           | No. 1 Engine - Scavenge Strainer (Accessory Gearbox) - Removal / Installation     |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                   |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | PN                                                                                | SN-UNKNOWN    | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                                   |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                            |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 792137           | No. 2 Engine - Scavenge Strainer (Accessory Gearbox) - Removal / Installation     |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                   |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | PN                                                                                | SN-UNKNOWN    | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                                                   |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                            |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 792138           | No. 1 Engine - Scavenge Strainer (Front Bearing Chamber) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                                   |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | PN                                                                                | SN-UNKNOWN    | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                                                   |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                                            |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                       |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|-----------------------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                                                       | Serial Number |                     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                                                | SW            |                     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                                            |               |                     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                                                     |               |                     |             |                 |     |                  |             |                     |         |              |
| 792138           | No. 2 Engine - Scavenge Strainer (Front Bearing Chamber) - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                                   |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | PN                                                                                | SN-UNKNOWN    | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                                   |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                            |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 792139           | No. 1 Engine - Scavenge Strainer (Rear Bearing Chamber) - Removal / Installation  |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                                   |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | PN                                                                                | SN-UNKNOWN    | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                                   |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                            |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 792139           | No. 2 Engine - Scavenge Strainer (Rear Bearing Chamber) - Removal / Installation  |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                                   |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | PN                                                                                | SN-UNKNOWN    | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                                   |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                            |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 792146           | No. 1 Engine - Scavenge Strainer (Forward Gearbox) - Inspection                   |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                                   |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                                                                   |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                                   |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                            |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 792146           | No. 2 Engine - Scavenge Strainer (Forward Gearbox) - Inspection                   |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                                   |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                                                                   |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                                   |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                            |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 792147           | No. 1 Engine - Scavenge Strainer (Aft Gearbox, Left) - Inspection                 |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                                   |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                                                                   |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                                   |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                            |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| 792147           | No. 2 Engine - Scavenge Strainer (Aft Gearbox, Left) - Inspection                 |               | HRS                 |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                                   |               | ENC                 |             | 392             |     |                  | 0           |                     |         | 0            |
|                  |                                                                                   |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                                   |               | MSC                 |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                            |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom  | Description                                                              |                     | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(* =Adj) | Max Due | Avg Man Hrs  |
|------------------|--------------------------------------------------------------------------|---------------------|-----|-------------|-----------------|-----|------------------|-------------|----------------------|---------|--------------|
|                  | Part Number                                                              | Serial Number       |     |             |                 |     |                  |             |                      |         | Approx Price |
| Logbook Position | HW                                                                       | SW                  |     |             |                 |     |                  |             |                      |         | Manufacturer |
|                  | MM Ref                                                                   |                     |     |             |                 |     |                  |             |                      |         | Date Type    |
|                  | Ops Number(s)                                                            |                     |     |             |                 |     |                  |             |                      |         |              |
| 792148           | No. 1 Engine - Scavenge Strainer (Aft Gearbox, Right) -<br>Inspection    |                     | HRS |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                  |                                                                          |                     | ENC |             | 392             |     |                  | 0           |                      | 0       |              |
|                  |                                                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                      |         |              |
|                  |                                                                          |                     | MSC |             |                 |     | O/C              |             |                      |         |              |
|                  | Engine                                                                   | [End Of Month Item] |     |             |                 |     |                  |             |                      |         |              |
| 792148           | No. 2 Engine - Scavenge Strainer (Aft Gearbox, Right) -<br>Inspection    |                     | HRS |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                  |                                                                          |                     | ENC |             | 392             |     |                  | 0           |                      | 0       |              |
|                  |                                                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                      |         |              |
|                  |                                                                          |                     | MSC |             |                 |     | O/C              |             |                      |         |              |
|                  | Engine                                                                   | [End Of Month Item] |     |             |                 |     |                  |             |                      |         |              |
| 792149           | No. 1 Engine - Scavenge Strainer (Accessory Gearbox) -<br>Inspection     |                     | HRS |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                  |                                                                          |                     | ENC |             | 392             |     |                  | 0           |                      | 0       |              |
|                  |                                                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                      |         |              |
|                  |                                                                          |                     | MSC |             |                 |     | O/C              |             |                      |         |              |
|                  | Engine                                                                   | [End Of Month Item] |     |             |                 |     |                  |             |                      |         |              |
| 792149           | No. 2 Engine - Scavenge Strainer (Accessory Gearbox) -<br>Inspection     |                     | HRS |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                  |                                                                          |                     | ENC |             | 392             |     |                  | 0           |                      | 0       |              |
|                  |                                                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                      |         |              |
|                  |                                                                          |                     | MSC |             |                 |     | O/C              |             |                      |         |              |
|                  | Engine                                                                   | [End Of Month Item] |     |             |                 |     |                  |             |                      |         |              |
| 792150           | No. 1 Engine - Scavenge Strainer (Front Bearing<br>Chamber) - Inspection |                     | HRS |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                  |                                                                          |                     | ENC |             | 392             |     |                  | 0           |                      | 0       |              |
|                  |                                                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                      |         |              |
|                  |                                                                          |                     | MSC |             |                 |     | O/C              |             |                      |         |              |
|                  | Engine                                                                   | [End Of Month Item] |     |             |                 |     |                  |             |                      |         |              |
| 792150           | No. 2 Engine - Scavenge Strainer (Front Bearing<br>Chamber) - Inspection |                     | HRS |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                  |                                                                          |                     | ENC |             | 392             |     |                  | 0           |                      | 0       |              |
|                  |                                                                          |                     | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                      |         |              |
|                  |                                                                          |                     | MSC |             |                 |     | O/C              |             |                      |         |              |
|                  | Engine                                                                   | [End Of Month Item] |     |             |                 |     |                  |             |                      |         |              |
| 792151           | No. 1 Engine - Scavenge Strainer (Rear Bearing<br>Chamber) - Inspection  |                     | HRS |             | 994.4           |     |                  | 0           |                      |         | 0            |
|                  |                                                                          |                     | ENC |             | 392             |     |                  | 0           |                      | 0       |              |
|                  |                                                                          |                     | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                      |         |              |
|                  |                                                                          |                     | MSC |             |                 |     | O/C              |             |                      |         |              |
|                  | Engine                                                                   | [End Of Month Item] |     |             |                 |     |                  |             |                      |         |              |

| ATA<br>U=Custom  | Description                                                                                                            |               | UOM | Times Since         | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------------------------------------------------------------------------------------|---------------|-----|---------------------|-----------------|-----|------------------|----------|--------------------|---------|--------------|
|                  | Part Number                                                                                                            | Serial Number |     |                     |                 |     |                  |          |                    |         | Approx Price |
| Logbook Position | HW                                                                                                                     | SW            |     |                     |                 |     |                  |          |                    |         | Manufacturer |
|                  | MM Ref                                                                                                                 |               |     |                     |                 |     |                  |          |                    |         | Date Type    |
|                  | Ops Number(s)                                                                                                          |               |     |                     |                 |     |                  |          |                    |         |              |
| 792151           | No. 2 Engine - Scavenge Strainer (Rear Bearing Chamber) - Inspection                                                   |               | HRS |                     | 994.4           |     |                  | 0        |                    | 0       |              |
|                  |                                                                                                                        |               | ENC |                     | 392             |     |                  | 0        |                    | 0       |              |
|                  |                                                                                                                        |               | MOS |                     | 41.9            |     | 15 Nov 2022      |          |                    |         |              |
|                  |                                                                                                                        |               | MSC |                     |                 | O/C |                  |          |                    |         |              |
|                  | Engine                                                                                                                 |               |     | [End Of Month Item] |                 |     |                  |          |                    |         |              |
| 792200           | No. 1 Engine - Fuel-Cooled Oil Cooler - Removal / Installation<br>55045001-31                      HEX95-0269          |               | HRS |                     | 994.4           |     |                  | 0        |                    | 0       |              |
|                  |                                                                                                                        |               | ENC |                     | 392             |     |                  | 0        |                    | 0       |              |
|                  |                                                                                                                        |               | MOS |                     | 41.8            |     | 17 Nov 2022      |          |                    |         |              |
|                  |                                                                                                                        |               | MSC |                     |                 | O/C |                  |          |                    |         |              |
|                  | Engine                                                                                                                 |               |     | [End Of Month Item] |                 |     |                  |          |                    |         |              |
| 792200           | No. 2 Engine - Fuel-Cooled Oil Cooler - Removal / Installation<br>55045001-31                      HEX95-0270          |               | HRS |                     | 994.4           |     |                  | 0        |                    | 0       |              |
|                  |                                                                                                                        |               | ENC |                     | 392             |     |                  | 0        |                    | 0       |              |
|                  |                                                                                                                        |               | MOS |                     | 41.9            |     | 15 Nov 2022      |          |                    |         |              |
|                  |                                                                                                                        |               | MSC |                     |                 | O/C |                  |          |                    |         |              |
|                  | Engine                                                                                                                 |               |     | [End Of Month Item] |                 |     |                  |          |                    |         |              |
| 792202           | No. 1 Engine - Cooler, Oil, Surface AIR Cooled - Removal / Installation<br>50028001-11                      SP013-0098 |               | HRS |                     | 994.4           |     |                  | 0        |                    | 0       |              |
|                  |                                                                                                                        |               | ENC |                     | 392             |     |                  | 0        |                    | 0       |              |
|                  |                                                                                                                        |               | MOS |                     | 41.8            |     | 17 Nov 2022      |          |                    |         |              |
|                  |                                                                                                                        |               | MSC |                     |                 | O/C |                  |          |                    |         |              |
|                  | Engine                                                                                                                 |               |     | [End Of Month Item] |                 |     |                  |          |                    |         |              |
| 792202           | No. 2 Engine - Cooler, Oil, Surface AIR Cooled - Removal / Installation<br>50028001-11                      SP013-0099 |               | HRS |                     | 994.4           |     |                  | 0        |                    | 0       |              |
|                  |                                                                                                                        |               | ENC |                     | 392             |     |                  | 0        |                    | 0       |              |
|                  |                                                                                                                        |               | MOS |                     | 41.9            |     | 15 Nov 2022      |          |                    |         |              |
|                  |                                                                                                                        |               | MSC |                     |                 | O/C |                  |          |                    |         |              |
|                  | Engine                                                                                                                 |               |     | [End Of Month Item] |                 |     |                  |          |                    |         |              |
| 793110           | No. 1 Engine - Oil Quantity Transducer - Removal / Installation<br>PN                      SN-UNKNOWN                  |               | HRS |                     | 994.4           |     |                  | 0        |                    | 0       |              |
|                  |                                                                                                                        |               | ENC |                     | 392             |     |                  | 0        |                    | 0       |              |
|                  |                                                                                                                        |               | MOS |                     | 41.8            |     | 17 Nov 2022      |          |                    |         |              |
|                  |                                                                                                                        |               | MSC |                     |                 | O/C |                  |          |                    |         |              |
|                  | Engine                                                                                                                 |               |     | [End Of Month Item] |                 |     |                  |          |                    |         |              |
| 793110           | No. 2 Engine - Oil Quantity Transducer - Removal / Installation<br>PN                      SN-UNKNOWN                  |               | HRS |                     | 994.4           |     |                  | 0        |                    | 0       |              |
|                  |                                                                                                                        |               | ENC |                     | 392             |     |                  | 0        |                    | 0       |              |
|                  |                                                                                                                        |               | MOS |                     | 41.9            |     | 15 Nov 2022      |          |                    |         |              |
|                  |                                                                                                                        |               | MSC |                     |                 | O/C |                  |          |                    |         |              |
|                  | Engine                                                                                                                 |               |     | [End Of Month Item] |                 |     |                  |          |                    |         |              |

| ATA<br>U=Custom  | Description                                                                         |                     | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|-------------------------------------------------------------------------------------|---------------------|-----|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                                                         | Serial Number       |     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                                                  | SW                  |     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                                              |                     |     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                                                       |                     |     |             |                 |     |                  |             |                     |         |              |
| 793200           | No. 1 Engine - Oil Temperature Transducer - Removal / Installation                  |                     | HRS |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                                     |                     | ENC |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | PN                                                                                  | SN-UNKNOWN          | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                                     |                     | MSC |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                              | [End Of Month Item] |     |             |                 |     |                  |             |                     |         |              |
| 793200           | No. 2 Engine - Oil Temperature Transducer - Removal / Installation                  |                     | HRS |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                                     |                     | ENC |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | PN                                                                                  | SN-UNKNOWN          | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                                     |                     | MSC |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                              | [End Of Month Item] |     |             |                 |     |                  |             |                     |         |              |
| 793201           | No. 1 Engine - Oil Temperature Transducer Assembly (No.2) - Removal / Installation  |                     | HRS |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                                     |                     | ENC |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | PN                                                                                  | SN-UNKNOWN          | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                                     |                     | MSC |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                              | [End Of Month Item] |     |             |                 |     |                  |             |                     |         |              |
| 793201           | No. 2 Engine - Oil Temperature Transducer Assembly (No.2) - Removal / Installation  |                     | HRS |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                                     |                     | ENC |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | PN                                                                                  | SN-UNKNOWN          | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                                     |                     | MSC |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                              | [End Of Month Item] |     |             |                 |     |                  |             |                     |         |              |
| 793300           | No. 1 Engine - Oil Differential Pressure Transducer - Removal / Installation        |                     | HRS |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                                     |                     | ENC |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | PN                                                                                  | SN-UNKNOWN          | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                                     |                     | MSC |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                              | [End Of Month Item] |     |             |                 |     |                  |             |                     |         |              |
| 793300           | No. 2 Engine - Oil Differential Pressure Transducer - Removal / Installation        |                     | HRS |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                                     |                     | ENC |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | PN                                                                                  | SN-UNKNOWN          | MOS |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                                     |                     | MSC |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                              | [End Of Month Item] |     |             |                 |     |                  |             |                     |         |              |
| 793301           | No. 1 Engine - Oil Differential Pressure Transducer (No.2) - Removal / Installation |                     | HRS |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                                     |                     | ENC |             | 392             |     |                  | 0           |                     |         | 0            |
|                  | PN                                                                                  | SN-UNKNOWN          | MOS |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                                     |                     | MSC |             |                 |     | O/C              |             |                     |         |              |
|                  | Engine                                                                              | [End Of Month Item] |     |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom  | Description                                                  |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|--------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                  | Serial Number |                     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                           | SW            |                     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                       |               |                     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                |               |                     |             |                 |     |                  |             |                    |         |              |
| 793301           | No. 2 Engine - Oil Differential Pressure Transducer (No.2)   |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | - Removal / Installation                                     |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | PN                                                           | SN-UNKNOWN    | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                              |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                       |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 793400           | No. 1 Engine - Oil Filter Differential Pressure Transducer - |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | Removal / Installation                                       |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | PN                                                           | SN-UNKNOWN    | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                              |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                       |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 793400           | No. 2 Engine - Oil Filter Differential Pressure Transducer - |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | Removal / Installation                                       |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | PN                                                           | SN-UNKNOWN    | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                              |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                       |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 80 - Starting    |                                                              |               |                     |             |                 |     |                  |             |                    |         |              |
| 801100           | No. 1 Engine - AIR Turbine Starter - Removal / Installation  |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | PN                                                           |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                              |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                              |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                       |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 801100           | No. 2 Engine - AIR Turbine Starter - Removal / Installation  |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | PN                                                           |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                              |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                              |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                       |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 801101           | No. 1 Engine - Starter AIR Valve - Removal / Installation    |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | PN                                                           |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                              |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  |                                                              |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                       |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 801101           | No. 2 Engine - Starter AIR Valve - Removal / Installation    |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  | PN                                                           |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                              |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  |                                                              |               | MSC                 |             |                 |     | O/C              |             |                    |         |              |
|                  | Engine                                                       |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                         |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|-------------------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                                                         | Serial Number |                                    |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                                                  | SW            |                                    |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                                              |               |                                    |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                                                       |               |                                    |             |                 |     |                  |             |                     |         |              |
| 801104           | No. 1 Engine - AIR Turbine Starter Magnetic Chip<br>Collector - Detailed Inspection |               | HRS                                |             | 137             | 6.5 | 600              | 857.4       | 1463.9*             | 1513.9  | 0            |
|                  |                                                                                     |               | ENC                                |             | 52              |     |                  | 340         |                     | 0       |              |
|                  |                                                                                     |               | MOS                                |             | 5.5             |     |                  | 27 Nov 2025 |                     |         |              |
|                  |                                                                                     |               | [End Of Month Item] [HRS: +50/-50] |             |                 |     |                  |             |                     |         |              |
| Engine           | 052001                                                                              |               |                                    |             |                 |     |                  |             |                     |         |              |
| 801104           | No. 2 Engine - AIR Turbine Starter Magnetic Chip<br>Collector - Detailed Inspection |               | HRS                                |             | 137             | 6.5 | 600              | 857.4       | 1463.9*             | 1513.9  | 0            |
|                  |                                                                                     |               | ENC                                |             | 52              |     |                  | 340         |                     | 0       |              |
|                  |                                                                                     |               | MOS                                |             | 5.5             |     |                  | 27 Nov 2025 |                     |         |              |
|                  |                                                                                     |               | [End Of Month Item] [HRS: +50/-50] |             |                 |     |                  |             |                     |         |              |
| Engine           | 052001                                                                              |               |                                    |             |                 |     |                  |             |                     |         |              |
| 801105           | No. 1 Engine - AIR Turbine Starter Oil - Change                                     |               | HRS                                |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                                     |               | ENC                                |             | 392             |     |                  | 0           |                     | 0       |              |
|                  |                                                                                     |               | MOS                                |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                                     |               | MSC                                |             |                 |     | O/C              |             |                     |         |              |
| Engine           |                                                                                     |               | [End Of Month Item]                |             |                 |     |                  |             |                     |         |              |
| 801105           | No. 2 Engine - AIR Turbine Starter Oil - Change                                     |               | HRS                                |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                                     |               | ENC                                |             | 392             |     |                  | 0           |                     | 0       |              |
|                  |                                                                                     |               | MOS                                |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                                     |               | MSC                                |             |                 |     | O/C              |             |                     |         |              |
| Engine           |                                                                                     |               | [End Of Month Item]                |             |                 |     |                  |             |                     |         |              |
| 801106           | No. 1 Engine - Starter Oil Level - Detailed Inspection                              |               | HRS                                |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                                     |               | ENC                                |             | 392             |     |                  | 0           |                     | 0       |              |
|                  |                                                                                     |               | MOS                                |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                                     |               | MSC                                |             |                 |     | O/C              |             |                     |         |              |
| Engine           |                                                                                     |               | [End Of Month Item]                |             |                 |     |                  |             |                     |         |              |
| 801106           | No. 2 Engine - Starter Oil Level - Detailed Inspection                              |               | HRS                                |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                                     |               | ENC                                |             | 392             |     |                  | 0           |                     | 0       |              |
|                  |                                                                                     |               | MOS                                |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                                     |               | MSC                                |             |                 |     | O/C              |             |                     |         |              |
| Engine           |                                                                                     |               | [End Of Month Item]                |             |                 |     |                  |             |                     |         |              |
| 801107           | No. 1 Engine - AIR Turbine Starter - Inspection / Check                             |               | HRS                                |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                                     |               | ENC                                |             | 392             |     |                  | 0           |                     | 0       |              |
|                  |                                                                                     |               | MOS                                |             | 41.8            |     |                  | 17 Nov 2022 |                     |         |              |
|                  |                                                                                     |               | MSC                                |             |                 |     | O/C              |             |                     |         |              |
| Engine           |                                                                                     |               | [End Of Month Item]                |             |                 |     |                  |             |                     |         |              |
| 801107           | No. 2 Engine - AIR Turbine Starter - Inspection / Check                             |               | HRS                                |             | 994.4           |     |                  | 0           |                     |         | 0            |
|                  |                                                                                     |               | ENC                                |             | 392             |     |                  | 0           |                     | 0       |              |
|                  |                                                                                     |               | MOS                                |             | 41.9            |     |                  | 15 Nov 2022 |                     |         |              |
|                  |                                                                                     |               | MSC                                |             |                 |     | O/C              |             |                     |         |              |
| Engine           |                                                                                     |               | [End Of Month Item]                |             |                 |     |                  |             |                     |         |              |



| ATA<br>U=Custom  | Description                                                    |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                    | Serial Number |                     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                             | SW            |                     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                         |               |                     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                  |               |                     |             |                 |     |                  |             |                    |         |              |
| 801108           | No. 1 Engine - Starter AIR Valve - Manual Override             |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                                |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                                         |               |                     | MSC         |                 |     | O/C              |             |                    |         |              |
|                  |                                                                |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 801108           | No. 2 Engine - Starter AIR Valve - Manual Override             |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                                |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                                         |               |                     | MSC         |                 |     | O/C              |             |                    |         |              |
|                  |                                                                |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 801109           | No. 1 Engine - Front Starter AIR Duct - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | PN                                                             | SN-UNKNOWN    | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                                         |               |                     | MSC         |                 |     | O/C              |             |                    |         |              |
|                  |                                                                |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 801109           | No. 2 Engine - Front Starter AIR Duct - Removal / Installation |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | PN                                                             | SN-UNKNOWN    | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                                         |               |                     | MSC         |                 |     | O/C              |             |                    |         |              |
|                  |                                                                |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 801110           | No. 1 Engine - Rear Starter AIR Duct - Removal / Installation  |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | PN                                                             | SN-UNKNOWN    | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                                         |               |                     | MSC         |                 |     | O/C              |             |                    |         |              |
|                  |                                                                |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 801110           | No. 2 Engine - Rear Starter AIR Duct - Removal / Installation  |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  | PN                                                             | SN-UNKNOWN    | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                  | Engine                                                         |               |                     | MSC         |                 |     | O/C              |             |                    |         |              |
|                  |                                                                |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| 801113           | No. 1 Engine - Starter AIR Ducts - General Visual Inspection   |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                  |                                                                |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                  |                                                                |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                  | Engine                                                         |               |                     | MSC         |                 |     | O/C              |             |                    |         |              |
|                  |                                                                |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom                            | Description                                                                                        |               | UOM                                | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|--------------------------------------------|----------------------------------------------------------------------------------------------------|---------------|------------------------------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                            | Part Number                                                                                        | Serial Number |                                    |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position                           | HW                                                                                                 | SW            |                                    |             |                 |     |                  |             |                    |         | Manufacturer |
|                                            | MM Ref                                                                                             |               |                                    |             |                 |     |                  |             |                    |         | Date Type    |
|                                            | Ops Number(s)                                                                                      |               |                                    |             |                 |     |                  |             |                    |         |              |
| 801113                                     | No. 2 Engine - Starter AIR Ducts - General Visual Inspection                                       |               | HRS                                |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                                            |                                                                                                    |               | ENC                                |             | 392             |     |                  | 0           |                    |         | 0            |
|                                            |                                                                                                    |               | MOS                                |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                                            |                                                                                                    |               | MSC                                |             |                 |     | O/C              |             |                    |         |              |
|                                            | Engine                                                                                             |               | [End Of Month Item]                |             |                 |     |                  |             |                    |         |              |
| 801114                                     | Starter AIR Valve Relay (Left) - Removal / Installation<br>Y-E4N-024                               |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                            |                                                                                                    |               | AFL                                |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                            |                                                                                                    |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                            |                                                                                                    |               | MSC                                |             |                 |     | O/C              |             |                    |         |              |
|                                            | Airframe                                                                                           |               |                                    |             |                 |     |                  |             |                    |         |              |
| 801115                                     | Starter AIR Valve Relay (Right) - Removal / Installation<br>Y-E4N-024                              |               | HRS                                |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                            |                                                                                                    |               | AFL                                |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                            |                                                                                                    |               | MOS                                |             | 128.6           |     |                  | 24 Aug 2015 |                    |         |              |
|                                            |                                                                                                    |               | MSC                                |             |                 |     | O/C              |             |                    |         |              |
|                                            | Airframe                                                                                           |               |                                    |             |                 |     |                  |             |                    |         |              |
| 801118                                     | No. 1 Engine - AIR Turbine Starter - General Visual Inspection                                     |               | HRS                                |             | 137             | 6.5 | 600              | 857.4       | 1463.9*            | 1513.9  | 0            |
|                                            |                                                                                                    |               | ENC                                |             | 52              |     |                  | 340         |                    |         | 0            |
|                                            |                                                                                                    |               | MOS                                |             | 5.3             |     |                  | 03 Dec 2025 |                    |         |              |
|                                            |                                                                                                    |               | [End Of Month Item] [HRS: +50/-50] |             |                 |     |                  |             |                    |         |              |
|                                            | Engine                                                                                             |               | 052001                             |             |                 |     |                  |             |                    |         |              |
| 801118                                     | No. 2 Engine - AIR Turbine Starter - General Visual Inspection                                     |               | HRS                                |             | 137             | 6.5 | 600              | 857.4       | 1463.9*            | 1513.9  | 0            |
|                                            |                                                                                                    |               | ENC                                |             | 52              |     |                  | 340         |                    |         | 0            |
|                                            |                                                                                                    |               | MOS                                |             | 5.3             |     |                  | 03 Dec 2025 |                    |         |              |
|                                            |                                                                                                    |               | [End Of Month Item] [HRS: +50/-50] |             |                 |     |                  |             |                    |         |              |
|                                            | Engine                                                                                             |               | 052001                             |             |                 |     |                  |             |                    |         |              |
| AD - Airworthiness Directives              |                                                                                                    |               |                                    |             |                 |     |                  |             |                    |         |              |
| 994081 - FAA AD<br>2023-21-05 <sup>U</sup> | Thales AVS France SAS Flight Management Computer Navigation Modules                                |               | HRS                                |             | 672.6           |     |                  | 2373.5      | 0                  |         | 0            |
|                                            |                                                                                                    |               | AFL                                |             | 299             |     |                  | 818         | 0                  |         | 0            |
|                                            | PN                                                                                                 | SN-UNKNOWN    | DATE                               |             | 802 d           |     | 30d**            | 29 Feb 2024 |                    |         |              |
| Airframe                                   |                                                                                                    |               |                                    |             |                 |     |                  |             |                    |         |              |
| CAA UK G-2025-0002<br>(992502)             | Appliance AD - CAA Uk G-2025-0002 - Pilot & CO-Pilot Seats - Inspection / Modification (Mandatory) |               | HRS                                |             |                 |     |                  |             |                    |         | 0            |
|                                            |                                                                                                    |               | AFL                                |             |                 |     |                  |             |                    |         | 0            |
|                                            |                                                                                                    |               | MOS                                |             | 12.8            |     |                  | 16 Apr 2025 |                    |         |              |
|                                            |                                                                                                    |               | MSC                                |             |                 |     | -                |             |                    |         |              |
| Airframe                                   |                                                                                                    |               |                                    |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom                                             | Description                                                                                                              |               | UOM                 | Times Since | Time<br>Accrued | Adj   | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|-------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-------|------------------|-------------|--------------------|---------|--------------|
|                                                             | Part Number                                                                                                              | Serial Number |                     |             |                 |       |                  |             |                    |         | Approx Price |
| Logbook Position                                            | HW                                                                                                                       | SW            |                     |             |                 |       |                  |             |                    |         | Manufacturer |
|                                                             | MM Ref                                                                                                                   |               |                     |             |                 |       |                  |             |                    |         | Date Type    |
|                                                             | Ops Number(s)                                                                                                            |               |                     |             |                 |       |                  |             |                    |         |              |
| <b>CAA UK G-2026-0001</b><br>(996313)<br><br>Airframe       | Appliance AD - Equipment / Furnishings - Passenger<br>Seats - Modification (Mandatory)                                   |               | HRS                 |             |                 |       |                  |             |                    |         | 0            |
|                                                             |                                                                                                                          |               | AFL                 |             |                 |       |                  |             |                    | 0       |              |
|                                                             |                                                                                                                          |               | MOS                 |             | 1.5             |       |                  | 27 Mar 2026 |                    |         |              |
|                                                             |                                                                                                                          |               | MSC                 |             |                 |       | -                |             |                    |         |              |
| <b>EASA 2013-0110</b><br>(993109)<br><br>Engine             | No. 1 Engine - EASA 2013-0110 - Engine Fuel and<br>Control - Spill Return to Fuel Pump Tube - Replacement                |               | HRS                 |             | 994.4           |       |                  | 0           |                    |         | 0            |
|                                                             |                                                                                                                          |               | ENC                 |             | 392             |       |                  | 0           |                    | 0       |              |
|                                                             |                                                                                                                          |               | MOS                 |             | 41.8            |       |                  | 17 Nov 2022 |                    |         |              |
|                                                             |                                                                                                                          |               | MSC                 |             |                 |       | -                |             |                    |         |              |
|                                                             |                                                                                                                          |               | [End Of Month Item] |             |                 |       |                  |             |                    |         |              |
| <b>EASA 2013-0110</b><br>(993109)<br><br>Engine             | No. 2 Engine - EASA 2013-0110 - Engine Fuel and<br>Control - Spill Return to Fuel Pump Tube - Replacement                |               | HRS                 |             | 994.4           |       |                  | 0           |                    |         | 0            |
|                                                             |                                                                                                                          |               | ENC                 |             | 392             |       |                  | 0           |                    | 0       |              |
|                                                             |                                                                                                                          |               | MOS                 |             | 41.8            |       |                  | 17 Nov 2022 |                    |         |              |
|                                                             |                                                                                                                          |               | MSC                 |             |                 |       | -                |             |                    |         |              |
|                                                             |                                                                                                                          |               | [End Of Month Item] |             |                 |       |                  |             |                    |         |              |
| <b>EASA 2013-0229 R02</b><br>(993117)<br><br>Engine         | No. 1 Engine - EASA 2013-0229 R02 - Engine Fuel and<br>Control - Fuel Metering Unit - Replacement                        |               | HRS                 |             | 960.6           |       |                  | 33.8        |                    |         | 0            |
|                                                             |                                                                                                                          |               | ENC                 |             | 377             |       |                  | 15          |                    | 0       |              |
|                                                             |                                                                                                                          |               | DATE                |             | 1192 d          | -3377 |                  | 04 Feb 2023 |                    |         |              |
|                                                             |                                                                                                                          |               | MSC                 |             |                 |       | -                |             |                    |         |              |
|                                                             |                                                                                                                          |               | [End Of Month Item] |             |                 |       |                  |             |                    |         |              |
| <b>EASA 2013-0229 R02</b><br>(993117)<br><br>Engine         | No. 2 Engine - EASA 2013-0229 R02 - Engine Fuel and<br>Control - Fuel Metering Unit - Replacement                        |               | HRS                 |             | 960.6           |       |                  | 33.8        |                    |         | 0            |
|                                                             |                                                                                                                          |               | ENC                 |             | 377             |       |                  | 15          |                    | 0       |              |
|                                                             |                                                                                                                          |               | DATE                |             | 1192 d          | -3377 |                  | 04 Feb 2023 |                    |         |              |
|                                                             |                                                                                                                          |               | MSC                 |             |                 |       | -                |             |                    |         |              |
|                                                             |                                                                                                                          |               | [End Of Month Item] |             |                 |       |                  |             |                    |         |              |
| <b>EASA 2019-0235</b><br>(994074)<br><br>Airframe           | EASA 2019-0235 - Equipment / Furnishings - Emergency<br>Locator Transmitter - Inspection / Modification /<br>Replacement |               | HRS                 |             | 1549            |       |                  | 1497.1      |                    |         | 0            |
|                                                             |                                                                                                                          |               | AFL                 |             | 632             |       |                  | 485         |                    | 0       |              |
|                                                             |                                                                                                                          |               | MOS                 |             | 67.2            |       |                  | 05 Oct 2020 |                    |         |              |
|                                                             |                                                                                                                          |               | MSC                 |             |                 |       | -                |             |                    |         |              |
| Notes: N/A DUE ELT NOT PREVIOUSLY INSTALLED ON A HELICOPTER |                                                                                                                          |               |                     |             |                 |       |                  |             |                    |         |              |

| ATA<br>U=Custom                  | Description                                                                                                                                      |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|----------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                  | Part Number                                                                                                                                      | Serial Number |                     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position                 | HW                                                                                                                                               | SW            |                     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                  | MM Ref                                                                                                                                           |               |                     |             |                 |     |                  |             |                    |         | Date Type    |
|                                  | Ops Number(s)                                                                                                                                    |               |                     |             |                 |     |                  |             |                    |         |              |
| EASA 2021-0137 <sup>U</sup>      | Appliance AD - Safran Seats - Pilot & CO-Pilot Seats / Longitudinal Locking System Pins - Measurement / Adjustment                               |               | HRS                 |             | 1416.3          |     |                  | 1629.8      |                    |         | 0            |
|                                  |                                                                                                                                                  |               | AFL                 |             | 540             |     |                  | 577         |                    |         | 0            |
|                                  |                                                                                                                                                  |               | MOS                 |             | 58.4            |     |                  | 30 Jun 2021 |                    |         |              |
|                                  |                                                                                                                                                  |               | MSC                 |             |                 |     | -                |             |                    |         |              |
|                                  |                                                                                                                                                  |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Airframe                         |                                                                                                                                                  |               |                     |             |                 |     |                  |             |                    |         |              |
| EASA 2024-0024                   | Appliance AD - EASA 2024-0024 - Navigation - Digital AIR Data Computer - Replacement (Mandatory)                                                 |               | HRS                 |             |                 |     |                  |             |                    |         | 0            |
|                                  |                                                                                                                                                  |               | AFL                 |             |                 |     |                  |             |                    |         | 0            |
|                                  |                                                                                                                                                  |               | MOS                 |             | 27.5            |     |                  | 25 Jan 2024 |                    |         |              |
|                                  |                                                                                                                                                  |               | MSC                 |             |                 |     | -                |             |                    |         |              |
|                                  |                                                                                                                                                  |               |                     |             |                 |     |                  |             |                    |         |              |
| (992424)                         |                                                                                                                                                  |               |                     |             |                 |     |                  |             |                    |         |              |
| Airframe                         |                                                                                                                                                  |               |                     |             |                 |     |                  |             |                    |         |              |
| EASA 2024-0136                   | No. 1 Engine - EASA 2024-0136 - Time Limits / Maintenance Checks - Time Limits Manual / Maintenance Program - Amendment (Mandatory)              |               | HRS                 |             | 337.3           |     |                  | 657.1       |                    |         | 0            |
|                                  |                                                                                                                                                  |               | ENC                 |             | 137             |     |                  | 255         |                    |         | 0            |
|                                  |                                                                                                                                                  |               | MOS                 |             | 11              |     |                  | 12 Jun 2025 |                    |         |              |
|                                  |                                                                                                                                                  |               | MSC                 |             |                 |     | -                |             |                    |         |              |
|                                  |                                                                                                                                                  |               |                     |             |                 |     |                  |             |                    |         |              |
| (994136)                         |                                                                                                                                                  |               |                     |             |                 |     |                  |             |                    |         |              |
| Engine                           |                                                                                                                                                  |               |                     |             |                 |     |                  |             |                    |         |              |
| EASA 2024-0136                   | No. 2 Engine - EASA 2024-0136 - Time Limits / Maintenance Checks - Time Limits Manual / Maintenance Program - Amendment (Mandatory)              |               | HRS                 |             | 337.3           |     |                  | 657.1       |                    |         | 0            |
|                                  |                                                                                                                                                  |               | ENC                 |             | 137             |     |                  | 255         |                    |         | 0            |
|                                  |                                                                                                                                                  |               | MOS                 |             | 11              |     |                  | 12 Jun 2025 |                    |         |              |
|                                  |                                                                                                                                                  |               | MSC                 |             |                 |     | -                |             |                    |         |              |
|                                  |                                                                                                                                                  |               |                     |             |                 |     |                  |             |                    |         |              |
| (994136)                         |                                                                                                                                                  |               |                     |             |                 |     |                  |             |                    |         |              |
| Engine                           |                                                                                                                                                  |               |                     |             |                 |     |                  |             |                    |         |              |
| EASA 2025-0088                   | Appliance AD - EASA 2025-0088 - Navigation - Satellite Based Augmentation Systems / Global Positioning System Receiver - Replacement (Mandatory) |               | HRS                 |             |                 |     |                  |             |                    |         | 0            |
|                                  |                                                                                                                                                  |               | AFL                 |             |                 |     |                  |             |                    |         | 0            |
|                                  |                                                                                                                                                  |               | MOS                 |             |                 |     | 24**             |             | 30 Apr 2027        |         |              |
|                                  |                                                                                                                                                  |               | MSC                 |             |                 |     |                  |             |                    |         |              |
|                                  |                                                                                                                                                  |               |                     |             |                 |     |                  |             |                    |         |              |
| (992588)                         |                                                                                                                                                  |               |                     |             |                 |     |                  |             |                    |         |              |
| Airframe                         |                                                                                                                                                  |               |                     |             |                 |     |                  |             |                    |         |              |
| EASA 994048 <sup>U</sup>         | EASA AD 2017-0192 - Recaro Aircraft Seating Model 3510A/3150D - Modification                                                                     |               | HRS                 |             | 2399.8          |     |                  | 646.3       |                    |         | 0            |
|                                  |                                                                                                                                                  |               | AFL                 |             | 946             |     |                  | 171         |                    |         | 0            |
|                                  |                                                                                                                                                  |               | MOS                 |             | 98.5            |     |                  | 28 Feb 2018 |                    |         |              |
|                                  |                                                                                                                                                  |               | MSC                 |             |                 |     | -                |             |                    |         |              |
|                                  |                                                                                                                                                  |               |                     |             |                 |     |                  |             |                    |         |              |
| (994048)                         |                                                                                                                                                  |               |                     |             |                 |     |                  |             |                    |         |              |
| Airframe                         |                                                                                                                                                  |               |                     |             |                 |     |                  |             |                    |         |              |
| Notes: N/A BY SEAT P/N INSTALLED |                                                                                                                                                  |               |                     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom                                                | Description                                                                                                 |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|----------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                                                | Part Number                                                                                                 | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position                                               | HW                                                                                                          | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                                                | MM Ref                                                                                                      |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                                                                | Ops Number(s)                                                                                               |               |     |             |                 |     |                  |             |                    |         |              |
| <b>EASA 994049<sup>U</sup></b><br><br>(994049)<br><br>Airframe | EASA AD 2017-0225 - Schroth Safety Products Gmbh -<br>Seat Restraint Systems – Afm Amendment / Modification |               | HRS |             | 2399.8          |     |                  | 646.3       |                    |         | 0            |
|                                                                |                                                                                                             |               | AFL |             | 946             |     |                  | 171         |                    |         | 0            |
|                                                                |                                                                                                             |               | MOS |             | 98.5            |     |                  | 28 Feb 2018 |                    |         |              |
|                                                                |                                                                                                             |               | MSC |             |                 |     | -                |             |                    |         |              |
| Notes: N/A BY EQUIPMENT INSTALLED                              |                                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| <b>EASA 994050<sup>U</sup></b><br><br>(994050)<br><br>Airframe | EASA AD 2016-0167 R1 - Rear Cabin Attendant Seat –<br>Inspection / Repair                                   |               | HRS |             | 2399.8          |     |                  | 646.3       |                    |         | 0            |
|                                                                |                                                                                                             |               | AFL |             | 946             |     |                  | 171         |                    |         | 0            |
|                                                                |                                                                                                             |               | MOS |             | 98.5            |     |                  | 28 Feb 2018 |                    |         |              |
|                                                                |                                                                                                             |               | MSC |             |                 |     | -                |             |                    |         |              |
| Notes: N/A BY EQUIPMENT INSTALLED                              |                                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| <b>EASA 994052<sup>U</sup></b><br><br>(994052)<br><br>Airframe | EASA AD 2018-0195 - Anjou Aeronautique - Restraint<br>Systems Rotary Buckle Sub Assy                        |               | HRS |             | 2252.1          |     |                  | 794         |                    |         | 0            |
|                                                                |                                                                                                             |               | AFL |             | 900             |     |                  | 217         |                    |         | 0            |
|                                                                |                                                                                                             |               | MOS |             | 91.5            |     |                  | 28 Sep 2018 |                    |         |              |
|                                                                |                                                                                                             |               | MSC |             |                 |     | -                |             |                    |         |              |
| Notes: N/A BY EQUIPMENT INSTALLED                              |                                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| <b>EASA 994053<sup>U</sup></b><br><br>(994053)<br><br>Airframe | EASA AD 2018-0223 - B/E Aerospace Fischer - Seat<br>Energy Absorber Assy - Modification                     |               | HRS |             | 2187.6          |     |                  | 858.5       |                    |         | 0            |
|                                                                |                                                                                                             |               | AFL |             | 888             |     |                  | 229         |                    |         | 0            |
|                                                                |                                                                                                             |               | MOS |             | 90.4            |     |                  | 31 Oct 2018 |                    |         |              |
|                                                                |                                                                                                             |               | MSC |             |                 |     | -                |             |                    |         |              |
| Notes: N/A BY EQUIPMENT INSTALLED                              |                                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| <b>EASA 994055<sup>U</sup></b><br><br>(994055)<br><br>Airframe | EASA AD 2018-0247 Trig Avionics Ltd Transponders -<br>Inspection / Modification                             |               | HRS |             | 2175.3          |     |                  | 870.8       |                    |         | 0            |
|                                                                |                                                                                                             |               | AFL |             | 879             |     |                  | 238         |                    |         | 0            |
|                                                                |                                                                                                             |               | MOS |             | 89.4            |     |                  | 30 Nov 2018 |                    |         |              |
|                                                                |                                                                                                             |               | MSC |             |                 |     | -                |             |                    |         |              |
| Notes: N/A BY PN OF EQUIPMENT INSTALLED                        |                                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| <b>EASA 994057<sup>U</sup></b><br><br>(994057)<br><br>Airframe | EASA AD 2019-0004 - Thales AVS France SAS - Global<br>Navigation Satellite System - Operational Limitations |               | HRS |             | 2120.8          |     |                  | 925.3       |                    |         | 0            |
|                                                                |                                                                                                             |               | AFL |             | 861             |     |                  | 256         |                    |         | 0            |
|                                                                |                                                                                                             |               | MOS |             | 86.5            |     |                  | 28 Feb 2019 |                    |         |              |
|                                                                |                                                                                                             |               | MSC |             |                 |     | -                |             |                    |         |              |
| Notes: N/A BY MANUFACTURER OF EQUIPMENT INSTALLED              |                                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom                                                | Description                                                                                                                                                            |               | UOM                 | Times Since | Time<br>Accrued | Adj   | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|----------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-------|------------------|-------------|--------------------|---------|--------------|
|                                                                | Part Number                                                                                                                                                            | Serial Number |                     |             |                 |       |                  |             |                    |         | Approx Price |
| Logbook Position                                               | HW                                                                                                                                                                     | SW            |                     |             |                 |       |                  |             |                    |         | Manufacturer |
|                                                                | MM Ref                                                                                                                                                                 |               |                     |             |                 |       |                  |             |                    |         | Date Type    |
|                                                                | Ops Number(s)                                                                                                                                                          |               |                     |             |                 |       |                  |             |                    |         |              |
| <b>EASA 994058<sup>U</sup></b><br><br>(994058)<br><br>Airframe | EASA AD 2018-0262 - Ipeco Holding Ltd - Pilot and CO-Pilot Seats - Modification / Inspection                                                                           |               | HRS                 |             | 2120.8          |       |                  | 925.3       |                    |         | 0            |
|                                                                |                                                                                                                                                                        |               | AFL                 |             | 861             |       |                  | 256         |                    |         | 0            |
|                                                                |                                                                                                                                                                        |               | MOS                 |             | 86.5            |       |                  | 28 Feb 2019 |                    |         |              |
|                                                                |                                                                                                                                                                        |               | MSC                 |             |                 |       | -                |             |                    |         |              |
| Notes: N/A BY MANUFACTURER OF EQUIPMENT INSTALLED              |                                                                                                                                                                        |               |                     |             |                 |       |                  |             |                    |         |              |
| <b>EASA 994060<sup>U</sup></b><br><br>(994060)<br><br>Airframe | EASA AD 2019-0010 - Safran Aerosystems - Life Jacket - Removal/Repair                                                                                                  |               | HRS                 |             | 2093.9          |       |                  | 952.2       |                    |         | 0            |
|                                                                |                                                                                                                                                                        |               | AFL                 |             | 840             |       |                  | 277         |                    |         | 0            |
|                                                                |                                                                                                                                                                        |               | MOS                 |             | 85.5            |       |                  | 27 Mar 2019 |                    |         |              |
|                                                                |                                                                                                                                                                        |               | MSC                 |             |                 |       | -                |             |                    |         |              |
| Notes: N/A BY MANUFACTURER OF EQUIPMENT INSTALLED              |                                                                                                                                                                        |               |                     |             |                 |       |                  |             |                    |         |              |
| <b>FAA 1974-08-09<br/>R03</b><br><br>(994002)<br><br>Airframe  | FAA 1974-08-09 R03 - Equipment/Furnishings - Installation of Placards Prohibiting Smoking In the Lavatory and Disposal of Cigarettes In the Lavatory Waste Receptacles |               | HRS                 |             | 1139.2          |       |                  | 1906.9      |                    |         | 0            |
|                                                                |                                                                                                                                                                        |               | AFL                 |             | 476             |       |                  | 641         |                    |         | 0            |
|                                                                |                                                                                                                                                                        |               | MOS                 |             | 46.1            |       |                  | 07 Jul 2022 |                    |         |              |
|                                                                |                                                                                                                                                                        |               | MSC                 |             |                 |       | -                |             |                    |         |              |
| <b>FAA 2013-12-03</b><br><br>(994003)<br><br>Engine            | No. 1 Engine - FAA 2013-12-03 - Engine Fuel and Control - Spill Return to Fuel Pump Tube - Replacement                                                                 |               | HRS                 |             | 994.4           |       |                  | 0           |                    |         | 0            |
|                                                                |                                                                                                                                                                        |               | ENC                 |             | 392             |       |                  | 0           |                    |         | 0            |
|                                                                |                                                                                                                                                                        |               | MOS                 |             | 41.8            |       |                  | 17 Nov 2022 |                    |         |              |
|                                                                |                                                                                                                                                                        |               | MSC                 |             |                 |       | -                |             |                    |         |              |
|                                                                |                                                                                                                                                                        |               | [End Of Month Item] |             |                 |       |                  |             |                    |         |              |
| <b>FAA 2013-12-03</b><br><br>(994003)<br><br>Engine            | No. 2 Engine - FAA 2013-12-03 - Engine Fuel and Control - Spill Return to Fuel Pump Tube - Replacement                                                                 |               | HRS                 |             | 994.4           |       |                  | 0           |                    |         | 0            |
|                                                                |                                                                                                                                                                        |               | ENC                 |             | 392             |       |                  | 0           |                    |         | 0            |
|                                                                |                                                                                                                                                                        |               | MOS                 |             | 41.9            |       |                  | 15 Nov 2022 |                    |         |              |
|                                                                |                                                                                                                                                                        |               | MSC                 |             |                 |       | -                |             |                    |         |              |
|                                                                |                                                                                                                                                                        |               | [End Of Month Item] |             |                 |       |                  |             |                    |         |              |
| <b>FAA 2014-12-03</b><br><br>(990014)<br><br>Engine            | No. 1 Engine - FAA 2014-12-03 - Engine Fuel and Control - Fuel Metering Units (Fmus) - Replacement                                                                     |               | HRS                 |             | 960.6           |       |                  | 33.8        |                    |         | 0            |
|                                                                |                                                                                                                                                                        |               | ENC                 |             | 377             |       |                  | 15          |                    |         | 0            |
|                                                                |                                                                                                                                                                        |               | DATE                |             | 1192 d          | -3094 |                  | 04 Feb 2023 |                    |         |              |
|                                                                |                                                                                                                                                                        |               | MSC                 |             |                 |       | -                |             |                    |         |              |
|                                                                |                                                                                                                                                                        |               | [End Of Month Item] |             |                 |       |                  |             |                    |         |              |

| ATA<br>U=Custom                    | Description                                                                                                                                                                            |               | UOM                 | Times Since | Time<br>Accrued | Adj   | Required<br>Freq | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-------|------------------|----------|--------------------|---------|--------------|
|                                    | Part Number                                                                                                                                                                            | Serial Number |                     |             |                 |       |                  |          |                    |         | Approx Price |
| Logbook Position                   | HW                                                                                                                                                                                     | SW            |                     |             |                 |       |                  |          |                    |         | Manufacturer |
|                                    | MM Ref                                                                                                                                                                                 |               |                     |             |                 |       |                  |          |                    |         | Date Type    |
|                                    | Ops Number(s)                                                                                                                                                                          |               |                     |             |                 |       |                  |          |                    |         |              |
| FAA 2014-12-03                     | No. 2 Engine - FAA 2014-12-03 - Engine Fuel and Control<br>- Fuel Metering Units (Fmus) - Replacement                                                                                  |               | HRS                 |             | 960.6           |       |                  | 33.8     |                    | 0       |              |
|                                    |                                                                                                                                                                                        |               | ENC                 |             | 377             |       | 15               |          | 0                  |         |              |
|                                    |                                                                                                                                                                                        |               | DATE                |             | 1192 d          | -3094 | 04 Feb 2023      |          |                    |         |              |
|                                    |                                                                                                                                                                                        |               | MSC                 |             |                 | -     |                  |          |                    |         |              |
| (990014)                           |                                                                                                                                                                                        |               | [End Of Month Item] |             |                 |       |                  |          |                    |         |              |
| FAA 2015-08-07                     | FAA 2015-08-07 - Oxygen - Zodiac Aerotechnics<br>(Formerly Intertechnique Aircraft Systems) Flightcrew<br>Oxygen Mask Regulators - Inspection / Replacement of<br>Inflatable Harnesses |               | HRS                 |             | 2673.8          |       |                  | 372.3    |                    | 0       |              |
|                                    |                                                                                                                                                                                        |               | AFL                 |             | 1020            |       | 97               |          | 0                  |         |              |
|                                    |                                                                                                                                                                                        |               | MOS                 |             | 109.7           |       | 20 Mar 2017      |          |                    |         |              |
|                                    |                                                                                                                                                                                        |               | MSC                 |             |                 | -     |                  |          |                    |         |              |
| (994018)                           |                                                                                                                                                                                        |               |                     |             |                 |       |                  |          |                    |         |              |
| Airframe                           |                                                                                                                                                                                        |               |                     |             |                 |       |                  |          |                    |         |              |
| Notes: PN: MC10-15-158 SN: <NONE>. |                                                                                                                                                                                        |               |                     |             |                 |       |                  |          |                    |         |              |
| FAA 2015-20-10                     | AD 2015-20-10 Gulfstream Aerospace Corporation                                                                                                                                         |               | HRS                 |             | 3033.8          |       |                  | 12.3     |                    | 0       |              |
|                                    |                                                                                                                                                                                        |               | AFL                 |             | 1112            |       | 5                |          | 0                  |         |              |
|                                    |                                                                                                                                                                                        |               | MOS                 |             | 124.2           |       | 05 Jan 2016      |          |                    |         |              |
|                                    |                                                                                                                                                                                        |               | MSC                 |             |                 | -     |                  |          |                    |         |              |
| (994020)                           |                                                                                                                                                                                        |               |                     |             |                 |       |                  |          |                    |         |              |
| Airframe                           |                                                                                                                                                                                        |               |                     |             |                 |       |                  |          |                    |         |              |
| FAA 2015-23-09<br>INSPECT          | AD 2015-23-09 Zodiac Aerotechnics Flightcrew Oxygen<br>Mask Regulators (Part 1 - Inspect)                                                                                              |               | HRS                 |             | 3033.8          |       |                  | 12.3     |                    | 0       |              |
|                                    |                                                                                                                                                                                        |               | AFL                 |             | 1112            |       | 5                |          | 0                  |         |              |
|                                    |                                                                                                                                                                                        |               | MOS                 |             | 124.1           |       | 07 Jan 2016      |          |                    |         |              |
|                                    |                                                                                                                                                                                        |               | MSC                 |             |                 | -     |                  |          |                    |         |              |
| (994021)                           |                                                                                                                                                                                        |               |                     |             |                 |       |                  |          |                    |         |              |
| Airframe                           |                                                                                                                                                                                        |               |                     |             |                 |       |                  |          |                    |         |              |
| FAA 2015-23-09<br>REPLACE          | AD 2015-23-09 Zodiac Aerotechnics Flightcrew Oxygen<br>Mask Regulators (Part 2 - Replace)                                                                                              |               | HRS                 |             | 3033.8          |       |                  | 12.3     |                    | 0       |              |
|                                    |                                                                                                                                                                                        |               | AFL                 |             | 1112            |       | 5                |          | 0                  |         |              |
|                                    |                                                                                                                                                                                        |               | MOS                 |             | 124.1           |       | 07 Jan 2016      |          |                    |         |              |
|                                    |                                                                                                                                                                                        |               | MSC                 |             |                 | -     |                  |          |                    |         |              |
| (994022)                           |                                                                                                                                                                                        |               |                     |             |                 |       |                  |          |                    |         |              |
| Airframe                           |                                                                                                                                                                                        |               |                     |             |                 |       |                  |          |                    |         |              |
| FAA 2015-24-06                     | AD 2015-24-06 Gulfstream Aerospace Corporation                                                                                                                                         |               | HRS                 |             | 2673.8          |       |                  | 372.3    |                    | 0       |              |
|                                    |                                                                                                                                                                                        |               | AFL                 |             | 1020            |       | 97               |          | 0                  |         |              |
|                                    |                                                                                                                                                                                        |               | MOS                 |             | 109.6           |       | 23 Mar 2017      |          |                    |         |              |
|                                    |                                                                                                                                                                                        |               | MSC                 |             |                 | -     |                  |          |                    |         |              |
| (994023)                           |                                                                                                                                                                                        |               |                     |             |                 |       |                  |          |                    |         |              |
| Airframe                           |                                                                                                                                                                                        |               |                     |             |                 |       |                  |          |                    |         |              |

| ATA<br>U=Custom                                              | Description                                                                                                                                                                                                                                  |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|--------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                                              | Part Number                                                                                                                                                                                                                                  | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position                                             | HW                                                                                                                                                                                                                                           | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                                              | MM Ref                                                                                                                                                                                                                                       |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                                                              | Ops Number(s)                                                                                                                                                                                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| FAA 2016-11-20                                               | FAA 2016-11-20 - Oxygen - Inspection and Replacement of B/E Aerospace Protective Breathing Equipment (Pbe), Part Number 119003-11 that Are Installed on Airplanes. Superseded By FAA AD 2017-18-12                                           |               | HRS |             | 2901            |     |                  | 145.1       |                    |         | 0            |
|                                                              |                                                                                                                                                                                                                                              |               | AFL |             | 1083            |     |                  | 34          |                    |         | 0            |
|                                                              |                                                                                                                                                                                                                                              |               | MOS |             | 117.6           |     |                  | 22 Jul 2016 |                    |         |              |
|                                                              |                                                                                                                                                                                                                                              |               | MSC |             |                 |     | -                |             |                    |         |              |
| (994026)                                                     |                                                                                                                                                                                                                                              |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                                                     |                                                                                                                                                                                                                                              |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: N/A BY PBE PART NUMBER INSTALLED                      |                                                                                                                                                                                                                                              |               |     |             |                 |     |                  |             |                    |         |              |
| FAA 2017-04-01                                               | FAA 2017-04-01 - Flight Controls - Accomplish an FCC Software Update as Applicable                                                                                                                                                           |               | HRS |             | 2342.8          |     |                  | 703.3       |                    |         | 0            |
|                                                              |                                                                                                                                                                                                                                              |               | AFL |             | 933             |     |                  | 184         |                    |         | 0            |
|                                                              |                                                                                                                                                                                                                                              |               | MOS |             | 95.8            |     |                  | 16 May 2018 |                    |         |              |
|                                                              |                                                                                                                                                                                                                                              |               | MSC |             |                 |     | -                |             |                    |         |              |
| (994035)                                                     |                                                                                                                                                                                                                                              |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                                                     |                                                                                                                                                                                                                                              |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: NO FURTHER ACTION REQ"D DUE PCW ASC037                |                                                                                                                                                                                                                                              |               |     |             |                 |     |                  |             |                    |         |              |
| FAA 2017-18-12                                               | FAA 2017-18-12 - Oxygen - Inspection and Replacement of B/E Aerospace Protective Breathing Equipment (Pbe), Part Number 119003-11 and 119003-21 that Are Installed on Airplanes                                                              |               | HRS |             | 2344.7          |     |                  | 701.4       |                    |         | 0            |
|                                                              |                                                                                                                                                                                                                                              |               | AFL |             | 935             |     |                  | 182         |                    |         | 0            |
|                                                              |                                                                                                                                                                                                                                              |               | MOS |             | 96.5            |     |                  | 27 Apr 2018 |                    |         |              |
|                                                              |                                                                                                                                                                                                                                              |               | MSC |             |                 |     | -                |             |                    |         |              |
| (994042)                                                     |                                                                                                                                                                                                                                              |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                                                     |                                                                                                                                                                                                                                              |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: N/A BY PART, ESSEX INDUSTRIES P/N: MR10093N INSTALLED |                                                                                                                                                                                                                                              |               |     |             |                 |     |                  |             |                    |         |              |
| FAA 2017-20-08                                               | FAA 2017-20-08 - Fuselage - Revise the Limitations Section of the Applicable Gulfstream Afm Specified In Paragraphs (H)(1) Through (H)(6) of This AD to Include the Information In the Applicable Gulfstream Afm Supplement (AFMS) Specified |               | HRS |             | 2504.1          |     |                  | 542         |                    |         | 0            |
|                                                              |                                                                                                                                                                                                                                              |               | AFL |             | 970             |     |                  | 147         |                    |         | 0            |
|                                                              |                                                                                                                                                                                                                                              |               | MOS |             | 101.8           |     |                  | 16 Nov 2017 |                    |         |              |
|                                                              |                                                                                                                                                                                                                                              |               | MSC |             |                 |     | -                |             |                    |         |              |
| (994045)                                                     |                                                                                                                                                                                                                                              |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                                                     |                                                                                                                                                                                                                                              |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: SUPPLEMENT INSTALLED INTO THE AFM                     |                                                                                                                                                                                                                                              |               |     |             |                 |     |                  |             |                    |         |              |



| ATA<br>U=Custom                                                                  | Description                                                                                                                                                                                                                     |               | UOM  | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|----------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                                                                  | Part Number                                                                                                                                                                                                                     | Serial Number |      |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position                                                                 | HW                                                                                                                                                                                                                              | SW            |      |             |                 |     |                  |             |                    |         | Manufacturer |
|                                                                                  | MM Ref                                                                                                                                                                                                                          |               |      |             |                 |     |                  |             |                    |         | Date Type    |
|                                                                                  | Ops Number(s)                                                                                                                                                                                                                   |               |      |             |                 |     |                  |             |                    |         |              |
| FAA 2018-12-07                                                                   | FAA 2018-12-07 - Landing Gear - Modification of the MLG and Brake Assemblies Following the Accomplishment of Gulfstream G650 CB155B, Dated July 26, 2017 and Gulfstream G650ER Customer Bulletin 155B Dated July 26, 2017       |               | HRS  |             | 2320.4          |     |                  | 725.7       |                    |         | 0            |
|                                                                                  |                                                                                                                                                                                                                                 |               | AFL  |             | 926             |     |                  | 191         |                    |         | 0            |
|                                                                                  |                                                                                                                                                                                                                                 |               | MOS  |             | 94.3            |     |                  | 02 Jul 2018 |                    |         |              |
|                                                                                  |                                                                                                                                                                                                                                 |               | MSC  |             |                 |     | -                |             |                    |         |              |
| (994065)                                                                         |                                                                                                                                                                                                                                 |               |      |             |                 |     |                  |             |                    |         |              |
| Airframe                                                                         |                                                                                                                                                                                                                                 |               |      |             |                 |     |                  |             |                    |         |              |
| Notes: NO FURTHER ACTION REQ"D DUE PREVIOUS ACCOMPLISHMENT OF CB155A AND ASC084A |                                                                                                                                                                                                                                 |               |      |             |                 |     |                  |             |                    |         |              |
| FAA 2018-20-04                                                                   | FAA 2018-20-04 - Flight Control - Revise the Normal Procedures and Abnormal Procedures Sections of the Airplane Flight Manual                                                                                                   |               | HRS  |             | 2250.2          |     |                  | 795.9       |                    |         | 0            |
|                                                                                  |                                                                                                                                                                                                                                 |               | AFL  |             | 899             |     |                  | 218         |                    |         | 0            |
|                                                                                  |                                                                                                                                                                                                                                 |               | MOS  |             | 91.3            |     |                  | 01 Oct 2018 |                    |         |              |
|                                                                                  |                                                                                                                                                                                                                                 |               | MSC  |             |                 |     | -                |             |                    |         |              |
| (994068)                                                                         |                                                                                                                                                                                                                                 |               |      |             |                 |     |                  |             |                    |         |              |
| Airframe                                                                         |                                                                                                                                                                                                                                 |               |      |             |                 |     |                  |             |                    |         |              |
| Notes: REQUIREMENTS SATISFIED AS SUPPLEMENT INCLUDED IN ELECTRONIC AFM           |                                                                                                                                                                                                                                 |               |      |             |                 |     |                  |             |                    |         |              |
| FAA 2018-21-14                                                                   | FAA 2018-21-14 - Oxygen - Oxygen Mask Regulator Harness Inflation Hoses - Inspection / Replacement                                                                                                                              |               | HRS  |             | 2093.9          |     |                  | 952.2       |                    |         | 0            |
|                                                                                  |                                                                                                                                                                                                                                 |               | AFL  |             | 840             |     |                  | 277         |                    |         | 0            |
|                                                                                  |                                                                                                                                                                                                                                 |               | MOS  |             | 85.5            |     |                  | 27 Mar 2019 |                    |         |              |
|                                                                                  |                                                                                                                                                                                                                                 |               | MSC  |             |                 |     | -                |             |                    |         |              |
| (994070)                                                                         |                                                                                                                                                                                                                                 |               |      |             |                 |     |                  |             |                    |         |              |
| Airframe                                                                         |                                                                                                                                                                                                                                 |               |      |             |                 |     |                  |             |                    |         |              |
| Notes: N/A BY PN OF CREW OXYGEN MASK REGULATORS INSTALLED                        |                                                                                                                                                                                                                                 |               |      |             |                 |     |                  |             |                    |         |              |
| FAA 2019-21-06 <sup>U</sup>                                                      | Appliance AD - FAA AD 2019-21-06 - Equipment/Furnishings - Ipeco Pilot & CO-Pilot Seats Modification (N/A Equipment Not Installed)                                                                                              |               | HRS  |             | 1786.7          |     |                  | 1259.4      |                    |         | 0            |
|                                                                                  |                                                                                                                                                                                                                                 |               | AFL  |             | 752             |     |                  | 365         |                    |         | 0            |
|                                                                                  |                                                                                                                                                                                                                                 |               | MOS  |             | 77.4            |     |                  | 29 Nov 2019 |                    |         |              |
|                                                                                  |                                                                                                                                                                                                                                 |               | MSC  |             |                 |     | N/A              |             |                    |         |              |
| [End Of Month Item]                                                              |                                                                                                                                                                                                                                 |               |      |             |                 |     |                  |             |                    |         |              |
| Airframe                                                                         |                                                                                                                                                                                                                                 |               |      |             |                 |     |                  |             |                    |         |              |
| FAA 2019-23-11                                                                   | FAA 2019-23-11 - Flight Controls - Revise the Airplane Flight Manual (Afm) By Adding an Airplane Flight Manual Supplement (AFMS), Which Contains Operating Limitations and Abnormal Procedures for Loss of Rudder or Yaw Damper |               | HRS  |             | 1745.4          |     |                  | 1300.7      |                    |         | 0            |
|                                                                                  |                                                                                                                                                                                                                                 |               | AFL  |             | 735             |     |                  | 382         |                    |         | 0            |
|                                                                                  |                                                                                                                                                                                                                                 |               | DATE |             | 2321 d          |     |                  | 02 Jan 2020 |                    |         |              |
|                                                                                  |                                                                                                                                                                                                                                 |               | MSC  |             |                 |     | -                |             |                    |         |              |
| (994078)                                                                         |                                                                                                                                                                                                                                 |               |      |             |                 |     |                  |             |                    |         |              |
| Airframe                                                                         |                                                                                                                                                                                                                                 |               |      |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom                                     | Description                                                                                                                                  |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|-----------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|----------|--------------------|---------|--------------|
|                                                     | Part Number                                                                                                                                  | Serial Number |                     |             |                 |     |                  |          |                    |         | Approx Price |
| Logbook Position                                    | HW                                                                                                                                           | SW            |                     |             |                 |     |                  |          |                    |         | Manufacturer |
|                                                     | MM Ref                                                                                                                                       |               |                     |             |                 |     |                  |          |                    |         | Date Type    |
|                                                     | Ops Number(s)                                                                                                                                |               |                     |             |                 |     |                  |          |                    |         |              |
| FAA 2020-02-18<br><br>(994079)<br><br>Airframe      | FAA 2020-02-18 - Flight Controls - Revise the Airplane Flight Manual (Afm) By Attaching an Airplane Flight Manual Supplement (AFMS)          |               | HRS                 |             | 1723.3          |     |                  | 1322.8   |                    | 0       |              |
|                                                     |                                                                                                                                              |               | AFL                 |             | 721             |     | 396              |          | 0                  |         |              |
|                                                     |                                                                                                                                              |               | DATE                |             | 2278 d          |     | 14 Feb 2020      |          |                    |         |              |
|                                                     |                                                                                                                                              |               | MSC                 |             |                 | -   |                  |          |                    |         |              |
| FAA 2020-11-01<br><br>(994080)<br><br>Airframe      | FAA 2020-11-01 - Flight Controls - Pfcas Remote Electronics Unit (Reu) - Software Update                                                     |               | HRS                 |             | 1642.8          |     |                  | 1403.3   |                    | 0       |              |
|                                                     |                                                                                                                                              |               | AFL                 |             | 682             |     | 435              |          | 0                  |         |              |
|                                                     |                                                                                                                                              |               | MOS                 |             | 70.4            |     | 30 Jun 2020      |          |                    |         |              |
|                                                     |                                                                                                                                              |               | MSC                 |             |                 | -   |                  |          |                    |         |              |
| FAA 2020-18-51-E<br><br>(990048)<br><br>Airframe    | FAA 2020-18-51-E - Sandia Aerospace - Airplane Flight Manual - Section Limitations - Amendment                                               |               | HRS                 |             | 1603.6          |     |                  | 1442.5   | 0                  | 0       |              |
|                                                     |                                                                                                                                              |               | AFL                 |             | 656             |     | 461              | 0        | 0                  |         |              |
|                                                     |                                                                                                                                              |               | MOS                 |             | 68.5            |     | 28 Aug 2020      |          |                    |         |              |
|                                                     |                                                                                                                                              |               | MSC                 |             |                 | -   |                  |          |                    |         |              |
| FAA 2021-07-13 <sup>U</sup><br><br><br><br>Airframe | Appliance AD - Equipment and Furnishing - Seat Restraint System Plastic Rotary Buckle Handle - Inspection/Replacement (Not Applicable)       |               | HRS                 |             | 1435.2          |     |                  | 1610.9   |                    | 0       |              |
|                                                     |                                                                                                                                              |               | AFL                 |             | 551             |     | 566              |          | 0                  |         |              |
|                                                     |                                                                                                                                              |               | MOS                 |             | 60.4            |     | 30 Apr 2021      |          |                    |         |              |
|                                                     |                                                                                                                                              |               | MSC                 |             |                 | N/A |                  |          |                    |         |              |
|                                                     |                                                                                                                                              |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| FAA 2021-08-07 <sup>U</sup><br><br><br><br>Airframe | Appliance AD - Rockwell Collins - Global Positioning System GPS-4000S - Upgrade (Not Applicable)                                             |               | HRS                 |             | 1435.2          |     |                  | 1610.9   |                    | 0       |              |
|                                                     |                                                                                                                                              |               | AFL                 |             | 551             |     | 566              |          | 0                  |         |              |
|                                                     |                                                                                                                                              |               | MOS                 |             | 60.4            |     | 30 Apr 2021      |          |                    |         |              |
|                                                     |                                                                                                                                              |               | MSC                 |             |                 | N/A |                  |          |                    |         |              |
|                                                     |                                                                                                                                              |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| FAA 2021-08-15 <sup>U</sup><br><br><br><br>Airframe | Appliance AD - Navigation - Garmin International Gmn-00962 Gts Processor Units, Part Number 011-02571-0() - Software Update (Not Applicable) |               | HRS                 |             | 1435.2          |     |                  | 1610.9   |                    | 0       |              |
|                                                     |                                                                                                                                              |               | AFL                 |             | 551             |     | 566              |          | 0                  |         |              |
|                                                     |                                                                                                                                              |               | MOS                 |             | 60.4            |     | 30 Apr 2021      |          |                    |         |              |
|                                                     |                                                                                                                                              |               | MSC                 |             |                 | N/A |                  |          |                    |         |              |
|                                                     |                                                                                                                                              |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |

| ATA<br>U=Custom            | Description                                                                                                                                      |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|----------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|----------|--------------------|---------|--------------|
|                            | Part Number                                                                                                                                      | Serial Number |     |             |                 |     |                  |          |                    |         | Approx Price |
| Logbook Position           | HW                                                                                                                                               | SW            |     |             |                 |     |                  |          |                    |         | Manufacturer |
|                            | MM Ref                                                                                                                                           |               |     |             |                 |     |                  |          |                    |         | Date Type    |
|                            | Ops Number(s)                                                                                                                                    |               |     |             |                 |     |                  |          |                    |         |              |
| FAA 2021-23-12             | FAA 2021-23-12 - Indicating / Recording / Navigation -<br>Radio (Radar) Altimeter - Afm Revision to Incorporate<br>Limitations                   |               | HRS |             | 1312.2          |     |                  | 1733.9   |                    | 0       |              |
|                            |                                                                                                                                                  |               | AFL |             | 509             |     | 608              |          | 0                  |         |              |
|                            |                                                                                                                                                  |               | MOS |             | 52.4            |     | 30 Dec 2021      |          |                    |         |              |
|                            |                                                                                                                                                  |               | MSC |             |                 | -   |                  |          |                    |         |              |
| (992199)                   |                                                                                                                                                  |               |     |             |                 |     |                  |          |                    |         |              |
| Airframe                   |                                                                                                                                                  |               |     |             |                 |     |                  |          |                    |         |              |
| FAA 2023-09-09             | FAA 2023-09-09 - Exhaust Turbine System (Recip) - Spot-<br>Welded Multi-Segment Exhaust Tailpipe V-Band Coupling<br>- Inspection/Replacement     |               | HRS |             |                 |     |                  |          |                    | 0       |              |
|                            |                                                                                                                                                  |               | AFL |             |                 |     |                  |          | 0                  |         |              |
|                            |                                                                                                                                                  |               | MOS |             | 26.2            |     | 05 Mar 2024      |          |                    |         |              |
|                            |                                                                                                                                                  |               | MSC |             |                 | -   |                  |          |                    |         |              |
| (990909)                   |                                                                                                                                                  |               |     |             |                 |     |                  |          |                    |         |              |
| Airframe                   |                                                                                                                                                  |               |     |             |                 |     |                  |          |                    |         |              |
| FAA 2023-09-09<br>PARA (H) | FAA 2023-09-09 Para (H) - Review the Aircraft<br>Maintenance Records to Determine the Number of Hours<br>Tis Accumulated on Each V-Band Coupling |               | HRS |             |                 |     |                  |          |                    | 0       |              |
|                            |                                                                                                                                                  |               | AFL |             |                 |     |                  |          | 0                  |         |              |
|                            |                                                                                                                                                  |               | MOS |             | 26.2            |     | 05 Mar 2024      |          |                    |         |              |
|                            |                                                                                                                                                  |               | MSC |             |                 | -   |                  |          |                    |         |              |
| (990910)                   |                                                                                                                                                  |               |     |             |                 |     |                  |          |                    |         |              |
| Airframe                   |                                                                                                                                                  |               |     |             |                 |     |                  |          |                    |         |              |
| FAA 2023-09-09<br>PARA (I) | FAA 2023-09-09 Para (I) - Remove the V-Band Coupling<br>from Service and Install A New V-Band Coupling                                           |               | HRS |             |                 |     |                  |          |                    | 0       |              |
|                            |                                                                                                                                                  |               | AFL |             |                 |     |                  |          | 0                  |         |              |
|                            |                                                                                                                                                  |               | MOS |             | 26.2            |     | 05 Mar 2024      |          |                    |         |              |
|                            |                                                                                                                                                  |               | MSC |             |                 | -   |                  |          |                    |         |              |
| (990911)                   |                                                                                                                                                  |               |     |             |                 |     |                  |          |                    |         |              |
| Airframe                   |                                                                                                                                                  |               |     |             |                 |     |                  |          |                    |         |              |
| FAA 2023-09-09<br>PARA (J) | FAA 2023-09-09 Para (J) - Visually Inspect the V-Band<br>Coupling                                                                                |               | HRS |             |                 |     |                  |          |                    | 0       |              |
|                            |                                                                                                                                                  |               | AFL |             |                 |     |                  |          | 0                  |         |              |
|                            |                                                                                                                                                  |               | MOS |             | 26.2            |     | 05 Mar 2024      |          |                    |         |              |
|                            |                                                                                                                                                  |               | MSC |             |                 | -   |                  |          |                    |         |              |
| (990912)                   |                                                                                                                                                  |               |     |             |                 |     |                  |          |                    |         |              |
| Airframe                   |                                                                                                                                                  |               |     |             |                 |     |                  |          |                    |         |              |
| FAA 2023-09-09<br>PARA (K) | FAA 2023-09-09 Para (K) - Inspections Without Removal<br>of the V-Band Coupling                                                                  |               | HRS |             |                 |     |                  |          |                    | 0       |              |
|                            |                                                                                                                                                  |               | AFL |             |                 |     |                  |          | 0                  |         |              |
|                            |                                                                                                                                                  |               | MOS |             | 26.2            |     | 05 Mar 2024      |          |                    |         |              |
|                            |                                                                                                                                                  |               | MSC |             |                 | -   |                  |          |                    |         |              |
| (990913)                   |                                                                                                                                                  |               |     |             |                 |     |                  |          |                    |         |              |
| Airframe                   |                                                                                                                                                  |               |     |             |                 |     |                  |          |                    |         |              |

| ATA<br>U=Custom                                            | Description                                                                                                                                           |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|----------|---------------------|---------|--------------|
|                                                            | Part Number                                                                                                                                           | Serial Number |     |             |                 |     |                  |          |                     |         | Approx Price |
| Logbook Position                                           | HW                                                                                                                                                    | SW            |     |             |                 |     |                  |          |                     |         | Manufacturer |
|                                                            | MM Ref                                                                                                                                                |               |     |             |                 |     |                  |          |                     |         | Date Type    |
|                                                            | Ops Number(s)                                                                                                                                         |               |     |             |                 |     |                  |          |                     |         |              |
| FAA 2023-09-09<br>PARA (L)<br><br>(990914)<br><br>Airframe | FAA 2023-09-09 Para (L) - Inspections With the Spot-Welded, Multi-Segment Exhaust Tailpipe V-Band Coupling Removed                                    |               | HRS |             |                 |     |                  |          |                     |         | 0            |
|                                                            |                                                                                                                                                       |               | AFL |             |                 |     |                  |          |                     | 0       |              |
|                                                            |                                                                                                                                                       |               | MOS | 26.2        |                 |     | 05 Mar 2024      |          |                     |         |              |
|                                                            |                                                                                                                                                       |               | MSC |             |                 | -   |                  |          |                     |         |              |
| FAA 2023-09-09<br>PARA (M)<br>(990915)<br><br>Airframe     | FAA 2023-09-09 Para (M) - Installation Prohibitions                                                                                                   |               | HRS |             |                 |     |                  |          |                     |         | 0            |
|                                                            |                                                                                                                                                       |               | AFL |             |                 |     |                  |          |                     | 0       |              |
|                                                            |                                                                                                                                                       |               | MOS | 26.2        |                 |     | 05 Mar 2024      |          |                     |         |              |
|                                                            |                                                                                                                                                       |               | MSC |             |                 | -   |                  |          |                     |         |              |
| FAA 2023-10-02<br><br>(992312)<br><br>Airframe             | Appliance AD - FAA 2023-10-02 - Indicating/Recording System/Navigation - Radio Altimeter - Afm Revision (Mandatory)                                   |               | HRS |             | 828.3           |     |                  | 2217.8   | 0                   |         | 0            |
|                                                            |                                                                                                                                                       |               | AFL |             | 348             |     |                  | 769      | 0                   |         | 0            |
|                                                            |                                                                                                                                                       |               | MOS | 34.4        |                 |     | 30 Jun 2023      |          |                     |         |              |
|                                                            |                                                                                                                                                       |               | MSC |             |                 | -   |                  |          |                     |         |              |
| FAA 2023-10-02<br>PARA (H)<br><br>(992313)<br><br>Airframe | FAA 2023-10-02 Para (H) - Revise the Limitations Section of the Existing Afm (until 30--June- 2023 - Satisfied By FAA 2021-23-12) (Mandatory)         |               | HRS |             | 828.3           |     |                  | 2217.8   | 0                   |         | 0            |
|                                                            |                                                                                                                                                       |               | AFL |             | 348             |     |                  | 769      | 0                   |         | 0            |
|                                                            |                                                                                                                                                       |               | MOS | 34.4        |                 |     | 30 Jun 2023      |          |                     |         |              |
|                                                            |                                                                                                                                                       |               | MSC |             |                 | -   |                  |          |                     |         |              |
| FAA 2023-10-02<br>PARA (I)<br><br>(992314)<br><br>Airframe | FAA 2023-10-02 Para (I) - Revise the Limitations Section and Remove the Afm Revision Required By Para (H) (after 30 Jun 2023) (Mandatory)             |               | HRS |             | 828.3           |     |                  | 2217.8   | 0                   |         | 0            |
|                                                            |                                                                                                                                                       |               | AFL |             | 348             |     |                  | 769      | 0                   |         | 0            |
|                                                            |                                                                                                                                                       |               | MOS | 34.4        |                 |     | 30 Jun 2023      |          |                     |         |              |
|                                                            |                                                                                                                                                       |               | MSC |             |                 | -   |                  |          |                     |         |              |
| FAA 2023-12-25<br><br>(991225)<br><br>Airframe             | FAA 2023-12-25 - Equipment / Furnishings - Survitec Group Limited (Rfd Beaufot Ltd.) Type 102 Mk 3, 102 Mk 4 and Type 105 Mk 1 Life Jackets - Replace |               | HRS |             | 793.5           |     |                  | 2252.6   | 0                   |         | 0            |
|                                                            |                                                                                                                                                       |               | AFL |             | 339             |     |                  | 778      | 0                   |         | 0            |
|                                                            |                                                                                                                                                       |               | MOS | 33.6        |                 |     | 22 Jul 2023      |          |                     |         |              |
|                                                            |                                                                                                                                                       |               | MSC |             |                 | -   |                  |          |                     |         |              |

| ATA<br>U=Custom                                           | Description                                                                                                                                           |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|-----------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|----------|--------------------|---------|--------------|
|                                                           | Part Number                                                                                                                                           | Serial Number |     |             |                 |     |                  |          |                    |         | Approx Price |
| Logbook Position                                          | HW                                                                                                                                                    | SW            |     |             |                 |     |                  |          |                    |         | Manufacturer |
|                                                           | MM Ref                                                                                                                                                |               |     |             |                 |     |                  |          |                    |         | Date Type    |
|                                                           | Ops Number(s)                                                                                                                                         |               |     |             |                 |     |                  |          |                    |         |              |
| FAA 2023-13-11<br><br>(991311)<br><br>Airframe            | Appliance AD - Oxygen - Oxygen Valve Assemblies /<br>Oxygen Cylinder and Valve Assemblies -<br>Inspection/Replacement (Mandatory)                     |               | HRS |             |                 |     |                  |          |                    |         | 0            |
|                                                           |                                                                                                                                                       |               | AFL |             |                 |     |                  |          |                    | 0       |              |
|                                                           |                                                                                                                                                       |               | MOS | 33.1        |                 |     | 07 Aug 2023      |          |                    |         |              |
|                                                           |                                                                                                                                                       |               | MSC |             |                 | -   |                  |          |                    |         |              |
| FAA 2023-13-11<br>PARA (H)<br>(991312)<br><br>Airframe    | Inspect the Oxygen Valve Assemblies and Oxygen<br>Cylinder and Valve Assemblies (Mandatory)                                                           |               | HRS |             |                 |     |                  |          |                    |         | 0            |
|                                                           |                                                                                                                                                       |               | AFL |             |                 |     |                  |          |                    | 0       |              |
|                                                           |                                                                                                                                                       |               | MOS | 33.1        |                 |     | 07 Aug 2023      |          |                    |         |              |
|                                                           |                                                                                                                                                       |               | MSC |             |                 | -   |                  |          |                    |         |              |
| FAA 2023-13-11<br>PARA (J)<br>(991313)<br><br>Airframe    | Report the Results of the Inspection and Return Parts (as<br>Required) (Mandatory)                                                                    |               | HRS |             |                 |     |                  |          |                    |         | 0            |
|                                                           |                                                                                                                                                       |               | AFL |             |                 |     |                  |          |                    | 0       |              |
|                                                           |                                                                                                                                                       |               | MOS | 33.1        |                 |     | 07 Aug 2023      |          |                    |         |              |
|                                                           |                                                                                                                                                       |               | MSC |             |                 | -   |                  |          |                    |         |              |
| FAA 2023-14-10<br><br>(991410)<br><br>Airframe            | Appliance AD - Flight Compartment Equipment - Ipeco<br>Holdings Limited (Ipeco) Pilot and CO-Pilot Seats -<br>Inspection/Modification (Mandatory)     |               | HRS |             |                 |     |                  |          |                    |         | 0            |
|                                                           |                                                                                                                                                       |               | AFL |             |                 |     |                  |          |                    | 0       |              |
|                                                           |                                                                                                                                                       |               | MOS | 33.1        |                 |     | 09 Aug 2023      |          |                    |         |              |
|                                                           |                                                                                                                                                       |               | MSC |             |                 | -   |                  |          |                    |         |              |
| FAA 2023-14-10<br>PARA (G)(1)<br>(991411)<br><br>Airframe | Modify and RE-Identify Each Affected Pilot and CO-Pilot<br>Seat (Seats that Have Not Installed the Track Lock Spring<br>Modification Kit) (Mandatory) |               | HRS |             |                 |     |                  |          |                    |         | 0            |
|                                                           |                                                                                                                                                       |               | AFL |             |                 |     |                  |          |                    | 0       |              |
|                                                           |                                                                                                                                                       |               | MOS | 33.1        |                 |     | 09 Aug 2023      |          |                    |         |              |
|                                                           |                                                                                                                                                       |               | MSC |             |                 | -   |                  |          |                    |         |              |
| FAA 2023-14-10<br>PARA (G)(2)<br>(991412)<br><br>Airframe | Inspect the Track Lock Spring of Each Seat (Mandatory)                                                                                                |               | HRS |             |                 |     |                  |          |                    |         | 0            |
|                                                           |                                                                                                                                                       |               | AFL |             |                 |     |                  |          |                    | 0       |              |
|                                                           |                                                                                                                                                       |               | MOS | 33.1        |                 |     | 09 Aug 2023      |          |                    |         |              |
|                                                           |                                                                                                                                                       |               | MSC |             |                 | -   |                  |          |                    |         |              |

| ATA<br>U=Custom                                           | Description                                                                                                                                        |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|-----------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|----------|--------------------|---------|--------------|
|                                                           | Part Number                                                                                                                                        | Serial Number |     |             |                 |     |                  |          |                    |         | Approx Price |
| Logbook Position                                          | HW                                                                                                                                                 | SW            |     |             |                 |     |                  |          |                    |         | Manufacturer |
|                                                           | MM Ref                                                                                                                                             |               |     |             |                 |     |                  |          |                    |         | Date Type    |
|                                                           | Ops Number(s)                                                                                                                                      |               |     |             |                 |     |                  |          |                    |         |              |
| FAA 2023-14-10<br>PARA (G)(3)<br>(991413)<br><br>Airframe | Send the Inspection Results, Including No Findings, to<br>Ipeco (Mandatory)                                                                        |               | HRS |             |                 |     |                  |          |                    |         | 0            |
|                                                           |                                                                                                                                                    |               | AFL |             |                 |     |                  |          |                    | 0       |              |
|                                                           |                                                                                                                                                    |               | MOS | 33.1        |                 |     | 09 Aug 2023      |          |                    |         |              |
|                                                           |                                                                                                                                                    |               | MSC |             |                 | -   |                  |          |                    |         |              |
| FAA 2023-14-10<br>PARA (H)<br>(991414)<br><br>Airframe    | Modify and RE-Identify Each Affected Seat (Mandatory)                                                                                              |               | HRS |             |                 |     |                  |          |                    |         | 0            |
|                                                           |                                                                                                                                                    |               | AFL |             |                 |     |                  |          |                    | 0       |              |
|                                                           |                                                                                                                                                    |               | MOS | 33.1        |                 |     | 09 Aug 2023      |          |                    |         |              |
|                                                           |                                                                                                                                                    |               | MSC |             |                 | -   |                  |          |                    |         |              |
| FAA 2023-21-05<br><br>(991205)<br><br>Airframe            | Appliance AD - FAA 2023-21-05 - Navigation - Flight<br>Management Computer 2/Navigation Modules -<br>Operational Limitations/Amendment (Mandatory) |               | HRS |             |                 |     |                  |          |                    |         | 0            |
|                                                           |                                                                                                                                                    |               | AFL |             |                 |     |                  |          |                    | 0       |              |
|                                                           |                                                                                                                                                    |               | MOS | 25.5        |                 |     | 28 Mar 2024      |          |                    |         |              |
|                                                           |                                                                                                                                                    |               | MSC |             |                 | -   |                  |          |                    |         |              |
| FAA 2025-07-01<br><br>(995701)<br><br>Airframe            | Appliance AD - 2025-07-01 - Thommen Aircraft Equipment<br>Ag (Thommen) AC32 Digital AIR Data Computers (Adcs)<br>(Mandatory)                       |               | HRS |             |                 |     |                  |          |                    |         | 0            |
|                                                           |                                                                                                                                                    |               | AFL |             |                 |     |                  |          |                    | 0       |              |
|                                                           |                                                                                                                                                    |               | MOS | 12.5        |                 |     | 28 Apr 2025      |          |                    |         |              |
|                                                           |                                                                                                                                                    |               | MSC |             |                 | -   |                  |          |                    |         |              |
| FAA 994046 <sup>U</sup><br>(994046)<br><br>Airframe       | FAA AD 2017-22-02 – Pilot and CO-Pilot Seats –<br>Modification                                                                                     |               | HRS | 2399.8      |                 |     | 646.3            |          |                    | 0       |              |
|                                                           |                                                                                                                                                    |               | AFL | 946         |                 |     | 171              |          | 0                  |         |              |
|                                                           |                                                                                                                                                    |               | MOS | 98.5        |                 |     | 28 Feb 2018      |          |                    |         |              |
|                                                           |                                                                                                                                                    |               | MSC |             |                 | -   |                  |          |                    |         |              |
| Notes: N/A BY EQUIPMENT INSTALLED                         |                                                                                                                                                    |               |     |             |                 |     |                  |          |                    |         |              |
| FAA 994047 <sup>U</sup><br>(994047)<br><br>Airframe       | FAA AD 2017-19-05 - Siemens S.A.S Smoke Detector<br>Replacement                                                                                    |               | HRS | 2399.8      |                 |     | 646.3            |          |                    | 0       |              |
|                                                           |                                                                                                                                                    |               | AFL | 946         |                 |     | 171              |          | 0                  |         |              |
|                                                           |                                                                                                                                                    |               | MOS | 98.5        |                 |     | 28 Feb 2018      |          |                    |         |              |
|                                                           |                                                                                                                                                    |               | MSC |             |                 | -   |                  |          |                    |         |              |
| Notes: N/A BY PN INSTALLED                                |                                                                                                                                                    |               |     |             |                 |     |                  |          |                    |         |              |

| ATA<br>U=Custom                                         | Description                                                                                                                                         |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|---------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                                         | Part Number                                                                                                                                         | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position                                        | HW                                                                                                                                                  | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                                         | MM Ref                                                                                                                                              |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                                                         | Ops Number(s)                                                                                                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| FAA 994051 <sup>U</sup><br><br>(994051)<br><br>Airframe | FAA AD 2018-03-04 - Rosemount Pitot Probes                                                                                                          |               | HRS |             | 2352.7          |     |                  | 693.4       |                    |         | 0            |
|                                                         |                                                                                                                                                     |               | AFL |             | 938             |     |                  | 179         |                    |         | 0            |
|                                                         |                                                                                                                                                     |               | MOS |             | 97.5            |     |                  | 28 Mar 2018 |                    |         |              |
|                                                         |                                                                                                                                                     |               | MSC |             |                 |     | -                |             |                    |         |              |
| Notes: BY SN OF EQUIPMENT INSTALLED                     |                                                                                                                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| FAA 994054 <sup>U</sup><br><br>(994054)<br><br>Airframe | FAA AD 2018-19-15 Geven S.P.A. Seat Assemblies, Type D1- 02 and D1-03                                                                               |               | HRS |             | 2175.3          |     |                  | 870.8       |                    |         | 0            |
|                                                         |                                                                                                                                                     |               | AFL |             | 879             |     |                  | 238         |                    |         | 0            |
|                                                         |                                                                                                                                                     |               | MOS |             | 89.4            |     |                  | 30 Nov 2018 |                    |         |              |
|                                                         |                                                                                                                                                     |               | MSC |             |                 |     | -                |             |                    |         |              |
| Notes: N/A BY EQUIPMENT INSTALLED                       |                                                                                                                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| FAA 994056 <sup>U</sup><br><br>(994056)<br><br>Airframe | FAA AD 2018-23-01 Zodiac Seats France Cabin Attendant Seats                                                                                         |               | HRS |             | 2175.3          |     |                  | 870.8       |                    |         | 0            |
|                                                         |                                                                                                                                                     |               | AFL |             | 879             |     |                  | 238         |                    |         | 0            |
|                                                         |                                                                                                                                                     |               | MOS |             | 89.4            |     |                  | 30 Nov 2018 |                    |         |              |
|                                                         |                                                                                                                                                     |               | MSC |             |                 |     | -                |             |                    |         |              |
| Notes: N/A DUE EQUIPMENT NOT INSTALLED                  |                                                                                                                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| FAA 994059 <sup>U</sup><br><br>(994059)<br><br>Airframe | FAA AD 2019-01-02 - Aspen Avionics, Inc., Evolution Flight Display Units                                                                            |               | HRS |             | 2120.8          |     |                  | 925.3       |                    |         | 0            |
|                                                         |                                                                                                                                                     |               | AFL |             | 861             |     |                  | 256         |                    |         | 0            |
|                                                         |                                                                                                                                                     |               | MOS |             | 86.5            |     |                  | 28 Feb 2019 |                    |         |              |
|                                                         |                                                                                                                                                     |               | MSC |             |                 |     | -                |             |                    |         |              |
| Notes: N/A BY MANUFACTURER OF EQUIPMENT INSTALLED       |                                                                                                                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| FAA 994062 <sup>U</sup><br><br>(994062)<br><br>Airframe | FAA AD 2019-07-03 - Equipment / Furnishings – Rear Cabin Attendant Seat – Inspection / Repair                                                       |               | HRS |             | 1920.3          |     |                  | 1125.8      |                    |         | 0            |
|                                                         |                                                                                                                                                     |               | AFL |             | 794             |     |                  | 323         |                    |         | 0            |
|                                                         |                                                                                                                                                     |               | MOS |             | 81.4            |     |                  | 31 Jul 2019 |                    |         |              |
|                                                         |                                                                                                                                                     |               | MSC |             |                 |     | -                |             |                    |         |              |
| Notes: N/A DUE EQUIPMENT NOT INSTALLED                  |                                                                                                                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| FAA 994063 <sup>U</sup><br><br>(994063)<br><br>Airframe | FAA AD 2019-13-03 - Trig Avionics TT31 MODE S Transponders Avadyne Corporation AXP340 MODE S Transponders Bendix King / Honeywell KT74 Transponders |               | HRS |             | 1920.3          |     |                  | 1125.8      |                    |         | 0            |
|                                                         |                                                                                                                                                     |               | AFL |             | 794             |     |                  | 323         |                    |         | 0            |
|                                                         |                                                                                                                                                     |               | MOS |             | 81.4            |     |                  | 31 Jul 2019 |                    |         |              |
|                                                         |                                                                                                                                                     |               | MSC |             |                 |     | -                |             |                    |         |              |
| Notes: N/A BY PN OF EQUIPMENT INSTALLED                 |                                                                                                                                                     |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom                                         | Description                                                                                                                                                 |               | UOM  | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|---------------------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|------|-------------|-----------------|-----|------------------|----------|--------------------|---------|--------------|
|                                                         | Part Number                                                                                                                                                 | Serial Number |      |             |                 |     |                  |          |                    |         | Approx Price |
| Logbook Position                                        | HW                                                                                                                                                          | SW            |      |             |                 |     |                  |          |                    |         | Manufacturer |
|                                                         | MM Ref                                                                                                                                                      |               |      |             |                 |     |                  |          |                    |         | Date Type    |
|                                                         | Ops Number(s)                                                                                                                                               |               |      |             |                 |     |                  |          |                    |         |              |
| FAA 994064 <sup>U</sup><br><br>(994064)<br><br>Airframe | FAA AD 2019-14-05 - Equipment / Furnishings - Seat<br>Energy Absorber Assembly - Modification                                                               |               | HRS  |             | 1920.3          |     |                  | 1125.8   |                    | 0       |              |
|                                                         |                                                                                                                                                             |               | AFL  |             | 794             |     | 323              |          | 0                  |         |              |
|                                                         |                                                                                                                                                             |               | MOS  |             | 81.4            |     | 31 Jul 2019      |          |                    |         |              |
|                                                         |                                                                                                                                                             |               | MSC  |             |                 | -   |                  |          |                    |         |              |
| Notes: N/A BY PN OF EQUIPMENT INSTALLED                 |                                                                                                                                                             |               |      |             |                 |     |                  |          |                    |         |              |
| FAA 994065 <sup>U</sup><br><br>(994065)<br><br>Airframe | FAA AD 2019-15-10 - Equipment / Furnishings - Safran<br>Life Jackets                                                                                        |               | HRS  |             | 1885.7          |     |                  | 1160.4   |                    | 0       |              |
|                                                         |                                                                                                                                                             |               | AFL  |             | 779             |     | 338              |          | 0                  |         |              |
|                                                         |                                                                                                                                                             |               | MOS  |             | 80.4            |     | 30 Aug 2019      |          |                    |         |              |
|                                                         |                                                                                                                                                             |               | MSC  |             |                 | -   |                  |          |                    |         |              |
| Notes: N/A BY MANUFACTURER OF EQUIPMENT INSTALLED       |                                                                                                                                                             |               |      |             |                 |     |                  |          |                    |         |              |
| SIAC - Service Information/Bulletins                    |                                                                                                                                                             |               |      |             |                 |     |                  |          |                    |         |              |
| 3202908-36-1912<br><br>(361107)<br><br>Airframe         | Sb 3202908-36-1912 - Honeywell Sb 3202908-36-1912 -<br>Rework Four Inch Diameter Check Valve, Pn 3202908-1<br>to Pn 3202908-2, Used on the Gulfstream G650. |               | HRS  |             | 3046.1          |     |                  | 0        |                    | 0       |              |
|                                                         |                                                                                                                                                             |               | AFL  |             | 1117            |     | 0                |          | 0                  |         |              |
|                                                         |                                                                                                                                                             |               | MOS  |             | 128.6           |     | 24 Aug 2015      |          |                    |         |              |
|                                                         |                                                                                                                                                             |               | MSC  |             |                 | -   |                  |          |                    |         |              |
| Notes: PN: 3215662-2 SN: 1917. MRI PARENT CODE: 361105  |                                                                                                                                                             |               |      |             |                 |     |                  |          |                    |         |              |
| 3202908-36-1912<br><br>(361106)<br><br>Airframe         | Sb 3202908-36-1912 - Honeywell Sb 3202908-36-1912 -<br>Rework Four Inch Diameter Check Valve, Pn 3202908-1<br>to Pn 3202908-2, Used on the Gulfstream G650. |               | HRS  |             | 3046.1          |     |                  | 0        |                    | 0       |              |
|                                                         |                                                                                                                                                             |               | AFL  |             | 1117            |     | 0                |          | 0                  |         |              |
|                                                         |                                                                                                                                                             |               | MOS  |             | 128.6           |     | 24 Aug 2015      |          |                    |         |              |
|                                                         |                                                                                                                                                             |               | MSC  |             |                 | -   |                  |          |                    |         |              |
| Notes: PN: 3215662-2 SN: 1993. MRI PARENT CODE: 361104  |                                                                                                                                                             |               |      |             |                 |     |                  |          |                    |         |              |
| 52-10-02-011<br><br>(252345)<br><br>Airframe            | Sb 52-10-02-011 - Enflite Sb 52-10-02-011 - 42600 Series<br>Electric Pocket Doors Drive Gear Assembly Replacement                                           |               | HRS  |             | 3046.1          |     |                  | 0        |                    | 0       |              |
|                                                         |                                                                                                                                                             |               | AFL  |             | 1117            |     | 0                |          | 0                  |         |              |
|                                                         |                                                                                                                                                             |               | DATE |             |                 |     |                  |          |                    |         |              |
|                                                         |                                                                                                                                                             |               | MSC  |             |                 | -   |                  |          |                    |         |              |
| ACB004A PART I<br><br>(990041)<br><br>Airframe          | ACB004A Part I - Landing Gear (ATA 32), Inspection -<br>Brake Inlet SELF-Sealing Couplings Torque                                                           |               | HRS  |             | 3033.8          |     |                  | 12.3     |                    | 0       |              |
|                                                         |                                                                                                                                                             |               | AFL  |             | 1112            |     | 5                |          | 0                  |         |              |
|                                                         |                                                                                                                                                             |               | MOS  |             | 124.2           |     | 05 Jan 2016      |          |                    |         |              |
|                                                         |                                                                                                                                                             |               | MSC  |             |                 | -   |                  |          |                    |         |              |



| ATA<br>U=Custom                                | Description                                                                                                                                         |               | UOM  | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |   |
|------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------|---------------|------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|---|
|                                                | Part Number                                                                                                                                         | Serial Number |      |             |                 |     |                  |             |                    |         | Approx Price |   |
| Logbook Position                               | HW                                                                                                                                                  | SW            |      |             |                 |     |                  |             |                    |         | Manufacturer |   |
|                                                | MM Ref                                                                                                                                              |               |      |             |                 |     |                  |             |                    |         | Date Type    |   |
|                                                | Ops Number(s)                                                                                                                                       |               |      |             |                 |     |                  |             |                    |         |              |   |
| <b>ACB004A PART II</b><br>(990042)<br>Airframe | ACB004A Part Ii - Landing Gear (ATA 32), Inspection - Brake Inlet SELF-Sealing Couplings Torque                                                     |               | HRS  |             | 2673.8          |     |                  | 372.3       |                    |         | 0            |   |
|                                                |                                                                                                                                                     |               | AFL  |             | 1020            |     |                  | 97          |                    |         | 0            |   |
|                                                |                                                                                                                                                     |               | MOS  |             | 109.6           |     |                  | 23 Mar 2017 |                    |         |              |   |
|                                                |                                                                                                                                                     |               | MSC  |             |                 |     | -                |             |                    |         |              |   |
| <b>ACB006</b><br>(990060)<br>Airframe          | ACB006 - Engine (ATA 72), Inspection- High Pressure Compressor Variable Stator Vanes Mechanism (Rolls-Royce Nmsb Sb-BR700-72-900178)                |               | HRS  |             | 1955.3          |     |                  | 1090.8      |                    |         | 0            |   |
|                                                |                                                                                                                                                     |               | AFL  |             | 803             |     |                  | 314         |                    |         | 0            |   |
|                                                |                                                                                                                                                     |               | MOS  |             | 81.9            |     |                  | 13 Jul 2019 |                    |         |              |   |
|                                                |                                                                                                                                                     |               | MSC  |             |                 |     | -                |             |                    |         |              |   |
| <b>ACB007</b><br>(990070)<br>Airframe          | ACB007 - Fuselage Structure (ATA 53) - Operational Limitations - Auxiliary Power Unit Enclosure Installation                                        |               | HRS  |             | 1454            |     |                  | 1592.1      |                    |         | 0            |   |
|                                                |                                                                                                                                                     |               | AFL  |             | 573             |     |                  | 544         |                    |         | 0            |   |
|                                                |                                                                                                                                                     |               | MOS  |             | 64.2            |     |                  | 05 Jan 2021 |                    |         |              |   |
|                                                |                                                                                                                                                     |               | MSC  |             |                 |     | -                |             |                    |         |              |   |
| <b>ACB008</b><br>(990080)<br>Airframe          | ACB008 - ACB008 - Fuselage Structure (ATA 53), Operational Limitations - Auxiliary Power Unit Enclosure Installation - Sealant Application          |               | HRS  |             |                 |     |                  |             |                    |         | 0            |   |
|                                                |                                                                                                                                                     |               | AFL  |             |                 |     |                  |             |                    |         |              | 0 |
|                                                |                                                                                                                                                     |               | DATE |             |                 |     |                  |             |                    |         |              |   |
|                                                |                                                                                                                                                     |               | MSC  |             |                 |     | -                |             |                    |         |              |   |
| <b>ACB009</b><br>(990090)<br>Airframe          | ACB009 - ACB009 - Fuselage Structure (ATA 53) - Operational Limitations - Auxiliary Power Unit Enclosure Installation - Exhaust Duct Fastener Pitch |               | HRS  |             | 1351.2          |     |                  | 1694.9      |                    |         | 0            |   |
|                                                |                                                                                                                                                     |               | AFL  |             | 516             |     |                  | 601         |                    |         | 0            |   |
|                                                |                                                                                                                                                     |               | MOS  |             | 54.6            |     |                  | 24 Oct 2021 |                    |         |              |   |
|                                                |                                                                                                                                                     |               | MSC  |             |                 |     | -                |             |                    |         |              |   |
| <b>ASC001B</b><br>(970012)<br>Airframe         | ASC 001B - G650 Dataplate - Installation                                                                                                            |               | HRS  |             | 3046.1          |     |                  | 0           |                    |         | 0            |   |
|                                                |                                                                                                                                                     |               | AFL  |             | 1117            |     |                  | 0           |                    |         | 0            |   |
|                                                |                                                                                                                                                     |               | MOS  |             | 120.2           |     |                  | 05 May 2016 |                    |         |              |   |
|                                                |                                                                                                                                                     |               | MSC  |             |                 |     | -                |             |                    |         |              |   |

Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.

| ATA<br>U=Custom  | Description                                              |               | UOM  | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------------|---------------|------|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                              | Serial Number |      |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                       | SW            |      |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                   |               |      |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                            |               |      |             |                 |     |                  |             |                     |         |              |
| ASC002A          | ASC002A - Communications (ATA 23) Communication          |               | HRS  |             | 3033.8          |     |                  | 12.3        |                     |         | 0            |
|                  | Management Function (Cmf) ARINC Direct (SM) Datalink     |               | AFL  |             | 1112            |     |                  | 5           |                     |         | 0            |
|                  | Service Provider                                         |               | MOS  |             | 124.2           |     |                  | 05 Jan 2016 |                     |         |              |
|                  |                                                          |               | MSC  |             |                 |     | -                |             |                     |         |              |
| (970021)         |                                                          |               |      |             |                 |     |                  |             |                     |         |              |
| Airframe         |                                                          |               |      |             |                 |     |                  |             |                     |         |              |
| ASC003A          | ASC003A - Communications (ATA 23) Communication          |               | HRS  |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  | Management Function (Cmf) SATCOM Direct SM Datalink      |               | AFL  |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | Service Provider                                         |               | DATE |             |                 |     |                  |             |                     |         |              |
|                  |                                                          |               | MSC  |             |                 |     | -                |             |                     |         |              |
| (970031)         |                                                          |               |      |             |                 |     |                  |             |                     |         |              |
| Airframe         |                                                          |               |      |             |                 |     |                  |             |                     |         |              |
| Notes: Cancelled |                                                          |               |      |             |                 |     |                  |             |                     |         |              |
| ASC003B          | ASC003B - Communication(ATA 23) - Communication          |               | HRS  |             |                 |     |                  |             |                     |         | 0            |
|                  | Management Function (Cmf) SATCOM Direct Datalink         |               | AFL  |             |                 |     |                  |             |                     |         | 0            |
|                  | Service Provider, Aircraft Service Change (Optional)     |               | DATE |             |                 |     |                  |             |                     |         |              |
|                  |                                                          |               | MSC  |             |                 |     | -                |             |                     |         |              |
| (970032)         |                                                          |               |      |             |                 |     |                  |             |                     |         |              |
| Airframe         |                                                          |               |      |             |                 |     |                  |             |                     |         |              |
| ASC004           | ASC004 - Information Systems (ATA 46) Aircraft Health    |               | HRS  |             | 3033.8          |     |                  | 12.3        |                     |         | 0            |
|                  | and Trend Monitoring System (Ahtms) - Cell Phone Data    |               | AFL  |             | 1112            |     |                  | 5           |                     |         | 0            |
|                  | Transmission Option                                      |               | MOS  |             | 124.2           |     |                  | 05 Jan 2016 |                     |         |              |
|                  |                                                          |               | MSC  |             |                 |     | -                |             |                     |         |              |
| (970040)         |                                                          |               |      |             |                 |     |                  |             |                     |         |              |
| Airframe         |                                                          |               |      |             |                 |     |                  |             |                     |         |              |
| ASC004A          | ASC004A - Information Systems (ATA 46) - Aircraft Health |               | HRS  |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                  | and Trend Monitoring System (Ahtms) - Cell Phone Data    |               | AFL  |             | 1117            |     |                  | 0           |                     |         | 0            |
|                  | Transmission Option                                      |               | DATE |             |                 |     |                  |             |                     |         |              |
|                  |                                                          |               | MSC  |             |                 |     | -                |             |                     |         |              |
| (970041)         |                                                          |               |      |             |                 |     |                  |             |                     |         |              |
| Airframe         |                                                          |               |      |             |                 |     |                  |             |                     |         |              |
| ASC004B          | ASC004B - Information Systems (ATA 46) - Aircraft Health |               | HRS  |             |                 |     |                  |             |                     |         | 0            |
|                  | and Trend Monitoring System (Ahtms) – Cell Phone Data    |               | AFL  |             |                 |     |                  |             |                     |         | 0            |
|                  | Transmission Option                                      |               | DATE |             |                 |     |                  |             |                     |         |              |
|                  |                                                          |               | MSC  |             |                 |     | -                |             |                     |         |              |
| (970042)         |                                                          |               |      |             |                 |     |                  |             |                     |         |              |
| Airframe         |                                                          |               |      |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom    | Description                                                                                    |               | UOM  | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|--------------------|------------------------------------------------------------------------------------------------|---------------|------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                    | Part Number                                                                                    | Serial Number |      |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position   | HW                                                                                             | SW            |      |             |                 |     |                  |             |                    |         | Manufacturer |
|                    | MM Ref                                                                                         |               |      |             |                 |     |                  |             |                    |         | Date Type    |
|                    | Ops Number(s)                                                                                  |               |      |             |                 |     |                  |             |                    |         |              |
| ASC004C            | ASC 004C - Information Systems (ATA 46) - Aircraft                                             |               | HRS  |             |                 |     |                  |             |                    |         | 0            |
|                    | Health and Trend Monitoring System (Ahtms) - Cell Phone                                        |               | AFL  |             |                 |     |                  |             |                    |         | 0            |
|                    | Data Transmission Option (Incorp Suspended By Mol-23-0001), Aircraft Service Change (Optional) |               | DATE |             |                 |     |                  |             |                    |         |              |
|                    |                                                                                                |               | MSC  |             |                 |     | -                |             |                    |         |              |
| (970043)           |                                                                                                |               |      |             |                 |     |                  |             |                    |         |              |
| Airframe           |                                                                                                |               |      |             |                 |     |                  |             |                    |         |              |
| ASC005B            | ASC005B - Navigation (ATA 34) Runway Awareness                                                 |               | HRS  |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                    | Advisory System (Raas) - Installation                                                          |               | AFL  |             | 1112            |     |                  | 5           |                    |         | 0            |
|                    |                                                                                                |               | MOS  |             | 124.2           |     |                  | 05 Jan 2016 |                    |         |              |
|                    |                                                                                                |               | MSC  |             |                 |     | -                |             |                    |         |              |
| (970052)           |                                                                                                |               |      |             |                 |     |                  |             |                    |         |              |
| Airframe           |                                                                                                |               |      |             |                 |     |                  |             |                    |         |              |
| ASC005C            | ASC005C - Navigation (ATA 34) - Runway Awareness                                               |               | HRS  |             |                 |     |                  |             |                    |         | 0            |
|                    | Advisory System (Raas) Installation, Aircraft Service                                          |               | AFL  |             |                 |     |                  |             |                    |         | 0            |
|                    | Change (Optional)                                                                              |               | MOS  |             | 32.9            |     |                  | 15 Aug 2023 |                    |         |              |
|                    |                                                                                                |               | MSC  |             |                 |     | -                |             |                    |         |              |
| (970053)           |                                                                                                |               |      |             |                 |     |                  |             |                    |         |              |
| Airframe           |                                                                                                |               |      |             |                 |     |                  |             |                    |         |              |
| ASC006B            | ASC006B - Navigation (ATA 34) Lightning Sensor System                                          |               | HRS  |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                    | (Lss) - Installation                                                                           |               | AFL  |             | 1112            |     |                  | 5           |                    |         | 0            |
|                    |                                                                                                |               | MOS  |             | 124.2           |     |                  | 05 Jan 2016 |                    |         |              |
|                    |                                                                                                |               | MSC  |             |                 |     | -                |             |                    |         |              |
| (970062)           |                                                                                                |               |      |             |                 |     |                  |             |                    |         |              |
| Airframe           |                                                                                                |               |      |             |                 |     |                  |             |                    |         |              |
| ASC006C            | ASC006C - Navigation (ATA 34) - Lightning Sensor                                               |               | HRS  |             | 2344.7          |     |                  | 701.4       |                    |         | 0            |
|                    | System (Lss) - Installation                                                                    |               | AFL  |             | 935             |     |                  | 182         |                    |         | 0            |
|                    |                                                                                                |               | MOS  |             | 96.5            |     |                  | 27 Apr 2018 |                    |         |              |
|                    |                                                                                                |               | MSC  |             |                 |     | -                |             |                    |         |              |
| (970063)           |                                                                                                |               |      |             |                 |     |                  |             |                    |         |              |
| Airframe           |                                                                                                |               |      |             |                 |     |                  |             |                    |         |              |
| Notes: PCW ASC006B |                                                                                                |               |      |             |                 |     |                  |             |                    |         |              |
| ASC006D            | ASC006D - Navigation (ATA 34) - Lightning Sensor                                               |               | HRS  |             |                 |     |                  |             |                    |         | 0            |
|                    | System (Lss) - Installation                                                                    |               | AFL  |             |                 |     |                  |             |                    |         | 0            |
|                    |                                                                                                |               | DATE |             |                 |     |                  |             |                    |         |              |
|                    |                                                                                                |               | MSC  |             |                 |     | -                |             |                    |         |              |
| (970064)           |                                                                                                |               |      |             |                 |     |                  |             |                    |         |              |
| Airframe           |                                                                                                |               |      |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom                                                                            | Description                                                                                                                        |               | UOM  | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|--------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------|---------------|------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                                                                            | Part Number                                                                                                                        | Serial Number |      |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position                                                                           | HW                                                                                                                                 | SW            |      |             |                 |     |                  |             |                    |         | Manufacturer |
|                                                                                            | MM Ref                                                                                                                             |               |      |             |                 |     |                  |             |                    |         | Date Type    |
|                                                                                            | Ops Number(s)                                                                                                                      |               |      |             |                 |     |                  |             |                    |         |              |
| ASC007A<br><br>(970071)<br><br>Airframe                                                    | ASC007A - Navigation (ATA 34) Predictive Windshear (Pws) - Activation                                                              |               | HRS  |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                                                                                            |                                                                                                                                    |               | AFL  |             | 1112            |     |                  | 5           |                    |         | 0            |
|                                                                                            |                                                                                                                                    |               | MOS  |             | 124.2           |     |                  | 05 Jan 2016 |                    |         |              |
|                                                                                            |                                                                                                                                    |               | MSC  |             |                 |     | -                |             |                    |         |              |
| ASC008A<br><br>(970081)<br><br>Airframe                                                    | ASC008A - Indicating / Recording (ATA 31) Xm Weather System - Installation (New Installations Discontinued See All Mol-22-0016)    |               | HRS  |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                                                                    |               | AFL  |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                                                                    |               | DATE |             |                 |     |                  |             |                    |         |              |
|                                                                                            |                                                                                                                                    |               | MSC  |             |                 |     | -                |             |                    |         |              |
| ASC010 PART 1<br><br>(970100)<br><br>Airframe                                              | ASC010 Part 1 - Aircraft General (ATA 4) European Aviation Safety Agency (EASA) Certification BASIC Requirements                   |               | HRS  |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                                                                    |               | AFL  |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                                                                    |               | MOS  |             | 118.3           |     |                  | 01 Jul 2016 |                    |         |              |
|                                                                                            |                                                                                                                                    |               | MSC  |             |                 |     | -                |             |                    |         |              |
| ASC010 PART 2<br><br>(970101)<br><br>Airframe                                              | ASC010 Part 2 - Aircraft General (ATA 4) European Aviation Safety Agency (EASA) Certification BASIC Requirements                   |               | HRS  |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                                                                    |               | AFL  |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                                                                    |               | MOS  |             | 78.6            |     |                  | 23 Oct 2019 |                    |         |              |
|                                                                                            |                                                                                                                                    |               | MSC  |             |                 |     | -                |             |                    |         |              |
| Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK. |                                                                                                                                    |               |      |             |                 |     |                  |             |                    |         |              |
| ASC010A PART 1<br><br>(970102)<br><br>Airframe                                             | ASC010A Part 1 - Aircraft General (ATA 04) - European Aviation Safety Agency (EASA) Certification BASIC Requirements (Fqms In Lbs) |               | HRS  |             | 1840.3          |     |                  | 1205.8      |                    |         | 0            |
|                                                                                            |                                                                                                                                    |               | AFL  |             | 763             |     |                  | 354         |                    |         | 0            |
|                                                                                            |                                                                                                                                    |               | MOS  |             | 78.6            |     |                  | 24 Oct 2019 |                    |         |              |
|                                                                                            |                                                                                                                                    |               | MSC  |             |                 |     | -                |             |                    |         |              |
| Notes: ASC 010 COMPLIED WITH AT BUILD. NO FURTHER WORK REQUIRED.                           |                                                                                                                                    |               |      |             |                 |     |                  |             |                    |         |              |
| ASC010A PART 2<br><br>(970103)<br><br>Airframe                                             | ASC010A Part 2 - Aircraft General (ATA 04) - European Aviation Safety Agency (EASA) Certification BASIC Requirements (Fqms In Kgs) |               | HRS  |             | 1840.3          |     |                  | 1205.8      |                    |         | 0            |
|                                                                                            |                                                                                                                                    |               | AFL  |             | 763             |     |                  | 354         |                    |         | 0            |
|                                                                                            |                                                                                                                                    |               | MOS  |             | 78.6            |     |                  | 24 Oct 2019 |                    |         |              |
|                                                                                            |                                                                                                                                    |               | MSC  |             |                 |     | -                |             |                    |         |              |
| Notes: ASC 010 COMPLIED WITH AT BUILD. NO FURTHER WORK REQUIRED                            |                                                                                                                                    |               |      |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom                                                                            | Description                                                                             |               | UOM  | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|--------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------|---------------|------|-------------|-----------------|-----|------------------|----------|--------------------|---------|--------------|
|                                                                                            | Part Number                                                                             | Serial Number |      |             |                 |     |                  |          |                    |         | Approx Price |
| Logbook Position                                                                           | HW                                                                                      | SW            |      |             |                 |     |                  |          |                    |         | Manufacturer |
|                                                                                            | MM Ref                                                                                  |               |      |             |                 |     |                  |          |                    |         | Date Type    |
|                                                                                            | Ops Number(s)                                                                           |               |      |             |                 |     |                  |          |                    |         |              |
| ASC014B PART 1                                                                             | ASC014B Part 1 - Aircraft General (ATA 4) - Gvi Extended Range (G650ER) - Modifications |               | HRS  |             | 3046.1          |     |                  | 0        |                    | 0       |              |
|                                                                                            |                                                                                         |               | AFL  |             | 1117            |     | 0                |          | 0                  |         |              |
|                                                                                            |                                                                                         |               | MOS  |             | 121.2           |     | 05 Apr 2016      |          |                    |         |              |
|                                                                                            |                                                                                         |               | MSC  |             |                 |     | -                |          |                    |         |              |
| (970144)                                                                                   |                                                                                         |               |      |             |                 |     |                  |          |                    |         |              |
| Airframe                                                                                   |                                                                                         |               |      |             |                 |     |                  |          |                    |         |              |
| Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK. |                                                                                         |               |      |             |                 |     |                  |          |                    |         |              |
| ASC014B PART 2                                                                             | ASC014B Part 2 - Aircraft General (ATA 4) - Gvi Extended Range (G650ER) - Modifications |               | HRS  |             | 3046.1          |     |                  | 0        |                    | 0       |              |
|                                                                                            |                                                                                         |               | AFL  |             | 1117            |     | 0                |          | 0                  |         |              |
|                                                                                            |                                                                                         |               | MOS  |             | 121.2           |     | 05 Apr 2016      |          |                    |         |              |
|                                                                                            |                                                                                         |               | MSC  |             |                 |     | -                |          |                    |         |              |
| (970145)                                                                                   |                                                                                         |               |      |             |                 |     |                  |          |                    |         |              |
| Airframe                                                                                   |                                                                                         |               |      |             |                 |     |                  |          |                    |         |              |
| Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK. |                                                                                         |               |      |             |                 |     |                  |          |                    |         |              |
| ASC014C PART 1                                                                             | ASC014C Part 1 - Aircraft General (ATA 4) - Gvi Extended Range (G650ER) - Modifications |               | HRS  |             | 3046.1          |     |                  | 0        |                    | 0       |              |
|                                                                                            |                                                                                         |               | AFL  |             | 1117            |     | 0                |          | 0                  |         |              |
|                                                                                            |                                                                                         |               | MOS  |             | 114.5           |     | 28 Oct 2016      |          |                    |         |              |
|                                                                                            |                                                                                         |               | MSC  |             |                 |     | -                |          |                    |         |              |
| (970146)                                                                                   |                                                                                         |               |      |             |                 |     |                  |          |                    |         |              |
| Airframe                                                                                   |                                                                                         |               |      |             |                 |     |                  |          |                    |         |              |
| Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK. |                                                                                         |               |      |             |                 |     |                  |          |                    |         |              |
| ASC014C PART 2                                                                             | ASC014C Part 2 - Aircraft General (ATA 4) - Gvi Extended Range (G650ER) - Modifications |               | HRS  |             | 3046.1          |     |                  | 0        |                    | 0       |              |
|                                                                                            |                                                                                         |               | AFL  |             | 1117            |     | 0                |          | 0                  |         |              |
|                                                                                            |                                                                                         |               | MOS  |             | 114.5           |     | 28 Oct 2016      |          |                    |         |              |
|                                                                                            |                                                                                         |               | MSC  |             |                 |     | -                |          |                    |         |              |
| (970147)                                                                                   |                                                                                         |               |      |             |                 |     |                  |          |                    |         |              |
| Airframe                                                                                   |                                                                                         |               |      |             |                 |     |                  |          |                    |         |              |
| Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK. |                                                                                         |               |      |             |                 |     |                  |          |                    |         |              |
| ASC014D PART 1                                                                             | ASC014D Part 1 - Aircraft General (ATA 4) - Gvi Extended Range (G650ER) - Modifications |               | HRS  |             | 3046.1          |     |                  | 0        |                    | 0       |              |
|                                                                                            |                                                                                         |               | AFL  |             | 1117            |     | 0                |          | 0                  |         |              |
|                                                                                            |                                                                                         |               | DATE |             |                 |     |                  |          |                    |         |              |
|                                                                                            |                                                                                         |               | MSC  |             |                 |     | -                |          |                    |         |              |
| (970148)                                                                                   |                                                                                         |               |      |             |                 |     |                  |          |                    |         |              |
| Airframe                                                                                   |                                                                                         |               |      |             |                 |     |                  |          |                    |         |              |
| ASC014D PART 2                                                                             | ASC014D Part 2 - Aircraft General (ATA 4) - Gvi Extended Range (G650ER) - Modifications |               | HRS  |             | 3046.1          |     |                  | 0        |                    | 0       |              |
|                                                                                            |                                                                                         |               | AFL  |             | 1117            |     | 0                |          | 0                  |         |              |
|                                                                                            |                                                                                         |               | DATE |             |                 |     |                  |          |                    |         |              |
|                                                                                            |                                                                                         |               | MSC  |             |                 |     | -                |          |                    |         |              |
| (970149)                                                                                   |                                                                                         |               |      |             |                 |     |                  |          |                    |         |              |
| Airframe                                                                                   |                                                                                         |               |      |             |                 |     |                  |          |                    |         |              |

| ATA<br>U=Custom                                                                            | Description                                                                                       |               | UOM  | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|--------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------|---------------|------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                                                                            | Part Number                                                                                       | Serial Number |      |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position                                                                           | HW                                                                                                | SW            |      |             |                 |     |                  |             |                    |         | Manufacturer |
|                                                                                            | MM Ref                                                                                            |               |      |             |                 |     |                  |             |                    |         | Date Type    |
|                                                                                            | Ops Number(s)                                                                                     |               |      |             |                 |     |                  |             |                    |         |              |
| ASC016<br><br>(970160)<br><br>Airframe                                                     | ASC016 - Engine Fuel and Control (ATA 73), Engine Electronic Controller - K7.1.3 Software Upgrade |               | HRS  |             | 2413.3          |     |                  | 632.8       |                    |         | 0            |
|                                                                                            |                                                                                                   |               | AFL  |             | 949             |     |                  | 168         |                    |         | 0            |
|                                                                                            |                                                                                                   |               | MOS  |             | 98.7            |     |                  | 19 Feb 2018 |                    |         |              |
|                                                                                            |                                                                                                   |               | MSC  |             |                 |     | -                |             |                    |         |              |
| ASC026<br><br>(970260)<br><br>Airframe                                                     | ASC026 - Placards and Markings (ATA 11) - Airport Access - 74,900 Pound Weight Limitation         |               | HRS  |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                                   |               | AFL  |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                                   |               | MOS  |             | 114.5           |     |                  | 28 Oct 2016 |                    |         |              |
|                                                                                            |                                                                                                   |               | MSC  |             |                 |     | -                |             |                    |         |              |
| Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK. |                                                                                                   |               |      |             |                 |     |                  |             |                    |         |              |
| ASC026A<br><br>(970261)<br><br>Airframe                                                    | ASC026A - Placards and Markings (ATA 11) - Airport Access 74,900 Pound Weight Limitation          |               | HRS  |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                                   |               | AFL  |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                                   |               | DATE |             |                 |     |                  |             |                    |         |              |
|                                                                                            |                                                                                                   |               | MSC  |             |                 |     | -                |             |                    |         |              |
| ASC027<br><br>(970270)<br><br>Airframe                                                     | ASC027 - Placards and Markings (ATA 11) - Airport Access - 90,000 Pound Weight Limitation         |               | HRS  |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                                   |               | AFL  |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                                   |               | MOS  |             | 114.5           |     |                  | 28 Oct 2016 |                    |         |              |
|                                                                                            |                                                                                                   |               | MSC  |             |                 |     | -                |             |                    |         |              |
| Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK. |                                                                                                   |               |      |             |                 |     |                  |             |                    |         |              |
| ASC027A<br><br>(970271)<br><br>Airframe                                                    | ASC027A - Placards and Markings (ATA 11) - Airport Access - 90,000 Pound Weight Limitation        |               | HRS  |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                                   |               | AFL  |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                                   |               | DATE |             |                 |     |                  |             |                    |         |              |
|                                                                                            |                                                                                                   |               | MSC  |             |                 |     | -                |             |                    |         |              |
| ASC028<br><br>(970280)<br><br>Airframe                                                     | ASC028 - Placards and Markings (ATA 11) - Airport Access - 95,000 Pound Weight Limitation         |               | HRS  |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                                   |               | AFL  |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                                   |               | MOS  |             | 114.5           |     |                  | 28 Oct 2016 |                    |         |              |
|                                                                                            |                                                                                                   |               | MSC  |             |                 |     | -                |             |                    |         |              |
| Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK. |                                                                                                   |               |      |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom                                                                            | Description                                                                                                          |               | UOM  | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|--------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------|---------------|------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                                                                            | Part Number                                                                                                          | Serial Number |      |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position                                                                           | HW                                                                                                                   | SW            |      |             |                 |     |                  |             |                    |         | Manufacturer |
|                                                                                            | MM Ref                                                                                                               |               |      |             |                 |     |                  |             |                    |         | Date Type    |
|                                                                                            | Ops Number(s)                                                                                                        |               |      |             |                 |     |                  |             |                    |         |              |
| ASC028A<br><br>(970281)<br><br>Airframe                                                    | ASC028A - Placards and Markings (ATA 11) - Airport<br>Access - 95,000 Pound Weight Limitation                        |               | HRS  |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                                                      |               | AFL  |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                                                      |               | DATE |             |                 |     |                  |             |                    |         |              |
|                                                                                            |                                                                                                                      |               | MSC  |             |                 |     | -                |             |                    |         |              |
| ASC030<br><br>(970300)<br><br>Airframe                                                     | ASC030 - Placards and Markings (ATA 11) - Maximum<br>Zero Fuel Weight Reduction - 60,000 Pounds                      |               | HRS  |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                                                      |               | AFL  |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                                                      |               | DATE |             |                 |     |                  |             |                    |         |              |
|                                                                                            |                                                                                                                      |               | MSC  |             |                 |     | -                |             |                    |         |              |
| ASC036<br><br>(970360)<br><br>Airframe                                                     | ASC036 - Navigation (ATA 34) - Automatic Dependent<br>Surveillance-Broadcast (ADS-B) Out Version 2 Installation      |               | HRS  |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                                                      |               | AFL  |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                                                      |               | MOS  |             | 118.9           |     |                  | 15 Jun 2016 |                    |         |              |
|                                                                                            |                                                                                                                      |               | MSC  |             |                 |     | -                |             |                    |         |              |
| Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK. |                                                                                                                      |               |      |             |                 |     |                  |             |                    |         |              |
| ASC036A<br><br>(970361)<br><br>Airframe                                                    | ASC036A - Navigation (ATA 34) - Automatic Dependent<br>Surveillance - Broadcast (ADS-B) Out Version<br>2INSTALLATION |               | HRS  |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                                                      |               | AFL  |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                                                      |               | MOS  |             | 116.6           |     |                  | 24 Aug 2016 |                    |         |              |
|                                                                                            |                                                                                                                      |               | MSC  |             |                 |     | -                |             |                    |         |              |
| Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK. |                                                                                                                      |               |      |             |                 |     |                  |             |                    |         |              |
| ASC036B<br><br>(970362)<br><br>Airframe                                                    | ASC036B - Navigation (ATA 34) - Automatic Dependent<br>Surveillance-Broadcast (ADS-B) Out Version 2 Installation     |               | HRS  |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                                                                                            |                                                                                                                      |               | AFL  |             | 1112            |     |                  | 5           |                    |         | 0            |
|                                                                                            |                                                                                                                      |               | MOS  |             | 124.1           |     |                  | 07 Jan 2016 |                    |         |              |
|                                                                                            |                                                                                                                      |               | MSC  |             |                 |     | -                |             |                    |         |              |
| Notes: COMPLIED WITH AS ASC 036 AT BUILD                                                   |                                                                                                                      |               |      |             |                 |     |                  |             |                    |         |              |
| ASC037<br><br>(970370)<br><br>Airframe                                                     | ASC037 - Flight Controls (ATA 27) - FCC Software Update                                                              |               | HRS  |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                                                                                            |                                                                                                                      |               | AFL  |             | 1112            |     |                  | 5           |                    |         | 0            |
|                                                                                            |                                                                                                                      |               | MOS  |             | 123.8           |     |                  | 18 Jan 2016 |                    |         |              |
|                                                                                            |                                                                                                                      |               | MSC  |             |                 |     | -                |             |                    |         |              |

| ATA<br>U=Custom                                                                            | Description                                                                                           |               | UOM  | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|--------------------------------------------------------------------------------------------|-------------------------------------------------------------------------------------------------------|---------------|------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                                                                            | Part Number                                                                                           | Serial Number |      |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position                                                                           | HW                                                                                                    | SW            |      |             |                 |     |                  |             |                    |         | Manufacturer |
|                                                                                            | MM Ref                                                                                                |               |      |             |                 |     |                  |             |                    |         | Date Type    |
|                                                                                            | Ops Number(s)                                                                                         |               |      |             |                 |     |                  |             |                    |         |              |
| ASC037A<br><br>(970371)<br><br>Airframe                                                    | ASC037A - Flight Controls (ATA 27) - FCC Software Update                                              |               | HRS  |             | 2802.5          |     |                  | 243.6       |                    |         | 0            |
|                                                                                            |                                                                                                       |               | AFL  |             | 1050            |     |                  | 67          |                    |         | 0            |
|                                                                                            |                                                                                                       |               | MOS  |             | 114.2           |     |                  | 06 Nov 2016 |                    |         |              |
|                                                                                            |                                                                                                       |               | MSC  |             |                 |     | -                |             |                    |         |              |
| Notes: PREVIOUSLY COMPLIED WITH AT BUILD 18 JAN 2016                                       |                                                                                                       |               |      |             |                 |     |                  |             |                    |         |              |
| ASC038<br><br>(970380)<br><br>Airframe                                                     | ASC038 - Indicating / Recording (ATA 31) - Planeview li Avionics Enhancement                          |               | HRS  |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                                       |               | AFL  |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                                       |               | MOS  |             | 112.6           |     |                  | 22 Dec 2016 |                    |         |              |
|                                                                                            |                                                                                                       |               | MSC  |             |                 |     | -                |             |                    |         |              |
| Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK. |                                                                                                       |               |      |             |                 |     |                  |             |                    |         |              |
| ASC038A<br><br>(970381)<br><br>Airframe                                                    | ASC038A - Indicating / Recording (ATA 31) - Planeview li Avionics Enhancement                         |               | HRS  |             | 2673.8          |     |                  | 372.3       |                    |         | 0            |
|                                                                                            |                                                                                                       |               | AFL  |             | 1020            |     |                  | 97          |                    |         | 0            |
|                                                                                            |                                                                                                       |               | MOS  |             | 109.4           |     |                  | 30 Mar 2017 |                    |         |              |
|                                                                                            |                                                                                                       |               | MSC  |             |                 |     | -                |             |                    |         |              |
| ASC038B<br><br>(970382)<br><br>Airframe                                                    | ASC038B - Indicating / Recording (ATA 31) - Planeview li Avionics Enhancement                         |               | HRS  |             | 1049.2          |     |                  | 1996.9      |                    |         | 0            |
|                                                                                            |                                                                                                       |               | AFL  |             | 440             |     |                  | 677         |                    |         | 0            |
|                                                                                            |                                                                                                       |               | MOS  |             | 43.4            |     |                  | 29 Sep 2022 |                    |         |              |
|                                                                                            |                                                                                                       |               | MSC  |             |                 |     | -                |             |                    |         |              |
| ASC046<br><br>(970460)<br><br>Airframe                                                     | ASC046 - Placards and Markings (ATA 11) - Maximum Zero Fuel Weight Reduction 59,500 Pounds            |               | HRS  |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                                       |               | AFL  |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                                       |               | DATE |             |                 |     |                  |             |                    |         |              |
|                                                                                            |                                                                                                       |               | MSC  |             |                 |     | -                |             |                    |         |              |
| ASC048 PART 2<br><br>(970481)<br><br>Airframe                                              | ASC048 Part 2 - Flight Controls (ATA 27), Spoiler Joint Anti-Rotation Retention Washer - Installation |               | HRS  |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                                       |               | AFL  |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                                       |               | MOS  |             | 102.5           |     |                  | 26 Oct 2017 |                    |         |              |
|                                                                                            |                                                                                                       |               | MSC  |             |                 |     | -                |             |                    |         |              |
| Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK. |                                                                                                       |               |      |             |                 |     |                  |             |                    |         |              |



| ATA<br>U=Custom                                                                            | Description                                               |               | UOM  | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|--------------------------------------------------------------------------------------------|-----------------------------------------------------------|---------------|------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                                                                            | Part Number                                               | Serial Number |      |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position                                                                           | HW                                                        | SW            |      |             |                 |     |                  |             |                    |         | Manufacturer |
|                                                                                            | MM Ref                                                    |               |      |             |                 |     |                  |             |                    |         | Date Type    |
|                                                                                            | Ops Number(s)                                             |               |      |             |                 |     |                  |             |                    |         |              |
| ASC048A PART 2<br><br>(970483)<br><br>Airframe                                             | ASC048A Part 2 - Flight Controls (ATA 27) - Spoiler Joint |               | HRS  |             | 2345.1          |     |                  | 701         |                    |         | 0            |
|                                                                                            | Anti-Rotation Retention Washer - Installation             |               | AFL  |             | 936             |     |                  | 181         |                    |         | 0            |
|                                                                                            |                                                           |               | MOS  |             | 97              |     |                  | 12 Apr 2018 |                    |         |              |
|                                                                                            |                                                           |               | MSC  |             |                 |     | -                |             |                    |         |              |
| ASC051<br><br>(970510)<br><br>Airframe                                                     | ASC051 - Electrical Power (ATA 24) - Secondary Power      |               | HRS  |             | 2673.8          |     |                  | 372.3       |                    |         | 0            |
|                                                                                            | Distribution - System (Spds) Software Update              |               | AFL  |             | 1020            |     |                  | 97          |                    |         | 0            |
|                                                                                            |                                                           |               | MOS  |             | 109.4           |     |                  | 31 Mar 2017 |                    |         |              |
|                                                                                            |                                                           |               | MSC  |             |                 |     | -                |             |                    |         |              |
| ASC051A<br><br>(970511)<br><br>Airframe                                                    | ASC051A - Electrical Power (ATA 24) - Secondary Power     |               | HRS  |             | 2342.8          |     |                  | 703.3       |                    |         | 0            |
|                                                                                            | Distribution System (Spds) Software Update                |               | AFL  |             | 933             |     |                  | 184         |                    |         | 0            |
|                                                                                            |                                                           |               | MOS  |             | 95.8            |     |                  | 16 May 2018 |                    |         |              |
|                                                                                            |                                                           |               | MSC  |             |                 |     | -                |             |                    |         |              |
| Notes: PCW ASC 051. AFMS G650-2016-02 CONFIRMED AS REMOVED                                 |                                                           |               |      |             |                 |     |                  |             |                    |         |              |
| ASC054B<br><br>(970542)<br><br>Airframe                                                    | ASC054B - Equipment and Furnishings (ATA 25) -            |               | HRS  |             |                 |     |                  |             |                    |         | 0            |
|                                                                                            | Emergency Vision Assurance System (EVAS) -                |               | AFL  |             |                 |     |                  |             |                    |         | 0            |
|                                                                                            | Installation, Aircraft Service Change (Not Applicable)    |               | DATE |             |                 |     |                  |             |                    |         |              |
|                                                                                            |                                                           |               | MSC  |             |                 |     | -                |             |                    |         |              |
| ASC055A<br><br>(970551)<br><br>Airframe                                                    | ASC055A - Landing Gear (ATA 32) Autobrake System -        |               | HRS  |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                                                                            | Installation                                              |               | AFL  |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                           |               | MOS  |             | 119.2           |     |                  | 06 Jun 2016 |                    |         |              |
|                                                                                            |                                                           |               | MSC  |             |                 |     | -                |             |                    |         |              |
| Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK. |                                                           |               |      |             |                 |     |                  |             |                    |         |              |
| ASC055B<br><br>(970552)<br><br>Airframe                                                    | ASC055B - Landing Gear (ATA 32) - Autobrake System -      |               | HRS  |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                                                                            | Installation                                              |               | AFL  |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                           |               | MOS  |             | 113.1           |     |                  | 07 Dec 2016 |                    |         |              |
|                                                                                            |                                                           |               | MSC  |             |                 |     | -                |             |                    |         |              |
| Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK. |                                                           |               |      |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom                                                                            | Description                                                                                    |               | UOM  | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|--------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------|---------------|------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                                                                            | Part Number                                                                                    | Serial Number |      |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position                                                                           | HW                                                                                             | SW            |      |             |                 |     |                  |             |                    |         | Manufacturer |
|                                                                                            | MM Ref                                                                                         |               |      |             |                 |     |                  |             |                    |         | Date Type    |
|                                                                                            | Ops Number(s)                                                                                  |               |      |             |                 |     |                  |             |                    |         |              |
| ASC055C<br><br>(970553)<br><br>Airframe                                                    | ASC055C - Landing Gear (ATA 32) - Autobrake System - Installation                              |               | HRS  |             | 2673.8          |     |                  | 372.3       |                    |         | 0            |
|                                                                                            |                                                                                                |               | AFL  |             | 1020            |     |                  | 97          |                    |         | 0            |
|                                                                                            |                                                                                                |               | MOS  |             | 109.4           |     |                  | 31 Mar 2017 |                    |         |              |
|                                                                                            |                                                                                                |               | MSC  |             |                 |     | -                |             |                    |         |              |
| ASC058<br><br>(970580)<br><br>Airframe                                                     | ASC058 - Doors (ATA 52) Main Entrance Door - Storage Box Spring Replacement                    |               | HRS  |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                                |               | AFL  |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                                |               | MOS  |             | 118.3           |     |                  | 01 Jul 2016 |                    |         |              |
|                                                                                            |                                                                                                |               | MSC  |             |                 |     | -                |             |                    |         |              |
| ASC065<br><br>(970650)<br><br>Airframe                                                     | ASC065 - Doors (ATA 52), Main Entrance Door Manual Operation Mechanism - Installation          |               | HRS  |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                                |               | AFL  |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                                |               | MOS  |             | 94.9            |     |                  | 15 Jun 2018 |                    |         |              |
|                                                                                            |                                                                                                |               | MSC  |             |                 |     | -                |             |                    |         |              |
| Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK. |                                                                                                |               |      |             |                 |     |                  |             |                    |         |              |
| ASC065A<br><br>(970651)<br><br>Airframe                                                    | ASC065A - Doors (ATA 52) - Main Entrance Door Manual Operation Mechanism - Installation        |               | HRS  |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                                |               | AFL  |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                                |               | DATE |             |                 |     |                  |             |                    |         |              |
|                                                                                            |                                                                                                |               | MSC  |             |                 |     | -                |             |                    |         |              |
| ASC068<br><br>(970680)<br><br>Airframe                                                     | ASC068 - Equipment and Furnishings (ATA 25) - Baggage Compartment - Grab Handle - Installation |               | HRS  |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                                |               | AFL  |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                                |               | MOS  |             | 115             |     |                  | 12 Oct 2016 |                    |         |              |
|                                                                                            |                                                                                                |               | MSC  |             |                 |     | -                |             |                    |         |              |
| Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK. |                                                                                                |               |      |             |                 |     |                  |             |                    |         |              |
| ASC068A<br><br>(970681)<br><br>Airframe                                                    | ASC068A - Equipment and Furnishings (ATA 25) - Baggage Compartment Grab Handle - Installation  |               | HRS  |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                                |               | AFL  |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                                |               | DATE |             |                 |     |                  |             |                    |         |              |
|                                                                                            |                                                                                                |               | MSC  |             |                 |     | -                |             |                    |         |              |

| ATA<br>U=Custom                                                                            | Description                                              |               | UOM  | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|--------------------------------------------------------------------------------------------|----------------------------------------------------------|---------------|------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                                                                            | Part Number                                              | Serial Number |      |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position                                                                           | HW                                                       | SW            |      |             |                 |     |                  |             |                    |         | Manufacturer |
|                                                                                            | MM Ref                                                   |               |      |             |                 |     |                  |             |                    |         | Date Type    |
|                                                                                            | Ops Number(s)                                            |               |      |             |                 |     |                  |             |                    |         |              |
| ASC069                                                                                     | ASC069 - Flight Controls (ATA 27) Primary Flight Control |               | HRS  |             | 2345.1          |     |                  | 701         |                    |         | 0            |
|                                                                                            | Actuation System (Pfcas) Remote Electronics Unit (Reu)   |               | AFL  |             | 936             |     |                  | 181         |                    |         | 0            |
|                                                                                            | Software Update                                          |               | MOS  |             | 96.6            |     |                  | 24 Apr 2018 |                    |         |              |
|                                                                                            |                                                          |               | MSC  |             |                 |     | -                |             |                    |         |              |
| (970690)                                                                                   |                                                          |               |      |             |                 |     |                  |             |                    |         |              |
| Airframe                                                                                   |                                                          |               |      |             |                 |     |                  |             |                    |         |              |
| ASC070                                                                                     | ASC070 - AIR Conditioning (ATA 21), Cockpit AIR Ducting  |               | HRS  |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                                                                            | - Velocity Reduction                                     |               | AFL  |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                          |               | DATE |             |                 |     |                  |             |                    |         |              |
|                                                                                            |                                                          |               | MSC  |             |                 |     | -                |             |                    |         |              |
| (970700)                                                                                   |                                                          |               |      |             |                 |     |                  |             |                    |         |              |
| Airframe                                                                                   |                                                          |               |      |             |                 |     |                  |             |                    |         |              |
| ASC071                                                                                     | ASC071 - Communication(ATA 23) - Communication           |               | HRS  |             |                 |     |                  |             |                    |         | 0            |
|                                                                                            | Management Function (Cmf) Global Data Center (Gdc)       |               | AFL  |             |                 |     |                  |             |                    |         | 0            |
|                                                                                            | Datalink Service Provider, Aircraft Service Change       |               | DATE |             |                 |     |                  |             |                    |         |              |
|                                                                                            | (Optional)                                               |               | MSC  |             |                 |     | -                |             |                    |         |              |
| (970710)                                                                                   |                                                          |               |      |             |                 |     |                  |             |                    |         |              |
| Airframe                                                                                   |                                                          |               |      |             |                 |     |                  |             |                    |         |              |
| ASC073                                                                                     | ASC073 - Landing Gear (ATA 32) - Tire Pressure           |               | HRS  |             | 2673.8          |     |                  | 372.3       |                    |         | 0            |
|                                                                                            | Monitoring Unit (Tpmu) Software Upgrade                  |               | AFL  |             | 1020            |     |                  | 97          |                    |         | 0            |
|                                                                                            |                                                          |               | MOS  |             | 109.7           |     |                  | 21 Mar 2017 |                    |         |              |
|                                                                                            |                                                          |               | MSC  |             |                 |     | -                |             |                    |         |              |
| (970730)                                                                                   |                                                          |               |      |             |                 |     |                  |             |                    |         |              |
| Airframe                                                                                   |                                                          |               |      |             |                 |     |                  |             |                    |         |              |
| ASC074                                                                                     | ASC074 - Landing Gear (ATA 32) - Nose Wheel Steering     |               | HRS  |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                                                                            | System - Upgrade                                         |               | AFL  |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                          |               | MOS  |             | 106.8           |     |                  | 16 Jun 2017 |                    |         |              |
|                                                                                            |                                                          |               | MSC  |             |                 |     | -                |             |                    |         |              |
| (970740)                                                                                   |                                                          |               |      |             |                 |     |                  |             |                    |         |              |
| Airframe                                                                                   |                                                          |               |      |             |                 |     |                  |             |                    |         |              |
| Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK. |                                                          |               |      |             |                 |     |                  |             |                    |         |              |
| ASC074A                                                                                    | ASC074A - Landing Gear (ATA 32) - Nose Wheel Steering    |               | HRS  |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                                                                            | System - Upgrade                                         |               | AFL  |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                          |               | MOS  |             | 104.9           |     |                  | 15 Aug 2017 |                    |         |              |
|                                                                                            |                                                          |               | MSC  |             |                 |     | -                |             |                    |         |              |
| (970741)                                                                                   |                                                          |               |      |             |                 |     |                  |             |                    |         |              |
| Airframe                                                                                   |                                                          |               |      |             |                 |     |                  |             |                    |         |              |
| Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK. |                                                          |               |      |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom                                                                            | Description                                                                                              |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|--------------------------------------------------------------------------------------------|----------------------------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                                                                            | Part Number                                                                                              | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position                                                                           | HW                                                                                                       | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                                                                            | MM Ref                                                                                                   |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                                                                                            | Ops Number(s)                                                                                            |               |     |             |                 |     |                  |             |                    |         |              |
| ASC074B<br><br>(970742)<br><br>Airframe                                                    | ASC074B - Landing Gear (ATA 32) - Nose Wheel Steering System - Upgrade                                   |               | HRS |             | 2120.8          |     |                  | 925.3       |                    |         | 0            |
|                                                                                            |                                                                                                          |               | AFL |             | 861             |     |                  | 256         |                    |         | 0            |
|                                                                                            |                                                                                                          |               | MOS |             | 86              |     |                  | 11 Mar 2019 |                    |         |              |
|                                                                                            |                                                                                                          |               | MSC |             |                 |     | -                |             |                    |         |              |
| ASC074C<br><br>(970743)<br><br>Airframe                                                    | ASC074C - Landing Gear (ATA 32) - Nose Wheel Steering System - Upgrade                                   |               | HRS |             | 1597.7          |     |                  | 1448.4      |                    |         | 0            |
|                                                                                            |                                                                                                          |               | AFL |             | 652             |     |                  | 465         |                    |         | 0            |
|                                                                                            |                                                                                                          |               | MOS |             | 68              |     |                  | 10 Sep 2020 |                    |         |              |
|                                                                                            |                                                                                                          |               | MSC |             |                 |     | -                |             |                    |         |              |
| ASC075<br><br>(970750)<br><br>Airframe                                                     | ASC075 - Placards and Markings (ATA 11) - Baggage Compartment Access Modification                        |               | HRS |             | 2345.1          |     |                  | 701         |                    |         | 0            |
|                                                                                            |                                                                                                          |               | AFL |             | 936             |     |                  | 181         |                    |         | 0            |
|                                                                                            |                                                                                                          |               | MOS |             | 96.7            |     |                  | 19 Apr 2018 |                    |         |              |
|                                                                                            |                                                                                                          |               | MSC |             |                 |     | -                |             |                    |         |              |
| ASC076<br><br>(970760)<br><br>Airframe                                                     | ASC076 - Information Systems (ATA 46) - Aircraft Health and Trend Monitoring System - Software Update 2  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                                          |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                                          |               | MOS |             | 78.5            |     |                  | 28 Oct 2019 |                    |         |              |
|                                                                                            |                                                                                                          |               | MSC |             |                 |     | -                |             |                    |         |              |
| Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK. |                                                                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| ASC076A<br><br>(970761)<br><br>Airframe                                                    | ASC076A - Information Systems (ATA 46) - Aircraft Health and Trend Monitoring System - Software Update 2 |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                                          |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                                          |               | MOS |             | 78.2            |     |                  | 04 Nov 2019 |                    |         |              |
|                                                                                            |                                                                                                          |               | MSC |             |                 |     | -                |             |                    |         |              |
| Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK. |                                                                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| ASC076B<br><br>(970762)<br><br>Airframe                                                    | ASC076B - Information Systems (ATA 46) - Aircraft Health and Trend Monitoring System - Software Update 2 |               | HRS |             | 1735.8          |     |                  | 1310.3      |                    |         | 0            |
|                                                                                            |                                                                                                          |               | AFL |             | 729             |     |                  | 388         |                    |         | 0            |
|                                                                                            |                                                                                                          |               | MOS |             | 75.2            |     |                  | 05 Feb 2020 |                    |         |              |
|                                                                                            |                                                                                                          |               | MSC |             |                 |     | -                |             |                    |         |              |

| ATA<br>U=Custom                                                                            | Description                                                                        |               | UOM  | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|--------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------|---------------|------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                                                                            | Part Number                                                                        | Serial Number |      |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position                                                                           | HW                                                                                 | SW            |      |             |                 |     |                  |             |                    |         | Manufacturer |
|                                                                                            | MM Ref                                                                             |               |      |             |                 |     |                  |             |                    |         | Date Type    |
|                                                                                            | Ops Number(s)                                                                      |               |      |             |                 |     |                  |             |                    |         |              |
| ASC078<br><br>(970780)<br><br>Airframe                                                     | ASC078 - Communications (ATA 23) High-Definition (Hd) Camera System - Installation |               | HRS  |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                    |               | AFL  |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                    |               | DATE |             |                 |     |                  |             |                    |         |              |
|                                                                                            |                                                                                    |               | MSC  |             |                 |     | -                |             |                    |         |              |
| ASC079<br><br>(970790)<br><br>Airframe                                                     | ASC079 - Landing Gear (ATA 32) - Landing Gear Control Unit MOD D Update            |               | HRS  |             | 2345.1          |     |                  | 701         |                    |         | 0            |
|                                                                                            |                                                                                    |               | AFL  |             | 936             |     |                  | 181         |                    |         | 0            |
|                                                                                            |                                                                                    |               | MOS  |             | 97.1            |     |                  | 09 Apr 2018 |                    |         |              |
|                                                                                            |                                                                                    |               | MSC  |             |                 |     | -                |             |                    |         |              |
| ASC081<br><br>(970810)<br><br>Airframe                                                     | ASC081 - Doors (ATA 52), Main Entrance Door Latch Actuator - Upgrade               |               | HRS  |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                    |               | AFL  |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                    |               | MOS  |             | 104.7           |     |                  | 21 Aug 2017 |                    |         |              |
|                                                                                            |                                                                                    |               | MSC  |             |                 |     | -                |             |                    |         |              |
| Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK. |                                                                                    |               |      |             |                 |     |                  |             |                    |         |              |
| ASC081A<br><br>(970811)<br><br>Airframe                                                    | ASC081A - Doors (ATA 52), Main Entrance Door Latch Actuator - Upgrade              |               | HRS  |             | 2345.1          |     |                  | 701         |                    |         | 0            |
|                                                                                            |                                                                                    |               | AFL  |             | 936             |     |                  | 181         |                    |         | 0            |
|                                                                                            |                                                                                    |               | MOS  |             | 96.6            |     |                  | 23 Apr 2018 |                    |         |              |
|                                                                                            |                                                                                    |               | MSC  |             |                 |     | -                |             |                    |         |              |
| ASC081B<br><br>(970812)<br><br>Airframe                                                    | ASC081B - Doors (ATA 52) - Main Entrance Door Latch Actuator - Upgrade             |               | HRS  |             | 2320.4          |     |                  | 725.7       |                    |         | 0            |
|                                                                                            |                                                                                    |               | AFL  |             | 926             |     |                  | 191         |                    |         | 0            |
|                                                                                            |                                                                                    |               | MOS  |             | 94.3            |     |                  | 02 Jul 2018 |                    |         |              |
|                                                                                            |                                                                                    |               | MSC  |             |                 |     | -                |             |                    |         |              |
| Notes: NO FURTHER ACTION REQ"D AS PREVIOUSLY COMPLIED WITH ASC081A                         |                                                                                    |               |      |             |                 |     |                  |             |                    |         |              |
| ASC083<br><br>(970830)<br><br>Airframe                                                     | ASC083 - Wings (ATA 57) - Flap Track D Rub Strips - Removal                        |               | HRS  |             | 1452            |     |                  | 1594.1      |                    |         | 0            |
|                                                                                            |                                                                                    |               | AFL  |             | 570             |     |                  | 547         |                    |         | 0            |
|                                                                                            |                                                                                    |               | MOS  |             | 63.9            |     |                  | 15 Jan 2021 |                    |         |              |
|                                                                                            |                                                                                    |               | MSC  |             |                 |     | -                |             |                    |         |              |

| ATA<br>U=Custom                                                                            | Description                                                                                      |               | UOM  | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|--------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------|---------------|------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                                                                            | Part Number                                                                                      | Serial Number |      |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position                                                                           | HW                                                                                               | SW            |      |             |                 |     |                  |             |                    |         | Manufacturer |
|                                                                                            | MM Ref                                                                                           |               |      |             |                 |     |                  |             |                    |         | Date Type    |
|                                                                                            | Ops Number(s)                                                                                    |               |      |             |                 |     |                  |             |                    |         |              |
| ASC083A                                                                                    | ASC083A - Wings (ATA 57) - Flap Track D Rub Strips - Removal, Aircraft Service Change (Optional) |               | HRS  |             |                 |     |                  |             |                    |         | 0            |
|                                                                                            |                                                                                                  |               | AFL  |             |                 |     |                  |             |                    |         | 0            |
| (970831)                                                                                   |                                                                                                  |               | DATE |             |                 |     |                  |             |                    |         |              |
| Airframe                                                                                   |                                                                                                  |               | MSC  |             |                 |     | -                |             |                    |         |              |
| ASC084                                                                                     | ASC 084 Main Landing Gear and Brake Assembly - Modification                                      |               | HRS  |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                                  |               | AFL  |             | 1117            |     |                  | 0           |                    |         | 0            |
| (970840)                                                                                   |                                                                                                  |               | MOS  |             | 116.7           |     |                  | 19 Aug 2016 |                    |         |              |
| Airframe                                                                                   |                                                                                                  |               | MSC  |             |                 |     | -                |             |                    |         |              |
| Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK. |                                                                                                  |               |      |             |                 |     |                  |             |                    |         |              |
| ASC084A                                                                                    | ASC 084A Main Landing Gear and Brake Assembly - Modification                                     |               | HRS  |             | 2673.8          |     |                  | 372.3       |                    |         | 0            |
|                                                                                            |                                                                                                  |               | AFL  |             | 1020            |     |                  | 97          |                    |         | 0            |
| (970841)                                                                                   |                                                                                                  |               | MOS  |             | 109.4           |     |                  | 29 Mar 2017 |                    |         |              |
| Airframe                                                                                   |                                                                                                  |               | MSC  |             |                 |     | -                |             |                    |         |              |
| ASC085                                                                                     | ASC 085 Ka-Band Fin CAP Radome - Installation                                                    |               | HRS  |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                                  |               | AFL  |             | 1117            |     |                  | 0           |                    |         | 0            |
| (970850)                                                                                   |                                                                                                  |               | MOS  |             | 86.1            |     |                  | 07 Mar 2019 |                    |         |              |
| Airframe                                                                                   |                                                                                                  |               | MSC  |             |                 |     | -                |             |                    |         |              |
| Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK. |                                                                                                  |               |      |             |                 |     |                  |             |                    |         |              |
| ASC085A                                                                                    | ASC 085A Ka-Band Fin CAP Radome - Installation                                                   |               | HRS  |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                                  |               | AFL  |             | 1117            |     |                  | 0           |                    |         | 0            |
| (970851)                                                                                   |                                                                                                  |               | DATE |             |                 |     |                  |             |                    |         |              |
| Airframe                                                                                   |                                                                                                  |               | MSC  |             |                 |     | -                |             |                    |         |              |
| ASC085B                                                                                    | Stabilizer (ATA 55) - Ka-Band Fin CAP Radome - Installation, Aircraft Service Change (Optional)  |               | HRS  |             |                 |     |                  |             |                    |         | 0            |
|                                                                                            |                                                                                                  |               | AFL  |             |                 |     |                  |             |                    |         | 0            |
| (970852)                                                                                   |                                                                                                  |               | DATE |             |                 |     |                  |             |                    |         |              |
| Airframe                                                                                   |                                                                                                  |               | MSC  |             |                 |     | -                |             |                    |         |              |
| ASC086                                                                                     | ASC 086 Main Entry Door - Service Door Panel Security Cover - Installation                       |               | HRS  |             | 2673.8          |     |                  | 372.3       |                    |         | 0            |
|                                                                                            |                                                                                                  |               | AFL  |             | 1020            |     |                  | 97          |                    |         | 0            |
| (970860)                                                                                   |                                                                                                  |               | MOS  |             | 109.7           |     |                  | 21 Mar 2017 |                    |         |              |
| Airframe                                                                                   |                                                                                                  |               | MSC  |             |                 |     | -                |             |                    |         |              |

| ATA<br>U=Custom                                                                            | Description                                                                                    |               | UOM  | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|--------------------------------------------------------------------------------------------|------------------------------------------------------------------------------------------------|---------------|------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                                                                            | Part Number                                                                                    | Serial Number |      |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position                                                                           | HW                                                                                             | SW            |      |             |                 |     |                  |             |                    |         | Manufacturer |
|                                                                                            | MM Ref                                                                                         |               |      |             |                 |     |                  |             |                    |         | Date Type    |
|                                                                                            | Ops Number(s)                                                                                  |               |      |             |                 |     |                  |             |                    |         |              |
| ASC087<br><br>(970870)<br><br>Airframe                                                     | ASC 087 Modification (for Installation of 72P5210904Z005<br>Main Entrance Door Damper Assembly |               | HRS  |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                                |               | AFL  |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                                |               | DATE |             |                 |     |                  |             |                    |         |              |
|                                                                                            |                                                                                                |               | MSC  |             |                 |     | -                |             |                    |         |              |
| ASC088<br><br>(970880)<br><br>Airframe                                                     | ASC 088 Engine Electronic Controller - K8.0.2 Software<br>Upgrade                              |               | HRS  |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                                |               | AFL  |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                                |               | MOS  |             | 91.5            |     |                  | 26 Sep 2018 |                    |         |              |
|                                                                                            |                                                                                                |               | MSC  |             |                 |     | -                |             |                    |         |              |
| Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK. |                                                                                                |               |      |             |                 |     |                  |             |                    |         |              |
| ASC088A<br><br>(970881)<br><br>Airframe                                                    | ASC 088A Engine Electronic Controller - K8.0.2 Software<br>Upgrade                             |               | HRS  |             | 2120.8          |     |                  | 925.3       |                    |         | 0            |
|                                                                                            |                                                                                                |               | AFL  |             | 861             |     |                  | 256         |                    |         | 0            |
|                                                                                            |                                                                                                |               | MOS  |             | 86              |     |                  | 11 Mar 2019 |                    |         |              |
|                                                                                            |                                                                                                |               | MSC  |             |                 |     | -                |             |                    |         |              |
| ASC089<br><br>(970890)<br><br>Airframe                                                     | ASC 089 Doors (ATA 52), Main Entrance Door - Bottom<br>Folding Step Stop Bolts - Replacement   |               | HRS  |             | 2673.8          |     |                  | 372.3       |                    |         | 0            |
|                                                                                            |                                                                                                |               | AFL  |             | 1020            |     |                  | 97          |                    |         | 0            |
|                                                                                            |                                                                                                |               | MOS  |             | 109.4           |     |                  | 29 Mar 2017 |                    |         |              |
|                                                                                            |                                                                                                |               | MSC  |             |                 |     | -                |             |                    |         |              |
| ASC090<br><br>(970900)<br><br>Airframe                                                     | ASC 090 Hydraulic Filter Monitoring System - Installation<br>and Activation                    |               | HRS  |             |                 |     |                  |             |                    |         | 0            |
|                                                                                            |                                                                                                |               | AFL  |             |                 |     |                  |             |                    |         | 0            |
|                                                                                            |                                                                                                |               | MOS  |             |                 |     |                  |             |                    |         |              |
|                                                                                            |                                                                                                |               | MSC  |             |                 |     | -                |             |                    |         |              |
| ASC090A<br><br>(970901)<br><br>Airframe                                                    | ASC 090A Hydraulic Filter Monitoring System - Installation<br>and Activation                   |               | HRS  |             | 1300.7          |     |                  | 1745.4      |                    |         | 0            |
|                                                                                            |                                                                                                |               | AFL  |             | 507             |     |                  | 610         |                    |         | 0            |
|                                                                                            |                                                                                                |               | MOS  |             | 51.4            |     |                  | 29 Jan 2022 |                    |         |              |
|                                                                                            |                                                                                                |               | MSC  |             |                 |     | -                |             |                    |         |              |
| ASC091<br><br>(970910)<br><br>Airframe                                                     | ASC 091 Acoustic Door Noise Reduction - Modification                                           |               | HRS  |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                                |               | AFL  |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                                |               | MOS  |             | 101.3           |     |                  | 01 Dec 2017 |                    |         |              |
|                                                                                            |                                                                                                |               | MSC  |             |                 |     | -                |             |                    |         |              |

| ATA<br>U=Custom                     | Description                                                                                                                            |               | UOM  | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|-------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------|---------------|------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                     | Part Number                                                                                                                            | Serial Number |      |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position                    | HW                                                                                                                                     | SW            |      |             |                 |     |                  |             |                    |         | Manufacturer |
|                                     | MM Ref                                                                                                                                 |               |      |             |                 |     |                  |             |                    |         | Date Type    |
|                                     | Ops Number(s)                                                                                                                          |               |      |             |                 |     |                  |             |                    |         |              |
| ASC091A<br>(970911)<br><br>Airframe | ASC 091A Acoustic Door Noise Reduction - Modification                                                                                  |               | HRS  |             | 2345.1          |     |                  | 701         |                    |         | 0            |
|                                     |                                                                                                                                        |               | AFL  |             | 936             |     |                  | 181         |                    | 0       |              |
|                                     |                                                                                                                                        |               | MOS  |             | 97              |     |                  | 10 Apr 2018 |                    |         |              |
|                                     |                                                                                                                                        |               | MSC  |             |                 |     | -                |             |                    |         |              |
| ASC092<br>(970920)<br><br>Airframe  | ASC 092 Primary Flight Control Actuation System (Pfcas) Motor Control Electronics (Mce) Software Update                                |               | HRS  |             | 2345.1          |     |                  | 701         |                    |         | 0            |
|                                     |                                                                                                                                        |               | AFL  |             | 936             |     |                  | 181         |                    | 0       |              |
|                                     |                                                                                                                                        |               | MOS  |             | 96.6            |     |                  | 24 Apr 2018 |                    |         |              |
|                                     |                                                                                                                                        |               | MSC  |             |                 |     | -                |             |                    |         |              |
| ASC093<br>(970930)<br><br>Airframe  | ASC 093 Flight Controls (ATA 27) - FCC Software Update                                                                                 |               | HRS  |             | 2345.1          |     |                  | 701         |                    |         | 0            |
|                                     |                                                                                                                                        |               | AFL  |             | 936             |     |                  | 181         |                    | 0       |              |
|                                     |                                                                                                                                        |               | MOS  |             | 96.6            |     |                  | 23 Apr 2018 |                    |         |              |
|                                     |                                                                                                                                        |               | MSC  |             |                 |     | -                |             |                    |         |              |
| ASC094<br>(970940)<br><br>Airframe  | ASC 094 Doors (ATA 52) - Electric Main Entrance Door (Emed) Wear PAD Modification                                                      |               | HRS  |             | 2760.6          |     |                  | 285.5       |                    |         | 0            |
|                                     |                                                                                                                                        |               | AFL  |             | 1040            |     |                  | 77          |                    | 0       |              |
|                                     |                                                                                                                                        |               | MOS  |             | 112.6           |     |                  | 22 Dec 2016 |                    |         |              |
|                                     |                                                                                                                                        |               | MSC  |             |                 |     | -                |             |                    |         |              |
| ASC095<br>(970950)<br><br>Airframe  | ASC 095 Auxiliary Power Unit Enclosure Installation - Modification                                                                     |               | HRS  |             |                 |     |                  |             |                    |         | 0            |
|                                     |                                                                                                                                        |               | AFL  |             |                 |     |                  |             |                    | 0       |              |
|                                     |                                                                                                                                        |               | DATE |             |                 |     |                  |             |                    |         |              |
|                                     |                                                                                                                                        |               | MSC  |             |                 |     | -                |             |                    |         |              |
| ASC095A<br>(970951)<br><br>Airframe | ASC095A - Fuselage Structure (ATA 53) - Auxiliary Power Unit Enclosure Installation - Modification, Aircraft Service Change (Optional) |               | HRS  |             |                 |     |                  |             |                    |         | 0            |
|                                     |                                                                                                                                        |               | AFL  |             |                 |     |                  |             |                    | 0       |              |
|                                     |                                                                                                                                        |               | DATE |             |                 |     |                  |             |                    |         |              |
|                                     |                                                                                                                                        |               | MSC  |             |                 |     | -                |             |                    |         |              |
| ASC096<br>(970960)<br><br>Airframe  | ASC 096 8.8 KHZ Underwater Acoustic Beacon (Uab) Installation                                                                          |               | HRS  |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                     |                                                                                                                                        |               | AFL  |             | 1117            |     |                  | 0           |                    | 0       |              |
|                                     |                                                                                                                                        |               | MOS  |             | 78.8            |     |                  | 17 Oct 2019 |                    |         |              |
|                                     |                                                                                                                                        |               | MSC  |             |                 |     | -                |             |                    |         |              |

Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.



| ATA<br>U=Custom                                                                            | Description                                             |               | UOM  | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|--------------------------------------------------------------------------------------------|---------------------------------------------------------|---------------|------|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                                                                                            | Part Number                                             | Serial Number |      |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position                                                                           | HW                                                      | SW            |      |             |                 |     |                  |             |                     |         | Manufacturer |
|                                                                                            | MM Ref                                                  |               |      |             |                 |     |                  |             |                     |         | Date Type    |
|                                                                                            | Ops Number(s)                                           |               |      |             |                 |     |                  |             |                     |         |              |
| ASC096A PART 1                                                                             | ASC 096A 8.8 KHZ Underwater Acoustic Beacon (Uab)       |               | HRS  |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                                                                                            | Installation (Part 1)                                   |               | AFL  |             | 1117            |     |                  | 0           |                     |         | 0            |
|                                                                                            | (970961)                                                |               | DATE |             |                 |     |                  |             |                     |         |              |
|                                                                                            | Airframe                                                |               | MSC  |             |                 |     | -                |             |                     |         |              |
| ASC096A PART 2                                                                             | ASC 096A 8.8 KHZ Underwater Acoustic Beacon (Uab)       |               | HRS  |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                                                                                            | Installation (Part 2)                                   |               | AFL  |             | 1117            |     |                  | 0           |                     |         | 0            |
|                                                                                            | (970962)                                                |               | DATE |             |                 |     |                  |             |                     |         |              |
|                                                                                            | Airframe                                                |               | MSC  |             |                 |     | -                |             |                     |         |              |
| ASC097                                                                                     | ASC 097 Primary Flight Control Actuation System (Pfcas) |               | HRS  |             | 2345.1          |     |                  | 701         |                     |         | 0            |
|                                                                                            | Remote Electronics Unit (Reu) Connector Updates         |               | AFL  |             | 936             |     |                  | 181         |                     |         | 0            |
|                                                                                            | (970970)                                                |               | MOS  |             | 96.6            |     |                  | 24 Apr 2018 |                     |         |              |
|                                                                                            | Airframe                                                |               | MSC  |             |                 |     | -                |             |                     |         |              |
| ASC098                                                                                     | ASC 098 Horizontal Stabilizer Control Unit (Hscu)       |               | HRS  |             | 2345.1          |     |                  | 701         |                     |         | 0            |
|                                                                                            | Software Update                                         |               | AFL  |             | 936             |     |                  | 181         |                     |         | 0            |
|                                                                                            | (970980)                                                |               | MOS  |             | 97.1            |     |                  | 09 Apr 2018 |                     |         |              |
|                                                                                            | Airframe                                                |               | MSC  |             |                 |     | -                |             |                     |         |              |
| ASC099                                                                                     | ASC 099 Main Entrance Door - Bottom Folding Step        |               | HRS  |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                                                                                            | Mechanism Improvement                                   |               | AFL  |             | 1117            |     |                  | 0           |                     |         | 0            |
|                                                                                            | (970990)                                                |               | MOS  |             | 99.8            |     |                  | 16 Jan 2018 |                     |         |              |
|                                                                                            | Airframe                                                |               | MSC  |             |                 |     | -                |             |                     |         |              |
| Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK. |                                                         |               |      |             |                 |     |                  |             |                     |         |              |
| ASC099A                                                                                    | ASC 099A Main Entrance Door - Bottom Folding Step       |               | HRS  |             | 2345.1          |     |                  | 701         |                     |         | 0            |
|                                                                                            | Mechanism Improvement                                   |               | AFL  |             | 936             |     |                  | 181         |                     |         | 0            |
|                                                                                            | (970991)                                                |               | MOS  |             | 96.6            |     |                  | 24 Apr 2018 |                     |         |              |
|                                                                                            | Airframe                                                |               | MSC  |             |                 |     | -                |             |                     |         |              |

| ATA<br>U=Custom                         | Description                                                                                                              |               | UOM  | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|-----------------------------------------|--------------------------------------------------------------------------------------------------------------------------|---------------|------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                         | Part Number                                                                                                              | Serial Number |      |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position                        | HW                                                                                                                       | SW            |      |             |                 |     |                  |             |                    |         | Manufacturer |
|                                         | MM Ref                                                                                                                   |               |      |             |                 |     |                  |             |                    |         | Date Type    |
|                                         | Ops Number(s)                                                                                                            |               |      |             |                 |     |                  |             |                    |         |              |
| ASC100<br><br>(971000)<br><br>Airframe  | ASC100 - Indicating / Recording (ATA 31) - Planeview™ li<br>Avionics Enhancement, Aircraft Service Change<br>(Optional)  |               | HRS  |             |                 |     |                  |             |                    |         | 0            |
|                                         |                                                                                                                          |               | AFL  |             |                 |     |                  |             |                    | 0       |              |
|                                         |                                                                                                                          |               | MOS  |             |                 |     |                  |             |                    |         |              |
|                                         |                                                                                                                          |               | MSC  |             |                 |     | -                |             |                    |         |              |
| ASC100A<br><br>(971001)<br><br>Airframe | ASC100A - Indicating / Recording (ATA 31) - Planeview™ li<br>Avionics Enhancement, Aircraft Service Change<br>(Optional) |               | HRS  |             | 562.4           |     |                  | 2483.7      |                    |         | 0            |
|                                         |                                                                                                                          |               | AFL  |             | 217             |     |                  | 900         |                    | 0       |              |
|                                         |                                                                                                                          |               | MOS  |             | 17.2            |     |                  | 06 Dec 2024 |                    |         |              |
|                                         |                                                                                                                          |               | MSC  |             |                 |     | -                |             |                    |         |              |
| ASC101<br><br>(971010)<br><br>Airframe  | ASC 101 Steep Approach to Landing Activation                                                                             |               | HRS  |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                         |                                                                                                                          |               | AFL  |             | 1117            |     |                  | 0           |                    | 0       |              |
|                                         |                                                                                                                          |               | DATE |             |                 |     |                  |             |                    |         |              |
|                                         |                                                                                                                          |               | MSC  |             |                 |     | -                |             |                    |         |              |
| ASC101A<br><br>(971011)<br><br>Airframe | ASC101A - Flight Controls (ATA 27) - Steep Approach to<br>Landing Activation, Aircraft Service Change (Optional)         |               | HRS  |             |                 |     |                  |             |                    |         | 0            |
|                                         |                                                                                                                          |               | AFL  |             |                 |     |                  |             |                    | 0       |              |
|                                         |                                                                                                                          |               | DATE |             |                 |     |                  |             |                    |         |              |
|                                         |                                                                                                                          |               | MSC  |             |                 |     | -                |             |                    |         |              |
| ASC102<br><br>(971020)<br><br>Airframe  | ASC 102 Modification FCC Software V8.2 Update                                                                            |               | HRS  |             | 2120.8          |     |                  | 925.3       |                    |         | 0            |
|                                         |                                                                                                                          |               | AFL  |             | 861             |     |                  | 256         |                    | 0       |              |
|                                         |                                                                                                                          |               | MOS  |             | 85.9            |     |                  | 14 Mar 2019 |                    |         |              |
|                                         |                                                                                                                          |               | MSC  |             |                 |     | -                |             |                    |         |              |
| ASC103<br><br>(971030)<br><br>Airframe  | ASC 103 Auxiliary Hydraulic Pump - Grounding<br>Installation                                                             |               | HRS  |             | 2120.8          |     |                  | 925.3       |                    |         | 0            |
|                                         |                                                                                                                          |               | AFL  |             | 861             |     |                  | 256         |                    | 0       |              |
|                                         |                                                                                                                          |               | MOS  |             | 86.2            |     |                  | 06 Mar 2019 |                    |         |              |
|                                         |                                                                                                                          |               | MSC  |             |                 |     | -                |             |                    |         |              |
| ASC105<br><br>(971050)<br><br>Airframe  | ASC 105 - Data LAN Management Unit Harness - Service<br>Loop Installation                                                |               | HRS  |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                         |                                                                                                                          |               | AFL  |             | 1117            |     |                  | 0           |                    | 0       |              |
|                                         |                                                                                                                          |               | MOS  |             | 86              |     |                  | 12 Mar 2019 |                    |         |              |
|                                         |                                                                                                                          |               | MSC  |             |                 |     | -                |             |                    |         |              |

Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK.

| ATA<br>U=Custom                         | Description                                                                                                    |               | UOM  | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|-----------------------------------------|----------------------------------------------------------------------------------------------------------------|---------------|------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                         | Part Number                                                                                                    | Serial Number |      |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position                        | HW                                                                                                             | SW            |      |             |                 |     |                  |             |                    |         | Manufacturer |
|                                         | MM Ref                                                                                                         |               |      |             |                 |     |                  |             |                    |         | Date Type    |
|                                         | Ops Number(s)                                                                                                  |               |      |             |                 |     |                  |             |                    |         |              |
| ASC105A<br><br>(971051)<br><br>Airframe | ASC 105A - Data LAN Management Unit Harness - Service Loop Installation                                        |               | HRS  |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                         |                                                                                                                |               | AFL  |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                         |                                                                                                                |               | DATE |             |                 |     |                  |             |                    |         |              |
|                                         |                                                                                                                |               | MSC  |             |                 |     | -                |             |                    |         |              |
| ASC106<br><br>(971060)<br><br>Airframe  | ASC 106 Pilot Clock Wiring Harness - Service Loop Installation                                                 |               | HRS  |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                         |                                                                                                                |               | AFL  |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                         |                                                                                                                |               | DATE |             |                 |     |                  |             |                    |         |              |
|                                         |                                                                                                                |               | MSC  |             |                 |     | -                |             |                    |         |              |
| ASC108<br><br>(971080)<br><br>Airframe  | ASC 108 Stabilizer (ATA 55) Kuka-Band Fin CAP Radome - Installation                                            |               | HRS  |             |                 |     |                  |             |                    |         | 0            |
|                                         |                                                                                                                |               | AFL  |             |                 |     |                  |             |                    |         | 0            |
|                                         |                                                                                                                |               | DATE |             |                 |     |                  |             |                    |         |              |
|                                         |                                                                                                                |               | MSC  |             |                 |     | -                |             |                    |         |              |
| ASC109<br><br>(971090)<br><br>Airframe  | ASC109 - Placards / Markings (ATA 11) - Category Ii Approach Enhancement, Aircraft Service Change (Superseded) |               | HRS  |             |                 |     |                  |             |                    |         | 0            |
|                                         |                                                                                                                |               | AFL  |             |                 |     |                  |             |                    |         | 0            |
|                                         |                                                                                                                |               | DATE |             |                 |     |                  |             |                    |         |              |
|                                         |                                                                                                                |               | MSC  |             |                 |     | -                |             |                    |         |              |
| ASC109A<br><br>(971091)<br><br>Airframe | ASC109A - Placards / Markings (ATA 11) - Category Ii Approach Enhancement, Aircraft Service Change (Optional)  |               | HRS  |             | 1049.2          |     |                  | 1996.9      |                    |         | 0            |
|                                         |                                                                                                                |               | AFL  |             | 440             |     |                  | 677         |                    |         | 0            |
|                                         |                                                                                                                |               | MOS  |             | 43.5            |     |                  | 26 Sep 2022 |                    |         |              |
|                                         |                                                                                                                |               | MSC  |             |                 |     | -                |             |                    |         |              |
| ASC110<br><br>(971100)<br><br>Airframe  | ASC 110 Flap Electronic Control Unit (Fecu) Software - Update                                                  |               | HRS  |             |                 |     |                  |             |                    |         | 0            |
|                                         |                                                                                                                |               | AFL  |             |                 |     |                  |             |                    |         | 0            |
|                                         |                                                                                                                |               | DATE |             |                 |     |                  |             |                    |         |              |
|                                         |                                                                                                                |               | MSC  |             |                 |     | -                |             |                    |         |              |
| ASC110A<br><br>(971101)<br><br>Airframe | ASC 110A Flap Electronic Control Unit (Fecu) Software - Update                                                 |               | HRS  |             | 1300.7          |     |                  | 1745.4      |                    |         | 0            |
|                                         |                                                                                                                |               | AFL  |             | 507             |     |                  | 610         |                    |         | 0            |
|                                         |                                                                                                                |               | MOS  |             | 51.3            |     |                  | 02 Feb 2022 |                    |         |              |
|                                         |                                                                                                                |               | MSC  |             |                 |     | -                |             |                    |         |              |

| ATA<br>U=Custom                                                                            | Description                                                                                                           |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|--------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                                                                            | Part Number                                                                                                           | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position                                                                           | HW                                                                                                                    | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                                                                            | MM Ref                                                                                                                |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                                                                                            | Ops Number(s)                                                                                                         |               |     |             |                 |     |                  |             |                    |         |              |
| ASC111<br><br>(971110)<br><br>Airframe                                                     | ASC 111 Engine FIRE Bottle Harness Installation - Modification                                                        |               | HRS |             | 2120.8          |     |                  | 925.3       |                    |         | 0            |
|                                                                                            |                                                                                                                       |               | AFL |             | 861             |     |                  | 256         |                    |         | 0            |
|                                                                                            |                                                                                                                       |               | MOS |             | 85.9            |     |                  | 14 Mar 2019 |                    |         |              |
|                                                                                            |                                                                                                                       |               | MSC |             |                 |     | -                |             |                    |         |              |
| ASC111A<br><br>(971111)<br><br>Airframe                                                    | ASC 111A Engine FIRE Bottle Harness Installation - Modification                                                       |               | HRS |             | 2052.4          |     |                  | 993.7       |                    |         | 0            |
|                                                                                            |                                                                                                                       |               | AFL |             | 831             |     |                  | 286         |                    |         | 0            |
|                                                                                            |                                                                                                                       |               | MOS |             | 84.5            |     |                  | 26 Apr 2019 |                    |         |              |
|                                                                                            |                                                                                                                       |               | MSC |             |                 |     | -                |             |                    |         |              |
| Notes: PCW CB220 - NO FURTHER ACTION REQ"D                                                 |                                                                                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| ASC113<br><br>(971130)<br><br>Airframe                                                     | ASC 113 APU Exhaust Fairing Drainage - Modification                                                                   |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                                                       |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                                                       |               | MOS |             | 89.3            |     |                  | 03 Dec 2018 |                    |         |              |
|                                                                                            |                                                                                                                       |               | MSC |             |                 |     | -                |             |                    |         |              |
| Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK. |                                                                                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| ASC113A<br><br>(971131)<br><br>Airframe                                                    | ASC 113A APU Exhaust Fairing Drainage - Modification                                                                  |               | HRS |             | 2120.8          |     |                  | 925.3       |                    |         | 0            |
|                                                                                            |                                                                                                                       |               | AFL |             | 861             |     |                  | 256         |                    |         | 0            |
|                                                                                            |                                                                                                                       |               | MOS |             | 85.9            |     |                  | 13 Mar 2019 |                    |         |              |
|                                                                                            |                                                                                                                       |               | MSC |             |                 |     | -                |             |                    |         |              |
| ASC116<br><br>(971160)<br><br>Airframe                                                     | ASC 116 Battery Charger MODE Control Relays and Electrical Backup Hydraulic Actuator Battery Charger No. 2 - Removal  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                                                       |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                                                       |               | MOS |             | 85              |     |                  | 10 Apr 2019 |                    |         |              |
|                                                                                            |                                                                                                                       |               | MSC |             |                 |     | -                |             |                    |         |              |
| Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK. |                                                                                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| ASC116A<br><br>(971161)<br><br>Airframe                                                    | ASC 116A Battery Charger MODE Control Relays and Electrical Backup Hydraulic Actuator Battery Charger No. 2 - Removal |               | HRS |             | 1735.8          |     |                  | 1310.3      |                    |         | 0            |
|                                                                                            |                                                                                                                       |               | AFL |             | 729             |     |                  | 388         |                    |         | 0            |
|                                                                                            |                                                                                                                       |               | MOS |             | 75.2            |     |                  | 05 Feb 2020 |                    |         |              |
|                                                                                            |                                                                                                                       |               | MSC |             |                 |     | -                |             |                    |         |              |

| ATA<br>U=Custom                         | Description                                                                                                                              |               | UOM  | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|-----------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------|---------------|------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                         | Part Number                                                                                                                              | Serial Number |      |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position                        | HW                                                                                                                                       | SW            |      |             |                 |     |                  |             |                    |         | Manufacturer |
|                                         | MM Ref                                                                                                                                   |               |      |             |                 |     |                  |             |                    |         | Date Type    |
|                                         | Ops Number(s)                                                                                                                            |               |      |             |                 |     |                  |             |                    |         |              |
| ASC117<br><br>(971170)<br><br>Airframe  | ASC 117 Hydraulic Line Support Bracket Installation -<br>Modification to Provide Side Brace Actuator Clearance                           |               | HRS  |             | 2120.8          |     |                  | 925.3       |                    |         | 0            |
|                                         |                                                                                                                                          |               | AFL  |             | 861             |     |                  | 256         |                    | 0       |              |
|                                         |                                                                                                                                          |               | MOS  |             | 86.2            |     |                  | 05 Mar 2019 |                    |         |              |
|                                         |                                                                                                                                          |               | MSC  |             |                 |     | -                |             |                    |         |              |
| ASC118<br><br>(971180)<br><br>Airframe  | ASC 118 Aft Equipment Bay Water Shield - Installation                                                                                    |               | HRS  |             |                 |     |                  |             |                    |         | 0            |
|                                         |                                                                                                                                          |               | AFL  |             |                 |     |                  |             |                    | 0       |              |
|                                         |                                                                                                                                          |               | DATE |             |                 |     |                  |             |                    |         |              |
|                                         |                                                                                                                                          |               | MSC  |             |                 |     | -                |             |                    |         |              |
| ASC119<br><br>(971190)<br><br>Airframe  | ASC119 - Doors (ATA 52) Acoustic Door Damped Spring<br>Reel - Installation, Aircraft Service Change (Optional)                           |               | HRS  |             |                 |     |                  |             |                    |         | 0            |
|                                         |                                                                                                                                          |               | AFL  |             |                 |     |                  |             |                    | 0       |              |
|                                         |                                                                                                                                          |               | DATE |             |                 |     |                  |             |                    |         |              |
|                                         |                                                                                                                                          |               | MSC  |             |                 |     | -                |             |                    |         |              |
| ASC120<br><br>(971200)<br><br>Airframe  | ASC120 - Navigation (ATA 34) - Predictive Weather<br>Activation, Aircraft Service Change (Optional)                                      |               | HRS  |             |                 |     |                  |             |                    |         | 0            |
|                                         |                                                                                                                                          |               | AFL  |             |                 |     |                  |             |                    | 0       |              |
|                                         |                                                                                                                                          |               | MOS  |             |                 |     |                  |             |                    |         |              |
|                                         |                                                                                                                                          |               | MSC  |             |                 |     | -                |             |                    |         |              |
| ASC121<br><br>(971210)<br><br>Airframe  | ASC121 - Navigation (ATA 34) - Situational Awareness<br>Package Installation, Aircraft Service Change (Optional)                         |               | HRS  |             |                 |     |                  |             |                    |         | 0            |
|                                         |                                                                                                                                          |               | AFL  |             |                 |     |                  |             |                    | 0       |              |
|                                         |                                                                                                                                          |               | MOS  |             |                 |     |                  |             |                    |         |              |
|                                         |                                                                                                                                          |               | MSC  |             |                 |     | -                |             |                    |         |              |
| ASC122<br><br>(971220)<br><br>Airframe  | FIRE Protection (ATA 26) - Engine FIRE Extinguishing<br>Bottle Cartridge - Wiring - Modification, Aircraft Service<br>Change (Cancelled) |               | HRS  |             |                 |     |                  |             |                    |         | 0            |
|                                         |                                                                                                                                          |               | AFL  |             |                 |     |                  |             |                    | 0       |              |
|                                         |                                                                                                                                          |               | MOS  |             |                 |     |                  |             |                    |         |              |
|                                         |                                                                                                                                          |               | MSC  |             |                 |     | -                |             |                    |         |              |
| ASC122A<br><br>(971221)<br><br>Airframe | FIRE Protection (ATA 26) - Engine FIRE Extinguishing<br>Bottle Cartridge Wiring - Modification, Aircraft Service<br>Change (Optional)    |               | HRS  |             | 1300.7          |     |                  | 1745.4      |                    |         | 0            |
|                                         |                                                                                                                                          |               | AFL  |             | 507             |     |                  | 610         |                    | 0       |              |
|                                         |                                                                                                                                          |               | MOS  |             | 51.4            |     |                  | 30 Jan 2022 |                    |         |              |
|                                         |                                                                                                                                          |               | MSC  |             |                 |     | -                |             |                    |         |              |

| ATA<br>U=Custom                                                                            | Description                                                                                                                          |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|--------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                                                                            | Part Number                                                                                                                          | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position                                                                           | HW                                                                                                                                   | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                                                                            | MM Ref                                                                                                                               |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                                                                                            | Ops Number(s)                                                                                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| ASC123<br>(971230)<br><br>Airframe                                                         | ASC 123 APU Electronic Control Unit Software - Update                                                                                |               | HRS |             | 1844.6          |     |                  | 1201.5      |                    |         | 0            |
|                                                                                            |                                                                                                                                      |               | AFL |             | 766             |     |                  | 351         |                    |         | 0            |
|                                                                                            |                                                                                                                                      |               | MOS |             | 79.3            |     |                  | 03 Oct 2019 |                    |         |              |
|                                                                                            |                                                                                                                                      |               | MSC |             |                 |     | -                |             |                    |         |              |
| Notes: PN: WE3888570-3 SN: 2114326-D14.                                                    |                                                                                                                                      |               |     |             |                 |     |                  |             |                    |         |              |
| ASC123A<br>(971231)<br><br>Airframe                                                        | ASC 123A APU Electronic Control Unit Software - Update                                                                               |               | HRS |             | 1650.8          |     |                  | 1395.3      |                    |         | 0            |
|                                                                                            |                                                                                                                                      |               | AFL |             | 691             |     |                  | 426         |                    |         | 0            |
|                                                                                            |                                                                                                                                      |               | MOS |             | 72              |     |                  | 10 May 2020 |                    |         |              |
|                                                                                            |                                                                                                                                      |               | MSC |             |                 |     | -                |             |                    |         |              |
| ASC124<br>(971240)<br><br>Airframe                                                         | ASC 124 Pylon Seal Retainer - Modification                                                                                           |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                                                                      |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                                                                      |               | MOS |             | 87.1            |     |                  | 08 Feb 2019 |                    |         |              |
|                                                                                            |                                                                                                                                      |               | MSC |             |                 |     | -                |             |                    |         |              |
| Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK. |                                                                                                                                      |               |     |             |                 |     |                  |             |                    |         |              |
| ASC124A<br>(971241)<br><br>Airframe                                                        | ASC 124A Pylon Seal Retainer - Modification                                                                                          |               | HRS |             | 1735.8          |     |                  | 1310.3      |                    |         | 0            |
|                                                                                            |                                                                                                                                      |               | AFL |             | 729             |     |                  | 388         |                    |         | 0            |
|                                                                                            |                                                                                                                                      |               | MOS |             | 75.7            |     |                  | 19 Jan 2020 |                    |         |              |
|                                                                                            |                                                                                                                                      |               | MSC |             |                 |     | -                |             |                    |         |              |
| ASC125<br>(971250)<br><br>Airframe                                                         | ASC125 - Navigation (ATA 34) - Heads Up Display (HUD) li Software Update, Aircraft Service Change (Optional)                         |               | HRS |             | 562.4           |     |                  | 2483.7      |                    |         | 0            |
|                                                                                            |                                                                                                                                      |               | AFL |             | 217             |     |                  | 900         |                    |         | 0            |
|                                                                                            |                                                                                                                                      |               | MOS |             | 17.2            |     |                  | 06 Dec 2024 |                    |         |              |
|                                                                                            |                                                                                                                                      |               | MSC |             |                 |     | -                |             |                    |         |              |
| ASC127<br>(971270)<br><br>Airframe                                                         | ASC127 - Navigation (ATA 34) - Predictive Landing Performance System (Plps) Package Installation, Aircraft Service Change (Optional) |               | HRS |             |                 |     |                  |             |                    |         | 0            |
|                                                                                            |                                                                                                                                      |               | AFL |             |                 |     |                  |             |                    |         | 0            |
|                                                                                            |                                                                                                                                      |               | MOS |             |                 |     |                  |             |                    |         |              |
|                                                                                            |                                                                                                                                      |               | MSC |             |                 |     | -                |             |                    |         |              |
| ASC128<br>(971280)<br><br>Airframe                                                         | ASC128 - Autoflight (ATA 22) - Auto-Pilot Coupled TCAS Activation, Aircraft Service Change (Optional)                                |               | HRS |             |                 |     |                  |             |                    |         | 0            |
|                                                                                            |                                                                                                                                      |               | AFL |             |                 |     |                  |             |                    |         | 0            |
|                                                                                            |                                                                                                                                      |               | MOS |             |                 |     |                  |             |                    |         |              |
|                                                                                            |                                                                                                                                      |               | MSC |             |                 |     | -                |             |                    |         |              |

| ATA<br>U=Custom                                                                            | Description                                                     |               | UOM  | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|--------------------------------------------------------------------------------------------|-----------------------------------------------------------------|---------------|------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                                                                            | Part Number                                                     | Serial Number |      |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position                                                                           | HW                                                              | SW            |      |             |                 |     |                  |             |                    |         | Manufacturer |
|                                                                                            | MM Ref                                                          |               |      |             |                 |     |                  |             |                    |         | Date Type    |
|                                                                                            | Ops Number(s)                                                   |               |      |             |                 |     |                  |             |                    |         |              |
| ASC129<br>(971290)<br><br>Airframe                                                         | ASC 129 Flap Track D Up-Stop Fitting - Improvement              |               | HRS  |             |                 |     |                  |             |                    |         | 0            |
|                                                                                            |                                                                 |               | AFL  |             |                 |     |                  |             |                    | 0       |              |
|                                                                                            |                                                                 |               | DATE |             |                 |     |                  |             |                    |         |              |
|                                                                                            |                                                                 |               | MSC  |             |                 |     | -                |             |                    |         |              |
| ASC131<br>(971310)<br><br>Airframe                                                         | ASC 131 Flap Track C Roller Fitting - Rub PAD Installation      |               | HRS  |             | 1452            |     |                  | 1594.1      |                    |         | 0            |
|                                                                                            |                                                                 |               | AFL  |             | 570             |     |                  | 547         |                    |         | 0            |
|                                                                                            |                                                                 |               | MOS  |             | 63.9            |     |                  | 15 Jan 2021 |                    |         |              |
|                                                                                            |                                                                 |               | MSC  |             |                 |     | -                |             |                    |         |              |
| ASC133<br>(971330)<br><br>Airframe                                                         | ASC 133 Engine Electronic Controller - K9.0.1 Software Upgrade  |               | HRS  |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                 |               | AFL  |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                 |               | MOS  |             | 80.6            |     |                  | 23 Aug 2019 |                    |         |              |
|                                                                                            |                                                                 |               | MSC  |             |                 |     | -                |             |                    |         |              |
| Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK. |                                                                 |               |      |             |                 |     |                  |             |                    |         |              |
| ASC133A<br>(971331)<br><br>Airframe                                                        | ASC 133A Engine Electronic Controller - K9.0.1 Software Upgrade |               | HRS  |             | 1885.7          |     |                  | 1160.4      |                    |         | 0            |
|                                                                                            |                                                                 |               | AFL  |             | 779             |     |                  | 338         |                    |         | 0            |
|                                                                                            |                                                                 |               | MOS  |             | 80.5            |     |                  | 27 Aug 2019 |                    |         |              |
|                                                                                            |                                                                 |               | MSC  |             |                 |     | -                |             |                    |         |              |
| ASC134 PART I<br>(971340)<br><br>Airframe                                                  | ASC 134 (Part 1) Wedge Installation - Trailing Edge, Rudder     |               | HRS  |             | 1784.3          |     |                  | 1261.8      |                    |         | 0            |
|                                                                                            |                                                                 |               | AFL  |             | 751             |     |                  | 366         |                    |         | 0            |
|                                                                                            |                                                                 |               | MOS  |             | 77.1            |     |                  | 08 Dec 2019 |                    |         |              |
|                                                                                            |                                                                 |               | MSC  |             |                 |     | -                |             |                    |         |              |
| ASC134 PART II<br>(971341)<br><br>Airframe                                                 | ASC 134 (Part 2) Wedge Installation - Trailing Edge, Rudder     |               | HRS  |             |                 |     |                  |             |                    |         | 0            |
|                                                                                            |                                                                 |               | AFL  |             |                 |     |                  |             |                    |         | 0            |
|                                                                                            |                                                                 |               | DATE |             |                 |     |                  |             |                    |         |              |
|                                                                                            |                                                                 |               | MSC  |             |                 |     | -                |             |                    |         |              |
| ASC134A PART I<br>(971342)<br><br>Airframe                                                 | ASC 134A (Part 1) Wedge Installation - Trailing Edge, Rudder    |               | HRS  |             | 1784.3          |     |                  | 1261.8      |                    |         | 0            |
|                                                                                            |                                                                 |               | AFL  |             | 751             |     |                  | 366         |                    |         | 0            |
|                                                                                            |                                                                 |               | MOS  |             | 77.1            |     |                  | 08 Dec 2019 |                    |         |              |
|                                                                                            |                                                                 |               | MSC  |             |                 |     | -                |             |                    |         |              |

| ATA<br>U=Custom                                 | Description                                                                                                                                |               | UOM  | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|-------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------|---------------|------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                                 | Part Number                                                                                                                                | Serial Number |      |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position                                | HW                                                                                                                                         | SW            |      |             |                 |     |                  |             |                    |         | Manufacturer |
|                                                 | MM Ref                                                                                                                                     |               |      |             |                 |     |                  |             |                    |         | Date Type    |
|                                                 | Ops Number(s)                                                                                                                              |               |      |             |                 |     |                  |             |                    |         |              |
| ASC134A PART II<br><br>(971343)<br><br>Airframe | ASC 134A (Part 2) Wedge Installation - Trailing Edge, Rudder                                                                               |               | HRS  |             | 1735.8          |     |                  | 1310.3      |                    |         | 0            |
|                                                 |                                                                                                                                            |               | AFL  |             | 729             |     |                  | 388         |                    |         | 0            |
|                                                 |                                                                                                                                            |               | MOS  |             | 75.2            |     |                  | 05 Feb 2020 |                    |         |              |
|                                                 |                                                                                                                                            |               | MSC  |             |                 |     | -                |             |                    |         |              |
| ASC134B PART I<br><br>(971344)<br><br>Airframe  | ASC 134B (Part 1) Wedge Installation - Trailing Edge, Rudder                                                                               |               | HRS  |             | 1650.8          |     |                  | 1395.3      |                    |         | 0            |
|                                                 |                                                                                                                                            |               | AFL  |             | 691             |     |                  | 426         |                    |         | 0            |
|                                                 |                                                                                                                                            |               | MOS  |             | 72.3            |     |                  | 01 May 2020 |                    |         |              |
|                                                 |                                                                                                                                            |               | MSC  |             |                 |     | N/A              |             |                    |         |              |
| ASC134B PART II<br><br>(971345)<br><br>Airframe | ASC 134B (Part 2) Wedge Installation - Trailing Edge, Rudder                                                                               |               | HRS  |             | 1650.8          |     |                  | 1395.3      |                    |         | 0            |
|                                                 |                                                                                                                                            |               | AFL  |             | 691             |     |                  | 426         |                    |         | 0            |
|                                                 |                                                                                                                                            |               | MOS  |             | 72.3            |     |                  | 01 May 2020 |                    |         |              |
|                                                 |                                                                                                                                            |               | MSC  |             |                 |     | -                |             |                    |         |              |
| ASC135<br><br>(971350)<br><br>Airframe          | ASC 135 Flight Control Computer (FCC) Software Update V10.1                                                                                |               | HRS  |             | 1452            |     |                  | 1594.1      |                    |         | 0            |
|                                                 |                                                                                                                                            |               | AFL  |             | 570             |     |                  | 547         |                    |         | 0            |
|                                                 |                                                                                                                                            |               | MOS  |             | 63.5            |     |                  | 27 Jan 2021 |                    |         |              |
|                                                 |                                                                                                                                            |               | MSC  |             |                 |     | -                |             |                    |         |              |
| ASC137<br><br>(971370)<br><br>Airframe          | ASC137 - Placards and Markings (ATA 11) - Category B Maximum Landing Weight Reduction - 65,000 Pound, Aircraft Service Change (Superseded) |               | HRS  |             |                 |     |                  |             |                    |         | 0            |
|                                                 |                                                                                                                                            |               | AFL  |             |                 |     |                  |             |                    |         | 0            |
|                                                 |                                                                                                                                            |               | DATE |             |                 |     |                  |             |                    |         |              |
|                                                 |                                                                                                                                            |               | MSC  |             |                 |     | -                |             |                    |         |              |
| ASC137A<br><br>(971371)<br><br>Airframe         | ASC137A - Placards and Markings (ATA 11) - Category B Maximum Landing Weight Reduction - 65,000 Pound, Aircraft Service Change (Optional)  |               | HRS  |             |                 |     |                  |             |                    |         | 0            |
|                                                 |                                                                                                                                            |               | AFL  |             |                 |     |                  |             |                    |         | 0            |
|                                                 |                                                                                                                                            |               | DATE |             |                 |     |                  |             |                    |         |              |
|                                                 |                                                                                                                                            |               | MSC  |             |                 |     | -                |             |                    |         |              |



| ATA<br>U=Custom  | Description                                              |               | UOM  | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------------|---------------|------|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                              | Serial Number |      |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                       | SW            |      |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                   |               |      |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                            |               |      |             |                 |     |                  |             |                     |         |              |
| ASC138           | ASC138 - Engine Fuel & Control (ATA 73) - Engine         |               | HRS  |             | 1178.9          |     |                  | 1867.2      |                     |         | 0            |
|                  | Electronic Controller - K10.1 Software Upgrade, Aircraft |               | AFL  |             | 487             |     |                  | 630         |                     |         | 0            |
|                  | Service Change (Optional)                                |               | MOS  |             | 48.2            |     |                  | 06 May 2022 |                     |         |              |
|                  |                                                          |               | MSC  |             |                 |     | -                |             |                     |         |              |
| (971380)         |                                                          |               |      |             |                 |     |                  |             |                     |         |              |
| Airframe         |                                                          |               |      |             |                 |     |                  |             |                     |         |              |
| ASC139           | ASC139 - Equipment and Furnishings (ATA 25) -            |               | HRS  |             | 562.4           |     |                  | 2483.7      |                     |         | 0            |
|                  | Emergency Vision Assurance System (EVAS) - Removal,      |               | AFL  |             | 217             |     |                  | 900         |                     |         | 0            |
|                  | Aircraft Service Change (Optional)                       |               | MOS  |             | 17.4            |     |                  | 29 Nov 2024 |                     |         |              |
|                  |                                                          |               | MSC  |             |                 |     | -                |             |                     |         |              |
| (971390)         |                                                          |               |      |             |                 |     |                  |             |                     |         |              |
| Airframe         |                                                          |               |      |             |                 |     |                  |             |                     |         |              |
| ASC140           | ASC140 - Information Systems (ATA 46) - Aircraft Health  |               | HRS  |             | 730.5           |     |                  | 2315.6      |                     |         | 0            |
|                  | and Trend Monitoring System (Ahtms) Software Update,     |               | AFL  |             | 315             |     |                  | 802         |                     |         | 0            |
|                  | Aircraft Service Change (Optional)                       |               | MOS  |             | 30.8            |     |                  | 18 Oct 2023 |                     |         |              |
|                  |                                                          |               | MSC  |             |                 |     | -                |             |                     |         |              |
| (971400)         |                                                          |               |      |             |                 |     |                  |             |                     |         |              |
| Airframe         |                                                          |               |      |             |                 |     |                  |             |                     |         |              |
| ASC141           | ASC141 - Communications (ATA 23) - Cockpit Voice         |               | HRS  |             |                 |     |                  |             |                     |         | 0            |
|                  | Recorder (Cvr) 25-Hour Upgrade Installation, Aircraft    |               | AFL  |             |                 |     |                  |             |                     |         | 0            |
|                  | Service Change (Optional)                                |               | DATE |             |                 |     |                  |             |                     |         |              |
|                  |                                                          |               | MSC  |             |                 |     | -                |             |                     |         |              |
| (971410)         |                                                          |               |      |             |                 |     |                  |             |                     |         |              |
| Airframe         |                                                          |               |      |             |                 |     |                  |             |                     |         |              |
| ASC141A          | ASC141A - Communications (ATA 23) Cockpit Voice          |               | HRS  |             |                 |     |                  |             |                     |         | 0            |
|                  | Recorder (Cvr) 25-Hour Upgrade Installation, Aircraft    |               | AFL  |             |                 |     |                  |             |                     |         | 0            |
|                  | Service Change (Optional)                                |               | DATE |             |                 |     |                  |             |                     |         |              |
|                  |                                                          |               | MSC  |             |                 |     | -                |             |                     |         |              |
| (971411)         |                                                          |               |      |             |                 |     |                  |             |                     |         |              |
| Airframe         |                                                          |               |      |             |                 |     |                  |             |                     |         |              |
| ASC142           | ASC142 - Fuselage Structure (ATA 53) - Auxiliary Power   |               | HRS  |             |                 |     |                  |             |                     |         | 0            |
|                  | Unit Enclosure - Exhaust Duct Fastener Pitch             |               | AFL  |             |                 |     |                  |             |                     |         | 0            |
|                  | Modification, Aircraft Service Change (Optional)         |               | DATE |             |                 |     |                  |             |                     |         |              |
|                  |                                                          |               | MSC  |             |                 |     | -                |             |                     |         |              |
| (971420)         |                                                          |               |      |             |                 |     |                  |             |                     |         |              |
| Airframe         |                                                          |               |      |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom  | Description                                                                                                                                                       |               | UOM  | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                                                                                                       | Serial Number |      |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                                                                                                                | SW            |      |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                                                                                                            |               |      |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                                                                                                                     |               |      |             |                 |     |                  |             |                    |         |              |
| ASC143           | ASC143 - Communications (ATA 23) - Communication Management Function (Cmf) SATCOM Direct (Non-Sita) Datalink Service Provider, Aircraft Service Change (Optional) |               | HRS  |             |                 |     |                  |             |                    |         | 0            |
|                  |                                                                                                                                                                   |               | AFL  |             |                 |     |                  |             |                    |         | 0            |
|                  |                                                                                                                                                                   |               | DATE |             |                 |     |                  |             |                    |         |              |
|                  |                                                                                                                                                                   |               | MSC  |             |                 |     | -                |             |                    |         |              |
| (971430)         |                                                                                                                                                                   |               |      |             |                 |     |                  |             |                    |         |              |
| Airframe         |                                                                                                                                                                   |               |      |             |                 |     |                  |             |                    |         |              |
| ASC144           | ASC144 - Navigation (ATA 34) - Attitude Heading Reference Unit Label Installation, Aircraft Service Change (Optional)                                             |               | HRS  |             | 562.4           |     |                  | 2483.7      |                    |         | 0            |
|                  |                                                                                                                                                                   |               | AFL  |             | 217             |     |                  | 900         |                    |         | 0            |
|                  |                                                                                                                                                                   |               | MOS  |             | 17.5            |     |                  | 28 Nov 2024 |                    |         |              |
|                  |                                                                                                                                                                   |               | MSC  |             |                 |     | -                |             |                    |         |              |
| (971440)         |                                                                                                                                                                   |               |      |             |                 |     |                  |             |                    |         |              |
| Airframe         |                                                                                                                                                                   |               |      |             |                 |     |                  |             |                    |         |              |
| ASC146           | Equipment and Furnishings (ATA 25) - Ebha Pdb Terminal Bracket Cover - Installation, Aircraft Service Change (Optional)                                           |               | HRS  |             | 562.4           |     |                  | 2483.7      |                    |         | 0            |
|                  |                                                                                                                                                                   |               | AFL  |             | 217             |     |                  | 900         |                    |         | 0            |
|                  |                                                                                                                                                                   |               | MOS  |             | 17.2            |     |                  | 05 Dec 2024 |                    |         |              |
|                  |                                                                                                                                                                   |               | MSC  |             |                 |     | -                |             |                    |         |              |
| (971460)         |                                                                                                                                                                   |               |      |             |                 |     |                  |             |                    |         |              |
| Airframe         |                                                                                                                                                                   |               |      |             |                 |     |                  |             |                    |         |              |
| ASC152           | ASC152 - Engine Controls (ATA 76) - Engine Fuel Control Panel Connector - Harness Modification, Aircraft Service Change (Optional)                                |               | HRS  |             |                 |     |                  |             |                    |         | 0            |
|                  |                                                                                                                                                                   |               | AFL  |             |                 |     |                  |             |                    |         | 0            |
|                  |                                                                                                                                                                   |               | MOS  |             |                 |     |                  |             |                    |         |              |
|                  |                                                                                                                                                                   |               | MSC  |             |                 |     | -                |             |                    |         |              |
| (971520)         |                                                                                                                                                                   |               |      |             |                 |     |                  |             |                    |         |              |
| Airframe         |                                                                                                                                                                   |               |      |             |                 |     |                  |             |                    |         |              |
| ASC152A          | ASC152A - Engine Controls (ATA 76) - Engine Fuel Control Panel Connector - Harness Modification, Aircraft Service Change (Optional)                               |               | HRS  |             |                 |     |                  |             |                    |         | 0            |
|                  |                                                                                                                                                                   |               | AFL  |             |                 |     |                  |             |                    |         | 0            |
|                  |                                                                                                                                                                   |               | MOS  |             |                 |     |                  |             |                    |         |              |
|                  |                                                                                                                                                                   |               | MSC  |             |                 |     | -                |             |                    |         |              |
| (971521)         |                                                                                                                                                                   |               |      |             |                 |     |                  |             |                    |         |              |
| Airframe         |                                                                                                                                                                   |               |      |             |                 |     |                  |             |                    |         |              |
| ASC153A          | ASC153A - Wings (ATA 57) - Flap Track D Anti-Friction Plates and SELF-Aligning Rollers - Installation, Aircraft Service Change (Optional)                         |               | HRS  |             |                 |     |                  |             |                    |         | 0            |
|                  |                                                                                                                                                                   |               | AFL  |             |                 |     |                  |             |                    |         | 0            |
|                  |                                                                                                                                                                   |               | MOS  |             |                 |     |                  |             |                    |         |              |
|                  |                                                                                                                                                                   |               | MSC  |             |                 |     | -                |             |                    |         |              |
| (971531)         |                                                                                                                                                                   |               |      |             |                 |     |                  |             |                    |         |              |
| Airframe         |                                                                                                                                                                   |               |      |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom                                                                            | Description                                              |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|--------------------------------------------------------------------------------------------|----------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                                                                            | Part Number                                              | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position                                                                           | HW                                                       | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                                                                            | MM Ref                                                   |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                                                                                            | Ops Number(s)                                            |               |     |             |                 |     |                  |             |                    |         |              |
| ASC155                                                                                     | ASC155 - Hydraulic Power (ATA 29) - Hydraulic            |               | HRS |             |                 |     |                  |             |                    |         | 0            |
|                                                                                            | Replenisher Selector Valve Connector (082L1P1) -         |               | AFL |             |                 |     |                  |             |                    |         | 0            |
|                                                                                            | Harness Modification, Aircraft Service Change (Optional) |               | MOS |             |                 |     |                  |             |                    |         |              |
|                                                                                            |                                                          |               | MSC |             |                 |     | -                |             |                    |         |              |
| (971550)                                                                                   |                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                                                                                   |                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| ASC156                                                                                     | ASC156 - Oil (ATA 79) - Oil Servicing Selector Valve     |               | HRS |             |                 |     |                  |             |                    |         | 0            |
|                                                                                            | Connector (082L4P1) - Harness Modification, Service      |               | AFL |             |                 |     |                  |             |                    |         | 0            |
|                                                                                            | Bulletin (Optional)                                      |               | MOS |             |                 |     |                  |             |                    |         |              |
|                                                                                            |                                                          |               | MSC |             |                 |     | -                |             |                    |         |              |
| (971560)                                                                                   |                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                                                                                   |                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| ASC159                                                                                     | ASC159 - Fuselage (ATA 53) - Aft Fuselage Water          |               | HRS |             | 137             |     |                  | 2909.1      |                    |         | 0            |
|                                                                                            | Drainage - Modification, Aircraft Service Change         |               | AFL |             | 52              |     |                  | 1065        |                    |         | 0            |
|                                                                                            | (Optional)                                               |               | MOS |             | 5.4             |     |                  | 29 Nov 2025 |                    |         |              |
|                                                                                            |                                                          |               | MSC |             |                 |     | -                |             |                    |         |              |
| (971590)                                                                                   |                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                                                                                   |                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| ASC902                                                                                     | ASC902 - Indicating / Recording (ATA 31) - Planeview li  |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                                                                            | Master Operating System Software Update                  |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                          |               | MOS |             | 112.6           |     |                  | 22 Dec 2016 |                    |         |              |
|                                                                                            |                                                          |               | MSC |             |                 |     | -                |             |                    |         |              |
| (979020)                                                                                   |                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                                                                                   |                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK. |                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| ASC902A                                                                                    | ASC902A - Indicating / Recording (ATA 31) - Planeview li |               | HRS |             | 2673.8          |     |                  | 372.3       |                    |         | 0            |
|                                                                                            | Master Operating System Software Update                  |               | AFL |             | 1020            |     |                  | 97          |                    |         | 0            |
|                                                                                            |                                                          |               | MOS |             | 109.4           |     |                  | 30 Mar 2017 |                    |         |              |
|                                                                                            |                                                          |               | MSC |             |                 |     | -                |             |                    |         |              |
| (979021)                                                                                   |                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                                                                                   |                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| ASC902B                                                                                    | ASC902B - Indicating / Recording (ATA ) - Planeview li   |               | HRS |             | 1049.2          |     |                  | 1996.9      |                    |         | 0            |
|                                                                                            | Master Operating System Software Update                  |               | AFL |             | 440             |     |                  | 677         |                    |         | 0            |
|                                                                                            |                                                          |               | MOS |             | 43.4            |     |                  | 29 Sep 2022 |                    |         |              |
|                                                                                            |                                                          |               | MSC |             |                 |     | -                |             |                    |         |              |
| (979022)                                                                                   |                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                                                                                   |                                                          |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom                                                                            | Description                                                                                                                          |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|--------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                                                                            | Part Number                                                                                                                          | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position                                                                           | HW                                                                                                                                   | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                                                                            | MM Ref                                                                                                                               |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                                                                                            | Ops Number(s)                                                                                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| ASC903<br><br>(979030)<br><br>Airframe                                                     | ASC903 - Indicating / Recording (ATA 31) - Planeview™ li<br>Master Operating System Software Update, Service<br>Bulletin (Optional)  |               | HRS |             |                 |     |                  |             |                    |         | 0            |
|                                                                                            |                                                                                                                                      |               | AFL |             |                 |     |                  |             |                    | 0       |              |
|                                                                                            |                                                                                                                                      |               | MOS |             |                 |     |                  |             |                    |         |              |
|                                                                                            |                                                                                                                                      |               | MSC |             |                 |     | -                |             |                    |         |              |
| ASC903A<br><br>(979031)<br><br>Airframe                                                    | ASC903A - Indicating / Recording (ATA 31) - Planeview™ li<br>Master Operating System Software Update, Service<br>Bulletin (Optional) |               | HRS |             | 562.4           |     |                  | 2483.7      |                    |         | 0            |
|                                                                                            |                                                                                                                                      |               | AFL |             | 217             |     |                  | 900         |                    | 0       |              |
|                                                                                            |                                                                                                                                      |               | MOS |             | 17.1            |     |                  | 09 Dec 2024 |                    |         |              |
|                                                                                            |                                                                                                                                      |               | MSC |             |                 |     | -                |             |                    |         |              |
| CB067A<br><br>(980671)<br><br>Airframe                                                     | CB067A - Indicating/Recording Systems (ATA 31),<br>Modification - CO-Pilots Crew Alerting System (CAS)<br>Scroll Switch Wiring       |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                                                                                            |                                                                                                                                      |               | AFL |             | 1112            |     |                  | 5           |                    | 0       |              |
|                                                                                            |                                                                                                                                      |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         |              |
|                                                                                            |                                                                                                                                      |               | MSC |             |                 |     | -                |             |                    |         |              |
| CB069A<br><br>(980691)<br><br>Airframe                                                     | CB069A - Fuselage (ATA 53) Inspection - Tailcone<br>Assembly Sealant Application                                                     |               | HRS |             | 3024.9          |     |                  | 21.2        |                    |         | 0            |
|                                                                                            |                                                                                                                                      |               | AFL |             | 1110            |     |                  | 7           |                    | 0       |              |
|                                                                                            |                                                                                                                                      |               | MOS |             | 123.5           |     |                  | 28 Jan 2016 |                    |         |              |
|                                                                                            |                                                                                                                                      |               | MSC |             |                 |     | -                |             |                    |         |              |
| CB076B<br><br>(980762)<br><br>Airframe                                                     | CB076B - Communications (ATA 23), Modification - High<br>Speed Data - Software Upgrade                                               |               | HRS |             | 2937.3          |     |                  | 108.8       |                    |         | 0            |
|                                                                                            |                                                                                                                                      |               | AFL |             | 1089            |     |                  | 28          |                    | 0       |              |
|                                                                                            |                                                                                                                                      |               | MOS |             | 119.2           |     |                  | 06 Jun 2016 |                    |         |              |
|                                                                                            |                                                                                                                                      |               | MSC |             |                 |     | -                |             |                    |         |              |
| Notes: FOUND EMBODIED                                                                      |                                                                                                                                      |               |     |             |                 |     |                  |             |                    |         |              |
| CB087<br><br>(980870)<br><br>Airframe                                                      | CB087 - FIRE Protection (ATA 26), Inspection - Engine<br>FIRE Bottle Cartridge (Squib) Electrical Connections                        |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                                                                                            |                                                                                                                                      |               | AFL |             | 1112            |     |                  | 5           |                    | 0       |              |
|                                                                                            |                                                                                                                                      |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         |              |
|                                                                                            |                                                                                                                                      |               | MSC |             |                 |     | -                |             |                    |         |              |
| Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK. |                                                                                                                                      |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom                                                                            | Description                                                                                                              |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|--------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                                                                                            | Part Number                                                                                                              | Serial Number |     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position                                                                           | HW                                                                                                                       | SW            |     |             |                 |     |                  |             |                     |         | Manufacturer |
|                                                                                            | MM Ref                                                                                                                   |               |     |             |                 |     |                  |             |                     |         | Date Type    |
|                                                                                            | Ops Number(s)                                                                                                            |               |     |             |                 |     |                  |             |                     |         |              |
| CB087A                                                                                     | CB087A - FIRE Protection (ATA 26) Inspection - Engine<br>FIRE Bottle Cartridge (Squib) Electrical Connections            |               | HRS |             | 3033.8          |     |                  | 12.3        |                     |         | 0            |
|                                                                                            |                                                                                                                          |               | AFL |             | 1112            |     |                  | 5           |                     | 0       |              |
|                                                                                            |                                                                                                                          |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                     |         |              |
|                                                                                            |                                                                                                                          |               | MSC |             |                 |     | -                |             |                     |         |              |
| (980871)                                                                                   |                                                                                                                          |               |     |             |                 |     |                  |             |                     |         |              |
| Airframe                                                                                   |                                                                                                                          |               |     |             |                 |     |                  |             |                     |         |              |
| CB088                                                                                      | CB088 - Doors (ATA 52), Replacement - Main Entrance<br>Door Torque Tube Bearing Housing Hardware                         |               | HRS |             | 3033.8          |     |                  | 12.3        |                     |         | 0            |
|                                                                                            |                                                                                                                          |               | AFL |             | 1112            |     |                  | 5           |                     | 0       |              |
|                                                                                            |                                                                                                                          |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                     |         |              |
|                                                                                            |                                                                                                                          |               | MSC |             |                 |     | -                |             |                     |         |              |
| (980880)                                                                                   |                                                                                                                          |               |     |             |                 |     |                  |             |                     |         |              |
| Airframe                                                                                   |                                                                                                                          |               |     |             |                 |     |                  |             |                     |         |              |
| CB089                                                                                      | CB089 - Equipment and Furnishings (ATA 25),<br>Replacement - Flashlights (ASC 025)                                       |               | HRS |             | 3033.8          |     |                  | 12.3        |                     |         | 0            |
|                                                                                            |                                                                                                                          |               | AFL |             | 1112            |     |                  | 5           |                     | 0       |              |
|                                                                                            |                                                                                                                          |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                     |         |              |
|                                                                                            |                                                                                                                          |               | MSC |             |                 |     | -                |             |                     |         |              |
| (980890)                                                                                   |                                                                                                                          |               |     |             |                 |     |                  |             |                     |         |              |
| Airframe                                                                                   |                                                                                                                          |               |     |             |                 |     |                  |             |                     |         |              |
| CB090                                                                                      | CB090 - Equipment and Furnishings (ATA 25), Inspection<br>- Passenger Seat Restraint System (Amsafe Sb 504443-<br>25-02) |               | HRS |             | 3033.8          |     |                  | 12.3        |                     |         | 0            |
|                                                                                            |                                                                                                                          |               | AFL |             | 1112            |     |                  | 5           |                     | 0       |              |
|                                                                                            |                                                                                                                          |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                     |         |              |
|                                                                                            |                                                                                                                          |               | MSC |             |                 |     | -                |             |                     |         |              |
| (980900)                                                                                   |                                                                                                                          |               |     |             |                 |     |                  |             |                     |         |              |
| Airframe                                                                                   |                                                                                                                          |               |     |             |                 |     |                  |             |                     |         |              |
| Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK. |                                                                                                                          |               |     |             |                 |     |                  |             |                     |         |              |
| CB090A                                                                                     | CB090A - Equipment and Furnishings (ATA 25),<br>Inspection - Passenger Seat Restraint System (Amsafe<br>Sb 504443-25-02) |               | HRS |             | 3033.8          |     |                  | 12.3        |                     |         | 0            |
|                                                                                            |                                                                                                                          |               | AFL |             | 1112            |     |                  | 5           |                     | 0       |              |
|                                                                                            |                                                                                                                          |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                     |         |              |
|                                                                                            |                                                                                                                          |               | MSC |             |                 |     | -                |             |                     |         |              |
| (980901)                                                                                   |                                                                                                                          |               |     |             |                 |     |                  |             |                     |         |              |
| Airframe                                                                                   |                                                                                                                          |               |     |             |                 |     |                  |             |                     |         |              |
| Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK. |                                                                                                                          |               |     |             |                 |     |                  |             |                     |         |              |
| CB090B                                                                                     | CB090B - Equipment and Furnishings (ATA 25),<br>Inspection - Passenger Seat Restraint System (Amsafe<br>Sb 504443-25-02) |               | HRS |             | 3033.8          |     |                  | 12.3        |                     |         | 0            |
|                                                                                            |                                                                                                                          |               | AFL |             | 1112            |     |                  | 5           |                     | 0       |              |
|                                                                                            |                                                                                                                          |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                     |         |              |
|                                                                                            |                                                                                                                          |               | MSC |             |                 |     | -                |             |                     |         |              |
| (980902)                                                                                   |                                                                                                                          |               |     |             |                 |     |                  |             |                     |         |              |
| Airframe                                                                                   |                                                                                                                          |               |     |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom                        | Description                                                                                                                         |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|----------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|----------|---------------------|---------|--------------|
|                                        | Part Number                                                                                                                         | Serial Number |     |             |                 |     |                  |          |                     |         | Approx Price |
| Logbook Position                       | HW                                                                                                                                  | SW            |     |             |                 |     |                  |          |                     |         | Manufacturer |
|                                        | MM Ref                                                                                                                              |               |     |             |                 |     |                  |          |                     |         | Date Type    |
|                                        | Ops Number(s)                                                                                                                       |               |     |             |                 |     |                  |          |                     |         |              |
| CB091<br><br>(980910)<br><br>Airframe  | CB091 - Standard Practices (ATA 20), Inspection - Itt<br>Cannon Connectors                                                          |               | HRS |             | 3021.1          |     |                  | 25       |                     |         | 0            |
|                                        |                                                                                                                                     |               | AFL |             | 1108            |     | 9                |          | 0                   |         |              |
|                                        |                                                                                                                                     |               | MOS |             | 122.6           |     | 24 Feb 2016      |          |                     |         |              |
|                                        |                                                                                                                                     |               | MSC |             |                 |     | -                |          |                     |         |              |
| CB091A<br><br>(980911)<br><br>Airframe | CB091A - Standard Practices (ATA 20) Inspection - Itt<br>Cannon Connectors                                                          |               | HRS |             | 3021.1          |     |                  | 25       |                     |         | 0            |
|                                        |                                                                                                                                     |               | AFL |             | 1108            |     | 9                |          | 0                   |         |              |
|                                        |                                                                                                                                     |               | MOS |             | 122.6           |     | 24 Feb 2016      |          |                     |         |              |
|                                        |                                                                                                                                     |               | MSC |             |                 |     | -                |          |                     |         |              |
| CB092<br><br>(980920)<br><br>Airframe  | CB092 - Nacelles and Pylons (ATA 54), Inspection -<br>Gearbox Breather Flex Boot Clamps                                             |               | HRS |             | 3033.8          |     |                  | 12.3     |                     |         | 0            |
|                                        |                                                                                                                                     |               | AFL |             | 1112            |     | 5                |          | 0                   |         |              |
|                                        |                                                                                                                                     |               | MOS |             | 124.2           |     | 05 Jan 2016      |          |                     |         |              |
|                                        |                                                                                                                                     |               | MSC |             |                 |     | -                |          |                     |         |              |
| CB093<br><br>(980930)<br><br>Airframe  | CB093 - Equipment and Furnishings (ATA 25),<br>Replacement - Flashlights (Oxley)                                                    |               | HRS |             | 3033.8          |     |                  | 12.3     |                     |         | 0            |
|                                        |                                                                                                                                     |               | AFL |             | 1112            |     | 5                |          | 0                   |         |              |
|                                        |                                                                                                                                     |               | MOS |             | 124.2           |     | 05 Jan 2016      |          |                     |         |              |
|                                        |                                                                                                                                     |               | MSC |             |                 |     | -                |          |                     |         |              |
| CB094<br><br>(980940)<br><br>Airframe  | CB094 - Ice and Rain Protection (ATA 30), Installation -<br>Windshield Heat Temperature Sensing Element Bonding<br>Jumper (ASC 067) |               | HRS |             | 3033.8          |     |                  | 12.3     |                     |         | 0            |
|                                        |                                                                                                                                     |               | AFL |             | 1112            |     | 5                |          | 0                   |         |              |
|                                        |                                                                                                                                     |               | MOS |             | 124.2           |     | 05 Jan 2016      |          |                     |         |              |
|                                        |                                                                                                                                     |               | MSC |             |                 |     | -                |          |                     |         |              |
| CB095<br><br>(980950)<br><br>Airframe  | CB095 - Water/Waste (ATA 38), Replacement - Water<br>Sterilizer Filters                                                             |               | HRS |             | 3033.8          |     |                  | 12.3     |                     |         | 0            |
|                                        |                                                                                                                                     |               | AFL |             | 1112            |     | 5                |          | 0                   |         |              |
|                                        |                                                                                                                                     |               | MOS |             | 124.2           |     | 05 Jan 2016      |          |                     |         |              |
|                                        |                                                                                                                                     |               | MSC |             |                 |     | -                |          |                     |         |              |
| CB096<br><br>(980960)<br><br>Airframe  | CB096 - Equipment and Furnishings (ATA 25), Inspection<br>- Velcro Installation Onupper Instrument Panel and<br>Glareshield         |               | HRS |             | 3033.8          |     |                  | 12.3     |                     |         | 0            |
|                                        |                                                                                                                                     |               | AFL |             | 1112            |     | 5                |          | 0                   |         |              |
|                                        |                                                                                                                                     |               | MOS |             | 124.2           |     | 05 Jan 2016      |          |                     |         |              |
|                                        |                                                                                                                                     |               | MSC |             |                 |     | -                |          |                     |         |              |

| ATA<br>U=Custom                       | Description                                                                                                          |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|---------------------------------------|----------------------------------------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                       | Part Number                                                                                                          | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position                      | HW                                                                                                                   | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                       | MM Ref                                                                                                               |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                                       | Ops Number(s)                                                                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| CB097<br><br>(980970)<br><br>Airframe | CB097 - Landing Gear (ATA 32), Inspection - Main<br>Landing Gear Door Stop Bolt Rigging                              |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                                       |                                                                                                                      |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                                       |                                                                                                                      |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         |              |
|                                       |                                                                                                                      |               | MSC |             |                 |     | -                |             |                    |         |              |
| CB098<br><br>(980980)<br><br>Airframe | CB098 - Ice and Rain Protection (ATA 30), Inspection -<br>Inlet Cowl Anti-Ice Pressure Sensing Line                  |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                                       |                                                                                                                      |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                                       |                                                                                                                      |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         |              |
|                                       |                                                                                                                      |               | MSC |             |                 |     | -                |             |                    |         |              |
| CB099<br><br>(980990)<br><br>Airframe | CB099 - Doors (ATA 52), Inspection - Main Entrance Door<br>(Med) Wiring Harness Routing                              |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                                       |                                                                                                                      |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                                       |                                                                                                                      |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         |              |
|                                       |                                                                                                                      |               | MSC |             |                 |     | -                |             |                    |         |              |
| CB100<br><br>(981000)<br><br>Airframe | CB100 - Doors (ATA 52), Inspection - Main Entrance Door<br>Damper Rigging                                            |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                                       |                                                                                                                      |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                                       |                                                                                                                      |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         |              |
|                                       |                                                                                                                      |               | MSC |             |                 |     | -                |             |                    |         |              |
| CB101<br><br>(981010)<br><br>Airframe | CB101 - Doors (ATA 52), Inspection - Auxiliary Pressure<br>Bulkhead Door Track                                       |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                                       |                                                                                                                      |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                                       |                                                                                                                      |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         |              |
|                                       |                                                                                                                      |               | MSC |             |                 |     | -                |             |                    |         |              |
| CB102<br><br>(981020)<br><br>Airframe | CB102 - Flight Controls (ATA 27), Modification - Flight<br>Control Computer (FCC) Software Upgrade 6.24 (ASC<br>037) |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                                       |                                                                                                                      |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                                       |                                                                                                                      |               | MOS |             | 123.8           |     |                  | 18 Jan 2016 |                    |         |              |
|                                       |                                                                                                                      |               | MSC |             |                 |     | -                |             |                    |         |              |
| CB103<br><br>(981030)<br><br>Airframe | CB103 - FIRE Protection (ATA 26), Inspection - Engine<br>FIRE Bottle Electrical Harness Routing                      |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                                       |                                                                                                                      |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                                       |                                                                                                                      |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         |              |
|                                       |                                                                                                                      |               | MSC |             |                 |     | -                |             |                    |         |              |

| ATA<br>U=Custom                        | Description                                                                                                                   |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|----------------------------------------|-------------------------------------------------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                        | Part Number                                                                                                                   | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position                       | HW                                                                                                                            | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                        | MM Ref                                                                                                                        |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                                        | Ops Number(s)                                                                                                                 |               |     |             |                 |     |                  |             |                    |         |              |
| CB104A<br><br>(981041)<br><br>Airframe | CB104A - Electrical Power (ATA 24), Modification - Uninterruptible Power Supply (UPS) Battery Upgrade                         |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                                        |                                                                                                                               |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                                        |                                                                                                                               |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         |              |
|                                        |                                                                                                                               |               | MSC |             |                 |     | -                |             |                    |         |              |
| CB105<br><br>(981050)<br><br>Airframe  | CB105 - Starting (ATA 80), Inspection - Starter AIR Valve (Rolls-Royce Nmsb BR700-80-900020)                                  |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                                        |                                                                                                                               |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                                        |                                                                                                                               |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         |              |
|                                        |                                                                                                                               |               | MSC |             |                 |     | -                |             |                    |         |              |
| CB106<br><br>(981060)<br><br>Airframe  | CB106 - Flight Controls (ATA 27), Inspection - Elevator Hinges for Paint Damage                                               |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                                        |                                                                                                                               |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                                        |                                                                                                                               |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         |              |
|                                        |                                                                                                                               |               | MSC |             |                 |     | -                |             |                    |         |              |
| CB107<br><br>(981070)<br><br>Airframe  | CB107 - Wings (ATA 57), Inspection - Inboard Wing Skins for Exposure of Shaved Fasteners (Triumph Sb MAA7-71258-08)           |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                        |                                                                                                                               |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                        |                                                                                                                               |               | MOS |             | 126.9           |     |                  | 14 Oct 2015 |                    |         |              |
|                                        |                                                                                                                               |               | MSC |             |                 |     | -                |             |                    |         |              |
| CB108<br><br>(981080)<br><br>Airframe  | CB108 - Engine Fuel and Control (ATA 73) Replacement - Engine Driven Fuel Pump V-Band Clamp (Rolls-Royce Sb -BR700-73-101929) |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                                        |                                                                                                                               |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                                        |                                                                                                                               |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         |              |
|                                        |                                                                                                                               |               | MSC |             |                 |     | -                |             |                    |         |              |
| CB109<br><br>(981090)<br><br>Airframe  | CB109 - Fuselage (ATA 53) Inspection - Aft Pressure Bulkhead Channel Beam Fasteners                                           |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                                        |                                                                                                                               |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                                        |                                                                                                                               |               | MOS |             | 124.2           |     |                  | 05 Jan 2016 |                    |         |              |
|                                        |                                                                                                                               |               | MSC |             |                 |     | -                |             |                    |         |              |
| CB110<br><br>(981100)<br><br>Airframe  | CB110 - Electrical Power (ATA 24) Inspection - Wire Harness to Support Bracket Contact                                        |               | HRS |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                                        |                                                                                                                               |               | AFL |             | 1112            |     |                  | 5           |                    |         | 0            |
|                                        |                                                                                                                               |               | MOS |             | 124             |     |                  | 11 Jan 2016 |                    |         |              |
|                                        |                                                                                                                               |               | MSC |             |                 |     | -                |             |                    |         |              |



| ATA<br>U=Custom  | Description                                                                                                                               |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-------------------------------------------------------------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                                                                               | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                                                                                        | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                                                                                    |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| CB111            | CB111 - Electrical Power (ATA 24) Inspection - Electrical Backup Hydraulic Actuator (Ebha) Distribution Box Power Cables                  |               | HRS |             | 3024.9          |     |                  | 21.2        |                    |         | 0            |
|                  |                                                                                                                                           |               | AFL |             | 1110            |     |                  | 7           |                    |         | 0            |
|                  |                                                                                                                                           |               | MOS |             | 123.7           |     |                  | 21 Jan 2016 |                    |         |              |
|                  |                                                                                                                                           |               | MSC |             |                 |     | -                |             |                    |         |              |
| (981110)         |                                                                                                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe         |                                                                                                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| CB112            | CB112 - Electrical Power (ATA 24) Inspection - Transformer Rectifier Unit (Tru) Electrical Connector Wiring                               |               | HRS |             | 3024.9          |     |                  | 21.2        |                    |         | 0            |
|                  |                                                                                                                                           |               | AFL |             | 1110            |     |                  | 7           |                    |         | 0            |
|                  |                                                                                                                                           |               | MOS |             | 123.5           |     |                  | 28 Jan 2016 |                    |         |              |
|                  |                                                                                                                                           |               | MSC |             |                 |     | -                |             |                    |         |              |
| (981120)         |                                                                                                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe         |                                                                                                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| CB113            | CB113 - Electrical Power (ATA 24) Inspection - Circuit Breaker Panel Electrical Harness Contact In Right Electronic Equipment Rack (Reer) |               | HRS |             | 3024.9          |     |                  | 21.2        |                    |         | 0            |
|                  |                                                                                                                                           |               | AFL |             | 1110            |     |                  | 7           |                    |         | 0            |
|                  |                                                                                                                                           |               | MOS |             | 123.5           |     |                  | 28 Jan 2016 |                    |         |              |
|                  |                                                                                                                                           |               | MSC |             |                 |     | -                |             |                    |         |              |
| (981130)         |                                                                                                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe         |                                                                                                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| CB114            | CB114 - Hydraulic Power (ATA 29) Inspection - Hydraulic Fittings AT Left Side Fuselage Station (FS) 739 Bulkhead                          |               | HRS |             | 3024.9          |     |                  | 21.2        |                    |         | 0            |
|                  |                                                                                                                                           |               | AFL |             | 1110            |     |                  | 7           |                    |         | 0            |
|                  |                                                                                                                                           |               | MOS |             | 123.5           |     |                  | 28 Jan 2016 |                    |         |              |
|                  |                                                                                                                                           |               | MSC |             |                 |     | -                |             |                    |         |              |
| (981140)         |                                                                                                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe         |                                                                                                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| CB115            | CB115 - Doors (ATA 52) - Replacement - Main Entrance Door Handrail Hardware                                                               |               | HRS |             | 3021.1          |     |                  | 25          |                    |         | 0            |
|                  |                                                                                                                                           |               | AFL |             | 1108            |     |                  | 9           |                    |         | 0            |
|                  |                                                                                                                                           |               | MOS |             | 122.6           |     |                  | 24 Feb 2016 |                    |         |              |
|                  |                                                                                                                                           |               | MSC |             |                 |     | -                |             |                    |         |              |
| (981150)         |                                                                                                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe         |                                                                                                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| CB116            | CB116 - Water/Waste (ATA 38) Inspection - Water System Tank Drain Hose Contact on Water Tank Shelf Support                                |               | HRS |             | 3021.1          |     |                  | 25          |                    |         | 0            |
|                  |                                                                                                                                           |               | AFL |             | 1108            |     |                  | 9           |                    |         | 0            |
|                  |                                                                                                                                           |               | MOS |             | 122.6           |     |                  | 24 Feb 2016 |                    |         |              |
|                  |                                                                                                                                           |               | MSC |             |                 |     | -                |             |                    |         |              |
| (981160)         |                                                                                                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe         |                                                                                                                                           |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                                | Serial Number |     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                         | SW            |     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                     |               |     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                              |               |     |             |                 |     |                  |             |                     |         |              |
| CB117            | CB117 - Water / Waste (ATA 38) Inspection - Water Tank     |               | HRS |             | 3021.1          |     |                  | 25          |                     |         | 0            |
|                  | Electrical Harness Installation                            |               | AFL |             | 1108            |     |                  | 9           |                     |         | 0            |
|                  |                                                            |               | MOS |             | 122.6           |     |                  | 24 Feb 2016 |                     |         |              |
|                  |                                                            |               | MSC |             |                 |     | -                |             |                     |         |              |
| (981170)         |                                                            |               |     |             |                 |     |                  |             |                     |         |              |
| Airframe         |                                                            |               |     |             |                 |     |                  |             |                     |         |              |
| CB118            | CB118 - Powerplant (ATA 71) Replacement - Engine           |               | HRS |             | 3021.1          |     |                  | 25          |                     |         | 0            |
|                  | Driven Hydraulic Pump V-Band Clamp (Rolls-Royce Sb-        |               | AFL |             | 1108            |     |                  | 9           |                     |         | 0            |
|                  | BR700-71-101928)                                           |               | MOS |             | 122.6           |     |                  | 24 Feb 2016 |                     |         |              |
|                  |                                                            |               | MSC |             |                 |     | -                |             |                     |         |              |
| (981180)         |                                                            |               |     |             |                 |     |                  |             |                     |         |              |
| Airframe         |                                                            |               |     |             |                 |     |                  |             |                     |         |              |
| CB119            | CB119 - Wings (ATA 57) Installation Add Drain Hole In      |               | HRS |             | 3021.1          |     |                  | 25          |                     |         | 0            |
|                  | Fixed Trailing Edge Lower Skin (Triumph Sb MAA7-71258      |               | AFL |             | 1108            |     |                  | 9           |                     |         | 0            |
|                  | -10)                                                       |               | MOS |             | 122.6           |     |                  | 24 Feb 2016 |                     |         |              |
|                  |                                                            |               | MSC |             |                 |     | -                |             |                     |         |              |
| (981190)         |                                                            |               |     |             |                 |     |                  |             |                     |         |              |
| Airframe         |                                                            |               |     |             |                 |     |                  |             |                     |         |              |
| CB120            | CB120 - FIRE Protection (ATA 26) Inspection - Engine /     |               | HRS |             | 3021.1          |     |                  | 25          |                     |         | 0            |
|                  | Auxiliary Power Unit (APU) FIRE Bottle Thermal Relief      |               | AFL |             | 1108            |     |                  | 9           |                     |         | 0            |
|                  | Discharge Port                                             |               | MOS |             | 122.6           |     |                  | 24 Feb 2016 |                     |         |              |
|                  |                                                            |               | MSC |             |                 |     | -                |             |                     |         |              |
| (981200)         |                                                            |               |     |             |                 |     |                  |             |                     |         |              |
| Airframe         |                                                            |               |     |             |                 |     |                  |             |                     |         |              |
| CB121            | CB121 - Flight Controls (ATA 27), Inspection - Flap Torque |               | HRS |             | 3021.1          |     |                  | 25          |                     |         | 0            |
|                  | Shafts Hardware                                            |               | AFL |             | 1108            |     |                  | 9           |                     |         | 0            |
|                  |                                                            |               | MOS |             | 122.6           |     |                  | 24 Feb 2016 |                     |         |              |
|                  |                                                            |               | MSC |             |                 |     | -                |             |                     |         |              |
| (981210)         |                                                            |               |     |             |                 |     |                  |             |                     |         |              |
| Airframe         |                                                            |               |     |             |                 |     |                  |             |                     |         |              |
| CB122            | CB122 - Electrical Power (ATA 24), Inspection - Ram AIR    |               | HRS |             | 3021.1          |     |                  | 25          |                     |         | 0            |
|                  | Turbine (RAT) Electrical Harness Missing Overbraid         |               | AFL |             | 1108            |     |                  | 9           |                     |         | 0            |
|                  | Ground                                                     |               | MOS |             | 122.5           |     |                  | 25 Feb 2016 |                     |         |              |
|                  |                                                            |               | MSC |             |                 |     | -                |             |                     |         |              |
| (981220)         |                                                            |               |     |             |                 |     |                  |             |                     |         |              |
| Airframe         |                                                            |               |     |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom                                                        | Description                                                                                                                        |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                                                        | Part Number                                                                                                                        | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position                                                       | HW                                                                                                                                 | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                                                        | MM Ref                                                                                                                             |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                                                                        | Ops Number(s)                                                                                                                      |               |     |             |                 |     |                  |             |                    |         |              |
| CB123                                                                  | CB123 - Electrical Power (ATA 24) Inspection Hydraulic System Manifolds Wiring Installation                                        |               | HRS |             | 3021.1          |     |                  | 25          |                    |         | 0            |
|                                                                        |                                                                                                                                    |               | AFL |             | 1108            |     |                  | 9           |                    | 0       |              |
|                                                                        |                                                                                                                                    |               | MOS |             | 122.5           |     |                  | 25 Feb 2016 |                    |         |              |
|                                                                        |                                                                                                                                    |               | MSC |             |                 |     | -                |             |                    |         |              |
| (981230)                                                               |                                                                                                                                    |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                                                               |                                                                                                                                    |               |     |             |                 |     |                  |             |                    |         |              |
| CB124                                                                  | CB124 - Electrical Power (ATA 24) Inspection Electrical Harness AT Fuselage Station 321 Below Floors                               |               | HRS |             | 3021.1          |     |                  | 25          |                    |         | 0            |
|                                                                        |                                                                                                                                    |               | AFL |             | 1108            |     |                  | 9           |                    | 0       |              |
|                                                                        |                                                                                                                                    |               | MOS |             | 122.5           |     |                  | 25 Feb 2016 |                    |         |              |
|                                                                        |                                                                                                                                    |               | MSC |             |                 |     | -                |             |                    |         |              |
| (981240)                                                               |                                                                                                                                    |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                                                               |                                                                                                                                    |               |     |             |                 |     |                  |             |                    |         |              |
| CB125                                                                  | CB125 - Fuselage (ATA 53), Inspection - Baggage Compartment Forward Electronic Equipment Rack for Contact With Fuselage Structure  |               | HRS |             | 3018.9          |     |                  | 27.2        |                    |         | 0            |
|                                                                        |                                                                                                                                    |               | AFL |             | 1107            |     |                  | 10          |                    | 0       |              |
|                                                                        |                                                                                                                                    |               | MOS |             | 122.2           |     |                  | 05 Mar 2016 |                    |         |              |
|                                                                        |                                                                                                                                    |               | MSC |             |                 |     | -                |             |                    |         |              |
| (981250)                                                               |                                                                                                                                    |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                                                               |                                                                                                                                    |               |     |             |                 |     |                  |             |                    |         |              |
| CB126                                                                  | CB126 - Powerplant (ATA 71), Replacement - Engine Driven Hydraulic Pump Depressurization Valve Connector                           |               | HRS |             | 2762.2          |     |                  | 283.9       |                    |         | 0            |
|                                                                        |                                                                                                                                    |               | AFL |             | 1041            |     |                  | 76          |                    | 0       |              |
|                                                                        |                                                                                                                                    |               | MOS |             | 112.8           |     |                  | 16 Dec 2016 |                    |         |              |
|                                                                        |                                                                                                                                    |               | MSC |             |                 |     | -                |             |                    |         |              |
| (981260)                                                               |                                                                                                                                    |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                                                               |                                                                                                                                    |               |     |             |                 |     |                  |             |                    |         |              |
| CB126A                                                                 | CB126A - Powerplant (ATA 71), Replacement - Engine Driven Hydraulic Pump Depressurization Valve Connector                          |               | HRS |             | 2680.9          |     |                  | 365.2       |                    |         | 0            |
|                                                                        |                                                                                                                                    |               | AFL |             | 1022            |     |                  | 95          |                    | 0       |              |
|                                                                        |                                                                                                                                    |               | MOS |             | 110.3           |     |                  | 03 Mar 2017 |                    |         |              |
|                                                                        |                                                                                                                                    |               | MSC |             |                 |     | -                |             |                    |         |              |
| (981261)                                                               |                                                                                                                                    |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                                                               |                                                                                                                                    |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: PREVIOUSLY COMPLIED WITH CB126 ON 16-DEC-2016 @ 283.9 FH, 76 FC |                                                                                                                                    |               |     |             |                 |     |                  |             |                    |         |              |
| CB127                                                                  | CB127 - Powerplant (ATA 71), Inspection - Right Engine General Services Harness Installation (Rolls-Royce Nmsb Sb-BR700-71-900578) |               | HRS |             | 3014.9          |     |                  | 31.2        |                    |         | 0            |
|                                                                        |                                                                                                                                    |               | AFL |             | 1106            |     |                  | 11          |                    | 0       |              |
|                                                                        |                                                                                                                                    |               | MOS |             | 122             |     |                  | 10 Mar 2016 |                    |         |              |
|                                                                        |                                                                                                                                    |               | MSC |             |                 |     | -                |             |                    |         |              |
| (981270)                                                               |                                                                                                                                    |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                                                               |                                                                                                                                    |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom                                                                            | Description                                             |               | UOM  | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|--------------------------------------------------------------------------------------------|---------------------------------------------------------|---------------|------|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                                                                                            | Part Number                                             | Serial Number |      |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position                                                                           | HW                                                      | SW            |      |             |                 |     |                  |             |                     |         | Manufacturer |
|                                                                                            | MM Ref                                                  |               |      |             |                 |     |                  |             |                     |         | Date Type    |
|                                                                                            | Ops Number(s)                                           |               |      |             |                 |     |                  |             |                     |         |              |
| CB135                                                                                      | CB135 - Doors (ATA 52), Replacement - Main Entrance     |               | HRS  |             | 2762.2          |     |                  | 283.9       |                     |         | 0            |
|                                                                                            | Door Bottom Folding Step Link Assembly, P/N             |               | AFL  |             | 1041            |     |                  | 76          |                     |         | 0            |
|                                                                                            | 60P5260000A004                                          |               | MOS  |             | 113             |     |                  | 12 Dec 2016 |                     |         |              |
|                                                                                            |                                                         |               | MSC  |             |                 |     | -                |             |                     |         |              |
| (981350)                                                                                   |                                                         |               |      |             |                 |     |                  |             |                     |         |              |
| Airframe                                                                                   |                                                         |               |      |             |                 |     |                  |             |                     |         |              |
| CB138                                                                                      | CB138 - Engine (ATA 72), Inspection - Accessory Gearbox |               | HRS  |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                                                                                            | Radial Drive Shaft Seal (Rolls-Royce Sb-BR700-72-       |               | AFL  |             | 1117            |     |                  | 0           |                     |         | 0            |
|                                                                                            | 900589)                                                 |               | MOS  |             | 120.5           |     |                  | 27 Apr 2016 |                     |         |              |
|                                                                                            |                                                         |               | MSC  |             |                 |     | -                |             |                     |         |              |
| (981380)                                                                                   |                                                         |               |      |             |                 |     |                  |             |                     |         |              |
| Airframe                                                                                   |                                                         |               |      |             |                 |     |                  |             |                     |         |              |
| Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK. |                                                         |               |      |             |                 |     |                  |             |                     |         |              |
| CB138A                                                                                     | CB138A - Engine (ATA 72) - Inspection - Accessory       |               | HRS  |             | 2658.1          |     |                  | 388         |                     |         | 0            |
|                                                                                            | Gearbox Radial Drive Shaft Seal(Rolls-Royce Nmsb Sb-    |               | AFL  |             | 1015            |     |                  | 102         |                     |         | 0            |
|                                                                                            | BR700-72-900589)                                        |               | MOS  |             | 107.6           |     |                  | 22 May 2017 |                     |         |              |
|                                                                                            |                                                         |               | MSC  |             |                 |     | -                |             |                     |         |              |
| (981381)                                                                                   |                                                         |               |      |             |                 |     |                  |             |                     |         |              |
| Airframe                                                                                   |                                                         |               |      |             |                 |     |                  |             |                     |         |              |
| CB142                                                                                      | CB142 - Fuel (ATA 28), Replacement - Pressure Fueling   |               | HRS  |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                                                                                            | Shut-Off Valves, P/N L94-51-602, With P/N L94-51-603    |               | AFL  |             | 1117            |     |                  | 0           |                     |         | 0            |
|                                                                                            |                                                         |               | MOS  |             | 90.8            |     |                  | 17 Oct 2018 |                     |         |              |
|                                                                                            |                                                         |               | MSC  |             |                 |     | -                |             |                     |         |              |
| (981420)                                                                                   |                                                         |               |      |             |                 |     |                  |             |                     |         |              |
| Airframe                                                                                   |                                                         |               |      |             |                 |     |                  |             |                     |         |              |
| Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK. |                                                         |               |      |             |                 |     |                  |             |                     |         |              |
| CB142A                                                                                     | CB142A - Fuel (ATA 28) - Replacement - Pressure Fueling |               | HRS  |             | 3046.1          |     |                  | 0           | 0                   |         | 0            |
|                                                                                            | Shut-Off Valves, P/N L94-51-602, With P/N L94-51-603    |               | AFL  |             | 1117            |     |                  | 0           | 0                   |         | 0            |
|                                                                                            |                                                         |               | MOS  |             | 79.1            |     |                  | 09 Oct 2019 |                     |         |              |
|                                                                                            |                                                         |               | MSC  |             |                 |     | -                |             |                     |         |              |
| (981421)                                                                                   |                                                         |               |      |             |                 |     |                  |             |                     |         |              |
| Airframe                                                                                   |                                                         |               |      |             |                 |     |                  |             |                     |         |              |
| Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK. |                                                         |               |      |             |                 |     |                  |             |                     |         |              |
| CB142B                                                                                     | CB142B - Fuel (ATA 28) - Replacement - Pressure         |               | HRS  |             | 3046.1          |     |                  | 0           | 0                   |         | 0            |
|                                                                                            | Fueling Shut-Off Valves, P/N L94-51-602, With P/N L94-  |               | AFL  |             | 1117            |     |                  | 0           | 0                   |         | 0            |
|                                                                                            | 51-603                                                  |               | DATE |             |                 |     |                  |             |                     |         |              |
|                                                                                            |                                                         |               | MSC  |             |                 |     | -                |             |                     |         |              |
| (981422)                                                                                   |                                                         |               |      |             |                 |     |                  |             |                     |         |              |
| Airframe                                                                                   |                                                         |               |      |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom                                                                            | Description                                                                                                         |               | UOM  | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|--------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------|---------------|------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                                                                            | Part Number                                                                                                         | Serial Number |      |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position                                                                           | HW                                                                                                                  | SW            |      |             |                 |     |                  |             |                    |         | Manufacturer |
|                                                                                            | MM Ref                                                                                                              |               |      |             |                 |     |                  |             |                    |         | Date Type    |
|                                                                                            | Ops Number(s)                                                                                                       |               |      |             |                 |     |                  |             |                    |         |              |
| CB142C                                                                                     | CB142C - Fuel (ATA 28) - Replacement - Pressure<br>Fueling Shut-Off Valves, P/N L94-51-602, With P/N L94-<br>51-603 |               | HRS  |             |                 |     |                  |             |                    |         | 0            |
|                                                                                            |                                                                                                                     |               | AFL  |             |                 |     |                  |             |                    |         | 0            |
|                                                                                            |                                                                                                                     |               | DATE |             |                 |     |                  |             |                    |         |              |
|                                                                                            |                                                                                                                     |               | MSC  |             |                 |     | -                |             |                    |         |              |
| (981423)                                                                                   |                                                                                                                     |               |      |             |                 |     |                  |             |                    |         |              |
| Airframe                                                                                   |                                                                                                                     |               |      |             |                 |     |                  |             |                    |         |              |
| CB143                                                                                      | CB143 - Landing Gear (ATA 32) - Modification - Landing<br>Gear Control Unit (Lgcu) MOD D Update (ASC 079)           |               | HRS  |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                                                     |               | AFL  |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                                                     |               | MOS  |             | 120             |     |                  | 10 May 2016 |                    |         |              |
|                                                                                            |                                                                                                                     |               | MSC  |             |                 |     | -                |             |                    |         |              |
| (981430)                                                                                   |                                                                                                                     |               |      |             |                 |     |                  |             |                    |         |              |
| Airframe                                                                                   |                                                                                                                     |               |      |             |                 |     |                  |             |                    |         |              |
| Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK. |                                                                                                                     |               |      |             |                 |     |                  |             |                    |         |              |
| CB143A                                                                                     | CB143A - Landing Gear (ATA 32) - Modification Landing<br>Gear Control Unit (Lgcu) MOD D Update (ASC 079)            |               | HRS  |             | 2345.1          |     |                  | 701         |                    |         | 0            |
|                                                                                            |                                                                                                                     |               | AFL  |             | 936             |     |                  | 181         |                    |         | 0            |
|                                                                                            |                                                                                                                     |               | MOS  |             | 97.1            |     |                  | 09 Apr 2018 |                    |         |              |
|                                                                                            |                                                                                                                     |               | MSC  |             |                 |     | -                |             |                    |         |              |
| (981431)                                                                                   |                                                                                                                     |               |      |             |                 |     |                  |             |                    |         |              |
| Airframe                                                                                   |                                                                                                                     |               |      |             |                 |     |                  |             |                    |         |              |
| CB144                                                                                      | CB144 - Fuselage Structure (ATA 53) - Inspection -<br>Cockpit Windshield and Side Window Frame Corrosion            |               | HRS  |             | 2673.9          |     |                  | 372.2       |                    |         | 0            |
|                                                                                            |                                                                                                                     |               | AFL  |             | 1020            |     |                  | 97          |                    |         | 0            |
|                                                                                            |                                                                                                                     |               | MOS  |             | 111.2           |     |                  | 04 Feb 2017 |                    |         |              |
|                                                                                            |                                                                                                                     |               | MSC  |             |                 |     | -                |             |                    |         |              |
| (981440)                                                                                   |                                                                                                                     |               |      |             |                 |     |                  |             |                    |         |              |
| Airframe                                                                                   |                                                                                                                     |               |      |             |                 |     |                  |             |                    |         |              |
| CB152                                                                                      | CB152 - Stabilizers (ATA 55) Inspection - Horizontal<br>Stabilizer Inboard Leading Edge Seal Installation           |               | HRS  |             | 2673.8          |     |                  | 372.3       |                    |         | 0            |
|                                                                                            |                                                                                                                     |               | AFL  |             | 1020            |     |                  | 97          |                    |         | 0            |
|                                                                                            |                                                                                                                     |               | MOS  |             | 109.6           |     |                  | 23 Mar 2017 |                    |         |              |
|                                                                                            |                                                                                                                     |               | MSC  |             |                 |     | -                |             |                    |         |              |
| (981520)                                                                                   |                                                                                                                     |               |      |             |                 |     |                  |             |                    |         |              |
| Airframe                                                                                   |                                                                                                                     |               |      |             |                 |     |                  |             |                    |         |              |
| CB155                                                                                      | CB155 - Landing Gear (ATA 32), Modification - Main<br>Landing Gear and Brake Assembly (ASC 084)                     |               | HRS  |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                                                     |               | AFL  |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                                                     |               | MOS  |             | 116.7           |     |                  | 19 Aug 2016 |                    |         |              |
|                                                                                            |                                                                                                                     |               | MSC  |             |                 |     | -                |             |                    |         |              |
| (981550)                                                                                   |                                                                                                                     |               |      |             |                 |     |                  |             |                    |         |              |
| Airframe                                                                                   |                                                                                                                     |               |      |             |                 |     |                  |             |                    |         |              |
| Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK. |                                                                                                                     |               |      |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom                                                                            | Description                                                                                                                             |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|--------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|----------|--------------------|---------|--------------|
|                                                                                            | Part Number                                                                                                                             | Serial Number |     |             |                 |     |                  |          |                    |         | Approx Price |
| Logbook Position                                                                           | HW                                                                                                                                      | SW            |     |             |                 |     |                  |          |                    |         | Manufacturer |
|                                                                                            | MM Ref                                                                                                                                  |               |     |             |                 |     |                  |          |                    |         | Date Type    |
|                                                                                            | Ops Number(s)                                                                                                                           |               |     |             |                 |     |                  |          |                    |         |              |
| CB155A                                                                                     | CB155A - Landing Gear (ATA 32) - Modification - Main<br>Landing Gear and Brake Assembly (ASC 084A)                                      |               | HRS |             | 2673.8          |     |                  | 372.3    |                    | 0       |              |
|                                                                                            |                                                                                                                                         |               | AFL |             | 1020            |     | 97               |          | 0                  |         |              |
|                                                                                            |                                                                                                                                         |               | MOS |             | 109.5           |     | 28 Mar 2017      |          |                    |         |              |
|                                                                                            |                                                                                                                                         |               | MSC |             |                 | -   |                  |          |                    |         |              |
| (981551)                                                                                   |                                                                                                                                         |               |     |             |                 |     |                  |          |                    |         |              |
| Airframe                                                                                   |                                                                                                                                         |               |     |             |                 |     |                  |          |                    |         |              |
| CB155B                                                                                     | CB155B - Landing Gear (ATA 32), Modification - Main<br>Landing Gear and Brake Assembly (ASC 084A)                                       |               | HRS |             | 2601.1          |     |                  | 445      |                    | 0       |              |
|                                                                                            |                                                                                                                                         |               | AFL |             | 996             |     | 121              |          | 0                  |         |              |
|                                                                                            |                                                                                                                                         |               | MOS |             | 105             |     | 11 Aug 2017      |          |                    |         |              |
|                                                                                            |                                                                                                                                         |               | MSC |             |                 | -   |                  |          |                    |         |              |
| (981552)                                                                                   |                                                                                                                                         |               |     |             |                 |     |                  |          |                    |         |              |
| Airframe                                                                                   |                                                                                                                                         |               |     |             |                 |     |                  |          |                    |         |              |
| Notes: PREVIOUSLY COMPLIED WITH CB155A                                                     |                                                                                                                                         |               |     |             |                 |     |                  |          |                    |         |              |
| CB158                                                                                      | CB158 - Landing Gear (ATA 32), Modification - Tire<br>Pressure Monitoring Unit (Tpmu) Software Upgrade                                  |               | HRS |             | 2673.8          |     |                  | 372.3    |                    | 0       |              |
|                                                                                            |                                                                                                                                         |               | AFL |             | 1020            |     | 97               |          | 0                  |         |              |
|                                                                                            |                                                                                                                                         |               | MOS |             | 109.7           |     | 21 Mar 2017      |          |                    |         |              |
|                                                                                            |                                                                                                                                         |               | MSC |             |                 | -   |                  |          |                    |         |              |
| (981580)                                                                                   |                                                                                                                                         |               |     |             |                 |     |                  |          |                    |         |              |
| Airframe                                                                                   |                                                                                                                                         |               |     |             |                 |     |                  |          |                    |         |              |
| CB160                                                                                      | CB160 - Engine and Fuel Control (ATA 73), Modification -<br>Engine Electronic Controller (Eec) - K7.1.3 Software<br>Upgrade (ASC 016)   |               | HRS |             | 3046.1          |     |                  | 0        |                    | 0       |              |
|                                                                                            |                                                                                                                                         |               | AFL |             | 1117            |     | 0                |          | 0                  |         |              |
|                                                                                            |                                                                                                                                         |               | MOS |             | 104.9           |     | 15 Aug 2017      |          |                    |         |              |
|                                                                                            |                                                                                                                                         |               | MSC |             |                 | -   |                  |          |                    |         |              |
| (981600)                                                                                   |                                                                                                                                         |               |     |             |                 |     |                  |          |                    |         |              |
| Airframe                                                                                   |                                                                                                                                         |               |     |             |                 |     |                  |          |                    |         |              |
| Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK. |                                                                                                                                         |               |     |             |                 |     |                  |          |                    |         |              |
| CB160A                                                                                     | CB160A - Engine and Fuel Control (ATA 73), Modification<br>- Engine Electronic Controller (Eec) - K7.1.3 Software<br>Upgrade (ASC 016)  |               | HRS |             | 2413.3          |     |                  | 632.8    |                    | 0       |              |
|                                                                                            |                                                                                                                                         |               | AFL |             | 949             |     | 168              |          | 0                  |         |              |
|                                                                                            |                                                                                                                                         |               | MOS |             | 98.7            |     | 20 Feb 2018      |          |                    |         |              |
|                                                                                            |                                                                                                                                         |               | MSC |             |                 | -   |                  |          |                    |         |              |
| (981601)                                                                                   |                                                                                                                                         |               |     |             |                 |     |                  |          |                    |         |              |
| Airframe                                                                                   |                                                                                                                                         |               |     |             |                 |     |                  |          |                    |         |              |
| CB161                                                                                      | CB161 - Engine and Fuel Control (ATA 73), Modification -<br>Replacement of Fuel Low Pressure Switch (Rolls-Royce<br>Sb-BR700-73-101965) |               | HRS |             | 2413.8          |     |                  | 632.3    |                    | 0       |              |
|                                                                                            |                                                                                                                                         |               | AFL |             | 949             |     | 168              |          | 0                  |         |              |
|                                                                                            |                                                                                                                                         |               | MOS |             | 98.6            |     | 22 Feb 2018      |          |                    |         |              |
|                                                                                            |                                                                                                                                         |               | MSC |             |                 | -   |                  |          |                    |         |              |
| (981610)                                                                                   |                                                                                                                                         |               |     |             |                 |     |                  |          |                    |         |              |
| Airframe                                                                                   |                                                                                                                                         |               |     |             |                 |     |                  |          |                    |         |              |

| ATA<br>U=Custom                                                                            | Description                                                                                                                 |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|--------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                                                                            | Part Number                                                                                                                 | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position                                                                           | HW                                                                                                                          | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                                                                            | MM Ref                                                                                                                      |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                                                                                            | Ops Number(s)                                                                                                               |               |     |             |                 |     |                  |             |                    |         |              |
| CB162                                                                                      | CB162 - Engine and Fuel Control (ATA 73), Modification - Revised Fuel System (Rolls-Royce Sb-BR700-73-101957)               |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                                                             |               | AFL |             | 1117            |     |                  | 0           |                    | 0       |              |
|                                                                                            |                                                                                                                             |               | MOS |             | 104.9           |     |                  | 15 Aug 2017 |                    |         |              |
|                                                                                            |                                                                                                                             |               | MSC |             |                 |     | -                |             |                    |         |              |
| (981620)                                                                                   |                                                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                                                                                   |                                                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK. |                                                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| CB166                                                                                      | CB166 - Electrical Power (ATA 24) - Modification - Secondary Power - Distribution System (Spds) Software - Update (ASC 051) |               | HRS |             | 2673.8          |     |                  | 372.3       |                    |         | 0            |
|                                                                                            |                                                                                                                             |               | AFL |             | 1020            |     |                  | 97          |                    | 0       |              |
|                                                                                            |                                                                                                                             |               | MOS |             | 109.4           |     |                  | 31 Mar 2017 |                    |         |              |
|                                                                                            |                                                                                                                             |               | MSC |             |                 |     | -                |             |                    |         |              |
| (981660)                                                                                   |                                                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                                                                                   |                                                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| CB166A                                                                                     | CB166A - Electrical Power (ATA 24) - Modification - Secondary Power Distribution System (Spds) Software Update (ASC 051)    |               | HRS |             | 2342.8          |     |                  | 703.3       |                    |         | 0            |
|                                                                                            |                                                                                                                             |               | AFL |             | 933             |     |                  | 184         |                    | 0       |              |
|                                                                                            |                                                                                                                             |               | MOS |             | 95.8            |     |                  | 16 May 2018 |                    |         |              |
|                                                                                            |                                                                                                                             |               | MSC |             |                 |     | -                |             |                    |         |              |
| (981661)                                                                                   |                                                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                                                                                   |                                                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: NO FURTHER ACTION REQ"D DUE PCW CB 166 AND ASC051A REQUIREMENTS ARE SATISFIED       |                                                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| CB168                                                                                      | CB168 - Doors (ATA 52), Inspection - Main Entrance Door Handrail Drive Fittings                                             |               | HRS |             | 2762.2          |     |                  | 283.9       |                    |         | 0            |
|                                                                                            |                                                                                                                             |               | AFL |             | 1041            |     |                  | 76          |                    | 0       |              |
|                                                                                            |                                                                                                                             |               | MOS |             | 113             |     |                  | 12 Dec 2016 |                    |         |              |
|                                                                                            |                                                                                                                             |               | MSC |             |                 |     | -                |             |                    |         |              |
| (981680)                                                                                   |                                                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                                                                                   |                                                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| CB169                                                                                      | CB169 - Equipment / Furnishings (ATA 25) Modification - Forward Left Side Lavatory Wiring Installation                      |               | HRS |             | 2345.1          |     |                  | 701         |                    |         | 0            |
|                                                                                            |                                                                                                                             |               | AFL |             | 936             |     |                  | 181         |                    | 0       |              |
|                                                                                            |                                                                                                                             |               | MOS |             | 97              |     |                  | 12 Apr 2018 |                    |         |              |
|                                                                                            |                                                                                                                             |               | MSC |             |                 |     | -                |             |                    |         |              |
| (981690)                                                                                   |                                                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                                                                                   |                                                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| CB169A                                                                                     | CB169A - Equipment / Furnishings (ATA 25) - Modification - Forward Left Side Lavatory Wiring Installation                   |               | HRS |             | 2324.9          |     |                  | 721.2       |                    |         | 0            |
|                                                                                            |                                                                                                                             |               | AFL |             | 929             |     |                  | 188         |                    | 0       |              |
|                                                                                            |                                                                                                                             |               | MOS |             | 94.7            |     |                  | 21 Jun 2018 |                    |         |              |
|                                                                                            |                                                                                                                             |               | MSC |             |                 |     | -                |             |                    |         |              |
| (981691)                                                                                   |                                                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                                                                                   |                                                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: PCW CB169                                                                           |                                                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom                                                                            | Description                                                                                                                          |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|--------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                                                                            | Part Number                                                                                                                          | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position                                                                           | HW                                                                                                                                   | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                                                                            | MM Ref                                                                                                                               |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                                                                                            | Ops Number(s)                                                                                                                        |               |     |             |                 |     |                  |             |                    |         |              |
| CB170                                                                                      | CB170 - Water / Waste (ATA 38), Modification - Removal of Water Sterilizer Filter End CAP SET Screw (lwg-A6 Vendor Service Bulletin) |               | HRS |             | 2673.8          |     |                  | 372.3       |                    |         | 0            |
|                                                                                            |                                                                                                                                      |               | AFL |             | 1020            |     |                  | 97          |                    |         | 0            |
|                                                                                            |                                                                                                                                      |               | MOS |             | 109.7           |     |                  | 21 Mar 2017 |                    |         |              |
|                                                                                            |                                                                                                                                      |               | MSC |             |                 |     | -                |             |                    |         |              |
| (981700)                                                                                   |                                                                                                                                      |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                                                                                   |                                                                                                                                      |               |     |             |                 |     |                  |             |                    |         |              |
| CB171                                                                                      | CB171 - Electrical Power (ATA 24), Inspection - Main Battery Ground Pads                                                             |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                                                                      |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                                                                      |               | MOS |             | 111.5           |     |                  | 26 Jan 2017 |                    |         |              |
|                                                                                            |                                                                                                                                      |               | MSC |             |                 |     | -                |             |                    |         |              |
| (981710)                                                                                   |                                                                                                                                      |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                                                                                   |                                                                                                                                      |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK. |                                                                                                                                      |               |     |             |                 |     |                  |             |                    |         |              |
| CB171A                                                                                     | CB171A - Electrical Power (ATA 24) - Inspection - Main Battery Ground Pads                                                           |               | HRS |             | 2673.8          |     |                  | 372.3       |                    |         | 0            |
|                                                                                            |                                                                                                                                      |               | AFL |             | 1020            |     |                  | 97          |                    |         | 0            |
|                                                                                            |                                                                                                                                      |               | MOS |             | 109.7           |     |                  | 21 Mar 2017 |                    |         |              |
|                                                                                            |                                                                                                                                      |               | MSC |             |                 |     | -                |             |                    |         |              |
| (981711)                                                                                   |                                                                                                                                      |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                                                                                   |                                                                                                                                      |               |     |             |                 |     |                  |             |                    |         |              |
| CB172                                                                                      | CB172 - Doors (ATA 52), Replacement - Main Entrance Door - Bottom Folding Step Stop Bolts (ASC 089)                                  |               | HRS |             | 2673.8          |     |                  | 372.3       |                    |         | 0            |
|                                                                                            |                                                                                                                                      |               | AFL |             | 1020            |     |                  | 97          |                    |         | 0            |
|                                                                                            |                                                                                                                                      |               | MOS |             | 109.4           |     |                  | 29 Mar 2017 |                    |         |              |
|                                                                                            |                                                                                                                                      |               | MSC |             |                 |     | -                |             |                    |         |              |
| (981720)                                                                                   |                                                                                                                                      |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                                                                                   |                                                                                                                                      |               |     |             |                 |     |                  |             |                    |         |              |
| CB174                                                                                      | CB174 - Flight Controls (ATA 27) - Inspection - Horizontal Stabilizer Trim Actuator Harness                                          |               | HRS |             | 2673.8          |     |                  | 372.3       |                    |         | 0            |
|                                                                                            |                                                                                                                                      |               | AFL |             | 1020            |     |                  | 97          |                    |         | 0            |
|                                                                                            |                                                                                                                                      |               | MOS |             | 109.6           |     |                  | 23 Mar 2017 |                    |         |              |
|                                                                                            |                                                                                                                                      |               | MSC |             |                 |     | -                |             |                    |         |              |
| (981740)                                                                                   |                                                                                                                                      |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                                                                                   |                                                                                                                                      |               |     |             |                 |     |                  |             |                    |         |              |
| CB175                                                                                      | CB175 - Electrical Power (ATA 24), Replacement Ram AIR Turbine (RAT) Control Handle Lockout Pin                                      |               | HRS |             | 2673.8          |     |                  | 372.3       |                    |         | 0            |
|                                                                                            |                                                                                                                                      |               | AFL |             | 1020            |     |                  | 97          |                    |         | 0            |
|                                                                                            |                                                                                                                                      |               | MOS |             | 109.7           |     |                  | 21 Mar 2017 |                    |         |              |
|                                                                                            |                                                                                                                                      |               | MSC |             |                 |     | -                |             |                    |         |              |
| (981750)                                                                                   |                                                                                                                                      |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                                                                                   |                                                                                                                                      |               |     |             |                 |     |                  |             |                    |         |              |



| ATA<br>U=Custom                              | Description                                                                                                                                  |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|----------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                              | Part Number                                                                                                                                  | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position                             | HW                                                                                                                                           | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                              | MM Ref                                                                                                                                       |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                                              | Ops Number(s)                                                                                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| CB176                                        | CB176 - Doors (ATA 52), Replacement - Main Entrance Door Handrail Drive Fittings                                                             |               | HRS |             | 2345.1          |     |                  | 701         |                    |         | 0            |
|                                              |                                                                                                                                              |               | AFL |             | 936             |     |                  | 181         |                    | 0       |              |
|                                              |                                                                                                                                              |               | MOS |             | 96.6            |     |                  | 24 Apr 2018 |                    |         |              |
|                                              |                                                                                                                                              |               | MSC |             |                 |     | -                |             |                    |         |              |
| (981760)                                     |                                                                                                                                              |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                                     |                                                                                                                                              |               |     |             |                 |     |                  |             |                    |         |              |
| CB177                                        | CB177 - Landing Gear (ATA 32), Inspection - Main Landing Gear Side Brace Actuator Band Clamps                                                |               | HRS |             | 2345.1          |     |                  | 701         |                    |         | 0            |
|                                              |                                                                                                                                              |               | AFL |             | 936             |     |                  | 181         |                    | 0       |              |
|                                              |                                                                                                                                              |               | MOS |             | 97.2            |     |                  | 06 Apr 2018 |                    |         |              |
|                                              |                                                                                                                                              |               | MSC |             |                 |     | -                |             |                    |         |              |
| (981770)                                     |                                                                                                                                              |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                                     |                                                                                                                                              |               |     |             |                 |     |                  |             |                    |         |              |
| CB177A                                       | CB177A - Landing Gear (ATA 32) - Inspection - Main Landing Gear Side Brace Actuator Band Clamps (Rescinded and Superseded By CB239 & ASC117) |               | HRS |             | 1992.1          |     |                  | 1054        |                    |         | 0            |
|                                              |                                                                                                                                              |               | AFL |             | 813             |     |                  | 304         |                    | 0       |              |
|                                              |                                                                                                                                              |               | MOS |             | 83.3            |     |                  | 01 Jun 2019 |                    |         |              |
|                                              |                                                                                                                                              |               | MSC |             |                 |     | -                |             |                    |         |              |
| (981771)                                     |                                                                                                                                              |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                                     |                                                                                                                                              |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: NO FURTHER ACTION REQUIRED            |                                                                                                                                              |               |     |             |                 |     |                  |             |                    |         |              |
| CB178                                        | CB178 - Fuel (ATA 28), Inspection - Fuel Cell Over-Wing Wiring AT Fuselage Station 536                                                       |               | HRS |             | 2673.8          |     |                  | 372.3       |                    |         | 0            |
|                                              |                                                                                                                                              |               | AFL |             | 1020            |     |                  | 97          |                    | 0       |              |
|                                              |                                                                                                                                              |               | MOS |             | 109.7           |     |                  | 21 Mar 2017 |                    |         |              |
|                                              |                                                                                                                                              |               | MSC |             |                 |     | -                |             |                    |         |              |
| (981780)                                     |                                                                                                                                              |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                                     |                                                                                                                                              |               |     |             |                 |     |                  |             |                    |         |              |
| CB179                                        | CB179 - Electrical Power (ATA 24), Inspection - Tail Compartment Ground Pads                                                                 |               | HRS |             | 2673.8          |     |                  | 372.3       |                    |         | 0            |
|                                              |                                                                                                                                              |               | AFL |             | 1020            |     |                  | 97          |                    | 0       |              |
|                                              |                                                                                                                                              |               | MOS |             | 109.4           |     |                  | 31 Mar 2017 |                    |         |              |
|                                              |                                                                                                                                              |               | MSC |             |                 |     | -                |             |                    |         |              |
| (981790)                                     |                                                                                                                                              |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                                     |                                                                                                                                              |               |     |             |                 |     |                  |             |                    |         |              |
| CB179A                                       | CB179A - Electrical Power (ATA 24) - Inspection - Tail Compartment Ground Pads                                                               |               | HRS |             | 2342.8          |     |                  | 703.3       |                    |         | 0            |
|                                              |                                                                                                                                              |               | AFL |             | 933             |     |                  | 184         |                    | 0       |              |
|                                              |                                                                                                                                              |               | MOS |             | 95.8            |     |                  | 16 May 2018 |                    |         |              |
|                                              |                                                                                                                                              |               | MSC |             |                 |     | -                |             |                    |         |              |
| (981791)                                     |                                                                                                                                              |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                                     |                                                                                                                                              |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: NO FURTHER ACTION REQ"D DUE PCW CB179 |                                                                                                                                              |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom                                      | Description                                                                                                                 |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                                      | Part Number                                                                                                                 | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position                                     | HW                                                                                                                          | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                                      | MM Ref                                                                                                                      |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                                                      | Ops Number(s)                                                                                                               |               |     |             |                 |     |                  |             |                    |         |              |
| <b>CB179B</b><br><br>(981792)<br><br>Airframe        | CB179B - Inspection – Tail Compartment Ground Pads                                                                          |               | HRS |             | 1928.2          |     |                  | 1117.9      |                    |         | 0            |
|                                                      |                                                                                                                             |               | AFL |             | 799             |     |                  | 318         |                    |         | 0            |
|                                                      |                                                                                                                             |               | MOS |             | 81.8            |     |                  | 17 Jul 2019 |                    |         |              |
|                                                      |                                                                                                                             |               | MSC |             |                 |     | -                |             |                    |         |              |
| Notes: NO FURTHER ACTION REQUIRED                    |                                                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| <b>CB180</b><br><br>(981800)<br><br>Airframe         | CB180 - Fuselage (ATA 53), Inspection - Aft Mid Lower Drain Valves AT Fuselage Station 756                                  |               | HRS |             | 2345.1          |     |                  | 701         |                    |         | 0            |
|                                                      |                                                                                                                             |               | AFL |             | 936             |     |                  | 181         |                    |         | 0            |
|                                                      |                                                                                                                             |               | MOS |             | 97.1            |     |                  | 07 Apr 2018 |                    |         |              |
|                                                      |                                                                                                                             |               | MSC |             |                 |     | -                |             |                    |         |              |
| <b>CB183</b><br><br>(981830)<br><br>Airframe         | CB183 - Doors (ATA 52), Inspection - Main Entrance Door Forward and Aft Lock Out Mechanical Stop Bracket Assemblies Sealing |               | HRS |             | 2345.1          |     |                  | 701         |                    |         | 0            |
|                                                      |                                                                                                                             |               | AFL |             | 936             |     |                  | 181         |                    |         | 0            |
|                                                      |                                                                                                                             |               | MOS |             | 96.7            |     |                  | 19 Apr 2018 |                    |         |              |
|                                                      |                                                                                                                             |               | MSC |             |                 |     | -                |             |                    |         |              |
| <b>CB184</b><br><br>(981840)<br><br>Airframe         | CB184 - Doors (ATA 52), Inspection - Main Entrance Door P-Clamp Orientation                                                 |               | HRS |             | 2345.1          |     |                  | 701         |                    |         | 0            |
|                                                      |                                                                                                                             |               | AFL |             | 936             |     |                  | 181         |                    |         | 0            |
|                                                      |                                                                                                                             |               | MOS |             | 97              |     |                  | 10 Apr 2018 |                    |         |              |
|                                                      |                                                                                                                             |               | MSC |             |                 |     | -                |             |                    |         |              |
| <b>CB186 PART I</b><br><br>(981860)<br><br>Airframe  | CB186 Part I - Flight Controls (ATA 27), Replacement - Flap Electronic Control Unit                                         |               | HRS |             | 2621.2          |     |                  | 424.9       |                    |         | 0            |
|                                                      |                                                                                                                             |               | AFL |             | 1009            |     |                  | 108         |                    |         | 0            |
|                                                      |                                                                                                                             |               | MOS |             | 107.2           |     |                  | 06 Jun 2017 |                    |         |              |
|                                                      |                                                                                                                             |               | MSC |             |                 |     | -                |             |                    |         |              |
| Notes: N/A BY FLAP UNIT S/N INSTALLED                |                                                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| <b>CB186 PART II</b><br><br>(981861)<br><br>Airframe | CB186 Part II - Flight Controls (ATA 27), Replacement - Flap Electronic Control Unit                                        |               | HRS |             | 2621.2          |     |                  | 424.9       |                    |         | 0            |
|                                                      |                                                                                                                             |               | AFL |             | 1009            |     |                  | 108         |                    |         | 0            |
|                                                      |                                                                                                                             |               | MOS |             | 107.2           |     |                  | 06 Jun 2017 |                    |         |              |
|                                                      |                                                                                                                             |               | MSC |             |                 |     | -                |             |                    |         |              |
| Notes: N/A BY FLAP UNIT S/N INSTALLED                |                                                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom                                              | Description                                              |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|--------------------------------------------------------------|----------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                                              | Part Number                                              | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position                                             | HW                                                       | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                                              | MM Ref                                                   |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                                                              | Ops Number(s)                                            |               |     |             |                 |     |                  |             |                    |         |              |
| CB187<br><br>(981870)<br><br>Airframe                        | CB187 - Landing Gear (ATA 32), Inspection - Nose         |               | HRS |             | 2618.1          |     |                  | 428         |                    |         | 0            |
|                                                              | Landing Gear Upper Torque ARM Pin                        |               | AFL |             | 1007            |     |                  | 110         |                    |         | 0            |
|                                                              |                                                          |               | MOS |             | 106.4           |     |                  | 29 Jun 2017 |                    |         |              |
|                                                              |                                                          |               | MSC |             |                 |     | -                |             |                    |         |              |
| Notes: N/A BY TORQUE ARM PIN SN FITTED (SN: 00435 INSTALLED) |                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| CB187A<br><br>(981871)<br><br>Airframe                       | CB187A - Landing Gear (ATA 32) - Inspection - Nose       |               | HRS |             | 1992.1          |     |                  | 1054        |                    |         | 0            |
|                                                              | Landing Gear Upper Torque ARM Pin                        |               | AFL |             | 813             |     |                  | 304         |                    |         | 0            |
|                                                              |                                                          |               | MOS |             | 83.3            |     |                  | 01 Jun 2019 |                    |         |              |
|                                                              |                                                          |               | MSC |             |                 |     | -                |             |                    |         |              |
| Notes: NO FURTHER ACTION REQUIRED                            |                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| CB190<br><br>(981900)<br><br>Airframe                        | CB190 - Pneumatic Systems (ATA 36), Inspection - Bleed   |               | HRS |             | 2618.1          |     |                  | 428         |                    |         | 0            |
|                                                              | AIR Manifold Gamah Couplers                              |               | AFL |             | 1007            |     |                  | 110         |                    |         | 0            |
|                                                              |                                                          |               | MOS |             | 106.4           |     |                  | 29 Jun 2017 |                    |         |              |
|                                                              |                                                          |               | MSC |             |                 |     | -                |             |                    |         |              |
| Notes: NIL DEFECTS NOTED                                     |                                                          |               |     |             |                 |     |                  |             |                    |         |              |
| CB193<br><br>(981930)<br><br>Airframe                        | CB193 - Landing Gear (ATA 32) Inspection - Nose          |               | HRS |             | 2345.1          |     |                  | 701         |                    |         | 0            |
|                                                              | Landing Gear Door Actuator Torque Tubes - Aft Bearings   |               | AFL |             | 936             |     |                  | 181         |                    |         | 0            |
|                                                              |                                                          |               | MOS |             | 97.1            |     |                  | 09 Apr 2018 |                    |         |              |
|                                                              |                                                          |               | MSC |             |                 |     | -                |             |                    |         |              |
| CB194<br><br>(981940)<br><br>Airframe                        | CB194 - Hydraulic Power (ATA 29), Inspection - Hydraulic |               | HRS |             | 2345.1          |     |                  | 701         |                    |         | 0            |
|                                                              | Return Tube AT Fuselage Station (FS) 1080 Left           |               | AFL |             | 936             |     |                  | 181         |                    |         | 0            |
|                                                              |                                                          |               | MOS |             | 97              |     |                  | 10 Apr 2018 |                    |         |              |
|                                                              |                                                          |               | MSC |             |                 |     | -                |             |                    |         |              |
| CB196<br><br>(981960)<br><br>Airframe                        | CB196 - Doors (ATA 52) - Modification - Main Entrance    |               | HRS |             | 2345.1          |     |                  | 701         |                    |         | 0            |
|                                                              | Door Bottom Folding Step Mechanism Improvement (ASC      |               | AFL |             | 936             |     |                  | 181         |                    |         | 0            |
|                                                              | 099)                                                     |               | MOS |             | 96.6            |     |                  | 24 Apr 2018 |                    |         |              |
|                                                              |                                                          |               | MSC |             |                 |     | -                |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                                                                                                    |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                                                                                                    | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                                                                                                             | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                                                                                                         |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                                                                                                                  |               |     |             |                 |     |                  |             |                    |         |              |
| CB197            | CB197 - Flight Controls (ATA 27) Modification - Flight Control Computer (FCC) Software Upgrade 7.1 (ASC 093)                                                   |               | HRS |             | 2345.1          |     |                  | 701         |                    |         | 0            |
|                  |                                                                                                                                                                |               | AFL |             | 936             |     |                  | 181         |                    |         | 0            |
|                  |                                                                                                                                                                |               | MOS |             | 96.6            |     |                  | 23 Apr 2018 |                    |         |              |
|                  |                                                                                                                                                                |               | MSC |             |                 |     | -                |             |                    |         |              |
| (981970)         |                                                                                                                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe         |                                                                                                                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| CB199            | CB199 - Flight Controls (ATA 27) Modification - Primary Flight Control Actuation System (Pfcas) Motor Control Electronics (Mce) Software Upgrade (ASC 092)     |               | HRS |             | 2345.1          |     |                  | 701         |                    |         | 0            |
|                  |                                                                                                                                                                |               | AFL |             | 936             |     |                  | 181         |                    |         | 0            |
|                  |                                                                                                                                                                |               | MOS |             | 96.6            |     |                  | 24 Apr 2018 |                    |         |              |
|                  |                                                                                                                                                                |               | MSC |             |                 |     | -                |             |                    |         |              |
| (981990)         |                                                                                                                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe         |                                                                                                                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| CB200            | CB200 - Flight Controls (ATA 27) Modification - Primary Flight Control Actuation System (Pfcas) Remote Electronics Unit (Reu) Connector Installation (ASC 097) |               | HRS |             | 2345.1          |     |                  | 701         |                    |         | 0            |
|                  |                                                                                                                                                                |               | AFL |             | 936             |     |                  | 181         |                    |         | 0            |
|                  |                                                                                                                                                                |               | MOS |             | 96.6            |     |                  | 24 Apr 2018 |                    |         |              |
|                  |                                                                                                                                                                |               | MSC |             |                 |     | -                |             |                    |         |              |
| (982000)         |                                                                                                                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe         |                                                                                                                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| CB201            | CB201 - Flight Controls (ATA 27) Modification - Primary Flight Control Actuation System (Pfcas) Remote Electronics Unit (Reu) Software Upgrade (ASC 069)       |               | HRS |             | 2345.1          |     |                  | 701         |                    |         | 0            |
|                  |                                                                                                                                                                |               | AFL |             | 936             |     |                  | 181         |                    |         | 0            |
|                  |                                                                                                                                                                |               | MOS |             | 96.6            |     |                  | 24 Apr 2018 |                    |         |              |
|                  |                                                                                                                                                                |               | MSC |             |                 |     | -                |             |                    |         |              |
| (982010)         |                                                                                                                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe         |                                                                                                                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| CB202            | CB202 - Wings (ATA 57) - Inspection - Wiring Installation AT Outboard Flight Spoiler Attach Fittings                                                           |               | HRS |             | 2345.1          |     |                  | 701         |                    |         | 0            |
|                  |                                                                                                                                                                |               | AFL |             | 936             |     |                  | 181         |                    |         | 0            |
|                  |                                                                                                                                                                |               | MOS |             | 97              |     |                  | 10 Apr 2018 |                    |         |              |
|                  |                                                                                                                                                                |               | MSC |             |                 |     | -                |             |                    |         |              |
| (982020)         |                                                                                                                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe         |                                                                                                                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| CB203            | CB203 - Electrical Power (ATA 24) Inspection - Wire Routing on Reer Forward Bulkhead                                                                           |               | HRS |             | 2345.1          |     |                  | 701         |                    |         | 0            |
|                  |                                                                                                                                                                |               | AFL |             | 936             |     |                  | 181         |                    |         | 0            |
|                  |                                                                                                                                                                |               | MOS |             | 97.1            |     |                  | 09 Apr 2018 |                    |         |              |
|                  |                                                                                                                                                                |               | MSC |             |                 |     | -                |             |                    |         |              |
| (982030)         |                                                                                                                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe         |                                                                                                                                                                |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom                                                                            | Description                                                                                                                                            |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|--------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                                                                            | Part Number                                                                                                                                            | Serial Number |                     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position                                                                           | HW                                                                                                                                                     | SW            |                     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                                                                            | MM Ref                                                                                                                                                 |               |                     |             |                 |     |                  |             |                    |         | Date Type    |
|                                                                                            | Ops Number(s)                                                                                                                                          |               |                     |             |                 |     |                  |             |                    |         |              |
| CB204                                                                                      | CB204 - Flight Controls (ATA 27) Modification - Horizontal Stabilizer Control Unit (Hscu) MOD 4 (ASC 098)                                              |               | HRS                 |             | 2345.1          |     |                  | 701         |                    |         | 0            |
|                                                                                            |                                                                                                                                                        |               | AFL                 |             | 936             |     |                  | 181         |                    |         | 0            |
|                                                                                            |                                                                                                                                                        |               | MOS                 |             | 97.1            |     |                  | 09 Apr 2018 |                    |         |              |
|                                                                                            |                                                                                                                                                        |               | MSC                 |             |                 |     | -                |             |                    |         |              |
| (982040)                                                                                   |                                                                                                                                                        |               |                     |             |                 |     |                  |             |                    |         |              |
| Airframe                                                                                   |                                                                                                                                                        |               |                     |             |                 |     |                  |             |                    |         |              |
| CB204A                                                                                     | CB204A - Flight Controls (ATA 27) - Modification - Horizontal Stabilizer Control Unit (Hscu) Hardware MOD 4 Verification and Software Update (ASC 098) |               | HRS                 |             | 2324.9          |     |                  | 721.2       |                    |         | 0            |
|                                                                                            |                                                                                                                                                        |               | AFL                 |             | 929             |     |                  | 188         |                    |         | 0            |
|                                                                                            |                                                                                                                                                        |               | MOS                 |             | 95              |     |                  | 12 Jun 2018 |                    |         |              |
|                                                                                            |                                                                                                                                                        |               | MSC                 |             |                 |     | -                |             |                    |         |              |
| (982041)                                                                                   |                                                                                                                                                        |               |                     |             |                 |     |                  |             |                    |         |              |
| Airframe                                                                                   |                                                                                                                                                        |               |                     |             |                 |     |                  |             |                    |         |              |
| Notes: PCW CB204, NO FURTHER ACTION REQUIRED                                               |                                                                                                                                                        |               |                     |             |                 |     |                  |             |                    |         |              |
| CB204B                                                                                     | CB204B - Flight Controls (ATA 27) Modification – Horizontal Stabilizer Control Unit (Hscu) Hardware MOD 4 Verification and Software Update (ASC 098)   |               | HRS                 |             | 2182.3          |     |                  | 863.8       |                    |         | 0            |
|                                                                                            |                                                                                                                                                        |               | AFL                 |             | 884             |     |                  | 233         |                    |         | 0            |
|                                                                                            |                                                                                                                                                        |               | MOS                 |             | 89.9            |     |                  | 13 Nov 2018 |                    |         |              |
|                                                                                            |                                                                                                                                                        |               | MSC                 |             |                 |     | -                |             |                    |         |              |
| (982042)                                                                                   |                                                                                                                                                        |               |                     |             |                 |     |                  |             |                    |         |              |
| Airframe                                                                                   |                                                                                                                                                        |               |                     |             |                 |     |                  |             |                    |         |              |
| Notes: NO FURTHER ACTION REQ"D DUE PCW CB 204 INITIAL REV                                  |                                                                                                                                                        |               |                     |             |                 |     |                  |             |                    |         |              |
| CB205                                                                                      | CB205 - Fuselage (ATA 53), Replacement - Cabin Floorboard 7D                                                                                           |               | HRS                 |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                                                                                            |                                                                                                                                                        |               | AFL                 |             | 315             |     |                  | 802         |                    |         | 0            |
|                                                                                            |                                                                                                                                                        |               | MOS                 |             | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
|                                                                                            |                                                                                                                                                        |               | MSC                 |             |                 |     | -                |             |                    |         |              |
| (982050)                                                                                   |                                                                                                                                                        |               |                     |             |                 |     |                  |             |                    |         |              |
| Airframe                                                                                   |                                                                                                                                                        |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Notes: DO IN COORDINATION WITH 531101                                                      |                                                                                                                                                        |               |                     |             |                 |     |                  |             |                    |         |              |
| CB206                                                                                      | CB206 - Equipment and Furnishings (ATA 25) - Life Raft Gas Cylinder Replacement AT Overhaul (Utas Sb 25-470)                                           |               | HRS                 |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                                                                                        |               | AFL                 |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                                                                                        |               | MOS                 |             | 95.8            |     |                  | 18 May 2018 |                    |         |              |
|                                                                                            |                                                                                                                                                        |               | MSC                 |             |                 |     | -                |             |                    |         |              |
| (982060)                                                                                   |                                                                                                                                                        |               |                     |             |                 |     |                  |             |                    |         |              |
| Airframe                                                                                   |                                                                                                                                                        |               |                     |             |                 |     |                  |             |                    |         |              |
| Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK. |                                                                                                                                                        |               |                     |             |                 |     |                  |             |                    |         |              |
| CB206A                                                                                     | CB206A - Equipment and Furnishings (ATA 25) - Life Raft Gas Cylinder Replacement AT Overhaul (Utas Sb 25-470)                                          |               | HRS                 |             | 2236.5          |     |                  | 809.6       |                    |         | 0            |
|                                                                                            |                                                                                                                                                        |               | AFL                 |             | 896             |     |                  | 221         |                    |         | 0            |
|                                                                                            |                                                                                                                                                        |               | MOS                 |             | 91              |     |                  | 12 Oct 2018 |                    |         |              |
|                                                                                            |                                                                                                                                                        |               | MSC                 |             |                 |     | -                |             |                    |         |              |
| (982061)                                                                                   |                                                                                                                                                        |               |                     |             |                 |     |                  |             |                    |         |              |
| Airframe                                                                                   |                                                                                                                                                        |               |                     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom                                                                            | Description                                             |               | UOM  | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|--------------------------------------------------------------------------------------------|---------------------------------------------------------|---------------|------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                                                                            | Part Number                                             | Serial Number |      |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position                                                                           | HW                                                      | SW            |      |             |                 |     |                  |             |                    |         | Manufacturer |
|                                                                                            | MM Ref                                                  |               |      |             |                 |     |                  |             |                    |         | Date Type    |
|                                                                                            | Ops Number(s)                                           |               |      |             |                 |     |                  |             |                    |         |              |
| CB206B                                                                                     | CB206B - Equipment and Furnishings (ATA 25) - Life Raft |               | HRS  |             | 1452            |     |                  | 1594.1      |                    |         | 0            |
|                                                                                            | Gas Cylinder Replacement AT Overhaul (Utas Sb 25-470 /  |               | AFL  |             | 570             |     |                  | 547         |                    |         | 0            |
|                                                                                            | Sb 25-476)                                              |               | MOS  |             | 63.7            |     |                  | 20 Jan 2021 |                    |         |              |
|                                                                                            |                                                         |               | MSC  |             |                 |     |                  |             |                    |         |              |
| (982062)                                                                                   |                                                         |               |      |             |                 |     |                  |             |                    |         |              |
| Airframe                                                                                   |                                                         |               |      |             |                 |     |                  |             |                    |         |              |
| CB207                                                                                      | CB207 - Electrical Power (ATA 24) - Inspection - Wire   |               | HRS  |             | 2345.1          |     |                  | 701         |                    |         | 0            |
|                                                                                            | Routing Aft Equipment Bay and Wheel Well                |               | AFL  |             | 936             |     |                  | 181         |                    |         | 0            |
|                                                                                            |                                                         |               | MOS  |             | 96.7            |     |                  | 19 Apr 2018 |                    |         |              |
|                                                                                            |                                                         |               | MSC  |             |                 |     |                  |             |                    |         |              |
| (982070)                                                                                   |                                                         |               |      |             |                 |     |                  |             |                    |         |              |
| Airframe                                                                                   |                                                         |               |      |             |                 |     |                  |             |                    |         |              |
| Notes: PN: GAP105F2C2 SN: <NONE>.                                                          |                                                         |               |      |             |                 |     |                  |             |                    |         |              |
| CB208                                                                                      | CB208 - Landing Gear (ATA 32) - Inspection - Main       |               | HRS  |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                                                                            | Landing Gear Axle Fitting Assembly (UTC Aerospace Sb    |               | AFL  |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                                                                            | C1A5400-32-009)                                         |               | MOS  |             | 86.9            |     |                  | 13 Feb 2019 |                    |         |              |
|                                                                                            |                                                         |               | MSC  |             |                 |     |                  |             |                    |         |              |
| (982080)                                                                                   |                                                         |               |      |             |                 |     |                  |             |                    |         |              |
| Airframe                                                                                   |                                                         |               |      |             |                 |     |                  |             |                    |         |              |
| Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK. |                                                         |               |      |             |                 |     |                  |             |                    |         |              |
| CB208A                                                                                     | CB208A - Landing Gear (ATA 32) - Inspection - Main      |               | HRS  |             | 1735.8          |     |                  | 1310.3      | 0                  |         | 0            |
|                                                                                            | Landing Gear Axle Fitting Assembly (UTC Aerospace Sb    |               | AFL  |             | 729             |     |                  | 388         | 0                  |         | 0            |
|                                                                                            | C1A5400-32-009)                                         |               | MOS  |             | 75.2            |     |                  | 05 Feb 2020 |                    |         |              |
|                                                                                            |                                                         |               | MSC  |             |                 |     |                  |             |                    |         |              |
| (982081)                                                                                   |                                                         |               |      |             |                 |     |                  |             |                    |         |              |
| Airframe                                                                                   |                                                         |               |      |             |                 |     |                  |             |                    |         |              |
| CB208B                                                                                     | CB208B - Landing Gear (ATA 32) - Inspection - Main      |               | HRS  |             | 1650.8          |     |                  | 1395.3      |                    |         | 0            |
|                                                                                            | Landing Gear Axle Fitting Assembly (UTC Aerospace Sb    |               | AFL  |             | 691             |     |                  | 426         |                    |         | 0            |
|                                                                                            | C1A5400-32-009)                                         |               | MOS  |             | 72              |     |                  | 10 May 2020 |                    |         |              |
|                                                                                            |                                                         |               | MSC  |             |                 |     |                  |             |                    |         |              |
| (982082)                                                                                   |                                                         |               |      |             |                 |     |                  |             |                    |         |              |
| Airframe                                                                                   |                                                         |               |      |             |                 |     |                  |             |                    |         |              |
| CB208C                                                                                     | CB208C - CB208C - Landing Gear (ATA 32) - Inspection -  |               | HRS  |             |                 |     |                  |             |                    |         | 0            |
|                                                                                            | Main Landing Gear Axle Fitting Assembly (UTC            |               | AFL  |             |                 |     |                  |             |                    |         | 0            |
|                                                                                            | Aerospace Sb C1A5400-32-009), (No Longer Required.)     |               | DATE |             |                 |     |                  |             |                    |         |              |
|                                                                                            |                                                         |               | MSC  |             |                 |     |                  |             |                    |         |              |
| (982083)                                                                                   |                                                         |               |      |             |                 |     |                  |             |                    |         |              |
| Airframe                                                                                   |                                                         |               |      |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom                                                                            | Description                                                                                                                                         |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|--------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                                                                            | Part Number                                                                                                                                         | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position                                                                           | HW                                                                                                                                                  | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                                                                            | MM Ref                                                                                                                                              |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                                                                                            | Ops Number(s)                                                                                                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| CB211                                                                                      | CB211 - Flight Controls (ATA 27) Inspection - Flight Controls Wiring Harness Installation Under Electrical Backup Hydraulic Actuator (Ebha) Battery |               | HRS |             | 2120.8          |     |                  | 925.3       |                    |         | 0            |
|                                                                                            |                                                                                                                                                     |               | AFL |             | 861             |     |                  | 256         |                    |         | 0            |
|                                                                                            |                                                                                                                                                     |               | MOS |             | 86              |     |                  | 11 Mar 2019 |                    |         |              |
|                                                                                            |                                                                                                                                                     |               | MSC |             |                 |     | -                |             |                    |         |              |
| (982110)                                                                                   |                                                                                                                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                                                                                   |                                                                                                                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| CB213 PART I                                                                               | CB213 Part I - Flight Controls (ATA 27) - Replacement - Flap Hydraulic Power Drive Unit                                                             |               | HRS |             | 2324.9          |     |                  | 721.2       |                    |         | 0            |
|                                                                                            |                                                                                                                                                     |               | AFL |             | 929             |     |                  | 188         |                    |         | 0            |
|                                                                                            |                                                                                                                                                     |               | MOS |             | 95              |     |                  | 12 Jun 2018 |                    |         |              |
|                                                                                            |                                                                                                                                                     |               | MSC |             |                 |     | -                |             |                    |         |              |
| (982130)                                                                                   |                                                                                                                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                                                                                   |                                                                                                                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| CB213 PART II                                                                              | CB213 Part II - Flight Controls (ATA 27) - Replacement - Flap Hydraulic Power Drive Unit                                                            |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                                                                                     |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                                                                                     |               | MOS |             | 92.1            |     |                  | 07 Sep 2018 |                    |         |              |
|                                                                                            |                                                                                                                                                     |               | MSC |             |                 |     | -                |             |                    |         |              |
| (982131)                                                                                   |                                                                                                                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                                                                                   |                                                                                                                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK. |                                                                                                                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| CB213A PART I                                                                              | CB213A Part I - Flight Controls (ATA 27) - Replacement - Flap Hydraulic Power Drive Unit                                                            |               | HRS |             | 2236.5          |     |                  | 809.6       |                    |         | 0            |
|                                                                                            |                                                                                                                                                     |               | AFL |             | 896             |     |                  | 221         |                    |         | 0            |
|                                                                                            |                                                                                                                                                     |               | MOS |             | 91              |     |                  | 12 Oct 2018 |                    |         |              |
|                                                                                            |                                                                                                                                                     |               | MSC |             |                 |     | -                |             |                    |         |              |
| (982132)                                                                                   |                                                                                                                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                                                                                   |                                                                                                                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: PART 1 PCW ON CMP CODE 982130 ON 12 JUN 2018 - CB 213 INITIAL REV                   |                                                                                                                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| CB213A PART II                                                                             | CB213A Part II - Flight Controls (ATA 27) - Replacement - Flap Hydraulic Power Drive Unit                                                           |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                                                                                     |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                                                                                     |               | MOS |             | 90.3            |     |                  | 01 Nov 2018 |                    |         |              |
|                                                                                            |                                                                                                                                                     |               | MSC |             |                 |     | -                |             |                    |         |              |
| (982133)                                                                                   |                                                                                                                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                                                                                   |                                                                                                                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK. |                                                                                                                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| CB213B PART I                                                                              | CB213B Part I -                                                                                                                                     |               | HRS |             | 2120.8          |     |                  | 925.3       |                    |         | 0            |
|                                                                                            |                                                                                                                                                     |               | AFL |             | 861             |     |                  | 256         |                    |         | 0            |
|                                                                                            |                                                                                                                                                     |               | MOS |             | 86.3            |     |                  | 01 Mar 2019 |                    |         |              |
|                                                                                            |                                                                                                                                                     |               | MSC |             |                 |     | -                |             |                    |         |              |
| (982134)                                                                                   |                                                                                                                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                                                                                   |                                                                                                                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: NO FURTHER ACTION REQ"D DUE PCW CB213 INITIAL REV                                   |                                                                                                                                                     |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom                                       | Description                                                                                                                                  |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|-------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                                       | Part Number                                                                                                                                  | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position                                      | HW                                                                                                                                           | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                                       | MM Ref                                                                                                                                       |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                                                       | Ops Number(s)                                                                                                                                |               |     |             |                 |     |                  |             |                    |         |              |
| <b>CB213B PART II</b><br><br>(982135)<br><br>Airframe | CB213B Part Ii -                                                                                                                             |               | HRS |             | 2120.8          |     |                  | 925.3       |                    |         | 0            |
|                                                       |                                                                                                                                              |               | AFL |             | 861             |     |                  | 256         |                    |         | 0            |
|                                                       |                                                                                                                                              |               | MOS |             | 86.2            |     |                  | 04 Mar 2019 |                    |         |              |
|                                                       |                                                                                                                                              |               | MSC |             |                 |     | -                |             |                    |         |              |
| <b>CB214</b><br><br>(982140)<br><br>Airframe          | CB214 - Equipment and Furnishings (ATA 25) - Electronic Control Unit (Ecu) Software for Vip Seats(RCO Sb RCO2017-10-12-1)                    |               | HRS |             | 2324.9          |     |                  | 721.2       |                    |         | 0            |
|                                                       |                                                                                                                                              |               | AFL |             | 929             |     |                  | 188         |                    |         | 0            |
|                                                       |                                                                                                                                              |               | MOS |             | 94.7            |     |                  | 21 Jun 2018 |                    |         |              |
|                                                       |                                                                                                                                              |               | MSC |             |                 |     | -                |             |                    |         |              |
| Notes: N/A BY SEAT PN                                 |                                                                                                                                              |               |     |             |                 |     |                  |             |                    |         |              |
| <b>CB215</b><br><br>(982150)<br><br>Airframe          | CB215 - Equipment / Furnishings (ATA 25) - Modification - Forward Left Side Lavatory Cabinet Wiring Installation (GPM412004707-301 Monument) |               | HRS |             | 2324.9          |     |                  | 721.2       |                    |         | 0            |
|                                                       |                                                                                                                                              |               | AFL |             | 929             |     |                  | 188         |                    |         | 0            |
|                                                       |                                                                                                                                              |               | MOS |             | 94.7            |     |                  | 21 Jun 2018 |                    |         |              |
|                                                       |                                                                                                                                              |               | MSC |             |                 |     | -                |             |                    |         |              |
| Notes: N/A BY A/C SERIAL NUMBER                       |                                                                                                                                              |               |     |             |                 |     |                  |             |                    |         |              |
| <b>CB220</b><br><br>(982200)<br><br>Airframe          | CB220 - FIRE Protection (ATA 26) - Modification - Engine FIRE Bottle Harness (ASC 111)                                                       |               | HRS |             | 2120.8          |     |                  | 925.3       |                    |         | 0            |
|                                                       |                                                                                                                                              |               | AFL |             | 861             |     |                  | 256         |                    |         | 0            |
|                                                       |                                                                                                                                              |               | MOS |             | 86              |     |                  | 11 Mar 2019 |                    |         |              |
|                                                       |                                                                                                                                              |               | MSC |             |                 |     | -                |             |                    |         |              |
| <b>CB220A</b><br><br>(982201)<br><br>Airframe         | CB220A - FIRE Protection (ATA 26) - Modification - Engine FIRE Bottle Harness (ASC 111)                                                      |               | HRS |             | 2052.4          |     |                  | 993.7       |                    |         | 0            |
|                                                       |                                                                                                                                              |               | AFL |             | 831             |     |                  | 286         |                    |         | 0            |
|                                                       |                                                                                                                                              |               | MOS |             | 84.5            |     |                  | 26 Apr 2019 |                    |         |              |
|                                                       |                                                                                                                                              |               | MSC |             |                 |     | -                |             |                    |         |              |
| Notes: PCW CB220 - NO FURTHER ACTION REQ"D            |                                                                                                                                              |               |     |             |                 |     |                  |             |                    |         |              |
| <b>CB221</b><br><br>(982210)<br><br>Airframe          | CB221 - Hydraulic Power (ATA 29) - Modification - Auxiliary Hydraulic Pump Grounding Installation (ASC 103)                                  |               | HRS |             | 2120.8          |     |                  | 925.3       |                    |         | 0            |
|                                                       |                                                                                                                                              |               | AFL |             | 861             |     |                  | 256         |                    |         | 0            |
|                                                       |                                                                                                                                              |               | MOS |             | 86.1            |     |                  | 08 Mar 2019 |                    |         |              |
|                                                       |                                                                                                                                              |               | MSC |             |                 |     | -                |             |                    |         |              |



| ATA<br>U=Custom  | Description                                                                                                                                       |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|---------------------------------------------------------------------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                                                                                       | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                                                                                                | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                                                                                            |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                                                                                                     |               |     |             |                 |     |                  |             |                    |         |              |
| CB223            | CB223 - Fuselage Structure (ATA 53) - Inspection /<br>Modification - Fuselage Skin and APU Exhaust Fairing<br>(ASC 113)                           |               | HRS |             | 2120.8          |     |                  | 925.3       |                    |         | 0            |
|                  |                                                                                                                                                   |               | AFL |             | 861             |     |                  | 256         |                    | 0       |              |
|                  |                                                                                                                                                   |               | MOS |             | 86.5            |     |                  | 27 Feb 2019 |                    |         |              |
|                  |                                                                                                                                                   |               | MSC |             |                 |     | -                |             |                    |         |              |
| (982230)         |                                                                                                                                                   |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe         |                                                                                                                                                   |               |     |             |                 |     |                  |             |                    |         |              |
| CB224            | CB224 - Engine Fuel and Control (ATA 73) - Modification -<br>Engine Electronic Controller (Eec) K8.0.2 Software<br>Upgrade (ASC 088)              |               | HRS |             | 2120.8          |     |                  | 925.3       |                    |         | 0            |
|                  |                                                                                                                                                   |               | AFL |             | 861             |     |                  | 256         |                    | 0       |              |
|                  |                                                                                                                                                   |               | MOS |             | 86              |     |                  | 11 Mar 2019 |                    |         |              |
|                  |                                                                                                                                                   |               | MSC |             |                 |     | -                |             |                    |         |              |
| (982240)         |                                                                                                                                                   |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe         |                                                                                                                                                   |               |     |             |                 |     |                  |             |                    |         |              |
| CB225            | CB225 - Flight Controls (ATA 27) - Retrofit of Electrical<br>Backup (Eb) Hydraulic Manifolds                                                      |               | HRS |             | 3046.1          |     |                  | 0           | 0                  |         | 0            |
|                  |                                                                                                                                                   |               | AFL |             | 1117            |     |                  | 0           | 0                  |         | 0            |
|                  |                                                                                                                                                   |               | MOS |             |                 |     |                  |             |                    |         |              |
|                  |                                                                                                                                                   |               | MSC |             |                 |     | -                |             |                    |         |              |
| (982250)         |                                                                                                                                                   |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe         |                                                                                                                                                   |               |     |             |                 |     |                  |             |                    |         |              |
| CB225A           | CB225A - Flight Controls (ATA 27) - Retrofit of Electrical<br>Backup (Eb) Hydraulic Manifolds                                                     |               | HRS |             | 1452            |     |                  | 1594.1      |                    |         | 0            |
|                  |                                                                                                                                                   |               | AFL |             | 570             |     |                  | 547         |                    | 0       |              |
|                  |                                                                                                                                                   |               | MOS |             | 63.5            |     |                  | 27 Jan 2021 |                    |         |              |
|                  |                                                                                                                                                   |               | MSC |             |                 |     | -                |             |                    |         |              |
| (982251)         |                                                                                                                                                   |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe         |                                                                                                                                                   |               |     |             |                 |     |                  |             |                    |         |              |
| CB226            | CB226 - Flight Controls (ATA 27) - Inspection - Motor<br>Control Electronics (Mce) J3 Connector (Parker Sb<br>469300-27-002 and Sb 469400-27-002) |               | HRS |             | 1452            |     |                  | 1594.1      |                    |         | 0            |
|                  |                                                                                                                                                   |               | AFL |             | 570             |     |                  | 547         |                    | 0       |              |
|                  |                                                                                                                                                   |               | MOS |             | 63.9            |     |                  | 13 Jan 2021 |                    |         |              |
|                  |                                                                                                                                                   |               | MSC |             |                 |     | -                |             |                    |         |              |
| (982260)         |                                                                                                                                                   |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe         |                                                                                                                                                   |               |     |             |                 |     |                  |             |                    |         |              |
| CB227            | CB227 - Flight Controls (ATA 27) - Inspection - Aileron<br>Motor Control Electronics (Mce) and Outboard Spoiler J-<br>Box Connectors              |               | HRS |             | 2120.8          |     |                  | 925.3       |                    |         | 0            |
|                  |                                                                                                                                                   |               | AFL |             | 861             |     |                  | 256         |                    | 0       |              |
|                  |                                                                                                                                                   |               | MOS |             | 86.5            |     |                  | 28 Feb 2019 |                    |         |              |
|                  |                                                                                                                                                   |               | MSC |             |                 |     | -                |             |                    |         |              |
| (982270)         |                                                                                                                                                   |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe         |                                                                                                                                                   |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom                                                                            | Description                                                                                                           |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|--------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                                                                            | Part Number                                                                                                           | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position                                                                           | HW                                                                                                                    | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                                                                            | MM Ref                                                                                                                |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                                                                                            | Ops Number(s)                                                                                                         |               |     |             |                 |     |                  |             |                    |         |              |
| CB228<br><br>(982280)<br><br>Airframe                                                      | CB228 - Navigation (ATA 34) - AIR Data Probe Heat Fault Monitoring - Loadable Diagnostic Information(Ldi) Update      |               | HRS |             | 2120.8          |     |                  | 925.3       |                    |         | 0            |
|                                                                                            |                                                                                                                       |               | AFL |             | 861             |     |                  | 256         |                    |         | 0            |
|                                                                                            |                                                                                                                       |               | MOS |             | 86.3            |     |                  | 01 Mar 2019 |                    |         |              |
|                                                                                            |                                                                                                                       |               | MSC |             |                 |     | -                |             |                    |         |              |
| CB231<br><br>(982310)<br><br>Airframe                                                      | CB231 - Flight Controls (ATA 27) - Modification - Flight Control Computer (FCC) Software Upgrade 8.2 (ASC 102)        |               | HRS |             | 2120.8          |     |                  | 925.3       |                    |         | 0            |
|                                                                                            |                                                                                                                       |               | AFL |             | 861             |     |                  | 256         |                    |         | 0            |
|                                                                                            |                                                                                                                       |               | MOS |             | 85.9            |     |                  | 14 Mar 2019 |                    |         |              |
|                                                                                            |                                                                                                                       |               | MSC |             |                 |     | -                |             |                    |         |              |
| CB232<br><br>(982320)<br><br>Airframe                                                      | CB232 - FIRE Protection (ATA 26) - Inspection - Right Engine FIRE Bottle Electrical Harness                           |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                                                       |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                                                       |               | MOS |             | 89.2            |     |                  | 05 Dec 2018 |                    |         |              |
|                                                                                            |                                                                                                                       |               | MSC |             |                 |     | -                |             |                    |         |              |
| Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK. |                                                                                                                       |               |     |             |                 |     |                  |             |                    |         |              |
| CB232A<br><br>(982321)<br><br>Airframe                                                     | CB232A - FIRE Protection (ATA 26) - Inspection - Right Engine FIRE Bottle Electrical Harness                          |               | HRS |             | 2120.8          |     |                  | 925.3       |                    |         | 0            |
|                                                                                            |                                                                                                                       |               | AFL |             | 861             |     |                  | 256         |                    |         | 0            |
|                                                                                            |                                                                                                                       |               | MOS |             | 85.9            |     |                  | 14 Mar 2019 |                    |         |              |
|                                                                                            |                                                                                                                       |               | MSC |             |                 |     | -                |             |                    |         |              |
| CB233<br><br>(982330)<br><br>Airframe                                                      | CB233 - Engine Starting (ATA 80) - Replacement - BR725 Engine Starter AIR Valve (Rolls Royce Nmsb Sb-BR700-80-900634) |               | HRS |             | 2120.8          |     |                  | 925.3       |                    |         | 0            |
|                                                                                            |                                                                                                                       |               | AFL |             | 861             |     |                  | 256         |                    |         | 0            |
|                                                                                            |                                                                                                                       |               | MOS |             | 86.3            |     |                  | 01 Mar 2019 |                    |         |              |
|                                                                                            |                                                                                                                       |               | MSC |             |                 |     | -                |             |                    |         |              |
| CB233A<br><br>(982331)<br><br>Airframe                                                     | CB233A -                                                                                                              |               | HRS |             | 1928.2          |     |                  | 1117.9      | 0                  |         | 0            |
|                                                                                            |                                                                                                                       |               | AFL |             | 799             |     |                  | 318         | 0                  |         | 0            |
|                                                                                            |                                                                                                                       |               | MOS |             | 81.8            |     |                  | 17 Jul 2019 |                    |         |              |
|                                                                                            |                                                                                                                       |               | MSC |             |                 |     | -                |             |                    |         |              |
| Notes: NO FURTHER ACTION REQUIRED                                                          |                                                                                                                       |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom                                                                            | Description                                                                                                                             |               | UOM  | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|--------------------------------------------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------|---------------|------|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                                                                                            | Part Number                                                                                                                             | Serial Number |      |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position                                                                           | HW                                                                                                                                      | SW            |      |             |                 |     |                  |             |                     |         | Manufacturer |
|                                                                                            | MM Ref                                                                                                                                  |               |      |             |                 |     |                  |             |                     |         | Date Type    |
|                                                                                            | Ops Number(s)                                                                                                                           |               |      |             |                 |     |                  |             |                     |         |              |
| CB233B                                                                                     | CB233B - Cb 233 - Engine Starting (ATA 80) -<br>Replacement - BR725 Engine Starter AIR Valve - (Rolls<br>Royce Nmsb Sb-BR700-80-900634) |               | HRS  |             |                 |     |                  |             |                     |         | 0            |
|                                                                                            |                                                                                                                                         |               | AFL  |             |                 |     |                  |             |                     |         | 0            |
|                                                                                            |                                                                                                                                         |               | DATE |             |                 |     |                  |             |                     |         |              |
|                                                                                            |                                                                                                                                         |               | MSC  |             |                 |     |                  | -           |                     |         |              |
| (982332)                                                                                   |                                                                                                                                         |               |      |             |                 |     |                  |             |                     |         |              |
| Airframe                                                                                   |                                                                                                                                         |               |      |             |                 |     |                  |             |                     |         |              |
| CB236                                                                                      | CB236 - Powerplant (ATA 71) - Inspection - Forward<br>Upper Engine Mount Fitting Contact With Pylon Seal<br>Retainer (ASC 124)          |               | HRS  |             | 3046.1          |     |                  | 0           |                     |         | 0            |
|                                                                                            |                                                                                                                                         |               | AFL  |             | 1117            |     |                  | 0           |                     |         | 0            |
|                                                                                            |                                                                                                                                         |               | MOS  |             | 87.3            |     |                  | 01 Feb 2019 |                     |         |              |
|                                                                                            |                                                                                                                                         |               | MSC  |             |                 |     | -                |             |                     |         |              |
| (982360)                                                                                   |                                                                                                                                         |               |      |             |                 |     |                  |             |                     |         |              |
| Airframe                                                                                   |                                                                                                                                         |               |      |             |                 |     |                  |             |                     |         |              |
| Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK. |                                                                                                                                         |               |      |             |                 |     |                  |             |                     |         |              |
| CB236A                                                                                     | CB236A - Powerplant (ATA 71) - Inspection - Forward<br>Upper Engine Mount Fitting Contact With Pylon Seal<br>Retainer (ASC 124)         |               | HRS  |             | 1735.8          |     |                  | 1310.3      |                     |         | 0            |
|                                                                                            |                                                                                                                                         |               | AFL  |             | 729             |     |                  | 388         |                     |         | 0            |
|                                                                                            |                                                                                                                                         |               | MOS  |             | 75.7            |     |                  | 19 Jan 2020 |                     |         |              |
|                                                                                            |                                                                                                                                         |               | MSC  |             |                 |     | -                |             |                     |         |              |
| (982361)                                                                                   |                                                                                                                                         |               |      |             |                 |     |                  |             |                     |         |              |
| Airframe                                                                                   |                                                                                                                                         |               |      |             |                 |     |                  |             |                     |         |              |
| CB237                                                                                      | CB237 - Indicating/Recording Systems (ATA 31) -<br>Inspection - Display Unit Tray Assembly, Ground Strap<br>Plating Flaking             |               | HRS  |             | 2120.8          |     |                  | 925.3       |                     |         | 0            |
|                                                                                            |                                                                                                                                         |               | AFL  |             | 861             |     |                  | 256         |                     |         | 0            |
|                                                                                            |                                                                                                                                         |               | MOS  |             | 86              |     |                  | 11 Mar 2019 |                     |         |              |
|                                                                                            |                                                                                                                                         |               |      |             |                 |     |                  |             |                     |         |              |
| (982370)                                                                                   |                                                                                                                                         |               |      |             |                 |     |                  |             |                     |         |              |
| Airframe                                                                                   |                                                                                                                                         |               |      |             |                 |     |                  |             |                     |         |              |
| CB239                                                                                      | CB239 - Landing Gear (ATA 32) - Modification - Main<br>Landing Gear Side Brace Actuator Configuration and<br>Clearance (ASC 117)        |               | HRS  |             | 2120.8          |     |                  | 925.3       |                     |         | 0            |
|                                                                                            |                                                                                                                                         |               | AFL  |             | 861             |     |                  | 256         |                     |         | 0            |
|                                                                                            |                                                                                                                                         |               | MOS  |             | 86.2            |     |                  | 05 Mar 2019 |                     |         |              |
|                                                                                            |                                                                                                                                         |               | MSC  |             |                 |     | -                |             |                     |         |              |
| (982390)                                                                                   |                                                                                                                                         |               |      |             |                 |     |                  |             |                     |         |              |
| Airframe                                                                                   |                                                                                                                                         |               |      |             |                 |     |                  |             |                     |         |              |
| CB240                                                                                      | CB240 - Electrical Power (ATA 24) - Modification - Battery<br>Charger, P/N 100-1311-01, Upgrade to MOD 11                               |               | HRS  |             | 1844.6          |     |                  | 1201.5      |                     |         | 0            |
|                                                                                            |                                                                                                                                         |               | AFL  |             | 766             |     |                  | 351         |                     |         | 0            |
|                                                                                            |                                                                                                                                         |               | MOS  |             | 79.3            |     |                  | 01 Oct 2019 |                     |         |              |
|                                                                                            |                                                                                                                                         |               | MSC  |             |                 |     | -                |             |                     |         |              |
| (982400)                                                                                   |                                                                                                                                         |               |      |             |                 |     |                  |             |                     |         |              |
| Airframe                                                                                   |                                                                                                                                         |               |      |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom                                                                            | Description                                                                                                                                 |               | UOM  | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|--------------------------------------------------------------------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------|---------------|------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                                                                            | Part Number                                                                                                                                 | Serial Number |      |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position                                                                           | HW                                                                                                                                          | SW            |      |             |                 |     |                  |             |                    |         | Manufacturer |
|                                                                                            | MM Ref                                                                                                                                      |               |      |             |                 |     |                  |             |                    |         | Date Type    |
|                                                                                            | Ops Number(s)                                                                                                                               |               |      |             |                 |     |                  |             |                    |         |              |
| CB241                                                                                      | CB241 - Landing Gear (ATA 32) - Replacement - Main<br>Landing Gear Shock Struts                                                             |               | HRS  |             | 1735.8          |     |                  | 1310.3      |                    |         | 0            |
|                                                                                            |                                                                                                                                             |               | AFL  |             | 729             |     |                  | 388         |                    | 0       |              |
|                                                                                            |                                                                                                                                             |               | MOS  |             | 75.2            |     |                  | 05 Feb 2020 |                    |         |              |
|                                                                                            |                                                                                                                                             |               | MSC  |             |                 |     | -                |             |                    |         |              |
| (982410)                                                                                   |                                                                                                                                             |               |      |             |                 |     |                  |             |                    |         |              |
| Airframe                                                                                   |                                                                                                                                             |               |      |             |                 |     |                  |             |                    |         |              |
| CB241A                                                                                     | CB241A - CB241A - Landing Gear (ATA 32) -<br>Replacement - Main Landing Gear Shock Strut (No<br>Longer Required)                            |               | HRS  |             |                 |     |                  |             |                    |         | 0            |
|                                                                                            |                                                                                                                                             |               | AFL  |             |                 |     |                  |             |                    | 0       |              |
|                                                                                            |                                                                                                                                             |               | DATE |             |                 |     |                  |             |                    |         |              |
|                                                                                            |                                                                                                                                             |               | MSC  |             |                 |     | -                |             |                    |         |              |
| (982411)                                                                                   |                                                                                                                                             |               |      |             |                 |     |                  |             |                    |         |              |
| Airframe                                                                                   |                                                                                                                                             |               |      |             |                 |     |                  |             |                    |         |              |
| CB242                                                                                      | CB242 - Electrical Power (ATA 24) - Modification -<br>Remove Battery Charger MODE Control Relays (ASC<br>116)                               |               | HRS  |             | 1735.8          |     |                  | 1310.3      |                    |         | 0            |
|                                                                                            |                                                                                                                                             |               | AFL  |             | 729             |     |                  | 388         |                    | 0       |              |
|                                                                                            |                                                                                                                                             |               | MOS  |             | 75.2            |     |                  | 05 Feb 2020 |                    |         |              |
|                                                                                            |                                                                                                                                             |               | MSC  |             |                 |     | -                |             |                    |         |              |
| (982420)                                                                                   |                                                                                                                                             |               |      |             |                 |     |                  |             |                    |         |              |
| Airframe                                                                                   |                                                                                                                                             |               |      |             |                 |     |                  |             |                    |         |              |
| CB245                                                                                      | CB245 - FIRE Protection (ATA 26) - Inspection - Left<br>Engine FIRE Bottle Ground Terminals                                                 |               | HRS  |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                                                                             |               | AFL  |             | 1117            |     |                  | 0           |                    | 0       |              |
|                                                                                            |                                                                                                                                             |               | MOS  |             | 80.9            |     |                  | 13 Aug 2019 |                    |         |              |
|                                                                                            |                                                                                                                                             |               | MSC  |             |                 |     | -                |             |                    |         |              |
| (982450)                                                                                   |                                                                                                                                             |               |      |             |                 |     |                  |             |                    |         |              |
| Airframe                                                                                   |                                                                                                                                             |               |      |             |                 |     |                  |             |                    |         |              |
| Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK. |                                                                                                                                             |               |      |             |                 |     |                  |             |                    |         |              |
| CB245A                                                                                     | CB245A - FIRE Protection (ATA 26) - Inspection - Left<br>Engine FIRE Bottle Ground Terminals                                                |               | HRS  |             | 1844.6          |     |                  | 1201.5      |                    |         | 0            |
|                                                                                            |                                                                                                                                             |               | AFL  |             | 766             |     |                  | 351         |                    | 0       |              |
|                                                                                            |                                                                                                                                             |               | MOS  |             | 79.4            |     |                  | 29 Sep 2019 |                    |         |              |
|                                                                                            |                                                                                                                                             |               | MSC  |             |                 |     | -                |             |                    |         |              |
| (982451)                                                                                   |                                                                                                                                             |               |      |             |                 |     |                  |             |                    |         |              |
| Airframe                                                                                   |                                                                                                                                             |               |      |             |                 |     |                  |             |                    |         |              |
| CB246                                                                                      | CB246 - Engine (ATA 72) - Inspection - High Pressure<br>Compressor Variable Stator Vanes Mechanism (Rolls-<br>Royce Nmsb SBBR700-72-900178) |               | HRS  |             | 1955.3          |     |                  | 1090.8      |                    |         | 0            |
|                                                                                            |                                                                                                                                             |               | AFL  |             | 803             |     |                  | 314         |                    | 0       |              |
|                                                                                            |                                                                                                                                             |               | MOS  |             | 81.9            |     |                  | 13 Jul 2019 |                    |         |              |
|                                                                                            |                                                                                                                                             |               |      |             |                 |     |                  |             |                    |         |              |
| (982460)                                                                                   |                                                                                                                                             |               |      |             |                 |     |                  |             |                    |         |              |
| Airframe                                                                                   |                                                                                                                                             |               |      |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                                                                                     |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------|-------------------------------------------------------------------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                  | Part Number                                                                                                                                     | Serial Number |     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position | HW                                                                                                                                              | SW            |     |             |                 |     |                  |             |                     |         | Manufacturer |
|                  | MM Ref                                                                                                                                          |               |     |             |                 |     |                  |             |                     |         | Date Type    |
|                  | Ops Number(s)                                                                                                                                   |               |     |             |                 |     |                  |             |                     |         |              |
| CB247            | CB247 - Wings (ATA 57) - Inspection - Wing Internal - Ignition Source Protection Sealant (Triumph G650 Wing Service Bulletin MAA7-71258-07_TGI) |               | HRS |             | 1735.8          |     |                  | 1310.3      |                     |         | 0            |
|                  |                                                                                                                                                 |               | AFL |             | 729             |     |                  | 388         |                     |         | 0            |
|                  |                                                                                                                                                 |               | MOS |             | 75.2            |     |                  | 05 Feb 2020 |                     |         |              |
|                  |                                                                                                                                                 |               | MSC |             |                 |     | -                |             |                     |         |              |
| (982470)         |                                                                                                                                                 |               |     |             |                 |     |                  |             |                     |         |              |
| Airframe         |                                                                                                                                                 |               |     |             |                 |     |                  |             |                     |         |              |
| CB248            | CB248 - Electrical Power (ATA 24) - Inspection - Wire Routing Flight Deck and Vestibule                                                         |               | HRS |             | 1735.8          |     |                  | 1310.3      |                     |         | 0            |
|                  |                                                                                                                                                 |               | AFL |             | 729             |     |                  | 388         |                     |         | 0            |
|                  |                                                                                                                                                 |               | MOS |             | 75.7            |     |                  | 20 Jan 2020 |                     |         |              |
|                  |                                                                                                                                                 |               | MSC |             |                 |     | -                |             |                     |         |              |
| (982480)         |                                                                                                                                                 |               |     |             |                 |     |                  |             |                     |         |              |
| Airframe         |                                                                                                                                                 |               |     |             |                 |     |                  |             |                     |         |              |
| CB249            | CB249 - Auxiliary Power Unit (ATA 49) - Update - APU Electronic Control Unit Software (ASC 123)                                                 |               | HRS |             | 1844.6          |     |                  | 1201.5      | 0                   |         | 0            |
|                  |                                                                                                                                                 |               | AFL |             | 766             |     |                  | 351         | 0                   |         | 0            |
|                  |                                                                                                                                                 |               | MOS |             | 79.3            |     |                  | 03 Oct 2019 |                     |         |              |
|                  |                                                                                                                                                 |               | MSC |             |                 |     | -                |             |                     |         |              |
| (982490)         |                                                                                                                                                 |               |     |             |                 |     |                  |             |                     |         |              |
| Airframe         |                                                                                                                                                 |               |     |             |                 |     |                  |             |                     |         |              |
| CB249A           | CB249A - Auxiliary Power Unit (ATA 49) - Update - APU Electronic Control Unit Software (ASC 123)                                                |               | HRS |             | 1650.8          |     |                  | 1395.3      |                     |         | 0            |
|                  |                                                                                                                                                 |               | AFL |             | 691             |     |                  | 426         |                     |         | 0            |
|                  |                                                                                                                                                 |               | MOS |             | 72.3            |     |                  | 01 May 2020 |                     |         |              |
|                  |                                                                                                                                                 |               | MSC |             |                 |     | -                |             |                     |         |              |
| (982491)         |                                                                                                                                                 |               |     |             |                 |     |                  |             |                     |         |              |
| Airframe         |                                                                                                                                                 |               |     |             |                 |     |                  |             |                     |         |              |
| CB250            | CB250 - Electrical Power (ATA 24) - Inspection - Wire Routing Cabin and Baggage Compartment                                                     |               | HRS |             | 994.2           |     |                  | 2051.9      |                     |         | 0            |
|                  |                                                                                                                                                 |               | AFL |             | 392             |     |                  | 725         |                     |         | 0            |
|                  |                                                                                                                                                 |               | MOS |             | 41              |     |                  | 12 Dec 2022 |                     |         |              |
|                  |                                                                                                                                                 |               | MSC |             |                 |     | -                |             |                     |         |              |
| (982500)         |                                                                                                                                                 |               |     |             |                 |     |                  |             |                     |         |              |
| Airframe         |                                                                                                                                                 |               |     |             |                 |     |                  |             |                     |         |              |
| CB251            | CB251 - Flight Controls (ATA 27) - Modification - Flap Electronic Control Unit (Fecu) Software (ASC 110)                                        |               | HRS |             | 1300.7          |     |                  | 1745.4      |                     |         | 0            |
|                  |                                                                                                                                                 |               | AFL |             | 507             |     |                  | 610         |                     |         | 0            |
|                  |                                                                                                                                                 |               | MOS |             | 51.3            |     |                  | 02 Feb 2022 |                     |         |              |
|                  |                                                                                                                                                 |               | MSC |             |                 |     | -                |             |                     |         |              |
| (982510)         |                                                                                                                                                 |               |     |             |                 |     |                  |             |                     |         |              |
| Airframe         |                                                                                                                                                 |               |     |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom                                                               | Description                                               |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|-------------------------------------------------------------------------------|-----------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                                                               | Part Number                                               | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position                                                              | HW                                                        | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                                                               | MM Ref                                                    |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                                                                               | Ops Number(s)                                             |               |     |             |                 |     |                  |             |                    |         |              |
| CB252                                                                         | CB252 - Communications (ATA 23) - Modification -          |               | HRS |             | 1885.7          |     |                  | 1160.4      |                    |         | 0            |
|                                                                               | Jetwave System BLV7.1 Software Release (Honeywell Sb      |               | AFL |             | 779             |     |                  | 338         |                    |         | 0            |
|                                                                               | Jetwave-23-0007)                                          |               | MOS |             | 80.3            |     |                  | 02 Sep 2019 |                    |         |              |
|                                                                               |                                                           |               | MSC |             |                 |     | -                |             |                    |         |              |
| (982520)                                                                      |                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                                                                      |                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: NOT INSTALLED                                                          |                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| CB253                                                                         | CB253 - Engine Fuel and Control (ATA 73) - Modification - |               | HRS |             | 1885.7          |     |                  | 1160.4      |                    |         | 0            |
|                                                                               | Engine Electronic Controller (Eec) - K9.0.1 Software      |               | AFL |             | 779             |     |                  | 338         |                    |         | 0            |
|                                                                               | Upgrade (ASC 133)                                         |               | MOS |             | 80.5            |     |                  | 27 Aug 2019 |                    |         |              |
|                                                                               |                                                           |               | MSC |             |                 |     | -                |             |                    |         |              |
| (982530)                                                                      |                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                                                                      |                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| CB254                                                                         | CB254 - Electrical Power (ATA 24) - Inspection - Wire     |               | HRS |             | 1300.7          |     |                  | 1745.4      |                    |         | 0            |
|                                                                               | Routing Vestibule Outboard of Left Electronic Equipment   |               | AFL |             | 507             |     |                  | 610         |                    |         | 0            |
|                                                                               | Rack (Leer)                                               |               | MOS |             | 51.2            |     |                  | 05 Feb 2022 |                    |         |              |
|                                                                               |                                                           |               | MSC |             |                 |     | -                |             |                    |         |              |
| (982540)                                                                      |                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                                                                      |                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| CB255                                                                         | CB255 - Fuel (ATA 28) - Inspection - Overwing Gravity     |               | HRS |             | 1735.8          |     |                  | 1310.3      |                    |         | 0            |
|                                                                               | Fueling Adapter Installation                              |               | AFL |             | 729             |     |                  | 388         |                    |         | 0            |
|                                                                               |                                                           |               | MOS |             | 75.6            |     |                  | 22 Jan 2020 |                    |         |              |
|                                                                               |                                                           |               | MSC |             |                 |     | -                |             |                    |         |              |
| (982550)                                                                      |                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                                                                      |                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| CB257                                                                         | CB257 - Ignition (ATA 74) - Replacement of Engine Igniter |               | HRS |             | 1844.2          |     |                  | 1201.9      |                    |         | 0            |
|                                                                               | Plugs With P/N CH34760-2 (Rolls-Royce Sb-BR700-74-        |               | AFL |             | 765             |     |                  | 352         |                    |         | 0            |
|                                                                               | 102003)                                                   |               | MOS |             | 78.7            |     |                  | 21 Oct 2019 |                    |         |              |
|                                                                               |                                                           |               | MSC |             |                 |     | -                |             |                    |         |              |
| (982570)                                                                      |                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                                                                      |                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: P/C/W 27 AUGUST 2019. ENGINE IGNITER PLUGS REPLACED WITH P/N CH34760-2 |                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| CB259                                                                         | CB259 - Hydraulic Power (ATA 29) - Hydraulic Filter       |               | HRS |             | 1300.7          |     |                  | 1745.4      |                    |         | 0            |
|                                                                               | Monitoring System - Installation and Activation (ASC 090) |               | AFL |             | 507             |     |                  | 610         |                    |         | 0            |
|                                                                               |                                                           |               | MOS |             | 51.4            |     |                  | 29 Jan 2022 |                    |         |              |
|                                                                               |                                                           |               | MSC |             |                 |     | -                |             |                    |         |              |
| (982590)                                                                      |                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                                                                      |                                                           |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                               |               | UOM  | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-----------------------------------------------------------|---------------|------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                               | Serial Number |      |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                        | SW            |      |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                    |               |      |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                             |               |      |             |                 |     |                  |             |                    |         |              |
| CB261            | CB261 - Doors (ATA 52) - Inspection - Main Entrance       |               | HRS  |             | 1452            |     |                  | 1594.1      |                    |         | 0            |
|                  | Door Wiring Harness Installation                          |               | AFL  |             | 570             |     |                  | 547         |                    |         | 0            |
|                  |                                                           |               | MOS  |             | 64              |     |                  | 12 Jan 2021 |                    |         |              |
|                  |                                                           |               | MSC  |             |                 |     | -                |             |                    |         |              |
| (982610)         |                                                           |               |      |             |                 |     |                  |             |                    |         |              |
| Airframe         |                                                           |               |      |             |                 |     |                  |             |                    |         |              |
| CB261A           | CB261A - CB261A - Doors (ATA 52), Inspection - Main       |               | HRS  |             |                 |     |                  |             |                    |         | 0            |
|                  | Entrance Door Wiring Harness Installation                 |               | AFL  |             |                 |     |                  |             |                    |         | 0            |
|                  |                                                           |               | DATE |             |                 |     |                  |             |                    |         |              |
|                  |                                                           |               | MSC  |             |                 |     | -                |             |                    |         |              |
| (982611)         |                                                           |               |      |             |                 |     |                  |             |                    |         |              |
| Airframe         |                                                           |               |      |             |                 |     |                  |             |                    |         |              |
| CB262            | CB262 - Wings (ATA 57) - Modification - Flap Track D Rub  |               | HRS  |             | 1452            |     |                  | 1594.1      |                    |         | 0            |
|                  | Strips Removal (ASC 083)                                  |               | AFL  |             | 570             |     |                  | 547         |                    |         | 0            |
|                  |                                                           |               | MOS  |             | 63.9            |     |                  | 15 Jan 2021 |                    |         |              |
|                  |                                                           |               | MSC  |             |                 |     | -                |             |                    |         |              |
| (982620)         |                                                           |               |      |             |                 |     |                  |             |                    |         |              |
| Airframe         |                                                           |               |      |             |                 |     |                  |             |                    |         |              |
| CB263            | CB263 - Information Systems (ATA 46) - Modification -     |               | HRS  |             | 1735.8          |     |                  | 1310.3      |                    |         | 0            |
|                  | Aircraft Health and Trend Monitoring System - Software    |               | AFL  |             | 729             |     |                  | 388         |                    |         | 0            |
|                  | Update 2 (ASC 076B)                                       |               | MOS  |             | 75.2            |     |                  | 05 Feb 2020 |                    |         |              |
|                  |                                                           |               | MSC  |             |                 |     | -                |             |                    |         |              |
| (982630)         |                                                           |               |      |             |                 |     |                  |             |                    |         |              |
| Airframe         |                                                           |               |      |             |                 |     |                  |             |                    |         |              |
| CB264            | CB264 - Wings (ATA 57) - Inspection - Winglet Attach      |               | HRS  |             |                 |     |                  |             |                    |         | 0            |
|                  | Joints                                                    |               | AFL  |             |                 |     |                  |             |                    |         | 0            |
|                  |                                                           |               | MOS  |             | 35.4            |     |                  | 31 May 2023 |                    |         |              |
|                  |                                                           |               | MSC  |             |                 |     | -                |             |                    |         |              |
| (982640)         |                                                           |               |      |             |                 |     |                  |             |                    |         |              |
| Airframe         |                                                           |               |      |             |                 |     |                  |             |                    |         |              |
| CB264A           | CB264A - Wings (ATA 57), Inspection - Winglet Attach      |               | HRS  |             | 1452            |     |                  | 1594.1      |                    |         | 0            |
|                  | Joints                                                    |               | AFL  |             | 570             |     |                  | 547         |                    |         | 0            |
|                  |                                                           |               | MOS  |             | 64              |     |                  | 11 Jan 2021 |                    |         |              |
|                  |                                                           |               | MSC  |             |                 |     | -                |             |                    |         |              |
| (982641)         |                                                           |               |      |             |                 |     |                  |             |                    |         |              |
| Airframe         |                                                           |               |      |             |                 |     |                  |             |                    |         |              |
| CB265            | CB265 - Flight Controls (ATA 27) , Modification of Rudder |               | HRS  |             | 1642.8          |     |                  | 1403.3      |                    |         | 0            |
|                  | Trailing Edge (ASC 134)                                   |               | AFL  |             | 682             |     |                  | 435         |                    |         | 0            |
|                  |                                                           |               | MOS  |             | 70.4            |     |                  | 30 Jun 2020 |                    |         |              |
|                  |                                                           |               | MSC  |             |                 |     | -                |             |                    |         |              |
| (982650)         |                                                           |               |      |             |                 |     |                  |             |                    |         |              |
| Airframe         |                                                           |               |      |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                                                                   |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-------------------------------------------------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                                                                   | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                                                                            | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                                                                        |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                                                                                 |               |     |             |                 |     |                  |             |                    |         |              |
| CB266            | CB266 - Navigation (ATA 34) - Inspection - Ahru Connectors                                                                    |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  |                                                                                                                               |               | AFL |             | 315             |     |                  | 802         |                    |         | 0            |
|                  |                                                                                                                               |               | MOS |             | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
|                  |                                                                                                                               |               | MSC |             |                 |     | -                |             |                    |         |              |
| (982660)         |                                                                                                                               |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe         |                                                                                                                               |               |     |             |                 |     |                  |             |                    |         |              |
| CB267            | CB267 - Electrical Wiring Installations (ATA 97) - Inspection - Below-Floors Wiring Installation AT Fuselage Station (FS) 370 |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  |                                                                                                                               |               | AFL |             | 315             |     |                  | 802         |                    |         | 0            |
|                  |                                                                                                                               |               | MOS |             | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
|                  |                                                                                                                               |               | MSC |             |                 |     | -                |             |                    |         |              |
| (982670)         |                                                                                                                               |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe         |                                                                                                                               |               |     |             |                 |     |                  |             |                    |         |              |
| CB268            | CB268 - Nacelles and Pylons (ATA 54) - Inspection - Pylon Wiring Installation for Contact With Pylon Rib Openings             |               | HRS |             | 1452            |     |                  | 1594.1      |                    |         | 0            |
|                  |                                                                                                                               |               | AFL |             | 570             |     |                  | 547         |                    |         | 0            |
|                  |                                                                                                                               |               | MOS |             | 63.9            |     |                  | 14 Jan 2021 |                    |         |              |
|                  |                                                                                                                               |               | MSC |             |                 |     | -                |             |                    |         |              |
| (982680)         |                                                                                                                               |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe         |                                                                                                                               |               |     |             |                 |     |                  |             |                    |         |              |
| CB269            | CB269 - Fuselage Structure (ATA 53) - Inspection - Horizontal Drag Brace Splice Fasteners AT Fuselage Station (FS) 245.5      |               | HRS |             | 1300.7          |     |                  | 1745.4      |                    |         | 0            |
|                  |                                                                                                                               |               | AFL |             | 507             |     |                  | 610         |                    |         | 0            |
|                  |                                                                                                                               |               | MOS |             | 51.8            |     |                  | 18 Jan 2022 |                    |         |              |
|                  |                                                                                                                               |               | MSC |             |                 |     | -                |             |                    |         |              |
| (982690)         |                                                                                                                               |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe         |                                                                                                                               |               |     |             |                 |     |                  |             |                    |         |              |
| CB271            | CB271 - Lighting (ATA 33) - Replacement - Cockpit Lighting Control Panels - Connector Plate Retaining Screws                  |               | HRS |             | 1452            |     |                  | 1594.1      |                    |         | 0            |
|                  |                                                                                                                               |               | AFL |             | 570             |     |                  | 547         |                    |         | 0            |
|                  |                                                                                                                               |               | MOS |             | 63.9            |     |                  | 15 Jan 2021 |                    |         |              |
|                  |                                                                                                                               |               | MSC |             |                 |     | -                |             |                    |         |              |
| (982710)         |                                                                                                                               |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe         |                                                                                                                               |               |     |             |                 |     |                  |             |                    |         |              |
| CB272            | CB272 - Engine AIR (ATA 75) - Replacement - Stage 5 Handling Bleed Valves (Rolls-Royce Sb-BR700-75-900673)                    |               | HRS |             | 1642.9          |     |                  | 1403.2      | 0                  |         | 0            |
|                  |                                                                                                                               |               | AFL |             | 682             |     |                  | 435         | 0                  |         | 0            |
|                  |                                                                                                                               |               | MOS |             | 70.3            |     |                  | 03 Jul 2020 |                    |         |              |
|                  |                                                                                                                               |               | MSC |             |                 |     | -                |             |                    |         |              |
| (982720)         |                                                                                                                               |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe         |                                                                                                                               |               |     |             |                 |     |                  |             |                    |         |              |



| ATA<br>U=Custom  | Description                                                                                                                   |               | UOM  | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-------------------------------------------------------------------------------------------------------------------------------|---------------|------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                                                                   | Serial Number |      |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                                                                            | SW            |      |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                                                                        |               |      |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                                                                                 |               |      |             |                 |     |                  |             |                    |         |              |
| CB272A           | CB272A - Engine AIR (ATA 75) - Replacement - Stage 5<br>Handling Bleed Valves (Rolls-Royce Sb-BR700-75-<br>900673)            |               | HRS  |             | 1537.8          |     |                  | 1508.3      |                    |         | 0            |
|                  |                                                                                                                               |               | AFL  |             | 625             |     |                  | 492         |                    |         | 0            |
|                  |                                                                                                                               |               | MOS  |             | 66.8            |     |                  | 16 Oct 2020 |                    |         |              |
|                  |                                                                                                                               |               | MSC  |             |                 |     | -                |             |                    |         |              |
| (982721)         |                                                                                                                               |               |      |             |                 |     |                  |             |                    |         |              |
| Airframe         |                                                                                                                               |               |      |             |                 |     |                  |             |                    |         |              |
| CB275            | CB275 - Electrical Wiring Installations (ATA 97) -<br>Inspection - Wiring Installation Below Baggage Floor                    |               | HRS  |             | 1452            |     |                  | 1594.1      |                    |         | 0            |
|                  |                                                                                                                               |               | AFL  |             | 570             |     |                  | 547         |                    |         | 0            |
|                  |                                                                                                                               |               | MOS  |             | 64              |     |                  | 12 Jan 2021 |                    |         |              |
|                  |                                                                                                                               |               | MSC  |             |                 |     | -                |             |                    |         |              |
| (982750)         |                                                                                                                               |               |      |             |                 |     |                  |             |                    |         |              |
| Airframe         |                                                                                                                               |               |      |             |                 |     |                  |             |                    |         |              |
| CB276            | CB276 - Flight Controls (ATA 27) - Flight Control<br>Computer (FCC) Software Update V10.1 (ASC 135)                           |               | HRS  |             | 1452            |     |                  | 1594.1      |                    |         | 0            |
|                  |                                                                                                                               |               | AFL  |             | 570             |     |                  | 547         |                    |         | 0            |
|                  |                                                                                                                               |               | MOS  |             | 63.5            |     |                  | 27 Jan 2021 |                    |         |              |
|                  |                                                                                                                               |               | MSC  |             |                 |     | -                |             |                    |         |              |
| (982760)         |                                                                                                                               |               |      |             |                 |     |                  |             |                    |         |              |
| Airframe         |                                                                                                                               |               |      |             |                 |     |                  |             |                    |         |              |
| CB277            | CB277 - FIRE Protection (ATA 26) - Modification - Engine<br>FIRE Extinguishing Bottle Cartridge Wiring (ASC 122)              |               | HRS  |             | 1300.7          |     |                  | 1745.4      |                    |         | 0            |
|                  |                                                                                                                               |               | AFL  |             | 507             |     |                  | 610         |                    |         | 0            |
|                  |                                                                                                                               |               | MOS  |             | 51.4            |     |                  | 30 Jan 2022 |                    |         |              |
|                  |                                                                                                                               |               | MSC  |             |                 |     | -                |             |                    |         |              |
| (982770)         |                                                                                                                               |               |      |             |                 |     |                  |             |                    |         |              |
| Airframe         |                                                                                                                               |               |      |             |                 |     |                  |             |                    |         |              |
| CB277A           | CB277A - CB277A - FIRE Protection (ATA 26) -<br>Modification - Engine FIRE Extinguishing Bottle Cartridge<br>Wiring (ASC 122) |               | HRS  |             | 919             |     |                  | 2127.1      |                    |         | 0            |
|                  |                                                                                                                               |               | AFL  |             | 371             |     |                  | 746         |                    |         | 0            |
|                  |                                                                                                                               |               | MOS  |             | 38.6            |     |                  | 23 Feb 2023 |                    |         |              |
|                  |                                                                                                                               |               | MSC  |             |                 |     | -                |             |                    |         |              |
| (982771)         |                                                                                                                               |               |      |             |                 |     |                  |             |                    |         |              |
| Airframe         |                                                                                                                               |               |      |             |                 |     |                  |             |                    |         |              |
| CB278            | CB278 - Wings (ATA 57) - Inspection - Unprimed Wing<br>Skin Fasteners Inboard of Rear Beam Station (Rbs) 62                   |               | HRS  |             |                 |     |                  |             |                    |         | 0            |
|                  |                                                                                                                               |               | AFL  |             |                 |     |                  |             |                    |         | 0            |
|                  |                                                                                                                               |               | DATE |             |                 |     |                  |             |                    |         |              |
|                  |                                                                                                                               |               | MSC  |             |                 |     | -                |             |                    |         |              |
| (982780)         |                                                                                                                               |               |      |             |                 |     |                  |             |                    |         |              |
| Airframe         |                                                                                                                               |               |      |             |                 |     |                  |             |                    |         |              |
| CB278A           | CB278A - Wings (ATA 57) - Inspection - Unprimed Wing<br>Skin Fasteners Inboard of Rear Beam Station (Rbs) 62                  |               | HRS  |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                  |                                                                                                                               |               | AFL  |             | 315             |     |                  | 802         |                    |         | 0            |
|                  |                                                                                                                               |               | MOS  |             | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
|                  |                                                                                                                               |               | MSC  |             |                 |     | -                |             |                    |         |              |
| (982781)         |                                                                                                                               |               |      |             |                 |     |                  |             |                    |         |              |
| Airframe         |                                                                                                                               |               |      |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom                        | Description                                                                                                                     |               | UOM  | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|----------------------------------------|---------------------------------------------------------------------------------------------------------------------------------|---------------|------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                        | Part Number                                                                                                                     | Serial Number |      |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position                       | HW                                                                                                                              | SW            |      |             |                 |     |                  |             |                    |         | Manufacturer |
|                                        | MM Ref                                                                                                                          |               |      |             |                 |     |                  |             |                    |         | Date Type    |
|                                        | Ops Number(s)                                                                                                                   |               |      |             |                 |     |                  |             |                    |         |              |
| CB279<br><br>(982790)<br><br>Airframe  | CB279 - Landing Gear (ATA 32) - Inspection - Main<br>Landing Gear Sponson Beam Upper Inboard Shim                               |               | HRS  |             |                 |     |                  |             |                    |         | 0            |
|                                        |                                                                                                                                 |               | AFL  |             |                 |     |                  |             |                    |         | 0            |
|                                        |                                                                                                                                 |               | DATE |             |                 |     |                  |             |                    |         |              |
|                                        |                                                                                                                                 |               | MSC  |             |                 |     | -                |             |                    |         |              |
| CB279A<br><br>(982791)<br><br>Airframe | CB279A - Landing Gear (ATA 32) - Inspection - Main<br>Landing Gear Sponson Beam Upper Inboard Shim                              |               | HRS  |             | 1300.7          |     |                  | 1745.4      |                    |         | 0            |
|                                        |                                                                                                                                 |               | AFL  |             | 507             |     |                  | 610         |                    |         | 0            |
|                                        |                                                                                                                                 |               | MOS  |             | 51.1            |     |                  | 08 Feb 2022 |                    |         |              |
|                                        |                                                                                                                                 |               | MSC  |             |                 |     | -                |             |                    |         |              |
| CB280<br><br>(982800)<br><br>Airframe  | CB280 - Stabilizers (ATA 55) - Inspection - Right Side<br>Horizontal Stabilizer - Clamp Installation (Fokker Sb Gf-20<br>-0011) |               | HRS  |             |                 |     |                  |             |                    |         | 0            |
|                                        |                                                                                                                                 |               | AFL  |             |                 |     |                  |             |                    |         | 0            |
|                                        |                                                                                                                                 |               | DATE |             |                 |     |                  |             |                    |         |              |
|                                        |                                                                                                                                 |               | MSC  |             |                 |     | -                |             |                    |         |              |
| CB281<br><br>(982810)<br><br>Airframe  | CB281 - CB281 - FIRE Protection (ATA 26) - Inspection -<br>Left FIRE Bottle/APU Cartridge Wire Harness Shield<br>Ground         |               | HRS  |             |                 |     |                  |             |                    |         | 0            |
|                                        |                                                                                                                                 |               | AFL  |             |                 |     |                  |             |                    |         | 0            |
|                                        |                                                                                                                                 |               | DATE |             |                 |     |                  |             |                    |         |              |
|                                        |                                                                                                                                 |               | MSC  |             |                 |     | -                |             |                    |         |              |
| CB282<br><br>(982820)<br><br>Airframe  | CB282 - CB282 - Wings (ATA 57) - Replacement - Flap<br>Track B Close-Out Skin                                                   |               | HRS  |             |                 |     |                  |             |                    |         | 0            |
|                                        |                                                                                                                                 |               | AFL  |             |                 |     |                  |             |                    |         | 0            |
|                                        |                                                                                                                                 |               | DATE |             |                 |     |                  |             |                    |         |              |
|                                        |                                                                                                                                 |               | MSC  |             |                 |     | -                |             |                    |         |              |
| CB282A<br><br>(982821)<br><br>Airframe | CB282A - CB282A - Wings (ATA 57) - Replacement - Flap<br>Track B Close-Out Skin                                                 |               | HRS  |             |                 |     |                  |             |                    |         | 0            |
|                                        |                                                                                                                                 |               | AFL  |             |                 |     |                  |             |                    |         | 0            |
|                                        |                                                                                                                                 |               | MOS  |             |                 |     |                  |             |                    |         |              |
|                                        |                                                                                                                                 |               | MSC  |             |                 |     | -                |             |                    |         |              |
| CB282B<br><br>(982822)<br><br>Airframe | CB282B - CB282B - Wings (ATA 57) - Replacement - Flap<br>Track B Close-Out Skin                                                 |               | HRS  |             |                 |     |                  |             |                    |         | 0            |
|                                        |                                                                                                                                 |               | AFL  |             |                 |     |                  |             |                    |         | 0            |
|                                        |                                                                                                                                 |               | MOS  |             |                 |     |                  |             |                    |         |              |
|                                        |                                                                                                                                 |               | MSC  |             |                 |     | -                |             |                    |         |              |

| ATA<br>U=Custom                        | Description                                                                                                                                     |               | UOM  | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|----------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------|---------------|------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                        | Part Number                                                                                                                                     | Serial Number |      |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position                       | HW                                                                                                                                              | SW            |      |             |                 |     |                  |             |                    |         | Manufacturer |
|                                        | MM Ref                                                                                                                                          |               |      |             |                 |     |                  |             |                    |         | Date Type    |
|                                        | Ops Number(s)                                                                                                                                   |               |      |             |                 |     |                  |             |                    |         |              |
| CB282C<br><br>(982823)<br><br>Airframe | CB282C - CB282C - Wings (ATA 57) - Replacement - Flap<br>Track B Close-Out Skin                                                                 |               | HRS  |             | 953.3           |     |                  | 2092.8      |                    |         | 0            |
|                                        |                                                                                                                                                 |               | AFL  |             | 376             |     |                  | 741         |                    | 0       |              |
|                                        |                                                                                                                                                 |               | MOS  |             | 39              |     |                  | 10 Feb 2023 |                    |         |              |
|                                        |                                                                                                                                                 |               | MSC  |             |                 |     | -                |             |                    |         |              |
| CB283<br><br>(982830)<br><br>Airframe  | CB283 - CB283 - Engine Fuel & Control (ATA 73) -<br>Modification - Engine Electronic Controller (Eec) - K10.1<br>Software Upgrade (ASC 138)     |               | HRS  |             | 1300.7          |     |                  | 1745.4      |                    |         | 0            |
|                                        |                                                                                                                                                 |               | AFL  |             | 507             |     |                  | 610         |                    | 0       |              |
|                                        |                                                                                                                                                 |               | MOS  |             | 51.4            |     |                  | 30 Jan 2022 |                    |         |              |
|                                        |                                                                                                                                                 |               | MSC  |             |                 |     | -                |             |                    |         |              |
| CB283A<br><br>(982831)<br><br>Airframe | CB283A - CB283A - Engine Fuel and Control (ATA 73) -<br>Modification - Engine Electronic Controller (Eec) - K10.1<br>Software Upgrade (ASC 138) |               | HRS  |             | 1301.1          |     |                  | 1745        |                    |         | 0            |
|                                        |                                                                                                                                                 |               | AFL  |             | 507             |     |                  | 610         |                    | 0       |              |
|                                        |                                                                                                                                                 |               | MOS  |             | 51.1            |     |                  | 08 Feb 2022 |                    |         |              |
|                                        |                                                                                                                                                 |               | MSC  |             |                 |     | -                |             |                    |         |              |
| CB285<br><br>(982850)<br><br>Airframe  | CB285 - Communications (ATA 23) - Modification -<br>Jetwave System BLV8.1 Software Release (Honeywell Sb<br>Jetwave-23-0009)                    |               | HRS  |             |                 |     |                  |             |                    |         | 0            |
|                                        |                                                                                                                                                 |               | AFL  |             |                 |     |                  |             |                    |         | 0            |
|                                        |                                                                                                                                                 |               | MOS  |             |                 |     |                  |             |                    |         |              |
|                                        |                                                                                                                                                 |               | MSC  |             |                 |     | -                |             |                    |         |              |
| CB285A<br><br>(982851)<br><br>Airframe | CB285A - Communications (ATA 23) - Modification -<br>Jetwave System BLV8.1 Software Release (Honeywell Sb<br>Jetwave-23-0009)                   |               | HRS  |             |                 |     |                  |             |                    |         | 0            |
|                                        |                                                                                                                                                 |               | AFL  |             |                 |     |                  |             |                    |         | 0            |
|                                        |                                                                                                                                                 |               | DATE |             |                 |     |                  |             |                    |         |              |
|                                        |                                                                                                                                                 |               | MSC  |             |                 |     | -                |             |                    |         |              |
| CB286<br><br>(982860)<br><br>Airframe  | CB286 - CB286 - Fuselage Structure (ATA 53) Inspection<br>- Wiring Mounting and Bracket Installation AT FS 942.5                                |               | HRS  |             | 994.2           |     |                  | 2051.9      |                    |         | 0            |
|                                        |                                                                                                                                                 |               | AFL  |             | 392             |     |                  | 725         |                    | 0       |              |
|                                        |                                                                                                                                                 |               | MOS  |             | 40.9            |     |                  | 14 Dec 2022 |                    |         |              |
|                                        |                                                                                                                                                 |               | MSC  |             |                 |     | -                |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                                                                             |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-----------------------------------------------------------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                                                                             | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                                                                                      | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                                                                                  |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                                                                                           |               |     |             |                 |     |                  |             |                    |         |              |
| CB287            | CB287 - CB287 - Stabilizers (ATA 55) - Inspection - Horizontal Stabilizer Wiring Installation (Fokker Sb Gf-19-0015)                    |               | HRS |             | 994.2           |     |                  | 2051.9      |                    |         | 0            |
|                  |                                                                                                                                         |               | AFL |             | 392             |     |                  | 725         |                    |         | 0            |
|                  |                                                                                                                                         |               | MOS |             | 40.8            |     |                  | 16 Dec 2022 |                    |         |              |
|                  |                                                                                                                                         |               | MSC |             |                 |     | -                |             |                    |         |              |
| (982870)         |                                                                                                                                         |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe         |                                                                                                                                         |               |     |             |                 |     |                  |             |                    |         |              |
| CB288            | CB288 - CB288 - Flight Controls (ATA 27) - Inspection - Fly-By-Wire Harness - Clamp Installation AT Fuselage Stations 733.2 and 1019.19 |               | HRS |             |                 |     |                  |             |                    |         | 0            |
|                  |                                                                                                                                         |               | AFL |             |                 |     |                  |             |                    |         | 0            |
|                  |                                                                                                                                         |               | MOS |             |                 |     |                  |             |                    |         |              |
|                  |                                                                                                                                         |               | MSC |             |                 |     | -                |             |                    |         |              |
| (982880)         |                                                                                                                                         |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe         |                                                                                                                                         |               |     |             |                 |     |                  |             |                    |         |              |
| CB289            | CB289 - Powerplant (ATA 71) - Inspection - Engine Cowl Hinge Lines (Rolls-Royce Sb-BR700-71-900701)                                     |               | HRS |             |                 |     |                  |             |                    |         | 0            |
|                  |                                                                                                                                         |               | AFL |             |                 |     |                  |             |                    |         | 0            |
|                  |                                                                                                                                         |               | MOS |             |                 |     |                  |             |                    |         |              |
|                  |                                                                                                                                         |               | MSC |             |                 |     | -                |             |                    |         |              |
| (982890)         |                                                                                                                                         |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe         |                                                                                                                                         |               |     |             |                 |     |                  |             |                    |         |              |
| CB289A           | CB289A - Powerplant (ATA 71), Inspection - Engine Cowl Hinge Lines (Rolls-Royce Sb-BR700-71-900701)                                     |               | HRS |             |                 |     |                  |             |                    |         | 0            |
|                  |                                                                                                                                         |               | AFL |             |                 |     |                  |             |                    |         | 0            |
|                  |                                                                                                                                         |               | MOS |             |                 |     |                  |             |                    |         |              |
|                  |                                                                                                                                         |               | MSC |             |                 |     | -                |             |                    |         |              |
| (982891)         |                                                                                                                                         |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe         |                                                                                                                                         |               |     |             |                 |     |                  |             |                    |         |              |
| CB289B           | CB289B - Powerplant (ATA 71), Inspection - Engine Cowl Hinge Lines (Rolls-Royce Sb-BR700-71-900701)                                     |               | HRS |             |                 |     |                  |             |                    |         | 0            |
|                  |                                                                                                                                         |               | AFL |             |                 |     |                  |             |                    |         | 0            |
|                  |                                                                                                                                         |               | MOS |             |                 |     |                  |             |                    |         |              |
|                  |                                                                                                                                         |               | MSC |             |                 |     | -                |             |                    |         |              |
| (982892)         |                                                                                                                                         |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe         |                                                                                                                                         |               |     |             |                 |     |                  |             |                    |         |              |
| CB289C           | CB289C - Powerplant (ATA 71), Inspection - Engine Cowl Hinge Lines (Rolls-Royce Sb-BR700-71-900701)                                     |               | HRS |             | 953.3           |     |                  | 2092.8      |                    |         | 0            |
|                  |                                                                                                                                         |               | AFL |             | 376             |     |                  | 741         |                    |         | 0            |
|                  |                                                                                                                                         |               | MOS |             | 39              |     |                  | 10 Feb 2023 |                    |         |              |
|                  |                                                                                                                                         |               | MSC |             |                 |     | -                |             |                    |         |              |
| (982893)         |                                                                                                                                         |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe         |                                                                                                                                         |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom                        | Description                                                                                                                |               | UOM  | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|----------------------------------------|----------------------------------------------------------------------------------------------------------------------------|---------------|------|-------------|-----------------|-----|------------------|----------|---------------------|---------|--------------|
|                                        | Part Number                                                                                                                | Serial Number |      |             |                 |     |                  |          |                     |         | Approx Price |
| Logbook Position                       | HW                                                                                                                         | SW            |      |             |                 |     |                  |          |                     |         | Manufacturer |
|                                        | MM Ref                                                                                                                     |               |      |             |                 |     |                  |          |                     |         | Date Type    |
|                                        | Ops Number(s)                                                                                                              |               |      |             |                 |     |                  |          |                     |         |              |
| CB289D<br><br>(982894)<br><br>Airframe | Powerplant (ATA 71) - Inspection - Engine Cowl Hinge Lines (Rolls-Royce Sb-BR700-71-900701), Customer Bulletin (Mandatory) |               | HRS  |             |                 |     |                  |          |                     |         | 0            |
|                                        |                                                                                                                            |               | AFL  |             |                 |     |                  |          |                     |         | 0            |
|                                        |                                                                                                                            |               | MOS  | 28.6        |                 |     | 22 Dec 2023      |          |                     |         |              |
|                                        |                                                                                                                            |               | MSC  |             |                 |     | -                |          |                     |         |              |
| CB290<br><br>(982900)<br><br>Airframe  | CB290 - CB290 - Flight Controls (ATA 27) - Inspection - Flap Track B Outboard Roller Fitting Hardware                      |               | HRS  |             |                 |     |                  |          |                     |         | 0            |
|                                        |                                                                                                                            |               | AFL  |             |                 |     |                  |          |                     |         | 0            |
|                                        |                                                                                                                            |               | MOS  |             |                 |     |                  |          |                     |         |              |
|                                        |                                                                                                                            |               | MSC  |             |                 |     | -                |          |                     |         |              |
| CB291<br><br>(982910)<br><br>Airframe  | CB291 - CB291 - Electrical Wiring Installations (ATA 97), Inspection - Vertical Fin Connectors                             |               | HRS  |             |                 |     |                  |          |                     |         | 0            |
|                                        |                                                                                                                            |               | AFL  |             |                 |     |                  |          |                     |         | 0            |
|                                        |                                                                                                                            |               | MOS  |             |                 |     |                  |          |                     |         |              |
|                                        |                                                                                                                            |               | MSC  |             |                 |     | -                |          |                     |         |              |
| CB292<br><br>(982920)<br><br>Airframe  | CB292 - CB292 - Fuselage Structure (ATA 53) - Inspection - Auxiliary Power Unit Enclosure                                  |               | HRS  |             |                 |     |                  |          |                     |         | 0            |
|                                        |                                                                                                                            |               | AFL  |             |                 |     |                  |          |                     |         | 0            |
|                                        |                                                                                                                            |               | MOS  |             |                 |     |                  |          |                     |         |              |
|                                        |                                                                                                                            |               | MSC  |             |                 |     | -                |          |                     |         |              |
| CB293<br><br>(982930)<br><br>Airframe  | CB293 - Fuel (ATA 28) Inspection - Fuel Tank Distribution System Components - Selant Application                           |               | HRS  |             |                 |     |                  |          |                     |         | 0            |
|                                        |                                                                                                                            |               | AFL  |             |                 |     |                  |          |                     |         | 0            |
|                                        |                                                                                                                            |               | MOS  |             |                 |     |                  |          |                     |         |              |
|                                        |                                                                                                                            |               | MSC  |             |                 |     | -                |          |                     |         |              |
| CB293A<br><br>(982931)<br><br>Airframe | CB293A - Fuel (ATA 28) - Inspection - Fuel Tank Distribution System Components - Sealant Application, Customer Bulletin    |               | HRS  |             |                 |     |                  |          |                     |         | 0            |
|                                        |                                                                                                                            |               | AFL  |             |                 |     |                  |          |                     |         | 0            |
|                                        |                                                                                                                            |               | MOS  |             |                 |     |                  |          |                     |         |              |
|                                        |                                                                                                                            |               | MSC  |             |                 |     | -                |          |                     |         |              |
| CB293B<br><br>(982932)<br><br>Airframe | CB293B - Fuel (ATA 28), Inspection - Fuel Tank Distribution System Components - Sealant Application                        |               | HRS  |             |                 |     |                  |          |                     |         | 0            |
|                                        |                                                                                                                            |               | AFL  |             |                 |     |                  |          |                     |         | 0            |
|                                        |                                                                                                                            |               | DATE |             |                 |     |                  |          |                     |         |              |
|                                        |                                                                                                                            |               | MSC  |             |                 |     | -                |          |                     |         |              |

| ATA<br>U=Custom                        | Description                                                                                                                 |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|----------------------------------------|-----------------------------------------------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                        | Part Number                                                                                                                 | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position                       | HW                                                                                                                          | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                        | MM Ref                                                                                                                      |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                                        | Ops Number(s)                                                                                                               |               |     |             |                 |     |                  |             |                    |         |              |
| CB293C<br><br>(982933)<br><br>Airframe | CB293C - Fuel (ATA 28), Inspection - Fuel Tank<br>Distribution System Components - Sealant Application                      |               | HRS |             |                 |     |                  |             |                    |         | 0            |
|                                        |                                                                                                                             |               | AFL |             |                 |     |                  |             |                    |         | 0            |
|                                        |                                                                                                                             |               | MOS |             |                 |     |                  |             |                    |         |              |
|                                        |                                                                                                                             |               | MSC |             |                 |     | -                |             |                    |         |              |
| CB294<br><br>(982940)<br><br>Airframe  | CB294 - CB294 - Inspection – Engine FIRE Bottle<br>Thermal Relief Discharge Port                                            |               | HRS |             | 994.2           |     |                  | 2051.9      |                    |         | 0            |
|                                        |                                                                                                                             |               | AFL |             | 392             |     |                  | 725         |                    |         | 0            |
|                                        |                                                                                                                             |               | MOS |             | 41.3            |     |                  | 01 Dec 2022 |                    |         |              |
|                                        |                                                                                                                             |               | MSC |             |                 |     | -                |             |                    |         |              |
| CB295<br><br>(982950)<br><br>Airframe  | CB295 - CB295 - Doors (ATA 52) - Inspection - Main<br>Entrance Door Electrical Harness Installation                         |               | HRS |             | 994.2           |     |                  | 2051.9      |                    |         | 0            |
|                                        |                                                                                                                             |               | AFL |             | 392             |     |                  | 725         |                    |         | 0            |
|                                        |                                                                                                                             |               | MOS |             | 40.8            |     |                  | 17 Dec 2022 |                    |         |              |
|                                        |                                                                                                                             |               | MSC |             |                 |     | -                |             |                    |         |              |
| CB296<br><br>(982960)<br><br>Airframe  | CB296 - Fuselage (ATA 53) - Inspection - Electrical<br>Connector Identification Decal - FS 224                              |               | HRS |             | 730.5           |     |                  | 2315.6      |                    |         | 0            |
|                                        |                                                                                                                             |               | AFL |             | 315             |     |                  | 802         |                    |         | 0            |
|                                        |                                                                                                                             |               | MOS |             | 28.7            |     |                  | 21 Dec 2023 |                    |         |              |
|                                        |                                                                                                                             |               | MSC |             |                 |     | -                |             |                    |         |              |
| CB297<br><br>(982970)<br><br>Airframe  | CB297 - CB297 - Flight Controls (ATA 27) - Inspection -<br>Horizontal Stabilizer Part Number                                |               | HRS |             | 706             |     |                  | 2340.1      |                    |         | 0            |
|                                        |                                                                                                                             |               | AFL |             | 306             |     |                  | 811         |                    |         | 0            |
|                                        |                                                                                                                             |               | MOS |             | 27.7            |     |                  | 19 Jan 2024 |                    |         |              |
|                                        |                                                                                                                             |               | MSC |             |                 |     | -                |             |                    |         |              |
| Notes: N/A by serial number            |                                                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |
| CB298<br><br>(982980)<br><br>Airframe  | CB298 - Electrical Power (ATA 24) - Inspection - Aircraft<br>Main Batteries (Saft SB0323), Customer Bulletin<br>(Mandatory) |               | HRS |             | 706             |     |                  | 2340.1      |                    |         | 0            |
|                                        |                                                                                                                             |               | AFL |             | 306             |     |                  | 811         |                    |         | 0            |
|                                        |                                                                                                                             |               | MOS |             | 27.7            |     |                  | 19 Jan 2024 |                    |         |              |
|                                        |                                                                                                                             |               | MSC |             |                 |     | -                |             |                    |         |              |
| Notes: N/A by serial number            |                                                                                                                             |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                                                                                                          |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(* =Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|----------|----------------------|---------|--------------|
|                  | Part Number                                                                                                                                                          | Serial Number |     |             |                 |     |                  |          |                      |         | Approx Price |
| Logbook Position | HW                                                                                                                                                                   | SW            |     |             |                 |     |                  |          |                      |         | Manufacturer |
|                  | MM Ref                                                                                                                                                               |               |     |             |                 |     |                  |          |                      |         | Date Type    |
|                  | Ops Number(s)                                                                                                                                                        |               |     |             |                 |     |                  |          |                      |         |              |
| CB298A           | CB298A - Electrical Power (ATA 24) - Inspection - Aircraft Main Batteries (Saft SB0323), Customer Bulletin (Mandatory)                                               |               | HRS |             |                 |     |                  |          |                      |         | 0            |
|                  |                                                                                                                                                                      |               | AFL |             |                 |     |                  |          | 0                    |         |              |
|                  |                                                                                                                                                                      |               | MOS | 29.8        |                 |     | 16 Nov 2023      |          |                      |         |              |
|                  |                                                                                                                                                                      |               | MSC |             |                 | -   |                  |          |                      |         |              |
| (982981)         |                                                                                                                                                                      |               |     |             |                 |     |                  |          |                      |         |              |
| Airframe         |                                                                                                                                                                      |               |     |             |                 |     |                  |          |                      |         |              |
| CB298B           | Electrical Power (ATA 24) - Inspection - Aircraft Main Batteries (Saft SB0323), Customer Bulletin (Mandatory)                                                        |               | HRS |             |                 |     |                  |          |                      |         | 0            |
|                  |                                                                                                                                                                      |               | AFL |             |                 |     |                  |          | 0                    |         |              |
|                  |                                                                                                                                                                      |               | MOS | 28.6        |                 |     | 22 Dec 2023      |          |                      |         |              |
|                  |                                                                                                                                                                      |               | MSC |             |                 | -   |                  |          |                      |         |              |
| (982982)         |                                                                                                                                                                      |               |     |             |                 |     |                  |          |                      |         |              |
| Airframe         |                                                                                                                                                                      |               |     |             |                 |     |                  |          |                      |         |              |
| CB299            | CB299 - Information Systems (ATA 46) - Modification - Aircraft Health and Trend Monitoring System (Ahtms) - Software Update (ASC 140), Customer Bulletin (Mandatory) |               | HRS |             | 562.4           |     |                  | 2483.7   |                      |         | 0            |
|                  |                                                                                                                                                                      |               | AFL |             | 217             |     | 900              |          | 0                    |         |              |
|                  |                                                                                                                                                                      |               | MOS | 17.1        |                 |     | 09 Dec 2024      |          |                      |         |              |
|                  |                                                                                                                                                                      |               | MSC |             |                 | -   |                  |          |                      |         |              |
| (982990)         |                                                                                                                                                                      |               |     |             |                 |     |                  |          |                      |         |              |
| Airframe         |                                                                                                                                                                      |               |     |             |                 |     |                  |          |                      |         |              |
| CB300            | CB300 - Landing Gear (ATA 32) - Inspection - Nose Landing Gear Control Manifold Connector, Customer Bulletin (Mandatory)                                             |               | HRS |             |                 |     |                  |          |                      |         | 0            |
|                  |                                                                                                                                                                      |               | AFL |             |                 |     |                  |          | 0                    |         |              |
|                  |                                                                                                                                                                      |               | MOS | 32.9        |                 |     | 15 Aug 2023      |          |                      |         |              |
|                  |                                                                                                                                                                      |               | MSC |             |                 | -   |                  |          |                      |         |              |
| (983000)         |                                                                                                                                                                      |               |     |             |                 |     |                  |          |                      |         |              |
| Airframe         |                                                                                                                                                                      |               |     |             |                 |     |                  |          |                      |         |              |
| CB300A           | CB300A - Landing Gear (ATA 32) - Inspection - Nose Landing Gear Control Manifold Connector, Customer Bulletin (Mandatory)                                            |               | HRS |             |                 |     |                  |          |                      |         | 0            |
|                  |                                                                                                                                                                      |               | AFL |             |                 |     |                  |          | 0                    |         |              |
|                  |                                                                                                                                                                      |               | MOS | 31.8        |                 |     | 18 Sep 2023      |          |                      |         |              |
|                  |                                                                                                                                                                      |               | MSC |             |                 | -   |                  |          |                      |         |              |
| (983001)         |                                                                                                                                                                      |               |     |             |                 |     |                  |          |                      |         |              |
| Airframe         |                                                                                                                                                                      |               |     |             |                 |     |                  |          |                      |         |              |
| CB301            | CB301 - Electrical Power (ATA 24) - Inspection - Cockpit Electrical Wire Harness Terminations, Customer Bulletin (Mandatory)                                         |               | HRS |             |                 |     |                  |          |                      |         | 0            |
|                  |                                                                                                                                                                      |               | AFL |             |                 |     |                  |          | 0                    |         |              |
|                  |                                                                                                                                                                      |               | MOS | 31.8        |                 |     | 18 Sep 2023      |          |                      |         |              |
|                  |                                                                                                                                                                      |               | MSC |             |                 | -   |                  |          |                      |         |              |
| (983010)         |                                                                                                                                                                      |               |     |             |                 |     |                  |          |                      |         |              |
| Airframe         |                                                                                                                                                                      |               |     |             |                 |     |                  |          |                      |         |              |

| ATA<br>U=Custom  | Description                                                                                                                                                     |               | UOM | Times Since | Time<br>Accrued | Adj         | Required<br>Freq | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-------------|------------------|----------|--------------------|---------|--------------|
|                  | Part Number                                                                                                                                                     | Serial Number |     |             |                 |             |                  |          |                    |         | Approx Price |
| Logbook Position | HW                                                                                                                                                              | SW            |     |             |                 |             |                  |          |                    |         | Manufacturer |
|                  | MM Ref                                                                                                                                                          |               |     |             |                 |             |                  |          |                    |         | Date Type    |
|                  | Ops Number(s)                                                                                                                                                   |               |     |             |                 |             |                  |          |                    |         |              |
| CB302            | CB302 - Flight Controls (ATA 27) - Inspection - Flap Actuator Attach Fitting Hardware, Customer Bulletin (Mandatory)                                            |               | HRS |             |                 |             |                  |          |                    |         | 0            |
|                  |                                                                                                                                                                 |               | AFL |             |                 |             |                  |          | 0                  |         |              |
|                  |                                                                                                                                                                 |               | MOS | 31.8        |                 |             | 18 Sep 2023      |          |                    |         |              |
|                  |                                                                                                                                                                 |               | MSC |             |                 | -           |                  |          |                    |         |              |
| (983020)         |                                                                                                                                                                 |               |     |             |                 |             |                  |          |                    |         |              |
| Airframe         |                                                                                                                                                                 |               |     |             |                 |             |                  |          |                    |         |              |
| CB303            | CB303 - Navigation (ATA 34) - Modification - Weather Radar System Processor V4 Software Release (Honeywell Sb 930-1003-34-0008), Customer Bulletin (Mandatory)  |               | HRS |             | 730.5           |             |                  | 2315.6   |                    |         | 0            |
|                  |                                                                                                                                                                 |               | AFL |             | 315             |             | 802              |          | 0                  |         |              |
|                  |                                                                                                                                                                 |               | MOS | 28.7        |                 | 21 Dec 2023 |                  |          |                    |         |              |
|                  |                                                                                                                                                                 |               | MSC |             |                 | -           |                  |          |                    |         |              |
| (983030)         |                                                                                                                                                                 |               |     |             |                 |             |                  |          |                    |         |              |
| Airframe         |                                                                                                                                                                 |               |     |             |                 |             |                  |          |                    |         |              |
| CB303A           | CB303A - Navigation (ATA 34) - Modification - Weather Radar System Processor V4 Software Release (Honeywell Sb 930-1003-34-0008), Customer Bulletin (Mandatory) |               | HRS |             | 699.8           |             |                  | 2346.3   |                    |         | 0            |
|                  |                                                                                                                                                                 |               | AFL |             | 302             |             | 815              |          | 0                  |         |              |
|                  |                                                                                                                                                                 |               | MOS | 26.7        |                 | 19 Feb 2024 |                  |          |                    |         |              |
|                  |                                                                                                                                                                 |               | MSC |             |                 | -           |                  |          |                    |         |              |
| (983031)         |                                                                                                                                                                 |               |     |             |                 |             |                  |          |                    |         |              |
| Airframe         |                                                                                                                                                                 |               |     |             |                 |             |                  |          |                    |         |              |
| CB304            | CB304 - Equipment and Furnishings (ATA 25) - Installation - Ebha Pdb Terminal Bracket Cover (ASC 146), Customer Bulletin (Mandatory)                            |               | HRS |             | 562.4           |             |                  | 2483.7   |                    |         | 0            |
|                  |                                                                                                                                                                 |               | AFL |             | 217             |             | 900              |          | 0                  |         |              |
|                  |                                                                                                                                                                 |               | MOS | 17.2        |                 | 05 Dec 2024 |                  |          |                    |         |              |
|                  |                                                                                                                                                                 |               | MSC |             |                 | -           |                  |          |                    |         |              |
| (983040)         |                                                                                                                                                                 |               |     |             |                 |             |                  |          |                    |         |              |
| Airframe         |                                                                                                                                                                 |               |     |             |                 |             |                  |          |                    |         |              |
| CB305            | CB305 - Communications (ATA 23) - Replacement - Satellite Data Units (Sdu) DL150-00, Customer Bulletin (Mandatory)                                              |               | HRS |             |                 |             |                  |          |                    |         | 0            |
|                  |                                                                                                                                                                 |               | AFL |             |                 |             |                  |          | 0                  |         |              |
|                  |                                                                                                                                                                 |               | MOS | 28.6        |                 | 22 Dec 2023 |                  |          |                    |         |              |
|                  |                                                                                                                                                                 |               | MSC |             |                 | -           |                  |          |                    |         |              |
| (983050)         |                                                                                                                                                                 |               |     |             |                 |             |                  |          |                    |         |              |
| Airframe         |                                                                                                                                                                 |               |     |             |                 |             |                  |          |                    |         |              |



| ATA<br>U=Custom                                                                                                                                                                                          | Description                                                |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                                                                                                                                                                                          | Part Number                                                | Serial Number |     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position                                                                                                                                                                                         | HW                                                         | SW            |     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                                                                                                                                                                                          | MM Ref                                                     |               |     |             |                 |     |                  |             |                    |         | Date Type    |
|                                                                                                                                                                                                          | Ops Number(s)                                              |               |     |             |                 |     |                  |             |                    |         |              |
| CB306                                                                                                                                                                                                    | CB306 - Navigation (ATA 34) Inspection - Ahru              |               | HRS |             | 562.4           |     |                  | 2483.7      |                    |         | 0            |
|                                                                                                                                                                                                          | Connectors With Pitch and Roll Information Recorded and    |               | AFL |             | 217             |     |                  | 900         |                    |         | 0            |
|                                                                                                                                                                                                          | the Installation of Ahru Labels ASC 144, Customer Bulletin |               | MOS |             | 17.4            |     |                  | 29 Nov 2024 |                    |         |              |
|                                                                                                                                                                                                          | (Mandatory)                                                |               | MSC |             |                 |     | -                |             |                    |         |              |
| (983060)                                                                                                                                                                                                 |                                                            |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                                                                                                                                                                                                 |                                                            |               |     |             |                 |     |                  |             |                    |         |              |
| CB307                                                                                                                                                                                                    | CB307 - Water/Waste (ATA 38) - Inspection - Forward        |               | HRS |             |                 |     |                  |             |                    |         | 0            |
|                                                                                                                                                                                                          | (Fwd) Water Tank Attachment Clip and Sensor Connector      |               | AFL |             |                 |     |                  |             |                    |         | 0            |
|                                                                                                                                                                                                          | Orientation, Customer Bulletin (Mandatory)                 |               | MOS |             | 22.1            |     |                  | 08 Jul 2024 |                    |         |              |
|                                                                                                                                                                                                          |                                                            |               | MSC |             |                 |     | -                |             |                    |         |              |
| (983070)                                                                                                                                                                                                 |                                                            |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                                                                                                                                                                                                 |                                                            |               |     |             |                 |     |                  |             |                    |         |              |
| CB321                                                                                                                                                                                                    | CB321 - Powerplant (ATA 71) Inspection - Engine Inlet      |               | HRS |             |                 |     |                  |             |                    |         | 0            |
|                                                                                                                                                                                                          | Cowl, Customer Bulletin (Mandatory)                        |               | AFL |             |                 |     |                  |             |                    |         | 0            |
|                                                                                                                                                                                                          |                                                            |               | MOS |             | 13.6            |     |                  | 24 Mar 2025 |                    |         |              |
|                                                                                                                                                                                                          |                                                            |               | MSC |             |                 |     | -                |             |                    |         |              |
| (983210)                                                                                                                                                                                                 |                                                            |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                                                                                                                                                                                                 |                                                            |               |     |             |                 |     |                  |             |                    |         |              |
| CB323                                                                                                                                                                                                    | CB323 - Fuselage (ATA 53) - Modification - Aft Fuselage    |               | HRS |             | 137             |     |                  | 2909.1      |                    |         | 0            |
|                                                                                                                                                                                                          | Water Drainage (ASC 159), Customer Bulletin                |               | AFL |             | 52              |     |                  | 1065        |                    |         | 0            |
|                                                                                                                                                                                                          | (Mandatory)                                                |               | MOS |             | 5.4             |     |                  | 29 Nov 2025 |                    |         |              |
|                                                                                                                                                                                                          |                                                            |               | MSC |             |                 |     | -                |             |                    |         |              |
| (983230)                                                                                                                                                                                                 |                                                            |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                                                                                                                                                                                                 |                                                            |               |     |             |                 |     |                  |             |                    |         |              |
| CB324                                                                                                                                                                                                    | CB324 - Flight Controls (ATA 27) Replacement - Flight      |               | HRS |             |                 |     |                  |             |                    |         | 0            |
|                                                                                                                                                                                                          | Control Computer (FCC) Channel A Com-Mon Modules,          |               | AFL |             |                 |     |                  |             |                    |         | 0            |
|                                                                                                                                                                                                          | Customer Bulletin (Mandatory)                              |               | MOS |             |                 |     | 12**             | 30 May 2026 |                    |         |              |
|                                                                                                                                                                                                          |                                                            |               | MSC |             |                 |     |                  |             |                    |         |              |
| (983240)                                                                                                                                                                                                 |                                                            |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                                                                                                                                                                                                 |                                                            |               |     |             |                 |     |                  |             |                    |         |              |
| CSB008                                                                                                                                                                                                   | Sb Csb-6008 - CSB008 -Cabin Systems (ATA 44)               |               | HRS |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                                                                                                                                                                                          | Advanced Cabin Server (Acs) System Software Upgrade        |               | AFL |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                                                                                                                                                                                          |                                                            |               | MOS |             | 131.2           |     |                  | 04 Jun 2015 |                    |         |              |
|                                                                                                                                                                                                          |                                                            |               | MSC |             |                 |     | -                |             |                    |         |              |
| (940080)                                                                                                                                                                                                 |                                                            |               |     |             |                 |     |                  |             |                    |         |              |
| Airframe                                                                                                                                                                                                 |                                                            |               |     |             |                 |     |                  |             |                    |         |              |
| Notes: EFFECTIVITY: THIS CABIN SERVICE BULLETIN IS APPLICABLE TO AIRCRAFT WITH ACFIRMWARE VERSION 4.4.3.9 INSTALLED. SERIAL NUMBER EFFECTIVITY INCLUDES 6003 THRU 6129. FINAL PHASE CUT-IN 6130 AND SUB. |                                                            |               |     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom                                                                                                                                                                                                                                                | Description                                                                                                        |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|----------|--------------------|---------|--------------|
|                                                                                                                                                                                                                                                                | Part Number                                                                                                        | Serial Number |     |             |                 |     |                  |          |                    |         | Approx Price |
| Logbook Position                                                                                                                                                                                                                                               | HW                                                                                                                 | SW            |     |             |                 |     |                  |          |                    |         | Manufacturer |
|                                                                                                                                                                                                                                                                | MM Ref                                                                                                             |               |     |             |                 |     |                  |          |                    |         | Date Type    |
|                                                                                                                                                                                                                                                                | Ops Number(s)                                                                                                      |               |     |             |                 |     |                  |          |                    |         |              |
| CSB009                                                                                                                                                                                                                                                         | Ce-Csb-6009 - CSB009 - Gulfstream Cabin Management Systems (ATA 44) Gcms Firmware Upgrade                          |               | HRS |             | 3046.1          |     |                  | 0        |                    |         | 0            |
|                                                                                                                                                                                                                                                                |                                                                                                                    |               | AFL |             | 1117            |     |                  | 0        |                    | 0       |              |
|                                                                                                                                                                                                                                                                |                                                                                                                    |               | MOS |             | 131.2           |     | 04 Jun 2015      |          |                    |         |              |
|                                                                                                                                                                                                                                                                |                                                                                                                    |               | MSC |             |                 | -   |                  |          |                    |         |              |
| (940090)                                                                                                                                                                                                                                                       |                                                                                                                    |               |     |             |                 |     |                  |          |                    |         |              |
| Airframe                                                                                                                                                                                                                                                       |                                                                                                                    |               |     |             |                 |     |                  |          |                    |         |              |
| Notes: EFFECTIVITY: THIS CABIN SERVICE BULLETIN IS APPLICABLE TO AIRCRAFT WITH GCMSCONTROLLER FIRMWARE VERSION 1.9.0 INSTALLED OR LATER APPROVED VERSION. SERIAL NUMBER EFFECTIVITY INCLUDES 6001 THRU 6135. FINAL PHASE CUT-IN STARTS WITH SERIAL NUMBER 6136 |                                                                                                                    |               |     |             |                 |     |                  |          |                    |         |              |
| CSB010                                                                                                                                                                                                                                                         | Ce-Csb-6010 - Csb 010 - Cabin Systems (ATA 44) - Advanced Cabin Server (Acs) System Software Upgrade               |               | HRS |             | 2762.2          |     |                  | 283.9    |                    |         | 0            |
|                                                                                                                                                                                                                                                                |                                                                                                                    |               | AFL |             | 1041            |     |                  | 76       |                    | 0       |              |
|                                                                                                                                                                                                                                                                |                                                                                                                    |               | MOS |             | 112.9           |     | 15 Dec 2016      |          |                    |         |              |
|                                                                                                                                                                                                                                                                |                                                                                                                    |               | MSC |             |                 | -   |                  |          |                    |         |              |
| (940100)                                                                                                                                                                                                                                                       |                                                                                                                    |               |     |             |                 |     |                  |          |                    |         |              |
| Airframe                                                                                                                                                                                                                                                       |                                                                                                                    |               |     |             |                 |     |                  |          |                    |         |              |
| CSB011                                                                                                                                                                                                                                                         | Ce-Csb-6011 - CSB011 - Cabin Systems (ATA 44) Gulfstream Cabin Management System (Gcms) Firmware Update            |               | HRS |             | 2762.2          |     |                  | 283.9    |                    |         | 0            |
|                                                                                                                                                                                                                                                                |                                                                                                                    |               | AFL |             | 1041            |     |                  | 76       |                    | 0       |              |
|                                                                                                                                                                                                                                                                |                                                                                                                    |               | MOS |             | 112.9           |     | 15 Dec 2016      |          |                    |         |              |
|                                                                                                                                                                                                                                                                |                                                                                                                    |               | MSC |             |                 | -   |                  |          |                    |         |              |
| (940110)                                                                                                                                                                                                                                                       |                                                                                                                    |               |     |             |                 |     |                  |          |                    |         |              |
| Airframe                                                                                                                                                                                                                                                       |                                                                                                                    |               |     |             |                 |     |                  |          |                    |         |              |
| CSB012                                                                                                                                                                                                                                                         | Ce-Csb-6012 - CSB012 - Cabin Systems (ATA 44) - Gulfstream Cabin Management System (Gcms) Firmware Update          |               | HRS |             | 2345.1          |     |                  | 701      |                    |         | 0            |
|                                                                                                                                                                                                                                                                |                                                                                                                    |               | AFL |             | 936             |     |                  | 181      |                    | 0       |              |
|                                                                                                                                                                                                                                                                |                                                                                                                    |               | MOS |             | 97              |     | 10 Apr 2018      |          |                    |         |              |
|                                                                                                                                                                                                                                                                |                                                                                                                    |               | MSC |             |                 | -   |                  |          |                    |         |              |
| (940120)                                                                                                                                                                                                                                                       |                                                                                                                    |               |     |             |                 |     |                  |          |                    |         |              |
| Airframe                                                                                                                                                                                                                                                       |                                                                                                                    |               |     |             |                 |     |                  |          |                    |         |              |
| CSB013                                                                                                                                                                                                                                                         | Ce-Csb-6013 - CSB013 - Cabin Systems (ATA 44) - Advanced Cabin Server (Acs) (Gen 4) - Cabinviewtm Software Upgrade |               | HRS |             | 2120.8          |     |                  | 925.3    |                    |         | 0            |
|                                                                                                                                                                                                                                                                |                                                                                                                    |               | AFL |             | 861             |     |                  | 256      |                    | 0       |              |
|                                                                                                                                                                                                                                                                |                                                                                                                    |               | MOS |             | 86              |     | 11 Mar 2019      |          |                    |         |              |
|                                                                                                                                                                                                                                                                |                                                                                                                    |               | MSC |             |                 | -   |                  |          |                    |         |              |
| (940130)                                                                                                                                                                                                                                                       |                                                                                                                    |               |     |             |                 |     |                  |          |                    |         |              |
| Airframe                                                                                                                                                                                                                                                       |                                                                                                                    |               |     |             |                 |     |                  |          |                    |         |              |
| CSB014                                                                                                                                                                                                                                                         | Ce-Csb-6014 - CSB014 - Cabin Systems (ATA 44) - Gulfstream Cabin Management System (Gcms 1) Firmware Update        |               | HRS |             | 2120.8          |     |                  | 925.3    |                    |         | 0            |
|                                                                                                                                                                                                                                                                |                                                                                                                    |               | AFL |             | 861             |     |                  | 256      |                    | 0       |              |
|                                                                                                                                                                                                                                                                |                                                                                                                    |               | MOS |             | 86              |     | 11 Mar 2019      |          |                    |         |              |
|                                                                                                                                                                                                                                                                |                                                                                                                    |               | MSC |             |                 | -   |                  |          |                    |         |              |
| (940140)                                                                                                                                                                                                                                                       |                                                                                                                    |               |     |             |                 |     |                  |          |                    |         |              |
| Airframe                                                                                                                                                                                                                                                       |                                                                                                                    |               |     |             |                 |     |                  |          |                    |         |              |

| ATA<br>U=Custom  | Description                                         |               | UOM  | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-----------------------------------------------------|---------------|------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                         | Serial Number |      |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                  | SW            |      |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                              |               |      |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                       |               |      |             |                 |     |                  |             |                    |         |              |
| CSB015           | Ce-Csb-6015 - CSB015 - Cabin Systems (ATA 44) -     |               | HRS  |             | 1987.9          |     |                  | 1058.2      |                    |         | 0            |
|                  | Advanced Cabin Server (Acs) (Gen 4) Cabinview       |               | AFL  |             | 810             |     |                  | 307         |                    |         | 0            |
|                  | Software Upgrade                                    |               | MOS  |             | 82.6            |     |                  | 22 Jun 2019 |                    |         |              |
|                  |                                                     |               | MSC  |             |                 |     | -                |             |                    |         |              |
| (940150)         |                                                     |               |      |             |                 |     |                  |             |                    |         |              |
| Airframe         |                                                     |               |      |             |                 |     |                  |             |                    |         |              |
| CSB017           | Ce-Csb-6017 - CSB017 - Cabin Systems (ATA 44) -     |               | HRS  |             | 1955.9          |     |                  | 1090.2      |                    |         | 0            |
|                  | Gulfstream Cabin Management System - (Gcms 1)       |               | AFL  |             | 804             |     |                  | 313         |                    |         | 0            |
|                  | Firmware Update                                     |               | MOS  |             | 82.1            |     |                  | 08 Jul 2019 |                    |         |              |
|                  |                                                     |               | MSC  |             |                 |     | -                |             |                    |         |              |
| (940170)         |                                                     |               |      |             |                 |     |                  |             |                    |         |              |
| Airframe         |                                                     |               |      |             |                 |     |                  |             |                    |         |              |
| CSB019           | Ce-Csb-6019 - CSB019 - Cabin Systems (ATA 44) - Gen |               | HRS  |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                  | 1 to Gen 2 Controller Upgrade                       |               | AFL  |             | 1117            |     |                  | 0           |                    |         | 0            |
|                  |                                                     |               | DATE |             |                 |     |                  |             |                    |         |              |
|                  |                                                     |               | MSC  |             |                 |     | -                |             |                    |         |              |
| (940190)         |                                                     |               |      |             |                 |     |                  |             |                    |         |              |
| Airframe         |                                                     |               |      |             |                 |     |                  |             |                    |         |              |
| CSB021           | Ce-Csb-6021 - CSB021 - Cabin Systems (ATA 44) -     |               | HRS  |             | 1531.2          |     |                  | 1514.9      |                    |         | 0            |
|                  | Advanced Cabin Server (Acs) (Gen 4) Cabinview       |               | AFL  |             | 621             |     |                  | 496         |                    |         | 0            |
|                  | Software Upgrade V2.2.3                             |               | MOS  |             | 66.5            |     |                  | 27 Oct 2020 |                    |         |              |
|                  |                                                     |               | MSC  |             |                 |     | -                |             |                    |         |              |
| (940210)         |                                                     |               |      |             |                 |     |                  |             |                    |         |              |
| Airframe         |                                                     |               |      |             |                 |     |                  |             |                    |         |              |
| CSB022           | Ce-Csb-6022 - CSB022 - Gulfstream Cabin Management  |               | HRS  |             | 1650.8          |     |                  | 1395.3      |                    |         | 0            |
|                  | System (Gcms 1) Firmware Update V1.10.6             |               | AFL  |             | 691             |     |                  | 426         |                    |         | 0            |
|                  |                                                     |               | MOS  |             | 72.3            |     |                  | 01 May 2020 |                    |         |              |
|                  |                                                     |               | MSC  |             |                 |     | -                |             |                    |         |              |
| (940220)         |                                                     |               |      |             |                 |     |                  |             |                    |         |              |
| Airframe         |                                                     |               |      |             |                 |     |                  |             |                    |         |              |
| CSB024           | Ce-Csb-6024 - CSB024 - Gulfstream Cabin Management  |               | HRS  |             | 1592.25         |     |                  | 1453.85     | 0                  |         | 0            |
|                  | System (Gcms 1) Firmware Update V1.10.7             |               | AFL  |             | 648             |     |                  | 469         | 0                  |         | 0            |
|                  |                                                     |               | MOS  |             | 67.8            |     |                  | 17 Sep 2020 |                    |         |              |
|                  |                                                     |               | MSC  |             |                 |     | -                |             |                    |         |              |
| (940240)         |                                                     |               |      |             |                 |     |                  |             |                    |         |              |
| Airframe         |                                                     |               |      |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                                                                                                                          |               | UOM  | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                                                                                          | Serial Number |      |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                                                                                                   | SW            |      |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                                                                                               |               |      |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                                                                                                        |               |      |             |                 |     |                  |             |                    |         |              |
| CSB025           | Ce-Csb-6025 - CSB025 - Gulfstream Cabin Management System (Gcms 2) - Firmware Update V2.3.0                                                          |               | HRS  |             |                 |     |                  |             |                    |         | 0            |
|                  |                                                                                                                                                      |               | AFL  |             |                 |     |                  |             |                    |         | 0            |
| (940250)         |                                                                                                                                                      |               | DATE |             |                 |     |                  |             |                    |         |              |
| Airframe         |                                                                                                                                                      |               | MSC  |             |                 |     | -                |             |                    |         |              |
| CSB026           | Ce-Csb-6026 - CSB026 - Gulfstream Cabin Management System (Gcms 2) Firmware Update V2.4.0, Cabin Service Bulletin (Recommended)                      |               | HRS  |             |                 |     |                  |             |                    |         | 0            |
|                  |                                                                                                                                                      |               | AFL  |             |                 |     |                  |             |                    |         | 0            |
| (940260)         |                                                                                                                                                      |               | DATE |             |                 |     |                  |             |                    |         |              |
| Airframe         |                                                                                                                                                      |               | MSC  |             |                 |     | -                |             |                    |         |              |
| CSB027           | Ce-Csb-6027 - CSB027 - Gulfstream Cabin Management System - (Gcms 1) Firmware Update V1.10.9, Cabin Service Bulletin (Recommended)                   |               | HRS  |             | 994.2           |     |                  | 2051.9      |                    |         | 0            |
|                  |                                                                                                                                                      |               | AFL  |             | 392             |     |                  | 725         |                    |         | 0            |
| (940270)         |                                                                                                                                                      |               | MOS  |             | 41.3            |     |                  | 01 Dec 2022 |                    |         |              |
| Airframe         |                                                                                                                                                      |               | MSC  |             |                 |     | -                |             |                    |         |              |
| CSB028           | Ce-Csb-6028 - CSB028 - Cabin Systems - Gulfstream Cabin Management System (Gcms 2) Firmware Update, Cabin Service Bulletin (Recommended)             |               | HRS  |             |                 |     |                  |             |                    |         | 0            |
|                  |                                                                                                                                                      |               | AFL  |             |                 |     |                  |             |                    |         | 0            |
| (940280)         |                                                                                                                                                      |               | DATE |             |                 |     |                  |             |                    |         |              |
| Airframe         |                                                                                                                                                      |               | MSC  |             |                 |     | -                |             |                    |         |              |
| CSB029           | Ce-Csb-6029 - CSB029 - Cabin Systems - Advanced Cabin Server (Acs) (Gen 4) Cabin View Software Update V2.2.5, Cabin Service Bulletin (Recommended)   |               | HRS  |             |                 |     |                  |             |                    |         | 0            |
|                  |                                                                                                                                                      |               | AFL  |             |                 |     |                  |             |                    |         | 0            |
| (940290)         |                                                                                                                                                      |               | DATE |             |                 |     |                  |             |                    |         |              |
| Airframe         |                                                                                                                                                      |               | MSC  |             |                 |     | -                |             |                    |         |              |
| CSB029A          | Ce-Csb-6029A - CSB029A - Cabin Systems - Advanced Cabin Server (Acs) (Gen 4) Cabin View Software Update V2.2.5, Cabin Service Bulletin (Recommended) |               | HRS  |             | 994.2           |     |                  | 2051.9      |                    |         | 0            |
|                  |                                                                                                                                                      |               | AFL  |             | 392             |     |                  | 725         |                    |         | 0            |
| (940291)         |                                                                                                                                                      |               | MOS  |             | 41.4            |     |                  | 30 Nov 2022 |                    |         |              |
| Airframe         |                                                                                                                                                      |               | MSC  |             |                 |     | -                |             |                    |         |              |

| ATA<br>U=Custom                              | Description                                                                                                                                     |               | UOM  | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|----------------------------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------|---------------|------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                              | Part Number                                                                                                                                     | Serial Number |      |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position                             | HW                                                                                                                                              | SW            |      |             |                 |     |                  |             |                    |         | Manufacturer |
|                                              | MM Ref                                                                                                                                          |               |      |             |                 |     |                  |             |                    |         | Date Type    |
|                                              | Ops Number(s)                                                                                                                                   |               |      |             |                 |     |                  |             |                    |         |              |
| CSB030<br><br>(940300)<br><br>Airframe       | Ce-Csb-6030 - CSB030 - Gulfstream Cabin Management System (Gcms 2) Firmware Update, Cabin Service Bulletin (Recommended)                        |               | HRS  |             |                 |     |                  |             |                    |         | 0            |
|                                              |                                                                                                                                                 |               | AFL  |             |                 |     |                  |             |                    |         | 0            |
|                                              |                                                                                                                                                 |               | DATE |             |                 |     |                  |             |                    |         |              |
|                                              |                                                                                                                                                 |               | MSC  |             |                 |     | -                |             |                    |         |              |
| CSB031<br><br>(940310)<br><br>Airframe       | Ce-Csb-6031 - CSB031 - Cabin Systems - Gulfstream Cabin Management System (Gcms 2) Firmware Update V2.4.9, Cabin Service Bulletin (Recommended) |               | HRS  |             | 877.3           |     |                  | 2168.8      |                    |         | 0            |
|                                              |                                                                                                                                                 |               | AFL  |             | 358             |     |                  | 759         |                    |         | 0            |
|                                              |                                                                                                                                                 |               | MOS  |             | 37.5            |     |                  | 26 Mar 2023 |                    |         |              |
|                                              |                                                                                                                                                 |               | MSC  |             |                 |     | -                |             |                    |         |              |
| MP-15-6510.1<br><br>(949019)<br><br>Airframe | Sb Mp-15-6510.1 - Sb 52-10-02-014 - Pocket Door General Upgrade                                                                                 |               | HRS  |             | 2120.8          |     |                  | 925.3       |                    |         | 0            |
|                                              |                                                                                                                                                 |               | AFL  |             | 861             |     |                  | 256         |                    |         | 0            |
|                                              |                                                                                                                                                 |               | MOS  |             | 86.2            |     |                  | 06 Mar 2019 |                    |         |              |
|                                              |                                                                                                                                                 |               | MSC  |             |                 |     | -                |             |                    |         |              |
| MP-15-6510.4<br><br>(949023)<br><br>Airframe | Sb Mp-15-6510.4 - Pocket Door Descender (Mp-15-6510)                                                                                            |               | HRS  |             | 2120.8          |     |                  | 925.3       |                    |         | 0            |
|                                              |                                                                                                                                                 |               | AFL  |             | 861             |     |                  | 256         |                    |         | 0            |
|                                              |                                                                                                                                                 |               | MOS  |             | 86              |     |                  | 11 Mar 2019 |                    |         |              |
|                                              |                                                                                                                                                 |               | MSC  |             |                 |     | -                |             |                    |         |              |
| MP-16-6502.1<br><br>(949032)<br><br>Airframe | Sb Mp-16-6502.1 - Sub-Woofer Wire Harness ( No: Vmp-16-6502)                                                                                    |               | HRS  |             | 2120.8          |     |                  | 925.3       |                    |         | 0            |
|                                              |                                                                                                                                                 |               | AFL  |             | 861             |     |                  | 256         |                    |         | 0            |
|                                              |                                                                                                                                                 |               | MOS  |             | 86.1            |     |                  | 08 Mar 2019 |                    |         |              |
|                                              |                                                                                                                                                 |               | MSC  |             |                 |     | -                |             |                    |         |              |
| MP-16-6505<br><br>(949036)<br><br>Airframe   | Sb Mp-16-6505 - Exit Signs (Mp-16-6505)                                                                                                         |               | HRS  |             | 2120.8          |     |                  | 925.3       |                    |         | 0            |
|                                              |                                                                                                                                                 |               | AFL  |             | 861             |     |                  | 256         |                    |         | 0            |
|                                              |                                                                                                                                                 |               | MOS  |             | 86              |     |                  | 12 Mar 2019 |                    |         |              |
|                                              |                                                                                                                                                 |               | MSC  |             |                 |     | -                |             |                    |         |              |
| MP-16-6506<br><br>(949037)<br><br>Airframe   | Sb Mp-16-6506 - Galley Pullout Work Surface (Mp-16-6506)                                                                                        |               | HRS  |             | 2120.8          |     |                  | 925.3       |                    |         | 0            |
|                                              |                                                                                                                                                 |               | AFL  |             | 861             |     |                  | 256         |                    |         | 0            |
|                                              |                                                                                                                                                 |               | MOS  |             | 86              |     |                  | 12 Mar 2019 |                    |         |              |
|                                              |                                                                                                                                                 |               | MSC  |             |                 |     | -                |             |                    |         |              |

| ATA<br>U=Custom                        | Description                                                                                            |               | UOM  | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|----------------------------------------|--------------------------------------------------------------------------------------------------------|---------------|------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                        | Part Number                                                                                            | Serial Number |      |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position                       | HW                                                                                                     | SW            |      |             |                 |     |                  |             |                    |         | Manufacturer |
|                                        | MM Ref                                                                                                 |               |      |             |                 |     |                  |             |                    |         | Date Type    |
|                                        | Ops Number(s)                                                                                          |               |      |             |                 |     |                  |             |                    |         |              |
| MP-16-6507<br>(949038)<br><br>Airframe | Sb Mp-16-6507 - Tia Brew Basket (Mp 16-6507)                                                           |               | HRS  |             | 2120.8          |     |                  | 925.3       |                    |         | 0            |
|                                        |                                                                                                        |               | AFL  |             | 861             |     |                  | 256         |                    |         | 0            |
|                                        |                                                                                                        |               | MOS  |             | 85.9            |     |                  | 13 Mar 2019 |                    |         |              |
|                                        |                                                                                                        |               | MSC  |             |                 |     | -                |             |                    |         |              |
| MP-16-6518<br>(949047)<br><br>Airframe | Sb Mp-16-6518 - Cabin Acoustics Enhancement (Mp-16-6518)                                               |               | HRS  |             | 2120.8          |     |                  | 925.3       |                    |         | 0            |
|                                        |                                                                                                        |               | AFL  |             | 861             |     |                  | 256         |                    |         | 0            |
|                                        |                                                                                                        |               | MOS  |             | 86              |     |                  | 12 Mar 2019 |                    |         |              |
|                                        |                                                                                                        |               | MSC  |             |                 |     | -                |             |                    |         |              |
| MP-16-6519<br>(949041)<br><br>Airframe | Sb Mp-16-6519 - Convection Oven Firmware Update R09 (Mp-16-6519)                                       |               | HRS  |             | 2120.8          |     |                  | 925.3       |                    |         | 0            |
|                                        |                                                                                                        |               | AFL  |             | 861             |     |                  | 256         |                    |         | 0            |
|                                        |                                                                                                        |               | MOS  |             | 85.9            |     |                  | 14 Mar 2019 |                    |         |              |
|                                        |                                                                                                        |               | MSC  |             |                 |     | -                |             |                    |         |              |
| MP-16-6524<br>(949052)<br><br>Airframe | Sb Mp-16-6524 - Manual Door Switch - (Mp-16-6524)                                                      |               | HRS  |             | 2120.8          |     |                  | 925.3       |                    |         | 0            |
|                                        |                                                                                                        |               | AFL  |             | 861             |     |                  | 256         |                    |         | 0            |
|                                        |                                                                                                        |               | MOS  |             | 86              |     |                  | 11 Mar 2019 |                    |         |              |
|                                        |                                                                                                        |               | MSC  |             |                 |     | -                |             |                    |         |              |
| MP-16-6525<br>(949054)<br><br>Airframe | Sb Mp-16-6525 - Aft Lav Door Enhancement Modification (Aft Lav Closet/Toilet Light Bleed) (Mp-16-6525) |               | HRS  |             | 2320.3          |     |                  | 725.8       |                    |         | 0            |
|                                        |                                                                                                        |               | AFL  |             | 926             |     |                  | 191         |                    |         | 0            |
|                                        |                                                                                                        |               | MOS  |             | 94.4            |     |                  | 29 Jun 2018 |                    |         |              |
|                                        |                                                                                                        |               | MSC  |             |                 |     | -                |             |                    |         |              |
| Notes: N/A BY A/C S/N                  |                                                                                                        |               |      |             |                 |     |                  |             |                    |         |              |
| MP-16-6526<br>(949055)<br><br>Airframe | Sb Mp-16-6526 - Aft Lav Door Enhancement Modification (Mp 16-6526)                                     |               | HRS  |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                        |                                                                                                        |               | AFL  |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                        |                                                                                                        |               | DATE |             |                 |     |                  |             |                    |         |              |
|                                        |                                                                                                        |               | MSC  |             |                 |     | -                |             |                    |         |              |
| MP-16-6530<br>(949060)<br><br>Airframe | Sb Mp-16-6530 - Rfu Forward Galley - Mp-16-6530                                                        |               | HRS  |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                        |                                                                                                        |               | AFL  |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                        |                                                                                                        |               | DATE |             |                 |     |                  |             |                    |         |              |
|                                        |                                                                                                        |               | MSC  |             |                 |     | -                |             |                    |         |              |

| ATA<br>U=Custom                                                                            | Description                                           |               | UOM  | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|--------------------------------------------------------------------------------------------|-------------------------------------------------------|---------------|------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                                                                            | Part Number                                           | Serial Number |      |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position                                                                           | HW                                                    | SW            |      |             |                 |     |                  |             |                    |         | Manufacturer |
|                                                                                            | MM Ref                                                |               |      |             |                 |     |                  |             |                    |         | Date Type    |
|                                                                                            | Ops Number(s)                                         |               |      |             |                 |     |                  |             |                    |         |              |
| MP-17-6501                                                                                 | Sb Mp-17-6501 - Aft Lavatory Door Magnetic Bumper     |               | HRS  |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                                                                            | Assembly - Hanging Mirror Configuration - Mp-17-6501  |               | AFL  |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                       |               | MOS  |             | 110.3           |     |                  | 01 Mar 2017 |                    |         |              |
|                                                                                            | (949062)                                              |               | MSC  |             |                 |     | -                |             |                    |         |              |
| Airframe                                                                                   |                                                       |               |      |             |                 |     |                  |             |                    |         |              |
| Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK. |                                                       |               |      |             |                 |     |                  |             |                    |         |              |
| MP-17-6510                                                                                 | Sb Mp-17-6510 - Flight Control Computers (FCC) V7.1   |               | HRS  |             | 2345.1          |     |                  | 701         |                    |         | 0            |
|                                                                                            | Software Update                                       |               | AFL  |             | 936             |     |                  | 181         |                    |         | 0            |
|                                                                                            |                                                       |               | MOS  |             | 96.6            |     |                  | 23 Apr 2018 |                    |         |              |
|                                                                                            | (949067)                                              |               | MSC  |             |                 |     | -                |             |                    |         |              |
| Airframe                                                                                   |                                                       |               |      |             |                 |     |                  |             |                    |         |              |
| MP-17-6512                                                                                 | Sb Mp-17-6512 - Emed Stop Bolts                       |               | HRS  |             | 3046.1          |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                       |               | AFL  |             | 1117            |     |                  | 0           |                    |         | 0            |
|                                                                                            | (949068)                                              |               | DATE |             |                 |     |                  |             |                    |         |              |
|                                                                                            | Airframe                                              |               | MSC  |             |                 |     | -                |             |                    |         |              |
| ST04027AT-D                                                                                | STC ST04027AT-D - SATCOM Direct Router (SDR)          |               | HRS  |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                                                                                            | Installation                                          |               | AFL  |             | 1112            |     |                  | 5           |                    |         | 0            |
|                                                                                            |                                                       |               | MOS  |             | 123.8           |     |                  | 18 Jan 2016 |                    |         |              |
|                                                                                            | (900007)                                              |               | MSC  |             |                 |     | -                |             |                    |         |              |
| Airframe                                                                                   |                                                       |               |      |             |                 |     |                  |             |                    |         |              |
| ST04252AT-D                                                                                | STC ST04252AT-D - Aircraft Interior                   |               | HRS  |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                                                                                            |                                                       |               | AFL  |             | 1112            |     |                  | 5           |                    |         | 0            |
|                                                                                            | (900001)                                              |               | MOS  |             | 123.8           |     |                  | 18 Jan 2016 |                    |         |              |
|                                                                                            | Airframe                                              |               | MSC  |             |                 |     | -                |             |                    |         |              |
| ST04254AT-D                                                                                | STC ST04254AT-D - Broad Band Multi-Link (Bbml)        |               | HRS  |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                                                                                            | Highspeed Data System Viasat Mobile Terminal Vmt-1500 |               | AFL  |             | 1112            |     |                  | 5           |                    |         | 0            |
|                                                                                            | -03                                                   |               | MOS  |             | 123.8           |     |                  | 18 Jan 2016 |                    |         |              |
|                                                                                            | (900004)                                              |               | MSC  |             |                 |     | -                |             |                    |         |              |
| Airframe                                                                                   |                                                       |               |      |             |                 |     |                  |             |                    |         |              |
| ST04277AT-D                                                                                | STC ST04277AT-D - Lightning Sensor                    |               | HRS  |             | 3033.8          |     |                  | 12.3        |                    |         | 0            |
|                                                                                            |                                                       |               | AFL  |             | 1112            |     |                  | 5           |                    |         | 0            |
|                                                                                            | (900002)                                              |               | MOS  |             | 123.8           |     |                  | 18 Jan 2016 |                    |         |              |
|                                                                                            | Airframe                                              |               | MSC  |             |                 |     | -                |             |                    |         |              |

SIAE - APU/Engine Service Information/Bulletins

| ATA<br>U=Custom                                                                            | Description                                                                                                                                                  |               | UOM  | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|--------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                                                                            | Part Number                                                                                                                                                  | Serial Number |      |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position                                                                           | HW                                                                                                                                                           | SW            |      |             |                 |     |                  |             |                    |         | Manufacturer |
|                                                                                            | MM Ref                                                                                                                                                       |               |      |             |                 |     |                  |             |                    |         | Date Type    |
|                                                                                            | Ops Number(s)                                                                                                                                                |               |      |             |                 |     |                  |             |                    |         |              |
| 49-7933 R06<br><br>(957936)<br><br>APU                                                     | APU - Sb 49-7933 R06 - Airborne Auxiliary Power Unit<br>(APU) - Oil - General - Approved Oils                                                                |               | HRS  |             | 2266.5          |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                                                                                              |               | APUS |             | 0               |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                                                                                              |               | MOS  |             | 109.9           |     |                  | 13 Mar 2017 |                    |         |              |
|                                                                                            |                                                                                                                                                              |               | MSC  |             |                 |     | -                |             |                    |         |              |
| Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK. |                                                                                                                                                              |               |      |             |                 |     |                  |             |                    |         |              |
| 49-7933 R08<br><br>(957938)<br><br>APU                                                     | APU - Sb 49-7933 R08 - Airborne Auxiliary Power Unit<br>(APU) - Oil - General - Approved Oils                                                                |               | HRS  |             | 2266.5          |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                                                                                              |               | APUS |             | 0               |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                                                                                              |               | DATE |             |                 |     |                  |             |                    |         |              |
|                                                                                            |                                                                                                                                                              |               | MSC  |             |                 |     | DUE**            |             |                    |         |              |
| 49-7997 R03<br><br>(957998)<br><br>APU                                                     | APU - Sb 49-7997 R03 - Standard Storage and<br>Preservation Guidelines                                                                                       |               | HRS  |             | 2266.5          |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                                                                                              |               | APUS |             | 0               |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                                                                                              |               | MOS  |             | 110.5           |     |                  | 28 Feb 2017 |                    |         |              |
|                                                                                            |                                                                                                                                                              |               | MSC  |             |                 |     | -                |             |                    |         |              |
| Notes: THIS CODE HAS BEEN CANCELLED. SEE COMPLIANCE REMARKS BY CLICKING SHOW REMARKS LINK. |                                                                                                                                                              |               |      |             |                 |     |                  |             |                    |         |              |
| 49-8252<br><br>(958252)<br><br>APU                                                         | APU - Sb 49-8252 - Airborne - Auxiliary Power Unit (APU)<br>- Approved Fuels for Honeywell Commercial Apus                                                   |               | HRS  |             | 2266.5          |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                                                                                              |               | APUS |             | 0               |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                                                                                              |               | DATE |             |                 |     |                  |             |                    |         |              |
|                                                                                            |                                                                                                                                                              |               | MSC  |             |                 |     | -                |             |                    |         |              |
| 499003 <sup>U</sup><br><br><br>APU                                                         | APU - APU - APU Soap Oil Sample and Filter Element<br>Analysis                                                                                               |               | HRS  |             | 87.5            |     | 500              | 2179        | 2679               |         | 0            |
|                                                                                            |                                                                                                                                                              |               | APUS |             | 0               |     |                  | 0           |                    |         | 0            |
|                                                                                            |                                                                                                                                                              |               | MOS  |             | 4.8             |     |                  | 18 Dec 2025 |                    |         |              |
| APU-49 R11<br><br><br>APU                                                                  | APU - Sil APU-49 R11 - Implementation of the Honeywell<br>Spectrometric Oil and Filter Analysis Program (Soap) for<br>Honeywell Auxiliary Power Units (Apus) |               | HRS  |             |                 |     |                  |             |                    |         | 0            |
|                                                                                            |                                                                                                                                                              |               | APUS |             |                 |     |                  |             |                    |         | 0            |
|                                                                                            |                                                                                                                                                              |               | DATE |             |                 |     |                  |             |                    |         |              |
|                                                                                            |                                                                                                                                                              |               | MSC  |             |                 |     | -                |             |                    |         |              |



| ATA<br>U=Custom  | Description                                                                                                                                                                                      |               | UOM  | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                  | Part Number                                                                                                                                                                                      | Serial Number |      |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position | HW                                                                                                                                                                                               | SW            |      |             |                 |     |                  |             |                    |         | Manufacturer |
|                  | MM Ref                                                                                                                                                                                           |               |      |             |                 |     |                  |             |                    |         | Date Type    |
|                  | Ops Number(s)                                                                                                                                                                                    |               |      |             |                 |     |                  |             |                    |         |              |
| APU-49 R12       | APU - Sil APU-49 R12 - Sil APU-49 R12 - Implementation of the Honeywell Spectrometric Oil and Filter Analysis Program (Soap) for Honeywell Auxiliary Power Units (Apus)                          |               | HRS  |             |                 |     |                  |             |                    |         | 0            |
|                  |                                                                                                                                                                                                  |               | APUS |             |                 |     |                  |             |                    |         | 0            |
|                  |                                                                                                                                                                                                  |               | DATE |             |                 |     |                  |             |                    |         |              |
|                  |                                                                                                                                                                                                  |               | MSC  |             |                 |     | -                |             |                    |         |              |
| (950011)         |                                                                                                                                                                                                  |               |      |             |                 |     |                  |             |                    |         |              |
| APU              |                                                                                                                                                                                                  |               |      |             |                 |     |                  |             |                    |         |              |
| APU-49 R13       | APU - Sil APU-49 R13 - Implementation of the Honeywell Spectrometric Oil and Filter Analysis Program (Soap) for Honeywell Auxiliary Power Units (Apus), Service Information Letter (Recommended) |               | HRS  |             | 87.5            |     | 500              | 2179        | 2679               |         | 0            |
|                  |                                                                                                                                                                                                  |               | APUS |             | 0               |     |                  | 0           |                    |         | 0            |
|                  |                                                                                                                                                                                                  |               | MOS  |             | 4.8             |     | 12               | 18 Dec 2025 | 18 Dec 2026        |         |              |
|                  |                                                                                                                                                                                                  |               | MSC  |             |                 |     | A/R              |             |                    |         |              |
| (950012)         |                                                                                                                                                                                                  |               |      |             |                 |     |                  |             |                    |         |              |
| APU              |                                                                                                                                                                                                  |               |      |             |                 |     |                  |             |                    |         |              |
| APU-49 R14       | APU - Sil APU-49 R14 - Implementation of the Honeywell Spectrometric Oil and Filter Analysis Program (Soap) for Honeywell Auxiliary Power Units (Apus), Service Information Letter (Recommended) |               | HRS  |             |                 |     |                  |             |                    |         | 0            |
|                  |                                                                                                                                                                                                  |               | APUS |             |                 |     |                  |             |                    |         | 0            |
|                  |                                                                                                                                                                                                  |               | MOS  |             |                 |     |                  |             |                    |         |              |
|                  |                                                                                                                                                                                                  |               | MSC  |             |                 |     | A/R**            |             |                    |         |              |
| (959549)         |                                                                                                                                                                                                  |               |      |             |                 |     |                  |             |                    |         |              |
| APU              |                                                                                                                                                                                                  |               |      |             |                 |     |                  |             |                    |         |              |
| BR700-36-101750  | No. 1 Engine - Sb BR700-36-101750 - Pneumatic - Cabin AIR Ducts - Introduction of Standard Bolts and Nuts Installed from the Front to the Rear                                                   |               | HRS  |             |                 |     |                  |             |                    |         | 0            |
|                  |                                                                                                                                                                                                  |               | ENC  |             |                 |     |                  |             |                    |         | 0            |
|                  |                                                                                                                                                                                                  |               | DATE |             |                 |     |                  |             |                    |         |              |
|                  |                                                                                                                                                                                                  |               | MSC  |             |                 |     | -                |             |                    |         |              |
| (880030)         |                                                                                                                                                                                                  |               |      |             |                 |     |                  |             |                    |         |              |
| Engine           | [End Of Month Item]                                                                                                                                                                              |               |      |             |                 |     |                  |             |                    |         |              |
| BR700-36-101750  | No. 2 Engine - Sb BR700-36-101750 - Pneumatic - Cabin AIR Ducts - Introduction of Standard Bolts and Nuts Installed from the Front to the Rear                                                   |               | HRS  |             |                 |     |                  |             |                    |         | 0            |
|                  |                                                                                                                                                                                                  |               | ENC  |             |                 |     |                  |             |                    |         | 0            |
|                  |                                                                                                                                                                                                  |               | DATE |             |                 |     |                  |             |                    |         |              |
|                  |                                                                                                                                                                                                  |               | MSC  |             |                 |     | -                |             |                    |         |              |
| (880030)         |                                                                                                                                                                                                  |               |      |             |                 |     |                  |             |                    |         |              |
| Engine           | [End Of Month Item]                                                                                                                                                                              |               |      |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom        | Description                                                                                                                                                                                                                                                              |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|----------|--------------------|---------|--------------|
|                        | Part Number                                                                                                                                                                                                                                                              | Serial Number |                     |             |                 |     |                  |          |                    |         | Approx Price |
| Logbook Position       | HW                                                                                                                                                                                                                                                                       | SW            |                     |             |                 |     |                  |          |                    |         | Manufacturer |
|                        | MM Ref                                                                                                                                                                                                                                                                   |               |                     |             |                 |     |                  |          |                    |         | Date Type    |
|                        | Ops Number(s)                                                                                                                                                                                                                                                            |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-71-101776<br>R01 | No. 1 Engine - Sb BR700-71-101776 R01 - Power Plant -<br>Drains Tank Ejector - Introduction of A Revised Seal Ring<br>Part Number for Spares Purposes, Service Bulletin<br>(Optional)                                                                                    |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                                                                          |               | ENC                 |             |                 |     |                  |          |                    | 0       |              |
|                        |                                                                                                                                                                                                                                                                          |               | MOS                 | 29.2        |                 |     | 05 Dec 2023      |          |                    |         |              |
|                        |                                                                                                                                                                                                                                                                          |               | MSC                 |             |                 | -   |                  |          |                    |         |              |
| (880234)               |                                                                                                                                                                                                                                                                          |               |                     |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                                                                                                          |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-71-101776<br>R01 | No. 2 Engine - Sb BR700-71-101776 R01 - Power Plant -<br>Drains Tank Ejector - Introduction of A Revised Seal Ring<br>Part Number for Spares Purposes, Service Bulletin<br>(Optional)                                                                                    |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                                                                          |               | ENC                 |             |                 |     |                  |          |                    | 0       |              |
|                        |                                                                                                                                                                                                                                                                          |               | MOS                 | 29.2        |                 |     | 05 Dec 2023      |          |                    |         |              |
|                        |                                                                                                                                                                                                                                                                          |               | MSC                 |             |                 | -   |                  |          |                    |         |              |
| (880234)               |                                                                                                                                                                                                                                                                          |               |                     |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                                                                                                          |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-71-101786        | No. 1 Engine - Sb BR700-71-101786 - Power Plant - Eng<br>Lt Engine Electronic Controller (Eec) Lane A E2-A Loom<br>1A and Lane B E2-B Loom 1B Electrical Harnesses -<br>Introduction of an Alternative Part Number for the<br>Protective Covers on the Spare Receptacles |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                                                                          |               | ENC                 |             |                 |     |                  |          |                    | 0       |              |
|                        |                                                                                                                                                                                                                                                                          |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                                                                                                                                                                                          |               | MSC                 |             |                 | -   |                  |          |                    |         |              |
| (880059)               |                                                                                                                                                                                                                                                                          |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                                                                                                          |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-71-101786        | No. 2 Engine - Sb BR700-71-101786 - Power Plant - Eng<br>Lt Engine Electronic Controller (Eec) Lane A E2-A Loom<br>1A and Lane B E2-B Loom 1B Electrical Harnesses -<br>Introduction of an Alternative Part Number for the<br>Protective Covers on the Spare Receptacles |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                                                                          |               | ENC                 |             |                 |     |                  |          |                    | 0       |              |
|                        |                                                                                                                                                                                                                                                                          |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                                                                                                                                                                                          |               | MSC                 |             |                 | -   |                  |          |                    |         |              |
| (880059)               |                                                                                                                                                                                                                                                                          |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                                                                                                          |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-71-101868        | No. 1 Engine - Sb BR700-71-101868 - Power Plant -<br>Bypass Section Harnesses - Introduction of A New<br>Bracket and Larger Diameter Clips                                                                                                                               |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                                                                          |               | ENC                 |             |                 |     |                  |          |                    | 0       |              |
|                        |                                                                                                                                                                                                                                                                          |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                                                                                                                                                                                          |               | MSC                 |             |                 | -   |                  |          |                    |         |              |
| (880069)               |                                                                                                                                                                                                                                                                          |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                                                                                                          |               |                     |             |                 |     |                  |          |                    |         |              |

| ATA<br>U=Custom        | Description                                                                                                                                                                                                                       |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                        | Part Number                                                                                                                                                                                                                       | Serial Number |                     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position       | HW                                                                                                                                                                                                                                | SW            |                     |             |                 |     |                  |             |                    |         | Manufacturer |
|                        | MM Ref                                                                                                                                                                                                                            |               |                     |             |                 |     |                  |             |                    |         | Date Type    |
|                        | Ops Number(s)                                                                                                                                                                                                                     |               |                     |             |                 |     |                  |             |                    |         |              |
| BR700-71-101868        | No. 2 Engine - Sb BR700-71-101868 - Power Plant - Bypass Section Harnesses - Introduction of A New Bracket and Larger Diameter Clips                                                                                              |               | HRS                 |             |                 |     |                  |             |                    |         | 0            |
|                        |                                                                                                                                                                                                                                   |               | ENC                 |             |                 |     |                  |             |                    |         | 0            |
|                        |                                                                                                                                                                                                                                   |               | DATE                |             |                 |     |                  |             |                    |         |              |
|                        |                                                                                                                                                                                                                                   |               | MSC                 |             |                 |     | -                |             |                    |         |              |
| (880069)               |                                                                                                                                                                                                                                   |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine                 |                                                                                                                                                                                                                                   |               |                     |             |                 |     |                  |             |                    |         |              |
| BR700-71-101928        | No. 1 Engine - Sb BR700-71-101928 - Power Plant - Left and Right Quick Engine Change Unit (Qecu) - Introduction of A Revised V-Clamp Coupling With Two Retaining Segments for the Hydraulic Pump                                  |               | HRS                 |             |                 |     |                  |             |                    |         | 0            |
|                        |                                                                                                                                                                                                                                   |               | ENC                 |             |                 |     |                  |             |                    |         | 0            |
|                        |                                                                                                                                                                                                                                   |               | DATE                |             |                 |     |                  |             |                    |         |              |
|                        |                                                                                                                                                                                                                                   |               | MSC                 |             |                 |     | -                |             |                    |         |              |
| (880109)               |                                                                                                                                                                                                                                   |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine                 |                                                                                                                                                                                                                                   |               |                     |             |                 |     |                  |             |                    |         |              |
| BR700-71-101928        | No. 2 Engine - Sb BR700-71-101928 - Power Plant - Left and Right Quick Engine Change Unit (Qecu) - Introduction of A Revised V-Clamp Coupling With Two Retaining Segments for the Hydraulic Pump                                  |               | HRS                 |             |                 |     |                  |             |                    |         | 0            |
|                        |                                                                                                                                                                                                                                   |               | ENC                 |             |                 |     |                  |             |                    |         | 0            |
|                        |                                                                                                                                                                                                                                   |               | DATE                |             |                 |     |                  |             |                    |         |              |
|                        |                                                                                                                                                                                                                                   |               | MSC                 |             |                 |     | -                |             |                    |         |              |
| (880109)               |                                                                                                                                                                                                                                   |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine                 |                                                                                                                                                                                                                                   |               |                     |             |                 |     |                  |             |                    |         |              |
| BR700-71-101928<br>R01 | No. 1 Engine - Sb BR700-71-101928 R01 - Power Plant - Left and Right Quick Engine Change Unit (Qecu) - Introduction of A Revised V-Clamp Coupling With Two Retaining Segments for the Hydraulic Pump, Service Bulletin (Optional) |               | HRS                 |             |                 |     |                  |             |                    |         | 0            |
|                        |                                                                                                                                                                                                                                   |               | ENC                 |             |                 |     |                  |             |                    |         | 0            |
|                        |                                                                                                                                                                                                                                   |               | MOS                 |             | 19.5            |     |                  | 25 Sep 2024 |                    |         |              |
|                        |                                                                                                                                                                                                                                   |               | MSC                 |             |                 |     | -                |             |                    |         |              |
| (880265)               |                                                                                                                                                                                                                                   |               |                     |             |                 |     |                  |             |                    |         |              |
| Engine                 |                                                                                                                                                                                                                                   |               |                     |             |                 |     |                  |             |                    |         |              |
| BR700-71-101928<br>R01 | No. 2 Engine - Sb BR700-71-101928 R01 - Power Plant - Left and Right Quick Engine Change Unit (Qecu) - Introduction of A Revised V-Clamp Coupling With Two Retaining Segments for the Hydraulic Pump, Service Bulletin (Optional) |               | HRS                 |             |                 |     |                  |             |                    |         | 0            |
|                        |                                                                                                                                                                                                                                   |               | ENC                 |             |                 |     |                  |             |                    |         | 0            |
|                        |                                                                                                                                                                                                                                   |               | MOS                 |             | 19.5            |     |                  | 25 Sep 2024 |                    |         |              |
|                        |                                                                                                                                                                                                                                   |               | MSC                 |             |                 |     | -                |             |                    |         |              |
| (880265)               |                                                                                                                                                                                                                                   |               |                     |             |                 |     |                  |             |                    |         |              |
| Engine                 |                                                                                                                                                                                                                                   |               |                     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom        | Description                                                                                                                                                                                                                             |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                        | Part Number                                                                                                                                                                                                                             | Serial Number |                     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position       | HW                                                                                                                                                                                                                                      | SW            |                     |             |                 |     |                  |             |                    |         | Manufacturer |
|                        | MM Ref                                                                                                                                                                                                                                  |               |                     |             |                 |     |                  |             |                    |         | Date Type    |
|                        | Ops Number(s)                                                                                                                                                                                                                           |               |                     |             |                 |     |                  |             |                    |         |              |
| BR700-71-101961        | No. 1 Engine - Sb BR700-71-101961 - Power Plant - Left and Right Engines - Engine Flange Mounted Engine Build Unit (Ebu)Brackets - Introduction of Redesigned Hydraulic Damper Brackets                                                 |               | HRS                 |             |                 |     |                  |             |                    |         | 0            |
|                        |                                                                                                                                                                                                                                         |               | ENC                 |             |                 |     |                  |             |                    | 0       |              |
|                        |                                                                                                                                                                                                                                         |               | DATE                |             |                 |     |                  |             |                    |         |              |
|                        |                                                                                                                                                                                                                                         |               | MSC                 |             |                 |     | -                |             |                    |         |              |
| (880135)               |                                                                                                                                                                                                                                         |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine                 |                                                                                                                                                                                                                                         |               |                     |             |                 |     |                  |             |                    |         |              |
| BR700-71-101961        | No. 2 Engine - Sb BR700-71-101961 - Power Plant - Left and Right Engines - Engine Flange Mounted Engine Build Unit (Ebu)Brackets - Introduction of Redesigned Hydraulic Damper Brackets                                                 |               | HRS                 |             |                 |     |                  |             |                    |         | 0            |
|                        |                                                                                                                                                                                                                                         |               | ENC                 |             |                 |     |                  |             |                    | 0       |              |
|                        |                                                                                                                                                                                                                                         |               | DATE                |             |                 |     |                  |             |                    |         |              |
|                        |                                                                                                                                                                                                                                         |               | MSC                 |             |                 |     | -                |             |                    |         |              |
| (880135)               |                                                                                                                                                                                                                                         |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine                 |                                                                                                                                                                                                                                         |               |                     |             |                 |     |                  |             |                    |         |              |
| BR700-71-101987        | No. 1 Engine - Sb BR700-71-101987 - Core Engine Harness - Introduction of New Lane A and Lane B Core Engine Harnesses and Deletion of the Turbine Case Cooling (TCC) Valve Thermocouples                                                |               | HRS                 |             |                 |     |                  |             |                    |         | 0            |
|                        |                                                                                                                                                                                                                                         |               | ENC                 |             |                 |     |                  |             |                    | 0       |              |
|                        |                                                                                                                                                                                                                                         |               | DATE                |             |                 |     |                  |             |                    |         |              |
|                        |                                                                                                                                                                                                                                         |               | MSC                 |             |                 |     | -                |             |                    |         |              |
| (880140)               |                                                                                                                                                                                                                                         |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine                 |                                                                                                                                                                                                                                         |               |                     |             |                 |     |                  |             |                    |         |              |
| BR700-71-101987        | No. 2 Engine - Sb BR700-71-101987 - Core Engine Harness - Introduction of New Lane A and Lane B Core Engine Harnesses and Deletion of the Turbine Case Cooling (TCC) Valve Thermocouples                                                |               | HRS                 |             |                 |     |                  |             |                    |         | 0            |
|                        |                                                                                                                                                                                                                                         |               | ENC                 |             |                 |     |                  |             |                    | 0       |              |
|                        |                                                                                                                                                                                                                                         |               | DATE                |             |                 |     |                  |             |                    |         |              |
|                        |                                                                                                                                                                                                                                         |               | MSC                 |             |                 |     | -                |             |                    |         |              |
| (880140)               |                                                                                                                                                                                                                                         |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine                 |                                                                                                                                                                                                                                         |               |                     |             |                 |     |                  |             |                    |         |              |
| BR700-71-101987<br>R01 | No. 1 Engine - Sb BR700-71-101987 R01 - Power Plant - Core Engine Harness - Introduction of New Lane A and Lane B Core Engine Harnesses and Deletion of the Turbine Case Cooling (TCC) Valve Thermocouples, Service Bulletin (Optional) |               | HRS                 |             |                 |     |                  |             |                    |         | 0            |
|                        |                                                                                                                                                                                                                                         |               | ENC                 |             |                 |     |                  |             |                    | 0       |              |
|                        |                                                                                                                                                                                                                                         |               | MOS                 |             | 29.2            |     |                  | 05 Dec 2023 |                    |         |              |
|                        |                                                                                                                                                                                                                                         |               | MSC                 |             |                 |     | -                |             |                    |         |              |
| (880235)               |                                                                                                                                                                                                                                         |               |                     |             |                 |     |                  |             |                    |         |              |
| Engine                 |                                                                                                                                                                                                                                         |               |                     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom        | Description                                                                                                                                                                                                                             |               | UOM  | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|------|-------------|-----------------|-----|------------------|----------|--------------------|---------|--------------|
|                        | Part Number                                                                                                                                                                                                                             | Serial Number |      |             |                 |     |                  |          |                    |         | Approx Price |
| Logbook Position       | HW                                                                                                                                                                                                                                      | SW            |      |             |                 |     |                  |          |                    |         | Manufacturer |
|                        | MM Ref                                                                                                                                                                                                                                  |               |      |             |                 |     |                  |          |                    |         | Date Type    |
|                        | Ops Number(s)                                                                                                                                                                                                                           |               |      |             |                 |     |                  |          |                    |         |              |
| BR700-71-101987<br>R01 | No. 2 Engine - Sb BR700-71-101987 R01 - Power Plant - Core Engine Harness - Introduction of New Lane A and Lane B Core Engine Harnesses and Deletion of the Turbine Case Cooling (TCC) Valve Thermocouples, Service Bulletin (Optional) |               | HRS  |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                                         |               | ENC  |             |                 |     |                  |          |                    | 0       |              |
|                        |                                                                                                                                                                                                                                         |               | MOS  | 29.2        |                 |     | 05 Dec 2023      |          |                    |         |              |
|                        |                                                                                                                                                                                                                                         |               | MSC  |             |                 | -   |                  |          |                    |         |              |
| (880235)               |                                                                                                                                                                                                                                         |               |      |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                                                                         |               |      |             |                 |     |                  |          |                    |         |              |
| BR700-71-102011        | No. 1 Engine - Sb BR700-71-102011 - Power Plant - Core Engine Lane A Loom 2A and Lane B Loom 2B Harnesses - Introduction of an Alternative Harness Tape                                                                                 |               | HRS  |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                                         |               | ENC  |             |                 |     |                  |          |                    | 0       |              |
|                        |                                                                                                                                                                                                                                         |               | DATE |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                                                                                                                                                         |               | MSC  |             |                 | -   |                  |          |                    |         |              |
| (880149)               | [End Of Month Item]                                                                                                                                                                                                                     |               |      |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                                                                         |               |      |             |                 |     |                  |          |                    |         |              |
| BR700-71-102011        | No. 2 Engine - Sb BR700-71-102011 - Power Plant - Core Engine Lane A Loom 2A and Lane B Loom 2B Harnesses - Introduction of an Alternative Harness Tape                                                                                 |               | HRS  |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                                         |               | ENC  |             |                 |     |                  |          |                    | 0       |              |
|                        |                                                                                                                                                                                                                                         |               | DATE |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                                                                                                                                                         |               | MSC  |             |                 | -   |                  |          |                    |         |              |
| (880149)               | [End Of Month Item]                                                                                                                                                                                                                     |               |      |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                                                                         |               |      |             |                 |     |                  |          |                    |         |              |
| BR700-71-102269        | No. 1 Engine - Sb BR700-71-102269 - Sb BR700-71-102269 - Power Plant - Eng Lt Engine Electronic Controller (Eec) Lane A and Lane B Harnesses - Introduction of Alternative Marker Sleeves for the Eec Harness Assemblies                |               | HRS  |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                                         |               | ENC  |             |                 |     |                  |          |                    | 0       |              |
|                        |                                                                                                                                                                                                                                         |               | DATE |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                                                                                                                                                         |               | MSC  |             |                 | -   |                  |          |                    |         |              |
| (880224)               | [End Of Month Item]                                                                                                                                                                                                                     |               |      |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                                                                         |               |      |             |                 |     |                  |          |                    |         |              |
| BR700-71-102269        | No. 2 Engine - Sb BR700-71-102269 - Sb BR700-71-102269 - Power Plant - Eng Lt Engine Electronic Controller (Eec) Lane A and Lane B Harnesses - Introduction of Alternative Marker Sleeves for the Eec Harness Assemblies                |               | HRS  |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                                         |               | ENC  |             |                 |     |                  |          |                    | 0       |              |
|                        |                                                                                                                                                                                                                                         |               | DATE |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                                                                                                                                                         |               | MSC  |             |                 | -   |                  |          |                    |         |              |
| (880224)               | [End Of Month Item]                                                                                                                                                                                                                     |               |      |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                                                                         |               |      |             |                 |     |                  |          |                    |         |              |

| ATA<br>U=Custom        | Description                                                                                                                                                                                                          |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|----------|--------------------|---------|--------------|
|                        | Part Number                                                                                                                                                                                                          | Serial Number |                     |             |                 |     |                  |          |                    |         | Approx Price |
| Logbook Position       | HW                                                                                                                                                                                                                   | SW            |                     |             |                 |     |                  |          |                    |         | Manufacturer |
|                        | MM Ref                                                                                                                                                                                                               |               |                     |             |                 |     |                  |          |                    |         | Date Type    |
|                        | Ops Number(s)                                                                                                                                                                                                        |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-71-900003<br>R01 | No. 1 Engine - Sb BR700-71-900003 R01 - Power Plant -<br>Left and Right Quick Engine Change Unit - Inspection of<br>the V-Band Coupling Clamp - Non-Modification Service<br>Bulletin (This Sb Is No Longer Valid)    |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                      |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                      |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                                                                                                                                      |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880206)               |                                                                                                                                                                                                                      |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                                                      |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-71-900003<br>R01 | No. 2 Engine - Sb BR700-71-900003 R01 - Power Plant -<br>Left and Right Quick Engine Change Unit - Inspection of<br>the V-Band Coupling Clamp - Non-Modification Service<br>Bulletin (This Sb Is No Longer Valid)    |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                      |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                      |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                                                                                                                                      |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880206)               |                                                                                                                                                                                                                      |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                                                      |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-71-900578        | No. 1 Engine - Sb BR700-71-900578 - Power Plant -<br>General Services Harness 2 Right Engine (Ebu) -<br>Inspection of the General Services Harness 2 for Correct<br>Installation - Non-Modification Service Bulletin |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                      |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                      |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                                                                                                                                      |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880112)               |                                                                                                                                                                                                                      |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                                                      |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-71-900578        | No. 2 Engine - Sb BR700-71-900578 - Power Plant -<br>General Services Harness 2 Right Engine (Ebu) -<br>Inspection of the General Services Harness 2 for Correct<br>Installation - Non-Modification Service Bulletin |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                      |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                      |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                                                                                                                                      |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880112)               |                                                                                                                                                                                                                      |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                                                      |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-71-900701        | No. 1 Engine - Sb BR700-71-900701 - Power Plant -<br>Fixed Cowl (Apron) and Fan Cowl Doors Hinge Line Edge<br>Inspection AT Outer Surface - Non-Modification Service<br>Bulletin                                     |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                      |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                      |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                                                                                                                                      |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (888850)               |                                                                                                                                                                                                                      |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                                                      |               |                     |             |                 |     |                  |          |                    |         |              |

| ATA<br>U=Custom  | Description                                                                                                                                                                                                                                               |               | UOM  | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|------|-------------|-----------------|-----|------------------|----------|--------------------|---------|--------------|
|                  | Part Number                                                                                                                                                                                                                                               | Serial Number |      |             |                 |     |                  |          |                    |         | Approx Price |
| Logbook Position | HW                                                                                                                                                                                                                                                        | SW            |      |             |                 |     |                  |          |                    |         | Manufacturer |
|                  | MM Ref                                                                                                                                                                                                                                                    |               |      |             |                 |     |                  |          |                    |         | Date Type    |
|                  | Ops Number(s)                                                                                                                                                                                                                                             |               |      |             |                 |     |                  |          |                    |         |              |
| BR700-71-900701  | No. 2 Engine - Sb BR700-71-900701 - Power Plant - Fixed Cowl (Apron) and Fan Cowl Doors Hinge Line Edge Inspection AT Outer Surface - Non-Modification Service Bulletin                                                                                   |               | HRS  |             |                 |     |                  |          |                    |         | 0            |
|                  |                                                                                                                                                                                                                                                           |               | ENC  |             |                 |     |                  |          |                    |         | 0            |
|                  |                                                                                                                                                                                                                                                           |               | DATE |             |                 |     |                  |          |                    |         |              |
|                  |                                                                                                                                                                                                                                                           |               | MSC  |             |                 |     | -                |          |                    |         |              |
| (888850)         | [End Of Month Item]                                                                                                                                                                                                                                       |               |      |             |                 |     |                  |          |                    |         |              |
| Engine           |                                                                                                                                                                                                                                                           |               |      |             |                 |     |                  |          |                    |         |              |
| BR700-72-101644  | No. 1 Engine - Sb BR700-72-101644 - High Pressure (Hp) Turbine Case Impingement Cooling Manifold - Introduction of A Turbine Case Cooling (TCC) Manifold With Improved Manufacturing Capabilities and Ease of Assembly                                    |               | HRS  |             |                 |     |                  |          |                    |         | 0            |
|                  |                                                                                                                                                                                                                                                           |               | ENC  |             |                 |     |                  |          |                    |         | 0            |
|                  |                                                                                                                                                                                                                                                           |               | DATE |             |                 |     |                  |          |                    |         |              |
|                  |                                                                                                                                                                                                                                                           |               | MSC  |             |                 |     | -                |          |                    |         |              |
| (880031)         | [End Of Month Item]                                                                                                                                                                                                                                       |               |      |             |                 |     |                  |          |                    |         |              |
| Engine           |                                                                                                                                                                                                                                                           |               |      |             |                 |     |                  |          |                    |         |              |
| BR700-72-101644  | No. 2 Engine - Sb BR700-72-101644 - High Pressure (Hp) Turbine Case Impingement Cooling Manifold - Introduction of A Turbine Case Cooling (TCC) Manifold With Improved Manufacturing Capabilities and Ease of Assembly                                    |               | HRS  |             |                 |     |                  |          |                    |         | 0            |
|                  |                                                                                                                                                                                                                                                           |               | ENC  |             |                 |     |                  |          |                    |         | 0            |
|                  |                                                                                                                                                                                                                                                           |               | DATE |             |                 |     |                  |          |                    |         |              |
|                  |                                                                                                                                                                                                                                                           |               | MSC  |             |                 |     | -                |          |                    |         |              |
| (880031)         | [End Of Month Item]                                                                                                                                                                                                                                       |               |      |             |                 |     |                  |          |                    |         |              |
| Engine           |                                                                                                                                                                                                                                                           |               |      |             |                 |     |                  |          |                    |         |              |
| BR700-72-101648  | No. 1 Engine - Sb BR700-72-101648 - High Pressure (Hp) Compressor Rotor and Shaft Discs - Introduction of A New Hp Compressor Stages 1 to 6 Rotor Drum Assembly With Revised Stages 4 and 6 Blisk Airfoils and Shank Nuts With Silver Coated Threads Only |               | HRS  |             |                 |     |                  |          |                    |         | 0            |
|                  |                                                                                                                                                                                                                                                           |               | ENC  |             |                 |     |                  |          |                    |         | 0            |
|                  |                                                                                                                                                                                                                                                           |               | DATE |             |                 |     |                  |          |                    |         |              |
|                  |                                                                                                                                                                                                                                                           |               | MSC  |             |                 |     | -                |          |                    |         |              |
| (880022)         | [End Of Month Item]                                                                                                                                                                                                                                       |               |      |             |                 |     |                  |          |                    |         |              |
| Engine           |                                                                                                                                                                                                                                                           |               |      |             |                 |     |                  |          |                    |         |              |
| BR700-72-101648  | No. 2 Engine - Sb BR700-72-101648 - High Pressure (Hp) Compressor Rotor and Shaft Discs - Introduction of A New Hp Compressor Stages 1 to 6 Rotor Drum Assembly With Revised Stages 4 and 6 Blisk Airfoils and Shank Nuts With Silver Coated Threads Only |               | HRS  |             |                 |     |                  |          |                    |         | 0            |
|                  |                                                                                                                                                                                                                                                           |               | ENC  |             |                 |     |                  |          |                    |         | 0            |
|                  |                                                                                                                                                                                                                                                           |               | DATE |             |                 |     |                  |          |                    |         |              |
|                  |                                                                                                                                                                                                                                                           |               | MSC  |             |                 |     | -                |          |                    |         |              |
| (880022)         | [End Of Month Item]                                                                                                                                                                                                                                       |               |      |             |                 |     |                  |          |                    |         |              |
| Engine           |                                                                                                                                                                                                                                                           |               |      |             |                 |     |                  |          |                    |         |              |

| ATA<br>U=Custom  | Description                                              |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|----------|--------------------|---------|--------------|
|                  | Part Number                                              | Serial Number |                     |             |                 |     |                  |          |                    |         | Approx Price |
| Logbook Position | HW                                                       | SW            |                     |             |                 |     |                  |          |                    |         | Manufacturer |
|                  | MM Ref                                                   |               |                     |             |                 |     |                  |          |                    |         | Date Type    |
|                  | Ops Number(s)                                            |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101649  | No. 1 Engine - Sb BR700-72-101649 - High Pressure (Hp)   |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Turbine Stage 2 Onward Nozzle Guide Vanes (Ngv) -        |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Introduction of New Hp Turbine Stage 2 Ngv Assemblies    |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                  | With A Chamfer AT the Rear Inner Platform                |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880014)         |                                                          |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine           |                                                          |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101649  | No. 2 Engine - Sb BR700-72-101649 - High Pressure (Hp)   |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Turbine Stage 2 Onward Nozzle Guide Vanes (Ngv) -        |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Introduction of New Hp Turbine Stage 2 Ngv Assemblies    |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                  | With A Chamfer AT the Rear Inner Platform                |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880014)         |                                                          |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine           |                                                          |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101670  | No. 1 Engine - Sb BR700-72-101670 - Internal Gearbox     |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Drive - Driven Assembly - Introduction of A New Lock Nut |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Assembly Made from A Different Material                  |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                  |                                                          |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880013)         |                                                          |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine           |                                                          |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101670  | No. 2 Engine - Sb BR700-72-101670 - Internal Gearbox     |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Drive - Driven Assembly - Introduction of A New Lock Nut |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Assembly Made from A Different Material                  |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                  |                                                          |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880013)         |                                                          |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine           |                                                          |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101682  | No. 1 Engine - Sb BR700-72-101682 - High Pressure (Hp)   |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Compressor Variable Inlet Guide Vane (Vigv) Rings and    |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Seals - Introduction of Nuts With Silver Coated Threads  |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                  | Only                                                     |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880001)         |                                                          |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine           |                                                          |               |                     |             |                 |     |                  |          |                    |         |              |



| ATA<br>U=Custom             | Description                                             |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|-----------------------------|---------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|----------|--------------------|---------|--------------|
|                             | Part Number                                             | Serial Number |                     |             |                 |     |                  |          |                    |         | Approx Price |
| Logbook Position            | HW                                                      | SW            |                     |             |                 |     |                  |          |                    |         | Manufacturer |
|                             | MM Ref                                                  |               |                     |             |                 |     |                  |          |                    |         | Date Type    |
|                             | Ops Number(s)                                           |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101682             | No. 2 Engine - Sb BR700-72-101682 - High Pressure (Hp)  |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                             | Compressor Variable Inlet Guide Vane (Vigv) Rings and   |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                             | Seals - Introduction of Nuts With Silver Coated Threads |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                             | Only                                                    |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880001)                    |                                                         |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine                      |                                                         |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101684             | No. 1 Engine - Sb BR700-72-101684 - High Pressure (Hp)  |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                             | Turbine and Low Pressure (Lp) Turbine Rotor Shafts and  |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                             | Bearings - Introduction of Nuts With Silver Coated      |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                             | Threads Only and the Definition of Bolts and Nuts as    |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| Mandatory Replacement Parts |                                                         |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| (880012)                    |                                                         |               |                     |             |                 |     |                  |          |                    |         |              |
| Engine                      |                                                         |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101684             | No. 2 Engine - Sb BR700-72-101684 - High Pressure (Hp)  |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                             | Turbine and Low Pressure (Lp) Turbine Rotor Shafts and  |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                             | Bearings - Introduction of Nuts With Silver Coated      |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                             | Threads Only and the Definition of Bolts and Nuts as    |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| Mandatory Replacement Parts |                                                         |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| (880012)                    |                                                         |               |                     |             |                 |     |                  |          |                    |         |              |
| Engine                      |                                                         |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101696             | No. 1 Engine - Sb BR700-72-101696 - High Pressure (Hp)  |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                             | Compressor and Hp Turbine Rotor Shafts and Bearings -   |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                             | Introduction of Nuts With Silver Coated Threads Only,   |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                             | Definition of Bolts and Nuts as Mandatory Replaceable   |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| Parts                       |                                                         |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| (880006)                    |                                                         |               |                     |             |                 |     |                  |          |                    |         |              |
| Engine                      |                                                         |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101696             | No. 2 Engine - Sb BR700-72-101696 - High Pressure (Hp)  |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                             | Compressor and Hp Turbine Rotor Shafts and Bearings -   |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                             | Introduction of Nuts With Silver Coated Threads Only,   |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                             | Definition of Bolts and Nuts as Mandatory Replaceable   |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| Parts                       |                                                         |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| (880006)                    |                                                         |               |                     |             |                 |     |                  |          |                    |         |              |
| Engine                      |                                                         |               |                     |             |                 |     |                  |          |                    |         |              |

| ATA<br>U=Custom     | Description                                             |               | UOM                         | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|---------------------|---------------------------------------------------------|---------------|-----------------------------|-------------|-----------------|-----|------------------|----------|--------------------|---------|--------------|
|                     | Part Number                                             | Serial Number |                             |             |                 |     |                  |          |                    |         | Approx Price |
| Logbook Position    | HW                                                      | SW            |                             |             |                 |     |                  |          |                    |         | Manufacturer |
|                     | MM Ref                                                  |               |                             |             |                 |     |                  |          |                    |         | Date Type    |
|                     | Ops Number(s)                                           |               |                             |             |                 |     |                  |          |                    |         |              |
| BR700-72-101697     | No. 1 Engine - Sb BR700-72-101697 - High Pressure (Hp)  |               | HRS                         |             |                 |     |                  |          |                    |         | 0            |
|                     | Turbine Stage 1 Nozzle Guide Vanes (Ngv) - Introduction |               | ENC                         |             |                 |     |                  |          |                    |         | 0            |
|                     | of Hp Turbine Stage 1 Ngvs Without Surface Coating      |               | DATE                        |             |                 |     |                  |          |                    |         |              |
|                     | (880005)                                                |               | MSC                         |             |                 |     | -                |          |                    |         |              |
| [End Of Month Item] |                                                         |               |                             |             |                 |     |                  |          |                    |         |              |
| Engine              |                                                         |               |                             |             |                 |     |                  |          |                    |         |              |
| BR700-72-101697     | No. 2 Engine - Sb BR700-72-101697 - High Pressure (Hp)  |               | HRS                         |             |                 |     |                  |          |                    |         | 0            |
|                     | Turbine Stage 1 Nozzle Guide Vanes (Ngv) - Introduction |               | ENC                         |             |                 |     |                  |          |                    |         | 0            |
|                     | of Hp Turbine Stage 1 Ngvs Without Surface Coating      |               | DATE                        |             |                 |     |                  |          |                    |         |              |
|                     | (880005)                                                |               | MSC                         |             |                 |     | -                |          |                    |         |              |
| [End Of Month Item] |                                                         |               |                             |             |                 |     |                  |          |                    |         |              |
| Engine              |                                                         |               |                             |             |                 |     |                  |          |                    |         |              |
| BR700-72-101698     | No. 1 Engine - Sb BR700-72-101698 - Low Pressure (Lp)   |               | HRS                         |             |                 |     |                  |          |                    |         | 0            |
|                     | Turbine Fuel Shut-Off (Fso) Cable and Fittings -        |               | ENC                         |             |                 |     |                  |          |                    |         | 0            |
|                     | Introduction of A New Fso Elbow Assembly With A RE-     |               | DATE                        |             |                 |     |                  |          |                    |         |              |
|                     | (880017)                                                |               | Aligned Machined Ferrule    | MSC         |                 |     | -                |          |                    |         |              |
| [End Of Month Item] |                                                         |               |                             |             |                 |     |                  |          |                    |         |              |
| Engine              |                                                         |               |                             |             |                 |     |                  |          |                    |         |              |
| BR700-72-101698     | No. 2 Engine - Sb BR700-72-101698 - Low Pressure (Lp)   |               | HRS                         |             |                 |     |                  |          |                    |         | 0            |
|                     | Turbine Fuel Shut-Off (Fso) Cable and Fittings -        |               | ENC                         |             |                 |     |                  |          |                    |         | 0            |
|                     | Introduction of A New Fso Elbow Assembly With A RE-     |               | DATE                        |             |                 |     |                  |          |                    |         |              |
|                     | (880017)                                                |               | Aligned Machined Ferrule    | MSC         |                 |     | -                |          |                    |         |              |
| [End Of Month Item] |                                                         |               |                             |             |                 |     |                  |          |                    |         |              |
| Engine              |                                                         |               |                             |             |                 |     |                  |          |                    |         |              |
| BR700-72-101700     | No. 1 Engine - Sb BR700-72-101700 - Combustion Rear     |               | HRS                         |             |                 |     |                  |          |                    |         | 0            |
|                     | Inner Case - Introduction of Nuts With Silver Coated    |               | ENC                         |             |                 |     |                  |          |                    |         | 0            |
|                     | Threads Only and Definition of Bolts and Nuts as        |               | DATE                        |             |                 |     |                  |          |                    |         |              |
|                     | (880023)                                                |               | Mandatory Replaceable Parts | MSC         |                 |     | -                |          |                    |         |              |
| [End Of Month Item] |                                                         |               |                             |             |                 |     |                  |          |                    |         |              |
| Engine              |                                                         |               |                             |             |                 |     |                  |          |                    |         |              |

| ATA<br>U=Custom  | Description                                            |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|--------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|----------|--------------------|---------|--------------|
|                  | Part Number                                            | Serial Number |                     |             |                 |     |                  |          |                    |         | Approx Price |
| Logbook Position | HW                                                     | SW            |                     |             |                 |     |                  |          |                    |         | Manufacturer |
|                  | MM Ref                                                 |               |                     |             |                 |     |                  |          |                    |         | Date Type    |
|                  | Ops Number(s)                                          |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101700  | No. 2 Engine - Sb BR700-72-101700 - Combustion Rear    |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Inner Case - Introduction of Nuts With Silver Coated   |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Threads Only and Definition of Bolts and Nuts as       |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                  | Mandatory Replaceable Parts                            |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880023)         |                                                        |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine           |                                                        |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101701  | No. 1 Engine - Sb BR700-72-101701 - High Pressure (Hp) |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Compressor Rear Rotor Discs and Blades - Introduction  |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                  | of A Modified Hp Compressor Stages 7 to 10 Rear Rotor  |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                  | Disc Assembly and New Balancing and Build Procedures   |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880034)         |                                                        |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine           |                                                        |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101701  | No. 2 Engine - Sb BR700-72-101701 - High Pressure (Hp) |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Compressor Rear Rotor Discs and Blades - Introduction  |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                  | of A Modified Hp Compressor Stages 7 to 10 Rear Rotor  |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                  | Disc Assembly and New Balancing and Build Procedures   |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880034)         |                                                        |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine           |                                                        |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101702  | No. 1 Engine - Sb BR700-72-101702 - High Pressure (Hp) |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Turbine Stage 2 Onward Nozzle Guide Vanes (Ngv) -      |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Introduction of New Hp Turbine Stage 2 Ngv Assemblies  |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                  | With Welded In Position Cooling AIR Inserts            |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880016)         |                                                        |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine           |                                                        |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101702  | No. 2 Engine - Sb BR700-72-101702 - High Pressure (Hp) |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Turbine Stage 2 Onward Nozzle Guide Vanes (Ngv) -      |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Introduction of New Hp Turbine Stage 2 Ngv Assemblies  |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                  | With Welded In Position Cooling AIR Inserts            |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880016)         |                                                        |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine           |                                                        |               |                     |             |                 |     |                  |          |                    |         |              |

| ATA<br>U=Custom  | Description                                                |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|----------|--------------------|---------|--------------|
|                  | Part Number                                                | Serial Number |                     |             |                 |     |                  |          |                    |         | Approx Price |
| Logbook Position | HW                                                         | SW            |                     |             |                 |     |                  |          |                    |         | Manufacturer |
|                  | MM Ref                                                     |               |                     |             |                 |     |                  |          |                    |         | Date Type    |
|                  | Ops Number(s)                                              |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101711  | No. 1 Engine - Sb BR700-72-101711 - Low Pressure (Lp)      |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Turbine Rotor Discs - Introduction of Nuts With Silver     |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Coated Threads Only and Definition of Bolts and Nuts as    |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                  | Mandatory Replacement Parts                                |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880035)         |                                                            |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine           |                                                            |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101711  | No. 2 Engine - Sb BR700-72-101711 - Low Pressure (Lp)      |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Turbine Rotor Discs - Introduction of Nuts With Silver     |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Coated Threads Only and Definition of Bolts and Nuts as    |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                  | Mandatory Replacement Parts                                |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880035)         |                                                            |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine           |                                                            |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101715  | No. 1 Engine - Sb BR700-72-101715 - Compressor             |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Intermediate Case and Fittings - Introduction of A Revised |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Intermediate Case Assembly                                 |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                  |                                                            |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880015)         |                                                            |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine           |                                                            |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101715  | No. 2 Engine - Sb BR700-72-101715 - Compressor             |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Intermediate Case and Fittings - Introduction of A Revised |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Intermediate Case Assembly                                 |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                  |                                                            |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880015)         |                                                            |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine           |                                                            |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101720  | No. 1 Engine - Sb BR700-72-101720 - High Pressure (Hp)     |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Compressor Variable Vanes and Nozzle Actuators             |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Controls - Introduction of Revised Hp Compressor           |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                  | Variable Stator Vane (Vsv) Bellcrank Tie-ROD Attaching     |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880026)         | Parts                                                      |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine           |                                                            |               |                     |             |                 |     |                  |          |                    |         |              |

| ATA<br>U=Custom  | Description                                                  |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|--------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|----------|--------------------|---------|--------------|
|                  | Part Number                                                  | Serial Number |                     |             |                 |     |                  |          |                    |         | Approx Price |
| Logbook Position | HW                                                           | SW            |                     |             |                 |     |                  |          |                    |         | Manufacturer |
|                  | MM Ref                                                       |               |                     |             |                 |     |                  |          |                    |         | Date Type    |
|                  | Ops Number(s)                                                |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101720  | No. 2 Engine - Sb BR700-72-101720 - High Pressure (Hp)       |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Compressor Variable Vanes and Nozzle Actuators               |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Controls - Introduction of Revised Hp Compressor             |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                  | Variable Stator Vane (Vsv) Bellcrank Tie-ROD Attaching Parts |               | MSC                 |             |                 |     | -                |          |                    |         |              |
|                  |                                                              |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| (880026)         |                                                              |               |                     |             |                 |     |                  |          |                    |         |              |
| Engine           |                                                              |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101725  | No. 1 Engine - Sb BR700-72-101725 - Low Pressure (Lp)        |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Turbine Case - Introduction of A New Lp Turbine Case         |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Assembly With Decreased Rear Flange Bolt Hole                |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                  | Diameter and Decreased Positional Tolerance                  |               | MSC                 |             |                 |     | -                |          |                    |         |              |
|                  |                                                              |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| (880057)         |                                                              |               |                     |             |                 |     |                  |          |                    |         |              |
| Engine           |                                                              |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101725  | No. 2 Engine - Sb BR700-72-101725 - Low Pressure (Lp)        |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Turbine Case - Introduction of A New Lp Turbine Case         |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Assembly With Decreased Rear Flange Bolt Hole                |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                  | Diameter and Decreased Positional Tolerance                  |               | MSC                 |             |                 |     | -                |          |                    |         |              |
|                  |                                                              |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| (880057)         |                                                              |               |                     |             |                 |     |                  |          |                    |         |              |
| Engine           |                                                              |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101735  | No. 1 Engine - Sb BR700-72-101735 - Bypass Service           |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Fairing - Left and Right Engines - Introduction of           |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Alternative Rivets for the Splitter Fairing Assembly         |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                  |                                                              |               | MSC                 |             |                 |     | -                |          |                    |         |              |
|                  |                                                              |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| (880073)         |                                                              |               |                     |             |                 |     |                  |          |                    |         |              |
| Engine           |                                                              |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101735  | No. 2 Engine - Sb BR700-72-101735 - Bypass Service           |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Fairing - Left and Right Engines - Introduction of           |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Alternative Rivets for the Splitter Fairing Assembly         |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                  |                                                              |               | MSC                 |             |                 |     | -                |          |                    |         |              |
|                  |                                                              |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| (880073)         |                                                              |               |                     |             |                 |     |                  |          |                    |         |              |
| Engine           |                                                              |               |                     |             |                 |     |                  |          |                    |         |              |

| ATA<br>U=Custom        | Description                                                                                                                       |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------------|-----------------------------------------------------------------------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                        | Part Number                                                                                                                       | Serial Number |                     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position       | HW                                                                                                                                | SW            |                     |             |                 |     |                  |             |                    |         | Manufacturer |
|                        | MM Ref                                                                                                                            |               |                     |             |                 |     |                  |             |                    |         | Date Type    |
|                        | Ops Number(s)                                                                                                                     |               |                     |             |                 |     |                  |             |                    |         |              |
| BR700-72-101737        | No. 1 Engine - Sb BR700-72-101737 - High Pressure (Hp)                                                                            |               | HRS                 |             |                 |     |                  |             |                    |         | 0            |
|                        | Compressor Front Split Case - Introduction of Two                                                                                 |               | ENC                 |             |                 |     |                  |             |                    |         | 0            |
|                        | Additional Borescope Access Ports to the Hp Compressor                                                                            |               | DATE                |             |                 |     |                  |             |                    |         |              |
|                        |                                                                                                                                   |               | MSC                 |             |                 |     | -                |             |                    |         |              |
| (880027)               |                                                                                                                                   |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine                 |                                                                                                                                   |               |                     |             |                 |     |                  |             |                    |         |              |
| BR700-72-101737        | No. 2 Engine - Sb BR700-72-101737 - High Pressure (Hp)                                                                            |               | HRS                 |             |                 |     |                  |             |                    |         | 0            |
|                        | Compressor Front Split Case - Introduction of Two                                                                                 |               | ENC                 |             |                 |     |                  |             |                    |         | 0            |
|                        | Additional Borescope Access Ports to the Hp Compressor                                                                            |               | DATE                |             |                 |     |                  |             |                    |         |              |
|                        |                                                                                                                                   |               | MSC                 |             |                 |     | -                |             |                    |         |              |
| (880027)               |                                                                                                                                   |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine                 |                                                                                                                                   |               |                     |             |                 |     |                  |             |                    |         |              |
| BR700-72-101737<br>R01 | No. 1 Engine - Sb BR700-72-101737 R01 - High Pressure (Hp)                                                                        |               | HRS                 |             |                 |     |                  |             |                    |         | 0            |
|                        | Compressor Front Split Case - Introduction of Two                                                                                 |               | ENC                 |             |                 |     |                  |             |                    |         | 0            |
|                        | Additional Borescope Access Ports to the Hp Compressor, Service Bulletin (Optional)                                               |               | MOS                 |             | 29.3            |     |                  | 01 Dec 2023 |                    |         |              |
|                        |                                                                                                                                   |               | MSC                 |             |                 |     | -                |             |                    |         |              |
| (880238)               |                                                                                                                                   |               |                     |             |                 |     |                  |             |                    |         |              |
| Engine                 |                                                                                                                                   |               |                     |             |                 |     |                  |             |                    |         |              |
| BR700-72-101737<br>R01 | No. 2 Engine - Sb BR700-72-101737 R01 - High Pressure (Hp)                                                                        |               | HRS                 |             |                 |     |                  |             |                    |         | 0            |
|                        | Compressor Front Split Case - Introduction of Two                                                                                 |               | ENC                 |             |                 |     |                  |             |                    |         | 0            |
|                        | Additional Borescope Access Ports to the Hp Compressor, Service Bulletin (Optional)                                               |               | MOS                 |             | 29.3            |     |                  | 01 Dec 2023 |                    |         |              |
|                        |                                                                                                                                   |               | MSC                 |             |                 |     | -                |             |                    |         |              |
| (880238)               |                                                                                                                                   |               |                     |             |                 |     |                  |             |                    |         |              |
| Engine                 |                                                                                                                                   |               |                     |             |                 |     |                  |             |                    |         |              |
| BR700-72-101743<br>R02 | No. 1 Engine - Sb BR700-72-101743 R02 - Low Pressure (Lp)                                                                         |               | HRS                 |             |                 |     |                  |             |                    |         | 0            |
|                        | Compressor Blades - Introduction of New Lp                                                                                        |               | ENC                 |             |                 |     |                  |             |                    |         | 0            |
|                        | Compressor Blades With Laser Shock Peening Treatment on the Hub Leading Edge of the Blade Airfoil, Service Bulletin (Recommended) |               | MOS                 |             | 29.2            |     |                  | 05 Dec 2023 |                    |         |              |
|                        |                                                                                                                                   |               | MSC                 |             |                 |     | -                |             |                    |         |              |
| (880232)               |                                                                                                                                   |               |                     |             |                 |     |                  |             |                    |         |              |
| Engine                 |                                                                                                                                   |               |                     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom        | Description                                                                     |               | UOM  | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------------|---------------------------------------------------------------------------------|---------------|------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                        | Part Number                                                                     | Serial Number |      |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position       | HW                                                                              | SW            |      |             |                 |     |                  |             |                    |         | Manufacturer |
|                        | MM Ref                                                                          |               |      |             |                 |     |                  |             |                    |         | Date Type    |
|                        | Ops Number(s)                                                                   |               |      |             |                 |     |                  |             |                    |         |              |
| BR700-72-101743<br>R02 | No. 2 Engine - Sb BR700-72-101743 R02 - Low Pressure                            |               | HRS  |             |                 |     |                  |             |                    |         | 0            |
|                        | (Lp) Compressor Blades - Introduction of New Lp                                 |               | ENC  |             |                 |     |                  |             |                    |         | 0            |
|                        | Compressor Blades With Laser Shock Peening Treatment                            |               | MOS  |             | 29.2            |     |                  | 05 Dec 2023 |                    |         |              |
|                        | on the Hub Leading Edge of the Blade Airfoil, Service<br>Bulletin (Recommended) |               | MSC  |             |                 |     | -                |             |                    |         |              |
| (880232)               |                                                                                 |               |      |             |                 |     |                  |             |                    |         |              |
| Engine                 |                                                                                 |               |      |             |                 |     |                  |             |                    |         |              |
| BR700-72-101747        | No. 1 Engine - Sb BR700-72-101747 - High Pressure (Hp)                          |               | HRS  |             |                 |     |                  |             |                    |         | 0            |
|                        | Compressor Rear Outer Case - Introduction of A Revised                          |               | ENC  |             |                 |     |                  |             |                    |         | 0            |
|                        | Hp Compressor Variable Stator Vane (Vsv) Actuator Rear                          |               | DATE |             |                 |     |                  |             |                    |         |              |
|                        | Support Bracket Assembly                                                        |               | MSC  |             |                 |     | -                |             |                    |         |              |
| (880020)               |                                                                                 |               |      |             |                 |     |                  |             |                    |         |              |
| Engine                 |                                                                                 |               |      |             |                 |     |                  |             |                    |         |              |
| BR700-72-101747        | No. 2 Engine - Sb BR700-72-101747 - High Pressure (Hp)                          |               | HRS  |             |                 |     |                  |             |                    |         | 0            |
|                        | Compressor Rear Outer Case - Introduction of A Revised                          |               | ENC  |             |                 |     |                  |             |                    |         | 0            |
|                        | Hp Compressor Variable Stator Vane (Vsv) Actuator Rear                          |               | DATE |             |                 |     |                  |             |                    |         |              |
|                        | Support Bracket Assembly                                                        |               | MSC  |             |                 |     | -                |             |                    |         |              |
| (880020)               |                                                                                 |               |      |             |                 |     |                  |             |                    |         |              |
| Engine                 |                                                                                 |               |      |             |                 |     |                  |             |                    |         |              |
| BR700-72-101751        | No. 1 Engine - Sb BR700-72-101751 - High Pressure (Hp)                          |               | HRS  |             |                 |     |                  |             |                    |         | 0            |
|                        | Turbine Stage 2 Onward Nozzle Guide Vanes (Ngv) -                               |               | ENC  |             |                 |     |                  |             |                    |         | 0            |
|                        | Introduction of New Hp Turbine Stage 2 Ngv Assemblies                           |               | DATE |             |                 |     |                  |             |                    |         |              |
|                        | Made from A Different Material and Deletion of Coating                          |               | MSC  |             |                 |     | -                |             |                    |         |              |
| (880029)               |                                                                                 |               |      |             |                 |     |                  |             |                    |         |              |
| Engine                 |                                                                                 |               |      |             |                 |     |                  |             |                    |         |              |
| BR700-72-101751        | No. 2 Engine - Sb BR700-72-101751 - High Pressure (Hp)                          |               | HRS  |             |                 |     |                  |             |                    |         | 0            |
|                        | Turbine Stage 2 Onward Nozzle Guide Vanes (Ngv) -                               |               | ENC  |             |                 |     |                  |             |                    |         | 0            |
|                        | Introduction of New Hp Turbine Stage 2 Ngv Assemblies                           |               | DATE |             |                 |     |                  |             |                    |         |              |
|                        | Made from A Different Material and Deletion of Coating                          |               | MSC  |             |                 |     | -                |             |                    |         |              |
| (880029)               |                                                                                 |               |      |             |                 |     |                  |             |                    |         |              |
| Engine                 |                                                                                 |               |      |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom  | Description                                               |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-----------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|----------|--------------------|---------|--------------|
|                  | Part Number                                               | Serial Number |                     |             |                 |     |                  |          |                    |         | Approx Price |
| Logbook Position | HW                                                        | SW            |                     |             |                 |     |                  |          |                    |         | Manufacturer |
|                  | MM Ref                                                    |               |                     |             |                 |     |                  |          |                    |         | Date Type    |
|                  | Ops Number(s)                                             |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101759  | No. 1 Engine - Sb BR700-72-101759 - No.2 Bearing          |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Assembly Front Panel - Introduction of A New No.2         |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Bearing Front Panel With Revised Geometric Tolerances     |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                  | to Ease the Assembly Process                              |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880058)         |                                                           |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine           |                                                           |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101759  | No. 2 Engine - Sb BR700-72-101759 - No.2 Bearing          |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Assembly Front Panel - Introduction of A New No.2         |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Bearing Front Panel With Revised Geometric Tolerances     |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                  | to Ease the Assembly Process                              |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880058)         |                                                           |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine           |                                                           |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101760  | No. 1 Engine - Sb BR700-72-101760 - Low Pressure (Lp)     |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Turbine Fuel Shut-Off (Fso) Cable and Fittings -          |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Introduction of A Revised Fso Cable Assembly Length       |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                  |                                                           |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880019)         |                                                           |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine           |                                                           |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101760  | No. 2 Engine - Sb BR700-72-101760 - Low Pressure (Lp)     |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Turbine Fuel Shut-Off (Fso) Cable and Fittings -          |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Introduction of A Revised Fso Cable Assembly Length       |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                  |                                                           |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880019)         |                                                           |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine           |                                                           |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101773  | No. 1 Engine - Sb BR700-72-101773 - NI Speed Probe        |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Harness and Accessories - Introduction of New Alternative |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                  | NI Speed Probe Brackets With Integrated Bushes            |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                  |                                                           |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880081)         |                                                           |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine           |                                                           |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101773  | No. 2 Engine - Sb BR700-72-101773 - NI Speed Probe        |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Harness and Accessories - Introduction of New Alternative |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                  | NI Speed Probe Brackets With Integrated Bushes            |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                  |                                                           |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880081)         |                                                           |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine           |                                                           |               |                     |             |                 |     |                  |          |                    |         |              |



| ATA<br>U=Custom        | Description                                              |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(* =Adj) | Max Due | Avg Man Hrs  |
|------------------------|----------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|----------|----------------------|---------|--------------|
|                        | Part Number                                              | Serial Number |                     |             |                 |     |                  |          |                      |         | Approx Price |
| Logbook Position       | HW                                                       | SW            |                     |             |                 |     |                  |          |                      |         | Manufacturer |
|                        | MM Ref                                                   |               |                     |             |                 |     |                  |          |                      |         | Date Type    |
|                        | Ops Number(s)                                            |               |                     |             |                 |     |                  |          |                      |         |              |
| BR700-72-101780        | No. 1 Engine - Sb BR700-72-101780 - High Pressure (Hp)   |               | HRS                 |             |                 |     |                  |          |                      |         | 0            |
|                        | Turbine Blades, Nozzle Guide Vanes (Ngv) and Seals -     |               | ENC                 |             |                 |     |                  |          |                      |         | 0            |
|                        | Introduction of Hp Turbine Stage 2 Blades Made from      |               | DATE                |             |                 |     |                  |          |                      |         |              |
|                        | Different Material and Hp Turbine Components With        |               | MSC                 |             |                 |     |                  |          |                      |         |              |
|                        | Modified Cooling AIR Flow                                |               |                     |             |                 |     | -                |          |                      |         |              |
|                        |                                                          |               | [End Of Month Item] |             |                 |     |                  |          |                      |         |              |
| (880088)               |                                                          |               |                     |             |                 |     |                  |          |                      |         |              |
| Engine                 |                                                          |               |                     |             |                 |     |                  |          |                      |         |              |
| BR700-72-101780        | No. 2 Engine - Sb BR700-72-101780 - High Pressure (Hp)   |               | HRS                 |             |                 |     |                  |          |                      |         | 0            |
|                        | Turbine Blades, Nozzle Guide Vanes (Ngv) and Seals -     |               | ENC                 |             |                 |     |                  |          |                      |         | 0            |
|                        | Introduction of Hp Turbine Stage 2 Blades Made from      |               | DATE                |             |                 |     |                  |          |                      |         |              |
|                        | Different Material and Hp Turbine Components With        |               | MSC                 |             |                 |     |                  |          |                      |         |              |
|                        | Modified Cooling AIR Flow                                |               |                     |             |                 |     | -                |          |                      |         |              |
|                        |                                                          |               | [End Of Month Item] |             |                 |     |                  |          |                      |         |              |
| (880088)               |                                                          |               |                     |             |                 |     |                  |          |                      |         |              |
| Engine                 |                                                          |               |                     |             |                 |     |                  |          |                      |         |              |
| BR700-72-101783<br>R01 | No. 1 Engine - Sb BR700-72-101783 R01 - Intermediate     |               | HRS                 |             |                 |     |                  |          |                      |         | 0            |
|                        | Case Module, Combustion and High Pressure (Hp)           |               | ENC                 |             |                 |     |                  |          |                      |         | 0            |
|                        | Turbine Module and Low Pressure (Lp) Turbine Module -    |               | DATE                |             |                 |     |                  |          |                      |         |              |
|                        | Introduction of Alternative Mainline Bearings            |               | MSC                 |             |                 |     |                  |          |                      |         |              |
|                        |                                                          |               |                     |             |                 |     | -                |          |                      |         |              |
|                        |                                                          |               | [End Of Month Item] |             |                 |     |                  |          |                      |         |              |
| (880152)               |                                                          |               |                     |             |                 |     |                  |          |                      |         |              |
| Engine                 |                                                          |               |                     |             |                 |     |                  |          |                      |         |              |
| BR700-72-101783<br>R01 | No. 2 Engine - Sb BR700-72-101783 R01 - Intermediate     |               | HRS                 |             |                 |     |                  |          |                      |         | 0            |
|                        | Case Module, Combustion and High Pressure (Hp)           |               | ENC                 |             |                 |     |                  |          |                      |         | 0            |
|                        | Turbine Module and Low Pressure (Lp) Turbine Module -    |               | DATE                |             |                 |     |                  |          |                      |         |              |
|                        | Introduction of Alternative Mainline Bearings            |               | MSC                 |             |                 |     |                  |          |                      |         |              |
|                        |                                                          |               |                     |             |                 |     | -                |          |                      |         |              |
|                        |                                                          |               | [End Of Month Item] |             |                 |     |                  |          |                      |         |              |
| (880152)               |                                                          |               |                     |             |                 |     |                  |          |                      |         |              |
| Engine                 |                                                          |               |                     |             |                 |     |                  |          |                      |         |              |
| BR700-72-101784        | No. 1 Engine - Sb BR700-72-101784 - High Pressure (Hp)   |               | HRS                 |             |                 |     |                  |          |                      |         | 0            |
|                        | Compressor Front Bearing and Support - Introduction of A |               | ENC                 |             |                 |     |                  |          |                      |         | 0            |
|                        | New Hp Compressor No.3 Bearing Assembly With             |               | DATE                |             |                 |     |                  |          |                      |         |              |
|                        | Improved Robustness                                      |               | MSC                 |             |                 |     |                  |          |                      |         |              |
|                        |                                                          |               |                     |             |                 |     | -                |          |                      |         |              |
|                        |                                                          |               | [End Of Month Item] |             |                 |     |                  |          |                      |         |              |
| (880084)               |                                                          |               |                     |             |                 |     |                  |          |                      |         |              |
| Engine                 |                                                          |               |                     |             |                 |     |                  |          |                      |         |              |

| ATA<br>U=Custom        | Description                                                                                                                                                                               |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|----------|--------------------|---------|--------------|
|                        | Part Number                                                                                                                                                                               | Serial Number |                     |             |                 |     |                  |          |                    |         | Approx Price |
| Logbook Position       | HW                                                                                                                                                                                        | SW            |                     |             |                 |     |                  |          |                    |         | Manufacturer |
|                        | MM Ref                                                                                                                                                                                    |               |                     |             |                 |     |                  |          |                    |         | Date Type    |
|                        | Ops Number(s)                                                                                                                                                                             |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101784        | No. 2 Engine - Sb BR700-72-101784 - High Pressure (Hp)<br>Compressor Front Bearing and Support - Introduction of A<br>New Hp Compressor No.3 Bearing Assembly With<br>Improved Robustness |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                           |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                           |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                                                                                                           |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880084)               |                                                                                                                                                                                           |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                           |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101790        | No. 1 Engine - Sb BR700-72-101790 - High Pressure (Hp)<br>Compressor Fairings - Introduction of New Fixed Fairings<br>With Modified Borescope Access Cutouts                              |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                           |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                           |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                                                                                                           |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880083)               |                                                                                                                                                                                           |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                           |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101790        | No. 2 Engine - Sb BR700-72-101790 - High Pressure (Hp)<br>Compressor Fairings - Introduction of New Fixed Fairings<br>With Modified Borescope Access Cutouts                              |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                           |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                           |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                                                                                                           |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880083)               |                                                                                                                                                                                           |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                           |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101808<br>R01 | No. 1 Engine - Sb BR700-72-101808 R01 - High Pressure<br>(Hp) Compressor Front Split Case - Introduction of<br>Borescope Plugs With Revised Stoving Temperature for<br>the Yellow Paint   |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                           |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                           |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                                                                                                           |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880077)               |                                                                                                                                                                                           |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                           |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101808<br>R01 | No. 2 Engine - Sb BR700-72-101808 R01 - High Pressure<br>(Hp) Compressor Front Split Case - Introduction of<br>Borescope Plugs With Revised Stoving Temperature for<br>the Yellow Paint   |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                           |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                           |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                                                                                                           |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880077)               |                                                                                                                                                                                           |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                           |               |                     |             |                 |     |                  |          |                    |         |              |

| ATA<br>U=Custom        | Description                                                                                                                                                                        |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|----------|--------------------|---------|--------------|
|                        | Part Number                                                                                                                                                                        | Serial Number |                     |             |                 |     |                  |          |                    |         | Approx Price |
| Logbook Position       | HW                                                                                                                                                                                 | SW            |                     |             |                 |     |                  |          |                    |         | Manufacturer |
|                        | MM Ref                                                                                                                                                                             |               |                     |             |                 |     |                  |          |                    |         | Date Type    |
|                        | Ops Number(s)                                                                                                                                                                      |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101810<br>R01 | No. 1 Engine - Sb BR700-72-101810 R01 - High Pressure (Hp) Compressor Rear Outer Case - Introduction of Borescope Plugs With Revised Stoving Temperature for the Yellow Paint      |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                    |               | ENC                 |             |                 |     |                  |          |                    | 0       |              |
|                        |                                                                                                                                                                                    |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                                                                                                    |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880078)               |                                                                                                                                                                                    |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                    |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101810<br>R01 | No. 2 Engine - Sb BR700-72-101810 R01 - High Pressure (Hp) Compressor Rear Outer Case - Introduction of Borescope Plugs With Revised Stoving Temperature for the Yellow Paint      |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                    |               | ENC                 |             |                 |     |                  |          |                    | 0       |              |
|                        |                                                                                                                                                                                    |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                                                                                                    |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880078)               |                                                                                                                                                                                    |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                    |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101812        | No. 1 Engine - Sb BR700-72-101812 - High Pressure (Hp) Turbine Rotor Discs - Introduction of New Part Numbers for the Hp Turbine Curvic Ring                                       |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                    |               | ENC                 |             |                 |     |                  |          |                    | 0       |              |
|                        |                                                                                                                                                                                    |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                                                                                                    |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880053)               |                                                                                                                                                                                    |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                    |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101812        | No. 2 Engine - Sb BR700-72-101812 - High Pressure (Hp) Turbine Rotor Discs - Introduction of New Part Numbers for the Hp Turbine Curvic Ring                                       |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                    |               | ENC                 |             |                 |     |                  |          |                    | 0       |              |
|                        |                                                                                                                                                                                    |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                                                                                                    |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880053)               |                                                                                                                                                                                    |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                    |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101835        | No. 1 Engine - Sb BR700-72-101835 - Low Pressure (Lp) Turbine Nozzle Guide Vanes (Ngv) - Introduction of A New Oil Feed Pipe With A Revised Surface Roughness for Improved Sealing |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                    |               | ENC                 |             |                 |     |                  |          |                    | 0       |              |
|                        |                                                                                                                                                                                    |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                                                                                                    |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880045)               |                                                                                                                                                                                    |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                    |               |                     |             |                 |     |                  |          |                    |         |              |

| ATA<br>U=Custom        | Description                                              |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------------|----------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|----------|--------------------|---------|--------------|
|                        | Part Number                                              | Serial Number |                     |             |                 |     |                  |          |                    |         | Approx Price |
| Logbook Position       | HW                                                       | SW            |                     |             |                 |     |                  |          |                    |         | Manufacturer |
|                        | MM Ref                                                   |               |                     |             |                 |     |                  |          |                    |         | Date Type    |
|                        | Ops Number(s)                                            |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101835        | No. 2 Engine - Sb BR700-72-101835 - Low Pressure (Lp)    |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        | Turbine Nozzle Guide Vanes (Ngv) - Introduction of A New |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                        | Oil Feed Pipe With A Revised Surface Roughness for       |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                        | Improved Sealing                                         |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880045)               |                                                          |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                          |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101836        | No. 1 Engine - Sb BR700-72-101836 - Low Pressure (Lp)    |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        | Turbine Fuel Shut-Off (Fso) Carrier - Introduction of A  |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                        | Redesigned Lp Turbine Fso Pawl Carrier With Two          |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                        | Modified Retaining Plate Bolt Holes                      |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880048)               |                                                          |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                          |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101836        | No. 2 Engine - Sb BR700-72-101836 - Low Pressure (Lp)    |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        | Turbine Fuel Shut-Off (Fso) Carrier - Introduction of A  |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                        | Redesigned Lp Turbine Fso Pawl Carrier With Two          |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                        | Modified Retaining Plate Bolt Holes                      |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880048)               |                                                          |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                          |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101853<br>R01 | No. 1 Engine - Sb BR700-72-101853 R01 - Low Pressure     |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        | (Lp) Turbine Case - Introduction of Lp Turbine Stage 1   |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                        | Liner Segment Assemblies With A Revised Geometry         |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                        |                                                          |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880079)               |                                                          |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                          |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101853<br>R01 | No. 2 Engine - Sb BR700-72-101853 R01 - Low Pressure     |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        | (Lp) Turbine Case - Introduction of Lp Turbine Stage 1   |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                        | Liner Segment Assemblies With A Revised Geometry         |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                        |                                                          |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880079)               |                                                          |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                          |               |                     |             |                 |     |                  |          |                    |         |              |

| ATA<br>U=Custom        | Description                                                                                                                                                                                                                                 |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|----------|--------------------|---------|--------------|
|                        | Part Number                                                                                                                                                                                                                                 | Serial Number |                     |             |                 |     |                  |          |                    |         | Approx Price |
| Logbook Position       | HW                                                                                                                                                                                                                                          | SW            |                     |             |                 |     |                  |          |                    |         | Manufacturer |
|                        | MM Ref                                                                                                                                                                                                                                      |               |                     |             |                 |     |                  |          |                    |         | Date Type    |
|                        | Ops Number(s)                                                                                                                                                                                                                               |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101857<br>R01 | No. 1 Engine - Sb BR700-72-101857 R01 - Low Pressure (Lp) Compressor Outlet Guide Stator Vanes - Introduction of A New Standard of Lp Compressor Outlet Guide Vane (Ogv) Assemblies                                                         |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                                             |               | ENC                 |             |                 |     |                  |          |                    | 0       |              |
|                        |                                                                                                                                                                                                                                             |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                                                                                                                                                             |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880080)               |                                                                                                                                                                                                                                             |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                                                                             |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101857<br>R01 | No. 2 Engine - Sb BR700-72-101857 R01 - Low Pressure (Lp) Compressor Outlet Guide Stator Vanes - Introduction of A New Standard of Lp Compressor Outlet Guide Vane (Ogv) Assemblies                                                         |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                                             |               | ENC                 |             |                 |     |                  |          |                    | 0       |              |
|                        |                                                                                                                                                                                                                                             |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                                                                                                                                                             |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880080)               |                                                                                                                                                                                                                                             |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                                                                             |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101861        | No. 1 Engine - Sb BR700-72-101861 - Combustion and High Pressure (Hp) Turbine Module Attaching Parts and Fittings - Introduction of Two New Brackets Made from Different Material and Installed AT the Combustion Chamber Outer Case (Ccoc) |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                                             |               | ENC                 |             |                 |     |                  |          |                    | 0       |              |
|                        |                                                                                                                                                                                                                                             |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                                                                                                                                                             |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880051)               |                                                                                                                                                                                                                                             |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                                                                             |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101861        | No. 2 Engine - Sb BR700-72-101861 - Combustion and High Pressure (Hp) Turbine Module Attaching Parts and Fittings - Introduction of Two New Brackets Made from Different Material and Installed AT the Combustion Chamber Outer Case (Ccoc) |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                                             |               | ENC                 |             |                 |     |                  |          |                    | 0       |              |
|                        |                                                                                                                                                                                                                                             |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                                                                                                                                                             |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880051)               |                                                                                                                                                                                                                                             |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                                                                             |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101863        | No. 1 Engine - Sb BR700-72-101863 - Low Pressure (Lp) Compressor Rotor Shaft, Lp Compressor Bearing Seals and Lp Compressor Static Seals - Introduction of A Revised Front Bearing Chamber (Fbc) Oil Sealing Arrangement                    |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                                             |               | ENC                 |             |                 |     |                  |          |                    | 0       |              |
|                        |                                                                                                                                                                                                                                             |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                                                                                                                                                             |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880071)               |                                                                                                                                                                                                                                             |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                                                                             |               |                     |             |                 |     |                  |          |                    |         |              |

| ATA<br>U=Custom  | Description                                                 |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|----------|--------------------|---------|--------------|
|                  | Part Number                                                 | Serial Number |                     |             |                 |     |                  |          |                    |         | Approx Price |
| Logbook Position | HW                                                          | SW            |                     |             |                 |     |                  |          |                    |         | Manufacturer |
|                  | MM Ref                                                      |               |                     |             |                 |     |                  |          |                    |         | Date Type    |
|                  | Ops Number(s)                                               |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101863  | No. 2 Engine - Sb BR700-72-101863 - Low Pressure (Lp)       |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Compressor Rotor Shaft, Lp Compressor Bearing Seals         |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                  | and Lp Compressor Static Seals - Introduction of A          |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                  | Revised Front Bearing Chamber (Fbc) Oil Sealing Arrangement |               | MSC                 |             |                 |     | -                |          |                    |         |              |
|                  |                                                             |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| (880071)         |                                                             |               |                     |             |                 |     |                  |          |                    |         |              |
| Engine           |                                                             |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101869  | No. 1 Engine - Sb BR700-72-101869 - High Pressure (Hp)      |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Compressor Bearing Front Support and Hp Compressor          |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Rotor Seals - Introduction of A Revised Front Bearing       |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                  | Chamber (Fbc) Rear Buffer Sealing Arrangement               |               | MSC                 |             |                 |     | -                |          |                    |         |              |
|                  |                                                             |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| (880072)         |                                                             |               |                     |             |                 |     |                  |          |                    |         |              |
| Engine           |                                                             |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101869  | No. 2 Engine - Sb BR700-72-101869 - High Pressure (Hp)      |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Compressor Bearing Front Support and Hp Compressor          |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Rotor Seals - Introduction of A Revised Front Bearing       |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                  | Chamber (Fbc) Rear Buffer Sealing Arrangement               |               | MSC                 |             |                 |     | -                |          |                    |         |              |
|                  |                                                             |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| (880072)         |                                                             |               |                     |             |                 |     |                  |          |                    |         |              |
| Engine           |                                                             |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101878  | No. 1 Engine - Sb BR700-72-101878 - High Pressure (Hp)      |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Compressor Fairings - Introduction of A New Fairing Panel   |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                  | (Channel) With Adjusted Dimensions and Deleted              |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                  | Blanking Plate                                              |               | MSC                 |             |                 |     | -                |          |                    |         |              |
|                  |                                                             |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| (880101)         |                                                             |               |                     |             |                 |     |                  |          |                    |         |              |
| Engine           |                                                             |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101878  | No. 2 Engine - Sb BR700-72-101878 - High Pressure (Hp)      |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Compressor Fairings - Introduction of A New Fairing Panel   |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                  | (Channel) With Adjusted Dimensions and Deleted              |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                  | Blanking Plate                                              |               | MSC                 |             |                 |     | -                |          |                    |         |              |
|                  |                                                             |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| (880101)         |                                                             |               |                     |             |                 |     |                  |          |                    |         |              |
| Engine           |                                                             |               |                     |             |                 |     |                  |          |                    |         |              |

| ATA<br>U=Custom        | Description                                                                                                     |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------------|-----------------------------------------------------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|----------|--------------------|---------|--------------|
|                        | Part Number                                                                                                     | Serial Number |                     |             |                 |     |                  |          |                    |         | Approx Price |
| Logbook Position       | HW                                                                                                              | SW            |                     |             |                 |     |                  |          |                    |         | Manufacturer |
|                        | MM Ref                                                                                                          |               |                     |             |                 |     |                  |          |                    |         | Date Type    |
|                        | Ops Number(s)                                                                                                   |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101896        | No. 1 Engine - Sb BR700-72-101896 - High Pressure (Hp)                                                          |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        | Compressor Blades - Introduction of Alternative Hp                                                              |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                        | Compressor Stages 7 to 10 Blades With Revised Leading Edges                                                     |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                                 |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880089)               |                                                                                                                 |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                 |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101896        | No. 2 Engine - Sb BR700-72-101896 - High Pressure (Hp)                                                          |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        | Compressor Blades - Introduction of Alternative Hp                                                              |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                        | Compressor Stages 7 to 10 Blades With Revised Leading Edges                                                     |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                                 |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880089)               |                                                                                                                 |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                 |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101903<br>R01 | No. 1 Engine - Sb BR700-72-101903 R01 - Low Pressure (Lp)/High Pressure (Hp) Turbine Stator Retainers/Seals -   |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        | Introduction of New Bearing Carriers With Tightened Geometrical Tolerances                                      |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                 |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                                 |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880105)               |                                                                                                                 |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                 |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101903<br>R01 | No. 2 Engine - Sb BR700-72-101903 R01 - Low Pressure (Lp)/High Pressure (Hp) Turbine Stator Retainers/Seals -   |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        | Introduction of New Bearing Carriers With Tightened Geometrical Tolerances                                      |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                 |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                                 |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880105)               |                                                                                                                 |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                 |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101907<br>R02 | No. 1 Engine - Sb BR700-72-101907 R02 - BR700-72-101907 R02 - High Pressure (Hp) Compressor Rotor               |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        | Hydraulic Seal - Introduction of A Modified Hp                                                                  |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                        | Compressor Hydraulic Seal Assembly With A Shortened Timing Lug and Modified Surface Treatment of the Timing Lug |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                                 |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880211)               |                                                                                                                 |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                 |               |                     |             |                 |     |                  |          |                    |         |              |

| ATA<br>U=Custom        | Description                                                                                       |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------------|---------------------------------------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|----------|--------------------|---------|--------------|
|                        | Part Number                                                                                       | Serial Number |                     |             |                 |     |                  |          |                    |         | Approx Price |
| Logbook Position       | HW                                                                                                | SW            |                     |             |                 |     |                  |          |                    |         | Manufacturer |
|                        | MM Ref                                                                                            |               |                     |             |                 |     |                  |          |                    |         | Date Type    |
|                        | Ops Number(s)                                                                                     |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101907<br>R02 | No. 2 Engine - Sb BR700-72-101907 R02 - BR700-72-101907 R02 - High Pressure (Hp) Compressor Rotor |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        | Hydraulic Seal - Introduction of A Modified Hp                                                    |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                        | Compressor Hydraulic Seal Assembly With A Shortened                                               |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                        | Timing Lug and Modified Surface Treatment of the Timing                                           |               | MSC                 |             |                 |     | -                |          |                    |         |              |
|                        | Lug                                                                                               |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| (880211)               |                                                                                                   |               |                     |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                   |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101913        | No. 1 Engine - Sb BR700-72-101913 - High Pressure (Hp)                                            |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        | Compressor Rear Rotor Discs - Introduction of Silver-Free                                         |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                        | Nuts for the Stages 6 to 7 Bolted Joint of the Hp                                                 |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                        | Compressor Rotor Assembly                                                                         |               | MSC                 |             |                 |     | -                |          |                    |         |              |
|                        |                                                                                                   |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| (880103)               |                                                                                                   |               |                     |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                   |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101913        | No. 2 Engine - Sb BR700-72-101913 - High Pressure (Hp)                                            |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        | Compressor Rear Rotor Discs - Introduction of Silver-Free                                         |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                        | Nuts for the Stages 6 to 7 Bolted Joint of the Hp                                                 |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                        | Compressor Rotor Assembly                                                                         |               | MSC                 |             |                 |     | -                |          |                    |         |              |
|                        |                                                                                                   |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| (880103)               |                                                                                                   |               |                     |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                   |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101915        | No. 1 Engine - Sb BR700-72-101915 - High Pressure (Hp)                                            |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        | Compressor Rear Rotor Discs - Introduction of New Anti-                                           |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                        | Score Plates                                                                                      |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                   |               | MSC                 |             |                 |     | -                |          |                    |         |              |
|                        |                                                                                                   |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| (880100)               |                                                                                                   |               |                     |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                   |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101915        | No. 2 Engine - Sb BR700-72-101915 - High Pressure (Hp)                                            |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        | Compressor Rear Rotor Discs - Introduction of New Anti-                                           |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                        | Score Plates                                                                                      |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                   |               | MSC                 |             |                 |     | -                |          |                    |         |              |
|                        |                                                                                                   |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| (880100)               |                                                                                                   |               |                     |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                   |               |                     |             |                 |     |                  |          |                    |         |              |



| ATA<br>U=Custom  | Description                                               |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-----------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|----------|--------------------|---------|--------------|
|                  | Part Number                                               | Serial Number |                     |             |                 |     |                  |          |                    |         | Approx Price |
| Logbook Position | HW                                                        | SW            |                     |             |                 |     |                  |          |                    |         | Manufacturer |
|                  | MM Ref                                                    |               |                     |             |                 |     |                  |          |                    |         | Date Type    |
|                  | Ops Number(s)                                             |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101924  | No. 1 Engine - Sb BR700-72-101924 - Turbine Exhaust       |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Supports - Introduction of Alternative Rear Support Strut |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Assemblies Made from A Different Material                 |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                  |                                                           |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880095)         |                                                           |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine           |                                                           |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101924  | No. 2 Engine - Sb BR700-72-101924 - Turbine Exhaust       |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Supports - Introduction of Alternative Rear Support Strut |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Assemblies Made from A Different Material                 |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                  |                                                           |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880095)         |                                                           |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine           |                                                           |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101932  | No. 1 Engine - Sb BR700-72-101932 - Internal Gearbox      |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Drive-Driven Assembly - Introduction of Alternative       |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Bearing Assemblies for the Radial Drive Shaft (Rds)       |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                  |                                                           |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880110)         |                                                           |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine           |                                                           |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101932  | No. 2 Engine - Sb BR700-72-101932 - Internal Gearbox      |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Drive-Driven Assembly - Introduction of Alternative       |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Bearing Assemblies for the Radial Drive Shaft (Rds)       |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                  |                                                           |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880110)         |                                                           |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine           |                                                           |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101936  | No. 1 Engine - Sb BR700-72-101936 - High Pressure (Hp)    |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Turbine Case Impingement Cooling Manifold -               |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Introduction of A Modified Upper Segment (Us) Turbine     |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                  | Case Cooling (TCC) Manifold With A Repositioned           |               | MSC                 |             |                 |     | -                |          |                    |         |              |
|                  | Turbine Gas Temperature (Tgt) Harness Connector           |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
|                  | Bracket                                                   |               |                     |             |                 |     |                  |          |                    |         |              |
| (880104)         |                                                           |               |                     |             |                 |     |                  |          |                    |         |              |
| Engine           |                                                           |               |                     |             |                 |     |                  |          |                    |         |              |

| ATA<br>U=Custom  | Description                                                                |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|----------------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|----------|--------------------|---------|--------------|
|                  | Part Number                                                                | Serial Number |                     |             |                 |     |                  |          |                    |         | Approx Price |
| Logbook Position | HW                                                                         | SW            |                     |             |                 |     |                  |          |                    |         | Manufacturer |
|                  | MM Ref                                                                     |               |                     |             |                 |     |                  |          |                    |         | Date Type    |
|                  | Ops Number(s)                                                              |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101936  | No. 2 Engine - Sb BR700-72-101936 - High Pressure (Hp)                     |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Turbine Case Impingement Cooling Manifold -                                |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Introduction of A Modified Upper Segment (Us) Turbine                      |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                  | Case Cooling (TCC) Manifold With A Repositioned                            |               | MSC                 |             |                 |     | -                |          |                    |         |              |
|                  | Turbine Gas Temperature (Tgt) Harness Connector Bracket                    |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| (880104)         |                                                                            |               |                     |             |                 |     |                  |          |                    |         |              |
| Engine           |                                                                            |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101938  | No. 1 Engine - Sb BR700-72-101938 - High Pressure (Hp)                     |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Compressor Stage 5 Onward Stator Vanes - Introduction                      |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                  | of Alternative Hp Compressor Stage 7 Vanes Produced to                     |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                  | A New Manufacturing Method                                                 |               | MSC                 |             |                 |     | -                |          |                    |         |              |
|                  |                                                                            |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| (880157)         |                                                                            |               |                     |             |                 |     |                  |          |                    |         |              |
| Engine           |                                                                            |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101938  | No. 2 Engine - Sb BR700-72-101938 - High Pressure (Hp)                     |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Compressor Stage 5 Onward Stator Vanes - Introduction                      |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                  | of Alternative Hp Compressor Stage 7 Vanes Produced to                     |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                  | A New Manufacturing Method                                                 |               | MSC                 |             |                 |     | -                |          |                    |         |              |
|                  |                                                                            |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| (880157)         |                                                                            |               |                     |             |                 |     |                  |          |                    |         |              |
| Engine           |                                                                            |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101943  | No. 1 Engine - Sb BR700-72-101943 - High Pressure (Hp)                     |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Turbine Rotor Discs and Hp Turbine Stage 1 Nozzle                          |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Guide Seals - Introduction of Hp Turbine Stage 1 and                       |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                  | Stage 2 Discs Made from A Different Material and                           |               | MSC                 |             |                 |     | -                |          |                    |         |              |
|                  | Introduction of A Redesigned Hp Turbine Stage 1 Preswirl Web Seal Assembly |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| (880134)         |                                                                            |               |                     |             |                 |     |                  |          |                    |         |              |
| Engine           |                                                                            |               |                     |             |                 |     |                  |          |                    |         |              |

| ATA<br>U=Custom   | Description                                              |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|-------------------|----------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|----------|--------------------|---------|--------------|
|                   | Part Number                                              | Serial Number |                     |             |                 |     |                  |          |                    |         | Approx Price |
| Logbook Position  | HW                                                       | SW            |                     |             |                 |     |                  |          |                    |         | Manufacturer |
|                   | MM Ref                                                   |               |                     |             |                 |     |                  |          |                    |         | Date Type    |
|                   | Ops Number(s)                                            |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101943   | No. 2 Engine - Sb BR700-72-101943 - High Pressure (Hp)   |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                   | Turbine Rotor Discs and Hp Turbine Stage 1 Nozzle        |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                   | Guide Seals - Introduction of Hp Turbine Stage 1 and     |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                   | Stage 2 Discs Made from A Different Material and         |               | MSC                 |             |                 |     | -                |          |                    |         |              |
|                   | Introduction of A Redesigned Hp Turbine Stage 1 Preswirl |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Web Seal Assembly |                                                          |               |                     |             |                 |     |                  |          |                    |         |              |
| (880134)          |                                                          |               |                     |             |                 |     |                  |          |                    |         |              |
| Engine            |                                                          |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101950   | No. 1 Engine - Sb BR700-72-101950 - High Pressure (Hp)   |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                   | Turbine Blades - Introduction of Hp Turbine Stage 1      |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                   | Blades Made from A Different Material                    |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                   |                                                          |               | MSC                 |             |                 |     | -                |          |                    |         |              |
|                   |                                                          |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| (880128)          |                                                          |               |                     |             |                 |     |                  |          |                    |         |              |
| Engine            |                                                          |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101950   | No. 2 Engine - Sb BR700-72-101950 - High Pressure (Hp)   |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                   | Turbine Blades - Introduction of Hp Turbine Stage 1      |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                   | Blades Made from A Different Material                    |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                   |                                                          |               | MSC                 |             |                 |     | -                |          |                    |         |              |
|                   |                                                          |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| (880128)          |                                                          |               |                     |             |                 |     |                  |          |                    |         |              |
| Engine            |                                                          |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101954   | No. 1 Engine - Sb BR700-72-101954 - Low Pressure (Lp)    |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                   | Compressor Rotor Disc - Introduction of an Lp            |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                   | Compressor Rotor Disc Produced In Accordance With A      |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                   | Different Manufacturing Process                          |               | MSC                 |             |                 |     | -                |          |                    |         |              |
|                   |                                                          |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| (880138)          |                                                          |               |                     |             |                 |     |                  |          |                    |         |              |
| Engine            |                                                          |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101954   | No. 2 Engine - Sb BR700-72-101954 - Low Pressure (Lp)    |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                   | Compressor Rotor Disc - Introduction of an Lp            |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                   | Compressor Rotor Disc Produced In Accordance With A      |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                   | Different Manufacturing Process                          |               | MSC                 |             |                 |     | -                |          |                    |         |              |
|                   |                                                          |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| (880138)          |                                                          |               |                     |             |                 |     |                  |          |                    |         |              |
| Engine            |                                                          |               |                     |             |                 |     |                  |          |                    |         |              |

| ATA<br>U=Custom  | Description                                             |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|---------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|----------|--------------------|---------|--------------|
|                  | Part Number                                             | Serial Number |                     |             |                 |     |                  |          |                    |         | Approx Price |
| Logbook Position | HW                                                      | SW            |                     |             |                 |     |                  |          |                    |         | Manufacturer |
|                  | MM Ref                                                  |               |                     |             |                 |     |                  |          |                    |         | Date Type    |
|                  | Ops Number(s)                                           |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101963  | No. 1 Engine - Sb BR700-72-101963 - High Pressure (Hp)  |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Turbine Case Impingement Cooling Manifold -             |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Introduction of Alternative Rivets for the Turbine Case |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                  | Cooling (TCC) Manifold                                  |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880144)         |                                                         |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine           |                                                         |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101963  | No. 2 Engine - Sb BR700-72-101963 - High Pressure (Hp)  |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Turbine Case Impingement Cooling Manifold -             |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Introduction of Alternative Rivets for the Turbine Case |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                  | Cooling (TCC) Manifold                                  |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880144)         |                                                         |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine           |                                                         |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101970  | No. 1 Engine - Sb BR700-72-101970 - NI Speed Probe      |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Harness and Accessories - Introduction of A New         |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Assembly Procedure for the NI Speed Probe Harness       |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                  | Assemblies                                              |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880117)         |                                                         |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine           |                                                         |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101970  | No. 2 Engine - Sb BR700-72-101970 - NI Speed Probe      |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Harness and Accessories - Introduction of A New         |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Assembly Procedure for the NI Speed Probe Harness       |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                  | Assemblies                                              |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880117)         |                                                         |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine           |                                                         |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101978  | No. 1 Engine - Sb BR700-72-101978 - NI Speed Probe      |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Harness and Accessories - Introduction of NI Speed      |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Probe Harness Assemblies With Revised Hermetic Seals    |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                  |                                                         |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880136)         |                                                         |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine           |                                                         |               |                     |             |                 |     |                  |          |                    |         |              |

| ATA<br>U=Custom  | Description                                               |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-----------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|----------|--------------------|---------|--------------|
|                  | Part Number                                               | Serial Number |                     |             |                 |     |                  |          |                    |         | Approx Price |
| Logbook Position | HW                                                        | SW            |                     |             |                 |     |                  |          |                    |         | Manufacturer |
|                  | MM Ref                                                    |               |                     |             |                 |     |                  |          |                    |         | Date Type    |
|                  | Ops Number(s)                                             |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101978  | No. 2 Engine - Sb BR700-72-101978 - NI Speed Probe        |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Harness and Accessories - Introduction of NI Speed        |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Probe Harness Assemblies With Revised Hermetic Seals      |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                  |                                                           |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880136)         |                                                           |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine           |                                                           |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101982  | No. 1 Engine - Sb BR700-72-101982 - Compressor            |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Intermediate Case and Fittings - Introduction of an       |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Alternative Casting for the Intermediate Case Assembly    |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                  |                                                           |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880143)         |                                                           |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine           |                                                           |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101982  | No. 2 Engine - Sb BR700-72-101982 - Compressor            |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Intermediate Case and Fittings - Introduction of an       |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Alternative Casting for the Intermediate Case Assembly    |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                  |                                                           |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880143)         |                                                           |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine           |                                                           |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101991  | No. 1 Engine - Sb BR700-72-101991 - Low Pressure (Lp)     |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                  | /High Pressure (Hp) Turbine Stator Retainers/Seals -      |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Introduction of A New Front Seal Carrier, A New Rear Seal |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                  | Carrier and New Bearing Carriers                          |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880148)         |                                                           |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine           |                                                           |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101991  | No. 2 Engine - Sb BR700-72-101991 - Low Pressure (Lp)     |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                  | /High Pressure (Hp) Turbine Stator Retainers/Seals -      |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Introduction of A New Front Seal Carrier, A New Rear Seal |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                  | Carrier and New Bearing Carriers                          |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880148)         |                                                           |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine           |                                                           |               |                     |             |                 |     |                  |          |                    |         |              |

| ATA<br>U=Custom  | Description                                                                                                                                                                                         |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|----------|--------------------|---------|--------------|
|                  | Part Number                                                                                                                                                                                         | Serial Number |                     |             |                 |     |                  |          |                    |         | Approx Price |
| Logbook Position | HW                                                                                                                                                                                                  | SW            |                     |             |                 |     |                  |          |                    |         | Manufacturer |
|                  | MM Ref                                                                                                                                                                                              |               |                     |             |                 |     |                  |          |                    |         | Date Type    |
|                  | Ops Number(s)                                                                                                                                                                                       |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101995  | No. 1 Engine - Sb BR700-72-101995 - Combustion and High Pressure (Hp) Turbine Module Attach Parts and Fittings - Introduction of A Redesigned FIRE Extinguisher Nozzle AT the Core Engine Flange CC |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                  |                                                                                                                                                                                                     |               | ENC                 |             |                 |     |                  |          |                    | 0       |              |
|                  |                                                                                                                                                                                                     |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                  |                                                                                                                                                                                                     |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880154)         |                                                                                                                                                                                                     |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine           |                                                                                                                                                                                                     |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-101995  | No. 2 Engine - Sb BR700-72-101995 - Combustion and High Pressure (Hp) Turbine Module Attach Parts and Fittings - Introduction of A Redesigned FIRE Extinguisher Nozzle AT the Core Engine Flange CC |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                  |                                                                                                                                                                                                     |               | ENC                 |             |                 |     |                  |          |                    | 0       |              |
|                  |                                                                                                                                                                                                     |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                  |                                                                                                                                                                                                     |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880154)         |                                                                                                                                                                                                     |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine           |                                                                                                                                                                                                     |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-102030  | No. 1 Engine - Sb BR700-72-102030 - Low Pressure (Lp) Compressor Front Bearing and Support - Removal of One Existing Alternative No.1 Bearing Assembly                                              |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                  |                                                                                                                                                                                                     |               | ENC                 |             |                 |     |                  |          |                    | 0       |              |
|                  |                                                                                                                                                                                                     |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                  |                                                                                                                                                                                                     |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880153)         |                                                                                                                                                                                                     |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine           |                                                                                                                                                                                                     |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-102030  | No. 2 Engine - Sb BR700-72-102030 - Low Pressure (Lp) Compressor Front Bearing and Support - Removal of One Existing Alternative No.1 Bearing Assembly                                              |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                  |                                                                                                                                                                                                     |               | ENC                 |             |                 |     |                  |          |                    | 0       |              |
|                  |                                                                                                                                                                                                     |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                  |                                                                                                                                                                                                     |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880153)         |                                                                                                                                                                                                     |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine           |                                                                                                                                                                                                     |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-102059  | No. 1 Engine - Sb BR700-72-102059 - NI Speed Probe Harness and Accessories - Introduction of New NI Speed Probe Brackets                                                                            |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                  |                                                                                                                                                                                                     |               | ENC                 |             |                 |     |                  |          |                    | 0       |              |
|                  |                                                                                                                                                                                                     |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                  |                                                                                                                                                                                                     |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880159)         |                                                                                                                                                                                                     |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine           |                                                                                                                                                                                                     |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-102059  | No. 2 Engine - Sb BR700-72-102059 - NI Speed Probe Harness and Accessories - Introduction of New NI Speed Probe Brackets                                                                            |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                  |                                                                                                                                                                                                     |               | ENC                 |             |                 |     |                  |          |                    | 0       |              |
|                  |                                                                                                                                                                                                     |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                  |                                                                                                                                                                                                     |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880159)         |                                                                                                                                                                                                     |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine           |                                                                                                                                                                                                     |               |                     |             |                 |     |                  |          |                    |         |              |

| ATA<br>U=Custom  | Description                                                |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|----------|--------------------|---------|--------------|
|                  | Part Number                                                | Serial Number |                     |             |                 |     |                  |          |                    |         | Approx Price |
| Logbook Position | HW                                                         | SW            |                     |             |                 |     |                  |          |                    |         | Manufacturer |
|                  | MM Ref                                                     |               |                     |             |                 |     |                  |          |                    |         | Date Type    |
|                  | Ops Number(s)                                              |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-102065  | No. 1 Engine - Sb BR700-72-102065 - Accessory              |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Gearbox Module - Introduction of an Alternative Transfer   |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Tube and an Alternative Identification Plate Support Plate |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                  | for the Accessory Gearbox                                  |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880158)         |                                                            |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine           |                                                            |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-102065  | No. 2 Engine - Sb BR700-72-102065 - Accessory              |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Gearbox Module - Introduction of an Alternative Transfer   |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Tube and an Alternative Identification Plate Support Plate |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                  | for the Accessory Gearbox                                  |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880158)         |                                                            |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine           |                                                            |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-102076  | No. 1 Engine - Sb BR700-72-102076 - Accessory              |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Gearbox Module - Introduction of Alternative Drain Plugs   |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                  | AT the Engine Oil Tank Drain Location of the Accessory     |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                  | Gearbox                                                    |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880164)         |                                                            |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine           |                                                            |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-102076  | No. 2 Engine - Sb BR700-72-102076 - Accessory              |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Gearbox Module - Introduction of Alternative Drain Plugs   |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                  | AT the Engine Oil Tank Drain Location of the Accessory     |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                  | Gearbox                                                    |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880164)         |                                                            |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine           |                                                            |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-102086  | No. 1 Engine - Sb BR700-72-102086 - Low Pressure (Lp)      |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Compressor Front Bearing and Support - Introduction of     |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                  | an Alternative Bearing No.1 from Another Manufacturer      |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                  |                                                            |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880172)         |                                                            |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine           |                                                            |               |                     |             |                 |     |                  |          |                    |         |              |

| ATA<br>U=Custom  | Description                                                                                                                                                      |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|----------|--------------------|---------|--------------|
|                  | Part Number                                                                                                                                                      | Serial Number |                     |             |                 |     |                  |          |                    |         | Approx Price |
| Logbook Position | HW                                                                                                                                                               | SW            |                     |             |                 |     |                  |          |                    |         | Manufacturer |
|                  | MM Ref                                                                                                                                                           |               |                     |             |                 |     |                  |          |                    |         | Date Type    |
|                  | Ops Number(s)                                                                                                                                                    |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-102086  | No. 2 Engine - Sb BR700-72-102086 - Low Pressure (Lp)                                                                                                            |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Compressor Front Bearing and Support - Introduction of an Alternative Bearing No.1 from Another Manufacturer                                                     |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                  |                                                                                                                                                                  |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                  |                                                                                                                                                                  |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880172)         |                                                                                                                                                                  |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine           |                                                                                                                                                                  |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-102106  | No. 1 Engine - Sb BR700-72-102106 - Compressor                                                                                                                   |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Intermediate Case and Fittings - Introduction of Alternative Bushes Made from A Different Material for Use In the Existing Intermediate Case                     |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                  |                                                                                                                                                                  |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                  |                                                                                                                                                                  |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880177)         |                                                                                                                                                                  |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine           |                                                                                                                                                                  |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-102106  | No. 2 Engine - Sb BR700-72-102106 - Compressor                                                                                                                   |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Intermediate Case and Fittings - Introduction of Alternative Bushes Made from A Different Material for Use In the Existing Intermediate Case                     |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                  |                                                                                                                                                                  |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                  |                                                                                                                                                                  |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880177)         |                                                                                                                                                                  |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine           |                                                                                                                                                                  |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-102157  | No. 1 Engine - Sb BR700-72-102157 - Low Pressure (Lp)                                                                                                            |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Compressor/Internal Gearbox AIR Distribution Tubes - Introduction of an AIR Manifold Housing Manufactured In Accordance With A More Precise Machining Definition |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                  |                                                                                                                                                                  |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                  |                                                                                                                                                                  |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880194)         |                                                                                                                                                                  |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine           |                                                                                                                                                                  |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-102157  | No. 2 Engine - Sb BR700-72-102157 - Low Pressure (Lp)                                                                                                            |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Compressor/Internal Gearbox AIR Distribution Tubes - Introduction of an AIR Manifold Housing Manufactured In Accordance With A More Precise Machining Definition |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                  |                                                                                                                                                                  |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                  |                                                                                                                                                                  |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880194)         |                                                                                                                                                                  |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine           |                                                                                                                                                                  |               |                     |             |                 |     |                  |          |                    |         |              |



| ATA<br>U=Custom        | Description                                               |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------------|-----------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|----------|--------------------|---------|--------------|
|                        | Part Number                                               | Serial Number |                     |             |                 |     |                  |          |                    |         | Approx Price |
| Logbook Position       | HW                                                        | SW            |                     |             |                 |     |                  |          |                    |         | Manufacturer |
|                        | MM Ref                                                    |               |                     |             |                 |     |                  |          |                    |         | Date Type    |
|                        | Ops Number(s)                                             |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-102165        | No. 1 Engine - Sb BR700-72-102165 - Low Pressure (Lp)     |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        | Turbine Fuel Shut-Off (Fso) Cable and Fittings -          |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                        | Introduction of A New Conduit Assembly for the Fuel Shut- |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                        | Off Mechanism                                             |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880207)               |                                                           |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                           |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-102165        | No. 2 Engine - Sb BR700-72-102165 - Low Pressure (Lp)     |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        | Turbine Fuel Shut-Off (Fso) Cable and Fittings -          |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                        | Introduction of A New Conduit Assembly for the Fuel Shut- |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                        | Off Mechanism                                             |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880207)               |                                                           |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                           |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-102171        | No. 1 Engine - Sb BR700-72-102171 - Internal Gearbox      |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        | Drive-Driven Assembly - Introduction of an Alternative    |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                        | Spiralock Insert for the Radial Drive Shaft (Rds) Lower   |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                        | Support Housing                                           |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880195)               |                                                           |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                           |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-102171        | No. 2 Engine - Sb BR700-72-102171 - Internal Gearbox      |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        | Drive-Driven Assembly - Introduction of an Alternative    |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                        | Spiralock Insert for the Radial Drive Shaft (Rds) Lower   |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                        | Support Housing                                           |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880195)               |                                                           |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                           |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-102214<br>R01 | No. 1 Engine - Sb BR700-72-102214 R01 - Sb BR700-72-      |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        | 102214 R01 - High Pressure (Hp) Compressor Front          |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                        | Case - Introduction of A New Hp Compressor Front Case     |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                        | Assembly Made By A Different Supplier                     |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880218)               |                                                           |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                           |               |                     |             |                 |     |                  |          |                    |         |              |

| ATA<br>U=Custom        | Description                                                                                                                                                                                                              |               | UOM  | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|------|-------------|-----------------|-----|------------------|----------|--------------------|---------|--------------|
|                        | Part Number                                                                                                                                                                                                              | Serial Number |      |             |                 |     |                  |          |                    |         | Approx Price |
| Logbook Position       | HW                                                                                                                                                                                                                       | SW            |      |             |                 |     |                  |          |                    |         | Manufacturer |
|                        | MM Ref                                                                                                                                                                                                                   |               |      |             |                 |     |                  |          |                    |         | Date Type    |
|                        | Ops Number(s)                                                                                                                                                                                                            |               |      |             |                 |     |                  |          |                    |         |              |
| BR700-72-102214<br>R01 | No. 2 Engine - Sb BR700-72-102214 R01 - Sb BR700-72-102214 R01 - High Pressure (Hp) Compressor Front Case - Introduction of A New Hp Compressor Front Case Assembly Made By A Different Supplier                         |               | HRS  |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                          |               | ENC  |             |                 |     |                  |          |                    | 0       |              |
|                        |                                                                                                                                                                                                                          |               | DATE |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                                                                                                                                          |               | MSC  |             |                 | -   |                  |          |                    |         |              |
| (880218)               | [End Of Month Item]                                                                                                                                                                                                      |               |      |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                                                          |               |      |             |                 |     |                  |          |                    |         |              |
| BR700-72-102214<br>R02 | No. 1 Engine - Sb BR700-72-102214 R02 - High Pressure (Hp) Compressor Front Case - Introduction of A New Hp Compressor Front Case Assembly Made By A Different Supplier, Service Bulletin (Optional)                     |               | HRS  |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                          |               | ENC  |             |                 |     |                  |          |                    | 0       |              |
|                        |                                                                                                                                                                                                                          |               | MOS  | 26.2        |                 |     | 06 Mar 2024      |          |                    |         |              |
|                        |                                                                                                                                                                                                                          |               | MSC  |             |                 | -   |                  |          |                    |         |              |
| (880230)               |                                                                                                                                                                                                                          |               |      |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                                                          |               |      |             |                 |     |                  |          |                    |         |              |
| BR700-72-102214<br>R02 | No. 2 Engine - Sb BR700-72-102214 R02 - High Pressure (Hp) Compressor Front Case - Introduction of A New Hp Compressor Front Case Assembly Made By A Different Supplier, Service Bulletin (Optional)                     |               | HRS  |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                          |               | ENC  |             |                 |     |                  |          |                    | 0       |              |
|                        |                                                                                                                                                                                                                          |               | MOS  | 26.2        |                 |     | 06 Mar 2024      |          |                    |         |              |
|                        |                                                                                                                                                                                                                          |               | MSC  |             |                 | -   |                  |          |                    |         |              |
| (880230)               |                                                                                                                                                                                                                          |               |      |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                                                          |               |      |             |                 |     |                  |          |                    |         |              |
| BR700-72-102227<br>R01 | No. 1 Engine - Sb BR700-72-102227 R01 - BR700-72-102227 R01 - Accessory Gearbox Module - Introduction of an Alternative Nut Standard and an Alternative Nail Standard Used for the Installation of the Nameplate Support |               | HRS  |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                          |               | ENC  |             |                 |     |                  |          |                    | 0       |              |
|                        |                                                                                                                                                                                                                          |               | DATE |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                                                                                                                                          |               | MSC  |             |                 | -   |                  |          |                    |         |              |
| (880222)               | [End Of Month Item]                                                                                                                                                                                                      |               |      |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                                                          |               |      |             |                 |     |                  |          |                    |         |              |
| BR700-72-102227<br>R01 | No. 2 Engine - Sb BR700-72-102227 R01 - BR700-72-102227 R01 - Accessory Gearbox Module - Introduction of an Alternative Nut Standard and an Alternative Nail Standard Used for the Installation of the Nameplate Support |               | HRS  |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                          |               | ENC  |             |                 |     |                  |          |                    | 0       |              |
|                        |                                                                                                                                                                                                                          |               | DATE |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                                                                                                                                          |               | MSC  |             |                 | -   |                  |          |                    |         |              |
| (880222)               | [End Of Month Item]                                                                                                                                                                                                      |               |      |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                                                          |               |      |             |                 |     |                  |          |                    |         |              |

| ATA<br>U=Custom  | Description                                                                                                                                                                                                                                                                                             |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |  |
|------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|----------|--------------------|---------|--------------|--|
|                  | Part Number                                                                                                                                                                                                                                                                                             | Serial Number |                     |             |                 |     |                  |          |                    |         | Approx Price |  |
| Logbook Position | HW                                                                                                                                                                                                                                                                                                      | SW            |                     |             |                 |     |                  |          |                    |         | Manufacturer |  |
|                  | MM Ref                                                                                                                                                                                                                                                                                                  |               |                     |             |                 |     |                  |          |                    |         | Date Type    |  |
|                  | Ops Number(s)                                                                                                                                                                                                                                                                                           |               |                     |             |                 |     |                  |          |                    |         |              |  |
| BR700-72-102232  | No. 1 Engine - Sb BR700-72-102232 - Sb BR700-72-102232 - High Pressure (Hp) Compressor Stage 4                                                                                                                                                                                                          |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |  |
|                  | Onward Stator Vanes - Introduction of A New Definition of the Maximum Permitted Quantity of Hp Compressor Stages 5 and 6 Undersize Vanes                                                                                                                                                                |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |  |
|                  |                                                                                                                                                                                                                                                                                                         |               | DATE                |             |                 |     |                  |          |                    |         |              |  |
|                  |                                                                                                                                                                                                                                                                                                         |               | MSC                 |             |                 |     | -                |          |                    |         |              |  |
| (880216)         |                                                                                                                                                                                                                                                                                                         |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |  |
| Engine           |                                                                                                                                                                                                                                                                                                         |               |                     |             |                 |     |                  |          |                    |         |              |  |
| BR700-72-102232  | No. 2 Engine - Sb BR700-72-102232 - Sb BR700-72-102232 - High Pressure (Hp) Compressor Stage 4                                                                                                                                                                                                          |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |  |
|                  | Onward Stator Vanes - Introduction of A New Definition of the Maximum Permitted Quantity of Hp Compressor Stages 5 and 6 Undersize Vanes                                                                                                                                                                |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |  |
|                  |                                                                                                                                                                                                                                                                                                         |               | DATE                |             |                 |     |                  |          |                    |         |              |  |
|                  |                                                                                                                                                                                                                                                                                                         |               | MSC                 |             |                 |     | -                |          |                    |         |              |  |
| (880216)         |                                                                                                                                                                                                                                                                                                         |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |  |
| Engine           |                                                                                                                                                                                                                                                                                                         |               |                     |             |                 |     |                  |          |                    |         |              |  |
| BR700-72-102270  | No. 1 Engine - Sb BR700-72-102270 - Sb BR700-72-102270 - High Pressure (Hp) Compressor Front Case - Introduction of Modified Hp Compressor Variable Inlet Guide Vane (Vigv) Bushes and Modified Hp Compressor Stages 1 to 3 Variable Stator Vane (Vsv) Bushes for the Hp Compressor Front Case Assembly |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |  |
|                  |                                                                                                                                                                                                                                                                                                         |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |  |
|                  |                                                                                                                                                                                                                                                                                                         |               | DATE                |             |                 |     |                  |          |                    |         |              |  |
|                  |                                                                                                                                                                                                                                                                                                         |               | MSC                 |             |                 |     | ESV**            |          |                    |         |              |  |
| (880226)         |                                                                                                                                                                                                                                                                                                         |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |  |
| Engine           |                                                                                                                                                                                                                                                                                                         |               |                     |             |                 |     |                  |          |                    |         |              |  |
| BR700-72-102270  | No. 2 Engine - Sb BR700-72-102270 - Sb BR700-72-102270 - High Pressure (Hp) Compressor Front Case - Introduction of Modified Hp Compressor Variable Inlet Guide Vane (Vigv) Bushes and Modified Hp Compressor Stages 1 to 3 Variable Stator Vane (Vsv) Bushes for the Hp Compressor Front Case Assembly |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |  |
|                  |                                                                                                                                                                                                                                                                                                         |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |  |
|                  |                                                                                                                                                                                                                                                                                                         |               | DATE                |             |                 |     |                  |          |                    |         |              |  |
|                  |                                                                                                                                                                                                                                                                                                         |               | MSC                 |             |                 |     | ESV**            |          |                    |         |              |  |
| (880226)         |                                                                                                                                                                                                                                                                                                         |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |  |
| Engine           |                                                                                                                                                                                                                                                                                                         |               |                     |             |                 |     |                  |          |                    |         |              |  |

| ATA<br>U=Custom                                           | Description                                               |               | UOM  | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|-----------------------------------------------------------|-----------------------------------------------------------|---------------|------|-------------|-----------------|-----|------------------|----------|--------------------|---------|--------------|
|                                                           | Part Number                                               | Serial Number |      |             |                 |     |                  |          |                    |         | Approx Price |
| Logbook Position                                          | HW                                                        | SW            |      |             |                 |     |                  |          |                    |         | Manufacturer |
|                                                           | MM Ref                                                    |               |      |             |                 |     |                  |          |                    |         | Date Type    |
|                                                           | Ops Number(s)                                             |               |      |             |                 |     |                  |          |                    |         |              |
| BR700-72-102277                                           | No. 1 Engine - Sb BR700-72-102277 - BR700-72-102277       |               | HRS  |             |                 |     |                  |          |                    |         | 0            |
|                                                           | - High Pressure (Hp) Turbine Rotor Discs and Hp Turbine   |               | ENC  |             |                 |     |                  |          |                    |         | 0            |
|                                                           | Stage 1 Nozzle Guide Seals - Introduction of an Hp        |               | DATE |             |                 |     |                  |          |                    |         |              |
|                                                           | Turbine Stage 1 Disc Without Coating on All Seal Fins and |               | MSC  |             |                 |     | -                |          |                    |         |              |
| Introduction of A Modified Hp Turbine Stage 1 Preswirl    |                                                           |               |      |             |                 |     |                  |          |                    |         |              |
| Web Seal Assembly                                         |                                                           |               |      |             |                 |     |                  |          |                    |         |              |
| (880228)                                                  |                                                           |               |      |             |                 |     |                  |          |                    |         |              |
| Engine                                                    |                                                           |               |      |             |                 |     |                  |          |                    |         |              |
| BR700-72-102277                                           | No. 2 Engine - Sb BR700-72-102277 - BR700-72-102277       |               | HRS  |             |                 |     |                  |          |                    |         | 0            |
|                                                           | - High Pressure (Hp) Turbine Rotor Discs and Hp Turbine   |               | ENC  |             |                 |     |                  |          |                    |         | 0            |
|                                                           | Stage 1 Nozzle Guide Seals - Introduction of an Hp        |               | DATE |             |                 |     |                  |          |                    |         |              |
|                                                           | Turbine Stage 1 Disc Without Coating on All Seal Fins and |               | MSC  |             |                 |     | -                |          |                    |         |              |
| Introduction of A Modified Hp Turbine Stage 1 Preswirl    |                                                           |               |      |             |                 |     |                  |          |                    |         |              |
| Web Seal Assembly                                         |                                                           |               |      |             |                 |     |                  |          |                    |         |              |
| (880228)                                                  |                                                           |               |      |             |                 |     |                  |          |                    |         |              |
| Engine                                                    |                                                           |               |      |             |                 |     |                  |          |                    |         |              |
| BR700-72-102282                                           | No. 1 Engine - Sb BR700-72-102282 - BR700-72-102282       |               | HRS  |             |                 |     |                  |          |                    |         | 0            |
|                                                           | - Low Pressure (Lp) Turbine Nozzle Guide Vanes (Ngv) -    |               | ENC  |             |                 |     |                  |          |                    |         | 0            |
|                                                           | Introduction of Two Changed Lp Turbine Stage 1 Ngv        |               | DATE |             |                 |     |                  |          |                    |         |              |
|                                                           | Assemblies Containing Modified Oil Scavenge and           |               | MSC  |             |                 |     | -                |          |                    |         |              |
| Oil/AIR Vent Pipes With Uncoated Union Adapters and       |                                                           |               |      |             |                 |     |                  |          |                    |         |              |
| Introduction of A Modified Oil Feed Pipe With an Uncoated |                                                           |               |      |             |                 |     |                  |          |                    |         |              |
| Union Adapter                                             |                                                           |               |      |             |                 |     |                  |          |                    |         |              |
| (880229)                                                  |                                                           |               |      |             |                 |     |                  |          |                    |         |              |
| Engine                                                    |                                                           |               |      |             |                 |     |                  |          |                    |         |              |
| BR700-72-102282                                           | No. 2 Engine - Sb BR700-72-102282 - BR700-72-102282       |               | HRS  |             |                 |     |                  |          |                    |         | 0            |
|                                                           | - Low Pressure (Lp) Turbine Nozzle Guide Vanes (Ngv) -    |               | ENC  |             |                 |     |                  |          |                    |         | 0            |
|                                                           | Introduction of Two Changed Lp Turbine Stage 1 Ngv        |               | DATE |             |                 |     |                  |          |                    |         |              |
|                                                           | Assemblies Containing Modified Oil Scavenge and           |               | MSC  |             |                 |     | -                |          |                    |         |              |
| Oil/AIR Vent Pipes With Uncoated Union Adapters and       |                                                           |               |      |             |                 |     |                  |          |                    |         |              |
| Introduction of A Modified Oil Feed Pipe With an Uncoated |                                                           |               |      |             |                 |     |                  |          |                    |         |              |
| Union Adapter                                             |                                                           |               |      |             |                 |     |                  |          |                    |         |              |
| (880229)                                                  |                                                           |               |      |             |                 |     |                  |          |                    |         |              |
| Engine                                                    |                                                           |               |      |             |                 |     |                  |          |                    |         |              |

| ATA<br>U=Custom  | Description                                                                                                                          |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|--------------------------------------------------------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|----------|--------------------|---------|--------------|
|                  | Part Number                                                                                                                          | Serial Number |     |             |                 |     |                  |          |                    |         | Approx Price |
| Logbook Position | HW                                                                                                                                   | SW            |     |             |                 |     |                  |          |                    |         | Manufacturer |
|                  | MM Ref                                                                                                                               |               |     |             |                 |     |                  |          |                    |         | Date Type    |
|                  | Ops Number(s)                                                                                                                        |               |     |             |                 |     |                  |          |                    |         |              |
| BR700-72-102306  | No. 1 Engine - Sb BR700-72-102306 - Low Pressure (Lp)                                                                                |               | HRS |             |                 |     |                  |          |                    |         | 0            |
|                  | Turbine Stage 2 Onward Nozzle Guide Vanes (Ngv) -                                                                                    |               | ENC |             |                 |     |                  |          |                    |         | 0            |
|                  | Introduction of A Modified Lp Turbine Interstage 1-2 Seal                                                                            |               | MOS |             |                 |     |                  |          |                    |         |              |
|                  | Assembly Made from A Different Material and According to<br>A Different Manufacturing Method, Service Bulletin<br>(Optional)         |               | MSC |             |                 |     | -                |          |                    |         |              |
| (880262)         |                                                                                                                                      |               |     |             |                 |     |                  |          |                    |         |              |
| Engine           |                                                                                                                                      |               |     |             |                 |     |                  |          |                    |         |              |
| BR700-72-102306  | No. 2 Engine - Sb BR700-72-102306 - Low Pressure (Lp)                                                                                |               | HRS |             |                 |     |                  |          |                    |         | 0            |
|                  | Turbine Stage 2 Onward Nozzle Guide Vanes (Ngv) -                                                                                    |               | ENC |             |                 |     |                  |          |                    |         | 0            |
|                  | Introduction of A Modified Lp Turbine Interstage 1-2 Seal                                                                            |               | MOS |             |                 |     |                  |          |                    |         |              |
|                  | Assembly Made from A Different Material and According to<br>A Different Manufacturing Method, Service Bulletin<br>(Optional)         |               | MSC |             |                 |     | -                |          |                    |         |              |
| (880262)         |                                                                                                                                      |               |     |             |                 |     |                  |          |                    |         |              |
| Engine           |                                                                                                                                      |               |     |             |                 |     |                  |          |                    |         |              |
| BR700-72-102317  | No. 1 Engine - Sb BR700-72-102317 - High Pressure (Hp)                                                                               |               | HRS |             |                 |     |                  |          |                    |         | 0            |
|                  | Compressor Front Case - Introduction of Modified Bushes                                                                              |               | ENC |             |                 |     |                  |          |                    |         | 0            |
|                  | Made from A Different Material Used AT the Hp                                                                                        |               | MOS |             |                 |     |                  |          |                    |         |              |
|                  | Compressor Variable Inlet Guide Vanes (Vigv) and AT the<br>Stages 1 to 3 Variable Stator Vanes (Vsv), Service Bulletin<br>(Optional) |               | MSC |             |                 |     | -                |          |                    |         |              |
| (880264)         |                                                                                                                                      |               |     |             |                 |     |                  |          |                    |         |              |
| Engine           |                                                                                                                                      |               |     |             |                 |     |                  |          |                    |         |              |
| BR700-72-102317  | No. 2 Engine - Sb BR700-72-102317 - High Pressure (Hp)                                                                               |               | HRS |             |                 |     |                  |          |                    |         | 0            |
|                  | Compressor Front Case - Introduction of Modified Bushes                                                                              |               | ENC |             |                 |     |                  |          |                    |         | 0            |
|                  | Made from A Different Material Used AT the Hp                                                                                        |               | MOS |             |                 |     |                  |          |                    |         |              |
|                  | Compressor Variable Inlet Guide Vanes (Vigv) and AT the<br>Stages 1 to 3 Variable Stator Vanes (Vsv), Service Bulletin<br>(Optional) |               | MSC |             |                 |     | -                |          |                    |         |              |
| (880264)         |                                                                                                                                      |               |     |             |                 |     |                  |          |                    |         |              |
| Engine           |                                                                                                                                      |               |     |             |                 |     |                  |          |                    |         |              |



| ATA<br>U=Custom               | Description                                                                                                                                                                                                                           |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|-------------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|----------|--------------------|---------|--------------|
|                               | Part Number                                                                                                                                                                                                                           | Serial Number |                     |             |                 |     |                  |          |                    |         | Approx Price |
| Logbook Position              | HW                                                                                                                                                                                                                                    | SW            |                     |             |                 |     |                  |          |                    |         | Manufacturer |
|                               | MM Ref                                                                                                                                                                                                                                |               |                     |             |                 |     |                  |          |                    |         | Date Type    |
|                               | Ops Number(s)                                                                                                                                                                                                                         |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-900179<br>R01        | No. 2 Engine - Sb BR700-72-900179 R01 - Engine - High Pressure (Hp) Compressor Variable Inlet Guide Vanes (Vigv) Actuating Mechanism - Inspection and Lubrication of the Vigv Actuating Mechanism - Non-Modification Service Bulletin |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                               |                                                                                                                                                                                                                                       |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                               |                                                                                                                                                                                                                                       |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                               |                                                                                                                                                                                                                                       |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880169)                      |                                                                                                                                                                                                                                       |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine                        |                                                                                                                                                                                                                                       |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-900467               | No. 1 Engine - Sb BR700-72-900467 - Accessory Gearbox Module - Inspection of the Accessory Gearbox Surface Protection - Non-Modification Service Bulletin                                                                             |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                               |                                                                                                                                                                                                                                       |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                               |                                                                                                                                                                                                                                       |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                               |                                                                                                                                                                                                                                       |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880004)                      |                                                                                                                                                                                                                                       |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine                        |                                                                                                                                                                                                                                       |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-900467               | No. 2 Engine - Sb BR700-72-900467 - Accessory Gearbox Module - Inspection of the Accessory Gearbox Surface Protection - Non-Modification Service Bulletin                                                                             |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                               |                                                                                                                                                                                                                                       |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                               |                                                                                                                                                                                                                                       |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                               |                                                                                                                                                                                                                                       |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880004)                      |                                                                                                                                                                                                                                       |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine                        |                                                                                                                                                                                                                                       |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-900589<br>R02 PART A | No. 1 Engine - Sb BR700-72-900589 R02 Part A - Internal Gearbox Drive - Inspection of the Radial Drive Shaft Seal Ring - Non-Modification Service Bulletin                                                                            |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                               |                                                                                                                                                                                                                                       |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                               |                                                                                                                                                                                                                                       |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                               |                                                                                                                                                                                                                                       |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880121)                      |                                                                                                                                                                                                                                       |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine                        |                                                                                                                                                                                                                                       |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-900589<br>R02 PART A | No. 2 Engine - Sb BR700-72-900589 R02 Part A - Internal Gearbox Drive - Inspection of the Radial Drive Shaft Seal Ring - Non-Modification Service Bulletin                                                                            |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                               |                                                                                                                                                                                                                                       |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                               |                                                                                                                                                                                                                                       |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                               |                                                                                                                                                                                                                                       |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880121)                      |                                                                                                                                                                                                                                       |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine                        |                                                                                                                                                                                                                                       |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-900589<br>R02 PART B | No. 1 Engine - Sb BR700-72-900589 R02 Part B - Internal Gearbox Drive - Inspection of the Radial Drive Shaft Seal Ring - Non-Modification Service Bulletin                                                                            |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                               |                                                                                                                                                                                                                                       |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                               |                                                                                                                                                                                                                                       |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                               |                                                                                                                                                                                                                                       |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880122)                      |                                                                                                                                                                                                                                       |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine                        |                                                                                                                                                                                                                                       |               |                     |             |                 |     |                  |          |                    |         |              |

| ATA<br>U=Custom                                             | Description                                                                                                                                                            |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|-------------------------------------------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|----------|--------------------|---------|--------------|
|                                                             | Part Number                                                                                                                                                            | Serial Number |                     |             |                 |     |                  |          |                    |         | Approx Price |
| Logbook Position                                            | HW                                                                                                                                                                     | SW            |                     |             |                 |     |                  |          |                    |         | Manufacturer |
|                                                             | MM Ref                                                                                                                                                                 |               |                     |             |                 |     |                  |          |                    |         | Date Type    |
|                                                             | Ops Number(s)                                                                                                                                                          |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-72-900589<br>R02 PART B<br><br>(880122)<br><br>Engine | No. 2 Engine - Sb BR700-72-900589 R02 Part B - Internal Gearbox Drive - Inspection of the Radial Drive Shaft Seal Ring - Non-Modification Service Bulletin             |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                                                             |                                                                                                                                                                        |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                                                             |                                                                                                                                                                        |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                                                             |                                                                                                                                                                        |               | MSC                 |             |                 |     | -                |          |                    |         |              |
|                                                             |                                                                                                                                                                        |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| BR700-72-900589<br>R02 PART C<br><br>(880123)<br><br>Engine | No. 1 Engine - Sb BR700-72-900589 R02 Part C - Internal Gearbox Drive - Inspection of the Radial Drive Shaft Seal Ring - Non-Modification Service Bulletin             |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                                                             |                                                                                                                                                                        |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                                                             |                                                                                                                                                                        |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                                                             |                                                                                                                                                                        |               | MSC                 |             |                 |     | -                |          |                    |         |              |
|                                                             |                                                                                                                                                                        |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| BR700-72-900589<br>R02 PART C<br><br>(880123)<br><br>Engine | No. 2 Engine - Sb BR700-72-900589 R02 Part C - Internal Gearbox Drive - Inspection of the Radial Drive Shaft Seal Ring - Non-Modification Service Bulletin             |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                                                             |                                                                                                                                                                        |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                                                             |                                                                                                                                                                        |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                                                             |                                                                                                                                                                        |               | MSC                 |             |                 |     | -                |          |                    |         |              |
|                                                             |                                                                                                                                                                        |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| BR700-72-900602<br><br><br>(880139)<br><br>Engine           | No. 1 Engine - Sb BR700-72-900602 - High Pressure (Hp) Turbine Rotor Discs - Data Matrix Deletion on Five Hp Turbine Stage 1 Discs - Non-Modification Service Bulletin |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                                                             |                                                                                                                                                                        |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                                                             |                                                                                                                                                                        |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                                                             |                                                                                                                                                                        |               | MSC                 |             |                 |     | -                |          |                    |         |              |
|                                                             |                                                                                                                                                                        |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| BR700-72-900602<br><br><br>(880139)<br><br>Engine           | No. 2 Engine - Sb BR700-72-900602 - High Pressure (Hp) Turbine Rotor Discs - Data Matrix Deletion on Five Hp Turbine Stage 1 Discs - Non-Modification Service Bulletin |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                                                             |                                                                                                                                                                        |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                                                             |                                                                                                                                                                        |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                                                             |                                                                                                                                                                        |               | MSC                 |             |                 |     | -                |          |                    |         |              |
|                                                             |                                                                                                                                                                        |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |



| ATA<br>U=Custom                                            | Description                                            |               | UOM         | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------------------------------------------------|--------------------------------------------------------|---------------|-------------|-------------|-----------------|-----|------------------|----------|--------------------|---------|--------------|
|                                                            | Part Number                                            | Serial Number |             |             |                 |     |                  |          |                    |         | Approx Price |
| Logbook Position                                           | HW                                                     | SW            |             |             |                 |     |                  |          |                    |         | Manufacturer |
|                                                            | MM Ref                                                 |               |             |             |                 |     |                  |          |                    |         | Date Type    |
|                                                            | Ops Number(s)                                          |               |             |             |                 |     |                  |          |                    |         |              |
| BR700-72-900780<br>R01                                     | No. 1 Engine - Sb BR700-72-900780 R01 - High Pressure  |               | HRS         |             |                 |     |                  |          |                    |         | 0            |
|                                                            | (Hp) Compressor Rear Inner Case - Hp Compressor        |               | ENC         |             |                 |     |                  |          |                    |         | 0            |
|                                                            | Stages 7 to 10 Rear Inner Case Rotor Path Liner        |               | DATE        |             |                 |     |                  |          |                    |         |              |
|                                                            | Borescope Inspection and Replacement of the Hp         |               | MSC         |             |                 |     | -                |          |                    |         |              |
|                                                            | Compressor Stages 7 to 10 Rear Inner Case Assemblies - |               |             |             |                 |     |                  |          |                    |         |              |
| Non-Modification Service Bulletin, Service Bulletin        |                                                        |               |             |             |                 |     |                  |          |                    |         |              |
| (Recommended)                                              |                                                        |               |             |             |                 |     |                  |          |                    |         |              |
| (887801.000)                                               |                                                        |               |             |             |                 |     |                  |          |                    |         |              |
| Engine                                                     |                                                        |               |             |             |                 |     |                  |          |                    |         |              |
| BR700-72-900780<br>R01                                     | No. 2 Engine - Sb BR700-72-900780 R01 - High Pressure  |               | HRS         |             |                 |     |                  |          |                    |         | 0            |
|                                                            | (Hp) Compressor Rear Inner Case - Hp Compressor        |               | ENC         |             |                 |     |                  |          |                    |         | 0            |
|                                                            | Stages 7 to 10 Rear Inner Case Rotor Path Liner        |               | DATE        |             |                 |     |                  |          |                    |         |              |
|                                                            | Borescope Inspection and Replacement of the Hp         |               | MSC         |             |                 |     | -                |          |                    |         |              |
|                                                            | Compressor Stages 7 to 10 Rear Inner Case Assemblies - |               |             |             |                 |     |                  |          |                    |         |              |
| Non-Modification Service Bulletin, Service Bulletin        |                                                        |               |             |             |                 |     |                  |          |                    |         |              |
| (Recommended)                                              |                                                        |               |             |             |                 |     |                  |          |                    |         |              |
| (887801.000)                                               |                                                        |               |             |             |                 |     |                  |          |                    |         |              |
| Engine                                                     |                                                        |               |             |             |                 |     |                  |          |                    |         |              |
| BR700-72-900780<br>R01 PART A                              | No. 1 Engine - Accomplish Sb BR700-72-900780 R01 -     |               | HRS         |             |                 |     | 1500**           |          | 1500               | 1750    | 0            |
|                                                            | High Pressure (Hp) Compressor Rear Inner Case - Hp     |               | ENC         |             |                 |     |                  |          |                    |         | 0            |
|                                                            | Compressor Stages 7 to 10 Rear Inner Case Rotor Path   |               | DATE        |             |                 |     |                  |          |                    |         |              |
|                                                            | Liner Borescope Inspection and Replacement of the Hp   |               | [HRS: +250] |             |                 |     |                  |          |                    |         |              |
|                                                            | Compressor Stages 7 to 10 Rear Inner Case Assemblies - |               |             |             |                 |     |                  |          |                    |         |              |
| Non-Modification Service Bulletin, Service Bulletin BR700- |                                                        |               |             |             |                 |     |                  |          |                    |         |              |
| 72-900780 R01 Part A - Borescope Inspection of the High    |                                                        |               |             |             |                 |     |                  |          |                    |         |              |
| Pressure (Hp) Compressor Stages 7 to 10 Rear Inner         |                                                        |               |             |             |                 |     |                  |          |                    |         |              |
| Case Rotor Path Liner and Blade Tip Clearance              |                                                        |               |             |             |                 |     |                  |          |                    |         |              |
| Measurement (Recommended)                                  |                                                        |               |             |             |                 |     |                  |          |                    |         |              |
| (887801.001)                                               |                                                        |               |             |             |                 |     |                  |          |                    |         |              |
| Engine                                                     |                                                        |               |             |             |                 |     |                  |          |                    |         |              |

| ATA<br>U=Custom                                            | Description                                          |               | UOM         | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------------------------------------------------|------------------------------------------------------|---------------|-------------|-------------|-----------------|-----|------------------|----------|--------------------|---------|--------------|
|                                                            | Part Number                                          | Serial Number |             |             |                 |     |                  |          |                    |         | Approx Price |
| Logbook Position                                           | HW                                                   | SW            |             |             |                 |     |                  |          |                    |         | Manufacturer |
|                                                            | MM Ref                                               |               |             |             |                 |     |                  |          |                    |         | Date Type    |
|                                                            | Ops Number(s)                                        |               |             |             |                 |     |                  |          |                    |         |              |
| BR700-72-900780<br>R01 PART A                              | No. 2 Engine - Accomplish Sb BR700-72-900780 R01 -   |               | HRS         |             |                 |     | 1500**           |          | 1500               | 1750    | 0            |
|                                                            | High Pressure (Hp) Compressor Rear Inner Case - Hp   |               | ENC         |             |                 |     |                  |          |                    |         | 0            |
|                                                            | Compressor Stages 7 to 10 Rear Inner Case Rotor Path |               | DATE        |             |                 |     |                  |          |                    |         |              |
|                                                            | Liner Borescope Inspection and Replacement of the Hp |               | [HRS: +250] |             |                 |     |                  |          |                    |         |              |
| Compressor Stages 7 to 10 Rear Inner Case Assemblies -     |                                                      |               |             |             |                 |     |                  |          |                    |         |              |
| Non-Modification Service Bulletin, Service Bulletin BR700- |                                                      |               |             |             |                 |     |                  |          |                    |         |              |
| 72-900780 R01 Part A - Borescope Inspection of the High    |                                                      |               |             |             |                 |     |                  |          |                    |         |              |
| Pressure (Hp) Compressor Stages 7 to 10 Rear Inner         |                                                      |               |             |             |                 |     |                  |          |                    |         |              |
| Case Rotor Path Liner and Blade Tip Clearance              |                                                      |               |             |             |                 |     |                  |          |                    |         |              |
| Measurement (Recommended)                                  |                                                      |               |             |             |                 |     |                  |          |                    |         |              |
| (887801.001)                                               |                                                      |               |             |             |                 |     |                  |          |                    |         |              |
| Engine                                                     |                                                      |               |             |             |                 |     |                  |          |                    |         |              |
| BR700-72-900780<br>R01 PART B                              | No. 1 Engine - Accomplish Sb BR700-72-900780 R01 -   |               | HRS         |             |                 |     | 1500**           |          | 1500               | 1750    | 0            |
|                                                            | High Pressure (Hp) Compressor Rear Inner Case - Hp   |               | ENC         |             |                 |     |                  |          |                    |         | 0            |
|                                                            | Compressor Stages 7 to 10 Rear Inner Case Rotor Path |               | DATE        |             |                 |     |                  |          |                    |         |              |
|                                                            | Liner Borescope Inspection and Replacement of the Hp |               | [HRS: +250] |             |                 |     |                  |          |                    |         |              |
| Compressor Stages 7 to 10 Rear Inner Case Assemblies -     |                                                      |               |             |             |                 |     |                  |          |                    |         |              |
| Non-Modification Service Bulletin, Service Bulletin BR700- |                                                      |               |             |             |                 |     |                  |          |                    |         |              |
| 72-900780 R01 Part B - Replacement of the High             |                                                      |               |             |             |                 |     |                  |          |                    |         |              |
| Pressure (Hp) Compressor Stages 7 to 10 Rear Inner         |                                                      |               |             |             |                 |     |                  |          |                    |         |              |
| Case Assemblies (Recommended)                              |                                                      |               |             |             |                 |     |                  |          |                    |         |              |
| (887801.002)                                               |                                                      |               |             |             |                 |     |                  |          |                    |         |              |
| Engine                                                     |                                                      |               |             |             |                 |     |                  |          |                    |         |              |
| BR700-72-900780<br>R01 PART B                              | No. 2 Engine - Accomplish Sb BR700-72-900780 R01 -   |               | HRS         |             |                 |     | 1500**           |          | 1500               | 1750    | 0            |
|                                                            | High Pressure (Hp) Compressor Rear Inner Case - Hp   |               | ENC         |             |                 |     |                  |          |                    |         | 0            |
|                                                            | Compressor Stages 7 to 10 Rear Inner Case Rotor Path |               | DATE        |             |                 |     |                  |          |                    |         |              |
|                                                            | Liner Borescope Inspection and Replacement of the Hp |               | [HRS: +250] |             |                 |     |                  |          |                    |         |              |
| Compressor Stages 7 to 10 Rear Inner Case Assemblies -     |                                                      |               |             |             |                 |     |                  |          |                    |         |              |
| Non-Modification Service Bulletin, Service Bulletin BR700- |                                                      |               |             |             |                 |     |                  |          |                    |         |              |
| 72-900780 R01 Part B - Replacement of the High             |                                                      |               |             |             |                 |     |                  |          |                    |         |              |
| Pressure (Hp) Compressor Stages 7 to 10 Rear Inner         |                                                      |               |             |             |                 |     |                  |          |                    |         |              |
| Case Assemblies (Recommended)                              |                                                      |               |             |             |                 |     |                  |          |                    |         |              |
| (887801.002)                                               |                                                      |               |             |             |                 |     |                  |          |                    |         |              |
| Engine                                                     |                                                      |               |             |             |                 |     |                  |          |                    |         |              |

| ATA<br>U=Custom        | Description                                                                                                                                                                        |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(* =Adj) | Max Due | Avg Man Hrs  |
|------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|----------------------|---------|--------------|
|                        | Part Number                                                                                                                                                                        | Serial Number |                     |             |                 |     |                  |             |                      |         | Approx Price |
| Logbook Position       | HW                                                                                                                                                                                 | SW            |                     |             |                 |     |                  |             |                      |         | Manufacturer |
|                        | MM Ref                                                                                                                                                                             |               |                     |             |                 |     |                  |             |                      |         | Date Type    |
|                        | Ops Number(s)                                                                                                                                                                      |               |                     |             |                 |     |                  |             |                      |         |              |
| BR700-72-<br>A900628   | No. 1 Engine - Sb BR700-72-A900628 - Asb BR700-72-A900628 - High Pressure (Hp) Turbine Blades - Replacement of Seven Hp Turbine Stage 1 Blades - Non-Modification Service Bulletin |               | HRS                 |             |                 |     |                  |             |                      |         | 0            |
|                        |                                                                                                                                                                                    |               | ENC                 |             |                 |     |                  |             |                      | 0       |              |
|                        |                                                                                                                                                                                    |               | DATE                |             |                 |     |                  |             |                      |         |              |
|                        |                                                                                                                                                                                    |               | MSC                 |             |                 |     | -                |             |                      |         |              |
| (880210)               |                                                                                                                                                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                      |         |              |
| Engine                 |                                                                                                                                                                                    |               |                     |             |                 |     |                  |             |                      |         |              |
| BR700-72-<br>A900628   | No. 2 Engine - Sb BR700-72-A900628 - Asb BR700-72-A900628 - High Pressure (Hp) Turbine Blades - Replacement of Seven Hp Turbine Stage 1 Blades - Non-Modification Service Bulletin |               | HRS                 |             |                 |     |                  |             |                      |         | 0            |
|                        |                                                                                                                                                                                    |               | ENC                 |             |                 |     |                  |             |                      | 0       |              |
|                        |                                                                                                                                                                                    |               | DATE                |             |                 |     |                  |             |                      |         |              |
|                        |                                                                                                                                                                                    |               | MSC                 |             |                 |     | -                |             |                      |         |              |
| (880210)               |                                                                                                                                                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                      |         |              |
| Engine                 |                                                                                                                                                                                    |               |                     |             |                 |     |                  |             |                      |         |              |
| BR700-73-101708<br>R01 | No. 1 Engine - Sb BR700-73-101708 R01 - Engine Fuel and Control - Fuel Pump - Introduction of A Revised Main Fuel Pump, Service Bulletin (Recommended)                             |               | HRS                 |             |                 |     |                  |             |                      |         | 0            |
|                        |                                                                                                                                                                                    |               | ENC                 |             |                 |     |                  |             |                      | 0       |              |
|                        |                                                                                                                                                                                    |               | MOS                 |             | 29.5            |     |                  | 28 Nov 2023 |                      |         |              |
|                        |                                                                                                                                                                                    |               | MSC                 |             |                 |     | -                |             |                      |         |              |
| (880240)               |                                                                                                                                                                                    |               |                     |             |                 |     |                  |             |                      |         |              |
| Engine                 |                                                                                                                                                                                    |               |                     |             |                 |     |                  |             |                      |         |              |
| BR700-73-101708<br>R01 | No. 2 Engine - Sb BR700-73-101708 R01 - Engine Fuel and Control - Fuel Pump - Introduction of A Revised Main Fuel Pump, Service Bulletin (Recommended)                             |               | HRS                 |             |                 |     |                  |             |                      |         | 0            |
|                        |                                                                                                                                                                                    |               | ENC                 |             |                 |     |                  |             |                      | 0       |              |
|                        |                                                                                                                                                                                    |               | MOS                 |             | 29.5            |     |                  | 28 Nov 2023 |                      |         |              |
|                        |                                                                                                                                                                                    |               | MSC                 |             |                 |     | -                |             |                      |         |              |
| (880240)               |                                                                                                                                                                                    |               |                     |             |                 |     |                  |             |                      |         |              |
| Engine                 |                                                                                                                                                                                    |               |                     |             |                 |     |                  |             |                      |         |              |
| BR700-73-101733<br>R01 | No. 1 Engine - Sb BR700-73-101733 R01 - Engine Fuel and Control - Fuel Manifold - Introduction of A New Standard of Flexible Fuel Tubes                                            |               | HRS                 |             |                 |     |                  |             |                      |         | 0            |
|                        |                                                                                                                                                                                    |               | ENC                 |             |                 |     |                  |             |                      | 0       |              |
|                        |                                                                                                                                                                                    |               | DATE                |             |                 |     |                  |             |                      |         |              |
|                        |                                                                                                                                                                                    |               | MSC                 |             |                 |     | -                |             |                      |         |              |
| (880091)               |                                                                                                                                                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                      |         |              |
| Engine                 |                                                                                                                                                                                    |               |                     |             |                 |     |                  |             |                      |         |              |
| BR700-73-101733<br>R01 | No. 2 Engine - Sb BR700-73-101733 R01 - Engine Fuel and Control - Fuel Manifold - Introduction of A New Standard of Flexible Fuel Tubes                                            |               | HRS                 |             |                 |     |                  |             |                      |         | 0            |
|                        |                                                                                                                                                                                    |               | ENC                 |             |                 |     |                  |             |                      | 0       |              |
|                        |                                                                                                                                                                                    |               | DATE                |             |                 |     |                  |             |                      |         |              |
|                        |                                                                                                                                                                                    |               | MSC                 |             |                 |     | -                |             |                      |         |              |
| (880091)               |                                                                                                                                                                                    |               | [End Of Month Item] |             |                 |     |                  |             |                      |         |              |
| Engine                 |                                                                                                                                                                                    |               |                     |             |                 |     |                  |             |                      |         |              |

| ATA<br>U=Custom        | Description                                                                                                                                                                                                                                                             |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                        | Part Number                                                                                                                                                                                                                                                             | Serial Number |                     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position       | HW                                                                                                                                                                                                                                                                      | SW            |                     |             |                 |     |                  |             |                    |         | Manufacturer |
|                        | MM Ref                                                                                                                                                                                                                                                                  |               |                     |             |                 |     |                  |             |                    |         | Date Type    |
|                        | Ops Number(s)                                                                                                                                                                                                                                                           |               |                     |             |                 |     |                  |             |                    |         |              |
| BR700-73-101745        | No. 1 Engine - Sb BR700-73-101745 - Engine Fuel and Control - External Fuel Distribution Tubes and Fittings and Oil Differential Pressure Transducer - Introduction of A New External Dressing Bracket and Shorter Oil Differential Pressure Transducer Attaching Bolts |               | HRS                 |             |                 |     |                  |             |                    |         | 0            |
|                        |                                                                                                                                                                                                                                                                         |               | ENC                 |             |                 |     |                  |             |                    |         | 0            |
|                        |                                                                                                                                                                                                                                                                         |               | DATE                |             |                 |     |                  |             |                    |         |              |
|                        |                                                                                                                                                                                                                                                                         |               | MSC                 |             |                 |     | -                |             |                    |         |              |
|                        |                                                                                                                                                                                                                                                                         |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| (880025)               |                                                                                                                                                                                                                                                                         |               |                     |             |                 |     |                  |             |                    |         |              |
| Engine                 |                                                                                                                                                                                                                                                                         |               |                     |             |                 |     |                  |             |                    |         |              |
| BR700-73-101745        | No. 2 Engine - Sb BR700-73-101745 - Engine Fuel and Control - External Fuel Distribution Tubes and Fittings and Oil Differential Pressure Transducer - Introduction of A New External Dressing Bracket and Shorter Oil Differential Pressure Transducer Attaching Bolts |               | HRS                 |             |                 |     |                  |             |                    |         | 0            |
|                        |                                                                                                                                                                                                                                                                         |               | ENC                 |             |                 |     |                  |             |                    |         | 0            |
|                        |                                                                                                                                                                                                                                                                         |               | DATE                |             |                 |     |                  |             |                    |         |              |
|                        |                                                                                                                                                                                                                                                                         |               | MSC                 |             |                 |     | -                |             |                    |         |              |
|                        |                                                                                                                                                                                                                                                                         |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| (880025)               |                                                                                                                                                                                                                                                                         |               |                     |             |                 |     |                  |             |                    |         |              |
| Engine                 |                                                                                                                                                                                                                                                                         |               |                     |             |                 |     |                  |             |                    |         |              |
| BR700-73-101767<br>R01 | No. 1 Engine - Sb BR700-73-101767 R01 - Engine Fuel and Control - Fuel Pump - Introduction of A New Main Fuel Pump With Modified Gears and Impeller Housing, Service Bulletin (Recommended)                                                                             |               | HRS                 |             |                 |     |                  |             |                    |         | 0            |
|                        |                                                                                                                                                                                                                                                                         |               | ENC                 |             |                 |     |                  |             |                    |         | 0            |
|                        |                                                                                                                                                                                                                                                                         |               | MOS                 |             | 29.4            |     |                  | 29 Nov 2023 |                    |         |              |
|                        |                                                                                                                                                                                                                                                                         |               | MSC                 |             |                 |     | -                |             |                    |         |              |
| (880242)               |                                                                                                                                                                                                                                                                         |               |                     |             |                 |     |                  |             |                    |         |              |
| Engine                 |                                                                                                                                                                                                                                                                         |               |                     |             |                 |     |                  |             |                    |         |              |
| BR700-73-101767<br>R01 | No. 2 Engine - Sb BR700-73-101767 R01 - Engine Fuel and Control - Fuel Pump - Introduction of A New Main Fuel Pump With Modified Gears and Impeller Housing, Service Bulletin (Recommended)                                                                             |               | HRS                 |             |                 |     |                  |             |                    |         | 0            |
|                        |                                                                                                                                                                                                                                                                         |               | ENC                 |             |                 |     |                  |             |                    |         | 0            |
|                        |                                                                                                                                                                                                                                                                         |               | MOS                 |             | 29.4            |     |                  | 29 Nov 2023 |                    |         |              |
|                        |                                                                                                                                                                                                                                                                         |               | MSC                 |             |                 |     | -                |             |                    |         |              |
| (880242)               |                                                                                                                                                                                                                                                                         |               |                     |             |                 |     |                  |             |                    |         |              |
| Engine                 |                                                                                                                                                                                                                                                                         |               |                     |             |                 |     |                  |             |                    |         |              |
| BR700-73-101769<br>R01 | No. 1 Engine - Sb BR700-73-101769 R01 - Engine Fuel and Control - Fuel Metering Unit (Fmu) - Introduction of A Revised Shut-Off Valve Servo Valve (Sovsv) With A New Gas Discharge Tube, Service Bulletin (Optional)                                                    |               | HRS                 |             |                 |     |                  |             |                    |         | 0            |
|                        |                                                                                                                                                                                                                                                                         |               | ENC                 |             |                 |     |                  |             |                    |         | 0            |
|                        |                                                                                                                                                                                                                                                                         |               | MOS                 |             | 29.3            |     |                  | 01 Dec 2023 |                    |         |              |
|                        |                                                                                                                                                                                                                                                                         |               | MSC                 |             |                 |     | -                |             |                    |         |              |
| (880244)               |                                                                                                                                                                                                                                                                         |               |                     |             |                 |     |                  |             |                    |         |              |
| Engine                 |                                                                                                                                                                                                                                                                         |               |                     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom        | Description                                                                                                                                                                                                                         |               | UOM | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(* =Adj) | Max Due | Avg Man Hrs  |
|------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|-----|-------------|-----------------|-----|------------------|----------|----------------------|---------|--------------|
|                        | Part Number                                                                                                                                                                                                                         | Serial Number |     |             |                 |     |                  |          |                      |         | Approx Price |
| Logbook Position       | HW                                                                                                                                                                                                                                  | SW            |     |             |                 |     |                  |          |                      |         | Manufacturer |
|                        | MM Ref                                                                                                                                                                                                                              |               |     |             |                 |     |                  |          |                      |         | Date Type    |
|                        | Ops Number(s)                                                                                                                                                                                                                       |               |     |             |                 |     |                  |          |                      |         |              |
| BR700-73-101769<br>R01 | No. 2 Engine - Sb BR700-73-101769 R01 - Engine Fuel and Control - Fuel Metering Unit (Fmu) - Introduction of A Revised Shut-Off Valve Servo Valve (Sovsv) With A New Gas Discharge Tube, Service Bulletin (Optional)                |               | HRS |             |                 |     |                  |          |                      |         | 0            |
|                        |                                                                                                                                                                                                                                     |               | ENC |             |                 |     |                  |          |                      | 0       |              |
|                        |                                                                                                                                                                                                                                     |               | MOS | 29.3        |                 |     | 01 Dec 2023      |          |                      |         |              |
|                        |                                                                                                                                                                                                                                     |               | MSC |             |                 | -   |                  |          |                      |         |              |
| (880244)               |                                                                                                                                                                                                                                     |               |     |             |                 |     |                  |          |                      |         |              |
| Engine                 |                                                                                                                                                                                                                                     |               |     |             |                 |     |                  |          |                      |         |              |
| BR700-73-101775<br>R01 | No. 1 Engine - Sb BR700-73-101775 R01 - Engine Fuel and Control - Low Pressure (Lp) Turbine Overspeed Control Unit and Manifold Splitter - Introduction of A Revised Overspeed and Splitter Unit (Osu), Service Bulletin (Optional) |               | HRS |             |                 |     |                  |          |                      |         | 0            |
|                        |                                                                                                                                                                                                                                     |               | ENC |             |                 |     |                  |          |                      | 0       |              |
|                        |                                                                                                                                                                                                                                     |               | MOS | 29.4        |                 |     | 29 Nov 2023      |          |                      |         |              |
|                        |                                                                                                                                                                                                                                     |               | MSC |             |                 | -   |                  |          |                      |         |              |
| (880246)               |                                                                                                                                                                                                                                     |               |     |             |                 |     |                  |          |                      |         |              |
| Engine                 |                                                                                                                                                                                                                                     |               |     |             |                 |     |                  |          |                      |         |              |
| BR700-73-101775<br>R01 | No. 2 Engine - Sb BR700-73-101775 R01 - Engine Fuel and Control - Low Pressure (Lp) Turbine Overspeed Control Unit and Manifold Splitter - Introduction of A Revised Overspeed and Splitter Unit (Osu), Service Bulletin (Optional) |               | HRS |             |                 |     |                  |          |                      |         | 0            |
|                        |                                                                                                                                                                                                                                     |               | ENC |             |                 |     |                  |          |                      | 0       |              |
|                        |                                                                                                                                                                                                                                     |               | MOS | 29.4        |                 |     | 29 Nov 2023      |          |                      |         |              |
|                        |                                                                                                                                                                                                                                     |               | MSC |             |                 | -   |                  |          |                      |         |              |
| (880246)               |                                                                                                                                                                                                                                     |               |     |             |                 |     |                  |          |                      |         |              |
| Engine                 |                                                                                                                                                                                                                                     |               |     |             |                 |     |                  |          |                      |         |              |
| BR700-73-101792<br>R02 | No. 1 Engine - Sb BR700-73-101792 R02 - Engine Fuel and Control - Engine Electronic Controller (Eec) - Introduction of K6.2.1 Software Standard on an Eec With Hardware Standard G3010ECU01, Service Bulletin (Optional)            |               | HRS |             |                 |     |                  |          |                      |         | 0            |
|                        |                                                                                                                                                                                                                                     |               | ENC |             |                 |     |                  |          |                      | 0       |              |
|                        |                                                                                                                                                                                                                                     |               | MOS | 29.2        |                 |     | 05 Dec 2023      |          |                      |         |              |
|                        |                                                                                                                                                                                                                                     |               | MSC |             |                 | -   |                  |          |                      |         |              |
| (880248)               |                                                                                                                                                                                                                                     |               |     |             |                 |     |                  |          |                      |         |              |
| Engine                 |                                                                                                                                                                                                                                     |               |     |             |                 |     |                  |          |                      |         |              |
| BR700-73-101792<br>R02 | No. 2 Engine - Sb BR700-73-101792 R02 - Engine Fuel and Control - Engine Electronic Controller (Eec) - Introduction of K6.2.1 Software Standard on an Eec With Hardware Standard G3010ECU01, Service Bulletin (Optional)            |               | HRS |             |                 |     |                  |          |                      |         | 0            |
|                        |                                                                                                                                                                                                                                     |               | ENC |             |                 |     |                  |          |                      | 0       |              |
|                        |                                                                                                                                                                                                                                     |               | MOS | 29.2        |                 |     | 05 Dec 2023      |          |                      |         |              |
|                        |                                                                                                                                                                                                                                     |               | MSC |             |                 | -   |                  |          |                      |         |              |
| (880248)               |                                                                                                                                                                                                                                     |               |     |             |                 |     |                  |          |                      |         |              |
| Engine                 |                                                                                                                                                                                                                                     |               |     |             |                 |     |                  |          |                      |         |              |

| ATA<br>U=Custom        | Description                                                                                                                                                                                                                        |               | UOM  | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|------|-------------|-----------------|-----|------------------|----------|--------------------|---------|--------------|
|                        | Part Number                                                                                                                                                                                                                        | Serial Number |      |             |                 |     |                  |          |                    |         | Approx Price |
| Logbook Position       | HW                                                                                                                                                                                                                                 | SW            |      |             |                 |     |                  |          |                    |         | Manufacturer |
|                        | MM Ref                                                                                                                                                                                                                             |               |      |             |                 |     |                  |          |                    |         | Date Type    |
|                        | Ops Number(s)                                                                                                                                                                                                                      |               |      |             |                 |     |                  |          |                    |         |              |
| BR700-73-101793<br>R04 | No. 1 Engine - Sb BR700-73-101793 R04 - Engine Fuel and Control - Engine Electronic Controller (Eec) - Introduction of K6.1.2 Software Standard on an Eec With Hardware Standard G3010ECU01, Service Bulletin (Optional)           |               | HRS  |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                                    |               | ENC  |             |                 |     |                  |          |                    | 0       |              |
|                        |                                                                                                                                                                                                                                    |               | MOS  | 29.4        |                 |     | 29 Nov 2023      |          |                    |         |              |
|                        |                                                                                                                                                                                                                                    |               | MSC  |             |                 | -   |                  |          |                    |         |              |
| (880250)               |                                                                                                                                                                                                                                    |               |      |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                                                                    |               |      |             |                 |     |                  |          |                    |         |              |
| BR700-73-101793<br>R04 | No. 2 Engine - Sb BR700-73-101793 R04 - Engine Fuel and Control - Engine Electronic Controller (Eec) - Introduction of K6.1.2 Software Standard on an Eec With Hardware Standard G3010ECU01, Service Bulletin (Optional)           |               | HRS  |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                                    |               | ENC  |             |                 |     |                  |          |                    | 0       |              |
|                        |                                                                                                                                                                                                                                    |               | MOS  | 29.4        |                 |     | 29 Nov 2023      |          |                    |         |              |
|                        |                                                                                                                                                                                                                                    |               | MSC  |             |                 | -   |                  |          |                    |         |              |
| (880250)               |                                                                                                                                                                                                                                    |               |      |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                                                                    |               |      |             |                 |     |                  |          |                    |         |              |
| BR700-73-101801<br>R01 | No. 1 Engine - Sb BR700-73-101801 R01 - Engine Fuel and Control - Engine Electronic Controller (Eec) - Introduction of K6.1.4 Software Standard on an Eec With Hardware Standard G3010ECU01, Service Bulletin (Optional)           |               | HRS  |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                                    |               | ENC  |             |                 |     |                  |          |                    | 0       |              |
|                        |                                                                                                                                                                                                                                    |               | MOS  | 29.4        |                 |     | 29 Nov 2023      |          |                    |         |              |
|                        |                                                                                                                                                                                                                                    |               | MSC  |             |                 | -   |                  |          |                    |         |              |
| (880252)               |                                                                                                                                                                                                                                    |               |      |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                                                                    |               |      |             |                 |     |                  |          |                    |         |              |
| BR700-73-101801<br>R01 | No. 2 Engine - Sb BR700-73-101801 R01 - Engine Fuel and Control - Engine Electronic Controller (Eec) - Introduction of K6.1.4 Software Standard on an Eec With Hardware Standard G3010ECU01, Service Bulletin (Optional)           |               | HRS  |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                                    |               | ENC  |             |                 |     |                  |          |                    | 0       |              |
|                        |                                                                                                                                                                                                                                    |               | MOS  | 29.4        |                 |     | 29 Nov 2023      |          |                    |         |              |
|                        |                                                                                                                                                                                                                                    |               | MSC  |             |                 | -   |                  |          |                    |         |              |
| (880252)               |                                                                                                                                                                                                                                    |               |      |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                                                                    |               |      |             |                 |     |                  |          |                    |         |              |
| BR700-73-101828        | No. 1 Engine - Sb BR700-73-101828 - Engine Fuel and Control - External Fuel System P30 and P50 AIR Tubes and Fittings Left Engine and Right Engine - Introduction of Modified Identity Bands of the Flexible P30 and P50 AIR Tubes |               | HRS  |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                                    |               | ENC  |             |                 |     |                  |          |                    | 0       |              |
|                        |                                                                                                                                                                                                                                    |               | DATE |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                                                                                                                                                    |               | MSC  |             |                 | -   |                  |          |                    |         |              |
| (880065)               |                                                                                                                                                                                                                                    |               |      |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                                                                    |               |      |             |                 |     |                  |          |                    |         |              |
| [End Of Month Item]    |                                                                                                                                                                                                                                    |               |      |             |                 |     |                  |          |                    |         |              |

| ATA<br>U=Custom        | Description                                                                                                                                                                                                                                                     |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                        | Part Number                                                                                                                                                                                                                                                     | Serial Number |                     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position       | HW                                                                                                                                                                                                                                                              | SW            |                     |             |                 |     |                  |             |                    |         | Manufacturer |
|                        | MM Ref                                                                                                                                                                                                                                                          |               |                     |             |                 |     |                  |             |                    |         | Date Type    |
|                        | Ops Number(s)                                                                                                                                                                                                                                                   |               |                     |             |                 |     |                  |             |                    |         |              |
| BR700-73-101828        | No. 2 Engine - Sb BR700-73-101828 - Engine Fuel and Control - External Fuel System P30 and P50 AIR Tubes and Fittings Left Engine and Right Engine - Introduction of Modified Identity Bands of the Flexible P30 and P50 AIR Tubes                              |               | HRS                 |             |                 |     |                  |             |                    |         | 0            |
|                        |                                                                                                                                                                                                                                                                 |               | ENC                 |             |                 |     |                  |             |                    |         | 0            |
|                        |                                                                                                                                                                                                                                                                 |               | DATE                |             |                 |     |                  |             |                    |         |              |
|                        |                                                                                                                                                                                                                                                                 |               | MSC                 |             |                 |     | -                |             |                    |         |              |
|                        |                                                                                                                                                                                                                                                                 |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| (880065)               |                                                                                                                                                                                                                                                                 |               |                     |             |                 |     |                  |             |                    |         |              |
| Engine                 |                                                                                                                                                                                                                                                                 |               |                     |             |                 |     |                  |             |                    |         |              |
| BR700-73-101838        | No. 1 Engine - Sb BR700-73-101838 - Engine Fuel and Control - Fuel Spray Nozzles - Introduction of A Redesigned Bracket Assembly Installed on the No.1 Burner Assembly Flange and Supporting A Stage 4 Pressure AIR Tube                                        |               | HRS                 |             |                 |     |                  |             |                    |         | 0            |
|                        |                                                                                                                                                                                                                                                                 |               | ENC                 |             |                 |     |                  |             |                    |         | 0            |
|                        |                                                                                                                                                                                                                                                                 |               | DATE                |             |                 |     |                  |             |                    |         |              |
|                        |                                                                                                                                                                                                                                                                 |               | MSC                 |             |                 |     | -                |             |                    |         |              |
|                        |                                                                                                                                                                                                                                                                 |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| (880054)               |                                                                                                                                                                                                                                                                 |               |                     |             |                 |     |                  |             |                    |         |              |
| Engine                 |                                                                                                                                                                                                                                                                 |               |                     |             |                 |     |                  |             |                    |         |              |
| BR700-73-101838        | No. 2 Engine - Sb BR700-73-101838 - Engine Fuel and Control - Fuel Spray Nozzles - Introduction of A Redesigned Bracket Assembly Installed on the No.1 Burner Assembly Flange and Supporting A Stage 4 Pressure AIR Tube                                        |               | HRS                 |             |                 |     |                  |             |                    |         | 0            |
|                        |                                                                                                                                                                                                                                                                 |               | ENC                 |             |                 |     |                  |             |                    |         | 0            |
|                        |                                                                                                                                                                                                                                                                 |               | DATE                |             |                 |     |                  |             |                    |         |              |
|                        |                                                                                                                                                                                                                                                                 |               | MSC                 |             |                 |     | -                |             |                    |         |              |
|                        |                                                                                                                                                                                                                                                                 |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| (880054)               |                                                                                                                                                                                                                                                                 |               |                     |             |                 |     |                  |             |                    |         |              |
| Engine                 |                                                                                                                                                                                                                                                                 |               |                     |             |                 |     |                  |             |                    |         |              |
| BR700-73-101847<br>R02 | No. 1 Engine - Sb BR700-73-101847 R02 - Engine Fuel and Control - External Fuel Distribution Tubes and Fittings - Introduction of A New Spill Return to Fuel Pump Tube Made from A Different Material and A New Assembly Procedure, Service Bulletin (Optional) |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                        |                                                                                                                                                                                                                                                                 |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                        |                                                                                                                                                                                                                                                                 |               | MOS                 |             | 41.8            |     |                  | 17 Nov 2022 |                    |         |              |
|                        |                                                                                                                                                                                                                                                                 |               | MSC                 |             |                 |     | -                |             |                    |         |              |
|                        |                                                                                                                                                                                                                                                                 |               |                     |             |                 |     |                  |             |                    |         |              |
| (880254)               |                                                                                                                                                                                                                                                                 |               |                     |             |                 |     |                  |             |                    |         |              |
| Engine                 |                                                                                                                                                                                                                                                                 |               |                     |             |                 |     |                  |             |                    |         |              |
| BR700-73-101847<br>R02 | No. 2 Engine - Sb BR700-73-101847 R02 - Engine Fuel and Control - External Fuel Distribution Tubes and Fittings - Introduction of A New Spill Return to Fuel Pump Tube Made from A Different Material and A New Assembly Procedure, Service Bulletin (Optional) |               | HRS                 |             | 994.4           |     |                  | 0           |                    |         | 0            |
|                        |                                                                                                                                                                                                                                                                 |               | ENC                 |             | 392             |     |                  | 0           |                    |         | 0            |
|                        |                                                                                                                                                                                                                                                                 |               | MOS                 |             | 41.9            |     |                  | 15 Nov 2022 |                    |         |              |
|                        |                                                                                                                                                                                                                                                                 |               | MSC                 |             |                 |     | -                |             |                    |         |              |
|                        |                                                                                                                                                                                                                                                                 |               |                     |             |                 |     |                  |             |                    |         |              |
| (880254)               |                                                                                                                                                                                                                                                                 |               |                     |             |                 |     |                  |             |                    |         |              |
| Engine                 |                                                                                                                                                                                                                                                                 |               |                     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom        | Description                                                                                                                                                                                                              |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|----------|--------------------|---------|--------------|
|                        | Part Number                                                                                                                                                                                                              | Serial Number |                     |             |                 |     |                  |          |                    |         | Approx Price |
| Logbook Position       | HW                                                                                                                                                                                                                       | SW            |                     |             |                 |     |                  |          |                    |         | Manufacturer |
|                        | MM Ref                                                                                                                                                                                                                   |               |                     |             |                 |     |                  |          |                    |         | Date Type    |
|                        | Ops Number(s)                                                                                                                                                                                                            |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-73-101886        | No. 1 Engine - Sb BR700-73-101886 - Engine Fuel and Control - Engine Electronic Controller (Eec) - Introduction of K6.2.2 Software Standard on an Eec With Hardware Standard G3010ECU01                                  |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                          |               | ENC                 |             |                 |     |                  |          |                    | 0       |              |
|                        |                                                                                                                                                                                                                          |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                                                                                                                                          |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880063)               |                                                                                                                                                                                                                          |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                                                          |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-73-101886        | No. 2 Engine - Sb BR700-73-101886 - Engine Fuel and Control - Engine Electronic Controller (Eec) - Introduction of K6.2.2 Software Standard on an Eec With Hardware Standard G3010ECU01                                  |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                          |               | ENC                 |             |                 |     |                  |          |                    | 0       |              |
|                        |                                                                                                                                                                                                                          |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                                                                                                                                          |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880063)               |                                                                                                                                                                                                                          |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                                                          |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-73-101886<br>R01 | No. 1 Engine - Sb BR700-73-101886 R01 - Engine Fuel and Control - Engine Electronic Controller (Eec) - Introduction of K6.2.2 Software Standard on an Eec With Hardware Standard G3010ECU01, Service Bulletin (Optional) |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                          |               | ENC                 |             |                 |     |                  |          |                    | 0       |              |
|                        |                                                                                                                                                                                                                          |               | MOS                 | 29.2        |                 |     | 05 Dec 2023      |          |                    |         |              |
|                        |                                                                                                                                                                                                                          |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880256)               |                                                                                                                                                                                                                          |               |                     |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                                                          |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-73-101886<br>R01 | No. 2 Engine - Sb BR700-73-101886 R01 - Engine Fuel and Control - Engine Electronic Controller (Eec) - Introduction of K6.2.2 Software Standard on an Eec With Hardware Standard G3010ECU01, Service Bulletin (Optional) |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                          |               | ENC                 |             |                 |     |                  |          |                    | 0       |              |
|                        |                                                                                                                                                                                                                          |               | MOS                 | 29.2        |                 |     | 05 Dec 2023      |          |                    |         |              |
|                        |                                                                                                                                                                                                                          |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880256)               |                                                                                                                                                                                                                          |               |                     |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                                                          |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-73-101892<br>R01 | No. 1 Engine - Sb BR700-73-101892 R01 - Engine Fuel and Control - External Fuel Distribution Tubes and Fittings - Introduction of A Low Pressure (Lp) Fuel Switch Sense Line Tube With Increased Volume                  |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                          |               | ENC                 |             |                 |     |                  |          |                    | 0       |              |
|                        |                                                                                                                                                                                                                          |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                                                                                                                                          |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880132)               |                                                                                                                                                                                                                          |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                                                          |               |                     |             |                 |     |                  |          |                    |         |              |



| ATA<br>U=Custom        | Description                                                                                                                                                                                                                          |               | UOM  | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|------|-------------|-----------------|-----|------------------|----------|--------------------|---------|--------------|
|                        | Part Number                                                                                                                                                                                                                          | Serial Number |      |             |                 |     |                  |          |                    |         | Approx Price |
| Logbook Position       | HW                                                                                                                                                                                                                                   | SW            |      |             |                 |     |                  |          |                    |         | Manufacturer |
|                        | MM Ref                                                                                                                                                                                                                               |               |      |             |                 |     |                  |          |                    |         | Date Type    |
|                        | Ops Number(s)                                                                                                                                                                                                                        |               |      |             |                 |     |                  |          |                    |         |              |
| BR700-73-101892<br>R01 | No. 2 Engine - Sb BR700-73-101892 R01 - Engine Fuel and Control - External Fuel Distribution Tubes and Fittings - Introduction of A Low Pressure (Lp) Fuel Switch Sense Line Tube With Increased Volume                              |               | HRS  |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                                      |               | ENC  |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                                      |               | DATE |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                                                                                                                                                      |               | MSC  |             |                 |     | -                |          |                    |         |              |
| (880132)               | [End Of Month Item]                                                                                                                                                                                                                  |               |      |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                                                                      |               |      |             |                 |     |                  |          |                    |         |              |
| BR700-73-101892<br>R02 | No. 1 Engine - Sb BR700-73-101892 R02 - Engine Fuel and Control - External Fuel Distribution Tubes and Fittings - Introduction of A Low Pressure (Lp) Fuel Switch Sense Line Tube With Increased Volume, Service Bulletin (Optional) |               | HRS  |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                                      |               | ENC  |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                                      |               | MOS  | 29.3        |                 |     | 01 Dec 2023      |          |                    |         |              |
|                        |                                                                                                                                                                                                                                      |               | MSC  |             |                 |     | -                |          |                    |         |              |
| (880258)               |                                                                                                                                                                                                                                      |               |      |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                                                                      |               |      |             |                 |     |                  |          |                    |         |              |
| BR700-73-101892<br>R02 | No. 2 Engine - Sb BR700-73-101892 R02 - Engine Fuel and Control - External Fuel Distribution Tubes and Fittings - Introduction of A Low Pressure (Lp) Fuel Switch Sense Line Tube With Increased Volume, Service Bulletin (Optional) |               | HRS  |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                                      |               | ENC  |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                                      |               | MOS  | 29.3        |                 |     | 01 Dec 2023      |          |                    |         |              |
|                        |                                                                                                                                                                                                                                      |               | MSC  |             |                 |     | -                |          |                    |         |              |
| (880258)               |                                                                                                                                                                                                                                      |               |      |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                                                                      |               |      |             |                 |     |                  |          |                    |         |              |
| BR700-73-101902<br>R01 | No. 1 Engine - Sb BR700-73-101902 R01 - Engine Fuel and Control - T30 Thermocouples - Introduction of A Revised T30 Thermocouple Installation on the Left Side of the Core Engine                                                    |               | HRS  |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                                      |               | ENC  |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                                      |               | DATE |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                                                                                                                                                      |               | MSC  |             |                 |     | -                |          |                    |         |              |
| (880120)               | [End Of Month Item]                                                                                                                                                                                                                  |               |      |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                                                                      |               |      |             |                 |     |                  |          |                    |         |              |
| BR700-73-101902<br>R01 | No. 2 Engine - Sb BR700-73-101902 R01 - Engine Fuel and Control - T30 Thermocouples - Introduction of A Revised T30 Thermocouple Installation on the Left Side of the Core Engine                                                    |               | HRS  |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                                      |               | ENC  |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                                      |               | DATE |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                                                                                                                                                      |               | MSC  |             |                 |     | -                |          |                    |         |              |
| (880120)               | [End Of Month Item]                                                                                                                                                                                                                  |               |      |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                                                                      |               |      |             |                 |     |                  |          |                    |         |              |

| ATA<br>U=Custom        | Description                                                                                                                                                                                                                                                         |               | UOM  | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|------|-------------|-----------------|-----|------------------|----------|--------------------|---------|--------------|
|                        | Part Number                                                                                                                                                                                                                                                         | Serial Number |      |             |                 |     |                  |          |                    |         | Approx Price |
| Logbook Position       | HW                                                                                                                                                                                                                                                                  | SW            |      |             |                 |     |                  |          |                    |         | Manufacturer |
|                        | MM Ref                                                                                                                                                                                                                                                              |               |      |             |                 |     |                  |          |                    |         | Date Type    |
|                        | Ops Number(s)                                                                                                                                                                                                                                                       |               |      |             |                 |     |                  |          |                    |         |              |
| BR700-73-101902<br>R02 | No. 1 Engine - Sb BR700-73-101902 R02 - Engine Fuel and Control - T30 Thermocouples - Introduction of A Revised T30 Thermocouple Installation on the Left Side of the Core Engine, Service Bulletin (Optional)                                                      |               | HRS  |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                                                                     |               | ENC  |             |                 |     |                  |          |                    | 0       |              |
|                        |                                                                                                                                                                                                                                                                     |               | MOS  | 29.2        |                 |     | 04 Dec 2023      |          |                    |         |              |
|                        |                                                                                                                                                                                                                                                                     |               | MSC  |             |                 | -   |                  |          |                    |         |              |
| (880261)               |                                                                                                                                                                                                                                                                     |               |      |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                                                                                                     |               |      |             |                 |     |                  |          |                    |         |              |
| BR700-73-101902<br>R02 | No. 2 Engine - Sb BR700-73-101902 R02 - Engine Fuel and Control - T30 Thermocouples - Introduction of A Revised T30 Thermocouple Installation on the Left Side of the Core Engine, Service Bulletin (Optional)                                                      |               | HRS  |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                                                                     |               | ENC  |             |                 |     |                  |          |                    | 0       |              |
|                        |                                                                                                                                                                                                                                                                     |               | MOS  | 29.2        |                 |     | 04 Dec 2023      |          |                    |         |              |
|                        |                                                                                                                                                                                                                                                                     |               | MSC  |             |                 | -   |                  |          |                    |         |              |
| (880261)               |                                                                                                                                                                                                                                                                     |               |      |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                                                                                                     |               |      |             |                 |     |                  |          |                    |         |              |
| BR700-73-101912        | No. 1 Engine - Sb BR700-73-101912 - Engine Fuel and Control - Fuel Differential Low Pressure (Lp) Transducer - Introduction of A Modified Lp Fuel Differential Pressure Transducer With A More Accurate Output Signal                                               |               | HRS  |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                                                                     |               | ENC  |             |                 |     |                  |          |                    | 0       |              |
|                        |                                                                                                                                                                                                                                                                     |               | DATE |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                                                                                                                                                                                     |               | MSC  |             |                 | -   |                  |          |                    |         |              |
| (880142)               | [End Of Month Item]                                                                                                                                                                                                                                                 |               |      |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                                                                                                     |               |      |             |                 |     |                  |          |                    |         |              |
| BR700-73-101912        | No. 2 Engine - Sb BR700-73-101912 - Engine Fuel and Control - Fuel Differential Low Pressure (Lp) Transducer - Introduction of A Modified Lp Fuel Differential Pressure Transducer With A More Accurate Output Signal                                               |               | HRS  |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                                                                     |               | ENC  |             |                 |     |                  |          |                    | 0       |              |
|                        |                                                                                                                                                                                                                                                                     |               | DATE |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                                                                                                                                                                                     |               | MSC  |             |                 | -   |                  |          |                    |         |              |
| (880142)               | [End Of Month Item]                                                                                                                                                                                                                                                 |               |      |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                                                                                                     |               |      |             |                 |     |                  |          |                    |         |              |
| BR700-73-101923        | No. 1 Engine - Sb BR700-73-101923 - Engine Fuel and Control - External Fuel Distribution Tubes and Fittings - Introduction of A New Fuel Tube With an Increased Wall Thickness, Which Is Installed Between the Fuel Cooled Oil Cooler (Fcoc) and the Main Fuel Pump |               | HRS  |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                                                                     |               | ENC  |             |                 |     |                  |          |                    | 0       |              |
|                        |                                                                                                                                                                                                                                                                     |               | DATE |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                                                                                                                                                                                     |               | MSC  |             |                 | -   |                  |          |                    |         |              |
| (880092)               | [End Of Month Item]                                                                                                                                                                                                                                                 |               |      |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                                                                                                     |               |      |             |                 |     |                  |          |                    |         |              |

| ATA<br>U=Custom        | Description                                                                                                                                                                                                                                                                                       |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                        | Part Number                                                                                                                                                                                                                                                                                       | Serial Number |                     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position       | HW                                                                                                                                                                                                                                                                                                | SW            |                     |             |                 |     |                  |             |                    |         | Manufacturer |
|                        | MM Ref                                                                                                                                                                                                                                                                                            |               |                     |             |                 |     |                  |             |                    |         | Date Type    |
|                        | Ops Number(s)                                                                                                                                                                                                                                                                                     |               |                     |             |                 |     |                  |             |                    |         |              |
| BR700-73-101923        | No. 2 Engine - Sb BR700-73-101923 - Engine Fuel and Control - External Fuel Distribution Tubes and Fittings - Introduction of A New Fuel Tube With an Increased Wall Thickness, Which Is Installed Between the Fuel Cooled Oil Cooler (Fcoc) and the Main Fuel Pump                               |               | HRS                 |             |                 |     |                  |             |                    |         | 0            |
|                        |                                                                                                                                                                                                                                                                                                   |               | ENC                 |             |                 |     |                  |             |                    |         | 0            |
|                        |                                                                                                                                                                                                                                                                                                   |               | DATE                |             |                 |     |                  |             |                    |         |              |
|                        |                                                                                                                                                                                                                                                                                                   |               | MSC                 |             |                 |     | -                |             |                    |         |              |
|                        |                                                                                                                                                                                                                                                                                                   |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| (880092)               |                                                                                                                                                                                                                                                                                                   |               |                     |             |                 |     |                  |             |                    |         |              |
| Engine                 |                                                                                                                                                                                                                                                                                                   |               |                     |             |                 |     |                  |             |                    |         |              |
| BR700-73-101923<br>R01 | No. 1 Engine - BR700-73-101923 R01 - Engine Fuel and Control - External Fuel Distribution Tubes and Fittings - Introduction of A New Fuel Tube With an Increased Wall Thickness, Which Is Installed Between the Fuel Cooled Oil Cooler (Fcoc) and the Main Fuel Pump, Service Bulletin (Optional) |               | HRS                 |             |                 |     |                  |             |                    |         | 0            |
|                        |                                                                                                                                                                                                                                                                                                   |               | ENC                 |             |                 |     |                  |             |                    |         | 0            |
|                        |                                                                                                                                                                                                                                                                                                   |               | MOS                 |             | 29.2            |     |                  | 05 Dec 2023 |                    |         |              |
|                        |                                                                                                                                                                                                                                                                                                   |               | MSC                 |             |                 |     | -                |             |                    |         |              |
| (880260)               |                                                                                                                                                                                                                                                                                                   |               |                     |             |                 |     |                  |             |                    |         |              |
| Engine                 |                                                                                                                                                                                                                                                                                                   |               |                     |             |                 |     |                  |             |                    |         |              |
| BR700-73-101923<br>R01 | No. 2 Engine - BR700-73-101923 R01 - Engine Fuel and Control - External Fuel Distribution Tubes and Fittings - Introduction of A New Fuel Tube With an Increased Wall Thickness, Which Is Installed Between the Fuel Cooled Oil Cooler (Fcoc) and the Main Fuel Pump, Service Bulletin (Optional) |               | HRS                 |             |                 |     |                  |             |                    |         | 0            |
|                        |                                                                                                                                                                                                                                                                                                   |               | ENC                 |             |                 |     |                  |             |                    |         | 0            |
|                        |                                                                                                                                                                                                                                                                                                   |               | MOS                 |             | 29.2            |     |                  | 05 Dec 2023 |                    |         |              |
|                        |                                                                                                                                                                                                                                                                                                   |               | MSC                 |             |                 |     | -                |             |                    |         |              |
| (880260)               |                                                                                                                                                                                                                                                                                                   |               |                     |             |                 |     |                  |             |                    |         |              |
| Engine                 |                                                                                                                                                                                                                                                                                                   |               |                     |             |                 |     |                  |             |                    |         |              |
| BR700-73-101929        | No. 1 Engine - Sb BR700-73-101929 - Engine Fuel and Control - Fuel Pump - Introduction of A Revised V-Clamp Coupling With Two Retaining Segments                                                                                                                                                  |               | HRS                 |             |                 |     |                  |             |                    |         | 0            |
|                        |                                                                                                                                                                                                                                                                                                   |               | ENC                 |             |                 |     |                  |             |                    |         | 0            |
|                        |                                                                                                                                                                                                                                                                                                   |               | DATE                |             |                 |     |                  |             |                    |         |              |
|                        |                                                                                                                                                                                                                                                                                                   |               | MSC                 |             |                 |     | -                |             |                    |         |              |
|                        |                                                                                                                                                                                                                                                                                                   |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| (880098)               |                                                                                                                                                                                                                                                                                                   |               |                     |             |                 |     |                  |             |                    |         |              |
| Engine                 |                                                                                                                                                                                                                                                                                                   |               |                     |             |                 |     |                  |             |                    |         |              |
| BR700-73-101929        | No. 2 Engine - Sb BR700-73-101929 - Engine Fuel and Control - Fuel Pump - Introduction of A Revised V-Clamp Coupling With Two Retaining Segments                                                                                                                                                  |               | HRS                 |             |                 |     |                  |             |                    |         | 0            |
|                        |                                                                                                                                                                                                                                                                                                   |               | ENC                 |             |                 |     |                  |             |                    |         | 0            |
|                        |                                                                                                                                                                                                                                                                                                   |               | DATE                |             |                 |     |                  |             |                    |         |              |
|                        |                                                                                                                                                                                                                                                                                                   |               | MSC                 |             |                 |     | -                |             |                    |         |              |
|                        |                                                                                                                                                                                                                                                                                                   |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| (880098)               |                                                                                                                                                                                                                                                                                                   |               |                     |             |                 |     |                  |             |                    |         |              |
| Engine                 |                                                                                                                                                                                                                                                                                                   |               |                     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom        | Description                                                                                                                                                                    |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                        | Part Number                                                                                                                                                                    | Serial Number |                     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position       | HW                                                                                                                                                                             | SW            |                     |             |                 |     |                  |             |                    |         | Manufacturer |
|                        | MM Ref                                                                                                                                                                         |               |                     |             |                 |     |                  |             |                    |         | Date Type    |
|                        | Ops Number(s)                                                                                                                                                                  |               |                     |             |                 |     |                  |             |                    |         |              |
| BR700-73-101929<br>R01 | No. 1 Engine - BR700-73-101929 R01 - Engine Fuel and Control - Fuel Pump - Introduction of A Revised V-Clamp Coupling With Two Retaining Segments, Service Bulletin (Optional) |               | HRS                 |             |                 |     |                  |             |                    |         | 0            |
|                        |                                                                                                                                                                                |               | ENC                 |             |                 |     |                  |             |                    | 0       |              |
|                        |                                                                                                                                                                                |               | MOS                 |             | 29.3            |     |                  | 01 Dec 2023 |                    |         |              |
|                        |                                                                                                                                                                                |               | MSC                 |             |                 |     | -                |             |                    |         |              |
| (880259)               |                                                                                                                                                                                |               |                     |             |                 |     |                  |             |                    |         |              |
| Engine                 |                                                                                                                                                                                |               |                     |             |                 |     |                  |             |                    |         |              |
| BR700-73-101929<br>R01 | No. 2 Engine - BR700-73-101929 R01 - Engine Fuel and Control - Fuel Pump - Introduction of A Revised V-Clamp Coupling With Two Retaining Segments, Service Bulletin (Optional) |               | HRS                 |             |                 |     |                  |             |                    |         | 0            |
|                        |                                                                                                                                                                                |               | ENC                 |             |                 |     |                  |             |                    | 0       |              |
|                        |                                                                                                                                                                                |               | MOS                 |             | 29.3            |     |                  | 01 Dec 2023 |                    |         |              |
|                        |                                                                                                                                                                                |               | MSC                 |             |                 |     | -                |             |                    |         |              |
| (880259)               |                                                                                                                                                                                |               |                     |             |                 |     |                  |             |                    |         |              |
| Engine                 |                                                                                                                                                                                |               |                     |             |                 |     |                  |             |                    |         |              |
| BR700-73-101941        | No. 1 Engine - Sb BR700-73-101941 - Engine Fuel and Control - T30 Thermocouples - Introduction of New T30 Thermocouples                                                        |               | HRS                 |             |                 |     |                  |             |                    |         | 0            |
|                        |                                                                                                                                                                                |               | ENC                 |             |                 |     |                  |             |                    | 0       |              |
|                        |                                                                                                                                                                                |               | DATE                |             |                 |     |                  |             |                    |         |              |
|                        |                                                                                                                                                                                |               | MSC                 |             |                 |     | -                |             |                    |         |              |
| (880119)               |                                                                                                                                                                                |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine                 |                                                                                                                                                                                |               |                     |             |                 |     |                  |             |                    |         |              |
| BR700-73-101941        | No. 2 Engine - Sb BR700-73-101941 - Engine Fuel and Control - T30 Thermocouples - Introduction of New T30 Thermocouples                                                        |               | HRS                 |             |                 |     |                  |             |                    |         | 0            |
|                        |                                                                                                                                                                                |               | ENC                 |             |                 |     |                  |             |                    | 0       |              |
|                        |                                                                                                                                                                                |               | DATE                |             |                 |     |                  |             |                    |         |              |
|                        |                                                                                                                                                                                |               | MSC                 |             |                 |     | -                |             |                    |         |              |
| (880119)               |                                                                                                                                                                                |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine                 |                                                                                                                                                                                |               |                     |             |                 |     |                  |             |                    |         |              |
| BR700-73-101957<br>R01 | No. 1 Engine - Sb BR700-73-101957 R01 - Engine Fuel and Control - Fuel System - Introduction of A Revised Fuel System                                                          |               | HRS                 |             |                 |     |                  |             |                    |         | 0            |
|                        |                                                                                                                                                                                |               | ENC                 |             |                 |     |                  |             |                    | 0       |              |
|                        |                                                                                                                                                                                |               | DATE                |             |                 |     |                  |             |                    |         |              |
|                        |                                                                                                                                                                                |               | MSC                 |             |                 |     | -                |             |                    |         |              |
| (880131)               |                                                                                                                                                                                |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine                 |                                                                                                                                                                                |               |                     |             |                 |     |                  |             |                    |         |              |
| BR700-73-101957<br>R01 | No. 2 Engine - Sb BR700-73-101957 R01 - Engine Fuel and Control - Fuel System - Introduction of A Revised Fuel System                                                          |               | HRS                 |             |                 |     |                  |             |                    |         | 0            |
|                        |                                                                                                                                                                                |               | ENC                 |             |                 |     |                  |             |                    | 0       |              |
|                        |                                                                                                                                                                                |               | DATE                |             |                 |     |                  |             |                    |         |              |
|                        |                                                                                                                                                                                |               | MSC                 |             |                 |     | -                |             |                    |         |              |
| (880131)               |                                                                                                                                                                                |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine                 |                                                                                                                                                                                |               |                     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom        | Description                                                                                                                                                                                                            |               | UOM  | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|------|-------------|-----------------|-----|------------------|----------|--------------------|---------|--------------|
|                        | Part Number                                                                                                                                                                                                            | Serial Number |      |             |                 |     |                  |          |                    |         | Approx Price |
| Logbook Position       | HW                                                                                                                                                                                                                     | SW            |      |             |                 |     |                  |          |                    |         | Manufacturer |
|                        | MM Ref                                                                                                                                                                                                                 |               |      |             |                 |     |                  |          |                    |         | Date Type    |
|                        | Ops Number(s)                                                                                                                                                                                                          |               |      |             |                 |     |                  |          |                    |         |              |
| BR700-73-101957<br>R02 | No. 1 Engine - Sb BR700-73-101957 R02 - Engine Fuel and Control - Fuel System - Introduction of A Revised Fuel System, Service Bulletin (Optional)                                                                     |               | HRS  |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                        |               | ENC  |             |                 |     |                  |          | 0                  |         |              |
|                        |                                                                                                                                                                                                                        |               | MOS  | 29.2        |                 |     | 05 Dec 2023      |          |                    |         |              |
|                        |                                                                                                                                                                                                                        |               | MSC  |             |                 | -   |                  |          |                    |         |              |
| (880231)               |                                                                                                                                                                                                                        |               |      |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                                                        |               |      |             |                 |     |                  |          |                    |         |              |
| BR700-73-101957<br>R02 | No. 2 Engine - Sb BR700-73-101957 R02 - Engine Fuel and Control - Fuel System - Introduction of A Revised Fuel System, Service Bulletin (Optional)                                                                     |               | HRS  |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                        |               | ENC  |             |                 |     |                  |          | 0                  |         |              |
|                        |                                                                                                                                                                                                                        |               | MOS  | 29.2        |                 |     | 05 Dec 2023      |          |                    |         |              |
|                        |                                                                                                                                                                                                                        |               | MSC  |             |                 | -   |                  |          |                    |         |              |
| (880231)               |                                                                                                                                                                                                                        |               |      |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                                                        |               |      |             |                 |     |                  |          |                    |         |              |
| BR700-73-101965<br>R01 | No. 1 Engine - Sb BR700-73-101965 R01 - Engine Fuel and Control - Fuel Low Pressure Switch - Introduction of A Revised Fuellow Pressure (Lp) Switch With A Decreased Pressure Trigger Point                            |               | HRS  |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                        |               | ENC  |             |                 |     |                  |          | 0                  |         |              |
|                        |                                                                                                                                                                                                                        |               | DATE |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                                                                                                                                        |               | MSC  |             |                 | -   |                  |          |                    |         |              |
| (880129)               | [End Of Month Item]                                                                                                                                                                                                    |               |      |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                                                        |               |      |             |                 |     |                  |          |                    |         |              |
| BR700-73-101965<br>R01 | No. 2 Engine - Sb BR700-73-101965 R01 - Engine Fuel and Control - Fuel Low Pressure Switch - Introduction of A Revised Fuellow Pressure (Lp) Switch With A Decreased Pressure Trigger Point                            |               | HRS  |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                        |               | ENC  |             |                 |     |                  |          | 0                  |         |              |
|                        |                                                                                                                                                                                                                        |               | DATE |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                                                                                                                                        |               | MSC  |             |                 | -   |                  |          |                    |         |              |
| (880129)               | [End Of Month Item]                                                                                                                                                                                                    |               |      |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                                                        |               |      |             |                 |     |                  |          |                    |         |              |
| BR700-73-101965<br>R02 | No. 1 Engine - BR700-73-101965 R02 - Engine Fuel and Control - Fuel Low Pressure Switch - Introduction of A Revised Fuel Low Pressure (Lp) Switch With A Decreased Pressure Trigger Point, Service Bulletin (Optional) |               | HRS  |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                        |               | ENC  |             |                 |     |                  |          | 0                  |         |              |
|                        |                                                                                                                                                                                                                        |               | MOS  | 29.3        |                 |     | 01 Dec 2023      |          |                    |         |              |
|                        |                                                                                                                                                                                                                        |               | MSC  |             |                 | -   |                  |          |                    |         |              |
| (880257)               |                                                                                                                                                                                                                        |               |      |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                                                        |               |      |             |                 |     |                  |          |                    |         |              |

| ATA<br>U=Custom        | Description                                                                                                                                                                                                            |               | UOM  | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|------|-------------|-----------------|-----|------------------|----------|--------------------|---------|--------------|
|                        | Part Number                                                                                                                                                                                                            | Serial Number |      |             |                 |     |                  |          |                    |         | Approx Price |
| Logbook Position       | HW                                                                                                                                                                                                                     | SW            |      |             |                 |     |                  |          |                    |         | Manufacturer |
|                        | MM Ref                                                                                                                                                                                                                 |               |      |             |                 |     |                  |          |                    |         | Date Type    |
|                        | Ops Number(s)                                                                                                                                                                                                          |               |      |             |                 |     |                  |          |                    |         |              |
| BR700-73-101965<br>R02 | No. 2 Engine - BR700-73-101965 R02 - Engine Fuel and Control - Fuel Low Pressure Switch - Introduction of A Revised Fuel Low Pressure (Lp) Switch With A Decreased Pressure Trigger Point, Service Bulletin (Optional) |               | HRS  |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                        |               | ENC  |             |                 |     |                  |          |                    | 0       |              |
|                        |                                                                                                                                                                                                                        |               | MOS  | 29.3        |                 |     | 01 Dec 2023      |          |                    |         |              |
|                        |                                                                                                                                                                                                                        |               | MSC  |             |                 | -   |                  |          |                    |         |              |
| (880257)               |                                                                                                                                                                                                                        |               |      |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                                                        |               |      |             |                 |     |                  |          |                    |         |              |
| BR700-73-101967<br>R01 | No. 1 Engine - Sb BR700-73-101967 R01 - Engine Fuel and Control - Engine Electronic Controller (Eec) - Introduction of K7.1.3 Software Standard on an Eec With Hardware Standard G3010ECU01                            |               | HRS  |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                        |               | ENC  |             |                 |     |                  |          |                    | 0       |              |
|                        |                                                                                                                                                                                                                        |               | DATE |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                                                                                                                                        |               | MSC  |             |                 | -   |                  |          |                    |         |              |
| (880130)               |                                                                                                                                                                                                                        |               |      |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                                                        |               |      |             |                 |     |                  |          |                    |         |              |
| BR700-73-101967<br>R01 | No. 2 Engine - Sb BR700-73-101967 R01 - Engine Fuel and Control - Engine Electronic Controller (Eec) - Introduction of K7.1.3 Software Standard on an Eec With Hardware Standard G3010ECU01                            |               | HRS  |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                        |               | ENC  |             |                 |     |                  |          |                    | 0       |              |
|                        |                                                                                                                                                                                                                        |               | DATE |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                                                                                                                                        |               | MSC  |             |                 | -   |                  |          |                    |         |              |
| (880130)               |                                                                                                                                                                                                                        |               |      |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                                                        |               |      |             |                 |     |                  |          |                    |         |              |
| BR700-73-101967<br>R02 | No. 1 Engine - BR700-73-101967 R02 - Engine Fuel and Control - Engine Electronic Controller (Eec) - Introduction of K7.1.3 Software Standard on an Eec With Hardware Standard G3010ECU01, Service Bulletin (Optional)  |               | HRS  |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                        |               | ENC  |             |                 |     |                  |          |                    | 0       |              |
|                        |                                                                                                                                                                                                                        |               | MOS  | 29.4        |                 |     | 29 Nov 2023      |          |                    |         |              |
|                        |                                                                                                                                                                                                                        |               | MSC  |             |                 | -   |                  |          |                    |         |              |
| (880255)               |                                                                                                                                                                                                                        |               |      |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                                                        |               |      |             |                 |     |                  |          |                    |         |              |
| BR700-73-101967<br>R02 | No. 2 Engine - BR700-73-101967 R02 - Engine Fuel and Control - Engine Electronic Controller (Eec) - Introduction of K7.1.3 Software Standard on an Eec With Hardware Standard G3010ECU01, Service Bulletin (Optional)  |               | HRS  |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                        |               | ENC  |             |                 |     |                  |          |                    | 0       |              |
|                        |                                                                                                                                                                                                                        |               | MOS  | 29.4        |                 |     | 29 Nov 2023      |          |                    |         |              |
|                        |                                                                                                                                                                                                                        |               | MSC  |             |                 | -   |                  |          |                    |         |              |
| (880255)               |                                                                                                                                                                                                                        |               |      |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                                                        |               |      |             |                 |     |                  |          |                    |         |              |

| ATA<br>U=Custom        | Description                                                                                                                                                                                                           |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|----------|--------------------|---------|--------------|
|                        | Part Number                                                                                                                                                                                                           | Serial Number |                     |             |                 |     |                  |          |                    |         | Approx Price |
| Logbook Position       | HW                                                                                                                                                                                                                    | SW            |                     |             |                 |     |                  |          |                    |         | Manufacturer |
|                        | MM Ref                                                                                                                                                                                                                |               |                     |             |                 |     |                  |          |                    |         | Date Type    |
|                        | Ops Number(s)                                                                                                                                                                                                         |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-73-102000        | No. 1 Engine - Sb BR700-73-102000 - Engine Fuel and Control - Engine Electronic Controller (Eec) - Introduction of K8.0.2 Software Standard on an Eec With Hardware Standard G3010ECU01                               |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                       |               | ENC                 |             |                 |     |                  |          |                    | 0       |              |
|                        |                                                                                                                                                                                                                       |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                                                                                                                                       |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880162)               |                                                                                                                                                                                                                       |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                                                       |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-73-102000        | No. 2 Engine - Sb BR700-73-102000 - Engine Fuel and Control - Engine Electronic Controller (Eec) - Introduction of K8.0.2 Software Standard on an Eec With Hardware Standard G3010ECU01                               |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                       |               | ENC                 |             |                 |     |                  |          |                    | 0       |              |
|                        |                                                                                                                                                                                                                       |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                                                                                                                                       |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880162)               |                                                                                                                                                                                                                       |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                                                       |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-73-102000<br>R01 | No. 1 Engine - BR700-73-102000 R01 - Engine Fuel and Control - Engine Electronic Controller (Eec) - Introduction of K8.0.2 Software Standard on an Eec With Hardware Standard G3010ECU01, Service Bulletin (Optional) |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                       |               | ENC                 |             |                 |     |                  |          |                    | 0       |              |
|                        |                                                                                                                                                                                                                       |               | MOS                 | 29.3        |                 |     | 01 Dec 2023      |          |                    |         |              |
|                        |                                                                                                                                                                                                                       |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880253)               |                                                                                                                                                                                                                       |               |                     |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                                                       |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-73-102000<br>R01 | No. 2 Engine - BR700-73-102000 R01 - Engine Fuel and Control - Engine Electronic Controller (Eec) - Introduction of K8.0.2 Software Standard on an Eec With Hardware Standard G3010ECU01, Service Bulletin (Optional) |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                       |               | ENC                 |             |                 |     |                  |          |                    | 0       |              |
|                        |                                                                                                                                                                                                                       |               | MOS                 | 29.3        |                 |     | 01 Dec 2023      |          |                    |         |              |
|                        |                                                                                                                                                                                                                       |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880253)               |                                                                                                                                                                                                                       |               |                     |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                                                       |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-73-102075        | No. 1 Engine - Sb BR700-73-102075 - Engine Fuel and Control - Fuel Temperature Transducer - Introduction of A New Duplex Fuel Temperature Transducer                                                                  |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                       |               | ENC                 |             |                 |     |                  |          |                    | 0       |              |
|                        |                                                                                                                                                                                                                       |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                                                                                                                                       |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880166)               |                                                                                                                                                                                                                       |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                                                       |               |                     |             |                 |     |                  |          |                    |         |              |

| ATA<br>U=Custom                              | Description                                                                                                                                                                                                           |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|----------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                                              | Part Number                                                                                                                                                                                                           | Serial Number |                     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position                             | HW                                                                                                                                                                                                                    | SW            |                     |             |                 |     |                  |             |                    |         | Manufacturer |
|                                              | MM Ref                                                                                                                                                                                                                |               |                     |             |                 |     |                  |             |                    |         | Date Type    |
|                                              | Ops Number(s)                                                                                                                                                                                                         |               |                     |             |                 |     |                  |             |                    |         |              |
| BR700-73-102075<br><br>(880166)<br>Engine    | No. 2 Engine - Sb BR700-73-102075 - Engine Fuel and Control - Fuel Temperature Transducer - Introduction of A New Duplex Fuel Temperature Transducer                                                                  |               | HRS                 |             |                 |     |                  |             |                    |         | 0            |
|                                              |                                                                                                                                                                                                                       |               | ENC                 |             |                 |     |                  |             |                    |         | 0            |
|                                              |                                                                                                                                                                                                                       |               | DATE                |             |                 |     |                  |             |                    |         |              |
|                                              |                                                                                                                                                                                                                       |               | MSC                 |             |                 |     | -                |             |                    |         |              |
|                                              |                                                                                                                                                                                                                       |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| BR700-73-102134<br>R02<br>(880185)<br>Engine | No. 1 Engine - Sb BR700-73-102134 R02 -                                                                                                                                                                               |               | HRS                 |             |                 |     |                  |             |                    |         | 0            |
|                                              |                                                                                                                                                                                                                       |               | ENC                 |             |                 |     |                  |             |                    |         | 0            |
|                                              |                                                                                                                                                                                                                       |               | DATE                |             |                 |     |                  |             |                    |         |              |
|                                              |                                                                                                                                                                                                                       |               | MSC                 |             |                 |     | -                |             |                    |         |              |
|                                              |                                                                                                                                                                                                                       |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| BR700-73-102134<br>R02<br>(880185)<br>Engine | No. 2 Engine - Sb BR700-73-102134 R02 -                                                                                                                                                                               |               | HRS                 |             |                 |     |                  |             |                    |         | 0            |
|                                              |                                                                                                                                                                                                                       |               | ENC                 |             |                 |     |                  |             |                    |         | 0            |
|                                              |                                                                                                                                                                                                                       |               | DATE                |             |                 |     |                  |             |                    |         |              |
|                                              |                                                                                                                                                                                                                       |               | MSC                 |             |                 |     | -                |             |                    |         |              |
|                                              |                                                                                                                                                                                                                       |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| BR700-73-102134<br>R03<br>(880251)<br>Engine | No. 1 Engine - BR700-73-102134 R03 - Engine Fuel and Control - Engine Electronic Controller (Eec) - Introduction of K9.0.1 Software Standard on an Eec With Hardware Standard G3010ECU01, Service Bulletin (Optional) |               | HRS                 |             |                 |     |                  |             |                    |         | 0            |
|                                              |                                                                                                                                                                                                                       |               | ENC                 |             |                 |     |                  |             |                    |         | 0            |
|                                              |                                                                                                                                                                                                                       |               | MOS                 |             | 29.4            |     |                  | 29 Nov 2023 |                    |         |              |
|                                              |                                                                                                                                                                                                                       |               | MSC                 |             |                 |     | -                |             |                    |         |              |
|                                              |                                                                                                                                                                                                                       |               |                     |             |                 |     |                  |             |                    |         |              |
| BR700-73-102134<br>R03<br>(880251)<br>Engine | No. 2 Engine - BR700-73-102134 R03 - Engine Fuel and Control - Engine Electronic Controller (Eec) - Introduction of K9.0.1 Software Standard on an Eec With Hardware Standard G3010ECU01, Service Bulletin (Optional) |               | HRS                 |             |                 |     |                  |             |                    |         | 0            |
|                                              |                                                                                                                                                                                                                       |               | ENC                 |             |                 |     |                  |             |                    |         | 0            |
|                                              |                                                                                                                                                                                                                       |               | MOS                 |             | 29.4            |     |                  | 29 Nov 2023 |                    |         |              |
|                                              |                                                                                                                                                                                                                       |               | MSC                 |             |                 |     | -                |             |                    |         |              |
|                                              |                                                                                                                                                                                                                       |               |                     |             |                 |     |                  |             |                    |         |              |
| BR700-73-102183<br><br>(880212)<br>Engine    | No. 1 Engine - Sb BR700-73-102183 - BR700-73-102183 - Engine Fuel and Control - Engine Electronic Controller (Eec) - Introduction of K10.1Software Standard on an Eec With Hardware Standard G3010ECU01               |               | HRS                 |             |                 |     |                  |             |                    |         | 0            |
|                                              |                                                                                                                                                                                                                       |               | ENC                 |             |                 |     |                  |             |                    |         | 0            |
|                                              |                                                                                                                                                                                                                       |               | DATE                |             |                 |     |                  |             |                    |         |              |
|                                              |                                                                                                                                                                                                                       |               | MSC                 |             |                 |     | -                |             |                    |         |              |
|                                              |                                                                                                                                                                                                                       |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |



| ATA<br>U=Custom        | Description                                                 |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------------|-------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                        | Part Number                                                 | Serial Number |                     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position       | HW                                                          | SW            |                     |             |                 |     |                  |             |                     |         | Manufacturer |
|                        | MM Ref                                                      |               |                     |             |                 |     |                  |             |                     |         | Date Type    |
|                        | Ops Number(s)                                               |               |                     |             |                 |     |                  |             |                     |         |              |
| BR700-73-102183        | No. 2 Engine - Sb BR700-73-102183 - BR700-73-102183         |               | HRS                 |             |                 |     |                  |             |                     |         | 0            |
|                        | - Engine Fuel and Control - Engine Electronic Controller    |               | ENC                 |             |                 |     |                  |             |                     |         | 0            |
|                        | (Eec) - Introduction of K10.1Software Standard on an Eec    |               | DATE                |             |                 |     |                  |             |                     |         |              |
|                        | With Hardware Standard G3010ECU01                           |               | MSC                 |             |                 |     | -                |             |                     |         |              |
| (880212)               |                                                             |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| Engine                 |                                                             |               |                     |             |                 |     |                  |             |                     |         |              |
| BR700-73-102183<br>R01 | No. 1 Engine - BR700-73-102183 R01 - Engine Fuel and        |               | HRS                 |             |                 |     |                  |             |                     |         | 0            |
|                        | Control - Engine Electronic Controller (Eec) - Introduction |               | ENC                 |             |                 |     |                  |             |                     |         | 0            |
|                        | of K10.1 Software Standard on an Eec With Hardware          |               | MOS                 |             | 29.4            |     |                  | 29 Nov 2023 |                     |         |              |
|                        | Standard G3010ECU01, Service Bulletin                       |               | MSC                 |             |                 |     | -                |             |                     |         |              |
| (880249)               |                                                             |               |                     |             |                 |     |                  |             |                     |         |              |
| Engine                 |                                                             |               |                     |             |                 |     |                  |             |                     |         |              |
| BR700-73-102183<br>R01 | No. 2 Engine - BR700-73-102183 R01 - Engine Fuel and        |               | HRS                 |             |                 |     |                  |             |                     |         | 0            |
|                        | Control - Engine Electronic Controller (Eec) - Introduction |               | ENC                 |             |                 |     |                  |             |                     |         | 0            |
|                        | of K10.1 Software Standard on an Eec With Hardware          |               | MOS                 |             | 29.4            |     |                  | 29 Nov 2023 |                     |         |              |
|                        | Standard G3010ECU01, Service Bulletin                       |               | MSC                 |             |                 |     | -                |             |                     |         |              |
| (880249)               |                                                             |               |                     |             |                 |     |                  |             |                     |         |              |
| Engine                 |                                                             |               |                     |             |                 |     |                  |             |                     |         |              |
| BR700-73-900009<br>R01 | No. 1 Engine - Sb BR700-73-900009 R01 - Engine Fuel         |               | HRS                 |             |                 |     |                  |             |                     |         | 0            |
|                        | and Control - Main Fuel Pump - Inspection of the V-Band     |               | ENC                 |             |                 |     |                  |             |                     |         | 0            |
|                        | Coupling Clamp - Non-Modification Service Bulletin          |               | DATE                |             |                 |     |                  |             |                     |         |              |
|                        |                                                             |               | MSC                 |             |                 |     | -                |             |                     |         |              |
| (880160)               |                                                             |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| Engine                 |                                                             |               |                     |             |                 |     |                  |             |                     |         |              |
| BR700-73-900009<br>R01 | No. 2 Engine - Sb BR700-73-900009 R01 - Engine Fuel         |               | HRS                 |             |                 |     |                  |             |                     |         | 0            |
|                        | and Control - Main Fuel Pump - Inspection of the V-Band     |               | ENC                 |             |                 |     |                  |             |                     |         | 0            |
|                        | Coupling Clamp - Non-Modification Service Bulletin          |               | DATE                |             |                 |     |                  |             |                     |         |              |
|                        |                                                             |               | MSC                 |             |                 |     | -                |             |                     |         |              |
| (880160)               |                                                             |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| Engine                 |                                                             |               |                     |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom           | Description                                                                                                                                                                                                                                           |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |   |
|---------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|----------|--------------------|---------|--------------|---|
|                           | Part Number                                                                                                                                                                                                                                           | Serial Number |                     |             |                 |     |                  |          |                    |         | Approx Price |   |
| Logbook Position          | HW                                                                                                                                                                                                                                                    | SW            |                     |             |                 |     |                  |          |                    |         | Manufacturer |   |
|                           | MM Ref                                                                                                                                                                                                                                                |               |                     |             |                 |     |                  |          |                    |         | Date Type    |   |
|                           | Ops Number(s)                                                                                                                                                                                                                                         |               |                     |             |                 |     |                  |          |                    |         |              |   |
| BR700-73-900141<br>PART A | No. 1 Engine - Sb BR700-73-900141 Part A - Engine Fuel and Control - External Fuel Distribution Tubes and Fittings - Inspection for the Correct Installation of the Fuel Low Pressure (Lp) Switch Sense Line Tube - Non-Modification Service Bulletin |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |   |
|                           |                                                                                                                                                                                                                                                       |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |   |
|                           |                                                                                                                                                                                                                                                       |               | DATE                |             |                 |     |                  |          |                    |         |              |   |
|                           |                                                                                                                                                                                                                                                       |               | MSC                 |             |                 |     | -                |          |                    |         |              |   |
|                           |                                                                                                                                                                                                                                                       |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |   |
| (880066)                  |                                                                                                                                                                                                                                                       |               |                     |             |                 |     |                  |          |                    |         |              |   |
| Engine                    |                                                                                                                                                                                                                                                       |               |                     |             |                 |     |                  |          |                    |         |              |   |
| BR700-73-900141<br>PART A | No. 2 Engine - Sb BR700-73-900141 Part A - Engine Fuel and Control - External Fuel Distribution Tubes and Fittings - Inspection for the Correct Installation of the Fuel Low Pressure (Lp) Switch Sense Line Tube - Non-Modification Service Bulletin |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |   |
|                           |                                                                                                                                                                                                                                                       |               | ENC                 |             |                 |     |                  |          |                    |         |              | 0 |
|                           |                                                                                                                                                                                                                                                       |               | DATE                |             |                 |     |                  |          |                    |         |              |   |
|                           |                                                                                                                                                                                                                                                       |               | MSC                 |             |                 |     | -                |          |                    |         |              |   |
|                           |                                                                                                                                                                                                                                                       |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |   |
| (880066)                  |                                                                                                                                                                                                                                                       |               |                     |             |                 |     |                  |          |                    |         |              |   |
| Engine                    |                                                                                                                                                                                                                                                       |               |                     |             |                 |     |                  |          |                    |         |              |   |
| BR700-73-900141<br>PART B | No. 1 Engine - Sb BR700-73-900141 Part B - Engine Fuel and Control - External Fuel Distribution Tubes and Fittings - Inspection for the Correct Installation of the Fuel Low Pressure (Lp) Switch Sense Line Tube - Non-Modification Service Bulletin |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |   |
|                           |                                                                                                                                                                                                                                                       |               | ENC                 |             |                 |     |                  |          |                    |         |              | 0 |
|                           |                                                                                                                                                                                                                                                       |               | DATE                |             |                 |     |                  |          |                    |         |              |   |
|                           |                                                                                                                                                                                                                                                       |               | MSC                 |             |                 |     | -                |          |                    |         |              |   |
|                           |                                                                                                                                                                                                                                                       |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |   |
| (880067)                  |                                                                                                                                                                                                                                                       |               |                     |             |                 |     |                  |          |                    |         |              |   |
| Engine                    |                                                                                                                                                                                                                                                       |               |                     |             |                 |     |                  |          |                    |         |              |   |
| BR700-73-900141<br>PART B | No. 2 Engine - Sb BR700-73-900141 Part B - Engine Fuel and Control - External Fuel Distribution Tubes and Fittings - Inspection for the Correct Installation of the Fuel Low Pressure (Lp) Switch Sense Line Tube - Non-Modification Service Bulletin |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |   |
|                           |                                                                                                                                                                                                                                                       |               | ENC                 |             |                 |     |                  |          |                    |         |              | 0 |
|                           |                                                                                                                                                                                                                                                       |               | DATE                |             |                 |     |                  |          |                    |         |              |   |
|                           |                                                                                                                                                                                                                                                       |               | MSC                 |             |                 |     | -                |          |                    |         |              |   |
|                           |                                                                                                                                                                                                                                                       |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |   |
| (880067)                  |                                                                                                                                                                                                                                                       |               |                     |             |                 |     |                  |          |                    |         |              |   |
| Engine                    |                                                                                                                                                                                                                                                       |               |                     |             |                 |     |                  |          |                    |         |              |   |
| BR700-73-900202<br>R01    | No. 1 Engine - Sb BR700-73-900202 R01 - Engine Fuel and Control and Oil - Fuel/Oil Temperature Transducer - Replacement of the Fuel/Oil Temperature Transducers - Non-Modification Service Bulletin                                                   |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |   |
|                           |                                                                                                                                                                                                                                                       |               | ENC                 |             |                 |     |                  |          |                    |         |              | 0 |
|                           |                                                                                                                                                                                                                                                       |               | DATE                |             |                 |     |                  |          |                    |         |              |   |
|                           |                                                                                                                                                                                                                                                       |               | MSC                 |             |                 |     | -                |          |                    |         |              |   |
|                           |                                                                                                                                                                                                                                                       |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |   |
| (880061)                  |                                                                                                                                                                                                                                                       |               |                     |             |                 |     |                  |          |                    |         |              |   |
| Engine                    |                                                                                                                                                                                                                                                       |               |                     |             |                 |     |                  |          |                    |         |              |   |

| ATA<br>U=Custom        | Description                                                                                                                                                                                                                                     |               | UOM  | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|------|-------------|-----------------|-----|------------------|----------|--------------------|---------|--------------|
|                        | Part Number                                                                                                                                                                                                                                     | Serial Number |      |             |                 |     |                  |          |                    |         | Approx Price |
| Logbook Position       | HW                                                                                                                                                                                                                                              | SW            |      |             |                 |     |                  |          |                    |         | Manufacturer |
|                        | MM Ref                                                                                                                                                                                                                                          |               |      |             |                 |     |                  |          |                    |         | Date Type    |
|                        | Ops Number(s)                                                                                                                                                                                                                                   |               |      |             |                 |     |                  |          |                    |         |              |
| BR700-73-900202<br>R01 | No. 2 Engine - Sb BR700-73-900202 R01 - Engine Fuel and Control and Oil - Fuel/Oil Temperature Transducer - Replacement of the Fuel/Oil Temperature Transducers - Non-Modification Service Bulletin                                             |               | HRS  |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                                                 |               | ENC  |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                                                 |               | DATE |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                                                                                                                                                                 |               | MSC  |             |                 |     | -                |          |                    |         |              |
| (880061)               | [End Of Month Item]                                                                                                                                                                                                                             |               |      |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                                                                                 |               |      |             |                 |     |                  |          |                    |         |              |
| BR700-73-900287        | No. 1 Engine - Sb BR700-73-900287 - Engine Fuel and Control - External Fuel Distribution Tubes and Fittings - Instruction to Test the Engine Following the Replacement of the Spill Return to Fuelpump Tube - Non-Modification Service Bulletin |               | HRS  |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                                                 |               | ENC  |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                                                 |               | DATE |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                                                                                                                                                                 |               | MSC  |             |                 |     | -                |          |                    |         |              |
| (880037)               | [End Of Month Item]                                                                                                                                                                                                                             |               |      |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                                                                                 |               |      |             |                 |     |                  |          |                    |         |              |
| BR700-73-900287        | No. 2 Engine - Sb BR700-73-900287 - Engine Fuel and Control - External Fuel Distribution Tubes and Fittings - Instruction to Test the Engine Following the Replacement of the Spill Return to Fuelpump Tube - Non-Modification Service Bulletin |               | HRS  |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                                                 |               | ENC  |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                                                 |               | DATE |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                                                                                                                                                                 |               | MSC  |             |                 |     | -                |          |                    |         |              |
| (880037)               | [End Of Month Item]                                                                                                                                                                                                                             |               |      |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                                                                                 |               |      |             |                 |     |                  |          |                    |         |              |
| BR700-73-900321<br>R02 | No. 1 Engine - Sb BR700-73-900321 R02 - Engine Fuel and Control - External Fuel Distribution Tubes and Fittings - Replacement of the Spill Return to Fuel Pump Tube - Non-Modification Service Bulletin                                         |               | HRS  |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                                                 |               | ENC  |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                                                 |               | DATE |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                                                                                                                                                                 |               | MSC  |             |                 |     | -                |          |                    |         |              |
| (880108)               | [End Of Month Item]                                                                                                                                                                                                                             |               |      |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                                                                                 |               |      |             |                 |     |                  |          |                    |         |              |
| BR700-73-900321<br>R02 | No. 2 Engine - Sb BR700-73-900321 R02 - Engine Fuel and Control - External Fuel Distribution Tubes and Fittings - Replacement of the Spill Return to Fuel Pump Tube - Non-Modification Service Bulletin                                         |               | HRS  |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                                                 |               | ENC  |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                                                 |               | DATE |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                                                                                                                                                                 |               | MSC  |             |                 |     | -                |          |                    |         |              |
| (880108)               | [End Of Month Item]                                                                                                                                                                                                                             |               |      |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                                                                                 |               |      |             |                 |     |                  |          |                    |         |              |

| ATA<br>U=Custom        | Description                                                                                                                                                                                |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|----------|--------------------|---------|--------------|
|                        | Part Number                                                                                                                                                                                | Serial Number |                     |             |                 |     |                  |          |                    |         | Approx Price |
| Logbook Position       | HW                                                                                                                                                                                         | SW            |                     |             |                 |     |                  |          |                    |         | Manufacturer |
|                        | MM Ref                                                                                                                                                                                     |               |                     |             |                 |     |                  |          |                    |         | Date Type    |
|                        | Ops Number(s)                                                                                                                                                                              |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-73-900608        | No. 1 Engine - Sb BR700-73-900608 - Engine Fuel and Control - Fuel Metering Unit (Fmu) - Replacement of the Fmu - Non-Modification Service Bulletin                                        |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                            |               | ENC                 |             |                 |     |                  |          |                    | 0       |              |
|                        |                                                                                                                                                                                            |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                                                                                                            |               | MSC                 |             |                 |     | ESV              |          |                    |         |              |
| (880137)               |                                                                                                                                                                                            |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                            |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-73-900608        | No. 2 Engine - Sb BR700-73-900608 - Engine Fuel and Control - Fuel Metering Unit (Fmu) - Replacement of the Fmu - Non-Modification Service Bulletin                                        |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                            |               | ENC                 |             |                 |     |                  |          |                    | 0       |              |
|                        |                                                                                                                                                                                            |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                                                                                                            |               | MSC                 |             |                 |     | ESV              |          |                    |         |              |
| (880137)               |                                                                                                                                                                                            |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                            |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-73-900636        | No. 1 Engine - Sb BR700-73-900636 - Engine Fuel and Control - Fuel Low Pressure (Lp) Switch - Replacement of the Fuel Lp Switch - Non-Modification Service Bulletin                        |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                            |               | ENC                 |             |                 |     |                  |          |                    | 0       |              |
|                        |                                                                                                                                                                                            |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                                                                                                            |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880150)               |                                                                                                                                                                                            |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                            |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-73-900636        | No. 2 Engine - Sb BR700-73-900636 - Engine Fuel and Control - Fuel Low Pressure (Lp) Switch - Replacement of the Fuel Lp Switch - Non-Modification Service Bulletin                        |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                            |               | ENC                 |             |                 |     |                  |          |                    | 0       |              |
|                        |                                                                                                                                                                                            |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                                                                                                            |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880150)               |                                                                                                                                                                                            |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                            |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-73-900662<br>R02 | No. 1 Engine - Sb BR700-73-900662 R02 - Engine Fuel and Control - Data Entry Plug (DEP) - RE-Configuration of the DEP Engine Pressure Ratio (Epr) Trim - Non-Modification Service Bulletin |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                            |               | ENC                 |             |                 |     |                  |          |                    | 0       |              |
|                        |                                                                                                                                                                                            |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                                                                                                            |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880190)               |                                                                                                                                                                                            |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                            |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-73-900662<br>R02 | No. 2 Engine - Sb BR700-73-900662 R02 - Engine Fuel and Control - Data Entry Plug (DEP) - RE-Configuration of the DEP Engine Pressure Ratio (Epr) Trim - Non-Modification Service Bulletin |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                            |               | ENC                 |             |                 |     |                  |          |                    | 0       |              |
|                        |                                                                                                                                                                                            |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                                                                                                            |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880190)               |                                                                                                                                                                                            |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                            |               |                     |             |                 |     |                  |          |                    |         |              |

| ATA<br>U=Custom          | Description                                                                                                                                                              |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|--------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                          | Part Number                                                                                                                                                              | Serial Number |                     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position         | HW                                                                                                                                                                       | SW            |                     |             |                 |     |                  |             |                    |         | Manufacturer |
|                          | MM Ref                                                                                                                                                                   |               |                     |             |                 |     |                  |             |                    |         | Date Type    |
|                          | Ops Number(s)                                                                                                                                                            |               |                     |             |                 |     |                  |             |                    |         |              |
| BR700-73-<br>A900258 R01 | No. 1 Engine - Sb BR700-73-A900258 R01 - Engine Fuel and Control - Fuel Manifold - Replacement of Non-Conforming Flexible Fuel Tubes - Non-Modification Service Bulletin |               | HRS                 |             |                 |     |                  |             |                    |         | 0            |
|                          |                                                                                                                                                                          |               | ENC                 |             |                 |     |                  |             |                    | 0       |              |
|                          |                                                                                                                                                                          |               | DATE                |             |                 |     |                  |             |                    |         |              |
|                          |                                                                                                                                                                          |               | MSC                 |             |                 |     | -                |             |                    |         |              |
| (880075)                 |                                                                                                                                                                          |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine                   |                                                                                                                                                                          |               |                     |             |                 |     |                  |             |                    |         |              |
| BR700-73-<br>A900258 R01 | No. 2 Engine - Sb BR700-73-A900258 R01 - Engine Fuel and Control - Fuel Manifold - Replacement of Non-Conforming Flexible Fuel Tubes - Non-Modification Service Bulletin |               | HRS                 |             |                 |     |                  |             |                    |         | 0            |
|                          |                                                                                                                                                                          |               | ENC                 |             |                 |     |                  |             |                    | 0       |              |
|                          |                                                                                                                                                                          |               | DATE                |             |                 |     |                  |             |                    |         |              |
|                          |                                                                                                                                                                          |               | MSC                 |             |                 |     | -                |             |                    |         |              |
| (880075)                 |                                                                                                                                                                          |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine                   |                                                                                                                                                                          |               |                     |             |                 |     |                  |             |                    |         |              |
| BR700-73-<br>A900309 R03 | No. 1 Engine - Sb BR700-73-A900309 R03 - Engine Fuel and Control - Fuel Metering Unit (Fmu) - Replacement of the Fmu - Non-Modification Service Bulletin                 |               | HRS                 |             |                 |     |                  |             |                    |         | 0            |
|                          |                                                                                                                                                                          |               | ENC                 |             |                 |     |                  |             |                    | 0       |              |
|                          |                                                                                                                                                                          |               | DATE                |             |                 |     |                  |             |                    |         |              |
|                          |                                                                                                                                                                          |               | MSC                 |             |                 |     | -                |             |                    |         |              |
| (880097)                 |                                                                                                                                                                          |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine                   |                                                                                                                                                                          |               |                     |             |                 |     |                  |             |                    |         |              |
| BR700-73-<br>A900309 R03 | No. 2 Engine - Sb BR700-73-A900309 R03 - Engine Fuel and Control - Fuel Metering Unit (Fmu) - Replacement of the Fmu - Non-Modification Service Bulletin                 |               | HRS                 |             |                 |     |                  |             |                    |         | 0            |
|                          |                                                                                                                                                                          |               | ENC                 |             |                 |     |                  |             |                    | 0       |              |
|                          |                                                                                                                                                                          |               | DATE                |             |                 |     |                  |             |                    |         |              |
|                          |                                                                                                                                                                          |               | MSC                 |             |                 |     | -                |             |                    |         |              |
| (880097)                 |                                                                                                                                                                          |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine                   |                                                                                                                                                                          |               |                     |             |                 |     |                  |             |                    |         |              |
| BR700-74-101762<br>R02   | No. 1 Engine - BR700-74-101762 R02 - Ignition - Igniter Plug - Introduction of Igniter Plugs With Silver Coated Threads, Service Bulletin (Optional)                     |               | HRS                 |             |                 |     |                  |             |                    |         | 0            |
|                          |                                                                                                                                                                          |               | ENC                 |             |                 |     |                  |             |                    | 0       |              |
|                          |                                                                                                                                                                          |               | MOS                 |             | 29.4            |     |                  | 29 Nov 2023 |                    |         |              |
|                          |                                                                                                                                                                          |               | MSC                 |             |                 |     | -                |             |                    |         |              |
| (880247)                 |                                                                                                                                                                          |               |                     |             |                 |     |                  |             |                    |         |              |
| Engine                   |                                                                                                                                                                          |               |                     |             |                 |     |                  |             |                    |         |              |
| BR700-74-101762<br>R02   | No. 2 Engine - BR700-74-101762 R02 - Ignition - Igniter Plug - Introduction of Igniter Plugs With Silver Coated Threads, Service Bulletin (Optional)                     |               | HRS                 |             |                 |     |                  |             |                    |         | 0            |
|                          |                                                                                                                                                                          |               | ENC                 |             |                 |     |                  |             |                    | 0       |              |
|                          |                                                                                                                                                                          |               | MOS                 |             | 29.4            |     |                  | 29 Nov 2023 |                    |         |              |
|                          |                                                                                                                                                                          |               | MSC                 |             |                 |     | -                |             |                    |         |              |
| (880247)                 |                                                                                                                                                                          |               |                     |             |                 |     |                  |             |                    |         |              |
| Engine                   |                                                                                                                                                                          |               |                     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom        | Description                                               |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------------|-----------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|--------------------|---------|--------------|
|                        | Part Number                                               | Serial Number |                     |             |                 |     |                  |             |                    |         | Approx Price |
| Logbook Position       | HW                                                        | SW            |                     |             |                 |     |                  |             |                    |         | Manufacturer |
|                        | MM Ref                                                    |               |                     |             |                 |     |                  |             |                    |         | Date Type    |
|                        | Ops Number(s)                                             |               |                     |             |                 |     |                  |             |                    |         |              |
| BR700-74-102002        | No. 1 Engine - Sb BR700-74-102002 - Ignition - Igniter    |               | HRS                 |             |                 |     |                  |             |                    |         | 0            |
|                        | Plug - Introduction of an Igniter Plug With Revised       |               | ENC                 |             |                 |     |                  |             |                    |         | 0            |
|                        | Semiconductorpellet Bonding                               |               | DATE                |             |                 |     |                  |             |                    |         |              |
|                        |                                                           |               | MSC                 |             |                 |     | -                |             |                    |         |              |
| (880147)               |                                                           |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine                 |                                                           |               |                     |             |                 |     |                  |             |                    |         |              |
| BR700-74-102002        | No. 2 Engine - Sb BR700-74-102002 - Ignition - Igniter    |               | HRS                 |             |                 |     |                  |             |                    |         | 0            |
|                        | Plug - Introduction of an Igniter Plug With Revised       |               | ENC                 |             |                 |     |                  |             |                    |         | 0            |
|                        | Semiconductorpellet Bonding                               |               | DATE                |             |                 |     |                  |             |                    |         |              |
|                        |                                                           |               | MSC                 |             |                 |     | -                |             |                    |         |              |
| (880147)               |                                                           |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine                 |                                                           |               |                     |             |                 |     |                  |             |                    |         |              |
| BR700-74-102002<br>R01 | No. 1 Engine - BR700-74-102002 R01 - Ignition - Igniter   |               | HRS                 |             |                 |     |                  |             |                    |         | 0            |
|                        | Plug - Introduction of an Igniter Plug With Revised       |               | ENC                 |             |                 |     |                  |             |                    |         | 0            |
|                        | Semiconductor Pellet Bonding, Service Bulletin (Optional) |               | MOS                 |             | 29.3            |     |                  | 01 Dec 2023 |                    |         |              |
|                        |                                                           |               | MSC                 |             |                 |     | -                |             |                    |         |              |
| (880245)               |                                                           |               |                     |             |                 |     |                  |             |                    |         |              |
| Engine                 |                                                           |               |                     |             |                 |     |                  |             |                    |         |              |
| BR700-74-102002<br>R01 | No. 2 Engine - BR700-74-102002 R01 - Ignition - Igniter   |               | HRS                 |             |                 |     |                  |             |                    |         | 0            |
|                        | Plug - Introduction of an Igniter Plug With Revised       |               | ENC                 |             |                 |     |                  |             |                    |         | 0            |
|                        | Semiconductor Pellet Bonding, Service Bulletin (Optional) |               | MOS                 |             | 29.3            |     |                  | 01 Dec 2023 |                    |         |              |
|                        |                                                           |               | MSC                 |             |                 |     | -                |             |                    |         |              |
| (880245)               |                                                           |               |                     |             |                 |     |                  |             |                    |         |              |
| Engine                 |                                                           |               |                     |             |                 |     |                  |             |                    |         |              |
| BR700-74-102003        | No. 1 Engine - Sb BR700-74-102003 - Ignition - Igniter    |               | HRS                 |             |                 |     |                  |             |                    |         | 0            |
|                        | Plug - Introduction of an Alternative Igniter Plug        |               | ENC                 |             |                 |     |                  |             |                    |         | 0            |
|                        | Manufactured By A Different Supplier                      |               | DATE                |             |                 |     |                  |             |                    |         |              |
|                        |                                                           |               | MSC                 |             |                 |     | -                |             |                    |         |              |
| (880173)               |                                                           |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine                 |                                                           |               |                     |             |                 |     |                  |             |                    |         |              |
| BR700-74-102003        | No. 2 Engine - Sb BR700-74-102003 - Ignition - Igniter    |               | HRS                 |             |                 |     |                  |             |                    |         | 0            |
|                        | Plug - Introduction of an Alternative Igniter Plug        |               | ENC                 |             |                 |     |                  |             |                    |         | 0            |
|                        | Manufactured By A Different Supplier                      |               | DATE                |             |                 |     |                  |             |                    |         |              |
|                        |                                                           |               | MSC                 |             |                 |     | -                |             |                    |         |              |
| (880173)               |                                                           |               | [End Of Month Item] |             |                 |     |                  |             |                    |         |              |
| Engine                 |                                                           |               |                     |             |                 |     |                  |             |                    |         |              |

| ATA<br>U=Custom        | Description                                                                                                                                                                     |               | UOM      | Times Since | Time<br>Accrued | Adj                 | Required<br>Freq | Last C/W    | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|----------|-------------|-----------------|---------------------|------------------|-------------|--------------------|---------|--------------|
|                        | Part Number                                                                                                                                                                     | Serial Number |          |             |                 |                     |                  |             |                    |         | Approx Price |
| Logbook Position       | HW                                                                                                                                                                              | SW            |          |             |                 |                     |                  |             |                    |         | Manufacturer |
|                        | MM Ref                                                                                                                                                                          |               |          |             |                 |                     |                  |             |                    |         | Date Type    |
|                        | Ops Number(s)                                                                                                                                                                   |               |          |             |                 |                     |                  |             |                    |         |              |
| BR700-74-102003<br>R01 | No. 1 Engine - Sb BR700-74-102003 R01 - Ignition - Igniter Plug - Introduction of an Alternative Igniter Plug Manufactured By A Different Supplier                              |               | HRS      |             |                 |                     |                  |             |                    |         | 0            |
|                        |                                                                                                                                                                                 |               | ENC      |             |                 |                     |                  |             |                    | 0       |              |
|                        |                                                                                                                                                                                 |               | DATE     |             |                 |                     |                  |             |                    |         |              |
|                        |                                                                                                                                                                                 |               | MSC      |             |                 |                     | -                |             |                    |         |              |
|                        |                                                                                                                                                                                 |               | (880184) |             |                 | [End Of Month Item] |                  |             |                    |         |              |
| Engine                 |                                                                                                                                                                                 |               |          |             |                 |                     |                  |             |                    |         |              |
| BR700-74-102003<br>R01 | No. 2 Engine - Sb BR700-74-102003 R01 - Ignition - Igniter Plug - Introduction of an Alternative Igniter Plug Manufactured By A Different Supplier                              |               | HRS      |             |                 |                     |                  |             |                    |         | 0            |
|                        |                                                                                                                                                                                 |               | ENC      |             |                 |                     |                  |             |                    | 0       |              |
|                        |                                                                                                                                                                                 |               | DATE     |             |                 |                     |                  |             |                    |         |              |
|                        |                                                                                                                                                                                 |               | MSC      |             |                 |                     | -                |             |                    |         |              |
|                        |                                                                                                                                                                                 |               | (880184) |             |                 | [End Of Month Item] |                  |             |                    |         |              |
| Engine                 |                                                                                                                                                                                 |               |          |             |                 |                     |                  |             |                    |         |              |
| BR700-74-102003<br>R02 | No. 1 Engine - Sb BR700-74-102003 R02 - Ignition - Igniter Plug - Introduction of an Alternative Igniter Plug Manufactured By A Different Supplier, Service Bulletin (Optional) |               | HRS      |             |                 |                     |                  |             |                    |         | 0            |
|                        |                                                                                                                                                                                 |               | ENC      |             |                 |                     |                  |             |                    | 0       |              |
|                        |                                                                                                                                                                                 |               | MOS      |             | 29.4            |                     |                  | 29 Nov 2023 |                    |         |              |
|                        |                                                                                                                                                                                 |               | MSC      |             |                 |                     | -                |             |                    |         |              |
|                        |                                                                                                                                                                                 |               | (880243) |             |                 |                     |                  |             |                    |         |              |
| Engine                 |                                                                                                                                                                                 |               |          |             |                 |                     |                  |             |                    |         |              |
| BR700-74-102003<br>R02 | No. 2 Engine - Sb BR700-74-102003 R02 - Ignition - Igniter Plug - Introduction of an Alternative Igniter Plug Manufactured By A Different Supplier, Service Bulletin (Optional) |               | HRS      |             |                 |                     |                  |             |                    |         | 0            |
|                        |                                                                                                                                                                                 |               | ENC      |             |                 |                     |                  |             |                    | 0       |              |
|                        |                                                                                                                                                                                 |               | MOS      |             | 29.4            |                     |                  | 29 Nov 2023 |                    |         |              |
|                        |                                                                                                                                                                                 |               | MSC      |             |                 |                     | -                |             |                    |         |              |
|                        |                                                                                                                                                                                 |               | (880243) |             |                 |                     |                  |             |                    |         |              |
| Engine                 |                                                                                                                                                                                 |               |          |             |                 |                     |                  |             |                    |         |              |
| BR700-74-102151        | No. 1 Engine - Sb BR700-74-102151 - Ignition - Igniter Plug - Definition of One Existing Igniter Plug as the Single Standard for Future Use                                     |               | HRS      |             |                 |                     |                  |             |                    |         | 0            |
|                        |                                                                                                                                                                                 |               | ENC      |             |                 |                     |                  |             |                    | 0       |              |
|                        |                                                                                                                                                                                 |               | DATE     |             |                 |                     |                  |             |                    |         |              |
|                        |                                                                                                                                                                                 |               | MSC      |             |                 |                     | -                |             |                    |         |              |
|                        |                                                                                                                                                                                 |               | (880192) |             |                 | [End Of Month Item] |                  |             |                    |         |              |
| Engine                 |                                                                                                                                                                                 |               |          |             |                 |                     |                  |             |                    |         |              |
| BR700-74-102151        | No. 2 Engine - Sb BR700-74-102151 - Ignition - Igniter Plug - Definition of One Existing Igniter Plug as the Single Standard for Future Use                                     |               | HRS      |             |                 |                     |                  |             |                    |         | 0            |
|                        |                                                                                                                                                                                 |               | ENC      |             |                 |                     |                  |             |                    | 0       |              |
|                        |                                                                                                                                                                                 |               | DATE     |             |                 |                     |                  |             |                    |         |              |
|                        |                                                                                                                                                                                 |               | MSC      |             |                 |                     | -                |             |                    |         |              |
|                        |                                                                                                                                                                                 |               | (880192) |             |                 | [End Of Month Item] |                  |             |                    |         |              |
| Engine                 |                                                                                                                                                                                 |               |          |             |                 |                     |                  |             |                    |         |              |

| ATA<br>U=Custom        | Description                                                                                                                                                                  |               | UOM  | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|------|-------------|-----------------|-----|------------------|----------|--------------------|---------|--------------|
|                        | Part Number                                                                                                                                                                  | Serial Number |      |             |                 |     |                  |          |                    |         | Approx Price |
| Logbook Position       | HW                                                                                                                                                                           | SW            |      |             |                 |     |                  |          |                    |         | Manufacturer |
|                        | MM Ref                                                                                                                                                                       |               |      |             |                 |     |                  |          |                    |         | Date Type    |
|                        | Ops Number(s)                                                                                                                                                                |               |      |             |                 |     |                  |          |                    |         |              |
| BR700-74-102151<br>R01 | No. 1 Engine - Sb BR700-74-102151 R01 - Ignition - Igniter Plug - Definition of One Existing Igniter Plug as the Single Standard for Future Use, Service Bulletin (Optional) |               | HRS  |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                              |               | ENC  |             |                 |     |                  |          |                    | 0       |              |
|                        |                                                                                                                                                                              |               | MOS  | 29.3        |                 |     | 01 Dec 2023      |          |                    |         |              |
|                        |                                                                                                                                                                              |               | MSC  |             |                 | -   |                  |          |                    |         |              |
| (880241)               |                                                                                                                                                                              |               |      |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                              |               |      |             |                 |     |                  |          |                    |         |              |
| BR700-74-102151<br>R01 | No. 2 Engine - Sb BR700-74-102151 R01 - Ignition - Igniter Plug - Definition of One Existing Igniter Plug as the Single Standard for Future Use, Service Bulletin (Optional) |               | HRS  |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                              |               | ENC  |             |                 |     |                  |          |                    | 0       |              |
|                        |                                                                                                                                                                              |               | MOS  | 29.3        |                 |     | 01 Dec 2023      |          |                    |         |              |
|                        |                                                                                                                                                                              |               | MSC  |             |                 | -   |                  |          |                    |         |              |
| (880241)               |                                                                                                                                                                              |               |      |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                              |               |      |             |                 |     |                  |          |                    |         |              |
| BR700-74-900166        | No. 1 Engine - Sb BR700-74-900166 - Ignition - Igniter Plug - Replacement of Non-Conforming Igniter Plugs - Non-Modification Service Bulletin                                |               | HRS  |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                              |               | ENC  |             |                 |     |                  |          |                    | 0       |              |
|                        |                                                                                                                                                                              |               | DATE |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                                                                                              |               | MSC  |             |                 | -   |                  |          |                    |         |              |
| (880060)               | [End Of Month Item]                                                                                                                                                          |               |      |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                              |               |      |             |                 |     |                  |          |                    |         |              |
| BR700-74-900166        | No. 2 Engine - Sb BR700-74-900166 - Ignition - Igniter Plug - Replacement of Non-Conforming Igniter Plugs - Non-Modification Service Bulletin                                |               | HRS  |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                              |               | ENC  |             |                 |     |                  |          |                    | 0       |              |
|                        |                                                                                                                                                                              |               | DATE |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                                                                                              |               | MSC  |             |                 | -   |                  |          |                    |         |              |
| (880060)               | [End Of Month Item]                                                                                                                                                          |               |      |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                              |               |      |             |                 |     |                  |          |                    |         |              |
| BR700-74-900568        | No. 1 Engine - Sb BR700-74-900568 - Ignition - High Energy Ignition Units - Replacement of Ignition Units - Non-Modification Service Bulletin                                |               | HRS  |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                              |               | ENC  |             |                 |     |                  |          |                    | 0       |              |
|                        |                                                                                                                                                                              |               | DATE |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                                                                                              |               | MSC  |             |                 | -   |                  |          |                    |         |              |
| (880093)               | [End Of Month Item]                                                                                                                                                          |               |      |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                              |               |      |             |                 |     |                  |          |                    |         |              |
| BR700-74-900568        | No. 2 Engine - Sb BR700-74-900568 - Ignition - High Energy Ignition Units - Replacement of Ignition Units - Non-Modification Service Bulletin                                |               | HRS  |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                              |               | ENC  |             |                 |     |                  |          |                    | 0       |              |
|                        |                                                                                                                                                                              |               | DATE |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                                                                                              |               | MSC  |             |                 | -   |                  |          |                    |         |              |
| (880093)               | [End Of Month Item]                                                                                                                                                          |               |      |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                              |               |      |             |                 |     |                  |          |                    |         |              |



| ATA<br>U=Custom                                      | Description                                                                                                                                                                                                     |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------------------------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|----------|--------------------|---------|--------------|
|                                                      | Part Number                                                                                                                                                                                                     | Serial Number |                     |             |                 |     |                  |          |                    |         | Approx Price |
| Logbook Position                                     | HW                                                                                                                                                                                                              | SW            |                     |             |                 |     |                  |          |                    |         | Manufacturer |
|                                                      | MM Ref                                                                                                                                                                                                          |               |                     |             |                 |     |                  |          |                    |         | Date Type    |
|                                                      | Ops Number(s)                                                                                                                                                                                                   |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-74-900594<br>R02<br><br>(880174)<br><br>Engine | No. 1 Engine - Sb BR700-74-900594 R02 - Ignition -<br>Igniter Plug - Replacement of the Igniter Plugs AT A<br>Specified Interval - Non-Modification Service Bulletin                                            |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                                                      |                                                                                                                                                                                                                 |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                                                      |                                                                                                                                                                                                                 |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                                                      |                                                                                                                                                                                                                 |               | MSC                 |             |                 |     | -                |          |                    |         |              |
|                                                      |                                                                                                                                                                                                                 |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| BR700-74-900594<br>R02<br><br>(880174)<br><br>Engine | No. 2 Engine - Sb BR700-74-900594 R02 - Ignition -<br>Igniter Plug - Replacement of the Igniter Plugs AT A<br>Specified Interval - Non-Modification Service Bulletin                                            |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                                                      |                                                                                                                                                                                                                 |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                                                      |                                                                                                                                                                                                                 |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                                                      |                                                                                                                                                                                                                 |               | MSC                 |             |                 |     | -                |          |                    |         |              |
|                                                      |                                                                                                                                                                                                                 |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| BR700-74-900649<br>R01<br><br>(880209)<br><br>Engine | No. 1 Engine - Sb BR700-74-900649 R01 - Ignition -<br>Igniter Plug - Inspection of the Igniter Plugs AT A Specified<br>Interval - Non-Modification Service Bulletin                                             |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                                                      |                                                                                                                                                                                                                 |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                                                      |                                                                                                                                                                                                                 |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                                                      |                                                                                                                                                                                                                 |               | MSC                 |             |                 |     | -                |          |                    |         |              |
|                                                      |                                                                                                                                                                                                                 |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| BR700-74-900649<br>R01<br><br>(880209)<br><br>Engine | No. 2 Engine - Sb BR700-74-900649 R01 - Ignition -<br>Igniter Plug - Inspection of the Igniter Plugs AT A Specified<br>Interval - Non-Modification Service Bulletin                                             |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                                                      |                                                                                                                                                                                                                 |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                                                      |                                                                                                                                                                                                                 |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                                                      |                                                                                                                                                                                                                 |               | MSC                 |             |                 |     | -                |          |                    |         |              |
|                                                      |                                                                                                                                                                                                                 |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| BR700-75-101704<br><br>(880011)<br><br>Engine        | No. 1 Engine - Sb BR700-75-101704 - AIR - AIR Bleed<br>Control Solenoid - Introduction of Washers With A Smaller<br>Outside Diameter for the Installation of the Handling Bleed<br>Valve Solenoid Control Block |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                                                      |                                                                                                                                                                                                                 |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                                                      |                                                                                                                                                                                                                 |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                                                      |                                                                                                                                                                                                                 |               | MSC                 |             |                 |     | -                |          |                    |         |              |
|                                                      |                                                                                                                                                                                                                 |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| BR700-75-101704<br><br>(880011)<br><br>Engine        | No. 2 Engine - Sb BR700-75-101704 - AIR - AIR Bleed<br>Control Solenoid - Introduction of Washers With A Smaller<br>Outside Diameter for the Installation of the Handling Bleed<br>Valve Solenoid Control Block |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                                                      |                                                                                                                                                                                                                 |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                                                      |                                                                                                                                                                                                                 |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                                                      |                                                                                                                                                                                                                 |               | MSC                 |             |                 |     | -                |          |                    |         |              |
|                                                      |                                                                                                                                                                                                                 |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |

| ATA<br>U=Custom        | Description                                                                                                                                                                                                                                                                  |               | UOM  | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|------|-------------|-----------------|-----|------------------|----------|--------------------|---------|--------------|
|                        | Part Number                                                                                                                                                                                                                                                                  | Serial Number |      |             |                 |     |                  |          |                    |         | Approx Price |
| Logbook Position       | HW                                                                                                                                                                                                                                                                           | SW            |      |             |                 |     |                  |          |                    |         | Manufacturer |
|                        | MM Ref                                                                                                                                                                                                                                                                       |               |      |             |                 |     |                  |          |                    |         | Date Type    |
|                        | Ops Number(s)                                                                                                                                                                                                                                                                |               |      |             |                 |     |                  |          |                    |         |              |
| BR700-75-101799<br>R01 | No. 1 Engine - Sb BR700-75-101799 R01 - AIR - Buffer<br>AIR Valve - Introduction of A New Buffer AIR Valve,<br>Changes to the HP4 AIR Tube and the HP2 Restrictor<br>Adapter and Introduction of A New Buffer AIR Valve<br>Setting Procedure, Service Bulletin (Recommended) |               | HRS  |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                                                                              |               | ENC  |             |                 |     |                  |          |                    | 0       |              |
|                        |                                                                                                                                                                                                                                                                              |               | MOS  | 29.2        |                 |     | 05 Dec 2023      |          |                    |         |              |
|                        |                                                                                                                                                                                                                                                                              |               | MSC  |             |                 | -   |                  |          |                    |         |              |
| (880239)               |                                                                                                                                                                                                                                                                              |               |      |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                                                                                                              |               |      |             |                 |     |                  |          |                    |         |              |
| BR700-75-101799<br>R01 | No. 2 Engine - Sb BR700-75-101799 R01 - AIR - Buffer<br>AIR Valve - Introduction of A New Buffer AIR Valve,<br>Changes to the HP4 AIR Tube and the HP2 Restrictor<br>Adapter and Introduction of A New Buffer AIR Valve<br>Setting Procedure, Service Bulletin (Recommended) |               | HRS  |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                                                                              |               | ENC  |             |                 |     |                  |          |                    | 0       |              |
|                        |                                                                                                                                                                                                                                                                              |               | MOS  | 29.2        |                 |     | 05 Dec 2023      |          |                    |         |              |
|                        |                                                                                                                                                                                                                                                                              |               | MSC  |             |                 | -   |                  |          |                    |         |              |
| (880239)               |                                                                                                                                                                                                                                                                              |               |      |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                                                                                                              |               |      |             |                 |     |                  |          |                    |         |              |
| BR700-75-101827        | No. 1 Engine - Sb BR700-75-101827 - AIR - Core AIR<br>Tubes and Fittings - Introduction of A Modified HP2<br>Restrictor Adapter With Increased Inner Diameter                                                                                                                |               | HRS  |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                                                                              |               | ENC  |             |                 |     |                  |          |                    | 0       |              |
|                        |                                                                                                                                                                                                                                                                              |               | DATE |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                                                                                                                                                                                              |               | MSC  |             |                 | -   |                  |          |                    |         |              |
| (880007)               |                                                                                                                                                                                                                                                                              |               |      |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                                                                                                              |               |      |             |                 |     |                  |          |                    |         |              |
| [End Of Month Item]    |                                                                                                                                                                                                                                                                              |               |      |             |                 |     |                  |          |                    |         |              |
| BR700-75-101827        | No. 2 Engine - Sb BR700-75-101827 - AIR - Core AIR<br>Tubes and Fittings - Introduction of A Modified HP2<br>Restrictor Adapter With Increased Inner Diameter                                                                                                                |               | HRS  |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                                                                              |               | ENC  |             |                 |     |                  |          |                    | 0       |              |
|                        |                                                                                                                                                                                                                                                                              |               | DATE |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                                                                                                                                                                                              |               | MSC  |             |                 | -   |                  |          |                    |         |              |
| (880007)               |                                                                                                                                                                                                                                                                              |               |      |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                                                                                                              |               |      |             |                 |     |                  |          |                    |         |              |
| [End Of Month Item]    |                                                                                                                                                                                                                                                                              |               |      |             |                 |     |                  |          |                    |         |              |
| BR700-75-101827<br>R01 | No. 1 Engine - Sb BR700-75-101827 R01 - AIR - Core<br>AIR Tubes and Fittings - Introduction of A Modified HP2<br>Restrictor Adapter With Increased Inner Diameter                                                                                                            |               | HRS  |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                                                                              |               | ENC  |             |                 |     |                  |          |                    | 0       |              |
|                        |                                                                                                                                                                                                                                                                              |               | DATE |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                                                                                                                                                                                              |               | MSC  |             |                 | -   |                  |          |                    |         |              |
| (880008)               |                                                                                                                                                                                                                                                                              |               |      |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                                                                                                              |               |      |             |                 |     |                  |          |                    |         |              |
| [End Of Month Item]    |                                                                                                                                                                                                                                                                              |               |      |             |                 |     |                  |          |                    |         |              |

| ATA<br>U=Custom        | Description                                                                                                                                                                      |               | UOM      | Times Since | Time<br>Accrued | Adj                 | Required<br>Freq | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|----------|-------------|-----------------|---------------------|------------------|----------|--------------------|---------|--------------|
|                        | Part Number                                                                                                                                                                      | Serial Number |          |             |                 |                     |                  |          |                    |         | Approx Price |
| Logbook Position       | HW                                                                                                                                                                               | SW            |          |             |                 |                     |                  |          |                    |         | Manufacturer |
|                        | MM Ref                                                                                                                                                                           |               |          |             |                 |                     |                  |          |                    |         | Date Type    |
|                        | Ops Number(s)                                                                                                                                                                    |               |          |             |                 |                     |                  |          |                    |         |              |
| BR700-75-101827<br>R01 | No. 2 Engine - Sb BR700-75-101827 R01 - AIR - Core<br>AIR Tubes and Fittings - Introduction of A Modified HP2<br>Restrictor Adapter With Increased Inner Diameter                |               | HRS      |             |                 |                     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                  |               | ENC      |             |                 |                     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                  |               | DATE     |             |                 |                     |                  |          |                    |         |              |
|                        |                                                                                                                                                                                  |               | MSC      |             |                 |                     | -                |          |                    |         |              |
|                        |                                                                                                                                                                                  |               | (880008) |             |                 | [End Of Month Item] |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                  |               |          |             |                 |                     |                  |          |                    |         |              |
| BR700-75-101827<br>R02 | No. 1 Engine - Sb BR700-75-101827 R02 - AIR - Core<br>AIR Tubes and Fittings - Introduction of A Modified HP2<br>Restrictor Adapter With Increased Inner Diameter                |               | HRS      |             |                 |                     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                  |               | ENC      |             |                 |                     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                  |               | DATE     |             |                 |                     |                  |          |                    |         |              |
|                        |                                                                                                                                                                                  |               | MSC      |             |                 |                     | -                |          |                    |         |              |
|                        |                                                                                                                                                                                  |               | (880021) |             |                 | [End Of Month Item] |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                  |               |          |             |                 |                     |                  |          |                    |         |              |
| BR700-75-101827<br>R02 | No. 2 Engine - Sb BR700-75-101827 R02 - AIR - Core<br>AIR Tubes and Fittings - Introduction of A Modified HP2<br>Restrictor Adapter With Increased Inner Diameter                |               | HRS      |             |                 |                     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                  |               | ENC      |             |                 |                     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                  |               | DATE     |             |                 |                     |                  |          |                    |         |              |
|                        |                                                                                                                                                                                  |               | MSC      |             |                 |                     | -                |          |                    |         |              |
|                        |                                                                                                                                                                                  |               | (880021) |             |                 | [End Of Month Item] |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                  |               |          |             |                 |                     |                  |          |                    |         |              |
| BR700-75-101831        | No. 1 Engine - Sb BR700-75-101831 - AIR - AIR Tubes<br>and Fittings - Deactivation of the Turbine Case Cooling<br>(TCC) System to Mitigate TCC Valve Reliability Concerns        |               | HRS      |             |                 |                     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                  |               | ENC      |             |                 |                     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                  |               | DATE     |             |                 |                     |                  |          |                    |         |              |
|                        |                                                                                                                                                                                  |               | MSC      |             |                 |                     | -                |          |                    |         |              |
|                        |                                                                                                                                                                                  |               | (880010) |             |                 | [End Of Month Item] |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                  |               |          |             |                 |                     |                  |          |                    |         |              |
| BR700-75-101831        | No. 2 Engine - Sb BR700-75-101831 - AIR - AIR Tubes<br>and Fittings - Deactivation of the Turbine Case Cooling<br>(TCC) System to Mitigate TCC Valve Reliability Concerns        |               | HRS      |             |                 |                     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                  |               | ENC      |             |                 |                     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                  |               | DATE     |             |                 |                     |                  |          |                    |         |              |
|                        |                                                                                                                                                                                  |               | MSC      |             |                 |                     | -                |          |                    |         |              |
|                        |                                                                                                                                                                                  |               | (880010) |             |                 | [End Of Month Item] |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                  |               |          |             |                 |                     |                  |          |                    |         |              |
| BR700-75-101831<br>R01 | No. 1 Engine - Sb BR700-75-101831 R01 - AIR - AIR<br>Tubes and Fittings - Deactivation of the Turbine Case<br>Cooling (TCC) System to Mitigate TCC Valve Reliability<br>Concerns |               | HRS      |             |                 |                     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                  |               | ENC      |             |                 |                     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                  |               | DATE     |             |                 |                     |                  |          |                    |         |              |
|                        |                                                                                                                                                                                  |               | MSC      |             |                 |                     | -                |          |                    |         |              |
|                        |                                                                                                                                                                                  |               | (880036) |             |                 | [End Of Month Item] |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                  |               |          |             |                 |                     |                  |          |                    |         |              |

| ATA<br>U=Custom        | Description                                                                                                                                                                                                   |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|----------|--------------------|---------|--------------|
|                        | Part Number                                                                                                                                                                                                   | Serial Number |                     |             |                 |     |                  |          |                    |         | Approx Price |
| Logbook Position       | HW                                                                                                                                                                                                            | SW            |                     |             |                 |     |                  |          |                    |         | Manufacturer |
|                        | MM Ref                                                                                                                                                                                                        |               |                     |             |                 |     |                  |          |                    |         | Date Type    |
|                        | Ops Number(s)                                                                                                                                                                                                 |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-75-101831<br>R01 | No. 2 Engine - Sb BR700-75-101831 R01 - AIR - AIR<br>Tubes and Fittings - Deactivation of the Turbine Case<br>Cooling (TCC) System to Mitigate TCC Valve Reliability<br>Concerns                              |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                               |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                               |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                                                                                                                               |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880036)               |                                                                                                                                                                                                               |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                                               |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-75-101831<br>R02 | No. 1 Engine - Sb BR700-75-101831 R02 - AIR - AIR<br>Tubes and Fittings - Deactivation of the Turbine Case<br>Cooling (TCC) System to Mitigate TCC Valve Reliability<br>Concerns, Service Bulletin (Optional) |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                               |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                               |               | MOS                 | 29.2        |                 |     | 05 Dec 2023      |          |                    |         |              |
|                        |                                                                                                                                                                                                               |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880237)               |                                                                                                                                                                                                               |               |                     |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                                               |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-75-101831<br>R02 | No. 2 Engine - Sb BR700-75-101831 R02 - AIR - AIR<br>Tubes and Fittings - Deactivation of the Turbine Case<br>Cooling (TCC) System to Mitigate TCC Valve Reliability<br>Concerns, Service Bulletin (Optional) |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                               |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                               |               | MOS                 | 29.2        |                 |     | 05 Dec 2023      |          |                    |         |              |
|                        |                                                                                                                                                                                                               |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880237)               |                                                                                                                                                                                                               |               |                     |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                                               |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-75-101844<br>R03 | No. 1 Engine - Sb BR700-75-101844 R03 - AIR - Buffer<br>AIR Valve - Introduction of A Revised Buffer AIR Valve, A<br>Revised HP2 Restrictor Adapter and A New Buffer AIR<br>Valve Setting Procedure           |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                               |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                               |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                                                                                                                               |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880062)               |                                                                                                                                                                                                               |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                                               |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-75-101844<br>R03 | No. 2 Engine - Sb BR700-75-101844 R03 - AIR - Buffer<br>AIR Valve - Introduction of A Revised Buffer AIR Valve, A<br>Revised HP2 Restrictor Adapter and A New Buffer AIR<br>Valve Setting Procedure           |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                               |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                               |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                                                                                                                               |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880062)               |                                                                                                                                                                                                               |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                                               |               |                     |             |                 |     |                  |          |                    |         |              |

| ATA<br>U=Custom        | Description                                                                                                                                                                                                                           |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W    | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|-------------|---------------------|---------|--------------|
|                        | Part Number                                                                                                                                                                                                                           | Serial Number |                     |             |                 |     |                  |             |                     |         | Approx Price |
| Logbook Position       | HW                                                                                                                                                                                                                                    | SW            |                     |             |                 |     |                  |             |                     |         | Manufacturer |
|                        | MM Ref                                                                                                                                                                                                                                |               |                     |             |                 |     |                  |             |                     |         | Date Type    |
|                        | Ops Number(s)                                                                                                                                                                                                                         |               |                     |             |                 |     |                  |             |                     |         |              |
| BR700-75-101918        | No. 1 Engine - Sb BR700-75-101918 - AIR - Turbine Case Cooling (TCC) Control Valve System and AIR Tubes and Fittings - Deletion of the TCC Control Valve System and Modification of Adjacent Components                               |               | HRS                 |             |                 |     |                  |             |                     |         | 0            |
|                        |                                                                                                                                                                                                                                       |               | ENC                 |             |                 |     |                  |             |                     | 0       |              |
|                        |                                                                                                                                                                                                                                       |               | DATE                |             |                 |     |                  |             |                     |         |              |
|                        |                                                                                                                                                                                                                                       |               | MSC                 |             |                 |     | -                |             |                     |         |              |
| (880102)               |                                                                                                                                                                                                                                       |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| Engine                 |                                                                                                                                                                                                                                       |               |                     |             |                 |     |                  |             |                     |         |              |
| BR700-75-101918        | No. 2 Engine - Sb BR700-75-101918 - AIR - Turbine Case Cooling (TCC) Control Valve System and AIR Tubes and Fittings - Deletion of the TCC Control Valve System and Modification of Adjacent Components                               |               | HRS                 |             |                 |     |                  |             |                     |         | 0            |
|                        |                                                                                                                                                                                                                                       |               | ENC                 |             |                 |     |                  |             |                     | 0       |              |
|                        |                                                                                                                                                                                                                                       |               | DATE                |             |                 |     |                  |             |                     |         |              |
|                        |                                                                                                                                                                                                                                       |               | MSC                 |             |                 |     | -                |             |                     |         |              |
| (880102)               |                                                                                                                                                                                                                                       |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| Engine                 |                                                                                                                                                                                                                                       |               |                     |             |                 |     |                  |             |                     |         |              |
| BR700-75-101918<br>R01 | No. 1 Engine - BR700-75-101918 R01 - AIR - Turbine Case Cooling (TCC) Control Valve System and AIR Tubes and Fittings - Deletion of the TCC Control Valve System and Modification of Adjacent Components, Service Bulletin (Optional) |               | HRS                 |             |                 |     |                  |             |                     |         | 0            |
|                        |                                                                                                                                                                                                                                       |               | ENC                 |             |                 |     |                  |             |                     | 0       |              |
|                        |                                                                                                                                                                                                                                       |               | MOS                 |             | 29.2            |     |                  | 05 Dec 2023 |                     |         |              |
|                        |                                                                                                                                                                                                                                       |               | MSC                 |             |                 |     | -                |             |                     |         |              |
| (880236)               |                                                                                                                                                                                                                                       |               |                     |             |                 |     |                  |             |                     |         |              |
| Engine                 |                                                                                                                                                                                                                                       |               |                     |             |                 |     |                  |             |                     |         |              |
| BR700-75-101918<br>R01 | No. 2 Engine - BR700-75-101918 R01 - AIR - Turbine Case Cooling (TCC) Control Valve System and AIR Tubes and Fittings - Deletion of the TCC Control Valve System and Modification of Adjacent Components, Service Bulletin (Optional) |               | HRS                 |             |                 |     |                  |             |                     |         | 0            |
|                        |                                                                                                                                                                                                                                       |               | ENC                 |             |                 |     |                  |             |                     | 0       |              |
|                        |                                                                                                                                                                                                                                       |               | MOS                 |             | 29.2            |     |                  | 05 Dec 2023 |                     |         |              |
|                        |                                                                                                                                                                                                                                       |               | MSC                 |             |                 |     | -                |             |                     |         |              |
| (880236)               |                                                                                                                                                                                                                                       |               |                     |             |                 |     |                  |             |                     |         |              |
| Engine                 |                                                                                                                                                                                                                                       |               |                     |             |                 |     |                  |             |                     |         |              |
| BR700-75-101972        | No. 1 Engine - Sb BR700-75-101972 - AIR - AIR Tubes and Fittings - Deletion of A Clamp Assembly from the High Pressure (Hp) Compressor Stage 8 Handling Bleed Valve AIR Tube                                                          |               | HRS                 |             |                 |     |                  |             |                     |         | 0            |
|                        |                                                                                                                                                                                                                                       |               | ENC                 |             |                 |     |                  |             |                     | 0       |              |
|                        |                                                                                                                                                                                                                                       |               | DATE                |             |                 |     |                  |             |                     |         |              |
|                        |                                                                                                                                                                                                                                       |               | MSC                 |             |                 |     | -                |             |                     |         |              |
| (880118)               |                                                                                                                                                                                                                                       |               | [End Of Month Item] |             |                 |     |                  |             |                     |         |              |
| Engine                 |                                                                                                                                                                                                                                       |               |                     |             |                 |     |                  |             |                     |         |              |

| ATA<br>U=Custom        | Description                                                                                                                                                                                                                                 |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------------|---------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|----------|--------------------|---------|--------------|
|                        | Part Number                                                                                                                                                                                                                                 | Serial Number |                     |             |                 |     |                  |          |                    |         | Approx Price |
| Logbook Position       | HW                                                                                                                                                                                                                                          | SW            |                     |             |                 |     |                  |          |                    |         | Manufacturer |
|                        | MM Ref                                                                                                                                                                                                                                      |               |                     |             |                 |     |                  |          |                    |         | Date Type    |
|                        | Ops Number(s)                                                                                                                                                                                                                               |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-75-101972        | No. 2 Engine - Sb BR700-75-101972 - AIR - AIR Tubes and Fittings - Deletion of A Clamp Assembly from the High Pressure (Hp) Compressor Stage 8 Handling Bleed Valve AIR Tube                                                                |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                                             |               | ENC                 |             |                 |     |                  |          |                    | 0       |              |
|                        |                                                                                                                                                                                                                                             |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                                                                                                                                                             |               | MSC                 |             |                 | -   |                  |          |                    |         |              |
| (880118)               |                                                                                                                                                                                                                                             |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                                                                             |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-75-101999        | No. 1 Engine - Sb BR700-75-101999 - AIR - AIR Bleed Control Solenoid - Introduction of A Revised Handling Bleed Valve Solenoid Control Block Without A Control Valve for the Turbine Case Cooling (TCC) Valve                               |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                                             |               | ENC                 |             |                 |     |                  |          |                    | 0       |              |
|                        |                                                                                                                                                                                                                                             |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                                                                                                                                                             |               | MSC                 |             |                 | -   |                  |          |                    |         |              |
| (880161)               |                                                                                                                                                                                                                                             |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                                                                             |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-75-101999        | No. 2 Engine - Sb BR700-75-101999 - AIR - AIR Bleed Control Solenoid - Introduction of A Revised Handling Bleed Valve Solenoid Control Block Without A Control Valve for the Turbine Case Cooling (TCC) Valve                               |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                                             |               | ENC                 |             |                 |     |                  |          |                    | 0       |              |
|                        |                                                                                                                                                                                                                                             |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                                                                                                                                                             |               | MSC                 |             |                 | -   |                  |          |                    |         |              |
| (880161)               |                                                                                                                                                                                                                                             |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                                                                             |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-75-101999<br>R01 | No. 1 Engine - BR700-75-101999 R01 - AIR - AIR Bleed Control Solenoid - Introduction of A Revised Handling Bleed Valve Solenoid Control Block Without A Control Valve for the Turbine Case Cooling (TCC) Valve, Service Bulletin (Optional) |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                                             |               | ENC                 |             |                 |     |                  |          |                    | 0       |              |
|                        |                                                                                                                                                                                                                                             |               | MOS                 | 29.2        |                 |     | 05 Dec 2023      |          |                    |         |              |
|                        |                                                                                                                                                                                                                                             |               | MSC                 |             |                 | -   |                  |          |                    |         |              |
| (880233)               |                                                                                                                                                                                                                                             |               |                     |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                                                                             |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-75-101999<br>R01 | No. 2 Engine - BR700-75-101999 R01 - AIR - AIR Bleed Control Solenoid - Introduction of A Revised Handling Bleed Valve Solenoid Control Block Without A Control Valve for the Turbine Case Cooling (TCC) Valve, Service Bulletin (Optional) |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                                             |               | ENC                 |             |                 |     |                  |          |                    | 0       |              |
|                        |                                                                                                                                                                                                                                             |               | MOS                 | 29.2        |                 |     | 05 Dec 2023      |          |                    |         |              |
|                        |                                                                                                                                                                                                                                             |               | MSC                 |             |                 | -   |                  |          |                    |         |              |
| (880233)               |                                                                                                                                                                                                                                             |               |                     |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                                                                             |               |                     |             |                 |     |                  |          |                    |         |              |

| ATA<br>U=Custom        | Description                                                            |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------------|------------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|----------|--------------------|---------|--------------|
|                        | Part Number                                                            | Serial Number |                     |             |                 |     |                  |          |                    |         | Approx Price |
| Logbook Position       | HW                                                                     | SW            |                     |             |                 |     |                  |          |                    |         | Manufacturer |
|                        | MM Ref                                                                 |               |                     |             |                 |     |                  |          |                    |         | Date Type    |
|                        | Ops Number(s)                                                          |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-75-102127        | No. 1 Engine - Sb BR700-75-102127 - AIR - AIR Bleed                    |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        | Control Valve and Stand Pipe - Introduction of High                    |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                        | Pressure (Hp) Compressor Handling Bleed Valves (Hbv)                   |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                        | With Changed Material for the Carbon Bush and the Triple Seal Assembly |               | MSC                 |             |                 |     | -                |          |                    |         |              |
|                        |                                                                        |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| (880196)               |                                                                        |               |                     |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                        |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-75-102127        | No. 2 Engine - Sb BR700-75-102127 - AIR - AIR Bleed                    |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        | Control Valve and Stand Pipe - Introduction of High                    |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                        | Pressure (Hp) Compressor Handling Bleed Valves (Hbv)                   |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                        | With Changed Material for the Carbon Bush and the Triple Seal Assembly |               | MSC                 |             |                 |     | -                |          |                    |         |              |
|                        |                                                                        |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| (880196)               |                                                                        |               |                     |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                        |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-75-102133        | No. 1 Engine - Sb BR700-75-102133 - AIR - High                         |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        | Pressure (Hp) Compressor Variable Vanes and Nozzle                     |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                        | Actuators - Introduction of Spare Parts for the Variable               |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                        | Stator Vane (Vsv) Actuator                                             |               | MSC                 |             |                 |     | -                |          |                    |         |              |
|                        |                                                                        |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| (880183)               |                                                                        |               |                     |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                        |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-75-102133        | No. 2 Engine - Sb BR700-75-102133 - AIR - High                         |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        | Pressure (Hp) Compressor Variable Vanes and Nozzle                     |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                        | Actuators - Introduction of Spare Parts for the Variable               |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                        | Stator Vane (Vsv) Actuator                                             |               | MSC                 |             |                 |     | -                |          |                    |         |              |
|                        |                                                                        |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| (880183)               |                                                                        |               |                     |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                        |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-75-900383<br>R01 | No. 1 Engine - Sb BR700-75-900383 R01 - AIR - Buffer                   |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        | AIR Valve - Visual Inspection and Readjustment of the                  |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                        | Buffer AIR Valve Tie-ROD Assembly - Non-Modification                   |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                        | Service Bulletin                                                       |               | MSC                 |             |                 |     | -                |          |                    |         |              |
|                        |                                                                        |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| (880040)               |                                                                        |               |                     |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                        |               |                     |             |                 |     |                  |          |                    |         |              |

| ATA<br>U=Custom           | Description                                                                                                                                                                                                                                        |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|---------------------------|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|----------|--------------------|---------|--------------|
|                           | Part Number                                                                                                                                                                                                                                        | Serial Number |                     |             |                 |     |                  |          |                    |         | Approx Price |
| Logbook Position          | HW                                                                                                                                                                                                                                                 | SW            |                     |             |                 |     |                  |          |                    |         | Manufacturer |
|                           | MM Ref                                                                                                                                                                                                                                             |               |                     |             |                 |     |                  |          |                    |         | Date Type    |
|                           | Ops Number(s)                                                                                                                                                                                                                                      |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-75-900383<br>R01    | No. 2 Engine - Sb BR700-75-900383 R01 - AIR - Buffer<br>AIR Valve - Visual Inspection and Readjustment of the<br>Buffer AIR Valve Tie-ROD Assembly - Non-Modification<br>Service Bulletin                                                          |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                           |                                                                                                                                                                                                                                                    |               | ENC                 |             |                 |     |                  |          |                    | 0       |              |
|                           |                                                                                                                                                                                                                                                    |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                           |                                                                                                                                                                                                                                                    |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880040)                  |                                                                                                                                                                                                                                                    |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine                    |                                                                                                                                                                                                                                                    |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-75-900655<br>PART A | No. 1 Engine - Sb BR700-75-900655 Part A - AIR -<br>Handling Bleed Vavle - Inspection of Bleed Vavle AT High<br>Pressure (Hp) Copmpressor Stage 5 and Stage 8 for<br>Deposities on the Inner Piston Surface - Non-Modification<br>Service Bulletin |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                           |                                                                                                                                                                                                                                                    |               | ENC                 |             |                 |     |                  |          |                    | 0       |              |
|                           |                                                                                                                                                                                                                                                    |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                           |                                                                                                                                                                                                                                                    |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880186)                  |                                                                                                                                                                                                                                                    |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine                    |                                                                                                                                                                                                                                                    |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-75-900655<br>PART A | No. 2 Engine - Sb BR700-75-900655 Part A - AIR -<br>Handling Bleed Vavle - Inspection of Bleed Vavle AT High<br>Pressure (Hp) Copmpressor Stage 5 and Stage 8 for<br>Deposities on the Inner Piston Surface - Non-Modification<br>Service Bulletin |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                           |                                                                                                                                                                                                                                                    |               | ENC                 |             |                 |     |                  |          |                    | 0       |              |
|                           |                                                                                                                                                                                                                                                    |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                           |                                                                                                                                                                                                                                                    |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880186)                  |                                                                                                                                                                                                                                                    |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine                    |                                                                                                                                                                                                                                                    |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-75-900655<br>PART B | No. 1 Engine - Sb BR700-75-900655 Part B - AIR -<br>Handling Bleed Vavle - Inspection of Bleed Vavle AT High<br>Pressure (Hp) Copmpressor Stage 5 and Stage 8 for<br>Deposities on the Inner Piston Surface - Non-Modification<br>Service Bulletin |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                           |                                                                                                                                                                                                                                                    |               | ENC                 |             |                 |     |                  |          |                    | 0       |              |
|                           |                                                                                                                                                                                                                                                    |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                           |                                                                                                                                                                                                                                                    |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880187)                  |                                                                                                                                                                                                                                                    |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine                    |                                                                                                                                                                                                                                                    |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-75-900655<br>PART B | No. 2 Engine - Sb BR700-75-900655 Part B - AIR -<br>Handling Bleed Vavle - Inspection of Bleed Vavle AT High<br>Pressure (Hp) Copmpressor Stage 5 and Stage 8 for<br>Deposities on the Inner Piston Surface - Non-Modification<br>Service Bulletin |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                           |                                                                                                                                                                                                                                                    |               | ENC                 |             |                 |     |                  |          |                    | 0       |              |
|                           |                                                                                                                                                                                                                                                    |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                           |                                                                                                                                                                                                                                                    |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880187)                  |                                                                                                                                                                                                                                                    |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine                    |                                                                                                                                                                                                                                                    |               |                     |             |                 |     |                  |          |                    |         |              |



| ATA<br>U=Custom           | Description                                               |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |  |
|---------------------------|-----------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|----------|--------------------|---------|--------------|--|
|                           | Part Number                                               | Serial Number |                     |             |                 |     |                  |          |                    |         | Approx Price |  |
| Logbook Position          | HW                                                        | SW            |                     |             |                 |     |                  |          |                    |         | Manufacturer |  |
|                           | MM Ref                                                    |               |                     |             |                 |     |                  |          |                    |         | Date Type    |  |
|                           | Ops Number(s)                                             |               |                     |             |                 |     |                  |          |                    |         |              |  |
| BR700-75-900655<br>PART C | No. 1 Engine - Sb BR700-75-900655 Part C - AIR -          |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |  |
|                           | Handling Bleed Vavle - Inspection of Bleed Vavle AT High  |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |  |
|                           | Pressure (Hp) Copmpressor Stage 5 and Stage 8 for         |               | DATE                |             |                 |     |                  |          |                    |         |              |  |
|                           | Deposities on the Inner Piston Surface - Non-Modification |               | MSC                 |             |                 |     |                  |          |                    |         |              |  |
|                           | Service Bulletin                                          |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |  |
| (880188)                  |                                                           |               |                     |             |                 |     |                  |          |                    |         |              |  |
| Engine                    |                                                           |               |                     |             |                 |     |                  |          |                    |         |              |  |
| BR700-75-900655<br>PART C | No. 2 Engine - Sb BR700-75-900655 Part C - AIR -          |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |  |
|                           | Handling Bleed Vavle - Inspection of Bleed Vavle AT High  |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |  |
|                           | Pressure (Hp) Copmpressor Stage 5 and Stage 8 for         |               | DATE                |             |                 |     |                  |          |                    |         |              |  |
|                           | Deposities on the Inner Piston Surface - Non-Modification |               | MSC                 |             |                 |     |                  |          |                    |         |              |  |
|                           | Service Bulletin                                          |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |  |
| (880188)                  |                                                           |               |                     |             |                 |     |                  |          |                    |         |              |  |
| Engine                    |                                                           |               |                     |             |                 |     |                  |          |                    |         |              |  |
| BR700-75-900655<br>PART D | No. 1 Engine - Sb BR700-75-900655 Part D - AIR -          |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |  |
|                           | Handling Bleed Vavle - Inspection of Bleed Vavle AT High  |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |  |
|                           | Pressure (Hp) Copmpressor Stage 5 and Stage 8 for         |               | DATE                |             |                 |     |                  |          |                    |         |              |  |
|                           | Deposities on the Inner Piston Surface - Non-Modification |               | MSC                 |             |                 |     |                  |          |                    |         |              |  |
|                           | Service Bulletin                                          |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |  |
| (880189)                  |                                                           |               |                     |             |                 |     |                  |          |                    |         |              |  |
| Engine                    |                                                           |               |                     |             |                 |     |                  |          |                    |         |              |  |
| BR700-75-900655<br>PART D | No. 2 Engine - Sb BR700-75-900655 Part D - AIR -          |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |  |
|                           | Handling Bleed Vavle - Inspection of Bleed Vavle AT High  |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |  |
|                           | Pressure (Hp) Copmpressor Stage 5 and Stage 8 for         |               | DATE                |             |                 |     |                  |          |                    |         |              |  |
|                           | Deposities on the Inner Piston Surface - Non-Modification |               | MSC                 |             |                 |     |                  |          |                    |         |              |  |
|                           | Service Bulletin                                          |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |  |
| (880189)                  |                                                           |               |                     |             |                 |     |                  |          |                    |         |              |  |
| Engine                    |                                                           |               |                     |             |                 |     |                  |          |                    |         |              |  |

| ATA<br>U=Custom        | Description                                                                                                                                         |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------------|-----------------------------------------------------------------------------------------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|----------|--------------------|---------|--------------|
|                        | Part Number                                                                                                                                         | Serial Number |                     |             |                 |     |                  |          |                    |         | Approx Price |
| Logbook Position       | HW                                                                                                                                                  | SW            |                     |             |                 |     |                  |          |                    |         | Manufacturer |
|                        | MM Ref                                                                                                                                              |               |                     |             |                 |     |                  |          |                    |         | Date Type    |
|                        | Ops Number(s)                                                                                                                                       |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-75-900673<br>R03 | No. 1 Engine - Sb BR700-75-900673 R03 - Sb BR700-75-900673 R03 - AIR - AIR Bleed Control Valve and Stand                                            |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        | Pipe - Replacement of Stage 5 High Pressure (Hp)                                                                                                    |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                        | Compressor Handling Bleed Valves (Hbv) - Non-                                                                                                       |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                        | Modification Service Bulletin (This Nmsb Sb-BR700-75-900673 Is No Longer Required and Can Be Closed)                                                |               | MSC                 |             |                 |     | -                |          |                    |         |              |
|                        |                                                                                                                                                     |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| (880214)               |                                                                                                                                                     |               |                     |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                     |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-75-900673<br>R03 | No. 2 Engine - Sb BR700-75-900673 R03 - Sb BR700-75-900673 R03 - AIR - AIR Bleed Control Valve and Stand                                            |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        | Pipe - Replacement of Stage 5 High Pressure (Hp)                                                                                                    |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                        | Compressor Handling Bleed Valves (Hbv) - Non-                                                                                                       |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                        | Modification Service Bulletin (This Nmsb Sb-BR700-75-900673 Is No Longer Required and Can Be Closed)                                                |               | MSC                 |             |                 |     | -                |          |                    |         |              |
|                        |                                                                                                                                                     |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| (880214)               |                                                                                                                                                     |               |                     |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                     |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-77-101866<br>R01 | No. 1 Engine - Sb BR700-77-101866 R01 - Engine Indicating - Nh Speed Signal Attenuating Plug - Introduction of A Nh 1/Rev Signal Attenuating Plug   |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                     |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                     |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                                                                     |               | MSC                 |             |                 |     | -                |          |                    |         |              |
|                        |                                                                                                                                                     |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| (880151)               |                                                                                                                                                     |               |                     |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                     |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-77-101866<br>R01 | No. 2 Engine - Sb BR700-77-101866 R01 - Engine Indicating - Nh Speed Signal Attenuating Plug - Introduction of A Nh 1/Rev Signal Attenuating Plug   |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                     |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                     |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                                                                     |               | MSC                 |             |                 |     | -                |          |                    |         |              |
|                        |                                                                                                                                                     |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| (880151)               |                                                                                                                                                     |               |                     |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                     |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-77-102159        | No. 1 Engine - Sb BR700-77-102159 - Engine Indicating - Oil FIRE Detection Thermocouple - Introduction of A New Turbine Oil FIRE (TOF) Thermocouple |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                     |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                     |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                                                                     |               | MSC                 |             |                 |     | -                |          |                    |         |              |
|                        |                                                                                                                                                     |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| (880201)               |                                                                                                                                                     |               |                     |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                     |               |                     |             |                 |     |                  |          |                    |         |              |

| ATA<br>U=Custom  | Description                                                                                                                                                                                                             |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|----------|--------------------|---------|--------------|
|                  | Part Number                                                                                                                                                                                                             | Serial Number |                     |             |                 |     |                  |          |                    |         | Approx Price |
| Logbook Position | HW                                                                                                                                                                                                                      | SW            |                     |             |                 |     |                  |          |                    |         | Manufacturer |
|                  | MM Ref                                                                                                                                                                                                                  |               |                     |             |                 |     |                  |          |                    |         | Date Type    |
|                  | Ops Number(s)                                                                                                                                                                                                           |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-77-102159  | No. 2 Engine - Sb BR700-77-102159 - Engine Indicating - Oil FIRE Detection Thermocouple - Introduction of A New Turbine Oil FIRE (TOF) Thermocouple                                                                     |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                  |                                                                                                                                                                                                                         |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                  |                                                                                                                                                                                                                         |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                  |                                                                                                                                                                                                                         |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880201)         |                                                                                                                                                                                                                         |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine           |                                                                                                                                                                                                                         |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-77-102160  | No. 1 Engine - Sb BR700-77-102160 - Engine Indicating - Turbine Gas Temperature Thermocouple - Introduction of New Turbine Gas Temperature (Tgt) Probes                                                                 |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                  |                                                                                                                                                                                                                         |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                  |                                                                                                                                                                                                                         |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                  |                                                                                                                                                                                                                         |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880202)         |                                                                                                                                                                                                                         |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine           |                                                                                                                                                                                                                         |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-77-102160  | No. 2 Engine - Sb BR700-77-102160 - Engine Indicating - Turbine Gas Temperature Thermocouple - Introduction of New Turbine Gas Temperature (Tgt) Probes                                                                 |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                  |                                                                                                                                                                                                                         |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                  |                                                                                                                                                                                                                         |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                  |                                                                                                                                                                                                                         |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880202)         |                                                                                                                                                                                                                         |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine           |                                                                                                                                                                                                                         |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-77-900176  | No. 1 Engine - Sb BR700-77-900176 - Engine Indicating - Oil FIRE Detection Thermocouple - Replacement of the Turbine Oil FIRE (TOF) Thermocouple and the Oil FIRE Detection Adapter - Non-Modification Service Bulletin |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                  |                                                                                                                                                                                                                         |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                  |                                                                                                                                                                                                                         |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                  |                                                                                                                                                                                                                         |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880064)         |                                                                                                                                                                                                                         |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine           |                                                                                                                                                                                                                         |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-77-900176  | No. 2 Engine - Sb BR700-77-900176 - Engine Indicating - Oil FIRE Detection Thermocouple - Replacement of the Turbine Oil FIRE (TOF) Thermocouple and the Oil FIRE Detection Adapter - Non-Modification Service Bulletin |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                  |                                                                                                                                                                                                                         |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                  |                                                                                                                                                                                                                         |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                  |                                                                                                                                                                                                                         |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880064)         |                                                                                                                                                                                                                         |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine           |                                                                                                                                                                                                                         |               |                     |             |                 |     |                  |          |                    |         |              |

| ATA<br>U=Custom        | Description                                                                                                                                                                                                                         |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*=Adj) | Max Due | Avg Man Hrs  |
|------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|----------|---------------------|---------|--------------|
|                        | Part Number                                                                                                                                                                                                                         | Serial Number |                     |             |                 |     |                  |          |                     |         | Approx Price |
| Logbook Position       | HW                                                                                                                                                                                                                                  | SW            |                     |             |                 |     |                  |          |                     |         | Manufacturer |
|                        | MM Ref                                                                                                                                                                                                                              |               |                     |             |                 |     |                  |          |                     |         | Date Type    |
|                        | Ops Number(s)                                                                                                                                                                                                                       |               |                     |             |                 |     |                  |          |                     |         |              |
| BR700-78-900332<br>R02 | No. 1 Engine - Sb BR700-78-900332 R02 - Exhaust - Thrust Reverser Unit (Tru) - Leak Check With Subsequent RE-Torque of the Direction Control Unit (Dcu) Double Ended Unions and Attached B-Nuts - Non-Modification Service Bulletin |               | HRS                 |             |                 |     |                  |          |                     |         | 0            |
|                        |                                                                                                                                                                                                                                     |               | ENC                 |             |                 |     |                  |          |                     |         | 0            |
|                        |                                                                                                                                                                                                                                     |               | DATE                |             |                 |     |                  |          |                     |         |              |
|                        |                                                                                                                                                                                                                                     |               | MSC                 |             |                 |     | -                |          |                     |         |              |
|                        |                                                                                                                                                                                                                                     |               | [End Of Month Item] |             |                 |     |                  |          |                     |         |              |
| (880191)               |                                                                                                                                                                                                                                     |               |                     |             |                 |     |                  |          |                     |         |              |
| Engine                 |                                                                                                                                                                                                                                     |               |                     |             |                 |     |                  |          |                     |         |              |
| BR700-78-900332<br>R02 | No. 2 Engine - Sb BR700-78-900332 R02 - Exhaust - Thrust Reverser Unit (Tru) - Leak Check With Subsequent RE-Torque of the Direction Control Unit (Dcu) Double Ended Unions and Attached B-Nuts - Non-Modification Service Bulletin |               | HRS                 |             |                 |     |                  |          |                     |         | 0            |
|                        |                                                                                                                                                                                                                                     |               | ENC                 |             |                 |     |                  |          |                     |         | 0            |
|                        |                                                                                                                                                                                                                                     |               | DATE                |             |                 |     |                  |          |                     |         |              |
|                        |                                                                                                                                                                                                                                     |               | MSC                 |             |                 |     | -                |          |                     |         |              |
|                        |                                                                                                                                                                                                                                     |               | [End Of Month Item] |             |                 |     |                  |          |                     |         |              |
| (880191)               |                                                                                                                                                                                                                                     |               |                     |             |                 |     |                  |          |                     |         |              |
| Engine                 |                                                                                                                                                                                                                                     |               |                     |             |                 |     |                  |          |                     |         |              |
| BR700-79-101718        | No. 1 Engine - Sb BR700-79-101718 - Oil - Engine Lubricating Oil Pump Unit (Pressure and Scavenge Pumps) - Introduction of A New Sealing Plate                                                                                      |               | HRS                 |             |                 |     |                  |          |                     |         | 0            |
|                        |                                                                                                                                                                                                                                     |               | ENC                 |             |                 |     |                  |          |                     |         | 0            |
|                        |                                                                                                                                                                                                                                     |               | DATE                |             |                 |     |                  |          |                     |         |              |
|                        |                                                                                                                                                                                                                                     |               | MSC                 |             |                 |     | -                |          |                     |         |              |
|                        |                                                                                                                                                                                                                                     |               | [End Of Month Item] |             |                 |     |                  |          |                     |         |              |
| (880003)               |                                                                                                                                                                                                                                     |               |                     |             |                 |     |                  |          |                     |         |              |
| Engine                 |                                                                                                                                                                                                                                     |               |                     |             |                 |     |                  |          |                     |         |              |
| BR700-79-101718        | No. 2 Engine - Sb BR700-79-101718 - Oil - Engine Lubricating Oil Pump Unit (Pressure and Scavenge Pumps) - Introduction of A New Sealing Plate                                                                                      |               | HRS                 |             |                 |     |                  |          |                     |         | 0            |
|                        |                                                                                                                                                                                                                                     |               | ENC                 |             |                 |     |                  |          |                     |         | 0            |
|                        |                                                                                                                                                                                                                                     |               | DATE                |             |                 |     |                  |          |                     |         |              |
|                        |                                                                                                                                                                                                                                     |               | MSC                 |             |                 |     | -                |          |                     |         |              |
|                        |                                                                                                                                                                                                                                     |               | [End Of Month Item] |             |                 |     |                  |          |                     |         |              |
| (880003)               |                                                                                                                                                                                                                                     |               |                     |             |                 |     |                  |          |                     |         |              |
| Engine                 |                                                                                                                                                                                                                                     |               |                     |             |                 |     |                  |          |                     |         |              |
| BR700-79-101829        | No. 1 Engine - Sb BR700-79-101829 - Oil - Oil Debris Monitoring System Magnetic and Electro Magnetic Chip Detectors - Introduction of SELF Closing Valve With Molded-In Seal Ring                                                   |               | HRS                 |             |                 |     |                  |          |                     |         | 0            |
|                        |                                                                                                                                                                                                                                     |               | ENC                 |             |                 |     |                  |          |                     |         | 0            |
|                        |                                                                                                                                                                                                                                     |               | DATE                |             |                 |     |                  |          |                     |         |              |
|                        |                                                                                                                                                                                                                                     |               | MSC                 |             |                 |     | -                |          |                     |         |              |
|                        |                                                                                                                                                                                                                                     |               | [End Of Month Item] |             |                 |     |                  |          |                     |         |              |
| (880070)               |                                                                                                                                                                                                                                     |               |                     |             |                 |     |                  |          |                     |         |              |
| Engine                 |                                                                                                                                                                                                                                     |               |                     |             |                 |     |                  |          |                     |         |              |

| ATA<br>U=Custom  | Description                                                |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------|------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|----------|--------------------|---------|--------------|
|                  | Part Number                                                | Serial Number |                     |             |                 |     |                  |          |                    |         | Approx Price |
| Logbook Position | HW                                                         | SW            |                     |             |                 |     |                  |          |                    |         | Manufacturer |
|                  | MM Ref                                                     |               |                     |             |                 |     |                  |          |                    |         | Date Type    |
|                  | Ops Number(s)                                              |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-79-101829  | No. 2 Engine - Sb BR700-79-101829 - Oil - Oil Debris       |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Monitoring System Magnetic and Electro Magnetic Chip       |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Detectors - Introduction of SELF Closing Valve With        |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                  | Molded-In Seal Ring                                        |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880070)         |                                                            |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine           |                                                            |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-79-101842  | No. 1 Engine - Sb BR700-79-101842 - Oil - Engine           |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Lubricating Oil Pump Unit (Pressure and Scavenge           |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Pumps) - Introduction of A New Oil Pump With Modified      |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                  | Gears                                                      |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880099)         |                                                            |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine           |                                                            |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-79-101842  | No. 2 Engine - Sb BR700-79-101842 - Oil - Engine           |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Lubricating Oil Pump Unit (Pressure and Scavenge           |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Pumps) - Introduction of A New Oil Pump With Modified      |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                  | Gears                                                      |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880099)         |                                                            |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine           |                                                            |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-79-101984  | No. 1 Engine - Sb BR700-79-101984 - Oil - Oil Filter POP-  |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Up Indicator - Correction of Erroneously Introduced Part   |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Number of the Seal Ring, Which Is Used for Installation of |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                  | the Oil Filter POP-Up Indicator                            |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880145)         |                                                            |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine           |                                                            |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-79-101984  | No. 2 Engine - Sb BR700-79-101984 - Oil - Oil Filter POP-  |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Up Indicator - Correction of Erroneously Introduced Part   |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                  | Number of the Seal Ring, Which Is Used for Installation of |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                  | the Oil Filter POP-Up Indicator                            |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880145)         |                                                            |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine           |                                                            |               |                     |             |                 |     |                  |          |                    |         |              |

| ATA<br>U=Custom        | Description                                                                                                                                                                                                             |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|----------|--------------------|---------|--------------|
|                        | Part Number                                                                                                                                                                                                             | Serial Number |                     |             |                 |     |                  |          |                    |         | Approx Price |
| Logbook Position       | HW                                                                                                                                                                                                                      | SW            |                     |             |                 |     |                  |          |                    |         | Manufacturer |
|                        | MM Ref                                                                                                                                                                                                                  |               |                     |             |                 |     |                  |          |                    |         | Date Type    |
|                        | Ops Number(s)                                                                                                                                                                                                           |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-79-101988        | No. 1 Engine - Sb BR700-79-101988 - Oil - Fuel Cooled Oil Cooler (Fcoc) - Introduction of an Oil-In Tube and an Oil-Out Tube With Revised Seals AT the Fcoc Side and Adjusted Double Ended Unions AT the Fcoc Oil Ports |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                         |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                         |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                                                                                                                                         |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880141)               |                                                                                                                                                                                                                         |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                                                         |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-79-101988        | No. 2 Engine - Sb BR700-79-101988 - Oil - Fuel Cooled Oil Cooler (Fcoc) - Introduction of an Oil-In Tube and an Oil-Out Tube With Revised Seals AT the Fcoc Side and Adjusted Double Ended Unions AT the Fcoc Oil Ports |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                         |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                         |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                                                                                                                                         |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880141)               |                                                                                                                                                                                                                         |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                                                         |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-79-102074        | No. 1 Engine - Sb BR700-79-102074 - Oil - Oil Temperature Transducer - Introduction of A New Duplex Oil Temperature Transducer                                                                                          |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                         |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                         |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                                                                                                                                         |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880167)               |                                                                                                                                                                                                                         |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                                                         |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-79-102074        | No. 2 Engine - Sb BR700-79-102074 - Oil - Oil Temperature Transducer - Introduction of A New Duplex Oil Temperature Transducer                                                                                          |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                         |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                         |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                                                                                                                                         |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880167)               |                                                                                                                                                                                                                         |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                                                         |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-80-101904<br>R02 | No. 1 Engine - Sb BR700-80-101904 R02 - Starting - Starter AIR Valve - Introduction of A Modified Starter AIR Valve                                                                                                     |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                         |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                         |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                                                                                                                                         |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880133)               |                                                                                                                                                                                                                         |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                                                         |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-80-101904<br>R02 | No. 2 Engine - Sb BR700-80-101904 R02 - Starting - Starter AIR Valve - Introduction of A Modified Starter AIR Valve                                                                                                     |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                         |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                        |                                                                                                                                                                                                                         |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                        |                                                                                                                                                                                                                         |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880133)               |                                                                                                                                                                                                                         |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine                 |                                                                                                                                                                                                                         |               |                     |             |                 |     |                  |          |                    |         |              |

| ATA<br>U=Custom        | Description                                                                                                                                                                                                            |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |  |
|------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|----------|--------------------|---------|--------------|--|
|                        | Part Number                                                                                                                                                                                                            | Serial Number |                     |             |                 |     |                  |          |                    |         | Approx Price |  |
| Logbook Position       | HW                                                                                                                                                                                                                     | SW            |                     |             |                 |     |                  |          |                    |         | Manufacturer |  |
|                        | MM Ref                                                                                                                                                                                                                 |               |                     |             |                 |     |                  |          |                    |         | Date Type    |  |
|                        | Ops Number(s)                                                                                                                                                                                                          |               |                     |             |                 |     |                  |          |                    |         |              |  |
| BR700-80-102332<br>R01 | No. 1 Engine - Campaign Sb - BR700-80-102332 R01 - Starting - Starter AIR Valve - Introduction of A Modified Starter AIR Valve With A Modified Body Assembly and A New Filter Assembly, Service Bulletin (Recommended) |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |  |
|                        |                                                                                                                                                                                                                        |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |  |
|                        |                                                                                                                                                                                                                        |               | MOS                 |             |                 |     | 36**             |          | 31 Jul 2027        |         |              |  |
| (883321)               |                                                                                                                                                                                                                        |               |                     |             |                 |     |                  |          |                    |         |              |  |
| Engine                 |                                                                                                                                                                                                                        |               |                     |             |                 |     |                  |          |                    |         |              |  |
| BR700-80-102332<br>R01 | No. 2 Engine - Campaign Sb - BR700-80-102332 R01 - Starting - Starter AIR Valve - Introduction of A Modified Starter AIR Valve With A Modified Body Assembly and A New Filter Assembly, Service Bulletin (Recommended) |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |  |
|                        |                                                                                                                                                                                                                        |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |  |
|                        |                                                                                                                                                                                                                        |               | MOS                 |             |                 |     | 36**             |          | 31 Jul 2027        |         |              |  |
| (883321)               |                                                                                                                                                                                                                        |               |                     |             |                 |     |                  |          |                    |         |              |  |
| Engine                 |                                                                                                                                                                                                                        |               |                     |             |                 |     |                  |          |                    |         |              |  |
| BR700-80-900020        | No. 1 Engine - Sb BR700-80-900020 - Starting - Starter AIR Valve - Inspection of Starter AIR Valves for Foreign Object Debris (FOD) - Non-Modification Service Bulletin                                                |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |  |
|                        |                                                                                                                                                                                                                        |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |  |
|                        |                                                                                                                                                                                                                        |               | DATE                |             |                 |     |                  |          |                    |         |              |  |
| (880094)               |                                                                                                                                                                                                                        |               | MSC                 |             |                 |     |                  |          |                    |         |              |  |
|                        |                                                                                                                                                                                                                        |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |  |
|                        |                                                                                                                                                                                                                        |               | Engine              |             |                 |     |                  |          |                    |         |              |  |
| BR700-80-900020        | No. 2 Engine - Sb BR700-80-900020 - Starting - Starter AIR Valve - Inspection of Starter AIR Valves for Foreign Object Debris (FOD) - Non-Modification Service Bulletin                                                |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |  |
|                        |                                                                                                                                                                                                                        |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |  |
|                        |                                                                                                                                                                                                                        |               | DATE                |             |                 |     |                  |          |                    |         |              |  |
| (880094)               |                                                                                                                                                                                                                        |               | MSC                 |             |                 |     |                  |          |                    |         |              |  |
|                        |                                                                                                                                                                                                                        |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |  |
|                        |                                                                                                                                                                                                                        |               | Engine              |             |                 |     |                  |          |                    |         |              |  |
| BR700-80-900434<br>R01 | No. 1 Engine - Sb BR700-80-900434 R01 - Starting - Starter AIR Valve - Repeat of the Supplier Acceptance Test Procedure of the Starter AIR Valve - Non-Modification Service Bulletin                                   |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |  |
|                        |                                                                                                                                                                                                                        |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |  |
|                        |                                                                                                                                                                                                                        |               | DATE                |             |                 |     |                  |          |                    |         |              |  |
| (880047)               |                                                                                                                                                                                                                        |               | MSC                 |             |                 |     |                  |          |                    |         |              |  |
|                        |                                                                                                                                                                                                                        |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |  |
|                        |                                                                                                                                                                                                                        |               | Engine              |             |                 |     |                  |          |                    |         |              |  |

| ATA<br>U=Custom          | Description                                                |               | UOM                 | Times Since | Time<br>Accrued | Adj | Required<br>Freq | Last C/W | Next Due<br>(*Adj) | Max Due | Avg Man Hrs  |
|--------------------------|------------------------------------------------------------|---------------|---------------------|-------------|-----------------|-----|------------------|----------|--------------------|---------|--------------|
|                          | Part Number                                                | Serial Number |                     |             |                 |     |                  |          |                    |         | Approx Price |
| Logbook Position         | HW                                                         | SW            |                     |             |                 |     |                  |          |                    |         | Manufacturer |
|                          | MM Ref                                                     |               |                     |             |                 |     |                  |          |                    |         | Date Type    |
|                          | Ops Number(s)                                              |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-80-900434<br>R01   | No. 2 Engine - Sb BR700-80-900434 R01 - Starting -         |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                          | Starter AIR Valve - Repeat of the Supplier Acceptance      |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                          | Test Procedure of the Starter AIR Valve - Non-Modification |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                          | Service Bulletin                                           |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880047)                 |                                                            |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine                   |                                                            |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-80-900634          | No. 1 Engine - Sb BR700-80-900634 - Replacement of         |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                          | Starter AIR Valves With Potential of Internal Freezing     |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                          |                                                            |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                          |                                                            |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880163)                 |                                                            |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine                   |                                                            |               |                     |             |                 |     |                  |          |                    |         |              |
| BR700-80-900634          | No. 2 Engine - Sb BR700-80-900634 - Replacement of         |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                          | Starter AIR Valves With Potential of Internal Freezing     |               | ENC                 |             |                 |     |                  |          |                    |         | 0            |
|                          |                                                            |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                          |                                                            |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (880163)                 |                                                            |               | [End Of Month Item] |             |                 |     |                  |          |                    |         |              |
| Engine                   |                                                            |               |                     |             |                 |     |                  |          |                    |         |              |
| RE220/HGT400-<br>49-8383 | APU - Sb RE220/HGT400-49-8383 - Sb RE220/HGT400-           |               | HRS                 |             |                 |     |                  |          |                    |         | 0            |
|                          | 49-8383 - Airborne Auxiliary Power - Gas Turbine Engine -  |               | APUS                |             |                 |     |                  |          |                    |         | 0            |
|                          | Inspect Specific Population of HGT400[G], RE220[Gvi]       |               | DATE                |             |                 |     |                  |          |                    |         |              |
|                          | and RE220[Gx] Engines for Duplex Ball Bearing Damage       |               | MSC                 |             |                 |     | -                |          |                    |         |              |
| (958383)                 | Prevention                                                 |               |                     |             |                 |     |                  |          |                    |         |              |
| APU                      |                                                            |               |                     |             |                 |     |                  |          |                    |         |              |