

Company

Owner: Eclair s.r.o.
Operator: Eclair s.r.o.

Major Assemblies

Airframe	G280	2253	16-Sep-2026	2160:57 Hrs	1,229 Ldg	1,224 SSCyc	SteepAprch
Eng 1	AS907-2-1G	P130647	16-Sep-2026	2136:33 Hrs	1,224 Enc		
Eng 2	AS907-2-1G	P130648	16-Sep-2026	2156:33 Hrs	1,236 Enc		
APU 1	GTCP36-150[IAI]	P-362	26-Aug-2026	Hrs	APUS		

Additional Information

Program Type: Standard, General Categories: RVSM,EMM,EASA

Cost: 3,125+
Man Hrs: 6,866+

Analyst: Robert Peterson rpeterson@jetsupport.com

Task No	Description	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note				DUE	Remaining
▼ 0 - GENERAL						
280-00-243	Aircraft General - Documentation Of Steep Approach Certification For Specific Serial Numbers (MOD G25-10059)		T (A/R)		Optional	
 0 A/F				Mos		
Eff: 31-Jan-2017				Hrs		
				Ldg		
280-00-243 Rev 1	Aircraft General - Documentation of Steep Approach Certification for Specific Serial Numbers (MODG25-10059)		RE (-)		Optional	
 0 A/F				Mos	10-Feb-2023	
Eff: 27-Jun-2017 Complied With				Hrs	24:24	
				Ldg	7	
G25-00151	PYLON COVERS MATERIAL CHANGE, MODIFICATION		RE (-)			
 0 A/F				Mos	20-Nov-2022	
Complied With	AT MANUFACTURE			Hrs	0	
				Ldg	0	
G25-00217	AUXILIARY DOOR MECHANISM- ADDING STOPPER, MODIFICATION		RE (-)			
 0 A/F				Mos	20-Nov-2022	
Complied With	AT MANUFACTURE			Hrs	0	
				Ldg	0	
G25-00330	BAGGAGE DOOR SPRING REEL- ENLARGE FORCE, MODIFICATION		RE (-)			
 0 A/F				Mos	20-Nov-2022	
Complied With	AT MANUFACTURE			Hrs	0	
				Ldg	0	
G25-00463	AUXILIARY BULKHD SPLICE - CHANGE RAW MATERIAL DUE LACK OF CURRENT MATERIAL, MODIFICATION		RE (-)			
 0 A/F				Mos	20-Nov-2022	
Complied With	AT MANUFACTURE			Hrs	0	
				Ldg	0	
G25-00512	REPLACEMENT OF HYDRAULIC RETURN LINE TUBES IN THE V/S, MODIFICATION		RE (-)			
 0 A/F				Mos	20-Nov-2022	
Complied With	AT MANUFACTURE			Hrs	0	
				Ldg	0	
G25-00679	MED LEVER-BOLT HEAD PROXIMETY, MODIFICATION		RE (-)			
 0 A/F				Mos	20-Nov-2022	
Complied With	AT MANUFACTURE			Hrs	0	
				Ldg	0	
G25-00705	ICE DETECTOR - CONDUCTIVE GASKET AND PROPER BONDING, MODIFICATION		RE (-)			
 0 A/F				Mos	20-Nov-2022	
Complied With	AT MANUFACTURE			Hrs	0	
				Ldg	0	

Task No	Description								
SEQ PN/SN	MOC Note			CW	REQ	TOL	Categories	Time	
							DUE	Remaining	
G25-00709	BAGGAGE DOOR- INTERLOCK ROLLER IMPROVEMENT, MODIFICATION						RE (-)		
 0 A/F				Mos	20-Nov-2022				
Complied With	AT MANUFACTURE			Hrs	0				
				Ldg	0				
G25-00899	MED MAIN AXLE - FASTENERS TORQUE CLARIFICATION TO EASE MANUFACTURING, MODIFICATION						RE (-)		
 0 A/F				Mos	20-Nov-2022				
Complied With	AT MANUFACTURE			Hrs	0				
				Ldg	0				
G25-00980	CHANGE PROCESS STANDARD AND TYPE OF RESIN FOR MANUFACTURING PYLON NACA SCOOPS, MODIFICATION						RE (-)		
 0 A/F				Mos	20-Nov-2022				
Complied With	AT MANUFACTURE			Hrs	0				
				Ldg	0				
G25-00993	ADD NOTE FOR LIQUID SHIM BETWEEN WING FITTINGS, MODIFICATION						RE (-)		
 0 A/F				Mos	20-Nov-2022				
Complied With	AT MANUFACTURE			Hrs	0				
				Ldg	0				
G25-01042	WING ICE INSPECTION AND LOGO LIGHTS CHECK ON GROUND WITHOUT OPERATING THE APU, MODIFICATION						RE (-)		
 0 A/F				Mos	20-Nov-2022				
Complied With	AT MANUFACTURE			Hrs	0				
				Ldg	0				
G25-01216	BAGGAGE COMPARTMENT- ADD TRANSPARENT ACCESS PANELS FOR DC BOXES, MODIFICATION						RE (-)		
 0 A/F				Mos	20-Nov-2022				
Complied With	AT MANUFACTURE			Hrs	0				
				Ldg	0				
G25-01237	TILLER (GSCH)- MANUFACTURING PROCESS CHANGE, MODIFICATION						RE (-)		
 0 A/F				Mos	20-Nov-2022				
Complied With	AT MANUFACTURE			Hrs	0				
				Ldg	0				
G25-01276	MODIFICATION OF COCKPIT PEDESTAL AND ILLUMINATED PANELS, MODIFICATION						RE (-)		
 0 A/F				Mos	20-Nov-2022				
Complied With	AT MANUFACTURE			Hrs	0				
				Ldg	0				
G25-01357	THERMAL AND ACOUSTIC INSULATION SYSTEM-BLANKET REINFORCEMENT, MODIFICATION						RE (-)		
 0 A/F				Mos	20-Nov-2022				
Complied With	AT MANUFACTURE			Hrs	0				
				Ldg	0				
G25-01441	BAGGAGE DOOR - OUTER HANDLE SLIDING MECHANISM - CHANGES IN MATERIAL AND GEOMETRY OF COMPONENTS TO PREVENT EXCESSIVE WEAR, MODIFICATION						RE (-)		
 0 A/F				Mos	20-Nov-2022				
Complied With	AT MANUFACTURE			Hrs	0				
				Ldg	0				
G25-01495	ELEVATOR SERVO ACTUATOR EXTERNAL PAINT REMOVAL, DUE NOT REQUIRED AND PEELING IN SERVICE, MODIFICATION						RE (-)		
 0 A/F				Mos	20-Nov-2022				
Complied With	AT MANUFACTURE			Hrs	0				
				Ldg	0				
G25-01504	CHANGE RAW MATERIAL OF SPLICE RHS LONG SIDE FR43, MODIFICATION						RE (-)		
 0 A/F				Mos	20-Nov-2022				
Complied With	AT MANUFACTURE			Hrs	0				
				Ldg	0				

Task No		Description				Categories	Time
SEQ	PN/SN	MOC Note	CW	REQ	TOL	DUE	Remaining
G25-01568		THERMAL AND ACOUSTIC INSULATION SYSTEM - BLANKET ADHESIVE TAPE OBSOLESCENCE FOR FERRY KITS, MODIFICATION		RE (-)			
	0 A/F		Mos	20-Nov-2022			
	Complied With	AT MANUFACTURE	Hrs	0			
			Ldg	0			
G25-01662		COCKPIT SIDE WINDOW-CHANGE PROFILE OF Z-RETAINER TO ENSURE REQUIRED GAP WITH STRUCTURE ON INSTALLATION, TO PREVENT NEED FOR REWORK, MODIFICATION		RE (-)			
	0 A/F		Mos	20-Nov-2022			
	Complied With	AT MANUFACTURE	Hrs	0			
			Ldg	0			
G25-01697		NOSE SECTION - HIGH PRESSURE OXYGEN FLEXIBLE HOSE - REPLACE WITH NON-MAGENETIC MODEL - TO REMOVE SUSPICIION OF INTERFERENCE WITH MAGNETOMETER LOCATED AT DISTANCE OF SEVERAL INCHES, MODIFICATION		RE (-)			
	0 A/F		Mos	20-Nov-2022			
	Complied With	AT MANUFACTURE	Hrs	0			
			Ldg	0			
G25-01698		NLG COMPONENTS - REFER TO IAI PS INSTEAD OF TO MIL SPEC FOR DEFINITION OF REQUIRED HEAT TREATMENT, PER IAI QA REQUIREMENT, AND CHANGE CONDITION FROM H975 TO G1D25, PER IAI M&P RECOMMENDATION, MODIFICATION		RE (-)			
	0 A/F		Mos	20-Nov-2022			
	Complied With	AT MANUFACTURE	Hrs	0			
			Ldg	0			
G25-01756		MFSA PAINT REMOVAL, MODIFICATION		RE (-)			
	0 A/F		Mos	20-Nov-2022			
	Complied With	AT MANUFACTURE	Hrs	0			
			Ldg	0			
G25-01772		GSA EXTERNAL PAINT REMOVAL, MODIFICATION		RE (-)			
	0 A/F		Mos	20-Nov-2022			
	Complied With	AT MANUFACTURE	Hrs	0			
			Ldg	0			
G25-02039		G25-02039 , Modification		RE (-)			
	0 A/F		Mos	20-Nov-2022			
	Complied With	AT MANUFACTURE	Hrs	0			
			Ldg	0			
G25-02051		G25-02051 , MODIFICATION		RE (-)			
	0 A/F		Mos	20-Nov-2022			
	Complied With	AT MANUFACTURE	Hrs	0			
			Ldg	0			
G25-02213		Brakes Accumulator And Landing Gear Pressure Vessel Nitrogen Charging Instructions - Correct Factors Used For Ambient Temperature Corrections, Modification		RE (-)			
	0 A/F		Mos	20-Nov-2022			
	Complied With	AT MANUFACTURE	Hrs	0			
			Ldg	0			
G25-02247		Rudder Closeout Ribs Installation - Rivet Instead Of Bond, To Prevent Need For Rework, Modification		RE (-)			
	0 A/F		Mos	20-Nov-2022			
	Complied With	AT MANUFACTURE	Hrs	0			
			Ldg	0			
G25-02285		G25-02285, Modification		RE (-)			
	0 A/F		Mos	20-Nov-2022			
	Complied With	AT MANUFACTURE	Hrs	0			
			Ldg	0			
G25-02317		G25-02317, H/S - V/S Pivot Freeplay Assurance - Change MODIFICATION		RE (-)			
	0 A/F		Mos	22-Nov-2022			
	Complied With		Hrs				
			Ldg				

Task No SEQ PN/SN	Description MOC Note			CW	REQ	TOL	Categories DUE	Time Remaining
G25-07112	ADD LIQUID SHIM BELOW FLAP TRACK D ROLLER FITTINGS, MODIFICATION						RE (-)	
 0 A/F			Mos	20-Nov-2022				
Complied With	AT MANUFACTURE		Hrs	0				
			Ldg	0				
G25-07243	IMS-6000 REPLACEMENT, MODIFICATION						RE (-)	
 0 A/F			Mos	20-Nov-2022				
Complied With	AT MANUFACTURE		Hrs	0				
			Ldg	0				
G25-10022	GADC -4 MODIFICATIONS AND WAI OPTIMIZATIONS, MODIFICATION						RE (-)	
 0 A/F			Mos	20-Nov-2022				
Complied With	AT MANUFACTURE		Hrs	0				
			Ldg	0				
G25-10023	MAIN STRUT - CHANGING INNER DIAMETER, UPDATING DEFINITION OF SHOT PEENING FORGING - ADDING CUT THROUGH TRUNNION HOLE FOR HEAT TREATMENT, MODIFICATION						RE (-)	
 0 A/F			Mos	20-Nov-2022				
Complied With	AT MANUFACTURE		Hrs	0				
			Ldg	0				
G25-10024	ACT-3010 AND OCMT-3900 MODIFICATION FOR RVSM GROUP APPROVAL, MODIFICATION						RE (-)	
 0 A/F			Mos	20-Nov-2022				
Complied With	AT MANUFACTURE		Hrs	0				
			Ldg	0				
G25-10026	MOOG FCECU SW VERSION 13, MODIFICATION						RE (-)	
 0 A/F			Mos	20-Nov-2022				
Complied With	AT MANUFACTURE		Hrs	0				
			Ldg	0				
G25-10032	RED LABEL RC VERSION 3.6 POST EIS IMPLEMENTATION, MODIFICATION						RE (-)	
 0 A/F			Mos	20-Nov-2022				
Complied With	AT MANUFACTURE		Hrs	0				
			Ldg	0				
G25-10033	G280AFM REV 3, MODIFICATION						RE (-)	
 0 A/F			Mos	20-Nov-2022				
Complied With	AT MANUFACTURE		Hrs	0				
			Ldg	0				
G25-10034	INTRODUCTION OF METAL AUXILIARY DOOR INST. OF COMP MATERIAL, MODIFICATION						RE (-)	
 0 A/F			Mos	20-Nov-2022				
Complied With	AT MANUFACTURE		Hrs	0				
			Ldg	0				
G25-10035	AFM UPDATE, MODIFICATION						RE (-)	
 0 A/F			Mos	20-Nov-2022				
Complied With	AT MANUFACTURE		Hrs	0				
			Ldg	0				
G25-10038	WINDSHIELD LOWERS SILLS IMPROVEMENT, COCKPIT, MODIFICATION						RE (-)	
 0 A/F			Mos	20-Nov-2022				
Complied With	AT MANUFACTURE		Hrs	0				
			Ldg	0				
G25-10039	ADD COLD WORK ON HOLES LOCATED BETWEEN FRAMES 32 THROUGH 36., MODIFICATION						RE (-)	
 0 A/F			Mos	20-Nov-2022				
Complied With	AT MANUFACTURE		Hrs	0				
			Ldg	0				

Task No SEQ PN/SN	Description MOC Note	CW	REQ	TOL	Categories DUE	Time Remaining
G25-10040	LOWER SILLS COLD WORK, COCKPIT, MODIFICATION				RE (-)	
 0 A/F		Mos	20-Nov-2022			
Complied With	AT MANUFACTURE	Hrs	0			
		Ldg	0			
G25-10041	AFM REV. 5, MODIFICATION				RE (-)	
 0 A/F		Mos	20-Nov-2022			
Complied With	AT MANUFACTURE	Hrs	0			
		Ldg	0			
G25-10044	ECU HARDWARE AND FADEC SOFTWARE UPDATE, V2G, MODIFICATION				RE (-)	
 0 A/F		Mos	20-Nov-2022			
Complied With	AT MANUFACTURE	Hrs	0			
		Ldg	0			
G25-10045	CRACKS ON INTERCOSTALS (LH & RH SIDES) STA4518., MODIFICATION				RE (-)	
 0 A/F		Mos	20-Nov-2022			
Complied With	AT MANUFACTURE	Hrs	0			
		Ldg	0			
G25-10046	REPLACING STOPPERS FITTING AND SERRATED PLATES ON AROUND STRUCTURE BAGGAGE COMP. BAY., MODIFICATION				RE (-)	
 0 A/F		Mos	20-Nov-2022			
Complied With	AT MANUFACTURE	Hrs	0			
		Ldg	0			
G25-10047	G280 AFM REV6 + ECL, MODIFICATION				RE (-)	
 0 A/F		Mos	20-Nov-2022			
Complied With	AT MANUFACTURE	Hrs	0			
		Ldg	0			
G25-10048	G280AFMREV7, MODIFICATION				RE (-)	
 0 A/F		Mos	20-Nov-2022			
Complied With	AT MANUFACTURE	Hrs	0			
		Ldg	0			
G25-10052	G280 IPPS-EATON FUEL AND HYDRAULIC HOSES, FIRE RESISTING SLEEVING, MODIFICATION				RE (-)	
 0 A/F		Mos	20-Nov-2022			
Complied With	AT MANUFACTURE	Hrs	0			
		Ldg	0			
G25-10053	G280 AFM AIRPLANE FLIGHT MANUAL (AFM) ISSUE 1 REV 0, MODIFICATION				RE (-)	
 0 A/F		Mos	20-Nov-2022			
Complied With	AT MANUFACTURE	Hrs	0			
		Ldg	0			
G25-10054	INCORPORATION OF UNCONTROLLED HIGH THRUST (UHT) AUTOMATIC PROTECTION ACTION, MODIFICATION				RE (-)	
 0 A/F		Mos	20-Nov-2022			
Complied With	AT MANUFACTURE	Hrs	0			
		Ldg	0			
G25-10063	G280 AIRPLANE FLIGHT MANUAL REVISION 3, MODIFICATION				RE (-)	
 0 A/F		Mos	20-Nov-2022			
Complied With	AT MANUFACTURE	Hrs	0			
		Ldg	0			
G25-10066	CHANGE OF THE BAGGAGE ACCESS DOOR LIMITATION PLACARD, MODIFICATION				RE (-)	
 0 A/F		Mos	20-Nov-2022			
Complied With	AT MANUFACTURE	Hrs	0			
		Ldg	0			
G25-10068	G280 AFM ISSUE 2 REV 1, G280 AFM ISSUE 1 REV 3, MODIFICATION				RE (-)	
 0 A/F		Mos	20-Nov-2022			
Complied With	AT MANUFACTURE	Hrs	0			
		Ldg	0			

Task No	Description					Categories	Time
SEQ PN/SN	MOC Note			CW	REQ	TOL	DUE Remaining
G25-10069	G280 AFM ISSUE 2 REV 3, MODIFICATION						RE (-)
 0 A/F			Mos	20-Nov-2022			
Complied With	AT MANUFACTURE		Hrs	0			
			Ldg	0			
G25-10070	FLIGHT CONTROL CABLES - SUBSTITUTE FOR OBSOLETE PART, MODIFICATION						RE (-)
 0 A/F			Mos	20-Nov-2022			
Complied With	AT MANUFACTURE		Hrs	0			
			Ldg	0			
G25-10071	G280 AFM ISSUE 2 REVISION 4 AND ISSUE 1 REVISION 4., MODIFICATION						RE (-)
 0 A/F			Mos	20-Nov-2022			
Complied With	AT MANUFACTURE		Hrs	0			
			Ldg	0			
G25-10074	G25-10074 , Modification						RE (-)
 0 A/F			Mos	20-Nov-2022			
Complied With	AT MANUFACTURE		Hrs	0			
			Ldg	0			
G25-10077	G25-10077 , MODIFICATION						RE (-)
 0 A/F			Mos	20-Nov-2022			
Complied With	AT MANUFACTURE		Hrs	0			
			Ldg	0			
G25-10078	G25-10078 , Modification						RE (-)
 0 A/F			Mos	20-Nov-2022			
Complied With	AT MANUFACTURE		Hrs	0			
			Ldg	0			
G25-10700	REDUCE LANDING AROUND ACCESS PANELS IN BAY 11 AND OUTBD FOR WEIGHT SAVINGS, MODIFICATION						RE (-)
 0 A/F			Mos	20-Nov-2022			
Complied With	AT MANUFACTURE		Hrs	0			
			Ldg	0			
G25-10702	DESIGN OF REAR SPAR INCORPORATING SERIAL FIXES FOR ULTIMATE LOAD TEST FAILURE, MODIFICATION						RE (-)
 0 A/F			Mos	20-Nov-2022			
Complied With	AT MANUFACTURE		Hrs	0			
			Ldg	0			
G25-10703	DESIGN OF WING RIBS INCORPORATING SERIAL FIXES FOR ULTIMATE LOAD TEST FAILURE, MODIFICATION						RE (-)
 0 A/F			Mos	20-Nov-2022			
Complied With	AT MANUFACTURE		Hrs	0			
			Ldg	0			
G25-10704	DESIGN OF WING STRINGERS INCORPORATING SERIAL FIXES FOR ULTIMATE LOAD TEST FAILURE, MODIFICATION						RE (-)
 0 A/F			Mos	20-Nov-2022			
Complied With	AT MANUFACTURE		Hrs	0			
			Ldg	0			
G25-10705	CHANGE TURN DOWN HOOK TO INCREASE GAP TO TRACK, MODIFICATION						RE (-)
 0 A/F			Mos	20-Nov-2022			
Complied With	AT MANUFACTURE		Hrs	0			
			Ldg	0			
G25-10706	FAA REQUIREMENT TO CORRECT ROUTING OF WIRE HARNESSSES TO ENSURE NO CHAFING WITH ADJACENT STRUCTURES OR SYSTEMS (ECP G28D-7501). ALSO INCORPORATES THE REQUIREMENT (ECP G280-7502) THAT THERE CANNOT BE ANY TWO CLAMPS LOST ON THE LE HARNESS, OR SINGLE CLAMP LOSS ON THE TE HARNESS RESULTING IN WIRE CONTACTING STRUCTURE OR SYSTEMS AND CHAFFING, MODIFICATION						RE (-)
 0 A/F			Mos	20-Nov-2022			
Complied With	AT MANUFACTURE		Hrs	0			
			Ldg	0			

Task No		Description				Categories	Time
SEQ	PN/SN	MOC Note		CW	REQ	TOL	DUE Remaining
G25-10708		CHANGE TRACK D ROLLER FITTINGS FOR FATIGUE, MODIFICATION					RE (-)
	0 A/F		Mos	20-Nov-2022			
	Complied With	AT MANUFACTURE	Hrs	0			
			Ldg	0			
G25-10709		FWD SPAR / RIB 0 FIXES FROM FATIGUE TEST FAILURES, MODIFICATION					RE (-)
	0 A/F		Mos	20-Nov-2022			
	Complied With	AT MANUFACTURE	Hrs	0			
			Ldg	0			
G25-10709 REVB		FWD SPAR FIXES FROM FATIGUE TEST FAILURES, MODIFICATION					RE (-)
	0 A/F		Mos	20-Nov-2022			
	Complied With	AT MANUFACTURE	Hrs	0			
			Ldg	0			
G25-10710		REDESIGN TRACK A ROLLER FITTINGS FOR FATIGUE, MODIFICATION					RE (-)
	0 A/F		Mos	20-Nov-2022			
	Complied With	AT MANUFACTURE	Hrs	0			
			Ldg	0			
G25-10711		IMPROVE SEALING BETWEEN OUTBOARD SPAR TO LOWER AND UPPER SKINS ATTACHMENTS., MODIFICATION					RE (-)
	0 A/F		Mos	20-Nov-2022			
	Complied With	AT MANUFACTURE	Hrs	0			
			Ldg	0			
G25-20006		ALTERNATIVE LEFT WHEEL SPROCKET, MODIFICATION					RE (-)
	0 A/F		Mos	20-Nov-2022			
	Complied With	AT MANUFACTURE	Hrs	0			
			Ldg	0			
G25-20007		MATERIAL CHANGE OF RIB 4 P/N 30P318354100-501 (PYLON) FROM TITANIUM TO ALUMINUM., MODIFICATION					RE (-)
	0 A/F		Mos	20-Nov-2022			
	Complied With	AT MANUFACTURE	Hrs	0			
			Ldg	0			
G25-20008		CROWN DAMPING, MODIFICATION					RE (-)
	0 A/F		Mos	20-Nov-2022			
	Complied With	AT MANUFACTURE	Hrs	0			
			Ldg	0			
G25-20016		PARKING BRAKE HANDLE (PBH) - NEW SUPPLIER, MODIFICATION					RE (-)
	0 A/F		Mos	20-Nov-2022			
	Complied With	AT MANUFACTURE	Hrs	0			
			Ldg	0			
G25-20018		PYLON TRAILING FADE FROM SHEETMETAL, MODIFICATION					RE (-)
	0 A/F		Mos	20-Nov-2022			
	Complied With	AT MANUFACTURE	Hrs	0			
			Ldg	0			
G25-20019		G280 REDESIGN OF MLG DOOR MECHANISM LOWER ROD 30P265036001-501, MODIFICATION					RE (-)
	0 A/F		Mos	20-Nov-2022			
	Complied With	AT MANUFACTURE	Hrs	0			
			Ldg	0			
G25-20023		BRAKE CONTROL SYSTEM - WHEEL SPEED TRANSDUCER (WST) CHANGE, MODIFICATION					RE (-)
	0 A/F		Mos	20-Nov-2022			
	Complied With	AT MANUFACTURE	Hrs	0			
			Ldg	0			
G25-20025		NEW FQMS SOFTWARE 738721-1-4, MODIFICATION					RE (-)
	0 A/F		Mos	20-Nov-2022			
	Complied With	AT MANUFACTURE	Hrs	0			
			Ldg	0			

Task No	Description				CW	REQ	TOL	Categories	Time
SEQ	PN/SN	MOC Note						DUE	Remaining
G25-20026		MED STOPPERS- REARRANGE ON FRAMES, MODIFICATION							
	0 A/F				Mos	20-Nov-2022		RE (-)	
	Complied With	AT MANUFACTURE			Hrs	0			
					Ldg	0			
G25-20029		NEW CVR RIPS PART NUMBER, MODIFICATION							
	0 A/F				Mos	20-Nov-2022		RE (-)	
	Complied With	AT MANUFACTURE			Hrs	0			
					Ldg	0			
G25-20031		GPS-4000S PRODUCT REPLACEMENT, MODIFICATION							
	0 A/F				Mos	20-Nov-2022		RE (-)	
	Complied With	AT MANUFACTURE			Hrs	0			
					Ldg	0			
G25-20032		NEW ANTI ROLL WASHERS FOR WING TO FUSE LINKS, MODIFICATION							
	0 A/F				Mos	20-Nov-2022		RE (-)	
	Complied With	AT MANUFACTURE			Hrs	0			
					Ldg	0			
G25-20034		AFD PART NUMBER CHANGE, MODIFICATION							
	0 A/F				Mos	20-Nov-2022		RE (-)	
	Complied With	AT MANUFACTURE			Hrs	0			
					Ldg	0			
G25-20035		CONTROL COLUMN - CHAIN AND SPROCKET SUPPLIER REPLACMENT, MODIFICATION							
	0 A/F				Mos	20-Nov-2022		RE (-)	
	Complied With	AT MANUFACTURE			Hrs	0			
					Ldg	0			
G25-20037		G280 WING-TIP LIGHT MODIFICATION, MODIFICATION							
	0 A/F				Mos	20-Nov-2022		RE (-)	
	Complied With	AT MANUFACTURE			Hrs	0			
					Ldg	0			
G25-20038		FTE AND LWR BAY MODIFICATION, MODIFICATION							
	0 A/F				Mos	20-Nov-2022		RE (-)	
	Complied With	AT MANUFACTURE			Hrs	0			
					Ldg	0			
G25-20040		ECE DC BOX, MODIFICATION							
	0 A/F				Mos	20-Nov-2022		RE (-)	
	Complied With	AT MANUFACTURE			Hrs	0			
					Ldg	0			
G25-20041		NWS NEW RACK P/N 30A2720181-001 FOR G-280 AND ADD INSERVICE GREASING REQUIREMENT, MODIFICATION							
	0 A/F				Mos	20-Nov-2022		RE (-)	
	Complied With	AT MANUFACTURE			Hrs	0			
					Ldg	0			
G25-20042		NLG P/N 30A2720451 (NWS) COLLAR -UPDATING PLATING DEFINITION AND ADD PERIODICAL GREASING REQUIREMENT, MODIFICATION							
	0 A/F				Mos	20-Nov-2022		RE (-)	
	Complied With	AT MANUFACTURE			Hrs	0			
					Ldg	0			
G25-20043		ACP REPLACEMENT, MODIFICATION							
	0 A/F				Mos	20-Nov-2022		RE (-)	
	Complied With	AT MANUFACTURE			Hrs	0			
					Ldg	0			
G25-20045		ECL DATABASE (-0004) UPDATE, MODIFICATION							
	0 A/F				Mos	20-Nov-2022		RE (-)	
	Complied With	AT MANUFACTURE			Hrs	0			
					Ldg	0			

Task No		Description			Categories		Time	
SEQ	PN/SN	MOC Note		CW	REQ	TOL	DUE	Remaining
G25-20047		TE AND LE HARNESSES SEPARATION (COMPLY TO 25.981), MODIFICATION			RE (-)			
	0 A/F		Mos	20-Nov-2022				
	Complied With	AT MANUFACTURE	Hrs	0				
			Ldg	0				
G25-20047A		TE AND LE HARNESSES SEPARATION (COMPLY TO 25.981), MODIFICATION			RE (-)			
	0 A/F		Mos	20-Nov-2022				
	Complied With	AT MANUFACTURE	Hrs	0				
			Ldg	0				
G25-20048		WWS SYSTEM HEATING CONTROL MODULE (SHCM) SOFTWARE MODIFICATION, MODIFICATION			RE (-)			
	0 A/F		Mos	20-Nov-2022				
	Complied With	AT MANUFACTURE	Hrs	0				
			Ldg	0				
G25-20049		WWS WATER CONTROL UNIT (WLS) SOFTWARE MODIFICATION, MODIFICATION			RE (-)			
	0 A/F		Mos	20-Nov-2022				
	Complied With	AT MANUFACTURE	Hrs	0				
			Ldg	0				
G25-20050		DGPU NEW AMND C - NEW IAI PART NUMBER, MODIFICATION			RE (-)			
	0 A/F		Mos	20-Nov-2022				
	Complied With	AT MANUFACTURE	Hrs	0				
			Ldg	0				
G25-20051		TQA MODIFICATION (-5), MODIFICATION			RE (-)			
	0 A/F		Mos	20-Nov-2022				
	Complied With	AT MANUFACTURE	Hrs	0				
			Ldg	0				
G25-20052		CONTAMINATED VSPEEDS DATA BASE UPDATE FOR AVIONICS S/W VERSION 3.6, MODIFICATION			RE (-)			
	0 A/F		Mos	20-Nov-2022				
	Complied With	AT MANUFACTURE	Hrs	0				
			Ldg	0				
G25-20053		G280 PERFORMANCE DATA BASE (PDB) INCORPORATION FOR SW VERSION 3.2.1, MODIFICATION			RE (-)			
	0 A/F		Mos	20-Nov-2022				
	Complied With	AT MANUFACTURE	Hrs	0				
			Ldg	0				
G25-20054		G280 VSPEEDS DATA BASE (DRY&WET) INCORPORATION FOR SW VERSION 3.2.1, MODIFICATION			RE (-)			
	0 A/F		Mos	20-Nov-2022				
	Complied With	AT MANUFACTURE	Hrs	0				
			Ldg	0				
G25-20055		WWS POTABLE WATER PUMP (PWP) DESIGN MODIFICATION OF HEATER, MODIFICATION			RE (-)			
	0 A/F		Mos	20-Nov-2022				
	Complied With	AT MANUFACTURE	Hrs	0				
			Ldg	0				
G25-20056		INSTALLATION OF ACOUSTIC INSULATION IN METAL AUX BULKHEAD DOOR, MODIFICATION			RE (-)			
	0 A/F		Mos	20-Nov-2022				
	Complied With	AT MANUFACTURE	Hrs	0				
			Ldg	0				
G25-20057		HARNESS ROUTING MODIFICATION IN FWD FUEL TANK, MODIFICATION			RE (-)			
	0 A/F		Mos	20-Nov-2022				
	Complied With	AT MANUFACTURE	Hrs	0				
			Ldg	0				
G25-20058		G280 PERFORMANCE DATA BASE (PDB) UPDATE FOR SW VERSION 3.6, MODIFICATION			RE (-)			
	0 A/F		Mos	20-Nov-2022				
	Complied With	AT MANUFACTURE	Hrs	0				
			Ldg	0				

Task No		Description				Categories	Time	
SEQ	PN/SN	MOC Note		CW	REQ	TOL	DUE	Remaining
G25-20059		BAGGAGE COMPARTMENT LINERS - USE OF NEW MATERIALS, MODIFICATION			RE (-)			
 0 A/F	Complied With	AT MANUFACTURE		Mos	20-Nov-2022			
				Hrs	0			
				Ldg	0			
G25-20060		PILOT CONTROL-WHEEL - DISCONNECT MECHANISM, MODIFICATION			RE (-)			
 0 A/F	Complied With	AT MANUFACTURE		Mos	20-Nov-2022			
				Hrs	0			
				Ldg	0			
G25-20061		FADEC SOFTWARE V1.5G UPDATE, MODIFICATION			RE (-)			
 0 A/F	Complied With	AT MANUFACTURE		Mos	20-Nov-2022			
				Hrs	0			
				Ldg	0			
G25-20062		EMPFR REPLACEMENT, MODIFICATION			RE (-)			
 0 A/F	Complied With	AT MANUFACTURE		Mos	20-Nov-2022			
				Hrs	0			
				Ldg	0			
G25-20063		PILOT/COPILOT CONTROL-WHEEL PITCH-TRIM SWITCH IMPROVEMENT, MODIFICATION			RE (-)			
 0 A/F	Complied With	AT MANUFACTURE		Mos	20-Nov-2022			
				Hrs	0			
				Ldg	0			
G25-20067		UNIFY SKIN AND DOUBLER, UPPER, STA. 1663 - 2669 30P311101002-001, MODIFICATION			RE (-)			
 0 A/F	Complied With	AT MANUFACTURE		Mos	20-Nov-2022			
				Hrs	0			
				Ldg	0			
G25-20068		OXYGEN CYLINDER ASSY.-REPLACEMENT, MODIFICATION			RE (-)			
 0 A/F	Complied With	AT MANUFACTURE		Mos	20-Nov-2022			
				Hrs	0			
				Ldg	0			
G25-20069		ADDITIONAL DRAIN HOLES TO FLAP ACTUATORS, MODIFICATION			RE (-)			
 0 A/F	Complied With	AT MANUFACTURE		Mos	20-Nov-2022			
				Hrs	0			
				Ldg	0			
G25-20070		UPDATING OF SHCM SW. WLS SW, PWM P/N, MODIFICATION			RE (-)			
 0 A/F	Complied With	AT MANUFACTURE		Mos	20-Nov-2022			
				Hrs	0			
				Ldg	0			
G25-20071		WDIC MODIFICATION, MODIFICATION			RE (-)			
 0 A/F	Complied With	AT MANUFACTURE		Mos	20-Nov-2022			
				Hrs	0			
				Ldg	0			
G25-20072		WAI - MANIFOLD PRESSURE SENSOR REMOVAL, MODIFICATION			RE (-)			
 0 A/F	Complied With	AT MANUFACTURE		Mos	20-Nov-2022			
				Hrs	0			
				Ldg	0			
G25-20073		REMOVAL OF PLACARD PROHIBITING WAI AUTO OPERATION, MODIFICATION			RE (-)			
 0 A/F	Complied With	AT MANUFACTURE		Mos	20-Nov-2022			
				Hrs	0			
				Ldg	0			
G25-20074		AUTOBRAKE SELECT SWITCH (ABS) P/N 90006480-1, MODIFICATION			RE (-)			
 0 A/F	Complied With	AT MANUFACTURE		Mos	20-Nov-2022			
				Hrs	0			
				Ldg	0			

Task No SEQ PN/SN	Description MOC Note			CW	REQ	TOL	Categories DUE	Time Remaining
G25-20075	MODIFY STATIC PORTS WITH LARGE HOLES, MODIFICATION						RE (-)	
 0 A/F				Mos	20-Nov-2022			
Complied With	AT MANUFACTURE			Hrs	0			
				Ldg	0			
G25-20077	DGCU NEW AMND D INCORPORATION, MODIFICATION						RE (-)	
 0 A/F				Mos	20-Nov-2022			
Complied With	AT MANUFACTURE			Hrs	0			
				Ldg	0			
G25-20078	HSTA SECONDARY MOTOR CAP SCREW INTERFERENCE, MODIFICATION						RE (-)	
 0 A/F				Mos	20-Nov-2022			
Complied With	AT MANUFACTURE			Hrs	0			
				Ldg	0			
G25-20079	UNIFY SKIN AND DOUBLER TO AN INTEGRAL PART, LOWER, STA. 1663 - 2669 30P311201003-001, MODIFICATION						RE (-)	
 0 A/F				Mos	20-Nov-2022			
Complied With	AT MANUFACTURE			Hrs	0			
				Ldg	0			
G25-20080	CHANGE LOCATION AND TYPE OF FASTENERS FOR EASE INSTALLATION AT MED STRUCTURE., MODIFICATION						RE (-)	
 0 A/F				Mos	20-Nov-2022			
Complied With	AT MANUFACTURE			Hrs	0			
				Ldg	0			
G25-20081	VHF COMM REPLACEMENT, MODIFICATION						RE (-)	
 0 A/F				Mos	20-Nov-2022			
Complied With	AT MANUFACTURE			Hrs	0			
				Ldg	0			
G25-20083	G280 ELEVATOR SERVO ACTUATOR - TRANSFER TUBE CHANGE, MODIFICATION						RE (-)	
 0 A/F				Mos	20-Nov-2022			
Complied With	AT MANUFACTURE			Hrs	0			
				Ldg	0			
G25-20086	MED AXLE - BEARING HOUSINGS CHANGE, MODIFICATION						RE (-)	
 0 A/F				Mos	20-Nov-2022			
Complied With	AT MANUFACTURE			Hrs	0			
				Ldg	0			
G25-20088	REPLACEMENT OF MATERIAL IN BLEED DUCT ASSY., MODIFICATION						RE (-)	
 0 A/F				Mos	20-Nov-2022			
Complied With	AT MANUFACTURE			Hrs	0			
				Ldg	0			
G25-20089	NOSE LANDING GEAR-STEERING CONTROL UNIT LPRV SUPPLIER CHANGE, MODIFICATION						RE (-)	
 0 A/F				Mos	20-Nov-2022			
Complied With	AT MANUFACTURE			Hrs	0			
				Ldg	0			
G25-20091	MODIFICATION OF UPPER JURY BRACE ON NLG BRACE ASSEMBLY, MODIFICATION						RE (-)	
 0 A/F				Mos	20-Nov-2022			
Complied With	AT MANUFACTURE			Hrs	0			
				Ldg	0			
G25-20092	PEDESTAL - CUTTING CORNER ON SIDE PANEL TO PREVENT DAMAGE ON FLOOR PANEL, MODIFICATION						RE (-)	
 0 A/F				Mos	20-Nov-2022			
Complied With	AT MANUFACTURE			Hrs	0			
				Ldg	0			
G25-20093	LH DISTRIBUTION BUS - NEW LOGIC (FOR DUAL GENERATOR FAIL), MODIFICATION						RE (-)	
 0 A/F				Mos	20-Nov-2022			
Complied With	AT MANUFACTURE			Hrs	0			
				Ldg	0			

Task No SEQ PN/SN	Description MOC Note		CW	REQ	TOL	Categories DUE	Time Remaining
G25-20095	FPCU DESIGN CHANGE, MODIFICATION					RE (-)	
 0 A/F			Mos	20-Nov-2022			
Complied With	AT MANUFACTURE		Hrs	0			
			Ldg	0			
G25-20096	RSA CET IMPROVEMENTS, MODIFICATION					RE (-)	
 0 A/F			Mos	20-Nov-2022			
Complied With	AT MANUFACTURE		Hrs	0			
			Ldg	0			
G25-20097	REVISE PLENUM BEAM TO INTEGRATE PLENUM RIBS, MODIFICATION					RE (-)	
 0 A/F			Mos	20-Nov-2022			
Complied With	AT MANUFACTURE		Hrs	0			
			Ldg	0			
G25-20101	AHRS (ATTITUDE AND HEADING REFERENCE SYSTEM) AND IRS (INERTIAL REFERENCE SYSTEM) MAGVAR TABLES AND SW UPDATE, MODIFICATION					RE (-)	
 0 A/F			Mos	20-Nov-2022			
Complied With	AT MANUFACTURE		Hrs	0			
			Ldg	0			
G25-20102	NEW CONFIGURATION OF BAGGAGE COMPARTMENT LOADING, MODIFICATION					RE (-)	
 0 A/F			Mos	20-Nov-2022			
Complied With	AT MANUFACTURE		Hrs	0			
			Ldg	0			
G25-20103	AFD-6510 REPLACEMENT, MODIFICATION					RE (-)	
 0 A/F			Mos	20-Nov-2022			
Complied With	AT MANUFACTURE		Hrs	0			
			Ldg	0			
G25-20105	APM 3RD PARTY OPTIONS FILE - DISABLE FMS PREDICTED STEPS FUNCTIONALITY, MODIFICATION					RE (-)	
 0 A/F			Mos	20-Nov-2022			
Complied With	AT MANUFACTURE		Hrs	0			
			Ldg	0			
G25-20108	REDUCE NUMBER OF DOOR SWITCHES, MODIFICATION					RE (-)	
 0 A/F			Mos	20-Nov-2022			
Complied With	AT MANUFACTURE		Hrs	0			
			Ldg	0			
G25-20113	IPPS- THRUST REVERSER INNER DUCT SKIN -ADDITION OF A TATANUM HEATSHIELD TO PROVIDE THERMAL PROTECTION, MODIFICATION					RE (-)	
 0 A/F			Mos	20-Nov-2022			
Complied With	AT MANUFACTURE		Hrs	0			
			Ldg	0			
G25-20118	TDR-94 REPLACEMENT, MODIFICATION					RE (-)	
 0 A/F			Mos	20-Nov-2022			
Complied With	AT MANUFACTURE		Hrs	0			
			Ldg	0			
G25-20119	MAIN ENTRANCE DOOR AXLE - FORWARD BEARING IMPROVEMENT, MODIFICATION					RE (-)	
 0 A/F			Mos	20-Nov-2022			
Complied With	AT MANUFACTURE		Hrs	0			
			Ldg	0			
G25-20121	RADIO INTERFACE UNIT (RIU) REPLACEMENT TO SUPPORT SECOND DATA LINK OPTION, MODIFICATION					RE (-)	
 0 A/F			Mos	20-Nov-2022			
Complied With	AT MANUFACTURE		Hrs	0			
			Ldg	0			
G25-20122	FMS PERFORMANCE DATABASE UPDATE - DUE ENGINE DECK #17 IMPLEMENTATION, MODIFICATION					RE (-)	
 0 A/F			Mos	20-Nov-2022			
Complied With	AT MANUFACTURE		Hrs	0			
			Ldg	0			

Task No		Description				Categories	Time
SEQ	PN/SN	MOC Note		CW	REQ	TOL	DUE Remaining
G25-20123		FMS VSPEEDS DATABASE UPDATE - DUE ENGINE DECK #17 IMPLEMENTATION, MODIFICATION					RE (-)
	0 A/F			Mos	20-Nov-2022		
	Complied With	AT MANUFACTURE		Hrs	0		
				Ldg	0		
G25-20124		MFG. IMPROVEMENT -PANELS 5 & 6, FWD FUSELAGE LHS & RHS PANELS (FASTENERS CHANGE), MODIFICATION					RE (-)
	0 A/F			Mos	20-Nov-2022		
	Complied With	AT MANUFACTURE		Hrs	0		
				Ldg	0		
G25-20128		DGCU AMDT E - PBIT SOFTWARE CHANGE AND GAIA CONVERTER MODIFICATIONS, MODIFICATION					RE (-)
	0 A/F			Mos	20-Nov-2022		
	Complied With	AT MANUFACTURE		Hrs	0		
				Ldg	0		
G25-20129		IMS-6000 SOFTWARE UPDATE, MODIFICATION					RE (-)
	0 A/F			Mos	20-Nov-2022		
	Complied With	AT MANUFACTURE		Hrs	0		
				Ldg	0		
G25-20130		G280 APU 36-150[IAI] COMPRESSOR SEAL IMPROVEMENT, MODIFICATION					RE (-)
	0 A/F			Mos	20-Nov-2022		
	Complied With	AT MANUFACTURE		Hrs	0		
				Ldg	0		
G25-20131		BAGGAGE COMPARTMENT LINERS -INSULATION FOAM USE OF NEW MATERIAL, MODIFICATION					RE (-)
	0 A/F			Mos	20-Nov-2022		
	Complied With	AT MANUFACTURE		Hrs	0		
				Ldg	0		
G25-20132		FORWARD FUEL TANK - ACCESS PANELS JUMPER ATTACHMENTS SEALING IMPROVEMENT, MODIFICATION					RE (-)
	0 A/F			Mos	20-Nov-2022		
	Complied With	AT MANUFACTURE		Hrs	0		
				Ldg	0		
G25-20133		TSSA-4100 REPLACEMENT, MODIFICATION					RE (-)
	0 A/F			Mos	20-Nov-2022		
	Complied With	AT MANUFACTURE		Hrs	0		
				Ldg	0		
G25-20134		CHANGE P/N OF SCOTCHMATE IN THE BC LINERS PANELS WAS: SJ3586FR AND SJ3587FR NOW: SJ3519FRAND SJ3518FR ALTERNATIVE, MODIFICATION					RE (-)
	0 A/F			Mos	20-Nov-2022		
	Complied With	AT MANUFACTURE		Hrs	0		
				Ldg	0		
G25-20135		VERTICAL STABILIZER RIBS - ENLARGE LIGHTENING HOLES AND CANCEL CHEMICAL MILLING, MODIFICATION					RE (-)
	0 A/F			Mos	20-Nov-2022		
	Complied With	AT MANUFACTURE		Hrs	0		
				Ldg	0		
G25-20136		HORIZONTAL STABILIZER LEADING EDGE CHEMICAL MILLING CANCELLATION AND MATERIAL CHANGE FOR COST REDUCTION, MODIFICATION					RE (-)
	0 A/F			Mos	20-Nov-2022		
	Complied With	AT MANUFACTURE		Hrs	0		
				Ldg	0		
G25-20137		MAIN ENTRANCE DOOR- AIRSTAIRS- ADD A STORAGE BOX, MODIFICATION					RE (-)
	0 A/F			Mos	20-Nov-2022		
	Complied With	AT MANUFACTURE		Hrs	0		
				Ldg	0		
G25-20138		FPCU ODC SOFTWARE CHANGE & FIDEX HARDWARE CHANGE, MODIFICATION					RE (-)
	0 A/F			Mos	20-Nov-2022		
	Complied With	AT MANUFACTURE		Hrs	0		
				Ldg	0		

Task No	Description				Categories	Time	
SEQ	PN/SN	MOC Note	CW	REQ	TOL	DUE	Remaining
G25-20139	ALLEVIATE SHOT PEENING PROCESS IN BRACE FITTING NLG BAY, MODIFICATION					RE (-)	
 0 A/F Complied With	AT MANUFACTURE		Mos	20-Nov-2022			
			Hrs	0			
			Ldg	0			
G25-20140	HIGH LEVEL SENSOR (HLS) - RESIN REPLACEMENT FROM SCOTCHCSST N8 TO DURALCO 4525., MODIFICATION					RE (-)	
 0 A/F Complied With	AT MANUFACTURE		Mos	20-Nov-2022			
			Hrs	0			
			Ldg	0			
G25-20141	GPS-4000S REPLACEMENT, MODIFICATION					RE (-)	
 0 A/F Complied With	AT MANUFACTURE		Mos	20-Nov-2022			
			Hrs	0			
			Ldg	0			
G25-20143	BLANKET ADHESIVE TAPE OBSOLESCENCE FOR FERRY KITS, MODIFICATION					RE (-)	
 0 A/F Complied With	AT MANUFACTURE		Mos	20-Nov-2022			
			Hrs	0			
			Ldg	0			
G25-20144	CHANGE HYDRAULIC TUBES MATERIAL - COST REDUCTION, MODIFICATION					RE (-)	
 0 A/F Complied With	AT MANUFACTURE		Mos	20-Nov-2022			
			Hrs	0			
			Ldg	0			
G25-20145	G25-20145 , Modification					RE (-)	
 0 A/F Complied With	AT MANUFACTURE		Mos	20-Nov-2022			
			Hrs	0			
			Ldg	0			
G25-20146	AUX BHD WEBS - CHANGE MATERIAL FROM COMPOSITE TO MACHINED ALUMINUM, MODIFICATION					RE (-)	
 0 A/F Complied With	AT MANUFACTURE		Mos	20-Nov-2022			
			Hrs	0			
			Ldg	0			
G25-20147	AFT FUSELAGE INSULATION FOAM ON SKIN -REVISED 168 AM JEHIER, MODIFICATION					RE (-)	
 0 A/F Complied With	AT MANUFACTURE		Mos	20-Nov-2022			
			Hrs	0			
			Ldg	0			
G25-20148	CENTER FUSELAGE- KEEPING TOOLING HOLES AND KEY HOLES UNPLUGGED IN INTERCOSTAL, MODIFICATION					RE (-)	
 0 A/F Complied With	AT MANUFACTURE		Mos	20-Nov-2022			
			Hrs	0			
			Ldg	0			
G25-20149	INCORPORATION OF THALES STARTER GENERATOR P/N G3666-400, MODIFICATION					RE (-)	
 0 A/F Complied With	AT MANUFACTURE		Mos	20-Nov-2022			
			Hrs	0			
			Ldg	0			
G25-20150	RUDDER PEDALS - USE ALUMINUM AS ALTERNATIVE MATERIAL, MODIFICATION					RE (-)	
 0 A/F Complied With	AT MANUFACTURE		Mos	20-Nov-2022			
			Hrs	0			
			Ldg	0			
G25-20152	STANDBY FLIGHT INSTRUMENT SYSTEM SFIS-3900 REPLACEMENT, MODIFICATION					RE (-)	
 0 A/F Complied With	AT MANUFACTURE		Mos	20-Nov-2022			
			Hrs	0			
			Ldg	0			
G25-20153	FMS DISABLE ETP FEATURE, MODIFICATION					RE (-)	
 0 A/F Complied With	AT MANUFACTURE		Mos	20-Nov-2022			
			Hrs	0			
			Ldg	0			

Task No	Description								
SEQ	PN/SN	MOC Note		CW	REQ	TOL	Categories	Time	
							DUE	Remaining	
G25-20154		FORWARD FUSELAGE - REMOVE REQUIREMENT TO PLUG A CERTAIN KEY HOLE AND CERTAIN TOOLING HOLES, MODIFICATION					RE (-)		
 0 A/F				Mos	20-Nov-2022				
Complied With		AT MANUFACTURE		Hrs	0				
				Ldg	0				
G25-20156		A/P SERVO CABLES - SUBSTITUTE FOR OBSOLETE PART, MODIFICATION					RE (-)		
 0 A/F				Mos	20-Nov-2022				
Complied With		AT MANUFACTURE		Hrs	0				
				Ldg	0				
G25-20157		REVISED EDGE SEAL ON G280 COMPOSITE FLOOR PANELS, MODIFICATION					RE (-)		
 0 A/F				Mos	20-Nov-2022				
Complied With		AT MANUFACTURE		Hrs	0				
				Ldg	0				
G25-20161		EMP EMI FILTER TERMINAL CONNECTIONS INSTALLATION CHANGE, MODIFICATION					RE (-)		
 0 A/F				Mos	20-Nov-2022				
Complied With		AT MANUFACTURE		Hrs	0				
				Ldg	0				
G25-20163		BC DOOR FILLER PADS NEW MATERIAL AND FLAMMABILITY TEST, MODIFICATION					RE (-)		
 0 A/F				Mos	20-Nov-2022				
Complied With		AT MANUFACTURE		Hrs	0				
				Ldg	0				
G25-20165		MFSA PAINT REMOVAL, MODIFICATION					RE (-)		
 0 A/F				Mos	20-Nov-2022				
Complied With		AT MANUFACTURE		Hrs	0				
				Ldg	0				
G25-20166		Mfsa Piston Seal And Rod End Bearing Redesign, Modification					RE (-)		
 0 A/F				Mos	20-Nov-2022				
Complied With		AT MANUFACTURE		Hrs	0				
				Ldg	0				
G25-20172		ECS LUGS ALTERNATIVE MATERIAL, CHANGE FROM CAST TO MACHINED LUGS, MODIFICATION					RE (-)		
 0 A/F				Mos	20-Nov-2022				
Complied With		AT MANUFACTURE		Hrs	0				
				Ldg	0				
G25-20173		Cvr Crew Ares Microphone (Cam) Replacement, Modification					RE (-)		
 0 A/F				Mos	20-Nov-2022				
Complied With		AT MANUFACTURE		Hrs	0				
				Ldg	0				
G25-20174		ECS SUPP BRACKET PN 2002 ATTEM MAT'L & PROD METHOD, MODIFICATION					RE (-)		
 0 A/F				Mos	20-Nov-2022				
Complied With		AT MANUFACTURE		Hrs	0				
				Ldg	0				
G25-20177		NEW WEATHER RADAR RTA-4218, WITH SDDDED PWS (PREDICTIVE WINDSHEAR) AND VWX (VERTICAL WEATHR) CAPABILITIES, MODIFICATION					RE (-)		
 0 A/F				Mos	20-Nov-2022				
Complied With		AT MANUFACTURE		Hrs	0				
				Ldg	0				
G25-20178		Fft- Relocation Of Stiffener On Forward Fuel Tank, Modification					RE (-)		
 0 A/F				Mos	20-Nov-2022				
Complied With		AT MANUFACTURE		Hrs	0				
				Ldg	0				
G25-20179		G25-20179 , MODIFICATION					RE (-)		
 0 A/F				Mos	20-Nov-2022				
Complied With		AT MANUFACTURE		Hrs	0				
				Ldg	0				

Task No SEQ PN/SN	Description MOC Note	CW	REQ	TOL	Categories DUE	Time Remaining
G25-20180	G25-20180 , Modification				RE (-)	
 0 A/F		Mos	20-Nov-2022			
Complied With	AT MANUFACTURE	Hrs	0			
		Ldg	0			
G25-20181	G25-20181 , Modification				RE (-)	
 0 A/F		Mos	20-Nov-2022			
Complied With	AT MANUFACTURE	Hrs	0			
		Ldg	0			
G25-20184	Gps-400S Software Update (Tso) , Modification				RE (-)	
 0 A/F		Mos	20-Nov-2022			
Complied With	AT MANUFACTURE	Hrs	0			
		Ldg	0			
G25-20185	New Ecs Insulation Blankets From Jahier, Modification				RE (-)	
 0 A/F		Mos	20-Nov-2022			
Complied With	AT MANUFACTURE	Hrs	0			
		Ldg	0			
G25-20187	G25-20187 , Modification				RE (-)	
 0 A/F		Mos	20-Nov-2022			
Complied With	AT MANUFACTURE	Hrs	0			
		Ldg	0			
G25-20189	G25-20189 , Modification				RE (-)	
 0 A/F		Mos	20-Nov-2022			
Complied With	AT MANUFACTURE	Hrs	0			
		Ldg	0			
G25-20191	Potable Water Control Unit Sw Change For Improved Quantity Indication Accuracy, Modification				RE (-)	
 0 A/F		Mos	20-Nov-2022			
Complied With	AT MANUFACTURE	Hrs	0			
		Ldg	0			
G25-20193	Heating Control Module Software Changes, Modification				RE (-)	
 0 A/F		Mos	20-Nov-2022			
Complied With	AT MANUFACTURE	Hrs	0			
		Ldg	0			
G25-20196	New Thermal Anti Ice Valve With Improved Reliability, Modification				RE (-)	
 0 A/F		Mos	20-Nov-2022			
Complied With	AT MANUFACTURE	Hrs	0			
		Ldg	0			
G25-20201	G25-20201 , Modification				RE (-)	
 0 A/F		Mos	20-Nov-2022			
Complied With	AT MANUFACTURE	Hrs	0			
		Ldg	0			
G25-20702	WING UPPER SKIN - INCREASE CHEM MILL POCKET (DECREASE RADIUS OF CORNERSS) AND REDUCE ALLOWED FLAP TRACK SHIM GAP, MODIFICATION				RE (-)	
 0 A/F		Mos	20-Nov-2022			
Complied With	AT MANUFACTURE	Hrs	0			
		Ldg	0			
G25-20703	WING LOWER SKIN - DECREASE CHEM MILL CORNER RADIUSSES & ADD CHAMFER TO NACA SCOOP HOLE CIRCUMFERENCE, MODIFICATION				RE (-)	
 0 A/F		Mos	20-Nov-2022			
Complied With	AT MANUFACTURE	Hrs	0			
		Ldg	0			
G25-20706	MODELLING OF RIB 00, MODIFICATION				RE (-)	
 0 A/F		Mos	20-Nov-2022			
Complied With	AT MANUFACTURE	Hrs	0			
		Ldg	0			

Task No SEQ PN/SN	Description MOC Note	CW	REQ	TOL	Categories DUE	Time Remaining
G25-20707	TRIM UP TO .24" FROM AFT EDGE OF LOWER SKIN TO ENSURE CLEARANCE WITH AIRLERON - 2005-2014 TO BE REWORKED TBD BY UPDATE TO ECP, MODIFICATION				RE (-)	
 0 A/F Complied With	AT MANUFACTURE	Mos	20-Nov-2022			
		Hrs	0			
		Ldg	0			
G25-20709	AILERON BALANCE WEIGHT - MASS OPTIMIZATION, MODIFICATION				RE (-)	
 0 A/F Complied With	AT MANUFACTURE	Mos	20-Nov-2022			
		Hrs	0			
		Ldg	0			
G25-20713	TRIM MATERIAL FROM TRACK C LOWER, MODIFICATION				RE (-)	
 0 A/F Complied With	AT MANUFACTURE	Mos	20-Nov-2022			
		Hrs	0			
		Ldg	0			
G25-20716	CHANGE FLAP TRACK D MATERIAL, MODIFICATION				RE (-)	
 0 A/F Complied With	AT MANUFACTURE	Mos	20-Nov-2022			
		Hrs	0			
		Ldg	0			
G25-20717	REVISE FASTENERS AT TRACK B OUTBOARD ROLLER, MODIFICATION				RE (-)	
 0 A/F Complied With	AT MANUFACTURE	Mos	20-Nov-2022			
		Hrs	0			
		Ldg	0			
G25-20718	MODIFY HOLE IN SIDF BRACE FOR BARREL NUTS AND FASTENER CHANGE, MODIFICATION				RE (-)	
 0 A/F Complied With	AT MANUFACTURE	Mos	20-Nov-2022			
		Hrs	0			
		Ldg	0			
G25-20719	REDUCE SPOILER HINGE BOLT TORQUE, MODIFICATION				RE (-)	
 0 A/F Complied With	AT MANUFACTURE	Mos	20-Nov-2022			
		Hrs	0			
		Ldg	0			
G25-20721	ADD DRAIN HOLE IN DRY BAY IN WING TORSION BOX, MODIFICATION				RE (-)	
 0 A/F Complied With	AT MANUFACTURE	Mos	20-Nov-2022			
		Hrs	0			
		Ldg	0			
G25-20722	AFT SPONSON BEAM BEARING INSTALLATION IMPROVEMENTS, MODIFICATION				RE (-)	
 0 A/F Complied With	AT MANUFACTURE	Mos	20-Nov-2022			
		Hrs	0			
		Ldg	0			
G25-20723	FUEL SYSTEM-SINGLE MOTOR ACTUATOR MODIFICATION, MODIFICATION				RE (-)	
 0 A/F Complied With	AT MANUFACTURE	Mos	20-Nov-2022			
		Hrs	0			
		Ldg	0			
G25-20725	CHANGE FLAP TRACK 8 & C ROLLER FITTINGS CONFIGURATION AND MATERIAL, MODIFICATION				RE (-)	
 0 A/F Complied With	AT MANUFACTURE	Mos	20-Nov-2022			
		Hrs	0			
		Ldg	0			
G25-20726	FEED TANK BRACKETS - ENLARGE CORNER HOLES TO PREVENT LOAD TRANSFER, MODIFICATION				RE (-)	
 0 A/F Complied With	AT MANUFACTURE	Mos	20-Nov-2022			
		Hrs	0			
		Ldg	0			

Task No	Description								
SEQ	PN/SN	MOC Note		CW	REQ	TOL	Categories	Time	
							DUE	Remaining	
G25-20728		UPDATE ACCESS PANEL CONFIGURATION TO SATISFY TCCA CERTIFICATION REQUIREMENTS., MODIFICATION					RE (-)		
 0 A/F				Mos	20-Nov-2022				
Complied With		AT MANUFACTURE		Hrs	0				
				Ldg	0				
G25-20729		INCREASED CLEARANCE REQUIRED FOR FLAP ROLLERS, MODIFICATION					RE (-)		
 0 A/F				Mos	20-Nov-2022				
Complied With		AT MANUFACTURE		Hrs	0				
				Ldg	0				
G25-20730		FLAP TRACK C OUTBD MID-FLANGE ADDITIONAL CHAMFER REWORK, MODIFICATION					RE (-)		
 0 A/F				Mos	20-Nov-2022				
Complied With		AT MANUFACTURE		Hrs	0				
				Ldg	0				
G25-20731		CREATE NEW METAL OUTBD FTE INSTEAD OF EXISTING COMPOSITE PART TO REDUCE MRBS DURING WING PRODUCTION., MODIFICATION					RE (-)		
 0 A/F				Mos	20-Nov-2022				
Complied With		AT MANUFACTURE		Hrs	0				
				Ldg	0				
G25-20733		GROUND SPOILER ACTUATOR ATTACHMENT HARDWARE CHANGE, MODIFICATION					RE (-)		
 0 A/F				Mos	20-Nov-2022				
Complied With		AT MANUFACTURE		Hrs	0				
				Ldg	0				
G25-20734		WIRING BUTTERFLY CLIPS MODIFICATIONS FOR EASE OF FASTENER INSTALLATION AND IMPROVED FATIGUE RESISTANCE, MODIFICATION					RE (-)		
 0 A/F				Mos	20-Nov-2022				
Complied With		AT MANUFACTURE		Hrs	0				
				Ldg	0				
G25-20735		MINIMAZE STEP ISSUE FROM WINGTET TO WING SKIN TO EASE MANUFACTURING, MODIFICATION					RE (-)		
 0 A/F				Mos	20-Nov-2022				
Complied With		AT MANUFACTURE		Hrs	0				
				Ldg	0				
G25-20736		ADDITIONAL AILERON WEIGHT CLEARANCE FOR INBOARD SIDE, MODIFICATION					RE (-)		
 0 A/F				Mos	20-Nov-2022				
Complied With		AT MANUFACTURE		Hrs	0				
				Ldg	0				
G25-20737		TRACK A - LOWER TURN DOWN HOOKS TO AN OPTIMA) LEVEL TO PREVENT FLAP NON SMOOTH MOVEMENTS, MODIFICATION					RE (-)		
 0 A/F				Mos	20-Nov-2022				
Complied With		AT MANUFACTURE		Hrs	0				
				Ldg	0				
G25-20738		FLAP UPPER MID SKIN- INCREASE CUTOUT AT SPOILER 3 POCKET TO PREVENT STRESS CONCENTRATION, MODIFICATION					RE (-)		
 0 A/F				Mos	20-Nov-2022				
Complied With		AT MANUFACTURE		Hrs	0				
				Ldg	0				
G25-20739		WING-INBD UPPER SKIN - MATERIAL CHANGE, MODIFICATION					RE (-)		
 0 A/F				Mos	20-Nov-2022				
Complied With		AT MANUFACTURE		Hrs	0				
				Ldg	0				
G25-20740		REDUCE BOSS ON INBOARD TRACK A ROLLER FITTING TO MATCH OUTBOARD ROLLER FITTING CONFIGURATION, MODIFICATION					RE (-)		
 0 A/F				Mos	20-Nov-2022				
Complied With		AT MANUFACTURE		Hrs	0				
				Ldg	0				
G25-20741		FEED TANK BRACKET ATTACH TO STRINGER 3 - ADD COLD WORK, MODIFICATION					RE (-)		
 0 A/F				Mos	20-Nov-2022				
Complied With		AT MANUFACTURE		Hrs	0				
				Ldg	0				

Task No SEQ PN/SN	Description MOC Note	CW	REQ	TOL	Categories DUE	Time Remaining
G25-20742	RIB 2 CUTOUT FOR STRINGER - MODIFY TO IMPROVE FATIGUE RESISTANCE, MODIFICATION		RE (-)			
 0 A/F		Mos	20-Nov-2022			
Complied With	AT MANUFACTURE	Hrs	0			
		Ldg	0			
▼ 4 - AIRCRAFT STATS / LIMITATIONS						
IL ISR-I-04-2020-06-02 R01	Revision Of Table 9 - Temporary Limitations And Inspection Requirements Of The Section 05-10-10 (Airworthiness Limitations Section) Of The G280 Airplane Maintenance Manual- Addition Of Awl-3 Task (Mandatory)		RE (-)			
 4 A/F		Mos	09-Nov-2022			
Complied With	AWL-3 TASK ADDED TO TABLE 9 OF ALS 05-10-10	Hrs				
		Ldg				
▼ 5 - TIME LIMITS/MAINTENANCE CHECKS						
ISR-I-04-2020-06-02	Revision of Table 9 - Temporary Limitations and Inspection Requirements of the Section 05-10-10 (Airworthiness Limitations Section) of the G280 Airplane Maintenance Manual - Addition of AWL-3 Task		RE (-)		Mandatory	
 5 A/F		Mos	10-Feb-2023			
Eff: 28-Jun-2020 Complied With	AWL-3 TASK ADDED TO TABLE 9 OF G280 AIRPLANE MAINTENANCE MANUALS SECTION 05-10-10 (AIRWORTHINESS LIMITATIONS SECTION)	Hrs	24:24			
		Ldg	7			
▼ 11 - PLACARDS AND MARKINGS						
280-11-028	Placards And Markings - Exterior Placards And Markings - Relocation Of "After Maintenance / Test Verify That Pitot / Static Drains Are Positively Closed" Placard (MODG25-0029)		RE (-)		Recommended	
 11 A/F		Mos	10-Feb-2023			
Eff: 23-Aug-2013 Not Applicable	PER AIRCRAFT SERIAL NUMBER	Hrs	24:24			
		Ldg	7			
280-11-035	Placards And Markings - Replacement Of Existing Bottle Preload Pressure, Reservoir Fill And Hydraulic Reservoir LHS / RHS Placards With New Placards (MODG25-00241)		RE (-)		Recommended	
 11 A/F		Mos	10-Feb-2023			
Eff: 23-Aug-2013 Not Applicable	PER AIRCRAFT SERIAL NUMBER	Hrs	24:24			
		Ldg	7			
280-11-088	Placards And Markings - Replacement Of Existing Life Line , Raft Line Attach Point Placards With New Placards (MODG25-00443)		RE (-)		Recommended	
 11 A/F		Mos	10-Feb-2023			
Eff: 28-Feb-2014 Not Applicable	PER AIRCRAFT SERIAL NUMBER	Hrs	24:24			
		Ldg	7			
280-11-160	Placards And Markings - Interior Placards And Markings - Removal Of Placards Prohibiting Wing Anti-Ice Auto Mode Operation (MODG25-20073)		RE (-)		Recommended	
 11 A/F		Mos	10-Feb-2023			
Eff: 19-Jan-2015 Not Applicable	PER AIRCRAFT SERIAL NUMBER	Hrs	24:24			
		Ldg	7			
280-11-252	Placards and Markings - Baggage Compartment Access Above 40,000 Feet (12,192 M)		RE (-)		Optional	
 11 A/F		Mos				
Eff: 12-Aug-2020		Hrs				
		Ldg				
280-11-337	Placards and Markings (ATA 11) - APU Fire Detector Loops - APU Fire Detector Wires Labeling Change		T (-)		Recommended	
 11 A/F		Mos				
Eff: 18-Sep-2025		Hrs				
		Ldg				
280-11-337 Rev 1	Placards and Markings - APU Fire Detector Loops - APU Fire Detector Wires Labeling Change		T		Recommended	
 11 A/F		Mos	36		15-May-2029	2.7 Years
Eff: 15-May-2026		Hrs				
		Ldg				

Task No		Description				Categories	Time
SEQ	PN/SN	MOC Note	CW	REQ	TOL	DUE	Remaining
▼ 21 - AIR CONDITIONING AND PRESSURIZATION							
280-21-315		Air Conditioning - Cabin Pressurization - Reduce Cabin Altitude to 5800ft Configuration		T (-)		Optional	
	21 A/F						
	Eff: 27-Mar-2026						
			Mos				
			Hrs				
			Ldg				
280-21-315 Rev 1		Air Conditioning - Cabin Pressurization - Reduce Cabin Altitude to 5800ft Configuration		T (-)		Optional	
	21 A/F						
	Eff: 02-Jul-2026						
			Mos				
			Hrs				
			Ldg				
280-21-315 Rev 2		Air Conditioning - Cabin Pressurization - Reduce Cabin Altitude Modification		T (A/R)		Optional	
	21 A/F						
	Eff: 30-Jul-2026						
			Mos				
			Hrs				
			Ldg				
▼ 23 - COMMUNICATIONS							
2013-18-09		HONEYWELL ASCA INC - Emergency Locator Transmitter - Battery Wiring Discrepancies (Superseded by FAA AD 2014-17-02)		RE (-)		Mandatory (Appliance AD)	
	23 A/F						
	Not Applicable	NOT INSTALLED					
			Mos	10-Feb-2023			
			Hrs	24:24			
			Ldg	7			
2014-17-02		Communications - ELT Model RESCU 406AF and 406AFN (This AD Replaces AD 2013-18-09)		RE (-)		Mandatory (Appliance AD)	
	23 A/F						
	Eff: 09-Sep-2014 Not Applicable	NOT INSTALLED					
			Mos	10-Feb-2023			
			Hrs	24:24			
			Ldg	7			
280-23-003		Communications - Audio System - Installation Of Third Audio System (MODG25- 10004)		RE (-)		Optional	
	23 A/F						
	Eff: 13-Nov-2012						
			Mos				
			Hrs				
			Ldg				
280-23-003 Rev 1		Communications - Audio System - Installation of Third Audio System		T (-)		Optional	
	23 A/F						
	Eff: 20-Dec-2013						
			Mos				
			Hrs				
			Ldg				
280-23-003 Rev 2		Communications - Audio System - Installation of Third Audio System		RE (-)		Optional	
	23 A/F						
	Eff: 01-Sep-2021 Complied With						
			Mos	10-Feb-2023			
			Hrs	24:24			
			Ldg	7			
280-23-006		Communications - High Frequency System - Installation of Second HF System		T (-)		Optional	
	23 A/F						
	Eff: 20-Nov-2012						
			Mos				
			Hrs				
			Ldg				
280-23-006 Rev 1		Communications - High Frequency System - Installation of Second HF System		T (-)		Optional	
	23 A/F						
	Eff: 20-Dec-2013						
			Mos				
			Hrs				
			Ldg				
280-23-006 Rev 2		Communications - High Frequency System - Installation of Second HF System		RE (-)		Optional	
	23 A/F						
	Eff: 01-Sep-2021 Complied With						
			Mos	10-Feb-2023			
			Hrs	24:24			
			Ldg	7			
280-23-007		Communications - Datalink System - Audio Integrating - Installation of Second Datalink System		T (-)		Optional	
	23 A/F						
	Eff: 21-Nov-2012						
			Mos				
			Hrs				
			Ldg				

Task No SEQ PN/SN	Description MOC Note		CW	REQ	TOL	Categories DUE	Time Remaining
280-23-007 Rev 1 23 A/F Eff: 31-Oct-2013	Communications - Datalink System - Audio Integrating - Installation of Second Datalink System			T (-)		Optional	
		Mos					
		Hrs					
		Ldg					
280-23-007 Rev 2 23 A/F Eff: 01-Jun-2015	Communications - Datalink System - Audio Integrating - Installation of Second Datalink System			T (-)		Optional	
		Mos					
		Hrs					
		Ldg					
280-23-007 Rev 3 23 A/F Eff: 01-Sep-2021 Complied With	Communications - Datalink System - Audio Integrating - Installation of Second Datalink System			RE (-)		Optional	
		Mos	10-Feb-2023				
		Hrs	24:24				
		Ldg	7				
280-23-320 23 A/F Not Applicable (UPDATE NOTE: N/A by SN of the aircraft)	Communications - Inspection and Replacement of VIASAT GAT-5510 Ka-Band Antenna			RE (-)		Recommended	
		Mos	29-Nov-2023		-/+1m		
		Hrs					
		Ldg					
280-23-336 23 A/F Eff: 25-Jul-2025	Communications - Datalink Radio Interface Unit (RIU-4010) - Upgrade			T (A/R)		Optional	
		Mos					
		Hrs					
		Ldg					
▼ 24 - ELECTRICAL POWER							
280-24-037 24 A/F Eff: 26-Apr-2013 Not Applicable	Electrical Power - DC Electrical Load Distribution - Replacement Of Existing Left, Right And Emergency DC Boxes (MODG25-20040)			RE (-)		Recommended	
	PER AIRCRAFT SERIAL NUMBER	Mos	10-Feb-2023				
		Hrs	24:24				
		Ldg	7				
280-24-061 24 A/F Eff: 16-May-2013 Not Applicable	Electrical Power - APU Starter - Generator Cables - Inspection - Sealing Rework (30P817582002)			RE (-)		Recommended	
	PER AIRCRAFT SERIAL NUMBER	Mos	10-Feb-2023				
		Hrs	24:24				
		Ldg	7				
280-24-073 24 A/F Eff: 30-Oct-2015 Not Applicable	Electrical Power - Addition Of Electrical Bonding On Forward Fuselage Structure Between Column Assembly And Seat Track (MODG25-00342)			RE (-)		Recommended	
	PER AIRCRAFT SERIAL NUMBER	Mos	10-Feb-2023				
		Hrs	24:24				
		Ldg	7				
280-24-075 24 A/F Eff: 17-Jan-2014 Not Applicable	Electrical Power - Harness 1302 - Local Split And Rerouting Above Forward Right Side Radio Rack (MODG25-00389)			RE (-)		Recommended	
	PER AIRCRAFT SERIAL NUMBER	Mos	10-Feb-2023				
		Hrs	24:24				
		Ldg	7				
280-24-077 24 A/F Eff: 04-Oct-2013 Not Applicable	Electrical Power - Wing Center Tank Fluid Quantity Measurement System (FQMS) - Wire Harness Installation Verification/Retrofit (MODG25-07092)			RE (-)		Mandatory	
	PER AIRCRAFT SERIAL NUMBER	Mos	10-Feb-2023				
		Hrs	24:24				
		Ldg	7				
280-24-080 24 A/F Eff: 21-Jun-2013 Not Applicable	Electrical Power - Cabin Power Bus Controller (CPBC) , Galley Power Bus Controller (GPBC)- Feeder Cable - Inspection			RE (-)		Recommended	
	PER AIRCRAFT SERIAL NUMBER	Mos	10-Feb-2023				
		Hrs	24:24				
		Ldg	7				

Task No SEQ PN/SN	Description MOC Note		CW	REQ	TOL	Categories DUE	Time Remaining
280-24-085	Electrical Power - DC Generation - Replacement of the Existing APU Digital Generator Control Unit (DGPU) MODS A and B with an Upgraded DGPU, MOD D (MODG25-20050)			RE (-)		Recommended	
 24 A/F Eff: 12-Jan-2016 Not Applicable	as per A/C S/N		Mos 19-Apr-2023				
			Hrs 124:16				
			Ldg 71				
280-24-085 Rev 1	Electrical Power - DC Generation - Replacement of the Existing APU Digital Generator Control Unit (DGPU) MODS A and B with an Upgraded DGPU, MOD D (MODG25-20050)			RE (-)		Recommended	
 24 A/F Eff: 28-Feb-2017 Not Applicable	PER AIRCRAFT SERIAL NUMBER		Mos 10-Feb-2023				
			Hrs 24:24				
			Ldg 7				
280-24-115	Electrical Power - Cabin Power Bus Controller (CPBC) - Feeder And Supply Cable - Replacement Of Terminal Lug			RE (-)		Recommended	
 24 A/F Eff: 21-Nov-2013 Not Applicable	PER AIRCRAFT SERIAL NUMBER		Mos 10-Feb-2023				
			Hrs 24:24				
			Ldg 7				
280-24-194	Electrical Power - Left Hand Distribution Bus - Add New Logic For Dual Generators Failure			RE (-)		Optional	
 24 A/F Eff: 09-Jun-2018			Mos				
			Hrs				
			Ldg				
280-24-201	Electrical Power - Inspection Of Left And Right Main Battery Bay - Fuse Holder Installation (MODG25-01156)			RE (-)		Recommended	
 24 A/F Eff: 16-Oct-2015 Not Applicable	PER AIRCRAFT SERIAL NUMBER		Mos 10-Feb-2023				
			Hrs 24:24				
			Ldg 7				
280-24-207	Electrical Power - Emergency Battery System - Impact Switch Installation Modification			RE (A/R)		Recommended	
 24 A/F Eff: 18-Mar-2016 Not Applicable	PER AIRCRAFT SERIAL NUMBER		Mos 10-Feb-2023				
			Hrs 24:24				
			Ldg 7				
280-24-208	Electrical Power - Cabin Amplifier - Fault Protection For Cabin Power Bus Controller Improvement			RE (-)		Recommended	
 24 A/F Eff: 18-Mar-2016 Not Applicable	PER AIRCRAFT SERIAL NUMBER		Mos 10-Feb-2023				
			Hrs 24:24				
			Ldg 7				
280-24-209	Electrical Power - DC Generation - Replacement Of The Existing Engines Digital Generator Control Unit (DGPU) MODS A And B With An Upgraded DGPU MOD D (MODG25-20077)			RE (-)		Recommended	
 24 A/F Eff: 12-Jan-2016 Not Applicable	as per A/C S/N		Mos 19-Apr-2023				
			Hrs 124:16				
			Ldg 71				
280-24-209 Rev 1	Electrical Power - DC Generation - Replacement of the Existing Engines Digital Generator Control Unit (DGPU) MODS A and B with an Upgraded DGPU MOD D (MOD G25-20077)			RE (-)		Recommended	
 24 A/F Eff: 28-Feb-2017 Not Applicable	PER AIRCRAFT SERIAL NUMBER		Mos 10-Feb-2023				
			Hrs 24:24				
			Ldg 7				
280-24-241	Electrical Power - Refuel/Defuel Panel - Electrical Connector 283Q1 Backshell Repositioning			RE (-)		Recommended	
 24 A/F Eff: 06-Oct-2017 Not Applicable	as per A/C S/N		Mos 19-Apr-2023				
			Hrs 124:16				
			Ldg 71				

Task No	Description	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note				DUE	Remaining
280-24-241 Rev 1	Electrical Power - Refuel/Defuel Panel - Electrical Connector 283Q1 Backshell Repositioning		RE (-)		Recommended	
24 A/F		Mos	10-Feb-2023			
Eff: 10-Apr-2018 Not Applicable	PER AIRCRAFT SERIAL NUMBER	Hrs	24:24			
		Ldg	7			
280-24-251	Electrical Power (ATA 24) - DC Generation - Replacement of the Existing Engine and APU Digital Generator Control Unit (DGPU) MOD's A, B, C and/or D with an Upgraded DGPU, MOD E		RE (-)		Recommended	
24 A/F		Mos	10-Feb-2023			
Eff: 29-Sep-2017 Not Applicable	PER AIRCRAFT SERIAL NUMBER	Hrs	24:24			
		Ldg	7			
ST04469AT	Installation Of The Concorde Lead Acid Battery Rg-380E , SupplementalType Certificate		RE (-)			
24 A/F		Mos	10-Feb-2023			
Complied With		Hrs	24:24			
		Ldg	7			
▼ 25 - EQUIPMENT/FURNISHINGS						
2014-20-11	Zodiac Seats France - Equipment/Furnishings - Seats		RE (-)		Mandatory (Appliance AD)	
25 A/F		Mos	10-Feb-2023			
Eff: 22-Oct-2014 Not Applicable	NOT INSTALLED	Hrs	24:24			
		Ldg	7			
2018-16-13	Zodiac Seats France - 537-Series Cabin Attendant Seats - Safety Belt Webbing - Inspection/ Modification		RE (-)		Mandatory (Appliance AD)	
25 A/F		Mos	10-Feb-2023			
Eff: 26-Oct-2018 Not Applicable	NOT INSTALLED	Hrs	24:24			
		Ldg	7			
2023-12-25	Equipment/Furnishings - Survitec Group Limited (RFD Beaufort Ltd.) Type 102 Mk 3, 102 Mk 4, and 105 Mk 1 Life Jackets		RE (-)		Mandatory	
25 A/F		Mos	10-Aug-2023			
Eff: 23-Aug-2023 Not Applicable		Hrs				
(UPDATE NOTE: N/A by type of the Life Jackets. Current Life Jackets made by ZODIAC AEROSPACE)		Ldg				
2023-12-25 Par. (g)	Equipment/Furnishings - Survitec Group Limited (RFD Beaufort Ltd.) Type 102 Mk 3, 102 Mk 4, and 105 Mk 1 Life Jackets - Inspection		RE (-)		Mandatory	
25 A/F		Mos	10-Aug-2023			
Eff: 23-Aug-2023 Not Applicable		Hrs				
(UPDATE NOTE: N/A by type of the Life Jackets. Current Life Jackets made by ZODIAC AEROSPACE)		Ldg				
2023-12-25 Par. (h)	Equipment/Furnishings - Survitec Group Limited (RFD Beaufort Ltd.) Type 102 Mk 3, 102 Mk 4, and 105 Mk 1 Life Jackets - Follow-On and Corrective Action		RE (-)		Mandatory	
25 A/F		Mos	10-Aug-2023			
Eff: 23-Aug-2023 Not Applicable		Hrs				
(UPDATE NOTE: N/A by type of the Life Jackets. Current Life Jackets made by ZODIAC AEROSPACE)		Ldg				
2023-14-10	Flight Compartment Equipment - Ipeco Holdings Limited (Ipeco) Pilot and Co-Pilot Seats (Supersedes FAA AD 2019-21-06)		RE (-)		Mandatory (Appliance AD)	
25 A/F		Mos	10-Aug-2023			
Eff: 07-Sep-2023 Not Applicable		Hrs				
(UPDATE NOTE: N/A by SN of the pilot/co-pilot seats)		Ldg				
2023-14-10 Par. (g)(1)	Flight Compartment Equipment - Ipeco Holdings Limited (Ipeco) Pilot and Co-Pilot Seats - Modify and Re-Identify each Affected Pilot and Co-Pilot Seat		RE (-)		Mandatory (Appliance AD)	
25 A/F		Yrs	10-Aug-2023			
Eff: 12-Dec-2017 Not Applicable		Hrs				
(UPDATE NOTE: N/A by SN of the pilot/co-pilot seats)		Ldg				
2023-14-10 Par. (g)(2)(i)	Flight Compartment Equipment - Ipeco Holdings Limited (Ipeco) Pilot and Co-Pilot Seats - Inspect the Track Lock Spring of Each Seat		RE (-)		Mandatory (Appliance AD)	
25 A/F		Mos	10-Aug-2023			
Not Applicable		Hrs	0			
(UPDATE NOTE: N/A by SN of the pilot/co-pilot seats)		Ldg				

Task No	Description				CW	REQ	TOL	Categories	Time
SEQ	PN/SN	MOC Note						DUE	Remaining
2023-14-10 Par. (g)(2)(ii)		Flight Compartment Equipment - Ipeco Holdings Limited (Ipeco) Pilot and Co-Pilot Seats - Replace both Track Lock Springs of the Affected Seat						RE (-)	Mandatory (Appliance AD)
25 A/F				Mos	10-Aug-2023				
Eff: 07-Sep-2023 Not Applicable				Hrs					
(UPDATE NOTE: N/A by SN of the pilot/co-pilot seats)				Ldg					
2023-14-10 Par. (h)		Flight Compartment Equipment - Ipeco Holdings Limited (Ipeco) Pilot and Co-Pilot Seats - New Mandatory Terminating Action						RE (-)	Mandatory (Appliance AD)
25 A/F				Mos	10-Aug-2023				
Eff: 07-Sep-2023 Not Applicable				Hrs					
(UPDATE NOTE: N/A by SN of the pilot/co-pilot seats)				Ldg					
2024-26-02		Cabin Equipment/Furnishings - Pacific Scientific Company - Buckle Handle (This AD Replaces AD 2021-07-13)						RE (-)	Mandatory (Appliance AD)
25 A/F				Mos	26-Feb-2025				
Eff: 07-Mar-2025 Not Applicable				Hrs					
(UPDATE NOTE: NA by PN of the installed parts)				Ldg					
2024-26-02 Par. (g)(1)		Cabin Equipment/Furnishings - Pacific Scientific Company - Buckle Handle - Inspect for Crack						RE (-)	Mandatory (Appliance AD)
25 A/F				Mos	26-Feb-2025				
Eff: 07-Mar-2025 Not Applicable				Hrs					
(UPDATE NOTE: NA by PN of the installed parts)				Ldg					
2024-26-02 Par. (g)(2)		Cabin Equipment/Furnishings - Pacific Scientific Company - Buckle Handle - Measure the Thickness of the Buckle Handle Vane						RE (-)	Mandatory (Appliance AD)
25 A/F				Mos	26-Feb-2025				
Eff: 07-Mar-2025 Not Applicable				Hrs					
(UPDATE NOTE: NA by PN of the installed parts)				Ldg					
280-25-014		Equipment and Furnishings - Flight Compartment - Flight Compartment Interior Furnishings Installation (MODG25-20004)						RE (-)	Recommended
25 A/F				Mos	10-Feb-2023				
Eff: 13-Nov-2012 Complied With				Hrs	24:24				
				Ldg	7				
280-25-053		Equipment And Furnishings - Baggage Compartment - Light Switch Angle Support Assembly Installation - Rework (MODG25-00319)						RE (-)	Recommended
25 A/F				Mos	19-Apr-2023				
Eff: 12-Dec-2014 Not Applicable	as per A/C S/N			Hrs	124:16				
				Ldg	71				
280-25-053 Rev 1		Equipment And Furnishings - Baggage Compartment - Light Switch Angle Support Assembly Installation - Rework (MODG25-00319)						RE (-)	Recommended
25 A/F				Mos	10-Feb-2023				
Eff: 02-Jul-2015 Not Applicable	PER AIRCRAFT SERIAL NUMBER			Hrs	24:24				
				Ldg	7				
280-25-148		Equipment And Furnishings - Flight Compartment - Installation Of Modification Label On Pilot And Copilot Seats (MODG25-00718)						RE (-)	Recommended
25 A/F				Mos	10-Feb-2023				
Eff: 02-Jul-2015 Not Applicable	PER AIRCRAFT SERIAL NUMBER			Hrs	24:24				
				Ldg	7				
280-25-175		Equipment And Furnishings - Replacement Of Cockpit Airworthiness Certificate Holder						RE (-)	Recommended
25 A/F				Mos	10-Feb-2023				
Eff: 08-May-2015 Not Applicable	PER AIRCRAFT SERIAL NUMBER			Hrs	24:24				
				Ldg	7				
280-25-212		Equipment and Furnishings - Baggage Compartment - Modified Configuration of Baggage Restraining System						RE (-)	Recommended
25 A/F				Mos	10-Feb-2023				
Eff: 23-Apr-2020 Not Applicable	PER AIRCRAFT SERIAL NUMBER			Hrs	24:24				
				Ldg	7				

Task No SEQ PN/SN	Description MOC Note			CW	REQ	TOL	Categories DUE	Time Remaining
280-25-213	Equipment/Furnishings - Emergency Escape Hatch Cabin Management System (CMS) Electrical Connectors - Inspection For Friction Only Installation Of Electrical Connectors				RE (-)		Recommended	
 25 A/F Eff: 11-Dec-2015 Not Applicable	PER AIRCRAFT SERIAL NUMBER		Mos	10-Feb-2023				
			Hrs	24:24				
			Ldg	7				
280-25-220	Equipment / Furnishings - Cabin Window Shade Improvement				RE (-)		Recommended	
 25 A/F Eff: 13-Apr-2016 Not Applicable	PER AIRCRAFT SERIAL NUMBER		Mos	10-Feb-2023				
			Hrs	24:24				
			Ldg	7				
280-25-255	Equipment / Furnishings - Microwave Installation				RE (-)		Optional	
 25 A/F Eff: 20-Nov-2017			Mos					
			Hrs					
			Ldg					
280-25-255 Rev 1	Equipment/Furnishings - Microwave Installation				RE (-)		Optional	
 25 A/F Eff: 22-Aug-2018			Mos					
			Hrs					
			Ldg					
280-25-309	Equipment / Furnishings - Baggage No Entry Sign				RE (-)		Recommended	
 25 A/F Eff: 10-Aug-2022 Not Applicable	PER AIRCRAFT SERIAL NUMBER		Mos	10-Feb-2023				
			Hrs	24:24				
			Ldg	7				
280-25-344	Equipment/Furnishings - Aft Cabin - Cabin Power Bus Controller System Thermistors Charred/Burned				RE (-)		Mandatory	
 25 A/F Eff: 20-Mar-2026 Not Applicable	by Aircraft SN.		Mos					
			Hrs					
			Ldg					
74-08-09 R3 Paragraph (k)	Equipment/furnishings - improper disposal of smoking materials in lavatory waste receptacles - Inspect all lavatory paper and linen waste receptacle enclosure access doors and disposal doors for proper operation, fit, sealing, and latching for the containment of possible trash fires.				RE		Mandatory	≈02-Dec-2027
 25 A/F Eff: 06-Aug-1974 Complied With			Mos	17-Apr-2026				
			Hrs	1887:38	1,000		2887:38	726:41 Hrs
			Ldg	1,073				
▼ 26 - FIRE PROTECTION								
2015-16-04	Fire Protection				RE (-)		Mandatory (Appliance AD)	
 26 A/F Eff: 15-Sep-2015 Not Applicable	NOT INSTALLED		Mos	10-Feb-2023				
			Hrs	24:24				
			Ldg	7				
2017-19-05	Smoke Detection - Inspection / Replacement				RE (-)		Mandatory (Appliance AD)	
 26 A/F Eff: 31-Oct-2017 Not Applicable	PART NUMBER NOT INSTALLED.		Mos	10-Feb-2023				
			Hrs	24:24				
			Ldg	7				
2020-21-02	Fire protection - Kidde Aerospace & Defense - Cargo Fire Extinguisher Halon Bottles				RE (-)		Mandatory (Appliance AD)	
 26 A/F Eff: 19-Nov-2020 Not Applicable	NOT INSTALLED		Mos	10-Feb-2023				
			Hrs	24:24				
			Ldg	7				
280-26-052	Fire Protection - Engine Fire Detection - Correction Of Wiring And Replacement Of Incorrectly Installed Pylon Fire Sensor BRD Labels (MODG25-00321				RE (-)		Recommended	
 26 A/F Eff: 21-Nov-2013 Not Applicable	PER AIRCRAFT SERIAL NUMBER		Mos	10-Feb-2023				
			Hrs	24:24				
			Ldg	7				

Task No SEQ PN/SN	Description MOC Note	CW	REQ	TOL	Categories DUE	Time Remaining
280-26-195	Fire Protection - Fire Protection Control Unit (FPCU) - Replacement of Existing FPCU P/N 30P841300000-001 with New FPCU P/N 30P841300000-003 (MODG25-20095)		RE (-)		Recommended	
 26 A/F Eff: 18-Sep-2015 Not Applicable	as per A/C S/N	Mos Hrs Ldg	19-Apr-2023 124:16 71			
280-26-195 Rev 1	Fire Protection - Fire Protection Control Unit (FPCU) - Replacement of Existing FPCU P/N 30P841300000-001 With New FPCU P/N 30P841300000-003 (MODG25- 20095)		RE (-)		Recommended	
 26 A/F Eff: 10-May-2017 Not Applicable	PER AIRCRAFT SERIAL NUMBER	Mos Hrs Ldg	10-Feb-2023 24:24 7			
280-26-246	Fire Protection - Fire Protection Control Unit (FPCU) - Replacement of Existing FPCUP/N 30P841300000-001 or FPCU P/N 30P841300000-003 with FPCU P/N 30P841300000-005		RE (-)		Recommended	
 26 A/F Eff: 24-Apr-2018 Not Applicable	PER AIRCRAFT SERIAL NUMBER	Mos Hrs Ldg	10-Feb-2023 24:24 7			
280-26-304	Fire Protection - Bleed Leak Detection Sensors - Inspection and Replacement in Aft Service Compartment		RE (-)		Recommended	
 26 A/F Eff: 16-Jun-2023 Not Applicable (UPDATE NOTE: N/A by SN of the aircraft)		Mos Hrs Ldg	10-Aug-2023			
280-26-307	Fire Protection - Bleed Leak Detection Sensors - Inspection and Replacement in Pylons and Baggage Compartment		RE (-)		Recommended	
 26 A/F Eff: 16-Jun-2023 Not Applicable (UPDATE NOTE: N/A by SN of the aircraft)		Mos Hrs Ldg	10-Aug-2023			
280-26-308	Fire Protection - Bleed Leak Detection Sensors - Inspection and Replacement Under Upper Fuselage Wing and Aft Fairings		RE (-)		Recommended	
 26 A/F Eff: 16-Jun-2023 Not Applicable (UPDATE NOTE: N/A by SN of the aircraft)		Mos Hrs Ldg	10-Aug-2023			
▼ 27 - FLIGHT CONTROLS						
2020-26-12	Flight controls - Revision of Table 9 - Temporary Limitations and Inspection Requirements of the Section 05-10-10 (Airworthiness Limitations Section) of the G280 Airplane Maintenance Manual - Addition of AWL-3 Task		RE (-)		Mandatory	
 27 A/F Eff: 01-Feb-2021 Not Applicable	N/A by original export CoA, SEE ISRAEL CAAI AD ISR-L-04-2020-06-02. AWL-3 TASK ADDED TO TABLE 9 OF G280 AIRPLANE MAINTENANCE MANUALS SECTION 05-10-10 (AIRWORTHINESS LIMITATIONS SECTION)	Mos Hrs Ldg				
2026-09-04	Flight Controls - Retrofitting of the Flight Controls Empennage Electrical Harness (IAW CAAI AD ISR I-27-2025-03-06 R1)		RE (-)		Mandatory	
 27 A/F Eff: 12-Jun-2026 Not Applicable	AIRCRAFT SN NOT AFFECTED	Mos Hrs Ldg				
280-27-056	Flight Controls - Multi-Function Spoiler Actuator (MFSA) And Ground Spoiler Actuator (GSA) - Gland Retainer Ring Inspection (MODG25-00242)		RE (-)		Recommended	
 27 A/F Eff: 26-Nov-2014 Not Applicable	PER AIRCRAFT SERIAL NUMBER	Mos Hrs Ldg	10-Feb-2023 24:24 7			
280-27-067	Flight Controls - Aileron Trim - Inspection Of Aileron Trim Actuator Inner And Outer Output Shafts (MODG25-00377)		RE (-)		Mandatory	
 27 A/F Eff: 12-Apr-2013 Not Applicable	PER AIRCRAFT SERIAL NUMBER	Mos Hrs Ldg	10-Feb-2023 24:24 7			

Task No	Description						
SEQ	PN/SN	MOC Note		CW	REQ	TOL	Categories DUE Time Remaining
280-27-068		Flight Controls - Aileron Trim - Rework Of Aileron Trim Actuator Output Shaft Arms (MODG25-00382)				RE (-)	Recommended
	27 A/F			Mos	19-Apr-2023		
	Eff: 30-Apr-2013 Not Applicable	as per A/C S/N		Hrs	124:16		
				Ldg	71		
280-27-068 Rev 1		Flight Controls - Aileron Trim - Rework Of Aileron Trim Actuator Output Shaft Arms (MODG25-00382)				RE (-)	Recommended
	27 A/F			Mos	10-Feb-2023		
	Eff: 21-Jun-2013 Not Applicable	PER AIRCRAFT SERIAL NUMBER		Hrs	24:24		
				Ldg	7		
280-27-081		Flight Controls - Flap Hydraulic Control Module (HCM) - Replacement (MODG25- 00433)				RE (-)	Recommended
	27 A/F			Mos	10-Feb-2023		
	Eff: 17-Apr-2015 Not Applicable	PER AIRCRAFT SERIAL NUMBER		Hrs	24:24		
				Ldg	7		
280-27-113		Flight Controls - Pilot/Copilot Control Wheel - Horizontal Trim Switch Replacement (MODG25-20063)				RE (-)	Recommended
	27 A/F			Mos	10-Feb-2023		
	Eff: 21-Nov-2014 Not Applicable	PER AIRCRAFT SERIAL NUMBER		Hrs	24:24		
				Ldg	7		
280-27-123		Flight Controls - Flap Drive Shaft Assemblies - Inspection And Reattachment (MODG25-00608)				RE (-)	Recommended
	27 A/F			Mos	10-Feb-2023		
	Eff: 24-Jan-2014 Not Applicable	PER AIRCRAFT SERIAL NUMBER		Hrs	24:24		
				Ldg	7		
280-27-141		Flight Controls - Flap Actuators - Drainage Improvement (MODG25-20069)				RE (-)	Recommended
	27 A/F			Mos	10-Feb-2023		
	Eff: 16-Oct-2015 Not Applicable	PER AIRCRAFT SERIAL NUMBER		Hrs	24:24		
				Ldg	7		
280-27-144		Flight Controls - Aileron Controls - Prevention Of Possible Interference Between Fuselage To Wing Control Rod Bolt And Bird Strike Plate (MODG25-07148)				RE (-)	Recommended
	27 A/F			Mos	10-Feb-2023		
	Eff: 30-Oct-2015 Not Applicable	PER AIRCRAFT SERIAL NUMBER		Hrs	24:24		
				Ldg	7		
280-27-165		Flight Controls - Horizontal Stabilizer Trim Actuator (HSTA) - Secondary Motor Cap Screw Interference (MODG25-20078)				RE (-)	Recommended
	27 A/F			Mos	10-Feb-2023		
	Eff: 08-Jul-2016 Not Applicable	PER AIRCRAFT SERIAL NUMBER		Hrs	24:24		
				Ldg	7		
280-27-198		Flight Controls - Rudder Servo Actuator - Replacement (MODG25-20096)				RE (-)	Recommended
	27 A/F			Mos	19-Apr-2023		
	Eff: 09-Jun-2016 Not Applicable	as per A/C S/N		Hrs	124:16		
				Ldg	71		
280-27-198 Rev1		Flight Controls - Rudder Servo Actuator - Replacement (MODG25-20096)				RE (-)	Recommended
	27 A/F			Mos	10-Feb-2023		
	Eff: 29-Jun-2018 Not Applicable	PER AIRCRAFT SERIAL NUMBER		Hrs	24:24		
				Ldg	7		
280-27-210		Flight Controls (ATA 27) Flight Control Electronic Control Unit (FCECU) #1 and #2 - Inspection and Replacement				RE (-)	Recommended
	27 A/F			Mos	19-Apr-2023		
	Eff: 11-Jul-2019 Not Applicable	as per A/C S/N		Hrs	124:16		
				Ldg	71		

Task No		Description	CW	REQ	TOL	Categories	Time
SEQ	PN/SN	MOC Note				DUE	Remaining
280-27-210 Rev 1		Flight Controls (ATA 27) - Flight Control Electronic Control Unit (FCECU) #1 - Inspection and Replacement				RE (-)	Recommended
	27 A/F		Mos	10-Feb-2023			
	Eff: 18-Oct-2019 Not Applicable	PER AIRCRAFT SERIAL NUMBER	Hrs	24:24			
			Ldg	7			
280-27-286		Flight Controls - Flight Control Electronic Control Unit (FCECU) #2 - Inspection and Replacement				RE (-)	Recommended
	27 A/F		Mos	10-Feb-2023			
	Eff: 18-Oct-2019 Not Applicable	PER AIRCRAFT SERIAL NUMBER	Hrs	24:24			
			Ldg	7			
280-27-303		Flight Controls - Ground Spoiler Actuator (GSA) Rod - End Torque				RE (-)	Recommended
	27 A/F		Mos	10-Feb-2023			
	Eff: 28-Oct-2022 Not Applicable	PER AIRCRAFT SERIAL NUMBER	Hrs	24:24			
			Ldg	7			
280-27-310		Flight Controls - Flaps - Actuator Mechanism Clearance Inspection and Rework				RE (-)	Recommended
	27 A/F		Mos	10-Sep-2024			
	Eff: 14-Jun-2024 Not Applicable		Hrs				
			Ldg				
280-27-311		Flight Controls - Vertical Stabilizer Control Rod - Elevator Control Rods Rigging Adjustment				RE (-)	Recommended
	27 A/F		Mos	10-Jul-2025			
	Eff: 20-Jun-2025 Not Applicable		Hrs				
	(UPDATE NOTE: NA by SN of the aircraft)		Ldg				
280-27-324		Flight Controls - Rudder Servo Actuator - Replacement				RE (-)	Recommended
	27 A/F		Mos	10-Jul-2025			
	Eff: 26-Jul-2023 Not Applicable		Hrs				
	(UPDATE NOTE: NA - SB 280-27-324 DONE)		Ldg				
280-27-324 Rev 1		Flight Controls - Rudder Servo Actuator - Replacement				RE (-)	Recommended
	27 A/F		Mos	10-Jul-2025			
	Eff: 26-Jul-2023 Not Applicable		Hrs				
	(UPDATE NOTE: N/A - SB 280-27-324 DONE)		Ldg				
280-27-335		Flight Controls (ATA 27) - Empennage Electrical Harness Retrofit				RE (-)	Mandatory
	27 A/F		Mos	03-Dec-2025			
	Eff: 17-Mar-2025 Not Applicable	Not AF by SN of the aircraft	Hrs				
			Ldg				
280-27-335 Rev 1		Flight Controls (ATA 27) - Empennage Electrical Harness Retrofit				RE (-)	Mandatory
	27 A/F		Mos	03-Dec-2025			
	Eff: 28-Jul-2025 Not Applicable	Not AF by SN of the aircraft	Hrs				
			Ldg				
280-27-339		Flight Controls (ATA 27) - Elevator Control System - Aft Quadrant Bolt				T (-)	Recommended
	27 A/F		Mos				
	Eff: 14-Aug-2025 Superseded by Rev 1.		Hrs				
			Ldg				
280-27-339 Rev 1		Flight Controls (ATA 27) - Elevator Control System - Aft Quadrant Bolt				T	Recommended
	27 A/F		Mos	24		14-Aug-2027	11 Months
	Eff: 14-Aug-2025		Hrs				
			Ldg				

Task No SEQ PN/SN	Description MOC Note			CW	REQ	TOL	Categories DUE	Time Remaining
▼ 28 - FUEL								
280-28-044	Fuel - Fluid Quantity Measuring Computer - Software Update (MODG25-20025)						RE (-)	Recommended
28 A/F				Mos	10-Feb-2023			
Eff: 27-Jun-2014 Not Applicable	PER AIRCRAFT SERIAL NUMBER			Hrs	24:24			
				Ldg	7			
280-28-062	Fuel - Wing Inboard Fuel Tank To Feed Tank Flapper Valve Sealing/Leakage Check (MODG25-00364)						RE (-)	Recommended
28 A/F				Mos	10-Feb-2023			
Eff: 02-Jul-2015 Not Applicable	PER AIRCRAFT SERIAL NUMBER			Hrs	24:24			
				Ldg	7			
280-28-063	Fuel - Fuel Distribution - Center Fuel Tank Tubing - Validation And Replacement Of Fuel Tubes (MODG25-00375)						RE (-)	Recommended
28 A/F				Mos	10-Feb-2023			
Eff: 26-Jul-2013 Not Applicable	PER AIRCRAFT SERIAL NUMBER			Hrs	24:24			
				Ldg	7			
280-28-065	Fuel - Fuel Storage - Positive/Negative Pressure Relief Valve - Updated Operational Check (MODG25-00368)						RE (-)	Recommended
28 A/F				Mos	10-Feb-2023			
Eff: 13-Dec-2013 Not Applicable	PER AIRCRAFT SERIAL NUMBER			Hrs	24:24			
				Ldg	7			
280-28-138	Fuel - Distribution - Wing Float Valve - Quality Conformance Inspection (MODG25- 00674)						RE (-)	Recommended
28 A/F				Mos	10-Feb-2023			
Eff: 26-Nov-2014 Not Applicable	PER AIRCRAFT SERIAL NUMBER			Hrs	24:24			
				Ldg	7			
280-28-168	Fuel - Engine Fuel Feed Line - Re-Torque Of Engine Fuel Feed Line Fittings (MODG25-00855)						RE (-)	Recommended
28 A/F				Mos	10-Feb-2023			
Eff: 03-Oct-2014 Not Applicable	PER AIRCRAFT SERIAL NUMBER			Hrs	24:24			
				Ldg	7			
280-28-237	Fuel - Forward Fuel Tank - Access Panels Jumper Attachments Sealing Improvement (MOD G25-20132)						RE (-)	Recommended
28 A/F				Mos	10-Feb-2023			
Eff: 22-Aug-2017 Not Applicable	PER AIRCRAFT SERIAL NUMBER			Hrs	24:24			
				Ldg	7			
D200906000007 Rev 2	Background and Current Situation Regarding Possible Fatty Acid Methyl Ester (FAME) Contamination in Aviation Turbine Fuel						T (A/R)	Service Information Letter
28 ENG1				Mos				
Eff: 02-Aug-2021				Hrs				
				Enc				
D200906000007 Rev 2	Background and Current Situation Regarding Possible Fatty Acid Methyl Ester (FAME) Contamination in Aviation Turbine Fuel						T (A/R)	Service Information Letter
28 ENG2				Mos				
Eff: 02-Aug-2021				Hrs				
				Enc				
D201907000030	Biocide Treatment Process						T (-)	Service Information Letter
28 ENG1				Mos				
Eff: 13-Aug-2019				Hrs				
				Enc				
D201907000030	Biocide Treatment Process						T (-)	Service Information Letter
28 ENG2				Mos				
Eff: 13-Aug-2019				Hrs				
				Enc				

Task No SEQ PN/SN	Description MOC Note	CW	REQ	TOL	Categories DUE	Time Remaining
D201907000030 Rev 1 28 ENG1 Eff: 07-May-2020	Biocide Treatment Process		T (-)		Service Information Letter	
		Mos				
		Hrs				
		Enc				
D201907000030 Rev 1 28 ENG2 Eff: 07-May-2020	Biocide Treatment Process		T (-)		Service Information Letter	
		Mos				
		Hrs				
		Enc				
D201907000030 Rev 2 28 ENG1 Eff: 02-Aug-2021	Biocide Treatment Process		T (A/R)		Service Information Letter	
		Mos				
		Hrs				
		Enc				
D201907000030 Rev 2 28 ENG2 Eff: 02-Aug-2021	Biocide Treatment Process		T (A/R)		Service Information Letter	
		Mos				
		Hrs				
		Enc				
▼ 29 - HYDRAULIC POWER						
280-29-072 29 A/F Eff: 13-Dec-2013 Not Applicable	Hydraulic Power - Fluid Quantity Measuring Computer (FQMC) - Correction Of Wiring In Plug 218Q3 And Replacement Of Incorrectly Installed BRD Labels 165C And 167C In Aft Fuselage (MODG25-00369) PER AIRCRAFT SERIAL NUMBER		RE (-)		Recommended	
		Mos	10-Feb-2023			
		Hrs	24:24			
		Ldg	7			
280-29-176 29 A/F Eff: 22-Nov-2016 Not Applicable	Hydraulic Power - Aft Fuselage - Right Hydraulic System Tube Chaffing (MODG25- 00917) PER AIRCRAFT SERIAL NUMBER		RE (-)		Recommended	
		Mos	10-Feb-2023			
		Hrs	24:24			
		Ldg	7			
280-29-214 29 A/F Eff: 17-Oct-2017 Not Applicable	Hydraulic Power - Vertical Stabilizer - Creating Positive Separation between Hydraulic Hoses and Electrical Harnesses PER AIRCRAFT SERIAL NUMBER		RE (-)		Recommended	
		Mos	10-Feb-2023			
		Hrs	24:24			
		Ldg	7			
280-29-300 29 A/F Eff: 09-Dec-2022 Not Applicable	Hydraulic Power (ATA 29) - Charging Placards PER AIRCRAFT SERIAL NUMBER		RE (-)		Recommended	
		Mos	10-Feb-2023			
		Hrs	24:24			
		Ldg	7			
▼ 30 - ICE AND RAIN PROTECTION						
280-30-017 30 A/F Eff: 12-Dec-2014 Not Applicable	Ice And Rain Protection - Wing Anti-Ice (WAI) System - Air Flow And General Aviation Digital Controller (GADC) Modifications - Installation Of System Crossover Valve And New GADC-4 (MODG25-10022, MODG25-00262, MODG25-00821 , MODG25- 00808) as per a/c S/N		RE (-)		Mandatory	
		Mos	17-Apr-2023			
		Hrs	122:11			
		Ldg	69			
280-30-017 Part A 30 A/F Not Applicable	Ice And Rain Protection - Wing Anti-Ice (WAI) System -Air Flow And General Aviation Digital Controller Modifications - Installation Of System Crossover Valve (Cancelled) as per a/c S/N		RE (-)		Mandatory	
		Mos	17-Apr-2023			
		Hrs	122:11			
		Ldg	69			

Task No SEQ PN/SN	Description MOC Note			CW	REQ	TOL	Categories DUE	Time Remaining
280-30-017 Part B	Ice And Rain Protection - Wing Anti-Ice (WAI) System -Air Flow And General Aviation Digital Controller Modifications - Installation Of System Crossover Valve (Cancelled)				RE (-)		Mandatory	
 30 A/F Not Applicable	as per a/c S/N		Mos	17-Apr-2023				
			Hrs	122:11				
			Ldg	69				
280-30-017 Part C	Ice And Rain Protection - Wing Anti-Ice (WAI) System -Air Flow And General Aviation Digital Controller Modifications - Installation Of System Crossover Valve (Cancelled)				RE (-)		Mandatory	
 30 A/F Not Applicable	as per a/c S/N		Mos	17-Apr-2023				
			Hrs	122:11				
			Ldg	69				
280-30-017 Part D	Ice And Rain Protection - Wing Anti-Ice (WAI) System -Air Flow And General Aviation Digital Controller Modifications - Installation Of System Crossover Valve (Cancelled)				RE (-)		Mandatory	
 30 A/F Not Applicable	as per a/c S/N		Mos	17-Apr-2023				
			Hrs	122:11				
			Ldg	69				
280-30-017 Rev 1	Ice and Rain Protection - Wing Anti-Ice (WAI) Sytem - Air Flow And General Aviation Digital Controller (GADC) Modifications - Installation Of System Crossover Valve And New General Aviation Digital Controller (GADC-4) (MODG25-00262)				RE (-)		Mandatory	
 30 A/F Eff: 12-Dec-2014 Not Applicable	as per a/c S/N		Mos	17-Apr-2023				
			Hrs	122:11				
			Ldg	69				
280-30-017 Rev 1 Part A	SB 280-30-017R1 Part A Wing Anti Ice System - Air Flow and General Aviation Digital Controller Modifications - Installation of System Crossover Valve				RE (-)		Mandatory	
 30 A/F Eff: 12-Dec-2014 Not Applicable	PER AIRCRAFT SERIAL NUMBER		Mos	10-Feb-2023				
			Hrs	24:24				
			Ldg	7				
280-30-017 Rev 1 Part B	SB 280-30-017R1 Part B Wing Anti Ice System - Air Flow and General Aviation Digital Controller Modifications - Installation of System Crossover Valve				RE (-)		Mandatory	
 30 A/F Eff: 12-Dec-2014 Not Applicable	PER AIRCRAFT SERIAL NUMBER		Mos	10-Feb-2023				
			Hrs	24:24				
			Ldg	7				
280-30-017 Rev 1 Part C	SB 280-30-017R1 Part C Wing Anti Ice System - Air Flow and General Aviation Digital Controller Modifications - Installation of System Crossover Valve				RE (-)		Mandatory	
 30 A/F Eff: 12-Dec-2014 Not Applicable	PER AIRCRAFT SERIAL NUMBER		Mos	10-Feb-2023				
			Hrs	24:24				
			Ldg	7				
280-30-017 Rev 1 Part D	SB 280-30-017R1 Part D Wing Anti Ice System - Air Flow and General Aviation Digital Controller Modifications - Installation of System Crossover Valve				RE (-)		Mandatory	
 30 A/F Eff: 12-Dec-2014 Not Applicable	PER AIRCRAFT SERIAL NUMBER		Mos	10-Feb-2023				
			Hrs	24:24				
			Ldg	7				
280-30-157	Ice/Rain Protection - Windshield De-Ice Control System - Replacement Of The Existing Controllers (5H AND 6H) P/N 25G8460007-003 With Modified Controllers P/N 25G8460007-005 (MODG25-20071)				RE (-)		Recommended	
 30 A/F Eff: 14-May-2015 Not Applicable	PER AIRCRAFT SERIAL NUMBER		Mos	10-Feb-2023				
			Hrs	24:24				
			Ldg	7				
280-30-158	Ice and Rain Protection - Addintional Wing Anti-Ice Manifold Pressure Sensor - Removal (MOD G25-20071)				RE (-)		Recommended	
 30 A/F Eff: 15-Dec-2015 Not Applicable	PER AIRCRAFT SERIAL NUMBER		Mos	10-Feb-2023				
			Hrs	24:24				
			Ldg	7				

Task No	Description	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note				DUE	Remaining
280-30-253	Ice and Rain Protection - Replacement of Wing Anti-Ice Crossover Valve - P/N 30P781007000-001 (P/N 63292106-2)		RE (-)		Recommended	
30 A/F		Mos	19-Apr-2023			
Eff: 01-Oct-2019 Not Applicable	as per A/C S/N	Hrs	124:16			
		Ldg	71			
280-30-253 Rev 1	Ice and Rain Protection - Replacement of Wing Anti-Ice Crossover Valve - P/N 30P781007000-001 (P/N 63292106-2)		RE (-)		Recommended	
30 A/F		Mos	10-Feb-2023			
Eff: 29-Oct-2020 Not Applicable	PER AIRCRAFT SERIAL NUMBER	Hrs	24:24			
		Ldg	7			
D202106001848	Thermal Anti Ice Valve (TAIV) Part Number (PN) WBG3020G103-003		T (A/R)		Service Information Letter	
30 ENG1		Mos				
Eff: 23-Jul-2021		Hrs				
		Enc				
D202106001848	Thermal Anti Ice Valve (TAIV) Part Number (PN) WBG3020G103-003		T (A/R)		Service Information Letter	
30 ENG2		Mos				
Eff: 23-Jul-2021		Hrs				
		Enc				
▼ 31 - INDICATING / RECORDING SYSTEM						
2026-13-02	Indicating/Recording System/Navigation -Radio Altimeter - 5G Lower C-Band Interference - Canadian Airspace Operating Limitations		RE (-)		Mandatory	
31 A/F		Mos	07-Jul-2026			
Eff: 01-Jul-2026 Complied With	implemented by new AFM revision	Hrs	2007:22			
(UPDATE NOTE: implemented by new AFM revision)		Ldg	1,147			
2026-13-02 Par. (h)	Indicating/Recording System/Navigation -Radio Altimeter - 5G Lower C-Band Interference - Canadian Airspace Operating Limitations - Airplane Flight Manual (AFM) Revision		RE (-)		Mandatory	
31 A/F		Mos	07-Jul-2026			
Eff: 30-Jun-2026 Complied With	implemented by new AFM revision	Hrs	2007:22			
(UPDATE NOTE: implemented by new AFM revision)		Ldg	1,147			
2026-13-02 Par. (i)	Indicating/Recording System/Navigation -Radio Altimeter - 5G Lower C-Band Interference - Canadian Airspace Operating Limitations - Terminating Action for AFM Limitations		T (A/R)		Mandatory	
31 A/F		Mos				
Eff: 01-Jul-2026		Hrs				
		Ldg				
280-31-009	Indicating/Recording Systems - Secondary Flight Data Recorder (FDR) System - Installation		T (-)		Optional	
31 A/F		Mos				
Eff: 19-Jun-2015		Hrs				
		Ldg				
280-31-009 Rev 1	Indicating/Recording Systems - Secondary Flight Data Recorder (FDR) System - Installation		T (-)		Optional	
31 A/F		Mos				
Eff: 24-Jul-2015		Hrs				
		Ldg				
280-31-009 Rev 2	Indicating/Recording Systems - Secondary Flight Data Recorder (FDR) System - Installation		T (-)		Optional	
31 A/F		Mos				
Eff: 04-Aug-2017		Hrs				
		Ldg				
280-31-009 Rev 3	Indicating/Recording Systems - Secondary Flight Data Recorder (FDR) System - Installation		T (-)		Optional	
31 A/F		Mos				
Eff: 01-Oct-2019		Hrs				
		Ldg				

Task No		Description				CW	REQ	TOL	Categories	Time
SEQ	PN/SN	MOC Note							DUE	Remaining
280-31-009 Rev 4		Indicating/Recording Systems - Secondary Flight Data Recorder (FDR) System - Installation						RE (-)		Optional
	31 A/F			Mos	10-Feb-2023					
	Eff: 01-Sep-2021 Complied With			Hrs	24:24					
				Ldg	7					
280-31-009 Rev 5		Indicating/Recording Systems - Secondary Flight Data Recorder (FDR) System - Installation						T (A/R)		Optional
	31 A/F			Mos						
	Eff: 02-Oct-2024			Hrs						
				Ldg						
280-31-011		Indicating/Recording - Cockpit Voice Recorder (CVR) - Installation Of Recorder Independent Power Supply (RIPS) (MODG25-10020)						RE (-)		Recommended
	31 A/F			Mos	19-Apr-2023					
	Eff: 30-Oct-2015 Not Applicable	as per A/C S/N		Hrs	124:16					
				Ldg	71					
280-31-043		Indicating/Recording - Replacement Of Existing Cockpit Voice Recorder (CVR) Independent Power Supply (RIPS) P/N 100-3010-000 With Upgraded RIPS P/N 100- 3010-001 (MODG25-20029)						RE (-)		Recommended
	31 A/F			Mos	10-Feb-2023					
	Eff: 09-Apr-2015 Not Applicable	PER AIRCRAFT SERIAL NUMBER		Hrs	24:24					
				Ldg	7					
280-31-173		Indicating/Recording Systems - Installation Of Quick Access Recorder (QAR)						T (-)		Optional
	31 A/F			Mos						
	Eff: 27-Feb-2015			Hrs						
				Ldg						
280-31-173 Rev 1		Indicating/Recording Systems - Installation Of Quick Access Recorder (QAR)						RE (-)		Optional
	31 A/F			Mos	10-Feb-2023					
	Eff: 22-Nov-2016 Complied With			Hrs	24:24					
				Ldg	7					
280-31-173 Rev 2		Indicating/Recording Systems - Installation of Micro Quick Access Recorder (QAR)						RE (-)		Optional
	31 A/F			Mos						
	Eff: 30-Jan-2026 Complied With	by previous revision.		Hrs						
				Ldg						
280-31-283		Indicating/Recording Systems - Adaptive Flight Display (AFD-6510) Inspection and Replacement						RE (-)		Recommended
	31 A/F			Mos	10-Sep-2024					
	Eff: 03-Mar-2023 Not Applicable			Hrs						
				Ldg						
280-31-283 Rev 1		Indicating/Recording Systems - Adaptive Flight Display (AFD-6510) Inspection and Replacement						RE (-)		Recommended
	31 A/F			Mos	10-Sep-2024					
	Eff: 07-Jun-2024 Not Applicable			Hrs						
				Ldg						
280-31-297		Indicating/Recording Systems - Adaptive Flight Display (AFD 6510-141) - Upgrade						RE (-)		Recommended
	31 A/F			Mos	10-Feb-2023					
	Eff: 23-Apr-2020 Not Applicable	PER AIRCRAFT SERIAL NUMBER		Hrs	24:24					
				Ldg	7					
▼ 32 - LANDING GEAR										
280-32-025		Landing Gear - Wheels And Brakes - Park / Emergency Brake Cable Replacement (MODG25-00122)						RE (-)		Recommended
	32 A/F			Mos	19-Apr-2023					
	Eff: 13-Sep-2013 Not Applicable	as per A/C S/N		Hrs	124:16					
				Ldg	71					

Task No		Description				Categories	Time	
SEQ	PN/SN	MOC Note		CW	REQ	TOL	DUE	Remaining
280-32-025 Rev 1		Landing Gear - Wheels And Brakes - Park / Emergency Brake Cable Replacement (MODG25-00122)					RE (-)	Recommended
	32 A/F			Mos	10-Feb-2023			
	Eff: 13-Sep-2013 Not Applicable	PER AIRCRAFT SERIAL NUMBER		Hrs	24:24			
				Ldg	7			
280-32-030		Landing Gear - Main Landing Gear (MLG) - Inboard And Outboard Harness - Improve Routing (MODG25-00235)					RE (-)	Recommended
	32 A/F			Mos	10-Feb-2023			
	Eff: 13-Sep-2013 Not Applicable	PER AIRCRAFT SERIAL NUMBER		Hrs	24:24			
				Ldg	7			
280-32-045		Landing Gear - Main Landing Gear (MLG) - Inboard Door Mechanism Lower Rod Replacement (MODG25-20019)					RE (-)	Recommended
	32 A/F			Mos	10-Feb-2023			
	Eff: 14-Nov-2014 Not Applicable	PER AIRCRAFT SERIAL NUMBER		Hrs	24:24			
				Ldg	7			
280-32-048		Landing Gear - Main Landing Gear (MLG) - Shock Strut Replacement (MODG25- 10023)					RE (-)	Recommended
	32 A/F			Mos	10-Feb-2023			
	Eff: 14-Nov-2016 Not Applicable	PER AIRCRAFT SERIAL NUMBER		Hrs	24:24			
				Ldg	7			
280-32-064		Landing Gear - Extension and Retraction - NLG Actuator - Inspection Of Rod End Securing Washer (MODG25-00393)					RE (-)	Recommended
	32 A/F			Mos	10-Feb-2023			
	Eff: 13-Dec-2013 Not Applicable	PER AIRCRAFT SERIAL NUMBER		Hrs	24:24			
				Ldg	7			
280-32-169		Landing Gear - Main Landing Gear (MLG) - Improved Routing And Support Of MLG Door Uplock Harness (MODG25-07182)					RE (-)	Recommended
	32 A/F			Mos	10-Feb-2023			
	Eff: 15-Nov-2016 Not Applicable	PER AIRCRAFT SERIAL NUMBER		Hrs	24:24			
				Ldg	7			
280-32-170		Landing Gear - Main Landing Gear (MLG) - Harness Routing Modification (MODG25- 00903)					RE (-)	Recommended
	32 A/F			Mos	10-Feb-2023			
	Eff: 30-Oct-2015 Not Applicable	PER AIRCRAFT SERIAL NUMBER		Hrs	24:24			
				Ldg	7			
280-32-190		Landing Gear - Modification Of Upper Jury Brace On NLG Brace Assembly (MODG25-20091)					RE (-)	Recommended
	32 A/F			Mos	10-Feb-2023			
	Eff: 14-Nov-2016 Not Applicable	PER AIRCRAFT SERIAL NUMBER		Hrs	24:24			
				Ldg	7			
280-32-202		Landing Gear - Nose Landing Gear (NLG) - Downlock Springs Replacement (MODG25-00995)					RE (-)	Mandatory
	32 A/F			Mos	10-Feb-2023			
	Eff: 15-Jan-2016 Not Applicable	PER AIRCRAFT SERIAL NUMBER		Hrs	24:24			
				Ldg	7			
280-32-225		Nose Landing Gear (NLG) – Modifying NLG Gear Up Hose Installation to Prevent Close Proximity with Structure					RE (-)	Recommended
	32 A/F			Mos	10-Feb-2023			
	Eff: 11-Apr-2018 Not Applicable	PER AIRCRAFT SERIAL NUMBER		Hrs	24:24			
				Ldg	7			
280-32-228		Landing Gear - Nose Landing Gear - Electrical Harness Routing Improvement (MODG25-01355)					RE (-)	Recommended
	32 A/F			Mos	10-Feb-2023			
	Eff: 22-Aug-2017 Not Applicable	PER AIRCRAFT SERIAL NUMBER		Hrs	24:24			
				Ldg	7			

Task No	Description	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note				DUE	Remaining
280-32-279	Landing Gear - Nose Landing Gear Wheel Well - Dual Parking Brake Valve (DPBV) Replacement		RE (-)		Recommended	
 32 A/F		Mos	10-Feb-2023			
Eff: 09-Apr-2020 Not Applicable	PER AIRCRAFT SERIAL NUMBER	Hrs	24:24			
		Ldg	7			
280-32-321	Landing Gear - Nose Wheel Steering Horn - Horn Replacement		T (A/R)		Optional	
 32 A/F		Mos				
Eff: 18-Sep-2024		Hrs				
		Ldg				
G-004-09-83	SUPERSEDED BY CAA UK AD 017-11-83		RE (-)		Mandatory	
 32 A/F		Mos	14-Apr-2023			
Eff: 12-Dec-1983 Superseded		Hrs	112:17			
		Ldg	61			
G-005-09-83	SUPERSEDED BY CAA UK AD 016-11-83		RE (-)		Mandatory	
 32 A/F		Mos	14-Apr-2023			
Eff: 12-Dec-1983 Superseded		Hrs	112:17			
		Ldg	61			
G-013-08-90	SUPERSEDED BY CAA UK AD 009-02-93		RE (-)		Mandatory	
 32 A/F		Mos	14-Apr-2023			
Eff: 20-Jan-1993 Superseded		Hrs	112:17			
		Ldg	61			
▼ 33 - LIGHTS						
280-33-121	Lights - Strobe Light - Addition Of Cap To Receptacle 57L (MODG25-00590)		RE (-)		Recommended	
 33 A/F		Mos	19-Apr-2023			
Eff: 14-Nov-2014 Not Applicable	as per A/C S/N	Hrs	124:16			
		Ldg	71			
280-33-121 Rev 1	Lights - Strobe Light - Addition Of Cap To Receptacle 57L (MODG25-00590)		RE (-)		Recommended	
 33 A/F		Mos	10-Feb-2023			
Eff: 14-Nov-2014 Not Applicable	PER AIRCRAFT SERIAL NUMBER	Hrs	24:24			
		Ldg	7			
280-33-322	Lights - Right Ground Escape, Recognition, External Baggage and Logo Lights - Replacement of External Incandescent Lights with LED Lights - Retrofit		T (A/R)		Optional	
 33 A/F		Mos				
Eff: 26-Sep-2025		Hrs				
		Ldg				
280-33-323	Lights - Taxi and Landing Lights - Taxi Lights and Landing Lights Retrofit		T (A/R)		Optional	
 33 A/F		Mos				
Eff: 26-Sep-2025		Hrs				
		Ldg				
280-33-331	Lights - Right Over Wing Escape (Emergency), Main Entrance Door (Emergency), and Wing Ice Inspection Lights - Replacement of External Incandescent to LED Lights Retrofit		T		OPERATORS DISCRETION, Optional, Recommended	
 33 A/F		Mos	96		[31-May-2033]	6.7 Years
		Hrs				
		Ldg				
280-33-332	Lights - Wing/Tail Position and Strobe Lights Replacement		T (-)		Optional	
 33 A/F		Mos				
Eff: 26-Sep-2025		Hrs				
		Ldg				
280-33-332 Rev 1	Lights - Wing/Tail Position and Strobe Lights Replacement		T (A/R)		Optional	
 33 A/F		Mos				
Eff: 04-Sep-2026		Hrs				
		Ldg				

Task No SEQ PN/SN	Description MOC Note	CW	REQ	TOL	Categories DUE	Time Remaining
280-33-341 33 A/F Eff: 26-Sep-2025	Lights - Right Ground Escape (Emergency) LED-Rework Wiring Connections For 28 Volt LED Installations		T (A/R)		Optional	
		Mos				
		Hrs				
		Ldg				
280-33-342 33 A/F Eff: 05-Dec-2025	Lights - Right Over Wing Escape (Emergency) LED, Main Entrance Door (Emergency) LED - Rework Wiring Connections for 28 Volt LED Installations		T (A/R)		Optional	
		Mos				
		Hrs				
		Ldg				
▼ 34 - NAVIGATION						
2000-07-27 34 A/F Not Applicable	Honeywell - Prevent Loss Of Air Data Sources NO ADIRU INSTALLED		RE (-)		Mandatory (Appliance AD)	
		Mos	10-Feb-2023			
		Hrs	24:24			
		Ldg	7			
2002-06-05 34 A/F Eff: 26-Apr-2002 Not Applicable	Mode C 621A-3 Air Traffic Control (ATC) Transponders COLLINS 622-9210-XXX TRANSPONDERS ARE INSTALLED		RE (-)		Mandatory (Appliance AD)	
		Mos	10-Feb-2023			
		Hrs	24:24			
		Ldg	7			
2012-02-08 34 A/F Eff: 13-Mar-2012 Not Applicable Brand A:9990-2012-02-08	Aviation Communication & Surveillance Systems (ACSS) Traffic Alert and Collision Avoidance System (TCAS) Units - Navigation NOT INSTALLED		RE (-)		Mandatory (Appliance AD)	
		Mos	10-Feb-2023			
		Hrs	24:24			
		Ldg	7			
2012-26-15 R1 34 A/F Eff: 03-Dec-2014 Not Applicable	Honeywell International Inc. - Air Data Pressure Transducers (This action rescinds AD 2012-26-15, Amendment 39-17310 (78 FR 1735, January 9, 2013).) NOT INSTALLED		RE (-)		Mandatory (Appliance AD)	
		Mos	10-Feb-2023			
		Hrs	24:24			
		Ldg	7			
2014-05-27 34 A/F Eff: 02-May-2014 Not Applicable Brand A:9990-2014-05-27	Rockwell Collins, Inc - Navigation - TPR-720 and TPR-900 Mode S transponders test and calibration BY MODEL AND P/N INSTALLED		RE (-)		Mandatory (Appliance AD)	
		Mos	10-Feb-2023			
		Hrs	24:24			
		Ldg	7			
2014-18-01 34 A/F Eff: 14-Oct-2014 Not Applicable Brand A:9990-2014-18-01	Rockwell Collins, Inc. - Navigation - inspect the airplane type code category strapping setting for a value of zero (0) or one (1) following Rockwell Collins, Inc. Service Information Letter 07-2, 523-0810069-101000, TDR-94() SIL 07-02. PER PART NUMBER		RE (-)		Mandatory (Appliance AD)	
		Mos	10-Feb-2023			
		Hrs	24:24			
		Ldg	7			
2017-11-11 34 A/F Eff: 11-Jul-2017 Not Applicable	ATC Transponder System - Automatic Dependent Surveillance Broadcast (ADS-B) Universal Access Transceiver Units MODEL NOT INSTALLED		RE (-)		Mandatory (Appliance AD)	
		Mos	10-Feb-2023			
		Hrs	24:24			
		Ldg	7			
2017-22-14 34 A/F Eff: 20-Dec-2017 Complied With	Navigation - Upgrade the Rockwell Collins, Inc. TSSA-4100 FLS to RCPN 810-0052-013 or 810-0052-102 IAI MOD25-20133, INCORPORATED IN PRODUCTION. UPGRADED THE TSSA-4100 FLS TO RCPN 810-0052-102.		RE (-)		Mandatory (Appliance AD)	
		Mos	10-Feb-2023			
		Hrs	24:24			
		Ldg	7			

Task No	Description	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note				DUE	Remaining
2019-12-09	Navigation - Rockwell Collins, Inc. (Rockwell Collins) Flight Display System Application FDSA-6500 - Revise AFM/ Fabricate Placard (Superseded by AD 2021-05-17)		RE (-)		Mandatory (Appliance AD)	
34 A/F		Mos	10-Feb-2023			
Eff: 23-Jul-2019 Not Applicable	NOT INSTALLED	Hrs	24:24			
		Ldg	7			
2020-08-02	Global Positioning System - Thales GPS/SBAS Receivers		RE (-)		Mandatory (Appliance AD)	
34 A/F		Mos	10-Feb-2023			
Eff: 19-May-2020 Not Applicable	NOT INSTALLED	Hrs	24:24			
		Ldg	7			
2021-23-12	Indicating/Recording System, Navigation - Radio Altimeter (Transport and Commuter Category Airplanes) (This AD is Superseded by FAA AD 2023-10-02)		RE (-)		Mandatory (Appliance AD)	
34 A/F		Mos	10-Aug-2023			
Eff: 03-Jan-2022 Complied With		Hrs				
(UPDATE NOTE: BY REVISING AFM LIMITATIONS BY REV. 9)		Ldg				
2023-04-02	Navigation - AFM Wet Runway Performance Tables		RE (-)		Mandatory	
34 A/F		Days	22-Mar-2023			
Eff: 07-Apr-2023 Complied With	AFM R10 in aircraft	Hrs				
		Ldg				
2023-10-02	Navigation - Radio Altimeters (This AD Replaces AD 2021-23-12)		RE (-)		Mandatory (Appliance AD)	
34 A/F		Mos	10-Aug-2023			
Eff: 26-May-2023 Complied With		Hrs				
(UPDATE NOTE: BY REVISING AFM LIMITATIONS BY REV. 9)		Ldg				
2023-10-02 Par. (h)	Navigation - Radio Altimeters - Airplane Flight Manual (AFM) Revision Until June 30, 2023		RE (-)		Mandatory (Appliance AD)	
34 A/F		Mos	10-Aug-2023			
Eff: 25-May-2023 Complied With		Hrs				
(UPDATE NOTE: BY REVISING AFM LIMITATIONS BY REV. 9)		Ldg				
2023-10-02 Par. (i)	Navigation - Radio Altimeters - AFM Revision After June 30, 2023		RE (-)		Mandatory (Appliance AD)	
34 A/F		Mos	10-Aug-2023			
Eff: 29-Jun-2023 Complied With		Hrs				
(UPDATE NOTE: BY REVISING AFM LIMITATIONS BY REV. 9)		Ldg				
2023-10-02 Par. (j)	Navigation - Radio Altimeters - Terminating Action for AFM Limitations		T (A/R)		Mandatory (Appliance AD)	
34 A/F		Mos				
Eff: 26-May-2023		Hrs				
		Ldg				
2023-21-05	Navigation - Thales AVS France SAS Flight Management Computer Navigation Modules (FMC2 NAVM)		RE (-)		Mandatory (Appliance AD)	
34 A/F		Mos	20-Nov-2023			
Eff: 12-Dec-2023 Not Applicable		Hrs				
(UPDATE NOTE: Thales AVS France SAS flight management computer navigation modules (FMC2 NAVM), part number (P/N) C13084CA03 - Not installed on the aircraft)		Ldg				
2023-21-05 Par. (g)(1)	Navigation - Thales AVS France SAS Flight Management Computer Navigation Modules (FMC2 NAVM) - Revise the Limitations Section of the Existing Airplane Flight Manual		RE (-)		Mandatory (Appliance AD)	
34 A/F		Days	20-Nov-2023			
Eff: 12-Dec-2023 Not Applicable		Hrs				
(UPDATE NOTE: Thales AVS France SAS flight management computer navigation modules (FMC2 NAVM), part number (P/N) C13084CA03 - Not installed on the aircraft)		Ldg				
2023-21-05 Par. (g)(2)	Navigation - Thales AVS France SAS Flight Management Computer Navigation Modules (FMC2 NAVM) - Update the Database for Thales FMC2 NAVM - P/N C13084CA03		RE (-)		Mandatory (Appliance AD)	
34 A/F		Days	20-Nov-2023			
Eff: 12-Dec-2023 Not Applicable		Hrs				
(UPDATE NOTE: Thales AVS France SAS flight management computer navigation modules (FMC2 NAVM), part number (P/N) C13084CA03 - Not installed on the aircraft)		Ldg				

Task No		Description				Categories	Time	
SEQ	PN/SN	MOC Note		CW	REQ	TOL	DUE	Remaining
2024-0024		Navigation - Digital Air Data Computer - Replacement				RE (-)	Mandatory (Appliance AD)	
	34 A/F			Mos	27-May-2024			
	Eff: 07-Feb-2024 Not Applicable	affected P/N not installed		Hrs	842:13			
				Ldg	496			
2025-0088		Navigation - Satellite Based Augmentation Systems / Global Positioning System Receiver - Replacement				RE (-)	Mandatory (Appliance AD)	
	34 A/F			Yrs	10-Jul-2025			
	Eff: 30-Apr-2025 Not Applicable			Hrs				
	(UPDATE NOTE: 822-2189-101 Note 3: For units with loadable software whose P/N can evolve independently of the HW P/N. In that case, the unit is affected only when the listed SW P/N is loaded in the HW P/N. - Not applicable)			Ldg				
280-34-001		Navigation - Radio Altimeter - Installation of Secondary Radio Altimeter				T (-)	Optional	
	34 A/F			Mos				
	Eff: 20-Nov-2012			Hrs				
				Ldg				
280-34-001 Rev 1		Navigation - Radio Altimeter - Installation of Secondary Radio Altimeter				T (-)	Optional	
	34 A/F			Mos				
	Eff: 31-Oct-2013			Hrs				
				Ldg				
280-34-001 Rev 2		Navigation - Radio Altimeter - Installation of Secondary Radio Altimeter				T (-)	Optional	
	34 A/F			Mos				
	Eff: 15-Dec-2015			Hrs				
				Ldg				
280-34-001 Rev 3		Navigation - Radio Altimeter - Installation of Secondary Radio Altimeter				T (-)	Optional	
	34 A/F			Mos				
	Eff: 01-Sep-2021			Hrs				
				Ldg				
280-34-001 Rev 4		Navigation - Radio Altimeter - Installation of Secondary Radio Altimeter				T (A/R)	Optional	
	34 A/F			Mos				
	Eff: 19-Aug-2026			Hrs				
				Ldg				
280-34-002		Navigation - Inertial Reference System (IRS) - Installation of Third IRS System				T (-)	Optional	
	34 A/F			Mos				
	Eff: 13-Nov-2012			Hrs				
				Ldg				
280-34-002 Rev 1		Navigation - Inertial Reference System (IRS) - Installation of Third IRS System				RE (-)	Optional	
	34 A/F			Mos	10-Feb-2023			
	Eff: 01-Sep-2021 Complied With			Hrs	24:24			
				Ldg	7			
280-34-004		Navigation - Automatic Direction Finder (ADF) - Installation of Second ADF System				T (-)	Optional	
	34 A/F			Mos				
	Eff: 20-Nov-2012			Hrs				
				Ldg				
280-34-004 Rev 1		Navigation - Automatic Direction Finder (ADF) - Installation of Second ADF System				T (-)	Optional	
	34 A/F			Mos				
	Eff: 20-Dec-2013			Hrs				
				Ldg				
280-34-004 Rev 2		Navigation - Automatic Direction Finder (ADF) - Installation of Second ADF System				RE (-)	Optional	
	34 A/F			Mos	10-Feb-2023			
	Eff: 01-Sep-2021 Complied With			Hrs	24:24			
				Ldg	7			

Task No		Description				Categories	Time
SEQ	PN/SN	MOC Note	CW	REQ	TOL	DUE	Remaining
280-34-005		Navigation - Very High Frequency (VHF) - Installation of Third VHF NAV System				T (-)	Optional
	34 A/F						
	Eff: 20-Nov-2012						
280-34-005 Rev 1		Navigation - Very High Frequency (VHF) - Installation of Third VHF NAV System				T (-)	Optional
	34 A/F						
	Eff: 15-Dec-2015						
280-34-005 Rev 2		Navigation - Very High Frequency (VHF) - Installation of Third VHF NAV System				T (A/R)	Optional
	34 A/F						
	Eff: 01-Sep-2021						
280-34-008		Navigation - Flight Management System (FMS) - Installation of Third FMS				T (-)	Optional
	34 A/F						
	Eff: 21-Nov-2012						
280-34-008 Rev 1		Navigation - Flight Management System (FMS) - Installation of Third FMS				T (-)	Optional
	34 A/F						
	Eff: 31-Oct-2013						
280-34-008 Rev 2		Navigation - Flight Management System (FMS) - Installation Of Third FMS System (MODG25-10005)				T (-)	Optional
	34 A/F						
	Eff: 15-Dec-2015						
280-34-008 Rev 3		Navigation - Flight Management System (FMS) - Installation of Third FMS				T (-)	Optional
	34 A/F						
	Eff: 23-Aug-2018						
280-34-008 Rev 4		Navigation - Flight Management System (FMS) - Installation of Third FMS				T (A/R)	Optional
	34 A/F						
	Eff: 01-Sep-2021						
280-34-018		Navigation - Reduced Vertical Separation Minimum (RVSM) - Group Approval (MODG25-10024)				RE (-)	Recommended
	34 A/F						
	Eff: 21-Nov-2012 Not Applicable	PER AIRCRAFT SERIAL NUMBER					
280-34-029		Navigation - Flight Environment Data - Improve Conductivity Of Static Ports (MODG25-00279)				RE (-)	Recommended
	34 A/F						
	Eff: 11-Apr-2014 Not Applicable	PER AIRCRAFT SERIAL NUMBER					
280-34-093		Navigation - Flight Management System - (FMS) - Performance Database (PDB) Upload (MODG25-20053)				RE (-)	Recommended
	34 A/F						
	Eff: 11-Apr-2014 Not Applicable	as per A/C S/N					
280-34-093 Rev 1		Navigation - Flight Management System - (FMS) - Performance Database (PDB) Upload (MODG25-20053)				RE (-)	Recommended
	34 A/F						
	Eff: 11-Apr-2014 Not Applicable	PER AIRCRAFT SERIAL NUMBER					

Task No SEQ PN/SN	Description MOC Note	CW	REQ	TOL	Categories DUE	Time Remaining
280-34-094	Navigation - Flight Management System (FMS) - Vspeed Database (VDB) Incorporation Of Software Version 3.2.1 (MODG25-20054)		RE (-)		Recommended	
34 A/F		Mos	10-Feb-2023			
Eff: 12-Sep-2014 Not Applicable	PER AIRCRAFT SERIAL NUMBER	Hrs	24:24			
		Ldg	7			
280-34-097	Navigation - Independent Position Determining - Automatic Dependent Surveillance - Broadcast (ADS-B) - Air Traffic Control (ATC) Transponder (TDR-94D) No. 2 Activation (MODG25-00426)		RE (-)		Recommended	
34 A/F		Mos	19-Apr-2023			
Eff: 27-Aug-2013 Not Applicable	as per A/C S/N	Hrs	124:16			
		Ldg	71			
280-34-097 Rev 1	Navigation - Independent Position Determining - Automatic Dependent Surveillance - Broadcast (ADS-B) - Air Traffic Control (ATC) Transponder (TDR-94D) No. 2 Activation (MODG-00426 , MODG25-00771)		RE (-)		Recommended	
34 A/F		Mos	10-Feb-2023			
Eff: 17-Apr-2015 Not Applicable	PER AIRCRAFT SERIAL NUMBER	Hrs	24:24			
		Ldg	7			
280-34-106	Navigation - Installation of Rockwell Collins Avionics Software Version V3.6 Configuration, Performance and V-Speed Databases - Retrofit (MODG25-10032)		RE (-)		Recommended	
34 A/F		Mos	10-Feb-2023			
Eff: 15-Dec-2015 Not Applicable	PER AIRCRAFT SERIAL NUMBER	Hrs	24:24			
		Ldg	7			
280-34-122	Navigation - Attitude And Direction - MGR-3000 Magnetometer - Extreme Temperature Improvement (MODG25-00607)		RE (-)		Recommended	
34 A/F		Mos	19-Apr-2023			
Eff: 26-Nov-2014 Not Applicable	as per A/C S/N	Hrs	124:16			
		Ldg	71			
280-34-122 Rev 1	Navigation - Attitude And Direction - MGR-3000 Magnetometer - Extreme Temperature Improvement (MODG25-00607)		RE (-)		Recommended	
34 A/F		Mos	10-Feb-2023			
Eff: 26-Nov-2014 Not Applicable	PER AIRCRAFT SERIAL NUMBER	Hrs	24:24			
		Ldg	7			
280-34-167	Navigation - Pitot/Static System - Modification Of Static Port Holes (MODG25-20075)		RE (-)		Recommended	
34 A/F		Mos	10-Feb-2023			
Eff: 10-Jul-2015 Not Applicable	PER AIRCRAFT SERIAL NUMBER	Hrs	24:24			
		Ldg	7			
280-34-204	Navigation - Flight Management System - Cancellation of FMS Predicted Steps Function Activation in the Aircraft Personality Module 3rd Party Option File (MODG25- 20105)		RE (-)		Recommended	
34 A/F		Mos	10-Feb-2023			
Eff: 27-Apr-2016 Not Applicable	PER AIRCRAFT SERIAL NUMBER	Hrs	24:24			
		Ldg	7			
280-34-236	Navigation - Information Management System (IMS-6000) - Software Update		RE (-)		Recommended	
34 A/F		Mos	19-Apr-2023			
Eff: 02-Oct-2017 Not Applicable	as per A/C S/N	Hrs	124:16			
		Ldg	71			
280-34-236 Rev 1	Navigation - Information Management System (IMS-6000) - Software Update		RE (-)		Recommended	
34 A/F		Mos	10-Feb-2023			
Eff: 25-Jul-2018 Not Applicable	PER AIRCRAFT SERIAL NUMBER	Hrs	24:24			
		Ldg	7			

Task No	Description					Categories	Time
SEQ PN/SN	MOC Note			CW	REQ	TOL	DUE Remaining
280-34-239	Navigation - TSSA-4100 Software Update (MOD G25-20133)				RE (-)		Recommended
 34 A/F			Mos	19-Apr-2023			
Eff: 10-May-2017 Not Applicable	as per A/C S/N		Hrs	124:16			
			Ldg	71			
280-34-239 Rev 1	Navigation Systems - Traffic Surveillance System Application (TSSA-4100) - Software Update				RE (-)		Mandatory
 34 A/F			Mos	10-Feb-2023			
Eff: 20-Dec-2017 Not Applicable	PER AIRCRAFT SERIAL NUMBER		Hrs	24:24			
			Ldg	7			
280-34-256	Navigation - Flight Management System (FMS) - Equal Time Point (ETP) Feature Disabling				RE (-)		Recommended
 34 A/F			Mos	19-Apr-2023			
Eff: 10-Jul-2018 Not Applicable	as per A/C S/N		Hrs	124:16			
			Ldg	71			
280-34-256 Rev 1	Navigation - Flight Management System (FMS) - Equal Time Point (ETP) Feature Disabling				RE (-)		Recommended
 34 A/F			Mos	10-Feb-2023			
Eff: 27-May-2021 Not Applicable	PER AIRCRAFT SERIAL NUMBER		Hrs	24:24			
			Ldg	7			
280-34-264	Common Computing Module (CCM-5110) - Upgrade				RE (-)		Recommended
 34 A/F			Mos	10-Feb-2023			
Eff: 22-Feb-2019 Not Applicable	PER AIRCRAFT SERIAL NUMBER		Hrs	24:24			
			Ldg	7			
280-34-265	NAV-4500 - Upgrade				RE (-)		Recommended
 34 A/F			Mos	19-Apr-2023			
Eff: 22-Feb-2019 Not Applicable	as per A/C S/N		Hrs	124:16			
			Ldg	71			
280-34-265 Rev 1	NAV-4500 - Upgrade				RE (-)		Recommended
 34 A/F			Mos	10-Feb-2023			
Eff: 09-May-2019 Not Applicable	PER AIRCRAFT SERIAL NUMBER		Hrs	24:24			
			Ldg	7			
280-34-266	NAV-4000 - Upgrade				RE (-)		Recommended
 34 A/F			Mos	19-Apr-2023			
Eff: 22-Feb-2019 Not Applicable	as per A/C S/N		Hrs	124:16			
			Ldg	71			
280-34-266 Rev 1	NAV-4000 - Upgrade				RE (-)		Recommended
 34 A/F			Mos	10-Feb-2023			
Eff: 09-May-2019 Not Applicable	PER AIRCRAFT SERIAL NUMBER		Hrs	24:24			
			Ldg	7			
280-34-268	Navigation - Information Management System (IMS-6000) - Upgrade				RE (-)		Recommended
 34 A/F			Mos	19-Apr-2023			
Eff: 22-Feb-2019 Not Applicable	as per A/C S/N		Hrs	124:16			
			Ldg	71			
280-34-268 Rev 1	Navigation - Information Management System (IMS-6000) - Upgrade				RE (-)		Recommended
 34 A/F			Mos	10-Feb-2023			
Eff: 12-May-2020 Not Applicable	PER AIRCRAFT SERIAL NUMBER		Hrs	24:24			
			Ldg	7			

Task No SEQ PN/SN	Description MOC Note	CW	REQ	TOL	Categories DUE	Time Remaining
280-34-269	Digital Switching Module (DSM-5110) - Upgrade		RE (-)		Recommended	
 34 A/F		Mos	10-Feb-2023			
Eff: 22-Feb-2019 Not Applicable	PER AIRCRAFT SERIAL NUMBER	Hrs	24:24			
		Ldg	7			
280-34-273	Navigation (ATA 34) - V3.6.1 Software Upgrade		RE (-)		Recommended	
 34 A/F		Mos	10-Feb-2023			
Eff: 05-May-2021 Not Applicable	PER AIRCRAFT SERIAL NUMBER	Hrs	24:24			
		Ldg	7			
280-34-290	Navigation - Terrain Awareness and Warning System - SMS Override Lighted Switch Retrofit and SMS/TLAF Application Enable		T (-)		Optional	
 34 A/F		Mos				
Eff: 27-May-2021		Hrs				
		Ldg				
280-34-290 Rev 1	Navigation - Terrain Awareness and Warning System - SMS Override Lighted Switch Retrofit and SMS/TLAF Application Enable		T (A/R)		Optional	
 34 A/F		Mos				
Eff: 08-Sep-2021		Hrs				
		Ldg				
280-34-291	Navigation - Predictive Wind Shear and Vertical Weather Upgrade		RE (-)		Optional	
 34 A/F		Mos	10-Feb-2023			
Eff: 27-May-2021 Complied With		Hrs	24:24			
		Ldg	7			
280-34-292	Navigation - Enhanced Data Load		RE (-)		Optional	
 34 A/F		Mos				
Eff: 27-May-2021		Hrs				
		Ldg				
280-34-293	Navigation - GPS-4000S No. 1 and No. 2 Replacement P/N 822-2189-100 with P/N 822-2189-101		RE (-)		Recommended	
 34 A/F		Mos	10-Feb-2023			
Eff: 16-Jul-2020 Not Applicable	PER AIRCRAFT SERIAL NUMBER	Hrs	24:24			
		Ldg	7			
280-34-295	Navigation - Weather Radar NVM Reset for RTA-4118		RE (-)		Recommended	
 34 A/F		Mos	10-Feb-2023			
Eff: 09-Apr-2020 Not Applicable	PER AIRCRAFT SERIAL NUMBER	Hrs	24:24			
		Ldg	7			
280-34-295 Rev 1	Navigation - Weather Radar NVM Reset for RTA-4118		RE (-)		Recommended	
 34 A/F		Mos	19-Apr-2023			
Eff: 27-May-2021 Not Applicable	as per A/C S/N	Hrs	124:16			
		Ldg	71			
280-34-301	Navigation - ALT-4000 No. 2, P/N 822-0615-315 Inspection and Replacement		RE (-)		Recommended	
 34 A/F		Mos	10-Feb-2023			
Eff: 29-Oct-2020 Not Applicable	PER AIRCRAFT SERIAL NUMBER	Hrs	24:24			
		Ldg	7			
280-34-302	Navigation - Information Management System (IMS) - IMS-6000 Replacement with IMS-6010		RE (-)		Optional	
 34 A/F		Mos	20-Nov-2023			
Eff: 27-May-2021 Not Applicable		Hrs				
(UPDATE NOTE: PER AIRCRAFT SERIAL NUMBER)		Ldg				
280-34-302 Rev 1	Navigation - Information Management System (IMS) - IMS-6000 Replacement with IMS-6010		RE (-)		Optional	
 34 A/F		Mos	20-Nov-2023			
Eff: 23-Oct-2023 Not Applicable		Hrs				
(UPDATE NOTE: PER AIRCRAFT SERIAL NUMBER)		Ldg				

Task No		Description				Categories	Time
SEQ	PN/SN	MOC Note	CW	REQ	TOL	DUE	Remaining
280-34-305		Navigation - SXM Weather Upgrade		RE (-)		Optional	
	34 A/F		Mos	10-Feb-2023			
	Eff: 27-May-2021 Not Applicable	PER AIRCRAFT SERIAL NUMBER	Hrs	24:24			
			Ldg	7			
280-34-328		Navigation - Flight Management System (FMS) - Vspeed Database Update to Versions -005/-006		RE (-)		Recommended	
	34 A/F		Mos	10-Jul-2025			
	Eff: 07-Oct-2024 Complied With (UPDATE NOTE: AF)		Hrs				
			Ldg				
280-34-328 Rev 1		Navigation (ATA 34) - Flight Management System (FMS) - Vspeed Database Update to Versions -005/-006		RE (-)		Recommended	
	34 A/F		Mos	10-Jul-2025			
	Eff: 07-Oct-2024 Complied With (UPDATE NOTE: AF)		Hrs				
			Ldg				
280-34-328 Rev 2		Navigation (ATA 34) - Flight Management System (FMS) - Vspeed Database Update to Versions -005/-006		RE (-)		Recommended	
	34 A/F		Mos	17-Apr-2026			
	Eff: 07-Oct-2024 Complied With		Hrs	1887:38			
			Ldg	1,073			
280-34-329		Navigation - RTA-4218 SB2 Performance Improvement for Predictive Windshear and Vertical Weather		RE (-)		Recommended	
	34 A/F		Mos				
	Eff: 25-Jul-2025 Not Applicable	by aircraft SN.	Hrs				
			Ldg				
280-34-333		Navigation - Information Management System (IMS) - IMS-6010 SB 5 Verification		RE (-)		Recommended	
	34 A/F		Mos				
	Eff: 02-Aug-2024		Hrs				
			Ldg				
280-34-334		Navigation - Traffic Surveillance System (TSS-4100) - TSS/TSSA Non-Compliance		RE (-)		Recommended	
	34 A/F		Mos	10-Jul-2025			
	Eff: 20-Jun-2025 Complied With (UPDATE NOTE: AF)		Hrs				
			Ldg				
CF-2024-14		Navigation - Aeroplane - Limitations of Operations with Non-Tolerant Radio Altimeter when Operating in Canada due to 5G C-Band Wireless Broadband Interference		RE (-)		Mandatory (Appliance AD)	
	34 A/F		Mos	27-May-2024			
	Eff: 29-May-2024 Complied With	AFM updated	Hrs	842:13			
			Ldg	496			
CF-2024-14 Part I		Navigation - Aeroplane - Limitations of Operations with Non-Tolerant Radio Altimeter when Operating in Canada due to 5G C-Band Wireless Broadband Interference - Radio Altimeter Tolerant Aeroplane / Non-Radio Altimeter Tolerant Aeroplane / Tolerance for Emissions		RE (-)		Mandatory (Appliance AD)	
	34 A/F		Mos	27-May-2024			
	Eff: 29-May-2024 Complied With	AFM updated	Hrs	842:13			
			Ldg	496			
CF-2024-14 Part II		Navigation - Aeroplane - Limitations of Operations with Non-Tolerant Radio Altimeter when Operating in Canada due to 5G C-Band Wireless Broadband Interference - Airplane Flight Manual (AFM) Revision		RE (-)		Mandatory (Appliance AD)	
	34 A/F		Mos	27-May-2024			
	Eff: 28-May-2024 Complied With	AFM updated	Hrs	842:13			
			Ldg	496			
CF-2024-14 Part III		Navigation - Aeroplane - Limitations of Operations with Non-Tolerant Radio Altimeter when Operating in Canada due to 5G C-Band Wireless Broadband Interference - Terminating Action for AFM Limitations		T (A/R)		Mandatory (Appliance AD)	
	34 A/F		Mos				
	Eff: 29-May-2024		Hrs				
			Ldg				

Task No		Description			Categories		Time	
SEQ	PN/SN	MOC Note		CW	REQ	TOL	DUE	Remaining
STC ST04339AT-D		Gulfstream Air Ionization System Installation						
	34 A/F		Mos	10-Feb-2023			RE (-)	
	Complied With		Hrs	24:24				
			Ldg	7				
▼ 35 - OXYGEN								
2011-04-09		Chemical oxygen generator deactivation (Superseded by FAA AD 2012-11-09)					RE (-)	Mandatory (Appliance AD)
	35 A/F		Mos	10-Feb-2023				
	Eff: 14-Mar-2011 Not Applicable	NOT INSTALLED	Hrs	24:24				
			Ldg	7				
2012-11-09 R1		Chemical Oxygen Generator Installation					RE (-)	Mandatory (Appliance AD)
	35 A/F		Mos	10-Feb-2023				
	Eff: 27-Jul-2015 Not Applicable	NOT INSTALLED	Hrs	24:24				
	Brand A:9990-2012-11-09R1		Ldg	7				
2015-08-07		Zodiac Aerotechnics (formerly Intertechnique Aircraft Systems) - Oxygen - Flightcrew Oxygen Mask Regulators					RE (-)	Mandatory (Appliance AD)
	35 A/F		Mos	10-Feb-2023				
	Eff: 16-Jun-2015 Not Applicable	PER MASK SERIAL NUMBER, REF. APPENDIX I OF ZODIAC AEROSPACE SERVICE BULLETIN MXH-35-240 REV. 7	Hrs	24:24				
			Ldg	7				
2015-23-09 Para (g)		Oxygen - Inspect Each Flightcrew Oxygen Mask Regulator To Identify The Part Number And Serial Number					RE (-)	Mandatory (Appliance AD)
	35 A/F		Mos	10-Feb-2023				
	Eff: 28-Dec-2015 Not Applicable	PER REGULATOR P/N	Hrs	24:24				
			Ldg	7				
2015-23-09 Para (i)		Oxygen - Regulator Replacement					RE (-)	Mandatory (Appliance AD)
	35 A/F		Mos	10-Feb-2023				
	Eff: 28-Dec-2015 Not Applicable	PER REGULATOR P/N	Hrs	24:24				
			Ldg	7				
2016-11-20 Paragraph (g)		Oxygen - Aerospace Protective Breathing Equipment (PBE), part number (P/N) 119003-11 - Inspection					RE (-)	Mandatory (Appliance AD)
	35 A/F		Mos	10-Feb-2023				
	Eff: 15-Jul-2016 Not Applicable	NOT INSTALLED	Hrs	24:24				
	Brand A:9990-2016-11-20(g)		Ldg	7				
2017-18-12		Oxygen - B/E Aerospace Protective Breathing Equipment (PBE) Units, P/N 119003-11 and 119003-21 - Inspect/ Replace (This AD replaces AD 2016-11-20)					RE (-)	Mandatory (Appliance AD)
	35 A/F		Mos	10-Feb-2023				
	Eff: 16-Oct-2017 Not Applicable	NOT INSTALLED	Hrs	24:24				
			Ldg	7				
2018-21-14		MC10 Series Crew Oxygen Mask Regulators - Inflatable Harness Assembly, P/N MXH20-1 or MXH21-1 - Inspection/ Replacement					RE (-)	Mandatory (Appliance AD)
	35 A/F		Mos	10-Feb-2023				
	Eff: 27-Mar-2019 Not Applicable	PER MASK PART NUMBER	Hrs	24:24				
			Ldg	7				
2023-13-11		Oxygen - AVOX Systems Inc. (Formerly Scott Aviation) Oxygen Cylinder and Valve Assemblies (Supersedes FAA AD 2022-04-09) (This AD is Superseded by AD 2024-19-15)					RE (-)	Mandatory (Appliance AD)
	35 A/F		Mos	26-Feb-2025				
	Eff: 05-Sep-2023 Not Applicable		Hrs					
	(UPDATE NOTE: NA - PNs not installed)		Ldg					
2024-19-15		Oxygen - Oxygen Leakage from Cylinder and Valve Assemblies (This AD Replaces AD 2023-13-11)					RE (-)	Mandatory (Appliance AD)
	35 A/F		Mos	26-Feb-2025				
	Eff: 26-Nov-2024 Not Applicable		Hrs					
	(UPDATE NOTE: NA - PNs not installed)		Ldg					

Task No		Description			CW	REQ	TOL	Categories	Time
SEQ	PN/SN	MOC Note						DUE	Remaining
2024-19-15 Par. (h)		Oxygen - Oxygen Leakage from Cylinder and Valve Assemblies - Retained Identification of Affected Cylinder and Valve Assemblies, with Updated Language						RE (-)	Mandatory (Appliance AD)
	35 A/F			Mos	26-Feb-2025				
	Eff: 05-Sep-2023 Not Applicable			Hrs					
	(UPDATE NOTE: NA - PNs not installed)			Ldg					
2024-19-15 Par. (i)		Oxygen - Oxygen Leakage from Cylinder and Valve Assemblies - Retained Inspection of the Gap, Parts Marking Actions, and Replacement, with Updated Language - Inspection of the Gap						RE (-)	Mandatory (Appliance AD)
	35 A/F			Mos	26-Feb-2025				
	Eff: 26-Nov-2024 Not Applicable			Hrs					
	(UPDATE NOTE: NA - PNs not installed)			Ldg					
2024-19-15 Par. (i)(1)		Oxygen - Oxygen Leakage from Cylinder and Valve Assemblies - Retained Inspection of the Gap, Parts Marking Actions, and Replacement, with Updated Language - Parts Marking Actions						RE (-)	Mandatory (Appliance AD)
	35 A/F			Mos	26-Feb-2025				
	Eff: 26-Nov-2024 Not Applicable			Hrs					
	(UPDATE NOTE: NA - PNs not installed)			Ldg					
2024-19-15 Par. (i)(2)		Oxygen - Oxygen Leakage from Cylinder and Valve Assemblies - Retained Inspection of the Gap, Parts Marking Actions, and Replacement, with Updated Language - Replacement						RE (-)	Mandatory (Appliance AD)
	35 A/F			Mos	26-Feb-2025				
	Eff: 26-Nov-2024 Not Applicable			Hrs					
	(UPDATE NOTE: NA - PNs not installed)			Ldg					
2024-19-15 Par. (l)		Oxygen - Oxygen Leakage from Cylinder and Valve Assemblies - New Identification of Additional Affected Cylinder and Valve Assemblies						RE (-)	Mandatory (Appliance AD)
	35 A/F			Days	19-Feb-2025				
	Eff: 26-Nov-2024 Not Applicable			Hrs					
	(UPDATE NOTE: NA - PNs not installed)			Ldg					
2024-19-15 Par. (m)		Oxygen - Oxygen Leakage from Cylinder and Valve Assemblies - New Inspection of the Gap, Parts Marking Actions, and Replacement for Additional Parts - Inspection of the Gap						RE (-)	Mandatory (Appliance AD)
	35 A/F			Mos	26-Feb-2025				
	Eff: 26-Nov-2024 Not Applicable			Hrs					
	(UPDATE NOTE: NA - PNs not installed)			Ldg					
2024-19-15 Par. (m)(1)		Oxygen - Oxygen Leakage from Cylinder and Valve Assemblies - New Inspection of the Gap, Parts Marking Actions, and Replacement for Additional Parts - Parts Marking Actions						RE (-)	Mandatory (Appliance AD)
	35 A/F			Mos	26-Feb-2025				
	Eff: 26-Nov-2024 Superseded			Hrs					
	(UPDATE NOTE: NA - PNs not installed)			Ldg					
2024-19-15 Par. (m)(2)		Oxygen - Oxygen Leakage from Cylinder and Valve Assemblies - New Inspection of the Gap, Parts Marking Actions, and Replacement for Additional Parts - Replacement						RE (-)	Mandatory (Appliance AD)
	35 A/F			Mos	26-Feb-2025				
	Eff: 26-Nov-2024 Not Applicable			Hrs					
	(UPDATE NOTE: NA - PNs not installed)			Ldg					
2025-26-06		Oxygen - Portable Breathing Equipment (PBE) - Incorrect Usage of PBEs (This AD Replaces AD 2025-25-02)						RE (-)	Mandatory (Appliance AD)
	35 A/F			Mos					
	Eff: 14-Jan-2026 Not Applicable	affected PNs not installed.		Hrs					
				Ldg					
280-35-184		Oxygen - Enlarge Clearance Between Oxygen Tube And Right Side Forward Radio Rack Structure (MODG25-00966)						RE (-)	Recommended
	35 A/F			Mos	10-Feb-2023				
	Eff: 22-Nov-2016 Not Applicable	PER AIRCRAFT SERIAL NUMBER		Hrs	24:24				
				Ldg	7				
▼ 36 - PNEUMATIC									
280-36-143		Pneumatics - Correct Interference Between Nose ECS System Installation And Structure (MODG25-00689)						RE (-)	Recommended
	36 A/F			Mos	10-Feb-2023				
	Eff: 01-Jun-2015 Not Applicable	PER AIRCRAFT SERIAL NUMBER		Hrs	24:24				
				Ldg	7				

Task No SEQ PN/SN	Description MOC Note			CW	REQ	TOL	Categories DUE	Time Remaining
▼ 38 - WATER/WASTE								
280-38-086	Water/Waste System - System Heater Control Module (SHCM), Water Control Unit (WLS) And Potable Water Pump (PWP) Replacement (MODG25-20048, G25-20049 G25-20055 , G25-20070)				RE (-)		Recommended	
 38 A/F			Mos	10-Feb-2023				
Eff: 21-Nov-2014 Not Applicable	PER AIRCRAFT SERIAL NUMBER		Hrs	24:24				
			Ldg	7				
280-38-281	Potable Water Tank Fill Nozzle Circlip Inspection and Replacement				RE (-)		Recommended	
 38 A/F			Mos	10-Feb-2023				
Eff: 16-Jul-2019 Not Applicable	PER AIRCRAFT SERIAL NUMBER		Hrs	24:24				
			Ldg	7				
280-38-294	Water/Waste System - Waste Tank Rinse Nozzle Reinforcement				RE (-)		Recommended	
 38 A/F			Mos	10-Feb-2023				
Eff: 18-Mar-2021 Not Applicable	PER AIRCRAFT SERIAL NUMBER		Hrs	24:24				
			Ldg	7				
280-38-343	Waste System - Waste Tank Flush Inlet Pressure Update - Inlet Pressure Placard Replacement				T (A/R)		Recommended	
 38 A/F			Mos				[27-Feb-2027]	5.4 Months
Eff: 25-Feb-2026			Hrs					
			Ldg					
G25-20206	G25-20206, Modification				RE (-)			
 38 A/F			Mos	20-Nov-2022				
Complied With	AT MANUFACTURE		Hrs	0				
			Ldg	0				
▼ 44 - CABIN SYSTEMS								
CE-CSB-2001	Cabin Systems (ATA 44) Advanced Cabin Server (ACS) System Firmware Update 4.4.3.3				T (A/R)		Cabin Service Bulletin	
 44 A/F			Mos					
Eff: 17-Feb-2014			Hrs					
			Ldg					
CE-CSB-2002	Cabin Service Bulletins (ATA 44) GCMS Cabin System Firmware Update 1.9.2				RE (-)		Recommended	
 44 A/F			Mos	19-Apr-2023				
Eff: 17-Feb-2014 Not Applicable	before aircraft manufacture		Hrs	124:16				
			Ldg	71				
CE-CSB-2002A	Cabin Service Bulletins (ATA 94) GCMS Cabin System Firmware Update 1.9.2.1				RE (-)		Recommended	
 44 A/F			Mos	19-Apr-2023				
Eff: 17-Feb-2014 Not Applicable	before aircraft manufacture		Hrs	124:16				
			Ldg	71				
CE-CSB-2002B	Cabin Service Bulletins (ATA 44) GCMS Cabin System Firmware Update 1.9.2.1				RE (-)		Recommended	
 44 A/F			Mos	19-Apr-2023				
Eff: 13-Nov-2014 Not Applicable	before aircraft manufacture		Hrs	124:16				
			Ldg	71				
CE-CSB-2003	Cabin Service Bulletins (ATA 44) Advanced Cabin Server (ACS) System Software Upgrade				T (A/R)		Cabin Service Bulletin	
 44 A/F			Mos					
Eff: 09-Jul-2015			Hrs					
			Ldg					
CE-CSB-2004	Cabin Service Bulletins (ATA 44) GCMS Cabin System Firmware Update				RE (-)		Recommended	
 44 A/F			Mos	19-Apr-2023				
Eff: 09-Jul-2015 Not Applicable	before aircraft manufacture		Hrs	124:16				
			Ldg	71				

Task No SEQ PN/SN	Description MOC Note	CW	REQ	TOL	Categories DUE	Time Remaining
CE-CSB-2005 44 A/F Eff: 09-Jul-2015	Cabin Service Bulletins (ATA 44) Advanced Cabin Server (ACS) System Software Upgrade				T (A/R)	Cabin Service Bulletin
CE-CSB-2006 44 A/F Eff: 24-Jun-2016 Not Applicable	Cabin Service Bulletins (ATA 44) GCMS Cabin System Firmware Update before aircraft manufacture				RE (-)	Recommended
CE-CSB-2007 44 A/F Eff: 07-Dec-2017 Not Applicable	Cabin Service Bulletins (ATA 44) GCMS Cabin System Firmware Update before aircraft manufacture				RE (N/A)	Recommended
CE-CSB-2008 44 A/F Eff: 04-May-2018	Cabin Systems (ATA 44) Advanced Cabin Server (ACS) (Gen 4) Cabin View tm Software Upgrade				T (A/R)	Cabin Service Bulletin
CE-CSB-2008 Rev A 44 A/F Eff: 10-May-2017	Cabin Systems (ATA 44) Advanced Cabin Server (ACS) (Gen 4) Cabinview tm Software Upgrade				T (A/R)	Cabin Service Bulletin
CE-CSB-2009 44 A/F Eff: 08-Aug-2018 Not Applicable	Cabin Service Bulletins (ATA 44) Gulfstream Cabin Management System (GCMS 1) Firmware Update before aircraft manufacture				RE (-)	Recommended
CE-CSB-2010 44 A/F Eff: 01-Feb-2019	Cabin Systems (ATA 44) Advanced Cabin Server (ACS) (GEN4) Cabinview tm Software Upgrade				T (A/R)	Cabin Service Bulletin
CE-CSB-2011 44 A/F Eff: 21-Mar-2019	Cabin Systems (ATA 44) Advanced Cabin Server (ACS) (GEN4) Cabinview tm Software Upgrade				T (A/R)	Cabin Service Bulletin
CE-CSB-2012 44 A/F Eff: 08-Apr-2019 Not Applicable	Cabin Service Bulletins (ATA 44) Gulfstream Cabin Management System (GCMS 1) Firmware Update before aircraft manufacture				RE (-)	Recommended
CE-CSB-2014 44 A/F Eff: 03-Dec-2019	Cabin Systems (ATA 44) Advanced Cabin Server (ACS) (Gen 4) Cabinview Software Upgrade V2.2.3				RE (-)	Cabin Service Bulletin
CE-CSB-2015 44 A/F Eff: 29-Oct-2019 Not Applicable	Cabin Systems (ATA 44) Gulfstream Cabin Management System (GCMS 1) Firmware Update V1.10.6 before aircraft manufacture				RE (-)	Recommended
CSB 016 44 A/F Eff: 01-May-2020 Not Applicable	Cabin Systems - Gulfstream Cabin Management System (GCMS 2) Firmware Update before aircraft manufacture				RE (-)	Recommended

Task No SEQ PN/SN	Description MOC Note		CW	REQ	TOL	Categories DUE	Time Remaining
CSB 017	Cabin Systems - Gulfstream Cabin Management System (GCMS 1) Firmware Update			RE (-)		Recommended	
44 A/F		Mos	19-Apr-2023				
Eff: 14-Aug-2020 Not Applicable	before aircraft manufacture	Hrs	124:16				
		Ldg	71				
CSB 018	Cabin Systems - Gulfstream Cabin Management System (GCMS 2) Firmware Update			RE (-)		Recommended	
44 A/F		Mos	19-Apr-2023				
Eff: 22-Oct-2020 Not Applicable	before aircraft manufacture	Hrs	124:16				
		Ldg	71				
CSB 021	Cabin Systems - Advanced Cabin Server (ACS) (Gen 4) / Cabin Processor Unit (CPU) (Gen 5) Cabin View Software Update			RE (-)		Cabin Service Bulletin, Recommended	
44 A/F		Mos	14-Apr-2023				
Eff: 06-Jul-2022 Not Applicable	by aircraft S/N	Hrs	112:17				
		Ldg	61				
CSB 022	Cabin Systems - Gulfstream Cabin Management System (GCMS 2) Firmware Update			RE (-)		Cabin Service Bulletin, Recommended	
44 A/F		Mos	20-Oct-2023				
Eff: 22-Mar-2023 Complied With		Hrs	490:27				
		Ldg	293				
CSB 023	Cabin Systems (ATA 44) - Cabin Processor Unit (CPU) (Gen 6) Windows 10 Update			T (-)		Recommended	
44 A/F		Mos					
Eff: 15-Jul-2025		Hrs					
		Ldg					
CSB 023A	Cabin Systems (ATA 44) - Cabin Processor Unit (CPU) (Gen 6) Windows 10 Update			T (A/R)		Recommended	
44 A/F		Mos					
Eff: 01-Aug-2025		Hrs					
		Ldg					
GPECSB20001	G280 Cabin System Level E Firmware Update (ATA 44)			T (A/R)		Optional	
44 A/F		Mos					
Eff: 26-Jan-2013		Hrs					
		Ldg					
▼ 46 - INFORMATION SYSTEMS							
280-46-041	Information Systems - Electronic Checklist (ECL) Database Update (MODG25-10035)			RE (-)		Recommended	
46 A/F		Mos	10-Feb-2023				
Eff: 11-Apr-2014 Not Applicable	PER AIRCRAFT SERIAL NUMBER	Hrs	24:24				
		Ldg	7				
280-46-316	Information Systems (ATA 46) - Information Management System (IMS) - IMS-6010 Software Update			RE (-)		Optional	
46 A/F		Mos					
Eff: 10-Feb-2023		Hrs					
		Ldg					
▼ 49 - AIRBORNE AUXILIARY POWER							
21-4187	Modification from part number 2119922-2S1, -3S1, and -4S1 to part number 2119922-6S1			T (A/R)			
49 APU1		Mos					
Eff: 17-Jun-2005		Hrs					
		APUS					
21-4187 Rev 1	Modification from part number 2119922-2S1, -3S1, and -4S1 to part number 2119922-6S1			T (A/R)			
49 APU1		Mos					
Eff: 15-Sep-2006		Hrs					
		APUS					

Task No		Description				CW	REQ	TOL	Categories	
SEQ	PN/SN	MOC Note							DUE	Time Remaining
280-49-249		Airborne Auxiliary Power - Firewall - Frame 64 Assembly and Structure Sealing (MODG25-01543)							RE (-)	Recommended
	 49 A/F				Mos	10-Feb-2023				
	Eff: 06-Sep-2017 Not Applicable	PER AIRCRAFT SERIAL NUMBER			Hrs	24:24				
					Ldg	7				
3610004-49-8319		Airborne Auxiliary Power - Gas Turbine Engine - Rework Fuel Nozzle Assembly, PN 3610004-3 and -4 to PN 3610004-5 and -6							RE (-)	Recommended
	 49 APU1				Mos	20-Oct-2023				
	Eff: 17-Mar-2020 Complied With	During manufacturing			Hrs					
					APUS					
36-49-8119		AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - Rotating Group Balance Procedure on 36-150[F] [R] [W] [BD] [CX] [DD] [HH] [RR] [F2M] and [IAI] Auxiliary Power Units (APUs)							T (A/R)	
	 49 APU1				Mos					
	Eff: 22-Aug-2013				Hrs					
					APUS					
36-49-8119 Rev 1		AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - Rotating Group Balance Procedure on 36-150[F] [R] [W] [BD] [CX] [DD] [HH] [RR] [F2M] and [IAI] Auxiliary Power Units (APUs)							T (A/R)	
	 49 APU1				Mos					
	Eff: 13-Sep-2013				Hrs					
					APUS					
36-49-8119 Rev 2		AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - Rotating Group Balance Procedure on 36-150[F] [R] [W] [BD] [CX] [DD] [HH] [RR] [F2M] and [IAI] Auxiliary Power Units (APUs)							T (A/R)	
	 49 APU1				Mos					
	Eff: 13-Jan-2014				Hrs					
					APUS					
36-49-8119 Rev 3		AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - Rotating Group Balance Procedure on 36-150[F] [R] [W] [BD] [CX] [DD] [HH] [RR] [F2M] and [IAI] Auxiliary Power Units (APUs)							T (A/R)	
	 49 APU1				Mos					
	Eff: 16-Apr-2014				Hrs					
					APUS					
36-49-8119 Rev 4		AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - Rotating Group Balance Procedure on 36-150[F] [R] [W] [BD] [CX] [DD] [HH] [RR] [F2M] and [IAI] Auxiliary Power Units (APUs)							T (A/R)	
	 49 APU1				Mos					
	Eff: 30-Mar-2017				Hrs					
					APUS					
36-49-8190		AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - Group Balance and Assembly of the Power Section for 36-150[IAI] APU PN 3800710-1 -2 and -3							T (-)	
	 49 APU1				Mos					
	Eff: 23-Mar-2017				Hrs					
					APUS					
36-49-8190 Rev 1		Airborne Auxiliary Power - Gas Turbine Engine - Group Balance and Assembly of the Power Section for 36-150[IAI] APU PN 3800710-1 -2 and -3							RE (-)	Recommended
	 49 APU1				Mos	17-Apr-2023				
	Eff: 13-Nov-2017 Not Applicable	before manufacture			Hrs					
					APUS					
36-49-8190 Rev 2		Airborne Auxiliary Power - Gas Turbine Engine - Group Balance and Assembly of the Power Section for 36-150[IAI] APU, PN 3800710-1, -2, and -3							RE (-)	Recommended
	 49 APU1				Mos	09-Apr-2024				
	Eff: 20-Aug-2018 Complied With				Hrs	443				
					APUS	626				
36-49-8361 Rev 2		Airborne Auxiliary Power - Gas Turbine Engine - Replace Rivet PN M24243/6A401H with Rivet PN 627-504-9209 on 36-150 Engine Models							RE (-)	Cat. 2 - Recommended
	 49 APU1				Mos	17-Apr-2023				
	Eff: 30-Mar-2022 Not Applicable	as per APU S/N			Hrs					
					APUS					

Task No SEQ PN/SN	Description MOC Note	CW	REQ	TOL	Categories	Time
					DUE	Remaining
36-49-8361 Rev 3 49 APU1 Eff: 14-Apr-2022 Not Applicable	Airborne Auxiliary Power - Gas Turbine Engine - Replace Rivet PN M24243/6A401H with Rivet PN 627-504-9209 on 36-150 Engine Models as per APU S/N	Mos Hrs APUS	17-Apr-2023		RE (-)	Cat. 2 - Recommended
36-49-8361 Rev 4 49 APU1 Eff: 18-Jan-2023 Not Applicable	Airborne Auxiliary Power - Gas Turbine Engine - Replace Rivet PN M24243/6A401H with Rivet PN 627-504-9209 on 36-150 Engine Models as per APU S/N	Mos Hrs APUS	17-Apr-2023		RE (-)	Cat. 2 - Recommended
36-49-8402 49 APU1 Eff: 25-Sep-2025	Airborne Auxiliary Power - Gas Turbine Engine - Replace Spring Washer PN S9479-45N with PN S9479-73 on the 36-150 Auxiliary Power Unit (APU)	Mos Hrs APUS			T (-)	Cat. 2 - Recommended
36-49-8402 Rev 1 49 APU1 Eff: 19-Jan-2026	Airborne Auxiliary Power - Gas Turbine Engine - Replace Spring Washer PN S9479-45N with PN S9479-73 on the 36-150 Auxiliary Power Unit (APU)	Mos Hrs APUS			T (A/R)	Cat. 2 - Recommended
3822101-49-8148 49 APU1 Eff: 10-Jul-2015 Not Applicable	Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of Compressor Rotors, P/N 3822101-1, on Multiple APU's as per compressor rotor P/N	Mos Hrs APUS	17-Apr-2023		RE (-)	Recommended
3822101-49-8148 Rev 1 49 APU1 Eff: 20-Oct-2015 Not Applicable	Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of Compressor Rotors, P/N 3822101-1, on Multiple APU's as per compressor rotor P/N	Mos Hrs APUS	17-Apr-2023		RE (-)	Recommended
3822101-49-8148 Rev 2 49 APU1 Eff: 10-Jan-2017 Not Applicable	Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of Compressor Rotors, P/N 3822101-1, on Multiple APU's as per compressor rotor P/N	Mos Hrs APUS	17-Apr-2023		RE (-)	Recommended
3822101-49-8148 Rev 3 49 APU1 Eff: 27-Nov-2017 Not Applicable	Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of Compressor Rotors, P/N 3822101-1, on Multiple APU's as per compressor rotor P/N	Mos Hrs APUS	17-Apr-2023		RE (-)	Recommended
3822632-49-8146 49 APU1 Eff: 02-Jul-2015 Not Applicable	Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of Compressor Rotor, PN 3822632-1, on Multiple APUS as per compressor rotor P/N	Mos Hrs APUS	17-Apr-2023		RE (-)	Recommended
3822632-49-8146 Rev 1 49 APU1 Eff: 24-Jul-2015 Not Applicable	Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of Compressor Rotor, PN 3822632-1, on Multiple APUS as per compressor rotor P/N	Mos Hrs APUS	17-Apr-2023		RE (-)	Recommended
3822632-49-8146 Rev 2 49 APU1 Eff: 31-Aug-2015 Not Applicable	Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of Compressor Rotor, PN 3822632-1, on Multiple APUS as per compressor rotor P/N	Mos Hrs APUS	17-Apr-2023		RE (-)	Recommended

Task No	Description	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note				DUE	Remaining
3822632-49-8146 Rev 3	Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of Compressor Rotor, PN 3822632-1, on Multiple APUs		RE (-)		Recommended	
49 APU1		Mos	17-Apr-2023			
Eff: 25-Oct-2016 Not Applicable	as per compressor rotor P/N	Hrs				
		APUS				
3822632-49-8146 Rev 4	Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of Compressor Rotor, PN 3822632-1, on Multiple APUs		RE (-)		Recommended	
49 APU1		Mos	17-Apr-2023			
Eff: 21-Nov-2017 Not Applicable	as per compressor rotor P/N	Hrs				
		APUS				
3842064-49-8192	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - Rework the Turbine Rotor PN 3842064-1 to PN 3842064-5 for Use on Multiple APUs		T (A/R)			
49 APU1		Mos				
Eff: 21-Oct-2016		Hrs				
		APUS				
3842064-49-8193	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - Balance Repair of the Turbine Rotors PN 3842064-1 and PN 3842064-5 on Multiple Auxiliary Power Units (APUs)		RE (-)	Recommended, Service Bulletin		
49 APU1		Mos	17-Apr-2023			
Eff: 23-Feb-2017 Not Applicable	Turbine rotor P/N not installed	Hrs				
		APUS				
3842064-49-8193 Rev 1	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - Balance Repair of the Turbine Rotors PN 3842064-1 and PN 3842064-5 on Multiple Auxiliary Power Units (APUs)		RE (-)	Recommended, Service Bulletin		
49 APU1		Mos	14-Apr-2023			
Eff: 14-Sep-2017 Not Applicable	turbine rotor P/N not installed	Hrs				
		APUS				
3882730-49-7974	INSTALL FUEL FLOW DEFLECTOR, PN 70720001-1 ON THE FUEL CONTROL DIFFERENTIAL PRESSURE (DELTA P) SLEEVE		T (A/R)			
49 APU1		Mos				
Eff: 25-Feb-2009		Hrs				
		APUS				
3882730-49-7974 Rev 1	INSTALL FUEL FLOW DEFLECTOR, PN 70720001-1 ON THE FUEL CONTROL DIFFERENTIAL PRESSURE (DELTA P) SLEEVE		T (-)			
49 APU1		Mos				
Eff: 10-Apr-2009		Hrs				
		APUS				
3882730-49-7974 Rev 2	Main Fuel Control Unit (FCU) - Install Fuel Flow Deflector, PN 70720001-1 On the Fuel Control Differential Pressure (DELTA P) Sleeve as Required at Next APU Shop Visit. Check Nameplate for Latest Change Number Prior to the FCU Removal		RE (-)		Recommended	
49 APU1		Mos	17-Apr-2023			
Eff: 11-May-2019 Not Applicable	before manufacture	Hrs				
		APUS				
3888021-49-8206	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - Rework Fluid Pressure Regulating Valve, PN 3888021-2, -5 Thru -17 to PN 70721587-4, on Multiple APUs		RE (-)		Recommended	
49 APU1		Mos	09-Apr-2024			
Eff: 07-Apr-2016 Complied With		Hrs	443			
		APUS	626			
49-7552	AIRBORNE AUXILIARY POWER - GAS TURBINE ENGINE - REPLACE ELECTRONIC CONTROL UNIT (ECU), PN 2118988-1 WITH PN 2118988-2		T (A/R)			
49 APU1		Mos				
Eff: 13-Oct-1999		Hrs				
		APUS				
49-7691	REPLACE FUEL SHUTOFF SOLENOID VALVE, PART NO. 692545-17 OR PART NO. 3888134-5 WITH PART NO. 692545-18		T (A/R)			
49 APU1		Mos				
Eff: 14-Aug-2002		Hrs				
		APUS				

Task No		Description				Categories	Time
SEQ	PN/SN	MOC Note	CW	REQ	TOL	DUE	Remaining
49-7691 Rev 1		REPLACE FUEL SHUTOFF SOLENOID VALVE, PART NO. 692545-17 OR PART NO. 3888134-5 WITH PART NO. 692545-18		T (A/R)			
	49 APU1		Mos				
	Eff: 01-Feb-2003		Hrs				
			APUS				
49-7691 Rev 2		REPLACE FUEL SHUTOFF SOLENOID VALVE, PART NO. 692545-17 OR PART NO. 3888134-5 WITH PART NO. 692545-18		T (A/R)			
	49 APU1		Mos				
	Eff: 03-Aug-2005		Hrs				
			APUS				
49-7717		Airborne Auxiliary Power - Gas Turbine Engine - Inspection/Replacement of the Coupling Clamp, PN 234-511-9059, T-Bolt (Fuel Control to Lube Pump Flanges)		T (A/R)			
	49 APU1		Mos				
	Eff: 25-Sep-2002		Hrs				
			APUS				
49-7717 Rev 1		Airborne Auxiliary Power - Gas Turbine Engine - Inspection/Replacement of the Coupling Clamp, PN 234-511-9059, T-Bolt (Fuel Control to Lube Pump Flanges)		T (A/R)			
	49 APU1		Mos				
	Eff: 25-Sep-2002		Hrs				
			APUS				
49-7717 Rev 2		Airborne Auxiliary Power - Gas Turbine Engine - Inspection/Replacement of the Coupling Clamp, PN 234-511-9059, T-Bolt (Fuel Control to Lube Pump Flanges)		T (A/R)			
	49 APU1		Mos				
	Eff: 17-Apr-2003		Hrs				
			APUS				
49-7730		REPLACE INLET SCREEN HALVES		T (A/R)			
	49 APU1		Mos				
	Eff: 22-Jul-2003		Hrs				
			APUS				
49-7933 Rev 10		Airborne Auxiliary Power Unit (APU) - Oil - General - Approved Oils		T (A/R)		Service Bulletin	
	49 APU1		Mos				
	Eff: 18-Jan-2022		Hrs				
			APUS				
49-7933 Rev 5		Airborne Auxiliary Power Unit (APU) - Oil - General - Approved Oils		T (-)		Service Bulletin	
	49 APU1		Mos				
	Eff: 23-Oct-2014		Hrs				
			APUS				
49-7933 Rev 6		Airborne Auxiliary Power Unit (APU) - Oil - General - Approved Oils		RE (-)		Service Bulletin	
	49 APU1		Mos				
			Hrs				
			APUS				
49-7933 Rev 7		Airborne Auxiliary Power Unit (APU) - Oil - General - Approved Oils		T (-)		Service Bulletin	
	49 APU1		Mos				
	Eff: 09-Feb-2017		Hrs				
			APUS				
49-7933 Rev 8		Airborne Auxiliary Power Unit (APU) - Oil - General - Approved Oils		T (-)		Service Bulletin	
	49 APU1		Mos				
	Eff: 27-Jul-2017		Hrs				
			APUS				
49-7933 Rev 9		Airborne Auxiliary Power Unit (APU) - Oil - General - Approved Oils		T (-)		Service Bulletin	
	49 APU1		Mos				
	Eff: 03-Apr-2020		Hrs				
			APUS				

Task No SEQ PN/SN	Description MOC Note	CW	REQ	TOL	Categories DUE	Time Remaining
49-7969 49 APU1 Eff: 30-Apr-2008	Replace the Plain Seal (Compressor Seal), Part Number 3616650-1 with Plain Seal (Compressor Seal), Part Number 3616650-3		T (A/R)			
		Mos				
		Hrs				
		APUS				
49-7969 Rev 1 49 APU1 Eff: 01-Feb-2013	Replace the Plain Seal (Compressor Seal), Part Number 3616650-1 with Plain Seal (Compressor Seal), Part Number 3616650-3		T (A/R)			
		Mos				
		Hrs				
		APUS				
49-7997 49 APU1 Eff: 16-Sep-2009 Complied With	Airborne Auxiliary Power - Gas Turbine Engine - Standard Storage and Preservation Guidelines.		RE (-)		Service Bulletin	
		Mos	09-Apr-2024			
		Hrs	443			
		APUS	626			
49-7997 Rev 1 49 APU1 Eff: 11-Feb-2010	Airborne Auxiliary Power - Gas Turbine Engine - Standard Storage and Preservation Guidelines		RE (-)		Service Bulletin	
		Mos				
		Hrs				
		APUS				
49-7997 Rev 2 49 APU1 Eff: 22-Dec-2010	Airborne Auxiliary Power - Gas Turbine Engine - Standard Storage and Preservation Guidelines		RE (-)		Service Bulletin	
		Mos				
		Hrs				
		APUS				
49-7997 Rev 3 49 APU1 Eff: 16-Jan-2014	Airborne Auxiliary Power - Gas Turbine Engine - Standard Storage and Preservation Guidelines		RE (-)		Service Bulletin	
		Mos				
		Hrs				
		APUS				
49-7997 Rev 4 49 APU1 Eff: 12-Jan-2015	Airborne Auxiliary Power - Gas Turbine Engine - Standard Storage and Preservation Guidelines		T (-)		Service Bulletin	
		Mos				
		Hrs				
		APUS				
49-7997 Rev 5 49 APU1 Eff: 03-Feb-2017	Airborne Auxiliary Power - Gas Turbine Engine - Standard Storage and Preservation Guidelines		T (-)		Service Bulletin	
		Mos				
		Hrs				
		APUS				
49-7997 Rev 6 49 APU1 Eff: 05-Nov-2020	Airborne Auxiliary Power - Gas Turbine Engine - Standard Storage and Preservation Guidelines		T (-)		Service Bulletin	
		Mos				
		Hrs				
		APUS				
49-7997 Rev 7 49 APU1 Eff: 05-Sep-2025	Airborne Auxiliary Power - Gas Turbine Engine - Standard Storage and Preservation Guidelines		T (-)		Service Bulletin	
		Mos				
		Hrs				
		APUS				
49-7997 Rev 8 49 APU1 Eff: 26-Dec-2025	Airborne Auxiliary Power - Gas Turbine Engine - Standard Storage and Preservation Guidelines		T (A/R)		Service Bulletin	
		Mos				
		Hrs				
		APUS				
49-8209 49 APU1 Eff: 06-Apr-2016 Complied With	AIRBORNE AUXILIARY POWER (APU) - GAS TURBINE ENGINE - Rework Fluid Pressure Regulating Valve PN 70721587-3 to PN 70721587-4 on Multiple APUs		RE (-)			
		Mos	09-Apr-2024			
		Hrs	443			
		APUS	626			
49-8210 49 APU1 Eff: 04-Apr-2016	SB 49-8210 - Inspect and Replace Fuel Shutoff Valve (FSOV), PN 692545-18, on 36-150 APUs.		T (A/R)			
		Mos				
		Hrs				
		APUS				

Task No		Description				Categories	Time
SEQ	PN/SN	MOC Note	CW	REQ	TOL	DUE	Remaining
49-8252		Airborne - Auxiliary Power Unit (APU) - Approved Fuels for Honeywell Commercial APUs				T (-)	
	49 APU1			Mos			
	Eff: 31-Aug-2018			Hrs			
				APUS			
49-8252 Rev 1		Airborne - Auxiliary Power Unit (APU) - Approved Fuels for Honeywell Commercial APUs				T (-)	
	49 APU1			Mos			
	Eff: 07-Mar-2019			Hrs			
				APUS			
49-8252 Rev 2		Airborne - Auxiliary Power Unit (APU) - Approved Fuels for Honeywell Commercial APUs				T (A/R)	Service Bulletin
	49 APU1			Mos			
	Eff: 13-Oct-2020			Hrs			
				APUS			
49-A7758		ONE TIME INSPECTION/LEAK CHECK ON THE DOWN STREAM SIDE OF THE APU FUEL SHUTOFF VALVE, PART NO. 692545-18				T (A/R)	
	49 APU1			Mos			
	Eff: 14-Aug-2003			Hrs			
				APUS			
49-A7758 Rev 1		ONE TIME INSPECTION/LEAK CHECK ON THE DOWN STREAM SIDE OF THE APU FUEL SHUTOFF VALVE, PART NO. 692545-18				T (A/R)	
	49 APU1			Mos			
	Eff: 04-Sep-2003			Hrs			
				APUS			
49-A7758 Rev 2		ONE TIME INSPECTION/LEAK CHECK ON THE DOWN STREAM SIDE OF THE APU FUEL SHUTOFF VALVE, PART NO. 692545-18				T (A/R)	
	49 APU1			Mos			
	Eff: 13-Dec-2004			Hrs			
				APUS			
70721597-49-8166		Balance Repair of Compressor Rotor, PN 70721597-1, on Multiple APUs				RE (-)	Recommended
	49 APU1			Mos	17-Apr-2023		
	Eff: 02-Jul-2015 Not Applicable	as per rotor P/N		Hrs			
				APUS			
70721597-49-8166 Rev 1		Balance Repair of Compressor Rotor, PN 70721597-1, on Multiple APUs				RE (-)	Recommended
	49 APU1			Mos	17-Apr-2023		
	Eff: 31-Aug-2015 Not Applicable	as per rotor P/N		Hrs			
				APUS			
70721597-49-8166 Rev 2		Balance Repair of Compressor Rotor, PN 70721597-1, on Multiple APUs				RE (-)	Recommended
	49 APU1			Mos	17-Apr-2023		
	Eff: 25-Oct-2016 Not Applicable	as per rotor P/N		Hrs			
				APUS			
70721597-49-8166 Rev 3		Balance Repair of Compressor Rotor, PN 70721597-1, on Multiple APUs				RE (-)	Recommended
	49 APU1			Mos	17-Apr-2023		
	Eff: 13-Oct-2017 Not Applicable	as per rotor P/N		Hrs			
				APUS			
70721598-49-8168		Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of Compressor Rotor, PN 70721598-1, on Multiple APUs				RE (-)	Recommended
	49 APU1			Mos	17-Apr-2023		
	Eff: 02-Jul-2015 Not Applicable	before manufacture		Hrs			
				APUS			
70721598-49-8168 Rev 1		Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of Compressor Rotor, PN 70721598-1, on Multiple APUs				RE (-)	Recommended
	49 APU1			Mos	17-Apr-2023		
	Eff: 20-Oct-2015 Not Applicable	before manufacture		Hrs			
				APUS			

Task No		Description				Categories	Time	
SEQ	PN/SN	MOC Note		CW	REQ	TOL	DUE	Remaining
70721598-49-8168 Rev 2		Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of Compressor Rotor, PN 70721598-1, on Multiple APUs			RE (-)		Recommended	
	49 APU1		Mos	17-Apr-2023				
	Eff: 10-Jan-2017 Not Applicable	before manufacture	Hrs					
			APUS					
70721598-49-8168 Rev 3		Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of Compressor Rotor, PN 70721598-1, on Multiple APUs			RE (-)		Recommended	
	49 APU1		Mos	09-Apr-2024				
	Eff: 14-Dec-2017 Complied With		Hrs	443				
			APUS	626				
70721725-49-8152		Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of The Dual Pilot Turbine Rotors, PN 70721725-2 and PN 70721725-5, on Multiple APUs			RE (-)		Recommended	
	49 APU1		Mos	17-Apr-2023				
	Eff: 27-May-2015 Not Applicable		Hrs					
			APUS					
70721725-49-8152 Rev 1		Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of The Dual Pilot Turbine Rotors, PN 70721725-2 and PN 70721725-5, on Multiple APUs			RE (-)		Recommended	
	49 APU1		Mos	17-Apr-2023				
	Eff: 27-May-2015 Not Applicable		Hrs					
			APUS					
70721725-49-8152 Rev 2		Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of The Dual Pilot Turbine Rotors, PN 70721725-2 and PN 70721725-5, on Multiple APUs			RE (-)		Recommended	
	49 APU1		Mos	17-Apr-2023				
	Not Applicable		Hrs					
			APUS					
70721725-49-8152 Rev 3		Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of The Dual Pilot Turbine Rotors, PN 70721725-2 and PN 70721725-5, on Multiple APUs			RE (-)		Recommended	
	49 APU1		Mos	17-Apr-2023				
	Eff: 27-Nov-2017 Not Applicable		Hrs					
			APUS					
70721725-49-8152 Rev 4		Airborne Auxiliary Power - Gas Turbine Engine - Balance Repair of the Dual Pilot Turbine Rotors, PN 70721725-2 and PN 70721725-5, on Multiple APUs			RE (-)		Recommended	
	49 APU1		Mos	09-Apr-2024				
	Eff: 19-Dec-2017 Complied With		Hrs	443				
			APUS	626				
APU-146		Special On-wing Troubleshooting Check Sheet for Oil “Smell-In-Cabin” (SIC) Complaints			T (A/R)		Service Information Letter	
	49 APU1		Mos					
	Eff: 18-Aug-2007		Hrs					
			APUS					
APU-151		Honeywell Commercial Auxiliary Power Unit (APU) Oil Approvals.			T (A/R)		Service Information Letter	
	49 APU1		Mos					
	Eff: 25-Oct-2007		Hrs					
			APUS					
APU-41		PRECAUTIONARY MEASURES TO PREVENT EXCESSIVE AXIAL LOADING OF APUGENERATOR OUTPUT SHAFT SEALS AND BEARINGS			RE (-)		Service Information Letter	
	49 APU1		Mos					
	Eff: 05-May-1989		Hrs					
			APUS					
APU-41 Rev 1		PRECAUTIONARY MEASURES TO PREVENT EXCESSIVE AXIAL LOADING OF APUGENERATOR OUTPUT SHAFT SEALS AND BEARINGS			T (A/R)		Service Information Letter	
	49 APU1		Mos					
	Eff: 05-May-1989		Hrs					
			APUS					
APU-42		IMPROPER SERVICING PROCEDURES - UNAUTHORIZED USE OF SILICONE BASEDLUBRICANTS ON OIL-WETTED COMPONENTS WITHIN THE APU'SLUBRICATION SYSTEM			T (A/R)		Service Information Letter	
	49 APU1		Mos					
	Eff: 17-Feb-1989		Hrs					
			APUS					

Task No		Description				Categories	Time
SEQ	PN/SN	MOC Note	CW	REQ	TOL	DUE	Remaining
APU-46		RECOMMENDED ONE-TIME INSPECTION OF NAMEPLATE RIVETS FOR PROPERINSTALLATION		T (A/R)		Service Information Letter	
	49 APU1						
	Eff: 25-Feb-1991						
APU-7		Aircraft De-icing and its Possible Effects on Honeywell Auxiliary Power Units (APUs)		RE (-)		Service Information Letter	
	49 APU1						
	Eff: 03-Mar-1988						
APU-7 Rev 1		Aircraft De-icing and its Possible Effects on Honeywell Auxiliary Power Units (APUs)		RE (-)		Service Information Letter	
	49 APU1						
	Eff: 03-Mar-1988						
APU-7 Rev 2		Aircraft De-icing and its Possible Effects on Honeywell Auxiliary Power Units (APUs)		T (A/R)		Service Information Letter	
	49 APU1						
	Eff: 02-Mar-2015						
APU-78		Auxiliary Power Unit (APU) Operational Instructions		RE (-)		Service Information Letter	
	49 APU1						
	Eff: 05-Aug-2003						
APU-78 Rev 1		Auxiliary Power Unit (APU) Operational Instructions		RE (-)		Service Information Letter	
	49 APU1						
	Eff: 30-Sep-2004						
APU-78 Rev 2		Auxiliary Power Unit (APU) Operational Instructions		T (A/R)		Service Information Letter	
	49 APU1						
	Eff: 30-Sep-2004						
APU-83		SPOTLIGHT TROUBLESHOOTING SYSTEM		RE (-)		Service Information Letter	
	49 APU1						
	Eff: 24-Dec-2003						
APU-83 Rev 1		SPOTLIGHT TROUBLESHOOTING SYSTEM		RE (-)		Service Information Letter	
	49 APU1						
	Eff: 31-Jan-2007						
APU-83 Rev 2		SPOTLIGHT TROUBLESHOOTING SYSTEM		T (A/R)		Service Information Letter	
	49 APU1						
	Eff: 31-Jan-2007						
D200904000013		To advise the field of the release of Service Bulletin GTC36-49-7969.		T (A/R)		Service Information Letter	
	49 APU1						
	Eff: 13-Apr-2009						
D201010000068		Operations in Volcanically Active Areas		T (A/R)		Service Information Letter	
	49 APU1						
	Eff: 03-Mar-2011						
D201012000013		General Handling Information for Ignition Exciters Containing the Radioactive Element Krypton-85(Krypton 85) Above 10,000 Becquerels		RE (-)		Service Information Letter	
	49 APU1						
	Eff: 08-Mar-2011						

Task No		Description	CW	REQ	TOL	Categories	Time
SEQ	PN/SN	MOC Note				DUE	Remaining
D201012000013 Rev 1		General Handling Information for Ignition Exciters Containing the Radioactive Element Krypton-85(Krypton 85) Above 10,000 Becquerels		T (A/R)		Service Information Letter	
	49 APU1						Mos
	Eff: 15-Jan-2015						Hrs
							APUS
D201107000024		Approved Use of Hydroprocessed Esters and Fatty Acids (HEFA) Biofuel Blends for all Honeywell Commercial Auxiliary Power Units (APU)		T (-)		Service Information Letter	
	49 APU1						Mos
	Eff: 07-Sep-2011						Hrs
							APUS
D201107000024 Rev 1		Approved Use of Biofuel Blends for All Honeywell Commercial and Military Auxiliary Power Units (APU)		T (A/R)		Service Information Letter	
	49 APU1						Mos
	Eff: 03-Jun-2020						Hrs
							APUS
D201107000065		Auxiliary Power Unit Operations in Volcanically Active Areas		T (A/R)		Service Information Letter	
	49 APU1						Mos
	Eff: 19-Aug-2011						Hrs
							APUS
D201112000050		Acceptance Criteria for On-Wing Borescope Inspections		RE (-)		Service Information Letter	
	49 APU1						Mos
	Eff: 13-Jan-2012						Hrs
							APUS
D201112000050 Rev 2		Acceptance Criteria for On-Wing Borescope Inspections		RE (-)		Service Information Letter	
	49 APU1			26-Feb-2025			Mos
	Eff: 26-Nov-2024 Complied With						Hrs
							APUS
D201112000050 Rev 3		Acceptance Criteria for On-Wing Borescope Inspections		T (A/R)		Service Information Letter	
	49 APU1						Mos
	Eff: 11-Mar-2025						Hrs
							APUS
D202311004191		GTC36-150 Series APU LCV Filter - Removal, Inspection, and Installation Procedure		T (A/R)		Service Information Letter	
	49 APU1						Mos
	Eff: 28-Nov-2023						Hrs
							APUS
D202603005252		36-150 Auxiliary Power Units (APU) - Incorporate Improved LOP Switch 3876001-4 Design by Supplier Custom Controls Sensors (CCS)		T (A/R)		Service Information Letter	
	49 APU1						Mos
	Eff: 13-Jul-2026						Hrs
							APUS
GTC36-49-8096		Airborne Auxiliary Power - Gas Turbine Engine - Replace the Fuel Supply Tube Assembly PN 3882732-1 with PN 3882732-2		RE (-)		Recommended, Service Bulletin	
	49 APU1			17-Apr-2023			Mos
	Eff: 22-Jul-2013 Not Applicable	APU P/N not installed					Hrs
							APUS
GTC36-49-8096 Rev 1		Airborne Auxiliary Power - Gas Turbine Engine - Replace the Fuel Supply Tube Assembly PN 3882732-1 with PN 3882732-2		RE (-)		Recommended, Service Bulletin	
	49 APU1			14-Apr-2023			Mos
	Eff: 24-Sep-2015 Not Applicable	as per APU S/N					Hrs
							APUS
GTC36-49-8119 Rev 4		Airborne Auxiliary Power - Gas Turbine Engine - Rotating Group Balance Procedure		T (A/R)		Optional	
	49 APU1						Mos
	Eff: 30-Mar-2017						Hrs
							APUS

Task No		Description				Categories	Time
SEQ	PN/SN	MOC Note	CW	REQ	TOL	DUE	Remaining
GTCP36-49-8191		Airborne Auxiliary Power - Gas Turbine Engine - Rework and Repair of Engine 36-150[IAI],PN 3800710-1 and PN 3800710-2, for Incorporation of Improved Compressor Carbon Seal and Related Components		T (-)		Optional	
	49 APU1						
	Eff: 14-Feb-2017						
GTCP36-49-8191 Rev 1		Airborne Auxiliary Power - Gas Turbine Engine - Rework and Repair of Engine 36-150[IAI], PN 3800710-1 and PN 3800710-2, for Incorporation of Improved Compressor Carbon Seal and Related Components		T (A/R)		Optional	
	49 APU1						
	Eff: 31-Jan-2019						
GTCP36-49-8318		Airborne Auxiliary Power - Gas Turbine Engine - Replace Fuel Nozzle Assembly, PN 3610004-3 and 3610004-4 with Fuel Nozzle Assembly PN 3610004-5 and 3610004-6 on Affected APU Models		RE (-)		Recommended	
	49 APU1						
	Eff: 30-Jun-2020 Not Applicable						
GTCP36-49-8332		Airborne Auxiliary Power - Gas Turbine Engine - Replace Ring Gear, PN 3860331-1 with Ring Gear PN 3860331-2 on Affected APU Models		RE (-)		Mandatory	
	49 APU1						
	Eff: 31-Jul-2020 Not Applicable	per APU P/N					
SIL 78		36-150 EMB APU Lift Fixture, Retrofit of sub-component PN 31060 shoulder bolt		T (A/R)		Service Information Letter	
	49 APU1						
	Eff: 11-Sep-2011						
SIL APU-152		Notify Field and Honeywell Operators of the Background and Current Situation Regarding Possible FAME (Fatty Acid Methyl Ester) Contamination in Aviation Turbine Fuel		RE (-)		Service Information Letter	
	49 APU1						
	Eff: 18-Jul-2008						
SIL APU-152 Rev 1		Notify Field and Honeywell Operators of the Background and Current Situation Regarding Possible FAME (Fatty Acid Methyl Ester) Contamination in Aviation Turbine Fuel		RE (-)		Service Information Letter	
	49 APU1						
	Eff: 24-Jul-2009						
SIL APU-152 Rev 2		Notify Field and Honeywell Operators of the Background and Current Situation Regarding Possible FAME (Fatty Acid Methyl Ester) Contamination in Aviation Turbine Fuel		RE (-)		Service Information Letter	
	49 APU1						
	Eff: 30-Nov-2010						
SIL APU-152 Rev 3		Notify Field and Honeywell Operators of the Background and Current Situation Regarding Possible FAME (Fatty Acid Methyl Ester) Contamination in Aviation Turbine Fuel		RE (-)		Service Information Letter	
	49 APU1						
	Eff: 19-Feb-2015						
SIL APU-152 Rev 4		Notify Field and Honeywell Operators of the Background and Current Situation Regarding Possible FAME (Fatty Acid Methyl Ester) Contamination in Aviation Turbine Fuel		T (A/R)		Service Information Letter	
	49 APU1						
	Eff: 08-Feb-2018						
SIL D201701000026		Airborn Auxiliary Power - Gas Turbine Engine - Honeywell Auxiliary Power Unit (APU) Rental Engine Worksheet for 36-100, 36-150, RE100, and RE220 APUs		RE (-)		Service Information Letter	
	49 APU1						
	Eff: 30-Jan-2017						

Task No		Description				Categories	Time
SEQ	PN/SN	MOC Note	CW	REQ	TOL	DUE	Remaining
SIL D201701000026 Rev 1		Airborn Auxiliary Power - Gas Turbine Engine - Honeywell Auxiliary Power Unit (APU) Rental Engine Worksheet for 36-100, 36-150, RE100, and RE220 APUs		T (-)		Service Information Letter	
	49 APU1						
	Eff: 23-Jan-2018						
SIL D201701000026 Rev 2		Airborn Auxiliary Power - Gas Turbine Engine - Honeywell Auxiliary Power Unit (APU) Rental Engine worksheet for 36-100, 36-150, RE100, and RE220 APUs		T (A/R)		Service Information Letter	
	49 APU1						
	Eff: 21-Mar-2018						
SIL No. APU-49 Rev 10		Implementation of the Honeywell Spectrometric Oil and Filter Analysis Program (SOAP) for Honeywell Auxiliary Power Units (APUs)		RE (-)		Service Information Letter	
	49 APU1						
SIL No. APU-49 Rev 11		Implementation of the Honeywell Spectrometric Oil and Filter Analysis Program (SOAP) for Honeywell Auxiliary Power Units(APUs)		RE (-)		Service Information Letter	
	49 APU1						
SIL No. APU-49 Rev 12		Implementation of the Honeywell Spectrometric Oil and Filter Analysis Program (SOAP) for Honeywell Auxiliary Power Units (APUs)		RE (-)		Service Information Letter	
	49 APU1						
SIL No. APU-49 Rev 13		Implementation of the Honeywell Spectrometric Oil and Filter Analysis Program (SOAP) for Honeywell Auxiliary Power Units (APUs)		T (-)		Service Information Letter	
	49 APU1						
	Eff: 23-Nov-2023						
SIL No. APU-49 Rev 14		Implementation of the Honeywell Spectrometric Oil and Filter Analysis Program (SOAP) for Honeywell Auxiliary Power Units (APUs)		T (-)		Service Information Letter	
	49 APU1						
	Eff: 12-Feb-2025						
SIL No. APU-49 Rev 15		Implementation of the Honeywell Aerospace Spectrometric Oil and Filter Analysis Program (SOAP) for Honeywell Aerospace Auxiliary Power Units (APUs)		T (A/R)		Service Information Letter	
	49 APU1						
	Eff: 10-Jul-2026						
▼ 52 - DOORS							
280-52-013		Doors - Main Entrance Door (MED) - Installation Of Fiber Optics Viewport (MODG25- 20003)		RE (-)		Mandatory	
	52 A/F						
	Eff: 13-Nov-2012 Complied With						
280-52-027		Doors Replacement Of The Existing Door Locks With New Door Locks On Aft Fuselage Service Door, Waste System Service Door And Air Turbine Starter (ATS) Door (MODG25-00172)		RE (-)		Recommended	
	52 A/F						
	Eff: 31-Jan-2014 Not Applicable	PER AIRCRAFT SERIAL NUMBER					
280-52-034		Doors - Baggage Door Mechanism - Replacement Of The Existing Track Rollers With Improved Track Rollers (MODG25-00496)		RE (-)		Recommended	
	52 A/F						
	Eff: 12-Dec-2014 Not Applicable	PER AIRCRAFT SERIAL NUMBER					
280-52-039		Doors - Auxiliary Bulkhead Door Lock Mechanism - Addition Of Arm Stopper (MODG25-00217)		RE (-)		Recommended	
	52 A/F						
	Eff: 05-Mar-2015 Not Applicable	PER AIRCRAFT SERIAL NUMBER					

Task No		Description			Categories	Time		
SEQ	PN/SN	MOC Note		CW	REQ	TOL	DUE	Remaining
280-52-090		Doors - Waste Panel Door Assembly Rework (MODG25-00450)			RE (-)		Recommended	
	52 A/F			Mos	10-Feb-2023			
	Eff: 21-Nov-2014 Not Applicable	PER AIRCRAFT SERIAL NUMBER		Hrs	24:24			
				Ldg	7			
280-52-103		Doors - Main Entrance Door - Door Holder Mechanism Spring - Inspection And Replacement (MODG25-00439)			RE (-)		Recommended	
	52 A/F			Mos	10-Feb-2023			
	Eff: 12-Dec-2014 Not Applicable	PER AIRCRAFT SERIAL NUMBER		Hrs	24:24			
				Ldg	7			
280-52-116		Doors - Fuselage Fairing Doors - Wing Tank Drain Valve Door Hinge Rework (MODG25-00579)			RE (-)		Recommended	
	52 A/F			Mos	14-Apr-2023			
	Eff: 26-Nov-2014 Not Applicable	as per a/c S/N		Hrs	112:17			
				Ldg	61			
280-52-116 Rev 1		Doors - Fuselage Fairing Doors - Wing Tank Drain Valve Door Hinge Rework (MODG25-00579)			RE (-)		Recommended	
	52 A/F			Mos	10-Feb-2023			
	Eff: 26-Nov-2014 Not Applicable	PER AIRCRAFT SERIAL NUMBER		Hrs	24:24			
				Ldg	7			
280-52-126		Doors - Auxiliary Bulkhead Door Lock Mechanism - D-Ring And Bolt Replacement (MODG25-00619)			RE (-)		Recommended	
	52 A/F			Mos	14-Apr-2023			
	Eff: 05-Mar-2015 Not Applicable	as per a/c S/N		Hrs	112:17			
				Ldg	61			
280-52-126 Rev 1		Doors - Auxiliary Bulkhead Door Lock Mechanism - D-Ring And Bolt Replacement (MODG25-00619)			RE (-)		Recommended	
	52 A/F			Mos	10-Feb-2023			
	Eff: 05-Mar-2015 Not Applicable	PER AIRCRAFT SERIAL NUMBER		Hrs	24:24			
				Ldg	7			
280-52-136		Doors - APU Door - Door Latch Installation Inspection			RE (-)		Recommended	
	52 A/F			Mos	10-Feb-2023			
	Eff: 30-May-2014 Not Applicable	PER AIRCRAFT SERIAL NUMBER		Hrs	24:24			
				Ldg	7			
280-52-137		Doors - Air Turbine Starter (ATS) Door - Contour - Rework (MODG25-00671)			RE (-)		Recommended	
	52 A/F			Mos	10-Feb-2023			
	Eff: 25-Sep-2015 Not Applicable	PER AIRCRAFT SERIAL NUMBER		Hrs	24:24			
				Ldg	7			
280-52-139		Doors - Emergency Exit Door - Inspection Of Brackets, P/N 30P332003600-001 (MODG25-00397)			RE (-)		Recommended	
	52 A/F			Mos	10-Feb-2023			
	Eff: 15-Nov-2015 Not Applicable	PER AIRCRAFT SERIAL NUMBER		Hrs	24:24			
				Ldg	7			
280-52-163		Doors - Exterior Door Locks Rework (MODG25-00847 , G25-01342)			RE (-)		Optional	
	52 A/F			Mos				
	Eff: 06-Apr-2016			Hrs				
				Ldg				
280-52-319		Doors - Main Entrance Door - Door Safety and Door Close Switches and Connectors - Replacement			RE (-)		Recommended	
	52 A/F			Mos	10-Feb-2023			
	Eff: 10-Aug-2022 Not Applicable	PER AIRCRAFT SERIAL NUMBER		Hrs	24:24			
				Ldg	7			

Task No		Description				Categories	Time
SEQ	PN/SN	MOC Note	CW	REQ	TOL	DUE	Remaining
280-52-319 Rev 1		Doors - Main Entrance Door - Door Safety and Door Close Switches and Connectors - Replacement		RE (-)		Recommended	
	52 A/F		Mos	10-Mar-2025			
	Eff: 10-Aug-2022 Complied With		Hrs				
	(UPDATE NOTE: AF by SN of the aircraft)		Ldg				
280-52-319 Rev 2		Doors - Main Entrance Door - Door Safety and Door Close Switches and Connectors - Replacement		RE (-)		Recommended	
	52 A/F		Mos	10-Jul-2025			
	Eff: 12-Dec-2024 Complied With		Hrs				
	(UPDATE NOTE: AF)		Ldg				
280-52-319 Rev 3		Doors - Main Entrance Door - Door Safety and Door Close Switches and Connectors - Replacement		RE (-)		Recommended	
	52 A/F		Mos	10-Jul-2025			
	Eff: 18-Jun-2025 Complied With		Hrs				
	(UPDATE NOTE: AF)		Ldg				
280-52-319 Rev 4		Doors - Main Entrance Door - Door Safety and Door Close Switches and Connectors - Replacement		T		Recommended	
	52 A/F		Mos	24		10-Jun-2028	1.7 Years
	Eff: 10-Jun-2026		Hrs				
			Ldg				
280-52-346		Doors - Main Entrance Door - Swap FWD and AFT Lift Fittings		RE (-)		Recommended	
	52 A/F		Mos				
	Eff: 07-Jul-2026		Hrs				
			Ldg				
280-52-346 Rev 1		Doors - Main Entrance Door - Swap FWD and AFT Lift Fittings		T		Recommended	≈18-Oct-2026
	52 A/F		Mos				
			Hrs				
			Ldg	1,250		1,250	21 Ldg
ISR-I-52-2026-07-32		Doors - Main Entrance Door (MED) Fittings - Discard and Replace		RE (-)		Mandatory	
	52 A/F		Mos	24-Aug-2026			
	Eff: 26-Jul-2026 Complied With	with Eclair AMPG280 Rev. 05 dated 24.08.2026.	Hrs				
			Ldg				
▼ 53 - FUSELAGE							
2020-15-02		Fuselage - FWD Fuel Tank Probes Clearance Verification		RE (-)		Mandatory	
	53 A/F		Mos	10-Feb-2023			
	Eff: 27-Aug-2020 Not Applicable	PER CAAI ISRAEL AD NO. ISR-I-53-19-10-5.	Hrs	24:24			
			Ldg	7			
280-53-020		Fuselage - Joining Assembly Bulkhead Aft Fuselage - Rework (MODG25-00255)		RE (-)		Recommended	
	53 A/F		Mos	10-Feb-2023			
	Eff: 13-Sep-2013 Not Applicable	PER AIRCRAFT SERIAL NUMBER	Hrs	24:24			
			Ldg	7			
280-53-023		Fuselage - Forward Pressure Bulkhead - Rework (MODG25-00210)		RE (-)		Recommended	
	53 A/F		Mos	10-Feb-2023			
	Eff: 13-Sep-2013 Not Applicable	PER AIRCRAFT SERIAL NUMBER	Hrs	24:24			
			Ldg	7			
280-53-031		Fuselage - Wing To Fuselage Connection, Right Side - Installation Of A New Bracket And Clamps To Support Electrical Harness (MODG25-00225)		RE (-)		Recommended	
	53 A/F		Mos	10-Feb-2023			
	Eff: 26-Jul-2013 Not Applicable	PER AIRCRAFT SERIAL NUMBER	Hrs	24:24			
			Ldg	7			

Task No SEQ PN/SN	Description MOC Note		CW	REQ	TOL	Categories DUE	Time Remaining
280-53-032	Fuselage - Joining, Forward Fuselage To Center Fuselage - Installation Of A New Bracket And Clamp To Support Water System Hose Near Floor Structure (MODG25- 00204)			RE (-)		Recommended	
 53 A/F Eff: 24-Jan-2014 Not Applicable	PER AIRCRAFT SERIAL NUMBER		Mos	10-Feb-2023			
			Hrs	24:24			
			Ldg	7			
280-53-042	Fuselage - Replacement Of Anti-Rotation Washers On Wing To Fuselage Links (MODG25-20032)			RE (-)		Mandatory	
 53 A/F Eff: 13-Sep-2013 Not Applicable	PER AIRCRAFT SERIAL NUMBER		Mos	10-Feb-2023			
			Hrs	24:24			
			Ldg	7			
280-53-051	Fuselage - Cockpit - Left And Right Side Console Structure - Replacement Of Existing Aircraft Personality Module (APM) Attachment Nut Plates (MODG25-00337)			RE (-)		Recommended	
 53 A/F Eff: 02-Aug-2013 Not Applicable	PER AIRCRAFT SERIAL NUMBER		Mos	10-Feb-2023			
			Hrs	24:24			
			Ldg	7			
280-53-069	Fuselage - Nose Structure - Avionics Bay Rework (MODG25-00396)			RE (-)		Recommended	
 53 A/F Eff: 04-Oct-2013 Not Applicable	PER AIRCRAFT SERIAL NUMBER		Mos	10-Feb-2023			
			Hrs	24:24			
			Ldg	7			
280-53-070	Fuselage - Aft Fuselage Left Side Panel - Installation Of Clamp To Support Electrical Harness Near R/T HF9030 Support Assembly (MODG25-00395)			RE (-)		Recommended	
 53 A/F Eff: 04-Oct-2013 Not Applicable	PER AIRCRAFT SERIAL NUMBER		Mos	10-Feb-2023			
			Hrs	24:24			
			Ldg	7			
280-53-074	Fuselage - Right Side Fuselage - Forward Fuel Tank Fairing - Rework (MODG25- 00387)			RE (-)		Recommended	
 53 A/F Eff: 30-Oct-2015 Not Applicable	PER AIRCRAFT SERIAL NUMBER		Mos	10-Feb-2023			
			Hrs	24:24			
			Ldg	7			
280-53-084	Fuselage - Right Side Forward Fairing - Installation Of Additional Clamps To Improve Attachment Of Electrical Harness 1527 To Fairing (MODG25-00405)			RE (-)		Recommended	
 53 A/F Eff: 10-Jan-2014 Not Applicable	PER AIRCRAFT SERIAL NUMBER		Mos	10-Feb-2023			
			Hrs	24:24			
			Ldg	7			
280-53-092	Fuselage - Aft Fuselage - Electrical Bonding Improvement Of Service Panel Light (MODG25-00424)			RE (-)		Recommended	
 53 A/F Eff: 26-Jun-2015 Not Applicable	PER AIRCRAFT SERIAL NUMBER		Mos	10-Feb-2023			
			Hrs	24:24			
			Ldg	7			
280-53-096	Fuselage - Forward Right Side - Fuel Tank Assembly Rework And Electrical Harness Routing Modification (MODG25-20057)			RE (-)		Recommended	
 53 A/F Eff: 07-Nov-2014 Not Applicable	as per a/c S/N		Mos	14-Apr-2023			
			Hrs	112:17			
			Ldg	61			
280-53-096 Rev 1	Fuselage - Forward Right Side - Fuel Tank Assembly Rework And Electrical Harness Routing Modification (MODG25-20057)			RE (-)		Recommended	
 53 A/F Eff: 07-Nov-2014 Not Applicable	PER AIRCRAFT SERIAL NUMBER		Mos	10-Feb-2023			
			Hrs	24:24			
			Ldg	7			

Task No	Description	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note				DUE	Remaining
280-53-104	Fuselage - Cockpit - Fuselage Stations 1663-4518 - Nose Landing Gear (NLG) Pivot Guide Tube Rework (MODG25-00454)		RE (-)		Recommended	
 53 A/F		Mos	10-Feb-2023			
Eff: 19-Dec-2014 Not Applicable	PER AIRCRAFT SERIAL NUMBER	Hrs	24:24			
		Ldg	7			
280-53-112	Fuselage - Forward Fuselage Bulkheads And Frames - Rudder Bellcrank And Support Fittings Rework (MODG25-00511)		RE (-)		Recommended	
 53 A/F		Mos	10-Feb-2023			
Eff: 12-Dec-2014 Not Applicable	PER AIRCRAFT SERIAL NUMBER	Hrs	24:24			
		Ldg	7			
280-53-117	Fuselage - Forward Fuselage - Potable Water Line Routing Modification (MODG25- 00580)		RE (A/R)		Recommended	
 53 A/F		Mos	10-Feb-2023			
Eff: 30-Oct-2015 Not Applicable	PER AIRCRAFT SERIAL NUMBER	Hrs	24:24			
		Ldg	7			
280-53-118	Fuselage Structure - Cockpit Window Structure - Windshield Lower Sill Rework		RE (-)		Recommended	
 53 A/F		Mos	10-Jul-2025			
Eff: 02-Jul-2025 Not Applicable		Hrs				
(UPDATE NOTE: NA by SN of the aircraft)		Ldg				
280-53-118 Rev 1	Fuselage Structure - Cockpit Window Structure - Windshield Lower Sill Rework		RE (-)		Recommended	
 53 A/F		Mos				
Eff: 01-Aug-2025 Not Applicable	by aircraft SN.	Hrs				
		Ldg				
280-53-119	Fuselage Structure - Center Fuselage - Flange Between Frames 32 Through 36 Under Escape Door Cold Work		RE (-)		Recommended	
 53 A/F		Mos	10-Mar-2025			
Eff: 16-Nov-2016 Not Applicable		Hrs				
(UPDATE NOTE: NA by SN of the Aircraft)		Ldg				
280-53-119 Rev 1	Fuselage Structure - Center Fuselage - Flange Between Frames 32 Through 36 Under Escape Door Cold Work		RE (-)		Recommended	
 53 A/F		Mos	10-Mar-2025			
Eff: 07-Mar-2025 Not Applicable		Hrs				
(UPDATE NOTE: NA by SN of the Aircraft)		Ldg				
280-53-119 Rev 2	Fuselage Structure - Center Fuselage - Flange Between Frames 32 Through 36 Under Escape Door Cold Work		RE (-)		Recommended	
 53 A/F		Mos				
Eff: 18-Sep-2025 Not Applicable	by aircraft SN.	Hrs				
		Ldg				
280-53-119 Rev 3	Fuselage Structure - Center Fuselage - Flange Between Frames 32 Through 36 Under Escape Door Cold Work		RE (-)		Recommended	
 53 A/F		Mos				
Eff: 18-Sep-2025 Not Applicable	by aircraft SN	Hrs				
		Ldg				
280-53-120	Fuselage Structure - Cockpit Window Structure - Lower Sill Cold Work		RE (-)		Recommended	
 53 A/F		Mos	10-Jul-2025			
Eff: 02-Jul-2025 Not Applicable		Hrs				
(UPDATE NOTE: NA by SN of the aircraft)		Ldg				
280-53-120 Rev 1	Fuselage Structure - Cockpit Window Structure - Lower Sill Cold Work		RE (-)		Recommended	
 53 A/F		Mos				
Eff: 01-Aug-2025 Not Applicable	by aircraft SN.	Hrs				
		Ldg				

Task No SEQ PN/SN	Description MOC Note	CW	REQ	TOL	Categories DUE	Time Remaining
280-53-134  53 A/F	Fuselage - Forward Fuel Tank And Forward Lower Fairing - Improvement Of Installation Process When Replacing Forward Fuel Tank (MODG25-00648)		RE (-)		Recommended	
		Mos				
		Hrs				
		Ldg				
280-53-140  53 A/F Eff: 30-Oct-2015 Not Applicable	Fuselage - Baggage Compartment Structure - Replacement Of Existing Stoppers And Serrated Plates (MODG25-10046) PER AIRCRAFT SERIAL NUMBER		RE (-)		Recommended	
		Mos	10-Feb-2023			
		Hrs	24:24			
		Ldg	7			
280-53-147  53 A/F Eff: 30-Oct-2015 Not Applicable	Fuselage - Aft Fuselage - High Frequency (HF) - Antenna Coax Cable Electrical Bonding - Rework (MODG25-00708) PER AIRCRAFT SERIAL NUMBER		RE (-)		Recommended	
		Mos	10-Feb-2023			
		Hrs	24:24			
		Ldg	7			
280-53-149  53 A/F Eff: 30-Oct-2015 Not Applicable	Fuselage - Right Aft Fuselage - Inspection For Possible Interference Between Angle And Skin At Frame 59 (MODG25-00739) PER AIRCRAFT SERIAL NUMBER		RE (-)		Recommended	
		Mos	10-Feb-2023			
		Hrs	24:24			
		Ldg	7			
280-53-162  53 A/F Eff: 02-Feb-2017 Not Applicable	Fuselage - Tail Compartment - Installation Of A Water Collection And Drainage Diversion At Frame 63 (MODG25-00841) as per a/c S/N		RE (-)		Recommended	
		Mos	14-Apr-2023			
		Hrs	112:17			
		Ldg	61			
280-53-162 Rev 1  53 A/F Eff: 02-Feb-2017 Not Applicable	Fuselage - Tail Compartment - Installation of a Water Collection and Drainage Diversion at Frame 63 (MODG25-00841) PER AIRCRAFT SERIAL NUMBER		RE (-)		Recommended	
		Mos	10-Feb-2023			
		Hrs	24:24			
		Ldg	7			
280-53-171  53 A/F Eff: 19-Jun-2015 Not Applicable	Fuselage - Aft Fuselage - Installation Of A New Bonding Jumper Between Frame 60 And Elevator Force Disconnect Unit (MODG25-00902) PER AIRCRAFT SERIAL NUMBER		RE (-)		Recommended	
		Mos	10-Feb-2023			
		Hrs	24:24			
		Ldg	7			
280-53-183  53 A/F Eff: 19-Jun-2015 Not Applicable	Fuselage - Aft Fuselage - Inverter/CVR Tray Assembly - Replacement of Fasteners Attaching Grounding Bracket And Modify Static Inverter Electrical Bonding Area (MODG25-00956) PER AIRCRAFT SERIAL NUMBER		RE (-)		Recommended	
		Mos	10-Feb-2023			
		Hrs	24:24			
		Ldg	7			
280-53-192  53 A/F Eff: 13-Jul-2022 Not Applicable	Fuselage - Cockpit Pedestal - Cockpit Floor Inspection and Repair as per a/c S/N		RE (-)		Recommended	
		Mos	14-Apr-2023			
		Hrs	112:17			
		Ldg	61			
280-53-218  53 A/F Eff: 24-Oct-2017 Not Applicable	Fuselage - Forward Fuselage - ATC Coax Cable under Forward Radio Rack Routing - Rework PER AIRCRAFT SERIAL NUMBER		RE (-)		Recommended	
		Mos	10-Feb-2023			
		Hrs	24:24			
		Ldg	7			
280-53-250  53 A/F Eff: 22-Aug-2017 Not Applicable	Structure - HF Radio Box and Hydraulic Tube Riding Condition (MODG25-01544) PER AIRCRAFT SERIAL NUMBER		RE (-)		Recommended	
		Mos	10-Feb-2023			
		Hrs	24:24			
		Ldg	7			

Task No	Description	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note				DUE	Remaining
280-53-263	Fuselage (ATA 53) - AFT Fuselage - Preventing Fluid Accumulation in Frame 64		RE (-)		Recommended	
 53 A/F		Mos	10-Feb-2023			
Eff: 09-Dec-2022 Not Applicable	PER AIRCRAFT SERIAL NUMBER	Hrs	24:24			
		Ldg	7			
280-53-282	Fuselage - Left Nose Avionics Equipment Bay - Thermal Switches Bracket Rework		RE (-)		Recommended	
 53 A/F		Mos	10-Feb-2023			
Eff: 09-Apr-2020 Not Applicable	PER AIRCRAFT SERIAL NUMBER	Hrs	24:24			
		Ldg	7			
280-53-287	Fuselage - Forward Fuel Tank Probe Clearance Verification		RE (-)		Mandatory, Service Bulletin	
 53 A/F		Mos	10-Feb-2023			
Eff: 19-Feb-2020 Not Applicable	PER AIRCRAFT SERIAL NUMBER	Hrs	24:24			
		Ldg	7			
280-53-312	Fuselage - Aft Fuselage - Avionic Harness Rerouting at Frame 63		RE (-)		Recommended	
 53 A/F		Mos	10-Feb-2023			
Eff: 11-Nov-2022 Not Applicable	PER AIRCRAFT SERIAL NUMBER	Hrs	24:24			
		Ldg	7			
280-53A-033	Fuselage Structure - Side Brace Fitting Bolts - Inspection And Repair (MODG25- 00304)		RE (-)		Mandatory	
 53 A/F		Mos	10-Feb-2023			
Eff: 23-Jan-2013 Not Applicable	PER AIRCRAFT SERIAL NUMBER	Hrs	24:24			
		Ldg	7			
ISR-I-53-19-10-5	Forward Fuel Tank Probes Clearance Verification		RE (-)		Mandatory	
 53 A/F		Mos	09-Nov-2022			
Eff: 30-Nov-2019 Not Applicable	BY AIRCRAFT SERIAL NUMBER	Hrs				
		Ldg				
▼ 54 - NACELLES/PYLONS						
D202010001408	Aircraft Nacelle Inlet Cowl Assembly - Gold Tinting/Discoloration of Lip Skin		T (A/R)		Service Information Letter	
 54 ENG1		Mos				
Eff: 17-Nov-2020		Hrs				
		Enc				
D202010001408	Aircraft Nacelle Inlet Cowl Assembly - Gold Tinting/Discoloration of Lip Skin		T (A/R)		Service Information Letter	
 54 ENG2		Mos				
Eff: 17-Nov-2020		Hrs				
		Enc				
▼ 55 - STABILIZERS						
280-55-021	Stabilizers - Vertical Stabilizer (V/S) And Horizontal Stabilizer (H/S) - Structure Joining Assemblies Repair (MODG25-00212)		RE (-)		Recommended	
 55 A/F		Mos	10-Feb-2023			
Eff: 12-Dec-2014 Not Applicable	PER AIRCRAFT SERIAL NUMBER	Hrs	24:24			
		Ldg	7			
280-55-024	Stabilizers - Horizontal Stabilizer - Brace Assembly Rework - Addition Of Chamfer To Scissor Attachment Bolts (Empennage) (MODG25-00236)		RE (-)		Recommended	
 55 A/F		Mos	10-Feb-2023			
Eff: 06-Feb-2015 Not Applicable	PER AIRCRAFT SERIAL NUMBER	Hrs	24:24			
		Ldg	7			

Task No	Description	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note				DUE	Remaining
280-55-026	Stabilizers - Horizontal Stabilizer Trim Actuator (HSTA) - Front Upper Attachment Assembly - Shear Rings - Rework (MODG25-00214)				RE (-)	Recommended
 55 A/F		Mos	10-Feb-2023			
Eff: 12-Dec-2014 Not Applicable	PER AIRCRAFT SERIAL NUMBER	Hrs	24:24			
		Ldg	7			
280-55-203	Stabilizers - Rudder Hinge - Drainage Holes Corrosion Protection On Middle Fitting (MODG25-01175)				RE (-)	Recommended
 55 A/F		Mos	10-Feb-2023			
Eff: 26-Jan-2017 Not Applicable	PER AIRCRAFT SERIAL NUMBER	Hrs	24:24			
		Ldg	7			
280-55-260	Stabilizers (ATA 55) - Horizontal Stabilizer - Inspection and Repair of the LH and RH Outer Front Spar Beam				RE (-)	Recommended
 55 A/F		Mos	27-May-2024			
Eff: 24-May-2024 Not Applicable	as per aircraft S/N	Hrs	842:13			
		Ldg	496			
▼ 56 - WINDOWS						
280-56-016	Windows - Cockpit Windshield - Modification Of Windshield De-Ice Cable Routing To Match New Terminal Board Position (MODG25-00164)				RE (-)	Recommended
 56 A/F		Mos	10-Feb-2023			
Eff: 13-Dec-2013 Not Applicable	PER AIRCRAFT SERIAL NUMBER	Hrs	24:24			
		Ldg	7			
280-56-016 PART A	Windows - Pilot - Cockpit Windshield - Modification Of Windshield De-Ice Cable Routing To Match New Terminal Board Position				RE (-)	
 56 A/F		Mos	10-Feb-2023			
Not Applicable	PER AIRCRAFT SERIAL NUMBER	Hrs	24:24			
		Ldg	7			
▼ 57 - WINGS						
2021-17-14	Wings - Crack at the Area of the Wing Rib 0 to the Front Spar				RE (-)	Mandatory
 57 A/F		Mos	09-Nov-2022			
Eff: 14-Oct-2021 Not Applicable	BY AIRCRAFT SERIAL NUMBER	Hrs	0			
		Ldg	0			
280-57-036	Wings - Wing Wiring Harness Installation Retrofit (MODG25-10706 , MODG25- 00469)				RE (-)	Mandatory
 57 A/F		Mos	10-Feb-2023			
Eff: 26-Jul-2013 Not Applicable	PER AIRCRAFT SERIAL NUMBER	Hrs	24:24			
Ref:AWL-1		Ldg	7			
280-57-040	Wings - Wing Flap Track C Modification And Scuff Plate Installation (MODG25- 20713)				RE (-)	Recommended
 57 A/F		Mos	10-Feb-2023			
Eff: 19-Jan-2015 Not Applicable	PER AIRCRAFT SERIAL NUMBER	Hrs	24:24			
		Ldg	7			
280-57-047	Wings - Wing Flap Track D Roller Fittings Retrofit (MODG25-10708 , MODG25- 07112)				RE (-)	Recommended
 57 A/F		Mos	14-Apr-2023			
Eff: 19-Jan-2015 Not Applicable	as per a/c S/N	Hrs	112:17			
		Ldg	61			
280-57-047 Rev 1	Wings - Wing Flap Track D Roller Fittings Retrofit (MODG25-10708 , MODG25- 07112)				RE (-)	Recommended
 57 A/F		Mos	10-Feb-2023			
Eff: 19-Jan-2015 Not Applicable	PER AIRCRAFT SERIAL NUMBER	Hrs	24:24			
		Ldg	7			

Task No		Description			CW	REQ	TOL	Categories	Time
SEQ	PN/SN	MOC Note						DUE	Remaining
280-57-059		Wings - Aileron - Aileron Position Sensor Bracket, Eccentric Bushing and Retainer Retrofit					RE (-)	Recommended	
 57 A/F Eff: 19-Apr-2024 Not Applicable	as per aircraft S/N		Mos	27-May-2024					
			Hrs	842:13					
			Ldg	496					
280-57-060		Wings - Wing Flap Track A , D Turn Down Hooks Retrofit (MODG25-10705)					RE (-)	Recommended	
 57 A/F Eff: 19-Jan-2015 Not Applicable	PER AIRCRAFT SERIAL NUMBER		Mos	10-Feb-2023					
			Hrs	24:24					
			Ldg	7					
280-57-071		Wings - Electrical Harnesses Routing Improvements Of Left And Right Wing Leading Edge Inboard Area And Left And Right Trailing Edge Near Spoiler Number 3 (MODG25-20047, MODG25-00469 , MODG25-00487)					RE (-)	Mandatory	
 57 A/F Eff: 26-Jul-2023 Not Applicable Ref:AWL-2	PER AIRCRAFT SERIAL NUMBER		Mos	10-Feb-2023					
			Hrs	24:24					
			Ldg	7					
280-57-078		Wings - Aileron - Divide Aileron Upper Cove Panel And Lower Seal Panel Into 3 Pieces					RE (-)	Recommended	
 57 A/F			Mos						
			Hrs						
			Ldg						
280-57-099		Adding a Doubler to the Forward Spar and Rib 0 Attachment					RE (-)	Mandatory	
 57 A/F Eff: 26-Feb-2019 Not Applicable	PER AIRCRAFT SERIAL NUMBER		Mos	10-Feb-2023					
			Hrs	24:24					
			Ldg	7					
280-57-100		Wings - Flaps - Retrofit Of Track D With Cres Track - And Rework Of Flap Tracks A, B, C And D (MODG25-20716, MODG25-070137 , MODG25-07141)					RE (-)	Recommended	
 57 A/F Eff: 19-Jan-2015 Not Applicable	PER AIRCRAFT SERIAL NUMBER		Mos	10-Feb-2023					
			Hrs	24:24					
			Ldg	7					
280-57-101		Wings - Flaps - Track B Outboard , Track C Inboard Roller Attach Fasteners Retrofit (MODG25-20717)					RE (-)	Recommended	
 57 A/F Eff: 31-Jan-2014 Not Applicable	PER AIRCRAFT SERIAL NUMBER		Mos	10-Feb-2023					
			Hrs	24:24					
			Ldg	7					
280-57-102		Wings - Fuel Drain Valves - Addition Of Sealant (Overcoating) To Drain Valve Fasteners (MODG25-07096)					RE (-)	Mandatory	
 57 A/F Eff: 04-Oct-2013 Not Applicable	PER AIRCRAFT SERIAL NUMBER		Mos	10-Feb-2023					
			Hrs	24:24					
			Ldg	7					
280-57-110		Wings- Wing Flap Track A , D Trailing Edge Roller Fitting Retrofit (MODG25-07081)					RE (-)	Recommended	
 57 A/F Eff: 04-Oct-2013 Not Applicable	PER AIRCRAFT SERIAL NUMBER		Mos	10-Feb-2023					
			Hrs	24:24					
			Ldg	7					
280-57-125		Wings - Install a New Bracket and Move the Existing P-Clamp to Prevent Wire Harness Proximity to Main Landing Gear (MLG)					RE (-)	Recommended	
 57 A/F Eff: 29-Oct-2020 Not Applicable	PER AIRCRAFT SERIAL NUMBER		Mos	10-Feb-2023					
			Hrs	24:24					
			Ldg	7					
280-57-127		Wings - Wing Anti-Ice Tubes - Adding Chamfer to Wing Anti-Ice Piccolo Tube Capture Brackets on the RH Wing Per MOD G25-07135					RE (-)	Recommended	
 57 A/F Eff: 19-Dec-2016 Not Applicable	PER AIRCRAFT SERIAL NUMBER		Mos	10-Feb-2023					
			Hrs	24:24					
			Ldg	7					

Task No		Description				Categories	Time	
SEQ	PN/SN	MOC Note		CW	REQ	TOL	DUE	Remaining
280-57-130		Wings - Re-Route Brake Line Hydraulic Tube To Provide Adequate Clearance To The Tire Burst Shield Bracket (MODG25-07062)				RE (-)	Recommended	
	57 A/F			Mos	10-Feb-2023			
	Eff: 08-Jul-2016 Not Applicable	PER AIRCRAFT SERIAL NUMBER		Hrs	24:24			
				Ldg	7			
280-57-133		Wings - Wing Flap Track A Inboard And Outboard Roller Fittings Retrofit (MODG25- 10710)				RE (-)	Recommended	
	57 A/F			Mos	14-Apr-2023			
	Eff: 19-Jan-2015 Not Applicable	as per a/c S/N		Hrs	112:17			
				Ldg	61			
280-57-133 Rev 1		Wings - Wing Flap Track A Inboard And Outboard Roller Fittings Retrofit (MODG25- 10710)				RE (-)	Recommended	
	57 A/F			Mos	10-Feb-2023			
	Eff: 19-Jan-2015 Not Applicable	PER AIRCRAFT SERIAL NUMBER		Hrs	24:24			
				Ldg	7			
280-57-142		Wings - Relocation Of Saddle Clamp Attaching Fuel Tube To Rib 1 Stiffener In The Left Hand Wing Fuel Tank (MODG25-07147)				RE (-)	Recommended	
	57 A/F			Mos	10-Feb-2023			
	Eff: 15-Dec-2016 Not Applicable	PER AIRCRAFT SERIAL NUMBER		Hrs	24:24			
				Ldg	7			
280-57-145		Wings - Shorten Wing Anti-Ice (WAI) Grounding Screw Length in Gap Band 1 and 3 (MODG25-07151)				RE (-)	Recommended	
	57 A/F			Mos	10-Feb-2023			
	Eff: 19-Dec-2016 Not Applicable	PER AIRCRAFT SERIAL NUMBER		Hrs	24:24			
				Ldg	7			
280-57-150		Wings - Wing Leading Edge Access Panels - Fastener Retrofit (MODG25-07153)				RE (-)	Recommended	
	57 A/F			Mos	10-Feb-2023			
	Eff: 30-Oct-2015 Not Applicable	PER AIRCRAFT SERIAL NUMBER		Hrs	24:24			
				Ldg	7			
280-57-151		Reduce Spoiler Hinge Bolt Torque				RE (-)	Recommended	
	57 A/F			Mos	10-Feb-2023			
	Eff: 04-Dec-2017 Not Applicable	PER AIRCRAFT SERIAL NUMBER		Hrs	24:24			
				Ldg	7			
280-57-152		Wings - Modifying Bracket On Stringer To Prevent Interference Between Bracket And Stringer (MODG25-07162)				RE (-)	Recommended	
	57 A/F			Mos	10-Feb-2023			
	Eff: 17-Nov-2016 Not Applicable	PER AIRCRAFT SERIAL NUMBER		Hrs	24:24			
				Ldg	7			
280-57-155		Wings - Retrofitting Electrical Bracket On The Jettison Rib To Eliminate Fastener Interference (MOD G25-07165)				RE (-)	Recommended	
	57 A/F			Mos	10-Feb-2023			
	Eff: 26-Jan-2017 Not Applicable	PER AIRCRAFT SERIAL NUMBER		Hrs	24:24			
				Ldg	7			
280-57-156		Wings - Wing Fuel Tank - Addition Of Drain Hole In Dry Bay (MODG25-20721)				RE (-)	Recommended	
	57 A/F			Mos	10-Feb-2023			
	Eff: 30-Oct-2015 Not Applicable	PER AIRCRAFT SERIAL NUMBER		Hrs	24:24			
				Ldg	7			
280-57-159		Wings - Re-Torque Winglet Cap Attach Fasteners				RE (-)	Recommended	
	57 A/F			Mos	10-Feb-2023			
	Eff: 16-Nov-2017 Not Applicable	PER AIRCRAFT SERIAL NUMBER		Hrs	24:24			
				Ldg	7			

Task No	Description	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note				DUE	Remaining
280-57-161	Wings - Ensure Clearance Between RHS FQMS Wire Harness P-Clamp Bolt And Stringer (MODG25-07179)		RE (-)		Recommended	
 57 A/F		Mos	10-Feb-2023			
Eff: 16-Nov-2016 Not Applicable	PER AIRCRAFT SERIAL NUMBER	Hrs	24:24			
		Ldg	7			
280-57-166	Wings - Main Landing Gear (MLG) Sponson - Retorquing of Aft Lug Bearing (MODG25-00851)		RE (-)		Required	
 57 A/F		Mos	10-Feb-2023			
Eff: 20-Nov-2015 Not Applicable	PER AIRCRAFT SERIAL NUMBER	Hrs	24:24			
		Ldg	7			
280-57-177	Wings - Addition of Bracket To Right Side Wing Inboard Leading Edge Wire Harness Assembly (MODG25-07189)		RE (-)		Recommended	
 57 A/F		Mos	10-Feb-2023			
Eff: 01-Jun-2017 Not Applicable	PER AIRCRAFT SERIAL NUMBER	Hrs	24:24			
		Ldg	7			
280-57-181	Wings - Lower Cove Panel Seals - Modification To Prevent Deflection (MODG25- 07192 , MODG25-07231)		RE (-)		Recommended	
 57 A/F		Mos	10-Feb-2023			
Eff: 01-Jun-2017 Not Applicable	PER AIRCRAFT SERIAL NUMBER	Hrs	24:24			
		Ldg	7			
280-57-182	Wings - Enlarging Holes on Feed Tank Bracket		RE (-)		Recommended	
 57 A/F		Mos	10-Aug-2023			
Eff: 23-Jun-2023 Not Applicable		Hrs				
(UPDATE NOTE: N/A by SN of the aircraft)		Ldg				
280-57-185	Wings - Wing Access Panels Installation - Modification for Improved Electrical Bonding		RE (-)		Recommended	
 57 A/F		Mos	10-Feb-2023			
Eff: 29-Oct-2020 Not Applicable	PER AIRCRAFT SERIAL NUMBER	Hrs	24:24			
		Ldg	7			
280-57-187	Wings - Rework The Mating Surface Under Flapper Valves On Wing Rib 6 (MODG25- 07203)		RE (-)		Recommended	
 57 A/F		Mos	10-Feb-2023			
Eff: 15-Dec-2016 Not Applicable	PER AIRCRAFT SERIAL NUMBER	Hrs	24:24			
		Ldg	7			
280-57-188	Wings - Adding A Clamp On The Center Tank FQMS Harness To Ensure Adequate Clearance With Fuel Tube (MODG25-07204)		RE (-)		Recommended	
 57 A/F		Mos	10-Feb-2023			
Eff: 15-Dec-2016 Not Applicable	PER AIRCRAFT SERIAL NUMBER	Hrs	24:24			
		Ldg	7			
280-57-193	Replace Shrink Splices on Landing Light Wire Harness		RE (-)		Recommended	
 57 A/F		Mos	10-Feb-2023			
Eff: 01-Feb-2018 Not Applicable	PER AIRCRAFT SERIAL NUMBER	Hrs	24:24			
		Ldg	7			
280-57-199	Wings - Torsion Box Fuel Tube Bracketry Grounding Improvement (MODG25-07215)		RE (-)		Recommended	
 57 A/F		Mos				
		Hrs				
		Ldg				
280-57-221	Installing Missing Flap Fasteners on G280 Flap		RE (-)		Recommended	
 57 A/F		Mos	10-Feb-2023			
Eff: 14-Feb-2018 Not Applicable	PER AIRCRAFT SERIAL NUMBER	Hrs	24:24			
		Ldg	7			

Task No		Description				Categories	Time
SEQ	PN/SN	MOC Note	CW	REQ	TOL	DUE	Remaining
280-57-222		Wings - Inspection and / or Repair of Flap Spar Cracks On Track D (MODG25-01308)				RE (-)	Recommended
	57 A/F		Mos	14-Apr-2023			
	Eff: 13-May-2016 Not Applicable	as per a/c S/N	Hrs	112:17			
			Ldg	61			
280-57-222 Rev 1		Wings - Inspection and / or Repair of Flap Spar Cracks On Track D (MODG25-01308)				RE (-)	Recommended
	57 A/F		Mos	10-Feb-2023			
	Eff: 13-May-2016 Not Applicable	PER AIRCRAFT SERIAL NUMBER	Hrs	24:24			
			Ldg	7			
280-57-227		Wings - Correct Sealant and Electrical Bonding for Scavenger Ejector Pump Installs				RE (-)	Recommended
	57 A/F		Mos	10-Aug-2023			
	Eff: 28-Jul-2023 Not Applicable		Hrs				
	(UPDATE NOTE: N/A by SN of the aircraft)		Ldg				
280-57-231		Wings - Retrofit Rear Spar Brackets for Missing EBL Requirements and Apply Fillet Seal				RE (-)	Recommended
	57 A/F		Mos	10-Jul-2025			
	Eff: 28-Jul-2023 Complied With		Hrs				
	(UPDATE NOTE: NA by SN of the aircraft)		Ldg				
280-57-231 Rev 1		Wings - Retrofit Rear Spar Brackets for Missing EBL Requirements and Apply Fillet Seal				RE (-)	Recommended
	57 A/F		Mos	10-Jul-2025			
	Eff: 12-Mar-2025 Not Applicable		Hrs				
	(UPDATE NOTE: NA by SN of the aircraft)		Ldg				
280-57-238		Ground Spoiler Actuator Attachment Hardware Change				RE (-)	Recommended
	57 A/F		Mos	10-Feb-2023			
	Eff: 25-Feb-2019 Not Applicable	PER AIRCRAFT SERIAL NUMBER	Hrs	24:24			
			Ldg	7			
280-57-242		Wings - Inspection and Retrofit of the Trailing Edge Wire Harness on Inboard Aileron				RE (-)	Recommended
	57 A/F		Mos	10-Feb-2023			
	Eff: 16-Jan-2023 Not Applicable	PER AIRCRAFT SERIAL NUMBER	Hrs	24:24			
			Ldg	7			
280-57-244		Wings (ATA 57) Inspection and Repair of Flap Rib Fastener Holes				RE (-)	Recommended
	57 A/F		Mos	26-Feb-2025			
	Eff: 27-Nov-2024 Not Applicable		Hrs				
	(UPDATE NOTE: NA by SN of the aircraft)		Ldg				
280-57-247		Wings - Increase Grip Length of Blind Rivets on Aft Spar Systems Tabs				RE (-)	Recommended
	57 A/F		Mos	26-Feb-2025			
	Eff: 11-Oct-2024 Not Applicable		Hrs				
	(UPDATE NOTE: not AF by SN of the aircraft)		Ldg				
280-57-274		Wings - Inspection for Corrosion Between Aileron Gear Tab Adjuster Nut and Gear Tab Control Rod and Replacement of Non-Conforming Nuts				RE (-)	Recommended
	57 A/F		Mos				
	Eff: 28-May-2024		Hrs				
			Ldg				
280-57-275		Wings - Apply Protective Coating to Areas Under Flapper Valves on Rib 2				RE (-)	Recommended
	57 A/F		Mos	10-Jul-2025			
	Eff: 05-May-2023 Not Applicable		Hrs				
	(UPDATE NOTE: N/A by SN of the aircraft)		Ldg				
280-57-275 Rev 1		Wings - Apply Protective Coating to Areas Under Flapper Valves on Rib 2				RE (-)	Recommended
	57 A/F		Mos	10-Jul-2025			
	Eff: 03-Jan-2025 Not Applicable		Hrs				
	(UPDATE NOTE: N/A by SN of the aircraft)		Ldg				

Task No		Description	CW	REQ	TOL	Categories	Time
SEQ	PN/SN	MOC Note				DUE	Remaining
280-57-275 Rev 2		Wings - Apply Protective Coating to Areas Under Flapper Valves on Rib 2				RE (-)	Recommended
	57 A/F						
	Eff: 18-Jul-2025 Not Applicable	by aircraft SN.					
280-57-276		Wings - FQMS Wire Harness Bend Radius Verification and Retrofit at Rib 2 and Rib 10				RE (-)	Recommended
	57 A/F						
	Eff: 09-Apr-2020 Not Applicable	as per aircraft S/N					
280-57-276 Rev 1		Wings - FQMS Wire Harness Bend Radius Verification and Retrofit at Rib 2 and Rib 10				RE (-)	Recommended
	57 A/F						
	Eff: 12-May-2020 Not Applicable	PER AIRCRAFT SERIAL NUMBER					
280-57-277		Wings - Cold Working of Holes in Lower Skin Stringer 3 Common to Outboard Feed Tank Lower Bracket				RE (-)	Recommended
	57 A/F						
	Eff: 23-Jun-2023 Not Applicable						
	(UPDATE NOTE: NA by SN of the Aircraft)						
280-57-277 Rev 1		Wings - Cold Working of Holes in Lower Skin Stringer 3 Common to Outboard Feed Tank Lower Bracket				RE (-)	Recommended
	57 A/F						
	Eff: 10-Oct-2024 Not Applicable						
	(UPDATE NOTE: NA by SN of the Aircraft)						
280-57-280		Wings - Trimming Rib 2 Cutout for Stringer 5 on Aft Lower Skin to Improve Fatigue Resistance				RE (-)	Recommended
	57 A/F						
	Eff: 19-Jul-2024 Not Applicable						
	(UPDATE NOTE: NA by SN of the aircraft)						
280-57-284		Wings - Applying Coating on Leading Edge Ground Studs				RE (-)	Recommended
	57 A/F						
	Eff: 05-Apr-2023 Not Applicable						
	(UPDATE NOTE: NOT APPLICABLE to aircraft serial number)						
280-57-288		Wings (ATA 57) - Aileron Lower Seal Panels Sealant Inspection and Repair				RE (-)	Recommended
	57 A/F						
	Eff: 13-Jan-2020 Not Applicable	PER AIRCRAFT SERIAL NUMBER					
280-57-289		Wings - Re-Torquing the Ground Stud Fasteners Located in the Wing Tank OB of Rib 15 on the LHS and RHS FWD Spars				RE (-)	Recommended
	57 A/F						
	Eff: 29-Oct-2020 Not Applicable	PER AIRCRAFT SERIAL NUMBER					
280-57-296		Wings - Access Panels - Add Conductive Finish to Lower Wing Skin and Access Panels and Retainers				RE (-)	Recommended
	57 A/F						
	Eff: 23-Jun-2023 Not Applicable						
	(UPDATE NOTE: not AF by SN of the aircraft)						
280-57-296 Rev 1		Wings - Access Panels - Add Conductive Finish to Lower Wing Skin and Access Panels and Retainers				RE (-)	Recommended
	57 A/F						
	Eff: 10-Oct-2024 Not Applicable						
	(UPDATE NOTE: not AF by SN of the aircraft)						
280-57-299		Wings - Flapper Valve - Fatigue Crack Preventing on Rib 2				RE (-)	Recommended
	57 A/F						
	Eff: 23-Jun-2023 Not Applicable						
	(UPDATE NOTE: N/A by SN of the aircraft)						

Task No		Description				CW	REQ	TOL	Categories	Time
SEQ	PN/SN	MOC Note							DUE	Remaining
280-57-313		Wings (ATA 57) - Fuel Access Panels - Grommet Replacement on LH & RH Wing Rib 6 Area							RE (-)	Service Bulletin
	57 A/F					Mos	17-Apr-2023			
	Eff: 24-Feb-2023 Not Applicable	as per a/c S/N				Hrs	122:11			
						Ldg	69			
280-57-314		Wings - Trailing Edge and Trailing Edge Devices - Flap Track A and D Trailing Edge Roller Fitting Assembly Fasteners Sealant and Torque							RE (-)	Recommended
	57 A/F					Mos	29-Nov-2023			
	Eff: 09-Oct-2023 Not Applicable					Hrs				
	(UPDATE NOTE: N/A by SN of the aircraft)					Ldg				
280-57-330		Wings - Addition of Drain Holes in Lower Ailerons Seal Panels							RE (-)	Recommended
	57 A/F					Mos	10-Sep-2024			
	Eff: 09-Aug-2024 Complied With					Hrs				
	(UPDATE NOTE: AF)					Ldg				
IL ISR-I-57-2020-06-01		Instructions To Install A Doubler At The Attachment Location Of The Wing Rib 0 And The Front Spar (Mandatory)							RE (-)	
	57 A/F					Mos	09-Nov-2022			
	Not Applicable	BY AIRCRAFT SERIAL NUMBER				Hrs				
						Ldg				
▼ 71 - POWER PLANT										
D201406000102		Setup Instructions for Electronic Engine Interface (EEI) Kit, PN 5837831-4, on all AS907 (HTF) Turbofan Engines							RE (-)	Service Information Letter
	71 ENG1					Mos				
	Eff: 08-Jul-2014					Hrs				
						Enc				
D201406000102		Setup Instructions for Electronic Engine Interface (EEI) Kit, PN 5837831-4, on all AS907 (HTF) Turbofan Engines							RE (-)	Service Information Letter
	71 ENG2					Mos				
	Eff: 08-Jul-2014					Hrs				
						Enc				
D201406000102 Rev 1		Setup Instructions for Electronic Engine Interface (EEI) Kit, PN 5837831-4, on all AS907 (HTF) Turbofan Engines							T (A/R)	Service Information Letter
	71 ENG1					Mos				
	Eff: 11-Jan-2021					Hrs				
						Enc				
D201406000102 Rev 1		Setup Instructions for Electronic Engine Interface (EEI) Kit, PN 5837831-4, on all AS907 (HTF) Turbofan Engines							T (A/R)	Service Information Letter
	71 ENG2					Mos				
	Eff: 11-Jan-2021					Hrs				
						Enc				
D201807000004		AS907 - Ice Formation in the Air Turbine Starter Start Valve Resulting in a No-Start Condition							T (A/R)	Service Information Letter
	71 ENG1					Mos				
	Eff: 10-Aug-2018					Hrs				
						Enc				
D201807000004		AS907 - Ice Formation in the Air Turbine Starter Start Valve Resulting in a No-Start Condition							T (A/R)	Service Information Letter
	71 ENG2					Mos				
	Eff: 10-Aug-2018					Hrs				
						Enc				
▼ 72 - ENGINE										
3727214-SB-001		DISKBAL BLADE MAPPING SOFTWARE PN 3727214							T (A/R)	
	72 ENG1					Mos				
	Eff: 28-Jan-2016					Hrs				
						Enc				
3727214-SB-001		DISKBAL BLADE MAPPING SOFTWARE PN 3727214							T (A/R)	
	72 ENG2					Mos				
	Eff: 28-Jan-2016					Hrs				
						Enc				

Task No SEQ PN/SN	Description MOC Note	CW	REQ	TOL	Categories DUE	Time Remaining
72-9045 72 ENG1 Eff: 18-Apr-2011	ENGINE - COMPRESSOR SECTION - Install Improved Annular Ball (Tower Shaft) Bearing, PN 3033024-2		T (A/R)			
		Mos				
		Hrs				
		Enc				
72-9045 72 ENG2 Eff: 18-Apr-2011	ENGINE - COMPRESSOR SECTION - Install Improved Annular Ball (Tower Shaft) Bearing, PN 3033024-2		T (A/R)			
		Mos				
		Hrs				
		Enc				
72-9045 Rev 1 72 ENG1 Eff: 19-Jul-2012	ENGINE - COMPRESSOR SECTION - Install Improved Annular Ball (Tower Shaft) Bearing, PN 3033024-2		T (A/R)			
		Mos				
		Hrs				
		Enc				
72-9045 Rev 1 72 ENG2 Eff: 19-Jul-2012	ENGINE - COMPRESSOR SECTION - Install Improved Annular Ball (Tower Shaft) Bearing, PN 3033024-2		T (A/R)			
		Mos				
		Hrs				
		Enc				
72-9047 72 ENG1 Eff: 13-Jun-2012 Complied With (UPDATE NOTE: AT MANUFACTURE)	ENGINE - BY-PASS SECTION - INSTALL NEW VIBRATION DAMPENERS PN 70040770-1		RE (-)			
		Mos	10-Feb-2023			
		Hrs				
		Enc				
72-9047 72 ENG2 Eff: 13-Jun-2012	ENGINE - BY-PASS SECTION - INSTALL NEW VIBRATION DAMPENERS PN 70040770-1		T (A/R)			
		Mos				
		Hrs				
		Enc				
72-9050 72 ENG1 Eff: 06-Sep-2012	ENGINE - LOW PRESSURE TURBINE - INSTALL WASHERS PN NAS1149E0432R IN PLACE OF WASHERSPN NAS1149C0432R		T (A/R)			
		Mos				
		Hrs				
		Enc				
72-9050 72 ENG2 Eff: 06-Sep-2012	ENGINE - LOW PRESSURE TURBINE - INSTALL WASHERS PN NAS1149E0432R IN PLACE OF WASHERSPN NAS1149C0432R		T (A/R)			
		Mos				
		Hrs				
		Enc				
AS907-3 72 ENG1 Eff: 23-Oct-2003	AS907 Jet-Care Trend Monitoring System		RE (-)		Service Information Letter	
		Mos				
		Hrs				
		Enc				
AS907-3 72 ENG2 Eff: 23-Oct-2003	AS907 Jet-Care Trend Monitoring System		RE (-)		Service Information Letter	
		Mos				
		Hrs				
		Enc				
AS907-3 Rev 1 72 ENG1 Eff: 05-Mar-2014	AS907 Jet-Care Trend Monitoring System		RE (-)		Service Information Letter	
		Mos				
		Hrs				
		Enc				
AS907-3 Rev 1 72 ENG2 Eff: 05-Mar-2014	AS907 Jet-Care Trend Monitoring System		RE (-)		Service Information Letter	
		Mos				
		Hrs				
		Enc				
AS907-3 Rev 2 72 ENG1 Eff: 08-Nov-2017	AS907 Jet-Care Trend Monitoring System		T (-)		Service Information Letter	
		Mos				
		Hrs				
		Enc				

Task No SEQ PN/SN	Description MOC Note	CW	REQ	TOL	Categories DUE	Time Remaining
AS907-3 Rev 2 72 ENG2 Eff: 08-Nov-2017	AS907 Jet-Care Trend Monitoring System		T (-)		Service Information Letter	
		Mos				
		Hrs				
		Enc				
AS907-3 Rev 3 72 ENG1 Eff: 02-Apr-2019	AS907 Trend Monitoring System		T (-)		Service Information Letter	
		Mos				
		Hrs				
		Enc				
AS907-3 Rev 3 72 ENG2 Eff: 02-Apr-2019	AS907 Trend Monitoring System		T (-)		Service Information Letter	
		Mos				
		Hrs				
		Enc				
AS907-3 Rev 4 72 ENG1 Eff: 06-Oct-2021	AS907 CAMP Trend Monitoring System		T (-)		Service Information Letter	
		Mos				
		Hrs				
		Enc				
AS907-3 Rev 4 72 ENG2 Eff: 06-Oct-2021	AS907 CAMP Trend Monitoring System		T (-)		Service Information Letter	
		Mos				
		Hrs				
		Enc				
AS907-3 Rev 5 72 ENG1 Eff: 14-Feb-2025	AS907 CAMP Trend Monitoring System Discussion		T (A/R)		Service Information Letter	
		Mos				
		Hrs				
		Enc				
AS907-3 Rev 5 72 ENG2 Eff: 14-Feb-2025	AS907 CAMP Trend Monitoring System Discussion		T (A/R)		Service Information Letter	
		Mos				
		Hrs				
		Enc				
AS907-72-9001 Rev 1 72 ENG1 Eff: 04-May-2017 Not Applicable	Engine - Compressor Section - Install Packings on the Compressor Variable Geometry (CVG) Unison Ring Pins to Prevent Variable Guide Vane Arm Bearing Loss on AS907 Model Engines as per engine S/N		RE (-)		Cat. 2 - Recommended	
		Mos	17-Apr-2023			
		Hrs	97:47			
		Enc	64			
AS907-72-9001 Rev 1 72 ENG2 Eff: 04-May-2017 Not Applicable	Engine - Compressor Section - Install Packings on the Compressor Variable Geometry (CVG) Unison Ring Pins to Prevent Variable Guide Vane Arm Bearing Loss on AS907 Model Engines as per engine S/N		RE (-)		Cat. 2 - Recommended	
		Mos	17-Apr-2023			
		Hrs	117:47			
		Enc	76			
AS907-72-9001 Rev 2 72 ENG1 Eff: 14-Aug-2018 Not Applicable	Engine - Compressor Section - Install Packings on the Compressor Variable Geometry (CVG) Unison Ring Pins to Prevent Variable Guide Vane Arm Bearing Loss on AS907 Model Engines as per engine S/N		RE (-)		Cat. 2 - Recommended	
		Mos	17-Apr-2023			
		Hrs	97:47			
		Enc	64			
AS907-72-9001 Rev 2 72 ENG2 Eff: 14-Aug-2018 Not Applicable	Engine - Compressor Section - Install Packings on the Compressor Variable Geometry (CVG) Unison Ring Pins to Prevent Variable Guide Vane Arm Bearing Loss on AS907 Model Engines as per engine S/N		RE (-)		Cat. 2 - Recommended	
		Mos	17-Apr-2023			
		Hrs	117:47			
		Enc	76			

Task No		Description				Categories	Time	
SEQ	PN/SN	MOC Note		CW	REQ	TOL	DUE	Remaining
AS907-72-9001 Rev 3		Engine - Compressor Section - Install Packings on the Compressor Variable Geometry (CVG) Unison Ring Pins to Prevent Variable Guide Vane Arm Bearing Loss on AS907 Model Engines			RE (-)		Cat. 2 - Recommended	
	72 ENG1 Eff: 28-Sep-2020 Not Applicable	as per engine S/N		Mos	17-Apr-2023			
				Hrs	97:47			
				Enc	64			
AS907-72-9001 Rev 3		Engine - Compressor Section - Install Packings on the Compressor Variable Geometry (CVG) Unison Ring Pins to Prevent Variable Guide Vane Arm Bearing Loss on AS907 Model Engines			RE (-)		Cat. 2 - Recommended	
	72 ENG2 Eff: 28-Sep-2020 Not Applicable	as per engine S/N		Mos	17-Apr-2023			
				Hrs	117:47			
				Enc	76			
AS907-72-9001 Rev 4		Engine - Compressor Section - Install Packings on the Compressor Variable Geometry (CVG) Unison Ring Pins to Prevent Variable Guide Vane Arm Bearing Loss on AS907 Model Engines			RE (-)		Cat. 2 - Recommended	
	72 ENG1 Eff: 21-Dec-2020 Not Applicable	as per engine S/N		Mos	17-Apr-2023			
				Hrs	97:47			
				Enc	64			
AS907-72-9001 Rev 4		Engine - Compressor Section - Install Packings on the Compressor Variable Geometry (CVG) Unison Ring Pins to Prevent Variable Guide Vane Arm Bearing Loss on AS907 Model Engines			RE (-)		Cat. 2 - Recommended	
	72 ENG2 Eff: 21-Dec-2020 Not Applicable	as per engine S/N		Mos	17-Apr-2023			
				Hrs	117:47			
				Enc	76			
AS907-72-9001 Rev 5		Engine - Compressor Section - Install Packings on the Compressor Variable Geometry (CVG) Unison Ring Pins to Prevent Variable Guide Vane Arm Bearing Loss on AS907 Model Engines			RE (-)		Cat. 2 - Recommended	
	72 ENG1 Eff: 05-May-2022 Not Applicable	as per engine S/N		Mos	17-Apr-2023			
				Hrs	97:47			
				Enc	64			
AS907-72-9001 Rev 5		Engine - Compressor Section - Install Packings on the Compressor Variable Geometry (CVG) Unison Ring Pins to Prevent Variable Guide Vane Arm Bearing Loss on AS907 Model Engines			RE (-)		Cat. 2 - Recommended	
	72 ENG2 Eff: 05-May-2022 Not Applicable	as per engine S/N		Mos	17-Apr-2023			
				Hrs	117:47			
				Enc	76			
AS907-72-9001 Rev 6		Engine - Compressor Section - Install Packings on the Compressor Variable Geometry (CVG) Unison Ring Pins to Prevent Variable Guide Vane Arm Bearing Loss on AS907 Model Engines			RE (-)		Cat. 2 - Recommended	
	72 ENG1 Eff: 07-Mar-2023 Not Applicable	as per engine S/N		Mos	17-Apr-2023			
				Hrs	97:47			
				Enc	64			
AS907-72-9001 Rev 6		Engine - Compressor Section - Install Packings on the Compressor Variable Geometry (CVG) Unison Ring Pins to Prevent Variable Guide Vane Arm Bearing Loss on AS907 Model Engines			RE (-)		Cat. 2 - Recommended	
	72 ENG2 Eff: 07-Mar-2023 Not Applicable	as per engine S/N		Mos	17-Apr-2023			
				Hrs	117:47			
				Enc	76			
AS907-72-9005		SB AS907-72-9005 - Installation of Engine Water Wash System			RE (-)			
	72 ENG1 Eff: 25-Mar-2005			Mos				
				Hrs				
				Enc				
AS907-72-9005		SB AS907-72-9005 - Installation of Engine Water Wash System			RE (-)			
	72 ENG2 Eff: 25-Mar-2005			Mos				
				Hrs				
				Enc				

Task No SEQ PN/SN	Description MOC Note	CW	REQ	TOL	Categories DUE	Time Remaining
AS907-72-9005 Rev 1 72 ENG1 Eff: 07-Aug-2013	ENGINE - GENERAL - Installation of Engine Water Wash System on AS907 Engines Models		T (A/R)			
		Mos				
		Hrs				
		Enc				
AS907-72-9005 Rev 1 72 ENG2 Eff: 07-Aug-2013	ENGINE - GENERAL - Installation of Engine Water Wash System on AS907 Engines Models		T (A/R)			
		Mos				
		Hrs				
		Enc				
AS907-72-9005 Rev 2 72 ENG1 Eff: 16-Nov-2015	ENGINE - GENERAL - Installation of Engine Water Wash System on AS907 Engines Models		T (A/R)			
		Mos				
		Hrs				
		Enc				
AS907-72-9005 Rev 2 72 ENG2 Eff: 16-Nov-2015	ENGINE - GENERAL - Installation of Engine Water Wash System on AS907 Engines Models		T (A/R)			
		Mos				
		Hrs				
		Enc				
AS907-72-9005 Rev 3 72 ENG1 Eff: 29-Aug-2016 Not Applicable	ENGINE - GENERAL - Installation of Engine Water Wash System on AS907 Engines Models PER ENGINE PART NUMBER		RE (-)	10-Feb-2023		
		Mos				
		Hrs				
		Enc				
AS907-72-9005 Rev 3 72 ENG2 Eff: 29-Aug-2016 Not Applicable	ENGINE - GENERAL - Installation of Engine Water Wash System on AS907 Engines Models PER ENGINE PART NUMBER		RE (-)	10-Feb-2023		
		Mos				
		Hrs				
		Enc				
AS907-72-9005 Rev 4 72 ENG1 Eff: 14-Jul-2020 Not Applicable	Engine - General - Installation of Engine Water Wash System, on AS907 Engines Models PER ENGINE PART NUMBER		T (-)	10-Feb-2023	Category 3	
		Mos				
		Hrs				
		Enc				
AS907-72-9005 Rev 4 72 ENG2 Eff: 14-Jul-2020 Not Applicable	Engine - General - Installation of Engine Water Wash System, on AS907 Engines Models PER ENGINE PART NUMBER		T (-)	10-Feb-2023	Category 3	
		Mos				
		Hrs				
		Enc				
AS907-72-9005 Rev 5 72 ENG1 Eff: 23-Jan-2025	Engine - General - Installation of Engine Water Wash System, on AS907 Engines Models		T (A/R)		Category 3	
		Mos				
		Hrs				
		Enc				
AS907-72-9005 Rev 5 72 ENG2 Eff: 23-Jan-2025	Engine - General - Installation of Engine Water Wash System, on AS907 Engines Models		T (A/R)		Category 3	
		Mos				
		Hrs				
		Enc				
AS907-72-9045 Rev 1 72 ENG1 Not Applicable	Compressor Section - Install Improved Annular Ball (Tower Shaft) Bearing, PN 3033024-2, -4 as per engine S/N		RE (-)	17-Apr-2023	Cat.2-Reliability	
		Mos				
		Hrs		97:47		
		Enc		64		
AS907-72-9045 Rev 1 72 ENG2 Not Applicable	Compressor Section - Install Improved Annular Ball (Tower Shaft) Bearing, PN 3033024-2, -4 as per engine S/N		RE (-)	17-Apr-2023	Cat.2-Reliability	
		Mos				
		Hrs		117:47		
		Enc		76		

Task No		Description			Categories		Time		
SEQ	PN/SN	MOC	Note		CW	REQ	TOL	DUE	Remaining
AS907-72-9045 Rev 2		Engine - Compressor Section - Install Improved Annular Ball (Tower Shaft) Bearing, PN 3033024-2, -4 or -6				RE (-)		Cat.2-Reliability	
	72 ENG1			Mos	17-Apr-2023				
	Eff: 06-Sep-2018 Not Applicable	as per engine S/N		Hrs	97:47				
				Enc	64				
AS907-72-9045 Rev 2		Engine - Compressor Section - Install Improved Annular Ball (Tower Shaft) Bearing, PN 3033024-2, -4 or -6				RE (-)		Cat.2-Reliability	
	72 ENG2			Mos	17-Apr-2023				
	Eff: 06-Sep-2018 Not Applicable	as per engine S/N		Hrs	117:47				
				Enc	76				
AS907-72-9045 Rev 3		Engine - Compressor Section - Install Improved Annular Ball (Tower Shaft) Bearing, PN 3033024-2, -4 or -6				RE (-)		Cat.2-Reliability	
	72 ENG1			Mos	26-Jan-2023				
	Eff: 18-Dec-2018 Complied With	AT MANUFACTURE		Hrs	0				
				Enc	0				
AS907-72-9045 Rev 3		Engine - Compressor Section - Install Improved Annular Ball (Tower Shaft) Bearing, PN 3033024-2, -4 or -6				RE (-)		Cat.2-Reliability	
	72 ENG2			Mos	20-Jan-2023				
	Eff: 18-Dec-2018 Complied With	AT MANUFACTURE		Hrs	0				
				Enc	0				
AS907-72-9046		Hp Turbine Section - Install New Hp Turbine Stage 2 Nozzle Segments Pn 3035141-3 -4 On As907 Engine Models				RE (-)		Cat.3-Product Improvement	
	72 ENG1			Mos	10-Feb-2023				
	Not Applicable	PER ENGINE PART NUMBER		Hrs					
				Enc					
AS907-72-9046		Hp Turbine Section - Install New Hp Turbine Stage 2 Nozzle Segments Pn 3035141-3 -4 On As907 Engine Models				RE (-)		Cat.3-Product Improvement	
	72 ENG2			Mos	10-Feb-2023				
	Not Applicable	PER ENGINE PART NUMBER		Hrs					
				Enc					
AS907-72-9046 Rev 1		HP Turbine Section - Install New HP Turbine Stage 2 Nozzle Segments PN 3035141-3, -4 on AS907 Engine Models				RE (-)		Cat.3-Product Improvement	
	72 ENG1			Mos	26-Jan-2023				
	Eff: 29-Mar-2018 Complied With	AT MANUFACTURE		Hrs	0				
				Enc	0				
AS907-72-9046 Rev 1		HP Turbine Section - Install New HP Turbine Stage 2 Nozzle Segments PN 3035141-3, -4 on AS907 Engine Models				RE (-)		Cat.3-Product Improvement	
	72 ENG2			Mos	20-Jan-2023				
	Eff: 29-Mar-2018 Complied With	AT MANUFACTURE		Hrs	0				
				Enc	0				
AS907-72-9047		Bypass Section - Install New Vibration Dampeners, Pn 70040770-1				RE (-)		Category 3	
	72 ENG1			Mos	10-Apr-2023				
	Complied With	AT MANUFACTURE		Hrs	84:18				
				Enc	54				
AS907-72-9047		Bypass Section - Install New Vibration Dampeners, Pn 70040770-1				RE (-)		Category 3	
	72 ENG2			Mos	10-Apr-2023				
	Complied With	AT MANUFACTURE		Hrs	104:18				
				Enc	66				
AS907-72-9050		Low Pressure Turbine - Install Washers, Pn Nas1149E0432R, In Place Of Washers, Pn Nas1149C0432R				RE (-)		Category 2	
	72 ENG1			Mos	26-Jan-2023				
	Complied With	AT MANUFACTURE		Hrs	0				
				Enc	0				
AS907-72-9050		Low Pressure Turbine - Install Washers, Pn Nas1149E0432R, In Place Of Washers, Pn Nas1149C0432R				RE (-)		Category 2	
	72 ENG2			Mos	20-Jan-2023				
	Complied With	AT MANUFACTURE		Hrs	0				
				Enc	0				

Task No SEQ PN/SN	Description MOC Note		CW	REQ	TOL	Categories DUE	Time Remaining
AS907-72-9051	ENGINE - HP TURBINE SECTION - INSTALL NEW STAGE 1 HIGH PRESSURE TURBINE (HPT1) ROTOR ASSEMBLY PN 70040856-1					RE (-)	
 72 ENG1			Mos	26-Jan-2023			
Eff: 14-Jan-2014 Complied With	AT MANUFACTURE		Hrs	0			
			Enc	0			
AS907-72-9051	ENGINE - HP TURBINE SECTION - INSTALL NEW STAGE 1 HIGH PRESSURE TURBINE (HPT1) ROTOR ASSEMBLY PN 70040856-1					RE (-)	
 72 ENG2			Mos	20-Jan-2023			
Eff: 14-Jan-2014 Complied With	AT MANUFACTURE		Hrs	0			
			Enc	0			
AS907-72-9052	ENGINE - HIGH PRESSURE TURBINE SECTION - Install New Double Stage 1 Nozzle Inner Seals PN70040688-1 and Stage 1 Nozzle Outer Seals PN 70040687-1 in the First Stage High Pressure TurbineNozzle Assembly on AS907-2-1G Engine Models					RE (-)	
 72 ENG1			Mos	10-Feb-2023			
Eff: 05-May-2015 Not Applicable	PER S/N. INCORPORATED IN PRODUCTION		Hrs				
			Enc	2			
AS907-72-9052	ENGINE - HIGH PRESSURE TURBINE SECTION - Install New Double Stage 1 Nozzle Inner Seals PN70040688-1 and Stage 1 Nozzle Outer Seals PN 70040687-1 in the First Stage High Pressure TurbineNozzle Assembly on AS907-2-1G Engine Models					RE (-)	
 72 ENG2			Mos	10-Feb-2023			
Eff: 05-May-2015 Not Applicable	PER S/N. INCORPORATED IN PRODUCTION		Hrs				
			Enc				
AS907-72-9053	ENGINE - BYPASS SECTION - Install New Fan Stator Vanes PN 70040191-1 or New/Reworked Fan Stator Vane Assembly for AS907-1-1A and AS907-2-1G Model Engines					RE (-)	
 72 ENG1			Mos	10-Feb-2023			
Eff: 20-Nov-2015 Not Applicable	PER S/N, incorporated in Production		Hrs				
			Enc				
AS907-72-9053	ENGINE - BYPASS SECTION - Install New Fan Stator Vanes PN 70040191-1 or New/Reworked Fan Stator Vane Assembly for AS907-1-1A and AS907-2-1G Model Engines					RE (-)	
 72 ENG2			Mos	10-Feb-2023			
Eff: 20-Nov-2015 Not Applicable	PER S/N, incorporated in Production		Hrs				
			Enc				
AS907-72-9055 Rev 1	Engine - High Pressure Compressor Assembly - Install New Stage 1 Variable Compressor Vanes, P/N 70040795-1, on AS907 Engines					RE (-)	Cat.2-Reliability
 72 ENG1			Mos	10-Feb-2023			
Eff: 20-Dec-2017 Not Applicable	PER ENGINE PART NUMBE		Hrs				
			Enc				
AS907-72-9055 Rev 1	Engine - High Pressure Compressor Assembly - Install New Stage 1 Variable Compressor Vanes, P/N 70040795-1, on AS907 Engines					RE (-)	Cat.2-Reliability
 72 ENG2			Mos	10-Feb-2023			
Eff: 20-Dec-2017 Not Applicable	PER ENGINE PART NUMBER		Hrs				
			Enc				
AS907-72-9057	Engine - HP Turbine Section - Install New Forward Vane Baffle, PN 70040799-1, on AS907-1-1A and AS907-2-1G Model Engines					RE (-)	
 72 ENG1			Mos	10-Feb-2023			
Eff: 13-Oct-2016 Not Applicable	PER S/N, incorporated in Production		Hrs				
			Enc				
AS907-72-9057	Engine - HP Turbine Section - Install New Forward Vane Baffle, PN 70040799-1, on AS907-1-1A and AS907-2-1G Model Engines					RE (-)	
 72 ENG2			Mos	10-Feb-2023			
Eff: 13-Oct-2016 Not Applicable	PER S/N, incorporated in Production		Hrs				
			Enc				

Task No SEQ PN/SN	Description MOC Note		CW	REQ	TOL	Categories DUE	Time Remaining
AS907-72-9057 Rev 1	Engine - HP Turbine Section - Install New Forward Vane Baffle, PN 70040799-1, on AS907-1-1A and AS907-2-1G Model Engines			RE (-)		Cat.2-Reliability, Cat.3-Product Improvement	
 72 ENG1 Eff: 05-Dec-2019 Not Applicable	per S/N		Mos	10-Apr-2023			
			Hrs	84:18			
			Enc	54			
AS907-72-9057 Rev 1	Engine - HP Turbine Section - Install New Forward Vane Baffle, PN 70040799-1, on AS907-1-1A and AS907-2-1G Model Engines			RE (-)		Cat.2-Reliability, Cat.3-Product Improvement	
 72 ENG2 Eff: 05-Dec-2019 Not Applicable	per S/N		Mos	10-Apr-2023			
			Hrs	104:18			
			Enc	66			
AS907-72-9060	ENGINE - HP COMPRESSOR - New Investment Cast Front Frame Assemblies PN 70040792-2 and PN 70040792-3 for Affected AS907 Engine Models			RE (-)			
 72 ENG1 Eff: 19-Dec-2014 Not Applicable	PER S/N. INCORPORATED IN PRODUCTION		Mos	10-Feb-2023			
			Hrs				
			Enc				
AS907-72-9060	ENGINE - HP COMPRESSOR - New Investment Cast Front Frame Assemblies PN 70040792-2 and PN 70040792-3 for Affected AS907 Engine Models			RE (-)			
 72 ENG2 Eff: 19-Dec-2014 Not Applicable	PER S/N. INCORPORATED IN PRODUCTION		Mos	10-Feb-2023			
			Hrs				
			Enc				
AS907-72-9061	ENGINE - HIGH PRESSURE COMPRESSOR (HPC) ASSEMBLY - Inspect the Bore of the 2nd 3rd and 4th Stage Axial Compressor Blisks and Replace Non-conforming Blisks on AS907-1-1A and AS907-2-1G Model Engines			RE (-)			
 72 ENG1 Eff: 01-Sep-2015 Not Applicable	PER S/N. INCORPORATED IN PRODUCTION		Mos	10-Feb-2023			
			Hrs				
			Enc				
AS907-72-9061	ENGINE - HIGH PRESSURE COMPRESSOR (HPC) ASSEMBLY - Inspect the Bore of the 2nd 3rd and 4th Stage Axial Compressor Blisks and Replace Non-conforming Blisks on AS907-1-1A and AS907-2-1G Model Engines			RE (-)			
 72 ENG2 Eff: 01-Sep-2015 Not Applicable	PER S/N. INCORPORATED IN PRODUCTION		Mos	10-Feb-2023			
			Hrs				
			Enc				
AS907-72-9063	Engine - HP Compressor - Install New Centrifugal Compressor Rotor PN 3033207-1 Shroud PN70040911-1 or PN 70040911-2 and Diffuser PN 70040018-1 for AS907-2-1G Engine Models			RE (-)			
 72 ENG1 Eff: 08-May-2015 Not Applicable	PER S/N, incorporated in Production		Mos	10-Feb-2023			
			Hrs				
			Enc				
AS907-72-9063	Engine - HP Compressor - Install New Centrifugal Compressor Rotor PN 3033207-1 Shroud PN70040911-1 or PN 70040911-2 and Diffuser PN 70040018-1 for AS907-2-1G Engine Models			RE (-)			
 72 ENG2 Eff: 08-May-2015 Not Applicable	PER S/N, incorporated in Production		Mos	10-Feb-2023			
			Hrs				
			Enc				
AS907-72-9063 Rev 1	Engine - HP Compressor - Install New Centrifugal Compressor Rotor, PN 3033207-1, Shroud, 70040911-1 or PN 70041133-1, and Diffuser, PN 70040018-1, for AS907-2-1G Engine Models			RE (-)		Category 3, Optional	
 72 ENG1 Eff: 31-Jul-2019 Not Applicable (UPDATE NOTE: N/A as per installed ECU on OK_GTX)			Mos	24-Jan-2024			
			Hrs				
			Enc				
AS907-72-9063 Rev 1	Engine - HP Compressor - Install New Centrifugal Compressor Rotor, PN 3033207-1, Shroud, 70040911-1 or PN 70041133-1, and Diffuser, PN 70040018-1, for AS907-2-1G Engine Models			RE (-)		Category 3, Optional	
 72 ENG2 Eff: 31-Jul-2019 Not Applicable (UPDATE NOTE: N/A as per installed ECU on OK_GTX)			Mos	24-Jan-2024			
			Hrs				
			Enc				

Task No SEQ PN/SN	Description MOC Note	CW	REQ	TOL	Categories DUE	Time Remaining
AS907-72-9064  72 ENG1 Eff: 12-Jun-2015	ENGINE - BYPASS SECTION - Apply Secondary Corrosion Protection (Paint) to Forward Outer FanBypass Duct PN WBA7271E102-XXX and/or Aft Outer Fan Bypass Duct PN WBA7271E112-XXX and/orInner Fan Bypass Duct Panels and Supports on AS907 Engines		T (A/R)			
		Mos				
		Hrs				
		Enc				
AS907-72-9064  72 ENG2 Eff: 12-Jun-2015	ENGINE - BYPASS SECTION - Apply Secondary Corrosion Protection (Paint) to Forward Outer FanBypass Duct PN WBA7271E102-XXX and/or Aft Outer Fan Bypass Duct PN WBA7271E112-XXX and/orInner Fan Bypass Duct Panels and Supports on AS907 Engines		T (A/R)			
		Mos				
		Hrs				
		Enc				
AS907-72-9064 Rev 1  72 ENG1 Eff: 14-Mar-2016 Not Applicable	ENGINE - BYPASS SECTION - Apply Secondary Corrosion Protection (Paint) to Forward Outer FanBypass Duct PN WBA7271E102-XXX and/or Aft Outer Fan Bypass Duct PN WBA7271E112-XXX and/orInner Fan Bypass Duct Panels and Supports on AS907 Engines PER ENGINE PART NUMBER		RE (-)			
		Mos	10-Feb-2023			
		Hrs				
		Enc				
AS907-72-9064 Rev 1  72 ENG2 Eff: 14-Mar-2016 Not Applicable	ENGINE - BYPASS SECTION - Apply Secondary Corrosion Protection (Paint) to Forward Outer FanBypass Duct PN WBA7271E102-XXX and/or Aft Outer Fan Bypass Duct PN WBA7271E112-XXX and/orInner Fan Bypass Duct Panels and Supports on AS907 Engines PER ENGINE PART NUMBER		RE (-)			
		Mos	10-Feb-2023			
		Hrs				
		Enc				
AS907-72-9065  72 ENG1 Eff: 08-Feb-2019 Not Applicable	Engine - Hp Compressor - Install New Compressor Case(s) with Reduced Number of Borescope Plugs on AS907 Engine Models as per engine S/N		RE (-)		Cat.3-Product Improvement	
		Mos	17-Apr-2023			
		Hrs	97:47			
		Enc	64			
AS907-72-9065  72 ENG2 Eff: 08-Feb-2019 Not Applicable	Engine - Hp Compressor - Install New Compressor Case(s) with Reduced Number of Borescope Plugs on AS907 Engine Models as per engine S/N		RE (-)		Cat.3-Product Improvement	
		Mos	17-Apr-2023			
		Hrs	117:47			
		Enc	76			
AS907-72-9066  72 ENG1 Eff: 19-Sep-2018	Engine - HP Turbine Section - Install New Stage 1 High Pressure Turbine (HTP1) Rotor Assembly PN 70040856-6 and High Pressure Turbine (HPT) Nozzle Support PN 3035056-6 for AS907-2-1G Model Engines		T (-)		Category 3, Optional	
		Mos				
		Hrs				
		Enc				
AS907-72-9066  72 ENG2 Eff: 19-Sep-2018	Engine - HP Turbine Section - Install New Stage 1 High Pressure Turbine (HTP1) Rotor Assembly PN 70040856-6 and High Pressure Turbine (HPT) Nozzle Support PN 3035056-6 for AS907-2-1G Model Engines		T (-)		Category 3, Optional	
		Mos				
		Hrs				
		Enc				
AS907-72-9066 Rev 1  72 ENG1 Eff: 25-Jul-2025 Not Applicable	Engine - HP Turbine Section - Install New Stage 1 High Pressure Turbine (HTP1) Rotor Assembly, PN 70040856-3 or 70040856-6, and High Pressure Turbine (HPT) Nozzle Support, PN 3035056-6, for AS907-2-1G Model Engines per Engine PN and SN.		RE (-)		Category 3, Optional	
		Mos				
		Hrs				
		Enc				
AS907-72-9066 Rev 1  72 ENG2 Eff: 25-Jul-2025 Not Applicable	Engine - HP Turbine Section - Install New Stage 1 High Pressure Turbine (HTP1) Rotor Assembly, PN 70040856-3 or 70040856-6, and High Pressure Turbine (HPT) Nozzle Support, PN 3035056-6, for AS907-2-1G Model Engines per Engine PN and SN.		RE (-)		Category 3, Optional	
		Mos				
		Hrs				
		Enc				

Task No SEQ PN/SN	Description MOC Note	CW	REQ	TOL	Categories DUE	Time Remaining
AS907-72-9068 72 ENG1 Eff: 22-Aug-2019	Engine - HP Compressor - New Investment Cast Front Frame Assemblies, PN 70040792-4, and PN 70040939-2, for AS907 Engine Models		RE (-)		Category 3, Optional	
		Mos				
		Hrs				
		Enc				
AS907-72-9068 72 ENG2 Eff: 22-Aug-2019	Engine - HP Compressor - New Investment Cast Front Frame Assemblies, PN 70040792-4, and PN 70040939-2, for AS907 Engine Models		RE (-)		Category 3, Optional	
		Mos				
		Hrs				
		Enc				
AS907-72-9071 72 ENG1 Eff: 12-Jun-2018 Not Applicable	Engine - HP Compressor - Install New Centrifugal Compressor Case (Impeller Shroud) PN 70041125-1 on AS907 Engine Models as per engine S/N		RE (-)		Cat.3-Product Improvement	
		Mos	17-Apr-2023			
		Hrs	97:47			
		Enc	64			
AS907-72-9071 72 ENG2 Eff: 12-Jun-2018 Not Applicable	Engine - HP Compressor - Install New Centrifugal Compressor Case (Impeller Shroud) PN 70041125-1 on AS907 Engine Models as per engine S/N		RE (-)		Cat.3-Product Improvement	
		Mos	17-Apr-2023			
		Hrs	117:47			
		Enc	76			
AS907-72-9071 Rev 1 72 ENG1 Eff: 07-Dec-2018 Not Applicable	Engine - HP Compressor - Install New Centrifugal Compressor Case (Impeller Shroud) PN 70041125-1, and PN 70041133-1, on AS907 Engine Models as per engine S/N		RE (-)		Cat.3-Product Improvement	
		Mos	17-Apr-2023			
		Hrs	97:47			
		Enc	64			
AS907-72-9071 Rev 1 72 ENG2 Eff: 07-Dec-2018 Not Applicable	Engine - HP Compressor - Install New Centrifugal Compressor Case (Impeller Shroud) PN 70041125-1, and PN 70041133-1, on AS907 Engine Models as per engine S/N		RE (-)		Cat.3-Product Improvement	
		Mos	17-Apr-2023			
		Hrs	117:47			
		Enc	76			
AS907-72-9076 72 ENG1 Eff: 07-Mar-2019 Not Applicable	Engine - Turbine Section - Install New Stage 1 Shroud Segments, PN 70041107-1, with HPT First Stage Seals, PN 70041109-1 and PN 70041110-1 on AS907 Model Engines as per engine S/N		RE (-)		Cat. 2 - Recommended	
		Mos	17-Apr-2023			
		Hrs	97:47			
		Enc	64			
AS907-72-9076 72 ENG2 Eff: 07-Mar-2019 Not Applicable	Engine - Turbine Section - Install New Stage 1 Shroud Segments, PN 70041107-1, with HPT First Stage Seals, PN 70041109-1 and PN 70041110-1 on AS907 Model Engines as per engine S/N		RE (-)		Cat. 2 - Recommended	
		Mos	17-Apr-2023			
		Hrs	117:47			
		Enc	76			
AS907-72-9076 Rev 1 72 ENG1 Eff: 17-Oct-2019 Complied With	Engine - Turbine Section - Install New Stage 1 Shroud Segments, PN 70041107-1, with High Pressure Turbine (HPT) First Stage Seals, PN 70041109-1 and PN 70041110-1 on AS907 Model Engines AT MANUFACTURE		RE (-)		Cat. 2 - Recommended	
		Mos	10-Apr-2023			
		Hrs	84:18			
		Enc	54			
AS907-72-9076 Rev 1 72 ENG2 Eff: 17-Oct-2019 Complied With	Engine - Turbine Section - Install New Stage 1 Shroud Segments, PN 70041107-1, with High Pressure Turbine (HPT) First Stage Seals, PN 70041109-1 and PN 70041110-1 on AS907 Model Engines AT MANUFACTURE		RE (-)		Cat. 2 - Recommended	
		Mos	10-Apr-2023			
		Hrs	104:18			
		Enc	66			

Task No SEQ PN/SN	Description MOC Note		CW	REQ	TOL	Categories DUE	Time Remaining
AS907-72-9076 Rev 3	Engine - Turbine Section - Install New Stage 1 Shroud Segments, PN 70041107-1, with High Pressure Turbine (HPT) First Stage Seals, PN 70041109-1 and PN 70041110-1 on AS907 Model Engines			RE (-)		Cat. 2 - Recommended	
 72 ENG1 Eff: 08-Apr-2024 Not Applicable	as per engine S/N	Mos	27-May-2024				
		Hrs	817:49				
		Enc	491				
AS907-72-9076 Rev 3	Engine - Turbine Section - Install New Stage 1 Shroud Segments, PN 70041107-1, with High Pressure Turbine (HPT) First Stage Seals, PN 70041109-1 and PN 70041110-1 on AS907 Model Engines			RE (-)		Cat. 2 - Recommended	
 72 ENG2 Eff: 08-Apr-2024 Not Applicable	as per engine S/N	Mos	27-May-2024				
		Hrs	837:49				
		Enc	503				
AS907-72-9077	Engine - Bypass Section - Install New Fan Rotor Assembly and Fan Stator Vane Assembly with Fan Stator Static Baffle on AS907-2-1G and AS907-3-1E Model Engines			RE (-)		Category 3, Optional	
 72 ENG1 Eff: 03-Sep-2019		Mos					
		Hrs					
		Enc					
AS907-72-9077	Engine - Bypass Section - Install New Fan Rotor Assembly and Fan Stator Vane Assembly with Fan Stator Static Baffle on AS907-2-1G and AS907-3-1E Model Engines			RE (-)		Category 3, Optional	
 72 ENG2 Eff: 03-Sep-2019		Mos					
		Hrs					
		Enc					
AS907-72-9077 Rev 1	Engine - Bypass Section - Install New Fan Rotor Assembly and Fan Stator Vane Assembly with Fan Stator Static Baffle on AS907-2-1A, AS907-2-1G, AS907-2-1S, and AS907-3-1E Model Engines			RE (-)		Category 3	
 72 ENG1 Eff: 23-Nov-2022 Not Applicable	as per engine S/N	Mos	17-Apr-2023				
		Hrs	97:47				
		Enc	64				
AS907-72-9077 Rev 1	Engine - Bypass Section - Install New Fan Rotor Assembly and Fan Stator Vane Assembly with Fan Stator Static Baffle on AS907-2-1A, AS907-2-1G, AS907-2-1S, and AS907-3-1E Model Engines			RE (-)		Category 3	
 72 ENG2 Eff: 23-Nov-2022 Not Applicable	as per engine S/N	Mos	17-Apr-2023				
		Hrs	117:47				
		Enc	76				
AS907-72-9079	Engine - Combustion Section - Install New Combustion Chamber Assembly, PN 3034088-6, on AS907 Model Engines			RE (-)		Category 3	
 72 ENG1 Eff: 18-Dec-2018 Not Applicable	as per engine S/N	Mos	17-Apr-2023				
		Hrs	97:47				
		Enc	64				
AS907-72-9079	Engine - Combustion Section - Install New Combustion Chamber Assembly, PN 3034088-6, on AS907 Model Engines			RE (-)		Category 3	
 72 ENG2 Eff: 18-Dec-2018 Not Applicable	as per engine S/N	Mos	17-Apr-2023				
		Hrs	117:47				
		Enc	76				
AS907-72-9080	Engine - Turbine Section - Install Improved No. 4 Roller Bearing PN 3035647-7 on AS907 Model Engines			RE (-)		Cat.2-Reliability	
 72 ENG1 Eff: 20-Sep-2018 Not Applicable	as per engine S/N	Mos	17-Apr-2023				
		Hrs	97:47				
		Enc	64				
AS907-72-9080	Engine - Turbine Section - Install Improved No. 4 Roller Bearing PN 3035647-7 on AS907 Model Engines			RE (-)		Cat.2-Reliability	
 72 ENG2 Eff: 20-Sep-2018 Not Applicable	as per engine S/N	Mos	17-Apr-2023				
		Hrs	117:47				
		Enc	76				

Task No		Description				Categories	Time
SEQ	PN/SN	MOC Note	CW	REQ	TOL	DUE	Remaining
AS907-72-9080 Rev 1		Engine - Turbine Section - Install Improved No. 4 Roller Bearing, PN 3035647-7, on AS907 Model Engines				RE (-)	Cat. 2 - Recommended
	72 ENG1		Mos	26-Jan-2023			
	Eff: 22-Nov-2019 Complied With	AT MANUFACTURE	Hrs	0			
			Enc	0			
AS907-72-9080 Rev 1		Engine - Turbine Section - Install Improved No. 4 Roller Bearing, PN 3035647-7, on AS907 Model Engines				RE (-)	Cat. 2 - Recommended
	72 ENG2		Mos	20-Jan-2023			
	Eff: 22-Nov-2019 Complied With	AT MANUFACTURE	Hrs	0			
			Enc	0			
AS907-72-9081		Engine - HP Compressor - Install Improved Compressor Stator Vanes PN 70040972-2, 70040973-3, 70040947-2, 70040899-3 and 70040036-5 on AS907 Model Engines				RE (-)	Category 3, Optional
	72 ENG1		Mos				
	Eff: 25-Sep-2018		Hrs				
			Enc				
AS907-72-9081		Engine - HP Compressor - Install Improved Compressor Stator Vanes PN 70040972-2, 70040973-3, 70040947-2, 70040899-3 and 70040036-5 on AS907 Model Engines				RE (-)	Category 3, Optional
	72 ENG2		Mos				
	Eff: 25-Sep-2018		Hrs				
			Enc				
AS907-72-9081 Rev 1		Engine - HP Compressor - Install Improved Compressor Stator Vanes PN 70040972-2, 70040973-3, 70040947-2, 70040899-3, 70040899-4, 70040036-5, and 70040036-6 on AS907 Model Engines				RE (-)	Category 3, Optional
	72 ENG1		Mos	26-Jan-2023			
	Eff: 22-Jan-2019 Complied With	AT MANUFACTURE	Hrs	0			
			Enc	0			
AS907-72-9081 Rev 1		Engine - HP Compressor - Install Improved Compressor Stator Vanes PN 70040972-2, 70040973-3, 70040947-2, 70040899-3, 70040899-4, 70040036-5, and 70040036-6 on AS907 Model Engines				RE (-)	Category 3, Optional
	72 ENG2		Mos	20-Jan-2023			
	Eff: 22-Jan-2019 Complied With	AT MANUFACTURE	Hrs	0			
			Enc	0			
AS907-72-9082		Engine - LP Turbine Section - Install Reworked or New Stage 2 Low Pressure Turbine (LPT) Rotor Assembly, PN 3035660-2, with Stage 2 LPT Blades, PN 3035602-2 and/or Reworked Stage 2 LPT Blades, PN 70041201-1, on AS907 Model Engines				RE (-)	Category 2
	72 ENG1		Mos	17-Apr-2023			
	Eff: 06-Jul-2020 Not Applicable	as per engine S/N	Hrs	97:47			
			Enc	64			
AS907-72-9082		Engine - LP Turbine Section - Install Reworked or New Stage 2 Low Pressure Turbine (LPT) Rotor Assembly, PN 3035660-2, with Stage 2 LPT Blades, PN 3035602-2 and/or Reworked Stage 2 LPT Blades, PN 70041201-1, on AS907 Model Engines				RE (-)	Category 2
	72 ENG2		Mos	17-Apr-2023			
	Eff: 06-Jul-2020 Not Applicable	as per engine S/N	Hrs	117:47			
			Enc	76			
AS907-72-9084		Engine - Servicing - Reduce Time Intervals for Oil Filter Replacement and Engine Fault Diagnostic Data (EEI) Download to Provide Enhanced Monitoring of Aft Sump Components				RE (-)	Cat. 2 - Recommended
	72 ENG1		Mos	17-Apr-2023			
	Eff: 12-Jun-2019 Not Applicable	as per engine S/N	Hrs	97:47			
			Enc	64			
AS907-72-9084		Engine - Servicing - Reduce Time Intervals for Oil Filter Replacement and Engine Fault Diagnostic Data (EEI) Download to Provide Enhanced Monitoring of Aft Sump Components				RE (-)	Cat. 2 - Recommended
	72 ENG2		Mos	17-Apr-2023			
	Eff: 12-Jun-2019 Not Applicable	as per engine S/N	Hrs	117:47			
			Enc	76			

Task No SEQ PN/SN	Description MOC Note		CW	REQ	TOL	Categories DUE	Time Remaining
AS907-72-9084 Rev 1	Engine - Servicing - Reduce Time Intervals for Oil Filter Replacement and Engine Fault Diagnostic Data (EEI) Download to Provide Enhanced Monitoring of Aft Sump Components			RE (-)		Cat. 2 - Recommended	
 72 ENG1 Eff: 21-Feb-2020 Not Applicable	as per engine S/N	Mos	17-Apr-2023				
		Hrs	97:47				
		Enc	64				
AS907-72-9084 Rev 1	Engine - Servicing - Reduce Time Intervals for Oil Filter Replacement and Engine Fault Diagnostic Data (EEI) Download to Provide Enhanced Monitoring of Aft Sump Components			RE (-)		Cat. 2 - Recommended	
 72 ENG2 Eff: 21-Feb-2020 Not Applicable	as per engine S/N	Mos	17-Apr-2023				
		Hrs	117:47				
		Enc	76				
AS907-72-9084 Rev 2	Engine - Servicing - Reduce Time Intervals for Oil Filter Replacement and Engine Fault Diagnostic Data (EEI) Download to Provide Enhanced Monitoring of Aft Sump Components			RE (-)		Cat. 2 - Recommended	
 72 ENG1 Eff: 03-Apr-2020 Not Applicable	as per engine S/N	Mos	17-Apr-2023				
		Hrs	97:47				
		Enc	64				
AS907-72-9084 Rev 2	Engine - Servicing - Reduce Time Intervals for Oil Filter Replacement and Engine Fault Diagnostic Data (EEI) Download to Provide Enhanced Monitoring of Aft Sump Components			RE (-)		Cat. 2 - Recommended	
 72 ENG2 Eff: 03-Apr-2020 Not Applicable	as per engine S/N	Mos	17-Apr-2023				
		Hrs	117:47				
		Enc	76				
AS907-72-9084 Rev 2 Par. E. (2)	Engine - Servicing - Reduce Time Intervals for Oil Filter Replacement and Engine Fault Diagnostic Data (EEI) Download to Provide Enhanced Monitoring of Aft Sump Components - Oil Filter Replacement			RE (-)		Cat. 2 - Recommended	
 72 ENG1 Eff: 12-Jun-2019 Not Applicable	as per engine S/N	Mos	17-Apr-2023				
		Hrs	97:47				
		Enc	64				
AS907-72-9084 Rev 2 Par. E. (2)	Engine - Servicing - Reduce Time Intervals for Oil Filter Replacement and Engine Fault Diagnostic Data (EEI) Download to Provide Enhanced Monitoring of Aft Sump Components - Oil Filter Replacement			RE (-)		Cat. 2 - Recommended	
 72 ENG2 Eff: 12-Jun-2019 Not Applicable	as per engine S/N	Mos	17-Apr-2023				
		Hrs	117:47				
		Enc	76				
AS907-72-9084 Rev 2 Par. E. (3)	Engine - Servicing - Reduce Time Intervals for Oil Filter Replacement and Engine Fault Diagnostic Data (EEI) Download to Provide Enhanced Monitoring of Aft Sump Components - (EEI) Download			RE (-)		Cat. 2 - Recommended	
 72 ENG1 Eff: 21-Feb-2020 Not Applicable	as per engine S/N	Mos	17-Apr-2023				
		Hrs	97:47				
		Enc	64				
AS907-72-9084 Rev 2 Par. E. (3)	Engine - Servicing - Reduce Time Intervals for Oil Filter Replacement and Engine Fault Diagnostic Data (EEI) Download to Provide Enhanced Monitoring of Aft Sump Components - (EEI) Download			RE (-)		Cat. 2 - Recommended	
 72 ENG2 Eff: 21-Feb-2020 Not Applicable	as per engine S/N	Mos	17-Apr-2023				
		Hrs	117:47				
		Enc	76				
AS907-72-9084 Rev 3	Engine - Servicing - Reduce Time Interval for Oil Filter Replacement or Engine Fault Diagnostic Data (EEI) Download to Provide Enhanced Monitoring of Aft Sump Components			RE (-)		Cat. 2 - Recommended	
 72 ENG1 Eff: 26-Jun-2021 Not Applicable	as per engine S/N	Mos	17-Apr-2023				
		Hrs	97:47				
		Enc	64				

Task No SEQ PN/SN	Description MOC Note	CW	REQ	TOL	Categories DUE	Time Remaining
AS907-72-9084 Rev 3	Engine - Servicing - Reduce Time Interval for Oil Filter Replacement or Engine Fault Diagnostic Data (EEI) Download to Provide Enhanced Monitoring of Aft Sump Components		RE (-)		Cat. 2 - Recommended	
 72 ENG2 Eff: 26-Jun-2021 Not Applicable	as per engine S/N	Mos Hrs Enc	17-Apr-2023 117:47 76			
AS907-72-9084 Rev 3 Par. E. (2) Part 1	Engine - Servicing - Reduce Time Interval for Oil Filter Replacement or Engine Fault Diagnostic Data (EEI) Download to Provide Enhanced Monitoring of Aft Sump Components - (EEI) Download		RE (-)		Cat. 2 - Recommended	
 72 ENG1 Eff: 26-Jun-2021 Not Applicable	as per engine S/N	Mos Hrs Enc	17-Apr-2023 97:47 64			
AS907-72-9084 Rev 3 Par. E. (2) Part 1	Engine - Servicing - Reduce Time Interval for Oil Filter Replacement or Engine Fault Diagnostic Data (EEI) Download to Provide Enhanced Monitoring of Aft Sump Components - (EEI) Download		RE (-)		Cat. 2 - Recommended	
 72 ENG2 Eff: 26-Jun-2021 Not Applicable	as per engine S/N	Mos Hrs Enc	17-Apr-2023 117:47 76			
AS907-72-9084 Rev 3 Par. E. (2) Part 2	Engine - Servicing - Reduce Time Interval for Oil Filter Replacement or Engine Fault Diagnostic Data (EEI) Download to Provide Enhanced Monitoring of Aft Sump Components - Oil Filter Analysis		RE (-)		Cat. 2 - Recommended	
 72 ENG1 Eff: 26-Jun-2021 Not Applicable	as per engine S/N	Mos Hrs Enc	17-Apr-2023 97:47 64			
AS907-72-9084 Rev 3 Par. E. (2) Part 2	Engine - Servicing - Reduce Time Interval for Oil Filter Replacement or Engine Fault Diagnostic Data (EEI) Download to Provide Enhanced Monitoring of Aft Sump Components - Oil Filter Analysis		RE (-)		Cat. 2 - Recommended	
 72 ENG2 Eff: 26-Jun-2021 Not Applicable	as per engine S/N	Mos Hrs Enc	17-Apr-2023 117:47 76			
AS907-72-9084 Rev 4	Engine - Servicing - Reduce Time Interval for Oil Filter Replacement or Engine Fault Diagnostic Data (EEI) Download to Provide Enhanced Monitoring of Aft Sump Components		RE (-)		CATEGORY 02 - RECOMMENDED	
 72 ENG1 Eff: 06-Aug-2026 Not Applicable	As per Engine SN.	Mos Hrs Enc				
AS907-72-9084 Rev 4	Engine - Servicing - Reduce Time Interval for Oil Filter Replacement or Engine Fault Diagnostic Data (EEI) Download to Provide Enhanced Monitoring of Aft Sump Components		RE (-)		CATEGORY 02 - RECOMMENDED	
 72 ENG2 Eff: 06-Aug-2026 Not Applicable	As per Engine SN.	Mos Hrs Enc				
AS907-72-9084 Rev 4 Par. E. (2) Part 1	Engine - Servicing - Reduce Time Interval for Oil Filter Replacement or Engine Fault Diagnostic Data (EEI) Download to Provide Enhanced Monitoring of Aft Sump Components - (EEI) download		RE (-)		CATEGORY 02 - RECOMMENDED	
 72 ENG1 Eff: 06-Aug-2026 Not Applicable	As per Engine SN.	Mos Hrs Enc				
AS907-72-9084 Rev 4 Par. E. (2) Part 1	Engine - Servicing - Reduce Time Interval for Oil Filter Replacement or Engine Fault Diagnostic Data (EEI) Download to Provide Enhanced Monitoring of Aft Sump Components - (EEI) download		RE (-)		CATEGORY 02 - RECOMMENDED	
 72 ENG2 Eff: 06-Aug-2026 Not Applicable	As per Engine SN.	Mos Hrs Enc				

Task No		Description				CW	REQ	TOL	Categories	Time
SEQ	PN/SN	MOC Note							DUE	Remaining
AS907-72-9084 Rev 4 Par. E. (2) Part 2		Engine - Servicing - Reduce Time Interval for Oil Filter Replacement or Engine Fault Diagnostic Data (EEL) Download to Provide Enhanced Monitoring of Aft Sump Components - Oil Filter Analysis					RE (-)		CATEGORY 02 - RECOMMENDED	
	72 ENG1					Mos				
	Eff: 06-Aug-2026 Not Applicable	As per Engine SN.				Hrs				
						Enc				
AS907-72-9084 Rev 4 Par. E. (2) Part 2		Engine - Servicing - Reduce Time Interval for Oil Filter Replacement or Engine Fault Diagnostic Data (EEL) Download to Provide Enhanced Monitoring of Aft Sump Components - Oil Filter Analysis					RE (-)		CATEGORY 02 - RECOMMENDED	
	72 ENG2					Mos				
	Eff: 06-Aug-2026 Not Applicable	As per Engine SN.				Hrs				
						Enc				
AS907-72-9085		Engine - LP Turbine Section - Install Reworked or New Stage 3 Low Pressure Turbine (LPT) Rotor Assembly, PN 3035662-3, with Stage 3 LPT Blades, PN 3035609-3, and/or Reworked Stage 3 LPT Blades, PN 70041202-1, on AS907 Model Engines					RE (-)		Category 2	
	72 ENG1					Mos	17-Apr-2023			
	Eff: 11-May-2021 Not Applicable	as per engine S/N				Hrs	97:47			
						Enc	64			
AS907-72-9085		Engine - LP Turbine Section - Install Reworked or New Stage 3 Low Pressure Turbine (LPT) Rotor Assembly, PN 3035662-3, with Stage 3 LPT Blades, PN 3035609-3, and/or Reworked Stage 3 LPT Blades, PN 70041202-1, on AS907 Model Engines					RE (-)		Category 2	
	72 ENG2					Mos	17-Apr-2023			
	Eff: 11-May-2021 Not Applicable	as per engine S/N				Hrs	117:47			
						Enc	76			
AS907-72-9086		Engine - LP Turbine Section - Install Reworked or New Stage 1 Low Pressure Turbine (LPT) Rotor Assembly, PN 3035692-2, with Stage 1 LPT Blades, PN 3035693-2, and/or Reworked Stage 1 LPT Blades, PN 70041200-1, on AS907 Model Engines					RE (-)		Cat. 2 - Recommended	
	72 ENG1					Mos	17-Apr-2023			
	Eff: 14-May-2021 Not Applicable	as per engine S/N				Hrs	97:47			
						Enc	64			
AS907-72-9086		Engine - LP Turbine Section - Install Reworked or New Stage 1 Low Pressure Turbine (LPT) Rotor Assembly, PN 3035692-2, with Stage 1 LPT Blades, PN 3035693-2, and/or Reworked Stage 1 LPT Blades, PN 70041200-1, on AS907 Model Engines					RE (-)		Cat. 2 - Recommended	
	72 ENG2					Mos	17-Apr-2023			
	Eff: 14-May-2021 Not Applicable	as per engine S/N				Hrs	117:47			
						Enc	76			
AS907-72-9089		Engine - Air Inlet Section - Install New Fan Inlet Housings on AS907 Model Engines_					T (A/R)		Category 3, Optional	
	72 ENG1					Mos				
	Eff: 03-Mar-2020					Hrs				
						Enc				
AS907-72-9089		Engine - Air Inlet Section - Install New Fan Inlet Housings on AS907 Model Engines_					T (A/R)		Category 3, Optional	
	72 ENG2					Mos				
	Eff: 03-Mar-2020					Hrs				
						Enc				
AS907-72-9090		Engine - LP Turbine Section - Install New No. 4 Bearing Carbon Seal on AS907 Model Engines					RE (-)		Category 3, Optional	
	72 ENG1					Mos				
	Eff: 28-Mar-2020					Hrs				
						Enc				
AS907-72-9090		Engine - LP Turbine Section - Install New No. 4 Bearing Carbon Seal on AS907 Model Engines					RE (-)		Category 3, Optional	
	72 ENG2					Mos				
	Eff: 28-Mar-2020					Hrs				
						Enc				

Task No		Description				Categories	Time	
SEQ	PN/SN	MOC Note		CW	REQ	TOL	DUE	Remaining
AS907-72-9090 Rev 1		Engine - LP Turbine Section - Install New No. 4 Bearing Carbon Seal on AS907 Model Engines			RE (-)		Category 3, Optional	
	72 ENG1		Mos					
	Eff: 16-Dec-2020		Hrs					
			Enc					
AS907-72-9090 Rev 1		Engine - LP Turbine Section - Install New No. 4 Bearing Carbon Seal on AS907 Model Engines			RE (-)		Category 3, Optional	
	72 ENG2		Mos					
	Eff: 16-Dec-2020		Hrs					
			Enc					
AS907-72-9090 Rev 2		Engine - LP Turbine Section - Install New No. 4 Bearing Carbon Seal on AS907 Model Engines (Inactive for Further Accomplishment)			RE (-)		Category 3, Optional	
	72 ENG1		Mos					
	Eff: 25-Nov-2021		Hrs					
			Enc					
AS907-72-9090 Rev 2		Engine - LP Turbine Section - Install New No. 4 Bearing Carbon Seal on AS907 Model Engines (Inactive for Further Accomplishment)			RE (-)		Category 3, Optional	
	72 ENG2		Mos					
	Eff: 25-Nov-2021		Hrs					
			Enc					
AS907-72-9091		Engine - HP Turbine Section - HPT-2 Rotor Assembly, PN 3035135-5/-6/-7, Institute Enhanced Inspection and Reporting for the HPT Rotating Interstage Seal, PN 3035134-3 on AS907 Model Engines			RE (-)		Cat. 2 - Recommended	
	72 ENG1		Mos	17-Apr-2023				
	Eff: 16-Oct-2020 Not Applicable	before manufacture	Hrs	97:47				
			Enc	64				
AS907-72-9091		Engine - HP Turbine Section - HPT-2 Rotor Assembly, PN 3035135-5/-6/-7, Institute Enhanced Inspection and Reporting for the HPT Rotating Interstage Seal, PN 3035134-3 on AS907 Model Engines			RE (-)		Cat. 2 - Recommended	
	72 ENG2		Mos	17-Apr-2023				
	Eff: 16-Oct-2020 Not Applicable	before manufacture	Hrs	117:47				
			Enc	76				
AS907-72-9091 Rev 1		Engine - HP Turbine Section - HPT-2 Rotor Assembly, PN 3035135-2/-4/-5/-6/-7, Institute Enhanced Inspection and Reporting for the HPT Rotating Interstage Seal, PN 3035134-1 or PN 3035134-3 on AS907 Model Engines			RE (-)		Cat. 2 - Recommended	
	72 ENG1		Mos	17-Apr-2023				
	Eff: 22-Mar-2021 Not Applicable	before manufacture	Hrs	97:47				
			Enc	64				
AS907-72-9091 Rev 1		Engine - HP Turbine Section - HPT-2 Rotor Assembly, PN 3035135-2/-4/-5/-6/-7, Institute Enhanced Inspection and Reporting for the HPT Rotating Interstage Seal, PN 3035134-1 or PN 3035134-3 on AS907 Model Engines			RE (-)		Cat. 2 - Recommended	
	72 ENG2		Mos	17-Apr-2023				
	Eff: 22-Mar-2021 Not Applicable	before manufacture	Hrs	117:47				
			Enc	76				
AS907-72-9092		Engine - Compressor Section - Installation of Improved Stage 2 Compressor Stator Vane, PN 70040972-3 and 70040035-3 and Enhanced Inspection with Reporting for the Stage 2 Compressor Stator Vane and Stage 3 Compressor Stator Vane of Select Identified Part Numbers			RE (-)		Cat. 2 - Recommended	
	72 ENG1		Mos	17-Apr-2023				
	Eff: 16-Jun-2021 Not Applicable	as per engine S/N	Hrs	97:47				
			Enc	64				
AS907-72-9092		Engine - Compressor Section - Installation of Improved Stage 2 Compressor Stator Vane, PN 70040972-3 and 70040035-3 and Enhanced Inspection with Reporting for the Stage 2 Compressor Stator Vane and Stage 3 Compressor Stator Vane of Select Identified Part Numbers			RE (-)		Cat. 2 - Recommended	
	72 ENG2		Mos	17-Apr-2023				
	Eff: 16-Jun-2021 Not Applicable	as per engine S/N	Hrs	117:47				
			Enc	76				

Task No SEQ PN/SN	Description MOC Note		CW	REQ	TOL	Categories DUE	Time Remaining
AS907-72-9094	Engine - Turbine Section - Install Improved No. 4 Bearing Carbon Seal, PN 70041289-2, on AS907 Model Engines			RE (-)		Cat. 2 - Recommended	
 72 ENG1		Mos	15-May-2025				
Eff: 01-Feb-2021 Complied With	INSTALLATION OF ENGINE #1 IMPROVED #4 CARBON SEAL CARRIED OUT IAW SB AS907-72-9094 AND POST ENGINE REBUILD GROUND RUNS CARRIED OUT	Hrs	1359:10				
		Enc	791				
AS907-72-9094	Engine - Turbine Section - Install Improved No. 4 Bearing Carbon Seal, PN 70041289-2, on AS907 Model Engines			RE (-)		Cat. 2 - Recommended	
 72 ENG2		Mos	15-May-2025				
Eff: 01-Feb-2021 Complied With	INSTALLATION OF ENGINE #2 IMPROVED #4 CARBON SEAL CARRIED OUT IAW SB AS907-72-9094 AND POST ENGINE REBUILD GROUND RUNS CARRIED OUT	Hrs	1379:10				
		Enc	803				
AS907-72-9095RWK	Engine - Turbine Section - Rework, HPT Case, Matched Set Assembly with New HPT1 Shroud Segments and/or New or Serviceable HPT2 Shroud Segments			RE (-)		Service Bulletin	
 72 ENG1		Mos	17-Apr-2023				
Eff: 13-Dec-2021 Not Applicable	applicable before manufacture	Hrs	97:47				
		Enc	64				
AS907-72-9095RWK	Engine - Turbine Section - Rework, HPT Case, Matched Set Assembly with New HPT1 Shroud Segments and/or New or Serviceable HPT2 Shroud Segments			RE (-)		Service Bulletin	
 72 ENG2		Mos	17-Apr-2023				
Eff: 13-Dec-2021 Not Applicable	applicable before manufacture	Hrs	117:47				
		Enc	76				
AS907-72-9096	Engine - Turbine Section - Install New No. 5 Segmented Carbon Seal, PN 3035687-3, and Packing, PN AS3209-163, on all AS907 Engine Models			RE (-)		Cat. 3 - Optional	
 72 ENG1		Mos					
Eff: 04-Jul-2022		Hrs					
		Enc					
AS907-72-9096	Engine - Turbine Section - Install New No. 5 Segmented Carbon Seal, PN 3035687-3, and Packing, PN AS3209-163, on all AS907 Engine Models			RE (-)		Cat. 3 - Optional	
 72 ENG2		Mos					
Eff: 04-Jul-2022		Hrs					
		Enc					
AS907-72-9104	Engine - HP Turbine Section - Inspect HPT1 Nozzle Segment, PN 70040855-1, for a Step in the Trailing Edge Surface			T (A/R)		Cat. 2 - Recommended	
 72 ENG1		Mos					
Eff: 17-Apr-2026		Hrs					
		Enc					
AS907-72-9104	Engine - HP Turbine Section - Inspect HPT1 Nozzle Segment, PN 70040855-1, for a Step in the Trailing Edge Surface			T (A/R)		Cat. 2 - Recommended	
 72 ENG2		Mos					
Eff: 17-Apr-2026		Hrs					
		Enc					
AS907-72-9106	Engine - High Pressure Turbine Section - Install Improved High Pressure Turbine Rotating Interstage Seal, PN 70041752-1 or PN 70041752-2, or High Pressure Turbine Stage 2 Rotor Assembly, PN 3035135-8 on AS907 Model Engines			T (A/R)		Cat. 2 - Recommended	
 72 ENG1		Mos					
Eff: 30-Jan-2026		Hrs					
		Enc					
AS907-72-9106	Engine - High Pressure Turbine Section - Install Improved High Pressure Turbine Rotating Interstage Seal, PN 70041752-1 or PN 70041752-2, or High Pressure Turbine Stage 2 Rotor Assembly, PN 3035135-8 on AS907 Model Engines			T (A/R)		Cat. 2 - Recommended	
 72 ENG2		Mos					
Eff: 30-Jan-2026		Hrs					
		Enc					
AS907-72-9109	Engine - Bypass Section - Forward Outer Fan Bypass Duct LP/HP Bleed Boss Joint Inspection and Repair for AS907-1 and AS907-2 Engines Inspected Off Wing for Maintenance			T (A/R)		Category 2, Recommended	
 72 ENG1		Mos					
Eff: 14-Jul-2025		Hrs					
		Enc					

Task No SEQ PN/SN	Description MOC Note	CW	REQ	TOL	Categories DUE	Time Remaining
AS907-72-9109  72 ENG2 Eff: 14-Jul-2025	Engine - Bypass Section - Forward Outer Fan Bypass Duct LP/HP Bleed Boss Joint Inspection and Repair for AS907-1 and AS907-2 Engines Inspected Off Wing for Maintenance		T (A/R)		Category 2, Recommended	Mos Hrs Enc
AS907-72-9111  72 ENG1 Eff: 31-Jul-2025	Engine - Bypass Section - AS907-1 and AS907-2 Engine Series Forward Outer Fan Bypass Duct LP/HP Bleed Boss Hi-Lok Repair Instructions for a Duct Installed on the Engine		T (A/R)		Category 2, Recommended	Mos Hrs Enc
AS907-72-9111  72 ENG2 Eff: 31-Jul-2025	Engine - Bypass Section - AS907-1 and AS907-2 Engine Series Forward Outer Fan Bypass Duct LP/HP Bleed Boss Hi-Lok Repair Instructions for a Duct Installed on the Engine		T (A/R)		Category 2, Recommended	Mos Hrs Enc
AS907-72-9113  72 ENG1 Eff: 12-Jan-2026	Engine - LP Turbine Section - Install New Stage 1 LPT Shroud Segments, PN 70041145-3 and PN 70041145-4, on AS907 Model Engines		T (A/R)		Cat. 2 - Recommended	Mos Hrs Enc
AS907-72-9113  72 ENG2 Eff: 12-Jan-2026	Engine - LP Turbine Section - Install New Stage 1 LPT Shroud Segments, PN 70041145-3 and PN 70041145-4, on AS907 Model Engines		T (A/R)		Cat. 2 - Recommended	Mos Hrs Enc
AS907-72-9114RWK  72 ENG1 Eff: 03-Sep-2025	Engine - HP Turbine Section - Rework HPT2 Rotor Assembly PN 3035135-5 to 3035135-6		T (A/R)		Category 3	Mos Hrs Enc
AS907-72-9114RWK  72 ENG2 Eff: 03-Sep-2025	Engine - HP Turbine Section - Rework HPT2 Rotor Assembly PN 3035135-5 to 3035135-6		T (A/R)		Category 3	Mos Hrs Enc
AS907-72-9115  72 ENG1 Eff: 29-Jan-2026	Engine - LP Turbine Section - Install LPT Stub Shaft, PN 3035691-4, on AS907 Model Engines		T (A/R)		Cat. 3 - Optional	Mos Hrs Enc
AS907-72-9115  72 ENG2 Eff: 29-Jan-2026	Engine - LP Turbine Section - Install LPT Stub Shaft, PN 3035691-4, on AS907 Model Engines		T (A/R)		Cat. 3 - Optional	Mos Hrs Enc
AS907-76-9034  72 ENG1 Eff: 03-Jul-2025	Engine Controls - Install Silicone Rubber Self-Fusing Tape to Surge Bleed Valve Electrical Connectors on AS907 Model Engines		T (A/R)		Category 2, Recommended	Mos Hrs Enc
AS907-76-9034  72 ENG2 Eff: 03-Jul-2025	Engine Controls - Install Silicone Rubber Self-Fusing Tape to Surge Bleed Valve Electrical Connectors on AS907 Model Engines		T (A/R)		Category 2, Recommended	Mos Hrs Enc
D201212000050 Rev 1  72 ENG1 Eff: 08-Aug-2023	Engine Preservation Procedures; Use of Castrol Brayco 599 Rust Preventive Concentrate for Synthetic Turbine Oil		T (A/R)		Service Information Letter	Mos Hrs Enc

Task No	Description	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note				DUE	Remaining
D201212000050 Rev 1	Engine Preservation Procedures; Use of Castrol Brayco 599 Rust Preventive Concentrate for Synthetic Turbine Oil		T (A/R)		Service Information Letter	
 72 ENG2		Mos				
Eff: 08-Aug-2023		Hrs				
		Enc				
D201603000064	AS907 Engine Ground Start Procedure Following Shutdown (Quick Turn Around)		RE (-)		Service Information Letter	
 72 ENG1		Mos				
Eff: 17-May-2016		Hrs				
		Enc				
D201603000064	AS907 Engine Ground Start Procedure Following Shutdown (Quick Turn Around)		RE (-)		Service Information Letter	
 72 ENG2		Mos				
Eff: 17-May-2016		Hrs				
		Enc				
D201603000064 Rev 1	AS907 Engine Ground Start Procedure Following Shutdown (Quick Turn Around)		T (A/R)		Service Information Letter	
 72 ENG1		Mos				
Eff: 27-Aug-2020		Hrs				
		Enc				
D201603000064 Rev 1	AS907 Engine Ground Start Procedure Following Shutdown (Quick Turn Around)		T (A/R)		Service Information Letter	
 72 ENG2		Mos				
Eff: 27-Aug-2020		Hrs				
		Enc				
D201903000028	AS907 Aft Sump Event Discussion		T (-)		Service Information Letter	
 72 ENG1		Mos				
Eff: 26-Mar-2019		Hrs				
		Enc				
D201903000028	AS907 Aft Sump Event Discussion		T (-)		Service Information Letter	
 72 ENG2		Mos				
Eff: 26-Mar-2019		Hrs				
		Enc				
D201903000028 Rev 1	AS907 Aft Sump Event Discussion		T (-)		Service Information Letter	
 72 ENG1		Mos				
Eff: 11-Jun-2021		Hrs				
		Enc				
D201903000028 Rev 1	AS907 Aft Sump Event Discussion		T (-)		Service Information Letter	
 72 ENG2		Mos				
Eff: 11-Jun-2021		Hrs				
		Enc				
D201903000028 Rev 2	AS907 Aft Sump Event Discussion		T (A/R)		Service Information Letter	
 72 ENG1		Mos				
Eff: 14-Jul-2026		Hrs				
		Enc				
D201903000028 Rev 2	AS907 Aft Sump Event Discussion		T (A/R)		Service Information Letter	
 72 ENG2		Mos				
Eff: 14-Jul-2026		Hrs				
		Enc				
D201908000020	Honeywell AS907 Oil Filter Analysis Program		T (-)		Service Information Letter	
 72 ENG1		Mos				
Eff: 21-Aug-2019		Hrs				
		Enc				
D201908000020	Honeywell AS907 Oil Filter Analysis Program		T (-)		Service Information Letter	
 72 ENG2		Mos				
Eff: 21-Aug-2019		Hrs				
		Enc				

Task No SEQ PN/SN	Description MOC Note	CW	REQ	TOL	Categories DUE	Time Remaining
D201908000020 Rev 1 72 ENG1 Eff: 14-Jul-2026	Honeywell AS907 Oil Filter Analysis Program		T (A/R)		Service Information Letter	
		Mos				
		Hrs				
		Enc				
D201908000020 Rev 1 72 ENG2 Eff: 14-Jul-2026	Honeywell AS907 Oil Filter Analysis Program		T (A/R)		Service Information Letter	
		Mos				
		Hrs				
		Enc				
D202001000409 72 ENG1 Eff: 22-Jan-2020	Usage-Based MSP Program		T (A/R)		Service Information Letter	
		Mos				
		Hrs				
		Enc				
D202001000409 72 ENG2 Eff: 22-Jan-2020	Usage-Based MSP Program		T (A/R)		Service Information Letter	
		Mos				
		Hrs				
		Enc				
D202008001224 72 ENG1 Eff: 27-Aug-2020	Transition of No. 4 Carbon Seal Oil Pressure Bimodality Monitoring and Inspection Recommendations via Engine Health Monitoring Report (EHM) to CAMP		T (-)		Service Information Letter	
		Mos				
		Hrs				
		Enc				
D202008001224 72 ENG2 Eff: 27-Aug-2020	Transition of No. 4 Carbon Seal Oil Pressure Bimodality Monitoring and Inspection Recommendations via Engine Health Monitoring Report (EHM) to CAMP		T (-)		Service Information Letter	
		Mos				
		Hrs				
		Enc				
D202008001224 Rev 1 72 ENG1 Eff: 14-Jul-2026	Transition of No. 4 Carbon Seal Oil Pressure Bimodality Monitoring and Inspection Recommendations via Engine Health Monitoring Report (EHM) to CAMP		T (A/R)		Service Information Letter	
		Mos				
		Hrs				
		Enc				
D202008001224 Rev 1 72 ENG2 Eff: 14-Jul-2026	Transition of No. 4 Carbon Seal Oil Pressure Bimodality Monitoring and Inspection Recommendations via Engine Health Monitoring Report (EHM) to CAMP		T (A/R)		Service Information Letter	
		Mos				
		Hrs				
		Enc				
D202102001590 72 ENG1 Eff: 22-Feb-2021	Engine - Electronic Engine Interface (EEI) Software, Introduce EEI for Forge Download and Honeywell Forge Engine Data Viewer (EDV)		T (-)		Service Information Letter	
		Mos				
		Hrs				
		Enc				
D202102001590 72 ENG2 Eff: 22-Feb-2021	Engine - Electronic Engine Interface (EEI) Software, Introduce EEI for Forge Download and Honeywell Forge Engine Data Viewer (EDV)		T (-)		Service Information Letter	
		Mos				
		Hrs				
		Enc				
D202102001590 Rev 1 72 ENG1 Eff: 14-Apr-2021	Engine - Electronic Engine Interface (EEI) Software, Introduce EEI for Forge Download and Honeywell Forge Engine Data Viewer (EDV)		T (-)		Service Information Letter	
		Mos				
		Hrs				
		Enc				
D202102001590 Rev 1 72 ENG2 Eff: 14-Apr-2021	Engine - Electronic Engine Interface (EEI) Software, Introduce EEI for Forge Download and Honeywell Forge Engine Data Viewer (EDV)		T (-)		Service Information Letter	
		Mos				
		Hrs				
		Enc				
D202102001590 Rev 2 72 ENG1 Eff: 14-May-2021	Engine - Electronic Engine Interface (EEI) Software, Introduce EEI for Forge Download and Honeywell Forge Engine Data Viewer (EDV)		T (-)		Service Information Letter	
		Mos				
		Hrs				
		Enc				

Task No SEQ PN/SN	Description MOC Note	CW	REQ	TOL	Categories DUE	Time Remaining
D202102001590 Rev 2  72 ENG2 Eff: 14-May-2021	Engine - Electronic Engine Interface (EEI) Software, Introduce EEI for Forge Download and Honeywell Forge Engine Data Viewer (EDV)		T (-)		Service Information Letter	
		Mos				
		Hrs				
		Enc				
D202102001590 Rev 3  72 ENG1 Eff: 27-Jan-2022	Engine - Electronic Engine Interface (EEI) Software, Introduce EEI for Forge Download 1.6.0 and Honeywell Forge Engine Data Viewer (EDV)		T (-)		Service Information Letter	
		Mos				
		Hrs				
		Enc				
D202102001590 Rev 3  72 ENG2 Eff: 27-Jan-2022	Engine - Electronic Engine Interface (EEI) Software, Introduce EEI for Forge Download 1.6.0 and Honeywell Forge Engine Data Viewer (EDV)		T (-)		Service Information Letter	
		Mos				
		Hrs				
		Enc				
D202102001590 Rev 4  72 ENG1 Eff: 14-Nov-2022	Engine - Electronic Engine Interface (EEI) Software, Introduce EEI for Forge Download 1.6.0 and Honeywell Forge Engine Data Viewer (EDV)		T (-)		Service Information Letter	
		Mos				
		Hrs				
		Enc				
D202102001590 Rev 4  72 ENG2 Eff: 14-Nov-2022	Engine - Electronic Engine Interface (EEI) Software, Introduce EEI for Forge Download 1.6.0 and Honeywell Forge Engine Data Viewer (EDV)		T (-)		Service Information Letter	
		Mos				
		Hrs				
		Enc				
D202102001590 Rev 5  72 ENG1 Eff: 29-Jun-2023	Engine - Electronic Engine Interface (EEI) Software, Introduce EEI for Forge Download 1.8.0 and Honeywell Forge Engine Data Viewer (EDV)		T (A/R)		Service Information Letter	
		Mos				
		Hrs				
		Enc				
D202102001590 Rev 5  72 ENG2 Eff: 29-Jun-2023	Engine - Electronic Engine Interface (EEI) Software, Introduce EEI for Forge Download 1.8.0 and Honeywell Forge Engine Data Viewer (EDV)		T (A/R)		Service Information Letter	
		Mos				
		Hrs				
		Enc				
D202109001999  72 ENG1 Eff: 21-Sep-2021	AS907 Turbofan Engine Low Pressure Turbine Blade; Recommended Service Lives		T (A/R)		Service Information Letter	
		Mos				
		Hrs				
		Enc				
D202109001999  72 ENG2 Eff: 21-Sep-2021	AS907 Turbofan Engine Low Pressure Turbine Blade; Recommended Service Lives		T (A/R)		Service Information Letter	
		Mos				
		Hrs				
		Enc				
D202208002772  72 ENG1 Eff: 10-Aug-2022	AS907 Engine Thermal Anti-Ice Valve (TAIV) PN WBG3020G103-003		T (A/R)		Service Information Letter	
		Mos				
		Hrs				
		Enc				
D202208002772  72 ENG2 Eff: 10-Aug-2022	AS907 Engine Thermal Anti-Ice Valve (TAIV) PN WBG3020G103-003		T (A/R)		Service Information Letter	
		Mos				
		Hrs				
		Enc				
D202306004018  72 ENG1 Eff: 22-Jun-2023	Honeywell Service Bulletin AS907-76-9014 for AS907-2-1G Model Engines Used on Gulfstream G280 Aircraft and an Impending Federal Aviation Administration (FAA) Airworthiness Directive (AD)		T (A/R)		Service Information Letter	
		Mos				
		Hrs				
		Enc				

Task No	Description				CW	REQ	TOL	Categories	Time
SEQ	PN/SN	MOC Note						DUE	Remaining
D202306004018		Honeywell Service Bulletin AS907-76-9014 for AS907-2-1G Model Engines Used on Gulfstream G280 Aircraft and an Impending Federal Aviation Administration (FAA) Airworthiness Directive (AD)						T (A/R)	Service Information Letter
 72 ENG2 Eff: 22-Jun-2023					Mos				
					Hrs				
					Enc				
D202511005107		Additional Maintenance Requirements for Non-Serviceable AS907 Model Engines Awaiting Maintenance						T (A/R)	Service Information Letter
 72 ENG1 Eff: 19-Nov-2025					Mos				
					Hrs				
					Enc				
D202511005107		Additional Maintenance Requirements for Non-Serviceable AS907 Model Engines Awaiting Maintenance						T (A/R)	Service Information Letter
 72 ENG2 Eff: 19-Nov-2025					Mos				
					Hrs				
					Enc				
D202602005170		Engine - New Electronic Engine Interface (EEI) Software Version 2.0.0.						T (A/R)	Service Information Letter
 72 ENG1 Eff: 16-Feb-2026					Mos				
					Hrs				
					Enc				
D202602005170		Engine - New Electronic Engine Interface (EEI) Software Version 2.0.0.						T (A/R)	Service Information Letter
 72 ENG2 Eff: 16-Feb-2026					Mos				
					Hrs				
					Enc				
▼ 73 - ENGINE - FUEL AND CONTROL									
2023-24-04		Engine Fuel and Control - Electronic Control Unit (ECU) Software Version - Replacement						RE (-)	Mandatory
 73 ENG1 Eff: 10-Jan-2024 Not Applicable (UPDATE NOTE: N/A as per installed ECU on OK_GTX)					Mos	24-Jan-2024			
					Hrs				
					Enc				
2023-24-04		Engine Fuel and Control - Electronic Control Unit (ECU) Software Version - Replacement						RE (-)	Mandatory
 73 ENG2 Eff: 10-Jan-2024 Not Applicable (UPDATE NOTE: N/A as per installed ECU on OK_GTX)					Mos	24-Jan-2024			
					Hrs				
					Enc				
2023-24-04 Par. (g)(2)		Engine Fuel and Control - Electronic Control Unit (ECU) Software Version - Replacement - Model AS907-2-1G Engines						RE (-)	Mandatory
 73 ENG1 Eff: 10-Jan-2024 Not Applicable (UPDATE NOTE: N/A as per installed ECU on OK_GTX)					Mos	24-Jan-2024			
					Hrs				
					Enc				
2023-24-04 Par. (g)(2)		Engine Fuel and Control - Electronic Control Unit (ECU) Software Version - Replacement - Model AS907-2-1G Engines						RE (-)	Mandatory
 73 ENG2 Eff: 10-Jan-2024 Not Applicable (UPDATE NOTE: N/A as per installed ECU on OK_GTX)					Mos	24-Jan-2024			
					Hrs				
					Enc				
442650-73-0001		Engine Fuel and Control - Model FH-C6 Hydromechanical Unit - Incorporation of New Main Body Assembly with Fuel Vent Plug to the PX2 Fuel Pressure Port						RE (-)	Recommended
 73 ENG1 Eff: 11-Feb-2019 Not Applicable	HMU 442650 not installed				Mos	14-Apr-2023			
					Hrs	87:53			
					Enc	56			
442650-73-0001		Engine Fuel and Control - Model FH-C6 Hydromechanical Unit - Incorporation of New Main Body Assembly with Fuel Vent Plug to the PX2 Fuel Pressure Port						RE (-)	Recommended
 73 ENG2 Eff: 11-Feb-2019 Not Applicable	HMU 442650 not installed				Mos	14-Apr-2023			
					Hrs	107:53			
					Enc	68			
442661-73-0001		ENGINE FUEL AND CONTROL - MODEL FH-C3 HYDROMECHANICAL UNIT (HMU) - Replacement of the Metering Valve Assembly With One Having a Larger Metered Flow Window For Increased Flow						T (A/R)	
 73 ENG1 Eff: 05-Apr-2017					Mos				
					Hrs				
					Enc				

Task No SEQ PN/SN	Description MOC Note	CW	REQ	TOL	Categories DUE	Time Remaining
442661-73-0001	ENGINE FUEL AND CONTROL - MODEL FH-C3 HYDROMECHANICAL UNIT (HMU) - Replacement of the Metering Valve Assembly With One Having a Larger Metered Flow Window For Increased Flow		T (A/R)			
 73 ENG2 Eff: 05-Apr-2017		Mos				
		Hrs				
		Enc				
442661-73-0002	Engine Fuel and Control - Model FH-C3 Hydromechanical Unit (HMU) (HFT 7000) - Incorporation of New Main Fuel Pump Assembly		RE (-)		Recommended	
 73 ENG1 Eff: 17-Jan-2019 Not Applicable	fuel pump PN 82011224-001 installed	Mos	14-Apr-2023			
		Hrs	87:53			
		Enc	56			
442661-73-0002	Engine Fuel and Control - Model FH-C3 Hydromechanical Unit (HMU) (HFT 7000) - Incorporation of New Main Fuel Pump Assembly		RE (-)		Recommended	
 73 ENG2 Eff: 17-Jan-2019 Not Applicable	fuel pump PN 82011224-001 installed	Mos	14-Apr-2023			
		Hrs	107:53			
		Enc	68			
AS907-73-9005	ENGINE FUEL AND CONTROL - CONTROLLING SECTION - Replace Non-Conforming Main Fuel Control PN 442324 with PN 442661 on AS907-2-1G Model Engines		RE (-)			
 73 ENG1 Eff: 14-Apr-2017 Not Applicable	PER ENGINE PART NUMBER	Mos	10-Feb-2023			
		Hrs				
		Enc				
AS907-73-9005	ENGINE FUEL AND CONTROL - CONTROLLING SECTION - Replace Non-Conforming Main Fuel Control PN 442324 with PN 442661 on AS907-2-1G Model Engines		RE (-)			
 73 ENG2 Eff: 14-Apr-2017 Not Applicable	PER ENGINE PART NUMBER	Mos	10-Feb-2023			
		Hrs				
		Enc				
AS907-73-9007	Engine Fuel and Control - Distribution - Replace Non-Conforming Fuel Hose Assemblies on AS907 Engine Models		RE (-)		Cat.2-Reliability	
 73 ENG1 Eff: 14-Aug-2018 Not Applicable	PER ENGINE PART NUMBER	Mos	10-Feb-2023			
		Hrs				
		Enc				
AS907-73-9007	Engine Fuel and Control - Distribution - Replace Non-Conforming Fuel Hose Assemblies on AS907 Engine Models		RE (-)		Cat.2-Reliability	
 73 ENG2 Eff: 14-Aug-2018 Not Applicable	PER ENGINE PART NUMBER	Mos	10-Feb-2023			
		Hrs				
		Enc				
▼ 75 - BLEED AIR						
AS907-75-9005	Air - Cooling - Install New Buffer Air Metal Tube Assemblies PN 70040490-1 for AS907 Model Engines		RE (-)		Cat.3-Product Improvement	
 75 ENG1 Eff: 05-Sep-2018 Not Applicable	PER ENGINE PART NUMBER	Mos	10-Feb-2023			
		Hrs				
		Enc				
AS907-75-9005	Air - Cooling - Install New Buffer Air Metal Tube Assemblies PN 70040490-1 for AS907 Model Engines		RE (-)		Cat.3-Product Improvement	
 75 ENG2 Eff: 05-Sep-2018 Not Applicable	PER ENGINE PART NUMBER	Mos	10-Feb-2023			
		Hrs				
		Enc				
▼ 76 - ENGINE CONTROLS						
2018-04-13 Par. (g)(1)(i)	Engine Controls Section - Engine Electronic Control Unit (ECU) - Apply Sealant (Terminating Action)		RE (-)		Mandatory	
 76 ENG1 Eff: 12-Apr-2018 Not Applicable		Mos	10-Feb-2023			
		Hrs				
		Enc				

Task No	Description				Categories	Time		
SEQ	PN/SN	MOC Note		CW	REQ	TOL	DUE	Remaining
2018-04-13 Par. (g)(1)(i)		Engine Controls Section - Engine Electronic Control Unit (ECU) - Apply Sealant (Terminating Action)			RE (-)		Mandatory	
	76 ENG2		Mos	10-Feb-2023				
	Eff: 12-Apr-2018 Not Applicable		Hrs					
			Enc					
2018-04-13 Par. (g)(2)(i)		Engine Controls Section - Engine Electronic Control Unit (ECU) - Revise AFM			RE (-)		Mandatory	
	76 ENG1		Mos	10-Feb-2023				
	Eff: 12-Apr-2018 Not Applicable		Hrs					
			Enc					
2018-04-13 Par. (g)(2)(i)		Engine Controls Section - Engine Electronic Control Unit (ECU) - Revise AFM			RE (-)		Mandatory	
	76 ENG2		Mos	10-Feb-2023				
	Eff: 12-Apr-2018 Not Applicable		Hrs					
			Enc					
2119576-76-4181		ENGINE CONTROLS - POWER CONTROLS - Modify the Electronic Control Unit (ECU) From PN 2119576-3001 to PN 2119576-3002			T (A/R)			
	76 ENG1		Mos					
	Eff: 15-Aug-2014		Hrs					
			Enc					
2119576-76-4181		ENGINE CONTROLS - POWER CONTROLS - Modify the Electronic Control Unit (ECU) From PN 2119576-3001 to PN 2119576-3002			T (A/R)			
	76 ENG2		Mos					
	Eff: 15-Aug-2014		Hrs					
			Enc					
2119576-76-4181 Rev 1		ENGINE CONTROLS - POWER CONTROLS - Modify the Electronic Control Unit (ECU) From PN 2119576-3001 to PN 2119576-3002			T (A/R)			
	76 ENG1		Mos	10-Feb-2023				
	Eff: 18-Sep-2014 Not Applicable	PER ECU PART NUMBER, incorporated in production	Hrs					
			Enc					
2119576-76-4181 Rev 1		ENGINE CONTROLS - POWER CONTROLS - Modify the Electronic Control Unit (ECU) From PN 2119576-3001 to PN 2119576-3002			RE (-)			
	76 ENG2		Mos	10-Feb-2023				
	Eff: 18-Sep-2014 Not Applicable	PER ECU PART NUMBER, incorporated in production	Hrs					
			Enc					
2119576-76-4182		Engine Controls - Power Controls - Modify the Electronic Control Unit (ECU) from PN 2119576-3001 or 2119576-3002 to PN 2119576-1013 after Software Update			RE (-)		Category 3, Optional	
	76 ENG1		Mos	26-Feb-2025				
	Eff: 20-Sep-2024 Not Applicable		Hrs					
	(UPDATE NOTE: Modify per SB I2119576-76-4181 Rev 1 - PER ECU PART NUMBER, incorporated in production)		Enc					
2119576-76-4182		Engine Controls - Power Controls - Modify the Electronic Control Unit (ECU) from PN 2119576-3001 or 2119576-3002 to PN 2119576-1013 after Software Update			RE (-)		Category 3, Optional	
	76 ENG2		Mos	26-Feb-2025				
	Eff: 20-Sep-2024 Not Applicable		Hrs					
	(UPDATE NOTE: Modify per SB I2119576-76-4181 Rev 1 - PER ECU PART NUMBER, incorporated in production)		Enc					
280-76-089		Engine Controls - Replacement Of The Existing Throttle Quadrant Assembly P/N 30P551100003-001 With New Throttle Quadrant Assembly P/N 30P551100004-001 (MODG25-20051)			RE (-)		Recommended	
	76 A/F		Mos	10-Feb-2023				
	Eff: 19-Jun-2014 Not Applicable	PER AIRCRAFT SERIAL NUMBER	Hrs	24:24				
			Ldg	7				
280-76-111		Engine Controls - Power Controls - Install Software Version 90721G0201 In Engine Electronic Control Unit (ECU) (MODG25-20061)			RE (-)		Recommended	
	76 A/F		Mos	10-Feb-2023				
	Eff: 17-Jan-2014 Not Applicable	PER AIRCRAFT SERIAL NUMBER	Hrs	24:24				
			Ldg	7				

Task No		Description				Categories	Time
SEQ	PN/SN	MOC Note	CW	REQ	TOL	DUE	Remaining
280-76-128		Engine Controls (ATA 76) - Power Controls - Install Improved Electronic Control Unit (ECU) P/N 2119576-3202 on AS907-2-1G Model Engines		RE (-)		Optional	
	76 A/F		Mos				
	Eff: 06-Oct-2020		Hrs				
			Ldg				
280-76-128 Rev 1		Engine Controls - Power Controls - Install Improved Electronic Control Unit (ECU) P/N 2119576-3202 on AS907-2-1G Model Engines		RE (-)		Optional	
	76 A/F		Mos	10-Oct-2024			
	Eff: 21-Feb-2023 Not Applicable		Hrs				
	(UPDATE NOTE: N/A by SN of the aircraft , ALLREADY NSTALLED IMPROVED ELECTRONIC CONTROL UNIT (ECU) P/N 2119576-3202 ON AS907-2-1G)		Ldg				
280-76-128 Rev 2		Engine Controls (ATA 76), Power Controls - Install Improved Electronic Control Unit (ECU) P/N 2119576-3202 on AS907-2-1G Model Engines		RE (-)		Recommended	
	76 A/F		Mos	10-Jul-2025			
	Eff: 07-Oct-2024 Not Applicable		Hrs				
			Ldg				
280-76-128 Rev 3		Engine Controls (ATA 76), Power Controls - Install Improved Electronic Control Unit (ECU) P/N 2119576-3202 on AS907-2-1G Model Engines		RE (-)		Recommended	
	76 A/F		Mos	10-Jul-2025			
	Eff: 22-May-2025 Not Applicable		Hrs				
			Ldg				
280-76-219 (Left)		Engine Controls - Power Controls - Replacement of the Overspeed Shutoff Detector (OSSD) P/N 3034256-2 With New OSSD P/N 3034256-4		RE (-)		Recommended	
	76 A/F		Mos	10-Feb-2023			
	Eff: 19-Feb-2016 Not Applicable	PER AIRCRAFT SERIAL NUMBER	Hrs	24:24			
			Ldg	7			
280-76-219 (Right)		Engine Controls - Power Controls - Replacement of the Overspeed Shutoff Detector (OSSD) P/N 3034256-2 With New OSSD P/N 3034256-4		RE (-)		Recommended	
	76 A/F		Mos	10-Feb-2023			
	Eff: 19-Feb-2016 Not Applicable	PER AIRCRAFT SERIAL NUMBER	Hrs	24:24			
			Ldg	7			
280-76-232		Engine Controls - Power Controls - Apply Sealant to Prevent Water Entry Into Electronic Control Unit (ECU) on AS907 Model Engines		RE (-)		Mandatory	
	76 ENG1		Mos	10-Feb-2023			
	Eff: 13-May-2016 Not Applicable	PER AIRCRAFT SERIAL NUMBER	Hrs				
			Enc				
280-76-232		Engine Controls - Power Controls - Apply Sealant to Prevent Water Entry Into Electronic Control Unit (ECU) on AS907 Model Engines		RE (-)		Mandatory	
	76 ENG2		Mos	17-Apr-2023			
	Eff: 13-May-2016 Not Applicable	as per a/c S/N	Hrs	117:47			
			Enc	76			
280-76-267		Throttle Quadrant Assembly (TQA) - Replacement / Upgrade		RE (-)		Recommended	
	76 A/F		Mos	10-Feb-2023			
	Eff: 22-Feb-2019 Not Applicable	PER AIRCRAFT SERIAL NUMBER	Hrs				
			Ldg				
540-1796-76-0001		ENGINE CONTROLS - SOLENOID OPERATED BLEED VALVE - Replace the Solenoid Assembly PN 540-1817-1 with PN 80000152-001		T (A/R)			
	76 ENG1		Mos				
	Eff: 06-Apr-2017		Hrs				
			Enc				
540-1796-76-0001		ENGINE CONTROLS - SOLENOID OPERATED BLEED VALVE - Replace the Solenoid Assembly PN 540-1817-1 with PN 80000152-001		T (A/R)			
	76 ENG2		Mos				
	Eff: 06-Apr-2017		Hrs				
			Enc				

Task No	Description	CW	REQ	TOL	Categories	Time
SEQ PN/SN	MOC Note				DUE	Remaining
540-1798-76-0001	ENGINE CONTROLS - SOLENOID OPERATED BLEED VALVE - Replace the Solenoid Assembly PN 540-1839-1 with PN 80000153-001		T (A/R)			
 76 ENG1		Mos				
Eff: 06-Apr-2017		Hrs				
		Enc				
540-1798-76-0001	ENGINE CONTROLS - SOLENOID OPERATED BLEED VALVE - Replace the Solenoid Assembly PN 540-1839-1 with PN 80000153-001		T (A/R)			
 76 ENG2		Mos				
Eff: 06-Apr-2017		Hrs				
		Enc				
76-9016	ENGINE CONTROLS - POWER CONTROLS - INSTALL SOFTWARE VERSION 90721G0201 IN ELECTRONIC CONTROL UNIT (ECU)		T (A/R)			
 76 ENG1		Mos				
Eff: 24-Jul-2013		Hrs				
		Enc				
76-9016	ENGINE CONTROLS - POWER CONTROLS - INSTALL SOFTWARE VERSION 90721G0201 IN ELECTRONIC CONTROL UNIT (ECU)		T (A/R)			
 76 ENG2		Mos				
Eff: 24-Jul-2013		Hrs				
		Enc				
76-9016 Rev 1	ENGINE CONTROLS - POWER CONTROLS - INSTALL SOFTWARE VERSION 90721G0201 IN ELECTRONIC CONTROL UNIT (ECU)		RE (-)			
 76 ENG1		Mos	26-Jan-2023			
Eff: 03-Dec-2013 Complied	AT MANUFACTURE	Hrs	0			
With		Enc	0			
76-9016 Rev 1	ENGINE CONTROLS - POWER CONTROLS - INSTALL SOFTWARE VERSION 90721G0201 IN ELECTRONIC CONTROL UNIT (ECU)		RE (-)			
 76 ENG2		Mos	20-Jan-2023			
Eff: 03-Dec-2013 Complied	AT MANUFACTURE	Hrs	0			
With		Enc	0			
AS907-76-9014	ENGINE CONTROLS - POWER CONTROLS - Install Improved Electronic Control Unit (ECU) PN 2119576-3102 on AS907-2-1G Model Engines		RE (-)			
 76 ENG1		Mos	10-Feb-2023			
Eff: 24-Jan-2017 Not	PER ENGINE PART NUMBER	Hrs				
Applicable		Enc				
AS907-76-9014	ENGINE CONTROLS - POWER CONTROLS - Install Improved Electronic Control Unit (ECU) PN 2119576-3102 on AS907-2-1G Model Engines		RE (-)			
 76 ENG2		Mos	10-Feb-2023			
Eff: 24-Jan-2017 Not	PER ENGINE PART NUMBER	Hrs				
Applicable		Enc				
AS907-76-9014 Rev 1	ENGINE CONTROLS - POWER CONTROLS - Install Improved Electronic Control Unit (ECU) PN 2119576-3102 on AS907-2-1G Model Engines		T (-)			
 76 ENG1		Mos				
Eff: 08-Sep-2017		Hrs				
		Enc				
AS907-76-9014 Rev 1	ENGINE CONTROLS - POWER CONTROLS - Install Improved Electronic Control Unit (ECU) PN 2119576-3102 on AS907-2-1G Model Engines		T (-)			
 76 ENG2		Mos				
Eff: 08-Sep-2017		Hrs				
		Enc				
AS907-76-9014 Rev 2	Engine Controls - Power Controls - Install Improved Electronic Control Unit (ECU), PN 2119576-3102 or 2119576-3202, on AS907-2-1G Model Engines		RE (-)		Cat.3-Product Improvement	
 76 ENG1		Mos	10-Feb-2023			
Eff: 30-Jan-2018 Not Applicable		Hrs				
(UPDATE NOTE: NA by ENG Part Number)		Enc				
AS907-76-9014 Rev 2	Engine Controls - Power Controls - Install Improved Electronic Control Unit (ECU), PN 2119576-3102 or 2119576-3202, on AS907-2-1G Model Engines		RE (-)		Cat.3-Product Improvement	
 76 ENG2		Mos	10-Feb-2023			
Eff: 30-Jan-2018 Not Applicable		Hrs				
(UPDATE NOTE: NA by ENG Part Number)		Enc				

Task No SEQ PN/SN	Description MOC Note		CW	REQ	TOL	Categories	Time
						DUE	Remaining
AS907-76-9014 Rev 3 76 ENG1 Eff: 22-Nov-2019	Engine Controls - Power Controls - Install Improved Electronic Control Unit (ECU), PN 2119576-3102 or 2119576-3202, on AS907-2-1G Model Engines					RE (-)	Category 3, Optional
		Mos					
		Hrs					
		Enc					
AS907-76-9014 Rev 3 76 ENG2 Eff: 22-Nov-2019	Engine Controls - Power Controls - Install Improved Electronic Control Unit (ECU), PN 2119576-3102 or 2119576-3202, on AS907-2-1G Model Engines					RE (-)	Category 3, Optional
		Mos					
		Hrs					
		Enc					
AS907-76-9014 Rev 4 76 ENG1 Eff: 04-Aug-2020 Not Applicable	Engine Controls - Power Controls - Install Improved Electronic Control Unit (ECU), PN 2119576-3102 or 2119576-3202, on AS907-2-1G Model Engines as per engine S/N					RE (-)	Category 2
		Mos	17-Apr-2023				
		Hrs	97:47				
		Enc	64				
AS907-76-9014 Rev 4 76 ENG2 Eff: 04-Aug-2020 Not Applicable	Engine Controls - Power Controls - Install Improved Electronic Control Unit (ECU), PN 2119576-3102 or 2119576-3202, on AS907-2-1G Model Engines as per engine S/N					RE (-)	Category 2
		Mos	17-Apr-2023				
		Hrs	117:47				
		Enc	76				
AS907-76-9014 Rev 5 76 ENG1 Eff: 09-Sep-2022 Not Applicable	Engine Controls - Power Controls - Install Improved Electronic Control Unit (ECU), PN 2119576-3102 or 2119576-3202, on AS907-2-1G Model Engines as per engine S/N					RE (-)	Category 2, Recommended
		Mos	17-Apr-2023				
		Hrs	97:47				
		Enc	64				
AS907-76-9014 Rev 5 76 ENG2 Eff: 09-Sep-2022 Not Applicable	Engine Controls - Power Controls - Install Improved Electronic Control Unit (ECU), PN 2119576-3102 or 2119576-3202, on AS907-2-1G Model Engines as per engine S/N					RE (-)	Category 2, Recommended
		Mos	17-Apr-2023				
		Hrs	117:47				
		Enc	76				
AS907-76-9014 Rev 6 76 ENG1 Eff: 10-Oct-2022 Not Applicable	Engine Controls - Power Controls - Install Improved Electronic Control Unit (ECU), PN 2119576-3102 or 2119576-3202, on AS907-2-1G Model Engines per S/N					RE (-)	Cat. 2 - Recommended
		Mos	10-Apr-2023				
		Hrs	84:18				
		Enc	54				
AS907-76-9014 Rev 6 76 ENG2 Eff: 10-Oct-2022 Not Applicable	Engine Controls - Power Controls - Install Improved Electronic Control Unit (ECU), PN 2119576-3102 or 2119576-3202, on AS907-2-1G Model Engines per S/N					RE (-)	Cat. 2 - Recommended
		Mos	10-Apr-2023				
		Hrs	104:18				
		Enc	66				
AS907-76-9015 76 ENG1 Eff: 09-Dec-2016 Not Applicable	ENGINE CONTROLS - EMERGENCY SHUTDOWN - Replace Bracket PN 3038418-14 With PN 70040451-2 on AS907 Model Engines PER S/N, incorporated in Production					RE (-)	
		Mos	10-Feb-2023				
		Hrs					
		Enc					
AS907-76-9015 76 ENG2 Eff: 09-Dec-2016 Not Applicable	ENGINE CONTROLS - EMERGENCY SHUTDOWN - Replace Bracket PN 3038418-14 With PN 70040451-2 on AS907 Model Engines PER S/N, incorporated in Production					RE (-)	
		Mos	10-Feb-2023				
		Hrs					
		Enc					
AS907-76-9017 76 ENG1 Eff: 08-Jan-2016 Not Applicable	ENGINE CONTROLS - EMERGENCY SHUTDOWN - Replace Potentially Non-Conforming Overspeed Shutoff Detector (OSSD) on AS907 Engines PER S/N. INCORPORATED IN PRODUCTION					RE (-)	Service Bulletin
		Mos	10-Feb-2023				
		Hrs					
		Enc					

Task No		Description		CW	REQ	TOL	Categories	
SEQ	PN/SN	MOC	Note				DUE	Time Remaining
AS907-76-9017		ENGINE CONTROLS - EMERGENCY SHUTDOWN - Replace Potentially Non-Conforming Overspeed Shutoff Detector (OSSD) on AS907 Engines				RE (-)	Service Bulletin	
	76 ENG2			Mos	10-Feb-2023			
	Eff: 08-Jan-2016 Not Applicable		PER S/N. INCORPORATED IN PRODUCTION	Hrs				
				Enc				
AS907-76-9018		ENGINE CONTROLS - EMERGENCY SHUTDOWN - New Alternate Overspeed Shutoff Detector (OSSD) on AS907 Engine Models				T (A/R)		
	76 ENG1			Mos				
	Eff: 23-Jan-2015			Hrs				
				Enc				
AS907-76-9018		ENGINE CONTROLS - EMERGENCY SHUTDOWN - New Alternate Overspeed Shutoff Detector (OSSD) on AS907 Engine Models				T (A/R)		
	76 ENG2			Mos				
	Eff: 23-Jan-2015			Hrs				
				Enc				
AS907-76-9018 Rev 1		ENGINE CONTROLS - EMERGENCY SHUTDOWN - New Alternate Overspeed Shutoff Detector (OSSD) on AS907 Engine Models				RE (-)		
	76 ENG1			Mos	26-Jan-2023			
	Eff: 09-Nov-2015 Complied With	AT MANUFACTURE		Hrs	0			
				Enc	0			
AS907-76-9018 Rev 1		ENGINE CONTROLS - EMERGENCY SHUTDOWN - New Alternate Overspeed Shutoff Detector (OSSD) on AS907 Engine Models				RE (-)		
	76 ENG2			Mos	20-Jan-2023			
	Eff: 09-Nov-2015 Complied With	AT MANUFACTURE		Hrs	0			
				Enc	0			
AS907-76-9021		SB AS907-76-9021 - Apply Sealant to Prevent Water Entry Into Electronic Control Unit (ECU) on AS907 Model Engines				T (A/R)		
	76 ENG1			Mos				
	Eff: 13-May-2016			Hrs				
				Enc				
AS907-76-9021		SB AS907-76-9021 - Apply Sealant to Prevent Water Entry Into Electronic Control Unit (ECU) on AS907 Model Engines				T (A/R)		
	76 ENG2			Mos				
	Eff: 13-May-2016			Hrs				
				Enc				
AS907-76-9021 Rev 1		ENGINE CONTROLS - POWER CONTROLS - Apply Sealant to Prevent Water Entry into Electronic Control Unit (ECU) on AS907 Model Engines				RE (-)	Service Bulletin	
	76 ENG1			Mos	26-Jan-2023			
	Eff: 13-May-2016 Complied With	AT MANUFACTURE		Hrs	0			
				Enc	0			
AS907-76-9021 Rev 1		ENGINE CONTROLS - POWER CONTROLS - Apply Sealant to Prevent Water Entry into Electronic Control Unit (ECU) on AS907 Model Engines				RE (-)	Service Bulletin	
	76 ENG2			Mos	20-Jan-2023			
	Eff: 13-May-2016 Complied With	AT MANUFACTURE		Hrs	0			
				Enc	0			
AS907-76-9023		Engine Controls - Power Controls - Install New Anti-Ice Dual Pressure Switch Bracket, P/N 3038453-8, on AS907 Model Engines				RE (-)	Cat.3-Product Improvement	
	76 ENG1			Mos	17-Apr-2023			
	Eff: 20-Dec-2017 Not Applicable	as per engine S/N		Hrs	97:47			
				Enc	64			
AS907-76-9023		Engine Controls - Power Controls - Install New Anti-Ice Dual Pressure Switch Bracket, P/N 3038453-8, on AS907 Model Engines				RE (-)	Cat.3-Product Improvement	
	76 ENG2			Mos	17-Apr-2023			
	Eff: 20-Dec-2017 Not Applicable	as per engine S/N		Hrs	117:47			
				Enc	76			

Task No	Description		CW	REQ	TOL	Categories	Time
SEQ	PN/SN	MOC Note				DUE	Remaining
AS907-76-9023 Rev 1	Engine Controls - Power Controls - Install New Anti-Ice Dual Pressure Switch Bracket, PN 3038453-8, on AS907 Model Engines					RE (-)	Category 3, Optional
76 ENG1			Mos	26-Jan-2023			
Eff: 13-May-2020 Complied With	AT MANUFACTURE		Hrs	0			
			Enc	0			
AS907-76-9023 Rev 1	Engine Controls - Power Controls - Install New Anti-Ice Dual Pressure Switch Bracket, PN 3038453-8, on AS907 Model Engines					RE (-)	Category 3, Optional
76 ENG2			Mos	20-Jan-2023			
Eff: 13-May-2020 Complied With	AT MANUFACTURE		Hrs	0			
			Enc	0			
AS907-76-9024	Engine Controls - Power Controls - New P3 Tube Assemblies PN 3038480-4 and PN 3038481-4 on AS907 Model Engines					RE (-)	Category 3, Optional
76 ENG1			Mos	26-Jan-2023			
Eff: 11-Feb-2019 Complied With	AT MANUFACTURE		Hrs	0			
			Enc	0			
AS907-76-9024	Engine Controls - Power Controls - New P3 Tube Assemblies PN 3038480-4 and PN 3038481-4 on AS907 Model Engines					RE (-)	Category 3, Optional
76 ENG2			Mos	20-Jan-2023			
Eff: 11-Feb-2019 Complied With	AT MANUFACTURE		Hrs	0			
			Enc	0			
AS907-76-9025	Install Improved Electronic Control Units on AS907 Model Engines					RE (-)	Cat.3-Product Improvement
76 ENG1			Mos	26-Jan-2023			
Eff: 18-Apr-2018 Complied With	AT MANUFACTURE		Hrs	0			
			Enc	0			
AS907-76-9025	Install Improved Electronic Control Units on AS907 Model Engines					RE (-)	Cat.3-Product Improvement
76 ENG2			Mos	20-Jan-2023			
Eff: 18-Apr-2018 Complied With	AT MANUFACTURE		Hrs	0			
			Enc	0			
AS907-76-9032	Engine Controls - Power Controls - Tube Assembly, Metal P3 Air TEE to Channel A PN 3038480-4 and Tube Assembly, Metal P3 Air TEE to Channel B PN 3038481-4 - Optional Removal of MIL-STD-1247 Function Tape as Necessary					RE (-)	Category 3, Optional
76 ENG1			Mos				
Eff: 15-Apr-2021			Hrs				
			Enc				
AS907-76-9032	Engine Controls - Power Controls - Tube Assembly, Metal P3 Air TEE to Channel A PN 3038480-4 and Tube Assembly, Metal P3 Air TEE to Channel B PN 3038481-4 - Optional Removal of MIL-STD-1247 Function Tape as Necessary					RE (-)	Category 3, Optional
76 ENG2			Mos				
Eff: 15-Apr-2021			Hrs				
			Enc				
AS907-76-9033	Engine Controls - Power Controls - Inspect W3 Wiring Harness for Possible Interference with the Nacelle Hold Open Rod, Repositioning of Bracket and Install Chafing Tape or Chafing Sleeve on Harness					RE (-)	Category 2, Recommended
76 ENG1			Mos	10-Jul-2025			
Eff: 23-Jan-2025 Not Applicable			Hrs				
(UPDATE NOTE: NA by SN of the engines)			Enc				
AS907-76-9033	Engine Controls - Power Controls - Inspect W3 Wiring Harness for Possible Interference with the Nacelle Hold Open Rod, Repositioning of Bracket and Install Chafing Tape or Chafing Sleeve on Harness					RE (-)	Category 2, Recommended
76 ENG2			Mos	10-Jul-2025			
Eff: 23-Jan-2025 Not Applicable			Hrs				
(UPDATE NOTE: NA by SN of the engines)			Enc				
AS907-76-9033 Rev 1	Engine Controls - Power Controls - Inspect W3 Wiring Harness for Possible Interference with the Nacelle Hold Open Rod, Repositioning of Bracket and Install Chafing Tape or Chafing Sleeve on Harness					RE (-)	Category 2, Recommended
76 ENG1			Mos	10-Jul-2025			
Eff: 18-Jun-2025 Not Applicable			Hrs				
(UPDATE NOTE: NA by SN of the engines)			Enc				

Task No		Description				CW	REQ	TOL	Categories	Time
SEQ	PN/SN	MOC Note							DUE	Remaining
AS907-76-9033 Rev 1		Engine Controls - Power Controls - Inspect W3 Wiring Harness for Possible Interference with the Nacelle Hold Open Rod, Repositioning of Bracket and Install Chafing Tape or Chafing Sleeve on Harness						RE (-)	Category 2, Recommended	
	76 ENG2 Eff: 18-Jun-2025 Not Applicable (UPDATE NOTE: NA by SN of the engines)					Mos	10-Jul-2025			
						Hrs				
						Enc				
AS907-76-9035		Engine Controls - Power Controls - Modify the Electronic Control Unit (ECU) from PN 2119576-3001 or 2119576-3002 to PN 2119576-1013 After Software Update						T (A/R)	Category 3	
	76 ENG1 Eff: 08-Aug-2025					Mos				
						Hrs				
						Enc				
AS907-76-9035		Engine Controls - Power Controls - Modify the Electronic Control Unit (ECU) from PN 2119576-3001 or 2119576-3002 to PN 2119576-1013 After Software Update						T (A/R)	Category 3	
	76 ENG2 Eff: 08-Aug-2025					Mos				
						Hrs				
						Enc				
D202401004213		A Discussion Regarding the AS907 Wire Harnesses; Issue and Investigation						T (A/R)	Service Information Letter	
	76 ENG1 Eff: 02-Feb-2024					Mos				
						Hrs				
						Enc				
D202401004213		A Discussion Regarding the AS907 Wire Harnesses; Issue and Investigation						T (A/R)	Service Information Letter	
	76 ENG2 Eff: 02-Feb-2024					Mos				
						Hrs				
						Enc				
▼ 77 - ENGINE INDICATING										
AS907-77-9001		ENGINE INDICATING - TEMPERATURE - Replace Brackets PN 3038418-13 and PN 3038418-15 With PN 70040328-2 on AS907 Model Engines						RE (-)		
	77 ENG1 Eff: 12-Dec-2016 Not Applicable	PER S/N, incorporated in Production				Mos	10-Feb-2023			
						Hrs				
						Enc				
AS907-77-9001		ENGINE INDICATING - TEMPERATURE - Replace Brackets PN 3038418-13 and PN 3038418-15 With PN 70040328-2 on AS907 Model Engines						RE (-)		
	77 ENG2 Eff: 12-Dec-2016 Not Applicable	PER S/N, incorporated in Production				Mos	10-Feb-2023			
						Hrs				
						Enc				
AS907-77-9002		Engine Indicating - Vibration - Install a Bracket, PN MS9593-562, and Loop Clamp, PN 211-592-9004, to Hold the Cable of the Vibration Sensor Transducer on AS907 Model Engines						RE (-)	Cat.3-Product Improvement	
	77 ENG1 Eff: 23-Jan-2019 Not Applicable	as per engine S/N				Mos	17-Apr-2023			
						Hrs	97:47			
						Enc	64			
AS907-77-9002		Engine Indicating - Vibration - Install a Bracket, PN MS9593-562, and Loop Clamp, PN 211-592-9004, to Hold the Cable of the Vibration Sensor Transducer on AS907 Model Engines						RE (-)	Cat.3-Product Improvement	
	77 ENG2 Eff: 23-Jan-2019 Not Applicable	as per engine S/N				Mos	17-Apr-2023			
						Hrs	117:47			
						Enc	76			
▼ 78 - EXHAUST										
280-78-022		Exhaust - Thrust Reverser (TR) - Pivot Door Kicker Plate Modification / Strap Repair (MODG25-00222)						RE (-)	Recommended	
	78 A/F Eff: 12-Dec-2014 Not Applicable	PER AIRCRAFT SERIAL NUMBER				Mos	10-Feb-2023			
						Hrs	24:24			
						Ldg	7			

Task No	Description		CW	REQ	TOL	Categories	Time
SEQ	PN/SN	MOC Note				DUE	Remaining
D202107001885		Aircraft Nacelle Thrust Reverser Unit (TRU) - Use of Non-Honeywell Authorized Corrosion Repairs and Prevention Systems		T (A/R)		Service Information Letter	
	 78 ENG1		Mos				
	Eff: 26-Jul-2021		Hrs				
			Enc				
D202107001885		Aircraft Nacelle Thrust Reverser Unit (TRU) - Use of Non-Honeywell Authorized Corrosion Repairs and Prevention Systems		T (A/R)		Service Information Letter	
	 78 ENG2		Mos				
	Eff: 26-Jul-2021		Hrs				
			Enc				
D202308004115		Thrust Reverser Unit (TRU) - MAPAERO Anomalies		T (-)		Service Information Letter	
	 78 ENG1		Mos				
	Eff: 09-Oct-2023		Hrs				
			Enc				
D202308004115		Thrust Reverser Unit (TRU) - MAPAERO Anomalies		T (-)		Service Information Letter	
	 78 ENG2		Mos				
	Eff: 09-Oct-2023		Hrs				
			Enc				
D202308004115 Rev 1		Thrust Reverser Unit (TRU) - MAPAERO Anomalies		T (-)		Service Information Letter	
	 78 ENG1		Mos				
	Eff: 17-Apr-2024		Hrs				
			Enc				
D202308004115 Rev 1		Thrust Reverser Unit (TRU) - MAPAERO Anomalies		T (-)		Service Information Letter	
	 78 ENG2		Mos				
	Eff: 17-Apr-2024		Hrs				
			Enc				
D202308004115 Rev 2		Thrust Reverser Unit (TRU) - MAPAERO Observations		T (A/R)		Service Information Letter	
	 78 ENG1		Mos				
	Eff: 17-Jun-2024		Hrs				
			Enc				
D202308004115 Rev 2		Thrust Reverser Unit (TRU) - MAPAERO Observations		T (A/R)		Service Information Letter	
	 78 ENG2		Mos				
	Eff: 17-Jun-2024		Hrs				
			Enc				
D202602005187		Thrust Reverser Unit (TRU) - Gulfstream MAPAERO Process Flow		T (A/R)		Service Information Letter	
	 78 ENG1		Mos				
	Eff: 04-Mar-2026		Hrs				
			Enc				
D202602005187		Thrust Reverser Unit (TRU) - Gulfstream MAPAERO Process Flow		T (A/R)		Service Information Letter	
	 78 ENG2		Mos				
	Eff: 04-Mar-2026		Hrs				
			Enc				
▼ 79 - OIL							
79-9050		ENGINE - LOW PRESSURE TURBINE - INSTALL WASHERS PN NAS1149E0432R IN PLACE OF WASHERS PN NAS1149C0432R ? INACTIVATED FOR FURTHER ACCOMPLISHMENT		T (A/R)			
	 79 ENG1		Mos				
	Eff: 06-Sep-2012		Hrs				
			Enc				
79-9050		ENGINE - LOW PRESSURE TURBINE - INSTALL WASHERS PN NAS1149E0432R IN PLACE OF WASHERS PN NAS1149C0432R ? INACTIVATED FOR FURTHER ACCOMPLISHMENT		T (A/R)			
	 79 ENG2		Mos				
	Eff: 06-Sep-2012		Hrs				
			Enc				

Task No SEQ PN/SN	Description MOC Note	CW	REQ	TOL	Categories DUE	Time Remaining
79-9050 Rev 1  79 ENG1 Eff: 06-Sep-2012	ENGINE - LOW PRESSURE TURBINE - INSTALL WASHERS PN NAS1149E0432R IN PLACE OF WASHERS PN NAS1149C0432R ? INACTIVATED FOR FURTHER ACCOMPLISHMENT		T (A/R)			
		Mos				
		Hrs				
		Enc				
79-9050 Rev 1  79 ENG2 Eff: 06-Sep-2012	ENGINE - LOW PRESSURE TURBINE - INSTALL WASHERS PN NAS1149E0432R IN PLACE OF WASHERS PN NAS1149C0432R ? INACTIVATED FOR FURTHER ACCOMPLISHMENT		T (A/R)			
		Mos				
		Hrs				
		Enc				
AS907-79-9007  79 ENG1 Eff: 15-Dec-2011	SB AS907-79-9007 - Rework Oil Filler Cap Assembly, PN 3036061-3, to Prevent Chain Interference During Oil Supply Servicing		T (A/R)			
		Mos				
		Hrs				
		Enc				
AS907-79-9007  79 ENG2 Eff: 15-Dec-2011	SB AS907-79-9007 - Rework Oil Filler Cap Assembly, PN 3036061-3, to Prevent Chain Interference During Oil Supply Servicing		T (A/R)			
		Mos				
		Hrs				
		Enc				
AS907-79-9007 Rev 1  79 ENG1 Eff: 10-Dec-2012	SB AS907-79-9007R1 - Rework Oil Filler Cap Assembly, PN 3036061-3, to Prevent Chain Interference During Oil Supply Servicing		T (A/R)			
		Mos				
		Hrs				
		Enc				
AS907-79-9007 Rev 1  79 ENG2 Eff: 10-Dec-2012	SB AS907-79-9007R1 - Rework Oil Filler Cap Assembly, PN 3036061-3, to Prevent Chain Interference During Oil Supply Servicing		T (A/R)			
		Mos				
		Hrs				
		Enc				
AS907-79-9007 Rev 2  79 ENG1 Eff: 09-Mar-2015	OIL - STORAGE SECTION - Rework Oil Filler Cap Assembly PN 3036061-3 to Prevent Chain Interference During Oil Supply Servicing for AS907 Model Engines		RE (-)			
		Mos				
		Hrs				
		Enc				
AS907-79-9007 Rev 2  79 ENG2 Eff: 09-Mar-2015	OIL - STORAGE SECTION - Rework Oil Filler Cap Assembly PN 3036061-3 to Prevent Chain Interference During Oil Supply Servicing for AS907 Model Engines		RE (-)			
		Mos				
		Hrs				
		Enc				
AS907-79-9007 Rev 3  79 ENG1 Eff: 29-Jan-2018 Complied With	Rework Oil Filler Cap Assembly Part No. 3036061-3 to Prevent Chain Interference During Oil Supply Servicing AT MANUFACTURE		RE (-)		Cat.2-Reliability	
		Mos	26-Jan-2023			
		Hrs	0			
		Enc	0			
AS907-79-9007 Rev 3  79 ENG2 Eff: 29-Jan-2018 Complied With	Rework Oil Filler Cap Assembly Part No. 3036061-3 to Prevent Chain Interference During Oil Supply Servicing AT MANUFACTURE		RE (-)		Cat.2-Reliability	
		Mos	20-Jan-2023			
		Hrs	0			
		Enc	0			
AS907-79-9008  79 ENG1 Eff: 27-Feb-2017 Not Applicable	OIL - DISTRIBUTION - Install New Oil Scavenge Metal Tube Assembly and Bracket for AS907 Engine Models PER S/N, incorporated in Production		RE (-)			
		Mos	10-Feb-2023			
		Hrs				
		Enc				

Task No SEQ PN/SN	Description MOC Note	CW	REQ	TOL	Categories DUE	Time Remaining
AS907-79-9008 79 ENG2 Eff: 27-Feb-2017 Not Applicable	OIL - DISTRIBUTION - Install New Oil Scavenge Metal Tube Assembly and Bracket for AS907 Engine Models PER S/N, incorporated in Production	Mos Hrs Enc	10-Feb-2023		RE (-)	
AS907-79-9009 79 ENG1 Eff: 05-May-2015 Complied With	OIL - DISTRIBUTION - Replace Bolt PN AS3236-06 with PN AS3236-05 on the Upper Tube Retainer of the No. 3 Bearing Oil Drain Tube Assembly on AS907-1-1A and AS907-2-1G Engines AT MANUFACTURE	Mos Hrs Enc	26-Jan-2023 0 0		RE (-)	
AS907-79-9009 79 ENG2 Eff: 05-May-2015 Complied With	OIL - DISTRIBUTION - Replace Bolt PN AS3236-06 with PN AS3236-05 on the Upper Tube Retainer of the No. 3 Bearing Oil Drain Tube Assembly on AS907-1-1A and AS907-2-1G Engines AT MANUFACTURE	Mos Hrs Enc	20-Jan-2023 0 0		RE (-)	
AS907-79-9010 79 ENG1 Eff: 28-Aug-2018 Not Applicable	Oil - Distribution - Replace Non-Conforming Oil Hose and Tube Assemblies on AS907 Engine Models PER ENGINE PART NUMBER	Mos Hrs Enc	10-Feb-2023		RE (-) Cat.2-Reliability	
AS907-79-9010 79 ENG2 Eff: 28-Aug-2018 Not Applicable	Oil - Distribution - Replace Non-Conforming Oil Hose and Tube Assemblies on AS907 Engine Models PER ENGINE PART NUMBER	Mos Hrs Enc	10-Feb-2023		RE (-) Cat.2-Reliability	
AS907-79-9012 79 ENG1 Eff: 18-Feb-2019	Oil - Distribution - Replace Lubricating Pump, PN 3038704-3 or PN 3038704-5 with PN 3038704-6	Mos Hrs Enc			RE (-) Category 3, Optional	
AS907-79-9012 79 ENG2 Eff: 18-Feb-2019	Oil - Distribution - Replace Lubricating Pump, PN 3038704-3 or PN 3038704-5 with PN 3038704-6	Mos Hrs Enc			RE (-) Category 3, Optional	
AS907-79-9012 Rev 1 79 ENG1 Eff: 09-May-2019 Complied With	Oil - Distribution - Replace Lubricating Pump, PN 3038704-3 or PN 3038704-5 with PN 3038704-6 AT MANUFACTURE	Mos Hrs Enc	26-Jan-2023 0 0		RE (-) Category 3, Optional	
AS907-79-9012 Rev 1 79 ENG2 Eff: 09-May-2019 Complied With	Oil - Distribution - Replace Lubricating Pump, PN 3038704-3 or PN 3038704-5 with PN 3038704-6 AT MANUFACTURE	Mos Hrs Enc	20-Jan-2023 0 0		RE (-) Category 3, Optional	
D201908000007 79 ENG1 Eff: 17-Sep-2019	AS907 Oil Pump Discussion	Mos Hrs Enc			T (A/R) Service Information Letter	
D201908000007 79 ENG2 Eff: 17-Sep-2019	AS907 Oil Pump Discussion	Mos Hrs Enc			T (A/R) Service Information Letter	

Task No		Description				Categories	Time
SEQ	PN/SN	MOC Note	CW	REQ	TOL	DUE	Remaining
▼ 80 - STARTING							
3506000-80-1872	SB 3506000-80-1872 - Conversion of the Air Turbine Engine Starter From PN 3506000-4 to PN 3506000-5					T (A/R)	
	80 ENG1		Mos				
	Eff: 15-Aug-2014		Hrs				
			Enc				
3506000-80-1872	SB 3506000-80-1872 - Conversion of the Air Turbine Engine Starter From PN 3506000-4 to PN 3506000-5					T (A/R)	
	80 ENG2		Mos				
	Eff: 15-Aug-2014		Hrs				
			Enc				
3506000-80-1872 Rev 1	ENGINE STARTING - AIR TURBINE ENGINE STARTER - Conversion of the Air Turbine Engine Starter From PN 3506000-4 to PN 3506000-5					RE (-)	
	80 ENG1		Mos	10-Apr-2023			
	Eff: 21-Nov-2014 Complied With		Hrs				
	(UPDATE NOTE: Verified Engine Starter PN 35060000-5 Installed)		Enc				
3506000-80-1872 Rev 1	ENGINE STARTING - AIR TURBINE ENGINE STARTER - Conversion of the Air Turbine Engine Starter From PN 3506000-4 to PN 3506000-5					RE (-)	
	80 ENG2		Mos	10-Apr-2023			
	Eff: 21-Nov-2014 Complied With		Hrs				
	(UPDATE NOTE: Verified Engine Starter PN 35060000-5 Installed)		Enc				
AS907-80-9001	STARTING - AIR TURBINE STARTER - Install Improved Packing on the Air Turbine Starter (ATS) on AS907-1-1A and -2-1G Engines					T (A/R)	
	80 ENG1		Mos				
	Eff: 09-Jun-2011		Hrs				
			Enc				
AS907-80-9001	STARTING - AIR TURBINE STARTER - Install Improved Packing on the Air Turbine Starter (ATS) on AS907-1-1A and -2-1G Engines					T (A/R)	
	80 ENG2		Mos				
	Eff: 09-Jun-2011		Hrs				
			Enc				
AS907-80-9001 Rev 1	STARTING - AIR TURBINE STARTER - Install Improved Packing on the Air Turbine Starter (ATS) on AS907-1-1A and -2-1G Engines					T (A/R)	
	80 ENG1		Mos				
	Eff: 29-Aug-2014		Hrs				
			Enc				
AS907-80-9001 Rev 1	STARTING - AIR TURBINE STARTER - Install Improved Packing on the Air Turbine Starter (ATS) on AS907-1-1A and -2-1G Engines					T (A/R)	
	80 ENG2		Mos				
	Eff: 29-Aug-2014		Hrs				
			Enc				
AS907-80-9001 Rev 2	STARTING - AIR TURBINE STARTER - Install Improved Packing on the Air Turbine Starter (ATS) on AS907-1-1A and -2-1G Engines					RE (-)	
	80 ENG1		Mos	26-Jan-2023			
	Eff: 10-Nov-2015 Complied	AT MANUFACTURE	Hrs	0			
	With		Enc	0			
AS907-80-9001 Rev 2	STARTING - AIR TURBINE STARTER - Install Improved Packing on the Air Turbine Starter (ATS) on AS907-1-1A and -2-1G Engines					RE (-)	
	80 ENG2		Mos	20-Jan-2023			
	Eff: 10-Nov-2015 Complied	AT MANUFACTURE	Hrs	0			
	With		Enc	0			
▼ 90 - GENERAL - SUPPLEMENTAL TYPE CERTIFICATE (STC)							
ST02893AT	LoPresti Boom Beam Lights					RE (-)	
	90 A/F		Mos	10-Feb-2023			
	Complied With		Hrs	24:24			
			Ldg	7			

Task No SEQ PN/SN	Description MOC Note	CW	REQ	TOL	Categories DUE	Time Remaining
ST04271AT-D	Installation of a Jump Seat in accordance with Gulfstream Aerospace Corporation Index List GA421328001, Revision G, dated November 3, 2012 or later FAA approved revision.		RE (-)		STC-Supplemental Type Certificate	
 90 A/F Complied With		Mos 02-Mar-2023				
		Hrs 34:12				
		Ldg 10				
ST04274AT-D	Installation of Rockwell Collins Second IFIS in accordance with Gulfstream Aerospace Corporation Index List GA41120800 1, Revision F, dated October 12, 2012, or later FAA approved revision		RE (-)		STC-Supplemental Type Certificate	
 90 A/F Complied With		Mos 02-Mar-2023				
		Hrs 34:12				
		Ldg 10				
ST04321AT-D	Installation of Viasat GAT-5510 Ka-Band High Speed Data (HSD) System in accordance with Gulfstream Aerospace Corporation Index List GA413038002, Revision "-" dated March 28, 2019 or later FAA approved revision		RE (-)		STC-Supplemental Type Certificate	
 90 A/F Complied With		Mos 02-Mar-2023				
		Hrs 34:12				
		Ldg 10				
▼ 94 - --						
949001	Brake Control Unit (Retrofit Program) (Cancelled)		RE (-)			
 94 A/F		Mos				
		Hrs				
		Ldg				
▼ 97 - ELECTRICAL WIRING INSTALLATIONS						
ISR-I-97-2022-04-9	Revision of G280 AFM Wet Runway Performance Tables		RE (-)		Mandatory	
 97 A/F Eff: 15-Jun-2022 Complied With		Mos 22-Mar-2023				
		Hrs				
		Ldg				
▼ 98 - --						
981060	SB 280-34-106 Navigation (ATA 34) - Installation Of Rockwell Collins Avionics Software Ver V3.6 Configuration		RE (-)		Mandatory	
 98 A/F Not Applicable	PER AIRCRAFT SERIAL NUMBER	Mos 17-Apr-2023				
		Hrs 122:11				
		Ldg 69				
▼ 100 - GENERAL						
D201910000091	To Notify Operators of Gulfstream G280 Aircraft and Engine Service Centers of the Recently Released Light Maintenance Manual (LMM) and Aircraft Maintenance Manual (AMM)		T (A/R)		Service Information Letter	
 100 ENG1 Eff: 13-Nov-2019		Mos				
		Hrs				
		Enc				
D201910000091	To Notify Operators of Gulfstream G280 Aircraft and Engine Service Centers of the Recently Released Light Maintenance Manual (LMM) and Aircraft Maintenance Manual (AMM)		T (A/R)		Service Information Letter	
 100 ENG2 Eff: 13-Nov-2019		Mos				
		Hrs				
		Enc				
D202005000806	Biocide Treatment Process		T (A/R)		Service Information Letter	
 100 APU1 Eff: 06-May-2020		Mos				
		Hrs				
		APUS				
D202011001451	Thrust Reverser Unit (TRU) - MAPAERO Overview		T (-)		Service Information Letter	
 100 ENG1 Eff: 06-Jan-2021		Mos				
		Hrs				
		Enc				

Task No		Description				Categories	Time
SEQ	PN/SN	MOC Note	CW	REQ	TOL	DUE	Remaining
D202011001451		Thrust Reverser Unit (TRU) - MAPAERO Overview		T (-)		Service Information Letter	
	100 ENG2						
	Eff: 06-Jan-2021						
D202011001451 Rev 1		Thrust Reverser Unit (TRU) - MAPAERO Overview		T (-)		Service Information Letter	
	100 ENG1						
	Eff: 05-May-2021						
D202011001451 Rev 1		Thrust Reverser Unit (TRU) - MAPAERO Overview		T (-)		Service Information Letter	
	100 ENG2						
	Eff: 05-May-2021						
D202011001451 Rev 2		Thrust Reverser Unit (TRU) - MAPAERO Overview		RE (-)		Service Information Letter	
	100 ENG1						
	Eff: 13-Jul-2022						
D202011001451 Rev 2		Thrust Reverser Unit (TRU) - MAPAERO Overview		RE (-)		Service Information Letter	
	100 ENG2						
	Eff: 13-Jul-2022						
D202011001451 Rev 3		Thrust Reverser Unit (TRU) - MAPAERO Overview		T (A/R)		Service Information Letter	
	100 ENG1						
	Eff: 04-Jan-2023						
D202011001451 Rev 3		Thrust Reverser Unit (TRU) - MAPAERO Overview		T (A/R)		Service Information Letter	
	100 ENG2						
	Eff: 04-Jan-2023						
D202406004425		Field Loadable Software Update Instructions for Connected Engine Data Service - EDG100		T (A/R)		Service Information Letter	
	100 ENG1						
	Eff: 02-Jul-2024						
D202406004425		Field Loadable Software Update Instructions for Connected Engine Data Service - EDG100		T (A/R)		Service Information Letter	
	100 ENG2						
	Eff: 02-Jul-2024						
G25-02030		Med Gooseneck Bolt - New Material Due Obsolesence, Modification		RE (-)			
	100 A/F						
	Complied With	AT MANUFACTURE					
G25-07339		G25-07339, Modification		RE (-)			
	100 A/F						
	Complied With	AT MANUFACTURE					
G25-20183		G25-20183, Modification		RE (-)			
	100 A/F						
	Complied With	AT MANUFACTURE					
G25-20188		G25-20188, Modification		RE (-)			
	100 A/F						
	Complied With	AT MANUFACTURE					

Task No		Description				Categories	Time	
SEQ	PN/SN	MOC Note		CW	REQ	TOL	DUE	Remaining
G25-20194		G25-20194, Modification			RE (-)			
	100 A/F		Mos	20-Nov-2022				
	Complied With	AT MANUFACTURE	Hrs	0				
			Ldg	0				
G25-20197		G25-20197, Modification			RE (-)			
	100 A/F		Mos	20-Nov-2022				
	Complied With	AT MANUFACTURE	Hrs	0				
			Ldg	0				
G25-20200		Aft Press BH Smoke Evacuation Tube Sponge Ring - Alternate Material, Modification			RE (-)			
	100 A/F		Mos	20-Nov-2022				
	Complied With	AT MANUFACTURE	Hrs	0				
			Ldg	0				
G25-20202		Waste Drain Valve - New Manufacturer - Improved Obtainability, Modification			RE (-)			
	100 A/F		Mos	20-Nov-2022				
	Complied With	AT MANUFACTURE	Hrs	0				
			Ldg	0				
G25-20209		G25-20209, Modification			RE (-)			
	100 A/F		Mos	20-Nov-2022				
	Complied With	AT MANUFACTURE	Hrs	0				
			Ldg	0				