



Life Limit / Overhaul Report

PC-12/47G PRO

S/N 3028 OK-CEO

OWNER: KARMONIKA AERO A.S.
ADDRESS: U RUSTONKY 714/1
PRAGUE CZECH 18600

OFFICE:
FAX:

OPERATOR: JET FOR TRIP S.R.O.
ADDRESS: ERBENOVA 877, MLADA BOLESLAV
11,
CZECH REPUBLIC CZECH 29301

OFFICE:
FAX:

CAMO: JET FOR TRIP S.R.O.
ADDRESS: ERBENOVA 877, MLADA BOLESLAV
11,
CZECH REPUBLIC CZECH 29301

OFFICE:
FAX:

ANALYST: ADRIEN LIMMELETTE
EMAIL: ADRIEN.LIMMELETTE@CAMPSYSTEMS.EU

+33 1.55.93.47.77 (DIRECT)
+33-1.55.93.45.80 (MAIN)
WWW.CAMPSYSTEMS.COM

PLEASE REACH OUT TO YOUR ANALYST TO
RECORD CHANGES TO ADDRESS, LAST ACTUALS
(IF ANY).

AIRCRAFT	SERIAL / REGNO: 3028/OK-CEO	MODEL: PC-12/47G PRO	MANUFACTURER: PILATUS AIRCRAFT LTDX
CERTIFICATION DATE: 07-JAN-2026		LAST ACTUALS: 84:54 A/C HRS as of 11-OCT-2026 72 AFL as of 11-OCT-2026	
ENGINE NO. 1	SERIAL / PART: PCE-HP0514/3126995-01 BS1369	MODEL: PT6E-67XP	MANUFACTURER: PRATT & WHITNEY CANADA CORP.
INSTALLED ON: 14-NOV-2025		LAST ACTUALS:	
0	ENG. HRS 0 A/C HRS	84:54 ENG. HRS	as of 11-OCT-2026
0	ENC	75 ENC	as of 11-OCT-2026
PROPELLER NO. 1	SERIAL / PART: SA1324/E5A01850SKD	MODEL: HC-E5A-31A	MANUFACTURER: HARTZELL PROPELLER LLC
INSTALLED ON: 14-NOV-2025		LAST ACTUALS:	
0	PROP HRS 0 A/C HRS	84:54 PROP HRS	as of 11-OCT-2026
0	PRC		



Life Limit / Overhaul Report

Model: PC-12/47G PRO Serial: 3028 RegNo: OK-CEO HRS: 84:54 AFL: 72 As Of: 11-Oct-2026

13-Oct-2026 08:42 AM

PN & SN	Unit	C/W	Next Due (ENG/APU) A/C	Interval	TSX/Adj.	Time Accrued	Est. Due	Remaining ^	Disposition
04-CA/1	AIRCRAFT LIMIT OF VALIDITY (LOV)							Service	ATA:04
	MOS	31-Jan-26				8.4	19-Jun-2442		LIFE LIMIT
	HRS	0	50000	50000		84:54		49915:06	
	AFL	0	60000	60000		72		59928	
PROC. REF: AMM 12-D-04-00-00-00A-000A-APROC. REF: AMM 12-D-04-00-00-00A-000A-A									
04-CA/2	WING STRUCTURE LIMIT OF VALIDITY (LOV) (WITHOUT SYSTEMS AND CONTROL SYSTEM STRUCTURE SUCH AS FLAPS AND AILERONS)							Service	ATA:04
	MOS	31-Jan-26				8.4	20-Jul-2317		LIFE LIMIT
	HRS	0	35000	35000		84:54		34915:06	
	AFL	0	43000	43000		72		42928	
PROC. REF: AMM 12-D-04-00-00-00A-000A-APROC. REF: AMM 12-D-04-00-00-00A-000A-A									
21-30/665	OUTFLOW VALVE- OVERHAUL							Service	ATA:21
	MOS	07-Jan-26				9.2	17-Jan-2066		OVERHAUL
	HRS	0	4800	4800 (+10%/-10%)		84:54		4715:06 (+480)	
	AFL	0				72			
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
21-30/666	OUTFLOW VALVE CONTROLLER - OVERHAUL							Service	ATA:21
	MOS	07-Jan-26				9.2	17-Jan-2066		OVERHAUL
	HRS	0	4800	4800 (+10%/-10%)		84:54		4715:06 (+480)	
	AFL	0				72			
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
24-30/492	OVERHAUL GENERATOR 1 (P/N 978.91.23.407)							Service	ATA:24
PN:978.91.23.407	MOS	31-Jan-26				8.4	25-Jan-2036		OVERHAUL
SN:P4267	HRS	0	1200	1200 (+10%/-10%)		84:54		1115:06 (+120)	
	AFL	0				72			
PROC. REF: AMM 12-B-24-30-01-00A-313A-APROC. REF: AMM 12-B-24-30-01-00A-313A-A									
24-30/493	OVERHAUL STARTER/GENERATOR 2 (P/N 978.91.23.407)							Service	ATA:24
PN:978.91.23.407	MOS	31-Jan-26				8.4	25-Jan-2036		OVERHAUL
SN:P4278	HRS	0	1200	1200 (+10%/-10%)		84:54		1115:06 (+120)	
	AFL	0				72			
PROC. REF: AMM 12-B-24-30-01-00A-313A-APROC. REF: AMM 12-B-24-30-01-00A-313A-A									

^ - Component service life remaining is based on Accumulated Total Cycles as determined by CAMP's implementation of the low-cycle fatigue formula and is not endorsed by Pratt & Whitney Canada

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Life Limit / Overhaul Report

Model: PC-12/47G PRO Serial: 3028 RegNo: OK-CEO HRS: 84:54 AFL: 72 As Of: 11-Oct-2026

13-Oct-2026 08:42 AM

PN & SN	Unit	C/W	Next Due (ENG/APU) A/C	Interval	TSX/Adj.	Time Accrued	Est. Due	Remaining ^	Disposition
25-62/643 DISCARD CO-PILOT LIFE VEST									Service ATA:25
PN:904.92.17.915	MOS	31-Aug-24	30-Jul-34 (M)	120		25.4	30-Jul-2034	2847 d	REPLACE
SN:L6576510	HRS								
	AFL								
Manufacture Date:: 31-Aug-24									
PROC. REF: AMM 12-B-25-62-00-00A-920A-APROC. REF: AMM 12-B-25-62-00-00A-920A-A									
25-62/643 DISCARD NO. 1 LIFE VEST									Service ATA:25
PN:904.92.17.913	MOS	28-Feb-25	31-Jan-35 (M)	120		19.5	31-Jan-2035	3032 d	REPLACE
SN:L6533318	HRS								
	AFL								
Manufacture Date:: 28-Feb-25									
PROC. REF: AMM 12-B-25-62-00-00A-920A-APROC. REF: AMM 12-B-25-62-00-00A-920A-A									
25-62/643 DISCARD NO. 2 LIFE VEST									Service ATA:25
PN:904.92.17.913	MOS	28-Feb-25	31-Jan-35 (M)	120		19.5	31-Jan-2035	3032 d	REPLACE
SN:L6533296	HRS								
	AFL								
Manufacture Date:: 28-Feb-25									
PROC. REF: AMM 12-B-25-62-00-00A-920A-APROC. REF: AMM 12-B-25-62-00-00A-920A-A									
25-62/643 DISCARD NO. 3 LIFE VEST									Service ATA:25
PN:904.92.17.913	MOS	28-Feb-25	31-Jan-35 (M)	120		19.5	31-Jan-2035	3032 d	REPLACE
SN:L6533289	HRS								
	AFL								
Manufacture Date:: 28-Feb-25									
PROC. REF: AMM 12-B-25-62-00-00A-920A-APROC. REF: AMM 12-B-25-62-00-00A-920A-A									
25-62/643 DISCARD NO. 4 LIFE VEST									Service ATA:25
PN:904.92.17.913	MOS	28-Feb-25	31-Jan-35 (M)	120		19.5	31-Jan-2035	3032 d	REPLACE
SN:L6533310	HRS								
	AFL								
Manufacture Date:: 28-Feb-25									
PROC. REF: AMM 12-B-25-62-00-00A-920A-APROC. REF: AMM 12-B-25-62-00-00A-920A-A									

^ - Component service life remaining is based on Accumulated Total Cycles as determined by CAMP's implementation of the low-cycle fatigue formula and is not endorsed by Pratt & Whitney Canada

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Life Limit / Overhaul Report

Model: PC-12/47G PRO Serial: 3028 RegNo: OK-CEO HRS: 84:54 AFL: 72 As Of: 11-Oct-2026

13-Oct-2026 08:42 AM

PN & SN	Unit	C/W	Next Due (ENG/APU) A/C	Interval	TSX/Adj.	Time Accrued	Est. Due	Remaining ^	Disposition
25-62/643 DISCARD NO. 5 LIFE VEST									Service ATA:25
PN:904.92.17.913	MOS	28-Feb-25	31-Jan-35 (M)	120		19.5	31-Jan-2035	3032 d	REPLACE
SN:L6533303	HRS								
	AFL								
Manufacture Date:: 28-Feb-25									
PROC. REF: AMM 12-B-25-62-00-00A-920A-APROC. REF: AMM 12-B-25-62-00-00A-920A-A									
25-62/643 DISCARD NO. 6 LIFE VEST									Service ATA:25
PN:904.92.17.913	MOS	28-Feb-25	31-Jan-35 (M)	120		19.5	31-Jan-2035	3032 d	REPLACE
SN:L6533302	HRS								
	AFL								
Manufacture Date:: 28-Feb-25									
PROC. REF: AMM 12-B-25-62-00-00A-920A-APROC. REF: AMM 12-B-25-62-00-00A-920A-A									
25-62/643 DISCARD NO. 7 LIFE VEST									Service ATA:25
PN:904.92.17.913	MOS	28-Feb-25	31-Jan-35 (M)	120		19.5	31-Jan-2035	3032 d	REPLACE
SN:L6533312	HRS								
	AFL								
Manufacture Date:: 28-Feb-25									
PROC. REF: AMM 12-B-25-62-00-00A-920A-APROC. REF: AMM 12-B-25-62-00-00A-920A-A									
25-62/643 DISCARD NO. 8 LIFE VEST									Service ATA:25
PN:904.92.17.913	MOS	28-Feb-25	31-Jan-35 (M)	120		19.5	31-Jan-2035	3032 d	REPLACE
SN:L6533276	HRS								
	AFL								
Manufacture Date:: 28-Feb-25									
PROC. REF: AMM 12-B-25-62-00-00A-920A-APROC. REF: AMM 12-B-25-62-00-00A-920A-A									
25-62/643 DISCARD PILOT LIFE VEST									Service ATA:25
PN:904.92.17.915	MOS	31-Aug-24	30-Jul-34 (M)	120		25.4	30-Jul-2034	2847 d	REPLACE
SN:L6576482	HRS								
	AFL								
Manufacture Date:: 31-Aug-24									
PROC. REF: AMM 12-B-25-62-00-00A-920A-APROC. REF: AMM 12-B-25-62-00-00A-920A-A									

^ - Component service life remaining is based on Accumulated Total Cycles as determined by CAMP's implementation of the low-cycle fatigue formula and is not endorsed by Pratt & Whitney Canada

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Life Limit / Overhaul Report

Model: PC-12/47G PRO Serial: 3028 RegNo: OK-CEO HRS: 84:54 AFL: 72 As Of: 11-Oct-2026

13-Oct-2026 08:42 AM

PN & SN	Unit	C/W	Next Due (ENG/APU) A/C	Interval	TSX/Adj.	Time Accrued	Est. Due	Remaining ^	Disposition
25-63/23 DISCARD ELT BATTERY									Service ATA:25
PN:985.13.80.882	MOS/MSC		31-Oct-31 (M)	DUE			31-Oct-2031	1844 d	DISCARD
SN:TM0000342491	HRS								
	AFL								
Expiry Date: : 31-Oct-31									
PROC. REF: AMM 12-B-25-63-00-00A-920B-APROC. REF: AMM 12-B-25-63-00-00A-920B-A									
25-CA/51 REPLACE / RECERTIFY FIRST AID KIT									Service ATA:25
PN:710108	MOS/MSC	08-Sep-26	31-Aug-27 (M)	DUE		1.2	31-Aug-2027	322 d	REPLACE
SN:2506-000505	HRS	58:09				26:45			
	AFL	47				25			
Expiry Date: : 31-Aug-27									
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
26-20/516 LIFE LIMIT - CABIN FIRE EXTINGUISHER (MODEL P3APP003010D)									Service ATA:26
PN:P3APP003010D	MOS	14-Sep-26	14-Sep-38	144		1	14-Sep-2038	4354 d	LIFE LIMIT
SN:130589	HRS	58:09				26:45			
	AFL	47				25			
PROC. REF: AMM 26-24-01PROC. REF: AMM 26-24-01									
26-20/516 LIFE LIMIT - COCKPIT FIRE EXTINGUISHER (MODEL P3APP003010D)									Service ATA:26
PN:959.08.06.224	MOS	30-Sep-25	30-Sep-37	144		12.5	30-Sep-2037	4005 d	LIFE LIMIT
SN:124854	HRS								
	AFL								
Manufacture Date:: 30-Sep-25									
PROC. REF: AMM 26-24-01PROC. REF: AMM 26-24-01									
27-10/444 LIFE LIMIT - FLIGHT CONTROL CABLES, AILERON									Service ATA:27
	MOS	31-Jan-26				8.4	18-Aug-2192		LIFE LIMIT
	HRS	0	20000	20000		84:54		19915:06	
	AFL	0	27000	27000		72		26928	
PROC. REF: AMM 12-B-27-10-01-00A-920A-APROC. REF: AMM 12-B-27-10-01-00A-920A-A									
27-10/445 LIFE LIMIT - AUTOPILOT CONTROL CABLE, AILERON									Service ATA:27
	MOS	31-Jan-26				8.4	18-Aug-2192		LIFE LIMIT
	HRS	0	20000	20000		84:54		19915:06	
	AFL	0	27000	27000		72		26928	

^ - Component service life remaining is based on Accumulated Total Cycles as determined by CAMP's implementation of the low-cycle fatigue formula and is not endorsed by Pratt & Whitney Canada

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Life Limit / Overhaul Report

Model: PC-12/47G PRO Serial: 3028 RegNo: OK-CEO HRS: 84:54 AFL: 72 As Of: 11-Oct-2026

13-Oct-2026 08:42 AM

PN & SN	Unit	C/W	Next Due (ENG/APU) A/C	Interval	TSX/Adj.	Time Accrued	Est. Due	Remaining ^	Disposition
PROC. REF: AMM 12-D-27-10-02-00A-920A-APROC. REF: AMM 12-D-27-10-02-00A-920A-A									
27-20/446	LIFE LIMIT - FLIGHT CONTROL CABLES, RUDDER								Service ATA:27
	MOS	31-Jan-26				8.4	18-Aug-2192		LIFE LIMIT
	HRS	0	20000	20000		84:54		19915:06	
	AFL	0	27000	27000		72		26928	
PROC. REF: AMM 12-B-27-20-01-00A-920A-APROC. REF: AMM 12-B-27-20-01-00A-920A-A									
27-20/447	LIFE LIMIT - AUTOPILOT CONTROL CABLES, RUDDER								Service ATA:27
	MOS	31-Jan-26				8.4	18-Aug-2192		LIFE LIMIT
	HRS	0	20000	20000		84:54		19915:06	
	AFL	0	27000	27000		72		26928	
PROC. REF: AMM 12-D-27-20-02-00A-920A-APROC. REF: AMM 12-D-27-20-02-00A-920A-A									
27-20/575	LIFE LIMIT - RUDDER BELLCRANK								Service ATA:27
PN:PN	MOS	31-Jan-26				8.4	18-Aug-2192		LIFE LIMIT
SN:UNKNOWN	HRS	0	20000	20000		84:54		19915:06	
	AFL	0	27000	27000		72		26928	
PROC. REF: AMM 12-B-27-20-04-00A-920A-APROC. REF: AMM 12-B-27-20-04-00A-920A-A									
27-30/448	LIFE LIMIT - FLIGHT CONTROL CABLES, ELEVATOR								Service ATA:27
	MOS	31-Jan-26				8.4	18-Aug-2192		LIFE LIMIT
	HRS	0	20000	20000		84:54		19915:06	
	AFL	0	27000	27000		72		26928	
PROC. REF: AMM 12-D-27-30-01-00A-920A-APROC. REF: AMM 12-D-27-30-01-00A-920A-A									
27-30/449	LIFE LIMIT - AUTOPILOT CONTROL CABLES, ELEVATOR								Service ATA:27
	MOS	31-Jan-26				8.4	18-Aug-2192		LIFE LIMIT
	HRS	0	20000	20000		84:54		19915:06	
	AFL	0	27000	27000		72		26928	
PROC. REF: AMM 12-D-27-30-02-00A-920A-APROC. REF: AMM 12-D-27-30-02-00A-920A-A									
27-40/3	LIFE LIMIT - PITCH TRIM ACTUATOR								Service ATA:27
PN:978.73.14.203	MOS	31-Jan-26				8.4	18-Aug-2192		LIFE LIMIT
SN:3901	HRS	0	20000	20000		84:54		19915:06	
	AFL	0	27000	27000		72		26928	

^ - Component service life remaining is based on Accumulated Total Cycles as determined by CAMP's implementation of the low-cycle fatigue formula and is not endorsed by Pratt & Whitney Canada

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Life Limit / Overhaul Report

Model: PC-12/47G PRO Serial: 3028 RegNo: OK-CEO HRS: 84:54 AFL: 72 As Of: 11-Oct-2026

13-Oct-2026 08:42 AM

PN & SN	Unit	C/W	Next Due (ENG/APU) A/C	Interval	TSX/Adj.	Time Accrued	Est. Due	Remaining ^	Disposition
PROC. REF: AMM 12-B-27-40-01-00A-313A-APROC. REF: AMM 12-B-27-40-01-00A-313A-A									
27-40/307	LIFE LIMIT - PITCH TRIM ACTUATOR ATTACHMENT PARTS, FAIL-SAFE PLATES AND THEIR ATTACHMENT PARTS (IPD 12-20-00-07)							Service	ATA:27
PN:978.73.14.203	MOS	31-Jan-26				8.4	09-May-2109		LIFE LIMIT
SN:3901	HRS	0	10000	10000		84:54		9915:06	
	AFL	0				72			
PROC. REF: AMM 12-B-27-40-02-00A-920A-APROC. REF: AMM 12-B-27-40-02-00A-920A-A									
27-40/508	PITCH TRIM ACTUATOR - OVERHAUL							Service	ATA:27
PN:978.73.14.203	MOS	31-Jan-26	31-Jan-31	60		8.4	31-Jan-2031	1571 d	OVERHAUL
SN:3901	HRS	0	5000	5000		84:54		4915:06	
	AFL	0				72			
PROC. REF: AMM 12-B-27-40-01-00A-920A-APROC. REF: AMM 12-B-27-40-01-00A-920A-A									
27-50/28	OVERHAUL FLAP POWER DRIVE UNIT							Service	ATA:27
PN:978.73.20.003	MOS	31-Jan-26				8.4	09-May-2109		OVERHAUL
SN:2366	HRS	0	10000	10000 (+500/-500)		84:54		9915:06 (+500)	
	AFL	0	13500	13500 (+500/-500)		72		13428 (+500)	
PROC. REF: AMM 12-B-27-50-01-00A-920A-APROC. REF: AMM 12-B-27-50-01-00A-920A-A									
27-50/414	LIFE LIMIT - FLAP LH							Service	ATA:27
PN:557.50.12.007	MOS	31-Jan-26				8.4	09-Apr-2234		LIFE LIMIT
SN:7300	HRS	0	25000	25000		84:54		24915:06	
	AFL	0	30000	30000		72		29928	
PROC. REF: AMM 12-B-57-50-01-00A-920A-APROC. REF: AMM 12-B-57-50-01-00A-920A-A									
27-50/414	LIFE LIMIT - FLAP RH							Service	ATA:27
PN:557.50.12.008	MOS	31-Jan-26				8.4	09-Apr-2234		LIFE LIMIT
SN:7300	HRS	0	25000	25000		84:54		24915:06	
	AFL	0	30000	30000		72		29928	
PROC. REF: AMM 12-B-57-50-01-00A-920A-APROC. REF: AMM 12-B-57-50-01-00A-920A-A									
27-50/451	LIFE LIMIT - LEFT INBOARD FLAP TENSION ROD							Service	ATA:27
PN:PN	MOS	31-Jan-26				8.4	18-Aug-2192		LIFE LIMIT
SN:UNKNOWN	HRS	0	20000	20000		84:54		19915:06	
	AFL	0	27000	27000		72		26928	

^ - Component service life remaining is based on Accumulated Total Cycles as determined by CAMP's implementation of the low-cycle fatigue formula and is not endorsed by Pratt & Whitney Canada

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Life Limit / Overhaul Report

Model: PC-12/47G PRO Serial: 3028 RegNo: OK-CEO HRS: 84:54 AFL: 72 As Of: 11-Oct-2026

13-Oct-2026 08:42 AM

PN & SN	Unit	C/W	Next Due (ENG/APU) A/C	Interval	TSX/Adj.	Time Accrued	Est. Due	Remaining ^	Disposition
PROC. REF: AMM 12-B-27-51-01-00A-920A-A, AMM 12-B-27-51-03-00A-920A-APROC. REF: AMM 12-B-27-51-01-00A-920A-A, AMM 12-B-27-51-03-00A-920A-A									
27-50/451	LIFE LIMIT - LEFT OUTBOARD FLAP TENSION ROD								Service ATA:27
PN:PN	MOS	31-Jan-26				8.4	18-Aug-2192		LIFE LIMIT
SN:UNKNOWN	HRS	0	20000	20000		84:54		19915:06	
	AFL	0	27000	27000		72		26928	
PROC. REF: AMM 12-B-27-51-01-00A-920A-A, AMM 12-B-27-51-03-00A-920A-APROC. REF: AMM 12-B-27-51-01-00A-920A-A, AMM 12-B-27-51-03-00A-920A-A									
27-50/451	LIFE LIMIT - RIGHT INBOARD FLAP TENSION ROD								Service ATA:27
PN:PN	MOS	31-Jan-26				8.4	18-Aug-2192		LIFE LIMIT
SN:UNKNOWN	HRS	0	20000	20000		84:54		19915:06	
	AFL	0	27000	27000		72		26928	
PROC. REF: AMM 12-B-27-51-01-00A-920A-A, AMM 12-B-27-51-03-00A-920A-APROC. REF: AMM 12-B-27-51-01-00A-920A-A, AMM 12-B-27-51-03-00A-920A-A									
27-50/451	LIFE LIMIT - RIGHT OUTBOARD FLAP TENSION ROD								Service ATA:27
PN:PN	MOS	31-Jan-26				8.4	18-Aug-2192		LIFE LIMIT
SN:UNKNOWN	HRS	0	20000	20000		84:54		19915:06	
	AFL	0	27000	27000		72		26928	
PROC. REF: AMM 12-B-27-51-01-00A-920A-A, AMM 12-B-27-51-03-00A-920A-APROC. REF: AMM 12-B-27-51-01-00A-920A-A, AMM 12-B-27-51-03-00A-920A-A									
27-50/485	LIFE LIMIT - LEFT INBOARD FLAP ACTUATOR (BLACK ANODIZED)								Service ATA:27
PN:978.73.20.309	MOS	31-Jan-26				8.4	18-Aug-2192		LIFE LIMIT
SN:9710	HRS	0	20000	20000		84:54		19915:06	
	AFL	0	27000	27000		72		26928	
PROC. REF: AMM 12-B-27-50-03-00A-920A-APROC. REF: AMM 12-B-27-50-03-00A-920A-A									
27-50/485	LIFE LIMIT - LEFT OUTBOARD FLAP ACTUATOR (BLACK ANODIZED)								Service ATA:27
PN:978.73.20.309	MOS	31-Jan-26				8.4	18-Aug-2192		LIFE LIMIT
SN:9725	HRS	0	20000	20000		84:54		19915:06	
	AFL	0	27000	27000		72		26928	
PROC. REF: AMM 12-B-27-50-03-00A-920A-APROC. REF: AMM 12-B-27-50-03-00A-920A-A									
27-50/485	LIFE LIMIT - RIGHT INBOARD FLAP ACTUATOR (BLACK ANODIZED)								Service ATA:27
PN:978.73.20.309	MOS	31-Jan-26				8.4	18-Aug-2192		LIFE LIMIT
SN:9709	HRS	0	20000	20000		84:54		19915:06	
	AFL	0	27000	27000		72		26928	

^ - Component service life remaining is based on Accumulated Total Cycles as determined by CAMP's implementation of the low-cycle fatigue formula and is not endorsed by Pratt & Whitney Canada

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Life Limit / Overhaul Report

Model: PC-12/47G PRO Serial: 3028 RegNo: OK-CEO HRS: 84:54 AFL: 72 As Of: 11-Oct-2026

13-Oct-2026 08:42 AM

PN & SN	Unit	C/W	Next Due (ENG/APU) A/C	Interval	TSX/Adj.	Time Accrued	Est. Due	Remaining ^	Disposition
PROC. REF: AMM 12-B-27-50-03-00A-920A-APROC. REF: AMM 12-B-27-50-03-00A-920A-A									
27-50/485 LIFE LIMIT - RIGHT OUTBOARD FLAP ACTUATOR (BLACK ANODIZED) Service ATA:27									
PN:978.73.20.309	MOS	31-Jan-26				8.4	18-Aug-2192		LIFE LIMIT
SN:9722	HRS	0	20000	20000		84:54		19915:06	
	AFL	0	27000	27000		72		26928	
PROC. REF: AMM 12-B-27-50-03-00A-920A-APROC. REF: AMM 12-B-27-50-03-00A-920A-A									
27-50/506 OVERHAUL LEFT INBOARD FLAP ACTUATOR (BLACK ANODIZED) (P/N 978.73.20.309) Service ATA:27									
PN:978.73.20.309	MOS	31-Jan-26				8.4	18-Sep-2067		OVERHAUL
SN:9710	HRS	0	5000	5000 (+500/-500)		84:54		4915:06 (+500)	
	AFL	0	7000	7000 (+500/-500)		72		6928 (+500)	
PROC. REF: AMM 12-B-27-50-03-00A-920A-APROC. REF: AMM 12-B-27-50-03-00A-920A-A									
27-50/506 OVERHAUL LEFT OUTBOARD FLAP ACTUATOR (BLACK ANODIZED) (P/N 978.73.20.309) Service ATA:27									
PN:978.73.20.309	MOS	31-Jan-26				8.4	18-Sep-2067		OVERHAUL
SN:9725	HRS	0	5000	5000 (+500/-500)		84:54		4915:06 (+500)	
	AFL	0	7000	7000 (+500/-500)		72		6928 (+500)	
PROC. REF: AMM 12-B-27-50-03-00A-920A-APROC. REF: AMM 12-B-27-50-03-00A-920A-A									
27-50/506 OVERHAUL RIGHT INBOARD FLAP ACTUATOR (BLACK ANODIZED)(P/N 978.73.20.309) Service ATA:27									
PN:978.73.20.309	MOS	31-Jan-26				8.4	18-Sep-2067		OVERHAUL
SN:9709	HRS	0	5000	5000 (+500/-500)		84:54		4915:06 (+500)	
	AFL	0	7000	7000 (+500/-500)		72		6928 (+500)	
PROC. REF: AMM 12-B-27-50-03-00A-920A-APROC. REF: AMM 12-B-27-50-03-00A-920A-A									
27-50/506 OVERHAUL RIGHT OUTBOARD FLAP ACTUATOR (BLACK ANODIZED) (P/N 978.73.20.309) Service ATA:27									
PN:978.73.20.309	MOS	31-Jan-26				8.4	18-Sep-2067		OVERHAUL
SN:9722	HRS	0	5000	5000 (+500/-500)		84:54		4915:06 (+500)	
	AFL	0	7000	7000 (+500/-500)		72		6928 (+500)	
PROC. REF: AMM 12-B-27-50-03-00A-920A-APROC. REF: AMM 12-B-27-50-03-00A-920A-A									
27-50/507 DISCARD LEFT INBOARD FLAP FLEXIBLE DRIVE SHAFT (P/N945.02.02.205) Service ATA:27									
PN:945.02.02.205	MOS	31-Jan-26				8.4	09-May-2109		DISCARD
SN:S11360	HRS	0	10000	10000 (+500/-500)		84:54		9915:06 (+500)	
	AFL	0	13500	13500 (+500/-500)		72		13428 (+500)	

^ - Component service life remaining is based on Accumulated Total Cycles as determined by CAMP's implementation of the low-cycle fatigue formula and is not endorsed by Pratt & Whitney Canada

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Life Limit / Overhaul Report

Model: PC-12/47G PRO Serial: 3028 RegNo: OK-CEO HRS: 84:54 AFL: 72 As Of: 11-Oct-2026

13-Oct-2026 08:42 AM

PN & SN	Unit	C/W	Next Due (ENG/APU) A/C	Interval	TSX/Adj.	Time Accrued	Est. Due	Remaining ^	Disposition
PROC. REF: AMM 12-B-27-50-02-00A-920A-APROC. REF: AMM 12-B-27-50-02-00A-920A-A									
27-50/507	DISCARD LEFT OUTBOARD FLAP FLEXIBLE DRIVE SHAFT (P/N 945.02.02.206)								Service ATA:27
PN:945.02.02.206	MOS	31-Jan-26				8.4	09-May-2109		DISCARD
SN:S11338	HRS	0	10000	10000 (+500/-500)		84:54		9915:06 (+500)	
	AFL	0	13500	13500 (+500/-500)		72		13428 (+500)	
PROC. REF: AMM 12-B-27-50-02-00A-920A-APROC. REF: AMM 12-B-27-50-02-00A-920A-A									
27-50/507	DISCARD RIGHT INBOARDFLAP FLEXIBLE DRIVE SHAFT (P/N945.02.02.205)								Service ATA:27
PN:945.02.02.205	MOS	31-Jan-26				8.4	09-May-2109		DISCARD
SN:S11305	HRS	0	10000	10000 (+500/-500)		84:54		9915:06 (+500)	
	AFL	0	13500	13500 (+500/-500)		72		13428 (+500)	
PROC. REF: AMM 12-B-27-50-02-00A-920A-APROC. REF: AMM 12-B-27-50-02-00A-920A-A									
27-50/507	DISCARD RIGHT OUTBOARD FLAP FLEXIBLE DRIVE SHAFT (P/N945.02.02.206)								Service ATA:27
PN:945.02.02.206	MOS	31-Jan-26				8.4	09-May-2109		DISCARD
SN:S11329	HRS	0	10000	10000 (+500/-500)		84:54		9915:06 (+500)	
	AFL	0	13500	13500 (+500/-500)		72		13428 (+500)	
PROC. REF: AMM 12-B-27-50-02-00A-920A-APROC. REF: AMM 12-B-27-50-02-00A-920A-A									
32-10/346	SUPPLEMENTAL STRUCTURAL INSPECTION PROGRAM - LEFT MLG YOKE FITTING O (ELECTRO MECHANICAL LANDING GEAR) OVERHAUL AND EDDY CURRENT INSPECTION								Service ATA:32
PN:PN	MOS	31-Jan-26				8.4	09-Apr-2234		OVERHAUL
SN:UNKNOWN	HRS	0	25000	T:25000		84:54		24915:06	
	AFL	0	30000	T:30000		72		29928	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
32-10/346	SUPPLEMENTAL STRUCTURAL INSPECTION PROGRAM - RIGHT MLG YOKE FITTING (ELECTRO MECHANICAL LANDING GEAR) OVERHAUL AND EDDY CURRENT INSPECTION								Service ATA:32
PN:PN	MOS	31-Jan-26				8.4	09-Apr-2234		OVERHAUL
SN:UNKNOWN	HRS	0	25000	T:25000		84:54		24915:06	
	AFL	0	30000	T:30000		72		29928	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

^ - Component service life remaining is based on Accumulated Total Cycles as determined by CAMP's implementation of the low-cycle fatigue formula and is not endorsed by Pratt & Whitney Canada

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Life Limit / Overhaul Report

Model: PC-12/47G PRO Serial: 3028 RegNo: OK-CEO HRS: 84:54 AFL: 72 As Of: 11-Oct-2026

13-Oct-2026 08:42 AM

PN & SN	Unit	C/W	Next Due (ENG/APU) A/C	Interval	TSX/Adj.	Time Accrued	Est. Due	Remaining ^	Disposition
32-10/347 SUPPLEMENTAL STRUCTURAL INSPECTION PROGRAM - LEFT MLG TRAILING LINK OVERHAUL AND EDDY CURRENT INSPECTION									Service ATA:32
PN:PN	MOS	31-Jan-26				8.4	09-Apr-2234		OVERHAUL
SN:UNKNOWN	HRS	0	25000	T:25000		84:54		24915:06	
	AFL	0	30000	T:30000		72		29928	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
32-10/347 SUPPLEMENTAL STRUCTURAL INSPECTION PROGRAM - RIGHT MLG TRAILING LINK OVERHAUL AND EDDY CURRENT INSPECTION									Service ATA:32
PN:PN	MOS	31-Jan-26				8.4	09-Apr-2234		OVERHAUL
SN:UNKNOWN	HRS	0	25000	T:25000		84:54		24915:06	
	AFL	0	30000	T:30000		72		29928	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
32-20/403 SUPPLEMENTAL STRUCTURAL INSPECTION PROGRAM - NLG - OVERHAUL									Service ATA:32
PN:532.20.12.045	MOS	31-Jan-26				8.4	09-Apr-2234		OVERHAUL
SN:VLG1511	HRS	0	25000	T:25000 (+500/-500)		84:54		24915:06 (+500)	
	AFL	0	30000	T:30000 (+500/-500)		72		29928 (+500)	
PROC. REF: AMM 32-20-05PROC. REF: AMM 32-20-05									
32-20/416 LIFE LIMIT - NLG UPPER RIGHT HAND DRAG LINK									Service ATA:32
PN:PN	MOS	31-Jan-26				8.4	09-Apr-2234		LIFE LIMIT
SN:UNKNOWN	HRS	0	25000	25000		84:54		24915:06	
	AFL	0	30000	30000		72		29928	
PROC. REF: AMM 12-D-04-00-00-00A-000A-APROC. REF: AMM 12-D-04-00-00-00A-000A-A									
32-30/423 LIFE LIMIT - LEFT MAIN LANDING GEAR ELECTRO MECHANICAL ACTUATOR									Service ATA:32
PN:959.56.01.853	MOS	31-Jan-26				8.4	02-Apr-2525		LIFE LIMIT
SN:2277	HRS	0				84:54			
	AFL	0	30000	30000		72		29928	
PROC. REF: AMM 12-B-32-30-01-00A-920B-A, AMM 12-B-32-30-02-00A-920B-APROC. REF: AMM 12-B-32-30-01-00A-920B-A, AMM 12-B-32-30-02-00A-920B-A									
32-30/423 LIFE LIMIT - NOSE LANDING GEAR ELECTRO MECHANICAL ACTUATOR									Service ATA:32
PN:959.56.01.852	MOS	31-Jan-26				8.4	02-Apr-2525		LIFE LIMIT
SN:1126	HRS	0				84:54			
	AFL	0	30000	30000		72		29928	
PROC. REF: AMM 12-B-32-30-01-00A-920B-A, AMM 12-B-32-30-02-00A-920B-APROC. REF: AMM 12-B-32-30-01-00A-920B-A, AMM 12-B-32-30-02-00A-920B-A									

^ - Component service life remaining is based on Accumulated Total Cycles as determined by CAMP's implementation of the low-cycle fatigue formula and is not endorsed by Pratt & Whitney Canada

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Life Limit / Overhaul Report

Model: PC-12/47G PRO Serial: 3028 RegNo: OK-CEO HRS: 84:54 AFL: 72 As Of: 11-Oct-2026

13-Oct-2026 08:42 AM

PN & SN	Unit	C/W	Next Due (ENG/APU) A/C	Interval	TSX/Adj.	Time Accrued	Est. Due	Remaining ^	Disposition
32-30/423 LIFE LIMIT - RIGHT MAIN LANDING GEAR ELECTRO MECHANICAL ACTUATOR									Service ATA:32
PN:959.56.01.853	MOS	31-Jan-26				8.4	02-Apr-2525		LIFE LIMIT
SN:2276	HRS	0				84:54			
	AFL	0	30000	30000		72		29928	
PROC. REF: AMM 12-B-32-30-01-00A-920B-A, AMM 12-B-32-30-02-00A-920B-APROC. REF: AMM 12-B-32-30-01-00A-920B-A, AMM 12-B-32-30-02-00A-920B-A									
32-30/435 LEFT MAIN LANDING GEAR ELECTRO MECHANICAL ACTUATORS ANTI-ROTATION PADS - DISCARD									Service ATA:32
PN:959.56.01.853	MOS	31-Jan-26				8.4	14-Jun-2225		DISCARD
SN:2277	HRS	0				84:54			
	AFL	0	12000	12000 (+500/-500)		72		11928 (+500)	
PROC. REF: AMM 12-B-32-30-01-01A-920B-A, AMM 12-B-32-30-02-01A-920B-APROC. REF: AMM 12-B-32-30-01-01A-920B-A, AMM 12-B-32-30-02-01A-920B-A									
32-30/435 NOSE LANDING GEAR ELECTRO MECHANICAL ACTUATORS ANTI-ROTATION PADS - DISCARD									Service ATA:32
PN:959.56.01.852	MOS	31-Jan-26				8.4	14-Jun-2225		DISCARD
SN:1126	HRS	0				84:54			
	AFL	0	12000	12000 (+500/-500)		72		11928 (+500)	
PROC. REF: AMM 12-B-32-30-01-01A-920B-A, AMM 12-B-32-30-02-01A-920B-APROC. REF: AMM 12-B-32-30-01-01A-920B-A, AMM 12-B-32-30-02-01A-920B-A									
32-30/435 RIGHT MAIN LANDING GEAR ELECTRO MECHANICAL ACTUATORS ANTI-ROTATION PADS - DISCARD									Service ATA:32
PN:959.56.01.853	MOS	31-Jan-26				8.4	14-Jun-2225		DISCARD
SN:2276	HRS	0				84:54			
	AFL	0	12000	12000 (+500/-500)		72		11928 (+500)	
PROC. REF: AMM 12-B-32-30-01-01A-920B-A, AMM 12-B-32-30-02-01A-920B-APROC. REF: AMM 12-B-32-30-01-01A-920B-A, AMM 12-B-32-30-02-01A-920B-A									
35-10/6 LIFE LIMIT - OXYGEN BOTTLE									Service ATA:35
PN:957.12.12.212	MOS	31-Oct-24	31-Oct-39	180		23.4	31-Oct-2039	4766 d	LIFE LIMIT
SN:C24102846	HRS								
	AFL								
Manufacture Date:: 31-Oct-24									
PROC. REF: AMM SIL-35-114PROC. REF: AMM SIL-35-114									
35-20/453 DISCARD NO. 1 LH SEAT PASSENGER OXYGEN MASK CARTRIDGE									Service ATA:35
PN:UNKN	MOS	30-Jun-24	31-May-30 (M)	72		27.5	31-May-2030	1326 d	LIFE LIMIT
SN:UNKNOWN	HRS								
	AFL								
Manufacture Date:: 30-Jun-24									
PROC. REF: AMM 12-B-35-20-07-00A-920A-APROC. REF: AMM 12-B-35-20-07-00A-920A-A									

^ - Component service life remaining is based on Accumulated Total Cycles as determined by CAMP's implementation of the low-cycle fatigue formula and is not endorsed by Pratt & Whitney Canada

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Life Limit / Overhaul Report

Model: PC-12/47G PRO Serial: 3028 RegNo: OK-CEO HRS: 84:54 AFL: 72 As Of: 11-Oct-2026

13-Oct-2026 08:42 AM

PN & SN	Unit	C/W	Next Due (ENG/APU) A/C	Interval	TSX/Adj.	Time Accrued	Est. Due	Remaining ^	Disposition
35-20/453 DISCARD NO. 2 RH SEAT PASSENGER OXYGEN MASK CARTRIDGE									Service ATA:35
PN:UNKN	MOS	30-Jun-24	31-May-30 (M)	72		27.5	31-May-2030	1326 d	LIFE LIMIT
SN:UNKNOWN	HRS								
	AFL								
Manufacture Date:: 30-Jun-24									
PROC. REF: AMM 12-B-35-20-07-00A-920A-APROC. REF: AMM 12-B-35-20-07-00A-920A-A									
35-20/453 DISCARD NO. 3 LH SEAT PASSENGER OXYGEN MASK CARTRIDGE									Service ATA:35
PN:UNKN	MOS	30-Jun-24	31-May-30 (M)	72		27.5	31-May-2030	1326 d	LIFE LIMIT
SN:UNKNOWN	HRS								
	AFL								
Manufacture Date:: 30-Jun-24									
PROC. REF: AMM 12-B-35-20-07-00A-920A-APROC. REF: AMM 12-B-35-20-07-00A-920A-A									
35-20/453 DISCARD NO. 4 RH SEAT PASSENGER OXYGEN MASK CARTRIDGE									Service ATA:35
PN:UNKN	MOS	30-Jun-24	31-May-30 (M)	72		27.5	31-May-2030	1326 d	LIFE LIMIT
SN:UNKNOWN	HRS								
	AFL								
Manufacture Date:: 30-Jun-24									
PROC. REF: AMM 12-B-35-20-07-00A-920A-APROC. REF: AMM 12-B-35-20-07-00A-920A-A									
35-20/453 DISCARD NO. 5 LH SEAT PASSENGER OXYGEN MASK CARTRIDGE									Service ATA:35
PN:UNKN	MOS	30-Jun-24	31-May-30 (M)	72		27.5	31-May-2030	1326 d	LIFE LIMIT
SN:UNKNOWN	HRS								
	AFL								
Manufacture Date:: 30-Jun-24									
PROC. REF: AMM 12-B-35-20-07-00A-920A-APROC. REF: AMM 12-B-35-20-07-00A-920A-A									
35-20/453 DISCARD NO. 6 RH SEAT PASSENGER OXYGEN MASK CARTRIDGE									Service ATA:35
PN:UNKN	MOS	30-Apr-23	30-Apr-29 (M)	72		41.5	30-Apr-2029	930 d	LIFE LIMIT
SN:UNKNOWN	HRS								
	AFL								
Manufacture Date:: 30-Apr-23									
PROC. REF: AMM 12-B-35-20-07-00A-920A-APROC. REF: AMM 12-B-35-20-07-00A-920A-A									

^ - Component service life remaining is based on Accumulated Total Cycles as determined by CAMP's implementation of the low-cycle fatigue formula and is not endorsed by Pratt & Whitney Canada

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Life Limit / Overhaul Report

Model: PC-12/47G PRO Serial: 3028 RegNo: OK-CEO HRS: 84:54 AFL: 72 As Of: 11-Oct-2026

13-Oct-2026 08:42 AM

PN & SN	Unit	C/W	Next Due (ENG/APU) A/C	Interval	TSX/Adj.	Time Accrued	Est. Due	Remaining ^	Disposition
35-20/453 DISCARD NO. 7 LH SEAT PASSENGER OXYGEN MASK CARTRIDGE									Service ATA:35
PN:UNKN	MOS	30-Apr-23	30-Apr-29 (M)	72		41.5	30-Apr-2029	930 d	LIFE LIMIT
SN:UNKNOWN	HRS								
	AFL								
Manufacture Date:: 30-Apr-23									
PROC. REF: AMM 12-B-35-20-07-00A-920A-APROC. REF: AMM 12-B-35-20-07-00A-920A-A									
35-20/453 DISCARD NO. 8 RH SEAT PASSENGER OXYGEN MASK CARTRIDGE									Service ATA:35
PN:UNKN	MOS	31-Mar-23	28-Feb-29 (M)	72		42.4	28-Feb-2029	869 d	LIFE LIMIT
SN:UNKNOWN	HRS								
	AFL								
Manufacture Date:: 31-Mar-23									
PROC. REF: AMM 12-B-35-20-07-00A-920A-APROC. REF: AMM 12-B-35-20-07-00A-920A-A									
35-20/453 DISCARD TOILET PASSENGER OXYGEN MASK CARTRIDGE									Service ATA:35
PN:UNKN	MOS	30-Jun-24	31-May-30 (M)	72		27.5	31-May-2030	1326 d	LIFE LIMIT
SN:UNKNOWN	HRS								
	AFL								
Manufacture Date:: 30-Jun-24									
PROC. REF: AMM 12-B-35-20-07-00A-920A-APROC. REF: AMM 12-B-35-20-07-00A-920A-A									
35-CA/1 OXYGEN CYLINDER REGULATOR - OVERHAUL									Service ATA:35
PN:957.12.12.212	MOS	31-Oct-24	31-Oct-29	60		23.4	31-Oct-2029	1114 d	OVERHAUL
SN:C24102846	HRS								
	AFL								
OverHaul Date:: 31-Oct-24									
PROC. REF: AMM SIL-35-114PROC. REF: AMM SIL-35-114									
52-30/8 LIFE LIMIT - NO. 1 CARGO DOOR LOWER LUG FITTING									Service ATA:52
PN:PN	MOS	31-Jan-26				8.4	03-May-2134		LIFE LIMIT
SN:UNKNOWN	HRS	0	13000	13000		84:54		12915:06	
	AFL	0	17000	17000		72		16928	
PROC. REF: AMM 12-B-52-30-07-00A-920A-APROC. REF: AMM 12-B-52-30-07-00A-920A-A									

^ - Component service life remaining is based on Accumulated Total Cycles as determined by CAMP's implementation of the low-cycle fatigue formula and is not endorsed by Pratt & Whitney Canada

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Life Limit / Overhaul Report

Model: PC-12/47G PRO Serial: 3028 RegNo: OK-CEO HRS: 84:54 AFL: 72 As Of: 11-Oct-2026

13-Oct-2026 08:42 AM

PN & SN	Unit	C/W	Next Due (ENG/APU) A/C	Interval	TSX/Adj.	Time Accrued	Est. Due	Remaining ^	Disposition
52-30/8	LIFE LIMIT - NO. 2 CARGO DOOR LOWER LUG FITTING							Service	ATA:52
PN:PN	MOS	31-Jan-26				8.4	03-May-2134		LIFE LIMIT
SN:UNKNOWN	HRS	0	13000	13000		84:54		12915:06	
	AFL	0	17000	17000		72		16928	
PROC. REF: AMM 12-B-52-30-07-00A-920A-APROC. REF: AMM 12-B-52-30-07-00A-920A-A									
52-30/8	LIFE LIMIT - NO. 3 CARGO DOOR LOWER LUG FITTING							Service	ATA:52
PN:PN	MOS	31-Jan-26				8.4	03-May-2134		LIFE LIMIT
SN:UNKNOWN	HRS	0	13000	13000		84:54		12915:06	
	AFL	0	17000	17000		72		16928	
PROC. REF: AMM 12-B-52-30-07-00A-920A-APROC. REF: AMM 12-B-52-30-07-00A-920A-A									
53-00/324	LIFE LIMIT - FUSELAGE AND ASSOCIATED STRUCTURE - POST SB 04-009							Service	ATA:53
PN:553.00.12.035	MOS	31-Jan-26				8.4	09-Apr-2234		LIFE LIMIT
SN:7298	HRS	0	25000	25000		84:54		24915:06	
	AFL	0	30000	30000		72		29928	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
53-00/9	LIFE LIMIT - FUSELAGE AND ASSOCIATED STRUCTURE - PRE SB 04-009							Service	ATA:53
PN:553.00.12.035	MOS	31-Jan-26				8.4	18-Aug-2192		LIFE LIMIT
SN:7298	HRS	0	20000	20000		84:54		19915:06	
	AFL	0	27000	27000		72		26928	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
55-00/10	LIFE LIMIT - TAIL STRUCTURE - PRE SB 04-009							Service	ATA:55
PN:PN	MOS	31-Jan-26				8.4	18-Aug-2192		LIFE LIMIT
SN:UNKNOWN	HRS	0	20000	20000		84:54		19915:06	
	AFL	0	27000	27000		72		26928	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
55-00/325	LIFE LIMIT - TAIL STRUCTURE - POST SB 04-009							Service	ATA:55
PN:PN	MOS	31-Jan-26				8.4	09-Apr-2234		LIFE LIMIT
SN:UNKNOWN	HRS	0	25000	25000		84:54		24915:06	
	AFL	0	30000	30000		72		29928	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

^ - Component service life remaining is based on Accumulated Total Cycles as determined by CAMP's implementation of the low-cycle fatigue formula and is not endorsed by Pratt & Whitney Canada

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Life Limit / Overhaul Report

Model: PC-12/47G PRO Serial: 3028 RegNo: OK-CEO HRS: 84:54 AFL: 72 As Of: 11-Oct-2026

13-Oct-2026 08:42 AM

PN & SN	Unit	C/W	Next Due (ENG/APU) A/C	Interval	TSX/Adj.	Time Accrued	Est. Due	Remaining ^	Disposition
55-10/415	LIFE LIMIT - HORIZONTAL STABILIZER							Service	ATA:55
PN:555.10.12.039	MOS	31-Jan-26				8.4	09-Apr-2234		LIFE LIMIT
SN:2327	HRS	0	25000	25000		84:54		24915:06	
	AFL	0	30000	30000		72		29928	
PROC. REF: AMM 12-B-55-10-01-00A-920A-APROC. REF: AMM 12-B-55-10-01-00A-920A-A									
57-00/11	LIFE LIMIT - LEFT WING STRUCTURE - PRE SB 04-009							Service	ATA:57
PN:557.00.12.067	MOS	31-Jan-26				8.4	18-Aug-2192		LIFE LIMIT
SN:7298	HRS	0	20000	20000		84:54		19915:06	
	AFL	0	27000	27000		72		26928	
PROC. REF: AMM 12-D-04-00-00-00A-000A-APROC. REF: AMM 12-D-04-00-00-00A-000A-A									
57-00/11	LIFE LIMIT - RIGHT WING STRUCTURE - PRE SB 04-009							Service	ATA:57
PN:557.00.12.068	MOS	31-Jan-26				8.4	18-Aug-2192		LIFE LIMIT
SN:7298	HRS	0	20000	20000		84:54		19915:06	
	AFL	0	27000	27000		72		26928	
PROC. REF: AMM 12-D-04-00-00-00A-000A-APROC. REF: AMM 12-D-04-00-00-00A-000A-A									
57-00/326	LIFE LIMIT - LEFT WING STRUCTURE - POST SB 04-009							Service	ATA:57
PN:557.00.12.067	MOS	31-Jan-26				8.4	09-Apr-2234		LIFE LIMIT
SN:7298	HRS	0	25000	25000		84:54		24915:06	
	AFL	0	30000	30000		72		29928	
PROC. REF: AMM 12-D-04-00-00-00A-000A-APROC. REF: AMM 12-D-04-00-00-00A-000A-A									
57-00/326	LIFE LIMIT - RIGHT WING STRUCTURE - POST SB 04-009							Service	ATA:57
PN:557.00.12.068	MOS	31-Jan-26				8.4	09-Apr-2234		LIFE LIMIT
SN:7298	HRS	0	25000	25000		84:54		24915:06	
	AFL	0	30000	30000		72		29928	
PROC. REF: AMM 12-D-04-00-00-00A-000A-APROC. REF: AMM 12-D-04-00-00-00A-000A-A									
61-10/08	NO. 1 PROPELLER - DE-ICE COMPONENT OVERHAUL							Service	ATA:61
	MOS	22-Jan-26	22-Jan-32	72		8.7	22-Jan-2032	1927 d	OVERHAUL
	HRS	0	(4000) 4000	4000		84:54		3915:06	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

^ - Component service life remaining is based on Accumulated Total Cycles as determined by CAMP's implementation of the low-cycle fatigue formula and is not endorsed by Pratt & Whitney Canada

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Life Limit / Overhaul Report

Model: PC-12/47G PRO Serial: 3028 RegNo: OK-CEO HRS: 84:54 AFL: 72 As Of: 11-Oct-2026

13-Oct-2026 08:42 AM

PN & SN	Unit	C/W	Next Due (ENG/APU) A/C	Interval	TSX/Adj.	Time Accrued	Est. Due	Remaining ^	Disposition
61-10/37	NO. 1 PROPELLER - OVERHAUL								Service ATA:61
	MOS	22-Jan-26	22-Jan-32	72		8.7	22-Jan-2032	1927 d	OVERHAUL
	HRS	0	(4000) 4000	4000		84:54		3915:06	
PROC. REF: SL HC-SL-61-61Y, POM 61-00-47PROC. REF: SL HC-SL-61-61Y, POM 61-00-47									
61-CA/3	NO. 1 ENGINE - OVERHAUL PROPELLER CONTROL UNIT								Service ATA:61
PN:3126986-03	MOS	14-Nov-25				11	18-Sep-2067		OVERHAUL
SN:WDA150059	HRS	0	(5000) 5000	5000 (+500)		84:54		4915:06 (+500)	
	ENC	0				75			
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
71-00/16	LIFE LIMIT - ENGINE MOUNTING FRAME - PRE SB 04-009								Service ATA:71
PN:571.20.12.008	MOS	31-Jan-26				8.4	18-Aug-2192		LIFE LIMIT
SN:660	HRS	0	20000	20000		84:54		19915:06	
	AFL	0	27000	27000		72		26928	
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
71-00/17	LIFE LIMIT - ENGINE MOUNTING FRAME, REPLACE ALL BOLTS, WASHERS AND NUTS								Service ATA:71
PN:571.20.12.008	MOS	31-Jan-26				8.4	06-Sep-2117		LIFE LIMIT
SN:660	HRS	0	11000	11000		84:54		10915:06	
	AFL	0				72			
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
71-00/327	LIFE LIMIT - ENGINE MOUNTING FRAME - POST SB 04-009								Service ATA:71
PN:571.20.12.008	MOS	31-Jan-26				8.4	09-Apr-2234		LIFE LIMIT
SN:660	HRS	0	25000	25000		84:54		24915:06	
	AFL	0	30000	30000		72		29928	
PROC. REF: AMM 12-C-71-00-05-00A-920A-APROC. REF: AMM 12-C-71-00-05-00A-920A-A									
71-00/490	OVERHAUL LOWER LEFT ENGINE SHOCK MOUNT ASSEMBLY								Service ATA:71
PN:944.81.21.409	MOS	31-Jan-26				8.4	18-Sep-2067		OVERHAUL
SN:17868	HRS	0	5000	5000 (+500/-500)		84:54		4915:06 (+500)	
	AFL	0				72			
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

^ - Component service life remaining is based on Accumulated Total Cycles as determined by CAMP's implementation of the low-cycle fatigue formula and is not endorsed by Pratt & Whitney Canada

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Life Limit / Overhaul Report

Model: PC-12/47G PRO Serial: 3028 RegNo: OK-CEO HRS: 84:54 AFL: 72 As Of: 11-Oct-2026

13-Oct-2026 08:42 AM

PN & SN	Unit	C/W	Next Due (ENG/APU) A/C	Interval	TSX/Adj.	Time Accrued	Est. Due	Remaining ^	Disposition
71-00/490 OVERHAUL LOWER RIGHT ENGINE SHOCK MOUNT ASSEMBLY									Service ATA:71
PN:944.81.21.409	MOS	31-Jan-26				8.4	18-Sep-2067		OVERHAUL
SN:17905	HRS	0	5000	5000 (+500/-500)		84:54		4915:06 (+500)	
	AFL	0				72			
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
71-00/490 OVERHAUL UPPER CENTER ENGINE SHOCK MOUNT ASSEMBLY									Service ATA:71
PN:944.81.21.409	MOS	31-Jan-26				8.4	18-Sep-2067		OVERHAUL
SN:17893	HRS	0	5000	5000 (+500/-500)		84:54		4915:06 (+500)	
	AFL	0				72			
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
71-00/490 OVERHAUL UPPER LEFT ENGINE SHOCK MOUNT ASSEMBLY									Service ATA:71
PN:944.81.21.409	MOS	31-Jan-26				8.4	18-Sep-2067		OVERHAUL
SN:17876	HRS	0	5000	5000 (+500/-500)		84:54		4915:06 (+500)	
	AFL	0				72			
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
71-00/490 OVERHAUL UPPER RIGHT ENGINE SHOCK MOUNT ASSEMBLY									Service ATA:71
PN:944.81.21.409	MOS	31-Jan-26				8.4	18-Sep-2067		OVERHAUL
SN:17895	HRS	0	5000	5000 (+500/-500)		84:54		4915:06 (+500)	
	AFL	0				72			
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
72-00/18/CT-1 NO. 1 ENGINE - REPLACE NO. 1 COMPRESSOR TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-51-01, EM 72-51-01PROC. REF: EM 72-51-01, EM 72-51-01									
72-00/18/CT-10 NO. 1 ENGINE - REPLACE NO. 10 COMPRESSOR TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-51-01, EM 72-51-01PROC. REF: EM 72-51-01, EM 72-51-01									

^ - Component service life remaining is based on Accumulated Total Cycles as determined by CAMP's implementation of the low-cycle fatigue formula and is not endorsed by Pratt & Whitney Canada

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Life Limit / Overhaul Report

Model: PC-12/47G PRO Serial: 3028 RegNo: OK-CEO HRS: 84:54 AFL: 72 As Of: 11-Oct-2026

13-Oct-2026 08:42 AM

PN & SN	Unit	C/W	Next Due (ENG/APU) A/C	Interval	TSX/Adj.	Time Accrued	Est. Due	Remaining ^	Disposition
72-00/18/CT-11 NO. 1 ENGINE - REPLACE NO. 11 COMPRESSOR TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-51-01, EM 72-51-01PROC. REF: EM 72-51-01, EM 72-51-01									
72-00/18/CT-12 NO. 1 ENGINE - REPLACE NO. 12 COMPRESSOR TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-51-01, EM 72-51-01PROC. REF: EM 72-51-01, EM 72-51-01									
72-00/18/CT-13 NO. 1 ENGINE - REPLACE NO. 13 COMPRESSOR TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-51-01, EM 72-51-01PROC. REF: EM 72-51-01, EM 72-51-01									
72-00/18/CT-14 NO. 1 ENGINE - REPLACE NO. 14 COMPRESSOR TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-51-01, EM 72-51-01PROC. REF: EM 72-51-01, EM 72-51-01									
72-00/18/CT-15 NO. 1 ENGINE - REPLACE NO. 15 COMPRESSOR TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-51-01, EM 72-51-01PROC. REF: EM 72-51-01, EM 72-51-01									

^ - Component service life remaining is based on Accumulated Total Cycles as determined by CAMP's implementation of the low-cycle fatigue formula and is not endorsed by Pratt & Whitney Canada

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Life Limit / Overhaul Report

Model: PC-12/47G PRO Serial: 3028 RegNo: OK-CEO HRS: 84:54 AFL: 72 As Of: 11-Oct-2026

13-Oct-2026 08:42 AM

PN & SN	Unit	C/W	Next Due (ENG/APU) A/C	Interval	TSX/Adj.	Time Accrued	Est. Due	Remaining ^	Disposition
72-00/18/CT-16 NO. 1 ENGINE - REPLACE NO. 16 COMPRESSOR TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-51-01, EM 72-51-01PROC. REF: EM 72-51-01, EM 72-51-01									
72-00/18/CT-17 NO. 1 ENGINE - REPLACE NO. 17 COMPRESSOR TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-51-01, EM 72-51-01PROC. REF: EM 72-51-01, EM 72-51-01									
72-00/18/CT-18 NO. 1 ENGINE - REPLACE NO. 18 COMPRESSOR TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-51-01, EM 72-51-01PROC. REF: EM 72-51-01, EM 72-51-01									
72-00/18/CT-19 NO. 1 ENGINE - REPLACE NO. 19 COMPRESSOR TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-51-01, EM 72-51-01PROC. REF: EM 72-51-01, EM 72-51-01									
72-00/18/CT-2 NO. 1 ENGINE - REPLACE NO. 2 COMPRESSOR TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-51-01, EM 72-51-01PROC. REF: EM 72-51-01, EM 72-51-01									

^ - Component service life remaining is based on Accumulated Total Cycles as determined by CAMP's implementation of the low-cycle fatigue formula and is not endorsed by Pratt & Whitney Canada

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Life Limit / Overhaul Report

Model: PC-12/47G PRO Serial: 3028 RegNo: OK-CEO HRS: 84:54 AFL: 72 As Of: 11-Oct-2026

13-Oct-2026 08:42 AM

PN & SN	Unit	C/W	Next Due (ENG/APU) A/C	Interval	TSX/Adj.	Time Accrued	Est. Due	Remaining ^	Disposition
72-00/18/CT-20 NO. 1 ENGINE - REPLACE NO. 20 COMPRESSOR TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-51-01, EM 72-51-01PROC. REF: EM 72-51-01, EM 72-51-01									
72-00/18/CT-21 NO. 1 ENGINE - REPLACE NO. 21 COMPRESSOR TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-51-01, EM 72-51-01PROC. REF: EM 72-51-01, EM 72-51-01									
72-00/18/CT-22 NO. 1 ENGINE - REPLACE NO. 22 COMPRESSOR TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-51-01, EM 72-51-01PROC. REF: EM 72-51-01, EM 72-51-01									
72-00/18/CT-23 NO. 1 ENGINE - REPLACE NO. 23 COMPRESSOR TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-51-01, EM 72-51-01PROC. REF: EM 72-51-01, EM 72-51-01									
72-00/18/CT-24 NO. 1 ENGINE - REPLACE NO. 24 COMPRESSOR TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-51-01, EM 72-51-01PROC. REF: EM 72-51-01, EM 72-51-01									

^ - Component service life remaining is based on Accumulated Total Cycles as determined by CAMP's implementation of the low-cycle fatigue formula and is not endorsed by Pratt & Whitney Canada

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Life Limit / Overhaul Report

Model: PC-12/47G PRO Serial: 3028 RegNo: OK-CEO HRS: 84:54 AFL: 72 As Of: 11-Oct-2026

13-Oct-2026 08:42 AM

PN & SN	Unit	C/W	Next Due (ENG/APU) A/C	Interval	TSX/Adj.	Time Accrued	Est. Due	Remaining ^	Disposition
72-00/18/CT-25 NO. 1 ENGINE - REPLACE NO. 25 COMPRESSOR TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-51-01, EM 72-51-01PROC. REF: EM 72-51-01, EM 72-51-01									
72-00/18/CT-26 NO. 1 ENGINE - REPLACE NO. 26 COMPRESSOR TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-51-01, EM 72-51-01PROC. REF: EM 72-51-01, EM 72-51-01									
72-00/18/CT-27 NO. 1 ENGINE - REPLACE NO. 27 COMPRESSOR TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-51-01, EM 72-51-01PROC. REF: EM 72-51-01, EM 72-51-01									
72-00/18/CT-28 NO. 1 ENGINE - REPLACE NO. 28 COMPRESSOR TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-51-01, EM 72-51-01PROC. REF: EM 72-51-01, EM 72-51-01									
72-00/18/CT-29 NO. 1 ENGINE - REPLACE NO. 29 COMPRESSOR TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-51-01, EM 72-51-01PROC. REF: EM 72-51-01, EM 72-51-01									

^ - Component service life remaining is based on Accumulated Total Cycles as determined by CAMP's implementation of the low-cycle fatigue formula and is not endorsed by Pratt & Whitney Canada

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Life Limit / Overhaul Report

Model: PC-12/47G PRO Serial: 3028 RegNo: OK-CEO HRS: 84:54 AFL: 72 As Of: 11-Oct-2026

13-Oct-2026 08:42 AM

PN & SN	Unit	C/W	Next Due (ENG/APU) A/C	Interval	TSX/Adj.	Time Accrued	Est. Due	Remaining ^	Disposition
72-00/18/CT-3 NO. 1 ENGINE - REPLACE NO. 3 COMPRESSOR TURBINE BLADE Service ATA:72									
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-51-01, EM 72-51-01PROC. REF: EM 72-51-01, EM 72-51-01									
72-00/18/CT-30 NO. 1 ENGINE - REPLACE NO. 30 COMPRESSOR TURBINE BLADE Service ATA:72									
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-51-01, EM 72-51-01PROC. REF: EM 72-51-01, EM 72-51-01									
72-00/18/CT-31 NO. 1 ENGINE - REPLACE NO. 31 COMPRESSOR TURBINE BLADE Service ATA:72									
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-51-01, EM 72-51-01PROC. REF: EM 72-51-01, EM 72-51-01									
72-00/18/CT-32 NO. 1 ENGINE - REPLACE NO. 32 COMPRESSOR TURBINE BLADE Service ATA:72									
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-51-01, EM 72-51-01PROC. REF: EM 72-51-01, EM 72-51-01									
72-00/18/CT-33 NO. 1 ENGINE - REPLACE NO. 33 COMPRESSOR TURBINE BLADE Service ATA:72									
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-51-01, EM 72-51-01PROC. REF: EM 72-51-01, EM 72-51-01									

^ - Component service life remaining is based on Accumulated Total Cycles as determined by CAMP's implementation of the low-cycle fatigue formula and is not endorsed by Pratt & Whitney Canada

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Life Limit / Overhaul Report

Model: PC-12/47G PRO Serial: 3028 RegNo: OK-CEO HRS: 84:54 AFL: 72 As Of: 11-Oct-2026

13-Oct-2026 08:42 AM

PN & SN	Unit	C/W	Next Due (ENG/APU) A/C	Interval	TSX/Adj.	Time Accrued	Est. Due	Remaining ^	Disposition
72-00/18/CT-34 NO. 1 ENGINE - REPLACE NO. 34 COMPRESSOR TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-51-01, EM 72-51-01PROC. REF: EM 72-51-01, EM 72-51-01									
72-00/18/CT-35 NO. 1 ENGINE - REPLACE NO. 35 COMPRESSOR TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-51-01, EM 72-51-01PROC. REF: EM 72-51-01, EM 72-51-01									
72-00/18/CT-36 NO. 1 ENGINE - REPLACE NO. 36 COMPRESSOR TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-51-01, EM 72-51-01PROC. REF: EM 72-51-01, EM 72-51-01									
72-00/18/CT-37 NO. 1 ENGINE - REPLACE NO. 37 COMPRESSOR TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-51-01, EM 72-51-01PROC. REF: EM 72-51-01, EM 72-51-01									
72-00/18/CT-38 NO. 1 ENGINE - REPLACE NO. 38 COMPRESSOR TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-51-01, EM 72-51-01PROC. REF: EM 72-51-01, EM 72-51-01									

^ - Component service life remaining is based on Accumulated Total Cycles as determined by CAMP's implementation of the low-cycle fatigue formula and is not endorsed by Pratt & Whitney Canada

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Life Limit / Overhaul Report

Model: PC-12/47G PRO Serial: 3028 RegNo: OK-CEO HRS: 84:54 AFL: 72 As Of: 11-Oct-2026

13-Oct-2026 08:42 AM

PN & SN	Unit	C/W	Next Due (ENG/APU) A/C	Interval	TSX/Adj.	Time Accrued	Est. Due	Remaining ^	Disposition
72-00/18/CT-39 NO. 1 ENGINE - REPLACE NO. 39 COMPRESSOR TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-51-01, EM 72-51-01PROC. REF: EM 72-51-01, EM 72-51-01									
72-00/18/CT-4 NO. 1 ENGINE - REPLACE NO. 4 COMPRESSOR TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-51-01, EM 72-51-01PROC. REF: EM 72-51-01, EM 72-51-01									
72-00/18/CT-40 NO. 1 ENGINE - REPLACE NO. 40 COMPRESSOR TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-51-01, EM 72-51-01PROC. REF: EM 72-51-01, EM 72-51-01									
72-00/18/CT-41 NO. 1 ENGINE - REPLACE NO. 41 COMPRESSOR TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-51-01, EM 72-51-01PROC. REF: EM 72-51-01, EM 72-51-01									
72-00/18/CT-42 NO. 1 ENGINE - REPLACE NO. 42 COMPRESSOR TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-51-01, EM 72-51-01PROC. REF: EM 72-51-01, EM 72-51-01									

^ - Component service life remaining is based on Accumulated Total Cycles as determined by CAMP's implementation of the low-cycle fatigue formula and is not endorsed by Pratt & Whitney Canada

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Life Limit / Overhaul Report

Model: PC-12/47G PRO Serial: 3028 RegNo: OK-CEO HRS: 84:54 AFL: 72 As Of: 11-Oct-2026

13-Oct-2026 08:42 AM

PN & SN	Unit	C/W	Next Due (ENG/APU) A/C	Interval	TSX/Adj.	Time Accrued	Est. Due	Remaining ^	Disposition
72-00/18/CT-43 NO. 1 ENGINE - REPLACE NO. 43 COMPRESSOR TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-51-01, EM 72-51-01PROC. REF: EM 72-51-01, EM 72-51-01									
72-00/18/CT-44 NO. 1 ENGINE - REPLACE NO. 44 COMPRESSOR TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-51-01, EM 72-51-01PROC. REF: EM 72-51-01, EM 72-51-01									
72-00/18/CT-45 NO. 1 ENGINE - REPLACE NO. 45 COMPRESSOR TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-51-01, EM 72-51-01PROC. REF: EM 72-51-01, EM 72-51-01									
72-00/18/CT-46 NO. 1 ENGINE - REPLACE NO. 46 COMPRESSOR TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-51-01, EM 72-51-01PROC. REF: EM 72-51-01, EM 72-51-01									
72-00/18/CT-47 NO. 1 ENGINE - REPLACE NO. 47 COMPRESSOR TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-51-01, EM 72-51-01PROC. REF: EM 72-51-01, EM 72-51-01									

^ - Component service life remaining is based on Accumulated Total Cycles as determined by CAMP's implementation of the low-cycle fatigue formula and is not endorsed by Pratt & Whitney Canada

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Life Limit / Overhaul Report

Model: PC-12/47G PRO Serial: 3028 RegNo: OK-CEO HRS: 84:54 AFL: 72 As Of: 11-Oct-2026

13-Oct-2026 08:42 AM

PN & SN	Unit	C/W	Next Due (ENG/APU) A/C	Interval	TSX/Adj.	Time Accrued	Est. Due	Remaining ^	Disposition
72-00/18/CT-48 NO. 1 ENGINE - REPLACE NO. 48 COMPRESSOR TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-51-01, EM 72-51-01PROC. REF: EM 72-51-01, EM 72-51-01									
72-00/18/CT-49 NO. 1 ENGINE - REPLACE NO. 49 COMPRESSOR TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-51-01, EM 72-51-01PROC. REF: EM 72-51-01, EM 72-51-01									
72-00/18/CT-5 NO. 1 ENGINE - REPLACE NO. 5 COMPRESSOR TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-51-01, EM 72-51-01PROC. REF: EM 72-51-01, EM 72-51-01									
72-00/18/CT-6 NO. 1 ENGINE - REPLACE NO. 6 COMPRESSOR TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-51-01, EM 72-51-01PROC. REF: EM 72-51-01, EM 72-51-01									
72-00/18/CT-7 NO. 1 ENGINE - REPLACE NO. 7 COMPRESSOR TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-51-01, EM 72-51-01PROC. REF: EM 72-51-01, EM 72-51-01									

^ - Component service life remaining is based on Accumulated Total Cycles as determined by CAMP's implementation of the low-cycle fatigue formula and is not endorsed by Pratt & Whitney Canada

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Life Limit / Overhaul Report

Model: PC-12/47G PRO Serial: 3028 RegNo: OK-CEO HRS: 84:54 AFL: 72 As Of: 11-Oct-2026

13-Oct-2026 08:42 AM

PN & SN	Unit	C/W	Next Due (ENG/APU) A/C	Interval	TSX/Adj.	Time Accrued	Est. Due	Remaining ^	Disposition
72-00/18/CT-8 NO. 1 ENGINE - REPLACE NO. 8 COMPRESSOR TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-51-01, EM 72-51-01PROC. REF: EM 72-51-01, EM 72-51-01									
72-00/18/CT-9 NO. 1 ENGINE - REPLACE NO. 9 COMPRESSOR TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-51-01, EM 72-51-01PROC. REF: EM 72-51-01, EM 72-51-01									
72-00/18/PT2-1 NO. 1 ENGINE - REPLACE NO. 1 2ND STAGE POWER TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-52-03PROC. REF: EM 72-52-03									
72-00/18/PT2-10 NO. 1 ENGINE - REPLACE NO. 10 2ND STAGE POWER TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-52-03PROC. REF: EM 72-52-03									
72-00/18/PT2-11 NO. 1 ENGINE - REPLACE NO. 11 2ND STAGE POWER TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-52-03PROC. REF: EM 72-52-03									

^ - Component service life remaining is based on Accumulated Total Cycles as determined by CAMP's implementation of the low-cycle fatigue formula and is not endorsed by Pratt & Whitney Canada

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Life Limit / Overhaul Report

Model: PC-12/47G PRO Serial: 3028 RegNo: OK-CEO HRS: 84:54 AFL: 72 As Of: 11-Oct-2026

13-Oct-2026 08:42 AM

PN & SN	Unit	C/W	Next Due (ENG/APU) A/C	Interval	TSX/Adj.	Time Accrued	Est. Due	Remaining ^	Disposition
72-00/18/PT2-12 NO. 1 ENGINE - REPLACE NO. 12 2ND STAGE POWER TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-52-03PROC. REF: EM 72-52-03									
72-00/18/PT2-13 NO. 1 ENGINE - REPLACE NO. 13 2ND STAGE POWER TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-52-03PROC. REF: EM 72-52-03									
72-00/18/PT2-14 NO. 1 ENGINE - REPLACE NO. 14 2ND STAGE POWER TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-52-03PROC. REF: EM 72-52-03									
72-00/18/PT2-15 NO. 1 ENGINE - REPLACE NO. 15 2ND STAGE POWER TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-52-03PROC. REF: EM 72-52-03									
72-00/18/PT2-16 NO. 1 ENGINE - REPLACE NO. 16 2ND STAGE POWER TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-52-03PROC. REF: EM 72-52-03									

^ - Component service life remaining is based on Accumulated Total Cycles as determined by CAMP's implementation of the low-cycle fatigue formula and is not endorsed by Pratt & Whitney Canada

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Life Limit / Overhaul Report

Model: PC-12/47G PRO Serial: 3028 RegNo: OK-CEO HRS: 84:54 AFL: 72 As Of: 11-Oct-2026

13-Oct-2026 08:42 AM

PN & SN	Unit	C/W	Next Due (ENG/APU) A/C	Interval	TSX/Adj.	Time Accrued	Est. Due	Remaining ^	Disposition
72-00/18/PT2-17 NO. 1 ENGINE - REPLACE NO. 17 2ND STAGE POWER TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-52-03PROC. REF: EM 72-52-03									
72-00/18/PT2-18 NO. 1 ENGINE - REPLACE NO. 18 2ND STAGE POWER TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-52-03PROC. REF: EM 72-52-03									
72-00/18/PT2-19 NO. 1 ENGINE - REPLACE NO. 19 2ND STAGE POWER TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-52-03PROC. REF: EM 72-52-03									
72-00/18/PT2-2 NO. 1 ENGINE - REPLACE NO. 2 2ND STAGE POWER TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-52-03PROC. REF: EM 72-52-03									
72-00/18/PT2-20 NO. 1 ENGINE - REPLACE NO. 20 2ND STAGE POWER TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-52-03PROC. REF: EM 72-52-03									

^ - Component service life remaining is based on Accumulated Total Cycles as determined by CAMP's implementation of the low-cycle fatigue formula and is not endorsed by Pratt & Whitney Canada

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Life Limit / Overhaul Report

Model: PC-12/47G PRO Serial: 3028 RegNo: OK-CEO HRS: 84:54 AFL: 72 As Of: 11-Oct-2026

13-Oct-2026 08:42 AM

PN & SN	Unit	C/W	Next Due (ENG/APU) A/C	Interval	TSX/Adj.	Time Accrued	Est. Due	Remaining ^	Disposition
72-00/18/PT2-21 NO. 1 ENGINE - REPLACE NO. 21 2ND STAGE POWER TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-52-03PROC. REF: EM 72-52-03									
72-00/18/PT2-22 NO. 1 ENGINE - REPLACE NO. 22 2ND STAGE POWER TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-52-03PROC. REF: EM 72-52-03									
72-00/18/PT2-23 NO. 1 ENGINE - REPLACE NO. 23 2ND STAGE POWER TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-52-03PROC. REF: EM 72-52-03									
72-00/18/PT2-24 NO. 1 ENGINE - REPLACE NO. 24 2ND STAGE POWER TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-52-03PROC. REF: EM 72-52-03									
72-00/18/PT2-25 NO. 1 ENGINE - REPLACE NO. 25 2ND STAGE POWER TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-52-03PROC. REF: EM 72-52-03									

^ - Component service life remaining is based on Accumulated Total Cycles as determined by CAMP's implementation of the low-cycle fatigue formula and is not endorsed by Pratt & Whitney Canada

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Life Limit / Overhaul Report

Model: PC-12/47G PRO Serial: 3028 RegNo: OK-CEO HRS: 84:54 AFL: 72 As Of: 11-Oct-2026

13-Oct-2026 08:42 AM

PN & SN	Unit	C/W	Next Due (ENG/APU) A/C	Interval	TSX/Adj.	Time Accrued	Est. Due	Remaining ^	Disposition
72-00/18/PT2-26 NO. 1 ENGINE - REPLACE NO. 26 2ND STAGE POWER TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-52-03PROC. REF: EM 72-52-03									
72-00/18/PT2-27 NO. 1 ENGINE - REPLACE NO. 27 2ND STAGE POWER TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-52-03PROC. REF: EM 72-52-03									
72-00/18/PT2-28 NO. 1 ENGINE - REPLACE NO. 28 2ND STAGE POWER TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-52-03PROC. REF: EM 72-52-03									
72-00/18/PT2-29 NO. 1 ENGINE - REPLACE NO. 29 2ND STAGE POWER TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-52-03PROC. REF: EM 72-52-03									
72-00/18/PT2-3 NO. 1 ENGINE - REPLACE NO. 3 2ND STAGE POWER TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-52-03PROC. REF: EM 72-52-03									

^ - Component service life remaining is based on Accumulated Total Cycles as determined by CAMP's implementation of the low-cycle fatigue formula and is not endorsed by Pratt & Whitney Canada

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Life Limit / Overhaul Report

Model: PC-12/47G PRO Serial: 3028 RegNo: OK-CEO HRS: 84:54 AFL: 72 As Of: 11-Oct-2026

13-Oct-2026 08:42 AM

PN & SN	Unit	C/W	Next Due (ENG/APU) A/C	Interval	TSX/Adj.	Time Accrued	Est. Due	Remaining ^	Disposition
72-00/18/PT2-30 NO. 1 ENGINE - REPLACE NO. 30 2ND STAGE POWER TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-52-03PROC. REF: EM 72-52-03									
72-00/18/PT2-31 NO. 1 ENGINE - REPLACE NO. 31 2ND STAGE POWER TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-52-03PROC. REF: EM 72-52-03									
72-00/18/PT2-32 NO. 1 ENGINE - REPLACE NO. 32 2ND STAGE POWER TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-52-03PROC. REF: EM 72-52-03									
72-00/18/PT2-33 NO. 1 ENGINE - REPLACE NO. 33 2ND STAGE POWER TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-52-03PROC. REF: EM 72-52-03									
72-00/18/PT2-34 NO. 1 ENGINE - REPLACE NO. 34 2ND STAGE POWER TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-52-03PROC. REF: EM 72-52-03									

^ - Component service life remaining is based on Accumulated Total Cycles as determined by CAMP's implementation of the low-cycle fatigue formula and is not endorsed by Pratt & Whitney Canada

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Life Limit / Overhaul Report

Model: PC-12/47G PRO Serial: 3028 RegNo: OK-CEO HRS: 84:54 AFL: 72 As Of: 11-Oct-2026

13-Oct-2026 08:42 AM

PN & SN	Unit	C/W	Next Due (ENG/APU) A/C	Interval	TSX/Adj.	Time Accrued	Est. Due	Remaining ^	Disposition
72-00/18/PT2-35 NO. 1 ENGINE - REPLACE NO. 35 2ND STAGE POWER TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-52-03PROC. REF: EM 72-52-03									
72-00/18/PT2-36 NO. 1 ENGINE - REPLACE NO. 36 2ND STAGE POWER TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-52-03PROC. REF: EM 72-52-03									
72-00/18/PT2-37 NO. 1 ENGINE - REPLACE NO. 37 2ND STAGE POWER TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-52-03PROC. REF: EM 72-52-03									
72-00/18/PT2-38 NO. 1 ENGINE - REPLACE NO. 38 2ND STAGE POWER TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-52-03PROC. REF: EM 72-52-03									
72-00/18/PT2-39 NO. 1 ENGINE - REPLACE NO. 39 2ND STAGE POWER TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-52-03PROC. REF: EM 72-52-03									

^ - Component service life remaining is based on Accumulated Total Cycles as determined by CAMP's implementation of the low-cycle fatigue formula and is not endorsed by Pratt & Whitney Canada

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Life Limit / Overhaul Report

Model: PC-12/47G PRO Serial: 3028 RegNo: OK-CEO HRS: 84:54 AFL: 72 As Of: 11-Oct-2026

13-Oct-2026 08:42 AM

PN & SN	Unit	C/W	Next Due (ENG/APU) A/C	Interval	TSX/Adj.	Time Accrued	Est. Due	Remaining ^	Disposition
72-00/18/PT2-4 NO. 1 ENGINE - REPLACE NO. 4 2ND STAGE POWER TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-52-03PROC. REF: EM 72-52-03									
72-00/18/PT2-40 NO. 1 ENGINE - REPLACE NO. 40 2ND STAGE POWER TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-52-03PROC. REF: EM 72-52-03									
72-00/18/PT2-41 NO. 1 ENGINE - REPLACE NO. 41 2ND STAGE POWER TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-52-03PROC. REF: EM 72-52-03									
72-00/18/PT2-42 NO. 1 ENGINE - REPLACE NO. 42 2ND STAGE POWER TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-52-03PROC. REF: EM 72-52-03									
72-00/18/PT2-43 NO. 1 ENGINE - REPLACE NO. 43 2ND STAGE POWER TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-52-03PROC. REF: EM 72-52-03									

^ - Component service life remaining is based on Accumulated Total Cycles as determined by CAMP's implementation of the low-cycle fatigue formula and is not endorsed by Pratt & Whitney Canada

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Life Limit / Overhaul Report

Model: PC-12/47G PRO Serial: 3028 RegNo: OK-CEO HRS: 84:54 AFL: 72 As Of: 11-Oct-2026

13-Oct-2026 08:42 AM

PN & SN	Unit	C/W	Next Due (ENG/APU) A/C	Interval	TSX/Adj.	Time Accrued	Est. Due	Remaining ^	Disposition
72-00/18/PT2-5 NO. 1 ENGINE - REPLACE NO. 5 2ND STAGE POWER TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-52-03PROC. REF: EM 72-52-03									
72-00/18/PT2-6 NO. 1 ENGINE - REPLACE NO. 6 2ND STAGE POWER TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-52-03PROC. REF: EM 72-52-03									
72-00/18/PT2-7 NO. 1 ENGINE - REPLACE NO. 7 2ND STAGE POWER TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-52-03PROC. REF: EM 72-52-03									
72-00/18/PT2-8 NO. 1 ENGINE - REPLACE NO. 8 2ND STAGE POWER TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-52-03PROC. REF: EM 72-52-03									
72-00/18/PT2-9 NO. 1 ENGINE - REPLACE NO. 9 2ND STAGE POWER TURBINE BLADE									Service ATA:72
PN:PN	MOS	14-Nov-25				11	18-Sep-2067		REPLACE
SN:UNKNOWN	HRS	0	(5000) 5000	5000		84:54		4915:06	
	ENC	0				75			
PROC. REF: EM 72-52-03PROC. REF: EM 72-52-03									

^ - Component service life remaining is based on Accumulated Total Cycles as determined by CAMP's implementation of the low-cycle fatigue formula and is not endorsed by Pratt & Whitney Canada

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Life Limit / Overhaul Report

Model: PC-12/47G PRO Serial: 3028 RegNo: OK-CEO HRS: 84:54 AFL: 72 As Of: 11-Oct-2026

13-Oct-2026 08:42 AM

PN & SN	Unit	C/W	Next Due (ENG/APU) A/C	Interval	TSX/Adj.	Time Accrued	Est. Due	Remaining ^	Disposition
72-00/488	NO. 1 ENGINE - OVERHAUL							Service	ATA:72
	MOS	14-Nov-25				11	18-Sep-2067		OVERHAUL
	HRS	0	(5000) 5000	5000 (+100/-100)		84:54		4915:06 (+100)	
	ENC	0				75			
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
72-00/489	NO. 1 ENGINE - ENGINE ACCESSORIES OVERHAUL							Service	ATA:72
	MOS/MSC	14-Nov-25		A/R		11			OVERHAUL
	HRS	0				84:54			
	ENC	0				75			
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
72-CA/10	NO. 1 ENGINE - SERVICE LIFE LIMIT COMPRESSOR ROTOR SHAFT							Service	ATA:72
PN:3043063	MOS	14-Nov-25				11	07-Apr-2425		LIFE LIMIT
SN:PKAAB127658	HRS	0				84:54			
	ENC	0	(24000) 23997 (M)			75		23925	
	ACCCYC	0		24000		75			
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
72-CA/11	NO. 1 ENGINE - SERVICE LIFE LIMIT 1ST-STAGE COMPRESSOR ROTOR							Service	ATA:72
PN:3042701	MOS	14-Nov-25				11	07-Apr-2425		LIFE LIMIT
SN:FRAEUBYB102	HRS	0				84:54			
	ENC	0	(24000) 23997 (M)			75		23925	
	ACCCYC	0		24000		75			
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
72-CA/12	NO. 1 ENGINE - SERVICE LIFE LIMIT 2ND-STAGE COMPRESSOR ROTOR							Service	ATA:72
PN:3040942	MOS	14-Nov-25				11	07-Apr-2425		LIFE LIMIT
SN:FRAEUBYB42	HRS	0				84:54			
	ENC	0	(24000) 23997 (M)			75		23925	
	ACCCYC	0		24000		75			
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

^ - Component service life remaining is based on Accumulated Total Cycles as determined by CAMP's implementation of the low-cycle fatigue formula and is not endorsed by Pratt & Whitney Canada

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Life Limit / Overhaul Report

Model: PC-12/47G PRO Serial: 3028 RegNo: OK-CEO HRS: 84:54 AFL: 72 As Of: 11-Oct-2026

13-Oct-2026 08:42 AM

PN & SN	Unit	C/W	Next Due (ENG/APU) A/C	Interval	TSX/Adj.	Time Accrued	Est. Due	Remaining ^	Disposition
72-CA/13 NO. 1 ENGINE - SERVICE LIFE LIMIT 3RD-STAGE COMPRESSOR ROTOR									Service ATA:72
PN:3040933	MOS	14-Nov-25				11	07-Apr-2425		LIFE LIMIT
SN:FRAEUCAC96	HRS	0				84:54			
	ENC	0	(24000) 23997 (M)			75		23925	
	ACCCYC	0		24000		75			
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
72-CA/14 NO. 1 ENGINE - SERVICE LIFE LIMIT 4TH-STAGE COMPRESSOR ROTOR									Service ATA:72
PN:3040944	MOS	14-Nov-25				11	07-Apr-2425		LIFE LIMIT
SN:FRAEUBWC71	HRS	0				84:54			
	ENC	0	(24000) 23997 (M)			75		23925	
	ACCCYC	0		24000		75			
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
72-CA/15 NO. 1 ENGINE - SERVICE LIFE LIMIT CENTRIFUGAL IMPELLER									Service ATA:72
PN:3036898	MOS	14-Nov-25				11	07-Apr-2425		LIFE LIMIT
SN:CRAZAGZM071	HRS	0				84:54			
	ENC	0	(24000) 23997 (M)			75		23925	
	ACCCYC	0		24000		75			
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
72-CA/16 NO. 1 ENGINE - SERVICE LIFE LIMIT COMPRESSOR TURBINE DISK									Service ATA:72
PN:3135705	MOS	14-Nov-25				11	02-Aug-2210		LIFE LIMIT
SN:FRAEUBYC74	HRS	0				84:54			
	ENC	0	(11111) 11108 (M)			75		11036	
	ACCCYC	0		10000		67.5		9932	
PROC. REF: EM 72-51-01, EM 72-51-01PROC. REF: EM 72-51-01, EM 72-51-01									
72-CA/17 NO. 1 ENGINE - SERVICE LIFE LIMIT 1ST-STAGE POWER TURBINE DISK									Service ATA:72
PN:3056485-01	MOS	14-Nov-25				11	14-May-2275		LIFE LIMIT
SN:A005HYTK	HRS	0				84:54			
	ENC	0	(15000) 14997 (M)			75		14925	
	ACCCYC	0		15000		75			

^ - Component service life remaining is based on Accumulated Total Cycles as determined by CAMP's implementation of the low-cycle fatigue formula and is not endorsed by Pratt & Whitney Canada

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Life Limit / Overhaul Report

Model: PC-12/47G PRO Serial: 3028 RegNo: OK-CEO HRS: 84:54 AFL: 72 As Of: 11-Oct-2026

13-Oct-2026 08:42 AM

PN & SN	Unit	C/W	Next Due (ENG/APU) A/C	Interval	TSX/Adj.	Time Accrued	Est. Due	Remaining ^	Disposition
PROC. REF: EM 72-52-03, EM 72-52-03PROC. REF: EM 72-52-03, EM 72-52-03									
72-CA/18	NO. 1 ENGINE - SERVICE LIFE LIMIT 2ND-STAGE POWER TURBINE DISK								Service ATA:72
PN:3123253-01	MOS	14-Nov-25				11	14-May-2275		LIFE LIMIT
SN:A005FTM7	HRS	0				84:54			
	ENC	0	(15000) 14997 (M)			75		14925	
	ACCCYC	0		15000		75			
PROC. REF: EM 72-52-03PROC. REF: EM 72-52-03									
73-CA/12	NO. 1 ENGINE - OVERHAUL OIL-TO-FUEL HEATER								Service ATA:73
PN:3124177-01	MOS	14-Nov-25				11	18-Sep-2067		OVERHAUL
SN:WA69724	HRS	0	(5000) 5000	5000 (+500)		84:54		4915:06 (+500)	
	ENC	0				75			
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
73-CA/13	NO. 1 ENGINE - OVERHAUL ENGINE ELECTRONIC CONTROL (EEC)								Service ATA:73
PN:3126984-06	MOS	14-Nov-25				11	18-Sep-2067		OVERHAUL
SN:WDA146561	HRS	0	(5000) 5000	5000 (+500)		84:54		4915:06 (+500)	
	ENC	0				75			
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
73-CA/14	NO. 1 ENGINE - OVERHAUL FLOW DIVIDER								Service ATA:73
PN:3133739-01	MOS	14-Nov-25				11	18-Sep-2067		OVERHAUL
SN:25DAA0309	HRS	0	(5000) 5000	5000 (+500)		84:54		4915:06 (+500)	
	ENC	0				75			
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
73-CA/15	NO. 1 ENGINE - OVERHAUL FUEL CONTROL UNIT								Service ATA:73
PN:3126985-05	MOS	14-Nov-25				11	18-Sep-2067		OVERHAUL
SN:WDA150269	HRS	0	(5000) 5000	5000 (+500)		84:54		4915:06 (+500)	
	ENC	0				75			
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

^ - Component service life remaining is based on Accumulated Total Cycles as determined by CAMP's implementation of the low-cycle fatigue formula and is not endorsed by Pratt & Whitney Canada

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Life Limit / Overhaul Report

Model: PC-12/47G PRO Serial: 3028 RegNo: OK-CEO HRS: 84:54 AFL: 72 As Of: 11-Oct-2026

13-Oct-2026 08:42 AM

PN & SN	Unit	C/W	Next Due (ENG/APU) A/C	Interval	TSX/Adj.	Time Accrued	Est. Due	Remaining ^	Disposition
73-CA/20 NO. 1 ENGINE - REPLACE ENGINE ELECTRONIC CONTROL (EEC)									Service ATA:73
PN:3126984-06	MOS	14-Nov-25				11	09-May-2109		REPLACE
SN:WDA146561	HRS	0	(10000) 10000	10000		84:54		9915:06	
	ENC	0				75			
PROC. REF: EM 73-20-04, EM 73-20-04, LMM 73-20-04, LMM 73-20-04PROC. REF: EM 73-20-04, EM 73-20-04, LMM 73-20-04, LMM 73-20-04									
73-CA/7 ^S NO. 1 ENGINE - REMOVE, DISCARD AND REPLACE THE FUEL FILTER ELEMENT									Service ATA:73
	MOS	14-Nov-25				11			REPLACE
	HRS	0		600 (+10%/-10%)		84:54			
	ENC	0				75			
PROC. REF: EM 73-10-06, EM 73-10-06, LMM 73-10-06, LMM 73-10-06PROC. REF: EM 73-10-06, EM 73-10-06, LMM 73-10-06, LMM 73-10-06									
74-CA/6 NO. 1 ENGINE - OVERHAUL IGNITION EXCITER									Service ATA:74
PN:3043937-10	MOS	14-Nov-25				11	18-Sep-2067		OVERHAUL
SN:254368	HRS	0	(5000) 5000	5000 (+500)		84:54		4915:06 (+500)	
	ENC	0				75			
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
75-CA/1 NO. 1 ENGINE - OVERHAUL COMPRESSOR BLEED VALVE									Service ATA:75
PN:3136596	MOS	14-Nov-25				11	18-Sep-2067		OVERHAUL
SN:AHX5000954	HRS	0	(5000) 5000	5000 (+500)		84:54		4915:06 (+500)	
	ENC	0				75			
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									
79-20/43 OVERHAUL OIL COOLER									Service ATA:79
PN:968.32.14.104	MOS	31-Jan-26				8.4	18-Sep-2067		OVERHAUL
SN:189	HRS	0	5000	5000 (+10%/-10%)		84:54		4915:06 (+500)	
	AFL	0				72			
PROC. REF: GENERIC NO REFPROC. REF: GENERIC NO REF									

^ - Component service life remaining is based on Accumulated Total Cycles as determined by CAMP's implementation of the low-cycle fatigue formula and is not endorsed by Pratt & Whitney Canada

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task



Life Limit / Overhaul Report

Model: PC-12/47G PRO Serial: 3028 RegNo: OK-CEO HRS: 84:54 AFL: 72 As Of: 11-Oct-2026

13-Oct-2026 08:42 AM

PN & SN	Unit	C/W	Next Due (ENG/APU) A/C	Interval	TSX/Adj.	Time Accrued	Est. Due	Remaining ^	Disposition
79-CA/3 ^S	NO. 1 ENGINE - REMOVE, DISCARD AND REPLACE THE OIL FILTER ELEMENT							Service	ATA:79
	MOS	14-Nov-25				11			REPLACE
	HRS	0		600 (+10%/-10%)		84:54			
	ENC	0				75			

PKG:3

PROC. REF: EM 79-20-01, EM 79-20-01, LMM 79-20-01, LMM 79-20-01PROC. REF: EM 79-20-01, EM 79-20-01, LMM 79-20-01, LMM 79-20-01

PC12A56110100	WINDSHIELD, LH, HR121							Component	ATA:56
PN:959.81.10.168	MOS/MSC	31-Jan-26		O/C	TSN 0	8.4			REPLACE
SN:25188H9708	HRS	0			TSN 0	84:54			
	AFL	0			TSN 0	72			

PROC. REF: AMM 12-D-56-11-01-00A-920A-APROC. REF: AMM 12-D-56-11-01-00A-920A-A

PC12A56110200	WINDSHIELD, RH, HR122							Component	ATA:56
PN:959.81.10.110	MOS/MSC	31-Jan-26		O/C	TSN 0	8.4			REPLACE
SN:25029H4120	HRS	0			TSN 0	84:54			
	AFL	0			TSN 0	72			

PROC. REF: AMM 12-D-56-11-01-00A-920A-APROC. REF: AMM 12-D-56-11-01-00A-920A-A

^ - Component service life remaining is based on Accumulated Total Cycles as determined by CAMP's implementation of the low-cycle fatigue formula and is not endorsed by Pratt & Whitney Canada

?-Insufficient Information S-Suppressed Requirement *-Estimated Due(New Requirement) (EFF)-Effective C/W (M)-Manual Due U-User Task Ex-Excluded Task