

CG Motorsports

11880 Hammersmith Way 150, Richmond, BC V7A 5C8
(604) 275-6638 | info@cgmotorsports.com

[Inspection Report](#)[Visit Details](#)**Your Visit**[View Details →](#)

Kurumasource Auto Sales LTD 2016 Land Rover Range Rover Sport

RO# 35471 | Time In 10/08/2026 10:12 AM

Service Advisor J Campbell

Vehicle Health

Checked & Okay May Require Attention Soon Requires Immediate Attention

**Technician Findings****✖ REAR TIRE TREAD DEPTH**

Finding:
5mm
tread is cracking badly requires replacement
tires are from 2015

**✖ EXTERIOR LIGHTS**

Finding:
right rear turn signal not working

! ROTATION NEEDED?

Finding:
front and rear tires are different brands. front tires are pirelli scorpions. rear tires are michelin latitudes

! BUSHINGS

Finding:
both front thrust arm bushings cracking

**! TRANSMISSION FLUID LEAKS**

Finding:
some sweating around rear of transmission. possibly transmission output seal but difficult to see origin of leak



ENGINE AIR FILTER

Finding:
recommend replace cabin filter as there is an odour coming from the hvac

WIPER BLADES

Finding:
streaking

Inspections Performed

Simple Multi-Point Vehicle Inspection

Inspection Task	Findings
STANDARD INSPECTION	
WIPER BLADES	streaking
TIRE PRESSURES	
FRONT TIRE TREAD DEPTH	6mm front tires are made in 2021
REAR TIRE TREAD DEPTH	5mm tread is cracking badly requires relacement tires are from 2015
FRONT BRAKE PAD MEASUREMENT	10mm
REAR BRAKE PAD MEASUREMENT	6mm
WARNING LIGHTS ON	
EXTERIOR LIGHTS	right rear turn signal not working
SUSPENSION	
ROTATION NEEDED?	front and rear tires are different brands. front tires are pirelli scorpions. rear tires are michelin latitudes
ALIGNMENT NEEDED?	
WEAR PATTERN DAMAGE	
BRAKE LINE	

Inspection Task	Findings
! BUSHINGS	both front thrust arm bushings cracking  
✓ STRUTS	
DRIVELINE	
✓ DRIVELINE, DRIVESHAFT(S), AXLES	
UNDERHOOD	
! ENGINE AIR FILTER	recommend replace cabin filter as there is an odour coming from the hvac
✓ EXHAUST SYSTEM COMPONENTS	
✓ HOSES & BELTS	
✓ WASHER FLUID	
! TRANSMISSION FLUID LEAKS	some sweating around rear of transmission. possibly transmission output seal but difficult to see origin of leak 
✓ ENGINE OIL LEAKS	
✓ POWER STEERING LEAKS	
✓ COOLANT	
✓ DIFFERENTIAL LEAK	
✓ BRAKE FLUID	
MAINTENANCE	
✓ RECOMMENDED MILEAGE MAINTENANCE	
✓ OTHER RECOMMENDED SERVICES	
7 technician concerns found	

Vehicle Drop off/Check-In Quick Inspection		^
Inspection Task	Findings	

0 technician concerns found

Need a copy for your records?

 Print

Questions? Contact Us.

 Call

 Email

 Text

