

CG Motorsports

11880 Hammersmith Way 150, Richmond, BC V7A 5C8
(604) 275-6638 | info@cgmotorsports.com



[Inspection Report](#) Visit Details

Your Visit


[View Details →](#)

Kurumasource Auto Sales LTD 1973 Mercedes-Benz 450SL

RO# 35583 | Time In 10/21/2026 01:35 PM

Service Advisor W Bowe

Vehicle Health



Technician Findings

⚠ ENGINE OIL LEAKS



Finding:
Minor sweat at bottom of engine, likely from previous repairs

⚠ POWER STEERING LEAKS



Finding:
Minor sweat around steering box, likely from previous repairs

⚠ DIFFERENTIAL LEAK



Finding:
Minor sweat around differential, likely from previous repairs

⚠ OTHER RECOMMENDED SERVICES



Finding:
Car has been driven very prior to inspection, recommend further driving to reinspect

Inspections Performed

Simple Multi-Point Vehicle Inspection



Inspection Task	Findings
STANDARD INSPECTION	
✓ WIPER BLADES	
✓ TIRE PRESSURES	
8,8	

Inspection Task	Findings
 FRONT TIRE TREAD DEPTH	
 REAR TIRE TREAD DEPTH	8,8
 FRONT BRAKE PAD MEASUREMENT	6
 REAR BRAKE PAD MEASUREMENT	6
 WARNING LIGHTS ON	
 EXTERIOR LIGHTS	
SUSPENSION	
 ROTATION NEEDED?	
 ALIGNMENT NEEDED?	
 WEAR PATTERN DAMAGE	
 BRAKE LINE	
 BUSHINGS	
 STRUTS	
DRIVELINE	
 DRIVELINE, DRIVESHAFT(S), AXLES	
UNDERHOOD	
 ENGINE AIR FILTER	
 EXHAUST SYSTEM COMPONENTS	
 HOSES & BELTS	
 WASHER FLUID	
 TRANSMISSION FLUID LEAKS	
 ENGINE OIL LEAKS	Minor sweat at bottom of engine, likely from previous repairs
 POWER STEERING LEAKS	Minor sweat around steering box, likely from previous repairs
 COOLANT	
 DIFFERENTIAL LEAK	Minor sweat around differential, likely from previous repairs
 BRAKE FLUID	
MAINTENANCE	

Inspection Task	Findings
 RECOMMENDED MILEAGE MAINTENANCE	
 OTHER RECOMMENDED SERVICES	Car has been driven very prior to inspection, recommend further driving to reinspect
4 technician concerns found	

Vehicle Drop off/Check-In Quick Inspection 	
Inspection Task	Findings
0 technician concerns found	

Need a copy for your records?

 Print

Questions? Contact Us.

 Call

 Email

 Text

