

VISIONSAFE

EVAS[®] Services Policy and Price Sheet

Effective: 01 October 2026

Service		Description of Item and/or Service	Price*
1	Biennial Service	Unit received up to 3 months after the Base Service Date as shown on the face of the EVAS [®] unit	\$1,104
2	Late Service	Unit received for Biennial Service 4-12 months after the Base Service Date as shown on the face of the EVAS [®] unit	\$2,117
3	Non-Standard Service	Unit received with evidence of liquid contamination, exposure of internal parts, customer damage to unit, or > 12 months after the Base Service Date as shown on the face of the EVAS [®] unit - replace multiple parts as necessary and perform Biennial Service. NOTE: If unit is not serviceable, it will be returned to owner unserviced, at no charge.	\$4,560
4	120 Month Rebuild	Replace IVU, Battery Pack, and other parts as needed, to conform to current configuration.	\$9,111
5	Inspected / Reissued	External Inspection, Internal inspection and functional testing	\$571
6	AOG Fee	Customer requests AOG service and VisionSafe accepts. - Biennial Service – 24 hours - 120 Month Rebuild – 72 hours	\$276 \$2,278
7	Exchange	Replacement with similar or newer unit.	\$3,499
8	120 Month Exchange	Applicable if 120 month rebuild is next service and not previously exchanged	\$11,844
9	Exchange Late Fee	Exchange unit received 4-12 months after base service date.	\$4,512.
10	Exchange Non-Standard	Exchange unit received with evidence of liquid contamination, exposure of internal parts, customer damage to unit, or > 12 months after the Base Service Date as shown on the face of the EVAS [®] unit - replace multiple parts as necessary and perform Biennial Service. .	\$6,955

*CPI information obtained from the [Bureau of Labor Statistics](https://www.bls.gov/)

VisionSafe • 46-217 Kahuhipa Street, Kaneohe, HI 96744 • Voice 808-235-0849 • Fax 808-247-6313 • www.visionsafe.com