



Tigo External Release Notes

EI Platform

SW Release 2026.06

June, 2026

This document outlines the enhancements and bug fixes implemented in the Energy Intelligence (EI) web and mobile applications for the June 2026 release. The new EI software versions are the following:

- **EI Portal Web Application ... Version 2026.06**
- **EI Mobile App ... Version 5.4.6**

Summary of Implemented Enhancements and Bug Fixes

New Features and Enhancements - Summary:

- This release includes EI API scaling, Reports tab enhancements, and lifetime energy accumulator support.
- This release also includes an additional 29 bug fixes and various customer driven enhancements.
- Delivered scope:
 - 6 feature enhancements
 - 5 customer driven fixes
 - 29 bug fixes across web, mobile, and backend
- NEW: API scaling. Added scaling and Rate-limit changes for high-volume consumers.
- NEW: API enhancements. Added bulk inverter data endpoint, query enhancements, and bulk insert performance improvements.
- NEW: Reports tab rebuilt using updated Vue framework. Includes report regeneration button and date/period selector.
- NEW: Lifetime energy accumulator updates.
- NEW: The mobile app performance and framework updates



Web Enhancements in SW 2026.06

- EI API scaling
 - Performance upgrades for high-volume consumers
 - Bulk inverter data API endpoint added
 - Query and performance updates
- Reports refactor using Vue
 - Vue refactoring, regenerate report button added, date/period selector enhancements
- Lifetime energy accumulator
 - Changes made adding the lifetime energy accumulator

Web Bug Fixes

- Batteries in CCA but not in portal
- SOC showing 0% on Power Flow with full battery
- Power Flow production not matching System View data
- Off-grid EI power flow chart shows no power to home
- TS4-X-O incorrect display
- System view calendar cuts off bottom month row
- Consumption values not shown
- "System Delete Requested" email has missing text
- Dashboard tooltips off screen
- Overview/Power Flow chart sizing and data mismatches
- Mapping/scanning TS4s into system
- Equipment page – DONE button clickable with validation errors
- Reports tab – Refresh icon undefined

Mobile Bug Fixes

- TS4-H-O / TS4-H-S incorrectly displayed to customer. Panel types corrected to TS4-A-* across portal, reports, and filter dropdowns.
- Off-grid power flow chart – no power to home
- CCA update prompts "Updates Legacy" instead of "Updates"
- System details optional fields
- Power Flow missing consumption direction arrows
- FW updates to progress bar
- Layout calendar – last month hidden off screen
- Sign Up – password field text shifted
- Android – can't proceed when adding system in commissioning
- Mapping/scanning TS4s into system (Apps)