

whirlwind

99 Ling Rd
Rochester NY 14612-1965
585 663-8820 Fax: 585 865-8930
e-mail sales@whirlwindusa.com
On the Web: <http://www.whirlwindusa.com>

Repair Procedure For Broken or Missing W2 Locking Tabs

1. **Drill out remaining piece with 7/64" drill**
2. **Tap with #6-32 tap**
3. **Install 6-32 1/8" Allen type screw (Whirlwind part # SCR6-32-18) with Loc-Tite®**