

issues

INFORMATION BULLETIN No. SportStar-047b

- 1. CONCERNING TO:** SportStar SL aircraft S/N 2017 2008.
- 2. REASON:** Performance of the activity according to the definition document No. Z-SP-01/2026.
- 3. REQUIRED ACTIONS:** Carry out in accordance with definition document No. Z-SP-01/2026.
- 4. LATEST DAY OF THE ACTION:** Immediately after receiving this bulletin.
- 5. CARRY OUT BY:** Maintenance Organisation Evektor-Aerotechnik a.s.
- 6. COST COVERED BY:** Aircraft manufacturer / Evektor-Aerotechnik a.s.
- 7. NECESSARY MATERIAL:** According to the definition document.
- 8. WORK PROCEDURE:** According to the definition document.
- 9. APPENDICES:** None.

Valid from: 03. 07. 2026

QS-406/F-05K