

Scan ID: 190304

Date: 2025-04-28

GPS Coordinates:

Accessibility Grade

Access Description

2 out of 5

Major Barriers to Access Found Material

Length

Inspected

17 ft

94 ft²

Concrete

Area Inspected

Detectable Warning

Truncated Domes

Percent Deteriorated

0%

GPS IMAGES AND COORDINATES HAVE BEEN REMOVED FROM THIS FILE FOR DATA PRIVACY



Scan Data

Metadata				
Scan ID	190304			
Inspection Date	2025-04-28			
GPS Coordinates				
Accessibility Grade	2			
Access Description	Major Barriers to Access Found			
Material	Concrete			
Detectable Warning	Truncated Domes			
Length Inspected	17 ft			
Area Inspected	94 ft²			

Condition Areas			
Cracked Area	0 ft ²		
Deteriorated Area	0 ft ²		
Panel Area	94 ft²		
Percent Deteriorated	0%		

Slopes & Measurements			
Average Cross Slope	3.3%		
Max Cross Slope	7.8%		
Average Running Slope	8.9%		
Max Running Slope	10.9%		
Average Width	64.3 in		
Min Clear Width	58.4 in		

Violations						
Cross Slope	Э	Running SI	Running Slope		Clear Width	
Extreme	1	Extreme	0	Extreme	0	
Severe	0	Severe	2	Severe	0	
Moderate	0	Moderate	0	Moderate	0	
Minor	1	Minor	0	Minor	0	



Annotated Raster Legend

Ramp Violation Thresholds

	Cross Slope		Run Slope		Width	Width	
Severity							
Minor	2.5% - 3%	CS	8.3% - 9%	RS	42" - 46"		
Moderate	3% - 4%	cs	9% - 10%	RS	36" - 42"	CW	
Severe	4% - 6%	cs	10% - 12%	RS	24" - 36"	CW	
Extreme	6+%	cs	12+%	RS	0" - 24"	(CW)	
Score Impact	High		High	High		High	

Regions



Midblock Violation Thresholds

	Cross Slope		Run Sle	Run Slope		Width	
Severity							
Minor	2.5% - 3%	CS	8.3% - 9%	RS	42" - 46"		
Moderate	3% - 4%	CS	9% - 10%	RS	36" - 42"	CW	
Severe	4% - 6%	cs	10% - 12%	RS	24" - 36"	CW	
Extreme	6+%	CS	12+%	RS	0" - 24"	(CW)	
Score Impact	High		High		High		

Manual Tags





