

Safety Instructions for ShadowMate and ShadowMate XL for the Manuowell Assassin Bait Boat

Warning:

The following safety instructions apply to the ShadowMate and ShadowMate XL, which have been specifically designed for use with the Manuowell Assassin Bait Boat. Failure to comply with these instructions may result in material damage, functional impairments, injury, or other harm. Damages caused by neglect are excluded from warranty and guarantee claims. By using the product for the first time, the user agrees to these safety instructions.

1. General Information:

- Read the installation and operating manual thoroughly before installing or using the ShadowMate or ShadowMate XL.
 - The ShadowMate and ShadowMate XL are intended exclusively for the Manuowell Assassin Bait Boat and must not be used with other boats.
 - Only use the included components and follow the installation instructions precisely.
-

2. Assembly and Installation:

- Ensure that the bait boat is switched off and disconnected from the power source before beginning installation.
 - Only use the screws included in the package and the original tools provided with the bait boat.
 - After assembly, check that the handle is securely and firmly attached to prevent accidental detachment during use.
-

3. Safety During Use:

- Use the ShadowMate or ShadowMate XL exclusively for the safe transport and handling of the bait boat.
 - Always hold the boat securely by the handle, especially when placing it in or removing it from the water.
 - Do not exceed the maximum load capacity of the bait boat to avoid material damage.
-

4. Notes on 3D-Printed Parts:

- The 3D-printed parts of the Wide Gap Handle are made of high-quality XPETG material, known for its excellent mechanical and thermal properties.
 - Despite its strength, the material is sensitive to excessive loads and impacts.
 - Regularly inspect the 3D-printed components for cracks or wear, and replace damaged parts immediately.
 - Avoid extreme temperatures or direct sunlight to prevent deformation.
-

5. Maintenance and Care:

- Clean the ShadowMate or ShadowMate XL regularly with clean water to remove dirt and sand.
 - Do not use aggressive cleaning agents, as they may damage the material.
 - Store the boat and handle in a dry place protected from direct sunlight when not in use.
-

6. Environmental and Material Information:

- Dispose of the 3D-printed parts and packaging materials in accordance with local waste disposal regulations.
 - Keep the ShadowMate or ShadowMate XL out of reach of children to prevent accidents.
-

7. Disclaimer of Liability:

- The manufacturer accepts no liability for damages or injuries resulting from improper use, modifications to the handle, or failure to follow the warning and safety instructions.
- The use of the ShadowMate or ShadowMate XL is at the user's own risk.