



DueList Report

FALCON 900

S/N 157 N328JL

OWNER: LAMON AVIATION, LLC
ADDRESS: 132 LEE DUGGAN DR. STE 3
TX 77498

OPERATOR: LAMON AVIATION, LLC
ADDRESS: 132 LEE DUGGAN DR. STE 3
TX 77498

OPERATOR: JET LINK AVIATION, LLC
ADDRESS: 132 LEE DUGAN DR
SUGAR LAND TX

CAMO: JET LINK AVIATION, LLC
ADDRESS: 132 LEE DUGAN DR
SUGAR LAND TX

OFFICE:
FAX:

OFFICE:
FAX:

OFFICE:
FAX:

OFFICE:
FAX:

ANALYST: FALCON ANALYST
EMAIL: ESIMPSON@CAMPSYSTEMS.COM

877-411-2267 (DIRECT)
+1-631-588-3200 (MAIN)
WWW.CAMPSYSTEMS.COM

800-787-9749 (EFAX-CARDS)
631-980-4222 (FAX)

PROJECTED: 12 MOS. to 11/14/2026

AIRCRAFT	SERIAL / REGNO: 157/N328JL	MODEL: FALCON 900	MANUFACTURER: DASSAULT AVIATION S.A.
CERTIFICATION DATE: 02-FEB-1996		LAST ACTUALS: 8560.9 A/C HRS as of 03-OCT-2025 5069 AFL as of 03-OCT-2025 6488.4 APH as of 03-OCT-2025	PROJECTED: 8800.90 5189 6728
APU	SERIAL / PART: P-276/3800188-2	MODEL: GTCP36-150(F)	MANUFACTURER: HONEYWELL
INSTALLED ON: 07-OCT-2024 6368.8 APU HRS 8507.6 A/C HRS APUS		LAST ACTUALS: 6488.4 APU HRS as of 03-OCT-2025 APUS as of 03-MAR-2025	PROJECTED: 6728.40 0
ENGINE NO. 1	SERIAL / PART: P-101280/3075330-3	MODEL: TFE731-5BR-1C	MANUFACTURER: HONEYWELL
INSTALLED ON: 01-JUN-2017 6449.4 ENG. HRS 6742.8 A/C HRS 3739 ENC		LAST ACTUALS: 8271.4 ENG. HRS as of 03-OCT-2025 4930 ENC as of 03-OCT-2025	PROJECTED: 8511.40 5134
ENGINE NO. 2	SERIAL / PART: P-101279/3075330-3	MODEL: TFE731-5BR-1C	MANUFACTURER: HONEYWELL
INSTALLED ON: 11-MAR-2020 7418 ENG. HRS 7541.7 A/C HRS 4343 ENC		LAST ACTUALS: 8437.2 ENG. HRS as of 03-OCT-2025 5021 ENC as of 03-OCT-2025	PROJECTED: 8677.20 5225
ENGINE NO. 3	SERIAL / PART: P-101282/3075330-3	MODEL: TFE731-5BR-1C	MANUFACTURER: HONEYWELL
INSTALLED ON: 17-NOV-2017 6727.4 ENG. HRS 6923.9 A/C HRS 3810 ENC		LAST ACTUALS: 8364.4 ENG. HRS as of 03-OCT-2025 4887 ENC as of 03-OCT-2025	PROJECTED: 8604.40 5091



Due List Report

Model: FALCON 900 Serial: 157 RegNo: N328JL HRS: 8560.9 AFL: 5069 As Of: 03-Oct-2025 Operator: LAMON AVIATION, LLC

Report Date: 14-Nov-2025

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
05-08-00-200-800-05		12 M/800 FH INSPECTION						Package ATA:05
	MOS	12 (+1m)		07-Oct-24	07-Oct-25	07-Nov-25	OVD	
	HRS	800 (+40)		8507.6	9307.6	9347.6	746.7 (+40)	
	AFL			5038				
		REF: GENERIC NO REF						
05-08-00-200-800-15		12 M INSPECTION						Package ATA:05
	MOS	12 (+1m)		07-Oct-24	07-Oct-25	07-Nov-25	OVD	
	HRS			8507.6				
	AFL			5038				
		REF: GENERIC NO REF						
05-60-00-200-801-01		BASIC INSPECTION						Service ATA:05
	MOS	12 (+1m)		07-Oct-24	07-Oct-25	07-Nov-25	OVD	
	HRS	400 (+40)		8507.6	8907.6	8947.6	346.7 (+40)	
	AFL			5038				
		REF: AMM 05-60-00-200-801						
05-60-00-200-801-03		BASIC INSPECTION - GROUND SERVICING CHECKS						Service ATA:05
	MOS	12 (+1m)		07-Oct-24	07-Oct-25	07-Nov-25	OVD	
	HRS	400 (+40)		8507.6	8907.6	8947.6	346.7 (+40)	
	AFL			5038				
		REF: AMM 05-60-00-200-801						
24-32-09-610-801-02		SERVICING OF "SAFT" NICKEL-CADMIUM STAND-BY BATTERIES - IRS 1 BATTERY (L12FP)						Service ATA:24
PN:135687	MOS	12 (+3%)		07-Oct-24	07-Oct-25	18-Oct-25	OVD	
SN:3505	HRS			8507.6				
	AFL			5038				
		REF: AMM 24-32-09-610-801						
24-32-09-610-801-03		SERVICING OF "SAFT" NICKEL-CADMIUM STAND-BY BATTERIES - IRS 2 BATTERY (R12FP)						Service ATA:24
PN:804747	MOS	12 (+3%)		07-Oct-24	07-Oct-25	18-Oct-25	OVD	
SN:1026	HRS			8507.6				
	AFL			5038				
		REF: AMM 24-32-09-610-801						
24-32-09-610-801-04		SERVICING OF "SAFT" NICKEL-CADMIUM STAND-BY BATTERIES - IRS 3 BATTERY (32FP)						Service ATA:24
PN:135687	MOS	12 (+3%)		07-Oct-24	07-Oct-25	18-Oct-25	OVD	
SN:5127	HRS			8507.6				
	AFL			5038				
		REF: AMM 24-32-09-610-801						

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: FALCON 900 Serial: 157 RegNo: N328JL HRS: 8560.9 AFL: 5069 As Of: 03-Oct-2025 Operator: LAMON AVIATION, LLC

Report Date: 14-Nov-2025

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
24-32-09-610-801-05		SERVICING OF "SAFT" NICKEL-CADMIUM STAND-BY BATTERIES - VHF 3 STAND-BY BATTERY (28RC)						Service ATA:24
PN:804747	MOS	12 (+3%)		07-Oct-24	07-Oct-25	18-Oct-25	OVD	
SN:2017	HRS			8507.6				
	AFL			5038				
REF: AMM 24-32-09-610-801								
25-61-00-200-881-01		INSPECTION OF THE EMERGENCY LOCATOR TRANSMITTER (ELT) SYSTEM (FAR 91.207)						Service ATA:25
	MOS	12		07-Oct-24	07-Oct-25		OVD	
	HRS			8507.6				
	AFL			5038				
Disposition: MANDATORY REF: AMM GENERIC 1								
253A05 U		EQUIPMENT AUDIT (TPED'S) (ST11071SC) (DOC# L60-CA001)						Service ATA:25
	MOS	12		07-Oct-24	07-Oct-25		OVD	
	HRS			8507.6				
	AFL			5038				
REF:								
26-20-13-960-801-01		DISCARD OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 1 FIRST-SHOOT PERCUSSION CARTRIDGE (L3WB)						Service ATA:26
PN:861385	MOS	60		27-Oct-20	27-Oct-25		OVD	
SN:N/A	HRS							
	AFL							
Disposition: SCRAP REF: AMM 26-20-13-960-801								
26-20-13-960-801-02		DISCARD OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 3 FIRST-SHOOT PERCUSSION CARTRIDGE (R3WB)						Service ATA:26
PN:861375	MOS	60		02-Sep-20	02-Sep-25		OVD	
SN:NSN	HRS							
	AFL							
Disposition: SCRAP REF: AMM 26-20-13-960-801								
26-20-13-960-801-03		DISCARD OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 2 SECOND-SHOOT LH PERCUSSION CARTRIDGE (L4WB)						Service ATA:26
PN:861375	MOS	60		27-Oct-20	27-Oct-25		OVD	
SN:N/A	HRS							
	AFL							
Disposition: SCRAP REF: AMM 26-20-13-960-801								
26-20-13-960-801-04		DISCARD OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 2 SECOND-SHOOT RH PERCUSSION CARTRIDGE (R4WB)						Service ATA:26
PN:861385	MOS	60		27-Oct-20	27-Oct-25		OVD	
SN:N/A	HRS							
	AFL							
Disposition: SCRAP REF: AMM 26-20-13-960-801								

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: FALCON 900 Serial: 157 RegNo: N328JL HRS: 8560.9 AFL: 5069 As Of: 03-Oct-2025 Operator: LAMON AVIATION, LLC

Report Date: 14-Nov-2025

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
26-20-13-960-801-05		DISCARD OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 1 SECOND-SHOOT PERCUSSION CARTRIDGE (L5WB)						Service ATA:26
PN:861385	MOS	60		27-Oct-20	27-Oct-25		OVD	
SN:N/A	HRS							
	AFL							
Disposition: SCRAP		REF: AMM 26-20-13-960-801						
26-20-13-960-801-06		DISCARD OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 3 SECOND-SHOOT PERCUSSION CARTRIDGE (R5WB)						Service ATA:26
PN:861375	MOS	60		27-Oct-20	27-Oct-25		OVD	
SN:N/A	HRS							
	AFL							
Disposition: SCRAP		REF: AMM 26-20-13-960-801						
26-20-13-960-801-07		DISCARD OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 2 FIRST-SHOOT LH PERCUSSION CARTRIDGE (L6WB)						Service ATA:26
PN:861375	MOS	60		27-Oct-20	27-Oct-25		OVD	
SN:N/A	HRS							
	AFL							
Disposition: SCRAP		REF: AMM 26-20-13-960-801						
26-20-13-960-801-08		DISCARD OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 2 FIRST-SHOOT RH PERCUSSION CARTRIDGE (R6WB)						Service ATA:26
PN:861385	MOS	60		27-Oct-20	27-Oct-25		OVD	
SN:N/A	HRS							
	AFL							
Disposition: SCRAP		REF: AMM 26-20-13-960-801						
26-20-15-720-801-01		WEIGHING OF THE PORTABLE FIRE EXTINGUISHERS - COCKPIT PORTABLE FIRE EXTINGUISHER (500WB)						Service ATA:26
PN:C352	MOS	12 (+3%)		07-Oct-24	07-Oct-25	18-Oct-25	OVD	
SN:Y-649043	HRS			8507.6				
	AFL			5038				
		REF: AMM 26-20-15-720-801						
26-20-15-720-801-02		WEIGHING OF THE PORTABLE FIRE EXTINGUISHERS - CABIN FRONT PORTABLE FIRE EXTINGUISHER (501WB)						Service ATA:26
PN:C352	MOS	12 (+3%)		07-Oct-24	07-Oct-25	18-Oct-25	OVD	
SN:Y-439906	HRS			8507.6				
	AFL			5038				
		REF: AMM 26-20-15-720-801						
26-20-15-720-801-03		WEIGHING OF THE PORTABLE FIRE EXTINGUISHERS - CABIN REAR PORTABLE FIRE EXTINGUISHER (502WB)						Service ATA:26
PN:C352	MOS	12 (+3%)		07-Oct-24	07-Oct-25	18-Oct-25	OVD	
SN:Y-547480	HRS			8507.6				
	AFL			5038				
		REF: AMM 26-20-15-720-801						

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: FALCON 900 Serial: 157 RegNo: N328JL HRS: 8560.9 AFL: 5069 As Of: 03-Oct-2025 Operator: LAMON AVIATION, LLC

Report Date: 14-Nov-2025

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
26-20-15-790-801-01		HYDROSTATIC TEST OF THE PORTABLE FIRE EXTINGUISHERS - COCKPIT PORTABLE FIRE EXTINGUISHER (500WB)						Service ATA:26
PN:C352	MOS	60		13-Nov-20	13-Nov-25		OVD	
SN:Y-649043	HRS			0				
	AFL			0				
REF: AMM 26-20-15-790-801								
26-20-15-790-801-02		HYDROSTATIC TEST OF THE PORTABLE FIRE EXTINGUISHERS - CABIN FRONT PORTABLE FIRE EXTINGUISHER (501WB)						Service ATA:26
PN:C352	MOS	60		13-Nov-20	13-Nov-25		OVD	
SN:Y-439906	HRS			7627.5				
	AFL			4445				
REF: AMM 26-20-15-790-801								
26-20-15-790-801-03		HYDROSTATIC TEST OF THE PORTABLE FIRE EXTINGUISHERS - CABIN REAR PORTABLE FIRE EXTINGUISHER (502WB)						Service ATA:26
PN:C352	MOS	60		13-Nov-20	13-Nov-25		OVD	
SN:Y-547480	HRS			7627.5				
	AFL			4445				
REF: AMM 26-20-15-790-801								
28-30-00-680-803-01		DRAINING OF THE GRAVITY DEFUELING LINE						Service ATA:28
	MOS	2 (+5d)		29-Jul-25	29-Sep-25	04-Oct-25	OVD	
	HRS			8559.4				
	AFL			5068				
REF: AMM 28-30-00-680-803								
28-30-00-680-804-01		DRAINING WATER FROM THE FUEL TANKS						Service ATA:28
	MOS	2 (+5d)		29-Jul-25	29-Sep-25	04-Oct-25	OVD	
	HRS			8559.4				
	AFL			5068				
REF: AMM 28-30-00-680-804								
32-00-00-700-801-01		CHECK OF THE MLG AND NLG UPLOCK BOXES - NLG UPLOCK BOX (13GA)						Service ATA:32
	MOS	18 (+1m)	Adj:-204d	07-Oct-24	15-Sep-25	15-Oct-25	OVD	
	HRS			8507.6				
	AFL			5038				
REF: AMM 32-00-00-700-801								
32-00-00-700-801-02		CHECK OF THE MLG AND NLG UPLOCK BOXES - LH MLG UPLOCK BOX (L7GA)						Service ATA:32
	MOS	18 (+1m)	Adj:-204d	07-Oct-24	15-Sep-25	15-Oct-25	OVD	
	HRS			8507.6				
	AFL			5038				
REF: AMM 32-00-00-700-801								



Due List Report

Model: FALCON 900 Serial: 157 RegNo: N328JL HRS: 8560.9 AFL: 5069 As Of: 03-Oct-2025 Operator: LAMON AVIATION, LLC

Report Date: 14-Nov-2025

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
32-00-00-700-801-03	CHECK OF THE MLG AND NLG UPLOCK BOXES - RH MLG UPLOCK BOX (R7GA)							Service ATA:32
	MOS	18 (+1m)	Adj:-204d	07-Oct-24	15-Sep-25	15-Oct-25	OVD	
	HRS			8507.6				
	AFL			5038				
	REF: AMM 32-00-00-700-801							
32-10-00-640-801-01	LUBRICATION OF THE MAIN LANDING GEARS (MLG) AND MLG DOORS - LH MLG AND DOORS							Service ATA:32
	MOS	8 (+1m)	Adj:-196d	29-Jul-25	14-Sep-25	14-Oct-25	OVD	
	HRS			8559.4				
	AFL	400		5068	5468		399	
	REF: AMM 32-10-00-640-801							
32-10-00-640-801-02	LUBRICATION OF THE MAIN LANDING GEARS (MLG) AND MLG DOORS - RH MLG AND DOORS							Service ATA:32
	MOS	8 (+1m)	Adj:-196d	29-Jul-25	14-Sep-25	14-Oct-25	OVD	
	HRS			8559.4				
	AFL	400		5068	5468		399	
	REF: AMM 32-10-00-640-801							
32-20-00-640-801-01	LUBRICATION OF THE NOSE LANDING GEAR (NLG) AND NLG DOORS - NLG LEG (3GF)							Service ATA:32
	MOS	8 (+1m)	Adj:-197d	29-Jul-25	13-Sep-25	13-Oct-25	OVD	
	HRS			8559.4				
	AFL	400		5068	5468		399	
	REF: AMM 32-20-00-640-801							
32-44-00-780-801-01	PRESSURE CHECK OF THE MLG AND NLG WHEEL TIRES							Service ATA:32
	MOS	2 (+5d)		29-Jul-25	29-Sep-25	04-Oct-25	OVD	
	HRS			8559.4				
	AFL			5068				
	REF: AMM 32-44-00-780-801							
33-50-05-350-803-01	RESTORATION OF THE AIR LITE 2R LED RECHARGEABLE FLASHLIGHTS (OVERHAUL) - FLASH LIGHT (2LT)							Service ATA:33
PN:P2-07-0025-001	MOS	12 (+3%)		07-Oct-24	07-Oct-25	18-Oct-25	OVD	
SN:UNKNOWN	HRS			8507.6				
	AFL			5038				
	REF: AMM 33-50-05-350-803							
345A12 ^U	EQUIPMENT INSPECTION AVANCE L5 BROADBAND SYSTEM (DOC#1038081)							Service ATA:34
	MOS	12		07-Oct-24	07-Oct-25		OVD	
	HRS			8507.6				
	AFL			5038				
	REF:							



Due List Report

Model: FALCON 900 Serial: 157 RegNo: N328JL HRS: 8560.9 AFL: 5069 As Of: 03-Oct-2025 Operator: LAMON AVIATION, LLC

Report Date: 14-Nov-2025

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
35-30-05-210-801-01		GENERAL VISUAL INSPECTION OF THE PORTABLE OXYGEN BOTTLE - PORTABLE OXYGEN BOTTLE AND MASKS (537WH)						Service ATA:35
PN:894-20330	MOS	12 (+3%)		07-Oct-24	07-Oct-25	18-Oct-25	OVD	
SN:P09081020	HRS			8507.6				
	AFL			5038				
REF: AMM 35-30-05-210-801								
38-10-00-670-801-01		STERILIZATION OF THE POTABLE WATER SYSTEM - STANDARD STERILIZATION						Service ATA:38
	MOS	6 (+1m)	Adj:-114d	29-Jul-25	07-Oct-25	07-Nov-25	OVD	
	HRS			8559.4				
	AFL			5068				
REF: AMM 38-10-00-670-801								
53-10-00-200-808-01C		INSPECTION OF THE NLG BAY (CPCP)						Service ATA:53
	MOS	12 (+1m)		07-Oct-24	07-Oct-25	07-Nov-25	OVD	
	HRS			8507.6				
	AFL			5038				
Disposition: CPCP REF: AMM 53-10-00-200-808								
53-40-00-200-804-01C		INSPECTION OF THE MLG BAYS - LH MLG BAY (CPCP)						Service ATA:53
	MOS	12 (+1m)		07-Oct-24	07-Oct-25	07-Nov-25	OVD	
	HRS			8507.6				
	AFL			5038				
Disposition: CPCP REF: AMM 53-40-00-200-804								
53-40-00-200-804-02C		INSPECTION OF THE MLG BAYS - RH MLG BAY (CPCP)						Service ATA:53
	MOS	12 (+1m)		07-Oct-24	07-Oct-25	07-Nov-25	OVD	
	HRS			8507.6				
	AFL			5038				
Disposition: CPCP REF: AMM 53-40-00-200-804								
53-50-00-210-804-02C		GENERAL VISUAL INSPECTION OF THE REAR COMPARTMENT (CPCP)						Service ATA:53
	MOS	12 (+1m)		07-Oct-24	07-Oct-25	07-Nov-25	OVD	
	HRS			8507.6				
	AFL			5038				
Disposition: CPCP REF: AMM 53-50-00-210-804								
54-00-00-210-810-01		GENERAL VISUAL INSPECTION OF THE ENGINE 1 AND 3 NACELLES AND PYLONS - ENGINE 1 (L4EZ)						Service ATA:54
	MOS	12 (+1m)		07-Oct-24	07-Oct-25	07-Nov-25	OVD	
	HRS	300 (+100)	Adj:-20.4	8507.6	8787.2	8887.2	226.3 (+100)	
	AFL			5038				
REF: AMM 54-00-00-210-810								



Due List Report

Model: FALCON 900 Serial: 157 RegNo: N328JL HRS: 8560.9 AFL: 5069 As Of: 03-Oct-2025 Operator: LAMON AVIATION, LLC

Report Date: 14-Nov-2025

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
54-00-00-210-810-01C	GENERAL VISUAL INSPECTION OF THE ENGINE 1 AND 3 NACELLES AND PYLONS - ENGINE 1 (L4EZ) (CPCP)							Service ATA:54
	MOS	12 (+1m)		07-Oct-24	07-Oct-25	07-Nov-25	OVD	
	HRS			8507.6				
	AFL			5038				
	APH							
Disposition: CPCP		REF: AMM 54-00-00-210-810						
54-00-00-210-810-02	GENERAL VISUAL INSPECTION OF THE ENGINE 1 AND 3 NACELLES AND PYLONS - ENGINE 3 (R4EZ)							Service ATA:54
	MOS	12 (+1m)		07-Oct-24	07-Oct-25	07-Nov-25	OVD	
	HRS	300 (+100)	Adj:-20.4	8507.6	8787.2	8887.2	226.3 (+100)	
	AFL			5038				
	REF: AMM 54-00-00-210-810							
54-00-00-210-810-02C	GENERAL VISUAL INSPECTION OF THE ENGINE 1 AND 3 NACELLES AND PYLONS - ENGINE 3 (R4EZ) (CPCP)							Service ATA:54
	MOS	12 (+1m)		07-Oct-24	07-Oct-25	07-Nov-25	OVD	
	HRS			8507.6				
	AFL			5038				
	APH							
Disposition: CPCP		REF: AMM 54-00-00-210-810						
54-00-00-210-811-01 ^S	GENERAL VISUAL INSPECTION OF THE ENGINE 2 NACELLE							Service ATA:54
	MOS	12 (+1m)		07-Oct-24	07-Oct-25 (M)	07-Nov-25	OVD	
	REF: AMM 54-00-00-210-811							
SB F900-388 REV 04	WINGS - WING TANK MODIFICATION, SERVICE BULLETIN							Bulletin ATA:57
	MOS	T:150		EFF	19-Apr-24 * (M)		OVD	
	HRS							
	AFL							
Disposition: MANDATORY		REF: BULLETINS						
25-62-01-720-801-02	FUNCTIONAL TEST OF THE FDR / CVR UNDERWATER LOCATOR BEACONS - FDR UNDERWATER LOCATOR BEACON (900FZ)							Service ATA:25
PN:DK120/90	MOS	25 (+3%)		10-Oct-23	10-Nov-25	02-Dec-25	TOL (+18 d)	14-Nov-2025
SN:AT123547	HRS			8437.6				
	AFL			4993				
	REF: AMM 25-62-01-720-801							
27-40-01-210-802-01	VISUAL INSPECTION OF THE HORIZONTAL STABILIZER ACTUATOR - HORIZONTAL STABILIZER ELECTRIC ACTUATOR (3CF)							Service ATA:27
PN:021121-11	MOS	72 (+3%)		25-Nov-19	25-Nov-25	29-Jan-26	11 d (+65)	25-Nov-2025
SN:141	HRS			7516.2				
	AFL	3750 (+3%)		4372	8122	8234.5	3053 (+112.5)	
	REF: AMM 27-40-01-210-802							

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: FALCON 900 Serial: 157 RegNo: N328JL HRS: 8560.9 AFL: 5069 As Of: 03-Oct-2025 Operator: LAMON AVIATION, LLC

Report Date: 14-Nov-2025

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
25-62-05-960-801-02		RESTORATION OF THE FDR / CVR UNDERWATER LOCATOR BEACONS (DISCARD OF THE FDR / CVR ULB BATTERY) - FDR ULB BATTERY (900FZ1)						Service ATA:25
PN:DK120/90	MOS	DUE		29-May-19	31-Dec-25 (M)		47 d	31-Dec-2025
SN:AT123547	HRS			7433.9				
	AFL			4313				
Disposition: LIFE LIMIT		REF: AMM 25-62-05-960-801						
32-44-00-250-801-03		SPECIAL DETAILED INSPECTION OF THE WHEEL SUBASSEMBLIES - RH MLG INBOARD WHEEL (R535GC)						Service ATA:32
PN:C20180120-2	MOS			30-Sep-21				01-Jan-2026
SN:F1106	HRS			8000.1				
	AFL	400 (+3%)		4685	5085	5097	16 (+12)	
		REF: AMM 32-44-00-250-801						
32-44-00-250-801-04		SPECIAL DETAILED INSPECTION OF THE WHEEL SUBASSEMBLIES - RH MLG OUTBOARD WHEEL (R540GC)						Service ATA:32
PN:C20180400	MOS			30-Sep-21				01-Jan-2026
SN:02606	HRS			8000.1				
	AFL	400 (+3%)		4685	5085	5097	16 (+12)	
		REF: AMM 32-44-00-250-801						
25-64-13-200-801-01		INSPECTION OF LIFE RAFT - NO. 1 LIFE RAFT						Service ATA:25
PN:1015FAUL-H30-1-100	MOS	36 (+3%)		12-Jan-23	12-Jan-26	14-Feb-26	59 d (+33)	12-Jan-2026
SN:10UL-02972	HRS							
	AFL							
		REF: AMM 25-64-13-200-801						
25-64-13-200-801-01		INSPECTION OF LIFE RAFT - NO. 2 LIFE RAFT						Service ATA:25
PN:1015FAUL-H30-1-100	MOS	36 (+3%)		12-Jan-23	12-Jan-26	14-Feb-26	59 d (+33)	12-Jan-2026
SN:10UL-02973	HRS			8290.3				
	AFL			4878				
		REF: AMM 25-64-13-200-801						
24-32-01-700-801-01		REGULAR CHECK OF A MAIN NICKEL-CADMIUM BATTERY - BATTERY 1 (L1PE)						Service ATA:24
PN:4076-10	MOS	6 (+10%)		29-Jul-25	29-Jan-26	16-Feb-26	76 d (+18)	29-Jan-2026(2)
SN:088398	HRS	250 (+25)		8559.4	8809.4	8834.4	248.5 (+25)	
	AFL			5068				
		REF: AMM 24-32-01-700-801						
24-32-01-700-801-02		REGULAR CHECK OF A MAIN NICKEL-CADMIUM BATTERY - BATTERY 2 (R1PE)						Service ATA:24
PN:4076-10	MOS	6 (+10%)		29-Jul-25	29-Jan-26	16-Feb-26	76 d (+18)	29-Jan-2026(2)
SN:121547	HRS	250 (+25)		8559.4	8809.4	8834.4	248.5 (+25)	
	AFL			5068				
		REF: AMM 24-32-01-700-801						

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: FALCON 900 Serial: 157 RegNo: N328JL HRS: 8560.9 AFL: 5069 As Of: 03-Oct-2025 Operator: LAMON AVIATION, LLC

Report Date: 14-Nov-2025

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
760130		NO. 1 ENGINE - DOWNLOAD ECTM						Service ATA:76
	MOS			03-Jul-25				04-Feb-2026(4)
	HRS			8266.2				
	ENC	50		4926	(4976)5115		46	
		REF: MSC CAMP EHM ADENDUM, LMM 76-10-03						
760130		NO. 2 ENGINE - DOWNLOAD ECTM						Service ATA:76
	MOS			03-Jul-25				04-Feb-2026(4)
	HRS			8432				
	ENC	50		5017	(5067)5115		46	
		REF: MSC CAMP EHM ADENDUM, LMM 76-10-03						
760130		NO. 3 ENGINE - DOWNLOAD ECTM						Service ATA:76
	MOS			03-Jul-25				04-Feb-2026(4)
	HRS			8359.2				
	ENC	50		4883	(4933)5115		46	
		REF: MSC CAMP EHM ADENDUM, LMM 76-10-03						
35-30-09-100-801-01		CLEANING OF THE PORTABLE OXYGEN MASKS - PORTABLE OXYGEN BOTTLE AND MASKS (537WH)						Service ATA:35
PN:894-20330	MOS	12 (+3%)	Adj:-171d	29-Jul-25	08-Feb-26	18-Feb-26	86 d (+10)	08-Feb-2026
SN:P09081020	HRS			8559.4				
	AFL			5068				
		REF: AMM 35-30-09-100-801						
FAA 2013-09-03		WINGS - FUEL TANK MODIFICATION						AD ATA:57
	MOS	T:150		EFF	14-Feb-26 *		92 d	14-Feb-2026
	HRS							
	AFL							
Disposition: MANDATORY		REF: AD						
499020		APU - REMOVE AND INSPECT MAGNETIC DRAIN PLUG						Service ATA:49
	MOS	17		07-Oct-24	07-Mar-26		113 d	07-Mar-2026
	HRS	750		6368.8	7118.8		630.4	
	APUS							
		REF: MM 49-90-46						
499030		APU - DRAIN AND REFILL OIL						Service ATA:49
	MOS	17		07-Oct-24	07-Mar-26		113 d	07-Mar-2026
	HRS	750		6368.8	7118.8		630.4	
	APUS							
		REF: MM 49-20-00						



Due List Report

Model: FALCON 900 Serial: 157 RegNo: N328JL HRS: 8560.9 AFL: 5069 As Of: 03-Oct-2025 Operator: LAMON AVIATION, LLC

Report Date: 14-Nov-2025

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
499040		APU - REMOVE AND REPLACE OIL FILTER ELEMENT						Service ATA:49
	MOS	17		07-Oct-24	07-Mar-26		113 d	07-Mar-2026
	HRS	750		6368.8	7118.8		630.4	
	APUS							
		REF: MM 49-90-47						
05-08-00-200-800-31		1C INSPECTION						Package ATA:05
	MOS	72 (+2m)		11-Mar-20	11-Mar-26	11-May-26	117 d (+61)	11-Mar-2026
	HRS			7541.7				
	AFL	3750		4391	8141		3072	
		REF: GENERIC NO REF						
05-50-00-910-801-01		AIRCRAFT CHECK FLIGHT						Service ATA:05
	MOS	72 (+2m)		11-Mar-20	11-Mar-26 (M)	11-May-26	117 d (+61)	11-Mar-2026
	HRS			7541.7				
	AFL	3750		4391	8141 (M)		3072	
		REF: AMM 05-50-00-910-801						
050A00 ^U		INSPECT HIGH SPEED INTERNET SYSTEM INSTALLATION						Service ATA:05
	MOS	72			11-Mar-26 (M)		117 d	11-Mar-2026
	HRS							
	AFL	3750			8141 (M)		3072	
		REF:						
32-11-00-220-801-01		DETAILED INSPECTION OF THE MLG LEGS - LH MLG LEG (L2GF)						Service ATA:32
PN:D22801100-11	MOS	72 (+8m)		11-Mar-20	11-Mar-26	11-Nov-26	117 d (+245)	11-Mar-2026
SN:U167	HRS			7541.7				
	AFL			4391				
		REF: AMM 32-11-00-220-801						
32-11-00-220-801-02		DETAILED INSPECTION OF THE MLG LEGS - RH MLG LEG (R2GF)						Service ATA:32
PN:D22801100-11	MOS	72 (+8m)		11-Mar-20	11-Mar-26	11-Nov-26	117 d (+245)	11-Mar-2026
SN:U166	HRS			7541.7				
	AFL			4391				
		REF: AMM 32-11-00-220-801						
32-11-25-220-801-01		DETAILED INSPECTION OF MLG BALL-JOINT BEARINGS AND BEARING BORES - LH MLG FRONT BALL-JOINT BEARING (L90GA)						Service ATA:32
	MOS	72 (+8m)		11-Mar-20	11-Mar-26	11-Nov-26	117 d (+245)	11-Mar-2026
	HRS			7541.7				
	AFL			4391				
		REF: AMM 32-11-25-220-801						



Due List Report

Model: FALCON 900 Serial: 157 RegNo: N328JL HRS: 8560.9 AFL: 5069 As Of: 03-Oct-2025 Operator: LAMON AVIATION, LLC

Report Date: 14-Nov-2025

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
32-11-25-220-801-02	DETAILED INSPECTION OF MLG BALL-JOINT BEARINGS AND BEARING BORES - LH MLG REAR BALL-JOINT BEARING (L100GA)							Service ATA:32
	MOS	72 (+8m)		11-Mar-20	11-Mar-26	11-Nov-26	117 d (+245)	11-Mar-2026
	HRS			7541.7				
	AFL			4391				
REF: AMM 32-11-25-220-801								
32-11-25-220-801-03	DETAILED INSPECTION OF MLG BALL-JOINT BEARINGS AND BEARING BORES - RH MLG FRONT BALL-JOINT BEARING (R90GA)							Service ATA:32
	MOS	72 (+8m)		11-Mar-20	11-Mar-26	11-Nov-26	117 d (+245)	11-Mar-2026
	HRS			7541.7				
	AFL			4391				
REF: AMM 32-11-25-220-801								
32-11-25-220-801-04	DETAILED INSPECTION OF MLG BALL-JOINT BEARINGS AND BEARING BORES - RH MLG REAR BALL-JOINT BEARING (R100GA)							Service ATA:32
	MOS	72 (+8m)		11-Mar-20	11-Mar-26	11-Nov-26	117 d (+245)	11-Mar-2026
	HRS			7541.7				
	AFL			4391				
REF: AMM 32-11-25-220-801								
32-21-00-220-801-01	DETAILED INSPECTION OF THE NLG LEG - NLG LEG (3GF)							Service ATA:32
PN:D22811200-13	MOS	72 (+8m)		11-Mar-20	11-Mar-26	11-Nov-26	117 d (+245)	11-Mar-2026
SN:U165	HRS			7541.7				
	AFL			4391				
REF: AMM 32-21-00-220-801								
32-21-09-220-801-01	DETAILED INSPECTION OF THE NLG LEG AND NLG DRAG BRACE BALL-JOINT BEARINGS AND BEARING BORES - LH NLG DRAG BRACE BALL-JOINT BEARING							Service ATA:32
	MOS	72 (+8m)		11-Mar-20	11-Mar-26	11-Nov-26	117 d (+245)	11-Mar-2026
	HRS			7541.7				
	AFL			4391				
REF: AMM 32-21-09-220-801								
32-21-09-220-801-02	DETAILED INSPECTION OF THE NLG LEG AND NLG DRAG BRACE BALL-JOINT BEARINGS AND BEARING BORES - RH NLG DRAG BRACE BALL-JOINT BEARING							Service ATA:32
	MOS	72 (+8m)		11-Mar-20	11-Mar-26	11-Nov-26	117 d (+245)	11-Mar-2026
	HRS			7541.7				
	AFL			4391				
REF: AMM 32-21-09-220-801								
32-21-09-220-801-03	DETAILED INSPECTION OF THE NLG LEG AND NLG DRAG BRACE BALL-JOINT BEARINGS AND BEARING BORES - LH NLG LEG BALL-JOINT BEARING							Service ATA:32
	MOS	72 (+8m)		11-Mar-20	11-Mar-26	11-Nov-26	117 d (+245)	11-Mar-2026
	HRS			7541.7				
	AFL			4391				
REF: AMM 32-21-09-220-801								



Due List Report

Model: FALCON 900 Serial: 157 RegNo: N328JL HRS: 8560.9 AFL: 5069 As Of: 03-Oct-2025 Operator: LAMON AVIATION, LLC

Report Date: 14-Nov-2025

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
32-21-09-220-801-04		DETAILED INSPECTION OF THE NLG LEG AND NLG DRAG BRACE BALL-JOINT BEARINGS AND BEARING BORES - RH NLG LEG BALL-JOINT BEARING						Service ATA:32
	MOS	72 (+8m)		11-Mar-20	11-Mar-26	11-Nov-26	117 d (+245)	11-Mar-2026
	HRS			7541.7				
	AFL			4391				
		REF: AMM 32-21-09-220-801						
53-00-00-220-801-01C		DETAILED INSPECTION OF THE FUSELAGE EXTERIOR - DETAILED INSPECTION (CPCP)						Service ATA:53
	MOS	72 (+2m)		11-Mar-20	11-Mar-26	11-May-26	117 d (+61)	11-Mar-2026
	HRS			7541.7				
	AFL			4391				
Disposition: CPCP		REF: AMM 53-00-00-220-801						
53-10-00-220-802-01C		DETAILED INSPECTION OF THE FLIGHT COMPARTMENT (CPCP)						Service ATA:53
	MOS	72 (+2m)		11-Mar-20	11-Mar-26	11-May-26	117 d (+61)	11-Mar-2026
	HRS			7541.7				
	AFL			4391				
Disposition: CPCP		REF: AMM 53-10-00-220-802						
53-10-33-220-802-01C		INSPECTION OF THE COCKPIT WINDSHIELD / WINDOW FRAMES / RETAINERS AND ATTACHMENTS (CPCP)						Service ATA:53
	MOS	72 (+2m)		11-Mar-20	11-Mar-26	11-May-26	117 d (+61)	11-Mar-2026
	HRS			7541.7				
	AFL			4391				
Disposition: CPCP		REF: AMM 53-10-33-220-802						
53-10-39-220-801-01C		DETAILED INSPECTION OF THE LOWER SECTION OF THE COCKPIT WINDSHIELD / WINDOW FRAMES (CPCP)						Service ATA:53
	MOS	72 (+2m)		11-Mar-20	11-Mar-26	11-May-26	117 d (+61)	11-Mar-2026
	HRS			7541.7				
	AFL			4391				
Disposition: CPCP		REF: AMM 53-10-39-220-801						
53-30-00-220-801-01C		DETAILED INSPECTION OF THE PASSENGER CABIN - UNDER THE FLOOR (CPCP)						Service ATA:53
	MOS	72 (+2m)		11-Mar-20	11-Mar-26	11-May-26	117 d (+61)	11-Mar-2026
	HRS			7541.7				
	AFL			4391				
Disposition: CPCP		REF: AMM 53-30-00-220-801						
53-40-00-220-801-01C		DETAILED INSPECTION OF THE FUSELAGE LOWER SECTION AREAS (CPCP)						Service ATA:53
	MOS	72 (+2m)		11-Mar-20	11-Mar-26	11-May-26	117 d (+61)	11-Mar-2026
	HRS			7541.7				
	AFL			4391				
Disposition: CPCP		REF: AMM 53-40-00-220-801						



Due List Report

Model: FALCON 900 Serial: 157 RegNo: N328JL HRS: 8560.9 AFL: 5069 As Of: 03-Oct-2025 Operator: LAMON AVIATION, LLC

Report Date: 14-Nov-2025

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
53-40-00-220-802-01C	DETAILED INSPECTION OF THE FUSELAGE STRUCTURAL FUEL TANKS (CPCP)							Service ATA:53
	MOS	72 (+2m)		11-Mar-20	11-Mar-26	11-May-26	117 d (+61)	11-Mar-2026
	HRS			7541.7				
	AFL			4391				
Disposition: CPCP			REF: AMM 53-40-00-220-802					
53-50-00-220-803-01C	DETAILED INSPECTION OF THE BAGGAGE COMPARTMENT (CPCP)							Service ATA:53
	MOS	72 (+2m)		11-Mar-20	11-Mar-26	11-May-26	117 d (+61)	11-Mar-2026
	HRS			7541.7				
	AFL			4391				
Disposition: CPCP			REF: AMM 53-50-00-220-803					
55-00-00-220-801-01C	DETAILED INSPECTION OF THE HORIZONTAL AND VERTICAL STABILIZERS AND OF ENGINE 2 AIR INTAKE AND S-DUCT (CPCP)							Service ATA:55
	MOS	72 (+2m)		11-Mar-20	11-Mar-26	11-May-26	117 d (+61)	11-Mar-2026
	HRS			7541.7				
	AFL			4391				
Disposition: CPCP			REF: AMM 55-00-00-220-801					
57-00-00-220-802-01C	DETAILED INSPECTION OF THE WINGS - LH WING (CPCP)							Service ATA:57
	MOS	72 (+2m)		11-Mar-20	11-Mar-26	11-May-26	117 d (+61)	11-Mar-2026
	HRS			7541.7				
	AFL			4391				
Disposition: CPCP			REF: AMM 57-00-00-220-802					
57-00-00-220-802-02C	DETAILED INSPECTION OF THE WINGS - RH WING (CPCP)							Service ATA:57
	MOS	72 (+2m)		11-Mar-20	11-Mar-26	11-May-26	117 d (+61)	11-Mar-2026
	HRS			7541.7				
	AFL			4391				
Disposition: CPCP			REF: AMM 57-00-00-220-802					
57-10-00-290-801-01C	BORESCOPE INSPECTION OF THE WING TANKS (CPCP)							Service ATA:57
	MOS	72 (+2m)		11-Mar-20	11-Mar-26	11-May-26	117 d (+61)	11-Mar-2026
	HRS			7541.7				
	AFL			4391				
Disposition: CPCP			REF: AMM 57-10-00-290-801					
FAA 1999-25-09 PARA (B) & (C)	ACCOMPLISH HINGE PIN ASSEMBLIES OF HORIZONTAL STABILIZER							AD ATA:27
	MOS	72		11-Mar-20	11-Mar-26		117 d	11-Mar-2026
	HRS			7541.7				
	AFL	3750		4391	8141		3072	
Disposition: MANDATORY			REF: AD					

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: FALCON 900 Serial: 157 RegNo: N328JL HRS: 8560.9 AFL: 5069 As Of: 03-Oct-2025 Operator: LAMON AVIATION, LLC

Report Date: 14-Nov-2025

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
32-44-00-250-801-05 SPECIAL DETAILED INSPECTION OF THE WHEEL SUBASSEMBLIES - LH NLG WHEEL (L565GC) Service ATA:32								
PN:C20182100	MOS			03-Aug-21				02-Apr-2026
SN:01018	HRS			7893.7				
	AFL	500 (+3%)		4615	5115	5130	46 (+15)	
REF: AMM 32-44-00-250-801								
32-44-00-250-801-06 SPECIAL DETAILED INSPECTION OF THE WHEEL SUBASSEMBLIES - RH NLG WHEEL (R565GC) Service ATA:32								
PN:C20182100	MOS			03-Aug-21				02-Apr-2026
SN:01179	HRS			7893.7				
	AFL	500 (+3%)		4615	5115	5130	46 (+15)	
REF: AMM 32-44-00-250-801								
057110 NO. 1 ENGINE - 150 TO 250 HOUR INSPECTION Package ATA:05								
	MOS			07-Oct-24				10-Apr-2026
	HRS	150 (+100)		8218.1	(8368.1)8657.6	8468.1	96.7 (+100)	
	ENC			4899				
REF: LMM 72-00-00								
057110 NO. 2 ENGINE - 150 TO 250 HOUR INSPECTION Package ATA:05								
	MOS			07-Oct-24				10-Apr-2026
	HRS	150 (+100)		8383.9	(8533.9)8657.6	8633.9	96.7 (+100)	
	ENC			4990				
REF: LMM 72-00-00								
057110 NO. 3 ENGINE - 150 TO 250 HOUR INSPECTION Package ATA:05								
	MOS			07-Oct-24				10-Apr-2026
	HRS	150 (+100)		8311.1	(8461.1)8657.6	8561.1	96.7 (+100)	
	ENC			4856				
REF: LMM 72-00-00								
24-31-17-220-803-01 CHECK OF THE ENGINE STARTER-GENERATOR BRUSHES - ENGINE 1 STARTER-GENERATOR (L1PA) Service ATA:24								
PN:8060-141-1	MOS			07-Oct-24				10-Apr-2026
SN:1148	HRS	150 (+3%)		8507.6	8657.6	8662.1	96.7 (+4.5)	
	AFL			5038				
REF: AMM 24-31-17-220-803								
24-31-17-220-803-02 CHECK OF THE ENGINE STARTER-GENERATOR BRUSHES - ENGINE 2 STARTER-GENERATOR (M1PA) Service ATA:24								
PN:8060-141-1	MOS			07-Oct-24				10-Apr-2026
SN:1037	HRS	150 (+3%)		8507.6	8657.6	8662.1	96.7 (+4.5)	
	AFL			5038				
REF: AMM 24-31-17-220-803								



Due List Report

Model: FALCON 900 Serial: 157 RegNo: N328JL HRS: 8560.9 AFL: 5069 As Of: 03-Oct-2025 Operator: LAMON AVIATION, LLC

Report Date: 14-Nov-2025

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
24-31-17-220-803-03 CHECK OF THE ENGINE STARTER-GENERATOR BRUSHES - ENGINE 3 STARTER-GENERATOR (R1PA) Service ATA:24								
PN:8060-141-1	MOS			07-Oct-24				10-Apr-2026
SN:54	HRS	150 (+3%)		8507.6	8657.6	8662.1	96.7 (+4.5)	
	AFL			5038				
REF: AMM 24-31-17-220-803								
24-33-05-220-803-01 CHECK OF THE APU STARTER-GENERATOR BRUSHES - APU STARTER-GENERATOR (21PA) Service ATA:24								
PN:8060-141-1	MOS			07-Oct-24				19-May-2026
SN:145	HRS			8507.6				
	AFL			5038				
	APH	150 (+3%)		6461.2	6611.2	6615.7	122.8 (+4.5)	
REF: AMM 24-33-05-220-803								
21-52-05-610-801-01 TURBOCOOLER OIL SERVICING - TURBOCOOLER (504HN) OIL TOP-UP Service ATA:21								
	MOS			07-Oct-24				25-Jun-2026
	HRS	200		8507.6	8707.6		146.7	
	AFL			5038				
REF: AMM 21-52-05-610-801								
FAA 1974-08-09 R03 LAVATORY PAPER OR LINEN WASTE RECEPTACLE FIRE PREVENTION AD ATA:25								
	MOS			24-Mar-21				08-Jul-2026
	HRS	1000		7716.7	8716.7		155.8	
	AFL			4493				
Disposition: MANDATORY REF: AD								
26-20-09-220-801-01 WEIGHING OF THE FIRE EXTINGUISHERS - APU, BAGGAGE COMPARTMENT FIRE EXTINGUISHER (22WB) Service ATA:26								
PN:861630	MOS	12 (+1m)		29-Jul-25	10-Jul-26	10-Aug-26	238 d (+31)	10-Jul-2026
SN:57501	HRS			8559.4				
	AFL			5068				
REF: AMM 26-20-09-220-801								
26-20-09-220-801-02 WEIGHING OF THE FIRE EXTINGUISHERS - ENGINE 1 FIRST-SHOOT, ENGINE 2 SECOND-SHOOT FIRE EXTINGUISHER (3WB1) Service ATA:26								
PN:861630	MOS	12 (+1m)		29-Jul-25	10-Jul-26	10-Aug-26	238 d (+31)	10-Jul-2026
SN:25795	HRS			8559.4				
	AFL			5068				
REF: AMM 26-20-09-220-801								
26-20-09-220-801-03 WEIGHING OF THE FIRE EXTINGUISHERS - ENGINE 2 FIRST-SHOOT, ENGINE 1 SECOND-SHOOT FIRE EXTINGUISHER (L3WB2) Service ATA:26								
PN:861630	MOS	12 (+1m)		29-Jul-25	10-Jul-26	10-Aug-26	238 d (+31)	10-Jul-2026
SN:58513	HRS			8559.4				
	AFL			5068				
REF: AMM 26-20-09-220-801								

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: FALCON 900 Serial: 157 RegNo: N328JL HRS: 8560.9 AFL: 5069 As Of: 03-Oct-2025 Operator: LAMON AVIATION, LLC

Report Date: 14-Nov-2025

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
26-20-09-220-801-04		WEIGHING OF THE FIRE EXTINGUISHERS - ENGINE 3 FIRST-SHOOT, ENGINE 2 SECOND-SHOOT FIRE EXTINGUISHER (3WB3)						Service ATA:26
PN:861630	MOS	12 (+1m)		29-Jul-25	10-Jul-26	10-Aug-26	238 d (+31)	10-Jul-2026
SN:56344	HRS			8559.4				
	AFL			5068				
REF: AMM 26-20-09-220-801								
26-20-09-220-801-05		WEIGHING OF THE FIRE EXTINGUISHERS - ENGINE 2 FIRST-SHOOT, ENGINE 3 SECOND-SHOOT FIRE EXTINGUISHER (R3WB2)						Service ATA:26
PN:861630	MOS	12 (+1m)		29-Jul-25	10-Jul-26	10-Aug-26	238 d (+31)	10-Jul-2026
SN:25783	HRS			8559.4				
	AFL			5068				
REF: AMM 26-20-09-220-801								
53-10-39-220-802-01		DETAILED INSPECTION OF THE COCKPIT WINDSHIELD / WINDOW FRAMES						Service ATA:53
	MOS	144 (+2m)		14-Jul-14	14-Jul-26	14-Sep-26	242 d (+62)	14-Jul-2026
	HRS			5799.6				
	AFL	5030		3266	8296		3227	
REF: AMM 53-10-39-220-802								
53-10-39-220-802-01C		DETAILED INSPECTION OF THE COCKPIT WINDSHIELD / WINDOW FRAMES (CPCP)						Service ATA:53
	MOS	144 (+2m)		14-Jul-14	14-Jul-26	14-Sep-26	242 d (+62)	14-Jul-2026
	HRS			5799.6				
	AFL			3266				
Disposition: CPCP REF: AMM 53-10-39-220-802								
55-10-00-220-801-01C		DETAILED INSPECTION OF THE HORIZONTAL STABILIZER INTERNAL BOX STRUCTURE - DETAILED INSPECTION OF THE HS INTERNAL BOX STRUCTURE (CPCP)						Service ATA:55
	MOS	144 (+2m)		14-Jul-14	14-Jul-26	14-Sep-26	242 d (+62)	14-Jul-2026
	HRS			5799.6				
	AFL			3266				
Disposition: CPCP REF: AMM 55-10-00-220-801								
21-31-09-350-801-01		RESTORATION OF THE NOSE CONE VENTILATION FAN (REPLACEMENT OF BEARINGS) - NOSE CONE FAN (3HQ)						Service ATA:21
PN:011479501	MOS			21-Nov-13				15-Jul-2026
SN:ASK542	HRS	3000		5721	8721		160.1	
	AFL			3221				
REF: AMM 21-31-09-350-801								
31-54-00-720-803-01		FUNCTIONAL TEST OF THE TAKE-OFF SAFETIES - ALARM TEST						Service ATA:31
	MOS			08-Feb-22				27-Jul-2026
	HRS	600 (+40)		8129.2	8729.2	8769.2	168.3 (+40)	
	AFL			4774				
REF: AMM 31-54-00-720-803								

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: FALCON 900 Serial: 157 RegNo: N328JL HRS: 8560.9 AFL: 5069 As Of: 03-Oct-2025 Operator: LAMON AVIATION, LLC

Report Date: 14-Nov-2025

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
24-32-01-350-801-01		RESTORATION OF A MAIN NICKEL-CADMIUM BATTERY (OVERHAUL) - BATTERY 1 (L1PE)						Service ATA:24
PN:4076-10	MOS	12 (+1m)		29-Jul-25	29-Jul-26	29-Aug-26	257 d (+31)	29-Jul-2026
SN:088398	HRS			8559.4				
	AFL			5068				
Disposition: OVERHAUL		REF: AMM 24-32-01-350-801						
24-32-01-350-801-02		RESTORATION OF A MAIN NICKEL-CADMIUM BATTERY (OVERHAUL) - BATTERY 2 (R1PE)						Service ATA:24
PN:4076-10	MOS	12 (+1m)		29-Jul-25	29-Jul-26	29-Aug-26	257 d (+31)	29-Jul-2026
SN:121547	HRS			8559.4				
	AFL			5068				
Disposition: OVERHAUL		REF: AMM 24-32-01-350-801						
24-32-09-610-801-01		SERVICING OF "SAFT" NICKEL-CADMIUM STAND-BY BATTERIES - STAND-BY HORIZON BATTERY (4FG)						Service ATA:24
PN:804747	MOS	12 (+3%)		29-Jul-25	29-Jul-26	09-Aug-26	257 d (+11)	29-Jul-2026
SN:3354	HRS			8559.4				
	AFL			5068				
		REF: AMM 24-32-09-610-801						
33-50-05-350-803-02		RESTORATION OF THE AIR LITE 2R LED RECHARGEABLE FLASHLIGHTS (OVERHAUL) - FLASH LIGHT (3LT)						Service ATA:33
PN:P2-07-0022-001	MOS	12 (+3%)		29-Jul-25	29-Jul-26	09-Aug-26	257 d (+11)	29-Jul-2026
SN:N/A	HRS			8559.4				
	AFL			5068				
		REF: AMM 33-50-05-350-803						
723110		NO. 3 ENGINE - COMPRESSOR ZONE INSPECTION (CZI)						Service ATA:72
	MOS			23-Feb-04				15-Aug-2026
	HRS	5000 (+200)		3545.2	(8545.2)8741.7	8745.2	180.8 (+200)	
	ENC			1830				
		REF: LMM 72-00-00						
726120		NO. 3 ENGINE - INSPECT ACCESSORY GEARBOX						Service ATA:72
PN:3070003-17	MOS			23-Feb-04				15-Aug-2026
SN:5401	HRS	5000 (+200)		3545.2	(8545.2)8741.7	8745.2	180.8 (+200)	
	ENC			1830				
		REF: LMM 72-60-02						
727110		NO. 3 ENGINE - INSPECT FAN SUPPORT ASSEMBLY						Service ATA:72
	MOS			23-Feb-04				15-Aug-2026
	HRS	5000 (+200)		3545.2	(8545.2)8741.7	8745.2	180.8 (+200)	
	ENC			1830				
		REF: LMM 72-70-06						

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: FALCON 900 Serial: 157 RegNo: N328JL HRS: 8560.9 AFL: 5069 As Of: 03-Oct-2025 Operator: LAMON AVIATION, LLC

Report Date: 14-Nov-2025

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
ASB TFE731-A72-3641 R07		NO. 3 ENGINE - PERFORM EDDY CURRENT INSPECTION OF HIGH PRESSURE COMPRESSOR (HPC) IMPELLER, ALERT SERVICE BULLETIN						Bulletin ATA:72
	MOS	-						15-Aug-2026
	HRS				(8545.2)8741.7 (M)		180.8	
	ENC							
Disposition: CATEGORY 1		REF: BULLETINS						
FAA 2000-15-09		NO. 3 ENGINE - ENGINE - HIGH PRESSURE COMPRESSURE (HPC) IMPELLER - REPLACE						AD ATA:72
	MOS							15-Aug-2026
	HRS	5000			(8545.2)8741.7 (M)		180.8	
	ENC							
Disposition: MANDATORY		REF: AD						
SB TFE731-72-3777 R02		NO. 3 ENGINE - ENGINE - COMPRESSOR SECTION - INSTALL IMPROVED LOW PRESSURE COMPRESSOR SECOND STAGE (LPC2) SHROUD, PN 3072403-6, SERVICE BULLETIN						Bulletin ATA:72
	MOS	T:DUE		EFF				15-Aug-2026
	HRS				(8545.2)8741.7 * (M)		180.8	
	ENC							
Disposition: CATEGORY 2		REF: BULLETINS						
25-60-00-200-801-03 ^S		INSPECTION OF THE SAFETY EQUIPMENT - FIRST AID KIT						Service ATA:25
	MOS			07-Oct-24	01-Sep-26 (M)		291 d	01-Sep-2026
		REF: AMM 25-60-00-200-801						
34-14-01-700-881-01		TEST NO. 1 AIR DATA (ADC1) COMPUTER (FAR 91.411)						Service ATA:34
PN:7000700-647	MOS	24		07-Oct-24	04-Sep-26		294 d	04-Sep-2026
SN:87102336	HRS			8507.6				
	AFL			5038				
Disposition: MANDATORY		REF: AMM GENERIC 2, FAR 91.411						
34-14-01-700-881-02		TEST NO. 2 AIR DATA (ADC 2) COMPUTER (FAR 91.411)						Service ATA:34
PN:7000700-647	MOS	24		07-Oct-24	04-Sep-26		294 d	04-Sep-2026
SN:88032573	HRS			8507.6				
	AFL			5038				
Disposition: MANDATORY		REF: AMM GENERIC 2, FAR 91.411						
34-15-01-700-881-01		TEST PILOT ALTIMETER (FAR 91.411)						Service ATA:34
PN:4016341-904	MOS	24		07-Oct-24	04-Sep-26		294 d	04-Sep-2026
SN:95027990	HRS			8507.6				
	AFL			5038				
Disposition: MANDATORY		REF: AMM GENERIC 2, FAR 91.411						

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: FALCON 900 Serial: 157 RegNo: N328JL HRS: 8560.9 AFL: 5069 As Of: 03-Oct-2025 Operator: LAMON AVIATION, LLC

Report Date: 14-Nov-2025

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
34-15-01-700-881-02		TEST COPILOT ALTIMETER (FAR 91.411)						Service ATA:34
PN:4016341-904	MOS	24		07-Oct-24	04-Sep-26		294 d	04-Sep-2026
SN:92097153	HRS			8507.6				
	AFL			5038				
Disposition: MANDATORY		REF: AMM GENERIC 2, FAR 91.411						
34-15-02-700-881-01		TEST PILOT STAND-BY ALTIMETER (FAR 91.411)						Service ATA:34
PN:64141-530-1	MOS	24		07-Oct-24	04-Sep-26		294 d	04-Sep-2026
SN:5024	HRS			8507.6				
	AFL			5038				
Disposition: MANDATORY		REF: AMM GENERIC 2, FAR 91.411						
34-54-00-700-881-01		TEST NO. 1 ATC TRANSPONDER (FAR 91.413)						Service ATA:34
PN:622-9210-501	MOS	24		07-Oct-24	04-Sep-26		294 d	04-Sep-2026
SN:224	HRS			8507.6				
	AFL			5038				
Disposition: MANDATORY		REF: AMM GENERIC 2, FAR 91.413						
34-54-00-700-881-02		TEST NO. 2 ATC TRANSPONDER (FAR 91.413)						Service ATA:34
PN:622-9210-501	MOS	24		07-Oct-24	04-Sep-26		294 d	04-Sep-2026
SN:2368	HRS			8507.6				
	AFL			5038				
Disposition: MANDATORY		REF: AMM GENERIC 2, FAR 91.413						
FAA 2016-09-03		EQUIPMENT/FURNISHINGS - REPLACE EACH SPRING HAVING PART NUMBER (P/N) 132100-19 AND P/N 147100-19 INSTALLED ON THE PILOT AND CO-PILOT SEATS WITH A SPRING AS SPECIFIED (FOR AIRPLANES THAT HAVE ACCUMULATED MORE THAN 3,750 TOTAL FLIGHT CYCLES OR HAVE EXCEEDED 74 MONTHS SINCE THE AIRPLANE'S FIRST FLIGHT AS OF THE EFFECTIVE DATE OF THIS AD)						AD ATA:25
	MOS	78		11-Mar-20	11-Sep-26		301 d	11-Sep-2026
	HRS			7541.7				
	AFL	3750		4391	8141		3072	
Disposition: MANDATORY		REF: AD						
26-20-13-960-801-02M		DISCARD NO. 3 ENGINE FIRST SHOOT FIRE EXTINGUISHER PERCUSSION (R3WB) CARTRIDGE (LIFE LIMIT)						Service ATA:26
PN:861375	MOS	84		20-Sep-19	20-Sep-26		310 d	20-Sep-2026
SN:NSN	HRS							
	AFL							
Disposition: LIFE LIMIT		REF: AMM 26-20-13-960-801						
25-64-17-350-802-01		RESTORATION OF THE CREW LIFE VESTS (OVERHAUL OR DISCARD) - LH PILOT LIFE VEST (L10ME)						Service ATA:25
PN:P01074-201	MOS	60 (+3%)		22-Mar-23	22-Sep-26 (M)	15-Nov-26	312 d (+54)	22-Sep-2026
SN:16091290027	HRS			8352.1				
	AFL			4919				
Disposition: OVERHAUL		REF: AMM 25-64-17-350-802						

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: FALCON 900 Serial: 157 RegNo: N328JL HRS: 8560.9 AFL: 5069 As Of: 03-Oct-2025 Operator: LAMON AVIATION, LLC

Report Date: 14-Nov-2025

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
25-64-17-350-802-02		RESTORATION OF THE CREW LIFE VESTS (OVERHAUL OR DISCARD) - RH PILOT LIFE VEST (R10ME)						Service ATA:25
PN:P01074-201	MOS	60 (+3%)		22-Mar-23	22-Sep-26 (M)	15-Nov-26	312 d (+54)	22-Sep-2026
SN:16091290038	HRS			8352.1				
	AFL			4919				
Disposition: OVERHAUL		REF: AMM 25-64-17-350-802						
25-64-17-350-802-03		RESTORATION OF THE CREW LIFE VESTS (OVERHAUL OR DISCARD) - THIRD CREW MEMBER LIFE VEST (M10ME)						Service ATA:25
PN:P01074-201	MOS	60 (+3%)		22-Mar-23	22-Sep-26 (M)	15-Nov-26	312 d (+54)	22-Sep-2026
SN:16091290029	HRS			8352.1				
	AFL			4919				
Disposition: OVERHAUL		REF: AMM 25-64-17-350-802						
25-64-17-350-803-01		RESTORATION OF THE PASSENGER LIFE VESTS (OVERHAUL OR DISCARD) - NO. 1 PASSENGER LIFE VEST						Service ATA:25
PN:P01074-201	MOS	60 (+3%)		22-Mar-23	22-Sep-26 (M)	15-Nov-26	312 d (+54)	22-Sep-2026
SN:16091290018	HRS			8352.1				
	AFL			4919				
Disposition: OVERHAUL		REF: AMM 25-64-17-350-803						
25-64-17-350-803-01		RESTORATION OF THE PASSENGER LIFE VESTS (OVERHAUL OR DISCARD) - NO. 10 PASSENGER LIFE VEST						Service ATA:25
PN:P01074-201	MOS	60		22-Mar-23	22-Sep-26 (M)		312 d	22-Sep-2026
SN:16091290026	HRS			8352.1				
	AFL			4919				
Disposition: OVERHAUL		REF: AMM 25-64-17-350-803						
25-64-17-350-803-01		RESTORATION OF THE PASSENGER LIFE VESTS (OVERHAUL OR DISCARD) - NO. 11 PASSENGER LIFE VEST						Service ATA:25
PN:P01074-201	MOS	60		22-Mar-23	22-Sep-26 (M)		312 d	22-Sep-2026
SN:16091290004	HRS			8352.1				
	AFL			4919				
Disposition: OVERHAUL		REF: AMM 25-64-17-350-803						
25-64-17-350-803-01		RESTORATION OF THE PASSENGER LIFE VESTS (OVERHAUL OR DISCARD) - NO. 12 PASSENGER LIFE VEST						Service ATA:25
PN:P01074-201	MOS	60		22-Mar-23	22-Sep-26 (M)		312 d	22-Sep-2026
SN:16091290001	HRS			8352.1				
	AFL			4919				
Disposition: OVERHAUL		REF: AMM 25-64-17-350-803						
25-64-17-350-803-01		RESTORATION OF THE PASSENGER LIFE VESTS (OVERHAUL OR DISCARD) - NO. 13 PASSENGER LIFE VEST						Service ATA:25
PN:P01074-201	MOS	60		22-Mar-23	22-Sep-26 (M)		312 d	22-Sep-2026
SN:16091290025	HRS			8352.1				
	AFL			4919				
Disposition: OVERHAUL		REF: AMM 25-64-17-350-803						



Due List Report

Model: FALCON 900 Serial: 157 RegNo: N328JL HRS: 8560.9 AFL: 5069 As Of: 03-Oct-2025 Operator: LAMON AVIATION, LLC

Report Date: 14-Nov-2025

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
25-64-17-350-803-01		RESTORATION OF THE PASSENGER LIFE VESTS (OVERHAUL OR DISCARD) - NO. 2 PASSENGER LIFE VEST						Service ATA:25
PN:P01074-201	MOS	60 (+3%)		22-Mar-23	22-Sep-26 (M)	15-Nov-26	312 d (+54)	22-Sep-2026
SN:16091290028	HRS			8352.1				
	AFL			4919				
Disposition: OVERHAUL			REF: AMM 25-64-17-350-803					
25-64-17-350-803-01		RESTORATION OF THE PASSENGER LIFE VESTS (OVERHAUL OR DISCARD) - NO. 3 PASSENGER LIFE VEST						Service ATA:25
PN:P01074-201	MOS	60 (+3%)		22-Mar-23	22-Sep-26 (M)	15-Nov-26	312 d (+54)	22-Sep-2026
SN:16091290019	HRS			8352.1				
	AFL			4919				
Disposition: OVERHAUL			REF: AMM 25-64-17-350-803					
25-64-17-350-803-01		RESTORATION OF THE PASSENGER LIFE VESTS (OVERHAUL OR DISCARD) - NO. 4 PASSENGER LIFE VEST						Service ATA:25
PN:P01074-201	MOS	60 (+3%)		22-Mar-23	22-Sep-26 (M)	15-Nov-26	312 d (+54)	22-Sep-2026
SN:16091290021	HRS			8352.1				
	AFL			4919				
Disposition: OVERHAUL			REF: AMM 25-64-17-350-803					
25-64-17-350-803-01		RESTORATION OF THE PASSENGER LIFE VESTS (OVERHAUL OR DISCARD) - NO. 5 PASSENGER LIFE VEST						Service ATA:25
PN:P01074-201	MOS	60		22-Mar-23	22-Sep-26 (M)		312 d	22-Sep-2026
SN:16091290040	HRS			8352.1				
	AFL			4919				
Disposition: OVERHAUL			REF: AMM 25-64-17-350-803					
25-64-17-350-803-01		RESTORATION OF THE PASSENGER LIFE VESTS (OVERHAUL OR DISCARD) - NO. 6 PASSENGER LIFE VEST						Service ATA:25
PN:P01074-201	MOS	60		22-Mar-23	22-Sep-26 (M)		312 d	22-Sep-2026
SN:16091290014	HRS			8352.1				
	AFL			4919				
Disposition: OVERHAUL			REF: AMM 25-64-17-350-803					
25-64-17-350-803-01		RESTORATION OF THE PASSENGER LIFE VESTS (OVERHAUL OR DISCARD) - NO. 7 PASSENGER LIFE VEST						Service ATA:25
PN:P01074-201	MOS	60		22-Mar-23	22-Sep-26 (M)		312 d	22-Sep-2026
SN:16091290002	HRS			8352.1				
	AFL			4919				
Disposition: OVERHAUL			REF: AMM 25-64-17-350-803					
25-64-17-350-803-01		RESTORATION OF THE PASSENGER LIFE VESTS (OVERHAUL OR DISCARD) - NO. 8 PASSENGER LIFE VEST						Service ATA:25
PN:P01074-201	MOS	60		22-Mar-23	22-Sep-26 (M)		312 d	22-Sep-2026
SN:16091290033	HRS			8352.1				
	AFL			4919				
Disposition: OVERHAUL			REF: AMM 25-64-17-350-803					



Due List Report

Model: FALCON 900 Serial: 157 RegNo: N328JL HRS: 8560.9 AFL: 5069 As Of: 03-Oct-2025 Operator: LAMON AVIATION, LLC

Report Date: 14-Nov-2025

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
25-64-17-350-803-01	RESTORATION OF THE PASSENGER LIFE VESTS (OVERHAUL OR DISCARD) - NO. 9 PASSENGER LIFE VEST							Service ATA:25
PN:P01074-201	MOS	60		22-Mar-23	22-Sep-26 (M)		312 d	22-Sep-2026
SN:16091290003	HRS			8352.1				
	AFL			4919				
Disposition: OVERHAUL		REF: AMM 25-64-17-350-803						
21-52-05-350-801-01	RESTORATION OF THE TURBOCOOLER (OVERHAUL) - TURBOCOOLER (504HN)							Service ATA:21
PN:3269B0202	MOS			01-Apr-14				28-Sep-2026
SN:311	HRS	3000 (+3%)		5770.4	8770.4	8860.4	209.5 (+90)	
	AFL			3247				
Disposition: OVERHAUL		REF: AMM 21-52-05-350-801						
05-08-00-200-800-06	24 M/1600 FH INSPECTION							Package ATA:05
	MOS	24 (+1m)		07-Oct-24	07-Oct-26	07-Nov-26	327 d (+31)	07-Oct-2026
	HRS	1600 (+40)		8507.6	10107.6	10147.6	1546.7 (+40)	
	AFL			5038				
		REF: GENERIC NO REF						
05-08-00-200-800-16	24 M INSPECTION							Package ATA:05
	MOS	24 (+1m)		07-Oct-24	07-Oct-26	07-Nov-26	327 d (+31)	07-Oct-2026
	HRS			8507.6				
	AFL			5038				
		REF: GENERIC NO REF						
34-16-00-720-801-01	FUNCTIONAL TEST OF THE AIR DATA INDICATORS - ADC 1 (L2FX)							Service ATA:34
PN:7000700-647	MOS	24 (+3%)		07-Oct-24	07-Oct-26	29-Oct-26	327 d (+22)	07-Oct-2026
SN:87102336	HRS			8507.6				
	AFL			5038				
		REF: AMM 34-16-00-720-801						
34-16-00-720-801-02	FUNCTIONAL TEST OF THE AIR DATA INDICATORS - ADC 2 (R2FX)							Service ATA:34
PN:7000700-647	MOS	24 (+3%)		07-Oct-24	07-Oct-26	29-Oct-26	327 d (+22)	07-Oct-2026
SN:88032573	HRS			8507.6				
	AFL			5038				
		REF: AMM 34-16-00-720-801						
34-16-00-720-801-03	FUNCTIONAL TEST OF THE AIR DATA INDICATORS - STAND-BY ALTIMETER (1FK)							Service ATA:34
PN:64141-530-1	MOS	24 (+3%)		07-Oct-24	07-Oct-26	29-Oct-26	327 d (+22)	07-Oct-2026
SN:5024	HRS			8507.6				
	AFL			5038				
		REF: AMM 34-16-00-720-801						

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: FALCON 900 Serial: 157 RegNo: N328JL HRS: 8560.9 AFL: 5069 As Of: 03-Oct-2025 Operator: LAMON AVIATION, LLC

Report Date: 14-Nov-2025

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
34-16-00-720-801-04 FUNCTIONAL TEST OF THE AIR DATA INDICATORS - STAND-BY MACH AIRSPEED INDICATOR (26FL) Service ATA:34								
PN:64032-229-1	MOS	24 (+3%)		07-Oct-24	07-Oct-26	29-Oct-26	327 d (+22)	07-Oct-2026
SN:1484	HRS			8507.6				
	AFL			5038				
REF: AMM 34-16-00-720-801								
34-54-00-720-802-01 FUNCTIONAL TEST OF THE AIR TRAFFIC CONTROL (ATC) SYSTEM - ATC 1 SYSTEM PERIODIC TESTS Service ATA:34								
PN:622-9210-501	MOS	24 (+3%)		07-Oct-24	07-Oct-26	29-Oct-26	327 d (+22)	07-Oct-2026
SN:224	HRS			8507.6				
	AFL			5038				
REF: AMM 34-54-00-720-802								
34-54-00-720-802-02 FUNCTIONAL TEST OF THE AIR TRAFFIC CONTROL (ATC) SYSTEM - ATC 2 SYSTEM PERIODIC TESTS Service ATA:34								
PN:622-9210-501	MOS	24 (+3%)		07-Oct-24	07-Oct-26	29-Oct-26	327 d (+22)	07-Oct-2026
SN:2368	HRS			8507.6				
	AFL			5038				
REF: AMM 34-54-00-720-802								
346171 ^U REPLACE NZ-2000 STANDBY BATTERY Component ATA:34								
PN:7020116-1	MOS	24	TSN:0	07-Oct-24	07-Oct-26		327 d	07-Oct-2026
SN:NSN	HRS		TSN:0	8507.6				
	AFL		TSN:0	5038				
REF:								
52-20-00-610-801-01A SERVICING OF THE EMERGENCY EXIT DOOR - TEST OF THE EMERGENCY EXIT DOOR UNLOCKING FROM INSIDE THE CABIN (MANDATORY 5-40) Service ATA:52								
	MOS	24		07-Oct-24	07-Oct-26		327 d	07-Oct-2026
	HRS			8507.6				
	AFL			5038				
Disposition: MANDATORY 5-40 REF: AMM 52-20-00-610-801								
53-00-00-210-801-01C GENERAL VISUAL INSPECTION OF THE FUSELAGE EXTERIOR - GENERAL VISUAL INSPECTION (CPCP) Service ATA:53								
	MOS	24 (+1m)		07-Oct-24	07-Oct-26	07-Nov-26	327 d (+31)	07-Oct-2026
	HRS			8507.6				
	AFL			5038				
Disposition: CPCP REF: AMM 53-00-00-210-801								
53-10-00-210-802-01 GENERAL VISUAL INSPECTION OF THE FLIGHT COMPARTMENT Service ATA:53								
	MOS	24 (+1m)		07-Oct-24	07-Oct-26	07-Nov-26	327 d (+31)	07-Oct-2026
	HRS	4000		8507.6	12507.6		3946.7	
	AFL			5038				
REF: AMM 53-10-00-210-802								



Due List Report

Model: FALCON 900 Serial: 157 RegNo: N328JL HRS: 8560.9 AFL: 5069 As Of: 03-Oct-2025 Operator: LAMON AVIATION, LLC

Report Date: 14-Nov-2025

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
53-11-00-210-801-02C	GENERAL VISUAL INSPECTION OF THE NOSE CONE AREA (CPCP)							Service ATA:53
	MOS	24 (+1m)		07-Oct-24	07-Oct-26	07-Nov-26	327 d (+31)	07-Oct-2026
	HRS			8507.6				
	AFL			5038				
	APH							
Disposition: CPCP			REF: AMM 53-11-00-210-801					
53-41-00-220-801-01C	DETAILED INSPECTION OF THE UPPER LH WING ROOT BOLT RECESSES (CPCP)							Service ATA:53
	MOS	24 (+1m)		07-Oct-24	07-Oct-26	07-Nov-26	327 d (+31)	07-Oct-2026
	HRS			8507.6				
	AFL			5038				
Disposition: CPCP			REF: AMM 53-41-00-220-801					
53-41-00-220-801-02C	DETAILED INSPECTION OF THE UPPER RH WING ROOT BOLT RECESSES (CPCP)							Service ATA:53
	MOS	24 (+1m)		07-Oct-24	07-Oct-26	07-Nov-26	327 d (+31)	07-Oct-2026
	HRS			8507.6				
	AFL			5038				
Disposition: CPCP			REF: AMM 53-41-00-220-801					
53-50-00-210-806-01C	GENERAL VISUAL INSPECTION OF THE BAGGAGE COMPARTMENT (CPCP)							Service ATA:53
	MOS	24 (+1m)		07-Oct-24	07-Oct-26	07-Nov-26	327 d (+31)	07-Oct-2026
	HRS			8507.6				
	AFL			5038				
Disposition: CPCP			REF: AMM 53-50-00-210-806					
53-50-00-220-805-02C	DETAILED INSPECTION OF THE REAR COMPARTMENT (CPCP)							Service ATA:53
	MOS	24 (+1m)		07-Oct-24	07-Oct-26	07-Nov-26	327 d (+31)	07-Oct-2026
	HRS			8507.6				
	AFL			5038				
Disposition: CPCP			REF: AMM 53-50-00-220-805					
55-00-00-210-801-01C	GENERAL VISUAL INSPECTION OF THE HORIZONTAL AND VERTICAL STABILIZERS AND OF ENGINE 2 AIR INTAKE AND S-DUCT (CPCP)							Service ATA:55
	MOS	24 (+1m)		07-Oct-24	07-Oct-26	07-Nov-26	327 d (+31)	07-Oct-2026
	HRS			8507.6				
	AFL			5038				
Disposition: CPCP			REF: AMM 55-00-00-210-801					
57-00-00-210-801-01C	GENERAL VISUAL INSPECTION OF THE WINGS - LH WING (CPCP)							Service ATA:57
	MOS	24 (+1m)		07-Oct-24	07-Oct-26	07-Nov-26	327 d (+31)	07-Oct-2026
	HRS			8507.6				
	AFL			5038				
Disposition: CPCP			REF: AMM 57-00-00-210-801					

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: FALCON 900 Serial: 157 RegNo: N328JL HRS: 8560.9 AFL: 5069 As Of: 03-Oct-2025 Operator: LAMON AVIATION, LLC

Report Date: 14-Nov-2025

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
57-00-00-210-801-02C		GENERAL VISUAL INSPECTION OF THE WINGS - RH WING (CPCP)						Service ATA:57
	MOS	24 (+1m)		07-Oct-24	07-Oct-26	07-Nov-26	327 d (+31)	07-Oct-2026
	HRS			8507.6				
	AFL			5038				
Disposition: CPCP		REF: AMM 57-00-00-210-801						
FAA 2008-04-14		OPERATIONAL TEST AND INSPECT OVERWING EMERGENCY EXIT						AD ATA:52
	MOS	24		07-Oct-24	07-Oct-26		327 d	07-Oct-2026
	HRS			8507.6				
	AFL			5038				
Disposition: MANDATORY		REF: AD						
05-08-00-200-800-07		36 M/2400 FH INSPECTION						Package ATA:05
	MOS	36 (+1m)		10-Oct-23	10-Oct-26	10-Nov-26	330 d (+31)	10-Oct-2026
	HRS	2400 (+40)		8437.6	10837.6	10877.6	2276.7 (+40)	
	AFL			4993				
		REF: GENERIC NO REF						
05-08-00-200-800-17		36 M INSPECTION						Package ATA:05
	MOS	36 (+1m)		10-Oct-23	10-Oct-26	10-Nov-26	330 d (+31)	10-Oct-2026
	HRS			8437.6				
	AFL			4993				
		REF: GENERIC NO REF						
24-31-13-350-801-04		RESTORATION OF THE STARTER-GENERATORS (OVERHAUL) - APU STARTER-GENERATOR (21PA)						Service ATA:24
PN:8060-141-1	MOS			28-Apr-21				25-Oct-2026
SN:145	HRS			7749.7				
	AFL			4515				
	APH	900 (+3%)		5815.7	6715.7	6742.7	227.3 (+27)	
Disposition: OVERHAUL		REF: AMM 24-31-13-350-801						
25-62-01-720-801-01		FUNCTIONAL TEST OF THE FDR / CVR UNDERWATER LOCATOR BEACONS - CVR UNDERWATER LOCATOR BEACON (900RK)						Service ATA:25
PN:DK120/90	MOS	25 (+3%)		07-Oct-24	07-Nov-26	29-Nov-26	358 d (+22)	07-Nov-2026
SN:AT208658	HRS			8507.6				
	AFL			5038				
		REF: AMM 25-62-01-720-801						
31-21-05-960-801-01		REPLACEMENT OF THE PILOT CLOCK BATTERIES - LH PILOT CLOCK (L1DT) BATTERY						Service ATA:31
PN:811BFTR24HR	MOS	25		07-Oct-24	07-Nov-26		358 d	07-Nov-2026
SN:30896	HRS			8507.6				
	AFL			5038				
Disposition: LIFE LIMIT		REF: AMM 31-21-05-960-801						

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: FALCON 900 Serial: 157 RegNo: N328JL HRS: 8560.9 AFL: 5069 As Of: 03-Oct-2025 Operator: LAMON AVIATION, LLC

Report Date: 14-Nov-2025

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due
31-21-05-960-801-02		REPLACEMENT OF THE PILOT CLOCK BATTERIES - RH PILOT CLOCK (R1DT) BATTERY						Service ATA:31
PN:811BFTR24HR	MOS	25		07-Oct-24	07-Nov-26		358 d	07-Nov-2026
SN:30897	HRS			8507.6				
	AFL			5038				
Disposition: SCRAP			REF: AMM 31-21-05-960-801					
33-50-37-960-802-01		DISCARD OF THE EPS BATTERY PACKS - EPS 1 (L3LW) BATTERY PACK						Service ATA:33
PN:D734-02-001	MOS	25		07-Oct-24	07-Nov-26		358 d	07-Nov-2026
SN:2990071	HRS			8507.6				
	AFL			5038				
Disposition: LIFE LIMIT			REF: AMM 33-50-37-960-802					
33-50-37-960-802-02		DISCARD OF THE EPS BATTERY PACKS - EPS 2 (R3LW) BATTERY PACK						Service ATA:33
PN:AD-C734-01-030	MOS	25		07-Oct-24	07-Nov-26		358 d	07-Nov-2026
SN:CF36701/03/23	HRS			8507.6				
	AFL			5038				
Disposition: LIFE LIMIT			REF: AMM 33-50-37-960-802					
33-50-37-960-802-03		DISCARD OF THE EPS BATTERY PACKS - EPS 3 (4LW) BATTERY PACK						Service ATA:33
PN:D734-02-001	MOS	25		07-Oct-24	07-Nov-26		358 d	07-Nov-2026
SN:1194	HRS			8507.6				
	AFL			5038				
Disposition: LIFE LIMIT			REF: AMM 33-50-37-960-802					