



DueList Report

FALCON 900

S/N 157 N328JL

OWNER: LAMON AVIATION, LLC ADDRESS: 132 LEE DUGGAN DR. STE 3 TX 77498 OFFICE: FAX:	OPERATOR: LAMON AVIATION, LLC ADDRESS: 132 LEE DUGGAN DR. STE 3 TX 77498 OFFICE: FAX:	OPERATOR: JET LINK AVIATION, LLC ADDRESS: 132 LEE DUGAN DR SUGAR LAND TX OFFICE: FAX:	CAMO: JET LINK AVIATION, LLC ADDRESS: 132 LEE DUGAN DR SUGAR LAND TX OFFICE: FAX:
ANALYST: CHRISTIAN HELLOFS EMAIL: CHELLOFS@CAMPSYSTEMS.COM	+1-912-298-1324 (DIRECT) +1-631-588-3200 (MAIN) WWW.CAMPSYSTEMS.COM	800-787-9749 (EFAX-CARDS) 631-980-4222 (FAX)	

PROJECTED: 6 MOS. to 07/30/2026

AIRCRAFT	SERIAL/REGNO: 157/N328JL	MODEL: FALCON 900	MANUFACTURER: DASSAULT AVIATION S.A.
----------	--------------------------	-------------------	--------------------------------------

CERTIFICATION DATE: 02-FEB-1996	LAST ACTUALS: 8561.3 A/C HRS as of 19-JAN-2026 5070 AFL as of 19-JAN-2026 6488.4 APH as of 19-JAN-2026	PROJECTED: 8680.32 5129 6607
---------------------------------	---	---------------------------------------

APU	SERIAL/PART: P-276/3800188-2	MODEL: GTCP36-150(F)	MANUFACTURER: HONEYWELL
-----	------------------------------	----------------------	-------------------------

INSTALLED ON: 07-OCT-2024 6368.8 APU HRS 8507.6 A/C HRS APUS	LAST ACTUALS: 6488.4 APU HRS as of 19-JAN-2026 APUS as of 03-MAR-2025	PROJECTED: 6607.42 0
--	---	----------------------------

ENGINE NO. 1	SERIAL/PART: P-101280/3075330-3	MODEL: TFE731-5BR-1C	MANUFACTURER: HONEYWELL
--------------	---------------------------------	----------------------	-------------------------

INSTALLED ON: 01-JUN-2017 6449.4 ENG. HRS 6742.8 A/C HRS 3739 ENC	LAST ACTUALS: 8271.8 ENG. HRS as of 19-JAN-2026 4931 ENC as of 19-JAN-2026	PROJECTED: 8390.82 5032
---	--	-------------------------------

ENGINE NO. 2	SERIAL/PART: P-101279/3075330-3	MODEL: TFE731-5BR-1C	MANUFACTURER: HONEYWELL
--------------	---------------------------------	----------------------	-------------------------

INSTALLED ON: 11-MAR-2020 7418 ENG. HRS 7541.7 A/C HRS 4343 ENC	LAST ACTUALS: 8437.6 ENG. HRS as of 19-JAN-2026 5022 ENC as of 19-JAN-2026	PROJECTED: 8556.62 5123
---	--	-------------------------------

ENGINE NO. 3	SERIAL/PART: P-101282/3075330-3	MODEL: TFE731-5BR-1C	MANUFACTURER: HONEYWELL
--------------	---------------------------------	----------------------	-------------------------

INSTALLED ON: 17-NOV-2017 6727.4 ENG. HRS 6923.9 A/C HRS 3810 ENC	LAST ACTUALS: 8364.8 ENG. HRS as of 19-JAN-2026 4888 ENC as of 19-JAN-2026	PROJECTED: 8483.82 4989
---	--	-------------------------------



Due List Report

Model: FALCON 900 Serial: 157 RegNo: N328JL HRS: 8561.3 AFL: 5070 As Of: 19-Jan-2026 Operator: LAMON AVIATION, LLC

Report Date: 30-Jan-2026

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est. Due
05-08-00-200-800-05		12 M/800 FH INSPECTION						Package ATA:05
	MOS	12 (+1m)		07-Oct-24	07-Oct-25	07-Nov-25	OVD	
	HRS	800 (+40)		8507.6	9307.6	9347.6	746.3 (+40)	
	AFL			5038				
REF: GENERIC NO REF								
05-08-00-200-800-15		12 M INSPECTION						Package ATA:05
	MOS	12 (+1m)		07-Oct-24	07-Oct-25	07-Nov-25	OVD	
	HRS			8507.6				
	AFL			5038				
REF: GENERIC NO REF								
05-60-00-200-801-01		BASIC INSPECTION						Service ATA:05
	MOS	12 (+1m)		07-Oct-24	07-Oct-25	07-Nov-25	OVD	
	HRS	400 (+40)		8507.6	8907.6	8947.6	346.3 (+40)	
	AFL			5038				
REF: AMM 05-60-00-200-801								
05-60-00-200-801-03		BASIC INSPECTION - GROUND SERVICING CHECKS						Service ATA:05
	MOS	12 (+1m)		07-Oct-24	07-Oct-25	07-Nov-25	OVD	
	HRS	400 (+40)		8507.6	8907.6	8947.6	346.3 (+40)	
	AFL			5038				
REF: AMM 05-60-00-200-801								
24-32-09-610-801-02		SERVICING OF "SAFT" NICKEL-CADMIUM STAND-BY BATTERIES - IRS 1 BATTERY (L12FP)						Service ATA:24
PN:135687	MOS	12 (+3%)		07-Oct-24	07-Oct-25	18-Oct-25	OVD	
SN:3505	HRS			8507.6				
	AFL			5038				
REF: AMM 24-32-09-610-801								
24-32-09-610-801-03		SERVICING OF "SAFT" NICKEL-CADMIUM STAND-BY BATTERIES - IRS 2 BATTERY (R12FP)						Service ATA:24
PN:804747	MOS	12 (+3%)		07-Oct-24	07-Oct-25	18-Oct-25	OVD	
SN:1026	HRS			8507.6				
	AFL			5038				
REF: AMM 24-32-09-610-801								
24-32-09-610-801-04		SERVICING OF "SAFT" NICKEL-CADMIUM STAND-BY BATTERIES - IRS 3 BATTERY (32FP)						Service ATA:24
PN:135687	MOS	12 (+3%)		07-Oct-24	07-Oct-25	18-Oct-25	OVD	
SN:5127	HRS			8507.6				
	AFL			5038				
REF: AMM 24-32-09-610-801								



Due List Report

Model: FALCON 900 Serial: 157 RegNo: N328JL HRS: 8561.3 AFL: 5070 As Of: 19-Jan-2026 Operator: LAMON AVIATION, LLC

Report Date: 30-Jan-2026

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est. Due
24-32-09-610-801-05		SERVICING OF "SAFT" NICKEL-CADMIUM STAND-BY BATTERIES - VHF 3 STAND-BY BATTERY (28RC)						
PN:804747	MOS	12 (+3%)		07-Oct-24	07-Oct-25	18-Oct-25	OVD	Service ATA:24
SN:2017	HRS			8507.6				
	AFL			5038				
REF: AMM 24-32-09-610-801								
25-61-00-200-881-01		INSPECTION OF THE EMERGENCY LOCATOR TRANSMITTER (ELT) SYSTEM (FAR 91.207)						
	MOS	12		07-Oct-24	07-Oct-25		OVD	Service ATA:25
	HRS			8507.6				
	AFL			5038				
Disposition: MANDATORY REF: AMM GENERIC 1								
25-62-01-720-801-02		FUNCTIONAL TEST OF THE FDR / CVR UNDERWATER LOCATOR BEACONS - FDR UNDERWATER LOCATOR BEACON (900FZ)						
PN:DK120/90	MOS	25 (+3%)		10-Oct-23	10-Nov-25	02-Dec-25	OVD	Service ATA:25
SN:AT123547	HRS			8437.6				
	AFL			4993				
REF: AMM 25-62-01-720-801								
25-62-05-960-801-02		RESTORATION OF THE FDR / CVR UNDERWATER LOCATOR BEACONS (DISCARD OF THE FDR / CVR ULB BATTERY) - FDR ULB BATTERY (900FZ1)						
PN:DK120/90	MOS	DUE		29-May-19	31-Dec-25 (M)		OVD	Service ATA:25
SN:AT123547	HRS			7433.9				
	AFL			4313				
Disposition: LIFE LIMIT REF: AMM 25-62-05-960-801								
253A05 ^U		EQUIPMENT AUDIT (TPED'S) (ST11071SC) (DOC# L60-CA001)						
	MOS	12		07-Oct-24	07-Oct-25		OVD	Service ATA:25
	HRS			8507.6				
	AFL			5038				
REF:								
26-20-13-960-801-01		DISCARD OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 1 FIRST-SHOOT PERCUSSION CARTRIDGE (L3WB)						
PN:861385	MOS	60		27-Oct-20	27-Oct-25		OVD	Service ATA:26
SN:N/A	HRS							
	AFL							
Disposition: SCRAP REF: AMM 26-20-13-960-801								
26-20-13-960-801-02		DISCARD OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 3 FIRST-SHOOT PERCUSSION CARTRIDGE (R3WB)						
PN:861375	MOS	60		02-Sep-20	02-Sep-25		OVD	Service ATA:26
SN:NSN	HRS							
	AFL							
Disposition: SCRAP REF: AMM 26-20-13-960-801								

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: FALCON 900 Serial: 157 RegNo: N328JL HRS: 8561.3 AFL: 5070 As Of: 19-Jan-2026 Operator: LAMON AVIATION, LLC

Report Date: 30-Jan-2026

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est.Due	
26-20-13-960-801-03		DISCARD OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 2 SECOND-SHOOT LH PERCUSSION CARTRIDGE (L4WB)						Service	ATA:26
PN:861375	MOS	60		27-Oct-20	27-Oct-25		OVD		
SN:N/A	HRS								
	AFL								
Disposition: SCRAP		REF: AMM 26-20-13-960-801							
26-20-13-960-801-04		DISCARD OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 2 SECOND-SHOOT RH PERCUSSION CARTRIDGE (R4WB)						Service	ATA:26
PN:861385	MOS	60		27-Oct-20	27-Oct-25		OVD		
SN:N/A	HRS								
	AFL								
Disposition: SCRAP		REF: AMM 26-20-13-960-801							
26-20-13-960-801-05		DISCARD OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 1 SECOND-SHOOT PERCUSSION CARTRIDGE (L5WB)						Service	ATA:26
PN:861385	MOS	60		27-Oct-20	27-Oct-25		OVD		
SN:N/A	HRS								
	AFL								
Disposition: SCRAP		REF: AMM 26-20-13-960-801							
26-20-13-960-801-06		DISCARD OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 3 SECOND-SHOOT PERCUSSION CARTRIDGE (R5WB)						Service	ATA:26
PN:861375	MOS	60		27-Oct-20	27-Oct-25		OVD		
SN:N/A	HRS								
	AFL								
Disposition: SCRAP		REF: AMM 26-20-13-960-801							
26-20-13-960-801-07		DISCARD OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 2 FIRST-SHOOT LH PERCUSSION CARTRIDGE (L6WB)						Service	ATA:26
PN:861375	MOS	60		27-Oct-20	27-Oct-25		OVD		
SN:N/A	HRS								
	AFL								
Disposition: SCRAP		REF: AMM 26-20-13-960-801							
26-20-13-960-801-08		DISCARD OF THE FIRE EXTINGUISHER PERCUSSION CARTRIDGES - ENGINE 2 FIRST-SHOOT RH PERCUSSION CARTRIDGE (R6WB)						Service	ATA:26
PN:861385	MOS	60		27-Oct-20	27-Oct-25		OVD		
SN:N/A	HRS								
	AFL								
Disposition: SCRAP		REF: AMM 26-20-13-960-801							

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: FALCON 900 Serial: 157 RegNo: N328JL HRS: 8561.3 AFL: 5070 As Of: 19-Jan-2026 Operator: LAMON AVIATION, LLC

Report Date: 30-Jan-2026

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est. Due	
26-20-15-720-801-01		WEIGHING OF THE PORTABLE FIRE EXTINGUISHERS - COCKPIT PORTABLE FIRE EXTINGUISHER (500WB)						Service	ATA:26
PN:C352	MOS	12 (+3%)		07-Oct-24	07-Oct-25	18-Oct-25	OVD		
SN:Y-649043	HRS			8507.6					
	AFL			5038					
REF: AMM 26-20-15-720-801									
26-20-15-720-801-02		WEIGHING OF THE PORTABLE FIRE EXTINGUISHERS - CABIN FRONT PORTABLE FIRE EXTINGUISHER (501WB)						Service	ATA:26
PN:C352	MOS	12 (+3%)		07-Oct-24	07-Oct-25	18-Oct-25	OVD		
SN:Y-439906	HRS			8507.6					
	AFL			5038					
REF: AMM 26-20-15-720-801									
26-20-15-720-801-03		WEIGHING OF THE PORTABLE FIRE EXTINGUISHERS - CABIN REAR PORTABLE FIRE EXTINGUISHER (502WB)						Service	ATA:26
PN:C352	MOS	12 (+3%)		07-Oct-24	07-Oct-25	18-Oct-25	OVD		
SN:Y-547480	HRS			8507.6					
	AFL			5038					
REF: AMM 26-20-15-720-801									
26-20-15-790-801-01		HYDROSTATIC TEST OF THE PORTABLE FIRE EXTINGUISHERS - COCKPIT PORTABLE FIRE EXTINGUISHER (500WB)						Service	ATA:26
PN:C352	MOS	60		13-Nov-20	13-Nov-25		OVD		
SN:Y-649043	HRS			0					
	AFL			0					
REF: AMM 26-20-15-790-801									
26-20-15-790-801-02		HYDROSTATIC TEST OF THE PORTABLE FIRE EXTINGUISHERS - CABIN FRONT PORTABLE FIRE EXTINGUISHER (501WB)						Service	ATA:26
PN:C352	MOS	60		13-Nov-20	13-Nov-25		OVD		
SN:Y-439906	HRS			7627.5					
	AFL			4445					
REF: AMM 26-20-15-790-801									
26-20-15-790-801-03		HYDROSTATIC TEST OF THE PORTABLE FIRE EXTINGUISHERS - CABIN REAR PORTABLE FIRE EXTINGUISHER (502WB)						Service	ATA:26
PN:C352	MOS	60		13-Nov-20	13-Nov-25		OVD		
SN:Y-547480	HRS			7627.5					
	AFL			4445					
REF: AMM 26-20-15-790-801									
27-40-01-210-802-01		VISUAL INSPECTION OF THE HORIZONTAL STABILIZER ACTUATOR - HORIZONTAL STABILIZER ELECTRIC ACTUATOR (3CF)						Service	ATA:27
PN:021121-11	MOS	72 (+3%)		25-Nov-19	25-Nov-25	29-Jan-26	OVD		
SN:141	HRS			7516.2					
	AFL	3750 (+3%)		4372	8122	8234.5	3052 (+112.5)		
REF: AMM 27-40-01-210-802									



Due List Report

Model: FALCON 900 Serial: 157 RegNo: N328JL HRS: 8561.3 AFL: 5070 As Of: 19-Jan-2026 Operator: LAMON AVIATION, LLC

Report Date: 30-Jan-2026

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est. Due
28-30-00-680-803-01		DRAINING OF THE GRAVITY DEFUELING LINE						Service ATA:28
	MOS	2 (+5d)		29-Jul-25	29-Sep-25	04-Oct-25	OVD	
	HRS			8559.4				
	AFL			5068				
		REF: AMM 28-30-00-680-803						
28-30-00-680-804-01		DRAINING WATER FROM THE FUEL TANKS						Service ATA:28
	MOS	2 (+5d)		29-Jul-25	29-Sep-25	04-Oct-25	OVD	
	HRS			8559.4				
	AFL			5068				
		REF: AMM 28-30-00-680-804						
32-00-00-700-801-01		CHECK OF THE MLG AND NLG UPLOCK BOXES - NLG UPLOCK BOX (13GA)						Service ATA:32
	MOS	18 (+1m)	Adj:-204d	07-Oct-24	15-Sep-25	15-Oct-25	OVD	
	HRS			8507.6				
	AFL			5038				
		REF: AMM 32-00-00-700-801						
32-00-00-700-801-02		CHECK OF THE MLG AND NLG UPLOCK BOXES - LH MLG UPLOCK BOX (L7GA)						Service ATA:32
	MOS	18 (+1m)	Adj:-204d	07-Oct-24	15-Sep-25	15-Oct-25	OVD	
	HRS			8507.6				
	AFL			5038				
		REF: AMM 32-00-00-700-801						
32-00-00-700-801-03		CHECK OF THE MLG AND NLG UPLOCK BOXES - RH MLG UPLOCK BOX (R7GA)						Service ATA:32
	MOS	18 (+1m)	Adj:-204d	07-Oct-24	15-Sep-25	15-Oct-25	OVD	
	HRS			8507.6				
	AFL			5038				
		REF: AMM 32-00-00-700-801						
32-10-00-640-801-01		LUBRICATION OF THE MAIN LANDING GEARS (MLG) AND MLG DOORS - LH MLG AND DOORS						Service ATA:32
	MOS	8 (+1m)	Adj:-196d	29-Jul-25	14-Sep-25	14-Oct-25	OVD	
	HRS			8559.4				
	AFL	400		5068	5468		398	
		REF: AMM 32-10-00-640-801						
32-10-00-640-801-02		LUBRICATION OF THE MAIN LANDING GEARS (MLG) AND MLG DOORS - RH MLG AND DOORS						Service ATA:32
	MOS	8 (+1m)	Adj:-196d	29-Jul-25	14-Sep-25	14-Oct-25	OVD	
	HRS			8559.4				
	AFL	400		5068	5468		398	
		REF: AMM 32-10-00-640-801						

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: FALCON 900 Serial: 157 RegNo: N328JL HRS: 8561.3 AFL: 5070 As Of: 19-Jan-2026 Operator: LAMON AVIATION, LLC

Report Date: 30-Jan-2026

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est. Due	
32-20-00-640-801-01		LUBRICATION OF THE NOSE LANDING GEAR (NLG) AND NLG DOORS - NLG LEG (3GF)						Service	ATA:32
	MOS	8 (+1m)	Adj:-197d	29-Jul-25	13-Sep-25	13-Oct-25	OVD		
	HRS			8559.4					
	AFL	400		5068	5468		398		
REF: AMM 32-20-00-640-801									
32-44-00-780-801-01		PRESSURE CHECK OF THE MLG AND NLG WHEEL TIRES						Service	ATA:32
	MOS	2 (+5d)		29-Jul-25	29-Sep-25	04-Oct-25	OVD		
	HRS			8559.4					
	AFL			5068					
REF: AMM 32-44-00-780-801									
33-50-05-350-803-01		RESTORATION OF THE AIR LITE 2R LED RECHARGEABLE FLASHLIGHTS (OVERHAUL) - FLASH LIGHT (2LT)						Service	ATA:33
PN:P2-07-0025-001	MOS	12 (+3%)		07-Oct-24	07-Oct-25	18-Oct-25	OVD		
SN:UNKNOWN	HRS			8507.6					
	AFL			5038					
REF: AMM 33-50-05-350-803									
345A12 ^U		EQUIPMENT INSPECTION AVANCE L5 BROADBAND SYSTEM (DOC#1038081)						Service	ATA:34
	MOS	12		07-Oct-24	07-Oct-25		OVD		
	HRS			8507.6					
	AFL			5038					
REF:									
35-30-05-210-801-01		GENERAL VISUAL INSPECTION OF THE PORTABLE OXYGEN BOTTLE - PORTABLE OXYGEN BOTTLE AND MASKS (537WH)						Service	ATA:35
PN:894-20330	MOS	12 (+3%)		07-Oct-24	07-Oct-25	18-Oct-25	OVD		
SN:P09081020	HRS			8507.6					
	AFL			5038					
REF: AMM 35-30-05-210-801									
38-10-00-670-801-01		STERILIZATION OF THE POTABLE WATER SYSTEM - STANDARD STERILIZATION						Service	ATA:38
	MOS	6 (+1m)	Adj:-114d	29-Jul-25	07-Oct-25	07-Nov-25	OVD		
	HRS			8559.4					
	AFL			5068					
REF: AMM 38-10-00-670-801									
53-10-00-200-808-01C		INSPECTION OF THE NLG BAY (CPCP)						Service	ATA:53
	MOS	12 (+1m)		07-Oct-24	07-Oct-25	07-Nov-25	OVD		
	HRS			8507.6					
	AFL			5038					
REF: AMM 53-10-00-200-808									
Disposition: CPCP									



Due List Report

Model: FALCON 900 Serial: 157 RegNo: N328JL HRS: 8561.3 AFL: 5070 As Of: 19-Jan-2026 Operator: LAMON AVIATION, LLC

Report Date: 30-Jan-2026

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est. Due	
53-40-00-200-804-01C		INSPECTION OF THE MLG BAYS - LH MLG BAY (CPCP)							Service ATA:53
	MOS	12 (+1m)		07-Oct-24	07-Oct-25	07-Nov-25	OVD		
	HRS			8507.6					
	AFL			5038					
Disposition: CPCP		REF: AMM 53-40-00-200-804							
53-40-00-200-804-02C		INSPECTION OF THE MLG BAYS - RH MLG BAY (CPCP)							Service ATA:53
	MOS	12 (+1m)		07-Oct-24	07-Oct-25	07-Nov-25	OVD		
	HRS			8507.6					
	AFL			5038					
Disposition: CPCP		REF: AMM 53-40-00-200-804							
53-50-00-210-804-02C		GENERAL VISUAL INSPECTION OF THE REAR COMPARTMENT (CPCP)							Service ATA:53
	MOS	12 (+1m)		07-Oct-24	07-Oct-25	07-Nov-25	OVD		
	HRS			8507.6					
	AFL			5038					
Disposition: CPCP		REF: AMM 53-50-00-210-804							
54-00-00-210-810-01		GENERAL VISUAL INSPECTION OF THE ENGINE 1 AND 3 NACELLES AND PYLONS - ENGINE 1 (L4EZ)							Service ATA:54
	MOS	12 (+1m)		07-Oct-24	07-Oct-25	07-Nov-25	OVD		
	HRS	300 (+100)	Adj:-20.4	8507.6	8787.2	8887.2	225.9 (+100)		
	AFL			5038					
Disposition: CPCP		REF: AMM 54-00-00-210-810							
54-00-00-210-810-01C		GENERAL VISUAL INSPECTION OF THE ENGINE 1 AND 3 NACELLES AND PYLONS - ENGINE 1 (L4EZ) (CPCP)							Service ATA:54
	MOS	12 (+1m)		07-Oct-24	07-Oct-25	07-Nov-25	OVD		
	HRS			8507.6					
	AFL			5038					
	APH								
Disposition: CPCP		REF: AMM 54-00-00-210-810							
54-00-00-210-810-02		GENERAL VISUAL INSPECTION OF THE ENGINE 1 AND 3 NACELLES AND PYLONS - ENGINE 3 (R4EZ)							Service ATA:54
	MOS	12 (+1m)		07-Oct-24	07-Oct-25	07-Nov-25	OVD		
	HRS	300 (+100)	Adj:-20.4	8507.6	8787.2	8887.2	225.9 (+100)		
	AFL			5038					
Disposition: CPCP		REF: AMM 54-00-00-210-810							
54-00-00-210-810-02C		GENERAL VISUAL INSPECTION OF THE ENGINE 1 AND 3 NACELLES AND PYLONS - ENGINE 3 (R4EZ) (CPCP)							Service ATA:54
	MOS	12 (+1m)		07-Oct-24	07-Oct-25	07-Nov-25	OVD		
	HRS			8507.6					
	AFL			5038					
	APH								
Disposition: CPCP		REF: AMM 54-00-00-210-810							

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: FALCON 900 Serial: 157 RegNo: N328JL HRS: 8561.3 AFL: 5070 As Of: 19-Jan-2026 Operator: LAMON AVIATION, LLC

Report Date: 30-Jan-2026

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est. Due
54-00-00-210-811-01 ^S		GENERAL VISUAL INSPECTION OF THE ENGINE 2 NACELLE						
	MOS	12 (+1m)		07-Oct-24	07-Oct-25 (M)	07-Nov-25	OVD	Service ATA:54
REF: AMM 54-00-00-210-811								
SB F900-388 REV 04		WINGS - WING TANK MODIFICATION, SERVICE BULLETIN						
	MOS	T:150		EFF	19-Apr-24 * (M)		OVD	Bulletin ATA:57
	HRS							
	AFL							
Disposition: MANDATORY REF: BULLETINS								
25-64-13-200-801-01		INSPECTION OF LIFE RAFT - NO. 1 LIFE RAFT						
PN:1015FAUL-H30-1-100	MOS	36 (+3%)		12-Jan-23	12-Jan-26	14-Feb-26	TOL (+15 d)	Service ATA:25 30-Jan-2026
SN:10UL-02972	HRS							
	AFL							
REF: AMM 25-64-13-200-801								
25-64-13-200-801-01		INSPECTION OF LIFE RAFT - NO. 2 LIFE RAFT						
PN:1015FAUL-H30-1-100	MOS	36 (+3%)		12-Jan-23	12-Jan-26	14-Feb-26	TOL (+15 d)	Service ATA:25 30-Jan-2026
SN:10UL-02973	HRS			8290.3				
	AFL			4878				
REF: AMM 25-64-13-200-801								
24-32-01-700-801-01		REGULAR CHECK OF A MAIN NICKEL-CADMIUM BATTERY - BATTERY 1 (L1PE)						
PN:4076-10	MOS	6 (+10%)		29-Jul-25	29-Jan-26	16-Feb-26	TOL (+17 d)	Service ATA:24 30-Jan-2026(2)
SN:088398	HRS	250 (+25)		8559.4	8809.4	8834.4	248.1 (+25)	
	AFL			5068				
REF: AMM 24-32-01-700-801								
24-32-01-700-801-02		REGULAR CHECK OF A MAIN NICKEL-CADMIUM BATTERY - BATTERY 2 (R1PE)						
PN:4076-10	MOS	6 (+10%)		29-Jul-25	29-Jan-26	16-Feb-26	TOL (+17 d)	Service ATA:24 30-Jan-2026(2)
SN:121547	HRS	250 (+25)		8559.4	8809.4	8834.4	248.1 (+25)	
	AFL			5068				
REF: AMM 24-32-01-700-801								
35-30-09-100-801-01		CLEANING OF THE PORTABLE OXYGEN MASKS - PORTABLE OXYGEN BOTTLE AND MASKS (537WH)						
PN:894-20330	MOS	12 (+3%)	Adj:-171d	29-Jul-25	08-Feb-26	18-Feb-26	9 d (+10)	Service ATA:35 08-Feb-2026
SN:P09081020	HRS			8559.4				
	AFL			5068				
REF: AMM 35-30-09-100-801								
FAA 2025-26-06		APPLIANCE AD - INCORRECT USAGE OF PORTABLE BREATHING EQUIPMENT						
	DAYS	T:30		EFF	13-Feb-26 *		14 d	AD ATA:35 13-Feb-2026
	HRS							
	AFL							
Disposition: MANDATORY REF: AD								

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: FALCON 900 Serial: 157 RegNo: N328JL HRS: 8561.3 AFL: 5070 As Of: 19-Jan-2026 Operator: LAMON AVIATION, LLC

Report Date: 30-Jan-2026

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est. Due
FAA 2013-09-03		WINGS - FUEL TANK MODIFICATION						AD ATA:57
	MOS	T:150		EFF	14-Feb-26 *		15 d	14-Feb-2026
	HRS							
	AFL							
Disposition: MANDATORY		REF: AD						
499020		APU - REMOVE AND INSPECT MAGNETIC DRAIN PLUG						Service ATA:49
	MOS	17		07-Oct-24	07-Mar-26		36 d	07-Mar-2026
	HRS	750		6368.8	7118.8		630.4	
	APUS							
		REF: MM 49-90-46						
499030		APU - DRAIN AND REFILL OIL						Service ATA:49
	MOS	17		07-Oct-24	07-Mar-26		36 d	07-Mar-2026
	HRS	750		6368.8	7118.8		630.4	
	APUS							
		REF: MM 49-20-00						
499040		APU - REMOVE AND REPLACE OIL FILTER ELEMENT						Service ATA:49
	MOS	17		07-Oct-24	07-Mar-26		36 d	07-Mar-2026
	HRS	750		6368.8	7118.8		630.4	
	APUS							
		REF: MM 49-90-47						
05-08-00-200-800-31		1C INSPECTION						Package ATA:05
	MOS	72 (+2m)		11-Mar-20	11-Mar-26	11-May-26	40 d (+61)	11-Mar-2026
	HRS			7541.7				
	AFL	3750		4391	8141		3071	
		REF: GENERIC NO REF						
05-50-00-910-801-01		AIRCRAFT CHECK FLIGHT						Service ATA:05
	MOS	72 (+2m)		11-Mar-20	11-Mar-26 (M)	11-May-26	40 d (+61)	11-Mar-2026
	HRS			7541.7				
	AFL	3750		4391	8141 (M)		3071	
		REF: AMM 05-50-00-910-801						
050A00 ^U		INSPECT HIGH SPEED INTERNET SYSTEM INSTALLATION						Service ATA:05
	MOS	72			11-Mar-26 (M)		40 d	11-Mar-2026
	HRS							
	AFL	3750			8141 (M)		3071	
		REF:						

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: FALCON 900 Serial: 157 RegNo: N328JL HRS: 8561.3 AFL: 5070 As Of: 19-Jan-2026 Operator: LAMON AVIATION, LLC

Report Date: 30-Jan-2026

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est. Due	
32-11-00-220-801-01		DETAILED INSPECTION OF THE MLG LEGS - LH MLG LEG (L2GF)						Service	ATA:32
PN:D22801100-11	MOS	72 (+8m)		11-Mar-20	11-Mar-26	11-Nov-26	40 d (+245)	11-Mar-2026	
SN:U167	HRS			7541.7					
	AFL			4391					
REF: AMM 32-11-00-220-801									
32-11-00-220-801-02		DETAILED INSPECTION OF THE MLG LEGS - RH MLG LEG (R2GF)						Service	ATA:32
PN:D22801100-11	MOS	72 (+8m)		11-Mar-20	11-Mar-26	11-Nov-26	40 d (+245)	11-Mar-2026	
SN:U166	HRS			7541.7					
	AFL			4391					
REF: AMM 32-11-00-220-801									
32-11-25-220-801-01		DETAILED INSPECTION OF MLG BALL-JOINT BEARINGS AND BEARING BORES - LH MLG FRONT BALL-JOINT BEARING (L90GA)						Service	ATA:32
	MOS	72 (+8m)		11-Mar-20	11-Mar-26	11-Nov-26	40 d (+245)	11-Mar-2026	
	HRS			7541.7					
	AFL			4391					
REF: AMM 32-11-25-220-801									
32-11-25-220-801-02		DETAILED INSPECTION OF MLG BALL-JOINT BEARINGS AND BEARING BORES - LH MLG REAR BALL-JOINT BEARING (L100GA)						Service	ATA:32
	MOS	72 (+8m)		11-Mar-20	11-Mar-26	11-Nov-26	40 d (+245)	11-Mar-2026	
	HRS			7541.7					
	AFL			4391					
REF: AMM 32-11-25-220-801									
32-11-25-220-801-03		DETAILED INSPECTION OF MLG BALL-JOINT BEARINGS AND BEARING BORES - RH MLG FRONT BALL-JOINT BEARING (R90GA)						Service	ATA:32
	MOS	72 (+8m)		11-Mar-20	11-Mar-26	11-Nov-26	40 d (+245)	11-Mar-2026	
	HRS			7541.7					
	AFL			4391					
REF: AMM 32-11-25-220-801									
32-11-25-220-801-04		DETAILED INSPECTION OF MLG BALL-JOINT BEARINGS AND BEARING BORES - RH MLG REAR BALL-JOINT BEARING (R100GA)						Service	ATA:32
	MOS	72 (+8m)		11-Mar-20	11-Mar-26	11-Nov-26	40 d (+245)	11-Mar-2026	
	HRS			7541.7					
	AFL			4391					
REF: AMM 32-11-25-220-801									
32-21-00-220-801-01		DETAILED INSPECTION OF THE NLG LEG - NLG LEG (3GF)						Service	ATA:32
PN:D22811200-13	MOS	72 (+8m)		11-Mar-20	11-Mar-26	11-Nov-26	40 d (+245)	11-Mar-2026	
SN:U165	HRS			7541.7					
	AFL			4391					
REF: AMM 32-21-00-220-801									



Due List Report

Model: FALCON 900 Serial: 157 RegNo: N328JL HRS: 8561.3 AFL: 5070 As Of: 19-Jan-2026 Operator: LAMON AVIATION, LLC

Report Date: 30-Jan-2026

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est. Due
32-21-09-220-801-01		DETAILED INSPECTION OF THE NLG LEG AND NLG DRAG BRACE BALL-JOINT BEARINGS AND BEARING BORES - LH NLG DRAG BRACE BALL-JOINT BEARING						Service ATA:32
	MOS	72 (+8m)		11-Mar-20	11-Mar-26	11-Nov-26	40 d (+245)	11-Mar-2026
	HRS			7541.7				
	AFL			4391				
REF: AMM 32-21-09-220-801								
32-21-09-220-801-02		DETAILED INSPECTION OF THE NLG LEG AND NLG DRAG BRACE BALL-JOINT BEARINGS AND BEARING BORES - RH NLG DRAG BRACE BALL-JOINT BEARING						Service ATA:32
	MOS	72 (+8m)		11-Mar-20	11-Mar-26	11-Nov-26	40 d (+245)	11-Mar-2026
	HRS			7541.7				
	AFL			4391				
REF: AMM 32-21-09-220-801								
32-21-09-220-801-03		DETAILED INSPECTION OF THE NLG LEG AND NLG DRAG BRACE BALL-JOINT BEARINGS AND BEARING BORES - LH NLG LEG BALL-JOINT BEARING						Service ATA:32
	MOS	72 (+8m)		11-Mar-20	11-Mar-26	11-Nov-26	40 d (+245)	11-Mar-2026
	HRS			7541.7				
	AFL			4391				
REF: AMM 32-21-09-220-801								
32-21-09-220-801-04		DETAILED INSPECTION OF THE NLG LEG AND NLG DRAG BRACE BALL-JOINT BEARINGS AND BEARING BORES - RH NLG LEG BALL-JOINT BEARING						Service ATA:32
	MOS	72 (+8m)		11-Mar-20	11-Mar-26	11-Nov-26	40 d (+245)	11-Mar-2026
	HRS			7541.7				
	AFL			4391				
REF: AMM 32-21-09-220-801								
53-00-00-220-801-01C		DETAILED INSPECTION OF THE FUSELAGE EXTERIOR - DETAILED INSPECTION (CPCP)						Service ATA:53
	MOS	72 (+2m)		11-Mar-20	11-Mar-26	11-May-26	40 d (+61)	11-Mar-2026
	HRS			7541.7				
	AFL			4391				
REF: AMM 53-00-00-220-801								
Disposition: CPCP								
53-10-00-220-802-01C		DETAILED INSPECTION OF THE FLIGHT COMPARTMENT (CPCP)						Service ATA:53
	MOS	72 (+2m)		11-Mar-20	11-Mar-26	11-May-26	40 d (+61)	11-Mar-2026
	HRS			7541.7				
	AFL			4391				
REF: AMM 53-10-00-220-802								
Disposition: CPCP								
53-10-33-220-802-01C		INSPECTION OF THE COCKPIT WINDSHIELD / WINDOW FRAMES / RETAINERS AND ATTACHMENTS (CPCP)						Service ATA:53
	MOS	72 (+2m)		11-Mar-20	11-Mar-26	11-May-26	40 d (+61)	11-Mar-2026
	HRS			7541.7				
	AFL			4391				
REF: AMM 53-10-33-220-802								
Disposition: CPCP								

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: FALCON 900 Serial: 157 RegNo: N328JL HRS: 8561.3 AFL: 5070 As Of: 19-Jan-2026 Operator: LAMON AVIATION, LLC

Report Date: 30-Jan-2026

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est. Due
53-10-39-220-801-01C		DETAILED INSPECTION OF THE LOWER SECTION OF THE COCKPIT WINDSHIELD / WINDOW FRAMES (CPCP)						Service ATA:53
	MOS	72 (+2m)		11-Mar-20	11-Mar-26	11-May-26	40 d (+61)	11-Mar-2026
	HRS			7541.7				
	AFL			4391				
Disposition: CPCP		REF: AMM 53-10-39-220-801						
53-30-00-220-801-01C		DETAILED INSPECTION OF THE PASSENGER CABIN - UNDER THE FLOOR (CPCP)						Service ATA:53
	MOS	72 (+2m)		11-Mar-20	11-Mar-26	11-May-26	40 d (+61)	11-Mar-2026
	HRS			7541.7				
	AFL			4391				
Disposition: CPCP		REF: AMM 53-30-00-220-801						
53-40-00-220-801-01C		DETAILED INSPECTION OF THE FUSELAGE LOWER SECTION AREAS (CPCP)						Service ATA:53
	MOS	72 (+2m)		11-Mar-20	11-Mar-26	11-May-26	40 d (+61)	11-Mar-2026
	HRS			7541.7				
	AFL			4391				
Disposition: CPCP		REF: AMM 53-40-00-220-801						
53-40-00-220-802-01C		DETAILED INSPECTION OF THE FUSELAGE STRUCTURAL FUEL TANKS (CPCP)						Service ATA:53
	MOS	72 (+2m)		11-Mar-20	11-Mar-26	11-May-26	40 d (+61)	11-Mar-2026
	HRS			7541.7				
	AFL			4391				
Disposition: CPCP		REF: AMM 53-40-00-220-802						
53-50-00-220-803-01C		DETAILED INSPECTION OF THE BAGGAGE COMPARTMENT (CPCP)						Service ATA:53
	MOS	72 (+2m)		11-Mar-20	11-Mar-26	11-May-26	40 d (+61)	11-Mar-2026
	HRS			7541.7				
	AFL			4391				
Disposition: CPCP		REF: AMM 53-50-00-220-803						
55-00-00-220-801-01C		DETAILED INSPECTION OF THE HORIZONTAL AND VERTICAL STABILIZERS AND OF ENGINE 2 AIR INTAKE AND S-DUCT (CPCP)						Service ATA:55
	MOS	72 (+2m)		11-Mar-20	11-Mar-26	11-May-26	40 d (+61)	11-Mar-2026
	HRS			7541.7				
	AFL			4391				
Disposition: CPCP		REF: AMM 55-00-00-220-801						
57-00-00-220-802-01C		DETAILED INSPECTION OF THE WINGS - LH WING (CPCP)						Service ATA:57
	MOS	72 (+2m)		11-Mar-20	11-Mar-26	11-May-26	40 d (+61)	11-Mar-2026
	HRS			7541.7				
	AFL			4391				
Disposition: CPCP		REF: AMM 57-00-00-220-802						

?-Insufficient Information S -Suppressed Requirement * -Estimated Due(New Requirement)(EFF) - Effective C/W M -Manual Due (EBT) - Estimated Base Time



Due List Report

Model: FALCON 900 Serial: 157 RegNo: N328JL HRS: 8561.3 AFL: 5070 As Of: 19-Jan-2026 Operator: LAMON AVIATION, LLC

Report Date: 30-Jan-2026

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est. Due
57-00-00-220-802-02C		DETAILED INSPECTION OF THE WINGS - RH WING (CPCP)						Service ATA:57
	MOS	72 (+2m)		11-Mar-20	11-Mar-26	11-May-26	40 d (+61)	11-Mar-2026
	HRS			7541.7				
	AFL			4391				
Disposition: CPCP		REF: AMM 57-00-00-220-802						
57-10-00-290-801-01C		BORESCOPE INSPECTION OF THE WING TANKS (CPCP)						Service ATA:57
	MOS	72 (+2m)		11-Mar-20	11-Mar-26	11-May-26	40 d (+61)	11-Mar-2026
	HRS			7541.7				
	AFL			4391				
Disposition: CPCP		REF: AMM 57-10-00-290-801						
FAA 1999-25-09 PARA (B) & (C)		ACCOMPLISH HINGE PIN ASSEMBLIES OF HORIZONTAL STABILIZER						AD ATA:27
	MOS	72		11-Mar-20	11-Mar-26		40 d	11-Mar-2026
	HRS			7541.7				
	AFL	3750		4391	8141		3071	
Disposition: MANDATORY		REF: AD						
32-44-00-250-801-03		SPECIAL DETAILED INSPECTION OF THE WHEEL SUBASSEMBLIES - RH MLG INBOARD WHEEL (R535GC)						Service ATA:32
PN:C20180120-2	MOS			30-Sep-21				17-Mar-2026
SN:F1106	HRS			8000.1				
	AFL	400 (+3%)		4685	5085	5097	15 (+12)	
		REF: AMM 32-44-00-250-801						
32-44-00-250-801-04		SPECIAL DETAILED INSPECTION OF THE WHEEL SUBASSEMBLIES - RH MLG OUTBOARD WHEEL (R540GC)						Service ATA:32
PN:C20180400	MOS			30-Sep-21				17-Mar-2026
SN:02606	HRS			8000.1				
	AFL	400 (+3%)		4685	5085	5097	15 (+12)	
		REF: AMM 32-44-00-250-801						
760130		NO. 1 ENGINE - DOWNLOAD ECTM						Service ATA:76
	MOS			03-Jul-25				21-Apr-2026(2)
	HRS			8266.2				
	ENC	50		4926	(4976)5115		45	
		REF: LMM 76-10-03, MSC CAMP EHM ADENDUM						
760130		NO. 2 ENGINE - DOWNLOAD ECTM						Service ATA:76
	MOS			03-Jul-25				21-Apr-2026(2)
	HRS			8432				
	ENC	50		5017	(5067)5115		45	
		REF: LMM 76-10-03, MSC CAMP EHM ADENDUM						



Due List Report

Model: FALCON 900 Serial: 157 RegNo: N328JL HRS: 8561.3 AFL: 5070 As Of: 19-Jan-2026 Operator: LAMON AVIATION, LLC

Report Date: 30-Jan-2026

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est. Due
760130		NO. 3 ENGINE - DOWNLOAD ECTM						Service ATA:76
	MOS			03-Jul-25				21-Apr-2026(2)
	HRS			8359.2				
	ENC	50		4883	(4933)5115		45	
REF: LMM 76-10-03, MSC CAMP EHM ADENDUM								
32-44-00-250-801-05		SPECIAL DETAILED INSPECTION OF THE WHEEL SUBASSEMBLIES - LH NLG WHEEL (L565GC)						Service ATA:32
PN:C20182100	MOS			03-Aug-21				18-Jun-2026
SN:01018	HRS			7893.7				
	AFL	500 (+3%)		4615	5115	5130	45 (+15)	
REF: AMM 32-44-00-250-801								
32-44-00-250-801-06		SPECIAL DETAILED INSPECTION OF THE WHEEL SUBASSEMBLIES - RH NLG WHEEL (R565GC)						Service ATA:32
PN:C20182100	MOS			03-Aug-21				18-Jun-2026
SN:01179	HRS			7893.7				
	AFL	500 (+3%)		4615	5115	5130	45 (+15)	
REF: AMM 32-44-00-250-801								
057110		NO. 1 ENGINE - 150 TO 250 HOUR INSPECTION						Package ATA:05
	MOS			07-Oct-24				26-Jun-2026
	HRS	150 (+100)		8218.1	(8368.1)8657.6	8468.1	96.3 (+100)	
	ENC			4899				
REF: LMM 72-00-00								
057110		NO. 2 ENGINE - 150 TO 250 HOUR INSPECTION						Package ATA:05
	MOS			07-Oct-24				26-Jun-2026
	HRS	150 (+100)		8383.9	(8533.9)8657.6	8633.9	96.3 (+100)	
	ENC			4990				
REF: LMM 72-00-00								
057110		NO. 3 ENGINE - 150 TO 250 HOUR INSPECTION						Package ATA:05
	MOS			07-Oct-24				26-Jun-2026
	HRS	150 (+100)		8311.1	(8461.1)8657.6	8561.1	96.3 (+100)	
	ENC			4856				
REF: LMM 72-00-00								
24-31-17-220-803-01		CHECK OF THE ENGINE STARTER-GENERATOR BRUSHES - ENGINE 1 STARTER-GENERATOR (L1PA)						Service ATA:24
PN:8060-141-1	MOS			07-Oct-24				26-Jun-2026
SN:1148	HRS	150 (+3%)		8507.6	8657.6	8662.1	96.3 (+4.5)	
	AFL			5038				
REF: AMM 24-31-17-220-803								



Due List Report

Model: FALCON 900 Serial: 157 RegNo: N328JL HRS: 8561.3 AFL: 5070 As Of: 19-Jan-2026 Operator: LAMON AVIATION, LLC

Report Date: 30-Jan-2026

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est. Due	
24-31-17-220-803-02		CHECK OF THE ENGINE STARTER-GENERATOR BRUSHES - ENGINE 2 STARTER-GENERATOR (M1PA)							Service ATA:24
PN:8060-141-1	MOS			07-Oct-24				26-Jun-2026	
SN:1037	HRS	150 (+3%)		8507.6	8657.6	8662.1	96.3 (+4.5)		
	AFL			5038					
REF: AMM 24-31-17-220-803									
24-31-17-220-803-03		CHECK OF THE ENGINE STARTER-GENERATOR BRUSHES - ENGINE 3 STARTER-GENERATOR (R1PA)							Service ATA:24
PN:8060-141-1	MOS			07-Oct-24				26-Jun-2026	
SN:54	HRS	150 (+3%)		8507.6	8657.6	8662.1	96.3 (+4.5)		
	AFL			5038					
REF: AMM 24-31-17-220-803									
26-20-09-220-801-01		WEIGHING OF THE FIRE EXTINGUISHERS - APU, BAGGAGE COMPARTMENT FIRE EXTINGUISHER (22WB)							Service ATA:26
PN:861630	MOS	12 (+1m)		29-Jul-25	10-Jul-26	10-Aug-26	161 d (+31)	10-Jul-2026	
SN:57501	HRS			8559.4					
	AFL			5068					
REF: AMM 26-20-09-220-801									
26-20-09-220-801-02		WEIGHING OF THE FIRE EXTINGUISHERS - ENGINE 1 FIRST-SHOOT, ENGINE 2 SECOND-SHOOT FIRE EXTINGUISHER (3WB1)							Service ATA:26
PN:861630	MOS	12 (+1m)		29-Jul-25	10-Jul-26	10-Aug-26	161 d (+31)	10-Jul-2026	
SN:25795	HRS			8559.4					
	AFL			5068					
REF: AMM 26-20-09-220-801									
26-20-09-220-801-03		WEIGHING OF THE FIRE EXTINGUISHERS - ENGINE 2 FIRST-SHOOT, ENGINE 1 SECOND-SHOOT FIRE EXTINGUISHER (L3WB2)							Service ATA:26
PN:861630	MOS	12 (+1m)		29-Jul-25	10-Jul-26	10-Aug-26	161 d (+31)	10-Jul-2026	
SN:58513	HRS			8559.4					
	AFL			5068					
REF: AMM 26-20-09-220-801									
26-20-09-220-801-04		WEIGHING OF THE FIRE EXTINGUISHERS - ENGINE 3 FIRST-SHOOT, ENGINE 2 SECOND-SHOOT FIRE EXTINGUISHER (3WB3)							Service ATA:26
PN:861630	MOS	12 (+1m)		29-Jul-25	10-Jul-26	10-Aug-26	161 d (+31)	10-Jul-2026	
SN:56344	HRS			8559.4					
	AFL			5068					
REF: AMM 26-20-09-220-801									
26-20-09-220-801-05		WEIGHING OF THE FIRE EXTINGUISHERS - ENGINE 2 FIRST-SHOOT, ENGINE 3 SECOND-SHOOT FIRE EXTINGUISHER (R3WB2)							Service ATA:26
PN:861630	MOS	12 (+1m)		29-Jul-25	10-Jul-26	10-Aug-26	161 d (+31)	10-Jul-2026	
SN:25783	HRS			8559.4					
	AFL			5068					
REF: AMM 26-20-09-220-801									



Due List Report

Model: FALCON 900 Serial: 157 RegNo: N328JL HRS: 8561.3 AFL: 5070 As Of: 19-Jan-2026 Operator: LAMON AVIATION, LLC

Report Date: 30-Jan-2026

PN & SN	Unit	Interval	TSX/Adj.	C/W	Next Due (ENG/APU) A/C	Max. Limit	Remaining	Est. Due
53-10-39-220-802-01		DETAILED INSPECTION OF THE COCKPIT WINDSHIELD / WINDOW FRAMES						Service ATA:53
	MOS	144 (+2m)		14-Jul-14	14-Jul-26	14-Sep-26	165 d (+62)	14-Jul-2026
	HRS			5799.6				
	AFL	5030		3266	8296		3226	
		REF: AMM 53-10-39-220-802						
53-10-39-220-802-01C		DETAILED INSPECTION OF THE COCKPIT WINDSHIELD / WINDOW FRAMES (CPCP)						Service ATA:53
	MOS	144 (+2m)		14-Jul-14	14-Jul-26	14-Sep-26	165 d (+62)	14-Jul-2026
	HRS			5799.6				
	AFL			3266				
		REF: AMM 53-10-39-220-802						
55-10-00-220-801-01C		DETAILED INSPECTION OF THE HORIZONTAL STABILIZER INTERNAL BOX STRUCTURE - DETAILED INSPECTION OF THE HS INTERNAL BOX STRUCTURE (CPCP)						Service ATA:55
	MOS	144 (+2m)		14-Jul-14	14-Jul-26	14-Sep-26	165 d (+62)	14-Jul-2026
	HRS			5799.6				
	AFL			3266				
		REF: AMM 55-10-00-220-801						
24-32-01-350-801-01		RESTORATION OF A MAIN NICKEL-CADMIUM BATTERY (OVERHAUL) - BATTERY 1 (L1PE)						Service ATA:24
PN:4076-10	MOS	12 (+1m)		29-Jul-25	29-Jul-26	29-Aug-26	180 d (+31)	29-Jul-2026
SN:088398	HRS			8559.4				
	AFL			5068				
		REF: AMM 24-32-01-350-801						
24-32-01-350-801-02		RESTORATION OF A MAIN NICKEL-CADMIUM BATTERY (OVERHAUL) - BATTERY 2 (R1PE)						Service ATA:24
PN:4076-10	MOS	12 (+1m)		29-Jul-25	29-Jul-26	29-Aug-26	180 d (+31)	29-Jul-2026
SN:121547	HRS			8559.4				
	AFL			5068				
		REF: AMM 24-32-01-350-801						
24-32-09-610-801-01		SERVICING OF "SAFT" NICKEL-CADMIUM STAND-BY BATTERIES - STAND-BY HORIZON BATTERY (4FG)						Service ATA:24
PN:804747	MOS	12 (+3%)		29-Jul-25	29-Jul-26	09-Aug-26	180 d (+11)	29-Jul-2026
SN:3354	HRS			8559.4				
	AFL			5068				
		REF: AMM 24-32-09-610-801						
33-50-05-350-803-02		RESTORATION OF THE AIR LITE 2R LED RECHARGEABLE FLASHLIGHTS (OVERHAUL) - FLASH LIGHT (3LT)						Service ATA:33
PN:P2-07-0022-001	MOS	12 (+3%)		29-Jul-25	29-Jul-26	09-Aug-26	180 d (+11)	29-Jul-2026
SN:N/A	HRS			8559.4				
	AFL			5068				
		REF: AMM 33-50-05-350-803						