Hollard Insurance Partners Limited

Locked Bag 2010 St Leonards NSW Australia

1590

Phone 1300 765 253 ABN 96067524216



CLAIM DETAILS

** Claim 22201038896

Third Party Policy No. Cover Type Market **Assessment Category Assessment Type**

Division

Special Instructions for Repairer

* Excess NIL

Policy Inception Date

INSPECTION DETAILS

At the repairer Address 2 McDonald Street Phone No.(W)

03 9350 2331

Suburb / Town Coburg North Fax

Authority Issued

Office Litigation Team

** Assessment party

State/Territory VIC Mobile No.

Post Code 3058

VEHICLE DETAILS

	Authority issued					
del Series GER GX HYBRID AV				Compliance Month/Year July 2023		
Engine Size	Colour White		•	Paint Code 089		
Expiry Da	te	Rego :	State	*Vehicle Condition Fair		
				RIABLE		
r		Tyre S Yes	erviceable	Brakes Serviceable Pass		
		Axles	Count			
2(1L+1R)		L 5	R 5			
2(1L+1R)		L 5	R 5			
	ER GX HYBRID AI Engine Size 4 Expiry Da r	ER GX HYBRID AWD AXUH78 Engine Size Colour 4 White Expiry Date r 2(1L+1R)	Series Equip Level	del Series Equip Level EER GX HYBRID AWD AXUH78R Engine Size Colour White COB Expiry Date Rego State VIC Transmission CONTINUOUS VA Tyre Serviceable Yes Axles Count 2 2(1L+1R) L 5 R 5		

Vehicle ID 0CPB23

*VIN/Chassis Number

5TDLB3CH50S128001

DAMAGE LOCATION: Shade claim damage, circle and describe old damage. Also show direction of impact

Type of Loss: Collision Non-Repairable Damage: No

Vehicle moved: No

*Repair	
R & R Labour	\$3,304.00
Repair Labour	\$1,813.00
Paint Labour	\$3,647.00
Mech. Labour	\$0.00
Misc. Labour	\$1,025.00
TOTAL LABOUR	\$9,789.00
Estimated Parts	\$1,961.31
(including Markup)	
Sublet	\$0.00
Net Total	\$11,750.31
GST	\$1,175.03
Total	\$12,925.34
Less ITC	
Less Excess	NIL
Less Contribution	
Estimated Total	\$12,925.34
Estimated Repair Reserve	
10tai 2000	
Total Loss Date Sum Insured /	
Market Value	
Cover Type Market	
Market Value	\$51,881.00
*Book Values	
Trade Low	\$41,500.00
Trade	\$49,100.00
Retail	\$56,400.00
Other	ψου,+ου.υυ
Avg.	30000.00 km
*Total Settlement	
Settlement Amount	\$51,881.00
Salvage Value	\$13,055.00
TOTAL SETTLEMENT	\$51,881.00
Cash Settled	
Certificate of	
Compliance Required	
*Salvage Condition	

Assessor : AAMC


Assessor's Name: Dion Naude PO Box 5752 Brendale QLD 4500

0439 846 136

Date Owner Advised 17/02/2025 Inspection Date

Type of Loss : Collision Incident Type Code: Impact (I)

Type of Total Loss:



ASSESSOR COMMENT (NOT VISIBLE TO THE REPAIRER)

Australian Accident Management Commercial Pty Ltd Level 1, Building 4, 205-215 South Pine Rd Brendale Qld 4500.

This Report and acknowledgment are the expert witness report of Dion Naude.

I have read the Magistrates Court of Victoria Expert Witness Code of Conduct, which is attached, and I agree to be bound by it.

My qualifications and experience are attached to this acknowledgement.

I have been advised that motor vehicle registered number 5JAAT was damaged in a motor vehicle collision on or about 06/01/2025 and have been asked to prepare a desktop assessment report.

VEHICLE DESCRIPTION AND VALUE

The vehicle is a 2023 TOYOTA KLUGER GX HYBRID AWD AXUH78R 5D WAGON INLINE 4 2487 cc DIRFI CONTINUOUS VARIABLE. The Vehicle appears to be in Fair pre-accident condition.

I estimate the fair market value to be \$51,881.00.

Fair market value does not include stamp duty and transfer fees.

Estimate Salvage value at time of loss \$13,055.00.

DAMAGES SUSTAINED

Accident damages are to the rear body area.

REPAIR WORK COMPLETED

I have reviewed the Estimate Number 5885 that was submitted by Sheen Panel Service Coburg and note the following:

Damaged area appears to be consistent with the incident description. After reviewing the documentation and photographic evidence supplied some adjustments were required to the repair estimate, to reflect costs that are consistent with my recent industry experience for similar labour operations (See adjustments on attached repair estimate).

I believe a fair and reasonable amount for the cost of repairs is based on my desktop assessment of \$12,925.34 inclusive of GST. Adjustments have not been discussed with the repairer.

Adjustments have not been agreed with repairer.

REPAIR TIME REQUIRED

I estimate the repair time for this type of repair process would be 12 working days.

This is based on my recent industry experience and has not been discussed with the Repairer.

GENERAL COMMENTS

I note very little evidence were supplied to substantiate the extend of the damage that is claimed by the repairer, as such, a live inspection would be beneficial to determine the full extend of repairs that were required.

I reserve the right to request an inspection opportunity if additional documentation and photos become available after my initial report. I also reserve the right to amend my recommendations once additional information becomes available.

If you have any further queries, please do not hesitate to contact our office.

AUSTRALIAN ACCIDENT MANAGEMENT COMMERCIAL

REPAIRER DETAILS

Sheen Panel Service Coburg

ABN

79751245723 **Address**

2 McDonald Street 2 McDonald Street

Phone No. 03 9350 2331 E-mail

admin.coburg@sheengroup.com.au

ACN

Suburb / Town

Coburg North

Fax

License No.

State/Territory VIC

Mobile No.

Post Code 3058

ASSESSMENT DETAILS

Assessment Type Inspection Type Post Repair Inspection Date 17/02/2025

Assessor AAMC

ABN 51 101 934 801

Assessor Name Dion Naude

Address Suburb

State/Territory

Country AUSTRALIA

Post Code Mobile No.

Phone No.(H)

Phone No.(W) 0439 846 136

Email dion.naude@aamc.com.au

Fax 07 3889 7471

Assessed Date 20/02/2025 Estimate No. Assessed Yes Amount \$12925.34

Quote Date 20/02/2025 Authority Issued No Issued Date

Authorised Labour Amount

Assessment Type

Inspection Date 17/02/2025

Inspection Type Post Repair

In Date

Estimated days to repair

Non-Repairable Damage No

Salvage Reference

Type of Total Loss

Authority Comment

Total Loss No **Total Loss Date**

Type of Loss Collision Salvage Value \$13055.00

Out Date

Owner Contribution

Owner Advised

Assessor Reserve

Manufactures Data Ref. CURRENT INDUSTRY REPAIR

STANDARDS

Vehicle pick up Date/Time

WOVR

Sheen Panel Service Coburg

2 McDonald Street Coburg North VIC Australia 3058 Phone No.(w) 03 9350 2331 ABN 79751245723

Contact Nicole Goh

Contact No. admin.coburg@sheengroup.com.au

Remove & Replace								
Quoted Rate \$0.00	Assessed Rate \$0.00							
escription		Assessor Note		Est.	Hours 0.00	Ass. Hours 0.00	Est. \$ \$7847.00	Ass. \$ As \$3304.00
				Total	0.00	0.00	\$7847.00	\$3304.00
Repair								
Quoted Rate \$0.00	Assessed Rate \$0.00			Fat	Hauma	Ass Hauss	Fat ¢	A ¢ A-
Description		Assessor Note			Hours 0.00	Ass. Hours 0.00	Est. \$ \$7266.00	Ass. \$ As \$1813.00 ↓
				Total	0.00	0.00	\$7266.00	\$1813.00
Paint								
Quoted Rate \$0.00	Assessed Rate \$0.00	ОК						
escription		Assessor Note		Est.	Hours 0.00	Ass. Hours 0.00	Est. \$ \$8617.00	Ass. \$ A \$3647.00
				Total	0.00	0.00	\$8617.00	\$3647.00 \$3647.00
/lechanical								
Quoted Rate \$0.00	Assessed Rate \$0.00	ОК						
escription		Assessor Note		Est.	Hours 0.00	Ass. Hours 0.00	Est. \$ \$0.00	Ass. \$ A \$0.00 C
				Total	0.00	0.00	\$0.00	\$0.00
Miscellaneous	A	014						
Quoted Rate \$0.00	Assessed Rate \$0.00	OK Assessor Note		Est.	Hours	Ass. Hours	Est. \$	Ass. \$ A
				Total	0.00	0.00 0.00	\$1928.00 \$1928.00	\$1025.00 \$1025.00
				Total Labour	0.00	0.00	\$25658.00	\$9789.00
Danta.								
Parts		A N - 1 -						
escription		Assessor Note	Part No	Src Qty	У	Est. \$ MUE	Ass. \$	MUA A
Description		Assessor Note	Part No ✓	1	\$24	149.77 %0.00	\$1961.31	
escription		Assessor Note			\$24 \$2 4		\$1961.31	\$0.00
		Assessor Note		1 Total	\$24 \$2 4	149.77 %0.00 1 49.77 \$0.00	\$1961.31 \$1961.31	\$0.00
Sublet				1 Total	\$24 \$2 4	149.77 %0.00 1 49.77 \$0.00	\$1961.31 \$1961.31 \$1961.31	\$0.00
Sublet		Assessor Note		1 Total	\$24 \$2 4	149.77 %0.00 149.77 \$0.00 149.77	\$1961.31 \$1961.31 \$1961.31 Est. \$	\$0.00 Ass. \$A
Sublet				1 Total	\$24 \$2 4	149.77 %0.00 1 49.77 \$0.00	\$1961.31 \$1961.31 \$1961.31	\$0.00 Ass. \$A
Sublet				1 Total	\$24 \$2 4	149.77 %0.00 149.77 \$0.00 149.77 Total	\$1961.31 \$1961.31 \$1961.31 Est. \$	\$0.00 Ass. \$A 0.00 (\$0.00
Sublet			,	1 Total	\$24 \$2 4	149.77 %0.00 149.77 \$0.00 149.77 Total	\$1961.31 \$1961.31 \$1961.31 \$1960.31	\$0.00 Ass. \$A 0.00 C \$0.00
Sublet				1 Total	\$24 \$24 \$2 4	149.77 %0.00 149.77 \$0.00 149.77 Total	\$1961.31 \$1961.31 \$1961.31 Est. \$ 0.00 \$0.00	\$0.00 Ass. \$A 0.00 C \$0.00 \$11750.31
Sublet			,	Total Total (with Markup)	\$24 \$24 \$24	149.77 %0.00 149.77 \$0.00 149.77 Total	\$1961.31 \$1961.31 \$1961.31 Est. \$ 0.00 \$0.00	\$0.00 Ass. \$A 0.00 (\$0.00 \$111750.31
Sublet			Original R & R Repair	Total Total (with Markup) Quoted \$7847.00 \$7266.00	\$24 \$24 \$24	149.77 %0.00 149.77 \$0.00 149.77 Total Net Total As: \$3304.00 \$1813.00	\$1961.31 \$1961.31 \$1961.31 \$1961.31 Est. \$ 0.00 \$0.00 \$28107.77	\$0.00 Ass. \$A 0.00 (\$0.00 \$11750.31 A(\$4543.0 \$5453.0
Sublet			Original R & R Repair Paint	Quoted \$7847.00 \$8617.00	\$24 \$24 \$24	149.77 %0.00 149.77 \$0.00 149.77 Total Net Total As: \$3304.00 \$1813.00 \$3647.00	\$1961.31 \$1961.31 \$1961.31 \$1961.31 Est. \$ 0.00 \$0.00 \$28107.77	\$0.00 Ass. \$A 0.00 C \$0.00 \$11750.31 Ac \$4543.0 \$5453.0 \$4970.0
Sublet			Original R & R Repair Paint Mech.	Quoted \$7847.00 \$7266.00 \$8617.00	\$24 \$24 \$24	149.77 %0.00 149.77 \$0.00 149.77 Total Net Total As: \$3304.00 \$1813.00 \$3647.00	\$1961.31 \$1961.31 \$1961.31 \$1961.31 Est. \$ 0.00 \$0.00 \$28107.77	\$0.00 Ass. \$A 0.00 C \$0.00 \$11750.31 Ac \$4543.0 \$5453.0 \$4970.0 \$0.0
Sublet			Original R & R Repair Paint Mech. Mis.	Quoted \$7847.00 \$7266.00 \$8617.00 \$1928.00	\$24 \$24 \$24	Total Net Total As: \$3304.00 \$1813.00 \$1025.00	\$1961.31 \$1961.31 \$1961.31 \$1961.31 Est. \$ 0.00 \$0.00 \$28107.77	\$0.00 Ass. \$A 0.00 C \$0.00 \$11750.31 Ac \$4543.0 \$5453.0 \$4970.0 \$0.0 \$903.0
Sublet			Original R & R Repair Paint Mech. Mis. Total Labour	Quoted \$7847.00 \$7266.00 \$8617.00 \$1928.00	\$24 \$24 \$24 \$20 \$24	Total Net Total As: \$3304.0(\$1813.0(\$0.00) \$1025.0(\$9789.00)	\$1961.31 \$1961.31 \$1961.31 \$1961.31 Est. \$ 0.00 \$0.00 \$28107.77	\$0.00 \$0.00 \$0.00 \$11750.31 Ac \$4543.0 \$5453.0 \$4970.0 \$0.0 \$15869.0
Sublet			R & R Repair Paint Mech. Mis. Total Labour Parts	Quoted \$7847.00 \$7266.00 \$8617.00 \$1928.00 \$25658.00 \$2449.77	\$24 \$24 \$24 \$20 \$24	As: \$3304.0(\$1025.0(\$9789.0) \$9789.0(\$1961.3)	\$1961.31 \$1961.31 \$1961.31 \$1961.31 Est. \$ 0.00 \$0.00 \$28107.77	\$0.00 Ass. \$A: 0.00 C \$0.00 \$11750.31 Ac \$4543.0 \$5453.0 \$4970.0 \$0.0 \$15869.0 \$488.4
Sublet			Original R & R Repair Paint Mech. Mis. Total Labour	Quoted \$7847.00 \$7266.00 \$8617.00 \$1928.00	\$24 \$24 \$24 \$26 \$26 \$27 \$27 \$27 \$27 \$27 \$27 \$27 \$27 \$27 \$27	Total Net Total As: \$3304.0(\$1813.0(\$0.00) \$1025.0(\$9789.00)	\$1961.31 \$1961.31 \$1961.31 \$1961.31 Est. \$ 0.00 \$0.00 \$28107.77	\$0.00 \$0.00 \$11750.31 \$4543.0 \$5453.0 \$4970.0 \$903.0 \$15869.0 \$488.4 \$0.0
Sublet			Original R & R Repair Paint Mech. Mis. Total Labour Parts M/U Sublet	Quoted \$7847.00 \$7266.00 \$8617.00 \$1928.00 \$25658.00 \$2449.77 \$0.00 \$0.00	\$24 \$24 \$24 \$26 \$26 \$26 \$26 \$26 \$26 \$26 \$26 \$26 \$26	As: \$3304.00 \$1813.00 \$1025.00 \$1961.3 \$0.00	\$1961.31 \$1961.31 \$1961.31 \$1961.31 Est. \$ 0.00 \$0.00 \$28107.77	\$0.00 Ass. \$A. 0.00 C \$0.00 \$11750.31 Ac \$4543.0 \$5453.0 \$4970.0 \$0.0 \$15869.0 \$488.4 \$0.0 \$0.0
Sublet Description			Original R & R Repair Paint Mech. Mis. Total Labour Parts M/U	Quoted \$7847.00 \$7266.00 \$8617.00 \$1928.00 \$25658.00 \$2449.77	\$24 \$24 \$24 \$26 \$27 \$29 \$29 \$29 \$29 \$29 \$29 \$29 \$29 \$29 \$29	Total Net Total As: \$3304.00 \$1813.00 \$1025.00 \$9789.00 \$1961.3	\$1961.31 \$1961.31 \$1961.31 \$1961.31 Est. \$ 0.00 \$0.00 \$28107.77	Ass. \$ As 0.00 C \$0.00

Total				
		Quoted	Ass.	Adj
Total Labour		\$25,658.00	\$9,789.00	\$15,869.00
Total Parts		\$2,449.77	\$1,961.31	\$488.46
Net Total		\$28,107.77	\$11,750.31	\$16,357.46
GST		\$2,810.78	\$1,175.03	\$1,635.75
	Total	\$30,918.55	\$12,925.34	\$17,993.21

Repairer

SHEEN PANEL SERVICE (COBURG) -

Phone , Fax , Email admin.coburg@sheengroup.com.au

ESTIMATE ASSESSED - BEN COOPER

VIKAS MANDHAN C/- AANDI LAWYERS

Owner

Vehicle 07/2023-Toyota Kluger

 Reg No
 5JAAT

 Claim #
 39455

 Our Ref
 3065983

 Quote No
 5885

Quote No Assessor	5885 BEN COOPER					
RR: (\$140)				Hrs		Adj
1. DE-CONTAN	MINATE VEHICLE FROM WAX	XES & SILICONES		1.00 .5		
2. WORK BAY	SET UP			1.00		
3. DISCONNEC	T & RE-CONNECT 12V BATT	ERY		0,50 .15	•	0.30
4. JACK & SUP	PORT VEHICLE - MULTIPLE	ΓIMES		1,00	•	0.50
5. L/H/R ROAD	WHEEL & RE-TORQUE			0.25		
6. L/H/R MUD I				0.20		
	L ARCH FLARE & REPLACE	CLIPS		0.45		
	D LINER & REPLACE CLIPS			0.30		
	WHEEL & RE-TORQUE			0.25		
10. R/H/R MUD				0.20		
11. R/H/R WHE	EL ARCH FLARE & REPLACE	CLIPS		0.45		
12. R/H/R GUA	RD LINER & REPLACE CLIPS			0.30		
13. REAR UND	ERSIDE SPLASH TRAYS			0.25		
14. BOOT MAT	T & BOARD & NEC COMPAR	TMENTS		0.50		
15. SPARE WH	EEL, TOOL KIT & JACK			0,40		
16. INNER BEA	VER TRIM			0.20		
17. L/H/R SEAT	BELT & ANCHOR			0,43 · 3		
18. L/H/R UPPE	R & LOWER QUARTER TRIM	S (RELEASE)		1.00		
19. L/H QUART	ER GLASS & RE-SEAL			1.20		
20. R/H/R SEAT	BELT & ANCHOR			0.45 - 3		
21. R/H/R UPPE	ER & LOWER QUARTER TRIM	S (RELEASE)		1.00		
22. R/H QUART	TER GLASS & RE-SEAL			1.20 /		
23. L/H TAILLA	AMP & CHECK OPERATION			0.30		
24. R/H TAILLA	AMP & CHECK OPERATION			0.30		
25. REAR BAR	& RE-BUILD TO NEW			3.00	•	2.00
26. REAR B/BA	R SENSORS, LOOMS, TIE BA	CK & RE-TRACE		0.50		
27. L/H & R/H B	BAR IRONS & REO - TO NEW			0.50		
28. TAILGATE	OPENING SEAL/PIPING			0.20		
29. BEAVER PA	ANEL H/WARE		7 No	0.45		
30. NEC BOOT	FLOOR H/WARE & MATTING	& TEMPLATE	7 SUPPORTING	0.50		
31. RELEASE H	IOOD LINING & SUPPORT - T S D&A & LIFT OFF (3 PERSON '	O ALLOW ACCESS		2.00		
32. FASTENER	S			\$0.00		
33. TAILGATE	D&A & LIFT OFF (3 PERSON '	FASK) No SciPPORT	INC FLINENSE	400 2.5		
34. TAILGATE	HINGES & RE-SEAL TO NEW	,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,		1.00		
	BADGES & CLEAN RESIDUE			0.50		
	OPENING H/WARE			0,45		
	AMP PANEL H/WARE			0.25		
38. L/H/R BAR				0.20		
	PANEL VENTS & GROMETS			0.25		
	& MOUNTING H/WARE			0.45		
41. FUEL LID	& MOONTHING II/ WARL	\		0.30		
	KET & TIE BACK NECK	>		0.30		
72. FULL BUCK	ALT & THE DACK NECK	(UEJU		

42 I /II TUDDET DAIL & MOULD	0.50 · 3
43. L/H TURRET RAIL & MOULD	
44. L/H/R DOOR - D&A & LIFT OFF	4.00 2.5
45. L/H/R DOOR LOWER MOULD & REPLACE CLIPS	0.45
46. L/H/R DOOR HANDLE, CAP & GASKETS	0,30
47. L/H/R DOOR SCUFF PLATE	0.15
48. L/H/R DOOR APERTURE SEAL & RE-SEAL 7 No SUPPORTING	0.20
49. L/H/R DOOR OPENING H/WARE	0.45
50. L/H CENTRE PILLAR SEAT BELT & ANCHOR	0.45
51. L/H CENTRE PILLAR UPPER & LOWER TRIMS	1,00
52. L/H/F DOOR - D&A, LIFT OFF & SAFE STORE	3.00
53. L/H/F DOOR KICK PANEL & SCUFF PLATE	0.20
54. L/H/F DOOR APERTURE SEAL & RE-SEAL	0/20
55. L/H/F DOOR OPENING H/WARE	0.45
56. L/H/F ROAD WHEEL & RE-TORQUE	0.25
57. L/H/F MUD FLAP	0/20
58. L/H/F WHEEL ARCH FLARE & REPLACE CLIPS	0.45
59. L/H/F GUARD LINER & REPLACE CLIPS	9.50
60. L/H/F GUARD DUST COVER	0.20
61. L/H WINDSCREEN PILLAR BLACK OUT TAPE & CLEAN	0.40
RESIDUE	0.40 7
62. R/H TURRET RAIL & MOULD	0.50
63. R/H TAIL LAMP PANEL H/WARE	925
	0.20
64. R/H/R BAR GUIDE	. L
65. R/H DROP PANEL VENTS & GROMETS 66. R/H BSM MONITOR & MOUNTING H/WARE 66. R/H BSM MONITOR & MOUNTING H/WARE	0.45
•	
67. R/H/R DOOR - D&A & LIFT OFF	4.00 Z.5
68. R/H/R DOOR LOWER MOULD & REPLACE CLIPS	9.45
69. R/H/R DOOR HANDLE, CAP & GASKETS	930
70. R/H/R DOOR APERTURE SCUFF PLATE	0,15
71. R/H/R DOOR SEAL & RE-SEAL TWO SUPPORTING EUIDENCE	0.20
7/00 301 311114 2 010000	
72. R/H/R DOOR OPENING H/WARE	0.45
72. R/H/R DOOR OPENING H/WARE 73. R/H CENTRE PILLAR SEAT BELT & ANCHOR	0.45
72. R/H/R DOOR OPENING H/WARE	0.45 1.00
72. R/H/R DOOR OPENING H/WARE 73. R/H CENTRE PILLAR SEAT BELT & ANCHOR	0.45 1.00 3.00
72. R/H/R DOOR OPENING H/WARE73. R/H CENTRE PILLAR SEAT BELT & ANCHOR74. R/H CENTRE PILLAR UPPER & LOWER TRIMS	0.45 1.00
72. R/H/R DOOR OPENING H/WARE 73. R/H CENTRE PILLAR SEAT BELT & ANCHOR 74. R/H CENTRE PILLAR UPPER & LOWER TRIMS 75. R/H/F DOOR D&A, LIFT OFF & SAFE STORE	0.45 1.00 3.00
72. R/H/R DOOR OPENING H/WARE 73. R/H CENTRE PILLAR SEAT BELT & ANCHOR 74. R/H CENTRE PILLAR UPPER & LOWER TRIMS 75. R/H/F DOOR D&A, LIFT OFF & SAFE STORE 76. R/H/F DOOR KICK PANEL & SCUFF PLATE	0.45 1.00 3.00 0.20
72. R/H/R DOOR OPENING H/WARE 73. R/H CENTRE PILLAR SEAT BELT & ANCHOR 74. R/H CENTRE PILLAR UPPER & LOWER TRIMS 75. R/H/F DOOR D&A, LIFT OFF & SAFE STORE 76. R/H/F DOOR KICK PANEL & SCUFF PLATE 77. R/H/F DOOR APERTURE SEAL & RE-SEAL	0.45 1.00 3.00 0.20 0.20
72. R/H/R DOOR OPENING H/WARE 73. R/H CENTRE PILLAR SEAT BELT & ANCHOR 74. R/H CENTRE PILLAR UPPER & LOWER TRIMS 75. R/H/F DOOR D&A, LIFT OFF & SAFE STORE 76. R/H/F DOOR KICK PANEL & SCUFF PLATE 77. R/H/F DOOR APERTURE SEAL & RE-SEAL 78. R/H/F DOOR OPENING H/WARE	0.45 1.00 3.00 0.20 0.20 0.45
72. R/H/R DOOR OPENING H/WARE 73. R/H CENTRE PILLAR SEAT BELT & ANCHOR 74. R/H CENTRE PILLAR UPPER & LOWER TRIMS 75. R/H/F DOOR D&A, LIFT OFF & SAFE STORE 76. R/H/F DOOR KICK PANEL & SCUFF PLATE 77. R/H/F DOOR APERTURE SEAL & RE-SEAL 78. R/H/F DOOR OPENING H/WARE 79. R/H/F ROAD WHEEL & RE-TORQUE	0.45 1.00 3.00 0.20 0.20 0.45 0.25
72. R/H/R DOOR OPENING H/WARE 73. R/H CENTRE PILLAR SEAT BELT & ANCHOR 74. R/H CENTRE PILLAR UPPER & LOWER TRIMS 75. R/H/F DOOR D&A, LIFT OFF & SAFE STORE 76. R/H/F DOOR KICK PANEL & SCUFF PLATE 77. R/H/F DOOR APERTURE SEAL & RE-SEAL 78. R/H/F DOOR OPENING H/WARE 79. R/H/F ROAD WHEEL & RE-TORQUE 80. R/H/F MUD FLAP 81. R/H/F WHEEL ARCH FLARE & REPLACE CLIPS	0.45 1.00 3.00 0.20 0.20 0.45 0.25 0.20 0.45
72. R/H/R DOOR OPENING H/WARE 73. R/H CENTRE PILLAR SEAT BELT & ANCHOR 74. R/H CENTRE PILLAR UPPER & LOWER TRIMS 75. R/H/F DOOR D&A, LIFT OFF & SAFE STORE 76. R/H/F DOOR KICK PANEL & SCUFF PLATE 77. R/H/F DOOR APERTURE SEAL & RE-SEAL 78. R/H/F DOOR OPENING H/WARE 79. R/H/F ROAD WHEEL & RE-TORQUE 80. R/H/F MUD FLAP 81. R/H/F WHEEL ARCH FLARE & REPLACE CLIPS 82. R/H/F GUARD LINER & REPLACE CLIPS	0.45 1.00 3.00 0.20 0.20 0.45 0.25 0.20 0.45 0.30
72. R/H/R DOOR OPENING H/WARE 73. R/H CENTRE PILLAR SEAT BELT & ANCHOR 74. R/H CENTRE PILLAR UPPER & LOWER TRIMS 75. R/H/F DOOR D&A, LIFT OFF & SAFE STORE 76. R/H/F DOOR KICK PANEL & SCUFF PLATE 77. R/H/F DOOR APERTURE SEAL & RE-SEAL 78. R/H/F DOOR OPENING H/WARE 79. R/H/F ROAD WHEEL & RE-TORQUE 80. R/H/F MUD FLAP 81. R/H/F WHEEL ARCH FLARE & REPLACE CLIPS 82. R/H/F GUARD LINER & REPLACE CLIPS 83. R/H/F GUARD DUST COVER	0.45 1.00 3.00 0.20 0.20 0.45 0.25 0.20 0.45 0.30 0.20
72. R/H/R DOOR OPENING H/WARE 73. R/H CENTRE PILLAR SEAT BELT & ANCHOR 74. R/H CENTRE PILLAR UPPER & LOWER TRIMS 75. R/H/F DOOR D&A, LIFT OFF & SAFE STORE 76. R/H/F DOOR KICK PANEL & SCUFF PLATE 77. R/H/F DOOR APERTURE SEAL & RE-SEAL 78. R/H/F DOOR OPENING H/WARE 79. R/H/F ROAD WHEEL & RE-TORQUE 80. R/H/F MUD FLAP 81. R/H/F WHEEL ARCH FLARE & REPLACE CLIPS 82. R/H/F GUARD LINER & REPLACE CLIPS 83. R/H/F GUARD DUST COVER 84. R/H WINDSCREEN PILLAR BLACK OUT TAPE & CLEAN	0.45 1.00 3.00 0.20 0.20 0.45 0.25 0.20 0.45 0.30
72. R/H/R DOOR OPENING H/WARE 73. R/H CENTRE PILLAR SEAT BELT & ANCHOR 74. R/H CENTRE PILLAR UPPER & LOWER TRIMS 75. R/H/F DOOR D&A, LIFT OFF & SAFE STORE 76. R/H/F DOOR KICK PANEL & SCUFF PLATE 77. R/H/F DOOR APERTURE SEAL & RE-SEAL 78. R/H/F DOOR OPENING H/WARE 79. R/H/F ROAD WHEEL & RE-TORQUE 80. R/H/F MUD FLAP 81. R/H/F WHEEL ARCH FLARE & REPLACE CLIPS 82. R/H/F GUARD LINER & REPLACE CLIPS 83. R/H/F GUARD DUST COVER 84. R/H WINDSCREEN PILLAR BLACK OUT TAPE & CLEAN RESIDUE	0.45 1.00 3.00 0.20 0.20 0.45 0.25 0.20 0.45 0.30 0.20 0.40
72. R/H/R DOOR OPENING H/WARE 73. R/H CENTRE PILLAR SEAT BELT & ANCHOR 74. R/H CENTRE PILLAR UPPER & LOWER TRIMS 75. R/H/F DOOR D&A, LIFT OFF & SAFE STORE 76. R/H/F DOOR KICK PANEL & SCUFF PLATE 77. R/H/F DOOR APERTURE SEAL & RE-SEAL 78. R/H/F DOOR OPENING H/WARE 79. R/H/F ROAD WHEEL & RE-TORQUE 80. R/H/F MUD FLAP 81. R/H/F WHEEL ARCH FLARE & REPLACE CLIPS 82. R/H/F GUARD LINER & REPLACE CLIPS 83. R/H/F GUARD DUST COVER 84. R/H WINDSCREEN PILLAR BLACK OUT TAPE & CLEAN RESIDUE 85. WIPERS + RE-SET SWEEP	0.45 1.00 3.00 0.20 0.20 0.45 0.25 0.25 0.30 0.20 0.40
72. R/H/R DOOR OPENING H/WARE 73. R/H CENTRE PILLAR SEAT BELT & ANCHOR 74. R/H CENTRE PILLAR UPPER & LOWER TRIMS 75. R/H/F DOOR D&A, LIFT OFF & SAFE STORE 76. R/H/F DOOR KICK PANEL & SCUFF PLATE 77. R/H/F DOOR APERTURE SEAL & RE-SEAL 78. R/H/F DOOR OPENING H/WARE 79. R/H/F ROAD WHEEL & RE-TORQUE 80. R/H/F MUD FLAP 81. R/H/F WHEEL ARCH FLARE & REPLACE CLIPS 82. R/H/F GUARD LINER & REPLACE CLIPS 83. R/H/F GUARD DUST COVER 84. R/H WINDSCREEN PILLAR BLACK OUT TAPE & CLEAN RESIDUE 85. WIPERS + RE-SET SWEEP 86. SCUTTLE TRAY AND NEC CLIPS AND SEALS	0.45 1.00 3.00 0.20 0.20 0.45 0.25 0.20 0.45 0.30 0.20 0.40
72. R/H/R DOOR OPENING H/WARE 73. R/H CENTRE PILLAR SEAT BELT & ANCHOR 74. R/H CENTRE PILLAR UPPER & LOWER TRIMS 75. R/H/F DOOR D&A, LIFT OFF & SAFE STORE 76. R/H/F DOOR KICK PANEL & SCUFF PLATE 77. R/H/F DOOR APERTURE SEAL & RE-SEAL 78. R/H/F DOOR OPENING H/WARE 79. R/H/F ROAD WHEEL & RE-TORQUE 80. R/H/F MUD FLAP 81. R/H/F WHEEL ARCH FLARE & REPLACE CLIPS 82. R/H/F GUARD LINER & REPLACE CLIPS 83. R/H/F GUARD DUST COVER 84. R/H WINDSCREEN PILLAR BLACK OUT TAPE & CLEAN RESIDUE 85. WIPERS + RE-SET SWEEP 86. SCUTTLE TRAY AND NEC CLIPS AND SEALS 87. COVER MASK & PROTECT EXPOSED CABIN	0.45 1.00 3.00 0.20 0.20 0.45 0.25 0.25 0.20 0.45 0.30 0.20 0.40
72. R/H/R DOOR OPENING H/WARE 73. R/H CENTRE PILLAR SEAT BELT & ANCHOR 74. R/H CENTRE PILLAR UPPER & LOWER TRIMS 75. R/H/F DOOR D&A, LIFT OFF & SAFE STORE 76. R/H/F DOOR KICK PANEL & SCUFF PLATE 77. R/H/F DOOR APERTURE SEAL & RE-SEAL 78. R/H/F DOOR OPENING H/WARE 79. R/H/F ROAD WHEEL & RE-TORQUE 80. R/H/F MUD FLAP 81. R/H/F WHEEL ARCH FLARE & REPLACE CLIPS 82. R/H/F GUARD LINER & REPLACE CLIPS 83. R/H/F GUARD DUST COVER 84. R/H WINDSCREEN PILLAR BLACK OUT TAPE & CLEAN RESIDUE 85. WIPERS + RE-SET SWEEP 86. SCUTTLE TRAY AND NEC CLIPS AND SEALS	0.45 1.00 3.00 0.20 0.20 0.45 0.25 0.20 0.45 0.30 0.20 0.40
72. R/H/R DOOR OPENING H/WARE 73. R/H CENTRE PILLAR SEAT BELT & ANCHOR 74. R/H CENTRE PILLAR UPPER & LOWER TRIMS 75. R/H/F DOOR D&A, LIFT OFF & SAFE STORE 76. R/H/F DOOR KICK PANEL & SCUFF PLATE 77. R/H/F DOOR APERTURE SEAL & RE-SEAL 78. R/H/F DOOR OPENING H/WARE 79. R/H/F ROAD WHEEL & RE-TORQUE 80. R/H/F MUD FLAP 81. R/H/F WHEEL ARCH FLARE & REPLACE CLIPS 82. R/H/F GUARD LINER & REPLACE CLIPS 83. R/H/F GUARD DUST COVER 84. R/H WINDSCREEN PILLAR BLACK OUT TAPE & CLEAN RESIDUE 85. WIPERS + RE-SET SWEEP 86. SCUTTLE TRAY AND NEC CLIPS AND SEALS 87. COVER MASK & PROTECT EXPOSED CABIN 88. SET UP ANTI-SPARK BLANKET & SECURE TO VEHICLE	0.45 1.00 3.00 0.20 0.20 0.45 0.25 0.20 0.45 0.30 0.20 0.40 0.20 0.40
72. R/H/R DOOR OPENING H/WARE 73. R/H CENTRE PILLAR SEAT BELT & ANCHOR 74. R/H CENTRE PILLAR UPPER & LOWER TRIMS 75. R/H/F DOOR D&A, LIFT OFF & SAFE STORE 76. R/H/F DOOR KICK PANEL & SCUFF PLATE 77. R/H/F DOOR APERTURE SEAL & RE-SEAL 78. R/H/F DOOR OPENING H/WARE 79. R/H/F ROAD WHEEL & RE-TORQUE 80. R/H/F MUD FLAP 81. R/H/F WHEEL ARCH FLARE & REPLACE CLIPS 82. R/H/F GUARD LINER & REPLACE CLIPS 83. R/H/F GUARD DUST COVER 84. R/H WINDSCREEN PILLAR BLACK OUT TAPE & CLEAN RESIDUE 85. WIPERS + RE-SET SWEEP 86. SCUTTLE TRAY AND NEC CLIPS AND SEALS 87. COVER MASK & PROTECT EXPOSED CABIN 88. SET UP ANTI-SPARK BLANKET & SECURE TO VEHICLE	0.45 1.00 3.00 0.20 0.20 0.45 0.25 0.25 0.20 0.45 0.30 0.20 0.40
72. R/H/R DOOR OPENING H/WARE 73. R/H CENTRE PILLAR SEAT BELT & ANCHOR 74. R/H CENTRE PILLAR UPPER & LOWER TRIMS 75. R/H/F DOOR D&A, LIFT OFF & SAFE STORE 76. R/H/F DOOR KICK PANEL & SCUFF PLATE 77. R/H/F DOOR APERTURE SEAL & RE-SEAL 78. R/H/F DOOR OPENING H/WARE 79. R/H/F ROAD WHEEL & RE-TORQUE 80. R/H/F MUD FLAP 81. R/H/F WHEEL ARCH FLARE & REPLACE CLIPS 82. R/H/F GUARD LINER & REPLACE CLIPS 83. R/H/F GUARD DUST COVER 84. R/H WINDSCREEN PILLAR BLACK OUT TAPE & CLEAN RESIDUE 85. WIPERS + RE-SET SWEEP 86. SCUTTLE TRAY AND NEC CLIPS AND SEALS 87. COVER MASK & PROTECT EXPOSED CABIN 88. SET UP ANTI-SPARK BLANKET & SECURE TO VEHICLE	0.45 1.00 3.00 0.20 0.20 0.45 0.25 0.20 0.45 0.30 0.20 0.40 0.20 0.40
72. R/H/R DOOR OPENING H/WARE 73. R/H CENTRE PILLAR SEAT BELT & ANCHOR 74. R/H CENTRE PILLAR UPPER & LOWER TRIMS 75. R/H/F DOOR D&A, LIFT OFF & SAFE STORE 76. R/H/F DOOR KICK PANEL & SCUFF PLATE 77. R/H/F DOOR APERTURE SEAL & RE-SEAL 78. R/H/F DOOR OPENING H/WARE 79. R/H/F ROAD WHEEL & RE-TORQUE 80. R/H/F MUD FLAP 81. R/H/F WHEEL ARCH FLARE & REPLACE CLIPS 82. R/H/F GUARD LINER & REPLACE CLIPS 83. R/H/F GUARD DUST COVER 84. R/H WINDSCREEN PILLAR BLACK OUT TAPE & CLEAN RESIDUE 85. WIPERS + RE-SET SWEEP 86. SCUTTLE TRAY AND NEC CLIPS AND SEALS 87. COVER MASK & PROTECT EXPOSED CABIN 88. SET UP ANTI-SPARK BLANKET & SECURE TO VEHICLE SubTotal Hrs SubTotal \$	0.45 1.00 3.00 0.20 0.20 0.45 0.25 0.20 0.45 0.30 0.20 0.40 0.40 1.00 0.50 57.90 56.05 \$7,847.00
72. R/H/R DOOR OPENING H/WARE 73. R/H CENTRE PILLAR SEAT BELT & ANCHOR 74. R/H CENTRE PILLAR UPPER & LOWER TRIMS 75. R/H/F DOOR D&A, LIFT OFF & SAFE STORE 76. R/H/F DOOR KICK PANEL & SCUFF PLATE 77. R/H/F DOOR APERTURE SEAL & RE-SEAL 78. R/H/F DOOR OPENING H/WARE 79. R/H/F ROAD WHEEL & RE-TORQUE 80. R/H/F MUD FLAP 81. R/H/F WHEEL ARCH FLARE & REPLACE CLIPS 82. R/H/F GUARD LINER & REPLACE CLIPS 83. R/H/F GUARD DUST COVER 84. R/H WINDSCREEN PILLAR BLACK OUT TAPE & CLEAN RESIDUE 85. WIPERS + RE-SET SWEEP 86. SCUTTLE TRAY AND NEC CLIPS AND SEALS 87. COVER MASK & PROTECT EXPOSED CABIN 88. SET UP ANTI-SPARK BLANKET & SECURE TO VEHICLE SubTotal Hrs SubTotal \$\$2,1	0.45 1.00 3.00 0.20 0.20 0.45 0.25 0.20 0.45 0.30 0.20 0.40 0.40 1.00 0.50 57.90 Hrs Adj
72. R/H/R DOOR OPENING H/WARE 73. R/H CENTRE PILLAR SEAT BELT & ANCHOR 74. R/H CENTRE PILLAR UPPER & LOWER TRIMS 75. R/H/F DOOR D&A, LIFT OFF & SAFE STORE 76. R/H/F DOOR KICK PANEL & SCUFF PLATE 77. R/H/F DOOR APERTURE SEAL & RE-SEAL 78. R/H/F DOOR OPENING H/WARE 79. R/H/F ROAD WHEEL & RE-TORQUE 80. R/H/F MUD FLAP 81. R/H/F WHEEL ARCH FLARE & REPLACE CLIPS 82. R/H/F GUARD LINER & REPLACE CLIPS 83. R/H/F GUARD DUST COVER 84. R/H WINDSCREEN PILLAR BLACK OUT TAPE & CLEAN RESIDUE 85. WIPERS + RE-SET SWEEP 86. SCUTTLE TRAY AND NEC CLIPS AND SEALS 87. COVER MASK & PROTECT EXPOSED CABIN 88. SET UP ANTI-SPARK BLANKET & SECURE TO VEHICLE SubTotal Hrs SubTotal \$\$\$\$(\$140)\$ 89. INSTALL ON CAR O LINER & CLAMP VEHICLE For Rack Dec	0.45 1.00 3.00 0.20 0.20 0.25 0.25 0.30 0.20 0.45 0.30 0.20 0.40 0.25 0.40 1.00 0.50 Hrs 2.50 No Supportung Edipositics
72. R/H/R DOOR OPENING H/WARE 73. R/H CENTRE PILLAR SEAT BELT & ANCHOR 74. R/H CENTRE PILLAR UPPER & LOWER TRIMS 75. R/H/F DOOR D&A, LIFT OFF & SAFE STORE 76. R/H/F DOOR KICK PANEL & SCUFF PLATE 77. R/H/F DOOR APERTURE SEAL & RE-SEAL 78. R/H/F DOOR OPENING H/WARE 79. R/H/F ROAD WHEEL & RE-TORQUE 80. R/H/F MUD FLAP 81. R/H/F WHEEL ARCH FLARE & REPLACE CLIPS 82. R/H/F GUARD LINER & REPLACE CLIPS 83. R/H/F GUARD DUST COVER 84. R/H WINDSCREEN PILLAR BLACK OUT TAPE & CLEAN RESIDUE 85. WIPERS + RE-SET SWEEP 86. SCUTTLE TRAY AND NEC CLIPS AND SEALS 87. COVER MASK & PROTECT EXPOSED CABIN 88. SET UP ANTI-SPARK BLANKET & SECURE TO VEHICLE SubTotal Hrs SubTotal \$ \$8/,1 Repair: (\$140) 89. INSTALL ON CAR O LINER & CLAMP VEHICLE OUT TAPE & ARCA DER 90. PULL, MEASURE, SQUARE & RE ALIGN REAR INCL. LATA RAMR TIMES	0.45 1.00 3.00 0.20 0.20 0.45 0.25 9.20 0.45 0.30 0.20 0.40 0.25 0.30 0.20 0.40 1.00 0.50 57.90 Hrs 2.50 No Supporting Eulipsines 2.00
72. R/H/R DOOR OPENING H/WARE 73. R/H CENTRE PILLAR SEAT BELT & ANCHOR 74. R/H CENTRE PILLAR UPPER & LOWER TRIMS 75. R/H/F DOOR D&A, LIFT OFF & SAFE STORE 76. R/H/F DOOR KICK PANEL & SCUFF PLATE 77. R/H/F DOOR APERTURE SEAL & RE-SEAL 78. R/H/F DOOR OPENING H/WARE 79. R/H/F ROAD WHEEL & RE-TORQUE 80. R/H/F MUD FLAP 81. R/H/F WHEEL ARCH FLARE & REPLACE CLIPS 82. R/H/F GUARD LINER & REPLACE CLIPS 83. R/H/F GUARD DUST COVER 84. R/H WINDSCREEN PILLAR BLACK OUT TAPE & CLEAN RESIDUE 85. WIPERS + RE-SET SWEEP 86. SCUTTLE TRAY AND NEC CLIPS AND SEALS 87. COVER MASK & PROTECT EXPOSED CABIN 88. SET UP ANTI-SPARK BLANKET & SECURE TO VEHICLE SubTotal Hrs SubTotal \$ \$8/,1 Repair: (\$140) 89. INSTALL ON CAR O LINER & CLAMP VEHICLE FLAT RACK FLAG 90. PULL, MEASURE, SQUARE & RE ALIGN REAR FAILL LASTA RATAR TIMES 91. REAR BAR MOUNTS & BRACKETS 7 NO SUPPORTING	0.45 1.00 3.00 0.20 0.20 0.20 0.45 0.25 0.20 0.45 0.30 0.20 0.40 0.25 0.40 1.00 0.50 57.90 Hrs 2.50 No Supplied Euldsings 2.00 1.00
72. R/H/R DOOR OPENING H/WARE 73. R/H CENTRE PILLAR SEAT BELT & ANCHOR 74. R/H CENTRE PILLAR UPPER & LOWER TRIMS 75. R/H/F DOOR D&A, LIFT OFF & SAFE STORE 76. R/H/F DOOR KICK PANEL & SCUFF PLATE 77. R/H/F DOOR APERTURE SEAL & RE-SEAL 78. R/H/F DOOR OPENING H/WARE 79. R/H/F ROAD WHEEL & RE-TORQUE 80. R/H/F MUD FLAP 81. R/H/F WHEEL ARCH FLARE & REPLACE CLIPS 82. R/H/F GUARD LINER & REPLACE CLIPS 83. R/H/F GUARD DUST COVER 84. R/H WINDSCREEN PILLAR BLACK OUT TAPE & CLEAN RESIDUE 85. WIPERS + RE-SET SWEEP 86. SCUTTLE TRAY AND NEC CLIPS AND SEALS 87. COVER MASK & PROTECT EXPOSED CABIN 88. SET UP ANTI-SPARK BLANKET & SECURE TO VEHICLE SubTotal Hrs SubTotal \$ \$8,1 Repair: (\$140) 89. INSTALL ON CAR O LINER & CLAMP VEHICLE FLAT RACK DER 90. PULL, MEASURE, SQUARE & RE ALIGN REAR INCL. LITTLE RAPE TIMES 91. REAR BAR MOUNTS & BRACKETS 92. REAR B/BAR REINFORCEMENT & IRONS SUBJECT: SUMMERIANCE 93. SUMMERIANCE 94. SUMMERIANCE 95. SUMMERIANCE 96. SUMMERIANCE 97. SUMMERIANCE 98. SUMMERIANCE 98. SUMMERIANCE 99. PULL, MEASURE, SQUARE & RE ALIGN REAR INCL. LITTLE RAPER TIMES 91. REAR BAR MOUNTS & BRACKETS 91. REAR BAR MOUNTS & BRACKETS 92. REAR B/BAR REINFORCEMENT & IRONS 94. SUMMERIANCE	0.45 1.00 3.00 0.20 0.20 0.45 0.25 0.25 0.20 0.45 0.30 0.20 0.40 0.25 0.40 1.00 0.50 57.90 Hrs 2.50 No Supporting Evidences 2.00 1.00 1.00
72. R/H/R DOOR OPENING H/WARE 73. R/H CENTRE PILLAR SEAT BELT & ANCHOR 74. R/H CENTRE PILLAR UPPER & LOWER TRIMS 75. R/H/F DOOR D&A, LIFT OFF & SAFE STORE 76. R/H/F DOOR KICK PANEL & SCUFF PLATE 77. R/H/F DOOR APERTURE SEAL & RE-SEAL 78. R/H/F DOOR OPENING H/WARE 79. R/H/F ROAD WHEEL & RE-TORQUE 80. R/H/F MUD FLAP 81. R/H/F WHEEL ARCH FLARE & REPLACE CLIPS 82. R/H/F GUARD LINER & REPLACE CLIPS 83. R/H/F GUARD DUST COVER 84. R/H WINDSCREEN PILLAR BLACK OUT TAPE & CLEAN RESIDUE 85. WIPERS + RE-SET SWEEP 86. SCUTTLE TRAY AND NEC CLIPS AND SEALS 87. COVER MASK & PROTECT EXPOSED CABIN 88. SET UP ANTI-SPARK BLANKET & SECURE TO VEHICLE SubTotal Hrs SubTotal \$ \$8/,1 Repair: (\$140) 89. INSTALL ON CAR O LINER & CLAMP VEHICLE FLAT RACK DER 90. PULL, MEASURE, SQUARE & RE ALIGN REAR INCL. LATAR RAMR TIMES 91. REAR BAR MOUNTS & BRACKETS 7 NO SUPPORTING	0.45 1.00 3.00 0.20 0.20 0.20 0.45 0.25 0.20 0.45 0.30 0.20 0.40 0.25 0.40 1.00 0.50 57.90 Hrs 2.50 No Supplied Euldsings 2.00 1.00

95. TAILGATE EXCESSIVE - REPAIRER CAUDED BY LIST PRICE 96. LIST PRICE - \$2363.59 - PART# 670050E540 NOT REPAIR TIME 97. TAILGATE APETURE 98. TAILGATE HINGE PAD'S 99. BOOT FLOOR & UNDERSIDE 100. L/H QUARTER PANEL 101. R/H QUARTER PANEL 102. TRIAL FIT FOR ALIGNMENT 103. MEASURE, TEMPLATE & DRILL SENSOR HOLES 104. BLACK OUTS AS REQ 105. SILL CLAMP MARKS 106. APPLY PROOF COAT	\$0.00 2.00 2.00 2.00 4.00 Z 4.00 Z 1.00 1.50 I 1.00 1.00 1.00 .5		
107. APPLY EPOXY PRIMER TO BARE METAL REPAIRS 108. APPLY HIGH-BUILD PRIMERS TO REPAIRS	0.20 0.25		
109. DUPLICATE OEM TEXTURES & SEALERS	1.00		
—110. APPLY CAVITY WAX TO NEW & REPAIRED PANELS	0.20		
CubTotal Ura			E1 60
SubTotal Hrs		•	51.90
SubTotal \$	\$7 ,2 66.00	•	\$7,266.00
Paint: (\$140)	Hrs 1.50		Adj
111. OVEN ALLOWANCE - 3 LAYER PEARL 112. MIX & MATCH COLOUR - 3 LAYER PEARL	1.50.		
113 INCLUDING SPRAY OUTS	\$0.00		
114. REAR B/BAR COVER	3.50 2.5		
115. REAR PARK SENSORS & RINGS	2,00 . 8		
116. REAR REINFORCMENT 3 NO SUPPORTING EVIDENCE	1,00		
116. REAR REINFORCMENT 117. BEAVER PANEL IN & OUT 118. BOOT FLOOR AS REQUIRED 118. SUPPORTING EVISENCE	2.00		
	1.50		
119. TAILGATE (LARGE PANEL) 120. TAILGATE APETURE 7	5,00 4.5 2,00		
121. TAILGATE HINGES ING SUPPORTING EVISENCE	1,20		
122. L/H TAIL LAMP PANEL	1,00		
123. L/H QRT & DROP PANE L	4.50 2.5		
124. FUEL FILLER FLAP	0.50		
125. FUEL BUCKET /NCL. WITH QTR PANEL	0.50		
126. L/H/R DOOR	3,50 2.5		
127. L/H/R DOOR HANDLE & CAP	0.50		
128. L/H/R DOOR APERTURE INC BIPLLAR 7 No SOPPORTING	2.00		
129. L/H CENRE PILLAR & HINGES 130. L/H/F DOOR APERTURE LIBERTURE 129. L/H CENRE PILLAR & HINGES EUISENCE	1.50 1.50		
131. L/H A PILLAR & HINGES	1.00		
132. L/H TURRET CANT RAIL & WINDSCREEN PILLAR	2.50 1.5		
133. R/H TAIL LAMP PANEL	1,00 .5		
134. R/H QRT & DROP PANEL	4,80 2.5		
135. R/H/R DOOR	3.50 2.5		
136. R/H/R DOOR HANDLE & CAP	0.50		
137. R/H/R DOOR APERTURE 138. R/H CENTRE PILLAR & HINGES 139. R/H/E DOOR APERTURE LIDENCE	1.50		
139. R/H/F DOOR APERTURE	1,50° 1,50		
140. R/H A PILLAR & HINGES	1.00		
141. R/H TURRET CANT RAIL & WINDSCREEN PILLAR	2.50 1.5		
142. UNDER BODY AS REQ NO SUPPORTING EUDENCE	1.00		
143. BRUSH TOUCH BOLTS	0.25		
144. DE-NIB & POLISH PAINTED & ADJACENT PANELS	2,00 /		
145. APPLY PLASTIC FLEX AID NCL. WITH RIBAR	9.60		
SubTotal Hrs	61.55		61.55
		•	
SubTotal \$	\$8,617.00	•	\$8,617.00

Tot	al Labour Hrs	171.35	•	169.50
	Total Labour	\$23,989.00	•	\$23,730.00
Part:		\$		Adj
146. REAR B/BAR COVER - MAIN New - 521590E923		\$242.19		•
147. REAR B/BAR COVER - LOWER MAIN New - 521	690E110	\$378.32		
148. L/H CENTRE PARK SENSOR & GASKET New - 8	934133220A1	\$229.75		
149. R/H CENTRE PARK SENSOR & GASKET New - 8	934133220A1	\$229.75		
150. REAR REO New - 521710E130		\$186.07		
151. L/H/R BAR SLIDE New - 521560E100		\$210.55		
152. R/H/R BAR SLIDE New - 521550E100		\$210.55		
153. T/GATE EMBLEM - (TOYOTA) New - 7540348010		\$74.87		
154. T/GATE EMBLEM - (KLUGER) New - 754420E110)	\$66.85		
155. T/GATE EMBLEM-(HYBRID) New - PZQ3148101	_	\$16.55		
156. L/H TAIL GATE HINGE New - 688200E230 ? WA		\$113.13		
157. R/H TAIL GATE HINGE New - 688100E290			_	
158. BEAVER PANEL INTERIOR TRIM New - 583870E		\$262.20 No SUPP	DATING EUN	GNCE
159. L/H WINDSCREEN PILLAR BLACK OUT TAPE N 759280E020	New -	\$57.93 /		
160. R/H WINDSCREEN PILLAR BLACK OUT TAPE N 759270E020	New -	\$57.93 /		
	SubTotal \$	\$2,449.77	•	\$2,449.77
Other:		\$		Adj
162. PLASTIC INTERIOR COVER SET		\$35.00 15		
163. ENVIRONMENT LEVY		\$35.00 10		
164. MISC W/SHOP CONSUMABLES		\$50.00		
-165. PROOF COAT **SUPPLY		\$25.00		
166. ZINC PRIMER **SUPPLY		\$20.00		
-167. CAVITY WAX **SUPPLY		\$20.00		
168. SPRAY & BRUSH SEALER **SUPPLY		\$25.00		
169. HIGH-BUILD PRIMERS **SUPPLY		\$25.00		
170. NUT, BOLTS, CLIPS		\$30.00		
171. CLEAN, RE-TAPE & RE-APPLY SENSOR CRADI	·-	\$75.00 60		
172. J-TAPE & SPECIAL MASK WINDSCREEN PILLA	IRS	\$85.00 120		
173. J-TAPE & SPECIAL MASK REAR GLASS		\$85.00 \$70.00		
174. ADMIN FEES	TEC In The			
175. MEASURE, TEMPLATE & APPLY T/GATE BADO 176. SPECIAL MASK TAILGATE INNERS - 1 PEICE IN	TEDIOD &	\$85.00		
EXTERIOR STANDARD MASKING PROCESS	NIERIOK &	\$25.00		
177. CLEAN, PREPARE & APPLY L/H & R/H WINDSO	CREEN	\$80.00		
PILLAR BLACK OUT DECALS 178. PRE & POST DTC CHECK & RESET ON-BOARDS	g	\$210.00		\$140.00 <i><</i>
	3	•	•	\$140.00
179. PRE DELIVERY DETAIL - EXSPOSED CABIN		\$210.00 60		#140
180. HOIST SET UP TIME INC		\$210.00 60	•	\$140.00
181. APPLY UNDERBODY PROOFCOATS TO REPAIR	RED AREAS	\$0.00	>	\$0.00
182. TEST DRIVE FOR NVH		\$140.00 6		
183. DISARM HYBRID HV SYSTEMS & REINITALISI	E	\$490.00 25		
AWP 17.2.25	SubTotal \$	\$2,068.00	•	\$1,928.00
DION AAMC	Total	\$28,506,7/7		\$28,107.17
de deserva	GST	\$2,850.68		\$2.810.79
CJO MUCLARU			•	φ2,010.78
C/O HXLARD * DESKTOP *	Grand Total	\$31,357.45	•	\$30,918.55







PHONE: (03) 8900 0688 EMAIL: ar@hfhautogroup.co

Bank Details NAME: HFH AUTO BERWICK BSB: 013-542 ACC NUMBER: 837 263 216







Invoice To SHEEN PANEL SERVICE COBURG 2 MCDONALD ST COBURG NORTH VIC 3058





Contact SHEEN PANEL SERVICE COBUR Phone: 93502331 Cust: T103949 Mob

PARTS TAX INVOICE

Invoice No.	1437121186		
Page	1		
Printed	03/02/2025 10:53		
Customer	T103949		
Туре	Account		
Customer P.O.	5885		
Sales Rep.	DH		
Document Number	O437148158		

Line	Bin	Part		Description	Ord	B/O	Supplied	List Price	Unit	Ext Price
1	RHE3	TOY	521590E923	COVER RR BUMPER	1		1	242.19	160.00	160.00
2	RAB3	TOY	521690E110	COVER RR BUMPER	1		1	378.32	240.00	240.00
3	DND6	TOY	8934133220A1	SENSOR ULTRASONIC	1		1	229.75	167.72	167.72
4	DND6	TOY	8934133220A1	SENSOR ULTRASONIC	1		1	229.75	167.72	167.72
5	NCF1	TOY	521710E130	REINFORCEMENT RR	1 1		1	186.07	125.00	125.00
6	EAH1	TOY	7540348010	EMBLEM SUB-ASSY	1		1	74.87	53.91	53.91
7	EUG4	TOY	754420E110	PLATE LUGGAGE COMPT	1		1	66.85	48.13	48.13
8	DQC2	TOY	PZQ3148101	BADGE HYBRID BASE GRADES	1		1	16.55	13.57	13.57
9	GNL1	TOY	521560E100	SUPPORT RR BUMPER	1		1	210.55	151.60	151.60
10	GNH1	TOY	521550E100	SUPPORT RR BUMPER	1		1	210.55	151.60	151.60
11		TOY	688200E230	HINGE ASSY BACK SPECIAL ORDERED PART, NON	1	1		113.13	81.45	.00
12		TOY	688100E290	RETURNABLE HINGE ASSY BACK SPECIAL ORDERED PART , NON RETURNABLE	1	1		113.13	81.45	.00
13		TOY	583870E090C0	PLATE RR FLOOR	1	1		262.20	188.78	.00
_								SUB TOTA	AI .	\$1279.25

SPECIALLY PROCURRED PARTS AND ELECTRICAL ITEMS NOT RETURNABLE FOR CREDIT ACCOUNT PAYMENT TERMS: 30 DAYS FROM END OF MONTH





Auto Group Parts Rd sham VIC 3810

PHONE: (03) 8900 0688 EMAIL: ar@hfhautogroup.com.au

Bank Details NAME: HFH AUTO BERWICK BSB: 013-542 ACC NUMBER: 837 263 216













	ice	

SHEEN PANEL SERVICE COBURG 2 MCDONALD ST COBURG NORTH VIC 3058

	Dispatch To					
HEEN	PANEL	SERVICE	COBURG			

SHEEN PANEL SE 2 MCDONALD ST COBURG NORTH VIC 3058

Contact: SHEEN PANEL SERVICE COBUR Phone: 93502331 Cust: T103949 Mob.

PARTS TAX INVOICE

Invoice No.	1437121186
Page	3
Printed	03/02/2025 10.53
Customer	T103949
Туре	Account
Customer P.O.	5885
Sales Rep.	DH
Document Number	O437148158

		Part Description Ord B/		A PROPERTY OF THE PARTY OF THE	Supplied	List Price	Unit	Ext Price
4 ENET 5 GKG:	TOY 759280E020 TOY 759270E020	SPECIAL ORDERED PART, NON RETURNABLE TAPE BLACK OUT TAPE BLACK OUT PLEASE NOTE ALL PARTS WITH NO BIN LOCATION ARE SPECIAL ORDERED PARTS AND ARE NON RETURNABLE. ALL ELECTRICAL PARTS ARE NON RETURNABLE	1 1		1	57.93 57.93	46.34 46.34 PARTS TOTAL GST	46.34 46.34 \$1371.93 \$137.19

PAY ID TYPE ACN

SPECIALLY PROCURRED PARTS AND ELECTRICAL ITEMS NOT RETURNABLE FOR CREDIT ACCOUNT PAYMENT TERMS: 30 DAYS FROM END OF MONTH



PHONE: (03) 8900 0688 EMAIL: ar@hfhautogroup.c

Bank Details NAME: HFH AUTO BERWICK BSB: 013-542 ACC NUMBER: 837 263 216





(med-	
2 PARTSCHEEK	

Invoice To							
SHEEN PANEL SER	VICE C	OBURG					
COBURG NORTH	VIC	3058					

Dispatch To					
SHEEN PANEL SERVICE COBURG 2 MCDONALD ST COBURG NORTH VIC 3058					
Contact SHEEN PANEL SERVICE COBUR					

Invoice No.	1437121457			
Page	1	_		
Printed	05/02/2025 07:2	28		
Customer	T103949			
Туре	Account			
Customer P.O.	5885			
Sales Rep.	DH			
Document Number	er O437148158			

PARTS TAX INVOICE

Line	Bin	Part	Description	Ord	B/O	Supplied	List Price	Unit	Ext Price
1	35.79	TOY 688200E230	HINGE ASSY BACK SPECIAL ORDERED PART, NON RETURNABLE	1		1	113.13	81.45	81.45
2		TOY 688100E290	HINGE ASSY BACK SPECIAL ORDERED PART, NON	1		1	113.13	81.45	81.45
3 TOY 583870E090C0		TOY 583870E090C0	RETURNABLE	1	ours s		262.20	188.78	188.78
			******* Continued ********				SUB TOTA		\$351.68





PHONE: (03) 8900 0688 EMAIL: ar@hfhautogroup.co

Bank Details NAME: HFH AUTO BERWICK BSB: 013-542 ACC NUMBER: 837 263 216



	nvoice	То	
SHEEN PANEL SER 2 MCDONALD ST	VICE C	OBURG	
COBURG NORTH	VIC	3058	

Dispatch To						
SHEEN PANEL SERVICE COBURG						
2 MCDONALD ST COBURG NORTH VIC 3058						
Contact SHEEN PANEL SERVICE COBUR						

Invoice No.	1437121457			
Page	3			
Printed	05/02/2025 0			
Customer	T103949			
Туре	Account			
Customer P.O.	5885			
Sales Rep.	DH			
Document Number	0437148158			

PARTS TAX INVOICE

Line	Bin	Part	Description	Ord	B/O	Supplied	List Price	Unit	Ext Price
								PARTS TOTAL GST	\$351.68 \$35.17
							TO		\$386.85



AAMC Calculation Sheet

22201038896 Claim No:

	\$140.00			\$140.00	\$140.00				
	R&R item	R&R item	R&R item	Repair	Paint	Mechanical	Parts	Parts	Misc
	0.50	2.50		1.00	1.50		242.19		15.00
	0.15	0.40		5.00	0.50		378.32		10.00
	0.50	0.50		2.00	2.50		229.75		50.00
	0.25	0.20		2.00	0.80		229.75		20.00
	0.20	2.50		1.00	4.50		186.07		20.00
	0.45	0.40		0.50	2.50		210.55		25.00
	0.30	0.50		0.25	0.50		210.55		25.00
	0.25	0.50		1.00	2.50		74.87		30.00
	0.20			0.20	0.50		66.85		60.00
	0.45				1.50		16.55		120.00
	0.30				0.50		57.93		80.00
	0.25				2.50		57.93		140.00
	0.20				2.50				60.00
	0.30				0.50				60.00
	1.00				1.50				60.00
	1.20				0.25				250.00
	0.30				1.00				
	1.00								
	1.20								
	0.30								
	0.30								
	2.00								
	0.50								
	0.20								
	2.50								
	0.50								
	0.20								
	0.30								
	0.30								
Supplementary:									
Cub Total			ć 2.204.00	ć 1 012 00	¢ 2.647.00	Ċ		¢ 106131	¢ 1.03F.00
Sub-Total			\$ 3,304.00	\$ 1,813.00	3,047.00 ج	\$ -		\$ 1,961.31	\$ 1,025.00

Assessor Notes:	
Assessed by:	Dion Naude

	Towing	
R&R Labour	\$	3,304.00
Repair Labour	\$	1,813.00
Paint Labour	\$	3,647.00
Total Labour	\$	8,764.00
Mechanical	\$	-
Parts	\$	1,961.31
Miscellaneous	\$	1,025.00
Towing	\$	-
Sub-Total pre GST	\$	11,750.31
GST	\$	1,175.03
TOTAL INC GST	\$	12,925.34
Original Quote	\$	30,918.55
Ammended Quote	\$	12,925.34
Difference b/w Quotes	\$	17,993.21



Pre-Accident Valuation Report

Created at 20/02/2025 8:13 PM AEDT by Dion Naude

2023 Toyota Kluger GX

Recommended PAV

\$51,881

This valuation is based on 2 vehicles advertised for sale in multiple online marketplaces. Where possible, we have utilised advertisements showing comparable vehicles for sale in the same state as the vehicle's current location. Where there are low volumes of comparable vehicles (or no vehicles at all) for sale in the same area as the vehicle, we utilise advertisements showing similar vehicles, or vehicles for sale in other states in order to substantiate our valuation. The industry guide price of this vehicle (adjusted where necessary to reflect condition, odometer reading, and accessory level) is \$52,550. The average price of the advertised vehicles (adjusted where necessary to reflect differences in condition, odometer readings, and accessory levels) is \$51,881. In considering the average price of vehicles advertised for sale in the market alongside industry valuation guides, we have calculated the value for this vehicle (rounded as appropriate) to be \$51,881.

Specifications

Make	Toyota	Transmission	Automatic
Model	Kluger	Model Year	-
Year	2023	Drive Type	Four Wheel Drive
Badge	GX	Vehicle Odo	123,879 km
Series	AXUH78R	RRP	\$57,620



Claim ID: 5JAAT Insurance Company: Hollard Vehicle Condition: Average

Reference Guide Valuation


Reference Guide: Glass's	Reference Code: OCPB23	Reference Value: \$52,550
Odometer Adjustment Not selected	Accessory Adjustment Not selected	Pre-Existing Damage Not selected

Net Reference Value (sum of Reference Value and all other adjustments made) = \$52,550

Pre-Accident Valuation Report

Market Comparison

2 vehicles selected Date of search: 20/02/2025 2:37 PM AEDT



YearMakeModelBadgeSeriesStateOdo2023ToyotaKlugerGXAXUH78RVIC61,264

Dealer Starting: \$52,990 Delisted at: 31/12/2024 10:40 PM AEDT

Adjustments

Odo Adjustment (-\$626)

Delisted Price \$52,990

Adjusted Price

\$52,364



YearMakeModelBadgeSeriesStateOdo2023ToyotaKlugerGXAXUH78RVIC64,655

Dealer Starting: \$51,990

Adjustments

Odo Adjustment (-\$592)

Latest Price \$51,990

Adjusted Price

\$51,398

AutoEdge



▶ Search ▶ Result List

Search

Selection Treeview Search NVIC

Help Files

Data Enquiry Form

Log out

2023 TOYOTA KLUGER GX HYBRID AWD AXUH78R 5D WAGON INLINE 4 2487 cc DIRFI CONTINUOUS VARIABLE

- Model Specification
- ▶ Pricing History
- **Forecaster**



Year	2023	NVIC		OCPB23	
Make	ТОҮОТА	Glass	Code	TOYKLUHA21250CPB2	023
Family	KLUGER	Class		LIGHT COMMERCIAL V	EHICLE
Variant	GX HYBRID AWD	Segme	ent	SUV LARGE	
Series	AXUH78R	Releas	se Date	October 2022	
Body	5D WAGON	Discor	ntinue Date	December 2023	
Engine	DIRECT FUEL INJ	ANCAI (5*=b	P Rating est)	***	
Engine Config	INLINE 4	Avera	ge KM	30,000	
сс	2487 cc	Actual	KM	123 X1000 km	
Transmission	CONTINUOUS VARI	ABLE			
Green Vehicle G	uide Overall Rating	(5*=best)	Not availabl	e	
Fuel Consumption City/Combined		5.6 litres/100km	CO2 Emiss	ion (g/km)	128
Fuel Consumption	on Highway	N/A	Green Hou	se Rating (10=best)	N/A
Fuel Type		PREMIUM UNLEADED/ELECTRIC	Air Pollutio	on Rating (10=best)	N/A

```
[12V+] Additional 12 Volt Socket/s
[12VO] 12 Volt Power Outlet
[21CY] 21CY Multi Media Platform
[21MM] 21MM Multi Media System
[2RSS] Second Row Seats - Sliding
[338R] 338mm Rear Brakes
[340B] 340mm Front Brakes
7SIN Seven Seat Interior
[ABB] Dual Front Airbags Package
[ABD] Airbag Driver
[ABKD] Airbag Driver
[ABKD] Airbag - Knee Driver
[ABKS] Anti-lock Braking
[ACA] Active Cornering Assist
[ACCD] Auto Climate Control with Dual Temp Zones
[ACHB] Active High Beam Control
[ACN] Automatic Collision Notification
[ACP] Apple Car Play
[ACSG] Active Safety Group
[AL] Alarm System/Remote Anti Theft
[ARDM] Auto Retractable Door Mirrors
[ARSB] Antenna - Roof-mounted Shark Fin type - Black
[ASS] Automatic Stop/Start
[ASTC] Adjustable Steering Column
[ASTY] All Season Tyres
[ASW] Adjustable Steering Wheel - Tilt & Telescopic
[AU] Android Auto
[AW18] 18 Inch Alloy Wheels
[BAGH] Bag Hooks
[BCDH] Body Coloured Exterior Door Handles
[BCEM] Body Coloured Exterior Mirrors
[BCS] Brake Control Systems
[BHFR] Bottle Holders - Front & Rear
[BS23] Bench Seat 2nd Row - 3 Person
[BS32] Bench Seat 3rd Row - 2 Person
BSM] Blind Spot Monitoring
[CAB] Curtain Airbags
[CCT] Centre Console Tray
[CDL] Centre Courtesy/Dome Light/s
[CFMT] Carpet Floor Mats
[CGC] Cargo Cover
[CHFR] Cup Holders - Front & Rear
[CHR] Cargo Tie Down Hooks/Rings
[CLE] Centre Console Box - Multi-purpose
[COAS] Collision Avoidance System
[CU] Cloth Upholstery
[CYCR] Cyclist Recognition
[DCDC] DC/DC Converter
[DCLF] Door Courtesy Lamp - Front
[DCM] Data Communication Module
[DECA] Deceleration Assist
[DMS] Driver Mode Selection
DPA] Dual Passenger Airbag
[DPFR] Door Pockets - Front & Rear
DRCC Dynamic Radar Cruise Control
[DRLS] Daytime Running Lights - LED
[DRSC] Drive Start Control
[DS08] Display Screen 8 Inch
[EAWD] Electric All-wheel Drive
[ECOM] ECO Mode
[EMTR] Exterior Mirrors - Tilt When Reversing
[EPB] Electric Parking Brake
[EPS] Electric Power Steering
[ESA] Emergency Steering Assist
[EVM] EV Mode
[FDTF] Fabric Door Trim Finish
[FLED] Fog Lights - LED
[GB] Glovebox Compartment
[HDMI] HDMI Input
[HML] Headlights - Manual Levelling
[HSA] Hill Start Assist
[HSLL] High Mounted Rear Stop Light - LED
[HYDS] Hybrid Drive System
[IABS] Impact Absorbing Body Structure
[IM] Engine Immobiliser
[IPOP] IP Ornament Panel - Painted
[LAGK] Leather Accented Gear Knob
[LAGL] Leather Accented Gear Shift lever
[LASW] Leather Accented Steering Wheel
[LCF] Lane Centering Function
[LDAL] Lane Departure Alert
[LECL] LED Clearance Lamp
[LED] LED Headlights
[LEDF] LED Front Cabin Lights
[LH] Load Hooks
[LTA] Lane Trace Assist
[MFFR] Mud Flaps - Front & Rear
[MFSW] Multi-function Steering Wheel
MID7] Multi Information Display 7.0 inch
[MIDC] Multi Information Display - Colour
MPH] Mobile Phone Connectivity
[MRCC] MyRemote Control Capability (inc climate control)
```

[MRL] Map/Reading Lights - Front

[NUKM] Normai Mode [OHC] Overhead Console/s [PAHL] Parabolic Headlights [PCB] Post Collision Braking [PCBS] Pre-Collision Braking System [PCU] Power Control Unit [PDCB] Parking Distance Control Front & Rear [PDO] Painted Door Ornament [PEDP] Pedestrian Protection [PEDR] Pedestrian Recognition [PKSB] Parking Support Brake [PMH] Power Exterior Mirrors - Heated [PMI] Power Mirrors With Indicators [PMSF] Permanent Magnet Synchronous Motor - Front Axle [PMSR] Permanent Magnet Synchronous Motor - Rear Axle [PPB] Pedestrian Protection Bonnet [PREC] Pre-collision Systems [PSG] Passive Safety Group [PWA] Power Windows - Auto Up/Down [PWAT] Power Windows - Anti-trap [RCA1] Rear Centre Armrest with Cup Holders [RCLL] Rear Combination Lights LED [RCSL] Rear Centre Spot Lamp [RCTA] Rear Cross Traffic Alert [RDHI] Resin Door Handles - Interior [REMS] Remote Services [RPG] Rear Privacy Glass RS] Rear Spoiler [RSA] Road Sign Assist [RSW] Rain Sensing Wipers [RVC] Reversing Camera [SABF] Side Airbags - Front Seats side [SBL2] Seatbelts - Load Limiters 2nd Row Outer [SBLL] Seatbelts - Load Limiters Front Seats [SBLS] Seatbelts - Lap/Sash for All Seats [SBP2] Seatbelts - Pre-tensioners 2nd Row Outer [SBPT] Seatbelts - Pre-tensioners Front Seats [SCPK] Storage Compartment Package [SCRS] Storage Compartment Under Rear Seats [SFRS] Split Fold Rear Seat [SFTR] Split Fold Third Row Seat [SGRS] Silver Grille Surround [SIND] Side Indicators [SM] Sports Mode SME] Smart Entry SMS1 Smart Start [SOSC] SOS Emergency Call [SPFS] Seatback Pockets - Front Seats [SS6] Sound System with 6 Speakers [STIP] Soft Touch Instrument Panel [SUNE] Sunvisor Extensions [SVMI] Sunvisors with Vanity Mirrors & Illumination [SVT] Stolen Vehicle Tracking [SZRC] Single Zone Rear Climate Control [TCS] Traction Control System [TEL] Telematics [TRM] Trail Mode [TRS] Third Row Seats [TSS] Toyota Safety Sense [TURN] Turn Assist [USB] USB Input Socket [USBC] USB-C Input Socket/s [VFDB] Ventilated Front Disc Brakes VRDB1 Ventilated Rear Disc Brakes [VRS] Voice Recognition System [VSC] Vehicle Stability Control [WFME] Wheel Finish - Metallic [WFSI] Wheel Finish - Silver [X] [CRPP] Crystal Pearl Paint [] [MIP] Mica Paint Cost Options/ **No Cost Options** [] [MP] Metallic Paint] [STPA] Standard Paint **User Option** /Accessories Value (\$) New Opt. (Value not Depreciated) Add User Option New Price Trade Low Trade Retail Glass's Value \$49,100 \$56,400 \$58,290 \$41,500 KM Adjustment (\$1,485.00)(\$2,475.00)(\$4,950.00)

\$330

\$40,345

\$550

\$47,175

\$1,100

\$52,550

Value of Options

Adjusted Values

\$680

\$58,970

New Price represents RRP or Drive Away Price. This is dependent on what we receive from the manufacturer.

▶ Disclaimer ▶ Privacy Statement ▶ Terms and Conditions ▶ Contact us

© GLASS'S INFORMATION SERVICES



Registration Check

Results for 5JAAT as at 20/02/2025 14:30 AEDT

2023 WHITE TOYOTA WAGON

Registration number: 5JAAT

Registration status & expiry Current - 16/03/2025

date: Vehicle:

VIN/Chassis: 5TDLB3CH50S128001

Engine number:A25AK885822Registration serial number:11413444Compliance plate / RAV entry07/2023

date:

Sanction(s) applicable: None
Goods carrying vehicle: No
Transfer in dispute: No

Important information

The information provided is not a comprehensive vehicle check. Visit PPSR.gov.au to get a comprehensive vehicle check.

For information on Fines Victoria Sanctions call 1300 396 851 or Hoon Sanctions call Victoria Police Impoundment Unit (03) 8480 1600. See our new <u>legal disclaimer</u> on our website.

Expert Witness Credentials

Name:	Dion Naude
Company:	Australian Accident Management Commercial

Summary

My credentials as an expert witness qualify me to give testimony based on my specialist knowledge in the vehicle accident, repair and insurance industry. In acting for the court only, after evaluation of all relevant case documents and related facts of the particular matter, I will provide testimony or opinion based on my knowledge, expertise and experience and communicate technical issues to counsel and court in such a manner as to be understood without being construed toward either the plaintiff or defendant.

Qualifications and Experience

I have been directly involved in the Collision Repair and Insurance industry for 30 years and my qualifications and industry experience are outlined as follows:

Qualifications

- (2019) Cert. IV Motor Loss Assessor
- Cert. IV equivalent Qualified Panel Beater & Spray Painter
- (2017) I-Car platinum individual
 - o (2012) FCR01 Fundamentals of Collision Repair
 - (2013) POP01 Collision Repairs for Select High Volume Vehicles
 - o (2014) ALT02A Hybrid Electric & Electric Vehicles
 - (2014) DAM05 Aluminium Panels & Structure Damage Analysis
 - o (2015) GMHA3 Holden SUV Collision Repair Overview
 - o (2015) SSS01 Structural Straightening Steel
 - o (2016) CPS01 Corrosion Protection
 - o (2017) WOV A11 I-Car
 - o (2021) RF045E01 Understanding Refinish Defects P.1
 - o (2021) RF045E01 Understanding Refinish Defects P.2
 - (2022) GE050E01 Hybrid Vehicle Identification and Damage Analysis
 - (2023) VT200E01 Calibration of Front Facing Cameras and Front Radars
 - (2024) VT465E01 Damage Discovery for ADAS Sensor Mounting Locations

- (2013) SPS07 Steel Unitised Structures Technologies and Repair
- o (2013) DAM08 Advanced Materials in Damage Analysis
- (2014) SPS09 Best Practice for High Strength Steel Repairs
- o (2015) FOM01 Automotive Foams
- o (2015) PLA03 Plastic & Composite Repairs
- (2016) EXT02 Weld & Adhesive Bonded Panel Replacement
- o (2016) Aluminium Exterior Panel Repair & Replacement
- o (2021) VT022E01 Vehicle Trends and Technology
- o (2022) VT430E01 Introduction to Electric Vehicles
- (2022) VT455E01 Electric Vehicle (EV) Damage Analysis
- (2023) VT265E01 Post Repair Advanced Driver Assistance Systems (ADAS) Testing
- (2024) EA065E02 Damage Analysis of Electronic Brake System

Experience

No of Years	Position
9 Years	Vehicle Loss Assessor – Australian Accident Management Commercial
5 Years	Branch Manager – Sheen Panel Service
15 Years	Panel beater

I confirm that the information detailed above is a true and accurate representation of my qualifications and experience. I acknowledge that in acting as an expert witness I will abide by the Expert Witness Code of Conduct and that my testimony will be truthful, thorough and impartial.

Signature: Date: 01/2025	Name:	Dion Naude		
Date: 01/2025	Signature:	Raude		
	Date:	01/2025		
Contact: Mob: 0439 846 136 Email: dion.naude@aamc.com.au	Contact:	Mob: 0439 846 136	Email: dion.naude@aamc.com.au	

Magistrates' Court General Civil Procedure Rules 2020 S.R. No. 112/2020

Form 44A—Expert witness code of conduct

Form 44A—Expert witness code of conduct

Rule 44.01

EXPERT WITNESS CODE OF CONDUCT

Application of Code

- This Code of Conduct applies to any expert witness engaged or appointed—
 - to provide an expert's report for use as evidence in proceedings or proposed proceedings; or
 - to give opinion evidence in proceedings or proposed proceedings.

General Duties to the Court

An expert witness is not an advocate for a party and has a paramount duty, overriding any duty to the party to the proceedings or other person retaining the expert witness, to assist the Court impartially on matters relevant to the area of expertise of the witness.

Content of Report

- Every report prepared by an expert witness for use in Court must clearly state the opinion or opinions of the expert and must state, specify or provide the following—
 - (a) the name and address of the expert;
 - (b) an acknowledgment that the expert has read this code and agrees to be bound by it;
 - (c) the qualifications of the expert to prepare the report;
 - (d) the assumptions and material facts on which each opinion expressed in the report is based (a letter of instructions may be annexed);
 - (e) the reasons for and any literature or other materials utilised in support of each such opinion;
 - (f) (if applicable) that a particular question, issue or matter falls outside the expert's field of expertise;
 - (g) any examinations, tests or other investigations on which the expert has relied, identifying the person who carried them out and that person's qualifications;
 - (h) to the extent to which any opinion which the expert has expressed involves the acceptance of another person's opinion, the identification of that other person and opinion expressed by that other person;

Magistrates' Court General Civil Procedure Rules 2020 S.R. No. 112/2020

Form 44A—Expert witness code of conduct

- (i) a declaration that the expert has made all the inquiries which the expert believes are desirable and appropriate (save for any matters identified explicitly in the report) and that no matters of significance which the expert regards as relevant have, to the knowledge of the expert, been withheld from the Court;
- any qualification of an opinion expressed in the report without which the report is or may be incomplete or inaccurate;
- (k) whether any opinion expressed in the report is not a concluded opinion because of insufficient research or insufficient data or for any other reason; and
- where the report is lengthy or complex, a brief summary of the report at the beginning of the report.

Supplementary Report Following Change of Opinion

- 4. Where an expert witness has provided to a party (or that party's legal representative) a report for use in Court, and the expert thereafter changes his or her opinion on a material matter, the expert must without delay provide to the party (or that party's legal representative) a supplementary report which must state, specify or provide the information referred to in paragraphs (a), (d), (e), (g), (h), (i), (j), (k) and (l) of clause 3 of this code and, if applicable, paragraph (f) of that clause.
- In any subsequent report (whether prepared in accordance with clause 4 or not) the expert may refer to material contained in the earlier report without repeating it.

Duty to Comply with the Court's Directions

- 6. If directed to do so by the Court, an expert witness must—
 - (a) confer with any other expert witness;
 - (b) provide the Court with a joint report specifying (as the case requires) matters agreed and matters not agreed and the reasons for the experts not agreeing; and
 - (c) abide in a timely way by any direction of the Court.

Conference of Experts

- 7. Each expert witness must—
 - (a) exercise the expert witness's independent judgment in relation to every conference in which the expert participates pursuant to a direction of the Court and in relation to each report thereafter provided, and must not act on any instruction or request to withhold or avoid agreement; and

Magistrates' Court General Civil Procedure Rules 2020 S.R. No. 112/2020

Form 44A—Expert witness code of conduct

(b)	endeavour to reach agreement with the other expert witness
	(or witnesses) on any issue in dispute between them, or
	failing agreement, endeavour to identify and clarify the basis
	of disagreement on the issues which are in dispute.





Added by: Maria Reyes Date: 14/02/2025 5:40 PM



Added by: Maria Reyes Date: 14/02/2025 5:40 PM





Added by: Maria Reyes Date: 14/02/2025 5:40 PM



Added by: Maria Reyes Date: 14/02/2025 5:40 PM







Added by: Maria Reyes Date: 14/02/2025 5:40 PM





Added by: Maria Reyes Date: 14/02/2025 5:40 PM







Added by: Maria Reyes Date: 14/02/2025 5:40 PM



Added by: Maria Reyes Date: 14/02/2025 5:40 PM



