


NOTE: When using SU-100 use
Com (pin 3) and N.C. (pin 5).

Motion Sensor
For Fully Automatic
Applications only



Installation Notes:

1. MC-521 Pro / IQ Safety Logic must be set to Value 10.
2. Set door speeds and verify proper door operation prior to final connection of sensors system.
3. Technician MUST WALK TEST to verify function and detection patterns comply with ANSI/BHMA A156.10 requirements.



Title: Stanley IQ / MC 521 Pro with Elite Pro		Drawing # 01STAIQELIP01 Rev 1
Drawing By: JAS	Date: 09-12-24	Sheet: 1 of 1
Optex Technologies Inc. 10741 Walker St., Suite 300, Cypress, CA 90630 Office: (800)877-6656, Fax: (310)214-8644		