




- Notes:
1. Verify proper door operation prior to final connections of sensors.
 2. Mandatory Dipswitch Setting  set dipswitch 15 & 16 ON (UP).
 3. Alternate frequency dipswitches 3 & 4, when installing two or more sensor in near promity with one another.
 4. Technician must perform a field test to verify substantial compliance with ANSI/BHMA A156.10 Section 8.

Title: 16300120 Dorma ESA II with i-oneX T		Drawing # 16300120
Drawing By: RNG	Date: 5/23/16	Sheet: 1 of 1
OPTEX Technologies Inc. 18730 S. Wilmington Ave. Unit 100 Rancho Dominguez, CA. 90220 800-877-6656 FAX 310-898-1098		