

# **TECHNICAL DATA SHEET**

## **TA63G20C00**

## Clear acrylic matt converter

Color	Clear	
Gloss	20	
Area of use	Base for tinting	
Application	Spray	
Mixing	Product TA63G20C00 JA052 Thinner	Weight 100 25 40-50

### **TECHNICAL CHARACTERISTICS:**

Specific gravity (kg/l)	0.920 ± 0.010
Solids content (%)	20 ± 1
Viscosity (DIN4 at 20°C)	110" ± 5

### **GENERAL CHARACTERISTICS:**

Pot-life at 20°C	3 h
Recommended application weight (g/m²)	Min 100 - Max 120
Drying time (100 g/m <sup>2</sup> at 20°C)	Dust free: 15-20' Touch dry: 30-45' Stackable: 6-8 hours
Shelf-life (months)	12

### ColorfactoryGmbH

N.B. Data provided on this Technical Data Sheet correspond to our best knowledge and experience. We assure consistency on thechemical-physical characteristics of our products, within the tolerance limits specified on our Technical Data Sheets. Responsibility of final result of product application isfully up to the users, who shall make sure that the productcorresponds to their own needs with regard to application system, to substrates used as well as to working conditions.



## TECHNICAL DATA SHEET

### **FEATURES:**

- can be pigmented with acrylic paste series The pigmented paste load in the converter varies depending on which color shade is needed. For dark colors pigmented pastes load is around 25-30%. Black color works with 10% of paste load.
- smooth to the touch

### **SUBSTRATE PREPARATION:**

The substrate must be properly prepared and cleaned of all kinds of dirt and dust.

#### **WARNING:**

Use only hardeners and thinners recommended by the company's technologists.

### TRANSPORTATION AND STORAGE:

The product should be stored in a tightly closed can, protected from moisture and direct sunlight. After opening the package, the product should be used as quickly as possible. More detailed information on handling the product please find in the safety data sheet.

### **HEALTH & SAFETY:**

For full Health and Safety information, please refer to Safety Data Sheet.

Suitable protective equipment (glasses, gloves, mask etc.) must be worn while using these products. Good ventilation must be provided in the working environment.