


T-bracket universal ø30mm



For other language variants of this document we refer to www.dol-sensors.com or your local dealer.

1 Product description

The T-bracket is an universal bracket for mounting capacitive sensors used for controlling feed transport systems.



- (A) Capacitive sensor $\varnothing 30$ mm
- (B) T-bracket Universal $\varnothing 30$ mm
- (C) Mounting strips
- (D) Plastic tube $\varnothing 40$ mm- 60 mm ($\varnothing 1,5''$ - $2.4''$)

2 Mounting guide

1. Clean the plastic tube.
2. Mount the T-bracket (B) on the plastic tube and fix it with two mounting strips (C).
3. Insert the capacitive $\varnothing 30$ mm sensor (A) into the T-bracket (B). Make sure that the sensor is pressed towards the plastic tube.
4. Fix the sensor with the mounting strips (C).

3 Dimensions

