

OK-ECR s/n 560 6189 Modifications

No	Description	Engineering	Date of CRS	Modified by	W/O
1					
2					
3					
4					
5					
6					
7					
8					
9					
10					
11					
12					
13					
14					
15					
16					
17					
18					
19					
20					
21					

OK-ECR S/N 560 6198 Repairs

No	Description	Engineering	Date of CRS	Repaired by	W/O / ATL
1	Perormed permanent repair of RH H-STAB leading edge after birdstrike. Permanent repair performed by leading edge and de-ice booth replacement IAW MODEL 560XL; 56XSR: Revision - 16, Revision Date - Aug 1, 2018; CHAPTER 51-10-01; 51-40-00; 51-40-01; 51-40-02; 51-40-03; 51-40-04; 51-40-05; 51-40-06; 51-40-08; 51-40-11 For more details see final report: Final_Report_20011887 OK-ECR and also CRS No. 20011887		09.10.2024	Cessna Dusseldorf Citation Srv Ctr GmbH	CRS NO: 20011887 ATL NO: 00036
