

**OWNER:** AEROPARTNER A.S.  
**ADDRESS:** K LETISTI / HANGAR C  
 PRAGUE 161 00  
**PHONE:**  
**FAX:**

**OPERATOR:** AEROPARTNER A.S.  
**ADDRESS:** K LETISTI / HANGAR C  
 PRAGUE 161 00  
**PHONE:**  
**FAX:**

**ANALYST:** COLIN DE MEYER  
**EMAIL:** COLIN.DEMEYER@CAMPSYSTEMS.EU

+33-1.55.93.45.91 (DIRECT)  
 +33 (0) 1.55.93.45.80 (OFFICE)  
 WWW.CAMPSYSTEMS.COM

PLEASE RECORD CHANGES TO ADDRESS, LAST ACTUALS (IF ANY) AND FAX THIS SHEET BACK TO CAMP.

**Filter Criteria:** Task Type In: ('AD','ADP','SB','SBP'); Group by Profile or Bulletin: Profile Type; Mode: With Compliance or Next Due; For: Airframe,Engine,APU Etc;

<b>AIRCRAFT</b>	<b>SERIAL/REGNO:</b> 560XL-6295/OK-WND	<b>MODEL:</b> 560XLS+CITATION XLS+ (MSG)	<b>MANUFACTURER:</b> TEXTRON AVIATION INC.
-----------------	--	--	--

<b>DATES</b>		<b>LAST ACTUALS</b>		<b>CURRENT ACTUAL</b>	
CERTIFICATION DATE:	17-DEC-2020	2092:44 A/C HRS	as of 30-JAN-2025	_____ A/C HRS	as of ____/____/____
		1368 AFL	as of 30-JAN-2025	_____ AFL	as of ____/____/____
		783:06 APH	as of 07-JAN-2025	_____ APH	as of ____/____/____
		1327 APS	as of 07-JAN-2025	_____ APS	as of ____/____/____

<b>APU</b>	<b>SERIAL/PART:</b> P-1098/3800722-1	<b>MODEL:</b> RE100 (XL)	<b>MANUFACTURER:</b> HONEYWELL
<b>INSTALLED ON 01-JAN-2021</b>		<b>LAST ACTUALS</b>	<b>CURRENT ACTUAL</b>
0	APU HRS	783:06 APU HRS	as of 07-JAN-2025 _____ APU HRS as of ____/____/____
0	APUS	1327 APUS	as of 07-JAN-2025 _____ APUS as of ____/____/____

<b>ENGINE NO. 1</b>	<b>SERIAL/PART:</b> PCE-DF0599/30J2934-01	<b>MODEL:</b> PW545C	<b>MANUFACTURER:</b> PRATT & WHITNEY CANADA CORP.
<b>INSTALLED ON 01-JAN-2021</b>		<b>LAST ACTUALS</b>	<b>CURRENT ACTUAL</b>
0	ENG. HRS	0 A/C HRS	2092:44 ENG. HRS as of 30-JAN-2025 _____ ENG. HRS as of ____/____/____
0	ENC	1368 ENC	as of 30-JAN-2025 _____ ENC as of ____/____/____

<b>ENGINE NO. 2</b>	<b>SERIAL/PART:</b> PCE-DF0598/30J2934-01	<b>MODEL:</b> PW545C	<b>MANUFACTURER:</b> PRATT & WHITNEY CANADA CORP.
<b>INSTALLED ON 01-JAN-2021</b>		<b>LAST ACTUALS</b>	<b>CURRENT ACTUAL</b>
0	ENG. HRS	0 A/C HRS	2092:44 ENG. HRS as of 30-JAN-2025 _____ ENG. HRS as of ____/____/____
0	ENC	1368 ENC	as of 30-JAN-2025 _____ ENC as of ____/____/____

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
<b>AIRFRAME - AD - 560XL-6295/OK-WND</b>							
FAA 1974-08-09 R03	LAVATORY PAPER OR LINEN WASTE RECEPTACLE FIRE PREVENTION					MANDATORY	NOT APPLICABLE - AD N/A - ALL PLACARDS ARE INSTALLED. STRICT NON-SMOKING POLICY IN THE AIRCRAFT
		MOS		12-JAN-2023			
		HRS/MSC	1000 (s)	820:45			
		AFL		519			
FAA 1994-01-04	REMOVE AND/OR MODIFY HONEYWELL TCAS II COMPUTERS					MANDATORY	COMPLIED WITH - AD 94-01-04 HAS BEEN COMPLIED WITH AT THE TEXTRON AVIATION INC. FACTORY.
		MOS		17-DEC-2020			
		HRS/MSC	A/R	7:24			
		AFL		5			
FAA 1998-25-02	SKYWATCH SKY 497					MANDATORY	NOT APPLICABLE - AD 98-25-02 IS NOT APPLICABLE DUE TO SUSPECT PARTS ARE NOT INSTALLED ON THIS AIRCRAFT.
		MOS		17-DEC-2020			
		HRS/MSC	A/R	7:24			
		AFL		5			
FAA 2000-03-09	ICING COND FM INFORMATION					MANDATORY	NOT APPLICABLE - AD 2000-03-09 IS NOT APPLICABLE DUE TO AIRCRAFT IS NOT IN THE SUSPECT SERIAL RANGE.
		MOS		17-DEC-2020			
		HRS/MSC	-	7:24			
		AFL		5			
FAA 2000-15-51	AILERON CABLE FAIRLEAD TUBE AND AILERON CABLE SECTOR					MANDATORY	COMPLIED WITH - AD 2000-15-51 HAS BEEN COMPLIED WITH AT THE TEXTRON AVIATION INC. FACTORY.
14-AUG-2000		MOS		17-DEC-2020			
		HRS/MSC	-	7:24			
		AFL		5			
FAA 2001-14-09	WIRING OF THE LANDING LIGHT SWITCH AND THE J-BOX FAIRING RELAYS					MANDATORY	COMPLIED WITH - AD 2001-14-09 HAS BEEN COMPLIED WITH AT THE TEXTRON AVIATION INC. FACTORY.
26-JUL-2001		MOS		17-DEC-2020			
		HRS/MSC	-	7:24			
		AFL		5			
FAA 2001-23-17	GARMIN INTERNATIONAL GNS 430					MANDATORY	NOT APPLICABLE - AD 2001-23-17 IS NOT APPLICABLE DUE TO SUSPECT PARTS ARE NOT INSTALLED ON THIS AIRCRAFT.
		MOS		17-DEC-2020			
		HRS/MSC	A/R	7:24			
		AFL		5			
FAA 2007-11-17	FIRE PROTECTION - INSTALLATION OF IDENTIFICATION SLEEVES ON THE WIRES FOR THE POSITIVE AND NEGATIVE TERMINAL STUDS OF THE APPLICABLE FIRE EXTINGUISHING BOTTLES					MANDATORY	COMPLIED WITH - AD 2007-11-17 HAS BEEN COMPLIED WITH AT THE TEXTRON AVIATION INC. FACTORY.
		MOS		17-DEC-2020			
		HRS/MSC	-	7:24			
		AFL		5			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2010-07-02	PERFORM A ONE-TIME GENERAL VISUAL INSPECTION OF THE MODIFICATION PLATE FOR THE HONEYWELL PRIMUS II NV-850 NAVIGATION RECEIVER MODULE (NRM)						NOT APPLICABLE - AD 2010-07-02 IS NOT APPLICABLE DUE TO SUSPECT PARTS ARE NOT INSTALLED ON THIS AIRCRAFT.
		MOS		17-DEC-2020			
		HRS/MSC	A/R	7:24			
		AFL		5			
FAA 2012-06-01	MODIFY THE DRAIN INSTALLATION OF THE TAILCONE STINGER ON THE AFT CANTED BULKHEAD					MANDATORY	NOT APPLICABLE - AD 2012-06-01 IS NOT APPLICABLE DUE TO AIRCRAFT IS NOT IN THE SUSPECT SERIAL RANGE.
		MOS		17-DEC-2020			
		HRS/MSC	-	7:24			
		AFL		5			
FAA 2012-09-01	LANDING GEAR - TORQUE LUG - INSPECTION					MANDATORY	NOT APPLICABLE - AD 2012-09-01 IS NOT APPLICABLE DUE TO AIRCRAFT IS NOT IN SUSPECT SERIAL RANGE.
07-JUN-2012		MOS		17-DEC-2020			
		HRS/MSC	-	7:24			
		AFL		5			
FAA 2013-09-11	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM					MANDATORY	NOT APPLICABLE - AD 2013-09-11 IS NOT APPLICABLE DUE TO AIRCRAFT IS NOT IN SUSPECT SERIAL RANGE.
05-JUL-2013		MOS		17-DEC-2020			
		HRS/MSC	-	7:24			
		AFL		5			
FAA 2013-09-11 PARA (G)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM INSPECTION FOR PART NUMBER (P/N)					MANDATORY	NOT APPLICABLE - AD 2013-09-11 IS NOT APPLICABLE DUE TO AIRCRAFT IS NOT IN SUSPECT SERIAL RANGE.
05-JUL-2013		DAYs		17-DEC-2020			
		HRS/MSC	-	7:24			
		AFL		5			
FAA 2013-09-11 PARA (H)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM INSPECTION A/C COMPRESSOR HOUR METER AND MAINTENANCE RECORDS					MANDATORY	NOT APPLICABLE - AD 2013-09-11 IS NOT APPLICABLE DUE TO AIRCRAFT IS NOT IN SUSPECT SERIAL RANGE.
05-JUL-2013		DAYs		17-DEC-2020			
		HRS/MSC	-	7:24			
		AFL		5			
FAA 2013-09-11 PARA (I) & (J)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM REPLACEMENT OF A/C COMPRESSOR MOTOR BRUSHES AND RELATED MAINTENANCE MANUAL INFORMATION					MANDATORY	NOT APPLICABLE - AD 2013-09-11 IS NOT APPLICABLE DUE TO AIRCRAFT IS NOT IN SUSPECT SERIAL RANGE.
05-JUL-2013		MOS		17-DEC-2020			
		HRS/MSC	-	7:24			
		AFL		5			
FAA 2013-09-11 PARA (K)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM DEACTIVATION OF A/C SYSTEM					MANDATORY	NOT APPLICABLE - AD 2013-09-11 IS NOT APPLICABLE DUE TO AIRCRAFT IS NOT IN SUSPECT SERIAL RANGE.
05-JUL-2013		MOS		17-DEC-2020			
		HRS/MSC	A/R	7:24			
		AFL		5			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2013-09-11 PARA (L)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM REACTIVATION OF A/C SYSTEM					MANDATORY	NOT APPLICABLE - AD 2013-09-11 IS NOT APPLICABLE DUE TO AIRCRAFT IS NOT IN SUSPECT SERIAL RANGE.
05-JUL-2013	MOS HRS/MSC AFL	A/R		17-DEC-2020 7:24 5			
FAA 2013-09-11 PARA (M)	AIR CONDITIONING - REPLACEMENT OF THE BRUSHES ON A/C COMPRESSOR MOTORS, PART NOS. 1134104-1/1134104-5, OR DEACTIVATION OF THE A/C SYSTEM PARTS RETURN AND REPORTING REQUIREMENTS					MANDATORY	NOT APPLICABLE - AD 2013-09-11 IS NOT APPLICABLE DUE TO AIRCRAFT IS NOT IN SUSPECT SERIAL RANGE.
05-JUL-2013	DAYS HRS/MSC AFL	- (s)		17-DEC-2020 7:24 5			
FAA 2014-18-01	NAVIGATION - ROCKWELL COLLINS, INC. MODE S TRANSPONDERS - INSPECTION / MODIFICATION					MANDATORY	NOT APPLICABLE - AD 2014-18-01 IS NOT APPLICABLE DUE TO PAGES 6 & 7 SECTION (C) (3) (V) AND ECR 58032.
14-OCT-2014	MOS HRS/MSC AFL	-		17-DEC-2020 7:24 5			
FAA 2017-04-14	ELECTRICAL POWER - INSPECTIONS OF THE FUEL TUBE AND RIGHT ALTERNATING CURRENT (AC) GENERATOR WIRES					MANDATORY	COMPLIED WITH - AD 2017-04-14 HAS BEEN COMPLIED WITH AT THE TEXTRON AVIATION INC. FACTORY.
09-MAR-2017	MOS HRS/MSC AFL	- (s)		17-DEC-2020 7:24 5			
FAA 2017-04-14 PARA (G)	ACCOMPLISH GENERAL VISUAL INSPECTIONS OF THE FUEL TUBE AND RIGHT ALTERNATING CURRENT (AC) GENERATOR WIRES FOR EVIDENCE OF DAMAGE, ALL APPLICABLE ADJUSTMENTS, AND ALL APPLICABLE CORRECTIVE ACTIONS					MANDATORY	COMPLIED WITH - AD 2017-04-14 PARA (G) HAS BEEN COMPLIED WITH AT THE TEXTRON AVIATION INC. FACTORY.
09-MAR-2017	DAYS HRS/MSC AFL	-		17-DEC-2020 7:24 5			
FAA 2017-04-14 PARA (H)	SUBMIT A REPORT OF THE FINDINGS (BOTH POSITIVE AND NEGATIVE) OF THE INSPECTIONS REQUIRED BY PARAGRAPH (G) OF THIS AD TO TEXTRON AVIATION					MANDATORY	COMPLIED WITH - AD 2017-04-14 PARA (H) HAS BEEN COMPLIED WITH AT THE TEXTRON AVIATION INC. FACTORY.
09-MAR-2017	DAYS HRS/MSC AFL	- (s)		17-DEC-2020 7:24 5			
FAA 2020-26-05	ENGINE CONTROLS - LEFT AND RIGHT THROTTLE QUADRANT ASSEMBLY SENSOR LINK AND SENSOR DRIVE ARM PIVOT RIVETS - INSPECTION/CORRECTIVE ACTION					MANDATORY	NOT APPLICABLE - NOT APPLICABLE - N/A BY AIRCRAFT S/N
17-DEC-2020	MOS HRS/MSC AFL	-		05-DEC-2022 795:08 499			
FAA 2023-10-02	INDICATING/RECORDING SYSTEM/NAVIGATION - RADIO ALTIMETER - AFM REVISION					MANDATORY	COMPLIED WITH - FAA 2023-10-02
	MOS HRS/MSC AFL APH			22-SEP-2023 1162:20 753			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
FAA 2023-10-02 PARA (H)	REVISE THE LIMITATIONS SECTION OF THE EXISTING AFM (UNTIL 30-JUNE-2023 - SATISFIED BY FAA 2021-23-12)					MANDATORY	COMPLIED WITH - FAA 2023-10-02
26-MAY-2023		MOS		22-SEP-2023			
		HRS/MSC	-	1162:20			
		AFL		753			
		APH					
FAA 2023-10-02 PARA (I)	REVISE THE LIMITATIONS SECTION AND REMOVE THE AFM REVISION REQUIRED BY PARA (H) (AFTER 30 JUN 2023)					MANDATORY	COMPLIED WITH - FAA 2023-10-02
26-MAY-2023		MOS		22-SEP-2023			
		HRS/MSC	-	1162:20			
		AFL		753			
		APH					

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
<b>APPLIANCE - 560XL-6295/OK-WND</b>							
FAA 2012-26-15 R01	APPLIANCE AD - AIR DATA PRESSURE TRANSDUCERS, AS INSTALLED IN AIR DATA COMPUTERS (ADC), AIR DATA MODULES (ADM), AIR DATA ATTITUDE HEADING REFERENCE SYSTEMS (ADAHRS), AND DIGITAL AIR DATA COMPUTERS (DADC)					MANDATORY	NOT APPLICABLE - AD 2012-26-15-R1 IS NOT APPLICABLE DUE TO SUSPECT PARTS ARE NOT INSTALLED ON THIS AIRCRAFT.
03-DEC-2014		MOS HRS/MSC - AFL		17-DEC-2020 7:24 5			
FAA 2020-10-05	APPLIANCE AD - NAVIGATION - ROCKWELL COLLINS PRO LINE 4 AND PRO LINE 21 FLIGHT MANAGEMENT SYSTEMS					MANDATORY	NOT APPLICABLE - AD 2020-10-05 IS NOT APPLICABLE DUE TO SUSPECT PARTS ARE NOT PROGRAMED FOR THIS OPTION.
24-JUN-2020		MOS HRS/MSC - (s) AFL		17-DEC-2020 7:24 5			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
<b>AIRFRAME - SB - 560XL-6295/OK-WND</b>							
SB	560XL-24-21	ELECTRICAL POWER - INSTALL NEW RIGHT ALTERNATOR POWER CONTROL UNIT (PCU) (UE016) MOUNTING BRACKET, SERVICE BULLETIN					COMPLIED WITH - SB560XL-24-21 HAS BEEN COMPLIED WITH AT THE TEXTRON AVIATION INC. FACTORY.
				MOS	17-DEC-2020		
	08-NOV-2019			HRS/MSC - (s)	7:24		
				AFL	5		
SL	SL560XL-23-14	COMMUNICATIONS - TRANSMITTAL OF COLLINS OPERATORS BULLETIN - OPSB 0244-23 RIU-4010 CPDLC ATN-B1 DROPOUTS, SERVICE LETTER				INFORMATIONAL	NOT APPLICABLE - N/A BY A/C SERIAL NUMBER
				MOS			
	27-NOV-2023			HRS/MSC -			
				AFL			
SL	SL560XL-25-20	EQUIPMENT/FURNISHINGS - INSPECTION OF THE INERTIAL REEL AND RESTRAINT SYSTEM, SERVICE LETTER				MANDATORY	NOT APPLICABLE - N/A
				MOS	22-SEP-2023		
	14-AUG-2023			HRS/MSC -	1162:20		
				AFL	753		
				APH			
SL	SL560XL-25-23	EQUIPMENT/FURNISHINGS - PASSENGER SEAT SWIVEL PLATE SWING ARM ASSEMBLY FASTENER INSPECTION FOR PROPER ADHESIVE APPLICATION, SERVICE LETTER				RECOMMENDED	NOT APPLICABLE - N/A
				MOS	22-SEP-2023		
	05-APR-2023			HRS/MSC -	1162:20		
				AFL	753		
				APH			
SL	SL560XL-31-08	INDICATING/RECORDING SYSTEMS - COLLINS ENVIRONMENTAL CONTROLLER (IEC) AND POWER SUPPLY (PWR) IAPS MODULES INSPECTION/REPLACEMENT, SERVICE LETTER				RECOMMENDED	NOT APPLICABLE - N/A FOR A/C SERIAL NUMBER
				MOS	22-SEP-2023		
	14-JUN-2023			HRS/MSC -	1162:20		
				AFL	753		
				APH			
SL	SL560XL-32-30	LANDING GEAR - BRAKE HYDRAULIC RESERVOIR SIGHT GLASS FASTENER TORQUE INSPECTION, SERVICE LETTER				RECOMMENDED	NOT APPLICABLE - N/A
				MOS	22-SEP-2023		
	11-SEP-2023			HRS/MSC -	1162:20		
				AFL	753		
				APH			
SL	SL560XL-52-10	DOORS - REPLACEMENT OF THE CABIN DOOR PRECATCH HOUSING ASSEMBLY, SERVICE LETTER				RECOMMENDED	COMPLIED WITH - ACCOMPLISHED CESSNA SL560XL-52-10, CABIN DOOR PRE-CATCH ASSEMBLY REPLACEMENT DATED 28OCT2021.
				MOS	11-JAN-2022		
	28-OCT-2021			HRS/MSC -	498:48		
				AFL	310		
SL	SL560XL-76-05	ENGINE CONTROLS - INSPECTION OF THE RIGHT ENGINE THROTTLE QUADRANT ROTARY VARIABLE DIFFERENTIAL TRANSFORMER (RVDT) ELECTRICAL WIRING, SERVICE LETTER				MANDATORY	COMPLIED WITH - RVDT ELECTRICAL WIRING INSPECTED, NO CHAFING FOUND. WIRING IN GOOD CONDITION, NO CONTACT WITH GUST LOCK ARM.
				DAYs	01-MAR-2023		
	06-FEB-2023			HRS/MSC -	846:19		
				AFL	533		

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
<b>ENGINE NO. 1 - SB - PCE-DF0599/30J2934-01</b>							
SB	PW500-72-30325 R03	NO. 1 ENGINE - REPLACEMENT OF OIL-PUMP PLAIN SEAL, SERVICE BULLETIN				CATEGORY 6	COMPLIED WITH - AT MANUFACTURE
30-AUG-2017		MOS HRS/MSC AFL ENC		17-DEC-2020 0 0			
SB	PW500-72-30333	NO. 1 ENGINE - REPLACEMENT / MODIFICATION OF FAN ROTOR BALANCING ASSEMBLY, SERVICE BULLETIN				CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
26-JAN-2010		MOS HRS/MSC ENC		17-DEC-2020 0 0			
SB	PW500-72-30354 R01	NO. 1 ENGINE - REPLACEMENT OF ACCESSORY-GEARBOX PLAIN-SEAL, SERVICE BULLETIN				CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
28-APR-2008		MOS HRS/MSC ENC		17-DEC-2020 0 0			
SB	PW500-72-30361	NO. 1 ENGINE - REPLACEMENT OUTER FRONT BYPASS DUCT WITH NEW STUDS, SERVICE BULLETIN				CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
05-MAY-2008		MOS HRS/MSC ENC		17-DEC-2020 0 0			
SB	PW500-72-30362	NO. 1 ENGINE - REPLACEMENT HP TURBINE DISK BALANCING ASSEMBLY WITH THICKER FEATHER SEALS, SERVICE BULLETIN				CATEGORY 6	COMPLIED WITH - AT MANUFACTURE
05-JUN-2008		MOS HRS/MSC ENC		17-DEC-2020 0 0			
SB	PW500-72-30365	NO. 1 ENGINE - REPLACEMENT INLET PRESSURE OIL TUBE ASSY, SERVICE BULLETIN				CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
09-MAY-2008		MOS HRS/MSC ENC		17-DEC-2020 0 0			
SB	PW500-72-30366	NO. 1 ENGINE - REPLACEMENT AIR/OIL SEPARATOR, SERVICE BULLETIN				CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
01-MAY-2008		MOS HRS/MSC ENC		17-DEC-2020 0 0			
SB	PW500-72-30369 R01	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OIL PUMP ASSEMBLY WITH A NEW REAR OIL PUMP HOUSING, SERVICE BULLETIN				CATEGORY 6	COMPLIED WITH - AT MANUFACTURE
02-SEP-2011		MOS HRS/MSC ENC	A/R	17-DEC-2020 0 0			
SB	PW500-72-30370 R01	NO. 1 ENGINE - REPLACEMENT FUEL METERING UNIT, SERVICE BULLETIN				CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
16-FEB-2009		MOS HRS/MSC ENC		17-DEC-2020 0 0			
SB	PW500-72-30371 R02	NO. 1 ENGINE - INTRODUCTION ACCESSORY GEARBOX FCU-STARTER GEARSHAFT OIL BAFFLE, SERVICE BULLETIN				CATEGORY 10	COMPLIED WITH - AT MANUFACTURE
11-MAR-2014		MOS HRS/MSC ENC		17-DEC-2020 0 0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PW500-72-30373	NO. 1 ENGINE - REPLACEMENT SECONDARY FUEL PRESSURE TUBE AND SUPPORT BRACKET, SERVICE BULLETIN					CATEGORY 3	COMPLIED WITH - AT MANUFACTURE
15-AUG-2008		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30376 R02	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF OIL PUMP ASSEMBLY AND OIL-PUMP-DRIVE SPUR GEAR, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
16-JUN-2016		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30379 R01	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF BY-PASS DUCTS, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
11-SEP-2015		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30380	NO. 1 ENGINE - GEARSHAFT / REPLACEMENT GEARBOX-DRIVE-SHAFT-ACCESSORY, GEARBOX DRIVE GEARSHAFT-ASSEMBLY, GEARBOX DRIVE SPLINE BEVEL, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
09-DEC-2008		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30384 R01	NO. 1 ENGINE - REPLACEMENT OF AIR/OIL SEPARATOR, SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH - AT MANUFACTURE
02-SEP-2011		MOS		17-DEC-2020			
		HRS/MSC	A/R	0			
		ENC		0			
SB PW500-72-30385	NO. 1 ENGINE - REPLACEMENT OF DATA COLLECTION UNIT, SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH - AT MANUFACTURE
27-JAN-2009		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30389	NO. 1 ENGINE - REPLACEMENT OF CARBON SEAL, NO. 4 BEARING, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
05-MAR-2009		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30391	NO. 1 ENGINE - REPLACEMENT INLET PRESSURE OIL TUBE ASSY, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
11-JUN-2009		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30392	NO. 1 ENGINE - REPLACEMENT OF BOLTS, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
25-JUN-2009		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30393 R01	NO. 1 ENGINE - REPLACEMENT OF EEC SUPPORT BRACKETS, SERVICE BULLETIN					CATEGORY 3	COMPLIED WITH - AT MANUFACTURE
02-JUN-2010		MOS		17-DEC-2020			
		HRS/MSC	A/R	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PW500-72-30400 R04	NO. 1 ENGINE - REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY AND INTERSHAFT SEAL CARRIER, SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH - AT MANUFACTURE
23-NOV-2016		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30403 R04	NO. 1 ENGINE - REPLACEMENT OF TEE HEAD BOLT/1ST.- 2ND. STAGE HP COMPRESSOR ASSEMBLIES, SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH - AT MANUFACTURE
12-FEB-2019		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30404 R03	NO. 1 ENGINE - REPLACEMENT OF SERVO VALVE FOR THE INTERCOMPRESSOR BLEED-VALVE, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
03-MAY-2010		MOS		17-DEC-2020			
		HRS/MSC	A/R	0			
		ENC		0			
SB PW500-72-30405 R04	NO. 1 ENGINE - REPLACEMENT OF FUEL NOZZLE MANIFOLD, SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH - AT MANUFACTURE
14-MAR-2018		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30407 R01	NO. 1 ENGINE - REPLACEMENT / MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC), SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
30-AUG-2017		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30411 R01	NO. 1 ENGINE - REPLACEMENT OF GASKETS, SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH - AT MANUFACTURE
22-MAR-2010		MOS		17-DEC-2020			
		HRS/MSC	A/R	0			
		ENC		0			
SB PW500-72-30413 R11	NO. 1 ENGINE - INTRODUCTION OF DEEPER SUMP, SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH - AT MANUFACTURE
30-NOV-2018		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30415 R03	NO. 1 ENGINE - REPLACEMENT OF NO. 4 ROLLER BEARING, SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH - AT MANUFACTURE
13-OCT-2016		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30416 R01	NO. 1 ENGINE - REPLACEMENT OF NO.4 BEARING CARBON SEAL, SERVICE BULLETIN					CATEGORY 10	COMPLIED WITH - AT MANUFACTURE
23-OCT-2013		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30417 R08	NO. 1 ENGINE - REPLACEMENT OF FRONT SEAL RUNNER, NO. 4 BEARING, SERVICE BULLETIN					CATEGORY 10	COMPLIED WITH - AT MANUFACTURE
23-NOV-2012		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30418 R02	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF ELECTRICAL WIRING HARNESS (TTO SENSOR), SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH - AT MANUFACTURE
12-MAY-2016		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PW500-72-30419 R01	NO. 1 ENGINE - REPLACEMENT OF COMBUSTION CHAMBER LINER, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
26-FEB-2016		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30420 R06	NO. 1 ENGINE - REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE, SERVICE BULLETIN				CATEGORY 3	COMPLIED WITH - AT MANUFACTURE	
16-JUL-2020		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30423 R01	NO. 1 ENGINE - REPLACEMENT/MODIFICATION INTERMEDIATE CASE ASSEMBLY, SERVICE BULLETIN				CATEGORY 6	COMPLIED WITH - AT MANUFACTURE	
17-SEP-2012		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30426	NO. 1 ENGINE - FAN CASE ASSEMBLY - REPLACEMENT OF, SERVICE BULLETIN				CATEGORY 7	COMPLIED WITH - AT MANUFACTURE	
08-JUL-2011		MOS		17-DEC-2020			
		HRS/MSC	A/R	0			
		ENC		0			
SB PW500-72-30427 R04	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY, SERVICE BULLETIN				CATEGORY 7	COMPLIED WITH - AT MANUFACTURE	
06-NOV-2018		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30428 R06	NO. 1 ENGINE - REPLACEMENT OF FUEL MANIFOLD SYSTEM INTERFACE, SERVICE BULLETIN				CATEGORY 6	COMPLIED WITH - AT MANUFACTURE	
08-FEB-2019		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30429 R06	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY, SERVICE BULLETIN				CATEGORY 6	COMPLIED WITH - AT MANUFACTURE	
02-AUG-2017		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30432 R01	NO. 1 ENGINE - PLAIN SEAL ACCESSORY GEARBOX - REPLACEMENT OF, SERVICE BULLETIN				CATEGORY 7	COMPLIED WITH - AT MANUFACTURE	
12-MAY-2011		MOS		17-DEC-2020			
		HRS/MSC	A/R	0			
		ENC		0			
SB PW500-72-30434 R05	NO. 1 ENGINE - REPLACEMENT - MODIFICATION OF ELECTRONIC ENGINE CONTROL (SUPERSEDED BY SB PW500-72-30478 R03), SERVICE BULLETIN				CATEGORY 10	COMPLIED WITH - AT MANUFACTURE	
15-JUL-2015		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30436 R04	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF LPT 2ND STAGE VANE ASSEMBLY, SERVICE BULLETIN				CATEGORY 7	COMPLIED WITH - AT MANUFACTURE	
18-APR-2018		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30438 R05	NO. 1 ENGINE - REPLACEMENT / MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC) (SUPERSEDED BY SB PW500-72-30478 R03), SERVICE BULLETIN				CATEGORY 10	COMPLIED WITH - AT MANUFACTURE	
15-JUL-2015		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PW500-72-30440 R06	NO. 1 ENGINE - REPLACEMENT OF NEW OR MODIFIED OIL TANK VENT TUBE ASSEMBLY, SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH - AT MANUFACTURE
24-MAY-2019		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30445	NO. 1 ENGINE - REPLACEMENT OF ELECTRICAL WIRING HARNESS, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
16-SEP-2011		MOS		17-DEC-2020			
		HRS/MSC	A/R	0			
		ENC		0			
SB PW500-72-30446 R02	NO. 1 ENGINE - REPLACEMENT OF LOW PRESSURE COMPRESSOR SHAFT BALANCING ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
11-MAR-2014		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30447 R01	NO. 1 ENGINE - NEW COATING MODIFICATION OF GAS GENERATOR CASE, SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH - AT MANUFACTURE
09-MAY-2012		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30449 R02	NO. 1 ENGINE - REPLACEMENT OF HP TURBINE DISK ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
11-SEP-2015		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30453 R03	NO. 1 ENGINE - REPLACEMENT OF NO. 4 CARBON SEAL, SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH - AT MANUFACTURE
11-AUG-2017		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30463 R02	NO. 1 ENGINE - REPLACEMENT OF ACCESSORY DRIVE LIP SEAL, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
18-AUG-2016		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30465 R02	NO. 1 ENGINE - REPLACEMENT OF FUEL MANIFOLD TUBES, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
08-JUL-2016		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30466 R02	NO. 1 ENGINE - REPLACEMENT / MODIFICATION OF 2ND STAGE TURBINE VANE ASSY, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
12-JUL-2018		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30470 R01	NO. 1 ENGINE - REPLACEMENT OF DATA COLLECTION UNIT, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
31-AUG-2015		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30474 R03	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF ELECTRICAL WIRING HARNESS, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
16-OCT-2018		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PW500-72-30475 R03	NO. 1 ENGINE - REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
18-AUG-2016		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30478 R04	NO. 1 ENGINE - REPLACEMENT / FIELD MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC), SERVICE BULLETIN			CATEGORY 3		COMPLIED WITH - AT MANUFACTURE	
01-DEC-2015		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30479 R06	NO. 1 ENGINE - REPLACEMENT OF NO. 4 BEARING FRONT COVER, HPT ROTOR SEAL, COLD START VALVE ASSEMBLY AND THE OIL TRANSFER TUBE, SERVICE BULLETIN			CATEGORY 3		COMPLIED WITH - AT MANUFACTURE	
20-MAY-2016		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30480	NO. 1 ENGINE - REPLACEMENT OF REAR OUTER BY-PASS DUCT, SILVER PLATED NUTS, SERVICE BULLETIN			CATEGORY 7		COMPLIED WITH - AT MANUFACTURE	
05-DEC-2013		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30481	NO. 1 ENGINE - REPLACEMENT OF FUEL SHUT-OFF CABLE, SERVICE BULLETIN			CATEGORY 7		COMPLIED WITH - AT MANUFACTURE	
06-DEC-2013		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30483 R03	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY (SUPERSEDED BY SB PW500-72-30492 R02), SERVICE BULLETIN			CATEGORY 10		COMPLIED WITH - AT MANUFACTURE	
22-OCT-2014		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30485 R02	NO. 1 ENGINE - REPLACEMENT OF REAR OUTER BY-PASS DUCT HARDWARE, SERVICE BULLETIN			CATEGORY 7		COMPLIED WITH - AT MANUFACTURE	
14-AUG-2017		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30491 R02	NO. 1 ENGINE - REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY, SERVICE BULLETIN			CATEGORY 7		COMPLIED WITH - AT MANUFACTURE	
27-JUL-2015		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30492 R04	NO. 1 ENGINE - REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER, SERVICE BULLETIN			CATEGORY 6		COMPLIED WITH - AT MANUFACTURE	
10-JAN-2017		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30495 R01	NO. 1 ENGINE - MODIFICATION OF ACCESSORY GEARBOX COVER BOLT TORQUING PROCEDURE, SERVICE BULLETIN			CATEGORY 10		COMPLIED WITH - AT MANUFACTURE	
13-OCT-2016		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PW500-72-30496 R01	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF SECOND STAGE TURBINE VANE, SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH - AT MANUFACTURE
01-OCT-2018		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30498 R03	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
20-SEP-2017		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30502 R04	NO. 1 ENGINE - REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
20-OCT-2016		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30504 R03	NO. 1 ENGINE - REPLACEMENT OF FUEL/OIL HEAT EXCHANGER, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
15-JAN-2019		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30505 R02	NO. 1 ENGINE - REPLACEMENT OF BLEED OFF VALVE (BOV) GASKETS, SERVICE BULLETIN					CATEGORY 3	COMPLIED WITH - AT MANUFACTURE
21-MAY-2015		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30506 R02	NO. 1 ENGINE - REPLACEMENT OF FUEL MANIFOLD ADAPTERS, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
11-SEP-2015		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30508 R03	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY AND OIL LEVEL INDICATORS, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
06-DEC-2018		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30510	NO. 1 ENGINE - REPLACEMENT OF PRIMARY AND SECONDARY FUEL TUBE SUPPORT BRACKET, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
29-JAN-2015		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30516 R02	NO. 1 ENGINE - REPLACEMENT OF HP TURBINE SEAL RINGS, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
22-JUN-2015		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30517 R01	NO. 1 ENGINE - DELETION OF IGNITER FLANGE GASKETS, SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH - AT MANUFACTURE
05-JAN-2016		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30521 R01	NO. 1 ENGINE - REPLACEMENT OF COMBUSTION CHAMBER LINER, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
18-DEC-2015		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PW500-72-30523 R01	NO. 1 ENGINE - REPLACEMENT OF ACCESSORY GEARBOX COVER GASKET, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
30-MAY-2016		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30534 R04	NO. 1 ENGINE - REPLACEMENT OF DATA COLLECTION UNIT, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
29-JUN-2018		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30535 R01	NO. 1 ENGINE - REPLACEMENT OF ENGINE SHIPPING CONTAINER, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
29-SEP-2017		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30539 R01	NO. 1 ENGINE - REPLACEMENT OF FUEL SUPPLY PAD, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
01-OCT-2019		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30541 R01	NO. 1 ENGINE - REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
12-JUN-2018		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30542	NO. 1 ENGINE - REPLACEMENT OF IGNITER CABLES, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
25-APR-2018		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30546 R01	NO. 1 ENGINE - REPLACEMENT OF HPT AIR SEAL, SERVICE BULLETIN					CATEGORY 9	COMPLIED WITH - AT MANUFACTURE
06-NOV-2019		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30548 R02	NO. 1 ENGINE - REPLACEMENT/MODIFICATION OF ANTI-ICING VALVE, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
21-SEP-2018		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30550	NO. 1 ENGINE - REPLACEMENT OF NO. 4 BEARING SEAL RUNNERS, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
09-MAY-2019		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
<b>ENGINE NO. 2 - SB - PCE-DF0598/30J2934-01</b>							
SB	PW500-72-30325 R03	NO. 2 ENGINE - REPLACEMENT OF OIL-PUMP PLAIN SEAL, SERVICE BULLETIN				CATEGORY 6	COMPLIED WITH - AT MANUFACTURE
30-AUG-2017		MOS HRS/MSC ENC		17-DEC-2020 0 0			
SB	PW500-72-30333	NO. 2 ENGINE - REPLACEMENT / MODIFICATION OF FAN ROTOR BALANCING ASSEMBLY, SERVICE BULLETIN				CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
26-JAN-2010		MOS HRS/MSC ENC		17-DEC-2020 0 0			
SB	PW500-72-30354 R01	NO. 2 ENGINE - REPLACEMENT OF ACCESSORY-GEARBOX PLAIN-SEAL, SERVICE BULLETIN				CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
28-APR-2008		MOS HRS/MSC ENC		17-DEC-2020 0 0			
SB	PW500-72-30361	NO. 2 ENGINE - REPLACEMENT OUTER FRONT BYPASS DUCT WITH NEW STUDS, SERVICE BULLETIN				CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
05-MAY-2008		MOS HRS/MSC ENC		17-DEC-2020 0 0			
SB	PW500-72-30362	NO. 2 ENGINE - REPLACEMENT HP TURBINE DISK BALANCING ASSEMBLY WITH THICKER FEATHER SEALS, SERVICE BULLETIN				CATEGORY 6	COMPLIED WITH - AT MANUFACTURE
05-JUN-2008		MOS HRS/MSC ENC		17-DEC-2020 0 0			
SB	PW500-72-30365	NO. 2 ENGINE - REPLACEMENT INLET PRESSURE OIL TUBE ASSY, SERVICE BULLETIN				CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
09-MAY-2008		MOS HRS/MSC ENC		17-DEC-2020 0 0			
SB	PW500-72-30366	NO. 2 ENGINE - REPLACEMENT AIR/OIL SEPARATOR, SERVICE BULLETIN				CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
01-MAY-2008		MOS HRS/MSC ENC		17-DEC-2020 0 0			
SB	PW500-72-30369 R01	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OIL PUMP ASSEMBLY WITH A NEW REAR OIL PUMP HOUSING, SERVICE BULLETIN				CATEGORY 6	COMPLIED WITH - AT MANUFACTURE
02-SEP-2011		MOS HRS/MSC ENC	A/R	17-DEC-2020 0 0			
SB	PW500-72-30370 R01	NO. 2 ENGINE - REPLACEMENT FUEL METERING UNIT, SERVICE BULLETIN				CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
16-FEB-2009		MOS HRS/MSC ENC		17-DEC-2020 0 0			
SB	PW500-72-30371 R02	NO. 2 ENGINE - INTRODUCTION ACCESSORY GEARBOX FCU-STARTER GEARSHAFT OIL BAFFLE, SERVICE BULLETIN				CATEGORY 10	COMPLIED WITH - AT MANUFACTURE
11-MAR-2014		MOS HRS/MSC ENC		17-DEC-2020 0 0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PW500-72-30373	NO. 2 ENGINE - REPLACEMENT SECONDARY FUEL PRESSURE TUBE AND SUPPORT BRACKET, SERVICE BULLETIN					CATEGORY 3	COMPLIED WITH - AT MANUFACTURE
15-AUG-2008		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30376 R02	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF OIL PUMP ASSEMBLY AND OIL-PUMP-DRIVE SPUR GEAR, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
16-JUN-2016		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30379 R01	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF BY-PASS DUCTS, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
11-SEP-2015		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30380	NO. 2 ENGINE - GEARSHAFT / REPLACEMENT GEARBOX-DRIVE-SHAFT-ACCESSORY, GEARBOX DRIVE GEARSHAFT-ASSEMBLY, GEARBOX DRIVE SPLINE BEVEL, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
09-DEC-2008		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30384 R01	NO. 2 ENGINE - REPLACEMENT OF AIR/OIL SEPARATOR, SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH - AT MANUFACTURE
02-SEP-2011		MOS		17-DEC-2020			
		HRS/MSC	A/R	0			
		ENC		0			
SB PW500-72-30385	NO. 2 ENGINE - REPLACEMENT OF DATA COLLECTION UNIT, SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH - AT MANUFACTURE
27-JAN-2009		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30389	NO. 2 ENGINE - REPLACEMENT OF CARBON SEAL, NO. 4 BEARING, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
05-MAR-2009		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30391	NO. 2 ENGINE - REPLACEMENT INLET PRESSURE OIL TUBE ASSY, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
11-JUN-2009		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30392	NO. 2 ENGINE - REPLACEMENT OF BOLTS, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
25-JUN-2009		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30393 R01	NO. 2 ENGINE - REPLACEMENT OF EEC SUPPORT BRACKETS, SERVICE BULLETIN					CATEGORY 3	COMPLIED WITH - AT MANUFACTURE
02-JUN-2010		MOS		17-DEC-2020			
		HRS/MSC	A/R	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PW500-72-30400 R04	NO. 2 ENGINE - REPLACEMENT OF INTERMEDIATE CASE ASSEMBLY AND INTERSHAFT SEAL CARRIER, SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH - AT MANUFACTURE
23-NOV-2016		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30403 R04	NO. 2 ENGINE - REPLACEMENT OF TEE HEAD BOLT/1ST.- 2ND. STAGE HP COMPRESSOR ASSEMBLIES, SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH - AT MANUFACTURE
12-FEB-2019		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30404 R03	NO. 2 ENGINE - REPLACEMENT OF SERVO VALVE FOR THE INTERCOMPRESSOR BLEED-VALVE, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
03-MAY-2010		MOS		17-DEC-2020			
		HRS/MSC	A/R	0			
		ENC		0			
SB PW500-72-30405 R04	NO. 2 ENGINE - REPLACEMENT OF FUEL NOZZLE MANIFOLD, SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH - AT MANUFACTURE
14-MAR-2018		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30407 R01	NO. 2 ENGINE - REPLACEMENT / MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC), SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
30-AUG-2017		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30411 R01	NO. 2 ENGINE - REPLACEMENT OF GASKETS, SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH - AT MANUFACTURE
22-MAR-2010		MOS		17-DEC-2020			
		HRS/MSC	A/R	0			
		ENC		0			
SB PW500-72-30413 R11	NO. 2 ENGINE - INTRODUCTION OF DEEPER SUMP, SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH - AT MANUFACTURE
30-NOV-2018		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30415 R03	NO. 2 ENGINE - REPLACEMENT OF NO. 4 ROLLER BEARING, SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH - AT MANUFACTURE
13-OCT-2016		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30416 R01	NO. 2 ENGINE - REPLACEMENT OF NO.4 BEARING CARBON SEAL, SERVICE BULLETIN					CATEGORY 10	COMPLIED WITH - AT MANUFACTURE
23-OCT-2013		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30417 R08	NO. 2 ENGINE - REPLACEMENT OF FRONT SEAL RUNNER, NO. 4 BEARING, SERVICE BULLETIN					CATEGORY 10	COMPLIED WITH - AT MANUFACTURE
23-NOV-2012		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30418 R02	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF ELECTRICAL WIRING HARNESS (TTO SENSOR), SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH - AT MANUFACTURE
12-MAY-2016		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PW500-72-30419 R01	NO. 2 ENGINE - REPLACEMENT OF COMBUSTION CHAMBER LINER, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
26-FEB-2016		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30420 R06	NO. 2 ENGINE - REPLACEMENT OF INTERCOMPRESSOR BLEED VALVE/ SERVO-VALVE, SERVICE BULLETIN				CATEGORY 3	COMPLIED WITH - AT MANUFACTURE	
16-JUL-2020		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30423 R01	NO. 2 ENGINE - REPLACEMENT/MODIFICATION INTERMEDIATE CASE ASSEMBLY, SERVICE BULLETIN				CATEGORY 6	COMPLIED WITH - AT MANUFACTURE	
17-SEP-2012		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30426	NO. 2 ENGINE - FAN CASE ASSEMBLY - REPLACEMENT OF, SERVICE BULLETIN				CATEGORY 7	COMPLIED WITH - AT MANUFACTURE	
08-JUL-2011		MOS		17-DEC-2020			
		HRS/MSC	A/R	0			
		ENC		0			
SB PW500-72-30427 R04	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY, SERVICE BULLETIN				CATEGORY 7	COMPLIED WITH - AT MANUFACTURE	
06-NOV-2018		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30428 R06	NO. 2 ENGINE - REPLACEMENT OF FUEL MANIFOLD SYSTEM INTERFACE, SERVICE BULLETIN				CATEGORY 6	COMPLIED WITH - AT MANUFACTURE	
08-FEB-2019		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30429 R06	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY, SERVICE BULLETIN				CATEGORY 6	COMPLIED WITH - AT MANUFACTURE	
02-AUG-2017		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30432 R01	NO. 2 ENGINE - PLAIN SEAL ACCESSORY GEARBOX - REPLACEMENT OF, SERVICE BULLETIN				CATEGORY 7	COMPLIED WITH - AT MANUFACTURE	
12-MAY-2011		MOS		17-DEC-2020			
		HRS/MSC	A/R	0			
		ENC		0			
SB PW500-72-30434 R05	NO. 2 ENGINE - REPLACEMENT - MODIFICATION OF ELECTRONIC ENGINE CONTROL (SUPERSEDED BY SB PW500-72-30478 R03), SERVICE BULLETIN				CATEGORY 10	COMPLIED WITH - AT MANUFACTURE	
15-JUL-2015		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30436 R04	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF LPT 2ND STAGE VANE ASSEMBLY, SERVICE BULLETIN				CATEGORY 7	COMPLIED WITH - AT MANUFACTURE	
18-APR-2018		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30438 R05	NO. 2 ENGINE - REPLACEMENT / MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC) (SUPERSEDED BY SB PW500-72-30478 R03), SERVICE BULLETIN				CATEGORY 10	COMPLIED WITH - AT MANUFACTURE	
15-JUL-2015		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PW500-72-30440 R06	NO. 2 ENGINE - REPLACEMENT OF NEW OR MODIFIED OIL TANK VENT TUBE ASSEMBLY, SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH - AT MANUFACTURE
24-MAY-2019		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30445	NO. 2 ENGINE - REPLACEMENT OF ELECTRICAL WIRING HARNESS, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
16-SEP-2011		MOS		17-DEC-2020			
		HRS/MSC	A/R	0			
		ENC		0			
SB PW500-72-30446 R02	NO. 2 ENGINE - REPLACEMENT OF LOW PRESSURE COMPRESSOR SHAFT BALANCING ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
11-MAR-2014		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30447 R01	NO. 2 ENGINE - NEW COATING MODIFICATION OF GAS GENERATOR CASE, SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH - AT MANUFACTURE
09-MAY-2012		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30449 R02	NO. 2 ENGINE - REPLACEMENT OF HP TURBINE DISK ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
11-SEP-2015		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30453 R03	NO. 2 ENGINE - REPLACEMENT OF NO. 4 CARBON SEAL, SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH - AT MANUFACTURE
11-AUG-2017		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30463 R02	NO. 2 ENGINE - REPLACEMENT OF ACCESSORY DRIVE LIP SEAL, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
18-AUG-2016		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30465 R02	NO. 2 ENGINE - REPLACEMENT OF FUEL MANIFOLD TUBES, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
08-JUL-2016		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30466 R02	NO. 2 ENGINE - REPLACEMENT / MODIFICATION OF 2ND STAGE TURBINE VANE ASSY, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
12-JUL-2018		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30470 R01	NO. 2 ENGINE - REPLACEMENT OF DATA COLLECTION UNIT, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
31-AUG-2015		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30474 R03	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF ELECTRICAL WIRING HARNESS, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
16-OCT-2018		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PW500-72-30475 R03	NO. 2 ENGINE - REPLACEMENT OF ACCESSORY DRIVE GEARSHAFT ASSEMBLY AND FUEL CONTROL DRIVE SPUR GEARSHAFT ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
18-AUG-2016		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30478 R04	NO. 2 ENGINE - REPLACEMENT / FIELD MODIFICATION OF ELECTRONIC ENGINE CONTROL (EEC), SERVICE BULLETIN			CATEGORY 3		COMPLIED WITH - AT MANUFACTURE	
01-DEC-2015		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30479 R06	NO. 2 ENGINE - REPLACEMENT OF NO. 4 BEARING FRONT COVER, HPT ROTOR SEAL, COLD START VALVE ASSEMBLY AND THE OIL TRANSFER TUBE, SERVICE BULLETIN			CATEGORY 3		COMPLIED WITH - AT MANUFACTURE	
20-MAY-2016		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30480	NO. 2 ENGINE - REPLACEMENT OF REAR OUTER BY-PASS DUCT, SILVER PLATED NUTS, SERVICE BULLETIN			CATEGORY 7		COMPLIED WITH - AT MANUFACTURE	
05-DEC-2013		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30481	NO. 2 ENGINE - REPLACEMENT OF FUEL SHUT-OFF CABLE, SERVICE BULLETIN			CATEGORY 7		COMPLIED WITH - AT MANUFACTURE	
06-DEC-2013		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30483 R03	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY (SUPERSEDED BY SB PW500-72-30492 R02), SERVICE BULLETIN			CATEGORY 10		COMPLIED WITH - AT MANUFACTURE	
22-OCT-2014		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30485 R02	NO. 2 ENGINE - REPLACEMENT OF REAR OUTER BY-PASS DUCT HARDWARE, SERVICE BULLETIN			CATEGORY 7		COMPLIED WITH - AT MANUFACTURE	
14-AUG-2017		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30491 R02	NO. 2 ENGINE - REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER ASSEMBLY, SERVICE BULLETIN			CATEGORY 7		COMPLIED WITH - AT MANUFACTURE	
27-JUL-2015		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30492 R04	NO. 2 ENGINE - REPLACEMENT / MODIFICATION OF COMBUSTION CHAMBER LINER, SERVICE BULLETIN			CATEGORY 6		COMPLIED WITH - AT MANUFACTURE	
10-JAN-2017		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30495 R01	NO. 2 ENGINE - MODIFICATION OF ACCESSORY GEARBOX COVER BOLT TORQUING PROCEDURE, SERVICE BULLETIN			CATEGORY 10		COMPLIED WITH - AT MANUFACTURE	
13-OCT-2016		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PW500-72-30496 R01	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF SECOND STAGE TURBINE VANE, SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH - AT MANUFACTURE
01-OCT-2018		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30498 R03	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
20-SEP-2017		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30502 R04	NO. 2 ENGINE - REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
20-OCT-2016		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30504 R03	NO. 2 ENGINE - REPLACEMENT OF FUEL/OIL HEAT EXCHANGER, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
15-JAN-2019		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30505 R02	NO. 2 ENGINE - REPLACEMENT OF BLEED OFF VALVE (BOV) GASKETS, SERVICE BULLETIN					CATEGORY 3	COMPLIED WITH - AT MANUFACTURE
21-MAY-2015		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30506 R02	NO. 2 ENGINE - REPLACEMENT OF FUEL MANIFOLD ADAPTERS, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
11-SEP-2015		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30508 R03	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF INTERMEDIATE CASE ASSEMBLY AND OIL LEVEL INDICATORS, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
06-DEC-2018		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30510	NO. 2 ENGINE - REPLACEMENT OF PRIMARY AND SECONDARY FUEL TUBE SUPPORT BRACKET, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
29-JAN-2015		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30516 R02	NO. 2 ENGINE - REPLACEMENT OF HP TURBINE SEAL RINGS, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
22-JUN-2015		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30517 R01	NO. 2 ENGINE - DELETION OF IGNITER FLANGE GASKETS, SERVICE BULLETIN					CATEGORY 6	COMPLIED WITH - AT MANUFACTURE
05-JAN-2016		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30521 R01	NO. 2 ENGINE - REPLACEMENT OF COMBUSTION CHAMBER LINER, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
18-DEC-2015		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			

Task No.	Description	Unit	Interval	Compliance	Next Due	Disposition	MOC
SB PW500-72-30523 R01	NO. 2 ENGINE - REPLACEMENT OF ACCESSORY GEARBOX COVER GASKET, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
30-MAY-2016		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30534 R04	NO. 2 ENGINE - REPLACEMENT OF DATA COLLECTION UNIT, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
29-JUN-2018		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30535 R01	NO. 2 ENGINE - REPLACEMENT OF ENGINE SHIPPING CONTAINER, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
29-SEP-2017		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30539 R01	NO. 2 ENGINE - REPLACEMENT OF FUEL SUPPLY PAD, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
01-OCT-2019		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30541 R01	NO. 2 ENGINE - REPLACEMENT OF FUEL CONTROL DRIVE AND ACCESSORY DRIVE PLAIN SEAL, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
12-JUN-2018		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30542	NO. 2 ENGINE - REPLACEMENT OF IGNITER CABLES, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
25-APR-2018		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30546 R01	NO. 2 ENGINE - REPLACEMENT OF HPT AIR SEAL, SERVICE BULLETIN					CATEGORY 9	COMPLIED WITH - AT MANUFACTURE
06-NOV-2019		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30548 R02	NO. 2 ENGINE - REPLACEMENT/MODIFICATION OF ANTI-ICING VALVE, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
21-SEP-2018		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			
SB PW500-72-30550	NO. 2 ENGINE - REPLACEMENT OF NO. 4 BEARING SEAL RUNNERS, SERVICE BULLETIN					CATEGORY 7	COMPLIED WITH - AT MANUFACTURE
09-MAY-2019		MOS		17-DEC-2020			
		HRS/MSC	-	0			
		ENC		0			